Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

May 1-31, 1983

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	٧
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	χV
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	10
Domestic Licensing of Special Nuclear Material — Docket 70	431
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	439
Licensing of Independent Spent Fuel Storage — Docket 72	444
Nondocketed Items	
10 CFR — Commission Meeting Records	445
ACRS — Adivsory Committee on Reactor Safeguards	446
ADVCM — NRC Advisory Committees	447
COMMISSION — NRC Commissioners	448
CONTRACT — NRC Contracts and Modifications	450
FOIA — Freedom of Information Act Requests and Releases	455
GEN TECH IS — Generic Technical Issues	475
I&E — Inspection and Enforcement	476
MISC — Public Document Room Miscellaneous	479
NUREG — NUREG Reports and Related Correspondence	480
ORG — Correspondence with Other Organizations	497
PR — Proposed Rule	498
PROJ — Projects - Predocket Licensing	501
PT 21 — Noncompliance Reports and Related Correspondence	502
QA999 — Quality Assurance Inspections	504
REGGD — Regulatory Guides	509
RES — Research and Technical Assistance Reports	509
REVIEW GROUP — NRC Research Review Groups	510
SECY — Position Papers Before the Commission	512
STATE PROG — State Programs	512
TOPREP — Vendor Reports and Related Correspondence	513
WASTE MGT — Nuclear Waste Management	518
XPORTLIC — Export and Import Licenses	519
Personal Author Index	525
Corporate Source Index	557
Report Number Index	589
Cross Reference of Enclosures to Principal Documents	591
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- 1. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P. Operating license stage documents & correspondence

8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research

Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 5 Tennessee Valley Authority. 6 82/03/04. 7 VASSALLO, D.B.

Operating Reactors Branch 2. 8 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
OSURE — Financial Disclosure Information
Freedom of Information Act Requests and Releases
H IS — Generic Technical Issues

I&E - Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP -- NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Ra	dwaste Disposal Sites - Docket 27		40-8064	Exxon Minerals Co. USA, Houston, TX	7
27-039	Sheffield, IL, U.S. Ecology, Inc	1	40-8084	Rio Algom Corp., Moab, UT	7
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8102	Exxon Co. USA, Houston, TX	7
			40-8137	Pacific Technical Corp., Santa Barbara, CA	7
75			40-8202	Battelle Memorial Institute, Columbus, OH	7
	nsing of Source Material — Docket 40		40-8348	Minerals Exploration Co., Los Angeles, CA	8
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1	40-8380	Rocky Mountain Energy Co.,	
40-0215	S. F. Applicance, Ltd., Morris, IL	1	10.0104	Broomfield, CO	8
40-0229	Union Carbide Corp., Riverton, WY	1	40-8406	Pesses Co., Solon, OH	8
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8452	Bear Creek Uranium Co., Casper, WY	8
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8502	Wyoming Mineral Corp., Lakewood, CO	8
40-1162	Western Nuclear, Inc., Jeffrey City, WY	4	40-8550	Holmes & Narver, Inc., Anaheim, CA	8
40-1341	Tennessee Valley Authority, Chattanooga, TN	5	40-8584	Minerals Exploration Co., Los Angeles, CA	8
40-1478	Spencer Chemical Co., Kansas City, MO	5	40-8602	Silver King Mines, Inc., Casper, WY	8
40-2061	Kerr-McGee Chemical Corp.,	3	40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	8
40-2001	Oklahoma City, OK	5	40-8675	Energy Fuels Nuclear, Inc., Denver, CO	9
40-2259	Pathfinder Mines Corp., Riverton, WY	5	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	9
40-3079	Technical Operations, Inc., Burlington, MA	5	40-8693	Ogle Petroleum, Inc., Santa Barbara, CA	9
40-3392	Allied Chemical Corp., Morristown, NJ	5	40-8697	Rocky Mountain Energy Co., Denver, CO	9
40-3453	Atlas Mineral, Inc., Denver, CO	5	40-8698	Plateau Resources, Ltd., Grand Junction, CO .	9
40-4492	Federal-American Partners, Riverton, WY	6	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	9
40-6500	Energy, Dept. of, Canonsburg, PA	6	40-8722	Brush Wellman, Inc., Cleveland, OH	9
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	6	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	9
40-6659	Getty Oil Co Petrotomics Co., Shirley Basin, WY	6	40-8745	Ogle Petroleum, Inc., Casper, WY	9
40-7097	MolyCorp, Inc., White Plains, NY	6	40-8752	Pinal Minerals & Mining, Ltd., Miami, AZ	9
40-7580	Fansteel, Inc., North Chicago, IL	6	40-8763	AluChem, Inc., Reading, OH	10
40-7708	Union Carbide Corp., New York, NY	6	40-8768	Kerr-McGee Nuclear Corp.,	10
40-7869	Plateau Resources, Ltd., Grand Junction, CO	6	40.0702	Oklahoma City, OK	10
40-8027	Kerr-McGee Nuclear Corp.,	7	40-8783 40-8786	Uranium Resources, Inc., Richardson, TX	10 10
	Oklahoma City, OK	7			
40-8035	Cotter Corp., Roswell, NM	7	40-8829	Wyoming Fuel Co., Lakewood, CO	10

Docket	Name	Page	Docket	Name	Page
	sing of Production and Utilization Facilities—		50-220	Nine Mile Point Nuclear Station, Unit 1	30
Docket 50		10	50-225	RPI Critical Experiment	34
50-3	Indian Point Station, Unit 1	10	50-237	Dresden Nuclear Power Station, Unit 2	34
50-10	Dresden Nuclear Power Station, Unit 1	11	50-238	Nuclear Ship Savannah	38
50-20	Massachusetts Institute of Technology Research Reactor	12	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	38
50-29	Yankee-Rowe Nuclear Power Station	12	50-245	Millstone Nuclear Power Station, Unit 1	41
50-54	Union Carbide Research Reactor	14	50-247	Indian Point Station, Unit 2	43
50-57	State Univ. of New York Research Reactor	14	50-249	Dresden Nuclear Power Station, Unit 3	49
50-62	Univ. of Virginia Research Reactor	14	50-250	Turkey Point Plant, Unit 3	52
50-70	General Electric Test Reactor	15	50-251	Turkey Point Plant, Unit 4	54
50-73	General Electric Nuclear Test Reactor	15	50-253	Accelerator Pulsed Fast Assembly	56
50-89	General Atomic Co.	15	50-254	Quad-Cities Station, Unit 1	56
50-97	Cornell Univ. Zero Power Reactor	15	50-255	Palisades Nuclear Plant	59
50-111	North Carolina State Univ. Research Reactor	15	50-259	Browns Ferry Nuclear Power Station, Unit 1	62
50-112	Univ. of Oklahoma Research Reactor	16	50-260	Browns Ferry Nuclear Power Station, Unit 2	65
50-123	Univ. of Missouri Research Reactor	16	50-261	H. B. Robinson Plant, Unit 2	68
50-128	Texas A&M Univ. Research Reactor	16	50-262	Brigham Young Univ. Research Reactor	71
50-129	West Virginia Univ. Research Reactor	16	50-263	Monticello Nuclear Generating Plant	71
50-131	Omaha Veterans Administration Hospital	16	50-264	Dow Chemical Co.	72
FO 100	Research Reactor	16	50-265	Quad-Cities Station, Unit 2	72
50-133	Humboldt Bay Power Plant, Unit 3	16	50-266	Point Beach Nuclear Plant, Unit 1	74
50-142	UCLA Training Reactor	17	50-267	Fort St. Vram Nuclear Generating Station	77
50-146	Saxton Nuclear Experimental Facility	18	50-269	Oconee Nuclear Station, Unit 1	79
50-148	Univ. of Kansas Research Reactor	19	50-270	Oconce Nuclear Station, Unit 2	82
50-155	Big Rock Point Nuclear Plant	19	50-271	Vermont Yankee Nuclear Power Station	84
50-156	Univ. of Wisconsin Research Reactor	22	50-272	Salem Nuclear Generating Station, Unit 1	86
50-157	Cornell Univ. Research Reactor	22	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	90
50-163	General Atomic Co.	23	50-277	Peach Bottom Atomic Power Station, Unit 2	95
50-170	National Naval Medical Center	23	50-278	Peach Bottom Atomic Power Station, Unit 3	97
50-184	National Bureau of Standards Reactor	23	50-280	Surry Power Station, Unit 1	100
50-192	Univ. of Texas Research Reactor	23	50-281	Surry Power Station, Unit 2	102
50-193	Rhode Island & Providence Plantations AEC	23	50-282	Prairie Island Nuclear Station, Unit 1	105
50-201	West Valley Reprocessing Plant	23	50-285	Fort Calhoun Station, Unit 1	107
50-206	San Onofre Nuclear Station, Unit I	24	50-286	Indian Point Station, Unit 3	108
50-213	Haddam Neck Plant	26	50-287	Oconec Nuclear Station, Unit 3	115
50-219	Oyster Creek Nuclear Power Plant	28	55 201	Sumon, Om J	, 10

Do	eket	Name	Page	Docket	Name	Page
	50-289	Three Mile Island Nuclear Station, Unit 1	118	50-339	North Anna Power Station, Unit 2	230
	50-293	Pilgrim Nuclear Power Station, Unit 1	124	5 0-341	Enrico Fermi Atomic Power Plant, Unit 2	233
	50-295	Zion Nuclear Power Station, Unit 1	127	50-344	Trojan Nuclear Plant	236
	50-296	Browns Ferry Nuclear Power Station, Unit 3	129	50-346	Davis-Besse Nuclear Power Station, Unit 1	237
	50-298	Cooper Nuclear Station	132	50-348	Joseph M. Farley Nuclear Plant, Unit 1	241
	50-301	Point Beach Nuclear Plant, Unit 2	134	50-352	Limerick Generating Station, Unit 1	243
	50-302	Crystal River Nuclear Plant, Unit 3	137	50-353	Limerick Generating Station, Unit 2	247
	50-304	Zion Nuclear Power Station, Unit 2	140	50-354	Hope Creek Nuclear Station, Unit 1	250
	50-305	Kewaunee Nuclear Power Plant	143	50-355	Hope Creek Nuclear Station, Unit 2	251
	50-306	Prairie Island Nuclear Station, Unit 2	145	50-358	William H Zimmer Nuclear Station, Unit 1	251
	50-309	Maine Yankee Atomic Power Plant	147	50-361	San Onofre Nuclear Station, Unit 2	256
	50-311	Salem Nuclear Generating Station, Unit 2	150	50-362	San Onofre Nuclear Station, Unit 3	259
	50-312	Rancho Seco Nuclear Generating Station	154	50-364	Joseph M. Farley Nuclear Plant, Unit 2	262
	50-313	Arkansas Nuclear One, Unit 1	157	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	263
	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	161	50-367	Bailly Generating Station	267
	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	165	50-368	Arkansas Nuclear One, Unit 2	267
	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	168	50-369	William B. McGuire Nuclear Station, Unit 1	271
	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	171	50-370	William B McGuire Nuclear Station, Unit 2	274
	50-320	Three Mile Island Nuclear Station, Unit 2	174	50-373	LaSalle County Station, Unit t	278
	50-321	Edwin I. Hatch Nuclear Plant, Unit I	179	50-374	LaSalle County Station, Unit 2	284
	50-322	Shoreham Nuclear Power Station	182	50-382	Waterford Generating Station, Unit 3	288
	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	188	50-387	Susquehanna Steam Electric Station, Unit 1	291
	50-324	Brunswick Steam Electric Plant, Unit 2	190	50-388	Susquehanna Steam Electric Station, Unit 2	294
	50-325	Brunswick Steam Electric Plant, Unit 1	194	50-389	St. Lucie Plant, Unit 2	295
	50-327	Sequoyah Nuclear Plant, Unit 1	197	50-390	Watts Bar Nuclear Plant, Unit 1	299
	50-328	Sequoyah Nuclear Plant, Unit 2	199	50-391	Watts Bar Nuclear Plant, Unit 2	302
	50-329	Midland Plant, Unit 1	202	50-395	Virgil C. Summer Nuclear Station, Unit 1	305
	50-330	Midland Plant, Unit 2	207	50-396	Univ. of Virginia Cavalier Reactor	309
	<i>5</i> 0-331	Duane Arnold Energy Center	212	50-397	WPPSS Nuclear Project, Unit 2	309
	50-332	Barnwell Reprocessing Plant	216	50-400	Shearon Harris Nuclear Power Plant, Unit 1	311
	50-333	James A. Fitzpatrick Nuclear Power Plant	216	50-401	Shearon Harris Nuclear Power Plant, Unit 2	315
	50-334	Beaver Valley Power Station, Unit 1	219	50-402	Shearon Harris Nuclear Power Plant, Unit 3	319
	50-335	St. Lucie Plant, Unit 1	221	50-403	Shearon Harris Nuclear Power Plant, Unit 4	319
	50-336	Millstone Nuclear Power Station, Unit 2	224	50-407	Univ. of Utah Research Reactor	319
	50-338	North Anna Power Station, Unit 1	227	50-409	La Crosse Boiling Water Reactor	320

Docket	Name	Page	Docket	Name	Page
50-410	Nine Mile Point Nuclear Station, Unit 2	321	STN-50-498	South Texas Project, Unit 1	403
50-412	Beaver Valley Power Station, Unit 2	325	STN-50-499	South Texas Project, Unit 2	406
50-413	Catawba Nuclear Station, Unit 1	327	50-500	Davis-Besse Nuclear Power Station, Unit 2	409
50-414	Catawba Nuclear Station, Unit 2	330	50-501	Davis-Besse Nuclear Power Station, Unit 3	409
50-416	Grand Gulf Nuclear Station, Unit 1	333	STN-50-502	Haven Nuclear Plant, Unit 1	409
50-417	Grand Gulf Nuclear Station, Unit 2	337	STN-50-503	Haven Nuclear Plant, Unit 2	409
50-423	Millstone Nuclear Power Station, Unit 3	339	STN-50-508	WPPSS Nuclear Project, Unit 3	409
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	340	50-513	WPPSS Nuclear Project, Unit 4	410
50 -425	Alvın W. Vogtle Nuclear Plant, Unit 2	341	50-514	Pebble Springs Nuclear Plant, Unit 1	410
STN-50-437	Floating Nuclear Plant	342	\$0-515	Pebble Springs Nuclear Plant, Unit 2	411
50-438	Bellefonte Nuclear Plant, Unit 1	342	STN-50-518	Hartsville Nuclear Plant, Unit 1	411
50-439	Bellefonte Nuclear Plant, Unit 2	344	STN-50-519	Hartsville Nuclear Plant, Unit 2	412
50-440	Perry Nuclear Power Plant, Unit 1	347	STN-50-520	Hartsville Nuclear Plant, Unit 3	412
50-441	Perry Nuclear Power Plant, Unit 2	351	STN-50-521	Hartsville Nuclear Plant, Unit 4	412
50-443	Seabrook Nuclear Station, Unit 1	355	50-522	Skagit Nuclear Power Project, Unit 1	412
50-444	Seabrook Nuclear Station, Unit 2	359	50-523	Skagit Nuclear Power Project, Unit 2	413
50-445	Comanche Peak Steam Electric Station, Unit 1	362	STN-50-528	Palo Verde Nuclear Station, Unit 1	414
50-446	Comanche Peak Steam Electric Station, Unit 2	367	STN-50-529	Palo Verde Nuclear Station, Unit 2	417
STN-50-447	GESSAR-238	372	STN-50-530	Palo Verde Nuclear Station, Unit 3	419
STN-50-454	Byron Station, Unit 1	372	50-537	Clinch River Breeder Reactor	· 422
STN-50-455	Byron Station, Unit 2	377	STN-50-546	Marble Hill Nuclear Station, Unit 1	425
STN-50-456	Braidwood Station, Unit 1	380	STN-50-547	Marble Hill Nuclear Station, Unit 2	427
50-457	Braidwood Station, Unit 2	382	STN-50-553	Phipps Bend Nuclear Station, Unit 1	429
50-458	River Bend Station, Unit 1	384	STN-50-554	Phipps Bend Nuclear Station, Unit 2	430
50-459	River Bend Station, Unit 2	387	STN-50-556	Black Fox Station, Unit 1	430
50-460	WPPSS Nuclear Project, Unit 1	389	STN-50-557	Black Fox Station, Unit 2	430
50-461	Clinton Power Station, Unit 1	390	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	431
50-462	Clinton Power Station, Unit 2	392	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	431
50-469	Kuosheng Power Station, Unit 1, Taiwan	393	STN-50-599	Carroll Facility I	431
STN-50-470	CESSAR System 80	393	STN-50-600	Carroll Facility II	431
STN-50-482	Wolf Creek Generating Station	394	Demostle #1	don of Co. of A Northern Mark 111 Product 60	
STN-50-483	Callway Plant, Unit 1	396		sing of Special Nuclear Material — Docket 70	401
TN-50-491	Cherokee Nuclear Station, Unit 1	401	70-0008	Battelle Memorial Institute, Columbus, OH	431
50-496	Montague Nuclear Power Station, Unit 1	401	70-0025	Rockwell International Corp., Canoga Park, CA	432
	intague Nuclear Power Station, Unit 2	402	70-0027	Babcock & Wilcox, Co., Lynchburg, VA	432

Docket	Name	Page	Docket	Name	Page
70-0033	Texas Instruments, Inc., Attleboro, MA	432	70-2982	Rochester, Univ of, Rochester, NY	439
70-0082	Nuclear Metals, Inc., West Concord, MA	432	70-2983	Pennsylvania Power & Light, Allentown, PA	439
70-0124	Teledyne Isotopes, Inc., Westwood, NJ	433			
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	433	Packaging of R of Radioactiv	tadioactive Material for Transport and Transports ve Material Under Certain Conditions — Docket 7	ition 1
70-0371	UNC Naval Products, Inc., Uncasville, CT	433	71-0001	ANEFCO, Inc.	439
70-0378	Army, Dept. of, Adelphi, MD	434	71-0143	Ranchers Exploration & Development Co.	440
70-0466	Maine Maritime Academy, Castine, ME	436	71-0166	New York Testing Labs, Inc.	440
70-0698	Westinghouse Electric Corp , Pittsburgh, PA	436	71-0494	Montana X-Ray, Inc	440
70-0712	Kerr-McGee Nuclear Corp.,	126	71-0495	Southwest X-Ray Corp	440
mo 0704	Oklahoma City, OK	436	71-0496	NUS Corp.	440
70-0734	GA Technologies, Inc., San Diego, CA	436	71-4986	Model: RA-2, RA-3, RA-J, General Electric	440
70-0754	General Electric Co., Pleasanton, CA	436	#4 #00¢	Co	440
70-0820	United Nuclear Corp., Wood River Junction, RI	436	71-5026	Model: CNS 14-190, Chem-Nuclear Systems, Inc.	440
70-0824	Babcock & Wilcox Co., Lynchburg, VA	436	71-5332	Model: 2030-1, Energy, Dept. of	440
70-0846	Texas Nuclear Corp., Austin, TX	436	71-5552	Model: Gas Cylinder Fire Impact Shield,	440
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	436	71-5607	Energy, Dept. of Model: T-2, Energy, Dept. of	440
70-0992	David Witherspoon, Inc., Knoxville, TN	437	71-5814	Model: NRBK-41, -42 & -43, Energy,	
70-1007	General Electric Co., San Jose, CA	437		Dept. of	440
70-1113	General Electric Co., Wilmington, NC	437	71-5874	Model: WAPD-40, Energy, Dept. of	440
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	437	71-5875	Model: WAPD-39 & NRBK-44, Energy, Dept. of	441
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	437	71-5957	Model: BMI-1, Battelle Columbus Laboratory	441
70-1193	Kerr-McGee Nuclear Corp.,	420	71-5979	Model: 5979, Alpha-Omega Services, Inc.	4 41
mp 4804	Oklahoma City, OK	438	71-5980	Model: GE-600, General Electric Co.	441
70-1201	Babcock & Wilcox Co., Lynchburg, VA	438	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	441
70-1224	Teleflex, Inc., North Wales, PA	438	71-6272	Model: 6272, U.S. Ecology	441
70-1257	Exxon Nuclear Co., Inc., Richland, WA	438	71-6294	Model: UNC-2901, Combustion	441
70-1301	Florida Power Corp., St. Petersburg, FL	438	m. 40.14	Engineering Co., Inc.	441
70-1308	General Electric Co., San Jose, CA	438	71-6346	Model: FSV-1, General Atomic Co.	441
70-1359	IRT Corp., San Diego, CA	439	71-6400	Model: 6400, Westinghouse Electric Corp.	441
70-1402	Abington Memorial Hospital, Abington, PA	439	71-6495	Model: PADUCAH Demonstration Cask, Energy, Dept. of	441
70-1621	Duquesne Light Co., Pittsburgh, PA	439	71-6550	Model: 6-GS-1, Energy, Dept. of	44 1
70-2926	Detroit Edison Co., Detroit, MI	439	71-6553	Model: PADUCAH Tiger, Energy, Dept. of	4 41
70-2932	Texas Utilities Generating Co., Dallas, TX	439	71-6601	Model: CNS 8-120, Chem-Nuclear Systems,	
70-2953	Connecticut, Univ. of, Storrs, CT	439		Inc.	441
70-2973	Commonwealth Edison Co., Chicago, IL	439	71-6639	Model: MH-1A, Energy, Dept. of	441

Docket	Name	Page	Docket	Name	Page
71-6708	Model: C-6, Energy, Dept. of	442	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems,	442
71-6717	Model: 6717-B, Gamma Industries	442		Inc	443
71-9010	Model: NLI-1/2, NL Industries, Inc	442	71-9135	Model: Century S & SA, Cen Univ. S & SA, Gamma Industries	443
71-9015	Model: TN-8, -8L, No Users	442	71-9148	Model, 770, Technical Operations, Inc	443
71-9033	Model: 660 & 660E, Technical Operations, Inc.	442	71-9150	Model: PAT-2, Energy, Dept. of	443
71-9044	Model GE-1600, General Electric Co	442	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	443
71-9049	Model: GE-500, General Electric Co.	442	71-9156	Model: IR-50, Industrial Nuclear Co.	443
71-9070	Model N-55, Energy, Dept. of	442	71-9163	Model: GNG-20, Gulf Nuclear, Inc.	443
71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	442	71-9175	Model, CNS6-80B, Nuclear Packaging, Inc	443
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	442	71-9177	Model NUPAC 10/140, Nuclear Packaging, Inc.	444
71-9081	Model. CNSI 1-13C, Chem-Nuclear Systems,		71-9180	Model: 500-SU, Automation Industries, Inc.	444
	Inc.	442	71-9181	Model: PAS-2, Nuclear Packaging, Inc.	444
71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	442	71-9510	Model: GPHS, Energy, Dept. of	444
71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	442	71-9788	Model: S5W Reactor Compartment, Energy, Dept. of	444
71-9103	Model: NLI-6502, No Users	443	71-9901	Model: 120, Energy, Dept. of	444
71-9105	Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	443	Licensing of In	dependent Spent Fuel Storage - Docket 72	
71-9106	Model: BW-20WC-3, Babcock & Wilcox Co.	443	72-0001	Morris Operations, General Electric Co.	444

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 27			Nuclear Dynamics, Inc , Phoenix, AZ	40-8663	8
Richland, WA, US. Ecology, Inc.	27-048	1	Nuclear Metals, Inc , Concord, MA	40-0672	2
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Ogle Petroleum, Inc., Casper, WY	40-8745	9
Domestic Licensing of Source Material — Docket 40			Ogle Petroleum, Inc., Santa Barbara, CA	40-8693	9
Allied Chemical Corp., Morristown, NJ	40-3392	5	Pacific Technical Corp., Santa Barbara, CA	40-8137	7
AluChem, Inc., Reading, OH	40-8763	10	Pathfinder Mines Corp., Riverton, WY	40-2259	5
Atlas Mineral, Inc., Denver, CO	40-3453	5	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	6
Battelle Memorial Institute, Columbus, OH	40-8202	7	Pesses Co., Solon, OH	40-8406	8
Bear Creek Uranium Co., Casper, WY	40-8452	8	Pinal Minerals & Mining, Ltd., Miami, AZ	40-8752	9
Brush Wellman, Inc., Cleveland, OH	40-8722	9	Plateau Resources, Ltd., Grand Junction, CO	40-7869	6
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	9	Plateau Resources, Ltd , Grand Junction, CO	40-8698	9
Cotter Corp., Roswell, NM	40-8035	7	Rio Algom Corp., Moab, UT	40-8084	7
	40-8675	9	Rocky Mountain Energy Co., Broomfield, CO	40-8380	8
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	9	Rocky Mountain Energy Co., Denver, CO	40-8697	9
Energy Fuels Nuclear, Inc., Denver, CO	40-6500		S. F. Applicance, Ltd., Morris, IL	40-0215	1
Energy, Dept. of, Canonsburg, PA		6	Silver King Mines, Inc., Casper, WY	40-8602	8
Exxon Co. USA, Houston, TX	40-8102	7	Spencer Chemical Co., Kansas City, MO	40-1478	5
Exxon Minerals Co. USA, Houston, TX	40-8064	7	Technical Operations, Inc., Burlington, MA	40-3079	5
Fansteel, Inc., North Chicago, IL	40-7580	6	Tennessee Valley Authority, Chattanooga, TN	40-1341	5
Federal-American Partners, Riverton, WY Getty Oil Co. — Petrotomics Co.,	40-4492	6	Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	9
Shirley Basin, WY	40-6659	6	Union Carbide Corp., Grand Junction, CO	40-0299	1
Holmes & Narver, Inc., Anaheim, CA	40-8550	8	Union Carbide Corp., New York, NY	40-7708	6
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	5	Union Carbide Corp., Riverton, WY	40-0229	1
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	7	Uranerz USA Inc., Casper, WY	40-8783	10
Kerr-McGee Nuclear Corp.,			Uranium Resources, Inc., Richardson, TX	40-8786	10
Oklahoma City, OK	40-8768	10	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Minerals Exploration Co., Los Angeles, CA	40-8348	8	Western Nuclear, Inc., Jeffrey City, WY	40-1162	4
Minerals Exploration Co., Los Angeles, CA	40-8584	8	Wyoming Fuel Co., Lakewood, CO	40-8829	10
MolyCorp, Inc., White Plains, NY	40-7097	6	Wyoming Mineral Corp., Lakewood, CO	40-8502	8

lame	Docket	Page	Name	Docket	Page
Domestic Licensing of Production and Utiliza	ition Facilities		Clinton Power Station, Unit 1	50-461	390
Docket 50			Clinton Power Station, Unit 2	50-462	392
Accelerator Pulsed Fast Assembly	50-253	56	Comanche Peak Steam Electric Station, Unit 1	50-445	362
Alvin W. Vogtle Nuclear Plant, Unit I	50-424	340	Comanche Peak Steam Electric Station, Unit 2	50-446	367
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	341	Cooper Nuclear Station	50-298	132
Arkansas Nuclear One, Unit 1	50-313	157	Cornell Univ Research Reactor	50-157	22
Arkansas Nuclear One, Unit 2	50-368	267	Cornell Univ. Zero Power Reactor	50-97	15
Bailly Generating Station	50-367	267	Crystal River Nuclear Plant, Unit 3	50-302	137
Barnwell Reprocessing Plant	50-332	216	Davis-Besse Nuclear Power Station, Unit 1	50-346	237
Beaver Valley Power Station, Unit 1	50-334	219	Davis-Besse Nuclear Power Station, Unit 2	50-500	409
Beaver Valley Power Station, Unit 2	50-412	325	Davis-Besse Nuclear Power Station, Unit 3	50-501	409
Bellefonte Nuclear Plant, Unit 1	50-438	342	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	90
Bellefonte Nuclear Plant, Unit 2	50-439	344	Diable Canyon Nuclear Power Plant, Unit 2	50-323	188
Big Rock Point Nuclear Plant	50-155	19	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	161
Black Fox Station, Unit 1	STN-50-556	430			165
Black Fox Station, Unit 2	STN-50-557	430	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	
Braidwood Station, Unit 1	STN-50-456	380	Dow Chemical Co.	50-264	72
Braidwood Station, Unit 2	STN-50-457	382	Dresden Nuclear Power Station, Unit 1	50-10	11
Brigham Young Univ. Research Reactor	50-262	71	Dresden Nuclear Power Station, Unit 2	50-237	34
Browns Ferry Nuclear Power Station, Unit 1	50-259	62	Dresden Nuclear Power Station, Unit 3	50-249	49
Browns Ferry Nuclear Power Station, Unit 2	50-260	65	Duane Arnold Energy Center	50-331	212
Browns Perry Nuclear Power Station, Unit 3	50-296	129	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	179
Brunswick Steam Electric Plant, Unit 1	50-325	194	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	263
Brunswick Steam Electric Plant, Unit 2	50-324	190	Enrico Fermi Atomic Power Plant, Unit 2	50-341	233
Byron Station, Unit 1	STN-50-454	372	Floating Nuclear Plant	STN-50-437	342
Byron Station, Unit 2	STN-50-455	377	Fort Calhoun Station, Unit 1	50-285	107
Callaway Plant, Unit 1	STN-50-483	396	Fort St. Vrain Nuclear Generating Station	50-267	77
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	168	General Atomic Co.	50-163	23
			General Atomic Co.	50-89	15
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	171	General Electric Nuclear Test Reactor	50-73	15
Carroll Facility I	STN-50-599	431	General Electric Test Reactor	50-70	15
Carroll Facility II	STN-50-600	431	GESSAR-238	STN-50-447	372
Catawba Nuclear Station, Unit 1	50-413	327	Grand Gulf Nuclear Station, Unit 1	50-416	333
Catawba Nuclear Station, Unit 2	50-414	330	Grand Gulf Nuclear Station, Unit 2	50-417	337
CESSAR System 80	STN-50-470	393	H. B. Robinson Plant, Unit 2	50-261	68
Cherokee Nuclear Station, Unit 1	STN-50-491	401	Haddam Neck Plant	50-213	26
'nch River Breeder Reactor	50-537	422	assument Liver A Mills	**	

Name	Docket	Page	Name	Docket	Page
Hartsville Nuclear Plant, Unit 1	STN-50-518	411	National Naval Medical Center	50-170	23
Hartsville Nuclear Plant, Unit 2	STN-50-519	412	Nine Mile Point Nuclear Station, Unit 1	50-220	30
Hartsville Nuclear Plant, Unit 3	STN-50-520	412	Nine Mile Point Nuclear Station, Unit 2	50-410	321
Hartsville Nuclear Plant, Unit 4	STN-50-521	412	North Anna Power Station, Unit 1	50-338	227
Haven Nuclear Plant, Unit 1	STN-50-502	409	North Anna Power Station, Unit 2	50-339	230
Haven Nuclear Plant, Unit 2	STN-50-503	409	North Carolina State Univ Research Reactor	50-111	15
Hope Creek Nuclear Station, Unit 1	50-354	250	Nuclear Ship Savannah	50-238	38
Hope Creek Nuclear Station, Unit 2	50-355	251	Oconee Nuclear Station, Unit 1	50-269	79
Humboldt Bay Power Plant, Unit 3	50-133	16	Oconee Nuclear Station, Unit 2	50-270	82
Indian Point Station, Unit 1	50-3	10	Oconee Nuclear Station, Unit 3	50-287	115
Indian Point Station, Unit 2	50-247	43	Omaha Veterans Administration Hospital Research Reactor	50-131	16
Indian Point Station, Unit 3	50-286	108	Oyster Creek Nuclear Power Plant	50-219	28
James A. Fitzpatrick Nuclear Power Plant	50-333	216	Palisades Nuclear Plant	50-255	59
Joseph M. Farley Nuclear Plant, Unit 1	50-348	241	Palo Verde Nuclear Station, Unit 1	STN-50-528	414
Joseph M. Farley Nuclear Plant, Unit 2	50-364	262	Palo Verde Nuclear Station, Unit 2	STN-50-529	417
Kewaunce Nuclear Power Plant	50-305	143	Palo Verde Nuclear Station, Unit 3	STN-50-530	419
Kuosheng Power Station, Unit 1, Taiwan	50-469	393	Peach Bottom Atomic Power Station, Unit 2	50-277	95
La Crosse Boiling Water Reactor	50-409	320	Peach Bottom Atomic Power Station, Unit 3	50-278	97
LaSalle County Station, Unit 1	50-373	278	Pebble Springs Nuclear Plant, Unit I	50-514	410
LaSalle County Station, Unit 2	50-374	284	Pebble Springs Nuclear Plant, Unit 2	50-514	411
Limerick Generating Station, Unit 1	50-352	243	Perry Nuclear Power Plant, Unit 1	50-440	347
Limerick Generating Station, Unit 2	50-353	247	Perry Nuclear Power Plant, Unit 2	50-441	351
Maine Yankee Atomic Power Plant	50-309	147	Phipps Bend Nuclear Station, Unit 1	STN-50-553	429
Marble Hill Nuclear Station, Unit 1	STN-50-546	425	Phipps Bend Nuclear Station, Unit 2	STN-50-554	430
Marble Hill Nuclear Station, Unit 2	STN-50-547	427	Pilgrim Nuclear Power Station, Unit 1	STN-50-293	124
Massachusetts Institute of Technology Research Reactor	50-20	12	Point Beach Nuclear Plant, Unit 1	50-266	74
Midland Plant, Unit 1	50-329	202	Point Beach Nuclear Plant, Unit 2	50-301	134
Midland Plant, Unit 2	50-330	207	Prairie Island Nuclear Station, Unit 1	50-282	105
Millstone Nuclear Power Station, Unit 1	50-245	41	Prairie Island Nuclear Station, Unit 2	50-306	145
Millstone Nuclear Power Station, Unit 2	50-336	224	Quad-Cities Station, Unit 1	50-254	56
Millstone Nuclear Power Station, Unit 3	50-423	339	Quad-Cities Station, Unit 2	50-265	72
Montague Nuclear Power Station, Unit 1	50-496	401	Rancho Seco Nuclear Generating Station	50-312	154
Montague Nuclear Power Station, Unit 2	50-497	402	Rhode Island & Providence Plantations AEC	50-193	23
Monticello Nuclear Generating Plant	50-263	71	River Bend Station, Unit 1	50-458	384
National Bureau of Standards Reactor	50-184	23	River Bend Station, Unit 2	50-459	387

'ame	Docket	Page	Name	Docket	Page	
obert Emmet Ginna Nuclear Plant, Unit 1	50-244	38	Union Carbide Research Reactor	50-54	14	
PI Critical Experiment	50-225	34	Univ. of Kansas Research Reactor	50-148	19	
alem Nuclear Generating Station, Unit 1	50-272	86	Univ of Missouri Research Reactor	50-123	16	
salem Nuclear Generating Station, Unit 2	50-311	150	Univ. of Oklahoma Research Reactor	50-112	16	
San Onofre Nuclear Station, Unit 1	50-206	24	Univ of Texas Research Reactor	50-192	23	
3an Onofre Nuclear Station, Unit 2	50-361	256	Umv. of Utah Research Reactor	50-407	319	
San Onofre Nuclear Station, Unit 3	50-362	259	Univ. of Virginia Cavalier Reactor	50-396	309	
axton Nuclear Experimental Facility	50-146	18	Univ. of Virginia Research Reactor	50-62	14	
seabrook Nuclear Station, Unit 1	50-443	355	Univ of Wisconsin Research Reactor	50-156	22	
Scabrook Nuclear Station, Unit 2	50-444	359	Vermont Yankee Nuclear Power Station	50-271	84	
Sequoyah Nuclear Plant, Unit 1	50-327	197	Virgil C. Summer Nuclear Station, Unit 1	50-395	305	
Sequoyah Nuclear Plant, Unit 2	50-328	199	Waterford Generating Station, Unit 3	50-382	288	
Shearon Harris Nuclear Power Plant, Unit 1	50-400	311	Watts Bar Nuclear Plant, Unit 1	50-390	299	
Shearon Harris Nuclear Power Plant, Unit 2	50-401	315	Watts Bar Nuclear Plant, Unit 2	50-391	302	
Shearon Harris Nuclear Power Plant, Unit 3	50-402	319	West Valley Reprocessing Plant	50-201	23	
Shearon Harris Nuclear Power Plant, Unit 4	50-403	319	West Virginia Univ Research Reactor	50-129	16	
Shoreham Nuclear Power Station	50-322	182	William B. McGuire Nuclear Station, Unit 1	50-369	271	
Skagit Nuclear Power Project, Unit 1	50-522	412	William B. McGuire Nuclear Station, Unit 2	50-370	274	
Skagit Nuclear Power Project, Unit 2	50-523	413	William H. Zummer Nuclear Station, Unit 1	50-358	251	
South Texas Project, Unit 1	STN-50-498	403	Wolf Creek Generating Station	STN-50-482	394	
South Texas Project, Unit 2	STN-50-499	406	WPPSS Nuclear Project, Unit 1	50-460	389	
St. Lucie Plant, Unit 1	50-335	221	WPPSS Nuclear Project, Unit 2	50-397	309	
St. Lucie Plant, Unit 2	50-389	295	WPPSS Nuclear Project, Unit 3	STN-50-508	409	
State Univ. of New York Research Reactor	50-57	14	WPPSS Nuclear Project, Unit 4	50-513	410	
Surry Power Station, Unit 1	50-280	100	Yankee-Rowe Nuclear Power Station	50-29	12	
Surry Power Station, Unit 2	50-281	102	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	431	
Susquehanna Steam Electric Station, Unit 1	50-387	291	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	431	
Susquehanna Steam Electric Station, Unit 2	50-388	294	Zion Nuclear Power Station, Unit 1	50-295	127	
Texas A&M Univ. Research Reactor	50-128	16	Zion Nuclear Power Station, Unit 2	50-304	140	
Three Mile Island Nuclear Station, Unit I	50-289	118				
Three Mile Island Nuclear Station, Unit 2	50-320	174	Domestic Licensing of Special Nuclear Materia		400	
Trojan Nuclear Plant	50-344	236	Abington Memorial Hospital, Abington, PA	70-1402	439	
Turkey Point Plant, Unit 3	50-250	52	Army, Dept. of, Adelphi, MD	70-0378	434	
Turkey Point Plant, Unit 4	50-251	54	Babcock & Wilcox Co., Lynchburg, VA	70-0027	432	
UCLA Training Reactor	50-142	17	Babcock & Wilcox Co., Lynchburg, VA	70-1201	438	
			Babcock & Wilcox Co., Lynchburg, VA	70-0824	436	

Name	Docket	Page	Name	Docket	Page
Battelle Memorial Institute, Columbus, OH	70-0008	431	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
Commonwealth Edison Co., Chicago, IL	70-2973	439	ANEFCO, Inc	71-0001	439
Connecticut, Univ of, Storrs, CT	70-2953	439	Model 120, Energy, Dept of	71-9901	444
David Witherspoon, Inc., Knoxville, TN	70-0992	437	Model 2030-1, Energy, Dept of	71-5332	440
Detroit Edison Co., Detroit, MI	70-2926	439	Model. 500-SU, Automation Industries, Inc	71-9180	444
Duquesne Light Co., Pittsburgh, PA	70-1621	439	Model: 5979, Alpha-Omega Services, Inc	71-5180	441
Exxon Nuclear Co, Inc, Richland, WA	70-1257	438	Model 6-GS-1, Energy, Dept. of	71-6550	441
Florida Power Corp., St. Petersburg, FL	70-1301	438	Model: 6244, Chem-Nuclear Systems, Inc	71-6244	441
GA Technologies, Inc., San Diego, CA	70-0734	436	Model 6272, U.S. Ecology	71-6272	441
General Electric Co., Pleasanton, CA	70-0754	436	5.	71-6400	
General Electric Co., San Jose, CA	70-1007	437	Model 6400, Westinghouse Electric Corp.	71-9033	441 442
General Electric Co., San Jose, CA	70-1308	438	Model: 660 & 660E, Technical Operations, Inc.		
General Electric Co., Wilmington, NC	70-1113	437	Model: 6717-B, Gamma Industries	71-6717	442
IRT Corp., San Diego, CA	70-1359	439	Model: 770, Technical Operations, Inc	71-9148	443
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0925	436	Model: 9080, Hittman Nuclear & Development Corp.	71-9080	442
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	438	Model: BMI-1, Battelle Columbus Laboratory Model: BW-20WC-3, Babcock & Wilcox Co.	71-5957 71-9106	441 443
Kerr-McGee Nuclear Corp., Okłahoma City, OK	70-0712	436	Model: C-6, Energy, Dept. of	71-6708	442
Maine Maritime Academy, Castine, ME	70-0466	436	Model Century S & SA, Cen. Univ. S & SA, Gamma Industries	71-9135	443
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	433	Model: CNS 14-190, Chem-Nuclear Systems,		
Nuclear Metals, Inc., West Concord, MA	70-0082	432	Inc.	71-5026	440
Pennsylvania Power & Light, Allentown, PA	70-2983	439	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	442
Rochester, Univ. of, Rochester, NY	70-2982	439	Model: CNS 6-80-2, Chem-Nuclear Systems,	g. 0.44	1.40
Rockwell International Corp., Canoga Park, CA	70-0025	432	Inc.	71-9111	443
Teledyne Isotopes, Inc., Westwood, NJ	70-0124	433	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	441
Teleflex, Inc., North Wales, PA	70-1224	438	Model: CNS6-80B, Nuclear Packaging, Inc.	71-9175	443
Texas Instruments, Inc., Attleboro, MA	70-0033	432	Model: CNSI 1-13C, Chem-Nuclear Systems,	m. 0041	
Texas Nuclear Corp., Austin, TX	70-0846	436	Inc.	71-9081	442
Texas Utilities Generating Co., Dallas, TX	70-2932	439	Model: FSV-1, General Atomic Co.	71-6346	441
UNC Naval Products, Inc., Uncasville, CT	70-0371	433	Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	71-5552	440
United Nuclear Corp., Wood River Junction, RI	70-0820	436	Model: GE-1600, General Electric Co.	71-9044	442
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	436	Model: GE-500, General Electric Co.	71-9049	442
Westinghouse Electric Corp., Pittsburgh, PA	70-1151	437	Model: GE-600, General Electric Co.	71-5980	441
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	437	Model: GNG-20, Gulf Nuclear, Inc.	71-9163	443

ame	Docket	Page	Name	Docket	Page
odel: GPHS, Energy, Dept. of	71-9510	444	Model. RA-2, RA-3, RA-J, General Electric Co.	71-4986	440
odel: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	442	Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	71-9105	443
odel: HN-100, Series 3, Hittman Nuclear & Development Corp	71-9151	443	Model: S5W Reactor Compartment, Energy, Dept. of	71-9788	444
odel: IR-50, Industrial Nuclear Co.	71-9156	443	Model: T-2, Energy, Dept. of	71-5607	440
odel: KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	442	Model: TN-8, -8L, No Users	71-9015	442
odel. MH-1A, Energy, Dept. of	71-6639	441	Model: UNC-2901, Combustion Engineering Co., Inc.	71-6294	441
lodel: N-55, Energy, Dept. of	71-9070	442			
odel: NLI-1/2, NL Industries, Inc.	71-9010	442	Model: WAPD-39 & NRBK-44, Energy, Dept. of	71-5875	441
fodel: NLI-6502, No Users	71-9103	443	Model: WAPD-40, Energy, Dept. of	71-5874	440
Iodel: NRBK-41, -42, & -43, Energy, Dept. of	71-5814	440	MONTANA X-Ray, Inc.	71-0494	440
fodel: NUPAC, 10/140, Nuclear Packaging, Inc.	71-9177	444	New York Testing Labs, Inc.	71-0166	440
Indels BADISCALL Description Cont.			NUS Corp.	71-0496	440
Iodel: PADUCAH Demonstration Cask, Energy, Dept. of	71-6495	441	Ranchers Exploration & Dev. Co.	71-0143	440
fodel: PADUCAH Tiger, Energy, Dept of	71-6553	441	Southwest X-Ray Corp.	71-0495	440
fodel: PAS-2, Nuclear Packaging, Inc.	71-9181	444	Licensing of Independent Spent Fire Standard	Dealest 72	
fodel: PAT-2, Energy, Dept. of	71-9150	443	Licensing of Independent Spent Fuel Storage — I Morris Operations, General Electric Co.	72-0001	444

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 BHEFFIELD, IL, U 8 ECOLOGY, INC

8305:10:80 Trip rept of 82:20:1-02 site visit to Sheffield, IL re site surface vegetation & drainage features SHAFFER, J. A. Low Level Waste Licensing Branch 83/01/25, SCARANO:R A. Low Level Waste Licensing Branch, 3pp. 18434-257

8305030517 Joint motion to continue proceedings until 830718 to provide add1 time for settlement negotiations Continued progress has been made, Certificate of Svc encl.
LESSY, R.P. Hearing Branch 3. WETTERHAMM, J. US Ecology, Inc. (formerly Nuclear Engineering), B3/04/29. Atomic Safety and Licensing Board Panel 4pp. 18294 176.

DOCKET 27-048 RICHLAND, HA, U.S. ECOLOGY, INC.

B305110155 Forwards monthly SNM receipt & burial rept for Mar 1983 & rept of isotopic activity, W/o encle, HIPSHER, M, M. US Ecology, Inc. (formerly Nuclear Engineering) 83/04/14. HAWKINS, E. Low Level Haste Licensing Branch. 2pp. 18434: 103.

8308110134 Application for mode to License 16-19204-01 facilitating specific radwaste receipt & disposal requirements of 10CFR61 "Licensing Requirements for Land Disposal of Radwaste "HIPSHER! M. M. US Ecology, Inc. (formerly Nuclear Engineering). 83/04/21. HAHKINS, E. Low Level Waste Licensing Branch. 3pp. 18421;359.

8305100379 Forwards IE Insp Repte 50-237/83-08 & 50-249/83-07 on 830222-25,0301.09 & 14 & notice of violation, HIND, J. Ä. Division of Radiological & Materials Safety Programs 83/04/22, REED, C. Commonwealth Edison Co. 2pp 18377-328, 24X Fiche: 50-237,83/04/22,8305100379.

---B305100416 IE Waste Packaging Insp Rept 15000046/B3-03 on B30216 Noncompliance noted: dose rate of 3 mrem/h existed in truck ceb.
THOMAS.R.D., B00K:H.E. Region 5: Office of Director. ELBEN:H.J. Washington: State of. B3/02/28. 4pp. 18377:344 24X Fiche:50-237,88/04/28.8305100379.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0084 N.R. GRACE & CO., POMPTON PLAINS, NJ

8305180325 Discusses items of interest, including natl response team, FEB for Kerr-McGee Rere Earth facility & radioactive property in Hayne, NJ.
PAGE. R. G. Uranium Fuel Licensing Branch, 83/05/05 DAVIS, J. G.
Office of Nuclear Material Safety & Safeguards, Director, 2pp. 18503-357.

DOCKET 40-0215 8. F. APPLICANCE: LTD. / HORRIS: IL

8303120465 Ack receipt of 830228 & 0310 ltrs informing NRC of steps taken to correct violations noted in IE insp of License STB-258.
WIEDEMAN D. G. Region 3, Office of Director. 83/04/29. JOHNSON, S. J. S. F. Appliance, Ltd. 1p. 18431:041.

--8305120476 Responds to NRC request for info re add1 user of License STB-258 Selection & training of individual should be completed within 1-3 months JONESON B J 8 F Appliance, Ltd 83/03/10, WIEDEMAN, D Region 3, Office of Director 1p. 18431.046

DOCKET 40-0229 UNION CARRIDE CORP : RIVERTON, WY

B305260388 Forwards revised Figure 1 2, "Grading of Reclaimed Surface," w/cross-section locations indicated Rev should replace Figure 1 2 in PJ Lyons B30328 1tr LUTKIN.M H Hater, Haste & Land, Inc. B3/04/08 PETTENDILL, H Uranium Recovery Licensing Branch 3pp 18647, 209

DOCKET 40-0299 UNION CARBIDE CORP. , GRAND JUNCTION, CO

8305120501 Comments on Union Carbide rept re requirements of 10CFR40.65 & Licenes Conditions 45.48.56 & 75. Third Guarter 1982 groundwater data not previously submitted was included w/submittel HOCLBEY/R.T. PETTENDILL, H J. Uranium Recovery Field Office, 83/04/01 Uranium Recovery Field Office 5pp. 18443 158

8305260386 Advises that licenses will temporarily curtail milling of mine ore through U mill at Gas Hills. HY as of 830601. Heap leach facility will continus to operate LYONS.P.J. Union Carbide Corp. 83/04/02 PETTENGILL. H Uranium Recovery Licensing Branch ip. 18647:212

8305170383 Comments on 830207 itr & encis re projected costs for tailings reclamation. Tailings pond reclamation cost analysis & pond summery consistent w/approved plan WOOLSEY, R T. Uranium Recovery Field Office WOOLSEY, R T Licensing Branch 2, 83/04/10 Uranium Recovery Field Office 2pp 18476*111.

8305140275 Summary of 830414 mesting w/Union Carbide Corp & NRC in Casper MY re proposed expansion of A-9 teilings disposal site. KEARNEY, B Wyoming, State of, 83/04/18 Wyoming, State of, ip. 18479:041

B305030499 Forwards fuel cycle & matis LER summary for Mar 1983 BROWN, O D. Division of Vendor & Technical Progress B3/04/27, DAVIS.J O. Office of Nuclear Material Bafety & Safeguards, Director, MICHELBON.C Director's Office 3pp. 18306:194.

8305170599 Reviews 40CFR190 compliance for Third Quarter 1982 for Gas Hills Mill Compliance acceptable, however, ability to perform pacessary calculations not demonstrated. 8CLLENBERGER, D., MARTIN, D.E. Low Level Haste Licensing Branch. 83/04/28, Low Level Waste Licensing Branch 4pp 18497:048

B3052603B9 Forwards State of WY.Dept of Environ Quality memo raising concerns on Union Carbide Corp proposed tailings embankments. State will defer further action until Pettengill can study review to determine if addl info needed. FREUDENTHAL.N. Wyoming, State of B3/04/ZB, SHITH.R.D. Uranium Recovery Field Defice 2pp. 18647-207.

8305260395 Forwards rept on 830413 spill of heap leach liquor from East Oss Hills Mill, Spill contained in restricted area w/no risk of spill reaching surface waterway LYONS, P. J. Union Carbide Corp. 83/04/28. BROWN, G. Region 4, Office of Director. 3pp. 18647:186

--8305260379 Forwards rept of B30414 spill of teilings liquor from East Gas Hills Hill, Spill contained within restricted area w/no risk of reaching surface waterway.
LYONER, J. Union Carbide Corp. B3/04/27. BROWN, Q. Region 4, Office of Director App. 18647:189.

- 8305260363 Advises that State of MY, Dept of Environ Quality, Water Quality Div has no objections to proposed increase in capacity of A-9 pit tailings area Proposal appears environmentally acceptable Comments listed OARLAND, W. L. Myoming, State of 83/05/04 PETTENGILL, H. NRC No Detailed Affiliation Given. Ip. 18647-289
- 8305260368 Lists State of HY, Dept of Environ Quelity, Water Quality Div concerns re application to install pumpback well to reverse groundwater gradient below A-9 tailings pond Guarterly repts for groundwater monitoring should be submitted GARLAND, H L Wyoning, Blate of 83/05/11 PETTENGILL, H NRC No Detailed Affiliation Qiven 1p 88447 289
- 8305250397 Submits review of 40CFR190 compliance for Fourth Guarter 1782 for Oas Hills Mill Revised data & dose calculations submitted 830427 acceptable SOLLENBEROER, D., MARTIN, D.E. Urenium Recovery Licensing Branch 83/05/13 HIGOINBOTHAM, L. Low Level Waste Licensing Branch 4pp 18594 323
- DOCKET 40-0672 NUCLEAR METALS, INC , CONCORD, MA
- 83051R0224 Addl response to FOIA request for license applications.
 license & insp repts re Nuclear Metals, Inc & correspondence on amployee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/03/01 MODNEY, B C Lowell Sun, Lowell, MA. 9pp 18460 050
- --9112160259 Forwards urinalysis history form for review by Occupational Health Stds Branch Info requested as result of recent insp at Nuclear Metal in Concord. MA where employees urine showed concentration of U in excess of licenses guide KINNEMAN. J D Materials Radiological Protection Section. 81/12/07. GRELLA.A W. Fuel Cycle & Materials Safety Section 4pp 18462 186.
- --8305120234 Insp Findings & Licensee Ack of d 620424 of License SMB-179.
 Insp findings no noncompliance noted,
 KLEVIN.P B Atomic Energy Commission 62/04/24 2pp 18460 060
- --8305120240 Insp Findings & Licensee Ack dtd 651207 & 08 of License 8MB-179 Insp Findings no noncompliance noted * Atomic Energy Commission 65/12/08 ip, 18460.062
- --8303120246 Notifies that Nuclear Metals Div of Textron. Inc acquired by Hhittaker Corp Approval for transfer of licenses requested THOMPSGN.P. Nuclear Metals. Inc 66/08/11 Atomic Energy Commission ip 18460-063
- --8305120251 IE Insp Findings & Licensee Ack dtd 671227 & 28 of License BH8-177 Insp findings, no noncomptiance noted GRELLA, A.W., BROWNE, H. Q. Atomic Energy Commission 67/12/28 ip. 18460-064
- --B303120257 Forwards IE Insp Findings & Licensee Ack dtd 671227 & 28 No noncompliance noted, M/o encl. KIRKMAN,R. M. Atomic Energy Commission 68/01/03 ABREAU,M A Whittaker Corp. 1p. 18460-065
- --B305120260 IE Insp Findings & Licensee Ack dtd 691202-03 of License SMB-177 Insp findings no noncompliance noted SMITH,R H Atomic Energy Commission. 69/12/03 ip. 18460 066
- -8305120264 Advises that response to 690822 application for License SHR-179 has not been received info re issuance of license requested LEE, M R. Whittaker Corp 69/10/22 NUSBBAUMER, D. A Atomic Energy Commission. Ip 18460:067
- -8305120248 Bubmits list of reglecement pages to application for License SNM-65.in response to 690923 comments.
 ISBEROW. B. Whittaker Corp. 69/10/22. NUSSBAUMER. D A. Atomic Energy Commission. 2pp 18460 068
- -8305120274 IE Insp Findings & Licensee Ack dtd 690903 & 04 of Licenses SNM-65 & SMB-179 Insp findings proper evaluations not made of certain aspects of health physics grogram per Sections II b 4 through II.h.6(b) of License Condition B. BROHNE, H 9. Atomic Energy Commission 69/09/18 Ip. 18460:071.
- 8305120279 Application for renewal of License SMB-179.authorizing possession & use of U-235 solid metal & alloy for fabrication & experimentation OUHHESON, P. U. Whittaker Corp. 69/08/22. 3pp. 18460-072

- --8303120283 Notifies that License BMB-179 expires on 690930 Renewal application should be filed within 30 days Encl certification of status of source matl activities form should be completed for nonrenewal of license NUSSBAUMER.D A Atomic Energy Commission 69/07/25 HANNA.H J Whittater Corp ip 18460 075
- --B305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & BNB-179 Insp findings.no noncompliance noted SMITH,R H Atomic Energy Commission 70/07/16, 1p 18460 076
- --8305120289 Notifies that no items of noncompliance observed during insp of Licenses SNH-65 & BMB-179 Corrective measures implemented re item of noncompliance during 670903 & 04 insp B Isserow replaced DB Knappel as criticality officer SMITH.R H. Atomic Energy Commission 70/01/06 Atomic Energy Commission. 1p. 18460:077,
- ---B305120294 IE Insp Findings & Licenses Ack dtd 710513 & 14 of Licenses BNM-65 & BNB-179. Insp findings no noncompliance noted. Related info encl BNITH-R H. Atomic Energy Commission, 71/05/14, 22pp. 18460.078
- --8305120278 Discusses 740913 smoke & paper emission from 5-gallon pail of U Fire dept removed pail Smoke & vapor emission ceased. No personnel contamination resulted or radiation released Caused by reaction between metal & oil GILMAN. A.R. Nuclear Metals, Inc. 74/09/13. Region 1, Philadelphia, Office of the Director, 3pp 18460-125
- --8305120303 Discusses insp of License 8M9-179 radiation control program.
 License classification should be changed from E-3 to B-1
 Next insp scheduled during Nov 1974.
 JERMAN,P C. Atomic Energy Commission, Directorate of Regulatory
 Operations 74/08/22 Atomic Energy Commission, Directorate of
 Regulatory Operations ip 18440-128
- --8305120307 Forwards Insp Rept 40-0672/74-01 on 740530 & 31.No noncompliance nated. NELBON.P.R Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22 TUFFIN, H B Nuclear Metals, Inc. 2pp. 1840-129.
- --8305120310 Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance noted Major areas inspected radiation control program. JERMAN.P.C., KNAPP.P J Region 1. Philadelphia, Office of the Director. 74/08/20 Ppp 18460.131.
- ---B905120316 Ack receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr 0/REILLY.J.P. Region i, Philadelphia, Office of the Director, 74/04/26. TUFFIN.H B. Nuclear Metals, Inc. ip. 18460 140
- --8305120352 Supple 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler, in response to 740404 telcon Related info encl. TUFFIN.W.B. Ruclear Hetals, Inc. 74/04/16, 0/REILLY.J.P. Region i, Philadelphia, Office of the Director Spp. 18460-141.
- --8305120356 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-28 & 740108-09 & notice of violation. We insp repts. O'REILLY, J. P. Region 1, Philadelphia, Office of the Director 74/02/15. TUFFIN, M. B. Nuclear Metals: Inc. 2pp 18460:146
- --8305120359 Notice of violation from insp of 731227-28 & 740108-09. Noncompliances noted: failure to conduct adequate evaluations of hand exposures to survey for airborne U-238 & to analyze environ water & soil samples * Region 1, Philadelphia, Office of the Director. 74/02/15 3pp. 18460-148
- --8305120369 Reaponds to NRC 740215 ltr ra violations noted in Insp Repts 70-0082/73-03 & 40-0672/73-02 Corrective actions finger desimeters placed on individual employees monthly on rotating basis. U handling employees surveyed, TUFFIN, H Nuclear Hetals, Inc. 74/03/27, O'REILLY, J. P. Region 1, Philadelphia, Office of the Director 11pp 18460:153.
- --8305120372 Insp Repts 40-0672/73-02 & 70-0082/73-03 on 721227-28 & 740108-09. Noncompliance noted:failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products.

 JERNAN, P. C., KNAPP, P. J. Region 1, Philadelphia, Office of the Director, 74/02/01. 20pp. 18460.164.
- ---8305120376 Confirms 740104 & 07 telcons relactions taken to correct violations noted in insp on 731227 & 28. Representatives will visit plant on 740107 to evaluate corrective actions. O'REILLY, U.P. Region 1. Philadelphia. Office of the Director. 74/01/07. TUFFIN, W. B. Nuclear Metels. Inc. 3pp. 18460:184.

- --8305120450 Forwards Insp Rept 40-0672/75-01 on 750527 & 30 No noncompliance noted Major areas inspected selective exam of procedures & representative records, interviews w/personnel, measurements made by inspector & observations W/o encl NELSON-P R Region 1, Philadelphia, Office of the Director 75/06/25 TUFFIN, W 8 Nuclear Metals, Inc 2pp 18460 191
- --8303120454 "Nuclear Reactor Fuel Svcs Semiannual Insp II Plan & Field Notes " EPBTEIN.E , MGCLINTOCK,R Office of Inspection & Enforcement, Office of the Director 75/06/23 16pp 18460 195
- --8305120462 IE Insp Rept 40-0672/75-01 on 750529-30 No noncompliance noted Major areas inspected mgt interview re scope of program & operations, external & internal exposures, stack air monitoring, liquid waste & controls EPSTEIN, E. MCCLINTOCK, R.O. Region i, Philadelphia, Office of the Director 75/06/23 4pp 18460 2ti
- --8305120478 Ack receipt of 770510 ltr re violations noted in 1E Insp Rept 40-0672/77-01 Records of evaluations denoting true exposure of individual exposed to contamination should be maintained for review during next insp NELSON:P R Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 77/05/31 TUFFIN.W B Nuclear Hetals, Inc 1p 18460 251
- --8305120480 Responds to NRC 770418 ltr re violations noted in IE Insp. Rapt 40-0672/77-01 Corrective actions employee will present badge to guard at exit Badge sealed within cleanable mylar envelope.

 TUPFIN.M. B. Nuclear Hatals, Inc. 77/05/10 NELBON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 3pp 18460 252
- --8305120483 Discusses IE Insp Rept 40-0672/77-01 on 770327 & forwards notice of Violation NELBON, PR Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/04/18 TUFFIN, WB Nuclear Metals, Inc 2pp 18460 255
- --8305120489 Notice of violation from insp on 770329 Noncompliance noted failura to perform surveys to assure compliance w/ 100FR20 101 & 100FR20 403 re radiation exposure to personnel monitoring (film) badge for Third Quarter 1976 * Region 1, Philadelphia, Office of the Director 77/04/18 1p 18460 257.
- --8305120473 Ack receipt of 780919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-02 GROCKER,H W Region i, Philadelphia, Fuel Facility & Materials 8afety Brench. 78/09/27 TUFFIN.W B Nuclear Metals. Inc 1p 18460 258
- --8305120494 Responds to NRC 780821 ltr re violations noted in IE Insp Rept 40-0672/78-02, Corrective actions, radiation levels along outside rear wall of Butler Bldg 1 reduced to 1 m/h Fencing placed between ends of bldgs TUFFIN, W B Nuclear Metals, Inc. 78/09/19 Region 1, Philadelphia, Office of the Director 1p, 18460, 259
- --B305120500 Forwards notice of violation from insp on 780727-28 Results of smear samples within license guidelines CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Sefety Brench 78/08/21 TUFFIN.W B Nuclear Metals, Inc. 3pp. 18460 260
- --B305120503 Notice of violation from insp on 780727-29. Two individuals working in restricted area received exposures to skin of 8,54 & 8.19 reme, respectively, during First Quarter CY78. Draft Insp Rept 78-02 encl
 # Region 1, Philadelphia, Office of the Director 78/08/21, 2pp 18460:263
- ~-8305120507 IE Insp Rept 40-0672/78-02 on 780727-28 Noncompliance noted two workers received skin dose in excess of 7.5 rems during first Quarter 1978 & levels outside Butler Bidg exceeded 2 m/h at 2 ft. QLENN.J E., MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 78/08/14, 10pp 18460 265

- --B305120507 Ack receipt of 780418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-01 Request to amend license must accompany changes to procedures noted in 780418 ltr NELSON.P R Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 78/05/11 TUFFIN.W 8 Nuclear Metals. Inc 2pp 18460 275
- --8305120511 Responds to NRC 780324 ltr re violations noted in IE insp on 780228-0301 Corrective actions personnel instructed to collect floor sweeping in containers color coded to identify scrap containing licensed matl TUFFIN.W B Nuclear Netals, Inc 78/04/18 Region i, Philadelphia. Office of the Director 2pp 18460 277
- --B305120514 Forwards notice of violation from insp on 780228 & 0301 Methods for detecting radioactive contamination should be reviewed Comments on smoking in restricted area requested NELBON.P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 78/03/24 TUFFIN.W B Nuclear Metals, Inc. 3pp 18460 279
- --8305120515 Notice of violation from insp on 780228 & 0301 Noncompliance noted failure to perform surveys re disposal of licensed matl in waste & radiation exposure to extremities * Region 1, Philadelphia, Office of the Director 78/03/24 ip 18460 282
- --8305120518 IE Insp Rept 40-0672/78-01 on 780228 & 0301 Noncompliance noted failure to evaluate exposure to extremity & to wear ring dosimeter in restricted area Radwaste found in trash dumpster
 OLENN, J. MCCLINTOCK, R. Region 1, Philadelphia, Office of the Director 78/03/13 Spp 18460 283
- --8303120519 Forwards proposed ack ltr to Nuclear Metals 801003 response to notice of violation & 800929 notice of proposed imposition of civil penalty QRIER. B H Region 1, Philadelphia, Office of the Director 80/11/19 THOMPSON. D Executive Officer for Operations Support 2pp 18461 026
- --8305i20523 Forwards draft enforcement action it & notice of violation & proposed imposition of civil penalty re failure to meet NRC & DDT requirements for shipment of radwasts to Barnwell burial site GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/26 THUMPSON, D Executive Officer for Operations Support 5pp 18461 107
- --8305120527 Amend 2 to License 8MB-179, revising Items 6 & 7 re source matl & max possession & use, per 751003 telegram DRAGONETTE.K 8 Division of Fuel Cycle & Material Bafety 73/10/08 ip 18461 185
- ---8305i20530 Confirms discussions re possible overexposure of employee to airborne concentration of depleted U JB Hursh & KM Strable engaged as consultants for NRC Assistance requested KINNEMANJ D Region 1, Philadelphia, Office of the Director B1/01/15 TUFFIN,W B Nuclear Metals, Inc. 3pp. 18461 199
- ---8305120540 Discusses IE Insp Rept 40-0472/80-04 on 801120 Proposed transmittal ltr & notice of violation & proposed imposition of civil penalties encl QRIER.B H Region i, Philadelphia, Office of the Director 81/02/03. THOMPSUN,D Office of Inspection & Enforcement, Office of the Director 10pp 18461 202
- --8305120602 Discusses IE insp on 801120 & forwards notice of violation & proposed imposition of civil penalty BTELLO.V. Director's Office, Office of Inspection and Enforcement 81/02/24 TUFFIN,W B Nuclear Netals, Inc 2pp 18461 227
- ~-8303120409 Notice of violation & proposed imposition of civil penalty in amount of \$5,000 Noncompliance noted low specific activity radioactive meth found leaking from Drum 58 STELLO, V Director's Office, Office of Inspection and Enforcement 81/02/26 2pp 18461 231
- --8305120620 Ack receipt of 810316 ltr & payment of civil penalty proposed in 810226 ltr THOMPSON D Director's Office (Pre 820201) 81/03/27 TUFFIN.W B Nuclear Metals, Inc ip 18461 258
- --8305120623 Discusses licensee 810312 fire Approx 10 lb U chips in drum in waste handling erea ignited by spontaneous combustion. Fire spread to flammable matl Wipes in area revealed gross beta contamination.

 COSTELLO.F M NRC No Detailed Affiliation Given B1/Q4/O3 KINNEMAN.J D NRC No Detailed Affiliation Given 2pp 18861 259

- --8305120627 Discusses 810312 fire caused by auto-ignition of 10 lb of encapsulated U turnings OILMAN, A R Nuclear Metals, Inc. 81/04/10 COSTELLO, F Region 1, Philadelphia, Office of the Director (81/03/01) 3pp 19845 261
- --8305120630 Forwards IE insp Rept 40-0672/Bi-Oi on 810219 No noncompliance noted Major areas inspected selective etams of procedures & representative records interviews w/personnel, measurements & observations by inspector. W/o encl KINNEMAN. J D Region I. Philadelphia, Office of the Director (81/03/01) Bi/O4/16 TUFFIN.W B Nuclear Metals, Inc 2p 1844 264
- --8305120633 Responds to 810724 application to amend source matl License Add1 info re incineration of U chips & turnings requested MANO.J C Division of Fuel Cycle & Material Bafety 81/09/29 GILMAN.A R Nuclear Metals, Inc 1p 18461 297
- --9305120642 Requests addl info re 810527 application to amend License BMB-179, proposing dilution factor of 143 be applied to air seffluent releases from ventilation stacks per 10CFR20 106(d) MANO, J C Division of Fuel Cycle & Material Safety 81/11/12 OILMAN, A R Nuclear Metals, Inc. 2pp 18461-326
- --8305130006 Ack receipt of application for renewal of License SMB-179 License will not expire until final action taken by NRC HICKEY, J. W. Division of Fuel Cycle & Material Safety 81/12/28 OLLMAN, A. R. Nuclear Metals, Inc. ip 18462 109
- --B305130011 Confirms B20216 conversation w/C Rowe re possible querterly skin overexposure to smployee Detailes rept forthcoming Info deleted VUMBACO,F. J. Nuclear Metals: Inc. 82/02/16 XINNEMAN, J. D. Ragion I. Office of Director ip. 18462 110
- --8305130016 Confirms talcon re-application for renewal of License SMB-179 Site visit scheduled for B20304 HICKEY, J.W. Division of Fuel Cycle & Material Safety 82/02/18 GILMAN, A.R. Nuclear Metals, Inc. 1p. 18462 111
- --8305130031 Discusses 820126 telcon re small crack in dite during discharge of U neutralized acid waste to lagoon.Possibly caused by freeze-thaw cycle Dike reinforced KINNEMAN.J D Region 1. Office of Director 82/03/24 Region 1. Office of Director ip 18462.130
- --8305130037 Comments on application for renewal of License 988-179
 Application should provide more specific procedures for
 frisking personnel & clothing at exits from controlled area
 KINNEMAN, J D Region 1. Office of Director 82/04/01
 HILLER, V L Office of Nuclear Haterial Bafety &
 Safeguards, Director 2pp 18462, 131
- --8305130042 Forwards Rev 2 to "NMI Scrap Packaging Procedures," for disposal of depleted U wastes in support of Dec 1981 license remewal submittal VUMBACO,F J Nuclear Metals, Inc 82/05/10 HICKEY,J Division of Fuel Cycle & Material Safety 1p. 18462 154
- --B305130053 Forwards 820513 request for addl info re licenses application for renewal application.
 HICKEY, 14 Division of Fuel Cycle & Meterial Bafety 82/05/13 KINNEMAN, J.D. Region 1. Office of Director 2pp 18462 174
- --8305130062 Act receipt of Billi6 application for renewal of License BMB-179, Addl info re temporary job sites at which source ratis will be possessed or used radiation survey progrem & waste dispusal requested. H/o stebed encl. WANO. J C. Division of Fuel Cycle & Material Bafety 82/05/13 OILMAN. A. R. Nuclear Metals, Inc. 4pp 18462: 176
- 8305060135 Addl response to FOIA request for info re Nuclear Metals, inc. including incidents of employee overexposures. Forwards App A documents info partially withheld names of overexposed individuals (ref FOIA Exemption 6) PELTON.J M Division of Rules and Records, 83/03/03 MOONEY, B C Lowell Sun, Lowell, MA 3pp 18353.145
- --B201070110 Confirms Bi1215 telcon agreement re consulting swis for probable U overexposure incident described in encl Work involves anelysis of health significance of uptake & most littely initial update of depleted U, Guidance & forms encl HAYNES,R C Region i, Philadelphia, Office of the Director (B1/03/01), B1/12/30 HURBH, J B Hursh, J B 12pp 18353 190.
- --8208080842 Forwards rept on last quarter 1981 skin dose to Nuclear Metals, Inc employee ALLARD, D. J. Nuclear Matals, Inc. 82/03/01 KINNEMAN, J. D. Division of Engineering & Technical Programs. 1p 18353'223

- ---8208060244 Rept on last quarter 1981 skin dose to Nuclear Metale, Inc employee ALLARD, D. J. Nuclear Metals, Inc. 82/03/01 15pp 18353 224
- --@305060141 Bubmits final rept re 740913 smoke & vapor emission at 5 gallon can of depleted U Analysis of conteiner & surrounding area revealed no spread of contamination Control procedures improved Info partially deleted GILMAN.A R Nuclear Metals, Inc. 74/10/24. ALLEN.W Region 1, Philadelphia. Office of the Director 5pp. 18353 169
- --8305060156 Ack receipt of 780630 transmittal of final overexposure rept.per 10CFR20, 405(a)
 MCCLINTOCK, R O Region i, Philedelphia, Fuel Fecility & Materials Sefety Brench 78/07/19 GILMAN, A R. Nuclear Metals, Inc. 2pp
- --8303060181 Bubmits rept re employee whole body overskposure to beta plus gamma radiation,per iOCFR20 405(a)(1) Film badge resvaluation & overskposure of U confirmed 780530.
 Reassignment of personnel & early alert procedure initiated.
 GIMANIA R Nuclear Metals, Inc. 78706/30 Region i, Philedelphis. Office of the Director Spp. 18353 180
- --8305060189 Forwards JE Olenn 810106 memo re allegations of unsafe conditions & improper firing of employee by Nuclear Metels. Inc No further action planned unless written complaint filed KINNEMAN, J D Nuclear Metals. Inc 81/01/13 SMITH, O H. Region I. Philadelphia, Office of the Director 1p 18353-187
- --8305060193 Discusses allegations by former Nuclear Metals, Inc amplayee re unsafe conditions & improper firing Info partially deleted GLENN.J.E Region 1, Philadelphia. Office of the Director B1/01/06 KINNEMAN.J D Region 1, Philadelphie, Office of the Director. 2pp 1838 188
- --83D5060200 Forwards "Analysis of Exposure Involving Depleted U at Nuclear Metals.Apr 1981," consultant rept HURBH.J B. Rochester, Univ of, 82/02/18 HAYNES,R C Region 1, Office of Director 1p 18353,202
- --8305060207 Discusses allegations made by Nuclear Metals, Inc employee re unsafe conditions involving risk of employee contemination, Related info encl Info partially deleted. ROME.C Region 1, Office of Director 82/04/22 XINNEMAN, J. D Region 1, Office of Director 1p 18353:241
- --8303060214 Notifies of results of inquiries re allegations made by Nuclear Metals, Inc employes. No items of concern represented noncompliance w/NRC regulations or safety hazards KINNEMMN.J D Region i, Office of Director 82/04/02 FIATARONE, J V Labor, Dept. of 19 18353 242
- --8305060220 Forwards compleint from Nuclear Metals, Inc employee re unsafe conditions & health hazards at facility Related info shel Info partially deleted FIATARORG, J. V. Labor, Dept. of 82/02/02 KINNEMAN. J. Region 1, Office of Director 20pp 18353:243
- DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY
- 8305020407 Forwards "Hater Quality Hampling Results Fourth Quarter 1982: 8plit Rock Hill, Jeffrey City, HY: "per License Condition 25 Hell 20 deta will be submitted in supplemental rept. BQQDEN, O Hestern Nucleer, Inc. (subs of Phelps Dodge Corp), 83/03/31 Region 4. Office of Director 1p 18273: 220.
- --8305020417 "Water Quality Sempling Results, Fourth Quarter 1982, Bplit Rock Mill-Jeffrey City, HY " Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.). 83/03/31, 185pp 18273 221.
- 8305030497 Forwards fuel cycle & matls LER summary for Mar 1983. BROWN 0 D Division of Vendor & Technical Programs. 83/04/27 DAVIS.J. C. Office of Nuclear Material Safety & Bafeguards, Director. 3pp. 18306.198
- 8305250175 Addendum to semiannual environ manitoring rept for Jul-Dec 1982 W/830510 ltr. BODDEN, O. Western Nuclear, Inc. (subs. of Phelps Dadge Corp.) B3/05/10, PETTENGILL, H.J. Uranium Recovery Licensing Branch. 37pp. 1839-131

DOCKETED ITEMS

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA. IN

8303030084 Informs that monitoring locations adequate to meet FEB Bection 4.2 criteria re evaluation of any adverse effects of decommissioning on environ & to ensure monitoring of critical pathways JOHNBON, T. Uranium Recovery Field Office LINEHAN, J.J. Region 4, Office of Director 83/03/25 Uranium Recovery Field Office 2pp 18310 339

DOCKET 40-1478 SPENCER CHEMICAL CO , KANSAS CITY, MO

- 8305230112 Final response to FOIA request for insp repts of safety violations at Kerr-McGee Pu plant at Cresant.OK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted FELTON.J M Division of Rules and Records 83/03/22 WIDMER,R R Affiliation Unknown ip 18543 154
- --8305230207 Forwards Region IV 660729 memo re facility clossout survey results Licensee measurements in 660609 ltr substantiated by Region IV findings.
 ROY.O W Atomic Energy Commission 66/08/08 NUSSEAUMER,D A Atomic Energy Commission ip 18543 222
- --8305230222 Discusses closeout insp of Licenses BMB-664 & BNM-695 on 660706 Recommends that licenses be authorized to transfer control of facilities to unlicensed recipient WALKER, D L. Atomic Energy Commission 66/07/29 DUBINBKI, L Atomic Energy Commission 4pp 18543 223
- --B305230233 Requests authorization to release vacated facilities at Cushing OK to refining div for unrestricted use Bldgs used by nuclear products dept cleaned & decontaminated. Health physics survey indicates contamination below limits MULLER, D B. Kerr-HcOse Nuclear Corp 66/06/09 NUSSBAUMER, D A Atomic Energy Commission 4pp 18543 227
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK
- B303280177 Forwards IE Insp Rept 40-2041/B3-01 on B30104-06 & 25-28 No noncompliance noted HIND, J A Region 3. Office of Director B3/02/23 SHELLEY, W J Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp) 2pp 17709: 277
- --B303280182 IE Insp Rept 40-2061/83-01 on 830104-06 & 25-28 No noncompliance noted Major areas inspected liquid efficient releases & new operational water retention sys, surface water results & work site NICHOLBON, N. A., BCHUMACHER, M. C. Region 3, Office of Director 83/02/17 7pp 17709 279
- 83050307040 Discusses items of interest, including DDE 830419 visit to NHBB to examine docket files of Kerr-htoge Mest Chicago Rare Earths Facility & Detroit Edison Co 830419 visit to discuss proposed license conditions for SMH-1915 for fuel storage. PAGE:RO Uranium Fuel Licensing Branch 83/04/20 DAVIS, J. 9 Division of Fuel Cycle & Material Safety 3pp. 18309:105
- B30517048B Order extending time until B30520 for Commission to act to review presiding officer B30315 decision CHILK,B.J. Office of the Bacretary of the Commission B3/05/13 Commissioners ip. 18470 008
- 8305200570 Order extending time until 830527 for Commission to act to review presiding officer 830315 decision. CHILK: 8. J. Office of the Secretary of the Commission. 83/05/19. Commissioners 1p. 18514 273
- B305240080 Confirms B30524 meeting in Olen Ellyn, IL to discuss noncompliance noted in recent insp.corrective actions & enforcement options available to NRC, per B30519 telton KEPPLER, J G Region 3, Office of Director, B3/05/19. RAINEY, J G Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp), 19 18549:175.
- 8305240282 Notification of significant licensee 830524 meeting in Olen Ellyn: IL to discuss NRC findings during recent insp. enforcement options available & licensee corrective actions e Region 3, Office of Director 83/05/20 Region 3, Office of Director. ip. 18548 201

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

- 8305130295 Reviews surety arrangements for decommissioning & reclamation costs for Lucky HcMill Cost analysis & summary acceptable WOOLSEY.R T Uranium Recovery Field Office 93/03/21 Uranium Recovery Field Office 2pp 18460
- 8305030711 Discusses Pathfinder. Inc 830314 request to reduce number of groundwater quality parameters to be monitored Wells UM-502 to AL-1 should continue to be sampled for entire suite of parameters Cation-anion balances should be reported KEARNEY, B. Hyoming, State of 83/04/05 Wyoming, State of 3pp 18309 090
- 8305160205 Submits recommendations re 830314 request for reduction (n parameters analysed for groundwater monitoring program SEIFFERT, S G Wyoming, State of 83/04/13 HARDORDVE, T Pathfinder Mines Corp 1p 18462 361
- 8305130312 Trip rept of 830419 meeting at Pathfinder mining site re seepage from Tailings Pond 1 Major seepage path identified to be paleochannel within cody shale Efforts to control seepage partially successful REARRY.B NRC No Detailed Affiliation Oiven 83/04/18 NRC No Detailed Affiliation Qiven 2pp 18457 319
- 8305260357 Advises that TW Hardgrove assumed responsibility of environ coordinator-overseeing radiation protection function in mill dept as of B30411 NUOENT.E L. Pathfinder Mines Corp. 83/04/22 WODLSEY.R T. Region 4. Office of Director ip. 18647-290
- DOCKET 40-3079 TECHNICAL OPERATIONS, INC , BURLINGTON, MA
- 8305050161 Forwards IE Insp Repts 40-3079/83-01.30-04576/83-01 & 30-09623/83-01 on 830309 No noncompliance noted MARTIN-T T. Division of Engineering & Technical Programs 83/04/20 LANDAUER R Technical Operations, Inc. 2pp 18342 222
- --8303050166 IE Insp Repts 40-3079/83-01,30-04576/83-01 & 30-09625/83-01 on 830309 No noncompliance noted Major areas inspected scope of operations, licensee action on praylous insp findings & followup on possible defect in exposure device ROME: C A , KINNEMAN, J D Region 1, Office of Director 83/04/19 5pp. 18342 224
- DOCKET 40-3392 ALLIED CHEMICAL CORP., MORRIBTOWN, NJ
- B305030671 Forwards request for add1 info needed to complete EIA for license renwal Most questions discussed during NRC B30413 site visit but written responses needed for renewal process by B30531 WYNOARDEN. B Uranium Fuel Licensing Branch B3/04/25 YATES, R W Allied Chemical Corp 4pp 18309 231
- 8305120127 Trip rept of 830419-20 site visit to Metropolis. IL refacility familiarization & initial comments on License 888-326 renewal application Rost. As Uranium Fuel Licensing Branch 83/05/04. CROW. W T Uranium Fuel Licensing Branch 1p 18435-311
- B305240337 Forwards IE Insp Rept 40-3392/B3-01 on B30419-20.No noncompliance noted.

 PAPERIELLO, C.J. Region 3, Office of Director B3/05/09 CIFOLLA: A.J. Allied Chemical Corp. 2pp 18575:107
- --8305240340 IE Insp Rept 40-3372/83-01 on 830419-20 No noncompliance noted Major areas inspected, radiation protection, radwaste mgt. safety committees & conduct of operations PECK, C C , MILLER, D. E. , OREGER, L. R. Region 3, Office of Director, 83/05/09 4pp, 18575 109.
- 8305170724 Confirms 830419-20 discussion re format for submittal of renewal application for License 808-526 Section specifying committed conditions of operation requested KOSLAP Uranium Fuel Licensing Branch 83/05/11 YAYE8,R W Allied Chemical Corp. ip 18496 185
- DOCKET 40-3453 ATLAS MINERAL, INC , DENVER, CO
- B305130297 Reviews Third Quarter 1982 environ monitoring data for Moab Mill Bampling & analysis acceptable OARCIA.P.J., PETTENGILL.H.J. Uranium Recovery Field Office, B3/03/21 Uranium Recovery Field Office, 4pp 18460 036

- B305120496 Comments on Atlas Minerals rept re 1982 land use survey for Moab Mill in accordance w/Condition 40 of Source Mati License SUA-917 Vendor has performed acceptable land use eurvey CARCIA.P J. PETTENGILL.H J. Uranium Recovery Field Office B3/04/06 Uranium Recovery Field Office ip 18443 172
- 8305130362 Requests extension of due date to 840430 for proposed plan for final reclamation phase mods to Moab Wash site.per License Condition 16 to License SUA-917 BLUBAUGH.R E Atlas Minerals 83/04/22 SMITH.D NRC - No Detailed Affiliation Olven 2pp 18443 322
- 8305170601 Reviews Thire Quarter 1982 Pb-210 environ monitoring data for Moso Hill Sampling data acceptable BRANSCOME.J M Uranium Recovery Field Office 83/05/21 Uranium Recovery Field Office 2pp 18497 046
- DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY
- 8305200031 Forwards Federal American Partners "Soil Testing Cas Draw, Cas Hills, Fremant County, My " SEIFFERT, SO Hyoming, State of 89/03/23 PETTENGILL, H J Uranium Recovery Field Office 3pp 18340 269
- --8305200037 "Soil Testing Gas Draw, Gas Hills, Fremont County, WY "
 Wiftour oversize maps Aperture cards are available in PDR
 * Federal American Partners 83/02/28 44pp 18540 272
- 8305130319 Notice of negative declaration re issuance of amend to License SUA-667 for operation of Federal-American Partners U mill in Oas Hills.WY LINEHAN.J J Uranium Recovery Field Office 89/04/11 ip
- DOCKET 40-6500 ENERGY, DEPT OF: CANONSBURG, PA
- B305180117 Forwards summary of data from radon monitoring network in Canonsburg-PA area for 811030-820127 Maps indicating monitoring locations epcl RUDY-C R Honsanto Co B3/04/15 CROW,W T Division of Fuel Cycle & Haterial Safety 1p 18503 320
- --8309180125 "Mound Radon Program, Summary of Outdoor Canonsburg Monitoring Data," 811030-820129 * Monsanto Co 83/04/15 3pp 18503 321
- 8305170116 Summarizes possible use of models for groundwater flow & transport in saturated & unsaturated layers for various UMTRA sites
 DEBLAK Roy F Weston, Inc. 83/04/21 NIXON:N A NRC No Detailed Affiliation Given 2pp 18496-361
- 8305180176 Comments on items of interest re listed meetings NMBS meeting notes encil PAGE.R O Uranium Fuel Licensing Branch 83/05/12 DAVIB.J Q. Defice of Nuclear Material Safety & Safeguards.Director Spp 18502 334
- DOCKET 40-6622 PATHFINDER MINES CORP . SHIRLEY BASIN, MY
- 8305020410 Forwards effluent monitoring data & 40CFR190 rept for Fourth Quarter 1982 per License SUA-442. Amend 2. Condition 37 & corrected Table VIID & VIIE. re ingestion & total dose at Bites 7R & GP 1

 BMITH. J C Pathfinder Mines Corp 83/03/24 BROWN 0 D Region 4, Office of Director ip 18281 266
- --8305020504 "Environ Monitoring Data W/Dose Calculations.Fourth Quarter 1982 " * Pathfinder Mines Corp 83/03/24 29gp 18281 267.
- 8305030277 Forwards effiuent monitoring data rept for Fourth Quarter 1982 Corrected Tables VIID re ingestion dose & VIIE retotal dose also encl
 8M17H.J C. Pathfinder Mines Corp 83/03/24. GARCIA.P Uranium Recovery Licensing Branch 1p 18309 300
- B3D5020491 Comments on State of WY Dept of Environ Quality 830222 ltr re environ monitoring program Deepening seepage collection trench would increase seepage rate & should be considered alternative WILLIAMS: R E R E. Hilliams & Associates, Inc. B3/03/29 QARGIA, P. Uranium Recovery Licensing Branch 4pp 18284 327.

- 630513032B Forwards request for add1 info re proposed reclamation plan for tailings impoundments for Shirley Basin Mine, per license renewal review PETTENGILL.H J. Uranium Recovery Field Office 83/03/31 RUSSELL.J E. Pathfinder Mines Corp. 5pp. 18457-272
- 8305030497 Forwards fuel cycle & matls LER summary for Mar 1983 BROWN, O D Division of Vendor & Technical Programs 83/04/27 DAVIS, J Q Office of Nuclear Material Safety & Bafeguards, Director 30p 18306 198
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CO . SHIRLEY BASIN, WY
- 8305020439 Forwards environ sample data for Third Guarter 1982 PFAFF,8 J Getty Oil Co (Petrotomics) 83/03/02 NRC - No Detailed Affiliation Given 2pp 18281 146
- --8305020443 Environ sample data. Third Guarter 1982 * Oetty Dil Co (Petrotomics) 83/03/02 65pp 18281 148
- 8305030499 Forwards fuel cycle & matis LER summary for Mar 1983 BROWN.0 D Division of Vendor & Technical Programs, 83/04/27 DAVIS.J Q Office of Nuclear Material Bafety & Bafeguards, Director 3np 18306 198
- DOCKET 40-7097 MOLYCORP, ING , WHITE PLAINS, NY
- 8305180200 Submits summary of decommissioning plan for facility Info needed to complete cost estimates included MARKOLLM, M. Melycorp. Inc. 83/04/21 800NG: A.L. NRC - No Detailed Affiliation Given 2pp. 18502 360
- DOCKET 40-7980 FANBTEEL, INC . NORTH CHICAGO, IL
- 8305160004 Application for amend to License BMB-911 authorizing const & operation of pond to receive, settle & store calcium base residues from regular industrial process stream W/four oversize maps Aperture cards available in PDR DUGGAN.J G. Fansteel Metals (subs. of Fansteel, Inc.) 83/03/04 Licensing Management Dranch 6pp 18462 348
- 8305160258 Forwards 830304 application for amend to License 8M8-911, apparently not received application NRC No Detailed Affiliation Given 1p 18475 043
- --B305160261 Application for amend to License BMB-911 to construct & aperate interior-lined pand to receive settle & store calcium-base residues fram industrial process stream DUOANN.J O Fansteel, Inc. B3/03/04 NRC No Detailed Affiliation Olven 6pp 18475 044
- DOCKET 40-7708 UNION CARBIDE CORP , NEW YORK, NY
- 8305180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses from U Fuel Licensing Branch to Region III PAGE.R G. Uranium Fuel Licensing Branch 83/05/05 HIND, J A Region 3. Office of Director ip 18505 075
- 8305180824 Notifies that official files for License 8BM-933 transferred to Region III as of 830401, as part of regional licensing program W/o stated FR notice PAOE. R O Uranium Fuel Licensing Branch 83/05/05 DEVERLY, R Q. Union Carbide Corp 1p. 18505 361
- 8303200154 Confirms 830504 conversation re expiration of License BMD-933 License amended to delete Item 4 expiration date of 770831 License shall remain in effect until NRC action initiated to terminate license PAGE.R.Q Uranium Fuel Licensing Branch 83/05/16 BEVERLY.R Q Union Carbide Corp 1p 18540 244.
- DOCKET 40-7859 PLATEAU REBOURCES, LTD , GRAND JUNCTION, CO
- B305040047 Forwards "Effluent Monitoring Rept, Jul-Dec 1982" OERDEMAN, F W. Plateau Resources: Ltd B3/04/13 Region 4, Office of Director 1p 18336/348.
- ~-8305040052 "Effluent Monitoring Rept. Jul-Dec 1982 "
 * Plateau Resources, Ltd 83/04/13 10pp 18336.349

- B305030499 Forwards fuel cycle & matis LER summary for Mar 1983 BROWN, Q D Division of Vendor & Technical Programs B3/04/27 DAVIS, J G Office of Nuclear Material Safety & Safeguards Director 3pp 1830& 198
- 8305250199 Recommends mod to License Condition 12 re transfer & disposal of contaminated matl at Shootaring Canyon mill tailings impoundment Mod authorizes Plateau Resources Limited 830221 proposal for use of three-drum slusher JOHNBON.T L , LINEHAN, J J Uranium Recovery Field Office 83/05/10 Uranium Recovery Field Office 1p 19395 338
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8305030237 Issues Amend 2i to License 8UB-1010, requiring sampling & analyzing of sediment every 6 months 8ER supporting amend encl
 PAGE, R Q Uranium Fuel Licensing Branch B3/04/20 SHELLEY, W J
 Kerr-McGee Nuclear Corp 2pp 18307 340
- --8305030246 SER supporting Amend 21 to License SUB-1010 re sampling & analyzing sediment
 RHDDES,M Uranium Fuel Licensing Branch 83/04/20 App
 18309 343
- 8305200032 Forwards 1982 completion rept re continued use of barium treated, neutralized solvent extraction raffinate as fartilizer.per Condition 12 of Amend 17 to License BUB-1010 W/two oversize figures Aperture cards in PDR 8HELLEY,W J Kerr-McGee Nuclear Corp 83/04/26 PAGE,R Q Uranium Fuel Licensing Branch 25pp 18528 314
- 8305180325 Discusses items of interest, including natl response team, FEB for Kerr-McGee Rare Earth facility & radioactive property in Wayne,NJ PAGE,R Q Uranium Fuel Licensing Branch 83/05/05 DAVIS,J Q Office of Nuclear Material Safety & Safeguards, Director 2pp 18503 357
- B305120479 Ack receipt of B30426 ltr informing NRC of steps taken to correct violations noted in IE insp of License SUB-1010 Add1 info re corrective actions requested within 10 days of ltr receipt BROWN.O D Region 4. Office of Director B3/05/10 SHELLEY.W J Kerr-McOee Corp ip 18431 057
- 8305250603 Issues Amend 22 to License 808-1010, authorizing injection of treated liquid raffinate in Sequoyah waste disposal well SER encl PAGE, R G Uranium Fuel Licensing Branch 83/05/18 SHELLEY, W J Kerr-McGee Nuclear Corp. 1p 18594 316
- --8305250604 SER supporting Amend 22 to License SUB-1010, authorizing injection of treated liquid raffinate in Sequovah waste disposal well HYNOARDEN, S. D. Uranium Fuel Licensing Branch 83/05/18 5pp 18594 317

DOCKET 40-8035 COTTER CORP : ROSWELL, NM

- 8305180183 Advises that only solution is cinst of masonry bldg w/concrete floor & roof Cotter has agreed to addi cost Prof drawings & procedures will be forwarded upon agreement w/alternate approach JARBOE,E D Futura Coatings, Inc 83/04/18 CROW,B NRC ~ No Datailed Affiliation Given 2pp 18502:357.
- 8305040707 Bummary of meeting w/Btats of MO & Future Chemical Co re possibility of restricting access to pile of conteminated soil w/residues from extraction of U from ore during World War II, Bldg should be constructed to house soil.
 PAGE.R O Uranium Fuel Licensing Branch 83704/28 DAVIB, J O Defice of Nuclear Material Bafety & Bafeguards, Director 2pp 18336, 333
- B305110117 Trip rept of B30421 meeting w/State of MO & Futura Chemical in Hazelwood, MO re State of MO proposals to restrict access to Futura Chemical property CROW-W.T. Uranium Fuel Licensing Branch B3/05/02 Uranium Fuel Licensing Branch ip 18421 315
- 8305180176 Comments on items of interest re listed meetings. NMSB meeting notes enci PAGE.R O Uranium Fuel Licensing Branch 83/05/12 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director Spp 18502, 334.

- DOCKET 40-8064 EXXON MINERALS CO USA, HOUSTON, TX
- 8305030719 Forwards summary of U data for Original Pilot In Situ Mine included in 821602 & 830128 quarterly repts ESTEY, HP Exxon Corp 83/04/06 LINEHAN, J J Uranium Recovery Field Office 2pp 18310 356
- 8305170242 Submits review comments on proposed restoration/postrestoration program for Exxon Highland Mill Mods to target restoration value & eccursion monitoring program recommended Program acceptable FREUDENTHAL.N. SMITH.M Wyoming State of 83/04/11 SHITH.R D Uranium Recovery Field Office 4pp 18496 177
- 8305170395 Summarizes review of Expanded Pilot R&D wellfield quarterly rept for Oct-Dec 1982 No followup actions necessany ROSS.F W. LINEHAN.J J Vrantum Recovery Field Office 83/04/21 Uranium Recovery Field Office 2pp 18493 360
- B305130363 Ack receipt of Exxon B30419 itr Dept of Environ Quality does not abject to Exxon mod of excursion monitoring program frequency from biweekly to monthly FREUDENTHAL:N Wyoming, State of B3/04/25 LINEHAN:J Uranium Recovery Field Office ip 18443 321
- 8305260145 Quarterly rept for Jan-Mar 1983 Original pilot observation wells will be sampled monthly until regulatory concurrence received Health physics surveys taken monthly SHANNON, J B Exton Corp. 83/04/27 LINEHAN, J Uranium Recovery Licensing Branch. 9pp. 18648-254

DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT

- 8305170585 Comments on 830215 survey rept re land use changes since 820901 rept No change identified which would warrant mode to environ monitoring program HASTLER.S L. LINEHAN, J. Uranium Recovery Field Office MASTLER.S L. Licensing Branch 1 83/04/08 Uranium Recovery Field Office ip 18496-108
- 8305060462 Elaborates on 830301 telcon re liability of Rio Algom Corp in processing & shipping of U concentrate owned by Brush Wellman. Inc Legally definitive answer to question of liability cannot be provided EVERETT.R J. Region 4. Office of Director 83/05/03 LAWTON.M D Rio Algom. Ltd 2pp 18351 192

DOCKET 40-8102 EXXON CO UBA. HOUSTON, TX

- B305250195 Informs that Permit Rav TFN 1-6/242 (Permit 218C) will be considered incomplete until finalized reclamation plans submitted BUNDIN:R E , FREUDENTHAL, N Hyoming, State of B3/03/25 BHANNON, J Exxon Corp 6pp 18596
- 8305030497 Forwards fuel cycle & matls LER summary for Mar 1983 BROWN,O D Division of Vendor & Technical Programs 83/04/27 DAV18,J G Office of Nuclear Material Safety & Safeguards, Director MICHELSON,C Director's Office 3pp 18306 198
- DOCKET 40-8137 PACIFIC TECHNICAL CORP , SANTA BARBARA, CA
- 8305260267 Forwards 1E Inap Rept 40-8137/83-01 on 830201-02 of activities under License 8U8-1137 No noncompliance noted 800K, H E Region 5, Office of Director 89/05/10 FELDMAN, F K Pacific Armatechnica Corp 2pp 18625 292
- ---8305260273 IE Insp Rept 40-8137/83-01 on 830201-02 No moncompliance noted Major areas inspected survey conducted in conjunction w/analytical assays of collected soil samples. Range 5 facility cannot be released for unrestricted use 8KOV.D.D. THOMAS.R D. BODK.H E Region 5. Office of Director 83/05/10 23pp 18625 294
- DOCKET 40-8202 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH
- 8305040623 Forwards IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401. No noncompliance noted PAPERIELLO, C J Region 3. Office of Director 83/05/03 UNGAR, E W Battelle Memorial Institute, Columbus Laboratories 2pp 18348 251

--8305060634 IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401
No noncompliance noted Major areas inspected radiation
protection, radwaste mgt. facility changes & safety
committees
PECK.C C , GREGER.L R Region 3, Office of Director 83/04/29
App 18348 253

DOCKET 40-8348 MINERALS EXPLORATION CO , LOS ANGELES, CA

B305040222 Discusses groundwater restoration & water quality analysis from land quality div sampling conducted in Dec 1982 Site should not be declared acceptably restored & holes should not be plugged Site should not be claimed as restored KEARNEY. B. Hyoming, State of B3/03/23 Myoming, State of 10pp 18364 309

8305130298 Comments on outstanding licensing review issues to A-3 Pilot Plant R&D ISL facility Meeting to settle issues recommended MASTLER'S L Uranium Recovery Field Office 83/04/21 Uranium Recovery Field Office 83/04/21

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD, CO

8305060226 Suggests presence at 830507-11 or 16-18 meetings w/land & water quality divs to discuss findings for final decision re Rocky Mountain Engineering plans for Nine Hile Lake BEACH, 9 Hyoming State of. 83/04/07. LINEHAN, J Uranium Recovery Field Office ip 18359-362

8305160274 Recommends 830511 meeting to discuss recent 9-mile proposal in order to draft final decision BEACH.O Hyoming. State of. 83/04/15 SUNDIN.R., OARLAND.8, SHAFFER.R Rocky Mountain Energy Co ip 18475 042

8305240364 "Nine Mile Lake Guarterly Rept First Guarter 1983." SPIELES.P R Rocky Mountain Energy Co 83/04/30 SMITH.R D Region 4. Office of Director 16pp 18648 005

DOCKET 40-8406 PESSES CO . SOLON, OH

8305180759 Lists official docket files & outstanding licensing actions transferred to Region I.effective 830401 PAGE.R O Uranium Fuel Licensing Branch 83/05/05 HARTIN.T T Division of Engineering & Technical Programs 1p 16506 033.

8305180820 Notifies that official files for License STB-1254 transferred to Region I as of 830401.as part of regional licensing program W/o stated FR notice PAGE.R G Uranium Fuel Licensing Branch 83/05/05 PE88ES,M Pesses Co ip. 18503:360

DOCKET 40-8452 BEAR CREEK URANIUM CO . CASPER, MY

B305020363 Forwards "Guarterly Environ Monitoring Rept,Oct-Dec 1982"

BLOSSOM, J N Bear Creek Uranium Co 83/03/04 Region 4, Office of Director. 1p 18276-344

8305020476 Submits evaluation of licensee 821206 environ monitoring rept for Third Quarter 1982 per 100FR40 65 Requirements of 100FR40 65 should be discussed w/licensee during next inspire compliance w/reporting period & rept timeliness SPITZBERO, D. B. Region 4. Office of Director 83/03/09 Region 4. Office of Director 1p. 18263 270

8305030499 Forwards fuel cycle & matls LER summary for Mar 1903 BROWNS D Division of Vendor & Technical Programs 83/04/27 DAVIS.J Q Office of Nuclear Material Safety & Safeguards. Director MICHELSON, C Director's Office 3pp 18306 198

B303250245 Discusses review of Bear Creek U Co rept for Yhird Quarter 1982 Remedial action not indicated PANOBURN. 0 C , PETTENGILL, H J Uranium Recovery Field Office B3/04/27 Uranium Recovery Field Office App 18626:355.

8305250591 Comments on environ monitoring data rept for Fourth Guarter 1982 for Bear Creek Rept acceptable PANOSURN'S C. PETTENDILL,H J. Uranium Recovery Field Office 83/04/27 Uranium Recovery Field Office App 18594:331

DOCKET 40-8502 HYDMING MINERAL CORP : LAKEWOOD, CO

8305160209 Informs of acceptance of 830317 data & drawdown maps demonstrating stabilization of well fields MODNEY.0 Wyoming, State of 83/04/11 FAUBER.J R Wyoming Hineral Corp ip 18471 342

B305260144 "Irigaray Mine Site Guarterly Rept, Jan-Mar 1983 " W/B30427 Itr RUFLEDGE, C Wyoming Mineral Corp B3/04/27 CHANCELLOR, R. Wyoming, State of 146pp 18648 263

DOCKET 40-8550 HOLMES & NARVER, INC , ANAHEIM, CA

8305250594 Forwards decontamination rept re final alpha survey for License SUA-1307 Acceptance of survey requested M/a encl PETTENOILL.H.J Uranium Recovery Field Office 83/05/16 BROWN, C. Region 4. Dffice of Director 1p 18594 327

DOCKET 40-8584 MINERALS EXPLORATION CO . LOS ANGELES, CA

B305030705 Discusses review of Dames & Moore, "Rept of Engineering Dasign Study, Tailings Disposal Sys: Sweetwater U Project, Near Rawlins, MY" of the 3207013 Engineer should be present to control field testing HOMARD, TR R & Williams & Associates, Inc. B3/04/04 GARCIA, P. Uranium Recovery Licensing Branch ip 18307 108

8305040002 Forwards memo outlining major deficiencies in application to amend modified tailings pond, including liner, aquifer monitoring & lask detection & long-term stability of reclamation pond Review of application incomplete ENGELMANN, R. Wyoming. State of 83/04/04 DYKERS.L. Minerals Exploration Co (subs of Union Oil Co of California), 13pp 18331.254

B305060389 Forwards B30325 ltr of bond transmittal & B30223 bond evaluation from State of HY Dept of Environ Quelity per License Condition 17 to License BUA-1350 BNYDER: H L. Union 76 Minerals Exploration Co B3/04/05, PETTENGILL. H Uranium Recovery Field Office, 9pp 18359; 290

8305130317 Forwards request for add1 info re proposed operational & reclamation plans for various alternatives for above-grade disposal Response by 830502 requested PETTENGILL.H J Uranium Recovery Field Office 83/04/07.

8NYDER.H L Minerals Exploration Co (subs of Union Oil Co of California) 2pp 18457 317

8305160211 Natifies of 830510 joint meeting w/NRC re tailings mod iicense/permit Rev TFN 1 5/294 Comments/issues for discussion requested BEACH, O Hypming, State of B9/04/18 SNYDER, L. Minerals Exploration Co (subs of Union Oil Co of California) 1p. 18462 362.

8305030499 Forwards fuel cycle & matte LER summary for Mar 1983 BROHN & D Division of Vendor & Technical Programs 83/04/27 DAVIS, J & Office of Nuclear Material Safety & Safeguards, Director 3pg 18306 198

DOCKET 40-8602 SILVER KING MINES, INC . CASPER, WY

B305120490 Comments on preoperational environ monitoring rept submitted on B30223 for Morton Ranch Project for License BUA-1336
MOOLSEY.R.T., PETYENOILL,H.J. Uranium Recovery Field Office,
B3/04/07 Uranium Recovery Field Office 3pp 18440 211.

DOCKET 40-8669 NUCLEAR DYNAMICS: INC : PHOENIX: AZ

8305130336 Advises that general content of 830330 request to renew License 80A-1331 acceptable. Before facility at Oshoto site can be abandoned, plan for decontamination of site facilities must be submitted.

LINEHAN, J Uranium Recovery Field Office, 83/04/21. STOICK, A F., Nuclear Dynamics. 2pp. 18457:321

8305240596 Modifies License SUA-1331.License Condition 4.extending expfration date for decommissioning activities to 840430 SMITH.R D Uranium Recovery Field Office 83/04/28 STOICK.A F. Nuclear Dynamics. 1p. 18594 210

- DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC , DENVER, CD
- 8305160256 Advises of issuance of amend to License BUA-1325 revising License Conditions 6-8 & adding License Condition 30 SMITH,R D Uranium Recovery Field Office 83/04/19 Energy Fuels Nuclear, Inc. 2pp 18475 050
- --8305160259 Bafsty evaluation supporting Amend 2 to License SUA-1325 re suspension of environ monitoring program at Hanksville Ore Buying Station GILLEN.D M , PETTENOILL.H J Uranium Recovery Field Office 83/04/19 3pp 18475 052
- DOCKET 40-8681 ENERGY FUELS NUCLEAR. INC . DENVER. CO
- 8305020481 Forwards "White Mesa Project Effluent & Monitoring Rept Oct-Dec 1992" ROBERTS:H R Energy Fuels Nuclear, Inc 83/02/20 GILLEN, D Uranium Recovery Licensing Branch Ip 18282 300
- --8305020484 "White Mesa Project Effluent & Monitoring Rept Oct-Dec 1982 "
 - Energy Fuels Nuclear, Inc 83/02/28 31pp 18282 301
- B305030499 Forwards fuel cycle & matls LER summary for Mar 1983 BRGWN, C D Division of Vendor & Technical Programs B3/04/27 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director Job B306 198
- DOCKET 40-8693 OGLE PETROLEUM, INC , SANTA BARBARA, CA
- 8305160251 Advises of issuance of amend to License Condition 2 of License SVA-1336, changing address SMITH.R D Uranium Recovery Field Office 83/04/14 Ogle Petroleum, Inc. ip 18471 361
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO . DENVER, CO
- 8305040651 Discusses final groundwater restoration Pattern II Restoration successfully demonstrated at Pattern II for all parameters, except U & pH Lab repts ench BCHMITTDIEL.P Hyoming, State of B3/03/21 Hyoming, State of Bpp 18359: 299
- B303030713 Forwards rept on insp & Pattern 2 sampling conducted B3020B-09 Rept placed in permanent insp file for Permit 479 MOONEY. O Wyoming, State of B3/04/ii SPIELES, P Rocky Mountain Energy Co 9pp. 18309 OB1
- 8305250171 Guarterly rept for Jan-Mar 1983 Both wells will remain shut/down while regulatory agencies evaluate restoration stability If restoration signoff received.well abandonment procedures will be initiated 8PIELEB.P R Rocky Mountain Energy Co 83/04/18 SMITH.R D Uranium Recovery Field Office 18pp 18626 330
- B305250241 Requests approval for releasing Rocky Mountain Energy from further groundwater restoration for Reno Creek ISL project MOONEY, O Hyoming, State of 83/04/27 BUNDIN, R E : FREUDENTHAL: N Hyoming, Btate of 1p. 18626 361
- 8305250283 Reviews 820716 groundwater stabilization rept for Test
 Pattern II at Reno Creek.Restoration program should exert
 greater effort to achieve lower concentrations Licensee
 should be notified that Pattern II restored
 KALMAN.K L . LINEHAN.J J Uranium Recovery Field Office. 83/05/03
 Uranium Recovery Field Office 5pp 18575 305
- DOCKET 40-8698 PLATEAU RESOURCES, LTD : GRAND JUNCTION: CO
- 8305250418 Forwards corrected Page 1 to "Interim Burety Estimates for Decommissioning & Reclamation, Apr 1983, "forwarded in B30411 ltr. Encl page entitled "List of Revs" should be inserted after title page.

 OERDEMAN.F W. Plateau Resources, Ltd 83/04/12 SMITH.D NRC No Detailed Affiliation Given 3pp 18629 357

- DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO . CLEVELAND. OH
- 8305060357 Forwards analysis of water samples taken at Collins Draw site Well Fields A & B samples exceeded baseline range for 0 several parameters, including potassium, ammonia, arsenic & seienium OOLE, K M Wyoming, State of 83/01/31 Wyoming, State of 18pp 18389 272
- 8305160232 Requests official communication or meeting to determine compliance w/Collins Draw groundwater restoration agreement.
 License 3RD & WY Environ Quality Act
 LOUDERDACK.T £ Cleveland-Cliffs Iron Co 83/04/15 MCCONEY, G
 Wyoming. State of 3pp 18471 343
- 8305260383 Forwards Cleveland-Cliffs 830415 ltr to State of WY Land Guality Div re Collins Draw Project.per 830429 discussions LOUDERBACK, T E Cleveland-Cliffs Iron Co 83/04/29 ROSS.F Uranium Recovery Licensing Dranch 36pp 18647 213
- DOCKET 40-8722 BRUSH WELLMAN, INC , CLEVELAND, OH
- 8305060462 Elaborates on B30301 telcon re liability of Rio Algom Corp in processing & shipping of U concentrate owned by Drush Wellman. Inc Legally definitive answer to question of liability cannot be provided EVERETT, R J Region 4. Office of Director 83/05/03 LAWTON. M D Rio Algom, Ltd 2pp 18351 192
- DOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY
- 8305030709 Formerds response to 821018 itr re M Zone restoration stability data for review & discussion MCCARTY.C L . PUCEL.P Wyoming. State of 83/03/15 APPEL.D Teton Exploration Drilling Co . Inc 11pp 18309 093
- 8305030283 Requests review input for restoration & stability of "H"
 Zone Teton, Levenberger sites & verification sampling as
 wrap-up
 FRANCIS, E Wyoming, State of 83/03/25 GARLAND, B Wyoming, State
 of ip 18309-334
- --8309030262 Notifies that discussions recently held w/RR Appel of Teton Exploration Co re procedures for declaration of restoration of M Zone aquifer FRANCIS.E Myoning, State of 83/03/23 LINEHAN, J Uranium Recovery Licensing Branch ip 18309 335
- --8309030273 Notifies that Land Quality Div Permit 522 was approved w/certain stipulations Upper control limit methodology for U & chloride in land quality permit should be identical to limits specified in NRG licensing action FREUDENTHAL.N Wyoming, State of 83/03/23 LINEHAN,J Uranium Recovery Licensing Branch 3pp 18309 336
- 83051302Bi First Quarterly Rept for 1983 re pond water level.
 radiological monitoring, site security checks & site cleanup
 grograms
 APPEL.R R Teton Exploration Drilling Co , inc
 88174/01
 88174.R D Division of Waste Management 8pp 18457 345
- DOCKET 40-8745 GOLE PETROLEUM, INC . CASPER. WY
- 8305160253 Advises of issuance of amend to License Condition 2 of License 8UA-1376:changing address BMITH.R D Uranium Recovery Field Office 83/04/14 Ogle Petroleum, Inc. ip 18471-362
- DDCKET 40-8752 PINAL MINERALS & MINING, LTD , MIAMI, AZ
- 8305130322 Advises that License SUA-1388 amended by revising License Conditions 3 & 14 & adding License Condition 15 SMITH.R.D. Uranium Recovery Field Office 83/04/22 Pinal Minerals & Mining, Ltd 3pp 18457 308.
- --8305130325 Advises that License SUA-1388 amended, extending existing license for 1 yr of possession only, during present nonoperational period of LLEN.D M. Uranium Recovery Field Office 83/04/22 Uranium Recovery Field Office 5pp 18457 311

DOCKET 40-8763 ALUCHEM, INC , READING, DH

- 8309180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses from U Fuel Licensing Branch to Region III PAGE.R O Uranium Fuel Licensing Branch 83/05/05 HIND, J A Region 3, Office of Director ip 18505 075
- 8305180834 Notifies that official files for License SMB-1375 transferred to Region III as of 830401.as part of regional licensing program M/o stated FR notice PAGE, R G Uranium Fuel Licensing Branch 83/05/05 ZAPLETAL, R P ALUCHEM, Inc. 1p 18506-010
- DOCKET 40-8748 KERR-MCGEE NUCLEAR CORP , DKLAHOMA CITY, DK
- B305i30337 Submits review of licensee Quarterly Repts for 1982 re Q Sand R&D Im Situ Project No problems or significant data trends identified Reported data within applicable limits GILLEN.D M Uranium Recovery Field Office 83/04/12 Uranium Recovery Field Office 4pp 18443 353
- 8305260404 Advises that gamma survey data confirmed O-sand survey points, except prognant surge tank area, are near background levels FREEMAN.M D Kerr-McGee Nuclear Corp 83/05/10 QILLEN.D Uranium Recovery Field Office ip 18647 185

DOCKET 40-8783 URANERZ USA: INC , CASPER, WY

- 8305060363 Issues Amend 4 to License SUA-1401, deleting Conditions 13 & 36 & revising Conditions 14, 16, 17 & 19 re well completion data, upper control limits & integrity tests SMITH, R D Uranium Recovery Field Office 83/03/25 Uraner; UBA, Inc 3pp 1833 093
- --8305060369 Safety evaluation supporting Amend 4 to License SUA-1401 YDUNG,Y A . RDSS,F W . LINEHAN,J J Uranium Recovery Field Office 83/03/25 9pp 18353 100
- 8305130330 Advises that no further licensing action necessary for approval of surface discharge from evaporation pends Intent of License Condition 49 does not apply SMITH.R D Uranium Recovery Field Office 83/04/15 Uraner: USA. Inc. 1p 18443 360
- --B305i30333 Advises that no amend necessary to allow licensee to discharge water from evaporation ponds License Condition 49 does not apply YOUNG, Y A. LYNEMAN, J. J. Uranium Recovery Field Office 83/04/13 Uranium Recovery Field Office 2pp 18443 361
- DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX
- 8305160228 Application for amend to License 8UA-1400 adjusting technical monitoring requirements during stability to permit nontechnical persons to perform nontechnical inspace FELIZA: M 8 Uranium Resources, Inc. 83/04/08 LINEMAN.J J Uranium Recovery Field Office. 3pp. 18471 348
- 8309280275 Informs that 8 McArt meets license requirements & qualifications for radiation safety technician HEBIROOK.K B , LINEHAN.J J Uranium Recovery Field Office 83/04/28 Uranium Recovery Field Office 1p 18995 331
- 8305250279 Comments on 821014 decommissioning plan for North Platte facility Info re locations & depths for soil samples.grid spacing used for soil survey & means of stabilizing sand & sludge left in evaporation ponds requested HESTBROOK, K I , LINEHAN, J J Uranium Recovery Field Office 83/04/29 Uranium Recovery Field Office 3pp 18595 328
- 8305280270 Submits review of U Resources, Inc 821208 response to notice of violation from insp on 821004-07 Corrective actions acceptable
 - acceptable
 JOHNSON T L. LINEHAN, J Uranium Recovery F(eld Office 83/05/05
 Uranium Recovery Field Office fp 18595 332
- 8305250593 Comments on Third & Fourth Quarter 1982 repts & preoperational monitoring info for License 8UA-1400 Review of frequency of post-excursion confirmatory samples & consideration of calcium excursion problem recommended JOHNSON, T.L., LINEHAN, J. Uranium Recovery Field Office 83/05/05 Uranium Recovery Field Office 93pg 18974 328

1 11 6

DOCKET 40-8829 WYOMING FUEL CO , LAKEWOOD, CO

830513028B Forwards administrative order issued by State of NE to Myoming Fuel Co & questions & statements to be addressed for underground injection control permit application MALL: R B Nebraska: State of 83/04/18 LINEMAN, J Uranium Recovery Field Office 12pp. 18457 353

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 6305230670 Advises that state can choose to offset or substitute compensatory planning measures in Iteu of local level emergency plan per cited conditions NUREG-0654-FEMA-REP-1. Rev 1 stds would place heavy resource burden on state OIUFFRIDA, L O Federal Emergency Management Agency 83/04/18 PALLADINO,N J. Commissioners ip 18542 329, 24X Fiche 50-003,83/04/18,8305230670
- --8305230676 Seeks clarification of issue to FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan PALLADIND, N J Commissioners 83/03/30 OIUFFRIDA, L Q Faderal Emergency Management Agency 2pp 18542-330 24X Fiche 50-003,83/04/18,8305230670
- 830502054B Responds to 830107 ltr re Rev 4 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable VAROA:S A Operating Reactors Branch 1 83/04/20 Consolidated Edison Co of New York, Inc. ip 18284 237 24X Fiche 50-003,83/04/20,8305020548
- 8305020575 Responds to 830128 ltr re Rev 9 to safeguards contingency plan Changet consistent w/10CFR50 54(p) & acceptable VAROA.8 A Operating Reactors Branch 1 83/04/20 0'TDQLE, J D Consolidated Edison Co. of New York, Inc. 1p 18284 232 24X Fiche 50-003,83/04/20,8305020575
- 8305040235 Releases public version of rev to amergency plan & emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch. ip. 18364 188 24X Fiche 50-003,83/04/22,8305040235
- --8303040242 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/04/07, HAYNES, R. C. Region 1, Deffice of Director 2pp 18364 190 24X Fiche 50-003,83/04/22,8305040235
- --B305040247 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IF-1045, "Activation of Alternate Emergency Operations Facility"

 LIEBLER, O H Consolidated Edison Co of New York, Inc B3/03/08
 Office of Nuclear Reactor Regulation, Director 2pp 18364 192
 24X Fichs 50-003.B3/04/R2.B305040235
- --8305040249 Public version of rev to Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility."

 * Consolidated Edison Co. of New York, Inc. 83/03/08 18pp 18364 194 24X Fiche. 30-003; 83/04/22, 8305040235
- --8305040254 Public version of revised emergency plan. **Consolidated Edison Co. of New York: Inc. 83/03/07 49pp. 18364 212 24X Fiche 50-003.83/04/22,8305040235
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for Dis & holders of CPs re clarification of access to control procedures for iau enforcement visits Bvc list encl
 EISENHUT, D Q, Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18340,095 24X
 Fichs 50-000,83/05/11,8305110034.

P Operating license stage documents & correspondence

8305020455 Opneric Ltr 83-i9 to all power reactor & testing licensees re new procedures for providing public notice concerning isquance of amends to OLs Svc list encl EISENHUT, D © Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441:120 24% F(che 50-000,83/05/02,8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT,D Q Division of Licensing 83/05/09 (Edison Co of New York, Inc. 16pp 18627 153 24x Fiche 50-000,83/05/09,8305090659

G Inspection reports, IE Bulletins & correspondence

- 9212060395 IE Info Notice 83-14, "Dewatered Spont Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list
- enci TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21: "Defective Emergency Use Respirator " 3030-0021 It into Notice 03-c11 Derective Limity of Street Section 19 Section
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 303040023 IL ATTO NO. 100 NO.
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list encl Bensing Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Bteam Generators at PMRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York. Inc 115pp 18382 047 24X Fiche 30-000.83/04/28.8303040026
- B303040027 IE Info Notice B3-25, "Standby Oas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- B30304002B IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svt list encl JCRDAN,E L Division of Emergency Preparadness & Engineering Response (Post B30103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 30-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Responso to Events Concerning Deliberate Acts Directed Against Plant Equipment * Svc list encl Concerning Designment Res Services 1. Services Res Services Res Services Res Services Res Regimeering Sequipment 8 Box list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp, 18382 282 24X Fiche 50-000.83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Byo list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 30-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " SVc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl. JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11. Consolidated Edison Co. of New York, Inc. 114pp 18524.003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program" SUC list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche, 50-000, 83/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp, 18447 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

- 8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & "Annual Radiological Environ Operating Rept, 1982," per App B O'TOOLE, J D Consolidated Edison Co of New York, Inc ALLAN, J M Region 1, Office of Director 2pp 18392 Fiche 50-003,83/05/02,8305110302 83/05/02 2pp 18392 221
- --8305i10307 "Annual Environ Protection Plan Rept for 1982 " * Consolidated Edison Co of New York, Inc 83 18392 223 24X Fiche 50-003.83/05/02.8305110302 83/05/02 8pp
- --8305110310 "Annual Radiological Environ Operating Rept.1982"

 * Consolidated Edison Co. of New York, Inc. 83/05/02 112pp
 18392 231 24X Fiche 50-003,83/05/02,8305110302

T Hearing transcripts on non-antitrust matters

- 8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR, per 10CFR9 Commission determination statement encl CHILK.8 J Office of the Secretary of the Commission 83/05/18 Public Document Branch 2pp 18393 063 24X Fiche 50-003.83/05/18,
- --8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington.DC * Commissioners 82/12/22 15pp 18593 065 24X Fichs 50-003.83/05/18.8305240566
- ---8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington.DC
 4 Commissioners 82/12/22 59pp 18593 082 24X Fiche 50-003, 83/05/18, 8305240564

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans

- 8303030335 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies

 APPERIELLO, C J Region 3, Office of Director 83/04/29 REED, C

 Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010, 83/04/29,
- --8305030348 Notice of deficiencies from insp on 830103-07 Public info brothures not distributed from Apr 1981 Dec 1982 & emergency action levels not reviewed w/state & local govt emergency action levels not reviewed w/state & local govt since 810401 * Region 3, Office of Director 83/04/29 2pp 18297 139 24X Fiche 50-010,83/04/29,8305030336
- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits SVc list entl EISENHUT, D 0 Division of Licensing B3/05/11 (Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000, 83/05/11, 8305110024 Consolidated
- 8305120116 Advises that onsite & offsite emergency preparedness adequate per iOCFR3D.App E Emergency plans upgraded per NUREO-0737, Item III A 2 1 Item complete CRUTCHFIELD.D Operating Reactors Branch 5 B3/05/11 FARRAR.D.L. Commonwealth Edison Co 3pp 18423 040 24X Fithe 50-010.83/05/11. 830512011A

J. Insurance & indomnity information

B305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Dresden Unit 1 & Endorsement 63 to NELIA Policy NF-201 & Endorsement 93 to MAELU Policy MF-44 for Zion Unit 1 W/o encl Quad Cities endorsements OBTER. J Commonwealth Edison Co 83/05/13 SALTZMAN. J Assistant Director for State & Licensea Relations 5pp 18537 174 24X Fiche 50-000,83/05/13,8305230500

P Operating license stage documents & correspondence

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT.D G Division of Licensing 83/05/02 Const Edison to of New York, Inc 30pp 18441 120 24X Fiche, 50-000, 83/05/02, 8305020455

- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list entl EISENMUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York Inc 16pp 18627 153 24X Fiche 50-000:83/05/09,8305090659
- Q Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ton Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Cansolidated Edison Co of New York, Inc 112pp 18308 319 24X Fichs. 30-000,83/03/21,8212040385
- 9305020467 Forwards IE Insp Repts 50-010/83-06.50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted STREETER, J F Region 3, Office of Director 83/04/13 REED, C Commonwealth Edison Co. 2pp 18283 073 24X Fiche 50-010.83/04/13, 8305020467
- --8305020480 IE Insp Repts 50-010/83-06.50-237/83-07 & 50-247/83-06 on 830203-0315 No noncompliance noted Major areas inspected operational safety, maint, surveillance, licensee events, plant trips, refueling activities & refueling surveillance TONGUE.T M. JURDAN M J. STASEK, S. Region 3. Office of Director 83/04/12 16pp 18283 075 24X Fiche 50-010.83/04/13.8305020467.
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc 11st encl
 JDRDAN/E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fichs 50-000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22. "BWR Safety/Relief Valve Failures "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383.089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enci JORDAM E L Division of Emergency Pregaredness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 11999 18381 271 24X Fiche 50-000,83/04/25,8303040025
- 8305020100 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-010/83-05, 50-237/83-03 & 50-247/83-04 SHAFER.W D Region 3, Office of Director 83/04/25 REED, C Commonwealth Edison Co ip 18278 243 24X Fiche 50-010,83/04/25, 8303020100
- --830502010å Responds to NRC 830304 ltr re violations noted in 1E Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 Corrective actions Amend 71 reissued & incorporated into Tech Specs Corporate 9A dept will sudit accounting & followup sys FARRAR.D L Commonwealth Edison Co 83/03/30 KEPPLER.J.O Region 3, Office of Director 3pp 18278 244 24X Fiche 50-010.83/04/25,8305020100
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs." Svc list encl.

 JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28. Consolidated Edison Co. of New York. Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026.
- 8303040027 IE Info Notice 83-25. "Standby Oss Treatment Bys Heater High Temp Trip Setpoint Adjustment." Svc list ancl JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103). 93/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fichs 50-000,83/04/28,8303040027
- 8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01; 50-237/83-01 t 50-249/83-01 on 830208 & farwards notice of deficiencies PAPERIELLO.C.J Region 3, Office of Director 83/04/29 REED.C Commonwealth Edison Co 2pp 18297 137 24X Fichs 50-010,83/04/29; 81050-0104
- --8305030348 Notice of deficiencies from insp on 830103-07. Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed W/state & local govt since 810401 * Region 3. Office of Director 83/04/29. 2pp. 18297/139 24X Fiche 50-010.83/04/29.8305030334

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8305100181 Ack receipt of B30411 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 B4HFER, U. Region 3, Office of Director 93/05/03 REED, C Commonwealth Edison Co ip. 18374:318 24X Fiche 50-010, 83/05/03, 8203100184
- ---8305100190 Responds to NRC 830311 ltr re deficiencies noted in IE Insp Repts 50-010/82-17.50-237/82-24 & 50-249/82-24 Corrective actions written agreement, EPIP200-11 re PMF for Units 2 & 3 between Corps of Engineers & util to be revised RYBAK, B Commonwealth Edison Co 83/04/11 KEPPLER, J. Q. Region 3, Office of Director 4pp 18374 319 24X Fiche 50-010, 83/05/03,8305100181
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Delifierate Acts Directed Against Plant Equipment " Svc list encl UDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001. 24X Fiche 50-000,83/05/04,8303040031,
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523:248 24X Fiche 50-000,83/05/06,8303040033.
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524-003 24X Fiche 50-000,83/05/11,8303040034.
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl.
 JURDAN.E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp. 18697 009 24X Fiche 30-000,83/05/19,8303040040
- 8303040046 TE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647-007 24X Fiche 50-000,83/05/26,8303040046.
- BOCKET 30-20 MABBACHUSETTB INST OF TECH RES REACTOR
- 8305160043 RD 50-20/1983-1 on 830419, mein intake valve closed & could not be reopened Caused by piston rod rupture near rod eye. leaving valve in closed position Defective hydraulic cylinder shaft replaced , KHOK, K., CLARK, L. Massachusetts Institute of Technology 83/04/29. ALIAN, J M. KINNEY, H. Region i, Office of Director 6pp. 18444 001 24X Fiche, 50-020, 83/04/29, 8305160043.
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

 F Sacurity, medical, emergency & fire protection plans
- B305060172 Notifies that amergency plan exercise planned for B30406. Bchedule coordinated w/plume emergency planning zone states & FEMA, Region I RAY, J A Yankee Atomic Electric Co B2/12/16 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18345 224. 24X Fichs. 50-029, B2/12/16, B305060172
- 8305060215 Forwards objectives for 830404 emergency plan exercise.per util 830113 & NRC 830202 ltms
 KAY, J A Yankee Atomic Electric Co 83/02/08 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18345.095 24X
 Fiche.50-029,83/02/08,8305040215

- 8305110010 Forwards "'Emergency Offsite Facility Out' Emergency Exercise & Evaluation Plan," for 1983 KAY, J A Yankee Atomic Electric Co 83/03/15 HAYNES, R C Region 1, Office of Director 1p 18409 240 24X Fiche 50-029,83/03/15, 8305110010
- 8305110049 Comments on implementation of NUREO-0737, Item III A 2 1.
 "Emergency Preparedness Upgrade Emergency Pians to App E.
 100FR50 " Onsite & offsite emergency preparedness adequate
 CRUTCHFIELD.D Operating Reactors Branch 5 83/05/10 KAY.J A
 Yankes Atomic Electric Co 3pp 18409 014 24x
 Fichs 50-027.83/05/10.8305110049
- ### 8305240227 Forwards IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted | MARTIN, T T Division of Engineering & Technical Programs | 83/05/10 | HEIDER, L H | Yankee Atomic Electric Co | 2pp | 18548 315 | 24X | Fiche 50-029, 83/05/10, 8305240227
- --8305240232 IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted Major areas inspected, emergency preparedness & observation of Phase I of annual exercise performed on 830406 MILLER, M T , CROCKER, H W Division of Engineering & Technical Programs 83/05/06 5pp 18548 317 24X Fiche 50-029,83/05/10,8305240227
- B305110034 Generic Ltr B3-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list ancl EIBENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- 8305250274 Advises that rev to security plan dtd 830209 consistent w/10CFR30 54(p) & acceptable Rev will be withheld (ref 10CFR73 21 & 9 12)
 ALLAN.J M Region 1. Diffice of Director 83/05/18 HEIDER, L H Yankae Atomic Electric Co 3pp 18572 298 24X
 Fichs 30-029,83/05/18,8305250274
- J Insurance & indemnity information
- 8303120200 Forwards Endorsement 104 to NELIA Policy NF-76 & Endorsement 86 to MAELU Policy MF-26 SINIBIJ, M Harsh & McLennan, Inc 93/05/03 BALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 18427 355 24X Fichs 30-027, 83/05/03, 8305120200
- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 8305180664 Summary of ACRS 830223 meeting w/Bubcommittee on SEP in Washington: DC to review facility integrated safety assessment # ACRS Advisory Committee on Reactor Safeguards 83/04/07 ACRS Advisory Committee on Reactor Safeguards 18pp. 18502 327 24X Fichs 50-027,83/04/07,8305180664
- P Operating license stage documents & correspondence
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of Amends to OLs Bvc list encl EISENHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Ficha. 50-000,83/05/02,8305020455.
- 8305170459 Forwards proposed schedule for resolution of SEP integrated assessment open items identified in NUREO-0825. "Integrated Plant Bafety Assessment "NRC will be informed immediately of any schedular difficulties.

 KAY. J. A Yankee Atomic Electric Co 93/05/02 CRUYCHFIELD. D Operating Reactors Branch 5 5pp. 18469 321 24X Fiche 50-029, 83/05/02. 8305170459.
- 8305040526 Advises that util action taken per Amend 79 to License DPR-3 re disposal of high level spent fuel through DOE contract & Oeneric Ltr B3-07 re Nuclear Waste Policy Act of 1982, considered complete.
 CRUTCHFIELD.D Depreting Reactors Branch 5, 83/05/03, KAY, J A Yankee Atomic Electric Co. 2pp. 18321 242 24X Fiche. 30-029,83/05/03,8305040526.

- 8305100228 Submits add1 info re environ qualification of safety-related electrical equipment to suppl 830201 response, providing justification for continued operation for Category 1 B.11 A & II B items

 KAY, J A Yankee Atomic Electric Co 83/05/06 EISENHUT, D O Division of Licensing 3pp 18374 131 24x Fiche 30-029, 83/05/06, 9305100228
- 8305110214 Summary of 830426 meeting w/util & Bechtel re licenses request for relief from installation of reactor vessel water level indication sys Slide presentations encl LYONG, J E Operating Reactors Branch 5 58pp 18406 342 24X Fiche 50-029,83/05/06.833110314
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list enci
 E18ENHUT, D Q Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659
- B305240358 Responds to Generic Ltr 83-10A re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps "
 Util will perform plant-specific study applying RELAPSYA Cade described in 830411 itr Three-phase program described MEIDER, L H Yankee Atomic Ejectric Co B3/05/13 EISENHUT, D G Division of Licensing 3pp 18575 101 24X Fiche. 50-027, 83/05/13, 8305240358
- 8305240364 Forwards updated list on environ qualification of safety-related electrical equipment noting equipment added & deleted since previous submittal
 KAY.J A Yankee Atomic Electric Co 83/05/20 EIBENHUT.D O
 Division of Licensing 6pp 18575-095 24X Fiche 50-027,83/05/20.8305240364
- 8305240490 Forwards revised final SER for SEP Topics VI-2 D. "Mass & Energy Release for Possible Pipe Breaks Inside Containment" & VI-3, "Containment Pressure & Heat Removal Capability "CRUTCHFIELD,D Operating Reactors Branch 3 83/05/23 KAY, J A Yankes Atomic Electric Co 3Bpp 18572 030 24% Fiche 50-029,83/05/23,8305240490
- G Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112p 18308,319 24X Fiche 50-000.83/03/21,8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Byc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valva Failures " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs " Byr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28, Consolidated Edison Co of New York, Inc. 115pp. 18382 047 24x Fiche 30-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Etendby Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN, E L Division of Emergency Preparefness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382-165 24X Fiche. 50-000, 83/04/28, 8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.

- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Swe list encl JORDANJE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Convolidated Edison Co of New York Inc 112pp 18382 282 24X Fichs 50-000.83/05/04,8303040030
- 8303040031 IE Info Natice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 30-000,83/05/04,8303040031
- 8303040033 [E Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305240227 Forwards IE lnsp Rept 50-029/83-05 on 830405-08 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/05/10 HEIDER.L H Yantes Atomic Electric Co 2pp 18548 315 24X Fiche 50-029,83/05/10,8305240227
- --8305240232 IE Insp Rept 50-027/83-05 on 830405-08 No noncompliance noted Major areas inspected emergency preparedness & observation of Phase I of annual exercise performed on 830405 MILLER: N T , CROCKER: H W Division of Engineering & Technical Programs 83/03/06 5pp 18548 317 24X Fiche 50-027,83/05/10,8305240227.
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11,8303040034
- 8305190017 Requests response to Required Actions 2,3,4 & 5 of IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers " Response required within 10 days of receipt of request STAROSTECKI.R Division of Project & Resident Programs 83/05/11 MEIDER, H Yankee Atomic Electric Co 2pp 18501 359 24X Fiche 30-029,83/05/11,8305190017
- 8305250427 Forwards 1E Insp Rept 50-029/83-04 on 830208-0418 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs. 83/05/11 HEIDER, L H Yankee Atomic Electric Co 2pp 18585 245 24X Fichs 50-029,83/05/11,8305250427
- --8303250431 IE Insp Rept 50-029/83-04 on 830208-0418 No noncompliance noted Major areas inspected actions on previous insp items, operational safety verification reviews, plant maint observation & plant surveillance observation COLLINS, 8 J , GALLO, R M Region 1, Office of Director 83/05/09 169p 18583 247 24X Fiche 50-029,83/05/11,8305280427
- 8303040040 IE info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDANNE L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303040046 IE Info Notice B3-33: "Nonrepresentative Sampling of Contaminated G11," Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). B3/05/26 Consolidated Edison Co of New
 York, Inc 114pp 18647 007 24% Fiche 50-000,83/03/26,8303040046.
- S Reportable occurrences. LERs & related correspondence
- B305030570 Forwards LER 83-012/01T-0. AUTIO, H A Yankee Atomic Electric Co 83/04/19 ALLAN, J A Region 1. Office of Director Ip 18305:360 24% Fiche 50-029, B3/04/19, B305030590
- --8305030597 LER 83-012/01T-0 on 830405, while performing hot leak insp. bonnet stud found failed on PR-MDV-191. Caused by leakage from globs valve 90-20321AB Valve replaced w/gate valve 8-31532-12-X FRENCH, L D Yankee Atomic Electric Co 83/04/19 Region 1, Office of Director 2pp 18305 361, 24X Fiche: 50-027; 83/04/19, 83050303990
- 8305050263 Forwards LER 83-013/017-0 AUTIO: H A Yankes Atomic Electric Co. 83/04/27 ALLAN, J Region 1: Office of Director 1p 18338,041 24X Fiche 50-029,83/04/27, 8305050263

- --8305050268 LER 83-013/01T-0 on B30413, review of design basis for low temp overpressure protection indicated that events in original basis could exceed pressure restrictions Caused by personnel error Procedures being revised RICE.D A Yankes Atomic Electric Co B3/04/27 Region 1, Office of Director 2pp 18338-042 24X Fichs 50-029,83/04/27,8305050263
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8305170495 Ack receipt of 830225 & 0413 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept S0-054/83-03 Current method of conducting monthly channel checks of coolant flow in violation of Tech Spacs STAROSTECKI.R Division of Project & Resident Programs 83/05/10 MCG0VERN.J J Union Carbide Corp 2pp 18470 036 24X Fichs 50-054, B3/05/10, 8305170495
- --B305170504 Supplemental response to NRC 830210 ltr re violations noted in IE Insp Rept 50-004/83-01 Corrective actions Tech Specs define three channel surveillance insps RUZICKA.W 0 Union Carbide Corp 83/04/13 KEIMIO,R R Region 1. Office of Director 4pp 18470 038 24X Fiche 50-054, 83/05/10.8305170495.
- --8305170508 Responds to NRC ltr re violations noted in IE Insp Rept 50-054/83-01. Corrective actions: surveillance requirements for monthly channel test of coolant flow met during period 820803-0930.

 RVZICKA: W G. Union Carbide Corp 83/02/25 STAROBIECKI, R Division of Project & Resident Programs 3pp 18470 042 24X Fiche 50-054, 83/05/10, 8305170495
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 9305020322 Forwards IE Insp Rept 50-057/83-01 on 830214-17 & notices of violation & deviation BTAROBTECKI.R Division of Project & Resident Programs. 83/04/18. HEXRY, L. Q. New York, State Univ. of, Buffelo, 2pp 18277.117 24X Fiche, 50-057/83/04/18, 8305020322
- --8305020324 Notice of violation from insp on 830214-17, a Region 1. Office of Director 83/04/18 2pp 18277-119, 24X Fiche 50-057,83/04/18,8305020322,
- --8305020327 Nutice of deviation from insp on 830214-17 ** Region 1, Office of Director. 83/04/18 1p 18277 121 24X Fiche 50-057.83/04/18.8305020322,
- --8305020332 IE Insp Rept 50-057/B3-01 on B30214-17 Noncompliance noted failure to implement instruction in radiation protection for security force, failure to review safety & nuclear safety committee did not meet twice per yr since Sept 1981 KINNEY.H W . ELBABSER.T C Region 1, Office of Director B3/03/28 12pp. 18277:122 24% Fiche 50-057,83/04/18,8305020322
- B. Reportable occurrences, LERs & related correspondence
- B305100252 Forwards last page inadvertently omitted from recent submittal re accident analysis of HX leak, HENRY.L G. New York, State Univ of Buffalo B3/05/06, YHOMAS.C O Standardization & Special Projects Branch. 2pp. 18373 276. 24X Fiche 50-057.83/05/06.8305100252
- DGCKET 50-62 UNIV OF VIROINIA RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- B305270316 Forwards IE Insp Rept 50-062/B3-01 on 830215-18 No noncompliance noted.

 VERRELLI, D M Division of Project & Resident Programs. B3/03/23 BRENIZER, J S Virginia, Univ. of, Charlottesville, VA 1p. 18642, 210 24X Fiche, 50-062, 83/03/23, 8305270316
- --8305270325 IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted Major areas inspected.radiation protection PERRY.W.W. BARR.K P Region 2. Office of Director 83/03/21. 6pp. 18642-211 24X Fiche 50-062/83/03/29,8305270316

G Inspection reports, IE Bulletins & correspondence

- 8305270316 Forwards IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/23 BRENIZER.J S Virginia, Univ of, Charlottesville, VA 1p 18442 210 244 Fiche 50-062,83/03/23,8305270316
- --8305270325 IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted Major areas inspected radiation protection PEGRY. H W. BARR. K P. Region 2, Office of Director 83/03/21 App. 18642 211 24X Fiche 50-062,83/03/23,8305270316
- 8305270196 Ack receipt of 830414 ltr re IE Insp Rept 50-062/83-01 & omittance of asterisk by name indicating attendance at exit masting Ltr will be filed w/rept to correct error NRC techniques for measuring radioactivity discussed VERRELLI.D M Division of Project & Resident Programs 83/05/io BRENIZER.J 9 Virginia, Univ of, Charlottesville, VA ip 18637 232 24X Fiche 50-062,83/05/IO.8305270196
- --B305270226 Ack receipt of B30323 itr & IE Insp Rept 50-062/B3-01
 Asterisk next to directors name indicating meeting
 attendance omitted NRC techniques for measuring
 radioactivity in water samples requested
 BRENIZER.J B Virginia. Univ of. Charlottesville, VA VERRELLI,D M Division of Project & Resident Programs 1p
 18637 233 24X Fiche 50-062, B3/05/10.8305270196

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

- 8305120057 Forwards Amend 13 to License TR-1.sefety evaluation & notice of issuance & availability Amend deletes physical security requirements of iOCFR93 34c & IOCFR73
 THOMAB.C.O Standardization & Special Projects Branch 83/05/03
 DARMITZRL.R.H. Qeneral Electric Co 2pp 18443'234 24X
 Fiche 50-070.83/05/03.8305120057
- --8305120067 Amend 13 to License TR-1, deleting physical security requirements of 100FR50 34c & 100FR73 THOMAS,C D Standardization & Special Projects Branch. 83/05/03 2pp 18443 236 24X Fiche 50-070,83/05/03,8305120057
- --8305120072 Bafety evaluation supporting Amend 13 to License TR-i # NRC - No Detailed Affiliation Given 83/05/03 2pp 18443 23B 24X Fiche 50-070,83/05/03,8305120057
- --B305120078 Notice of issuance & availability of Amend 13 to License TR-1

 SCALETTI, D C Standardization & Special Projects Branch

 B3/05/03. 2pp 18443 240 24X Fiche 50-070, B3/05/03, B305120057

G. Adjudicatory correspondence

- 8305030532 Order extending time until 830603 for Commission to act to review ALAB-720
 CHILK.S.J. Office of the Secretary of the Commission 83/04/29
 Commissioners ip 18275 328 24X Fiche 50-070.83/04/29, 8305030532
- 8305130035 Memorandum & order extending OE time to respond to ABLB 830408 inquiry into license renewal application until 15 days following svc of Commission decision whether to review ALAB-720 FRYE.J.H Atomic Safety and Licensing Board Panel 83/05/12 General Electric Co. 2pp 18436 315 24X Fichs 50-070,83/05/12,8305130035

P Operating license stage documents & correspondence

- 8305120057 Forwards Amend 13 to License TR-1, safety evaluation & notice of issuance & availability Amend deletes physical security requirements of iOCFR90, 34c & iOCFR93.
 THOMAS.C O. Standardization & Special Projects Branch 83/05/03.
 DARMITZEL.R.W. General Electric Co 2pp 18443:234, 24X
 Fiche. 50-070, 83/05/03, 8305120037
- --B305120067 Amend 13 to License TR-1, deleting physical security requirements of 100FR50.34c & 100FR73 THOMAB.C.O. Btandardization & Special Projects Branch. B3/05/03 2pp. 18443:236. 24X Fiche*50-070.B3/05/03.B305120057
- --8305120072 Bafety evaluation supporting Amend 13 to License TR-1 * NRC - No Detailed Affiliation Given B3/05/03 2pp. 18443 R3B R4X Fiche. 50-070, 83/05/03, 8305120057

- ---B305120078 Notice of issuance & availability of Amend 13 to License TR-1
 SCALETTI,D C Standardization & Special Projects Branch
 B3/05/03 2pp 18443 240 24% Fiche 50-070, 83/05/03, 8305120057
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR
- P Operating license stage documents & correspondence
- B3051200B9 Forwards Amend 15 to License R-33 & safety evaluation Amend reduces possession limits for unirradiated SNM to 4 kg U-235 as fuel for operation
 THOMAB.C O Standardization & Special Projects Branch 83/05/03 DARMITZEL.R W General Electric Co 2pp 18443 186 24X Fiche 50-073.83/05/03.8305120089
- --8305120096 Amend 15 to License R-33, reducing possession limits for unimpadiated SNM to 4 kg U-235 as fuel for operation THOMAS, C O Standardization & Special Projects Branch 83/05/03 2pp 18443 188 24x Fiche 50-073,83/05/03.8305120089
- --8303120100 Safety evaluation supporting Amend 15 to License R-33
 * Standardization & Special Projects Branch 83/05/03 1p
 18443 170 24X Fiche 50-073.83/05/03.8305120089

DOCKET 50-89 GENERAL ATOMIC CO

- J Insurance & indemnity information
- 8303160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAELU Policy MF-39 ASHBURN, D J Marsh & McLennan, Inc 83/05/06 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18450 353 24X Fiche 50-089, 83/05/06,8305160084
- Q Inspection reports, IE Bullatins & correspondence
- 8305170427 Forwards IE Insp Repts 50-089/83-01 & 50-143/83-01 on 830404-08 & notice of violation 8TERNEERG.D M Region 5, Office of Director 83/04/25 PARKER, J W 9A Technologies, Inc / General Atomic Co 2pp 18471 237 24X Fiche 50-089, 83/04/25, 8305170429
- --8305170432 Notice of violation from insp on 830404-08 KIRSCH D F Region 5, Office of Director 83/04/25 in 18471 239 24% Fiche 50-089,83/04/25,8305170429
- --8305170437 IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08 Noncompliance noted failure to conspicuously post high radiation area during performance of reactor experiment JOHNSON.P H, KIRSCH.D F Region 5, Office of Director 83/04/22 5pp 18471 240 24X Fiche 50-089,83/04/25.8305170429

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

- @ Inspection reports, IE Bulletins & correspondence
- 8305050223 Forwards IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23 & notice of violation BTARGSTECKI.R Division of Project & Resident Programs 83/04/21 STREETT, W B Cornell Univ 2pp 18338 096 24X Fiche 50-097,83/04/21,8305050223
- --8305050230 Notice of vialation from insp on 830321-23 * Region 1, Office of Director 83/04/21 ip 18338 098 24X Fiche 50-097,83/04/21,8305050223
- --B305050236 IE Insp Repts 50-097/B3-01 & 50-157/B3-01 on B303≥1-23
 Noncompliance noted failure of ward leb safety committee to
 perform annual audits of operations since 1980 & failure of
 committee to meet quarterly in 1982
 KINNEY,M W , ELSASSER,T C Region i, Office of Director
 83/04/18 App 18338 099, 24X Fiche 50-097,83/04/21,8305030223

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8303270465 Forwards IE Insp Rept 50-111/83-01 on B30405-06 No noncompliance noted VERRELLID, M. Division of Project & Resident Programs B3/04/22 CDCKRELLIR 9 North Carolina State Univ 1p 18644 154 24X Fiche 50-111/83/04/22

--8305270469 IE Insp Rept 50-iii/83-01 on 930405-04 No noncompliance noted Major areas inspected radiation protection associated w/termination of R-3 reactor literase KAHLEJ B Region 2, Office of Director BARR.K P Division of Project & Resident Programs B3/04/21 3pp 18444 155 24X Fichs 50-111,83/04/22.8305270465

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR
H General correspondence

8305250478 Informs of C Jenson appointment as director of facility EGLE, D.H. Dkishoma, Univ of 83/05/16 MILLER, J. Division of Licensing Ip 18589-032 24X Fiche 50-112,83/05/16,8305250478

P Operating license stage documents & correspondence

B305170114 Notification of B30517-19 meetings w/Univ of OK & LASL on site to review & evaluate reactor facility in connection w/application for UL renewal
BERNARD.H Standardization & Special Projects Branch B3/05/12
THOMAS.C 0 Standardization & Special Projects Branch 2pp
18495-359 24X Fichs 50-112,83/05/12,8305170114

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR
P Operating litense stage documents & correspondence

8305310006 Advises that MK Straka hired as reactor manager, effective 830307 80LON, A E Missouri, Univ of, Rolla 83/05/23 CARTER, R E

BOLON, A E Missouri, Univ of, Rolla 83/05/23 CARTER, R E Standard: Iation & Special Projects Branch 2pp 18653 238, 24X Fiche 50-123,83/05/23,8305310006

R Periodic operating reports & related correspondence

8305030375 "Progress Rept.Univ of MO-Rolla Apr 1982 - Mar 1983 " BOLON.A E . BTRAKA.H Missouri. Univ of, Rolla B3/03/31 137pp 18292 179 24X Fiche 50-123,83/03/31,8305030375

DOCKET 30-128 TEXAS ALM UNIV RESEARCH REACTOR
P Operating license stage documents & correspondence

8305120524 Forwards Amend 9 to License R-83, safety evaluation.EIA & notice of issuance/negative declaration Amend renews OL for 20 yes from date of issuance W/O SER EIGENRUT.D 0 Division of Licensing 83/03/30 ERDMAN,C A Texas A&M Univ . College Station. TX 3pp 18442 001 24X Fiche 50-128,83/03/30.8305120524

--8305120532 Amend 9 to License R-83 renewing OL for 20 yrs from date of lasuance EISENHUT.D 0 Division of Licensing 83/03/30 49pp 18442 004 24X Fiche 50-128,83/03/30,8305120524

--8305120537 EIA supporting Amend 9 to Litense R-83 * NRC - No Detailed Affiliation Given 83/03/30 App 18442 071 24X Fiche 50-128,83/03/30,8305120524

--8305120544 Notice of issuance/negative declaration for Amend 9 to License R-B3 EISENHUT,D 0 Division of Licensing 83/03/30 2pp 18442 077 24% Fiche 50-128,83/03/30,8305120524

8305050252 Forwards "Completion & Results of Phase | of NSCR Post-Damage Pulse Test Program for Full FLIF TRIOA Core "FELTZ,D E Texas ABM Univ, College Station, TX 83/04/27 HOMAS.c O. Standarfization & Special Projects Branch ip 1833B-022 24X Fiche 50-128,83/04/29,8305050252.

--8305050257 "Completion & Results of Phase I of NSCR Post-Damage Pulse Test Program for Full FLIP TRIGA Core " JENNINGS: F Teras Ald Univ , College Station, TX, 83/04/13 16pp 18338 023 24X Fiche 50-128,83/04/29,8305050252.

G. Inspection reports, 1E Bulletins & correspondence

B305090066 Ack receipt of B30412 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-128/82-03 MADSEN,O L Region 4. Office of Director B3/05/04 PORTER.W.A. Texas A&M Univ , College Station, TX. ip 18363 331, 24X Fiche.50-128,83/03/04,8305090066

--8305090073 Responds to NRC 830316 ltr re violations noted in IE Insp Rept 5D-128/82-03 Corrective actions training sessions conducted for reactor operations personnel to demonstrate proper preparation of ice bath PORTER.W A Teras A&M Univ . College Station, TX 83/04/12 HADSEN.G L Region 4. Office of Director 8pp 18363 332 24X Fiche 50-128,83/05/04,8305090066

R Periodic operating reports & related correspondence

8305250528 Ninsteenth Prograss Rept of TX A&M Univ Nuclear Science Ctr 1982 W/830516 ltr * Texas A&M Univ. College Station. TX 83/04/30 THOMAS.C Standardization & Special Projects Branch 88pp 18587 347 24X Fichs 50-128.83/04/30,8305250528

DOCKET 50-129 HEST VIROINIA UNIV RESEARCH REACTOR
H Decommissioning Stage Documents & Correspondence

8305240308 Requests termination of License R-58 before GL Blackshaw departure on 830430 Facility dismantled per approved procedures following receipt of 800122 authorization, CDLLINS, W E West Virginia Univ 83/05/23 THOMAS, C O Standardization & Special Projects Branch 28pp 18626-268 24X Fiche 50-129,83/05/23,8305240308

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR
P Operating license stage documents & correspondence

8305310012 Forwards response to 830511 questions re exhaust sys, reflector platform, reactor bridge, pneumatic transfer tube terminus assembly, scram circuit relays radioactivity monitor & automatic regulating channel servo TURCOTTE.R L Vet Admin. Hosp Dmaha.NE 83/05/23 THOMAB.C D Standardization & Special Projects Branch 9pp 18653 221 24X Ficha 50-131.83/05/23,6305310012

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Becurity, medical, emergency & fire protection plans

B30502010B Forwards revs to security plan Revs withheld (ref 10CR73 21) CRANE,P A Pacific Gas & Electric Co B3/04/25 DENTON,H R Office of Muclear Reactor Regulation, Director 2pp 18278 241 24X Fiche. 50-133,83/04/25,830502010B

8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for QLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. 0 Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

P Operating license stage documents & correspondence

8305230407 Informs that backfitting mat1 will be forwarded as soon as available. In response to 830208 ltr
FURBUSH. M. H. Parific Gas & Electric Co 83/02/23 TOURTELLOTTE. J. Regulatory Reform Task Force 1p 18543.357 24X
Fiche 50-000.83/02/23.8305230407

8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO,N J. Commissioners. 2pp. 18542;272 24X Fiche: 50-000,83/04/11,8305230720

8305020455 Demeric Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of Amends to OLs 8vc list encl EISENHUT, D G. Division of Licensing. 83/05/02. Consolidated Edison Co. of New York, Inc. 50pp. 1844:120 24X Fiche. 50-000, 83/05/02, 8305020455.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of GPs re integrated scheduling for implementation of plant mods 8vc list encl EI8ENHUT.D.Q Division of Licensing. 83/05/09 Consolidated Edison Co. of New York. Inc. 16pp. 18627 153 24X Fiche 30-000,83/05/09,8305090659.

G Inspection reports, IE Bulletins & correspondence

- 8212060385 IE Info Notice 83-14, "Dewatered Spant Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Bvc list enc! TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 317 24X Fiche 50-000, 83/03/21, 8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 30-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PHRs." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382 047 24% Fichs 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list and JORDANIE L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp, 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B303040028 IE Info Notice B3-26, "Failure of Bafetg/Relief Valve Discharge Line Vacuum Breakers," Byo list and JURDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000, B3/05/03, B303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc 11st encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp, 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 [E] Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04, Consolidated Edison Co of New York, Inc. 119pp. 18441 001 24X Fiche.50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Suc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06. Consolidated Edison Co of New York, Inc. 115pp. 18523-248 24X Fiche 50-000.83/05/06.8303040033
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines." Svc list encl URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/05/11 Consolidated Edison Co. of New York, Inc. 114pp. 18524:003 24X Fiche: 50-000, B3/05/11, 8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program," Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19, Consolidated Edison Co. of New York, Inc. i14pp. 18697-009 24X Fichs 50-000.83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Gil" Syc list encl.

 JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007. 24X Fiche: 50-000, 83/05/26, 8303040046.

S. Reportable occurrences, LERs & related correspondence

8305170336 Forwards revised LER 83-001/03L-1. 8HIFFER.J.D. Pacific Gas & Electric Co 83/05/06. MARTIN.J.B. Region 5. Office of Director 1p. 18465:123. 24X Fiche: 50-133,83/05/06.8305170336 --8305170342 Revised LER 83-001/03L-1 on 830316, fire occurred in 480-volt circuit breaker supplying radwaste pump Caused by fault to ground exacerbated by over capacity of fuse Design change will be implemented to correct overrated fuses GETTY, B C Pacific Gas & Electric Co 83/03/06 Region 5, Office of Director 2pp 18465-124 24X Fiche 50-133, 83/05/06, 8305170336

DOCKET 50-142 UCLA TRAINING REACTOR

O Adjudicatory correspondence

B305030524 Response to Committee to Bridge the Cap B30414 motion opposing scheduling earlier date for filing of written testimony UCLA wishes to reserve right to modify witness list if new date set for hearing Certificate of Svc encl CORMIER.W H California: Univ of. Los Angeles B3/04/29 Atomic Bafety and Licensing Board Panel 4pp 18306-358 24X Fiche 50~142.83/04/29.8305030524

- 8305030568 Response to ASLB 830414 order detailing licensee legal position re Committee to Bridge the Cap motion for summary disposition of Contention XVII Summary disposition should not be granted Certificate of Svc encl
 CORNIER.W H California, Univ of, Los Angeles 83/04/29 11pp 18305 324 24X Fiche 50-142,83/04/29.8305030568
- 8305030574 Response to Committee to Bridge the Cap (CBO) 830414 motion to strike portions of UCLA response to CBO request for speedsted ruling on Contention XIII Certificate of Svc encl CORMIER.W H California. Univ of Los Angeles 83/04/29 Atomic Bafety and Licensing Board Panel Spp 18303 3ii 24X Fiche 50-142,83/04/29,8305030574
- B305030494 Petition for reconsideration of AGLB B30422 order denying motions for summary disposition of Contention II (class of license) Argument completely devoid of merit Certificate of Bvc encl WOODHEAD: C P Hearing Branch 4 B3/05/02 Atomic Bafety and Licensing Board Panel 13pp 18306 332 24X Fiche 50-142,83/05/02,8305030494
- 8305030582 Memorandum & order denying Committee to Bridge the Gap 830414 motion to strike portions of NRC & UCLA responses & 830315 motion for supedited ruling on Oap 820907 motion for partial summary disposition of Contention XIII FRYE.J H. BRICHT.0 D. LUEBKE.E A Atomic Safety and Licensing Board Panel 83/05/02 Committee to Bridge the Gap 4pp 18306 094 24X Ficha 50-142.83/05/02.8305030582
- 8305060520 Hemorandum & order deferring consideration of NRC 830502 petition for reconsideration of ABLB 830422 memorandum & order denying motions for summary disposition of Contention II Ruling awaits receipt of alternate ABLB member rept BRIGHT.0 O . LUEBKE.E A . FRYE.J H Atomic Safety and Licensing Board Panel B3/05/04 3pp 18351 092 24X Fiche 50-142.83/05/04.8305060520
- B305090473 Motion for reconsideration of ASLB B30422 memorandum & order to clarify scope of Contention II proceedings Centificate of Bvc encl Accounting based on actual use of reactor demonstrates that costs attributed to noncommercial use CORMIER.W H California, Univ of, Los Angeles B3/05/04 Atomic Bafety and Licensing Board Panel 7pp 18362-272 24X Fiche: 50-142, 83/05/04, 8305090473
- 8305100330 Memorandum & order referring UCLA 830504 motion for reconsideration of ABLB 830422 order to alternate ABLB member. Responses to motion should be filed w/alternate ABLB member on schedule to be established BRIGHT.0 D. LUEBKE.E A , FRYE.J H Atomic Bafety and Licensing Board Panel. 83/05/06 2pp 18378 360 24X Fiche 50-142.83/05/06.8305100330
- 8305100312 Forwards portion of Univ of FL SAR explaining spatial relationships & components of Argonaut in response to ASLB 830425 request WOODHEAD.C.P. Office of the Executive Legal Director 83/05/07 FRYE.J H . BRIGHT.O D . LUEBKE.E A Atomic Safety and Licensing Board Panel 25pp 18370 100, 24X Fiche 50-142, B3/05/07, 8305100312
- B305130076 Memorandum & order denying NRC 810413 motion for summary disposition of Contention XX re-physical accuraty NRC directed to physically inventory SNM at UCLA & to rept findings to ASLB & parties BRIGHT.6 O., LUEBKE, E A , FRYE, J H Atomic Bafety and Licensing Board Panel 83/05/11 Office of the Executive Legal Director 27pp. 18437.053 24X Fiche, 50-142, 83/05/11, 8305130076

- 8305130079 Hemorandum & order memorializing 830505 telcon Discussions held on NRC testimony filing dates, hearing dates & issues BRIGHT.0 O , LUEBKE.E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/11 Spp 18437 080 24% Fiche 50-142/83/05/11,
- B305130150 Memorandum & order that sabotage issue will not be considered under Contention XIX Issue will be considered under Contention XX Issue will be considered under Contention XX BRIGHT.0 O. LUEBKE.E A. FRYE.J H. Atomic Safety and Licensing Board Panel 83/05/11 4pp 18437 178 24X Fiche 50-142,83/05/11,83005/13 8305130150
- B305160164 Forwards prof qualifications of six NRC witnesses to appear at Summer & Fall 1983 hearings on safety issues WCODHEAD, C.P. Hearing Branch 4 B3/05/12 FRVE, J.H., BRIGHT, G.D., LVEBKE, E.A. Atomic Safety and Licensing Board Panel Bpp 18445 120 24X Fiche 50-142, B3/05/12, B305160164
- 8305160163 Memorandum & order deferring ruling on UCLA, NRC & Committee to Bridge the Cap motions for summary disposition of Contention XVII.pending outcome of inherent safety hearings BRIGHT.G CI. LUEBKE, E. A., FRYE, J. H. Atomic Safety and Licensing Board Panel 83/05/13 California, Univ. of, Los Angeles 4pp 18444-030 24X Fiche: 50-142,83/05/13,8305140143
- 305170001 Response to alternate ASLB member 830422 order establishing 830524 hearing date Lists mat! facts not in dispute.mat! facts in dispute.mat! facts in dispute.NRC witnesses & tastimony.exhibits & time necessary for NRC presentation Certificate of 8vc enc! MODDHEAD.C P Hearing Branch & 83/05/13 10pp 18466:215 24X Fiche 50-142.83/05/13,8305170001
- 3305170063 Forwards stipulation ra preparation for hearing on Contention II WODDHEAD.C P Hearing Branch 4 83/03/13 LAURENSON, J A Safety and Licensing Beard Panel 1p 18466 233 24X Fiche 50-142,83/05/13,8305170063 Atomic
- --8305170067 Stipulation re preparation for hearing on Contention II Lists erhibits to be introduced-witnesses to be called & estimates of time necessary to present case MOODHEAD.C P Hearing Branch 4 THOMPSON.D Committee to Bridge the Oap CORMIER.W Celifornia. Univ. of. Los Angeles 83/05/12 79p 18466 254 24% Fiche 50-142,83/03/13-8305170063
- 305170325 Discusses 830506 telton per ASLB 830422 order. Items discussed, including estimates for direct presentation of cases, contained in stipulation forwarded separately Summary of witness testimony in upcoming hearing encl
 HIRSCH D Committee to Bridge the Cap 83/05/13 LAURENSON, J A
 Atomic Safety and Licensing Board Panel 2pp 18465 225 24X
 Fiche 50-142,83/05/13,8305170325
- 1305240479 Response to Judge Laurenson 830422 order re Contention 11 SUD240479 Mesponse to Judge Laurenson B30422 arcer to Contention :
 Parties stipulated to witnesses & exhibits Summarizes
 witnesses testimony UCLA case will be presented in 4 h
 Certificate of Svc encl
 CORMIERN H California. Univ of, Los Angeles 83/05/13 App
 18549 332 24x Fiche 50-142,83/05/13,8305240479
- 1305200496 Forwards subposes re class-of-license evidentiary hearing, for issuants Subposes relats to reactor operational & financial records detailing use & cost allocation for facility Related correspondence
 HIRSCH D Committee to Bridge the Cap 83/05/16 LAURENSON, J A Atomic Safety and Licensing Board Panel 1p 18514 031 24X
 Fiche 30-142,83/05/16,8303200496
- 1305200652 Forwards L Wayne statement of prof qualifications. Hayne will testify on combustion, chemical reactions. Higner energy & release & dispersion of radionuclides HIRBCH.D Committee to Bridge the Cap 83/03/16 MOODHEAD.C Hearing Branch 4. CORMIER.W California, Univ of. Los Angeles NALISBFF.L Santa Monica, CA 2pp 18519 338 24X Fiche 50-142.83/03/16.8305200652
- 305240499 Advises that Univ has not received statements of prof-qualifications of all proposed witnesses in license renawal proceeding. Btatements will be forwarded upon receipt CORMIER.W H California, Univ of, Los Angeles 83/05/18 FRYE, J H , BRIGHT, O D , LUEBKE.E. A Atomic Safety and Licensing Board Panel 1p. 18572:027 24X Ficha 50-142.83/05/18.8305240499
- 305230236 Notice of appearance in proceeding Certificate of Svc encl YOUNG:M A Hearing Branch 4 83/05/19 3pp 18539 184 24X Fiche. 50-142, 83/05/19, 8305230236.

- B305240521 Response supporting UCLA B30504 motion for reconsideration of A9LB B30422 order establishing special prehearing conference for Contention II Issue of commercial use of reactor must be decided Certificate of Svc encl HOODHEAD, C.P. Hearing Branch 4 B3/05/23 Atomic Bafety and Licensing Board Panel App 18571 110 24x Fiche 50-142,83/05/23,8305240521
- H General correspondence
- 8305050041 Forwards May 1983 Playboy article, "Terrorist Quide to 1934 Olympics, " for info BAY, J H Affiliation Unknown 83/04/28 Atomic Safety and Licensing Board Panel App 18342 086 24X Fiche 50-142,83/04/28,
- @ Inspection reports. IE Bulletins & correspondence
- 8305160029 Ack receipt of 830429 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-142/83-01
 BOOK, H E Region 5, Office of Director 83/05/11 WEOST, H F California, Univ of, Los Angeles ip 18453 007, 24X
 Fichs 50-142,83/05/11,8305160029
- --B305160037 Responds to NRC 830323 ltr re violations noted in IE Insp Rept 50-142/83-01 Corrective actions routine survey findings to be routed to radiation safety officer.background & calibr check data entered into log & survey results tabulated WEOST: W F California, Univ of, Los Angeles, B3/04/27 BBOK.H E Region 5, Office of Director 5pp. 18453 008 24X Fiche 50-142,83/05/11,8305160029
- T Hearing transcripts on non-antitrust matters
- B305200613 Forwards JC Petersen testimony Petersen will testify at B30524 hearing on Contention II WOODHEAD.C P Hearing Branch 4 B3/05/17 LAURENSON.J A Atomic Bafety and Licensing Board Panel. Ip 18520 135 24X Fiche 50-142,83/05/19.8305200613
- --B305200424 Testimony of JC Petersen re Committee to Bridge the Cap Contention II Use of reactor from accounting & financial standpoint discussed Reactor primarily used for educational purposes MA Young notice of appearance encl PETERSEN.J C Diffice of State Programs, Director 83/05/19 14pp 18520 136 24X Fiche 30-142.83/05/19.8305200613
- 8305310195 Transcript of 830524 hearing in Los Angeles, CA re proposed license renewal Pp 1-183, s Atomic Sefety and Licensing Board Panel 83/05/24 185pp 1851 023 24X Fichs 30-142,83/05/24,8305310195
- DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY H General correspondence
- 8305020563 Forwards documents & matls to establish LPDR, focusing on decommissioning & possible dismantling of facility W/o encia SOUDER, J. L. Division of Rules and Records 83/04/25 PENNELL.L 2pp 18284 243 24X Fiche.50-146,83/04/25,8305020563
- 8305040056 Responds to 830328 ltr expressing concern re possible dismantling of facility Saxton Nuclear Engineering Corp plans to request authorization to dismantle facility during latter 1980s

 DENTON.H R Office of Nuclear Reactor Regulation, Director 83/04/25 FULLER.E Affiliation Unknown 2pp. 18336,323. 24X Fiche 50-146.83/04/25.8305040036
- P. Operating license stage documents & correspondence
- 8305180097 Forwards std order for DDE work for "Consultant Syts, P Neogg, for Hearing Support-Univ of CA Nonpower Reactor License Renewal Application " Cost of project funded by NRR operating reserve requested, W/o encl.
 EIBENHUT, D. O. Division of Licensing FIN A-3727 83/04/07 DENTON, H R. Office of Nuclear Reactor Regulation, Director 18479 362 24X Fiche: 50-146,83/04/07,8305180097

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

- B305200192 Ack receipt of B30414 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-148/B3-01 MADBEN:0 L Region 4, Office of Director 83/05/16 KRAFT,D C Kansas, Univ of 1p 18517 093 24X Flche 50-148,83/05/16,8305200192
- --8305200196 Responds to NRC 930325 ltr re violations noted in IE Insp Rept 50-148/83-01 Corrective actions R Mesier will be appointed member of committee on radiation sources by 830301 KRAFT.D C Kensas, Univ of 83/04/14 MADSEN, G L Region 4, Office of Director ip 18517 094 R4X Fiche 50-148,83/05/16, 8305200192

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

- B305110067 Responds to B21105 ltr transmitting changes to suitability, training & qualification plan Changes acceptable except for items identified in enci Change re Item 4 requested per 10CFR30.79 Enci withheld (ref 10CFR30.21) GRUTCHFIELD, D. Operating Reactors Branch 5 83/05/06 VANDEMALLE, D. J. Consumers Power Co 1p 18408 111 24% Fiche, 50-195, 83/05/06, 8305110067
- 8305170404 Forwards description of scope & objectives for emergancy exercise scheduled for 830725-26.per NRC 820112 request VANDEMALLE, D. J. Consumers Power Co. 83/05/09 KEPPLER, J. Q. Region 3, Office of Director. 4pp. 18467 358 24X Flche 50-155, 83/05/09, 8305170404
- B305i10034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing B3/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X
 Fiche 50-000.B3/05/11.8305110034
- 8305170369 Comments on NUREG-0737, Item III A 2.1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR30 " Unsite & offsite emergency preparedness adequate Item complete CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/16 VANDEWALLE, D. J. Consumers Power Co 5pp 18466:077 24X Fichs, 30-155, 83/05/16, 8305170369
- 8305240376 Ack receipt of 830509 ltr describing scope & objectives of emergency exercise scheduled for 830725-26. Agrees to verbal request for postponement of accountability/assembly drill as part of exercise until plant resumes full operation PAPERIELLO.G J. Region 3, Office of Director 83/05/19 DEWITT.R.S. Consumers Power Co 1p 18574, 282, 24X Fiche 50-155, 83/05/19, 8305240376.
- 8305240239 Ack receipt of 830131 ltr Informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-13 Noncompliance i withdrawn Updated Tech Specs re fire barriers will be requested.

 BPE88ARD.R.L. Division of Engineering 83/05/20. DEWITT.R 8 Consumers Power Co 2pp 18626 083 24X Fiche 50-155,83/05/20,8305260259
- --8305260266 Responds to NRC 821203 ltr re violations noted in IE Insp Rept 30-155/82-13. Corrective actions plant drawings reviewed to verify that all ventilation duct dampers included in new test procedure & emergency lighting test process developed. VANDEMALLE, D. J. Consumers Power Co 83/01/31. KEPPLER, J. 9. Region 3. Office of Director 23pp 18626-085 24X Fiche; 50-155, 83/05/20, 8305260259,

O Adjudicatory correspondence

- 8305100404 Comments on licensee proposals to remedy deficiencies identified in ASLB 820914 initial decision re emergency planning. Licensee has provided reasonable assurance of adequate protective measures in event of emergency.

 GODDARD.R.J. Hearing Branch 3 83/04/07 lp 18378;029, 24% Fiche: 50-155,83/04/07,8305100404.
- ---8305100409 Comments on FEMA assessments of util responses to ASLB contentions re emergency preparedness program protective measures for offsite population
 HIND.J.A. Division of Radiological & Materials Safety Programs.
 B3/03/31. EIEEMHUT.D. 9. Division of Licensing 2pp (8378-030.
 24% Fiche: 50-155.83/04/07.8305100404.

- --B305100414 Requests assistance in initiating action to assure that deficiencies identified in ASLB B20914 second initial decision corrected Certificate of Svc encl ORIMES. B K Division of Emergency Preparedness (Pre B30103) B2/11/30 KRIMM.R W Federal Emergency Management Agency 14pp 18378 032 24X Fiche 50-155,83/04/07,8305100404
- B305160250 Informs that B30207 itr re proposed expansion of spent full storage capacity forwarded to ABLB for consideration as limited appearance statement No request pending for operating permit Full-term OL granted on 640501 (RUICHFIELD, D. Operating Reactors Branch 5 83/04/28 ANDERSON, J Affiliation Unknown 1p 18472 004 24X Fiche 50-135, 83/04/28, B305140250
- 8305040534 Responds to 830411 & 13 10CFR2 206 petition requesting not add1 fuel be allowed in spent fuel pool until issue of structural adequacy resolved NRC is addressing substantive issues raised by petition No add1 action will be taken DENTON; HR Office of Nuclear Reactor Regulation, Director, 83/05/03 CHRISTA-MARIA Christa-Maria 5pp 18321 109 24x Fichs 30-155,83/05/03,8305040534
- --8305040336 Director's Decision DD-83-07 re J Blur & Christa-Maria 10CFR2 206 patition requesting no add1 fuel be allowed in spent fuel pool NRC is taking action requested by petitioners so no further action needed at present time DENTON.H R Office of Nuclear Reactor Regulation, Director 83/05/03 Spp 18321 114 24X Fiche 50-155,83/05/03.8305040534
- --8305040537 Forwards SER re spent fuel pool thermal hydraulic analysis supporting request for continued operation Tomp of spent fuel pool concrete structure can be maintained below 150 F if normal fuel pool cooling sus 10st CRUTCHFIELD, D Operating Reactors Branch 5 62/07/02. VANDEMALLE, D Consumers Power Co 2pp 18321 119 24X Fiche 50-135.83/05/03.8305040534
- --8305040539 Safety evaluation re spent fuel pool thermal hydraulic analysis supporting request for continued operation NRC No Datailed Affiliation Given 82/07/02 5pp 1832: 121 24X Fiche 30-155,83/05/03.8305040854
- --8305040540 Notice of issuance of Director's Decision DD-83-07 re
 J Bier & Christa-Maria 10CFR2 204 petition requesting no
 add1 fuel be allowed in spent fuel pool until issue of pool
 thermal/structural adequacy resolved
 CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 2pp
 18321 145 24X Fiche 50-155,83/05/03,8305040534
- --B303040542 Telecopy 10CFR2 206 petition requesting no add1 fuel be allowed in spent fuel pool until lasue of pool thermal/ structural adequacy resolved BIER, J Affillation Unknown CHRISTA-MARIA Christa-Maria B3/04/11 Commissioners 2pp 18321 147 24X Fiche 50-155,83/05/03.8305040534
- --8305040543 Telecopy errata to 830503 telecopy 10CFR2 206 petition readdition to spent fuel pool
 BIER: J Affiliation Unknown 83/04/12 Commissioners 1p
 18321 130 24% Fiche 50-155, 83/05/03, 8305040534
- --8305040545 Advises that concerns raised by Concerned Citizens of Charlevoir 830411 100FR2 206 petition are issues before ASLB or are being addressed by NRC Petition can be answered briefly & quickly.

 LIEBERMAN, J. Regional Operations & Enforcement Division 83/04/19 DENTON:H R Office of Nuclear Reactor Regulation, Director 1p 18321 151, 24X Fiche 50-155.83/05/03.8305040534
- 8303040625 Responds to 830411 & 12 10CFR2 206 getitions requesting no add1 fuel be allowed in spent fuel pool until lasur of structural adequacy resolved NRC is addressing substantive issues raised by petition No add1 action will be taken DENTON.H R. Office of Nuclear Reactor Regulation, Director 83/03/03 BIER, J Affiliation Unknown Spe 18320:116 24% Fiche:50-155,83/05/03,8305040625
- 8305040495 Repts results of 830428 conference w/NRC & Christa-Maria in Hashington, DC, No basis exists for resolving matters raised by intervenors which would lead to dismissal of emergency planning subcontentions.

 OALLO, J Isham, Lincoln & Beale OALLO, J Consumers Power Co 83/05/03 BLOCH, P. PARIS, O H., SHON, F. J Atomic Safety and Licensing Board Panel 2pp 18251 154 24X Fiche: 50-155, 83/05/03.

- 8305100290 Reserves right to contest appropriateness of licensee motion for summary disposition re emergency planning contentions on spent fuel pool mod Disputed issues of fact can be resolved only by hearing Certificate of Svc encl.

 SEMMEL.H Antioch School of Law, Washington, DC SEMMEL.H Christa-Maria 83/05/04 BLOCH.P., PARIS.D.H., SHON.F.J Atomic Safety and Licensing Board Panel 3pg 19371 265 24x

 Fiche 30-155,83/05/04,8305100290
- B305ii0141 Forwards Charlevolx County B30427 resolution & B30427 ltr to Charlevolx County Board of Commissioners re application for financial assistance to support emergency preparedness plan & funds for training emergency personnel COPELAND, V.O. Isham, Lincoln & Beale B3/05/05 BLOCH, P. PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Panel App. 18393 338. 24X Fichs 50-155,83/05/05,8305110141
- 8305120287 Concurs w/H Semmel understanding of Judge Block 830503 telcone re emergency planning/spent fuel pool mod ASLB awaiting testimony before taking action O'MEILL, J O'Neill, J 83/05/09 BLOCH, P. B., PARIS, O. H., BHON, F. J Atomic Bafety and Licensing Board Panel Ip 18431 023 24X Fichs 50-155,83/05/09,8305120287
- B305130185 Requests ASLB synthesize existing record & rule on whether any disputed issue of fact exists warranting convening hearing Further deterioration of situation should be avoided GALLO, J. Isham: Lincoln & Beale GALLO, J. Consumers Power Co B3/05/09 BLOCH, P. B. , PARIB, O. H. , SHQN, F. J. Atomic Safety and Licensing Board Penal 2pp 18440 047 24x Fiche 50-135, B3/05/09, B305130185
- B305190245 Advises that appeal of ASLAB B30427 Decision ALAB-725, will be filed at appropriate time Extension to 830402 for filing objections requested O'NEILL, J. H. O'Neill, J. 83705716. PALLADINO, N. J., ROBERTS, T., AHEARNE, J. Commissioners. 1p. 18501:303 24X Fiche 50-155,83705716,8305190245
- 8303190366 Motion that all ASLB partiel initial decisions be set aside as June 1982 hearings proceeded on basis of util misrepresentation. Monetary & punitive railef also reported SEMMEL, H Christa-Maria SEMMEL, H Antioch School of Law. Washington: DC 83/05/16 Atomic Safety and Licensing Board Panel 3pp 18500.073 24X Fiche 50-155.83/05/16.8305190366
- --830519027f Advises of util continuing misrepresentation affecting safety & integrity of Commission processes Discrepancies exist in Util statements re necessity of unloading entire core to complete 10-yr inservice insp program SEMMEL. H Antioch School of Law, Hashington, DC SEMMEL. H Christa-Haria 83/05/06 PALLADINO, N J , AHEARNE, J , GILINSKY, V Commissioners 2pp. 18500 076 24% Fiche 50-155,83/05/16.
- ---8305170375 Affidavit from H Sammel B30505 telcon w/NRC project manager R Emch Util intends to conduct 10-ur inap w/o ramoving all fuel from reactor core Fuel that cannot fit in pool will be moved Cartificate of Svc encl SEMMEL.H Christa-Maria 63/05/17. 3pp. 18500 084 24X Fiche. 50-155.83/05/16,8305190366
- 8303260180 Advises that funding assistance imperative if emergency planning guidelines to be met Funds needed to complete emergency response personnel training & equip smergency operations tr W/Certificate of Svc Related correspondence BREAKEY, T MUMA.F. E Charlevoix, MI. 83/05/18 Atomic Safety and Licensing Board Panel Spp 18599 262, 24% Fiche. 50-155, 83/05/18, 8305260180.
- 8305200548 Order extending time until 830705 for Commission to act to review ALAB-725 Time for filing petitions for Commission review of ALAB-725 extended until 830502 CHILK.S J. Office of the Secretary of the Commission. 83/05/19 Commissioners Ip. 18516:001 24X Fiche 50-155,83/05/19,8305200548,
- B305200639 Confirms B30519 telcon in response to J Gallo B30509 ltr to BJ Chili Response to H Semmel B30506 communication should be directed to ASLB BTUCKY, S W Docketing & Services Branch. B3/05/19. OALLO, J. Isham, Lincoln & Beale. ip. 18520-152 24X Fiche: 50-155,83/05/19. B305200438

- 8305240528 Motion to reconsider ASLAB 830427 Decision ALAB-725 & for leave to file out-of-time ASLAB should instruct ASLB that ASLB may require analysis of criticality if ASLB enumerates facte that trigger erercise of discretionary judgement. O'NEILL. J D'Neill. J 83/05/19 Atomic Safety and Licensing Appeal Panel 2pp 18571 189 24X Fiche 50-155,83/05/19,8305240508
- B30524043B Hotion for extension until B306i3 to reply to intervenors Christa-María motion re misrepresentation by licensee Certificate of 8vc encl GALLO,J Consumers Power Co GALLO,J Isham, Lincoln & Beale. B3/05/20 Atomic Safety and Licensing Board Panel 5pp 1B571 063 24% Fiche 50-155.83/05/20.830524043B
- 8305240520 Order granting J O'Neill 830517 motion to consider motion for reconsideration out-of-time Motion for reconsideration of ASLAB 830427 Decision ALAB-725 denied 6HOEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/05/20 2pp 18571-179 24X Fichs 50-155,83/05/20,8305240520
- 8305240513 Responds to J Gallo & J D'Neill 830507 ltrs ASLB decision re emergency planning contention should await NRC region & FEMA comments on intervenor 830314 filing concerning util response to ASLB 830914 order BACHMANN.R G. Hearing Branch i 83/05/23 BLOCH.P B , SHON.F J , PARIS, O H Atomic Sefety and Licensing Board Panel 2pp. 18371 116 24X Fichs 50-155,83/05/23.8305240513
- B305270020 Motion for extension until 830606 to file NRC response to J D'Neill B30519 petition for Commission review of ALAB-725 Motion sent by telex but not received by NRC until B30325 Certificate of 8vc encl BACHMANN.R O Hearing Branch 1 B3/05/23 Commissioners, 3pp 18638.314 24X Fiche: 50-153. B3/05/23, B305270020
- 8305310021 Order extending time until 830630 for Commission to act to review Director's Decision DD-83-7 CHILM, 8 J Dffice of the Secretary of the Commission 83/05/26 Commissioners ip 18653 126 24X Fiche 50-155,83/05/26,
- J. Insurance & indemnity information
- 8305240280 Forwards Endorsement 95 to NELIA Policy NF-117
 FROUNFELKER: R Consumers Power Co 83/05/20 SALTZMAN, J NRC No
 Detailed Affiliation Given 2pp 18548.202 24X
 Fiche 50-155.83/05/20,8305240280
- P Operating license stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J. Regulatory Reform Yask Force B3/04/11 PALLADINO, N. J. Commissioners 2pp 18542 272 24X Fiche. 50-000, B3/04/11, B305230720
- 8305020202 Forwards analysis of SEP Topic XV-B, "Control Rod Misoperation," per integrated assessment 821115-19 meetings, Acceptable fuel damage limit for single control rod withdrawal accident not exceeded Topic resolved TONER, K. A. Consumers Fower Co. 83/04/25 CRUTCHFIELD, D. Operating Reactors Branch 5, 7pp 18278 135 24X Fiche 50-155,83/04/25,830802020
- 8305020294 Forwards response to NRC 830315 questions on sensitivity studies performed on RETRAN analysis Approval requested prior to scheduled startup following next refuesting outage BORDINE, T C Consumers Power Co 83/04/26 CRUTCHFIELD, D Operating Reactors Brench 5 App 18277 244 24X Fiche, 50-155, 83/04/26, 8305020294
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Syc list encl EISENHUT.D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp. 18441:120 24X Ficha 50-000,83/05/02,8305020455
- B305040166 Advises that action required by Amend 56 to License DPR-6 to initiate negotiations w/DDE re disposal of high level waste or spent nuclear fuel considered complete based on pursuit of contract w/DDE CRUTCHFIELD D. Operating Reactors Branch 5. B3/05/03, YANDEWALLE, D J Consumers Fower Co 3pp 18324 031, 24X Fichs 50-135,83/05/03,8305040166
- 8303040196 Notification of 830309 meeting w/util & NUS in Germantown, MD to discuss thermal analysis of spent fuel pool EMCH.R.L. Operating Reactors Branch 5 83/05/03 CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp 18323

- B305170410 Responds to B30203 ltr re performance of containment integrated leak rate tests Util does not concur w/ interpretation of App J requirements that corrected results for 1982 Type A test exceeded max allowable leakage limits UANDEWALLE, D J Consumers Power Co 83/05/06 KEPPLER, J O Region 3, Office of Director 2pp 18469 246 24x Fiche 50-155,83/05/06,8305170410
- 8303090659 Generic Ltr 83-20 to all operating reactor licensess to holders of CPs re integrated scheduling for implementation of plant mode 8 Vc list encl EIBEN-RUT. D © Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 30-000.83/05/09.8305090659
- 8305240505 Forwards Rev 1 to CPC-2A "GA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112 Submittal serves as annual rept VANDEHALLE, D J Consumers Power Co 83/05/11 KEPPLER, J Q Region 3, Office of Director 2pp 18575 116 24X Fiche 50-000, 83/05/11, 8305240505
- --8305240365 Rev 1 to "GA Program Description for Operational Nuclear Power Plants" REVNOLDB.J W , DEWITT.R B , COOK.J N Consumers Power Co CPC-2/ R01 83/01/10 90pp 18575 118 24X Fiche 50-000,83/05/11, 8305240505
- B305160031 Bummary of B30429 meeting w/util & NUB Corp in Germantown, MD re thermal/atructural analysis of spent fuel pool List of requested addl info on unresolved issues encl EMCH.R L. Operating Reactors Branch 5 83/05/13 Operating Reactors Branch 5. 6pp 18453 143 24X Fichs 50-155,83/05/13, B305160031.
- 8305190196 Forwards "BEP Investigation Into Possible Existence of Bolution Cavities Beneath Big Rock Point Nuclear Power Plant Near Charlsvoix.MI." in response to NRC 821012 8ER re 8EP Topics 11-4 B IT-4 B TONER.K A Consumers Power Co 83/05/13 CRUYCHFIELD.D Operating Reactors Branch 5 2pp 18502 267 24X Fiche 50-155,83/05/13,8305190196.
- --8303190201 "BEP' Investigation Into Possible Existence of Bolution Cavities Beneath Big Rock Point Nuclear Power Plant Near Charlevoix MI." BREWETER: A. MEISENHEIMER, J. Offbert/Commanweelth Cos. 83/02/09 9pp. 18502 268 24X Fiche: 50-155,83/05/13,8305190196.
- --8305180297 Bafety evaluation approving use of spent fuel pool to licensed capacity of 193 spent fuel assemblies provided reactor not operating or in cold shutdown # Office of Nuclear Reactor Regulation, Director 83/05/16 7pp 18490-337 24X Fiche. 50-155, 83/05/16, 8305180292
- B303200610 Forwards miscellaneous documents w/varying degrees of pertinence to proceeding Documents relate to spent fuel pool thermal/structural analyses OALLO, J Isham, Lincoln & Beale, OALLO, J Consumers Power Co B3/05/18 BLGCH.P.B., PARIS.O H, SHON.F.J Atomic Safety and Licensing Board Panel, 17pp 18520:045 24X Fiche: 50-155.83/05/18, B305200610.
- 8305310145 Notification of 830602 meeting w/util & Nuclear Utils Svc in BethesdawND to discuss thermal analysis of spent fuel pool. EMCH:R.L. Operating Reactors Branch 5. 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5. 3pp. 18659:041 24X Ficha:30-135.83/05/26:8303310145
- Q. Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Svc list end.
 TAYLOR.J.M. Division of Bafeguards & Inspection Programs (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc 112pp. 18308-319 24X Fiche 50-000,83/03/21,8212060385.
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator."
 Byc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15, Consolidated Edison Co of New
 York, Inc. 126pp. 18435.155. 24X Fiche: 50-000.83/04/15,8303040021

- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 183B3 089 24X Fiche 50~000.83/04/22,8303040023
- 8303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list enct JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 63/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 03/04/25, 0303040025
- 8305170166 Forwards IE Insp Rept 50-155/83-04 on 830101-0304 & 14 & notice of violation SHAFER: N D Region 3, Office of Director 83/04/27 DEWITT, R B Consumers Power Co 2pp 18469 163 24% Fiche 50-155,83/04/27,8305170166
- --805170168 Notice of violation from insp on B30101-0304 & 14 BMAFER, W D Region 3, Office of Director B3/04/27 3pp 18467 165 24X Fiche 50-155, B3/04/27, B305170166
- ---B305170174 IE Insp Rept 50-155/83-04 on B30101-0304 & 14 Noncompliance noted ends of pipe & tubing not taped in storage, tape & shipping stickers not chloride-free used on stainless steel & storage areas not maintained clean & dry WRIGHT, 0 C , PARKER, M E , BOYD, D C Region 3, Office of Director B3/04/27 9pp 18469 168 24% Fiche 50-155,83/04/27,8305170166
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Cenerators at PHRs " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830102) 83/04/28 Consolidated Edison Co of Naw York, Inc 113pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Int 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B303040028 IE Info Notice B3-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3705/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Peliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list ench JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 117pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- BSOSIG0215 Forwards Magnaflux Test & Insp Procedures 22 A 36,22 A 35, 22 A 21 & 27 A 1 used in BSOSII demonstration of ultrasonic test performance capability in detection of intergranular stress corrosion tracking,per IE Bulletin BS-02 BORDINE:T C Consumers Power Co BS/05/04 KEPPLER:J O Region 3, Office of Director Bpp IB439,251 24X Fiche 50-155,B3/05/04,BSO5IG0215
- --8305130221 Rev O to Test & Insp Procedure 22 A 36, "Remote Recording Devices During Ultrasonic Exam "

 * Magnaflux, Corp 83/02/25 7pp 18439 259 24% Fiche 50-153,83/05/048305120215
- --8305130233 Rev 2 to Test & Insp Procedure 22 A 35, "Ultrasonic Exem of Austeritic Piping & Branch Connected Welds for Intergranular Stress Corrosion Cracking " * Magnaflux, Corp 83/03/05 26pp 18439 266 24X Fiche 50-155,83/05/04.8305130218
- --8305i30237 Rev O to Test & Insp Procedure 22 A 21, "Ultrasonic Exam General Requirements." * Magnaflux, Corp. 82/12/30, 14pp 18439 292 24X Fiche 50-155:83/05/04/8305i30215
- --8305130241 Rev O to Test & Insp Procedure 27 A 1. "Making & Incrementing of Helds for NDE "

 # Hagnaflux, Corp 83/02/25 12pp 18439 306 24X
 Fichs.30-155.83/05/04.8305130215

- 8305090484 Summary of 830419 meeting w/util in Bethesda.HD re integrated assessment & ranking scheme utilized by util Next meeting will be held oneite on 830509-it EMCH.R L. Operating Reactors Branch 5 83/09/05 Operating Reactors Branch 5 3pp 18360 220 24X Fiche 50-155.83/05/05.8309090484
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Evol list encl JRBDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18923 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305190317 Responds to Action Item 2 of IE Bulletin 83-02. "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BHR Plants " Eleven welds incorporated in inservice insp BDRDINE: T C Consumers Power Co 83/05/12 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18501 057 24X Fiche 50-155,83/05/12,8305170317
- 8305230044 Forwards addit request for relief from performing ultrasonic exam of instrument line nozzle inner radius sections as part of ASME Code inservice inspirequirements Notification needed by 830601 if request denied BORDINE. T.C. Consumers Power Co. 83/05/16 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 18539.194 24X Fiche: 50-185,83/05/16,8305230044
- 8303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program"
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303260257 Ack receipt of 830131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-195/82-13
 Noncompliance 1 withfraum Updated Tech Specs re fire barriers will be requested
 SPESSARD, R L Division of Engineering 83/05/20 DEHITT, R B
 Consumers Power Co 2pp 18626 083 24X Fiche 50-155,83/05/20,8303260259
- --9305260266 Responds to NRC 821203 ltr re violations noted in IE Insp. Rept 50-185/82-13 Corrective actions plant drawings reviewed to verify that all ventilation duct dampers included in new test procedure & emergency lighting test process developed VANDEWALLE.D J Consumers Power Co 93/01/31, KEPPLER.J G Region 3, Office of Director. 23pp 18626 095 24X Fiche 50-155,83/05/20,8305260259
- 8303040046 [E Info Notice 83-33, "Nonrepresentative Sampling of Conteminated Oil," Svc list encl
 JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- R Periodic operating reports & related correspondence
- B305230270 "Active Mod Projects.Operating PWR,1982" * Consumers Fower Co B2/12/31 App. 18576 332 24X Fiche: 50-000, B2/12/31, B305230270;
- S Reportable occurrences, LERs & related correspondence
- B305230570 Forwards engineering evaluation rept. "Cracks & Leaks in Small Diameter Piping" BROWN.E J Reactor Operations Analysis Branch 83/04/19 BEYPRIT.K V Reactor Operations Analysis Branch ip 18541 342 24X Fithe 50-000
- ---B305230619 "Cracks & Leaks in Bmell Diameter Piping," engineering evaluation rept Bmall pipe leaks associated w/unanticipated vibration problems require addit supports or rerouting of piping BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche, 50-000, 83/04/19, 8303230573.

- DOCKET 50-154 UNIV OF WISCONSIN RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- B305100363 Forwards IE Bafeguards Insp Rept 50-156/B3-01 on B30404-06 & notice of violation Notice of violation & rept details withheld (ref 100FR73 21 & 2 790)
 MILLER, J R Region 3, Office of Director 83/05/04 CASHWELL, R J Histonsin, Univ of Madison 2pp 18379 039 24X
 Fiche 50-156,83/05/04,8305100363
- --8305100371 IE Safeguards Insp Rept 50-156/83-01 on 830404-06 Noncompliance noted provisions of 10CFR73,21 not implamented as required Details withheld (ref 10CFR73 21 & 2 790) STAPLETON,D W , CREED, J R Region 3, Office of Director 83/05/04 ip 18379 041 24% Fitche 50-156,83/05/04:8305100363
- 8305100323 Forwards IE Bafeguards Insp Rept 50-156/83-02 on 830419 & 20 No noncompliance noted HILLER. J. Region 3. Office of Director 83/05/06 CABHMELL. R J. Wisconsin. Univ of Madison 2pp 18378-322 24X Fiche: 30-156.83/05/06.8305100323
- --8305300365 IE 8afeguards Insp Rept 50-156/83-02 on 830419 & 20 No noncompliance noted Major areas inspected nuclear math control & accountability, measurement & controls & shipping & receiving Details withheld (ref 10CFR2 790) KNICELEY.J R. CREED,J R. Region 3. Office of Director 83/05/05 ip 18378 324 24X Fiche 50-156,83/05/06,8305100323
- G Inspection reports, IE Bulletins & correspondence
- 8305100363 Forwards IE Bafeguards Insp Rept 50-156/83-01 on 830404-06 & notice of violation Notice of violation & rept details withheld (ref 10CFR73.21 & 2.790) MILLER, J. R. Region 3. Office of Director 83/05/04 CABHWELL, R. J. Wisconsin, Univ. of, Madison 2pp 18379 039 24X Fiche. 50-156, 83/05/04, 8305100343
- --8305100371 IE Safeguards 1nsp Rept 50-156/83-01 on 830404-06 Noncompliance noted provisions of 10CFR73 21 not implemented as required Details withheld (ref 10CFR73 21 & 2 790) STAPLETON, B W. CREED, J.R. Region 3, Office of Director 83/05/04 1p 18379 041 24X Fiche 30-156.83/05/04.8305100363.
- 8305100323 Forwards IE Bafeguards Insp Rept 30-156/83-02 on B30419 & 20. No noncompliance noted NILLER, J. Region 3. Office of Director B3/05/06 CABHWELL, R. J. Wisconsin, Univ. of, Madison 2pp 18378 322, 24X Fiche. 50-136. 83/05/06. B305100323.
- --8305100365 IE Bafeguards Insp Rept 50-156/83-02 on 830419 & 20. No noncompliance noted Major areas inspected, nuclear mati control & accountability, measurement & controls & shipping & receiving Details withheld (nef 10CFR2 790) KNICELEY, J. R., CREED, J. R. Region 3. Diffice of Director. 83/05/05 ip 18378.324 24X Fiche 30-156.83/05/06.8305100323
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR
- G. Inspection reports: IE Bulletins & correspondence
- 830505023 Forwards IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23 & notice of violation BTAROSTECKI.R. Division of Project & Resident Programs 83/04/21, 8TREETT.W.B. Cornell Univ 2pp 18338-096 24X Fichs.30-097,83/04/21,8305050223
- --8305050230 Notice of violation from insp on 830321-23 * Region 1, Office of Director 83/04/21 1p 18338:098 24X Fiche:50-097,83/04/21,8305050223
- --8305050236 IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23.

 Noncompliance noted:failure of ward lab safety committee to perform annual audits of operations since 1980 & failure of committee to meet quarterly in 1982

 KINNEY,M. W., ELSASSER,T C Region 1, Office of Director.

 83/04/18 6pp 18338 099 24% Fiche 50-097,83/04/21,8305050223.

00 DIMOTA JARBARO E61-06 TRADOC

- J, Insurance & indemnity information
- 8305160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAELU Policy MF-59 ABHBURN, D Marsh & McLennan, Inc. 83/05/06 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18450 353 24X Fiche 50-089,83/05/06,8305160084
- @ Inspection reports, IE Bulletins & correspondence
- 8305170429 Forwards IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08 & notice of violation 8TERNBERG,D M Region 5, Office of Director 83/04/25 PARKER,J W QA Technologies, Inc. (General Atomic Co 2pp 18471 237 24X Fiche 50-089,83/04/25,8305170429
- --8305170432 Notice of violation from insp on 830404-08 KIRBCH,D F Region 5, Office of Director 83/04/25 ip 18471 239 24X Fiche 50-089,83/04/25,8305170429
- --B305170437 IE Insp Repts 50-089/B3-01 & 50-163/83-01 on 830404-08 Noncompliance noted failure to conspicuously post high radiation area during performance of reactor experiment JOHNBON,P.H., KIRBCH.D.F. Region 5, Office of Director 3pp 18471 240 24X Fiche 50-089,83/04/25,8305170429

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

- U. Congressional/Executive Correspondence
- 8305180437 Responds to 830511 ltr re licensing renewal proceeding Commission cannot respond to substantive matters due to pendency of licensing adjudication before ABLB FITZOERALD. J A Office of the General Counsel 83/05/17 BOEROERS. M. Maryland. State of in 18486-060 24X Fiche-30-170,83/05/17.8305180437
- --B305180439 Expresses concern on behalf of Citizens for Nuclear Reactor Safety re licensing renewal proceeding BOERGERS M Maryland, State of 83/05/11 PALLADING, N J Commissioners ip 18486.061 24X Fiche 50-170,83/05/17,8305180437

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

- G Inspection reports: IE Bulletins & correspondence
- 8305270204 Forwards IE Insp Rept 50-184/83-02 on 830404-08. No noncompliance noted.

 8TARGBIECKI, R Division of Project & Resident Programs 83/05/13 CARTER, R. B. Commerce, Dept. of, National Dureau of Standards 2ps 18637-304. 24X Fiche, 50-184, 83/05/13, 8305270204
- ---830527020B IE Insp Rept 50-184/83-02 on 830406-08 No noncompliance noted Major areas inspected licensee action on previous insp findings, organization, logs & records, reviews & audits & operator requalification training KINNEY, W W. ELBASSER, T C. Region 1, Office of Director 83/05/12, 8pp. 18637:306 24X Fiche 50-184,83/05/13,8305270204
- B305230454 Corrects rept number for IE insp on B30406-08 Number should be 30-184/83-03, not B3-02. BTAROSTECKI.R Division of Project & Resident Programs. B3/05/19. CARTER,R. B Commerce. Dept of. National Bureau of Standards. 2pp 18585.212. 24X Fiche 30-184.83/05/19.8305250454
- --8305250456 IE Insp Rept 50-184/83-03 on 830406-08, reflecting corrected rept number W/o details.
 KINNEY, H. W., ELBABBER, T C. Region 1, Office of Director 83/05/12, 1p 18585 213. 24X Fiche 50-184, 83/05/17, 8305250454.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 8305100006 Forwards IE Insp Rept 50-192/83-03 on 830310-11. No nuncompliance noted SEIDLE.W. C. Region 4. Office of Director 83/04/11 BAUER.T L. Texas, Univ. of 2pp 18377: 206 24X Fiche: 50-192, 83/04/11. 8305100006.

- --8305100009 IE Insp Rept 50-192/83-03 on 830310-11 No noncompliance noted Major areas inspected reactor facility program organization.audit & review.procedures, surveillance, experiments, environ protection & emergency planning TAPIA.J I HUNNICUTT.D M . SEIDLE.W C Region 4. Office of Director 83/05/08 5pp 18377 208 24X Fiche 50-192.83/04/11, 8305100006
- P Operating license stage documents & correspondence
- 8305100005 Forwards responses to license renewal questions in NRC 830415 ltr Responses to Questions 4,5,6 % 16 provided in encl updated SAR pages
 BAUER.T L , KLEIN.D Texas, Univ of 83/05/02 THOMAS.C D Division of Licensing 22pp 18377 184 24X Fiche 50~192.83/05/02.8305100005
- Q Inspection reports, IE Bulletins & correspondence
- 8305100006 Forwards IE Insp Rept 50-192/83-03 on 830310-11 No noncompliance noted BEIDLE: W C Region 4. Office of Director 83/04/11 BAUER, T L Texas, Univ of 2pp 18377 206 24X Fiche 50-192, 83/04/11, 8305100006
- --B305100007 IE Insp Rept 50-172/B3-03 on B30310-11 No noncompliance noted Major areas inspected reactor facility program organization, audit & review, procedures, surveillance, experiments, environ protection & emergency planning TAPIA, J I, HUNNICUTT, D M , BEIDLE, H C Region 4, Office of Director 83/05/08 5pp 18377 208 24X Fiche 50-192,83/04/11,8305100006

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

- 8 Reportable occurrences, LERs & related correspondence
- B303240384 RO on B30516, seepage of approx 160 cm3/h in reactor pool water discovered from area below thermal column case Leak will be isolated to determine cause Tech Specs do not specify pool leak rate
 DIMEGLIO.A F Rhode Island & Providence Plantation 83/05/17
 BERNARD.H Btandardization & Special Projects Branch. 1p
 18571.041 24X Fiche 50-193,83/05/17,8305240384
- 8305250445 RD on 830516, sespage of reactor pool water discovered below thermal column case investigation revealed seepage from norizontal const joint in concrete biological shield Procedures initiated to isolate leak DIMEOLIO, A F. Rhode Island & Providence Plantation 83/05/17 KINNEY, M. Region 1, Office of Director 1p 18585 283 24X Fiche 30-193.83/05/17.8305250445

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- P Operating license stage documents & correspondence
- 8305030688 Clarifies definitions of plant & project low level radwastes to be used in developing West Valley Demonstration Project mpt plan & subsequent environ assessment documentation HANNUM, H Energy, Dept of, 83/04/01 GLARK, A T Advanced Fuel & Bpent Fuel Licensing Branch 2pp 18309 138 24X Fiche, 50-201, 83/04/01, 8305030688
- 8305230015 Forwards Rev 1 to "Functional & Operational Requirements for Component Test Stand." for comments by 830915 HUNNUM.W H. Energy. Dept of: Idaho Operations Ofc 83/04/18. CLARKA T Advanced Fuel & Spent Fuel Licensing Branch 1p 18542 232. 24X Fiche 50-201,83/04/18.8305230015
- ---8305230020 Rev i to "Functional & Operational Requirements for Component Test Bland" * West Valley Nuclear Bervices Co , Inc 83/03/23 22pp 18542 233 24X Fiche 50-201/83/04/18/8305230015
- B305240614 Requests comments on "Geological Recommendations for Investigation of NRC Disposal Area," by B30527 HANNUM.W H Energy, Dept of, Idaho Derations Ofc B3/04/21 CLARK.A T, Advanced Fuel & Bpent Fuel Licensing Branch ip. IB593 142 24X Fiche.50-201.83/04/21.8305240614
- --8305240618 "Geological Recommendations for Investigation of NRC Disposal Area "

 * Hest Valley Nuclear Bervices Co , Inc 83/03/16 2ipp 18593-143, 24% Fiche 30-201/83/04/21/8305240614

- DOCKET 90-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8305110059 Advises that onsite & offsite emergency preparedness adequate Emergency plans upgraded per NUREO-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E.10CFR50" Item complete CRUTCHFIELD. D. Operating Reactors Branch 5 83/03/09 DIETCH.R Southern California Edison Co. 3pp 18408 106 24X Fiche 50-206.83/03/09.8305110059
- 8305060372 Forwards Amend 69 to License DPR-13 & notice of issuance & availability Amend deletes Tech Specs requiring audits of emergency & contingency (security) plans once every 12 months CRUTCHFIELD D Operating Reactors Branch 5 83/03/03 DIETCH, R Southern California Edison Co 3pp 18344 137 24% Fiche 50-206,83/03/03,8305060372
- --8305060381 Amend 69 to License DPR-13, deleting Tech Specs requiring Audits of emergency & contingency (security) plans by appropriate persons once every 12 months CRUTCHFIELD, D Operating Reactors Brench 3 83/05/03 5pp 18344 141 24X Fiche 50-206,83/05/03,8305060372
- --8305060385 Notice of issuance & availability of Amend 69 to License DPR-13 CRUTCHFIELD,D Operating Reactors Branch 5 83/05/03 2pp 18344 146 24% Fiche 50-206,83/05/03,8305060372
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits SVC list enc!
 EISEMHUI.D O Division of ticensing 83/05/11 Consolidated Edison Co of New York Inc 16pp 18540 075 24X
 Fiche 50-000.83/05/11.8305110034
- 8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-18 on 830425-27 No noncompliance noted Details withheld (ref 100FR73 21)
 NORDERHAUGLE Region 5. Office of Director 83/05/12. PAPAY.L T Southern California Edison Co 2pp 18599 322 24X
 Fichs 50-206.83/05/12.8305260242
- 8305240198 Provides into re emergency operations facility in response to NRC request When control room HVAC is upgraded as result of NUREO-0737, Item III D 3 4.tachnical support ctr NVAC will be reviewed to ensure uniformity of design BASKIN.K P Southern California Edison Co 83/05/20 CRUICHFIELD, D Operating Reactors Branch 5 2pp 18548 010 24X Fiche 50-206,83/05/20,8305240198

H Concrat correspondence

- 8305090024 Add1 response to FOIA request for documents of B21130 special insp rept Forwards App A documents Portions of Documents I & 2 in App B withheld (ref FOIA Exemption 7) Documents J & 4 withheld (ref FOIA Exemption 7) FELTON, J M Division of Rules and Records 83/03/21 QARDE, 8 Government Accountability Project 4pp 18381 138 24X Fichs 50-206,83/03/21,8305090024
- 8305120178 Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcombe replaces OD Cotton as representative authorized to sign NRC licensing documents
 HOLCOMBE.J C Ban Diego Gas & Electric Co 83/05/06 EISENHUT, D Q Division of Licensing ip 18427 156 24% Fiche 50-206, 83/05/06, 8305120178

P Operating license stage documents & correspondence

- 8305060073 Add1 response to FOIA request for documents re efforts to make facility more earthquake resistant Documents 1 through 7 listed on app enci Documents B through 10 withheld (ref FOIA Exemption 5), FELTON.J M Division of Rules and Records. 83/03/14 WHARTON.R.J. 8an Diego State College 3pp 18365 023 24X Fiche 50-206.83/03/14.8305060073
- --8203180052 Discusses facility capability to shut down safely for postulated steam line breaks regardless of whether failure seismically induced Unit to remain shut down until issues resolved
 DENION.H R Defice of Nuclear Reactor Regulation, Director, 82/03/02 REMICK.F J Office of Policy Evaluations 3pp 18365 121 24X Fichs 50-206,83/03/14.8305060073

- --8204190027 Updates status of resolution of steam line break & seishic upgrade issues for facility, identified in 820302 memo DENTON, H R. Office of Nuclear Reactor Regulation, Director 82/04/08 REMICK,F J Office of Policy Evaluations 6pp 18365 126 24X Fiche 50-206.83/03/14.8305060073
- B305060235 Notification of contract execution, Mod 5 to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for San Gnofte Nuclear Generating Station Unit 1 Final Rept '"
 Contractor Univ of California at San Diego
 BMITH, P A Division of Contracts FIN 8-6531 83/04/25
 DENTON, H R Office of Nuclear Reactor Regulation, Director REITER, L NRC No Detailed Affiliation Given ip 18359 352 24X
 Fiche. 50-206.83/04/25.8305060235
- --8309060239 Mod 5, deobligating funds for closeout, to "Review of Rept Entitled 'Bimulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit I - Final Rept " + California, Univ of, San Diego SMITH,P A Division of Contracts, FIN 8-6531 83/04/25 1p 18359 353 24X Fiche 50-206.83/04/25.8305060235
- 8305020427 Forwards "Seismic Evaluation of Reinforced Concrete Masonry Mails:" par SEP Topic III-6 re seismic design considerations Results tan be compared to test results to assess conservatism of analysis methodology BASKIN, K.P. Southern California Edison Co. 83/04/28 CRUTCHFIELD, D. Operating Reactors Branch 5 1p. 18281 237, 24X Fiche 30-206,83/04/28,8305020427
- --8305020433 "Beismic Evaluation of Reinforced Concrete Masonry Walls "
 # Computech Engineering Services, Inc. 83/04/30 6pp
 18881 238 24X Fiche: 50-206,83/04/28,8305020427
- 8305030414 Forwards final BER re SEP Topic VI-10 A concerning testing of reactor trip sys & ESF & including response-time testing Mods to Tech Specs & equipment to implement response-time testing recommended.

 PAULSON, W. A. Departing Reactors Branch 5 83/04/28 DIETCH, R Southern California Edizon Ca. 5pp. 18306, 242 24X Fichs 30-206, 83/04/28, 8305030414
- 8305020455 Generic Ltr 83~19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OL; 8vc list encl EISENHUT.D G. Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441 120 24X Fiche 50~000.83/05/02:8305020455
- 830505003B Forwards final safety assessment rept re SEP Topic II-1.C, "Potential Hazards Due to Nearby Transportation.
 Institutional, industrial & Military Facilities " Probability of explosions acceds current criteria PAULSON, H A Operating Reactors Branch 5 83/05/03 DIETCH, R Southern California Edican Co. 39pp 18336, 277 24X Fiche 50-206, 83/05/03, 830505003B
- 8305060225 Forwards Amend 68 to License DPR-13, safety evaluation & notice of issuence & evaluability Amend changes Tech Specs & bases to incorporate electrical power availability requirements furing refueling or cold shutdown. FAULSON, M. A. Operating Reactors Branch 5 83/05/03 DIETCH, R. Southern California Editon Co. Spp. 18345, 076 24X Fiche 50-206, 83/05/03, 8305060225
- --8303060228 Amend 68 to License DPR-13, changing App A Tech Specs & bases to incorporate conditions for electrical power availability during cold shutdown or refueling. CRUTCHFIELD. D. Operating Reactors Branch 5 83/03/03, 6pp 18345 079 24% Fiche 50-204, 83/05/03, 8305060225.
- --8305050232 Sefety evaluation supporting Amend 68 to License DPR-13 * Office of Nuclear Reactor Regulation, Director 83/05/03 3pp 19345 085. 24% Fiche-30-206,83/05/03,8305060225
- --8305060234 Notice of isquances & availability of Amend 68 to License DPR-13 CRUTCHFIELD,D Operating Reactors Branch 5, 83/05/03 2pp 18345,088 24% Fiche. 50-206,83/05/03,8305060225
- 8305060372 Forwards Amend 69 to License DPR-13 & notice of issuance & availability Amend deletes Tech Specs requiring audits of emergency & contingency (security) plans once every 12 months.

 CRUICHPIELD, D. Operating Reactors Branch 5 83/05/03 DIETCH, R
 - GRUTCHPIELD, D. Operating Reactors Branch 5 83/05/03 DIETCH, R Bouthern California Edison Co. 3pp 18344·137 24K Fiche 5D-206, 83/05/03, 8305060372.
- --B3050603B1 Amend 69 to License DPR-13, deleting Tech Bares requiring audits of amergency & contingancy (security) plans by appropriate persons once every 12 months CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/03. 5pp 18344 141 24X Fiche: 50-206, 83/05/03, 8305060372

- --8305060385 Notice of issuance & availability of Amend 69 to License DPR-13
 - DERT 13 CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 2pp 18344 146 24X Fichs 50-206.83/05/03.8305060372
- 8305100377 Informs that qualification documentation for resistance temp 305100377 Informs that qualification documentation for resist detectors, limit switches, containment water level monitors & valva indicators will be available prior to return to operation from current outage Numerous delays encountered KRIEGER, R W Sputhern California Edison Co 83/05/06 CRUTCHFIELD.D Operating Reactors Branch 5 ip 18379 045 Fiche 50-206,83/05/06,83/05/00377 18379 049 24X
- B305090659 Generic Ltr B3-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D @ Division of Licensing B3/05/09 Consolidated Edison Co Fich# 50-000, 83/05/09, 8305090659
- B305120166 Advises of Westinghouse Dwners Group schedule for response to TMI Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps " Two-pert program will be undertaken Perts 1 & 2 scheduled for completion by B30731 & B31231.respectively KRIEGER W Bouthern California Edison Co B3705/10 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18422 002 24X Fiche 50-206.83/05/10,8305120166
- B305120189 Informs that post-implementation revise info on NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 will not be provided until 830701 due to higher priority post-TMI work KRIEGER, R W Southern California Edison Co 83/05/10 CRUTCHFIELD, D Operating Reactors Branch 5 ip 18427 152 24X Fiche 50-206,83/05/10,8305120189
- 8305240501 Provides status of actions requested in 830401 clarification of 821120 SER on environ qualification of safety-related electrical equipment BASKIN: K P Southers electrical equipment
 BASKIN;K P Southern California Edison Co 83/03/20
 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18572 028 24X
 Fichs 50-206,83/05/20,8305240501
- A305240509 Discusses status of activities on environ qualification of safety-related equipment in response to 10CFR30 49(g) Review of nonsafety-related equipment under 10CFR30 49(b)(2) planned BABKIN,K.P. Bouthern California Edison Co. 83/05/20 CRUTCHFIELD,D. Operating Reactors Branch 5 2pp. 18571 271 24X Fichs: 50-206: 83/05/20, 8305240509
- 8305310227 Notifies of decision to refund Class III fee remitted for Proposed Change 108 dtd 820105 to permit raising allowable phosphate discharge limit, as application no longer applicable.
 MILLER,W D License Fee Management Branch 8: Southern California Edison Co 1p 18662 259 Fiche 50-206.83/05/20,8305310227 83/05/20 DIETCHAR
- 8305250512 Forwards responses to issues raised in 830502-04 meetings re BEP Topic III-6 concerning seismic design considerations Add1 info requested at 830502-04 meetings will be provided by 830410
 BABKIN.K.P. Bouthern California Edison Co. 83/05/23 oy 830610 BABKIN,K P Southern California Edison Co 83/05/23 CRUTCHFIELD,D Operating Reactors Branch 5 49pp 18588 104 24X Fiche: 50-206, 83/05/23, 8305250512
- --8305250520 "Balance-of-Plant Mechanical Equipment & Piping Beismic Resystuation Criteria " * Bechtel Corp 83/05/20 27pp 18588 139 24X Fiche 50-206,63/05/23,8305250512
- 8305260263 Notification of 830601 meeting w/util in Bethesda. MD to discuss proposed integrated schedule for implementation of backfit items PAULSON.W A Operating Reactors Branch 5. B3/05/24 CRUTCHFIELD.D Derating Reactors Branch 5. 3pp. 18626 003 24X Fiche: 50-206.83/05/24.8305260263
- G. Inspection reports, IE Bullstins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list TAYLOR, J M Division of Bafeguards & Inspection Programs (Post B30103) 83/03/21. Consolidated Edison Co. of New York, Inc 112pp 18308 319. 24X Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Byc list ancl.

 JORDANIE, L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15. Consolidated Edison Co. of New
 York, Inc. 126pp 18435-155 24X Fiche 50-000,83/04/15,8303040021

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/22 Consolidated Edison Co of New

 York, Inc. 112pp 18383 089 24% Fiche 30-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list encl JURDAN:E L Division of Emergency Proparedness & Engineering Response (Post B33003) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Louse Parts in Secondary Side of Steam Generators at PWRs " Svc list oncl URDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York. Inc 113pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- B303040027 IE Info Notice B3-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list enc! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24% Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN: L L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705703 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83705703,8303040028
- 8305170363 Forwards IE Insp Rept 50-206/83-12 on 830425-29 No noncompliance noted BIBHOP,T W Region 5, Office of Director 83/05/03 PAPAY,L T Southern California Edison Co 2pp 18466 087 24X Fiche 50-206,83/05/03,8305170363
- -8305170365 IE Insp Rept 50-206/83-12 on 830425-29 No noncompliance noted Major areas inspected licenses implementation of THI action item commitments & requirements KIRGCH.DF Region 5, Dffice of Director 83/05/03 4pp 18466 089 24X Fichs 50-206.83/05/03.8305170363
- B303040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24x Fiche 50-000.83/05/04,8303040030
- B303040031 IE Info Natice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past B30103) B3705704 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83705704,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl
 JORDAN: E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/06 Consolidated Edison Co of New
 York, Inc 115pp 18523 248 24X Fiche 50-000:83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness % Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B305260242 Forwards IE Bafeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-19 on 830425-27 No noncompliance noted Details withheld (ref 10CFR73 21) NCRDERHAUG, L R Region 5, Office of Director 83/05/12 PAPAY, L T Southern California Edison Co 2pp 18599 322 24X Fiche 50-206,83/05/12,8303260242
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " 105404040 12 into Action of Emergency Preparedness & Engineering
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/17 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- 8305310190 Forwards safety evaluation of conceptual design info submitted on 830928 re proposed redesign of safety injection sys Proposed design acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/27 DIETCH, R Southern California Edison Co. 2pp 18653 047 24X Fichs 50-206,83/03/27,8305310190

DOCKET 50-213 HADDAM NECK PLANT

- F Security, medical, emergency & fire protection plans
- B305060213 Forwards objectives for B30423 full-scale emergency preparedness exercise info from NRC requested by B30401 re names of personnel attending social security numbers & security clearance itrs requested by NRC by B30401 COUNSIL. W 9 SEARS, C.F. Connecticut Yankee Atomic Power Co COUNSIL. W 9 Northeast Utilities B3/02/04 HAYNES, R.C. Region I. Office of Director 6pp 18345 097 24X Fiche 50-213.83/02/04. B303060213
- 8305110069 Forwards "Haddam Neck Plant Emergency Response Exercise "
 COUNSILLY G . MERNER.R P Connecticut Vankee Atomic Power Co
 83/03/09 HAYNES.R C Region 1. Office of Director 2pp
 18402 338 24% Fiche 30-213,83/03/07,8305110069
- --B305[1007] "Haddam Nucl Plant Emergency Response Exercise " Supporting documentation enc!

 * Connecticut Yankee Atomic Power Co * Northeast Utilities
 Service Co B3/04/23 700pp 18402 340 24%
 Fiche 50-213.83/03/09,8305110069
- 8305110569 Releases public version of revised amergency plan implementing procedures FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18421 089 24X Fiche 50-213,83/04/26, 8303110369
- --8303110374 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1 3-2 re notification & communication. EPIP 1 5-7 re radiological dose assessment & EPIP 1 5-14 re evacuation & assembly CQUNSIL:N O Northeast Nuclear Energy Co (subs of Northeast Utilities) CQUNSIL:N O Northeast Utilities CQUNSIL:N O Northeast Utilities CQUNSIL:N O Northeast Utilities CQUNSIL:N O ODIVISION OF COUNTY OF STANDARD COUNTY
- --8303110379 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-2 re notification & communication, EPIP 1.5-7 re radiological dose assessment & EPIP 1.5-14 re sysculation & assembly # Northeast Nuclear Energy Co (subs of Northeast Utilities) 63/03/15 145pp 18421 092 24X Fiche 50-213,83/04/26, 6305110569
- 830310030? Forwards supporting stage-vol & stage-area info re Quabbin Reservoir Study effort requested to assist in disaster contingency planning BRUTBCH: W A Massachusetts: Commonwealth of, 83/05/04, CRUTCHFIELD.D Operating Reactors Branch 5 CHERY.D L NRC No Details Affiliation Given ip 18380 086 24X Fiche 50-213.83/05/04.8305100309
- 8305170213 Documents agreement reached during 830505 telcon w/NRC re 830131 request for exemption from certain requirements in 100FR30. App R for central room fire review One channel of pressurizer level (indication will be installed at panel COUNSIL. N O Connecticut Yankee Atomic Power Co 83/05/10 EISENRUT, D Q Division of Licensing 2pp 18466 330 24X Fiche 50-213,83/05/10,8305170213
- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, Svc list encl E188hHVT.D O Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fichs 50-000,83/05/11.8305110034
- 8305180893 Authorizes refund for review of 821230 & 830408 requests from reviewed schedule for conducting amergency exercise MILLER.W O License Fee Management Branch 83/05/11. CQUNSIL.W O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 1p 18504 030 24X Fiche 50-000,83/05/11.8305180853

- B305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NURRO-0737. Item III A 2 I I tem complete CRUTCHFIELD. D Operating Reactors Branch 5 B3/05/13 COUNSIL, W G Connecticut Yankee Atomic Power Co CDUNSIL, W G Northeast Nuclear Energy Co (Subs of Northeast Utilities) 4pp 18452 349 24X Ficha 50-000, B3/05/13, B305160082
- 8305290307 Forwards IE Insp Rept 50-213/83-07 on 830307-0410 No noncompliance noted STAROBTECKI.R Division of Project & Resident Programs 83/05/13 COUNGIL.W G Connecticut Yankee Atomic Power Co 2pp 18592 035 24X Fiche 50-213.83/05/13.8305250307
- --8305250309 IE Insp Rept 50-243/83-09 on 830307-0410 No noncompliance noted Major areas inspected plant operations review of periodic & special repts, shift lops & operating records, surveillance activities & physical security REBELOWBKI,T H Region 1, Office of Director ELBA89ER,T C Division of Project & Resident Programs 63/05/12 11pp 18592 037 24X Fiche 50-213,83/05/13,8305250307
- J Insurance & indemnity information
- 8305120006 Forwards Endorsements 75 & 66 to NELIA Policy NF-151 & MAELU Policy MF-39, respectively SINIBI.J M Marsh & McLennan, Inc 83/05/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 18423 073 24X Fiche 50-213,83/05/05,8305120006
- P Operating license stage documents & correspondence
- B305230616 Forwards info in response to 83020B itr requesting backfit cost data for operating nuclear units Cost categorized according to NRC imposed. THI & non-TMI backfits. util-initiated & hybrid backfits
 CDUNSIL.W O Connecticut Yankee Atomic Power Co COUNBIL.W G Northbast Nuclear Energy Co (subs of Northbast Utilities)
 CDUNSIL.W G Northbast Utilities B3/03/21 TOURTELLOTTE, J Regulatory Reform Task Force 25pp 18543 038 24X
 Fiche 50-000.83/03/21.8305230616
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADIND.N J Commissioners 2pp 18542 272 24X Fich# 50-000.83/04/11.8305230720
- 8305100331 Forwards proprietary & nonproprietary versions of "TMI Item II K 3 30 Revised Small Break LDCA Analysis " Proprietary version withheld (ref 10CFR2 790) COUNSIL, M G Connecticut Yankee Atomic Power Co 83/04/14 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18379 115 24X Fiche, 50-213, 83/04/14, 8305100331
- --8305100335 Nonproprietary version of "TMI Item II K 3 30 Revised Small Break LOCA Analysis "

 * Northeast Utilities Service Co 83/04/14 327pp 18379:117 24X Fiche, 50-213, 83/04/14, 8305100331
- B30516018B Advises that action required by 830126 Amends B8,51 & 80 to Licenses DPR-21.DPR-61 & DPR-65, respectively & Generic Ltr B3-07 complete, based on util negotiations w/DDE re disposal of high level waste or spent nuclear fuel CLARK,R A Dperating Reactors Branch 3 83/04/20 COUNSIL,W C Connecticut Yankee Atomic Power Co 2pp 18462:355 24X Fiche 50-000,83/04/20,8305160188
- 8305100385 Forwards affidavit detailing basis for withholding 830414 submittal describing LOCA program (NULAPS). YMI Item II.K 3 30. from public disclosure, per 100FR2 790 COUNSIL.W G. SEARS, C.F. Connecticut Yankee Atomic Power Co 83/04/25 CRUTCHFIELD, D. Operating Reactors Branch 5 App 18378 218 24X Fiche 50-213.83/04/25.8305100385
- 8305050054 Forwards comments on Generic Ltr 82-32, "Potential Steam Generator Related Requirements," Vendor input should be sought, especially in areas of steam generator tube inservice insp t design considerations COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities), COUNSIL.W G Northeast Utilities 83/04/29 EISENNUT.D G, DIVISION of Licensing App 18337 085 24X Fiche, 50-000, 83/04/29, 8305050054,
- B305050112 Provides progress rept on piping mods completed during Cycle
 12 refueling outage re BEP Topic III-6, "Seismic Design
 Considerations," per B20927 commitment
 GOUNSIL.W G Connecticut Yankes Atomic Power Co B3/04/29
 GRUTCHFIELD,D Operating Reactors Branch 5 2pp. 18341 066 24X
 Fiche 50-213.83/04/29,8305050112

- B305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Manual," per 10CFR50.App E.Section V W/o encls COUMBIL, W G COUNBIL, W G COUMBIL, W G COUM
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Svc list encl EISENHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8303090488 Forwards Amend 36 to License DFR-61 & notice of issuance & availability Amend deletes requirements for monitoring fish impingement on intake screens from App B ETS CRUTCHFIELD, D Dearating Reactors Branch 5 83/05/02 CGUNSIL, W G Connecticut Yankee Atomic Power Ca 3pp 18361 127 24X Fiche 50-213,83/05/02,8305090488
- --8305090491 Amend 56 to License DPR-61, changing ETS Pages 1,2 3-1 through 2 3-3a,3 i-1.5 1-1.5 3-1 & 5 5-1 to delete requirements for monitoring fish impingement on intake screens.

 CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/02 9pp 18361 130 24X Fiche 50-213,83/05/02,8305090488
- --8305090492 Notice of issuance & availability of Amend 56 to License DPR-61 CRUTCHFIELD, D Operating Reactors Branch 5 83/05/02 2pp 18361 137 24x Fiche 50-213,83/05/02,8305090488
- 8303160183 Application for amend to License DPR-61, revising Tech Specs re post-accident instrumentation.clarifying definition of containment integrity, adding new containment isolation valve installed & adding new limiting conditions for operation COUNSILW 0. SEARS.C.F. Connecticut Yankee Atomic Power Co 83/05/02 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp. 18445 156 24X Fichs 50-213,63/05/02,8305160183
- --8305160189 Proposed Tech Spec re post-accident instrumentation, clarifying definition of containment integrity, adding new containment isolation valve installed & adding new limiting conditions for operation a Connecticut Yankse Atomic Power Co 83/05/02 22pp 18445 158 24X Fiche 50-213,83/05/02,8305160183
- 8305090404 Comments on 821229 ltr re rev of procedures concerning river flooding & shutdown outside control room (SEP Topics II-g, B i & VII-g) Topics resolved CDUNBIL.W Q . BEARS, C F Connecticut Yankee Atomic Power Co 83/05/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18362 361 24X Fiche 50-213,83/05/03,8305090404
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EIBENHUT, D. O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- B305230510 Application to amend Licenses DPR-61, DPR-21 & DPR-65 deleting B20630 deadline date for conformance w/final rule 10CFR50 49 removing requirement for central equipment qualification file CDUNBIL.W Q. SEARS, C.F. Northeast Nuclear Energy Co (subs of Northeast Utilities). CDUNBIL.W Q Connecticut Yankee Atomic Power Co B3/05/18 CLARK, R A Operating Reactors Branch 3. CRUTCHFIELD.D Operating Reactors Branch 5. 3pp 18589 278 24X Fiche 50-000,83/05/18,8305250510
- --8305250518 Proposed Tech Bpsc changes deleting 820630 deadline for environ qualification of electrical equipment * Northeast Nuclear Energy Co (subs. of Northeast Utilities). 83/05/18 7pp 18588-281 24X Fichs 50-000,83/05/18,8305250510
- 8305230276 Forwards W'Control of Heavy Loads (C-10) Haddam Nack Plant," draft technical evaluation rept Response within 60 days of receipt of itr requested CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/19 COUNBIL, W. O. Connecticut Yankes Atomic Power Co. 2pp 18539 006 24X Fiche: 50-213,83/05/19,8305230276
- --B305230284 "Control of Heavy Loads (C-10) Haddam Nack Plant," draft technical evaluation rept. BOMBERGER, C., AHMED, N. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-358 DRFT B3/02/15 CLEMENSON, F. NRC - No Detailed Affiliation Given. 35pp 18539 OOB. 24X Fiche 50-213,83/05/19,8305230276

- Q Inspection reports, 16 Bulletins & correspondence
- 8212060385 JE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exchangic Chemical Reaction " Svc list encl
 TAYLOR. J M Division of Safeguards & Inspection Programs (Post 80103) 83/03/21 Consolidated Edison Co of New York, Inc
 112pp 18308 317 24X Fiche 50-000.83/03/21.8212060385
- 9304110686 Provides add1 info re IE Bulletin 81-03, "Flow Blockage of Caoling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)," in response to NRC 810410 & 930202 ltrs COUNSIL.W G Connecticut Yankee Atomic Power Co 93/04/04 JURDAN.E L Director's Office, Office of Inspection and Enforcement 3pp 17913 008 24X Fiche 30-213.83/04/04,830410686
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" 8vc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc. 126pp 18435-155 24X Fichs 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B305270224 "Steam Generator Tube Insp Rept for 1983 Refueling Outage "
 W/B30504 ltr
 QRAVES,R H Connecticut Yankee Atomic Power Go B3/04/25
 ALLAN,J M Region 1. Office of Director 19pp 18637 213 24X
 Fiche 50-213,B3/04/25,B305270224
- 8305020395 Ack receipt of 830407 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-06 MARTIN.T T Division of Engineering & Technical Programs 83/04/26 COUNSIL.W O Connecticut Yankee Atomic Power Co ip 18274 115 24X Fiche 50-213,83/04/26,8305020395
- ---B305020399 Responds to NRC 930308 itr re violations noted in IE Insp Rept 50-213/83-06 Corrective actions cure time for drums of solidified waste increased to 7 days & independent check for residual water performed COUNSIL,W 0 Connecticut Vankee Atomic Power Co 83/04/07 ALLAN.J M Region 1, Office of Director 4pp 18274 116 24X Fiche 50-213,83/04/26.8305020395
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/20 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 830304002B IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co., of New York Inc 122pp 18441 170 24X Fiche 30-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list end: JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche 30-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-2B, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Consolidated Edison Co of New York: Inc 117pp 1844; 001 24X Fiche 50-000:83/05/04.8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JGRDAN,E.L Division of Emergency Preparadness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co of New York, Inc. 115p 18523 248 24X Fiche 50-000/839/05/06/8303040033

- 8305190305 Responds to Items 1.2 & 4 of IE Bulletin 82-02 redegradation of threaded fasteners in RCPB.per NRC 820602 request Maint procedures & QA measures implemented Four steam generator manuay studs w/linear indications replaced COUNSIL.W Q Connecticut Yankoe Atomic Power Co 83/05/10 ALLAN.J M Region I. Diffice of Director 4pp 18501 079 24X Fiche 50~213.83/05/10.8305190305
- 8303040034 IE Into Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JDRDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York Inc 114pp 18524 003 24X Ficha 50-000,83/05/11,8303040034
- B303250497 Forwards IE Insp Rept 50-213/B3-12 on 830411-14 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 83/05/11 COUNSIL.W G Connecticut Yankse Atomic Power Co 2pp 18588 255 24X Fiche 50-213
- --8305250504 IE (nsp Rept 50-213/83-12 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737. Item II B 2. "Design Revise of Plant Shielding"

 BAUNACK, W H . EAFEN.P K . PLISCO.L R Region 1. Office of Director 83/05/10 9pp 18588 257 24X Fiche 50-213.83/05/11. 8305250497
- B305290307 Forwards IE insp Rept 50-213/83-09 on 830307-0410.No noncompliance noted STAROSTECFI, R Division of Project & Resident Programs B3/05/13 COUNSIL W G Connecticut Yantes Atomic Power Co. 2pp 18592 035 24X Fiche 50-213.83/05/13.8309250307
- --B305250309 IE Insp Rept 50-213/83-09 on 830307-0410 No noncompliance noted Major areas inspected plant aperations, review of persodic k special repts, shift logs & operating records, surveillance activities & physical security REBELOMENT, T Region I. Office of Director ELEASSER, T C Division of Project & Resident Pragrams 83/05/12 11pp 18592 037 24X Fiche 50-213.83/05/13.8305250307
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B305250560 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-07
 BELLAMV.R R Division of Engineering & Technical Programs 83/05/20 COUNSIL.H 0 Connecticut Yankee Atomic Power Co 2pp 18388 180 24% Fiche 50-213.03/05/20.8305250560
- --8309250565 Responds to NRC 830405 ltr re violations noted in IE Insp Rept 50-213/83-07 Corrective actions appropriate procedures will be revised by 830601 to include operational setpoints & high radiation areas will be reteyed COUNSIL.W Connecticut Yankee Atomic Power Co 83/05/04 MARTIN.T T Division of Engineering & Technical Programs. Spp. 18588 182 24X Fiche 30-213.83/05/20,8305250560
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.
- R Pariodic operating reports & related correspondence
- 8305270224 "Steam Generator Tube Insp Rept for 1983 Refueling Outage " W/830504 ltr GRAVES,R H Connecticut Yankee Atomic Power Co 83/04/25 ALLAN.J M Region I. Office of Director 19pp 18637 213 24X Fiche 50-213,83/04/25,8305270224
- S Reportable occurrences, LERs & related correspondence
- 8305230430 Forwards engineering evaluation rept, "Degradation of Bafety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria ASHE.F Reactor Operations Analysis Branch 83/04/18 SEYFRIT.K V Reactor Operations Analysis Dranch 2pp 18545 356 24X Fiche 50-000,83/04/18,8305230430
- --8303230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Call Cases t/or Other Possible Aging-Related Mechanisms," engineering evaluation rept LERs resafety-related battery degradation reviewed.

 ABHEF Reactor Operations Analysis Branch. 83/04/18 5pp. 18345-338 24X Fiche 50-000.83/04/18.8305230430

- 8305200608 Forwards LER 83-008/03L-0 ORAVES,R H Connecticut Yankee Atomic Power Co 83/05/12 ALLAN,J M Region 1, Office of Director 1p 18526 042 24X Fiche 50-213,83/05/12.8305200608
- --8305200701 LER 83-008/03L-0 on 830414, increase on condenser air radiation monitor indicated primary to secondary steam generator leaks Gause will be identified & steam generator tube repaired during next scheduled refueling outage WATERS, J. J. Connecticut Yankee Atomic Power Co. 83/05/12 Region 1. Office of Director 1p. 18526-043 24X Fiche 50-213,83/05/12,8305200608

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical: smergency & fire protection plans

- 8305050022 Forwards status, description & schedule for meeting requirements re emergency response capabilities, per Generic Ltr 82-33 (Buppl 1 to NUREQ-0737)
 FIEDLER.P B General Public Utilities QPU Service Corp 83/04/15
 EISENHUT, D G Division of Licensing 17pp 18342 118 24X
 Fiche 30-219, 83/04/15, 8305050022
- 8305030365 Forwards Rev 5 to security officer training & qualification plan Rev withheld (ref 10CFR2 790)
 FIEDLER.P B General Public Utilities GPU Service Corp 83/04/26
 CRUTCHFIELD.D Operating Reactors Branch 5 1p 18306 215, 24X
 Fiche 50-217.83/04/26.8305030365
- G305190260 Forwards IE 1nsp Rept 50-219/83-08 on 830308-0404 & notice of violation STARDSTECKI,R Division of Project & Resident Programs B3/05/05, FIEDLER,P D General Public Utilities GPU Service Corp 3pp 18501 247 24X Ficha 50-219,83/05/05,8305190260
- --8305190263 Notice of violation from insp on 830308-0404 Bafeguards info deleted * Region 1. Office of Director 83/05/05 ip 18501 249 24X Fiche 50-219,83/05/05,8305190260
- --8305190266 IE Insp Rept 50-219/83-08 on 830308-0404 Noncompliance noted violation of security plan provisions Safeguards info deleted COHOILL. C. THOMAS. J. KEIMIO.R R. Region 1. Office of Director 83/04/28 12pp 18501-250 24X Fiche 50-219.83/05/05,8305190260.
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law anforcement visits Svc list encl
 EISENHUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540-075 24X
 Fiche 50-000.83/05/11.8305110034
- o Adjudicatory correspondence
- B305240534 Affidavit of RE Rogan confirming util commitment to activate emergency operations facility & staff facility w/emergency support director within 1 h of site area or general emergency notification or declaration ROGAN RE Oeneral Public Utilities GPU Service Corp 83/05/20 4pg 18576 087 24X Fiche 50-000,83/05/20,8305240536
- I Financial information
- J Insurance & indemnity information
- B305230037 Forwards Endorsement 87 to NELIA Policy NF-164
 OERETY.H F General Public Utilities OPU Service Corp B3/05/16
 SALTYMAN.J. Antitrust & Economic analysis Branch (Utility Finance)
 2pp 18539 192 24X Fichs 50-219

P Operating license stage documents & correspondence

- 8305170558 Submits status of analysis of Mark I containment torus-to-drywell vacuum breaker valves for condensation oscillation & chugging loads & util proposed schedule for completion Final analysis scheduled for 830901
 FIEDLER.P B General Public Utilities GPU Service Corp 83/05/1
 E18ENHUT.D G Division of Licensing 2pp 18468 123 24X
 Fiche 50-219.80/35/11.8305170558
- B305230402 Forwards info on costs incurred from backfitting & upgrading facilities, per 830210 request Mods categorized NRC-required.
 TMI-lessons learned or util-initiated
 DIECKAMP, H General Public Utilities GPU Service Corp 83/03/08
 TOUTTELLOTTE, J Regulatory Reform Task Force 9pp 18576-318 24X
 Fiche 30-000,83/03/08.8305230402
- 8303230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- 8305020513 Grants exemption from fee requirements for 830211 application for amend to License DPR-16, deleting nonradiological water quality conditions Reimbursement forthcoming MILLER, W.O. License Fee Management Branch 83/04/25 FIEDLER, P.B. General Public Utilities OPU Service Corp. 1p. 18284-324 24X Fiche 50-219,83/04/25.8305020513
- 8305020362 Forwards plant-specific responses to six NRC questions re "safety/relief valve testing (NUREQ-0737 Itam II D 1),per 821217 request Safety/relief valve discharge piping utilizes y quencher w/sparger at discharge pipe exit FIEDLER.P B General Public Utilities OPU Service Corp 83/04/27 CRUTCHFIELD.D Operating Reactors Branch 5 21pp 18274 058 24X Fiche 50-217.83/04/27,8305020362
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to GLs 8vc list encl EISENHUT, D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305040474 Informs that analysis of aircraft traffic for facility per integrated assessment rept (NUREQ-0822) followup acceptable. GRUTCHFIELD.D. Operating Reactors Branch 5 83/05/03 FIEDLER.P D General Public Utilities OPU Service Corp. 2pp 18319 315 24X Fiche 50-219.83/05/03.8305040474
- 8305110374 Forwards addl info re NUREO-0737. Items II F 1 4, II F 1 5 & II F 1 6 concerning containment pressure, water level & hydrogen monitors, respectively, per 830106 request No obstructions would prevent hydrogen from escaping from core FIEDLER, P 8 General Public Utilities GPU Service Corp 83/05/06 CRUTCHFIELD, D Operating Reactors Branch 5 8pp 18406 279 24% Fiche 50-219, 83/05/06, 8305110374
- B305090659 Generic Ltr B3-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods, 8vc list encl EISENHUT, D G. Division of Licensing 83/05/09 Gonsolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- B3051B0A33 Forwards sefety evaluation re BWR Owners Croup B01230 response to NUREO-0737. Item II K. 3 45. "Depressurization W70ther Than Automatic Depressurization Sys " No mods required CRUTCHFIELD.D Operating Reactors Branch 5 B3/05/17, FIEDLER.P.B General Public Utilities OPU Service Corp 2pp 18486:175 24X Fiche 50-219,83/05/17,8305180433
- --8305180440 Bafety evaluation of BWR Dwners Group generic response to NUREG-0737. Item II.K. 3.45. "Depressurization W/Other Than Automatic Depressurization Sys " No mods required # Operating Reactors Branch 5 83/05/17 4pp. 18486 197 24X Fiche 30-219.83/05/17.8305180433
- 8305270082 Updates 630415 ltr re installation & operability of postaccident sampling sys per NUREO-0737. Item II 8 3 Items agreed upon at 830512 meeting listed. Installation work will be completed during current refueling outage. FIEDLER, P 8 General Public Utilities - GPU Service Corp EISENHUT, D. Q. Division of Licensing 2pp 18638 289 24X Fichs 50-219,83/05/20,8305270082

- B30531010B Forwards request for add1 info on in-plant safety relief valve tests w/Y-quencher device to determine adequacy of hydrodynamic ladd specs as part of Mark I long-term program Response within 30 days requested CRUTCHFIELD.D Operating Reactors Branch 5 B3/05/27 FIEDLER, P B General Public Utilities CPU Service Corp 3pp 18658 060 24x Fiche 50-219.83/05/27.8305310108
- 8303310213 Forwards safety evaluation of util 830328 response to NUREO-0737. Item II K 3 21. "Core Spray & LPCI Sys Low Level Initiation" Proposed mod designs acceptable CRUTCHFIELD.D Deprating Reactors Branch 3 83/05/27 FIEDLER.P B General Public Utilities OPU Service Corp 4pp 18658 142 24X Fishe 50-219.83/05/27.0305310213
- Q Inspection reports: IE Bulletins & correspondence
- B2120A03B5 IE Info Notice B3-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 1830B 317 24% Fiche 30-000.B3/03/21.B212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fichs 30-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp (B383 089 24X Fiche 50-000,83/04/22,8303040023
- 8305040184 Notification of significant licensee 830512 meeting in Forked River,NJ to discuss results of SALP TRIPP,LE Division of Project & Resident Programs B3/04/28 Division of Project & Resident Programs ip 18326 356 24X Fiche 50-219,83/04/22,8305040184
- 8303040029 IE Info Natice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enci JORDANIC L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice B3-24, "Laose Parts in Secondary Bide of Steam Generators at PMRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, B3/04/28, B30304002A
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Int 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 iE Info Natice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Byc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24x Fische. 50-00D B3/05/04, 8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 30-000, 83/05/04, 8303040031.
- 8305190260 Forwards IE Insp Rept 50-219/83-08 on 830308-0404 & notice of violation STARGSTECKI, R Division of Project & Resident Programs, 83/05/05 FIEDLER(P D General Public Utilities GPU Service Corp 3pp 18501 247 24X Fiche 50-219,83/05/03,8305190260
- ---B305190263 Notice of violation from insp on B30308-0404. Safeguards info deleted
 **Region I: Office of Director B3/05/05 ip 18501.247 24X Fiche 50-219.83/05/05.8305190260.

- --8305190266 IE Insp Rept 50-219/83-08 on 830308-0404 Nancompliance noted violation of security plan provisions Safeguards info deleted COHGILL.C . THOMAS.J , KEIMIG.R R Region 1, Office of Director 83/04/28 12pp 18501 250 24x Ficha 50-219.83/05/05.8305190260
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Beformation " Svc list encl JORDAN,E C Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Int 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- B305160018 Ack receipt of B30425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-24 MARTINA T Division of Engineering & Technical Programs 83/05/10 FIEOLER, P B General Public Utilities GPU Service Corp 18452 338 24% Fithe 50-219,83/05/10.8305160018
- --8305160023 Responds to NRC 830329 ltr re violations noted in IE lnsp Rept 50~219/82-24 Corrective actions radiological controls personnel will be reinstructed & request for measurement procedures sent to vendor Completion expected by 830931 FIEDLER.P B General Public Utilities - GPU Bervice Corp 83/04/25 MRTIN,T T Division of Engineering & Technical Programs 2pp 18452 339 24X Fiche 30-219,83/05/10,8395160018
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/11 Consulidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305250291 Forwards IE Insp. Rept 50-219/83-05 on 830214-tB,0301-04, 21-22,24 & 28 No noncompliance noted MARTINIT T Division of Engineering & Technical Programs 83/05/12 FIEDLER, B General Public Utilities - GPU Service Corp 2pp 18592-067 24X Fichs 50-219,83/05/12,8305250291
- --8305250275 IE Insp Rept 50-219/83-05 on 830214-18,0301-04,21-22,24 & 28 No noncompliance noted Wagor areas inspected inservice insp activities, including program & procedure review & licenses response to IE Bulletin 82-03 MCRREARTY,R A , DURR.J P Region 1. Office of Director 6pp 18592 069 24% Fiche 50-219,83/05/12,8305230291
- 8305200500 Forwards response to IE Bulletin 80-13, "Cracking in Core Boray Spargers " Augmented insp program includes in-vessel eram of annulus piping & sparger assemblies by combination of remote visual, ultrasonic & air testing techniques FIEDLER,P B General Public Utilities - GPU Service Corp Region i, Office of Director 13pp 18514-018 24X Fiche 50-219,83/05/13,8305200500.
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Bvc list end |
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24X Fiche B0-000.83/05/t9.8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated O41 " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fich = 50-000, 83/05/26, 8303040046
- R Periodic operating reports & related correspondence
- 830524048B Forwards INFO "Evaluation of Dyster Creek Nuclear Generating Station, 1982" Evaluation conducted 821025-1101

 ERUNNER, E. J. Division of Project & Resident Programs 83/05/06

 TAYLOR, J.M. Division of Reactor Programs (Pre 830103) 19

 18371 315 284 Fiche 50-219,03/05/06,8305240488
- --8305240476 "Evaluation of Oyster Creek Nuclear Generating Station; 1982" • Institute of Nuclear Power Operations 83/03/31 44pp 1857; 316 24X Fiche 50~219;83/05/06;8305240488
- 8305230406 Forwards monthly operating rept for Apr 1983 FIEDLER:P D General Public Utilities - QPU Service Corp 83/05/17 Division of Data Automation & Management Information 1p 18538 205 24X Ficher 50-219, 83/05/17, 8305230426
- --8305230437 Monthly operating rept for Apr 1983 BARAN.R General Public Utilities - GPU Bervice Corp 6pp 18538 207 24X Fiche 30-219.83/05/17.8305230436

- 8 Reportable occurrences, LERs & related correspondence
- E305230573 Forwards engineering evaluation rept. "Cracks & Leaks in Small Diameter Piping" BRDMN,E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT.K V Reactor Operations Analysis Branch ip 18541 342 24X Fiche 50-000
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leats associated w/unanticipated vbrattion problems require addl supports or rerouting of piping BROWN, E. J. Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fithe 50-000, 83/04/19, 8305230573
- 8305030441 Forwards LER 63-014/01Y-0 Detailed event analysis encl FIEDLER.P D General Public Utilities - QPU Bervice Corp 83/04/20 Region 1. Diffice of Director 3pp 19306-324 24X Fiche 50-217, 83/04/20, 8305030441
- --B303030447 LER B3-014/01T-0 on B30406, design deficiency discovered in heating coil control circuitry for standby gas treatment systrains Temporary regundant power feed provided until permanent mod installed during current maint outage DICKINSON A C General Public Utilities OPU Service Corp B3/04/ZO Region 1, Office of Director 1p 18304 327 24X Fiche 50-219, 83/04/20, 8305030441
- B303020459 PNS-1-83-009 on B30427, bomb threat phoned in by unidentified male caller, Evacuation initiated Search conducted winegative findings Normal operations resumed Authorities notified MADDEN, N. CODY, A.T., JUYNER, J. H. Region 1, Office of Director 983/04/27 1p 18283 310 24X Fiche 50-219,83/04/27,8305020459
- 8305190072 PND-I-B3-051 on 830516, vehicle ran stop sign & struck licensee-owned van carrying radioactive mat! Package not damaged & no contamination found Package returned to site for repackaging THOMAS: CONNER Region 1. Office of Director 83/05/16 1p 18502 068 24X Fiche 50-217:83/05/16.8305190072
- DOCKET 50-220 NINE MILE POINT NUCLEAR BTATION, UNIT 1
 C Utility Environmental Report (ER), amends & correspondence
- B305230574 Forwards repts in response to FSAR & environ rept OL stage acceptance review questions per NRC request for add1 info to B30419 submitted re OL application List of repts submitted encl

 MANGAN, C V Niagara Mohawk Power Corp B3/05/13 EIBENHUT, D Q
 Division of Licensing 3pp 18400 001 24X Fiche 50-410, B3/05/13, B308230574
- --8305230585 "316(a) Demonstration Submission, NPDE8 Permit NY 0001015. "
 * Niagara Mohawk Fower Corp 83/05/13 224pp 18600 007 24X
 Fiche 50-410,83/05/13,8305230574
- --8303230387 "Evaluation of Angeled Screen Fish Divers Bys at Oswego Bteam Station Unit 6." interim rept LABLER, Hatusky & Skelly Engineers LABE-82/0091&191-05B 82/04/30 829p 18600 231 24% Fiche 50-410.83/05/13.8305230574.
- --8305230592 "316(a) Demonstration Submission Permit NY 0020109 "

 B Power Authority of the State of New York 83/05/13 217pp 18600 308 24X Fiche, 50-410, 83/05/13, 8305230574
- --8305230599 "316(b) Demonstration Submission Permit NY 0020109 "

 # Power Authority of the State of New York 83/05/13 325pp
 19601 165 24X Fiche 50-410.83/03/13,8305230374
- --8305230603 "Fish Tag Rept Summary 1972-76" SYORR, J F Storr, J F 76/12/31 95pp 18602 130 24X Ficha 50-410,83/05/13,8305230574
- --8305230407 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Denthos, Fish, 1973 " * Quink, Lawler & Matusky Engineers 74/08/31 591pp 18602 225 24% Fichs 50-410, 83/05/13, 8305230574
- --8305230614 Vol II to "Nine Hile Point Aquatic Ecology Studies:Fish Impingement.Water Quality:1973 " e Quirk, Lawler & Metusky Engineers 74/08/31 268pp 18604 096 28% Fiche 50-410.83/03/13.8305230574
- --8305230622 Vol III to "Nine Mile Point Aquetic Ecology Studies:Part 1. Apps I-III (a-d) Methods & Meths,Statistical Procedures. Plankton:1773." > Quirk, Lawler & Matusty Engineers 83/05/13. 508pp 18605 OOI 24X Fiche 50-410.83/05/13.8305230574

- --8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 2, App III (e-p) Plankton.1973 " * Quirk. Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24X Fiche 50-410.83/05/13.8305230574
- --B305230637 Vol III to "Nine Mile Point Aquatic Ecology Btudies,Part 3, Apps 1V,V.VI Tenthos,Fish,Fish Impingement, 1973 " + Buirk, Lawler & Matusky Engineers B3/05/13 376pp 18608:006 24X Fiche 30-410.B3/05/13,B305230574
- --8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4, 305220344 Vol. 111 to "Nine mile Form Aquatic Ecology St. App VII Water Quality, 1973"

 # Quirk, Lawler & Matusky Engineers 83/05/13 291pp
 18610 015 24X Fiche 50-410,83/05/13,8305230574
- --8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV. 1974. Lawler Matusky & Bkelly Engineers 75/12/31 333pp 409 042 24X Fiche 50-410,83/05/13,8305230574 18409 042
- VII-X), 1974
 - # Lawler, Matusky & Skelly Engineers, 75/12/31 280pp 18410:304 24X Fiche 80-410,83/05/13,8305230574
- Tables name mile Point Aquetic Ecology Studies, 1975 "
 Lewier Matusky & Skelly Engineers LMSE-76/0081&191-033
 76/05/31 497pp 18611 226 24X Fiche 50-410.83/05/13,
 8305230574 --8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975 "
- --8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
 # Lawler, Matusky & Bkelly Engineers 77/05/31 489pp
 18613 001 24X Fiche, 50-410, 83/05/13, 8305230574
- --8305230678 Vol II to "Nine Hile Point Aquatic Ecology Studies, App I-IX, 1976 " Lawler, Matusky & Skelly Engineers 77/05/31 451pp 514 130 24X Fiche 50-410, 83/05/13, 8305230574
- --8303230680 "Nine Mile Point Aquatic Ecology Studies, 1977 " * Texas Instruments, Inc 78/05/31 215pp 18618 001 24X Fichs, 50-410, 83/05/13, 8305230574
- --8305230681 "316(a) Damonstration Bubmission, NPDE8 Permit 070 0X2 2 000632 NY (0003212) " * Niagara Mohawk Power Corp 83/05/13 150pp 18618 216 24X Ficha 50-410,83/05/13,8305230574
- --B305230684 "Intake Considerations.NPDE8 Permit 070 0X2 2 00632 NY (0003212) "
 - Niagara Mohawk Power Corp. 83/05/13 50pp 18619 006 24X Fiche. 30-410, 83/05/13, 8305230574
- --B305230687 "316(a) Demonstration Submission NPDES Permit 070 0X2 2 000693 NY (0003221)."

 * Niagara Mohauk Power Corp LMSE-75/0363%191/029 B3/05/13 152pp. 18619 059 24X Fiche 50-410.83/05/13.8305230574.
- --8305230671 "Intake Considerations NPDEB Permit 070 0X2 2 000633 NY (0003221) " 83/05/13 50pp 18419 205 24X
 - * Niagara Mohawk Power Corp. 83 Fiche: 50-410, 83/05/13, 8305230574
- --8305230694 "316(A) Demonstration Bubmission NPDEB Permit NY 0002184 "
 # Niagera Mohawk Power Corp. 83/05/13 460pp 18619 249 24X Fiche: 50-410,83/05/13,8305230574.
- ---8305230699 "Intake Considerations.NPDES Permit NY 0002186 "
 # Niagara Mohawk Power Corp 83/05/13 149pp 18620 349 24X
 Fiche.50-410,83/05/13,8305230574
- --8305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 5 Oswego Steam Station."

 * Stone & Webster Engineering Corp. 77/05/31 52pp 18621 138 24% Fiche. 50-410.83/05/13,8305230574
- F. Security, medical, emergency & fire protection plans
- 8305020569 Responds to B30119 ltr re changes to facility security plan. Changes consistent w/10CFR50, 54(p) & acceptable. VASBALLO. D. B. Operating Reactors Branch 2 83/04/21 SUNBER. J J Niegara Mohawk Power Corp 2pp 18284.236 24X Fiche: 50-220.63/04/21,8305020569

- 8305200386 Forwards IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance noted
 STARUSTECKI.R Division of Project & Resident Programs
 RHODE, G K Niagara Mohawk Power Corp 2pp 18518 163
 Fishe 50-220.83/04/25,8305200386 83/04/25
- --8305200392 IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance NOSCOLAY2 IE INSP REPT 50-220/83-06 on 830301-31 No noncomp noted Major areas inspected licensee actions on previous insp findings, plant tours, physical security & IE circulars Sefeguards info deleted (ref 100FR73 21 & 10CFR7 5(a)(4)) HUDSON, 8 D. KISTER.H B. Region 1, Office of Director 8 9pp 18518 165 24X Fiche 50-220, 83/04/25, 8305200386 83/04/13
- 8305040483 Forwards application for amend to License DPR-63 changing Tech Specs re fire protection program MANOAN,C V Niagara Mohawk Power Corp 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18319 273 R4X Fiche 50-220,83/05/02,8305040483
- --8305040493 Application for amend to License DPR-63 changing Tech Specs re fire protection program MANGAN,C V Niegara Mohawk Power Corp 83/05/02 2pp 18319 274 24X Fiche 50-220,83/05/02,8305040483
- ---8305040500 Proposed Tech Spec changes re fire protection program * Niagara Mohawk Power Corp 83/05/02 39pp 18319 276 2: Fiche 50-220,83/05/02,8305040483
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for QLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISEMHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 075 24X Fiche 50-000,83/05/11,8305110034
- 8305200382 Ack receipt of 830331 ltm informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-220/40-11 RAPTIN-T T Division of Engineering & Technical Programs B3 RHODE: O K Niagara Mohawk Power Corp 2pp 18517 314 24X Fiche 30-220-83/05/17,8305200382 83/05/17.
- --83052003B3 Responds to NRC 830304 ltr re violations noted in IE Health Physics Approisal Rept 50-220/80-i1 Corrective actions internal exposure control, respiratory protection program surveillance control all closed in Insp 82-20 LEMPGES.T E Niagara Mohawk Power Corp 83/03/31 HAYNES.R Region i, Office of Director 29pp 18517 316 24X Fiche 50-220.83/05/17.8305200382
- 8305240576 Informs that NUREQ-0737, Item III A 2 1. "Emergency Preparedness Upgrade Emergency Plans to App E, 10CFR50," completed Item closed VASSALLQ, D B. Operating Reactors Branch 2 83/05/18 RHQDE, C. K Niagara Mohauk Power Corp 3pp 18594 214 24X Fiche 50-220,83/05/18,8305240576
- 8305270026 Provides clarification of util position on NUREO-0737. Items I.A 1.3. "Min Shift Crew" & III A 1 2. "Staffing Level for Emergency Bituations "
 MANGAN, C V. Niagara Mohawk Power Corp 83/05/24 VASSALLO, D. B
 Operating Reactors Branch 2 2pp 18638 304 24X
 Fiche: 50-220, 83/05/24, 8305270026
- P Operating license stage documents & correspondence
- 8304210050 Clarifies B21220 environ qualification SER. Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review.per encl guidelines.due in 30 days VASSALLO.D B Operating Reactors Branch 2 83/04/08 RHODE.Q K Niagara Mohawk Power Corp 5pp 18118 347 24X Fiche 50-220.83/04/08.8304210050
- 8305020455 Generic Ltr 83-i9 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs 8vc list encl EIBENHUT, D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 30pp. 18441'120 24X Fiche' 50-000,83/05/02,8305020455
- B3050404B3 Forwards application for amend to License DPR-63 changing Tech Specs re fire protection program MANOAN.C.V. Niagara Mohawk Power Corp B3/05/02 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 18319 273 Ficha 50-220,83/05/02,8305040483
- --8305040493 Application for amend to License DPR-63 changing Tech Specs re fire protection program HANOAN.C V. Niagara Mohawk Power Corp 83/05/02. 2pp 18319 274 24X Fiche,50-220,83/05/02,8305040483.

- --B305040500 Proposed Tech Spec changes re fire protection program

 * Niagara Mohauk Power Corp B3/05/02 39pp 18319 276 24%

 Fithe 50-220, 83/05/02, 8305040483
- 8305050020 Forwards application for amend to License DPR-63.proposing Tach Spec changes to reflect change in surveillance requirements for reactor vessel matl samples MANGAN.C V Niagara Mohawk Power Corp 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18341-089 24X Fiche 30-220.83/05/02.8305050020.
- --8305050031 Application for amend to License DPR-63, proposing Tech Spec changes to reflect change in surveillance requirements for reactor vessel matl samples MANGAN.C V Niagara Nohawk Power Corp 83/05/02 2pp 18541 090 24X Fiche 50-220, 83/05/02, 8305050020
- --9305230431 Proposed Tech Spacs reflecting change in surveillance requirements for reactor vessel math samples Supporting infoenci * Niagara Hohaut Power Corp 83/05/02 4pp 18541 092 24X Fiche 50-220.83/05/02.8305050020
- 8305060043 Forwards application for amend to License DPR-63, revising Tech Spec Section 3 & 5 re radioactive matl sources to clarify inventory requirements RKODE,0 K Miagara Mohauk Power Corp 83/05/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18345 io3 24X Fiche 30-220,83/05/03,8305040043
- --8305060046 Application for amend to License DFR-63, revising Tach Spec Section 3.6.5 re radioactive matl sources to clarify invantory requirements RHODE,0 K. Niagara Mohauk Power Corp. 83/05/03.5pp. 18345-104.24X Fiche 50-220:83/05/03.8305060043
- --8305060040 Proposed Tach Spac Section 3 & 5 re radioactive matl sources. Clarifying inventory requirements

 * Niagara Mohauk Power Corp 83/05/03 2pg 18345 109 24X Fichs 50-220, 83/05/03, 8305060043
- 8305170027 Forwards Amend 52 to License DPR-63.safety evaluation & notice of issuance & availability Amend changes test duration for containment integrated leak rate test to min of 8 h
 HERMANN.8 Operating Reactors Branch 2 83/05/04 RHODE.0 K
 Niagara Hohawk Power Corp 2pp 18494 171 24X
 Fiche.30-220.83/05/04.8305170027.
- --8305170052 Amend 52 to License DPR-63 changing test duration for containment integrated leak rate test to min of 8 h VASSALLO.D B Operating Reactors Branch 2 83/05/04 4pp. 18494 173 24% Fiche 50-220,83/05/04/8305170027
- --8305170056 Safety evaluation supporting Amend 32 to License DPR-63 * Office of Nuclear Reactor Regulation, Director 83/05/04 2pp 18494 177 24X Fiche 50-220,83/05/04.8305170027
- --B305170060 Notice of issuance & availability of Amend 52 to License PPR-63 VABSALLO.D B Operating Reactors Branch 2 B3/05/04. 2pp 18494 179 24% Fiche 50-220, B3/05/04. B305170027
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24% Ficha 50-000,83/03/09,8305090659
- 8305160015 Submits schedule for providing info re NUREO-0737, Item II.B 3, "Post-Accident Sampling Capability " Formal grocedure for relating radionuclide concentrations to core damage expected by startup from 1984 refueling outage. MANGAN,C V. Niagara Mohawk Power Carp B3/03/11. EISENRUT.D.Q Division of Licensing ip 18453 162 24X Fiche, 50-220, 83/05/11, 8305360013
- 8303200345 Advises that justification for continued operation on items for which prior justification not supplied will be submitted by 830520 MANGAM.G V Niagera Mohawk Power Corp 83/05/16 VASBALLG.D.B Operating Reactors Branch 2 1p 18516 234, 24x Fiche 50-220.83/05/16.8305200345
- 8303230514 Forwards eafety evaluation re BUR Owners Group response to NUREG-0737, Item II X 3.45. "Depressuritation W/Other Than Automatic Depressuritation Bys " Action on item complete VASSALLO, b. B. Operating Reactors Granch 2 83/05/18. RHODE, G K Niegers Mohauk Power Corp 2pp. 18375 310 24X Fiche. 50-220, 83/05/18, 8305250514

- --9305250523 Bafety evaluation supporting BWR Owners Group generic response to Item II K 3 45 of NUREQ-0737, "Depressurization H/Other Than Automatic Depressurization Sys" a NRC No Detailed Affiliation Olven 83/05/18 5pp 18595 312 24X Fiche 50-220,83/05/18,8305250514
- 8305240402 Forwards info re unviron qualification of electrical equipment, per NRC requests for add1 info & clarifications Justification for continued operation completed safety-related equipment list & response to 10CFR50 47 discussed MANDAN, C V Niegara Mohawk Power Corp 83/03/20 VASSALLO, D E Operating Reactors Branch 2 104pp 18574 325 24X Fiche 50-220, 83/05/20, 8305240402
- 8305270026 Provides clarification of util position on NUREO-0737, Items I A 1 3, "Min Shift Crew" & III A 1 2, "Staffing Level for Emergency Situations "HANDAN,C V Niagara Mohawk Power Corp 83/05/24 VASSALLO,D 8 Operating Reactors Branch 2 2pp 19638 304 24X Fiche 30-220,83/05/24,8305270026
- @ Inspection reports, IE Bulletins & correspondence
- 8212040985 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list anc!
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 317 24x Fiche 30-000.83/03/21.8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 30~000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22. "BWR Safety/Relief Valve Failures "
 8vc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Rasponse (Post B30103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24% Fiche 50-000.83/04/22.8303040023.
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Bensing Sys." Svc list encl, JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381: 271. 24X Fiche 50-000.83/04/25.8303040025
- 8305200386 Forwards IE Insp Rept 50-220/83~06 on 830301-31, No nencompliance noted STANDSTECKI.R Division of Project & Resident Programs 83/04/25, RHODE.9 K Niegara Mohawk Power Corp 2pp. 18518 163 24X Fiche 30-220.83/04/25,8303200386
- --8305200392 IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance noted Major areas inspected licenese actions on previous insp findings, plant tours, physical security & IE circulars, Bafeguards info deleted (ref 100FR73 21 & 100FR7 3(a)(4)), HUBBON, B D , KIBTER, H D Region 1, Dffice of Director 83/04/13 pp 18518 165 24X Fichs 50-220.83/04/25,8303200386
- 8303040026 IE Info Notice 83-24, "Loose Parts in Becondary Bide of Steam Generators at PMRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 113pp 18382:047 24X Fiche 30~000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 8301033) 83/04/28. Consolidated Edison Co of New York: Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Swc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441:170 24X Fiche 50-000,83/05/03.8303040028.
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Byo list encl UCRDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282, 24X Fiche: 50-000,83/05/04,8303040030.
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103), B3/05/04 Consolidated Edison Co. of New York, Inc. 119pp. 18441.001 24X Fiche.50-000,B3/05/04.B303040031.

- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305200382 Ack receipt of 830331 itr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-220/80-11 MARTIN, T T Division of Engineering & Technical Programs 83/05/17 RHODE, G K Niagara Mohawk Power Corp 2pp 18517 314 24X Fiche: 50-220, 83/05/17, 8305200382
- ---B305200383 Responds to NRC 830304 ltr re violations noted in IE Health Physics Appraisal Rept 50-220/80-11 Corrective actions internal exposure control, respiratory protection program surveillance control all closed in Insp 82-20 LEMPGES, TE Niagara Mohauk Power Corp 83/03/31 HAYNES, R Region 1, Office of Director 29pp 18517 316 24X Fiche 50-220,83/05/17,8305200382
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program" 8vc 11st encl

 JORDAN,E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 0:1" Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/26 Consolidated Edison Co of New York
- R. Periodic operating reports & related correspondence
- 8304110516 Forwards "Nine Mile Point Unit 1 Aquatic Ecology Studies, 1982."
 LEMPOES, T. E. Niagara Mohawk Power Corp 83/03/30 HAYNES, R C Region 1. Office of Director 1p 17909 074 24X Fiche: 50-220, 83/03/30, 8304110516
- ---8304110519 "Nine Mile Point Unit 1 Aquatic Ecology Btudies, 1982 "

 ** Ecological Analysts, Inc. NMP11K 83/03/31 102pp
 17909:075. 24X Fiche 50-220, 83/03/30, 8304110516
- B305160097 Forwards "Annual Environ Operating Rept,Part 8 Radiological Rept. 1982 " Nonradiological aquatic ecology studies data rept for 1982 submitted under separate cover LEMPOES,T E Niagara Mohawk Power Corp B3/04/25 ALLAN,J Region 1 Office of Director 1p. 18450 224. 24% Fiche 50-220,B3/04/25,B305160097
- --8305160103 "Annual Environ Operating Rept.Part 8 Radiological Rept. 1982,"

 * Niagara Hohawk Power Corp. 83/04/30 123pp. 18450 225 24X
 Fiche: 50-220:83/04/25,8305160097
- 8305100272 Forwards "Quarterly Task Person-Rem Rept, Jan-Mar 1983," per Amend 50 to License DPR-63 MANGAN C. V. Niagara Mohawk Power Corp 83/04/29 EIBENHUT, D 6 Division of Licensing 1p 18371 301. 24X Fiche 50-220, 83/04/29, 8305100272
- --8305100277 "Guarterly Task Person-Rem Rept, Jan-Mar 1783 "
 + Niagara Mohawk Power Corp 83/04/29 27pp 18371 302 24X Fiche: 50-220, 83/04/29, 8305100272
- 8305170393 Forwards monthly operating rapt for Apr 1983 LEMPOES, T. E. Niagara Mohauk Power Corp. 83/05/10 Director's Office: Office of Inspection and Enforcement ip 18471: 205 24X Fiche: 50-220.83/05/10.8305170393
- --8305170395 Munthly operating rept for Apr 1983 ROMAN, T. W. Niagara Mohawk Power Corp. 83/05/04 5pp 18471;206 24X Fiche. 50-220, 83/05/10, 8305170393
- 8305230574 Forwards repts in response to FSAR & environ rept OL stage acceptance review questions per NRC request for add1 into to 830419 submittel re OL application.List of repts submitted encl.

 MANOAN, C. V Niagara Mohawk Power Curp 83/05/13 EISENHUT, D. O. Division of Licensing. 3pp. 18600:001 24X Fiche: 30-410,83/05/13,8305230574.

- --8305230587 "Evaluation of Angeled Screen Fish Divers Bys at Oswago Btwam Station Unit 6." interim rept * Lawler, Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 82pp 18600 231 24X Fiche 50-410.83/05/13.8305230574
- --8305230603 "Fish Tag Rept Summary 1972-76 " BTORR.J F Storr. J F 76/12/31 95pp 18602 130 24X Fiche 50-410.83/05/13.8305230574
- --B305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish. 1973" " Quirk, Lauler & Matusky Engineers 74/08/31 591pp 18602 225 24% Fiche 50-410, 83/05/13, 8305230574
- --8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies, Fish Impingement, Mater Quality, 1973" ** Quirk, Lawler & Matusky Engineers 74/08/31 268pp 18604 096 24X Fiche 30-410,83/05/13,8305230574
- --8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies Part 1. Apps 1-III (a-d) Methods & Matls Statistical Procedures, Plankton: 1973 " % Guirk Lauler & Matusky Engineers 63/05/13 508pp 18605 001 24X Fiche 50-410.83/05/13.8305230574
- --8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (4-p) Plankton. 1973 "
 * Quirk, Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24% Fiche 50-410. 83/05/13. 8305230574
- --8305230637 Vol III to "Nine Mile Point Aquatic Ecology Btudies.Part 3. Apps IV.V.VI:Benthos.Fish.Fish Impingement:1973 " + Quirk. Lawler & Matusky Engineers 83/05/13 396pp 18608 006 24X Fiche 50-410.83/05/13,8305230074
- --8305230444 Vol III to "Nine Mile Point Aquatic Ecology Studies: Part 4: App VII Water Quality, 1973 "
 - Guirk, Lauler & Matusky Engineers 83/05/13 291pp
 18610 015 24X Fiche: 30-410, 83/05/13, 8305230574
- --8305230450 Vol I to "Nins Hile Point Aquatic Ecology Studies: Chapters I-IV, 1974 "

 * Lawler: Matusky & Skelly Engineers 75/12/31 333pp 18609 042 24% Fiche: 50-410, 83/05/13, 8305230574
- --8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies. (Chapters VII-X), 1974 " # Lawler: Matusky & Skelly Engineers 75/12/31, 280pp 18610 306 24X Fiche 50-410,83/05/13,8305230574
- --8305230461 "Nine Mile Point Aquetic Ecology Studies, 1975 "

 * Lauler, Matusky & Skelly Engineers LMSE-76/0081&191-033
 76/05/31 497pp 18611 226 24% Fiche 50-410,83/05/13,8305230574
- --8305230656 Vol I to "Nime Hile Point Aquatic Ecology Studies, 1976 "
 * Lawler, Matusky & Bkelly Engineers 77/05/31, 489pp
 18613 001 24X Fiche 50-410, 83/05/13, 8305230574
- ---B305230678 Vol II to "Nine Mile Point Aquatic Ecology Btudies.App I-IX, 1976."

 ** Lawler, Matusky & Skelly Engineers 77/05/31 65ipp 19614 130. 24X Fiche 50-410,83/05/13,8305230374
- ---B305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 " * Texas Instruments, Inc. 78/05/31 215pp 18618 001 24X Fiche, 50-410, 83/05/13, 8305230574
- S Reportable occurrences, LERs & related correspondence
- 8305060426 Forwards LER 81-053/03L-1 LEMPGES,T E Niagara Mohauk Power Corp 83/04/27 ALLAN, J M Region 1, Office of Director 1p 18343 225 24X Fiche 50-220, 83/04/27, 8305060426
- --B305060428 LER 81-053/03L-1 on Bill20.6(scovered that single failure of electrical gower supply could either isolate both condenser sys or cause failure to isolate Logic for initiation & isolation of condenser sys reviewed RANDALL.R. © Niagara Mohauk Power Corp B3/04/18 Region 1, Office of Director 1p. 1B343:226 24X Fiche:50-220, B3/04/27, B305060426
- 8305060533 Forwards updated LER 83-020/03X-I LEMPGEB,T E. Niagara Hohawk Power Corp 83/04/27. ALLAN, J. M Region 1, Dffice of Director 1p 18347 303 24X Fichs 30-220 83/04/27,8305060533

- --9305060540 Updated LER 83-020/03X-1 on 830121.during major outage while performing local leak rate testing, leakage from valves 58 1-01 & 58 1-02 found to exceed Tech Specs Caused by corrosion buildup New clapper installed RANDALL:R 0 Niagara Mohawk Power Corp 83/04/27 Region 1. Office of Director 2pp 18347-304 24X Fiche 50-220.83/04/27. R305040533
- 8305200283 Forwards LER 83-006/03L-0 LEMPGES.T E Niagara Mohauk Power Corp 83/05/11 ALLAN, J M Region 1, Office of Director 1p 18517 063 24X Fiche 50-220,83/03/11,8305200283
- --8305200270 LER 83-006/03L-0 on 830411, while performing design review, discovered that poured concrete north to west walls of control room would not meet original seismic criteria. Mods made to improve wall structural loading capabilities. RANDALL.R Q Niagara Hohawk Power Corp. 83/05/11 Region 1, 04/16; of Director ip. 18517-064 24X Fiche 50-220, 83/05/(1, 8305200283).
- 8305270075 LER 83-007/03L-0 on 830419.30-ft wind direction sensor arimuth alignment found misaligned by 9 8 degrees Caused by improper alignment of mounting plates when installed Sensors readjusted & checked W1630519 ltr
 IAVENDITTI.A , MANOAN.C V Niegara Mohawk Power Corp 83/05/17 ALLAN.J M Region 1. Office of Director 3pp 18638 298 24X Fiche 50-220.83/05/17.8305270075
- DOCKET 50-225 RP1 CRITICAL EXPERIMENT
- F Security, medical, emergency & fire protection plans
- 8303170466 Forwards revised physical security plan, replacing 820426 plan Plan withheld (ref 10CFR2 790 & 73 21) MICKS.F. HARRIS,D Ransselaer Polytechnic Inst 83/04/26 HOMAS.C 0 Standardization & Special Projects Branch 1p 18470 005 24X Fiche 30-225,83/04/26,8305170466
- 8305110388 Forwards IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 83/04/29 LANEY,R T Rensselaer Polytechnic Inst 2pp 18406 212 24X Fiche 50-225/83/04/29,8305110388
- --8303110395 IE Inap Rept 50-225/83-02 on 830324-23 No noncompliance noted Major areas inspected action on previous (nap findings, facility operations, organization, logs & records, surveillance activities & emergency procedures XINNEY, W W. ELSAGSER, T C. Region 1, Office of Director 83/04/28 6pp 18406 214 24X Fiche 50-225,83/04/29,8305110388
- P Operating license stage documents & correspondence
- 8305170100 Notification of 830523-26 meetings w/Rensselaer Polytechnic Inst & LASL in Bohamectady.NY to review & evaluate reactor facility in connection w/application for OL renewal BERNARD.H Btandardisation & Special Projects Branch 83/05/12 THOMAS.C O Standardisation & Special Projects Branch 2pp 18495 338 24x Fiche 50-225.83/05/12.8305170100
- Q Inspection reports, IE Bulletins & correspondence
- 8305110388 Forwards IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted BTARDETECKI.R Division of Project & Resident Programs, 83/04/29 LAHEY.R T Renssalær Polytechnic Inst 2pp 18406:212 24X Ficha 50-225,83/04/29,8305110388
- --8305110395 IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted Major areas inspected action on previous insp findings facility operations, organization, logs & records, surveillance activities & mergency procedures KINNEY, W W. ELBASSER, T C. Region t, Office of Director 83/04/28 App 18406 214 24X Fiche 50-225.83/04/29,8305110388
- DDCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8305030334 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies PAPERIELLO.C J Region 3. Office of Director 83/04/29 REED.C. Commonwealth Edison Co. 2pp. 18297 137 24X Fiche 50-010,83/04/29,83050303036

- --830503034B Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401 e Region 3. Office of Director 83/04/29 2pp 18297 139 24X Fiche 50-010, 83/04/29, 8305030336
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche 50-000,83/05/11.8305110034
- B305120116 Advises that onsite & offsite emergency preparedness adaquate per 10CFR50, App E Emergency plans upgraded per NUREO-0737, Item 111 A 2 i Item complete CRUTCHFIELD, D Operating Reactors Branch 5 83/05/11 FARRAR, D L, Commonwealth Edison Co 3pp 18423,040 24X Fiche 50-010,83/05/11,820320146
- 8305240245 Requests schedular exemptions allowing delay in implementing iOCFR50 4B requirements for installation of fire protection mods Request based on AE, manufacturer & const personnel anticipated implementation schedule RYBAK.8 Commonwealth Edison Co. 83/05/18 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 6pp 19548: 204 24X Fiche: 50-000, 83/05/18, 8305240245
- P Operating license stage documents & correspondence
- 8305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records, 83/03/29 BREADY, J C KHC, Inc 1p 18505 230 24% Fichs 50-237,83/03/29,8305180316
- --8305180328 Notifies of results of BEP review of facility, BIRCKS,W J Diffice of the Executive Director for Operations SECY-83-017 83/01/12 47pp 18505 246 24X Fichs 50-237,83/03/29,8305180316
- B305020455 Generic Ltr B3-19 to all power reactor & tasting licenses re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EIEENHUT.D Q Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000.B3/05/02.B305020455
- 6305040446 Application for amend to Licenses DPR-19 & DPR-25, revising Tech Specs to clarify min reactor pressure when conducting scram testing following refuelling outage & requirement for isolation control rod drive pumps
 RVEAK.8 Commonwealth Edison Co 83/05/02 DENTON.H R Office of Nuclear Reactor Regulation, Director Zpp 18322 238, 24X
 Fiche 50-237,83/05/02,8305040446
- --8305040456 Proposed changes to Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & revise requirement for isolation control rad drive pumps to apply only to single rad scram testing * Commonwealth Edison Co 83/05/02 2pp. 18322 240 24X Fiche 50-237,83/05/02.8305040446
- 8305040488 Responds to 821221 & 830224 requests to withhold info submitted in connection w/application to change Tech Specs re Cycle 9 reload Request approved per 10CFR2.790(b)(5) Attachments 2 & 3 to 821221 & 830224 ltrs will be withheld, CRUTCHFIELD.D Deparating Reactors Branch 5 83/05/02 FARRAR,D L Commonwealth Edison Co 4pp 18319 266 24X Fiche, 50-237, 83/05/02, 8305504088
- 8305040520 Supplemental application for amend to Licenses DPR-19 & DPR-23, proposing changes to Tech Spec 4 3.0 1 b to verify nuclear response to control rod drive w/experienced uncoupling at power levels above 20% RYBAK.8 Commonwealth Edison Co. 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 18321 244 24% Fiche 50-237, 83/05/02, 8305040520
- --8305040524 Proposed Tech Bpec 4 3.B.i b (Page 56) requiring verification of nuclear response to control rod drive w/experienced uncoupling at power levels above 20% & Commonwealth Edison Co 83/05/02. 3pp 18321 246 24X Fiche 50-237,83/05/02,8305040520
- B305040551 Application to amend Licenses DPR-19, DPR-25, DPR-29 & DPR-30, changing App A Tech Specs re economic generation control operation
 RYBAK, B Commonwealth Edison Co B3/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321-279 24X Fiche-50-000, 83/05/02,8305040551

- --8303040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes * Commonwealth Edison Co 83/05/02 ip 18321 281 24X Fiche 50-000.83/05/02.8305040551
- 8303130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods.per 830420

 1tr Operation w/RPS mod.installed per 10CFR30 57 & w/o Tech Specs.will not compromise safe operation of facilities RYBAK.B Commonwealth Edison Co 83/05/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18439 330 24X Fiche 50-000.83/05/06.8305130209
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 30-000,83/05/09,8305090659
- 8303130038 Responds to 830316 request for addi info re NUREG-0737. Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurfication 89s Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-018 RYBAK.B Commonwealth Edison Co 83/05/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X Fiche 50-000, 83/05/10, 8305130038
- B305120370 Forwards Accident Evaluation Branch SER input re NUREG-0737, Item III D. 34: "Control Room Habitability " Bys acceptable CRUTCHFIELD, D Operating Reactors Branch 5 83/05/11 FARRAR, D L Commonwealth Edison Co 6pp 18432 275 24X Fiche 50-237, 83/03/11, 8305120370
- --8305120374 Advises that licensee proposed program re NUREQ-0737. Item III.D 3 4. "Control Room Habitability." acceptable MURPHY.D W Battelle Memorial Institute: Pacific Northwest Leboratory FIN B-2323 82/03/23 HULMAN.L.O Accident Evaluation Branch 2pp 18432 301 24X Fiche 50-237,83/05/11,8305120370
- 8305200707 Forwards request for add1 info on NUREG-0737. Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 day VABBALLO, D B Operating Reactors Branch 2 83/05/ii FARRAR, D L Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000, 83/05/ii, 230/03/077
- 8305200186 Notifies that 830425 amend application for proposed Tech Bpec changes re TMI Action Item II K 3 15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys DI00S.R.M. License Fee Management Branch 83/05/12 FARRAR.D L Commonwealth Edison Co. 1p 18540 228 24X Fiche 50-000,83/05/12.8305200186
- 8305180374 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment QE affidavit per 100FR2 790 received Westinghouse affidavit farthcoming RYBAK.9 Commonwealth Edison Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 18490,347 24X Fiche: 50-000,83/05/13,8305180376
- B305260290 Commits to resolution of three open items re NUREQ-0612, "Control of Heavy Loads," Using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable RYBAK, B. Commonwealth Edison Co B3/05/19. DENTON, H R. Dffice of Nuclear Reactor Regulation. Director ip 18625.354 24X Fiche.50-237,83/05/19,8305260290
- 8305270419 Notifies that response to 830316,0510 & il requests for additinfo re TMI Item Il K 3 28. "Gualification of Automatic Depressurization Sys Accumulators." addressed in 830510 ltr RYBAK, B. Commonwealth Edison Co 83/05/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Ip 18642 298 24X Fiche: 50-000,83/05/23,8305270419
- 8305310037 Advises that listed items of shubber action plan sent on B30520.per 830513 ltr Bubmittal of plan for checking for clamp interference during 62-day shubber insp deferred until 830603 to incorporate binding study results.

 RYBAK.B Commonwealth Edison Co B3/05/24 KEPPLER.J 9, Region 3, Office of Director 18pp. 18653 186 24X Fiche 50-237, B3/05/24, B305310037
- 8305310086 Notification of 830614 meeting w/util in Betheeda, MD to discuss util DCRDR program plan OLBERTI.R.A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658-063, 24X Fiche. 50-000, 83/05/26, 8305310086

- 8305310028 Advises that requirements of NUREG-0737, Item II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved.per 821220 & 801215 submittals CRUTCHFIELD, D Operating Reactors Branch 5 83/05/27 FARRAR, D L Commonwealth Edison Co 7pp 18653 213 24X Fiche 50-000, 83/05/27, 8305310028
- G Inspection reports, IE Bulletins & correspondence
- 8212050385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list and!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24x Fiche 30-000, 83/03/21, 8212060385
- 8304040268 Requests that insp program re [E Bulletin 80-13, "Cracking in Core Spray Spargers," be performed every 3 yrs in conjunction w/reactor vessel internal insp No abnormalities noted per subj bulletin RYBAK.B Commonwealth Edison Co 83/03/25 KEPPLER.J Q Region 3. Office of Director 2pp 17816 282 24X Fiche 50-237,83/03/25,830400268
- B305020467 Forwards IE Insp Repts 50-010/83-06.50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted STREETER. J F Region 3. Office of Director 83/04/13 REED. C Commonwealth Edison Co 2pp 18283 073 24X Fiche 50-010.83/04/13, 8305020467
- --8305020480 IE Insp Repts 50-010/83-06, 50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted Major areas inspected operational safety, maint surveillance, licenses events, plant trips, refueling activities & refueling surveillance TONQUE.T M. JORDAN, M J., STASEK.S Region 3, Office of Director 83/04/12 16pp 18283 075 24X Fiche 50-010.83/04/13.8305020467
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN.BC L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22. "BHR Bafety/Relief Valve Failures "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc. i12pp 18383 087 24X Fiche 50-000, 83/04/22, 83003040023
- 8305100379 Forwards IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25,0301,09 & 14 & notice of violation HIND, J A. Division of Radiological & Materials Safety Programs 83/04/22 REED, C. Commonwealth Edison Co. 2pp 18377 328 24X Fichs 50-237,83/04/22,8305100379
- --8305i003B7 Notice of violation from insp on 830222-25.030i.09 & 14 HIND, J A Region 3, Office of Director 83/04/22 2pp 18377 330 24% Fiche 50-237.83/04/22.8305100379
- --B305100402 IE insp Repts 50-237/B3-08 & 50-249/B3-07 on 830222-25,0301, op & 14 Noncompitance noted DOT radiation limits exceeded & failure to follow health physics procedures PAUL.R A, LOVENDALE,P C, GREGER,L R, Region 3, Office of Director 83/04/21 12pp 18377 332 24% Fiche 50-237,83/04/22,8305100379
- --8305100416 IE Waste Packaging Insp Rept 15000046/83-03 on 830216 Noncompliance noted dose rate of 3 mrem/h existed in truck cab. THOMAS.R D , BOOK.H E Region 5, Office of Director ELSEN.M J Hashington, State of 83/02/28 4pp 18377 344, 24X Fiche 30-237.83/04/22,8305100379
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Bvc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Respanse (Post 830103) 83/04/25. Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 50-000.83/04/25,8303040025
- 8305020100 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 SHAFER: M D Region 3, Office of Director 83/04/25 REED, C. Commonwealth Edison Co. ip 18278 243 24X Fiche 50-010,83/04/25, 8308780100

DOCKETED ITEMS

- B30502010& Responds to NRC B30304 ltr re violations noted in IE Insp. Repts 50-010/83-05.50-237/83-05 & 50-249/83-04 Corrective ections Amend 71 retissued & incorporated into Tech Specs Corporate GA dept will audit accounting & followup sys FARRAB, D.L. Commonwealth Edison Co. 83/03/30 KEPPLER, J. G. Region 3, Office of Director 3pp. 18278 244 24X Fiche 50-010, 83/04/25, 8305020100
- 05120440 Forwards IE Insp Rept 50-237/83-03 on 830111-0324 & notice OSIZO440 FORMARDS 16 INSPIRED OF VIOLETION OF VIOLETION OF VIOLETION OF VIOLETION OF VIOLETION OF THE STATE O
- 8305120444 Notice of violation from insp on 830111-0324 LITTLE,W B Region 3, Office of Director 83/04/25 18431 073 24K Fiche 50-237,83/04/25,8305120440 83/04/25 1p
- 8305120449 IE Insp Rept 50-237/83-03 on 830111-0324 Noncompliance noted failure to control recirculation riser sipe well rod stude. Unused rolls of E308L-16 stainless steel wire KEY, H J., DANIELSON, D H Region 3, Office of Director 11pp 18431: 094 24X Fiche 50-237,83/04/25,8305120440.
- 03040026 IE Info Notice B3-24, "Loose Parts in Secondary Bids of Bteam Generators at PHRs " Byo list and JORDAN, E L. Division of Emergency Preparedness & Engineering Responses (Post B3D103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp. 18392 047 24X Fiche 30-000, B3/04/28, 8303040026
- 103040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater Kigh Temp Trip Setpoint Adjustment " Svc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New Yark: Inc 118pp 18382.165. 24X Fiche 50-000,83/04/28.8303040027
- 105040441 Confirms plans to mest u/util on 830505 in Olen Ellyn, IL to discuss status of actions taken re 830317 confirmatory action ltr concerning main steam line snubbers NORELIUS, C E Division of Project & Resident Programs 83/04/28 REED, C Commonwealth Edison Co ip 85343, 147 24X Ficha: 50-237, 83/04/28, 8305060441
- 05100092 Provides status of safe shutdown path support installation, par IE Dullatin 79-14 & util 830416 commitment Remaining accessible hanger & four inaccessible hangers util be completed by mid-May & during Fail 1983 outage: respectively RYBAX.B Commonwealth Edison to 83/04/28 KEPPLER.J Q Region 3, Office of Director 2pp 18377 218 24X Fiche 50-237,83/04/28. 8305100092
- 105030334 Discusses IE Fmergency Preparedness Insp Repts 30-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies PAPERIELLO, C.J. Region 3, Office of Director 83/04/29 REED, C. Commonwealth Edison Co. 2pp. 18297 137. 24X Fiche 50-010,83/04/29,8303030334
- -8308030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401 + Region 3, Office of Director 93/04/29 2pp 18297 139 24X Fiche 50-010, 83/04/29, 8305030336
- 303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vecuum Breakers " Svc list encl UDRDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 930103). 83/05/03 Consolidated Edison Co. of New York: Inc 122pp. 18441 170 24X Fiche 50-000.83/05/03;8303040028
- 1910015059
- -8305100170 Responds to NRC 830311 ltr re deficiencies noted in IE Insp. Repts 50-010/82-17,50-237/82-24 & 50-249/82-24 Corrective actions written agreement EPIP200-11 re PMF for Units 2 & 3 between Corps of Engineers & util to be revised RYBAK: B Commonwealth Edison Co 83/04/11 KEPPLER: J Q Region 3, 09fice of Director 4pp 18374 319 24X Fichs 50-010, 83/05/03,8305100181.
- 303040030 IE Info Notice 83-27, "Operational Response to Events JOSOPHOLOGY IN THE CONTROLLE STATE OF THE TOTAL RESPONSE TO EVERTS
 CONCERNING Deliberate Acts Directed Against Plant
 Equipment " Svc list encl.
 JOHDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/05/04 Consolidated Edison Co. of New
 York: Int 112pp. 18382,282 24K Fiche 50-000,83/05/04,8303040030.

- B303040031 IE Info Notice B3-28. "Criteria for Protective Action Recommendations for General Emergencies" Byc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post B30103) B3/03/04 Consolidated Edison Co. 18441 001 24X Fich+ 50-000.83/05/04.8303040031 117pp
- 8303040033 IE Info Notice 83~29, "Fuel Binding Caused by Fuel Rack Daformation " Svc list ancl JORDAN-E.L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New 114pp. 18524-003 24X Fiche 50-000,83/05/11,8303040034.
- 8305200421 Advises that util response to 820714 confirmatory action ltr rs IE Bullstin 79-14, piping analysis to restore hot shutdown peth piping sys to FSAR requirements by 830215, acceptable. 8PE89ARD, R L Division of Engineering 83/05/18 REED, C Commonwealth Edison Co. 2pp 18517 116, 24x Fiche. 50-000, 83/05/18, 8303200421
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." 303040040 IE 1870 ROSSE SECTION 100 ROSSE ROSSE
- B305250377 Forwards "QE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to 1E Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to 1E Bulletin 79-01B. "RYBAK.B Commonwealth Edison Co 83/05/19 DENTON, H R C Nuclear Reactor Regulation, Director 2,118pp 18578 001 Fiche: 50-000, 83/05/19,8305250377 Office of
- --8305250393 "GE-NEBS Electrical Penetration Assembly Gualification * Becatel Corp. 83/05/18, 354pp 18578.175 24X Fiche 50-000,83/05/19,8305250377.
- --B305250399 Rev 2 to Vols 1 & 2 to "Environ Qualification of Electrical Equipment Dresden Nuclear Power Station Unit 2" + Bechtel Corp B3/05/31. 416pp 18579 171. 24X Fiche: 50-000:83/05/19.B305280377
- --8305250407 Rev 2 to Vols 1 & 2 to "Response to IE Bulletin 79-018 for Dresden Nuclear Power Station Unit 3 "
 + Bechtel Corp 83/05/31 387pp. 18380.226 24X Fiche, 50-000.83/05/19.8305250377
- --8305250413 Rev 2 to Vols 1-3 to "Response to IE Builetin 79-018.Guad Cities Nuclear Power Station Units 1 & 2 " + Bechtel Corp. 83/05/31 786pp. 18581:253 24X Fiche: 50-000.83/05/19.8305250377
- 8305270395 Notifies that work to be performed on mesonry walls, per IE Bulletin 80-11, "Masonry Wall Design," will be completed on 830715. Thirty mesonry walls required mods RYBAK.B Commonwealth Edison Co. 83/05/23 KEPPLER.J O Region 30/fice of Director 1p 18642.335 24X Fiche 30-237.83/05/23.8302270395.
- B305310113 Ack receipt of B30519 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/83-03, LITTLE: W B Region 3, Office of Director B3/05/24 REED, C. Commonwealth Edison Co. ip. IB458:070. 24% Fiche 50-237.83/05/24, 8305310113.
- --8303310117 Responds to NRC 830423 ltr re violations noted in IE Insp Rept 50-237/83-03 Corrective actions; uncontrolled welding matls disposed of & personnel instructed re control of
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl JORDAN'E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/26, Consolidated Edison Co. of New York, Inc. 114pp, 18647-007 24X Fiche.30-000,83/03/26,8303040046

- R Periodic operating reports & related correspondence
- 8305130197 Forwards monthly operating rept for Apr 1983 BCOTT,D J Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement 1p 18440 050 24X Fiche 30-237,83/05/02,8305130197
- --8305130202 Monthly operating rept for Apr 1983 BCHROEDER,B A Commonwealth Edison Co 83/05/02 18pp 18440 051 24X Fiche 50-237,83/05/02,8305130197
- B Reportable occurrences: LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept. "Cracks & Leaks in Bmall Diameter Piping " BROWN:E J Reactor Operations Analysis Branch 83/04/19 BEYFRIT.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000
- --B305230617 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROHNE J. Reactor Operations Analysis Branch. 83/04/19 9pp 18541 343 24X Fiche 50-000.83/04/19.8305230573
- 8305060511 Forwards updated LER 83-008/01X-1 8COTT.D J Commonwealth Edison Co 83/04/25 KEPPLER, J 9 Regio 3. Office of Director 1p 18348 083 24X Fiche 50-237,83/04/25, 8305060511
- --8305060517 Updated LER 83-008/01X-1 on 830115, during inservice insp of recirculation piping, rejectable indications discovered in 10 circumferential welds Caused by intergranular stress corrosion cracking Welds will be examined at mid-cycle HYLKA:R Commonwealth Edison Co 83/04/25 Region 3, Office of Director 12pp 18348 084 24X Fiche 50-237,83/04/25,8305060511
- 8305060416 Forwards LER 83-024/03L-0 SCOTT.D J Commonwealth Edison Co 83/04/26 KEPPLER.J Q Region 3. Office of Director ip 18343 i90 24X Fiche 50-237.83/04/26. 8305060416
- --8305060422 LER 83-024/03L-0. on 830403, while performing core apray operability test.valve MO 1402-4A failed to open Caused by burned out motor Motor replaced ANANDAPPA. A Commenwealth Edison Co 83/04/26 Region 3, Office of Director, 2pp 18343 [7] 24X Fiche. 50-237.83/04/26. R30306041A.
- 8305060590 Forwards LER 83-022/03L-0 8CDTT,D J Commonwealth Edison Co. 83/04/27 KEPPLER,J. 0, Region 3, Office of Director. ip. 18349 011 24X Fiche 50-237,83/04/27, 8305040890
- --8305060599 LER 83-022/03L-0.on 830403.during refuel outage.no position indication found for core spray injection valve MO 1402-258 Valve would not open Caused by one phase of breaker tripping before design overload reached.

 ANANDAPPA: A Commonwealth Edison Co 83/04/27 Region 3. Office of Director 2pp 18349 012 24X Fiche 50-237.83/04/27, 8305060590
- 8305060603 Forwards LER 83-023/03L-0 8COTT,D J Commonwealth Edison Co. 83/04/27 KEPPLER,J 9. Region 3. Office of Director 1p. 18348 247 24% Fiche 50-237,83/04/27, 8305060603
- --B305060611 LER B3-023/03L-0 on B30406, during surveillance of component cooling svc water vault floor drain (DDS 4400-1), condensate pump room flood switch actuated & drain valve A0-2-4797-74 failed to close, Cause undetermined, Investigation underway COVLE, L. M. Commonwealth Edison Co. B3/04/27 Region 3, Office of Director, 2pp 18348 248, 24X Fiche 50-237, B3/04/27, B305060603.
- 8305060496 Forwards LER 83-029/01T-0 BCOTT.D.J. Commonwealth Edison Co 83/04/29 KEPPLER.J.O. Regio 3. Office of Director. 1p 18348 149 24% Fiche 50-237.83/04/29. 8305060486
- --8305060492 LER 83-029/01T-0 on 830418, air leaks found at actuating arms for six torus-to-drywell vacuum breakers Caused by failure of vacuum breaker actuating arm seals All seals replaced w/improved design. No further leakage problems observed HHALEN.R.J Commonwealth Edison Co 83/04/29 Region 3. Office of Director 4pp 18348-150 24X Fiche 50-237.83/04/29, 8305060486

- B305170134 Forwards LER 83-025/03L-0 SCOTT:D J Commonwealth Edison Co B3/05/04 KEPPLER, J Q Region 3. Office of Director 2pp 18466 267 24% Fiche 50-237.83/05/04. 8305170134
- --B305170140 LER 83-025/03L-0 on 830409, reactor bldg fuel pool channel A high radiation alarm activated, causing reactor bldg vent sys to trip Caused by burned out relay coil Relay coil replaced MERRITT,8 Commonwealth Edison Co 83/05/04 Region 3, Office of Director ip 18466 267 24X Fichs 50-237, 83/05/04, 8305170134
- B305240202 Updated LER 83-011/01X-1 on 830203, NDT performed on new fillet weld Crack found between torus shell & ring girder separating bays 8 & 9 Cause not determined Flaw removed by grinding & filled w/hydrogen electrode deposit W/830304 ltr TANGHEE, D , SCOTT, D J Commonwealth Edison Co 83/05/04 KEPPLER, J O Region 3, Office of Director 4pp 18348 027 24X Fiche 50-237, 83/05/04, 8305240202
- 8305170159 Forwards LER 83-027/03L-0 8CDTT.D J Commonwealth Edison Co 83/05/05 KEPPLER.J 0 Region 3. Office of Director 2pp 18466 294 24x Fiche 50-237.83/05/05. 8305170159
- --8305170143 LER 83-027/03L-0 on 830408, during valve insp.grease discovered on seats & discs Caused by maint procedures not prohibiting personnel placing grease on seat & disc Grease removed, valves repaired & procedures will be revised STACHNIAK.R Commonwealth Edison Co 83/05/05 Region 3, Office of Director 3pp 18466 296 24X Fiche 50-237,83/05/05,8305170159
- 8305240207 LER B3-026/03L-0 on 830412, during refueling outage, snubber 52 failed during test required to return snubber to store room Cause unknown Investigation underway M/830510 ltr RHEE, 8 . BCOTT, D J Cammonwealth Edison Co 83/03/10 KEPPLER, J Q Region 3, Office of Director 3pp 18548 016 24X Fiche 50-237, 83/05/10.8305240207
- 8305240494 LER 93-028/03L-0 on 830417. Juring refueling, Channel B fuel pool radiation monitor downscals alarm received Alarm could not be reset Caused by burned out coil in relay 1705-108 Relay replaced w/spare W/830510 ltr HERRITT. 8. SCOTT. D J Commonwealth Edison Co 83/05/10 KEPPLER. J G Region 3, Office of Director 3pp 18571 176 24X Fiche 50-237,83/05/10.8305240494
- 8305240335 LER 83-030/03L-0 on 83042i.24-volt low voltage power supply failed, causing channel A isolation condensor vent monitor, reactor bidg vent & fuel pool area radiation monitor to move downscale Caused by bad voltage regulator W/830511 ltr MERRITTIS : 800TT D J Commonwealth Edison Co. 83/05/11 KEPPLERJ O Region 3, Office of Director 3pp 18574 082 24X Fiche 50-237,83/05/11,8305240335
- 8305200295 Forwards 7-day evaluation.out-of-plant test results & action plan re main steam line snubber failures investigation of clamp interference & possibility of thermal growth continuing RYBAK.B Commonwealth Edison Co 83/05/13 KEPPLER.J 0 Region 3, Office of Director 3pp 18516 324 24X Fiche 50-237.83/05/13, 8305200295
- --8305200301 "Dresden-2 Main Steam Monitoring Procedure 7-Day Data Evaluation "
- --8305200307 "Preliminary Test Rept on Dynamic Testing of Drasden 2
 Mechanical Pipe Bnubbers "
 NOTHELFER, T , PLUMMER, M C NUTECH Engineers, Inc * Commonwealth
 Edison Co COMOSB 0011 0007 83/05/11 18pp 18517 004 24X
 Fiche
- 8303310182 LER 83-032/03L-0 on 830425, during unit startup, reactor water sample not pulled every 4 h per Tech Spec requirements. Caused by lack of communication between technicians during shift change & failure to use flashing sign. M/830517 ltr TURNOUEST.L. SCOTT, D J Commonwealth Edison Co 83/05/17 KEPPLER, J Q. Region 3, 0ffice of Director 3pp 18658, 168 24X Fiche 50-237, 83/05/17, 8305310182
- 8305310149 LER 83-033/03L-0 on 830426, during testing of MSIV iD & 2D, half scram occurred on reactor protection sys. Caused by failure of scram interlock contact of limit switch to reset after valve iB tested Switch edjusted W/8305iB ltr BEVERLY,K & SCOTID J Commonwealth Edison Co 83/05/18 KEPPLERJ 9. Region 3, Office of Director 3pp. 18659 141 24X Fichs 50-237,83/05/18,8305310149

- 8305340165 LER 83-041/OIL-O on 830506, calibr of drywell pressure switch DIS 1500-4, relay 1530-297 failed to pick up when pressure switch 1501-620 functionally teated Caused by loose connection in wiring circuitry W/830520 ltr CHRISTEL, B. SCOTT, D. J. Commonwealth Edison Co. 83/05/19 KEPPLER, J. & Region 3, Office of Director. 3pp. 18652 287 24X Fichs 50-237, 83/05/19, 8305310165
- B305310158 LER 83-038/03L-0 on B30505, average power range monitor (APRM) 4 flow biased rod black setpoint found in excess of Tech Spec limit Caused by instrument drift APRM 4 adjusted per Procedure DIS-700-6 W/B30320 ltr
 BEVERLY, K P , SCOTT, D J Commonwealth Edison Co 83/05/20
 KEPPLERJ Q Region 3, Office of Director 3pp 18651 224 24X
 Fichs 50-237,83/05/20.8305310138

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

- R Pariodic operating reports & related correspondence
- 8303060377 Forwards semiannual survey repts for 820317-18 & 0916, per Amend 10 to License NS-1 Info contains TLD monitoring badge locations, direct radiation survey contamination survey results & environ sample analysis rept GUERRY, J E South Carolina, State of 83/02/28 NRC No Datailed Apfillation Given 3pp 18347 257 24% Fiche 50-238,83/02/28,8305060577
- --83050605B2 "Semiannual Survey Rept " # South Carolina, State of 82/03/18 14pp 18347 260 24X Fiche 50-238,83/02/28,8305060577
- --8305060586 "Semiannual Buryey Rept"
 * South Caroline, State of 82/09/16 7pp 18347, 274 24X
 Fiche 50-238,83/02/28,8305060577
- --8305060613 "Procedure for Testing Controlled Radiation Area Intrusion Alarm " HALDRUP.U South Carolina, State of 82/12/02 9pp 18347-283 24X Fiche 50-238,83/02/28,8305060577
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8304270278 Requests that Rev 8 to security plan be modified to incorporate commitments re frequency of alarm station amergency power annunciator sys tests Resubmittal within 30 days requested ALLAN.J M Region I, Office of Director 83/04/21 MAIER.J E Rochester Gas & Electric Corp 3pp 18232 287 24X Fiche 50-244.83/04/21.8304270278
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for QLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EIBENHUT,D Q. Division of Licensing 83/05/il Consolidated Edison Co of New York, Inc 16pp 18540 075 24X
 Fichs 50-000,83/05/ii,8305110034
- 8305180361 Notification of 830518 meeting w/Hestinghouse in Dethesda. HD to discuss NRC review of safety parameter display sys for emergency response facility design & V & V process.

 DICK. 0. F Operating Reactors Branch 5 83/05/16 CRUTCHFIELD: D Operating Reactors Branch 5 3pp 18485 223 24X Fiche: 50-244: 83/05/16: 8305180361
- B303310218 Forwards revised Page 3,6,modifying Rev 18 to security plan re testing frequency of emergency power annunciation sys Page withheid (ref 100FR73 21). MAIER.JE Rochester Gas & Electric Corp B3/05/19 ALLAN.J H Region 1, Office of Director 1p 18658 L48 24X Ficher 50-244,83/05/19,8305310218
- B305270077 Advises that NUREC-0737. Item III A 2 1, "Emergency Preparadness. Upgrade Emergency Plans to App E, 10CFR50," complete CRUTCHFIELD. D Operating Reactors Branch 5 83/05/25, MAIER, J & Rochaster Oas & Electric Corp 3pp 18638 153 24X Fiche: 30-244.83/05/28, 80305270077
- J. Insurance & indemnity information
- B305120110 Forwards Endorsement B6 to NELIA Policy NF-170 & Endorsement 72 to MAELU Policy MF-46.
 SINIBI, J M Marsh & McLennan, Inc 83/05/05 SALTZMAN, J D. Assistant Director for State & Licensee Relations 3pp. 18428, 257. 24X Fiche 50-244, 83/05/05, 8305;20110.

- D Advisory Committee on Reactor Safeguards reports & correspondence
- B305130290 Summary of 268th AGRS meetings on 820812-14 in Washington: BC * AGRS - Advisory Committee on Reactor Safeguards 83/05/05 AGRS - Advisory Committee on Reactor Safeguards 529pp 18458 225 24X Fiche 50-000: 83/05/05: 8309130270
- P Operating license stage documents & correspondence
- 8305030021 Forwards "Structural Reanalysis Program for RE Oinne Nuclear Power Plant," per SEP Topics II-2 A: III-2, III-4 A & III-7 B Final design expected to require 18-24 months Final installation expected to require 2 to 2-1/2 yrs MAIER-JE Ruchester Gas & Electric Corp 83/04/22 CRUTCHFIELD, D Operating Reactors Branch 5. 2pp 18300 128 24X Fiche 50-244.83/04/22,8305030021
- --8305030024 "Structural Reanalysis Program for RE Dinna Nuclear Power Plant " a Rochester Gas & Electric Corp 83/04/22 38pp 18300:130 24X Fiche 50-244,83/04/22,8305030021
- 8305030352 Submits add1 info re proposed tubesheet sleeve design, per request Info addresses inspectability, pullout & corrosion potential Fifty tubesheet sleeves will be installed during present refueling outage, per 830420 ltr.
 MAIER. J E Rochester Cas & Electric Corp 83/04/26 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18277 099 24X Fiche 50-244,83/04/26,8305030352
- 8305020060 Forwards info re blocking of safety injection signal during cooldown based on review of PWRs using improper procedure Response requested within 30 days CRUTCHFIELD.D Operating Reactors Branch 5 83/04/28 MAIER, J E. Rochester Gas & Electric Corp. 4pp 19279 102 24X Fiche 50-244, 83/04/28, 8305020060
- 8305020499 Approves installation of containment closure device to provide containment isolation barrier during refueling activities per 830218 ltr
 CRUTCHFIELD, D. Operating Reactors Branch 5 83/04/29 MAIER, J.E. Rochester Gas & Electric Corp. 2pp. 18282 296 24X
 Fiche 50-244,83/04/28,8305020499
- 8305040271 Forwards "Containment Vessel Evaluation of Dome Liner & Studs," re SEP Topic III-7.8, "Load Combinations (Containment Liner Analysis) "

 MAIER.J E Rochester Gas & Electric Corp 83/04/28 CRUTCHFIELD.8 Operating Reactors Branch 5 ip, 18344 332 24X Fichs 50-244,83/04/28,8305040271
- --B305060277 "Containment Vessel Evaluation of Dome Liner & Btuds "FULTON, J F , HERR, J C , CHEN, C Gilbert/Commonwealth Cos, 83/04/15 51pp 18344 333 24X Fiche 50-244,83/04/28,8305060271,
- 8305060404 Forwards list of safety-related masonry walls per SEP Topics II-2 A.III-2: III-4 A & III-7 B, "Structural Reanalysis Program Block Walls"

 MAIER J E Rochester Cas & Electric Corp. 83/04/28 CRUTCHFIELD.D. Operating Reactors Branch 5 Spp 18343 187 24X Fiche 30-244.83/04/28.8305060404
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EIBENHUT, D Q. Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- B305:30084 Responds to G Dick & M Wigdon 820301 telcon re fuse coordination on control circuit for level control valve 427 RA Bakar 8304:5 & 19 summaries justifying proper fuse coordination encl MAIER.J E Rochester Cas & Electric Corp 83/05/02 CRUTCHFIELD, D Operating Reactors Branch 5 3pp. 18436:266 24X Fiche: 30-244,83/05/02.8305:330084
- --8305130086 "Level Control Valve 427 Fuse Coordination Ginna Station "
 BRICKS,G , MANLEY, J Rochester Gas & Electric Corp 0383-03
 83/04/15, 4pp 18436 269. 24X Fiche 50-244,83/05/02,8305130084
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Syc list encl EISENHUT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche.50-000.83/03/09.8305090659

- 8305110426 Notification of 830512 meeting w/util in Bethesda: MD to discuss ongoing steam generator tube sleeving program DICK.0 F Operating Reactors Branch 5 83/05/10 CRUTCHFIELD. Operating Reactors Branch 5 2pp 18392 014 24X Fiche 50-244.83/05/10.8305110426 . 3 83/05/10 CRUTCHFIELD, D 18392 014 24X
- B305180340 Notification of B30520 meeting w/util in Bethesda.HD to discuss results of tube sleeving Portions of meeting, including discussion of proprietary info, will be closed DICK, 0 F Operating Reactors Branch 5 B3/05/17 CRUTCHFIELD, I Operating Reactors Branch 3 3pp 18486 057 24X Fiche 30-244, B3/05/17, B305180340 17 CRUTCHFIELD, D 24X
- 8305310085 Responds to 10CFR50 49, "Environ Qualification of Electrical 305310085 Responds to 10CFR50 49. "Environ Qualification of Equipment " Status of review contained in 821213 SER Equipment analysis, test, design & procurement may delay establishing final environ qualification by end of 1984 MAIER, J E Rochester Qas & Electric Corp 83/05/19 (Operating Reactors Branch 5 2pp 18655 074 24X Fiche 50-244,83/05/19,8305310085 CRUTCHFIELD, D
- B305310125 Forwards Apps A.B.C & D to structural reanalysis program re BEP Topics II-2 A.III-2.III-4 A & III-7 B transmitted by B30422 correspondence
 MAIER.J E Rochester Gas & Electric Corp B3/05/19 CRUTCHFIELD
 Opensting Reactors Branch 5 1p 16458 171 24X
 Fichs 50-244.83/05/19.8303310125 89/05/19 CRUTCHFIELD, D
- --8305310133 App A to structural reanelysis program, "Evaluation Rept for NRC SEP Topics II-2 A, 'Severe Weather Phenomena,' III-2, 'Hind & Tornado Loading' & III-7 B, 'Design Codes, Design Criteria & Load Combinations '"

 * Rochester Oas & Electric Corp 83/03/31 85pp 18658 172 24X Fiche 50-244,83/05/19,8305310125
- --8305310141 App B to structural reanalysis program, "Criticality Analysis for Spent Fuel Storage Racks " = Pickard, Lowe & Garrick, Inc 83/03/31 5pp 18658 257 24X Fiche 50-244.83/05/17.8305310125
- ---8305310157 App C to structural reanalysis program, "Utility Pole Tornado Missile Trajectory Analysis " TWIBDALE.L A , DUNN, W L Applied Research Associates, Inc 83/03/08 23pp 1858.262 24X Fiche 30-244.83/05/19.8305310125
- --8303310159 App D to structural reanalysis program, "Uniform Load Test on Wall Panels" & "Physical Testing of Fasteners " * Pittsburgh Testing Laboratory 83/03/03 112pp 18458 285 24X Fiche. 50-244, 83/05/19.8305310125
- 8305310020 Forwards two oversize drawings to assist in review of safety injection & auxiliary cooling sys.in response to NRC request Aperture cards are available in PDR MAIER, J E Rochester Qas & Electric Corp 83/05/20 CRUTCHFIELD, D Operating Reactors Branch 5 p 18655 126 24X Fiche 50-244,83/05/20,8305310020
- 8305310232 Bubmits addl info re potential effects of flood levels from Deer Creek in excess of std project flood levels from Deer Creek in excess of std project flood oem EEP Topic II-3,8 Additional cost of mod to meet PMF unwarranted MAIER, J E. Rochester Qas & Electric Corp. 83/05/20 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18558 084 24X Fiche 50-244,83/05/20,8305310232
- 8305260237 Summary of B30512 site meeting w/util re steam generator sleeving program Sleeving mode adequate pending formal submittel of mod procedures, review of insp results & stress analysis Next meeting scheduled for B30520 DICK, Q.F. Operating Reactors Branch 5 83/05/24 Operating Reactors Branch 5 11pp 18622.076 24X Fiche 50-244.83/05/24, B309260237
- B305270060 Forwards safety evaluation of util response to BER, NUREQ-0916, Item 3 re effluent radioactivity monitoring sys alarm setpoints & surveillance requirements. Monitoring eys acceptable CRUTCHFIELD, D Operating Reactors Branch 5 83/05/24 Rochester Oas & Electric Corp 4pp, 18638 333 24X Fiche: 50-244,83/05/26,8305270060 83/05/26 MAIER, J. E.
- --- 8305270071 Bafety evaluation supporting licenses corrective actions subsequent to 820123 steam generator tube rupture Main steam & air ejector radiation monitoring sys acceptable * Office of Nuclear Reactor Regulation, Director. 83/05/26 18638:337. 24X Fichs. 50-244, 83/05/26, 8305270060

- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 30-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 - JOSPONOET 12 into Nature 35 21.

 See I ist encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 1030-0023 IE info worste bares, and activities the first section of Emergency Preparedness & Enginebring Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York: Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23. "Inoporable Containment Atmosphere Bensing Sys " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York
- 8305040547 Requests remittance of Class III fee for Div of Licensing approval of 82015 application for rev to inservice insp program, deleting 25 sleeve limit per steam generator insp DIOOB.R M License Fee Management Branch B3/04/27 MAIER, J E Rochester Gas & Electric Corp ip 18351 231 24X Fiche 50-244.83/04/27,8305040547
- 8305050246 Ack receipt of 830111 & 0224 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-244/82-23 Item C of notice of violation re spent fuel storage grid map rescinded
 MARTIN.T I Division of Engineering & Technical Programs (
 MAIER, J E Rochester Cas & Electric Corp 2pp 18337 335
 Fiche 50-244, 83/04/27, 8305030246 83/04/27
- --B305050248 Responds to NRC 821213 itr re item 5 e 3 noted in IE Insp Rept 50-244/82-23 Spent fuel storage grid map correctly shows spent fuel assembly in Location A-17 Reevaluation of item requested MAIER, J E Rochester Qas & Electric Corp 83/02/2 Division of Engineering & Technical Programs ip Fiche 50-244,83/04/27,8305050246 03/02/24 MARTIN 03/02/24 MARTIN 03/02/24
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of 18382 047 24X Fiche 50-000, 83/04/28, 8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Svc list encl. JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382 165 24X Fiche 50-000, 83/04/28,8303040027
- B303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " 8vc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Set list end! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York Inc 112pp 18382 282 24X Fiche 50-000.83/03/04.8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- B305110065 Forwards fee for review of application proposing inservice insp program rev to delete 25 slesve limitation per steam generator insp, in response to B30427 request MAIER, J E. Rochester Gas & Electric Corp. 83/05/05 DIGGS, R.M. License Fee Management Branch. 2pp. 18409-012 24X Ficher 30-244; B3/05/05, B305110065

- B303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) B3705706 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fichs 50-000,83705706,8303040033
- 8303040034 IE Info Natice 83-30, "Hisapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B305250438 Forwards IE insp Rept 50-244/83-05 on 830301-0407 & natices of deviation & violation Enforcement action considered for failure to perform adequate post-maint test of containment personnel hatch
 BTARCSTECKI,R Division of Project & Resident Programs B3/05/12
 MAIER,J E Rochester Gas & Electric Corp 2pp 18585 214 24X
 Fiche 30-244,83/05/12,8305250438
- --8305250444 Notice of violation from imap on 830301-31 a Region i, Office of Director 83/05/12 ip 18585 216 24X Fiche 50-244,83/05/12,8305250438
- --8305250446 Notice of deviation from insp on 830301-31 * Region i, Office of Director 83/05/12 2pp 18585 217 24% Fiche 50-244,83/05/12.8305250438
- --8305250453 IE Insp Rept 50-244/83-05 on E30301-0407 Noncompliance noted failure to perform post-maint testing, to perform safety analysis for proposed mod & to implement commitments re corrective actions for previously missed surveillance ZIMMERMAN.R P , BAUNACK, W H Region 1, Dffice of Director KISTER.H B Division of Project & Resident Programs 83/04/26 9pp 18585 219 24% Fiche 50-244,83/05/12,8305250438
- 8305190440 Discusses NDE support to Task Order 5-83, which H Conrad requested CV Dodd to undertake is steam generator eddy current insp Evaluation of effectiveness of insp techniques to identify intergranular attack planned FRANK, L Materials Engineering Branch FIN 8-0775-3 83/05/13 MCCLUNO, R H Dak Ridge National Laboratory ip 18523 168 24X Fiche 50-244,83/05/13,8305190440
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Bvc list enc!
 JONDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305270571 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/83-03 BTAROSTECKI.R. Division of Project & Resident Programs 83/05/19 MAIER, J E Rochester Gas & Electric Corp | p | 1844 355 24X Fiche 30-244.83/05/19,8305270571
- --8305270578 Responds to NRC 830323 ltr re violations noted in IE Insp. Rspt 50-244/83-03 corrective actions calculation based on isotopic analysis & monthly releases will be performed for period since initiation of B steam generator leak test. HAIER, J E Rochester Gas & Electric Corp. 83/04/22 ALLAN, J M Region 1. Office of Director. 3pp. 18644-356. 24X Fiche 50-244,83/05/19.8305270571
- 8305260237 Summary of B30512 site meeting w/util re steam generator sleeving program Sleeving mods adequate pending formal submittal of mod procedures review of insp results & stress analysis Next meeting scheduled for B30520 DICK.OF Operating Reactors Branch 5 83/05/24 Operating Reactors Branch 5 11pp 18622 076 24X Fiche 50-244.83/05/24.
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York: Inc. 114pp 18647-007 24X Fiche 30-000,83/05/26,8303040046
- R Periodic Operating reports & related correspondence
- B305240510 Forwards "RE Ginna Nuclear Power Plant, 1982 Evaluation "
 BRUNNER, E J Division of Engineering & Technical Programs.
 B3/05/06 TAYLOR, J M Division of Bafeguards & Inspection Programs (Post B30103) CASE, E. Q Office of Nuclear Reactor Regulation,
 Director 19 18571 274 24X Fichs 30-244,83/05/06,8305240510.
- --8305240517 "RE Ginna Nuclear Power Plant 1982 Evaluation," conducted during whs of 820531 & 0.007 * Institute of Nuclear Power Operations 83/05/06 41pp 18571.275 24X Fiche.50-244.83/05/06.8305240510

- 8 Reportable occurrences, LERs & related correspondence
- 8305230926 LER 83-013/01T-O results of multi-frequency eddy current exam of steam generator A inlet & outlet revealed no tubes w/indications above plugging limit Twenty-three tubes w/intergranular attack indications found in generator B SNOW, B A Rockester Oas & Electric Corp 83/04/19 ALLAN, J M Region 1, Office of Director 1p 18537 341 24X Fiche 50-244,83/04/19,8305230526
- 830511031B Forwards LER 83-014/03L-0 MATER, J E Rochester Cas & Electric Corp 83/04/25 ALLAN, J M Region 1, DPfice of Director 1p 18406 075 24X Fiche 50-244, 83/04/25, 830511031B
- --B305110328 LER 83-D14/03L-O on 830329, during refueling calibr, certain steam generator level transmitter outputs shifted low by 2 to 2 5% of span. Caused by instrument drift Transmitters recalibr EDGAR.E C Rochester Oas & Electric Corp 83/04/25 Region 1. Office of Director 1p 18406 076 24X Fiche 50-244,83/04/25. 8305110318
- 8305230561 Førwards LER 83-015/03L-0 MAIERJ E Rochester Gas & Electric Corp 83/04/29 ALLAN, J M Region i, Office of Director ip 18537 094 24X Fiche. 50-244, 83/04/27, 8305230561
- --B305230564 LER 83-015/03L-O on 830412.RHR pump manually tripped following loss of RHR on hot leg of loop Caused by leak in steam generator A temporary cold leg norite isolation device, allowing air in RCB & RHR suction line LARIZZA, O F Rochester Cas & Electric Corp 83/04/27 Region 10 Office of Director 3pp 18537-095 24X Fiche 30-244, 83/04/29, 8305230561
- 8305160114 Forwards LER 83~013/017-0 MAIER J E Rochester Oss & Electric Corp 83/05/03 ALLAN, J M. Region 1. Office of Director ip 18450 349 24X Fiche 50-244,89/05/03,8305160114
- --8305160119 LER 83-013/01T-0 on 830419,23 tubes in steam generator inlet B showed tube sheet crevice intergranular attach indication above 40% through well defect Caused by caustics &/or altaline earth concentrations Tubes sleeved or plugged MEYER.T A Rocksater Oas & Electric Corp 83/05/03 Region 1, Office of Director 2pp. 18450 349 24% Fiche 50-244,83/05/03, 8305160114
- 8305190170 Forwards LER 83-016/03L-0 MAIER J E Rochester Qas & Electric Corp 83/05/06 ALLAN, J. M Region 1. Office of Director 1p. 18502 216 24X Fichs 50-244 83/05/06.8305190170
- --8305190175 LER 83-016/03L-0. on 830418, during maint, pinhole leak discovered on boric acid transfer sys branch connection off boric acid filter outlet. Caused by intergranular attack due to stress corrosion cracking Piping will be replaced.

 BCRULER, T R Rochester Qas & Electric Corp 83/05/06 Region 1. Office of Director 2pp 18302 217 24X Fiche 50-244, 83/05/06, 8305190170
- 8305190234 Forwards LER 82-028/03L-0
 MAIER, J E Rochester Gas & Electric Corp 83/05/06 ALLAN, J M.
 Region 1, Office of Director 1p 18501 315 24X
 Ficher 50-244,83/05/06,8305190234
- --B30517023B LER 82-028/OSL-O on 821219, while performing nitrogen makeup to accumulator & charging RCB overpressurization sys nitrogen containment isolation valve ADV-846 opened & closed sluggishly Caused by matl in plug Seet replaced BCHULER, T. R. Rochester Gea & Electric Corp. 83/05/06 Region 1, Defice of Director 2pp. 18501-316. 24X Fichs 50-244, 83/05/06, 8305170234
- #305230452 Forwards LER #3-012/03L-1 MAIER J & Rochester Gas & Electric Corp #3/05/06. ALLAN, J. M Region 1, Office of Director 19 19537 349. 24X Fiche 50-244 #3/05/06, #305230452
- --8305230458 LER 83-012/03L-1 on 830323, individual doors for personnel hatch had higher leak rate than allowed Caused by incorrect maint procedure on 821007 requiring only door seal leak testing Procedure revised. Other procedures reviewed SPECTOR, 8 M Rochester Qas & Electric Corp 83/05/06 Region 1, Office of Director 23pp 18337.350 24X Fiche. 50-244, 83/05/06, 8305230452.

DOCKET 30-243 MILLSTONE NUCLEAR POWER STATION, UNIT I F Security, medical, emergency & fire protection plans

- 8305040022 Releases public version of revised emergency plan implementing procedures FELTON. JM Division of Rules and Records 83/04/25 Document Management Branch ip 18330 065 24x Fiche 30-245,83/04/25.
- --8305040034 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/12 EISENHUT,D O Division of Licensing 2pp 18330:066 24X Fiche 50-245.83/04/25.8305040022
- --8303040039 Public version of revised emergency plan implementing procedures, including Procedures EPIF 4214 re Unit 1 reactor coolent & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 300pp 18330-068 24X Fiche 50-245, 83/04/25. 8305040022
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EISENHUT, D Q Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000.83/05/11.8305110034
- 8305180833 Authorizes refund for review of 821230 & 830408 requests from revised schedule for conducting emergency exercise MILLER. H O License Fee Hangement Branch 83/05/11 COUNBIL, H O Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 18504.030 24X Fiche 50-000.83/05/11.8305180853
- 8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREO-0737. Item III A 2 i Item complete CRUTCHFIELD, D Operating Reactors Branch 5 83/05/13 COUNSIL, W CONNECTED TO A COUNSIL, W CONNECTED TO A COUNSIL, W CONNECTED TO A COUNSIL, W CONNECTED TO COUNSIL, W CONNECTE
- 8305230323 Forwards emergency procedures generation package containing procedure guidelines, writers guide & training program in response to NUREQ-0737. Suppl 1 (Generic Ltr 82-33).
 "Requirements for Emergency Response Capability "
 CDUNBIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNBIL.W Q Northeast Utilities 83/05/13 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 18538 264 24X Fiche 50-245,83/05/13,8305230323
- --8305230330 "Emergency Procedure Guidelines "

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)

 83/05/13, 55pp 18538 265 24X Fiche 50-245,83/05/13,8305230323
- ---8305230338 Rev 26 to ACP-GA-3 02, "Millstone Point Generating Station Writers Quide for Emergency Operating Procedure"
 # Northeast Nuclear Energy Co. (subs of Northeast Utilities)
 83/03/13 47pp 18538-321 24X Fiche 50-245,83/05/13,8305230323

I. Financial information

8305020093 Forwards "Annual Rept of Electric Utils, Licensess & Others (Class A & Class B)," FERC Form i BISHOP, R. H. Northeast Utilities, 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279-109 24X Fichs, 50-245, 83/04/26, 8305020093

J Insurance & indomnity information

8305120156 Forwards Endorsements 87 & 78 to NELIA Policy NF-173 & MAELU Policy MF-72, respectively 81N181, J.M. Marsh & McLennan, Inc 83/05/05 SALTIMAN, J D Assistant Director for State & Licensee Relations 3pp 18427 153 24X Fiche 50-245,83/05/05,8305120154

- P Operating license stage documents & correspondence
- 8305240249 F01A request for three categories of documents ry Reactor Safety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515.2787 & 2802) SHOLLY.8 C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24% Fiche 50-000,83/03/11.8305240249
- B305230616 Forwards info in response to B30208 ltr requesting backfit cost data for operating nuclear units Cost categorized according to NRC imposed THI & non-THI backfits, util-initiated & hybrid backfits
 COUNBIL.W O Connecticut Yankes Atomic Power Co COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities)
 COUNBIL.W O Northeast Utilities 83/03/21 TOURTECLOTTE.J
 Regulatory Reform Task Force 25pp 18543 O3B 24X
 Fiche 30-000.83/03/21.8305230616
- 8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Bearch for addi documents in progress FELTON.J M Division of Rules and Records 83/03/31 8HOLLY,8 C Union of Concerned Scientists 2pp 18393 179 24X Fiche 50-000.83/03/31,8305240254
- 8305230720 Forwards list of utile responding to requests for cost figures on backPitting TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11 PALLADINO, N. J. Commissioners 2pp 18542 272 24% Fich > 50-080,83/04/11,8305230720
- 8303140188 Advises that action required by 830124 Amends 88.51 & 80 to Licenses DPR-21.DPR-61 & DPR-65-respectively & Generic Ltr 83-07 complete, based on util negotiations w/DDE re disposal of high level waste or spent nuclear fuel CLARK.R A Operating Reactors Branch 3 83/04/20 COUNSIL.W 9 Connecticut Yankee Atomic Power Co 2pp 18462 355 24X Fiche 50-000.83/04/20, BJ05160188
- B305030620 Forwards add! info re containment leak rate continuous monitoring in response to NRC B30121 request W/4 oversize drawlings & 7 aperture cards Aperture cards are available in FDR GUUNBIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.H 0 Northeast Utilities B3/04/26 CRUTCHFIELD, D Operating Reactors Branch 5, 3pp 18302 327 24X Fiche 30-245/83/04/26,8305030620
- --8305030624 Rev 1 to 8P 639 1, "Frimary Containment Nitrogen Make-up & Usage"
 BHINE:C Northeast Nuclear Energy Co (subs of Northeast Utilities) SHINE:C Northeast Utilities 78/03/08 3pp 18302 332 24X Fiche 50-245,83/04/26,8305030620
- --8305030628 Rev 13 to OP 311, "Containment Sys " MCCCLLUM: Northeast Nuclear Energy Co (sub: of Northeast Utilities), MCCCLLUM: Northeast Utilities 82/12/09 28pp 18302 335 24K Fiche: 50-245, 83/04/26, 8303030620
- B305030404 Informs that value-impact analysis has resulted in cancellation of proposed renoute of reactor water cleanup sys to all feedwater notices Renoute unnecessary if triple-sleeve spargers do not leak COUNSIL.W Q. SERRE.CF Northeast Nuclear Energy Co (subs of Northeast Willittes) COUNSIL.W Q. Northeast Utilities B3/04/27 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18291 221 24X Fiche 50-245,83/04/27,8300030404
- 8305020121 Forwards Franklin Research Ctr request for info re structural aspects of plant-unique analysis rept on Hark I containment long-term program concerning torus & vent & piping sys (TER-C5506-317) Response due within 45 days CRUYCHFIELD, D. Operating Reactors Branch 5 83/04/2B COUNBIL, W Q Northeast Nuclear Energy Co (subs of Northwast Utilities) 5pp 18278 235 24X Fiche 50-245,83/04/28,8305020121
- B3D505029 Submits progress rept re TMI Items II F 1.1 & II F 1.2 re
 effluent monitor mods Vendor schedular uncertainties
 resolved Remaining work consists of training operators,
 software changes & minor wiring change
 CDUNSIL, W Q. Northeast Nuclear Energy Co (subs. of Northeast
 Utilities) CDUNBIL, W Q Northeast Utilities. B3/04/29
 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18338 062 24X
 Fiche 30-245,83/04/29,8305050229

- B305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Hanual." per 10CFR50, App E. Section V H/o ancis COUNSIL, H G Connecticut Yankes Atomic Power Co COUNSIL, H G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H O Northeast Utilities B3/04/29 EISENHUT, D G Division of Licensing 2pp 18362 256 24X Fiche 50-000,83/04/29.
- 8305020455 Generic Ltr 83-17 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to CLs Svc list encl EISCNHUT.D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 30pp 18441 120 24X Fiths 30-000, 83/05/02, 83050204955
- 830509047; Updated application for amend to License DPR-21, proposing Tech Spec change re reactor protection sys power monitoring, per 821015 proposal Proposed change conforms to STS requirements willsted exceptions addressed in 830405 ltr COUNSIL.W 0 . SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 83/05/02 CRUICHFIELD.D Operating Reactors Branch 5 2pp 18362 267 24X Fichs 30-245.83/03/02.8305090471
- --8305090474 Proposed Tech Spec 3/4 i-i re reactor protection sys power monitoring ** Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 2pp 18362 269 24X Fiche 50-245,83/05/02,830509047;
- 8305070426 Forwards Amends 91 & 86 to Licenses DPR-21 & OPR-65, respectively & notice of issuance & availability Amends change ownership interests in facilities
 CRUTCHF(ELD.D Operating Reactors Branch 5 B3/05/05 COUNSIL.W & Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 18360 236 24x Fichs 50-245,83/05/05,8305090426
- --8303090436 Amend 91 to License DPR-21, reflecting merger of Connecticut Light & Power Co & Hartford Electric Light Co CRUTCHFIELD, D Operating Reactors Branch 5 89/05/05 5pp 18360 239 24% Fichs 50-245,03/05/05.8305090426
- --8305090442 Corrected App A Tech Spec Page 5-i of Amend 9! to License DPR-2!.containing captioned amend number & vertical line indicating change # Division of Licensing 83/05/05 2pp 18360 244 24X Fiche 50-243.83/05/05.8305090426
- --8305090460 Amend 86 to License DPR-65, reflecting merger of Connecticut Light & Power Co & Martford Ejectric Light Co Pages 1 & 2 of Amend 4 to License DPR-21 encl CLARX, R A Operating Reactors Dranch 3 83/05/05 4pp 18360 246 24X Fiche 50-245,83/05/05,8305090426
- --8305090463 Notice of issuance & availability of Amends 91 & 86 to Licenses DPR-21 & DPR-65; respectively CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 2pp 18360 250 24x Fiche 50-245,83/05/05,8305090426
- B303100348 Advises that w/erception of Item II K 2 31 on compliance w/10CFR50 56.830324 comments applicable to 830321 draft generic itr Review of 830324 submittal re-comments on draft NURGC-0737 BHR Tech Specs requested COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/05 EISENHUT. D G Division of Licensing 2pp 18378 212 24X F(che 30-245,83/05/05,8305100368
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York: Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659
- 830518026B Advises that Atwood Morrill vacuum breakers acceptable asbuilt Chugging impact velocity results in insignificant loading on valve Ten valves modified to replace aluminum casting dists w/more ductile aluminum plate matl COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 83/05/10 CRUTCHTIELD,D Decating Reactors Branch 3 2pp 18490 069, 24X Fiche 50-245.83/05/10/830318026B
- 8305180304 Forwards "SEP Topic VIII-2: Onsite Emergency Power Bys Gas
 Turbine Generator Preventative Maint Program " Program
 adequate except for engine-mounted fuel pump, fuel shutoff
 valve & air start regulating valve
 COUNSIL. H O Northeast Nuclear Energy Co (subs of Northeast
 Utilities) COUNSIL. H O Northeast Utilities 83/05/10
 CRUICHTELD. D Operating Reactors Branch 3 2pp 18486 293 24X
 Fiche 50-245,83/05/10,8305180304

- ~-8305180311 "SEP Topic VIII-2.Onsite Emergency Power Sys Gas Turbine Generator Preventative Maint Program " * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/31 4pp 18486 275 24% Fiche 50-245,83/05/10.8305180304
- 8305250510 Application to amend Licenses DPR-61 DPR-21 & DPR-65 deleting 820630 deadline date for conformance w/final rule 10CFR80 49 removing requirement for central equipment qualification file COUNSIL.W 6 . SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W 0 Connecticut Yankee Atomic Power Co 83705718 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 Fichs 50-000,83705718,8305250510
- --8305250518 Proposed Tech Spec changes deleting 820630 deadline for environ qualification of electrical equipment * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/18 7pp 18588 281 24X Fiche 50-000,83/05/18,8305250510
- 6305270114 Forwards Rev 1 to "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Unit 1." technical rept Unit 1." technical rept COUNSIL: 0 OSARB.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL: 0 Northeast Utilities 83/05/18 CRUFCRFIELD.D Operating Reactors Branch 5 1p 18640 331 24% Fiche 50-245.83/05/18.8305270114
- --8305270119 Rev 1 to "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Unit 1." technical rept Teledyne Engineering Services TR-5318-1 RO1 83/04/04 140pp 18640.332 24X Fiche 50-245,83/05/18.8305270114
- Q Inspection reports. IE Bulletins & correspondence
- 8212040395 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Ca of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fichs 50-000, 83/04/15, 8303040021.
- 9303040023 IE Info Notice 93-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089, 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bansing Sys " Svc l(st enc) JOROAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York, Inc lipp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Becondary 81de of Steam Generators at PWRs " Svc list encl JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gos Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 1844i 170 24X Fichs 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc 1[st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidate Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Beformation " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- B303040034 IE Info Notice B3-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidolines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000.83/05/11,8303040034
- B305250437 Forwards IE Insp Rept 50-245/83-07 on 830411-14 No noncompliance noted STAROBIECKI.R Division of Project & Resident Programs 83/05/11 COUNSIL-W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588 075 24X Fiche 50-245.83/05/11.8305250437
- --8305250443 IE Insp Rept 50-245/83-07 on 830411-14 Na noncompliance noted Major areas inspected actions taken to comply w/NUREO-0737, Item II B 2, "Design Review of Plant Shielding"

 BRIGOS.L. EAPEN.P., PLISCO.L. Region I, Office of Director 83/05/09 App 18588 077 24X Fiche 50-245,83/05/11,8305250437
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8303040046 IE Info Notice 83-33; "Nonrepresentative Sampling of Contaminated Oil " Syc list encl Proparedness & Engineering JORDANIE L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/03/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- B303060501 Forwards LER B3-014/03L-0 Detailed event analysis encl MRUCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/04/29 ALLAN,J M Region 1 Office of Director 3pp 18351 139 24X Fiche 50-245, B3/04/29, B305060501
- --8305060512 LER 83-014/03L-0 on 830331.gas turbins accelerated on air start motor, but failed to achieve ignition Gause unknown Investigation initiated to evaluate & determins cause of event
 THULL.T 8 Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/27 Ragion 1, Office of Director ip 18351 142 24X Fiche 50-245.83/04/29,8305060501
- B305230549 Forwards LER B3-015/03L-0 Detailed event analysis encl MR0CZKA:E J. Northeast Nuclear Energy Go (subs of Northeast Utilities) B3/05/10 ALLAN,J M Region 1, Defice of Director 2pp 18537 087 24% Fiche 50-245,83/05/10,8305230549
- --8305230557 LER 83-015/03L-0 on B30411, during tubine control valve fast closure functional & calibr test, time delay relays 590-125A & 590-125D tripped at 261 & 262 milliseconds, respectively Caused by setpoint drift Relays adjusted & tested THULL.T B Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/10 Region 1. Office of Director ip 18537-089 24X Fiche 50-245.83/05/10.8305230549
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination FARRELLY.T J. Consolidated Edison Co. of New York, Inc. 83/04/28 LEMIS.D Atomic Safety and Licensing Board Panel 24pp 18300 315 24X Fiche: 50-247,83/04/28,8305030531
- F Security, medical, emergency & fire protection plans
- 8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions NURCG-0654-FEMA-REP-1. Rev 1 stds would place heavy resource burden on state QIUFFRIDAL O Federal Emergency Management Agency. 83/04/18 PALLADINO, N J Commissioners. 1p 18542 327 24X Fiche 50-003,83/04/18,8305230670.

- --8305230676 Seeks clarification of issue to FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan PALLADIND, N J Commissioners 83/03/30 OlUFFRIDA, L D Federal Emergency Management Agency 2pp 18542 330 24X Fiche 50-003,83/04/18,8305230670
- 830502054B Responds to 830107 ltr re Rev 4 to physical security plan Changes consistent w/provisions of 10CFR90 54(p) 2 acceptable VAROA.S A Departing Reactors Branch 1 83/04/20 Consolidated Edison Co of New York, Inc. 1p 18284 257 24X Fiche 30-003,83/04/20,8305020548
- 8305020575 Responds to 830128 ltr re Rev 3 to safeguards contingency plan Changes consistent w/100FR90 54(p) & acceptable VAROA,8 A Operating Reactors Branch 1 83/04/20 D'TOOLE, J D Consolidated Edison Co of New York, Inc 1p 18284 232 24X Fiche 50-003,83/04/20,8305020575
- 8305050187 Forwards IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 & notice of violation Notice of violation withheld (ref 10CFR73 21 & 10CFR2 790)

 MARTIN.T T Division of Engineering & Tachnical Programs 83/04/20 0'10DLE.J D Commonwealth Edison Co 20p 18341 068 24X Fiche 30-247.83/04/20.8305050187
- ~~8305050190 IE Safeguards Insp Rept 50-247/83-08 on 830228-0304
 Noncompliance noted barrier of one vital area not
 maintained Safeguards info deleted (ref 10CFR2 790)
 BAILEY,R J. 600Y,A T. Region 1. Office of Director 83/04/12
 6pp 18341 070 24X Fiche 50-247,83/04/20,8305050187
- 8305040235 Releases public version of rev to emergency plan & emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/04/22 Document Management Branch ip 18364-188 24% Fiche 50-003,83/04/22, 8305040235
- ---B305040242 Forwards public version of revs to emergency plan to Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility"

 D'TODLE.J D Consolidated Edison Co of New York, Inc. B3/04/07

 HAYNEB.R C Region 1, Office of Director 2pp 18364 170 24X

 Fiche 50-003, 83/04/22, 8305040235
- --8305040247 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Fac(1)ty "

 LIEBLER, O H Consolidated Edison Co of New York, Inc 83/03/08

 Qffice of Nuclear Reactor Regulation, Director 2pp 18364 192
 24% Fiche 50-003.83/04/22,8305040235
- --B305040249 Public version of rev to Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility"

 * Consolidated Edison Co. of New York, Inc. 83/03/0B IBpp. 18364 194 24X Fiche 50-003/83/04/22.8305040235
- --8305040254 Public version of revised emergency plan

 * Consolidated Edison Co of Now York, Inc. 83/03/07 49pp
 18364 212 24X Fiche 50-003.83/04/22.8305040235
- 8303020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning, for info Certificate of Svc encl Related correspondence OLABS, S. M. Føderal Emergency Management Agency 83/04/25 OLEASON, J. P., SHDN, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247, 83/04/25, 8305020419
- 8305100427 Forwards IE Insp Rept 50-247/83-10 on 830302-0404 & notices of violation & deviation STARDSTECKI, R Division of Project & Resident Programs 83/04/25 0'1001E-J D Consolidated Edison Co of New York, Inc 2pp 18410
- --8305100428 Notice of violation from insp on 830302-0404 * Region 1, Office of Director 83/04/25 2pp 18410 338 24X Fiche 50-247, 83/04/25, 8305100427
- --8305100431 Notice of deviation from insp on 830302-0404 * Region 1, Office of Director 83/04/25 ip 18410 340 24X Fiche 50-247, 83/04/25,8305100427
- --8305100433 IE Insp Rept 50-247/83-10 on 830302-0404 Noncompliance noted failure to meet Tech Spec requirements re reportability of fire barriers, failure to establish GA procedures & failure to meet radwaste processing FOLEY, T, KOLTAY, P. Region I. Office of Director KISTER, H.B. Division of Project & Resident Programs 83/04/19 17pp 18410 341 24X Fiche 50-247,83/04/25,8305100427

- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISEMHUT, D 0 Division of Licensing B3/05/11 Consolidated Edison Co of New York Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.8305110034
- B305240312 Informs of full cooperation between licensee & local govt in development & exercise of emergency radiological response plan, contrary to Commissioner Ahearne B30504 statement HEIMBACH, L. New York, State of B3/05/20 PALLADING, N Commissioners ip (B548 184 24% Fiche 50-247, 83/05/20, 8305240312
- B305310047 Responds to 830523 Itr outlining specific proposals for ameliorating facility offsite preparedness situation by views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness OIUFFRIDAL D Federal Emergency Management Agency B3/05/25 CUOMO, M N New York, State of 4pp 18453 284 24X Fiche 50-247,83/05/25,8305310049

O Adjudicatory correspondence

- B305030608 Motion for permission to present rebuttal witnesses on subjorf prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence POTTERFIELD.A Union of Concerned Scientists POTTERFIELD.A Public Interest Research Group, New York KAPLAN,C New York, NY 83/04/19 4pp 18308 050 24% Fiche 50-247.83/04/19.8303030608
- --8305030619 Testimony of D Gutman re prevailing wind patterns GUTMAN.D Union of Concerned Scientists GUTMAN.D Public Interest Research Group. New York GUTMAN.D New York NY 83/04/19 4pp 18308-054 24X Fiche 50-247.83/04/19.8305030608
- --8305030633 Reorganized testimony of JR Thornborough & D Bohning re Contention 6.2 concerning impact of shutdown on physical environ near facility POSNER.P Parents Concerned About Indian Point 83/04/19 44pp 18308 095 24X Fiche 50-247.83/04/19.8305030608
- --8305030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site L difficulty of evacuation in emergency POTTERFIELD.A Public Interest Research Group, New York POTTERFIELD.A Union of Concerned Scientists, 83/04/26 Atomic Safety and Licensing Board Panel 8pp 18308,139, 24X Fiche 30-247,83/04/19.8305030608
- --8305030646 Affidavit of KT Erickson & AJ Soinit re radiological emergency response plan ERICKSON, K T Public Interest Research Oroup, New York ERICKSON, K T Union of Concerned Scientists ERICKSON, K T Vale Univ. New Haven, CT 83/04/26 42pp 18308 148 24X Fiche 30-247,83/04/19,8305030608
- --B305030652 Motion requesting completeness of record on NRC Questions 3 & 4 re emergency planning issues; including capability for handling phone calls in emergency planning zone during emergency POTTERFIELD, A. PDTTERFIELD, A. Union of Concerned Scientists B3/04/25 Atomic Safety and Licensing Board Panel 4pp 18308 180 24X Fichs 50-247,83/04/19,8305030608
- B305020428 Mation to strike partions of 830309 emergency drill testimany Under Cammissian Questions 3 & 4 filed by witnesses for various intervenors Certificate of Svc enc! Related correspondence
 BRANDENBURG.8 Consolidated Edison Co of New York, Inc B3/04/22
 Atomic Safety and Licensing Board Panel 22pp 18273 075 24X Fiche 50-247.83704/22,8305020428
- 9305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning for info Certificate of Svc enci Related correspondence GLASS,8 M Federal Emergency Management Agency 83/04/25 GLEASDN.JP. SHON.F.J. PARIS.O H Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 30-247,83/04/25,

- 8305030549 Motion for subpoena to be issued to RW Krimm of FEMA Subpoena necessary to complete record on generic nature of deficiencies cited by FEMA & FEMA change in evaluation criteria Certificate of Svc encl MCROAN.C Power Authority of the State of New York MCROAN.C Morgan Associates 83/04/26 Atomic Safety and Licensing Board Panel 40pp 18306 147 24X Fichs 30-247/83/04/26/8305030549
- 8305020401 Motion to amend svc list to add SP Wasserman & delete P Chessin.LR Schwartz & M Oppel Notice of appearance & Certificate of 8vc enc!
 WASSERMAN.B P Metropolitan Transportation Authority New York, NY WASSERMAN.B P Botein, Hays. Stlar & Heriberg 83/04/27 Atomic Safety and Licensing Board Panel App 18273 067 24X
 Fiche 50-247.83/04/27.8305020401
- 8305020451 Submits info on status of Ray Miller, Inc problems affecting plant, per ASLB request MODRE, J E Hearing Branch 1 83/04/28 GLEASON, J P. SHON, F J., PAR13, O H Atomic Safety and Licensing Board Panel 88pp 18283
- 8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination
 FARRELLY: T J Consolidated Edison Co of New York, Inc 83/04/28, LEWIS. D Atomic Safety and Licensing Board Panel 24pp 18300 315 24X Fiche 50-247.83/04/28,8305030331
- B305040505 Forwards will onsite emergency plans per ABLB request that documents be mailed rather than delivered BRANDENBURG.B Consolidated Edison Co of New York, Inc 89/04/28 OLEASON.J P. BHON.F J. PARIS.O H Atomic 88fety and Licensing Board Panel ip 18322:110 24X Fiche 50-247,83/04/28,8305040505
- 8305030583 Forwards summary of training activities re offsite response organizations that might be called upon to respond to onsite emergencies.per ASLB 830223 oral request Util training detailed in 830405 submittal Related correspondence RAANDENBURG.B Office of the General Counsel 83/04/29 LEMIS.D Atomic Safety and Licensing Board Panel 7pp 18303 355 24X Fiche 50-247.83/04/29,8305030583
- 8305040464 Requests official position re long-term operation of facilities

 OLEASON.JP, PARIB.OH, SHON.FJ Atomic Safety and Licensing Board Panel 83/05/02 CUOMO.HM New York, State of 2pp 18321 295 24X Fiche 50-247.83/05/02,8305040464
- B305050035 Proposes alternative views to questions posed in 8J Chilk B30426 ltr to FEMA re emergency planning & evacuation PLEISHER, X S West Branch Conservation Association 83/05/02 PALLADINO, N J O'LLINSKY, V . AHEARNE, J F Commissioners 3pp 18342 096 24X Fiche 50-247,83/05/02,8305050035
- 8305140304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc MILES, E. B. Administrative Contracts Branch FIN B-8855 83/05/02 8ASSETT.H S. Office of Resource Management, Director FITTI, C. Atomic Safety and Licensing Board Penel 1p 18471 247 24X Fichs 50-247,83/05/02.8305160304
- ---8305160312 Contract: "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc # Central Data Processing, Inc MATTIA:M J Division of Contracts FIN R-8855 83/05/02 2pp 18471 248 24X Fiche 50-247,83/05/02,8305160304
- --8305160316 Solicitation.offer & award to "Conversion of Prefiled Testimony for Indian Point Hearings," to Central Data Processing.inc CGUCH,M J Central Data Processing, Inc MATTIA,M J, Administrative Contracts Branch FIN 8-8855 83/04/26 36pp 18471-250 24X Fiche: 30-247,83/05/02,8305160304
- B305050037 Forwards NY State Disaster Preparedness Commission B30504 memo re State of NY commitment to continue work to ensure residents protected by best practicable emergency preparedness plan
 DAYNEJ P Power Authority of the State of New York B3/05/04
 PALLADIND, N J , QILINSKY, V , AHEARNE, J F Commissioners 3pp 18339 105 24X Fiche 30-247, B3/05/04, B305050037
- B305040496 Forwards NY State Disaster Preparedness Commission B30504 ltr providing State of NY commitment to ensure residents protected by best practicable emergency preparedness plan BAYNE.JP Power Authority of the State of New York B3/05/04 PALLADIND,N J , GILINSKY,V , AHEARNE.JF Commissioners 3pp 18348 105 24X Fiche 50-247,B3/05/04,B305060496

- B305060506 Responds to B30426 ltr re Westchester County,NY bus draver issue,Rockland County,NY plan issue & questions raised re FEMA briefing & status rept on offsite emergency preparedness KRIMM,R W Federal Emergency Management Agency B3/05/04 CHILK,B J Office of the Secretary of the Commission 16pp 18348 331 24% Fiche 50-247.83/05/04,8305060506
- --8305060629 Responds to request for clarification of issue on whether state emergency plan can substitute for county which does not have emergency plan State can substitute plan but NUREO-0534 places heavy resource burden on state OIUFFRIDAL O Federal Emergency Management Agency 83/04/15 PALLADINO.N J Commissioners 2pp 18348 347 24X Fiche 50-247.83/05/04.8305060506
- 8305040468 Order CLI-83-11 advising that Commission will issue order by 830409 suspending plant operation unless FEMA determines significant deficiencies no longer exist or util shows compensating actions taken or deficiencies insignificant HCYLE.J Office of the Becretary of the Cammission 83/05/05 5pp 18348 075 24X Fiche 50-247,83/05/05,8305040468
- 8305090458 Memo providing citations to decisions referred to in hearing re-commitments from bus drivers needed in emergency evacuation plans
 PARIS,O H Atomic Safety and Licensing Board Panel 83/05/05 2pp
 18362 259 24X Fiche 50-247,83/03/05,8305090458
- B30510020B Motion for extension of deadline until B30627 for all parties to submit proposed opinion, findings of fact & recommendations re enforcement action on emergency planning issues, Certificate of Svc encl
 BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. HORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan
 Associates 83/05/06 PALLADINO, N. J., QILINBKY, V., AHEARNE, J. F. Commissioners 9pp 18374 014 24X Fiche 30-247, 83/05/06, B30510020B
- 8305100204 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11.establishing procedures for decision on enforcement action on emergency planning issues Cartificate of Byc encl WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/05/09 Commissioners 6pp 18374 193 24X Fiche 50-247,83/05/09,8305100204
- 8305130064 Motion for reconsideration of ruling denying licensee motion to receive DP McGuire deposition transcript into evidence Licensees entitled to place deposition in record Certificate of Bvc encl BRANGENBURG. B Consolidated Edison Co of New York, Inc. MDRGAN, C Power Authority of the State of New York MCRGAN, C Morgan Associates 83/05/09 Atomic Safety and Licensing Board Panel 15pp 18426.230 24X Fichs 30-247.83/05/09.8305130064
- 8305120309 Order authorizing ASLD to grant relief from 830527 deadline for filing proposed findings of fact & conclusions of law since oral presentations before Commission to take place on 830826 CHILK:8 J Office of the Secretary of the Commission 89/05/10 Admic Bafety and Licensing Board Panel 2pp 18424,100 24X Fiche 50-247,83/05/10,8305120309
- B305140024 Forwards I Levi affidavit clarifying B30211 testimony on suggested method of making sensible probability Judgments described in Section 5
 HARTZMAN.R M Friends of the Earth HARTZMAN.R M Audubon Society B3/05/10. GLEASON, J P , PARIS.O H , SHON, F, J Atomic Safety and Licensing Board Panel ip 18452 353 24X Fiche 50-247,83/05/10,8305140024
- ---B30516002B Affidavit of I Levi clarifying B302li testimony re suggested method of making sensible probability judgments described in Section 5 LEVI.I. Friends of the Earth. LEVI.I Audubon Society B3/05/10 2pp 18452.354
- B305130030 Memorandum & order granting licenses B30506 motion for extension until B30627 to file proposed findings of fact & recommendations, Date extended until B30829 for ASLB to submit recommendations to Commission PARIS.O H. BHON.F J. Atomic Bafety and Licensing Board Panel B3/05/11 Consolidated Edison Co. of New York, Inc. 2pp. 18437,102, 24% Fichs 50-247,83/05/11,B305130030
- 8305130071 Motion for extension of deadline (to 830615) for filing corrections to transcripts & deadline (to 830624) for filing comments Certificate of Syc encl BRANDENBURG, B Consolidated Edison Co. of New York, Inc. MOROAN, C Power Authority of the State of New York MOROAN, C Morgan Associates 83/05/11 Atomic Safety and Licensing Board Panel 7pp, 18437-045, 24% Fichs 50-247,83/05/11.8305130071

- 8305190342 Supports immediate plant shutdown Emergency response plan represents theory & not practicality OALEF, 9 R Westchester County, NY 83/05/11 PALLADINO, N J Commissioners 6pp 18500 227 24X Fiche 50-247.83/05/11, 8305190362
- 8305160133 Telecopy order granting licensee 830511 motion for extension of date to file motions to correct transcript Motions due on 830613 GLEASON, J.P. Atomic Safety and Licensing Board Panel 83/05/13 Consolidated Edison Co. of New York. Inc. 4pp. 18446 116 24X Fiche 30-247,83/05/13,8305160133
- 8305160167 Order clarifying Commission 830505 order Comments from parties & general public, relevant to enforcement action, will be considered Public comments to be filed by 830523 Oral presentations limited to licensees & interested govts CHILK, 8 J Defice of the Secretary of the Commission 83/05/13 Commissioners 4pp 18445 152 24X Fiche 50-247,83/05/13,8305160167
- 8305190220 Motion for apportunity to address issues autlined in Commission B30505 Order CLI-83-il establishing procedures for decision on sufforcement action Intervenor entitled to participate as matter of right Certificate of Svc encl RODRIGUEZ.P Parents Concerned About Indian Point B3/05/13 Commissioners 3pp 18502 143 24% Fiche 50-247.83/05/13, 8305190220
- 8305200649 Advises that day of reckoning re evacuation plan issue coming on 830609 Interim compensating actions by FEMA cannot compensate for unchangeable factors of problem roads & population density TOSCANI.K Affiliation Unknown 83/05/15 Commissioners 3pp 18320 122 24X Fiche 50-247.83/05/15.8305200649
- 8305180143 Order providing time (until 830610) to parties to respond to P Amico. ABLB consultant.830902 ltr summarizing conclusions based on review of testimony & hearing transcripts ra Commission Question 1
 QLEASON. J P Atomic Safety and Licensing Board Panel 83/05/16
 Office of the Executive Legal Director 1p 18490 022 24X
 Fiche 50-247.83/05/16.8305180143
- --8305180146 Summarizes rept on review of testimony & hearing transcripts re Commission Question i Addl testimony recommended on current analytical methods for risk assessment & on issues not dealt win probabilistic safety study or NRC analysis AMICO.P J Applied Risk Technology Corp AMICO.P J Atomic Safety and Licensing Board Panel 83/05/02 QLEASON, J P. SHON.F J . PARIS.O H Atomic Safety and Licensing Board Panel 4pp 18490 023 24X Fiche 50-247,83/05/16,8305180143
- 8305180424 Requests time to address Commission on 830526 re Commission 830519 order ODANSKI,5 Rockland County, NY 83/05/16 CHILK Commissioners ip 18485 302 24% Fiche 50-247,83/05/16,8305180424,
- 8305200605 Requests time to speak on 830526 State of NY claims unsubstantiated NRC should adopt policy of communicating w/public FLEISHER: Z B West Branch Conservation Association 83/05/16 PALLADIND, N J , OILINSKY, V , AMEARNE, J Commissioners 12pp 18514 070 24X Fiche 50-247-83/05/16:8305200605
- 8305240535 Citizens advisory committee progress repts re nuclear evacuation & general disaster preparedness plan * Rockland County, NY 83/05/16 34pp 18576 053 24X Fiche 50-247,83/05/16,8305240535
- 8305240508 Forwards Desining Town Board resolution expressing concerns re emergency plans Deficiencies must be corrected before plan approved WISHNIE: R G Desining NY 83/05/19 Office of the Secretary of the Commission 4pp 18571 260 24X Fichs 50-247,83/05/19,8305240508
- 8305240530 Expresses concerns re adequacy & workability of evacuation plans BOGARDUS,R H Affiliation Unknown 83/05/19 NRC - No Detailed Affiliation Given 2pp 19571 236 24X Fichs 50-247,83/05/19, 8305240530
- 8305240546 Forwards citizen & group statements expressing concern replant safety & flawed evacuation plan in response to Commission Order CLI-83-11 ELLIOTT.N R Yorktown NY B3/05/19 NRC No Detailed Affiliation Given, 10pp 18575 266 24X Fiche, 50-247, B3/05240546

- 8305240547 Forwards board of trustees of Village of Buchanan statement that plants are safe & provide ctean energy PIERCE.F W Buchanan, NY 03/05/19 PALLADINO,N J Commissioners 2pp 18575 281 24X Fiche 50-247,83/05/19,8305240547
- 8305270583 Requests concrete actions re emergency evacuation plan in light of FEMA stated deficiencies, in response to Commission 830505 Order CLI-83-11 ELLIOTTON R Yorktown, NY 83/05/19 Commissioners ip 18446-343 24X Fiche 50-247,83/05/19,8305270583
- 8305240454 Motion for leave to submit written comments on NRC 830505 order to suspend facility operations Deficiencies determined to be significant by FEMA are not sufficiently deficient to require suspending operations
- B305240446 Response to Commission B30505 order establishing procedures for decision on enforcement action Emergency planning deficiencies not significant NRC enforcement action unwarranted & improper H/Certificate of Svc MORGAN. C Fouer Authority of the State of New York MORGAN. C Morgan Associates 83/05/20 43pp 18573 181 24X Fiche 30-247,83/05/20,8305240466
- B305240527 Views re radiological emergency planning in response to Commission B30505 order FEMA & NRC should rule that plants no longer have significant deficiencies based on improvement & interim compensating actions GLOCK. J D BRANDENBURG. D Consolidated Edison Co of New York, Inc B3/05/20 41pp 18571 132 24X Fiche 50-247, B3/05/20, B305240527
- G305240532 Opinion on NRC B30505 order to FEMA rept on licensee emergency planning & preparedness & possible suspension of plant operations Immediate shutdown urged KAPLAN.C New York, NY XAPLAN.C National Emergency Civil
- 8305290337 Submission re Commission 830505 order on intention to shut down facility on 830507 if emergency preparedness problems not resolved Adequate protective action in case of radiological emergency cannot be guaranteed by 830607 GOLDBERG, M. L. Public Interest Research Group, New York. 83/05/21 17pp 18385 302 24x Fiche 50-247.83/05/21.8305250337.
- 8305240523 Order providing guidance for 830526 oral presentations to Commission re possible plant shutdown CHILK.8 J. Office of the Secretary of the Commission 83/05/23 App 18571 119 24X Fiche 30-247.83709/23.8305240523
- 8305240938 Forwards comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action HEISS.ER Harmon & Weiss WEISS.ER Union of Concerned Scientists 83/05/23 PALLADIND,N J , AHEARNE, J F , ASSELSTINE, J, K Commissioners Ip 18576 093 24% Fiche 50-247,83/05/23,8305240538
- --8305240542 Comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action Emergency planning deficiencies fundamental Adequate interim compensating measures impossible Centificate of Svc encl HEISS.E R Union of Concerned Scientists HEISS.E R Harmon & Heiss 83/03/23 19pp. 18374 074 24X Fiche 50-247,83/05/23,8305240838
- 8303240543 Submission re Commission 830505 Order CLI-83-11 Emergency planning must be well developed & detailed w/special emphasis on health & safety of children POSNER,P Parents Concerned About Indian Point 83/05/23 20pp
- 8305250223 Submission addressing Commission 830505 order on possible facility closing Requests oral presentation on 830526 re economic inpact of facility shutdown Economic impact is not compelling reason for continued operation CORREN.D Greater New York Council on Energy 83/05/23 12pp 18588 083 24X Fiche 50-247,83/05/23,8305250223
- 8305270386 Response opposing licensee motion for reconsideration of ABLB denial of licensee motion to admit DP McGuire testimony before trial THORSEN.E O Rockland County, NY 83/05/24 Atomic Safety and Licensing Board Panel 6pp 18645 335 24X Fiche 50-247,83/05/24,8305270586

H General correspondence

- B305240441 Opines that Secision re continued plant operation must weigh health effects of replacement by coal burning plants JAFFE.H Affiliation Unknown B3/05/16 AHEARNE, J Atomic Safety and Licensing Board Panel 2pp 18571 068 24X Fiche 50-247,83/05/16,8305240441
- 830.9240517 Supports continued facility operation SCHULER:R T., HEALEY, J.A., IRMIN.R D. Affiliation Unknown 83/05/16 FALLADINO, N. J. Commissioners 27pp 18571 191 24X Fiche 30-247.83/05/16.8305240917
- B305240537 Supports closing down of facility CINQUEMANI.D., CINQUEMANI.F Affiliation Unknown B3/05/1° Commissioners ip 18576 039 24X Fichs 50-247, 83/05/19, B305240537
- 8305270566 Supports shutdown of facilities on 830609 EFSTEIN.R B Affiliation Unknown 83/05/19 Commissioners 2pp 18646 114 24% Fiche 50-247.83/05/19.8305270566
- 8305240541 Supports suspension of plant operation ORANNIS.A B. New York. State of ELLIOTT.N R. Yorktown, NY 83/05/20 NRC No Detailed Affiliation Given 2pp 18576 091 24X Fiche 50-247.83/05/20.8305240541
- 8305270575 Package of two citizens itrs supporting continued facility operation
 WUNKEL.T C . WEIGANDT, J T Affiliation Unknown B3/05/20
 PALLADING, N J Commissioners 2pp 18447 125 24X
 Fiche 50-247, 83/05/20.8305270575
- 8305240453 Supports continued plant operations Plants should not be held hostage to evacuation process TODOROVICH.M H Affiliation Unknown 83/05/23 CHILK.S J Office of the Secretary of the Commission 5pp 18575 252 24X Fiche 50~247.83/05/23.8305240453
- P Operating license stage documents & correspondence
- 8305030436 Application for amend to License DPR-26, changing Tech Specs by permitting extension of 48 h to current 24 h limitation w/containment spray pump 21 out of svc GRDSCUP, C W Consolidated Edison Co of New York, Inc 83/04/28 VARGA, S A Operating Reactors Branch 1 2pp 18306 277 24X Fiche 50-247,83/04/28,8305030456
- --8305030458 Proposed Tech Spec changes, permitting extension of 48 h to current 24 h limitation w/containment spray pump 21 out of svc ** Consolidated Edison Co of New York, Inc 83/04/28 ip 18305 279 24% Fichs 50-247,83/04/28,8305030454
- B305060355 Confirms B3042B telcon approving proposed Tech Spec amend re containment spray gump LAINA9.6 C Assistant Director for Operating Reactors B3/04/28 O'TOBLE.J D Consolidated Edison Co of New York, Inc 18353 109 24X Fiche 50-247, B3/04/28, B305040355
- 8305100175 Forwards add1 info re instrument accuracy & related data for containment pressure monitors, containment water level monitors & containment hydrogen monitors (NCMEG-0737, Items II F 1 4. II F 1 5 & II. F 1 6), per 821118 request 0'TGOLE, J D Consolidated Edison Co of New York, Inc 83/04/29 VARGA/8 A Operating Reactors Branch 1 14pp 18374 274 24X Fiche 50-247,83/04/29,8305100175
- 8303020435 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D G Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24% Fiche 50-000, 83/05/02, 8305020455
- 8303170644 Clarifies 830105 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review per encl guidelines due in 30 days VAROA-S A Operating Reactors Branch 1 83/05/02 0'TOOLE, J D Consolidated Edison Co of New York, Inc 5pp 18496 349 24X Fiche. 50-247, 83/05/02, 8305170644
- 8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 rg Unresolved Safety Issue A-17 EISENHUT, D G Division of Licensing 83/05/04 PALLADING, N., GILINGKY, V., ROBERTS, T M Commissioners 22pp 18337 139, 24X Fiche 50-000, 83/05/04, 8305040323

- --B305050287 Forwards "Statisticians View of NRC Statistics," presented to American Stds Assoc Advisory Committee on Nuclear Research RUBENSTEIN,D Applied Statistics Branch 81/02/04 ABRAMSON,E.
 - RUBENSTEIN.D Applied Statistics Branch 81/02/04 ABRAMSON.E BASSETT.H , ABELL.T NRC - No Detailed Affiliation Given 8pp 18337 236 24X Fiche 50-247.83/05/04.8305040323
- --8301120436 Draft "Random Thoughts on Uncertainties, Risk Analysis & Nuclear Regulation "
 RUBENSTEIN.D Reliability & Risk Assessment Branch 81/10/26
 12pp 18337 244 24x Fiche 50-247, 83/05/04, 8305040323
- --B305050295 Comments on draft ltr from Handuer to Cooper on NUPPSCO committee Ltr acceptable, however, info re safety classification/terminology issue requires further discussion to standardize term definitions CONRAN, J NRC No Detailed Affiliation Given 82/03/18 COFFMAN, F NRC No Detailed Affiliation Given 5pp 18337 256 24X Fiche 50-247,83/05/04,83050403R3
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods. Bvc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24x Fiche 50-000:83/05/09.8303090659
- 8305130018 Forwards application for amend to License DPR-26.proposing change to Tech Bpc G 3 B.allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of syc Class III amend fee sncl O'TOOLE.J D Consolidated Edison Co of New York, Inc 83/05/09 VARGA,8 A Operating Reactors Branch 1 ip 18436-317 24x Fiche 50-247.83/05/09.8305130018
- --8305130022 Application for amend to License PPR-26, proposing change to Tech Spec 3 3 B, allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of svc O'TOOLE.J D Consolidated Edison Co of New York, Inc 83/05/09 2pp 18436 318, 24X Fiche 50-247,83/05/09,8305130018
- --8305130024 Proposed Tech Spec 3 3 8 (Page 3 3-4), allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of syc Safety assessment & Affidavit of Syc encl.

 * Consolidated Edison Co of New York, Inc 83/05/31 App 1843A 320 24X Fiche 50-247,83/05/09,8305130018
- B30518003B Notification of contract execution, Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ HOYLE.A Administrative Contracts Branch FIN D-8644 83/05/10 DENTON.H Office of Nuclear Reactor Regulation, Director. CODELL, R NRC NO Detailed Affiliation Olven 1p 18499 289 24X Fiche 50-247, 83/05/10, 8305180038
- --8305180047 Mod i.extending period of performance to 830630 & changing payment & general provisions to "Consulting Svc on Indian Point Probabilistic Safety Study"

 LEWIB.J P Columbia Univ REBELLO.J E Division of Contracts 83/05/10. ip. 18499-290 24X Fiche 50-247.83/05/10.8305180038
- Q. Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list ancl.
 TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc. 112pp. 18308 319. 24X Fiche 30-000/83/03/21.8212060385.
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" 8vc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000:83/04/15.8303040021.
- 8305050187 Forwards IE Safaguards Insp Rept 50-247/83-08 on 830228-0304 & notice of violation Notice of violation withheld tref 10CFR73.2 t 4 10CFR2 770)

 MARTINIT T Division of Engineering & Technical Programs. 83/04/20 O'TDOLE, J D Commonwealth Edison Co 2pp. 18341 068. 24X Fiche: 30-247,83/04/20,8305050187
- --8305050190 IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 Noncompliance noted barrier of one vital area not maintained Safeguards info deleted (ref 10CFR2 790) BAILEY,R J., ODDY,A T., Region 1. Office of Director 6pp. 18341 070 24X Fiche 50-247,83/04/20,8305050187

- B303040023 IE Info Notice B3-22, "BWR Safety/Retief Valve Failures "

 Bvc list enc]

 JORDAN.E L. Division of Emergency Preparedness & Engineering

 Response (Post B30103) B3/04/22 Consolidated Edison Co. of New

 York, Inc. 112pp 1B383 087 24X Fiche 50-000, B3/04/22, B303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Past 830(03) 83/04/25 Consolidated Edison Co of New York Inc 119pp 18381 291 24X Fiche 50-000.83/04/25.8303040025
- 8305100427 Forwards IE Insp. Rept. 50-247/83-10 on 830302-0404 & notices of violation & deviation STAROBIECKI, R. Division of Project & Resident Programs 83/04/25 0'TOOLE, J. D. Consolidates Edison Co. of New York, Inc. 2pp. 18410-336 24X Fiche 50-247,83/04/25,8305100427
- --8305100428 Notice of violation from insp on 830302-0404 * Region 1. Office of Director 83/04/25 2pp 18410 338 24X Fiche 50-247,83/04/25,8305100427
- --8305100431 Notice of deviation from insp on 830302-0404 * Region 1, Office of Director 83/04/25 ip 18410 340 24x Fiche 50-247.83/04/25.8305100427
- --B305100433 IE Insp Rept 30-247/83-10 on 830302-0404 Noncompliance noted failure to meet Tech Spec requirements re reportability of fire barriers, failure to establish GA procedures & failure to meet radwaste processing FOLEY.T. KOLTAY.P Region I, Office of Director KISTER.H B Division of Project & Resident Programs 83704/19 19pp 18410 341 24X Fiche 50-247,83/04/25,8305100427
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 30-000,83/04/28,8303040026
- 8.303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Pivision of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 18pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- B305020451 Submits info on status of Ray Milier, Inc problems affecting plant; per ASLB request MODRE, J E Hearing Branch 1 B3/04/28 GLEASON, J P. SHON, F J . PARIS, O H Atomic Safety and Licensing Board Panel BBpp 18283 180 24X Fiche 50-247, 83/04/28, 8305020451
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl URDAN.E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83705703 Consolidated Edison Co of New York, Inc 822pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies " Byo list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response /Post B30103) B3705704 Consolidated Edison Co of New York: Inc 117pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305200191 Forwards request for addi info resulting from review of 820816 response to IE Bulletin 80-11. "Masonry Wall Design "
 Info must be provided within 30 days of 1tr receipt VARQA.8 A Operating Reactors Branch 1 83/05/12 O'100LE.J D Consolidated Edison Co of New York, Inc. 3pp 18540 225 24X Fiche. 50-247,83/05/12,830520191

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
- 30304040 to the through the service of the service
- 8303040046 IE Info Notice 82-33. "Nonrepresentative Sampling of Contaminated Dil " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York: Inc 114pp 18647 007 24X Fiche 30-000,83/05/26,8303040046
- A Periodic operating reports & related correspondence
- 8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & "Annual Radiological Environ Operating Rept.1982." per App B D'TOOLE J D Consolidated Edison Co of New York, Inc. 83/05/02 ALLAN, J M Region 1. Office of Director 2pp 18392 221 24X Fiche 50-003,83/05/02,8305110302
- --8305110307 "Annual Environ Protection Plan Rept for 1982 "
 * Consolidated Edison Co of New York, Inc 83/05/02 8pp
 18372 223 24X Fiche 50-003.83/05/02,8305110302
- --8305110310 "Annual Radiological Environ Operating Rept. 1982 "

 * Consolidated Edison Co. of New York: Inc. 83/05/02 112pp.
 18372 231 24X Fiche 50-003.83/05/02,8305110302
- S Reportable occurrences. LERs & related correspondence
- 8305030400 Forwards LER 83-006/03L-0 O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/04/1 ALLAN, J M Region 1, Office of Director 19 18291 219 24X 83/04/15 Fiche 50-247, 83/04/15, 8305030400
- --8303030407 LER 83-006/03L-0-on 830316, reactor cavity continuous sump level monitor indicated 3 ft above normal & declared inoperable Caused by drifted output from level transmitter LT 3302 in conservative direction Transmitter recalibr HINRICHS, 0 Consolidated Edison Co of New York, inc 83/04/15 Region 1, Office of Director ip 18271 220 24X Fiche 50-247,83/04/15.8305030400
- B305230430 Forwards engineering evaluation rept, "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases 6/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria ASHEF Reactor Operations Analysis Branch 83/04/19 SE Reactor Operations Analysis Branch 2pp 18545-356 24X SEYFRIT, K V Fiche 50-000, 83/04/18, 8305230430
- --8305230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mcchamisms," engineering evaluation rept.LERs re safety-related battery degradation reviewed ASHE-F Reactor Operations Analysis Branch 83/04/18 3pp 18545-338 24X Fiche 50-000.83/04/18,8305230430
- 8305030373 Forwards LER 83-007/03L-0 O'YOULE J D Consolidated Edison Co of New York, Enc 83/04/2 ALLAN J M Region 1, Office of Director 1p 18306 255 24X 83/04/21 Fiche 50-247, 83/04/21, 8305030373
- --B3050303B0 LER 83-007/O3L-0 on B30322, svc water pump 26 removed from svc due to inoperable strainer. Gaused by sheared key connecting drive notor to filter shaft due to accessive debris accumulation within strainer basist Basket cleaned HINRICHS.0 Consolidated Edison Co of New York, Inc 83/04/21. Region i. Office of Director 2pp 18306 256 24X Fiche 50-247,83/04/21,8305030373
- 8305110393 Forwards LER 83-008/03L-0 0'TOOLE.J D Consolidated Edison Co of New York, Inc 83 ALLAN.J H Region I, Gffice of Director Ip 18406 197. Fiche 80-247.83/04/27.8305110393 83/04/27
- --8305110403 LER 83-008/03L-0 on 830328, electric heat trace circuit 518 found w/inoperable primary circuit Caused by primary heating element to be open circuit Element replaced. Circuit tested & returned to svc MODNEY. J Consolidated Edison Co of New York, Inc 83/04/27. Region i. Diffice of Director 1p 18406 198 24X Fiche: 50-247,83/04/27.8305110393
- 8305t60075 Forwards LER 83-009/03L-0 0'700LE: J D Consolidated Edison Co of New Yort, Inc 83/04/2 ALLAN, J M Region 1. Office of Director 19 18451 004 24X Fiche: 50-247, 83/04/30, 8305160075 83/04/30.

- --- 8305160079 LER 83-009/03L-0 on 83033L when operator attempted to start safety injection pump 23 during steady-state operation.pump motor breaker failed to close Caused by seized closing solenoid Breaker replaced MOUNEY, J Consolidated Edison Co of New York, Inc 83/04/30 Region 1, Office of Director 2pp 18451 005 24X Fiche 50-247,83/04/30,8305160075
- 8305160020 Forwards LER 83-010/03L-0 D'TODLE J D Consolidated Edison Co of New York, Inc E ALLAN, J M Region 1, Office of Director 1p 18452 345 Fiche 50-247,83/05/01.8305160020 83/05/01
- --8305160025 LER 83-010/03L-0 on 830401. svc water pump 25 declared inoperable when pump could not be restarted after pump trip Caused by nylon rope from old cathodic protection sys in travelling screens wrapping around impeller & shaft HINRICHS. O Consolidated Edison Co of New York. Inc Region 1. Office of Director ip 18452 346 24X Fiche 30-247, 83/05/01.8305160020
- 8305250483 LER B3-011/O3L-O on 830413 during inservice valve test, valve B878 in suction line to safety injection pump 22 found inoperative Valve 887A operative Caused by pinched & grounded wire for motor on Limitorque valve aperator W/830513 itr MOONEY.J. O'TODLE.J. Consolidated Edison Co of New York, Inc 83/05/13 MURLEY,T E Region in Office of Director 2pp 18588 251 24X Fiche 50-247,83/05/13,8305250483
- T Hearing transcripts on non-antitrust matters
- 8305230001 Transcript of B30322 hearing in White Plains,NY Pp 10.737-11.117 Supporting documentation encl * Atomic Bafety and Licensing Board Panel B3/03/22 612pp 18322 021 24X Fiche 50-247.83/03/22.8305230001
- B305110002 Excerpts from transcript of 830407 hearing Pp 13.017-13.019 * NRC NO Detailed Affiliation Given B3/04/07 3pp 18409 009 24X Fiche 30-247.83/04/07.8305110002
- 8305030608 Motion for permission to present rebuttal witnesses on subj of prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence POTTERFIELD.A Union of Concerned Scientists POTTERFIELD.A, Public Interest Research Group, New York KAPLAN, C New York, NY, 83/04/19 4pp 18308 050 24% Fichs 50-247.83/04/19.8305030608
- ---B305030619 Testimony of D Outman re prevailing wind patterns OUTMAN, D Union of Concerned Scientists QUTMAN, D Public Interest Research Group, New York OUTMAN, D New York, NY B3/04/17 4pp 18308:054 24X Fiche 30-247
- --8305030627 Testimony of RR Holt re sample surveys & bystander behavior. HOLT, R R Union of Concerned Scientists HOLT, R R Public Interest Research Group. New York HOLT, R R New York, NY 83704/19 37pp 18308 058 24X Fiche 50-247, 83704/19, 8303030608.
- --8305030A33 Reorganized testimony of JR Thornborough & D Bohning re Contention 6 2 concerning impact of shutdown on physical environ near facility FOSNER, F Parents Concerned About Indian Point 83/04/19 44pp 18308 095 24% Fich 80-247,83/04/19,8305030608 POSNER. P
- --8305030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site & difficulty of evacuation in emergency POTTERFIELD. A Public Interest Research Group, New York POTTERFIELD. A Union of Concerned Scientists 83/04/26. Atomic Safety and Licensing Board Panel Bpp 18308 137 24X Fiche 50-247,83/04/19,8305000608
- ---8305030452 Hotion requesting completeness of record on NRC Guestions
 3 & 4 rs emergency planning issues, including capability for
 handling phone calls in emergency planning zone during emergancy.

 POTTERFIELD, A , POTTERFIELD, A Union of Concerned Scientists.

 83/04/25 Atomic Safety and Licensing Board Panel App.

 18308-180 24X Fiche. 50-247, 83/04/19, 8305030608
- 8303020077 Transcript of B30426 hearing in White Plains,NY Pp 14,419-14.596 Supporting documentation enci * Atomic Safety and Licensing Board Panel B3/04/26 210pp 18278 250 24X Fiche 50-247, 83/04/26, 8305020077
- 8305030386 Transcript of 830427 hearing in White Plains, NY. Pp 14,597-14,702 * Atomic Safety and Licensing Board Panel 83/04/27, 115pp 18272-001 24X Fiche 50~247,83/04/27,8305030386

- 8305040172 Transcript of 830428 hearing in White Plains, NY Pp 14,703-15,087 Supporting documentation encl # Atomic Safety and Licensing Board Panel 83/04/28 526pp 18324 297 24X Fiche 50-247,83/04/28,8305040172
- 8305090425 Testimony of LA Cohen in rebuttal to testimony of D Gutman Testimony to be included w/ABLB 830420 transcript Certificate of Svc encl COHEN.L A Consolidated Edison Co of New York, Inc 83/04/28 10pp 18363 321 24X Fiche 50-247.83/04/28.8305070425
- 8305040347 Transcript of B30429 hearing in White Plains, NY Pp 15.088-15.226 Supplemental testimonies encl # Atomic Safety and Licensing Board Panel B3/04/29 149pp 18322:242 24X Fiche 50-247.83/04/29.8305040347
- 8305130327 Transcript of Commission 830505 meeting discussion & possible vote in Washington DC re status of emergency planning at facilities Pp 1-22 + Cammissioners 83/05/05 27pp 18457 277 24X Fisher 50-247, 83/05/05, 8305130327
- 8303240534 Statement to be incorporated in minutes of Commission B30526 public hearing State/federal govt must force counties to devise evacuation plans Problems w/emergency plans must be resolved before 830607
 DI GIACOMO, C Q Cortland, NY 83/05/18 4pp 18576 027, 24X Fichs 50-247,83/05/18,830524055
- 8303240366 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PPR, per 100FR9 Commission determination statement end CHILK, B J Dffice of the Secretary of the Commission 83/05/18 Public Document Branch 2pp 18593 063 24X Fiche 30-003,83/05/18,8305240566
- --8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington, DC # Commissioners 82/12/22 15pp 18593 065 24X Fiche: 50-003, 83/05/16, 8305240566
- --8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Mashington.DC + Commissioners 82/12/22 59pp 18593 082 24X Fiche 50-003.83/05/18.8305240566
- 8305240531 Bitatement of Clargy Religious & Laity Concerned About Indian Point, Common citizens reject idea that expertise irrelevant Value of human life is suprame value # Affiliation Unknown 83/05/20 4pp 18571 105 24X Fiche: 50-247, 83/05/20, 8305240531.
- 8305240533 Forwards written testimony on efforts to address deficiencies in emergency response plan since 830505 O'ROURKE, A.P. Westchester County, NY 83/05/20. PALLADINO, N.J., GILINBRY, V., AHEARNE, J. Commissioners 1p 18576, 043 24X Fiche: 50-247, 83/05/20, 8305240533
- --8305240539 Testimony of AP O'Rourke re actions taken to improve smergency planning since Commission 830505 order Unions representing bus drivers fully support orientation course on radiological emergency response procedures
 O'ROURKE A P. Wastchester County, NY 83/05/20, 6pp 18576,044
 24X Fiche 50-247,83/05/20,8305240533
- B303240355 Forwards statement for inclusion in special proceeding testimony.
 WEISB.T. House of Rep B3/05/20. PALLADINO.N Commissioners ip 18576:023. 24X Fiche 50-247.83/05/20.8305240555
- --8303240558 Statement of T Weiss re proposed svacuation plans Plants should be shut down permanently Planning for nuclear accident futile Public safety should be top priority WEISS.T House of Rep. 83/05/19. 3pp 18576-026. 24X Fichs.50-247,83/05/20,8305240555
- 8305310002 Testimony of RW Carlisle re potential hazards of nuclear accidents Long-range educ in nuclear radiation should be implemented. Robots should be developed to dismantle plant after meltdown.

 CARLISLER W. Affiliation Unknown 83/05/20, 3pp 18653 240 24X Fiche: 50-247, 83/05/20, 8305310002
- 8305310035 Transcript of Commission 830523 discussion of Indian Point order in Washington, DC. Pp 1-17 # Commissioners, 83/05/23, 23pp 18463, 128 24X Fichel 30-247, 83/05/23, 8305310055,

- U Congressional/Executive Correspondence
- B305240555 Forwards statement for inclusion in special proceeding testimony MEISS, 7 House of Rep 83/05/20 PALLADING, N Commissioners is 18576-025 24X Fiche 50-247,83/05/20,8305240555
- ---8305240538 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile Public safety should be top priority WEISS.7 House of Rep. 83/05/19 3pp. 18578-026 24X Fiche 30-247.83/05/20.8305240555
- B305310059 Commends State of NY commitment of resources & cooperation w/licensees & local govts to implement offsite smergency preparedness plan pakLLADIND.N J Commissioners 83/05/25 CUUMO.M New York, State of 1p 18653 280 24X Fiche 50-247,83/05/25,8303310059
- --8305310070 Expresses concern that addl actions required to satisfy mandates per 10CFR50 54(5)(1) State of NY Disaster Preparedness Commission will work w/vtils until Rockland County completes amergency preparedness plans CUOMO.M M New York, State of 83/05/25 PALLADINO.N J Commissioners 3pp 18453 281 24X Fache 50-247.83/05/25, 8305310059
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Becurity, medical, emergency & fire protection plans
- B305030336 Discusses 1E Emergency Preparedness Insp Repts 50-010/83-01. 30-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies PAPEMIELLO,C J Region 3. Office of Director B3/04/29 REED,C Cammonwealth Edison Co 2pp 18297 137 24X Fiche 30-010,83/04/29. 8305030334
- --8305030348 Notice of deficiencies from Insp on 830103-07 Public info brochures not distributed from Apr 1781 - Dec 1782 & emergency action levels not reviewed w/state & local govt since 810401 * Region 3, Office of Director 83/04/27 2pp 18297 139 24X Fiche 50-010,83/04/29,8305030336
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISENHUT, D 9 Division of Licensing 83/03/11 Consolidated Edison Co of New York, Inc. 16pp 18540-095 24X Fiche. 30-000, 83/05/11, 8305110034
- 8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR50.App E Emergency plans upgraded per NUREO-0737.Item III A 2 I item complete CHUTCHFIELD.D Operating Reactors Branch 5 83/05/11 FARRAR.D L Commonwealth Edison Co 3pp 18423 040 24X Fiche 50-010,83/05/11,8305120116
- 8305240245 Requests schedular exemptions allowing delay in implementing 10CFR50 48 requirements for installation of fire protection mods Request based on AE.manufacturer & const personnel anticipated implementation schedule RYBAK, B Commonwealth Edison Co 83/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18548 204 24X Fiche 30-000,63/05/18,8305240245
- P. Operating license stage documents & correspondence
- B305020455 Generic Ltr 83-19 to all power reactor & testing licensees per new procedures for providing public notice concerning issuence of amends to GLs Syc list encl EISENHUT.D. @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441:120 24X Fiche 50-000,83/05/02.8305020455
- B3D5040446 Application for amend to Licenses DPR-19 & DPR-25 revising Tech Specs to clarify min reactor pressure when conducting scram testing following refusing outage & requirement for isolation control rod drive pumps.

 RYBAK, B Commonwealth Edison Co B3/05/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18322 23B, 24X Fiche: 50-237, 83/05/02, 8305040446
- --8305040456 Proposed changes to Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & rayise requirement for isolation control rod drive pumps to apply only to single rod scram testing.

 * Commonwealth Edison Co 83/05/02 2pp 18322 240 24X Fiche 50-237,83/05/02.8305040446.

- 8305040520 Supplemental application for amend to Licenses DPR-19 & DPR-23.proposing changes to Tech Spec 4 3 B 1 b to verify nuclear response to control rod drive w/experienced uncoupling at power levels above 20% RYBAK. B Commonwealth Edison Co 83/03/02 DENTON. H R Office of Nuclear Reactor Regulation. Director 2pp 18321 244 24% Ficha 50-237.83/05/02.8305040520
- --8305040524 Proposed Tech Spac 4 3 8 1 b (Page 36) requiring verification of nuclear response to control rod drive w/experienced uncoupling at power levels above 20% a Commonwealth Edison Co 83/05/02 3pp 18321 246 24X Fiche 50-237,83/05/02,8305040520
- 8305040551 Application to amend Licenses DPR-19. DPR-25. DPR-29 & DPR-30. changing App A Jech Specs re economic generation control operation RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321 279 24X Fiche 50-000, 83/05/02, 83055040551
- --8303040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes + Commonwealth Edison Co 83/05/02 ip 18321 281 24X Fiche 50-000,83/05/02,8305040551
- B305130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods.per B30420 ltr Operation w/RPS mod.installed per 1007R50 39 & w/a Tech Specs. will not compromise safe aperation of facilities RYBAK.B Commanwealth Edison Co B3/05/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18439 330 24X Fiche 50-000.83/05/06.8305130209
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT, D G Division of Licensing 83/05/07 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000,83/05/09,8305090659
- 8305130038 Responds to 830316 request for add1 info re NUREG-0737, Item II K 3 28. "Verify Qualification of Accumulators on Automatic Depressuriation Sys Valves "Environ & seismic qualification will be in accordance w/IE Bullstin 77-018 RYBAK.8 Commonwealth Edison Co 83/05/10 DENTON.H R Office of Nuclear Reactar Regulation. Director 2pp 18436-339 24X Fiche 50-000.83/05/10.8305130038
- 8305120370 Forwards Accident Evaluation Stanch SER input to NUREO-0737. Item III D 3 4. "Control Room Habitability " Sys acceptable CRUTCHFIELD.D Operating Reactors Branch 5 B3/03/II FARRAR.D L Commonwealth Edison Co App 18432 275 24X Fichs 50-237.83/05/II, 8305120370
- --8305120374 Advises that licenses proposed program re NUREO-0737. Item III D 3 4. "Control Room Habitability." acceptable MURPHY.D W Battelle Memorial Institute. Pacific Northwest Laboratory FIN 8-2323 82/03/23 HULHAN,L 0 Accident Evaluation Branch 2pp 16432 301 24% Fiche 50-237.83/05/11.8305120370
- 8305200707 Forwards request for add1 info on NUREO-0737. Item II K 3 28 re qualification of automatic depressurization system accumulators Response requested within 45 days
 VASSALLOID 8 Operating Reactors Branch 2 83/05/11 FARRAR, D L
 Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000, 83/05/11, 8308300707
- 8305200184 Notifies that 830425 amend application for groposed Tech Spac changes re TMI Action Item II K 3 15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys DIQOS,R M License Fee Management Branch 83705/12 FARRAR,D L Commonwealth Edison Co 1p 18340 228 24X Fiche 50-000,83/05/12,8305200186
- 8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment OE affidavit per 10CFR2.790 received Westinghouse affidavit forthcoming RYBAK, B. Commonwealth Edison Co 83/05/13 DENTON, H R Defice of Nuclear Reactor Regulation, Director 3pp 18490-347 24% Fiche 50-000, 83/05/13, 8305180376
- B303240290 Commits to resolution of three open items re NUREO-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable RYBAK. B Commonwealth Edison Co 83/05/19 BENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18623-334 24X Fiche 50-237.83/05/19,8305260290

- 8305270419 Notifies that response to 830316.0510 & 11 requests for add1 info re TNI Item II K 3 2B, "Qualification of Automatic Depressurization Sys Accumulators," addressed in 830510 ltr RYBAK, B Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18642 278 24X Fiche 30-000.83/05/23,8305270419
- B305310086 Notification of B30614 meeting w/util in Bethesda, MD to discuss util DCRDR grogram plan OILBERTIR A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000,83/05/26,8309310086
- 8308310028 Advises that requirements of NUREO-0737. Item II F 1 4.

 "Containment Pressure Monitor." II F 1 5. "Containment Water
 Level Monitor" & II F 1 6. "Containment Hydrogen Monitor"
 resolved.per 821220 & 801215 submittals

 CRUTCHFIELD.D Operating Reactors Branch 5 83/05/27 FARRAR.D L.,
 Commonwealth Edison Co 7pp. 18653 213 24X Fiche 50-000.83/05/27,
 8308310028
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list and! TAYLOR.J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8304040268 Requests that insp program re IE Bulletin 80-13, "Cracking in Core Spray Spargers," be performed every 3 yrs in conjunction w/reactor vessel internal insp No abnormalities noted per subj bulletin RYBAK.B Commonwealth Edison Co 83/03/25 KEPPLER, J. G. Region CO Pfice of Director 2pp 17816 282 24X Fiche 50-237, 83/03/25, 8304040268
- 8305020467 Forwards IE Insp Repts 50-010/83-04.50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted STREETER.JF Region 3. Office of Director 83/04/13 REED.C Commonwealth Edison Co 2pp 18283 073 24X Fiche 50-010.83/04/13.83030204647
- --8305020480 IE Insp Repts 50-010/83-06.50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompitance noted Major areas inspected operational safety, maint, surveillance, licensee events, plant trips, refueling activities & refueling surveillance tonous, T M , JORDAN, M J , STASEK, B Region 3, Office of Director, 83/04/12 16pp 18283 075 24X Fichs 50-010.83/04/13,8303020467
- 8303040021 IE Info Notice 83-21, "Defective Emergency Usa Respirator "
 8vc list encl
 JGRDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche; 50-000, 83/04/15, 8303040021
- 8303040D23 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 112pp 18383 089 24X Fiche; 30-000, 83/04/22, 8303040023
- 8305100379 Forwards IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25.0301.09 & 14 & notice of violation HIND-J A Division of Radiological & Materials Safety Programs 83/04/22 REED.C Commonwealth Edison Co 2pp 18377 328 24X Fiche 50-237.83/04/22.8305100379
- --8305100387 Notice of violation from insp on 830222-25.0301.09 & 14 HIND.J A Region 3, Office of Director 83/04/22 2pp 18377 330 24X Fiche.50-237.83/04/22,8305100379
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 19381 291 24x Fiche 50-000,83/04/25,8303040025.
- B305020100 Ack receipt of B30330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-05.

 50-237/83-05 & 50-249/83-04

 BHAFER, W D Region 3. Office of Director B3/04/25 REED, C
 Commonwealth Edison Co ip 18278-243 24X Fichs 50-010,83/04/25.

 8305020100

- --8305020106 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-010/83-05,50-237/83-05 & 50-247/83-04 Corrective actions Amend 71 reissued & incorporated into Tech Specs Corporate QA dept will audit accounting & followup sys FARRAR,D L. Commonwealth Edison Co. 93/03/30 KEPPLER,J 9 Region 3, Office of Director 3pp 18278 244 24X Fichs 50-010,83/04/25,8305020100
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary 8ide of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpaint Adjustment " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8305100092 Provides status of safe shutdown path support installation. per IE Bulletin 79-14 & util 830416 commitment Remaining accessible hanger & four inaccessible hangers will be completed by mid-May & during Fall 1983 outage, respectively RYBAK.B Commonwealth Edison Co 83/04/28 KEPPLER.J 0 Region 3. Office of Director 2pp 18377 218 24X Fiche 50-237.83/04/28, 830510092
- 8305030334 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01. 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies PAPERIELLO.C J Region 3, Office of Director 83/04/27 REED.C Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010.83/04/27. 830803034
- --8303030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401 • Region 3, Office of Director 83/04/29 2pp 18297 139 24X Fiche 50-010,83/04/29,83030303336
- 8303040028 IE Info Notice B3-26. "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Evc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8305100181 Ack receipt of 830411 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 BHAFER, W D Region 3. Office of Director 83/05/03 REED, C Commonwealth Edison Co 1p. 18374 318 24X Fiche 50-010, 83/05/03, 8305100181.
- --8305100190 Responds to NRC 830311 ltr re deficiencies noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24. Corrective actions. written agreement, EPIP200-11 re PMF for Units 2 & 3 between Corps of Engineers & util to be revised RYBAK, B Commonwealth Edison Co 83/04/11 KEPPLER. J 0 Region 3, Office of Director 4pp 18374 319 24% Fiche 50-010, 83/05/03, 8305100181
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc 11st encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for Oeneral Emergencies" Svc list encl, JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705704, Consolidated Edison Co. of New York, Inc. 117pp 18441 001 24X Fichs 50-000.83705704.8303040031.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation," Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp. 18523:248 24X Fiche:50-000:83/05/06:8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EDP) Outdelines " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524,003 24X Fiche 50-000,83/05/11,8303040034.

- 8305200421 Advises that util response to 820714 confirmatory action itre IE Builtetin 79-14, piping analysis to restore hot shutdown path piping sys to FBAR requirements by 830215, acceptable SPESBARD, R. L. Division of Engineering 83/05/18 REED, C Commonwealth Edison Co. 2pp 18517 116 24X Fiche 50-000.83/05/18, 830820421
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " 8vc list enci JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18497 009 24X Fiche 50-000,83/05/19,8303040040
- B309250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program." Vols 1 & 2 to "Response to IE Bulletin 79-018 Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-018 "
 RYBAK.B Commonwealth Edison Co B3/05/19 DENTON,H R Office of Nuclear Reactor Regulation. Director 2,118pp 18578 001 24X
 Fiche 50-000.83/05/19.8305250377
- --8305250373 "OE-NE88 Electrical Penetration Assembly Qualification Program" * Bechtel Corp 83/05/18 356pp 18578 175 24X Fiche 50-000,83/05/19,8302250377
- --8305250407 Rev 2 to Vols 1 & 2 to "Response to IE Bulletin 77-018 for Dresden Nuclear Power Station Unit 3 "

 # Bechtel Corp 83/05/31 387pp 18580 226 24X Fiche 50-000.83/05/19.8305250377
- 8305270395 Notifies that work to be performed on masonry walls, per IE
 Bulletin 80-11. "Masonry Wall Design." will be completed on
 830715 Thirty masonry walls required mods
 RYBAK, B Commonwealth Edison Co 83/05/23 KEPPLER, J O Region 3.
 Office of Director ip 18642 335 24X Fiche 50-237,83/05/23.
 83043204385
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24% Fiche 50-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305040581 Forwards LER 83-015/03L-0 8COTT, D J Commonwealth Edison Co 83/03/25 KEPPLER, J G. Region 3. Office of Director ip 18349 049 24X Fiche 50-249,83/03/25, 8305060581
- --8305040394 LER 63-015/03L-0 on 830404 during normal operation w/DIS 287-1 in progress, pressure switch PS 3-1554 F would not operate at required pressure Caused by plugged instrument snubber Snubber cleaned & switch replaced COYLE, L M Commonwealth Edison Co 83/04/25 Region 3. Office of Director 2pp 18349 050 24x Fichs 50-249,83/03/25.
- B305230573 Forwards engineering evaluation rept. "Crecks & Leaks in Bmall Diameter Piping" BROWN.E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT.K V Reactor Operations Analysis Branch ip 18541 342 24X Fiche 30-000
- --8305230419 "Cracks & Leaks in Small Diameter Piping." engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 348 24% Fiche 50-000, 83/04/19, 8305230573
- 8305020244 Forwards LER 83-013/03L-0 8CDTT.D J Commonwealth Edison Co 83/04/21 KEPPLER, J & Region 3. Geffice of Director 1p 18277 265 24X Fiche. 50-249, 83/04/21, 8305020246
- --8305020256 LER 83-013/03L-0 on 830322, while performing main steam line high flow surveillance, switch 3-261-21 tripped beyond Tech Spac limit Caused by particle on switch gear movement Switch cleaned & retested ANAKDAPPA, A Commonwealth Edison Co 83/04/18 Region 3, Office of Director, 2pp. 18277 266 24X Fiche 50-249,83/04/21,8305020246.
- 8305060963 Forwards LER 83-014/03L-0 BCDTT,D.J. Commonwealth Edison Co 83/04/22 KEPPLER,J Ø Region 3: Office of Director 1p 18348 259 24% Fichs 30-249,83/04/22. 8305060563

- --B305060571 LER 83-014/03L-0 on B30405, main steam line log radiation monitor 3A experienced loss of high voltage power causing monitor to go downscale Caused by burned out resistor on high voltage power supply Monitor 3A replaced MERITY, B Commonwealth Edison Co 83/04/21 Region 3, Office of Director 2pp 18348 260 24x Fiche 50-249,83/04/22,
- B305240366 LER B3-016/01T-0 on B30504, station notified that hydraulic snubber 16, paplaced in Fab 1983, attached on one and only Caused by insufficient personnel interface Work package procedures revised H/830517 ltr
 CUEN.R. SCOTT.D J Commonwealth Edison Co 83/05/17 KEPPLER.J Q Region 3, Office of Director 4pp 18549 291 24X Fiche 50-249,83/05/17,8305240366
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8305110223 Responds to 811031.820702 & 830104 requests for exception from Table 1 of NUREQ-0737.Suppl 1 requirements re location of smergency operations facility Exception granted EISENHUT.D 9 Division of Licensing 83/04/29 UHRIG.R E, Fibrida Power & Light Co 2pp 18434.334 24X Fiche 50-230.83/04/29.830510223
- 8305130008 Informs that emergency offsite facility (EGF) operational w/escaption of issuance of Procedure 1212 & installation of dedicated phone lines at near-site support ctr & EGF, per Owners Ltr 82-33

 UHR10,R E Florida Power & Light Co 83/05/09 EISENHUT, D C Division of Licensing Ip 18436-326 24X Fiche 50-250,83/05/09, 2004520008
- 8303170104 Notification of 830515 meeting w/util in Bethasda,MD to discuss App R alternative shutdown capability details MCDDNALD.D 0 Operating Reactors Branch I 83/05/10 VAROA:8 A Operating Reactors Branch 1 2pp 18475 343 24K Fiche.50-250,83/05/10,8305170104
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re ciarification of access to control procedures for law enforcement visits. Bvc list encl.
 EISENNUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc. 16pp 18540-095 24X
 Fiche 50-000.83/05/11.8305110034
- B305170546 Requests exemption from App R Section III O requiring reactor coolant pump lube oil collection sys to be capable of containing entire lube oil sys inventory Existing sys adequate UHRIG.R E Florida Power & Light Co 83/05/12 EISENHUT.D. O Division of Licensing. 2pp 18469 029 24X Fiche 50-250,83/05/12,8305170546
- 8305200099 Confirms that Div of Safeguards will conduct safeguards regulatory effectiveness review on 830523-27 Review will evaluate overall effectiveness of security program List of review team members encl VAROA 6 A Operating Reactors Branch 1 83/05/12 UHRIO.R E Florida Power & Light Co 3pp 18540 352 24X Fichs 50-250,83/05/12,8305200099
- 8305180568 Informs that emergency plan upgrade to meet 10CFR50 App E. NUREO-0737, Itym III A, 2 1.complete Item closed VAROA.S A Decrating Reactors Brench | 83/05/13 UHRIG.R E Florida Power & Light Co. 3pp | 18505 295 24X Fichs 30-250,83/05/13,8305180568
- J Insurance & indemnity information
- 8305040208 Forwards Endorsement & 4 to NELIA Policy NF-185 & Endorsement 54 to MAELU Policy NF-55
 DUCKLJR Marsh & McLennan: Fnc. B3/04/27 SALTZMAN.J Assistant Director for State & Licensee Relations. 3pp 18323-213 24X Fichs. 50-250, 83/04/29, 8305040208
- P. Operating license stage documents & correspondence
- 8305050293 Forwards draft SER of NUREC-0737, Item II B 3, "Post-Accident Bampling " Eight of 11 criteria met.Criterion 2,10 & 11 incomplete Add1 info requested to complete review of PABS sys VAROA.68 A Operating Reactors Branch 1 83/04/22. UHRIO.R.E Florida Power & Light Co. 31pp 18352-074. 24X Fiche: 50-250,83/04/22,8305050293

- 8305040672 Informs that Amend 91 to License DPR-31 & Amend 85 to License DPR-41 & Generic Ltr B3-07 requirements requiring action to initiate negotiations w/DEF re disposal of high level waste or spent nuclear fuel completed WARGA: 9 A Operating Reactors Branch 1 83/04/25 UHRIG.R E Florida Power & Light Co 2pp 18336 236 24X Fiche 50-250.83/04/25,8305040672
- 8305040653 Advises that addl testing in specific cases re use of energy balance technique & arching action for masonry wall qualification not warranted Decision based on technical info presented during & subsequent to 830120 meeting VARGA-S A Operating Reactors Branch 1 83/04/26 UHRIQ-R E Florida Power & Light Co 2pp 18358 360 24X Fichs 50-250,83/04/26,8305060653
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EIGENRUT, D.O. Division of Licensing 83/05/02 Consolidated Edison Co. of Naw York, Inc. SOpp. 18441 120 24X Fiche 50-000, 83/05/02,8305020455
- 8305180854 Forwards safety evaluation of util submittals re NUREO-0737, Items II F 1 4, II F 1 5 & II F 1 6 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately VARGA: B A Operating Reactors Branch 1 83/05/02 UHRIG: R E Florida Power & Light Co 2pp 18506 031 24X Fiche 50-250.83/05/02.8305180854
- --8305180856 Bafety evaluation of util submittals re NUREO-0737, Items II F 1 4 re containment pressure monitor. II F 1 5 on containment water level monitor & II F 1 6 re containment hydrogen monitor. Licensea design acceptable Uffice of Nuclear Reactor Regulation, Director 83/05/02 5pp. 18306-033 24X Fichs 50-250, 83/05/02, 8305180854
- 8303090432 Forwards justification for continued operation w/electrical equipment in Categories I B & II A identified in Franklin Research Ctr technical evaluation rept per NRC 821213 & 830327 & 31 ltrs
 UHRIO.R E Florida Power & Light Co 83/05/04 VARGA, 8 A Operating Reactors Branch 1 70pp 18363 250 24X Fishe 50-250, 83/05/04, 8305090432
- 8305180541 Summarizes 830329-30 site visit re radiation protection & ALARA aspects of steam generator replacement effort MCDONALD.D G. Operating Reactors Branch 1 83/05/04 UHRIQ.R E. Florida Power & Light Co opp 18505 078 24X Fiche 50-250.83/05/04.8305180541
- B305100165 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETB re terrestrial biological & physical monitoring programs Request did B30210 re deletion of groundwater monitoring program withdrawn.

 UHRIG.R E Florida Power & Light Co B3/05/05 EISENHUT, D G Division of Licensing 5pp 18374 345 24X Fiche: 50-250, 83/05/05, 8303100145
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISEMHUT, D G Division of Licensing 83/05/09, Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fiche 50-000,83/05/09,8305090659
- B305260207 Forwards revised order confirming licenses commitments on NUREO-0727-Item II F. 1, "Post-Accident Monitoring." per B30331 & 0411 ltrs Extended completion schedule to B40515 acceptable VARQA.S.A Operating Reactors Branch 1 83/05/11 UHRIG.R E Fiorida Power & Light Co 3pp 18629 340 24X Fiche 30-250.83/05/11.8305260207
- --8305260211 Revised order confirming licensee commitments on post-THI related issues
 EISENHUT, D. G. Division of Licensing 83/05/11 Florida Power &
 Light Co. 9pp 18629 343 24X Fichs 50-250,83/05/11,8305260207.
- 8305170520 Application for amend to Liceness DPR-31 & 41 providing requirement for monthly walkdown of all accessible safety-related flow paths to verify correct valve position UHRIG.R E. Florida Power & Light Co 83/05/13 EISENHUT, D. O. Division of Licensing 4pp 18467:252 24X Fiche 50-250.83/05/19.8305170520
- --8305i70525 Proposed changes to Tech Specs providing requirement for monthly walkdown of all accessible safety-related flowpaths to verify correct valve position.

 * Florida Power & Light Co. 83/05/13 4pp. 18467.256 24X Fiche: 50-250, 83/05/13, 8305170520

- B305250472 Forwards "Bt Lucie Units 1 & 2 & Turkey Point Units 3 & 4
 Detailed Control Room Design Reviews Program Plan," per
 B30415 commitment re Suppl 1 to NUREG-0737
 UHRIO,R E Florida Power & Light Co B3/05/20 EISENHUT,D G
 Division of Licensing 1p 18589 333 24% Fiche 50-000,83/05/20,
 B305250472
- --B305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan " # Florida Power & Light Co B3/04/30 34pp 1858B 334 24X Fiche 50-000, B3/05/20, B303230472
- 8305230519 Forwards schedule for qualification or replacement of equipment important to safety per IOCFR50 49 Items identified in technical evaluation rept as not within scope of IE Bulletin 79-018 being evaluated UHRIO, R E Florida Power & Light Co 83/05/20 VARGA, S A Division of Licensing 21pp 18583 319 24X Fiche 50-250,83/05/20, 220-250419
- 8303310034 Forwards Class I & III fees for proposed license amend re monthly sys walkdowns UHR70,R E Florida Power & Light Co 83/05/26 EISENHUT,D o Division of Licensing 1p 18653 309 24X Fiche 50-250,83/05/26, R308310034
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319, 24X Fiche 30-000,83/03/21.8212060385
- 8305270129 Supple 830203 response to notice of violation contained in IE Insp Repts 50-250/82-37 & 50-251/82-37 Corrective actions procedure revised to require clearance reviews prior to starting unit from cold or hot shutdown UHRIG.R.E. Florida Power & Light Co 83/03/21 O'REILLY, J P Region 2. Dffice of Director 2pp 18638 215 24% Fiche 50-250, 83/03/21, 8305270129
- 8305270569 Forwards IE Insp Rept 50-25i/83-08 on 830322-24 No noncompliance noted. DANGE.H C. Division of Project & Resident Programs 83/04/05 UHRIO,R E Fiorida Power & Light Co 2pp 18646 338 24X Fiche 50-25i.83/04/05.8305270568
- --8305270587 IE Insp Repts 50-250/83-08 & 50-251/83-08 on 830322-24 No noncompliance noted Major areas inspected hydrostatic testing of reconstituted steam generators KRUO.H E Region 2. Office of Director JAPE.F Division of Engineering & Radiological Safety Programs 83/04/04 3pp 18646 340 24X Fichs.50-251.83/04/05.8305270568
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15, Consolidated Edison Co of New
 York, Inc 126pp 18435 155, 24X Fiche 50-000,83/04/15,8303040021.
- B303040023 IE Info Natice 83-22. "BWR Safety/Relief Valve Failures."
 Svc list encl.

 JORDAN-E. L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/22 Consolidated Edison Co. of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.
- B303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys." 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103), B3/04/25 Consolidated Edison Co of New York, Inc 119p 18381:291 24X Fiche 50-000,83/04/25,8303040025.
- 8305090085 Forwards safety evaluation & notice of granting of relief from inservice insp requirements for ASME Class 1,2 & 3 components, per 770225 request. VAROA,8,A. Operating Reactors Branch 1 83/04/26 UHRIO,R E Fiorida Power & Light Co. 3pp 18367 126 24X Fiche: 50-250,83/04/26,8305090085
- --8305090091 Bafety evaluation supporting requests for relief from inservice insp requirements for ABME Class 1,2 & 3 components.

 # Office of Nuclear Reactor Regulation, Director 83/04/26 7pp 18367;129. 24X Fiche:50-250,83/04/26,8305090085
- --8209150251 "Turkey Point Nuclear Generating Station Units 3 & 4
 Inservice Insp Program," technical evaluation rept

 * Science Applications, Inc. NRC-03-82-076. BAI-186-028-18
 B2/09/10. NRC No Detailed Affiliation Given 35pp.
 18367-138. 24X Fiche-50-000,83/04/26,8305090085.

- --9305070104 Notice of granting of relief from ASME Section XI inservice insp requirements for ASME Class 1.2 & 3 components VAROA.S A Operating Reactors Branch 1 03/04/26 2pp 18367 173 24X Fiche 30-230.83/04/26.83050970085
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Opnerators at PWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, B3/04/28, B30303040026
- B303040027 IE Info Notice 83-25, "Standby Gas Treatment Bys Heater High Tomp Trip Setpoint Adjustment " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3704/28 Consolidated Edison Co of New York. Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027
- 8305030372 Forwards tabulation of equipment qualification proprietary info listed by supplier ref in util response to IE Bulletin 79-018.per 821213 request UHRIG.R E Florida Power & Light Co 83/04/29 VARGA.S A Operating Reactors Branch i 2pp 18306 262 24X Fiche 50-250.83/04/29.8305030392
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8305120398 Discusses IE Insp Repts 50-250/83-04 & 50-251/83-04 on 830222-25 & 03-04 & forwards notice of violation & proposed imposition of civil penalty 0'REILLY.JP Region 2. Office of Director 83/03/03 UHRIG.R E Florida Power & Light Co 3pp 18441 333 24x Fiche 50-250,83/05/03,8305120598
- --8305120604 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted on 830201 & 602, self-reading dosimeter of individual found offscale & 11 individuals performed work in high radiation area O'REILLY.J P Region 2. Office of Director 83/05/03 3pp 18441 336 24X Fiche 50-250,83/05/03,8305120598
- 8303040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24% Fiche 50-000,83/05/06.8303040033
- 8305100001 Submits steam generator repair program cleanliness rept Post-contamination & final loop insps & steam generator search & retrieval accomplished to meet primary & secondary side cleanliness commitments

 UHRIO,R E Florida Power & Light Co 93/05/06 EISENHUT,D G Division of Licensing ip 18377 215 24% Fiche 50-250.83/05/06, 8305300001
- 8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted. DANCE: H C Division of Project & Resident Programs 83/05/06 UHRIG.R E Florida Power & Light Co 2pp 18637 327 24X Fiche. 50-250, 83/05/06, 8303270215
- --8305270219 IE Insp Repts 50-250/83-05 & 50-251/83-05 on B30115-0225 No noncompliance noted Major areas inspected follows on pravious insp findings IE bulletins post-TMI implementation, surveillance testing & maint activities
 VD07-LOWELL,R , AGLESIJ. A Region 2. Office of Director
 JULIAN,C. Division of Project & Resident Programs 83/05/05
 Bpp 18637 331 24% Fiche 50-250, 83/05/06, 8305270215
- 8305270376 Forwards IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted DANCE: H C Division of Project & Resident Programs. B3/05/06 UHRIGA E Florida Power & Light Co 20p 18643-001 24X Fiche: 50-250, 83/05/06, 8305270376

- --93052703B4 IE Insp Repts 50-250/B3-10 & 50-251/B3-10 on 830404-G6 No noncompliance noted Major areas inspected licensee program for keeping radiation doses ALARA DEBS.B T. HOSEY.C M. BARR.K P. Region 2. Office of Director 83/05/04 Bpp 18643 003 24X Fiche 50-230.B3/03/06.B305270376
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EDP) Quidelines " Svc list encl JOHDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORRANNEL Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/19 Compolidated Edison Co of New
 York: Inc 114pp 18697 009 24% Fiche 50-000,83/05/19.8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305230573 Forwards angineering evaluation rept, "Cracks & Leaks in Small Diameter Piping" BROWN,E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000
- --B305230619 "Cracts & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated winnanticipated vibration problems require add1 supports or rerouting of piping BRDHN.E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000/83/04/19/8305230573
- 8305030405 EN-83-027 on 830503 notice of violation & proposed imposition of civit penalty in amount \$40,000 to be issued for licenses failure to perform evaluations to ensure dose stds for workers expased to radiation not exceeded FLACK,E , AXELRAD.J Director's Office, Office of Inspection and Enforcement 83/04/28 ip 18306-312 24X Fiche 50-250,83/04/28,8305030405
- 8305110487 Forwards LER 83-007/01T-0 HILLIAKS.J W Florida Power & Light Co 83/05/03 O'REILLY.J P Region 2. Office of Director 1p 18405 051 24X Fiche 50-250.83/05/03.8305110487
- --8305110496 LER 83-007/01T-D on 830419 manual valves on steam supply lines to auxiliary feedwater pump turbines B & C discovered closed Caused by personnel error in rechanging tage Valves immediately locked open & pumps satisfactorily tested EEARY, Z E Florida Power & Light Co 83/05/03 Region 2, Office of Director 2pp (8405-052 24K Fiche 30-250,83/05/03,830510687
- 8305100098 PNO-II-83-034 on 830504.licensee issued news release re inoperability of two auxiliary feedwater pumps on 830419 Caused by valves inadvartently closed on 830414 JULEAN.C A , LEWIS.R C Region 2, Office of Director 83/05/05 2pp. 18377 255 24X Fiche 30-250.83/05/05.8305100098
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

 F Security, medical, emergency & fire protection plans
- B303110223 Responds to B11031,820702 & B30104 requests for exception from Table 1 of NUREC-0737, Suppl 1 requirements re location of emergency operations facility Exception granted EISCNHUT, D G Division of Licensing B3/04/29 UHRIO,R E Florida Power & Light Co 2pp 18434 334 24X Fiche 50-250,83/04/29,830310223
- B30513000B informs that emergency offsite facility (EGF) operational whereaption of issuance of Procedure 1212 & installation of dedicated phone lines at hear-site support ctr & EGF, per Centric Ltr 82-33

 UHRIG-R E Florida Power & Light Co 83/05/09 EISENHUT.D G Division of Licensing 1p 18436-326 24X Fiche 50-250.83/05/09, Procisionof
- 8305170104 Notification of 830515 meeting w/util in Bathesda: MD to discuss App R alternative shutdown capability details, MCDONALD: D 0 Operating Reactors Branch 1 83/05/10 VARGA: 8 A Operating Reactors Branch 1 2pp 18495 343 24X Fiche 50-250:83/05/10:8305170104

- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits 9vc list encl EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540-095 24X Fiche 50-000,83/05/11,8305110034
- 8303170546 Requests exemption from App R Section III O requiring reactor coolant pump lube oil collection sys to be capable of containing entire lube oil sys inventory Existing sys adequate
 UHRIGAR E Florida Power & Light Co 83/05/12 EISENHUT.D 9
 Division of Licensing 2pp 18468 029 24X Fiche 50-250,83/05/12,8303170546
- 8305200097 Confirms that Div of Safeguards will conduct safeguards regulatory effectiveness review on 830520-27 Review will svaluate overall effectiveness of security program List of review team members encl VAROA.S A Operating Reactors Branch 1 83/05/12 UHRIG.R E Florida Power & Light Co 3pp 18540 352 24X Fichs 30-250.83/05/12.8305200099
- 8305180568 Informs that emergency plan upgrade to meet 10CfR50 App E. NVREO-0737. Item III A 2 1. complete Item closed VARGA. 8 A Operating Reactors Branch 1 83/05/13 UHRIG.R E Florida Power & Light Co 3pp 18505 295 24X Fiche 50-250.83/05/13.8305180568
- J Insurance & indemnity information
- 8305040208 Forwards Endorsement 64 to NELIA Policy NF-185 & Endorsement 54 to MAELU Policy NF-55
 DUCK, J. R. Marsh & McLennan, Inc. 83/04/29 SALTZMAN, J. Assistant Director for State & Licenses Relations 3pp 18323 213 24X Fiche 50-250,83/04/29,8305040208
- P Operating license stage documents & correspondence
- 9305050293 Forwards draft BER of NUREG-0737. Item II B 3, "Post-Accident Bampling " Eight of 11 criteria met Criterion 2.10 % 11 incomplete Add1 info requested to complete review of PASS sys VAROA, S A Operating Reactors Branch 1 83/04/22 UHRIG.R E Florida Power & Light Co 3ipp 18352 074 24X Fiche 50-250,83/04/22,8305030293
- 8305040672 Informs that Amend 91 to License DPR-31 & Amend 85 to License DPR-41 & Generic Ltr 83-07 requirements requiring action to sinitiate negotiations w/DGE re disposal of high level waste or spent nuclear fuel completed VAROA, 8 A Operating Reactors Branch 1 83/04/25 UHRIO, R E Florida Power & Light Co 2pp 18336 256 24% Fiche 50-250.83/04/25,8305040672
- 8303060653 Advises that additesting in specific cases he use of energy belance technique & arching action for masonry wall qualification not warranted Decision based on technical info gresented during & subsequent to 830120 meeting VAROA:8 A Operating Reactors Branch 1 83/04/26 UHRIO:R E Fiorida Power & Light Co 2pp 18358 360 24X Fiche 30-250:83/04/26.8305060653
- B305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Syc list encl EISENHUT, D 9 Division of Licensing 83/05/02. Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455
- 8305180854 Forwards safety evaluation of util submittals re NUREG-0737, Items II F i 4, II F i 5 & II F i 6 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately UARGA-8 A Operating Reactors Branch i 83/05/02 UHRIG-R.E flortida Power & Light Co 2pp i8506 031 24X Fiche 50-250.83/05/02.8305180854
- --8305180856 Bafety evaluation of util submittals re NUREQ-0737, Items
 II F. 1 4 re containment pressure monitor. II F 1 5 on
 containment water level monitor & II F 1 6 re containment
 hydrogen monitor Licensee design acceptable
 4 Office of Nuclear Reactor Regulation, Director 83/05/02 5ps.
 18506 033 24X Fiche 50-250, 83/05/02, 8305180854
- 8305090432 Forwards justification for continued operation w/electrical aquipment in Categories I B & II A identified in Franklin Research Ctr technical evaluation rept per NRC 921213 & 830329 & 31 ltrs
 UHRIO.R.E Florida Power & Light Co 83/05/04 VARGA, S A Operating Reactors Branch 1. 70pp 18363 250 24X
 Fiche 50-250.83/05/04.8305090432

- B305180541 Summarizes B30329-30 site visit re radiation protection & ALARA aspects of steam generator replacement effort MCDONALD, D 0 Operating Reactors Branch i B3/05/04 UHRIG, R E Florida Power & Light Co 4pp 18305 078 24% Fiche 30-250, B3/05/04, B305180541
- B305100165 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETS re terrestrial biological & physical manitoring programs Request dtd B30210 re deletion of groundwater monitoring program withdrawn UMRIG.R E Florida Power & Light Co 83/05/05 EISENHUT, D G Division of Licensing Spp 18374 345 24X Fiche 50-250,83/05/05, B305100165
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl cIBEN-HUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24x Fiche 50-000.83/05/09.8305090659
- B305i40010 Advises that mods to undervoltage protection sys will not be completed until next refueling outage in Mar 1984, in response to NRC 821028 itr re adequacy of electric distribution sys voltages
 UHRIO,R E Florida Power & Light Co 83/05/11 VAROA,8 A Operating Reactors Branch 1 ip 18456 082 24X
 Fiche 50-251,83/05/11,8305160010
- 8305260207 Forwards revised order confirming licensee commitments on NUREO-0737. Item II F 1. "Post-Accident Monitoring," per 830331 & 0411 ltrs Extended completion schedule to 840515 acceptable UAROA, 8 A. Operating Reactors Branch 1 83/05/11 UHRIG, R E Florida Power & Light Co 3pp 18629 340 24X Fiche; 50-250, 83/05/11, 8305260207
- --83052602ii Revised order confirming licensee commitments on post-TMI related issues EISEN-UT-D © Division of Licensing 83/05/11 Florida Power & Light Co 9pp 18629 343 24X Fiche 50-250,89/05/11,8305260207
- 8305170520 Application for amend to Licenses DPR-31 & 41 providing requirement for monthly walkdown of all accessible safety-related flow paths to verify correct valve position UHRIO, R E Florida Power & Light Co 83/05/13 EISENHUT, D 0 Division of Licensing 4pp 18467 252 24% Fichs 50-250, B3/05/13, B305170520
- --8305170525 Proposed changes to Yech Specs providing requirement for monthly walkdown of all accessible safety-related flowpaths to verify correct valve position * Florida Power & Light Co 83/05/13 4pp 18467 256 24X Fiche 50-250,83/05/13,8305170520
- 8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4
 Datailed Control Room Design Reviews Program Plan," per
 B30415 commitment re Suppl 1 to NUREO-0737
 UHRIO, R E Florida Power & Light Co. 83/05/20 EISENKUT, D O
 Division of Licensing 1p 18588 333 24X Fiche 50-000,83/05/20,
- ---8305250491 "8t Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan "
 + Florida Power & Light Co 83/04/30 34pp 18588 334 24X
 Fiche 50-000.83/05/20.8305250472
- B305250519 Forwards schedule for qualification or replacement of equipment important to safety per iOCFR30 49 Items identified in technical evaluation rept as not within scope of IE Bulletin 79-018 being evaluated UHRIG.R E Florida Power & Light Co 83/05/20 VARGA.8 A Division of Licensing 21pp 18383 317 24X Ficha 50-250.83/05/20,8305250519
- B305310034 Forwards Class I & III fees for proposed license amend re monthly eys welkdowns UHRIG.R. E Florida Power & Light Co B3/05/26 EISENHUT.D. Q Division of Licensing, 1p 18653 309 24X Fiche 50-250, B3/05/26, B305310034
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " 8vc list entl.

 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp. 18308 319. 24X Fiche 30-000,83/03/21,8212060385

- 8305270129 Suppls 830203 response to notice of violation contained in IE Insp Repts 50-250/82-37 & 50-251/82-37 Corrective actions procedure revised to require clearance reviews prior to starting unit from rold or hot shutdown UMRIG.R E Floride Power & Light Co 83/03/21 D'REILLY, J P Region 2. Office of Director 2pp 18638 215 24X Fichs 50-250.83/03/21,8305270129
- B305270568 Forwards IE Insp Rept 50~251/83-08 on 830322-24 No noncompliance noted DANCE. H C Division of Project & Resident Programs B3/04/05 URRIG. R E Florida Power & Light Co 2pp 18646 338 24x Fiche 50-251.83/04/05.8305270568
- --8305270587 IE Insp Repts 50-250/83-08 & 50-251/83-08 on 830322-24 No noncompliance noted Major areas inspected hydrostatic testing of reconstituted steam generators KRUO, H E Region 2, Office of Director JAPE, F Division of Engineering & Radiological Bafety Programs 83/04/04 3pp 18446 340 24% Fiche 50-251, B3/04/05, B305270568
- 8303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 Svc list and
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fishe 30-000,83/04/15,8303040021
- 8303040023 IE Info Notice B3-22, "BWR Safety/Relief Valve Failures"
 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 118pp 18383 089 24x Fiche 30-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 1199p 18381 291 24X Fiche 50-000.83/04/25.8303040025
- B305090085 Forwards safety evaluation & notice of granting of relief from inservice insp requirements for ASME Class I.2 & 3 components.per 770225 request VARQA:8 A Deprating Reactors Branch 1 83/04/26 UHRIG.R E Florida Power & Light Co 3pp 18367 126 24X Fiche 30-250.83/04/26.8305090085
- --B305090091 Safety evaluation supporting requests for relief from inservice insp requirements for ASME Class 1,2 & 3 components

 * Office of Nuclear Reactor Regulation, Director 83/04/26 9pp 18367 129 24X Fiche 50-250.83/04/26 8305090085
- --R209150251 "Turkey Point Nuclear Generating Station Units 3 & 4
 Inservice Insp Programs" technical evaluation rept

 * Science Applications: Inc NRC-03-82-096 SAI-186-028-18
 82/09/10 NRC No Detailed Affiliation Given 35pp
 18367 138 24X Fiche 50-000; B3/04/26; B303090085
- --8305090104 Notice of granting of relief from ASME Section XI inservice insp requirements for ASME Class 1,2 & 3 components VARQA,S A Operating Reactors Branch 1 83/04/26 2pp 18367 173 24X Fiche 50-220,83/04/26.8305090085
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Bvc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New Yerk, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- B3D3040027 IE Info Notice B3-25, "Btandby Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York, Int 118pp. 18382 165 24X Fiche 50-000,83/04/28.8303040027
- 8305030392 Forwards tabulation of equipment qualification proprietary info listed by supplier ref in util response to IE Bulletin 79-018, per 821213 request URRIG.R E Florida Power & Light Co 83/04/29 VARGA.S A Operating Reactors Branch 1 2pp 18305 262 24X Fiche 50-250,83/04/29,8305030392
- 8303D40028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JARDAN.E L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03.8303040028

- 8305120398 Discusses IE Insp Repts 50-250/83-06 & 30-251/83-06 on 830222-25 & 03-04 & forwards notice of violation & proposed imposition of civil penalty 0'REILLY.J P Region 2. Office of Director 83/09/03 UHRIQ.R E Florida Power & Light Co. 3pp 18441 333 24X Fiche 30-250.83/03/03,8305120598
- --B305120604 Notice of violation & proposed imposition of civil penalty in amount of \$40.000 Noncompliance noted on 830201 & 02. setf-reading dosimeter of individual found offscals & II individuals performed work in high radiation area O'REILLY, P Region 2. Office of Director 83/05/03 3pp 1841 336 24X Fitch 50-250.83/05/03.8305120398
- 8203040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of Now York, Inc. 112pp 18382 282 24x Fichs 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24x Fiche 50-000,83/05/04.8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305100001 Submits steam generator repair progrem cleanliness rept
 Post-contamination & final loop insps & steam generator
 search & retrieval accomplished to meet primary & secondary
 side cleanliness commitments
 UHRIG.R E Florida Power & Light Co 83/05/06 EISENHUT, D G
 Division of Licensing ip 18377 215 24X Fiche 50-230.83/05/06.
 8305100001
- 8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on B30113-0225 No mancompliance noted DANCE, H C Division of Project & Resident Programs 83/05/06 UHR16, R E Florida Power & Light Co 2pp 18637 329 24% Fiche 50-250,83/05/06,8305270215
- --8305270219 iE insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted Major areas inspected follows on previous insp findings: E bulletins; post-TMI implementation, surveillance testing & maint activities VOOT-LDHELL,R , AGLES,J A Region 2, Office of Director JULIAN.C Division of Project & Resident Programs 83/05/05 8pp 18637 331 24X Fiche 50-250,83/05/06,8305270215
- 8305270376 Forwards IE Insp Repts 50-250/83-10 \$ 50-251/83-10 on 830404-06 No noncompliance noted DANCE-H C Division of Project & Resident Programs 83/05/06 UHRIO,R E Florida Power & Light Co 2pp 18643 001 24X Fiche 50-250,83/05/06.8305270376
- --8305270384 IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted Major areas inspected licenses program for keeping radiation doses ALARA BEBS B Y , HOSEY, C M , BARR, K P Region 2, Office of Director 83/05/04 8pp 18643 003. 24X Fiche 50-250,63/03/06,8305270376
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 CO2 24X Fiche 50-000,83/05/11.8303040034.
- 8303040040 IE Info Notice 83-31, "Error in ABLPIPE Computer Program "
 Bvc list encil
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of Naw
 York, Inc. 114pp 18697-009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-93, "Nonrepresentative Sampling of Contaminated QII" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18447 007 24X Fiche 30-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305030168 Forwards third radiological progress rept for steam generator rapair program UHRIO:R E Florida Power & Light Co. 83/04/29 VAROA:8 A Operating Reactors Branch 1. ip 18300 211 24X Ficha: 50-231,83/04/29,8305030168

- ---8309030173 "Steam Generator Repair Program," radiological progress tept for 830203-0331 # Fiorida Power & Light Co 83/04/29 30pp 18300 212 24X Fichs 50-251.83/04/29,8305030168
- S Reportable occurrences. LERs & related correspondence
- 8305030405 EN-83-027 on 830503 notice of violation & proposed imposition of civil penalty in amount \$40,000 to be issued for licensee failure to perform evaluations to ensure dose stds for workers exposed to radiation not exceeded FLACK.E. AXELRAD. J Director's Office. Office of Inspection and Enforcement 83/04/28 ip 18306-312 24X Fiche 50-250,83/04/28,8305030405
- 8305100251 Forwards LER 83-003/01T-0 WILLIAMS, J W Florida Power & Light Co 83/05/02 O'REILLY, J P Region 2, Defice of Director ip 18374 044 24X Fiche 50-251,83/05/02,8305100251
- --8305100253 LER 83-003/01T-0 on 830417, during spiral loading of core, fuel assembly X-04 observed leaning across empty core ctr & resting against assembly N-51 Caused by assembly not properly seated on guide pins.

 EERRY, Z E Florida Power & Light Co 83/05/02 Region 2, Office of Director 3pp 18374 065 24X Fichs 50-251.83/05/02, 8305100251
- DUCKET 50-253 ACCELERATOR PULSED FAST ASSEMBLY
- Q Inspection reports, IE Bulletins & correspondence
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Svc list encl JORDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103). B3/04/15. Consolidated Edison Co of New York, Inc. 126pp 18435-155 24X Fiche 50-000,83/04/15,8303040021
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8305110034 Cameric Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENNUT.D Q. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X Fichs 50-000 83/05/11 8305110034
- B305240245 Requests schedular exemptions allowing delay in implementing 10CFRSO 48 requirements for installation of fire protection mods Request based on AE. manufacturer & const personnel anticipated implementation schedule RYBAK: B Commonwealth Edison Co B3/03/18 DENTON: H R Office of Nuclear Reactor Regulation, Director App 18548 204 24X Fiche 50-000.83/05/18.8305240245
- 8305250141 Informs that NUREG-0737. Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility item closed.

 VASSALLO, D. B. Operating Reactors Branch 2 83/05/18 FARRAR, D L Commonwealth Edison Co. 3pp 19596 198 24X Fichs 50-254, 83/05/18, 8305250141
- J Insurance & indomnity information
- 8305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Dresden Unit 1 & Endorsement 63 to NELIA Policy NF-201 & Endorsement 53 to MAELU Policy MF-44 for Zion Unit 1 M/o encl Quad Cities endorsements OBTER: J Commonwealth Edison Co 93/05/13 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 18537 174 24X Fiche 50-000,83/05/13.8305230500
- P Operating license stage documents & correspondence
- 8305020597 Forwards safety evaluation on NUREO-0737, Item II B 2 2, "Plant Shielding Node for Vital Area Access " Requirements met VASSALLO.D B Operating Reactors Branch 2 83/04/22 FARMAR, D Commonwealth Edison Co 5pp. 18284 222, 24X Fiche 50-254,83/04/22,8305020397

- 830502045B Forwards info re NUREG-0737.[tem [] D 1, "Performance Testing of BWR Safety/Relief Valves," per NRC 830104 request Applicability of load combination info to BWR Owners Oroup generic test rept acceptable RYBAK,B Commonwealth Edison Co 83/04/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 18pp 18283 311 24X Fiche 50-254,83/04/27,8305020458
- 8305020455 Generic Ltr 83-19 to all power reactor b testing licensees re new procedures for providing public notice concerning issuance of emends to OLs Svc list encl
 EIBENHUT, D 9 Division of Licensing 83/05/02 Consolidated
 Edison Co of New York, Inc 50pp 18441 120 24X
 Fiche 50-000,83/05/02,8305020485
- 8305040551 Application to amend Licenses DPR-19, DPR-25, DPR-29 & DPR-30, changing App A Tech Specs re economic generation control operation RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321 279 24X Fiche 30-000, 83/05/02, 8305040551
- --8305040555 Proposed changes to App A Tech Boots re economic generation control operation W/o detailed changes # Commonwealth Edison Co 83/05/02 pp 18321 281 24X Fiche 50-000,83/05/02,8305040551
- 8305050043 Application for amend to Licenses DPR-29 & DPR-30, changing Tech Specs to limit control rod drive pump isolation from accumulators to single rod scram testing RYBAK, B. Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18342 083 24X Fichs 50-254.83/05/02/8305050043
- 8305130207 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods.per 830420 ltr Operation w/RPS mod, installed per 10CFR30 57 & w/o Tech Specs.will not compromise safe operation of facilities RYBAK.B Commonwealth Edison Co 83/05/06 DENTON.H R Office of Nuclsar Reactor Regulation, Director 2pp 18439 330 24% Fiche 50-000.83/05/06.8305130209
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode 8vc list enci.
 EIBENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000,83/05/09,8305090659
- 8303170716 Advises that action required by 830120 Amend 85 to License DPR-27 & Generic Ltr 83-07 complete based on util negotiating w/DGE re disposal of high level waste or spent nuclear fuel VASSALLO, D B Operating Reactors Branch 2 83/05/07 FARRAR, D L Commonwealth Edison Co 2pp 18476 250 24X Fiche 50-254,83/05/09,830813014
- 8305130038 Responds to 830316 request for add1 info re NUREG-0737, Item II.K. 3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves "Environ & seismic qualification will be in accordance w/IE Bulletin 79-018 RYBAK.B Commonwealth Edison Co 83/05/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X Fiche 30-000,83/05/10,8305130038
- 8305200707 Forwards request for addl info on NUREC-0737. Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days VABBALLO.D B Operating Reactors Branch 2 83/03/11 FARRAR.D L Commonwealth Edison Co 5pp 18528:350 24X Fiche 50-000,83/05/11,8305200707
- 8305200184 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K.3.15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys DIGOS, R M License Fee Management Branch 83/03/12 FARRAR, D L. Commonwealth Edison Co ip 18540 228 24X Fiche 50-000, 83/05/12, 830520018A
- 8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment GE affidavit per 10CFR2 790 received. Westinghouse affidavit forthcoming RYSAK,B. Commonwealth Edison Co 83/05/13 DENTON.H R Office of Nuclear Results Regulation, Director 3pp 18490 347 24X Fiche 50-000,83/05/13,8305180376
- 8305310231 Advises that responses to NUREQ-0737. Item III D 3 4, "Control Room Habitability," acceptable, completing action on item. Safety evaluation encl VABBALLO, D. B. Licensing Brench 2. 83/05/17 FARRAR, D. L. Commonwealth Edison Co 4pp 18662 255 24X Fiche 50-254,83/05/17,8305310231.

- 8305240573 Notifies that NUREG-0737. Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl VASSALLO, D B Operating Reactors Branch 2 83/05/18 FARRAR, D L Commonwealth Edison Co 7pp 18593 338 24X Fiche 50-254, 83/05/18, 8305240573
- 8305270419 Notifies that response to B30316.0510 & 11 requests for addlinfo re TMI Item II K 3 28, "Qualification of Automatic Depressurization Bys Accumulators," addressed in 830510 ltr RYBAK.B Commonwealth Edison Co 83/05/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18642 298 24X Fiche 30-000,83/05/23.8305270419
- B305310086 Notification of B30614 meeting w/util in Bethesda:MD to discuss util DCRDR program plan GILBERT,R A Operating Reactors Branch 5 B3/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000
- 830531002B Advises that requirements of NUREO-0737. Item II F 1 4.

 "Containment Pressure Monitor." II F 1 5. "Containment Mater
 Level Monitor" & II F 1 6. "Containment Hydrogen Monitor"
 resolved.per 821220 & 801215 submittals
 GRUTCHFIELD.D Operating Reactors Branch 5 83/05/27 FARRAR.D L
 Commonwealth Edison Co 7pp 18453 213 24X Fiche 50-000.83/05/27,
 p303310020

Q Inspection reports: IE Bulletins & carrespondence

- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" gvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Résponse (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bansing Sys " Syc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83704/25 Consolidated Edison Co. of New York, Inc. 117pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment 8ys Heater High Temp Trip Betpoint Adjustment " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382 165 24X Fiche 3D-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New Yark, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24x Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Evolist encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705704 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83705704,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24x Fiche 50-000,83/05/04,8303040033

- 8305170167 Forwards response to 83041; notice of violation & proposed imposition of civil penalties re IE Insp Repts 50-254/82-26 1, 50-265/82-26 Also includes remittance in amount of 940,000 of inoperable reactor protection sys subchannel REED, C. Commonwealth Edison Co. 83/05/09 Director's Office. Office of Inspection and Enforcement 1p 18466-308 24X Ficher 50-254,83/05/09,8305170167
- --8305170184 Responds to notice of violation noted in IE Insp Repts 50-234/82-26 & 50-265/82-26 on 82118-22 & 1213-16 Corrective actions Startup Protedure GGP 1-1 revised to include sign-off for verifying clearance of alarm REED.C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 9pp 18466 309 24X Fiche 50-254.83/05/09.8305170167
- B303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Responts (Post B30103). B3703/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11.8303040034
- 8305310105 Forwards IE Insp Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance notes SMAFER, N D Region 3, Office of Director 83/09/12 REED, C Commonwealth Edison Co 2pp 18638-051 24X Fiche 50-254, 83/05/12, 8305310105
- --B305310112 IE Insp Repts 50-254/B3-06 & 50-265/B3-06 on B30219-0422 No noncompliance noted Major areas inspected operational safety,maint. surveillance, licensee monthly repts, regional requests. LERs & public info & special repts CHRISOTIMOS, N , MALKER, R D Region 3, Office of Director B3/05/10 Spp 18628 053 24x Fiche 50-254,83/05/12,8305310105
- 8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14,piping analysis to restore hot shutdown path piping sys to FSAR requirements by 830215,acceptable SPESSARD.R L Division of Engineering 83/05/18 REED.C Commonwealth Edison Co. 2pp 18517 116 24X Fiche 50-000.83/05/1B.8303200421
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"

 8vc Iist ent!

 SVC IIst ent!

 100040, EL Division of Emergency Preparedness % Engineering

 Response (Post 830103) 83/05/19 Compolidated Edison Co of New

 York: Inc 114pp 18697-009 24X Fiche 50-000,83/05/19.8303040040.
- 8305250377 Forwards "GE-NEGS Electrical Penetration Assembly Gualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-018 Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-018" "RYBAK.8 Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2, 118pp 18978 001 24x Fichs 50-000,83/05/19,8305250377
- --8305250393 "GE-NEBS Electrical Penetration Assembly Gualification Program "
 - # Bechtel Corp 83/05/18 356pp 18578 175 24X Fiche 50-000:83/05/19,8305250377
- --83052504i3 Rev 2 to Vols i-3 to "Response to IE Bulletin 79-0iB.Quad Cities Nuclear Power Station Units i & 2" # Bechtel Corp 83/05/31 784pp 18581 253 24X Fiche 50-000.83/05/19.8305250377
- 8305270216 Ack receipt of 830509 transmittal forwarding full payment of proposed civil penalty Corrective actions will be stamined during future insps.

 AMELRAD, J A Enforcement Staff 83/03/25 REED, C R Commonwealt Edison Co 2pp 18637 323 24X Fiche 50-254,83/03/25.8305270216
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Bampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305170972 Forwards monthly operating repts for Apr 1783 KALIVIANAXIS, N Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement ip 18466-053 24X Fiche.50-234, 83/05/02,8305170372
- --8305170376 Monthly operating repts for Apr 1983 MISAK.A Commonwealth Edison Co 83/05/02 21pp 18466 056. 24X Fiche-50-254,83/05/02,8305170372

- 8 Reportable occurrences. LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept. "Cracks & Leeks in Small Diameter Piping" BRDWN, E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT, K V Reactor Operations Analysis Branch ip 18541 342 24X Fiche 50-000, 83/04/19, 8305230573
- --8305230617 "Cracks & Leaks in Small Diameter Piping." engineering evaluation rept Small pipe leaks associated w/unanticipated v/brattion problems require addi supports or rerouting of piping BROWN.E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573
- 8305020142 Forwards LER 83-014/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 83/04/20 KEPPLER,J 6 Region 3, Defice of Director ip 18284 056 24X Fiche 50-254,83/04/20,8305020142
- --8305020154 LER 83-014/03L-0 on 830322, low electrolyte level found in station battery cell 100 Caused by crack in bottom corner of casing Normal loads transferred to Unit 2 250-volt battery on 830324 Cell replaced
 IBEN.C A Commonwealth Edison Co 83/04/20 Region 3, Office of Director 3pp 18284 057 24X Fiche 50-254,83/04/20,8303020142
- 8305030321 Forwards LER 83-015/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 83/04/22 KEPPLER.J Region 3. Office of Director 1p i8297 048 24X Fiche 50-254.83/04/22.8305030321
- ---B305030333 LER 83-015/03L-0 on B30405, reactor bldg & control room ventilation sys isolated & standby gas treatment autostarted Gaused by failure of relay coil 1701-100A Coil replaced Relay will be replaced CLARK, D @ Commonwealth Edison Co 83/04/22 Region 3, Office of Director 2pp 18277 047 24X Fiche 50-254, 83/04/22, 820330321
- 8305060390 Forwards LER 83-016/03L-0
 KALIVIANAKIB: N Commonwealth Edison Co 83/04/27 KEPPLER, J Q
 Region 3. Office of Director ip 18343 155 24X
 Fiche 50-254,83/04/27,8305060390
- --8305060391 LER 83-016/03L-0 on 830331, reactor operator found RHR discharge pressure greater than 90 psig, exceeding Tech Spec range Caused by valve leaking from condensate transfer sys into RHR discharge piping Mod implemented MISAK. A Commonwealth Edison Co 83/04/27 Region 3, Office of Director 3pp 18343 156 24X Fiche 90-254, 83/04/27, 8305060390.
- 8305130212 Forwards LER 83-019/03L-0 KALIVIANAKIS-N Commonwealth Edison Co 83/05/03 KEPPLER, J Region 3, Office of Director |p 18440 085 24X Fiche 50-254,83/05/03,8305130212
- --8305130220 LER 83-019/03L-0 on 830412.1A loop core spray discharge piping pressure indicated above Tech Specs Caused by operator failure to properly bleed down core spray discharge piping & failure of high pressure alarm to annunciate HEBEL.C Commonwealth Edison Co 83/05/03 Region 3. Office of Director. 3pp 18440 086 24X Fiche 50-254.83/05/03,8305130212
- 8305240317 LER 83-017/03L-0 on B30412.RHR evc water pump 1-1001-65C taken out of svc to facilitate repair of broken coupling on RHR svc water vault room cooler 1-5745-C drain line Caused by overpressurization of piping W/830510 ltr LEAVERTON, W . KALIVIANAKIS, N Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 2pp 18548 175 24% Fiche 50-254.83/05/10.8305240317
- 8305240321 LER 83-018/03L-0 on 830412, excessively high discharge pressure & low flow observed from RHR svc water pump i-1001-65C Caused by anti-rotation pin falling out of valve greater Pin replaced & screw tightened W/830510 itr REVNOLDB.S , KALIVIANAKIB.N Commonwealth Edison Co 83/05/10 KEPPLER.J 9 Region 3, Office of Director 4pp 18548 063 24) Fiche 50-254.83/05/10.8305240321
- B305310142 LER B2-027/03L-1 on B30702, due to error in sefety classification for procurement of main valve guides in electromatic relief valves, nonsafety-related parts ordered New administrative procedure written W/B30516 ltr KALIVIANAKIB.N., TIETZ.O Commonwealth Edison Co H3/05/16 KEPPLER.J O Region 3, Office of Director 3pp 18655 025 24X Fiche 50-254, 83/05/16.8305310142

- DOCKET 50-255 PALISADES NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- B305020079 Forwards "Site Emergency Plan B30524-25 Exercise Scenario"

 BEWITT.R B Consumers Power Co 83/04/11 KEPPLER.J G Region 3.

 Office of Director 1p 18279 255 24X Fiche 50-255.83/04/11.

 B305020079
- --8305020083 "Bite Emergency Plan 830524-25 Exercise Scenario " * Consumers Power Co FALEX-83 83/04/11 18pp 18277 256 24X Fiche 50-255,83/04/11 8305020079
- B305020389 Forwards IE Bafeguards Insp Rept 50-255/83-07 on B30328-31 No noncompliance noted MILLER, J. R. Region 3. Office of Director B3/04/27 DEWITT, R. B. Consumers Power Co. 2pp 18276 216 24% Fiche 50-255, B3/04/27, B305020389
- --8305020397 IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization mgt & security program audit Details withheld (ref 10cFR73 21)
 BELANGER.J.L. CHRISTOFFER.G. CREED, J. R. Region 3, Office of Director 83/04/27 2pp 18276 218 24X Fiche 50-255.83/04/27, 8305020389
- 8305120147 Forwards revised closed circuit television coverage & security sys mods resulting from implementation of technical support ctr Encis withheld (ref 10CFR73 21) VANDEHALLE, D J Consumers Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 2pp 18427 157 24X Fiche, 50-255, 83/05/05, 8305120147
- 8303110074 Responds to B21105 ltr transmitting changes to suitability, training & qualification plan Changes acceptable except for items identified in enci change re item 4 requested per iOCFR50 20; CRUTCHFIELD, D Operating Reactors Branch 5 83/05/09 VANDEWALLE, D J Consumers Power Co ip 18408 110 24X Fiche, 30-235, 83/05/09, 8305110074
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034
- 8305200200 Responds to 830218 ltr providing responses to 821209 regulatory effectiveness review rept as result of 830328-0401 safeguards insp Determinations from 830401 safeguards insp listed.
 CRUTCHFIELD.D. Operating Reactore Branch 5 83/05/12 VANDEWALLE, D.J. Consumers Power Cq. 2pp 18540 217 24X Fiche 30-255,83/05/12,8305200200
- B305240043 Bupple B20602 response to IE lnsp Rept 50-255/82-03 Initial responsibility for communications to offsite monitoring team will be kept at technical support ctr until emergency operations facility activated JOHNSON, B D. Consumers Power Co. B3/05/18, KEPPLER, J O. Region 3, Office of Director ip 18547 124 24% Fiche 50-255, 83/05/18, 830524043
- 8305270007 Forwards safety evaluation accepting licensee plan for safe shutdown after fire in Fire Areas 1-4 or in area of auxiliary, shutdown control panel. Plan complies w/10CFR50, App R. Section III Q 3 & III L requirements QRUTCHFIELD, D Operating Reactors Branch 5 83/05/26 VANDEMALLE, D. J. Consumers Power Co 2pp 18633, 329 24X Fiche 50-255, 83/05/26, 8305270007
- --8305270010 Befety evaluation accepting licensee plan for safe shutdown after fire in Fire Areas 1-4 or in area of auxiliary shutdown control panel, per 100FR50. App R. Section III 0 3 & III L requirements # Office of Nuclear Reactor Regulation, Director 83/05/26 13pp 18639 331. 24X Fiche. 50-255.83/05/26.8305270007
- 8305310046 Informs of NRC determination that onsite & offsite amergency preparedness adequate & amergency plans upgraded per NUREO-0737. Item III A 2.1 Item complete CRUTCHFIELD. D. Operating Reactors Branch 5 83/05/27 VANDEHALLE, D. J. Consumers Power Co. Spp. 18653 149 24X Fiche 30-255, 83/05/27, 8305310046

- J Insurance & indemnity information
- 8305240290 Forwards Endorsement 78 to NELIA Policy NF-179 & Endorsement 67 to MAELU Policy NF-50 FROUNFELKER, R Consumers Power Co 83/05/20 SALIZMAN, J Dffice of Nuclear Reactor Regulation, Director 3pp 18548 112 24x Fiche 50-255,83/05/20,8305240290
- P Operating license stage documents & correspondence
- 830523072D Forwards list of utils responding to requests for cost figures on backfitting TOURTELLDTE. J Regulatory Reform Task Force 83/04/11 PALLADIND.N J Commissioners 2pp 18342 272 24X Fiche 30-000.83/04/11.8305230720
- 8305020066 Forwards SER based on review of NUREO-0737, Item III D 3 4. "Control Room Habitability," submitted in 801219 & 821019 ltrs Control room habitability sys acceptable CRUTCHFIELD, D Operating Reactors Branch 5 83/04/29 VANDENALLE, D J Consumers Power Co 6pp 18276 236 24X Fiche 50-255,83/04/29,8305020066
- --8207080528 Notifies that control room meants requirements of SRP 2 2 1 2 2 2.2 2 3 & a 4 & General Design Criteria 4 % 19
 Conclusions based on present plant sys & presumes implementation of effective HVAC mods by licenses MURPHY, D W Battelie Memorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/24 HULMAN, L Q Accident Evaluation Branch 2pp 18276 242 24X Fiche 50-255, 83/04/29, 8305020046
- B303020455 Generic Ltr B3-17 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to QLs Svc list encl EISENHUT, D 0 Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 30-000, B3/05/02, B305020455
- 8305040312 Advises that action required by Amend 73.Paragraph 3 to License DPR-20 to Initiate negotiations w/DDE re disposal of high level or spent nuclear fuel considered complete, based on pursuit of contract w/DDE GRUTCHFIELD.D Derating Reactors Branch 5 83/05/03 VANDEVALLE.D J Consumers Power Co 2pp 18323 291 24X Fiche 50-255.83/08/03.8305040312
- B305100170 Forwards check in response to B30428 ltr requesting remittance of fee for changes to Tech Specs submitted since B21112
 JOHNSON, B D Consumers Power Co B3/05/03 CRUICHFIELD, D Operating Reactors Branch 5 1p 18370 264 24X
 Fiche 50-255, 83/05/03, 8305100170
- 8305100279 Forwards application for amend to License DPR-20, changing Tech Epecs to allow surveillance tests that require cold shutdown conditions to be performed on refueling cycle frequency rather than current iB-month cycle VANDENALLE, D. J. Consumers Power Co. 83/05/05 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 18371 272 24X Fiche 50-255,83/05/05,8305100279
- --8305100787 Application for amend to License DPR-20, changing Tech Specs to allow surveillance tests that require cold shutdown conditions to be performed on refueling cycle rather than current 18-month cycle

 DEHITT: R B Consumers Power Co 83/05/05 9pp 18371 273 24X Fiche 30-255,83/05/05,8305100279
- ---8305100291 Proposed Tech Spec change request re surveiliance testing frequency * Consumers Power Co. 83/05/05 19pp 18371 282 24% Fiche 50-255.83/05/05.8305100279
- 8305160090 Forwards response to 830425 10-day info request on environ qualification of safety-related electrical equipment Qualification of Rosemount transmitters will be maintained by geriodic replacement of degradable D-rings TONER, K. A. Consumers Power Co. 83/05/06 CRUTCHFIELD.D. Operating Reactors Brench 5. 30pp. 18450 131. 24% Fiche 50-255.83/05/06, 8305160090
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl
 EIBENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp. 18627 183 24X
 Fiche 50-000,83/05/09,8305090459

- 8305240305 Forwards Rev 1 to CPC-2A "GA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112 Submittal serves as annual rept
 VANDEWALLE, D. J. Consumers Power Co. 83/05/11 KEPPLER, J. G. Region 3, Office of Director. 2pp. 18575-116. 24X Fiche 50-000,83/05/11.
- --8305240365 Rev 1 to "QA Program Description for Operational Nuclear Power Plants " REYNOLDS.J W. BEWITT, R B . COOK, J N. Consumers Power Co. CPC-26 R01 83/01/10 90pp 18575 118 24X Fiche 50-000.83/05/11.
- @ Inspection reports: IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Erothermic Chemical Reaction" Svc list encl
 TAYLOR, J. H. Division of Safoguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fishe 50-000/83/03/21,8212060385
- B303040023 IE Info Notice B3-22, "BWR Bafety/Relief Valve Failures"
 8vc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list ent! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- 8305020389 Forwards IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted MILLER, J. R. Region 3, Office of Director 83/04/27 DEMITT, R B Consumers Power Co 2pp 18276-216 24X Fiche 50-255, 83/04/27, 620
- --8305020397 IE Bafeguards Insp Rept 50-255/83-07 on 830328-31 No nancompliance noted Major areas inspected security plan & implementing procedures, security organisation mgt & security program audit Details withheld (ref 10CFR73 21) BELANGER, J. L. CHRISTOFFER. G., CREED, J. R. Region 3, Office of Director 83/04/27 2pp 18276 218 24X Fiche 50-255,83/04/27,8305020389
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Cenerators at PURs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24X Fiche 30-000.83/04/28,8303040027
- 8305040475 Submits results of 821123 split sample from clean waste receiver tank for tritium.Sr-89.Sr-90 & gross beta activity analysis Open item in IE Insp Rept 50-235/82-22 on 821028 resolved JOHNSON, B D Consumers Power Co 83/04/29 KEPPLER, J O Region 3, Office of Director ip 18319 145 24X Fiche 50-255.83/04/29, 8309040475
- B303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Braakers " Svc list enc! JORPANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3705703 Consolidated Edison Co of New York, Inc 122pp 1844; 170 24X Fiche 50-000,83705703,8303040028
- 8305200239 Forwards IE Insp Rept 50-255/83-06 on 830301-31 & notice of violation
 SHAFER H D Region 3, Office of Director 83/09/03 DEWITT.R B Consumers Power Co 2pp 18517 107 24x Fiche 50-255.83/05/03, 8306500239
- --8309200244 Notice of Violatian from insp on 830301-31 SHAFER.W D Region 3. Office of Director 83/05/03 1p 19517 109 24X Fiche 50-255,83/05/03.8305200239
- --8305200247 IE Insp Rept 50-255/83-06 on 830301-31 Noncompliance noted failure to follow instrument alarm operability surveillance test procedure

 JORGENSEN. B L . HELLER, J K , BOYD, D C Region 3, Office of Director 83/04/28 6pp 18317 110 24X Fiche 50-255.83/05/03, 8305200219

- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list enc!
 JURDANIE L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JCRDAN; E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc. 117pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031
- 8305170275 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/83-05 NRELIUS, C E Division of Project & Resident Programs 83/05/05 DEGHITT, B Consumers Power Co ip 18465 294 24X Fiche 50-255,83/05/05,8305170275
- ~~8305170300 Responds to NRC 830405 ltr rs violations noted in 1E Insp
 Rept 50~259/83-05 Corrective actions instruments inspected
 for proper valve alignment found in correct position Review
 of instrument calibr data ongoing
 VANDEWALLE, D J Consumers Power Co 83/04/21 KEPPLER, J G
 Region 3, Office of Director 2pp 18465 295 24X
 Fiche 50-255,83/03/05,8305170275
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN: L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 0305190178 Forwards IE Insp Rept 50-255/83-08 on 930328-29
 No noncompliance noted
 LITTLE.W S region 3, Office of Director 83/05/06 DEWITT, R.B.
 Consumers Power Co 2pp 18502 211 24X Fiche 50-255,83/05/06,8303180178
- --8305170183 IE Insp Rept 50~255/83-08 on 830328+29 No noncompliance noted Major areas inspected support structure evaluations & analysis for safety injection & refueling water tank KEATINO, DE . DANIELSON, DH Region 3, Office of Director 83/05/05 3pp 18302 213 24X Fiche 50-255,83/05/06,8305170178
- 8305240020 Forwards IE Insp Rept 50-255/83-07 on 830406-08 & 11-12 No noncompliance noted PAPERIELLO.C J. Region 3. Office of Director 83/05/09 DEWITT-R B. Consumers Power Co. 2pp 18549 014 24X Fiche 50-255.83/05/09.8303240020
- --B305240026 IE Insp Rept 50-255/83-09 on B30406-0B & 11-12 No noncompliance noted Major areas Inspected radiation protection programs including qualifications, audits, radiation protection procedures & status of TMI action items LOVENDALE, P. C. QREGER, L. R. Region 3, Office of Director B3/05/09 Bpp 18549 018 24X Fichs 50-255,83/05/09,8305240020.
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.
- 8305200200 Responds to 830218 ltr providing responses to 821207 regulatory effectiveness review rept as result of 830328-0401 safeguards insp Determinations from 830401 safeguards insp listed CRUTCHFIELD D Operating Reactors Branch 5 83/05/12 VANDENALLE, D J Consumers Power Co 2pp 18540 217 24X Fiche 30-255,83/05/12,8305200200
- 8305240032 Forwards IE Insp Rept 50-255/83-10 on 830401-30 No noncompliance noted 8HAFER.N D Region 3, Office of Director 83/05/17 DEWITT.R B Consumers Power Co 2pp 18549 115 24X Fiche 50-255,83/05/17, 8305240032
- --8305240037 IE Insp Rept 50-255/83-10 on 830401-30 No noncompliance noted Major areas inspected LERs. IE builetins operational safety, surveillance, maint receipt of new fuel & previous insp findings JORGENSEN. B L . HELLER, J K . BOYD, D C Region 3, Office of Director 83/05/13 7pp 18549 117 24X Ficha 50-255, 83/05/17, 8305240032
- B305240367 Ack receipt of B30404 ltr informing NRC of changes in steps taken to correct violations noted in IE Insp Rept 30-235/82-15 Changes examined during IE Insp Rept 30-235/83-10 & acceptable BHAFER.W D Region 3, Office of Director 83/05/17 DEWITT.R.B Consumers Power Co ip 18374 008 24X Fiche 50-255/83/05/17 BB305240367

- --830524037i Amends response to NRC 820823 ltr re violations noted in IE Insp Rept 50-255/82-15 Corrective actions Surveillance Test MO-24 changed from 1 wk after startup to prior to primary coolant temp of 325 F JOHNSON, B. D. Consumers Power Co. 83/04/04 KEPPLER, J. G. Region 3, Office of Director 3pp 18574 009 24X Fiche 50-255, 83/05/17,8305240367
- 8305240043 Supple 820602 response to IE Insp Rept 50-255/82-03 Initial responsibility for communications to offsite monitoring team will be kept at technical support ctr until emergency operations facility activated JOHNBON, B D Consumers Power Co 83/05/18 KEPPLER. J O Region 3. Defice of Director 10 18349 124 24X Fiche 50-255,83/05/19,820824064
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " 8vc 11st enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Bampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24Y Fichs 50-000.83/05/26.8303040046
- R Periodic operating reports & related correspondence
- 8305230270 "Active Mod Projects Operating PWR.1982" + Consumers Power Co 82/12/31 4pp 18576 332 24x Fichs 50-000 82/12/31 8305230270
- 8305100076 Forwards "Annual Environ Operating Rept, 1982 "
 JOHNSDN. B D Consumers Power Co 83/04/27 KEPPLER, J Ø Region 3,
 Office of Director 1p 18377 116 24X Fiche 50-255, 83/04/27,
 8305100076
- --8305100085 "Annual Environ Operating Rept, 1982 "

 --Consumers Power Co B3/04/27 App 18377 117 24X
 Fichs 50-255,83/04/27,8305100076
- 8305110396 Forwards monthly operating rept for Apr 1983
 KENNEDY, D M Consumers Power Co 83/05/05 NRC No Detailed
 Affiliation Given 1p 18406 190 24X Fiche 50-255,83/05/05,
- --8305110402 Monthly operating rept for Apr 1983 PATERSON, D A Consumers Power Co 83/05/05 4pp. 18404 191 24X Fiche 50-255,83/05/05,8305110396
- B305240410 "1982 Radiological Environ Monitoring Rept (Add) Info),"
 revised Tables RBD-E-O3A & RBD-3-O3D
 JOHNSON, B D Consumers Power Co 83/O3/18 KEPPLER, J 0 Region 3,
 Dffice of Director 4pp 18973 397 24X Fiche 50-235,83/
- B Reportable occurrences, LERs & related correspondence
- 6305020138 Forwards LER 83-022/01T-0 JOHNBON, B D Consumers Power Co 83/04/21 KEPPLER, J O. Region 3, Office of Director, 1p 19278, 214 24X Fiche 30-255, 83/04/21, 8305020138
- --8305020145 LER 83-022/01T-0 on 830411 sample from T-82D safety injection tank showed boron concentration below Tech Spec limit Caused by minor leak past loop check valve & safety injection tank check valve or fill & drain valve. * Consumers Power Co. 83/04/21 Region 3. Office of Director. ip. 18278 215 24X Fiche 50-255,83/04/21,8305020138
- 8305020173 Forwards LER 83-021/03L-0 JOHNSON B D Consumers Pawer Co 83/04/21 KEPPLER.J.O Region 3. Dffice of Director. 1p. 18284 066 24X Fiche 50-253,83/04/21, 8305020173
- --B305020179 LER 83-021/03L-0'on 830326, sample from safety injection tank D showed boron concentration below 1,720 ppm Tech Spec ifmit, Caused by minor leakage past loop check valve & safety injection tank check valve or fill & drain valve.
 # Consumers Power Co B3/04/21 Region 3, Office of Director ip 18284:067 24% Fiche, 50-255, 83/04/21, 8305020173
- 8305030642 Telecopy RO:on 830423, safety injection tank inogerable due to routine sempling Additionally, another tenk became inoperable due to low level
 RRICHR M. Consumers Power Co. 83/04/25 Region 3. Office of Director ip, 18305-284 R4X Fiche:50-255,83/04/25,8305030642

- 8305030195 Telecopy RO on B30429, two safety injection tanks inoperable Caused by low level & routine testing Tank level restored RRICH.R N Consumers Power Co. B3/04/26 Region 3, Office of Director 1p 18306 331 24X Fiche 50-255, 83/04/26, 8305030155
- 8305100378 Forwards LER 83-023/017-0 JOHNSON, 8 D Consumers Power Co 83/04/27 KEPPLER, J Q Region 3, Office of Director 1p 18378 224 24X Fiche 50-255, 83/04/27, 8305100378
- --830\$100384 LER 83-023/01T-0 on B30415,during routine sampling of safety injection tank D. tank level fell below Tech Spec limit of 186 inches Caused by delayed fill operations when low flow alarm received for cooling water * Consumers Power Co B3/04/27 Region 3. Office of Director ip 18378 225 24% Fichs 50-255,83/04/27,8305100378
- B305100396 Forwards LER 83-014/017-0 JOHNSON.B D Consumers Power Co 83/04/27 KEPPLER.J Q Region 3, Office of Director 1p 18377 356 24% Ficha 50-255,83/04/27, B30810026
- --B305100403 LER 83-014/01T-0 on 830309.w/safety injection tank D (SIT) imperable due to routine evolution second BIT became inoperable due to low level Gaused by leakage past fill & drain valve on SIT B while draining SIT D for sampling & Consumers Pawer Co 83/04/27 Region 3, Office of Director ip 18377 336 24X Fiche 50-255.83/04/27.8305100396
- 8305060477 Provides update to corrective actions resafety injection refueling water tank support structure discrepancies reported in LER 83-06 Tank design fix planned for 1985 refueling outage Quarterly insps will continue VANDEWALLE.D J Consumers Power Co 83/04/28 KEPPLER.J 0 Region 3, Office of Director 2pp 18348-129 24X Fiche 50-255,83/04/28,8305060477
- B305100250 Updated RO 83-04 evaluation of discrepancies between asmobilit & actual design of safety injection refueling water tank support structure indicated sufficient capacity to resist loadings Schedule for mods & design review submitted VANDEMALLE, D. J. Consumers Power Co. 83/04/28 KEPPLER, J. O. Region 3, Office of Director 2pp (8410 362 24X Fiche 50-255,83/04/28,8305100250
- B305060388 Forwards LER B3-024/01T-0
 JOHNSON, B D Consumers Power Co 83/04/29 KEPPLER, J O Region 3,
 Office of Director 1p 18343 154 24X Fiche 50-255, 83/04/29,
 B305060388
- --8305060393 LER 83-024/01T-D on 830423 safety imjection tanks T-828 & T-82D became inoperable due to low level & routine evolution, respectively Caused by leakage past fill & drain valve Fill & drain valves will be inspected & Consumers Power Co 83/04/29 Region 3, Office of Director ip 18343 154 24X Fiche 50-255,83/04/29,8305060388
- 8305100306 Telecopy RO on 830429, sample from T-82D (safety injection tank D) showed boron concentration below Tech Spec limit While attempting to increase boron level-addl safety injection of T-82B occurred T-82D & T-82B restored KRICH-R M Consumers Power Co 83/05/02 Region 3. Office of Director ip 18371 138 24X Fiche 50-255, 83/05/02, 8305100306
- 8305130140 Forwards LER 83-026/017-0 JOHNSON, B D Consumers Power Co 83/05/09 KEPPLER, J & Region 3, Office of Director 1p 18440 045 24X Fiche 50-255,83/05/09, 8305130140
- --8305130145 LER 83-026/017-0 on 830428, sample from T-82D (safety tank D) showed boron concentration below Tech Spec limit Caused by boron dilution due to minor leakage past loop check valve Primary coolant leak rate monitored * Consumers Power Co 83/03/09 Region 3, Office of Director ip 18440-046 24X Fiche 50-255,83/03/09,8305130140
- 8305130208 Forwards LER 83-027/01T-0 JGHN80N,B D Consumers Power Co 83/05/09 KEPPLER, J Q Region 3 Office of Director. 1p 18440 069 24X Ficher 50-255,83/05/09, 8305130208
- --B305130214 LER 83-027/01T-0 on B30428, w/safety injection tank D T-820 inoperable, tank T-828 bacame inoperable due to low level Caused by leakage past fill & drain valve on tank B fill & drain valves to be inspected & repaired * Consumers Power Co B3/05/09 Region 3, Office of Director ip. 18440-070 24X Fiche 30-255,83/05/09,8305130208
- 8305130225 Forwards LER 83-025/03L-0 JOHN8DN:8 D. Consumers Power Co 83/05/09 KEPPLER:J G Region 3, Office of Director 1p 18439 327 24X Fiche 50-255,83/05/09, 8303130225

- --8305(30230 LER 83-025/03L-O on 830410, sample from T-82c showed boron concentration below Tech Spec limit of 1720 ppm Caused by minor leakage past loop check valve 5 BIT check valve Primary coolant leak rate being closely monitored consumers Pawer Co. 83/05/09 Region 3. Office of Director 1p. 18437 328 24x Fishe 50-255,83/05/09.8305130225
- 8305240011 LER 83-028/03L-0 on 830415, level of safety injection tank D reached Tech Spec limit of 198 inches Caused by minor leakage past loop check valve Leak rate being closely monitored Valves will be inspected W/830511 ltr JUHNSON, 8 D Consumers Power Co 83/05/11 KEPPLER. J O Region 3, Office of Director 2pp 18549 026 24X Fiche 30-255, 83/05/11.
- 8305200407 Ack receipt of 830428 ltr providing updated info re RO 83-06 & proposed schedule for mods to safety injection refueling water tank support structure per FSRR & ACI code Remedial work to be completed during 1982 refueling outage SPEGSARD, R L Region 3, Office of Director 83/05/17 VANDEMALLE, D J Consumers Power Co 2pp 18518 120 24X Fiche 30-255,83/05/17,8305200407
- 8305270152 PNO-III-83-039 on 830323.util emplayee entered protected area through open & unmonitored entrance to receive whole body count Individual escorted out of area Region III will investigate
 CREED.J. HIND.J Region 3. Office of Director 83/05/23 ip 18638 is9 24x Fiche 50-255,83/05/23,8305270152
- 8305310148 LER 93-030/01T-0 on 830509, sample from safety injection tank T-82D showed boron concentration below Tech Spec 3 imit Caused by minor leakage past loop chock valve & safety injection tank check or fill & drain valve W/830323 ltr +. JOHNSON.B D Consumers Power Co. 83/05/23 KEPPLER, J Q Region 3. Office of Director 2pp 18652 333 24X Fiche 50-235, 83/05/23, 8305310148
- B305310197 LER 83-031/01T-0 on B30509, w/safety injection tank (SIT) D (T-82D) inoperable due to routine evolution second SIT (T-82D) became inoperable due to low level Caused by Leakage past fill & drain valve on SIT B W/B30923 ltr JOHNSON, B D Consumers Fourt Co B3/05/23 KEPPLER, J O Region 3, Office of Director 2pp 18638 136 24X Fiche 50-255,83/05/23,8305310197
- 8305310202 LER 83-029/03L-0 on 830422.safety injection tank B reached Tech Spec limit of 19B (nohes Caused by minor leakage past loop check valve Primary coolant leak rate being monitored Tank restored to normal range W/830523 Ltr JGHNSON.B D Consumers Power Co 83/05/23 KEPPLER, J Q Region 3 Office of Director 2pp 18651 021 24X Fiche 50-255,83/05/23,83053/0602
- DOCKET 50-259 BROWNS FERRY NUCLEAR POHER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8303090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-256/82-47 on 82(220 & forwards notice of violation & proposed (aposition of civil penalty Encls withheld (ref 10CFR2 790)

 U'REILLY, J P Region 2, Office of Director 83/01/13 PARRIS, H Q Tennessee Valley Authority 3pp 18363 119 24x

 Fiche 50-259,83/01/13,8305090191
- 8305040628 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18327 006 24% Fiche 50-259,83/04/26,8305040628
- --8303040633 Forwards public version of revised emergency plan implementing procedures, including Procedure IP-2 renotification of unusual event, IP-3 realert & IP-4 resite area emergency KAMMER-D S Tennessee Valley Authority 83/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18329 007 24X Fiche 50-259, 83/04/26, 8305040628
- --8305040655 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency * Tennessee Valley Authority 63/03/03 84pp 18327 000 24x Fiche 50-259, 83/04/26, 8305040628
- B305100234 Requests that Figures B 5-48 & B 3-13B be removed from updated FSAR & destroyed & replaced w/encl pages since figures contain info classified as safeguards info per 10CFR73 HILLB.L H Tennessee Valley Authority, B3/05/04, DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18373 266 24X Fiche, 50-259, 83/05/04, 8305100234

- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list ent]
 EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 80-000,83/05/11.8305110034
- 8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Itom III A 2 I VASSALLO, D D Operating Reactors Branch 2 83/05/18 PARRIS, H G Tennessee Valley Authority 3pg 18648 107 24X Fichs 50-259,83/05/18,8305260177
- J Insurance & indemnity information
- B305160005 Forwards Endorsements 65 & 54 to NELIA Policy NF-198 & MAELU Policy MF-66, respectively DUCK, J R Harsh & McLennen, Inc. 83/05/03 BALTZMAN, J Assistant Director for State & Licensee Relations. 3pp. 18456-059 24X Fiche 50-259,83/05/03,8305160005
- P Operating license stage documents & correspondence
- 8305040730 Discusses AEOD/E309, "Potential for Water Hammer Damage During Restart of RHR Pumps at BWR Nuclear Power Plants "Recommendations provided do not extend beyond procedural development & operator awareness
 HELTEMES: C J Director's Office B3/04/22 EIBENHUT, D Division of Licensing BPEIS. T Division of Safety Technology 1p 18328 067 24% Fiche 50-259.83/04/22,8305040730
- --8305040737 Forwards AEOD/E309, "Potential for Hater Hammer During Restart of RNR Pumps at SWR Nuclear Power Plants" RUBIN/S Reactor Operations Analysis Branch 83/04/21 SEYFRITIK V Reactor Operations Analysis Branch ip 18683 319 24X Fiche 50-259,83/04/22,8305040730
- --8305040745 "Potential for Water Hammer During Restart of RHR Pumps at BMR Nuclear Power Plants." AEOD engineering evaluation rapt RUBIN.6 . LANIK. @ Director's Office 83/04/30 29pp. 18328 069 24X Fichs. 50-259.83/04/22
- 8305040511 Application for amend to Licenses DPR-33, DPR-52 & DPR-68 revising stated isolation logic for Group 7 isolation valves to reflect actual logic.

 MILLB.L.M. Tennessee Valley Authority 83/04/28 DENTON:H R. Office of Nuclear Reactor Regulation. Director 2pp 18322,038 24X Ficha 50-259,83/04/28,8305040511
- --8305040517 Proposed changes to Tech Spacs revising stated isolation logic for Group 7 isolation valves to reflect actual logic * Tennessee Valley Authority 83/04/28 5pp 18322 040 24X Fiche 50-259, 83/04/28, 8305040511
- 8305020435 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
 EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24x Fiche 50-000,83/05/07,8305090659
- 8305180845 Advises that action required by Amends 86.83 & 57 to Licenses DPR-33.DPR-52 & DPR-68.respectively & Generic Ltr 83-07 complete.based on util negotiating w/DDE re disposal of high level waste VASSALLO.D B Operating Reactors Branch 2 83/05/07 PARRIS.H O Tennesee Valley Authority 2pp 18506 018 24% Fiche 50-259.83/05/09.8309180845
- 8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983, in response to NRC 830429 request NILLS.L M Tennesser Valley Authority 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18437.008 24X Fiche 50-259,83/05/10,8305130003
- 8305230136 Forwards request for add1 info rs NUREG-0737. Item II.K 3 28; "Qualification of ADS Accumulators" Info requested within 45 days
 VASSALLO, D 8 Operating Reactors Branch 2 83/05/11 PARRIS.H 0.
 Tennessee Valley Authority 3pp 18576 204 24X
 Fiche: 50-259, 83/05/11, 8305250136

- 83052A0187 Forwards safety evaluation re BWR Dwners Group response to NUREG-0737. Item II K 3 45, "Depressuriation W/Other Than Autometic Depressurization Sys " Action complete VABSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G Tennessee Valley Authority 2pp 18648 099 24X Fiche 50-259, 83/05/18, 8305260187
- 8303250473 Forwards info re status of environ qualification of equipment per 10CFR50 47(g) Gualification status table, achedule for qualifying deficient equipment & addl justification for continued operation encl KAMMER.D S Tennessee Valley Authority 83/05/20 DENTON, H R D#fice of Nuclear Reactor Regulation. Director 94pp 18585 110 24% Fiche 50-259,83/05/20,8305250473
- 8305240372 Requests remittance of balance due for review of 820721
 application to amend Browns Ferry 1 Toch Specs re Cycle 5
 MCPR values & 820623 application re physical security plan
 changes for Sequoyah 1 & 2
 MILER.W O License Fee Management Branch 83/05/20 PARRIS.H Q
 Tennessee Valley Authority 2pp 18647 284 24X
 Fiche 50-000,83/05/20,8305260372
- B305270021 Notifies that util will submit schedule for performing mods to Mark I containment drywell/wetwell vacuum breakers once calculations complete & mods identified in response to Generic Ltr B3-08
 MILLS.L M Tennessee Valley Authority 83/05/23 DENTON.H R. Office of Nuclear Reactor Regulation. Director ip 18638-313 24X Fiche: 50-207, 83/05/28.8305270021
- B305270030 Forwards response to B30316 request to document compliance w/acceptance criteria & schedule for NUREO-0737. Item II K 3 13, "Separate HPCI & RCIC Initiation Levels "Criteria will be met HILL9.L M Tennessee Valley Authority B3/05/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18638 306 24X Fichs 50-259, 83/05/24, 8305270030
- @ Inspection reports, IE Bulletins & correspondence
- #305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (reficeFR2 790) O'REJLLY, J.P. Region 2. Office of Director B3/01/13 PARRIS, H.O., Tennesse Valley Authority 3pp 18363 119 24X Fichs 50-259, 83/01/13, 8305090191
- 8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33,50-260/82-33 & 50-296/82-33 will be delayed until 830301 MILLO.L M Tennessee Valley Authority 83/01/28 O'REILLY.J P Region 2, Office of Director ip 18638 071 24X Fiche 50-259,83/01/28,8305270171
- 8305270177 Forwards 830111 response to notice of violation & proposed imposition of civil penalty erroneously submitted to JP G'Reilly W/o encl HILE.L M Tennessee Vallay Authority 83/02/10 DEYOUNO,R C Director's Office, Office of Inspection and Enforcement ip 18637-362 24X Fiche 50-259,83/02/10,8305270177
- B2120A0385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Bvc list enci. TAYLOR.J M Division of Safeguards & Inspection Programs (Post B30103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche S0-000,83/03/21,8212060385
- 8305270514 Forwards IE Insp Repts 90-297/83-06.50-260/83-06 t 50-276/83-06 on 830214-19 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/30 PARRIES H C. Tennessee Valley Authority 2pp 18646 182 24X Fiche: 50-259.83/03/30.8305270514
- --8305270526 IE Insp Repts 50-259/83-06.50-260/83-06 & 50-276/83-06 on 830214-19 No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performance & results HMITENER, H. J. JAPE.F. Region 2. Office of Director 83/03/28 8pp. 18646 184 24X Fiche 50-259,83/03/30.8305270514
- 8305270202 Concurs w/util 830401 request for extension of commitment dates for responding to violations noted in IE Insp Repts 50-295/82-16. 50-286/82-16 until 830701 LEMIS.R C Division of Project & Resident Programs 83/04/07. PARRIE.H O Tannesses Valley Authority ip 18637 170 24X Fiche: 50-259. 83/04/07. 8305270202

- --8305270206 Advises that new full compliance date of 830901 required to complete review of procedures, preparation of revs & issuance of revised instructions in 1 esponse to IE Insp. Repts 30-259/82-16, 30-260/82-16 & 50-276/82-16

 MILLS.L M Tennessee Valley Authority 83/04/01 O'REILLY, J.P. Region 2, Office of Director 1p 18637 171 24X
 Fiche 50-259, 83/04/07, 8303270202
- 8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 VERRELLI.D M Division of Project & Resident Programs 83/04/07 PARRIS.H 9 Tonnessee Valley Authority 1p 18662 132 24X Fiche 50-259.83/04/07,8305270642
- --8305270652 Responds to NRC 830210 ltr re violations noted in IE Insp Repts 50-259/83-02, 90-260/83-02 & 90-296/83-02 Corrective actions radiochemical lab manual Procedure 728 [II 2 1 wil] be revised HILLS, L M Tennessee Valley Authority 83/03/16 (I'REILLY, J P Region 2, Office of Director 3pp 18662 133 24X Fichs 50-259,83/04/07.8305270642
- --8305270638 Forwards IE Insp Repts 50-259/83-02.50-260/83-02 & 50-296/83-02 on 830117-18 & notice of violation VERRELLID M Division of Project & Resident Programs 83/02/10 PARRISH 0 Tennessee Valley Authority 2pp 18662 136 24X Fiche 50-259.83/04/07.8305270642
- --8305270661 Natice of violation from insp on 8301(7-18 * Region 2, Office of Director 83/02/10 ip 18662 i38 24X Fiche 50-259,83/04/07.8305270642
- --B305270666 IE Insp Repts 50-259/83-02.50-260/83-02 & 50-296/83-02 on B30117-18 Moncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis COLLINS.T R . BARR,K P Region 2. Office of Director 83/02/10 3pp 18662 139 24X Fiche 50-259.83/04/07.8305270642
- B305270653 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-44. 30-240/82-44 & 50-296/82-44 VERRELLI-D M Division of Project & Resident Programs 83/04/13 PARRIS
- --8305270660 Responds to NRC 830225 ltr re violations noted in 1E Insp Repts 50-259/82-44,50-260/82-44 & 50-296/82-44 Corrective actions interim criteria for removal of waste oil & miscellaneous wasts from regulated areas developed MILLS,L H Tennessee Valley Authority 83/04/01 O'REILLY,J P Region 2, Office of Director 5pp 18645 202 24X Fichs 50-259,83/04/13,8305270653
- --B305270664 Forwards IE Insp Repts 50-259/82-44.50-240/82-44 & 50-276/82-44 on B21(15-19 & notice of violation O'REILLY, J.P. Region 2. Office of Director B3/02/25 PARRIS.H G. Tennessee Valley Authority 2pp 18645 207 24X Fichs 50-259,83/04/13.8305270653
- --8305270665 Notice of violation from insp on 821115-19 * Region 2, Office of Director 83/02/23 2pp 18645 209 24% Fichs 30-239,83/04/13.8305270653
- --8305270668 IE Insp Repts 50-259/82-44.50-260/82-44 & 50-296/82-44 on B21115-19 Noncompliance noted licensee transferred licensed matt to unauthorized recipients & disposed of matt by unapproved means DBBS, B T. BARR, K P. Region 2, Office of Director B2/12/23 7pp. 18649 211 24% Fiche 30-289, 83/04/13,8305270453
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303270266 Forwards IE Insp Repts 50-259/83-13,50-260/83-13 & 50-296/83-13 on 830329-30 No noncompliance noted Major areas inspected procedures, representative records & observations of demonstrated ultrasonic methodology W/o encl VERRELLI, D H Division of Project & Resident Programs 83/04/19 PARRIS, H O Tennessee Valley Authority 3pp IB641 326 24% Fiche 30-259,83/04/19,8305270266
- 8303040023 IE Info Notice 83-22, "BWR Sefety/Relief Valve Failures "

 Svc list encl
 JGRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

- B305030625 Forwards add1 info re masonry wall per IE Bulletin 80-11, in response to NRC B30128 ltr Results of wall displacement analysis will be submitted by B30715 W/three oversize drawings Aperture cards are in PDR MILLS, L M Tennessee Valley Authority B3/04/22 DENYON, H R Office of Nuclear Reactor Regulation, Director 7pp 18303 001 24% Fiche 50-259, B3/04/22, B305030625
- --8305030631 Rev 2 to BFN-50-D709, "Detailed Design Criteria for Reevaluation Criteria for Masonry Halls " * Tennessee Valley Authority 82/03/26 162pp 18303 009 24X Fiche 50-259,83/04/22,8305030625
- 8305270510 Forwards IE Insp Repts 50-259/83-08,50-260/83-08 & 50-296/83-08 on 830327-31 No noncompliance notes 'VERRELLI.D H Division of Project & Resident Programs 83/04/22 PARRISH 0 Tennessee Velley Authority 2pp 18646 065 24X Fiche 50-259,83/04/22,8305270510
- --8305270528 IE insp Repts 50-259/83-08.50-260/83-08 & 50-296/83-08 on B30328-31 No noncompliance noted Major areas inspected mgt & administrative controls status review of radiological environ monitoring program & insp of monitoring stations CUNNINGHAM.A L. HONTOUMERY, D M. Regian 2. Dffice of Director B3/04/20 Spg 18846-067 24X Fiche 50-295,83/04/22.8305270510
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 1838; 29: 24x Fiche 50-000,83/04/25,8303040025
- 8303040026 JE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consulidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl URBPANCE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705703 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83705703,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Swc list end URBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830(03) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp. 18382 282 24X Fiche 50-009,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl URDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 89/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fichs 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list enci JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Editon Co. of New York
- 8305270345 Act receipt of 830421 itr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-257/83-05.
 50-260/83-05 & 50-296/83-05.
 LEWISIR C Division of Project & Resident Programs 83/05/09 PARRISI
- --8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-259/83-05, 30-260/83-05 & 30-296/83-05 Corrective actions-conduit mounting supports connected to conduits & supported per General Const Spec 0-3. MILLS.L M Tennessee Valley Authority 83/04/21 O'REILLY, J P Region 2. Office of Director App 18642 080 24X Fiche 50-259, 83/05/09, 8305270345
- --8303270362 Forwards (E Insp Repts 50-259/83-05.50-260/83-05 & 50-276/83-05 on 830126-0225 & notice of violation LEWIS, R C Division of Project & Resident Programs 83/03/16. PARRIS,N, 9 Tennessee Valley Authority. 2pp 18642.084. 24X Fiche-50-259,83/05/09.8305270345

- --8305270368 Notice of violation from insp on 830126-0225 = Region 2, Office of Director 83/03/16 2pp 18642 086. 24X Fiche 30-229, 83/05/09, 8305270345
- --8305270381 IE Inap Repts 50-259/83-05.50-260/83-05 & 50-296/83-05 on 830126-0228 Noncompliance noted violation of 105FR30.App B. Criterion V in maint area & violation of Tech Spec re Surveillance Insp 2
 PAULK.O L. Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 83/03/14 8pp 18642 088 24% Fiche 50-259.83/05/09.8305270345
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000.83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp. 18697 009 24X Fichs 50-000,83/05/19,8303040040
- B303040046 JE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Qil " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18447 007 24X Fiche 50-000, B3/05/26, B303040046.
- S Reportable occurrences, LERs & related correspondence
- B305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping" BROWN.E J Reactor Operations Analysis Branch B3/04/19 BEYFRIF.K V Reactor Operations Analysis Branch ip 18541 342 24X Fiche 50-000
- --8305230619 "Cracks & Leaks in Bmail Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN, E. J. Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573
- B305030501 Telecopy RG 50-259/B3021 on B30424,130 fuel bundles unloaded from core & placed in high density fuel storage rack in spent fuel atorage pool not tested for boron concentration Causad by inadequate procedures COFFEY. J A Tennessee Valley Authority 83/04/25 Region 2, Office of Director 2pp 18294 168 24x Fichs 50-259,83/04/25, B305030501.
- B305050266 Forwards LER 83-020/01T-0 GREEN,H J Tennessee Valley Authority 83/04/29 O'REILLY,J P Region 2. Office of Director 1p 18338 044 24X Fiche 50-259, B3/04/29, B305050266
- --8305050272 LER 83-020/01T-0 on B30418, line A, B, C & D MSIVs exceeded allowable leakage rates Caused by deterioration of MSIV seating surfaces during operation Valves will be repaired prior to startup & MSIV improvement program implemented HOLDER, E T Tennessee Valley Authority 83/04/29 Region 2, Office of Director 2pp, 18338-045 24% Fiche 50-259, 83/04/29, 8305050266
- B305100001 Forwards updated LER 82~030/03X-1 QREEN.H J Tennessee Valley Authority 83/05/03 D'REILLY, J.F. Region R. Office of Director 1p 18377 262 24X Fiche: 50-259, 83/05/03, 8305100081
- --8305100083 Updated LER 82-030/03X-1 on 820506 during normal operation. GE error noted in transient analysis for Cycle 5 Caused by procedural error Min critical power ratio increased by 0, 02 (1 6%). Data constants will be changed LOCHBAUM, D A Tennessee Valley Authority. 83/05/03 Region 2, Defice of Director 3pp 18377 263 24X Fiche 50-259, 83/05/03, 8305100081.
- B305100012 Forwards updated LER 80-047/03X-1 QREEN.H J. Tennessee Valley Authority 83/05/04, O'REILLY, J P Region 2, Office of Director 19 18377, 154 24X Fichs. 50-259, B3/05/04, B305100012
- --8305100014 Updated LER 80-047/03X-1 on 800620, increase in pressure detected on shell side of RHR i-C HX Caused by loose locking & full nuts on floating head due to thermal cycling & vibration Locking tabs installed on nuts HOLDER, E. T. Tennessee Valley Authority 83/05/07 Region 2, Uffice of Director, 2pp 18377 155 24X Fiche 50-259, 83/05/04, 8305100012

- 8305110355 Forwards LER 83-019/03L-0 QREEN,H J Tennessee Valley Authority 83/05/06 O'REILLY, J P Region 2, Office of Director ip 18406 079 24X Fiche 50-259,83/05/06,8305110355
- --8305110367 LER 83-019/03L-0 on 830410. smoke detector XB-39-66XM alarmed due to leakage of water into detector Bource of water not determined Detector replaced & will be relocated to avoid leakage MURPHY.D Tennessee Valley Authority 83/05/06 Region 2. Office of Director 2pp 18406 080 24X Fiche 50-259.83/05/06.830510355
- 8305130085 Forwards LER 83-021/01T-0 QREEN.H J Tennessee Valley Authority 83/03/06 O'REILLY,J P Region 2: Office of Director Ip 18436 016 24X Fiche 50-259,83/05/06.8305130085
- --8305130091 LER 83-021/017-0 on 830424.130 fuel bundles unloaded from core into high-density spent fuel storage rack (HDSF8R) did not have required post-installation boron test Caused by personnel failure to verify HDSF8R acceptability HHITBON D R Tennessee Valley Authority 83/05/06 Region 2. Dffice of Director 3pp 18436-017 24X Fiche 50-259,83/05/06,830513085
- 8305200588 PNO-II-83-039 two intergranular stress corrosion cracks found on recirculation line end cap weld Cracks found during ultrasonic insp per IE Bulletin 83-02 Further weld insps planned BLAKE, J. J., BUTCHER, R. C. Region 2, Office of Director 83/05/16 1p 18514-247 24% Fiche 50-259,83/05/16.8305200588
- 8305250402 Telecopy RO 50-259/83024 on 830517, design review of emergency diesel generator room ventilation sys capabilities revealed design temp limits of some electrical components may be exceeded Caused by error in heat dissipation data CDFFEY. J A. Tennessee Valley Authority 83/05/18 Region 2, Office of Director 2pp 18585 333 24X Fiche 50-259,83/05/18,8305250402
- X Onsite Storage of Low Level Waste
- 8305030679 Requests remittance of add1 sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste HILLER, H. O. License Fee Hanagement Dranch 83/04/22 HILLB, L. M. Tennessee Valley Authority 2pp. 18309 193 24X Fiche 30-000,83/04/22.8305030679
- DOCKET 50-260 BROWNS FERRY NUGLEAR POWER STATION, UNIT 2

 F Security, medical, amergency & fire protection plans
- 8305090191 Discusses IE Security Insp Repts 50-259/82-47, 30-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encis withheld (ref 10CFR2, 790).

 O'REILLY, U.P. Region 2, Office of Director 83/01/13 PARRIS, H. & Tennessee Valley Authority. Spp 18363 119 24X
 Fiche' 50-259:83/01/13,8305090191
- 8303040628 Releases public version of revised emergency plan implementing procedures FELTDN.J.H. Division of Rules and Records. 83/04/26 Document Management Branch. ip 18327-006 24X Fiche 30-239,83/04/26, 8303040628
- --8305040633 Forwards public version of revised emergency plan implementing procedures, including Procedure IP-2 renotification of unusual event, IP-3 realert & IP-4 resite area emergency.

 KANMER, D. B. Tennessee Valley Authority 83/03/21. DENTON, H R Office of Nuclear Reactor Regulation. Director 1p. 18329 007 24% Fiche 50-259, 83/04/26, 8305040628
- --8303040655 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event; IP-3 re alert & IP-4 re site area emergency, e Tannessee Valley Authority 83/03/03, 84pp. 18329 008, 24x Fiche, 50-259, 83/04/26, 8305040628.
- 8305100234 Requests that Figures 8 5-48 & 8,5-138 be removed from updated FSAR & destroyed & replaced w/encl pages since figures contain info classified as safeguards info per 10CFR73.
 MILLS,L M Tennesse Valley Authority, 83/05/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp 18373 266 24X Fiche. 50-259,83/05/04,8305100234

- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16ps 18540 095 24X
 Fiche 30-000,83/09/11,8305110034
- 8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans uppraded per NUREO-0737, Item III A 2 1
 VASSALLO.D B Operating Reactors Branch 2 83/05/18 PARRIS.H G Tennessee Valley Authority 3pp 18648 107 24X
 Fiche 50-259,83/05/18,8305260177

J Insurance & indemnity information

- B303160005 Formands Endorsements 65 & 54 to NELIA Policy NF-198 & MAELU Policy MF-66, respectively DUCK, JR Marsh & McLennan, Inc. 83/05/03 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18456-059 24X Fiche 30-239, 83/05/03, 83/35160005
- P Operating license stage documents & correspondence
- 83033003B7 Forwards Amend 83 to License DPR-52, safety evaluation & notice of issuance & availability Amend revises Tech Specs to incorporate limiting conditions for operation during Cycle 5 & reflects procedural mods CLARK-R J Operating Reactors Branch 2 83/03/11 PARRIS-H & Tennessee Valley Authority 2pp 17753 211 24X Fiche 50-260.83/03/11.8303300387
- --B303300396 Amend B5 to License DPR-52, revising Tech Specs to incorporate limiting conditions for operation during Cycle 5 & reflecting design, equipment & procedural mode made during refueling outage
 VAESALLO,D B Operating Reactors Branch 2 83/03/11 77pp 17753 213 24X Fiche 30-260,83/03/11.8303300387
- --8303300401 Bafaty evaluation supporting Amend 85 to License DPR-52 * Office of Nuclear Reactor Regulation, Director 83/03/11 12pp 17753-290 24X Fiche 50-260.83/03/11.8303300387
- --8303300408 Notice of issuance & availability of Amend 85 to License DPR-52
 VABBALLO.D B Operating Reactors Branch 2 83/03/11 2pp 17753:302 24% Fiche: 50-260, 83/03/11, 8303300387
- 8303040511 Application for amend to Licenses DPR-33.DPR-52 & DPR-68 revising stated isolation logic for Group 7 isolation valves to reflect actual logic MILLS.L.M Tennessee Valley Authority 83/04/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18322 038 24X Fiche 50-259,83/04/28,8305040511
- ~-8303040517 Proposed changes to Tech Specs revising stated isolation logic for Group 7 isolation valves to reflect actual logic * Tennessee Valley Authority 83/04/28 5pp. 18322'040, 24X Fiche-50-29,83/04/28,8305040511
- 8305020455 Owneric Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuence of emends to OLs Svc list encl.
 EISENMUT, D 0 Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441-120, 24X
 Fiche 50-000,83/05/02,8305020495
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode 8vc list enc! EISENMUT.D 9 Division of Licensing. 83/05/09 Consolidated Edison Co. of New York. Inc. 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659
- 8305180771 Requests permission for M Tokar.Core Performance Branch.to Visit site on 830512 to discuss 821023-1101 test on fuel bundles Fuel failures caused by crud-induced localized corrosion VASBALLO, D. E. Operating Reactors Branch 2 83/05/09 PARRIS.H O Tennessee Valley Authority 2pp 18506 057 24X Fiche 50-260.83/05/09.8303180771
- BJ051B0B45 Advises that action required by Amends B6:83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively & Generic Ltr 83-07 complets, based on util negotiating w/DBF re disposal of high level waste VABBALLO, D B Operating Reactors Branch 2, B3/05/09 PARRIB, H Q Tennessee Valley Authority. 2pp 18506:016 24% Fiche 50-239, B3/05/09, B3051B0B45

- 8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983.in response to NRC 830429 request HILLS, L M Tennessee Valley Authority 83/05/10 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 1p 18437 008 24X Fiche 50-259,83/05/10,8305130003
- 8305230136 Forwards request for additinfo re NVREG-0737, Item 11 K 3 28, "Gualification of ADS Accumulators" Info requested within 43 days
 VASSALLO, D B Operating Reactors Branch 2 83/05/11 PARRIS, H G
 Tennesses Valley Authority 3pp 18598 204 24X
 Fichs 30-239,83/05/11.8305230136
- 8305250473 Forwards info re status of environ qualification of equipment per 10CFR50 49(g) Qualification status table, schedule for qualifying deficient equipment k addijustification for continued operation encl
 HAMMER, D 8 Tennessee Valley Authority 83/05/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 94pp 18385 110
 24X Fiche 50-259,83/05/20,8305250473
- 8305270021 Notifies that util will submit schedule for performing mods to Mark I combainment drywell/wetwell vacuum breakers once calculations complete & mods identified in response to Generic Ltr 83-08
 MILLS: L. M. Tennessee Valley Authority 83/05/23 DENTON: H. R. Office of Nuclear Reactor Regulation, Director 1p 18638-313 24X Fiche 50-239.83/05/23.8305270021
- 8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREQ-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels "Criteria unil be met MILLS,L M Tennessee Valley Authority 83/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18638 306 24X Fiche 50-259,83/05/24-8305270030

Q Inspection reports, IE Bulletins & correspondence

- 8305090191 Discusses 1E Security Insp Repts 30-239/82-47, 50-260/82-47 & 30-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2 790)
 O'REILLY, J F Region 2, Office of Director 83/01/13 PARRIS, H G Tennessee Valley Authority 3pp 18363 119 24X
 Fiche 50-259, 83/01/13, 8305090191
- 8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33, 50-260/82-33 & 50-296/82-33 will be delayed until 803001 MILLS.L M Tennessee Valley Authority 83/01/28 O'REILLY.J P Region 2. Office of Director ip 18638 071 24X Fiche 50-257,83/01/28.8305270171
- 8305270177 Forwards 830111 response to notice of violation & proposed imposition of civil penalty arroneausly submitted to JP O'Reilly M/o encl HiLLB, L M Tennesses Valley Authority 83/02/10 DEYOUNG, R C Director's Office
- 8212040385 TE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York: Inc 112pp. 18308 317 24x Fiche 50-000.83/03/21.8212040385
- 8305270514 Formards IE Insp Repts 50-259/83-06.50-260/83-06 & 30-276/83-06 on B30214-19 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/30 PARRIES.H G Tennessee Valley Authority 2pp 18646 182 24X Fiche 50-259.83/03/30.8305270514
- --8305270526 IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19. No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performence & results HHITENER, H. L. JAPE, F. Region 2, Office of Director 83/03/28 Bpp 18646, 184 24% Fichs 50-259/83/03/20,8305270514
- B305270202 Concurs w/util B30401 request for extension of commitment dates for responding to violations noted in IE insp Repts 50-239/82-16.50-260/82-16.50-296/82-16 until B30901 LEHIS.R.C. Division of Project & Resident Programs B3/04/07 PARRIS.H 0 Tennessee Valley Authority tp. 18637 170 24X Fiche 50-259.83/04/07,8305270202

- --8305270206 Advises that new full compliance date of 830901 required to complete review of procedures preparation of revs & issuance of revised instructions in response to IE Insp Repts 30-259/82-16.50-260/82-16 & 50-294/82-16 MILLS.L M Tennessee Valley Authority 83/04/01 O'REILLY.J P Region 2. Defice of Director ip 18637 171 24X Fiche 30-259.83/04/07.8305270202
- 8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-02, 50-260/83-02 & 50-296/83-02 & The state of Project & Resident Programs 83/04/07 PARRIS.H 0 Tennessee Valley Authority ip 18662 132 24% Fiche 50-259, 83/04/07, 8305270642
- --8305270452 Responds to NRC 830210 ltr re violations noted in IE Inap Repts 30-259/83-02.50-260/83-02 & 30-296/83-02 Corrective actions radiochemical lab manual Procedure 728 III 2 1 will be revised MILLS.L M Tennessee Valley Authority 83/03/16 O'REILLY, J P Region 2, Office of Director 3pp 18662 133 24X Fiche 50-259.83/04/07,8305270642
- --9305270658 Forwards IE Insp Repts 50-259/83-02, 30-260/83-02 & 50-276/83-02 on 830117-18 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/02/10 PARRIS, H G Tennessee Vallay Authority 2pp 18662 136 24X Fiche 50-259, 83/04/07, 8305270642
- --8305270661 Notice of violation from insp on 830117-18 * Region 2, Office of Director 83/02/10 ip 18662 138 24X Fiche 50-259,83/04/07,8305270642
- --8305270466 IE Insp Repts 50-257/83-02,50-260/83-02 & 50-296/83-02 on B30117-18 Noncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis COLLINS, T R , BARR, K P Region 2, Office of Director 83/02/10 3pp 18662 139 24x Fiche. 50-259,83/04/07,8305270642
- 8305270653 Ack receipt of 930401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-44, 30-240/82-44 & 50-296/82-44 VERELLI.D M Division of Project & Resident Programs 93/04/13 PARRIS.H O Tennessee Vailey Authority ip 18445 201 24X Fiche 50-259, 83/04/13, 8305270653
- --8305270640 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44, Corrective actions interim criteria for removal of waste oil & miscellaneous wastes from regulated areas developed MILLS.L M Tennessee Valley Authority 83/04/01 D'REILLY, J P Region 2. Office of Director 5pp 18645 202 24X Fiche 50-259,83/04/13,8305270653
- --8303270664 Forwards IE Insp Repts 50-259/82-44,50-260/82-44 & 50-296/82-44 on B21115-19 & notice of violation O'REILLY, J P. Region 2, Office of Director 83/02/25, FARRIS, H O Tennesses Valley Authority 2pp 18645 207 24X fiche 50-259,83/04/13,8305270653
- --8305270665 Notice of violation from insp on 821115-19 # Region 2, Office of Director 83/02/25 2pp 18645 209 24X Fich: 50-259,83/04/13,8305270653
- --B305270468 IE Imsp Repts 50-259/82-44, 50-260/82-44 & 50-294/82-44 on 821115-19 Noncompliance noted licensee transferred licensed matl to unauthorized recipients & disposed of matl by unapproved means DEBS, T. BARR, K. P. Region 2, Office of Director 82/12/23 7pp 18645 211 24X Fiche 50-259,83/04/13,8305270653
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp. 18435 155 24X Fiche 50-000, 83/04/15, 8303040021
- 8305270266 Forwards IE Insp Repts 50-259/83-13,50-260/83-13 & 50-296/83-13 on 830329-30 No noncompliance noted Major areas inspected procedures, representative records & observations of demonstrated ultrasonic methodology M/a anci VERRELLI.D M Division of Project & Resident Programs 83/04/19 PARRIES H G Tennessee Valley Authority 3pp 18641 326, 24X Fiche 50-259,83/04/19.8305270266.
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list enc! JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24x Fiche 50-000,83/04/22,8303040023

- 8305030625 Forwards add1 info re masonry wall per IE Bulletin 80-11, in response to NRC 830128 itr Results of wall displacement analysis will be submitted by 830715 W/three oversize drawings Aperture cards are in PDR MILLS L.M Tennesses Valley Authority 83/04/22 DENTON, H R G#fice of Nuclear Reactor Regulation, Director 7pp 18303 001 24X Fiche 30-259,83/04/22,8305030625
- --8305030631 Rev 2 to BFN-50-D709, "Detailed Design Criteria For Recyaluation Criteria for Masonry Walls " * Tennesses Valley Authority 82/03/26 162pp 18303 008 24X Fiche 50-259.83/04/22.8305030625
- 8305270510 Forwards IE Insp Repts 50-239/83-08,50-260/83-08 & 50-276/83-08 on 830329-31 Na noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/04/22 PARRIS.M Q Tennessee Valley Authority 2pp 18646 065 24X Fiche 50-259.83/04/22,0305270510
- --B305270528 IE Insp Repts 50-257/83-08, 50-240/83-08 & 50-294/83-08 on B30328-31 No noncompliance noted Major areas inspected mgt & administrative controls status review of radiological environ monitoring program & insp of monitoring stations CUNNINGHAM, A. L. MONTOOMERY, D. M. Region 2, Office of Director B3/04/20. Spp 18446 047 24X Fiche 50-259,83/04/22,8305270310
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Bensing Sys." By: tist encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/R5 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Bteam Generators at PWRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047 24X Fiche, 30-000, 83/04/28, 8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Bys Heater High Tamp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 1189p 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list end; JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Byc list encl JGRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Gonsolidated Edison Co of New York, Inc. 112pp 18362 282 24X Fichs 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl. JORDAN,E L Division of Emergency Preparadness & Engineering Response (Poet 830103), 83/03/04 Consolidated Edison Co of New York, Inc. 119pp 18441'001 24X Fichs 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation." Bvc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705706. Consolidated Edison Co. of New York, Inc. 115pp 18523.248 24X Ficha 50-000.83705706.8303040033.
- 8305270345 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-05; 50-260/83-05 & 50-296/83-05 LEHIB; R C. Division of Project & Resident Programs. 83/05/09 PARRIB; H Q Tennessee Valley Authority. 1p. 18642 079 24X Fiche. 50-259, 83/05/09, 8305270345
- --8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp. Repts 50-257/83-05, 50-267/83-05 & 50-276/83-05 Corrective actions: conduit mounting supports connected to conduits & supported per General Const Spec G-3
 MILLS, L. M. Tennessee Valley Authority, 83/04/21 O'REILLY, J. P. Region 2, Office of Director 4pp 18442 ORO 24X Fiche: 50-259, 83/05/09, 8305270345
- --8305270362 Forwards IE Insp Repts 50-257/83-05.50-260/83-05 & 30-284/83-05 on 830126-0225 & notice of violation LEWIS, RC Division of Project & Resident Programs. 83/03/16 PARRIS.H. 9 Tennessee Valley Authority 2pp. 18642-084 24X Fiche: 50-259,83/05/09,8305270345.

- --8305270368 Natice of violation from insp on 830126-0225 • Region 2, Office of Director 83/03/16 2pp 18642 086 24X Fiche 30-239,83/09/09,8303270349
- --8305270391 IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 on 830126-0225 Noncomptiance noted violation of 10cF650. App B. Criterion V in maint area & violation of Tech Spec re Surveillance Insp 2
 PAULK.G L. Region 2. Office of Director CANTRELL, F. S. Division of Project & Resident Programs 83/03/14 8pp 18642 088 24X Fiche 30-259, 83/05/09, 8305270345
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Sycilist encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidate Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Syc list entl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19.8393040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl
 JGRDAN, E.L. Division of Emergency Preparedness > Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305050238 Forwards LER 83-014/03L-0 OREEN.H J Tennessee Valley Authority 83/04/28 O'REILLY.J P Region 2, Office of Director 2pp 18337 299 24X Fiche: 50-260.83/04/28.8305050238
- --B305050245 LER B3-014/03L-0 on B30330 air operator on main steam relief valve PCV-1-B0 found assembled incorrectly Caused by failure to follow reassembly procedures Valve repaired & insp procedure clarified HOLDER, E T Tennessee Valley Authority B3/04/28 Region 2, Office of Director 2pp 18337 300 24X Fiche 50-260,83/04/28, B30505023B
- 8305100031 Forwards LER B3-015/03L-0 QREEN.H J Tennessee Valley Authority B3/05/04 O'REILLY, J P Region 2, Office of Director 19 18377 144 24X Fiche 50-260.83/05/04.830510031
- --B305100036 LER 83-015/03L-0 on 830406, drywell pressure switch 2-P8-64-57A found operating above Tech Spec Limit Caused by setpoint drift Static O-ring switch Model 12N-AA4, recalibr, tested & returned to svc BASS, O H Tennessee Valley Authority 83/05/04 Region 2, Office of Director 3pp 18377 145 24X Fiche 30-260,83/05/04, 2335100041
- 8305100285 Forwards LER 83-016/03L-0 OREEN.H J Tennessee Valley Authority 83/05/04 D'REILLY, J P Region 2, Office of Director 1p 18971 243 24X Fiche. 50-260.83/05/04.8305100285
- --8305100292 LER 83-016/03L-0.on 830406, drywell pressure switches 2-P5-64-98D, SM 1 & 2 found to operate at setting exceeding Tech Spec limit Caused by setpoint drift Static D-ring switch IZN-AA4 recalibr BASB, 0 M Tennessee Valley Authority B3/05/04 Region 2. Dffice of Director 3pp 18371 244 24X Fiche 50-260, 83/05/04, 8305100285
- 8305190191 Forwards LER 83-017/03L-0 OREEN-H J Tennessee Valley Authority B3/05/05 O'REILLY, J P Region 2, Office of Director 1p 18437 202 24X Fiche 50-260-83/05/05.8305190131
- --8305130141 LER 83-017/03L-0 on 830409, hydrogen analyser B, H2AN-76-104 declared inogerable due to receipt of loss-of-flow light 76-88 Caused by moisture collecting in sample lines Lines blown down & dried Moisture collection devices to be added. LITELE, G V Tennessee Valley Authority 63/05/05 Region 2, Office of Director 2pp 18437 203 24x Fiche, 50-260, 83/05/05, 8305130311
- 8305170330 Forwards LER 83-020/03L-0 QREEN.H J Tennessee Valley Authority 83/05/09 D'REILLY, J P Region 2. Office of Director ip 18465 141 24x Fichs 50-260.83/05/07.8305170330

- --8305170340 LER 93-020/03L-0 on B30410 during power maneuvers for recirculation sys testing calculated R factor was less than R setpoint for 2 h 45 minutes Caused by power peating due to zenon transients from previous power changes WINGD, M D Tannessee Valley Authority 83/05/09 Region 2, Office of Director 2pp 18465 (42 24X Fiche 30-260, 83/05/09, 23/3170730
- 8305200420 Forwards LER 83-018/03L-0 OREEN.H J Tennessee Valley Authority 83/05/11 O'REILLY, J P Region 2. Office of Director 1p 18517 157 24X Fichs 30-260.83/05/11.8305200420
- --8305200426 LER 83-018/03L-0 on 830413, core max fraction of critical power determined that min critical power ratio exceeded Caused by withdrawal of deep control rode Control rode inserted to reduce core max fraction of critical power STILES, H. Tennessee Vallay Authority 83/05/11 Region 2. Office of Director 2pp 18517 160 24X Ficha 50-260,83/05/11,830520420
- 8305200288 Forward: LER 83-019/03L-0 OREEN.H J Tennessee Valley Authority 83/05/12 O'REILLY, J P Region 2. Office of Director 1p 18516 267 24X Fiche 50-260.83/05/12.8308200288
- ~-8305200300 LER 83-019/031-0 on 830413, w/unit at 72 9% power returning to rated power, calculated R factor less than R setpoint for 4 h 44 minutes Caused by local power peaking Setting adjusted NGVE/E D Tannesses Valley Authority 83/05/12 Region 2, Office of Director 2pp 18316 268 24% Fiche 50-240/83/05/12, 8303200288
- 0305250357 LER 93-021/03L-0.on 830423 calculated R factor less than flow biss Tech 8pec setpoint Caused by pulling group of eight rods four notches to fully withdrawn position Tech 8pec revs submitted H/830520 ltr LOCKBAUND A . OREEN.H J Tennessee Valley Authority 83/05/20 O'REILLY, J P. Region 2. Office of Director 3pp 18585 352 24X Fichs 50-260.83/05/20.8305250357
- X Onsite Storage of Low Level Waste
- 8305030679 Requests remittance of add1 sum to complete payment of B00731 & 1124 amend applications to permit storage of low level radwaste
 MILLER.H O Licente Fee Management Branch 83/04/22 MILLS.L H
 Tennessee Valley Authority 2pp 18309 193 24X
 Fiche 50-000.83/04/22.8305030679,
- DOCKET 50-261 H D ROBINSON PLANE, UNIT 2
 F Sacurity, medical, emergency & fire protection plans
- 8305270390 Forwards IE Insp Rept 50-261/83-09 on 830305-0410 No nancompliance noted VERRELLI, D.M. Division of Project & Resident Programs 83/04/26 UTLEY, E.E. Carolina Power & Light Co. 2pp 96207 294 24X Fiche 50-261,83/04/26,8305270390
- --8305270401 IE Insp Rept 50-261/83-07 on B30305-0410 No noncompliance noted Hayer areas inspected Tech Spec compliance, plant tour, upgrations performance.RDs, housekeeping, site security, surveillance & maint activities & IE bulletin followup HEISE, 8 , BEMISI P , HARDIN A K Region 2, Office of Director 83/04/25 12pp 18643-059 24K Fichs 50-261,83/04/26,8305270390
- 8305110618 Natification of 830510 meeting w/util in Bethesda, MD to discuss App R exemption request technical submittal schedule, REGUA, O Operating Reactors Branch 1 83/05/05 VARGA, S A Operating Reactors Branch 1 2pp 18415 361 24X Fiche: 50-261, 83/05/05, 8305110618.
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 5vc list ancl EIBENRUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc. 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- B305170048 Advises that NUREO-0737, Item III A 2 1. "Amend 10CFR50 & App E." considered complete following comprehensive 2-wk onsite emergency preparadness appraisal VAROA, 5 A Operating Reactors Branch 1 B3/05/11 UTLEY, E E Caraline Power & Light Co 3pp 18494-181 24X Fiche: 50-261, 83/05/11, 8305170048

- G Adjudicatory correspondence
- B305030486 Objection to B30412 order following special prehearing conference & motion for referral NRC licenses failed to cite precedent far disallowing Contentions 4.5 & 9
 Certificate of Svc encl
 HATTHENS B A Affiliation Unknown B3/04/26 Atomic Safety and Licensing Board Panel 13pp 18306 201 24x Fiche 50-261,83/04/26,8305030486
- 8305030493 Informs that conference call no longer required to determine licensee intentions re sleeving of steam generator tubes MATTHEWS B A Affiliation Unknown 83/04/30 MARQULIES M B Atomic Safety and Licensing Board Panel 1p 18295 303 24X Fiche 50-261,83/04/30,8305030493
- 8305090470 Request for authorization to reply to Hartsville Group 830426 objection to 830412 order & motion for denial of Contentions 4.5 & 9 Certificate of Suc end TROWBRIDGE.O.F Carolina Power & Light Co TROWBRIDGE.O F Shaw. Pittman. Potts & Trowbridge 83/05/04 Atomic Sarety and Licensing Board Panel 5pp 18360 258 24X Fiche 50-261,83/05/04,8305090470
- 8305100413 Grants unopposed applicant request for permission to reply on 830511 to objections to ASLB special prehearing conference order.

 ### HARQUIES, H B Atomic Sefety and Licensing Board Panel 19 18378-079 24X Fiche 50-261.83/05/06.8305100413
- 8305130092 First set of interrogatories to Hartsville Group on Contention 3 re cost-ineffectiveness of proposed steam generator repair Responses due within 45 days Certificate of Svc encl Related correspondence TROWSRIDGE. G F Carolina Power & Light Co TROWSRIDGE. G. F. Shaw, Pittman, Potts & Trowbridge 83/05/ii Hartsville Group, 6pp. 18437 213 24% Fichs 50-261,83/05/ii,83051300092
- 8305130137 Notice of appearance in proceeding Certificate of Svc encl. RIDOMAY.D A Shaw. Pittman, Potts & Trambridge 83/05/11 4pp 18437 187 24X Fiche 50-261.83/05/11.8305130137
- 8305130162 Response to Hartsville Oroup 830426 objection to ASLB B30412 order following special prehearing conference & motion for referral Hartsville failed to challenge foundation of ASLB rulings rejecting contentions W/Certificate of Svc TROHERIDOE, 9 F Carolina Power & Light Co TROHERIDOE, 0, F Shaw, Pittman, Potts & Trowbridge 83/05/11 Atomic Safety and Licensing Board Panel 14pp 18437:339 24X Ficha.50-261.83/05/11.
- 8305170555 Response opposing Hartsville Group 830426 objection to ABLB 630412 special prehearing conference order No bases furnished for assumption util cannot hire workers to handle proposed steem generator replacement H/Certificate of 8vc. KARMAN, M Hearing Branch i 83/05/16 Atomic Safety and Licensing Board Panel 7pp 18468 (6) 24X Fiche 50-261,83/05/16,8305170555
- 8303180299 Motion to require NRC responses to Hartsville Group interrogatories & requests to produce Answers necessary for proper decision & not reasonably obtainable from any other source Related correspondence
 MATTHEMS B. A Hartsville Group 83/05/16 Atomic Sefety and Licensing Board Panel ip 18490 344 24X Fiche 50-261,83/05/16,8305180299
- 9305180452 First set of interrogetories & requests to produce Affidavit of Svc enci.
 MATTHEMS.B.A. Hartsville Group 93/05/16 Office of the Executive Legal Director. 58pp 18486.067. 24X
 Fiche: 50-261, 83/05/16, 8305180452
- 8305270014 Order disallowing Hartsville Group 830426 objections to ASLB 830412 order denying request for admission of Contentions 4.5 & 9 Request for referral of Contention 4 to ASLAB denied. Contention does not involve policy issue MAROULIES. M B Atomic Safety and Licensing Board Panel 83/05/25. Hartsville Group 7pp 18638 318 24% Fiche 50-261,83/05/25,8305270014
- H General correspondence
- 8303030477 Requests that JC Ruoff be added to syc list for proceeding. MATTHEMS: B A. Affiliation Unknown 83/04/30 MARGULIES, M, B Atomic Bafety and Licensing Board Panel 1p 18308 246 24X Fiche. 50-261:83/04/30,8303030477

- B305200600 Requests plant general mgr be placed on distribution list to receive correspondence from Div of Licensing concerning facility ZIMMERMAN, S R Carolina Power & Light Co 83/05/17 EISENHUT, b G
 - Carolina Power & Light Co 83/05/17 EISENHUT, D G ensing ip 18514 113 24X Fiche 50-261.83/05/17, Division of Licensing

J. Insurance & indemnity information

- B303160045 Forwards Endorsement 73 to NELIA Policy NF-180 BARHAN.C D Carolina Power & Light Co B3/05/02 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 2pp 18453 016 24x Fiche 50-261.83/05/02.8303160045
- P Operating license stage documents & correspondence
- B303230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
 BMITH-8 H Carolina Power & Light Co B3/03/22 TOURTELLOTTE, J
 Regulatory Reform Task Force 13pp 18543 277 24X
 Fichs 50-000, 83/03/22, 8305230283
- 8305230720 Forwards list of utils responding to requests for cost requests for tills responding to requests for figures on backfitting
 TOURTELLOTTE. J Regulatory Reform Task Force 83/04/11
 PALLADINO, N J Commissioners 2pp 18542 272 24X
 Fichs 50~000.83/04/11.8305230720
- 8305020453 Forwards add1 info per NRC 821210 request re Generic Ltr 82-28 concerning inadequate core cooling sys Procurement of reactor vessel level instrumentation sys completed Sys installation 30% complete EURY: L W Carolina Power & Light Co 83/04/26 EIBENHUT. D G. Division of Licensing 2pp 18281:222 24% Fiche 50-261,83/04/26,8305020453
- 8305160346 Forwards Amend 76 to License DPR-23, safety evaluation & notice of issuance & availability Amend changes particle size distribution specified for implace testing of HEPA filters in fuel & control room filter sys REGUA: O Operating Reactors Branch 1. 83/04/26. UTLEY, E Carolina Power & Light Co 2pp. 18472 005 24X Fiche: 50-261, 83/04/26, 8305160346
- --8305160349 Amend 76 to License DPR-23, changing particle size distribution specified for in-place testing of HEPA filters in fuel & control room filter sys VARQA:8 A Depreting Reactors Branch 1 83/04/26 5pp 18472.007 24X Fiche 50-261.83/04/26.8305160346
- --8305160351 Safety evaluation supporting Amend 76 to License DPR-23 * Office of Nuclear Reactor Regulation, Director 83/04/26 2pp 18472:012 24X Fiche: 50-261,83/04/26,8305160346.
- -- 8305160386 Notice of issuance & availability of Amend 76 to License DPR-23 VARQA.B.A. Operating Reactors Branch 1 83/04/26 2pp 18472.014, 24X Fiche.50-261/83/04/26/8305160346
- 8305170597 Clarifies 830105 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review.per encl guidelines.due in 30 days VAROA: S.A. Operating Reactors Branch 1 83/04/28 UTLEY, E. Caroline Power & Light Co. 5pp 18495 019. 24% Fichs 50-261,83/04/28,8305170597.
- B305040362 Responds to B30217 & 0407 requests for add1 info re NUREO-0737. Item II. K. 3 17. "ECCS Outages " Info compiled from equipment inoperability record which is completed each shift during cold shutdown HURFORD. M. J. Carolina Power & Light Co 83/04/29 VARGA. S A Operating Reactors Branch 1. 4pp. 18323 174 24X Fiche 50-261.83/04/29,8305040362
- 8305020455 Generic Ltr 83-19 to all power reactor % testing licenses re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl ETSENHUT; D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. SOpp. 18441 120 24X Fiche: 50-000, 83/05/02, 8305020455
- B305060378 Notification of B30505 meeting w/util in Sethesda.MD to discuss achedule & prioritize open items REQUA, 0. Operating Reactors Branch i B3/05/02 VAROA, S. A Operating Reactors Branch i. 2pp 18353-090 24X Operating Reactors Branch 1. 2pp Fiche: 50-261,83/05/02,8305060378,

- B305060478 Notification of B30506 meeting w/util in Bethesda,MD to discuss technical aspects of steam generator replacement MATDOTO program REGUA, C Operating Reactors Branch i 83/05/02 VAR9A,8 A. Operating Reactors Branch i 2pp 18387-324 24X Fiche 50-261,83/05/02,8305060678
- 8305180586 Forwards EIA of licensee 830331 request for approval of proposed procedures to stabilize in-place low level contaminated soil Radiation risks involved in transfer VARGA.8 A Operating Reactors Branch 1 83/05/03 UTLEY, E.E. Carolina Power & Light Co Spp 18505 303 Fiche 50-261,83/05/03,8305180586
- --8305180587 EIA supporting licensee 830331 request for approval of proposed procedures to stabilize in-place low level contaminated soil
 * NRC No Detailed Affiliation Given 83/05/03 3pp 18505 305 24% Fiche: 50-261, 83/05/03.8305180586
- B305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 183 24X Fiche 50-000.83/05/09.8305090659 Consolidated
- 8305200435 Forwards revised & reformatted comprehensive list of 305200435 Forwards ravised & reformatted comprehensive list or NUREO-0737 licensing issues containing status & priority assigned for open items
 ZIMMERMAN. 8 R. Carolina Power & Light Co. 83/05/17 VARQA. 8 A. Operating Reactors Branch 1 lipp 18517 134 24X
 Fiche 50-261,83/05/17.8305200435
- B305260022 Requests 1-month extension until B30701 to respond to B30428 ltr re environ qualification of safety-related electrical equipment Environ qualification erpertise dedicated to preparing responses to B30105 & 0329 SERs ZIMMERNAN. S R Carolina Power & Light Co B3/05/20 VAROA. B A Operating Reactors Branch 1 ip 18599 307 24% Fiche 50-261, B3/05/20, B305260022
- 830527000B Forwards list of qualified electrical equipment important to safety & response to SERs Final environ qualification scheduled to be completed by 850331

 UTLEY, E E Carolina Power & Light Co 83/05/20 VARGA. 8 A

 Operating Reactors Brench 1 615pp 18632-022 24X

 Fiche 50-261,83/05/20,8305270008
- --8305270011 "Qualification Test Rept on In-Containment Cables for CP&L " MARCONNET, J. JORDAN, H. KIMBRELL, M. Wyle Laboratories 45307-1 81/12/23 375pp 18632 262 24X Fiche: 50-261, 83/05/20, 8305270008
- 8305250249 Forwards Rev 1 to figures from 830331 final steam generator repair rept Corrected page list & figure list encl EURYL W Carolina Power & Light Co 83/05/23 VAROA, B. A Operating Reactors Branch 1 19pp 18592 278 24X Fiche 50-261,83/05/23,8305250249
- Q Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl, TAYLOR, J M enci, TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc 112pp. 18308 319 24X Fiche 50-000.83/03/21,8212060385.
- 8305270229 Forwards IE Insp Rept 50-261/83-06 on 830307-11. No Noncompliance noted

 VERRELLI, D.M. Division of Project & Resident Programs. 83/04/01.

 UTLEY, E. Carolina Power & Light Co. 2pp. 18637.206. 24X

 Fiche 50-261.83/04/01.8305270229
- --8305270231 IE Insp Rept 50-261/83-06 on 830307-11 No noncompliance noted Major areas inspected, radioactive effluents, external exposure control, solid radwaste & preplanning for 1984 steam generator outage. ALBRIGHT.R.H., BARR,K P Region 2, Office of Director Spp. 18637 208 24X Fiche,30-261,83/04/01.8305270229 83/03/25
- 8305270479 Ack receipt of 830325 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-261/83~02 LEWIS,R C Division of Project & Resident Programs 83/04/07. UTLEY,R E Carolina Power & Light Co 2pp 18644.032. 24X Fiche: 50-261,83/04/07.8305270479.

- --8305270487 Responds to NRC 830223 ltr re violations noted in IE Insp Rept 50-261/83-02 Corrective actions programs to visually verify positions of valves being developed by GA & onsite nuclear safety groups STARKEY.R B Carolina Power & Light Co 83/03/25 0'REILLY, J P Region 2: Office of Director 5pp 18644 033 24X Fichs 30-261.83/04/07.8305270479
- --8305270494 Forwards IE Insp Rept 50-261/83-02 on 830110-0210 & notice of violation LEMIS,R C Division of Project & Resident Programs 83/02/23 UTLEY.E E Carolina Power & Light Co 2pp 18644 038 24X Fiche 50-261.83/04/07.8305270477
- --8305270500 Notice of violation from insp on 830110-0210 * Region 2, Office of Director 83/02/23 2pp 18644 040 24X Fiche 50-261,83/04/07,8305270479
- --8305270506 IE Insp Rept 50-261/83-02 on 830110-0210 Noncompliance noted failure to implement equipment control procedures, to initiate prompt corrective action 4 to maintain annunciator procedures
 WEISE, 8 Region 2. Office of Director BEMIS.P Division of Project & Resident Programs 83/02/22 12pp 18644 042 24X Fiche 50-261.83/04/07.8305270479
- 9305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted O'REILLY, J P. Region 2, Office of Director 83/04/11 UTLEY, E Carolina Power & Light Co. 2pp 18644 158 24X Fiche 50-000, 83/04/11, 8305270461
- --8305270474 IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of raduaste containing free liquid & inoperability of standby gas treatment deluge sys LEHIS.R C Division of froject & Resident Programs B3/04/07 3pp 18644 160 24X Fiche 50-000, 83/04/11,8305270461
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Bvc list encl JURRBANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list and
 JORDAN, EL Division of Emergency Preparadness & Engineering
 Response (Post 930103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 30-000,83/04/25,8303040025
- 8305170654 Requests TLD dosineter data be collected from steam generator insplactivities, for independent determination of bets dose using theoretical model w/gamma calibr factor VARGA: B A Decreting Reactors Branch 1 83/04/26 UTLEY, E Carolina Power & Light Co 2pp 18476 246 24X Fichs 50-261:83/04/26,8305170854
- 8305270390 Forwards IE Insp Rept 50~261/83-09 on 830305-0410 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/04/26 UTLEV.E E Carolina Power & Light Co 2pp 96207 294 24X Fiche 50~261.83/04/26
- --8305270401 IE Insp Rept 50-261/83-09 on 830303-0410 No noncompliance noted Major areas inspected Tech Spec compliance, plant tour, operations performance.RDs, housekeeping, site security, surveillance & maint activities & IE bulletin followup MEISE.S , BEMIG.P , HARDIN & K Region 2. Office of Director 83/04/25 12pp. 18643 059 24V Fiche 50-261.83/04/26.8305270390
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Sec list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp 18392-047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAM: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 145 24X Fiche 50-000:83/04/28.8303040027

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24x Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fishe 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 30-000,83/05/04,830304003J
- 8305270380 Forwards 1E Insp Rept 50-261/83-11 on 830412-15 & 18-19 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/04 UTLEY/E E Carolina Power & Light Co 200 18643 050 24X Fiche 50-261/83/05/04/8305270380
- --8305270387 IE Insp Rept 50-26i/83-ii on 0304i2-i5 & 18-i9 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys & pipe support baseplates using concrete expansion anchors ANO,W P Region 2. Office of Director BLAKE,J J Division of Engineering & Radiological 034ety Programs 83/05/02 5pp 18643 032 24X Fiche 50-261.89/05/04.8305270380
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24x Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24x Fiche 50-000,83/05/11,8303040034
- 8305200009 Confirms commitments for operation of Cycle 9 Summary tables of steam generator eddy current insp results for May 1983 outage & justification for continued operation encl EURY-L W Carolina Power & Light Co 83/05/16 VARGA-8 A Operating Reactors Branch 1 5pp 18519 077 24X Fiche 50-261.83/05/16.83052000009
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program," Svc 11st encl
 JURDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103), B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, B3/05/26, B303040046
- 6 Reportable occurrences, LERs & related correspondence
- 8305030599 RD on 830424, svc water booster pump B declared inoperable due to bearing failure & plant shutdown commenced following pump A trip due to blown control power fuses Fuses replaced & pump A restarted investigation continuing 8TARKEV.R B Carolina Power & Light Co 83/04/25 O'REILLY. J P Region 2. Office of Director ip 18303 214 24X Fiche 50-261,83/04/25,8305030599
- 8305030256 PNO-II-83-030 on 830428; controlled shutdown begun due to steam generator tube leak which increased from 0 1 to 0 308 gpm Licensee plans to keep plant out of svc for 3 wks to repair leak & conduct eddy current testing HARDIN, A K. VERRELLI, D M. Region 2. Office of Director 83/04/28 ip 18300 038 24% Fiche 50-261,83/04/28,8305030256
- 8305050247 RD on 830427, svc water pump A removed from svc for normal preventative maint & replaced w/rebuilt spare pump Post-maint testing resulted in pump over current trip Caused by internal binding of rebuilt pump BTARKEY, R B Carolina Power & Light Co 83/04/28 D'REILLY, J P. Region 2. Dffice of Director 2pp 18337 340 24X Fiche 50-261,83/04/28,8305050249

DOCKETED ITEMS

- 8305110251 Forwards LER 83-005/01T-0 8TARKEY.R B Carolina Power & Light Co 83/05/06 D'REILLY, J P Region 2. Office of Director 1p 18393 286 24X Fiche 50-261.83/05/06.8305110251
- --8305110256 LER 83-005/01T-0 on 830424.svc water booster pump B declared inoperable due to loss of boaring oil Caused by bearing oil slinger being positioned near vent hole Pump inspected & oil replenished COX.H T Carolina Power & Light Co 83/05/06 Region 2, Office of Director 3pp 18393 287 24X Fiche 50-261,83/05/06.
- 8305250423 LER 83-004/03L-0 on 830419, w/unit at 0% power following reactor trip, auxiliary feedwater pump 8 tripped on low discharge pressure Caused by pump cavitation resulting from buildup of water vepor inside pump casing W/830518 ltr COX,H T. 8TARKEY,R 8 Carolina Power & Light Ca B3/05/18 O'REILLY,J P Region 2, Office of Director 3pp 18583 355 24% Fiche 30-261,83/05/18,8305250423

DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR P Operating license stage documents & correspondence

8305160129 Requests clarification if license authorizes unloading & shipping of fuel Info on procedures & dismantling plans to decommission L-77 reactors also requested LAMBERT.N E Brigham Young Univ 83/05/09 CARTER.R E Btandardization & Special Projects Branch ip 18448 142 24X Fiche 50-262,83/05/09,8305160129

DOCKET 50-243 MONTICELLO NUCLEAR GENERATING PLANT F Security, medical, emergency & fire protection plans

- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visite 8vc list encl EISENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- B305190343 Forwards Rev 1 to NUREO-0728, "NRC Incident Response Plan," in response to B30429 ltr requesting updated ltr of agreement M/o encl
 HIND. J A Division of Radiological & Materials Safety Programs
 B3/05/13 LARSUN.C E Northern States Power Co 2pp 18500 225
 24X Fiche 50-000, B3/05/19, B305190343
- B305240572 Informs that NUREG-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR30." completed Item closed VABBALLO, D B Operating Reactors Branch 2 83/05/18 MUSDLF, D M Northern States Power Co 3pp 18593 345 24X Fiche 50-263.83/05/18.8305240572

K. Utility Final Bafety Analysis Report (FSAR) & amends

- 8305030603 Forwards Rev 1 to updated FSAR & "Annual Rept of Changes, Tests & Experiments, Jan-Oct 1982" MUSDLF, D. Northern Btates Power Co. 83/04/29 Office of Nuclear Reactor Regulation, Director 1p. 18304-001 24X Fichs: 50-263, 83/04/29, 8305030603
- ---8305030410 "Annual Rept of Changes, Tests & Experiments, Jan-Oct 1982 "
 * Northern States Power Co 83/04/29 12pp 19304 002 24X
 Fiche 50-263, 83/04/29, 8305030603
- --8305030613 Rev 1 to updated FSAR * Northern States Power Co 62/10/31 496pp 18304 014 24X Fiche 50-263,83/04/29,8305030603

P. Operating license stage documents & correspondence

- B303180429 Forwards response to B30208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1.337 MHE (summer) net HADLEY,C D Northern States Power Co B3/03/15 TOURTELLOTTE, J. Regulatory Reform Task Force Opp 18541 041 24X Fiche 30-000,83/03/15,8303180429
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J. Regulatory Reform Task Force 83/04/11 PALLADINO.N.J. Commissioners 2pp 18542 272 24X Ficha: 50-000,83/04/11,8305230720

- B305020455 Generic Ltr B3-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to CLs Svc list encl EISENHUT.D 0 Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 30pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8303230248 Forwards safety evaluation supporting resolution of NUREO-0737, Item II F 3 22. "Automatic Switchover of RCIC Switting," based on review of util 811231 % 820708 submittals re-procedure verification & design mod VABSALLO, D 8 Operating Reactors Branch 2 83/05/05 MUSOLF, D M Northern States Power Co 5pp 18543 244 24X Fiche 50-263,83/05/05,8305230248
- BJ05070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list enc1
 EISENHUT.D Q Division of Licensing BJ/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090639
- B305240542 Clarifies B30104 safety evaluation on environ qualification of safety-related electrical equipment Requirements of 10CFR30 49 superseded 90-day response to SER Schedule of equipment qualification required by B30520 VASSALLG,D D Operating Reactors Branch 2 B3/05/11 MUSQLF,D M Northern States Power Co 4pp 18593 351 24X Fiche 50-263,83/05/11,8305240562
- B305260201 Forwards request for add1 info re 911231 response to NUREG-0737. Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt VABSALLO.D D Operating Reactors Branch 2 83/05/11 MU90LF, D M Northern States Power Co 3pp 18448 067 24X Fiche 50-263, 83/05/11, 8305260201
- B305240537 Informs that NUREG-0737. Item 11 K 3 45, "Depressurization w/Other than Automatic Depressurization Sys." completed Item closed Bafety evaluation encl VABBALLO. D B Operating Reactors Branch 2 83/05/18 MUSDLF. D M Northern States Power Co 7pp 18373 270 24X Fiche 50-243, 83/05/18, 8305240557

Q Inspection reports, IE Bulletins & correspondence

- B212060385 IE Info Notice 83-t4. "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000/83/03/21,82(2060385
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000, B3/04/22, B303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X F(cho 50-000, B3/04/25, B303040025
- B303040026 IE Info Notice 83-24, "Loose Parts in Secondary 8ide of Steam Generators at PHRs " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Betpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830102) 83/04/28 Consolidated Edison Co of New York, Inc 1189p 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B305200591 Forwards IE Insp Rept 50-263/83-06 on B30302-0401.No noncompliance noted SHAFER, W D Region 3, Office of Director B3/05/02 LARSON, C E Northern States Power Co 2pp 18514 107 24X Fiche 50-263,83/05/02,8305200591

- --8303200611 IE Insp Rept 50-263/83-06 on 830302-0401 No noncompliance noted Major areas inspected operational safety verification onsite review committee.LER followup & regional requests re main steam safety valve excessive blowdown BROWN.C H. WALKER.R D. Region 3. Office of Director 83/04/28 4pp 18514 109 24% fiche 50-263,83/05/02,8305200591
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breaters " Svc list enc! JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co of New York Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc. 182p 18382 282 24X Piche 30-000,83/03/04-8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L Division of Emergency Preparedness & Enginsering Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc. 119pp 18441 001. 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JRDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24x Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/11 Canolidated Edison Co of New York: Inc. 114pp. 18524 003 24X Fiche 50-000,83/05/11.8303040034
- 8305180352 Responds to violations noted in 830411 enforcement ltr Carrective actions combustible gas control sys isolation valve & local leak rate test connection valves closed, leak test connection cap replaced & agt meeting conducted LARBON.C E Northern States Power Co 83/05/11 DEYOUNG,R C Director's Office. Office of Inspection and Enforcement. 10pp 18485-268 24X Fiche 50-263,83/05/11,8305180352
- 8305200291 Ack receipt of 830511 ltr transmitting payment of proposed civil panalty Response to notice of violation & proposed imposition of civil panalty will be evaluated & corrective actions evanimed during future inspa AXELRAD. J A. Director's Office, Office of Inspection and Enforcement 83/05/18 LARSON.C E Northern States Power Ca 1p 18516 323 24X Ficha 50-243,83/05/18.8305200291
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN.E L Division of Emergency Praparedness & Engineering
 Response (Post B30103) 63/05/19 Consolidated Edison Co of New
 Yark, Inc 114pp 18697-009 24X Fiche 50-000,83/05/19.8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.

 JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidates Edison Co of New York, Inc. 114pp 18647-007 24X Fichs 50-000,83/05/26.8303040046
- R Periodic operating reports & related correspondence
- B305030603 Forwards Rev 1 to updated FSAR & "Annual Rept of Changes, Tasts & Esperiments, Jen-Oct 1982 " MUSDLF.D Northern States Power Co. 83/04/29 Office of Nuclear Reactor Regulation, Director 19 18304 001 24X Fiche 50-263.83/04/29.8305030603
- --8305030610 "Annual Rept of Changes, Tests & Experiments, Jan-Oct 1982 "

 * Morthern States Power Co 83/04/27 12pp 18304 002 24X |
 Fiche 50-263-83/04/29, 8305030864
- 8305160092 Forwards monthly operating rept for Apr 1983 MUSOLF.D. Northern States Power Co 83/05/11 Office of Resource Management. Director ip 18452 008 24X Fiche 50-263,83/05/11, 8305160092
- --8305160098 Monthly operating rept for Apr 1983 MYRABO.A L Northern States Power Co 83/05/03 4pp 18452 009 24% Fiche, 50-263, 83/05/11, 8305160092

- 5 Reportable occurrences, LERs & related correspondence
- B305020488 Forwards LER 83-006/01T-0 MUSBLF,D Northern States Power Co 83/04/22 Region 3. Office of Director 10 18281 247 24X Fiche 50-263,83/04/22.8305020488.
- --B305020492 LER 83-006/017-0 on 830408.HPCI Hoodward Governor EGR hydraulic actuator coil tailed Caused by lead wire insulation degradation allowing ground fault to EGR housing EGR replaced HPCI satisfactorily tested HDJCHGUSKI.A V Northern States Power Co 83/04/22 Region 3. Office of Director ip 18281 248 24X Fiche 50-263.83/04/22. 830302048
- 8305260314 PNO-III-83-03B on 830517, reactor placed in hot shutdown to investigate & repair steam leak in drain line between moisture separator & preheater in nonsafety-related turbine sys Addi steam leak found in turbine control valve flange WALKERR D., SNAFER, W.D. Region 3. Office of Director 83/05/20 ip 18625 178 24X Fiche 50-263,83/05/20,8305260314

DOCKET 50-264 DOW CHEMICAL CO

- F Security, medical, emergency & fire protection plans
- 8305030513 Forwards IE Safeguards Insp Rept 50-264/B9-01 on 830405-06. No noncompliance noted HILLERJ R Region 3, Office of Director 83/04/29 RAMPY, L. W. Dow Chemical Co 2pp 18294 173 24X Fiche 50-264, 83/04/29, 8305030513
- --B305030921 IE Safeguards Insp Rept 50-264/83-01 on 830405-06 No noncompliance noted Major areas inspected facility organization & operation.measurement & statistical control Details withheld (ref 10CFR2 790)
 MADEDA:T J. KNICCLEY, J.R. CREED, J.R. Region 3, Office of Director 83/04/29 ip 18294 175 24x Fiche: 30-264, 83/04/29, 8305030513
- @ Inspection reports. IE Bulletins & correspondence
- 8305030513 Forwards IE Befeguards Insp Rept 50-264/83-01 on 830405-06. No noncompliance noted MILLER, J R Region 3, Office of Director 83/04/29, RAMPY, L W Dow Chemical Co 2pp 18294 173 24X Fiche 50-264, 83/04/29, 830803
- --8305030521 IE Safeguards Insp Rept 50-264/83-01 on 830405-06 No noncompliance noted Major areas inspected facility organization & operation measurement & statistical control Details withheld (ref 100FRZ 790) MADEDA: T J. KNICELEY, J R., CREED, J R. Region 3, Office of Director 83/04/29 ip 18274 175 24X Fiche, 30-264, 83/04/29, 8305030513

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8305i10034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits.

 8vc list encl
 EIGENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18340 075 24X
 Fiche 50-000,83/05/11,8305110034
- 8305240245 Requests schedular examptions allowing delay in implementing iOCFR30 4B requirements for installation of fire protection mods Request based on Atmanufacturer & const personnel anticipated implementation schedule ATM DENTON, H. R. Office of Nuclear Reactor Regulation Director opp. 18548 204. 24X Fiche 50-000,83/05/18,8305240245
- B305230141 Informs that NUREQ-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFRDO App E requirements complete for factility Item closed VASSALLO, D. B Operating Reactors Branch 2 B3/05/1B FARRAR, D. L. Commonwealth Edison Co 3pp 18596 198 24X Fiche 50-254, 83/05/1B, 8305250141.

DOCKETED ITEMS

- P Operating license stage documents & correspondence
- B305020597 Forwards safety evaluation on NUREG-0737. Item II B 2 2. "Plant Shielding Mods for Vital Area Access " Requirements met VASSALLO, D B Operating Reactors Branch 2 83/04/22 FARRAR. D Commonwealth Edison Co 5pp 18284 222 24X Fiche 50-254.83/04/22, 8305020597
- 830502045B Forwards info re NUREO-0737. Item II D 1. "Performance Testing of BUR Safety/Relief Valves," per NRC 830104 request Applicability of load combination info to BUR Owners Oroup generic test rept acceptable RYBAK. B Commonwealth Edison Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18283 311 24X Fiche: 50-234.83/04/27.8305020458
- 8305020455 Generic Ltr 83-19 to all power reactor 2 testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Svc list encl
 EIBENHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
 Fiche 30-000.83/05/02.8305020455
- 830504D551 Application to amend Licenses DPR-19.DPR-25.DPR-27 & DPR-30, changing App A Tech Specs re economic generation control operation RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 24X Fiche, 50-000, 83/05/02, 8305040551
- --8305040355 Proposed changes to App A Tech Specs re oconomic generation control operation W/o detailed changes * Commonwealth Edison Co 83/05/02 ip 24X Fiche 50-000,83/05/02,830504055i
- 8305050043 Application for amend to Licenses DFR-27 & DFR-30, changing Tach Specs to limit control rod drive pump isolation from accumulators to single rod scram testing RYBAK.B Commonwealth Edison Co B3/03/02 DENTUN,H R. Office of Nuclear Reactor Regulation, Director 3pp 18342-083 24X Fiche 50-254.B3/05/02.8305050043
- 8305130209 Concurs w/NRC changes to draft Tech Spacs re reactor protection sys (RPS) protective relaying mods.per 830420 ltr Operation w/RPS mod, installed per 100CR30 39 & w/o Tech Specs, will not compromise safe operation of facilities RYSAK, B. Commonwealth Edison Co 83/05/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18439 330 24X Fiche: 50-000, 83/05/06, 8305130209
- 8303070637 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENHUT, D 0 Division of Licensing 83/05/07 Consolidated Edison CO of New York, Inc. 16pp 18627-153 24X Fishe 50-000.83/03/07/83030706597
- 8305130038 Responds to 830316 request for add1 info re NUREO-0737. Item
 II K 3 28, "Verify Qualification of Accumulators on
 Automatic Depressurization Sys Valves "Environ & seismic
 qualification will be in accordance w/1E Bulletin 77-018
 RVBAK.B Commonwealth Edison Co 83/05/10 DENTON, H R. Office of
 Nuclear Reactor Regulation, Director 2pp 18436 339 24X
 Fische 50-000.83/05/10.8303130038
- 8305200707 Forwards request for addl info on NUREO-0737, Item II K.S 28 re qualification of automatic depressurization sys accumulators. Response requested within 45 days VABBALLO, D. B Operating Reactors Branch 2 83/05/11 FARRAR, D L Commonwealth Edison Co 5pp 18528 350 24X Fichs 50-000, 83/05/11, 8305200707
- 8305200186 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K 3 15 on isolation of HPGI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys DIOGS,R M License Fee Management Branch 83/05/12 FARRAR,D.L. Commonwealth Edison Co. ip 18540 228 24X Fichs 50-000,83/05/12, 8305200186
- 8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment GE affidavit per 10CFR2 790 received Westinghouse affidavit forthcoming RYBAK, B Commonwealth Edison Co 83/05/13 DENTON, H R. Office on Nuclear Reactor Regulation, Director 3pp 18470 347 24X Fiche: 50-000;83/05/13,8305180376

- B305310231 Advises that responses to NUREC-0737. Item III D 3 4, "Control Room Habitability," acceptable, completing action on item Bafety evaluation encl VASBALLO.D B Licensing Branch 2 B3/05/17 FARRAR, D L Commanwealth Edison Co 4pp 18662 255 24X Fiche 50-254, 83/05/17, 8305310231
- 8305240573 Notifies that NUREO-0737. Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl VASSALLO.D B Operating Reactors Branch 2 83/05/18 FARRAR, D L Commonwealth Edison Co 7pp 18593 338 24x Fiche 50-254.83/05/18, 8305240573
- 8305270419 Notifies that response to 830315.0510 & 11 requests for add1 info me TMI Item II K 3 28, "Qualification of Automatic Depressurization Bys Accumulators," addressed in 830510 ltr RVBAK-B Commonwealth Edison Co 83/05/23 DENTON.H R Office of Nuclear Reactor Regulation. Director Ip 18442 298 24X Fiche 50-000.83/05/20.8305270419
- 8305310086 Notification of 830614 meeting w/util in Bethes6a, MD to discuss util DCRDR program plan GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24x Fiche 50-000, 83/05/26, 8305310086
- 8305310028 Advises that requirements of NUREQ-0737. Item II F 1.4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved per 821220 & 801215 submittals CRUTCHFIELD. D Operating Reactors Branch 5 83/05/27 FARRAR, D Commonwealth Edison Co 7pp 18653 213 24X Fiche 50-000, 83/05/27, 8305310028
- G Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Demotered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE info Notice 83-22. "BWR Safety/Relief Valve Failures "
 8vc 11st encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Natice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Byt list entl JORDAN:E L. Division of Emergency Preparadness & Engineering Respanse (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 117pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- B303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDANNE L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Btandby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/20 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" By¢ list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031

- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305170167 Forwards response to 830411 notice of violation & proposed imposition of civi) penalties re IE [nsp Repts 50-254/82-26 & 30-265/82-26 Also includes remittance in amount of \$60.000 rs inoperable reactor protection sys subchanne? REED.C Commonwealth Edison Co 83/05/07 Director's Office. Office of Inspection and Enforcement 1p 18466 308 24X Fiche 50-254,83/05/09,8305170167
- --8305170184 Responds to notice of violation noted in IE [Insp Repts 50-294/82-26 & 50-285/82-26 on 821118-22 & 1213-16 Corrective actions Startup Procedure GCP 1-1 revised to include sign-off for verifying clearance of alarm REED. C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 9pp 18466 309 24X Fiche 50-254,83/05/09,8305170167
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EDP) Guidelines " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24x Fiche 50-000.83/05/11,8303040034
- 8305310105 Forwards IE this Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance noted SHAFER.N D. Region 3. Office of Director 83/05/12 REED.C Commonwealth Edison Co. 2pp. 18658-051 24X Fiche 50-254.83/05/12.8303310105
- --8305310112 IE insp Repts 50-254/83-06 t 50-265/83-06 on 830219-0422 No noncompliance noted Major areas inspected operational safety, maint, surveillance, licensee monthly repts, regional requests. LERs t public info t special repts CRRISSOTINOS, N HALKER, R D Region 3. Office of Director 83/05/10 8pp 18658-033 24X Fiche 50-234,83/05/12,8305310105
- 8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14.piping analysis to restore hot shutdown path piping says to FSAR requirements by 830215.acceptable SPESSARD, R. L. Division of Engineering 83/05/18 REED, C. Commonwealth Edison Co. 2pp 18517 116 24X Fiche 50-000.83/05/18, 8305200421
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/03/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 30-000,83/05/19,8303040000
- 8303250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-018 Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-018 "
 RVBAK.B Commonwealth Edison Co B3/05/19 DENTON,H R Office of Nuclear Reactar Lign. Director 2,118pp 18378 001 24X Fiche 50-000,83/05/19,8305250377
- --8305250090 "GE-NEBS Electrical Penetration Assembly Qualification Program"
 - * Bechtel Corp 83/05/18 203pp 18578 174 24x Fiche 50-080,83/05/19,8305250377
- --8305250413 Rev 2 to Vols 1-3 to "Response to IE Bulletin 79-018. Quad Cities Nuclear Power Station Units : 5 2 " * Bechtel Corp 83/05/31 786pp 18581 253 24x Fithe 50-000.63/05/19.8305250377
- 8305270216 Ack receipt of 830509 transmittal forwarding full payment of proposed civil penalty Corrective actions will be examined during future insps AXELRAD. A Enforcement Staff 83/05/25 REED, C R Commonwealth Editon Co
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list enci JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 930103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports &'related correspondence
- B305170372 Forwards monthly operating repts for Apr 1983 KALIVIANAKIS.N Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement 1p 18466 055 24: Fiche 50-254.83/05/02.8305170372

- --8305170376 Monthly operating repts for Apr 1983 MISAK A Commonwealth Edison Co 83/05/02 21pp 18466 056 24x Fiche 50-234, 63/05/02, 8305170372
- S Reportable occurrences, LERs & related correspondence
- 8305250286 LER 83-006/03L-0 on 830424, AD 2-203-2D MSIV failed to initiate half scram on reactor protection sys channel B Caused by channel B 10% closure limit switch failure Limit switch replaced w/like-for-like switch W/B30516 ltr FUHB, A , WALIVIANAKIE, A Commonwealth Edison Co 83/05/16 KEPPLER, J Region 3, Office of Director 3pp 18625 351 24X Fiche 50-265, 83/05/16, 8305260286
- 8303310132 LER 83-007/01T-0 on 830309, while reviewing out-of-syc documentation, discovered that control rod drives (CRD) 38-07 & 46-55 on Unit 2 & 06-43 on Unit 1 made inoperable w/o verifiying shutdown margin or insertion W/830323 ltr WUNDERLICH.J. XALIVIANAKIS.N Commonwealth Edison Co 83/05/23 KEPPLER.J & Region 3, Office of Director 1p 18653 044 24X Fiche 50-265,83/05/23,8305310152
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8305030323 Requests revs to proposed mods to 10CFR30 App R exemption requests re separation requirements, per 830322 meeting & 830325 & 31 telcons Detailed discussion of revs encl FAY.C W Wisconsin Electric Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 29pp 18300 286 24X Fiche 50-266,83/04/28,8305030023
- 8305110540 Forwards exemption from App R in partial response to 820630 ltr & 820929 & 1011 suppls Exemption permits relief from requirements to install fixed suppression says & fire barriers to separate hydrogen lines from safety equipment CLARK.R A Deparating Reactors Branch 3 83/04/28 FAY.C W Hisconsin Electric Power Co 5pp 18415 104 24X Fiche 50-266.83/04/28,8305110540
- --8305110542 Exemption from requirements of 10CFR50, App R, Section III 0 re fixed fire suppression sys in control room EISENHUT, D. G. Division of Licensing 83/04/28 Wisconsin Electric Power Co. 3pp 18415 107 24X Fiche 50-266,83/04/28,830410340
- 8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation 1 re fire signaling systesting withdrawn SPESSARD:R L Division of Engineering 83/05/09 BURSTEIN, S Hisconsin Electric Power Co 2pp 18464 333 24X Fiche 50-266.83/05/09,8305170241
- ---8305170252 Responds to NRC 821130 itr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include add1 performance data Fire protection tests reviewed FAY.C W Wisconsin Electric Power Cp 83/01/21 KEPPLER, J G Region 3. Office of Director 42pp 18464 335 24X Fichs 50-266:83/05/09.8305170241
- --8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity FAY.C W Hisconsin Electric Power Co 83/02/24 KEPPLER.J O Region J. Office of Director 3pp 18465 015 24X Fiche 50-266.B3/05/09.8305170241
- 8303170138 Ack receipt of 830413 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 HIND, J A Division of Radiological & Materials Safety Programs 83/05/10 BURBTEIN, S Wisconsin Electric Power Co ip 18466 270 24X Fiche 50-266,83/05/10,8303170138
- --8305170144 Responds to NRC 830314 ltr re violetions noted in IE Safeguards Insp Repts 30-266/83-03 & 50-301/83-05 Corrective actions withheld (ref 100FR73 21)
 BURSTEIN,S Wisconsin Electric Power Co 83/04/13 HIND, J A Division of Radiological & Materials Safety Programs 1p 18466 271 24X Fiche 50-266.83/05/10.8305170138
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits. 8vc list encl EISENRUT: D 9 Davision of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fichs 50-000.83/05/11.8305110034

B3Q52Q0021 Notifies that NUREG-0737. Item JII A 2 1. "Emergency Praparedness. Upgrade Emergency Plans to App E. 10CFR90." completed Item closed CLARK.R A Operating Reactors Branch 3 B3/05/12 FAY.C W Hisconsin Electric Power Co Opp 18540 114 24X Fiche 50-266. B3/05/12. B305200021

Q Adjudicatory correspondence

- B305020438 Brief opposing Wisconsin Environ Decade exceptions to ASLB B30204 initial decision authorizing full-scale sleeving Exceptions waived for failure to brief or arguments w/o marits GHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge B3/04/29 Atomic Safety and Litensing Appeal Panel 32pp 19281 111 24X Fiche 50-266, B3/04/27, B305020438
- 8305100314 Brief in opposition to Wisconsin Environ Decade 830214 appeal of ASLB 830204 memorandum & order LSP-83-4 ASLAB should respect exceptions not briefed & affirm ASLB order restand generator tube rupture WCertificate of Syc BACHHANN, R G Hearing Branch 1 83/05/09 Atomic Safety and Licensing Appeal Panel 189p 18371 141 24% Fiche 50-266, 83/05/09, 8305100314
- B305170291 Opposes Wisconsin Environ Decade 830506 request to provide Westinghouse proprietary info from licensee Decade petition for discretionary Commission review does not entitle petitioner to proprietary info 8vc list encl CHURCHILL, B W Bhaw, Pittman, Potts & Trowbridge CHURCHILL, B W Wisconsin Electric Power Co B37037/13 MODRETT S. JOHNBON, W R., GOTCHY, R L. Atomic Safety and Licensing Appeal Panel 3pp 18466-121 24X Fichs 50-266,83/05/13,8305170291
- B30527055B Requests info re date, time & location for Commission meeting on emergency operations facility location Leave to address Commission requested FAY.C W Wisconsin Electric Power Co 83/05/20 CHILK,B J Office of the Secretary of the Commission in 18646 154 24X Fiche 50-246,83/05/20,830527055B

P Operating license stage documents & correspondence

- B305230724 Forwards estimated annual regulatory t nonregulatory axpanditures in 830208 ltrs re cost of backfitting Combined capacity of facilities is 994 MMe
 BURSTEIN, B Wisconsin Electric Power Co B3/02/25 TOURTELLOTTE, J
 Regulatory Reform Task Force 3pp 18542 269 24X
 Fiche 50-266,83/02/25,8305230724
- B305020272 Forwards Affidavit AW-B0-27 in support of request to withhold proprietary info re effect of radiation on insulating matis in Westinghouse medium motor per 100FR2 770 re encl util draft B30413 ltr WIEBEMANN.R A Westinghouse Electric Corp B3/04/13 THOMAS,C D Division of Licensing 9pp 18277 194 24% Fiche 50-266,83/04/13.B305020272.
- --8305020292 Nonproprietary version of "Effect of Radiation on Insulating Matls Used in Westinghouse Medium Motors " BARTMO, J. Westinghouse Electric Corp. 71-162-RADMC-R1 71/04/10 39pp. 18277 205 24X Fiche 50-266,83/04/13,8305020272
- 8305020128 Forwards safety evaluation of util preferred ac power sys conformance to ODC 17 Power sys do not fully meet intent of QDC 17 since sys could be automatically disconnected from 4.160-volt safeguards buses in worst case accident loads NORELIUS, C.E. Division of Project & Resident Programs 83/04/25 EIBENHUT, D. D. Division of Licensing 3pp 18278 220 24X Fithe. 50-266, 83/04/25, 8305020128
- --8305020137 Safety evaluation of util preferred ac power sys conformance ODC 17 Proximity of low voltage transformers does not fully meet ODC 17 requirements for physical separation, but deluge sprinkler sys adequate * NRC No Detailed Affiliation Given 83/04/25 8pp 18278. 223 24X Fiche 50-266,83/04/25,8303020128
- B305060001 Forwards E0&0 summary of discussion re radiological effluent
 Teth Specs during 820602-03 plant visit Final draft of
 proposed radiological effluent Tech Specs & offsite dose
 calculation manual should be developed within 60 days
 GLARK, R, A Operating Reactors Branch 3 83/04/25 FAY, C W
 Wisconsin Electric Power Co 45pp 18353 263 24X
 Fiths. 50-266, 83/04/25, 8305060001
- --B305060007 STANDARD RADIOLOGICAL EFFLUENT TECHNICAL SPECIFICATIONS FOR PRESSURIZED WATER REACTORS SEPTEMBER 1982 NRC -- No Detailed Affiliation Given NUREO-0472 D07 R03 82/09/03 B3pp 18353 308 24% Fiche 50-266.83/04/25,8305060001

- B303090946 Lists drawings needed to review inservice testing program Two sets of full size drawings requested CLARK,R A Operating Reactors Branch 3 83/04/27 FAY,C W Wisconsin Electric Power Co 3pp 18381 205 24X Fiche 30-246
- B305110028 Informs of Class I & III fee classification for B30324 application for Tech Spec changes re auxiliary feedwater sys operability Overpayment for 790926 application for administrative changes will be applied toward current fees MILLER.W O License Fee Management Branch B3/04/27 FAY.C & Wisconsin Electric Power Co 2pp 18421 313 24X Fiche 50-266.83/04/27,8305110028
- 8305020455 Generic Ltr 83-19 to all power reactor 3 testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. Sopp. 18441 120 24X
 Fiche 50-900, 83/05/02, 8305020455
- 830504040B Requests extension of deadline for environ qualification of equipment until 840330 for Unit 2 841101 for both units for environ qualification of all 10CFR50 47(b)(3) equipment items
 BURSTEIN.S Wisconsin Electric Power Co. 83/05/04 DENTON.R R
 Office of Nuclear Reactor Regulation, Director CLARK, A A Operating Reactors Branch 3 3pp 18348 210 24X
 Fitche 50-286,83/05/04,8303060408
- 8305110075 Remits license amend approval fee for temporary clarification of Tech Specs re auxiliary feedwater sys operability BURSTEIN.5 Wisconsin Electric Power Cg 83/05/04 DENTON.H A Office of Nuclear Reactor Regulation, Director MILLER.W D License Fee Management Branch ip 18408 109 24X Fiche 50-266.83/05/04.830510075
- 8305ii0181 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 91 re limiting conditions for operation requiring both RHR loops be operable unless reactor sys is in refueling shutdown condition BURSTEIN: 8 Wisconsin Electric Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18407 122 24% Fiche 50-266.83/05/04.8305110181
- --8305110187 Tech Spec Change Request 91 re limiting conditions for operation requiring both RMR loops be operable unless reactor sys is in refueling shutdown condition wisconsin Electric Power Co. 83705/04 App. 18407 125 24X Fiche 50-R66,83705/04,8305110181
- B303ii020i Forwards addl fees associated w/Tech Spec Change Request 69 to allow regain of degraded steam generator tubes by sleeving BVRSTEIN.S Wisconsin Electric Power Co B3/05/04 DENTDN.H R Dffice of Nuclear Reactor Regulation. Director D1005,R M License Fee Management Branch 1p 18407 111 24X Fiche 50-266.83/05/04, B305110201
- 8305120475 Fowards Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends allow temporary isolation of shared motor driven auxiliary feedwater pumps CDLBURN.T G Operating Reactors Branch 3 B3/05/04 FAY.C W Wisconsin Electric Power Co 4pp 18440 214 24X Fiche 50-266.83/05/Q4.B305120475
- --8305120498 Amends 73 % 78 to Licenses DPR-24 % DPR-27, respectively, allowing temporary isolation of shared motor driven auriliary feedwater pumps for unit during startup, shutdown & surveillance testing of other unit CLARK, R A Derating Reactors Branch 3 83/05/04 6pp 18440 218 24% Fiche 50-266.83/05/04,8305120493
- --8305120502 Safety evaluation supporting Amends 73 5 78 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 83/05/04 2pp 18440 224 24X Fiche 50-266,83/05/04.8303120495
- --8305120505 Notice of issuance & availability of Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively TRANMELL-C M Operating Reactors Branch 3 83/05/04 2pp 18440 224 24X Fiche 50-246.83/05/04.8305120495
- 8305130007 Updates progress in meeting schedular commitments per NRC 830314 order re implementation of post-TML Action Item II F 1. "Addi Accident Monitoring Instrumentation "FAY.C W Misconsin Electric Power Co 83/05/06 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 3pp 18436 341 24X Fiche 50-266,83/05/06.8305130007

- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enc? EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 19627 153 24X Fithe 50-000,83/03/09.8305090659 Consolidated
- 8305240131 Informs that piping & instrumentation diagrams requested in 830427 itr re inservice testing program will be forwarded In BJ042/ Itr re inservice testing program will be forwarded under separate cover FAY,C N Wisconsin Electric Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 Ip 18549 006 24X Fichs 50-266.B3/05/19,8305240131
- 8305240497 Forwards list of electric equipment important to safety to be environmentally qualified at facilities Info duplicates 811008 response.per 1E Bulletin 79-01B.w/listed exceptions FAY.C H Hisconsin Electric Power Co 83/05/20 PENTON.H R Office of Nuclear Reactor Regulation. Director 29pp 18571 360 24X Fiche 50-266,83/05/20,8305240497

O Inspection reports. IE Bulletins & correspondence

- 8212060385 (E Info Notice 83-14, "Demotered Spent for Erchange Resin Susceptibility to Erpthermic Chemical Reaction " Svc list
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50~000.83/03/21.8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator "
 - Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24x Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures " Svc list encl
 - JORDAN,E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fithe 50-600,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 930103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305120456 Forwards IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 & notice of violation No reply to Item 2 of notice of violation required BHAFER.H D Region 3, Office of Director 83/04/25 BURSTEIN:S Hisconsin Electric Power Co 2pp 18431 029 24% Fichs 30-266.83/04/25.8305120456
- --8305120463 Notice of violation from Insp on B30201-0331 SMAFER,W D Region 3, Office of Director B3/04/25 18431 031 24% Fiche 50-265.83/04/25,8305120495
- ~~8305120468 IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 Noncompliance noted gensonnel failed to check out when exiting containment per Procedure HP 2 4 k two Eberline Nodel DAI-6CC area radiation monitors not labeled HABUE.R L , FITZPATRICK.B . JACKIH, I N Region 3. Office of Director 83/04/22 Ppp 18431 032 24X Fiche 50-266,83/04/25,8305120456
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list enc! JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc. 315pp 18382-047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 J45 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-25, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl URDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03. Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24% Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list enc!
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030

- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc 11st encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705704 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83705704.8303040031
- 8305120408 Submits addi response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Mechanical corrections installed w/asception of two corrections requiring welding to RHR piping
 BURSTEIN, S Hisconsin Electric Power Co 83/05/04 KEPPLER, J Q
 Region 3, Office of Director 2pp 18431 150 24X
 Fiche 50-246.83/05/04,8305120408
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305200229 Clarifies position re maint & testing program for HVAC filter units not controlled by Tech 8pecs & for respirator fitting program.per IE Insp Repts 50-264/83-03 & 50-301/83-03 dtd 830216 although no noncompliance noted FAV.C & Wisconsin Electric Power Co 83/05/06 KEPPLER, J. O Region 3, Office of Director 5pp 18517 102 24X Fiche 30-266,83/05/06,8305200229
- 8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation 1 re fire signaling sys testing withdrawn BPESSARD.R L Division of Engineering 83/05/09 BURSTEIN, B Wisconsin Electric Power Co 2pp 18464 333 24X Fiche 50-266,83/05/09,8305170241
- --B305170252 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include add1 performance data Fire protection tests reviseed PAY. C W Wisconsin Electric Power Co 83/01/21 KEPPLER, J 0 Region 3, Diffice of Director 42pp 18464 335 24% Fiche 50-266,83/05/09,8305170241
- --B305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity FAY.C W Hisconsin Electric Power Co B3/02/24 KEPPLER, J Q Region 3. Office of Director 3pp 18465 015 24X Fiche 50+266,83/05/09,8305170241
- 8305170130 Ark receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Inep Repts 50-266/89-05 & 50-301/83-05 HIND.J A Division of Radiological & Materials Safety Programs 83/05/10 24X Fiche 50-266,83/05/10,8305170138
- --8305170144 Responds to NRC 830314 ltr re violations noted in IE Safeguards Insp Repts 50~266/83~03 & 50~301/83~05 Corrective actions withheld (ref 10CFR73 21)
 BURSTEIN: 8 Wisconsin Electric Power Co 83/04/13 HIND, J A Division of Radiological & Materials Safety Programs Ip 18466 271 24X Fiche 50~266,83/05/10,8305170138
- 8303040034 IE Info Notice 83~30, "Misapplication of Generic Emergency Operating Procedures (EQP) Quidelines "Svc list encl ORROANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of New 114pp 18524 003 24x Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "

 8vc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/17 Consolidated Edison Co. of New

 York, Inc. 1149p 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305240380 Confirmatory action ltr re NRC 830314 order specifying certain TMI action items as complete or completion dates noted ltem II F 1.i, "Noble Gas Effluent Montior." complete, however main steam line monitors not operational KEPPLER, J O Region 3, Office of Director 83/05/20 BURSTEIN, S Hisconsin Electric Power Co 1p 18375 072 24X Fiche 50-266.83/05/20,8305240380
- B30527024i Documents agreement per B30517 conference call re timing requirements for notification of state & local agencies for unusual event or alertiper IE Insp.Repts 30-266/83-01 & 30-301/83-01. Procedure to be initiated by B30701 FAY, C W Wisconsin Electric Power Co B3/05/23 KEPPLER, J 9 Region 3, Office of Director ip 18637, 161 24% Fiche 50-266, B3/05/23, B305270241

- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN:E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- B305160169 Forwards monthly operating repts for Apr 1983 FAV.C W Wisconsin Electric Power Co B3/03/10 NRC - No Detailed Affiliation Given ip 18446 073 24X Fiche 50-266, 83/05/10, 8305160169
- --8305160171 Monthly operating repts for Apr 1983 FAY.C W Wisconsin Electric Power Co 83/05/09 9pp 18446 074 24X Fichø 50-266.83/05/10.8305160169
- 8 Reportable occurrences, LERs & related correspondence
- B305030376 Forwards updated LER 82-022/01X-2
 FAY.C W Wisconsin Electric Power Co B3/04/25 KEPPLER, J G
 Region 3. Office of Director Ip 18308 216 24X
 Fiche 50-266:83/04/25, B305030376
- --8309030382 Updated LER 82-022/01X-R on 821111, eddy current indications of mechanical damage in excess of Tech Spec plugging limit identified Caused by foreign objects in steam generator secondary side Tubes w/mechanical damage plugged FAY.C W Wisconsin Electric Power Co 83/04/25 Region 3. Office of Director 5pp 18308 217 24X Fiche 50-266,83/04/25,83050374
- B305130034 NPDES noncompliance notification on 830429, daily max pH effluent limit exceeded Investigation will include review of sampling & analysis techniques, insp of treatment equipment & review of operator logs FAY.C W Hisconsin Electric Power Co 83/05/05 Wisconsin Btate of 2pp 18436 208 24X Fiche 50-266, 83/05/05, 8305130034
- B305190226 Followup to B30331 NPDES noncompliance notification On B30316 & 17, retention pond discharge (Sample Point 501) exceeded pH limit Caused by carryover of line from water treatment sys FAY.C W Wisconsin Electric Power Ca B3/05/12 Wisconsin, Btate of 2pp 1B300 202 24X Fiche 30-266.B3/05/12,8305190226
- 8305240002 PND-III-83-037 on 830509, Region III radiation specialist learned that main steam line noble gas monitors not yet installed per 830314 commitment data Ofc of Investigation investigating failure Monitors to be installed by mid June LOVENDALE, P. PAPERIELLO, C. Region 3, Office of Director 83/05/18 ip 18549 138 24X Fiche 50-266, 83/05/18, 8305240002
- B305240379 NPDES noncompliance notification on 830429,pH of retention pond discharge found above limit Caused by demineralized makeup water treatment sys problems re undissolved line carrying through to pressure filter sys FAY,C,W Wisconsin Electric Power Co B3/05/18 Wisconsin, State of ip 18571 040 24% Fiche 50-246,83/05/19,8305240379
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- B303050146 Forwards rev to Chapter 9 of amended security plan Rev withheld (ref 10CFR73 21) MCBRIDE.L M, Public Servics Co of Colorado 83/03/28 COLLINS.J T Region 4. Office of Director 1p 18342 231 24X Fiche 50-267,83/03/28,8305050146
- B305120566 Releases public version of changes to radiological emergency response plan implementing procedures FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18442 079 24X Fiche 50-267.83/05/02, 8305120566
- ---B305120570 Forwards public version of Issue 4 to Radiological Emergency Response Plan RERP-HOME. "Home Packet for Off-Shift Notifications" & Issue 15 to RERP-PHONE LISTB WAREMOURO, D W Public Service Co of Colorado 83/02/16 EISENHUT, D Q Division of Licensing COLLINS, J T Region 4, Office of Director 2pp 18442 081 24% Fiche 50-267, 83/05/02, 8305120366
- --8305120578 Public version of Issue 4 to Radiological Emergency Response Plan RERP-HOME, "Home Packet for Off-Shift Notifications" & Issue 15 to RERP-PHONE LISTS WAREMBOURG, D. W. Public Service Co. of Colorado. 83/02/16

- B305200494 Responds to NRC B30331 ltr rc diviation noted in IE Insp. Rept 50-267/83-03 an B30117-21 Corrective actions emergency plan implementing procedures revised to state responsibilities of shift supervisor/emergency coordinator WAREHBOVES.D W Public Service Co of Colorado B3/05/06 COLLINS.J T Region 4. Office of Director 2pp 18513 005 24X Fiche 50-267.83/05/06,8305200494
- 8305110034 General Ltr 83-21 to all licensies of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enci EISENHUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc. 16pp 18540 095 24X Ficha 50-000,83/05/11,8305110034
- Q Adjudicatory correspondence
- B305200914 Forwards order confirming util commitments on post-TM1related issues Order based on commitments in util 820317 5 0905 1trs responding to Generic Ltrs 82-05 & 92-10 MADSEN.G L Region 4, Office of Director 83/04/27 LEE.Q R Public Service Co of Colorado 4pp 18516 045 24X Fiche 50-267.B3/04/27,B305200316
- --8305200578 Order confirming licensee commitments on post-TMI-related issues Schedule changes acceptable for TMI Items (A. 3 i. II B.2.) II B.3. II B.4 & II F.1 GAGLIARDD, J.E. Division of Resident, Reactor Project & Engineering Programs 83/04/27 Public Service Co. of Colorado. 11pp 18516-049 24X Fiche 50-267.83/04/27.8303200916
- P Operating license stage documents & correspondence
- 8305020462 Advises that NRC 830228 requested documentation re nuclear detector decalibr will be transmitted within 30 days Existing drawings described in Encl 3 to 830228 ltr do not reflect proposed changes

 BREV.H L. Public Bervice Co of Colorado 83/04/15 COLLING.J T Region 4. Office of Director 2pp 18283 308 24%

 Fiche 30-267.83/04/15.9305020462
- 8305050214 Forwards application to amend License DPR-34 Amend assures operability of plant protective sys % other critical instrumentation by defining min operable instrument channels & trip settings in response to RD-83-001 LEE, D R Public Service Co of Colorada 83/04/19 COLLINS, J T Region 4. Office of Director 2pp 18338 112 24X Fiche 50-267, 83/04/19, 8303030214
- --8303050222 Application to amend License DPR-34, revising App A Tech Specs to assure operability of plant protective sys & other critical instrumentation by defining min operable instrument channels & trip settings LEE.O R Public Service Co of Colorado 83/04/19 8pp 1833B 114 24X Fiche 50~267,83/04/19,8305050214
- --B305050228 Proposed Tech Spec Tables 4 4-1 4 4-4 re instrument operating requirements for plant protective sys.scram.loop shutdown.cir.culator trip & reactor protective sys rod withdrawal prohibit
 # Public Service Co of Colorado B3/04/19 24pp 18338 122 24x Fiche 50-267,83/04/19,8305030214
- B30516004B Clarifies proposed changes in undervoltage protection & reiterates schedule for implementation of design changes & mods Existing non-Class IE undervoltage relays will be retained as protection for 4.160-volt buses
 BREY,H L Public Bervice Co of Colorado B3/04/27 COLLINS,J T Region 4. Office of Director 2pp 18453-141 24X
 Fiche 30-267,83/04/27,8305160048
- B305160059 Forwards comments of util & OA Technologies re interim rept by LASE on PRCV liner hot spots Util does not concur w/categorization of hot spots according to universal & relative degrees of severity BREY,H L. Public Service Co. of Colorado. B3/04/27 CDLLINS.J T Region 4. Office of Director. 9pp. 18459-132 24X Fiche 50-267.83/04/27.8305160053
- 8303170380 Informs that control room HVAC sys satisfies requirements of single-failure criteria for control room habitability No further mods anticipated BREY.H L Public Service Co of Colorade 83/04/29 MADSEN.G L Region 4. Dffice of Director 2pp 18469 211 24X Fiche 50-267. 83/04/29, 8305170380
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to DLs Svc list encl EISENHUT.D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02.8305020455

- 8305200494 Responds to MRC 830331 ltr re deviation noted in 1E Insp Rept 50-267/83-03 on B301t7-21 Corrective actions emergency plan implementing procedures revised to state responsibilities of shift supervisor/emergency coordinator WAREMBOURG, D W Public Service Co of Colorado 83/05/06 COLLINS. J T Region 4, Office of Director 2pp 18513 G05 24X Fiche 50-267, B3/05/06, B305200494
- 9305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISEMMUT. D. 9 Division of Licensing 83/05/09 Consolidated Edison Co. of New York. Inc. 16pp. 18627-153 24X Fiche 30-000,83/03/09,8305090659
- B305200167 Summary of B30428-29 & 0502-04 & 06 meetings in Bethesda, MD re impact of Public Law 97-145 (Sholly Decision) on licensing activities
 HAGNER, P.C. NRC No Detailed Affiliation Given 83/05/11
 GAGLIARDD, J.E. Division of Resident, Reactor Project & Engineering Programs 3pp 18519 067 24% Fichs 50-267, 83/05/11, 8305200167
- 8305200178 Requests remittance of RETS amend fee due from review of B10102 application within 15 days of ltr receipt MLLER.W O License Fee Hanagement Branch 83/05/12 LEE.O R public Service Co of Colorado 1p 18540 229 24x Fiche 50-267.83/05/12.8305200178
- 8305230546 Requests clarification & add) info re 830415 ltr on control rod drive mechanisms operating temp limitations, within 60 days of ltr receipt Adequate assurance exists for safe interim operation MADSEN.G L. Region 4. Office of Director 83/05/16 LEE, 0 R Public Service Co of Cotorado 4pp 1853/098 24X Fiche 50-26/.83/05/16,8305230546
- 8305240477 Forwards nuclear detector decalibr documentation per NRC B30228 request Documentation unavailable when originally requested due to plant procedures which permit revs only after mod approved & installation begun W/o documentation DREY.H I Public Service Co of Colorado 83/05/16 COLLINS,J T Region 4. Office of Director 3pp 18549 338 24% Fiche 50-267,83/05/16,8305240477
- 8305310027 Discusses changes to operating procedures for issuance of licensing actions Util will provide State of CD w/copy of amend applications filed w/NRC Util 801001 amend application enci H/o enci HAONER, P C Region I, Office of Director 83/05/20 HAZLE, A J Colorado. State of 10 18653 178 24x Fiche 50-267, 83/05/20, 8305310027
- 8305310090 Requests Fr publication of notice of consideration of 830419 OL amend request & proposed no significant hazards consideration determination & opportunity for hearing MADSEN.O L Region 4, Office of Director 83/05/20 CLARK.R A Operating Reactors Branch 3 2pp 18655 127 24X Fiche 50-267,83/05/20,8305310090
- 83053101ti Forwards fees for radiological ETS changes proposed in 830323 it's reformat of Tech Specs into STS developed by EONO per Jan 1981 request MAREMBOURG, D Public Service Co of Colorado 83/05/20 CDLLINS, J. T. Region 4, Office of Director 3pp 18658 048 24X Fiche 50-267,83/05/20.8305310111
- 8305310227 Requests FR publication of notice of proposed issuance of amend to GL. proposing no significant hazards consideration determination since proposed amend incorporates present NRC guidelines

 MADSEN, G L Region 4, Office of Director 83/05/20 CLARK, R A Operating Reactors Branch 3 2pp 18658 082 24X

 Fiche 50-267, 83/05/20,8305310229
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Devatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York. Inc 112pp 18308 319 244 Fichs 50-000.83/03/21.8212060385
- B303040021 (E Info Natice 83-21, "Defective Emergency Use Respirator"
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021,

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures *

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 16382 047 24% Fiche 50-000.83/04/28,6303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syc list encl JORDAN,E L Division of Emergency Preparednasa & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28.8303040027
- 830304002B IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JGRÐAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441-170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JURBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fichs 50-000,83/05/04,8303040930
- B3D304003i IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past B30103) B3/05/04 Consolidated Edison Ca of New York, Inc 119pp iB441 001 24X Fiche 50-000, B3/05/04, B303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24% Fichs 50-000,83/05/04.8303040033
- 8303040034 JE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Quidelines " Svc list ancl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc 1ist encl
 JURDANN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fichs 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305060546 Forwards revised "Initial Approach to Power Tests (B-Series)," Interim Rept 26 for period ending 830222 MAREMBOURG, D Public Service Co of Colorado 83/04/13 COLLINS, J T Region 4. Office of Director 2pp 18348 302. 24X Fiche 50-267.83/04/13,8305060546
- --8303060552 "Initial Approach to Power Tests (B-Series)," Interim Rept 26 for period ending 830222 + Public Bervice Co of Colorado, 83/02/22 2pp 18348.304 24X Fiche 30-267.83/04/13/8305060546
- B305090499 Forwards revised "Rept of Changes, Tests & Experiments Not Requiring Prior Commission Approval Per 10CFR50 39(4) for 1982" HAREMBOURG, D Public Service Co of Colorado 83/04/25 COLLINS, J. T. Region 4, Dffice of Director 2pp 18360 113, 24% Fiche 50-267, 83/04/25, 8305090489
- --B305090565 Revised "Rept of Changes Tests & Experiments Not Requiring Commission Approval per 100FR80 59(a) for 1982 " # Public Service Co of Colorado B3/04/25 37pp. 18360 115 24% Fiche 50-267.83/04/25.8303090489

- 8305230426 Forwards monthly operating rept for Apr 1983 WAREMBOURG. D Public Service Co of Colorado 83/05/12 Director's Office, Office of Inspection and Enforcement 1 18538 219 24X Fiche 50-267.83/05/12.8305230426
- --8305230427 Monthly operating rept for Apr 1983 FULLER.C H Public Service Co of Colorado 83/05/10 8pp 18538 220 24X Fiche 50-247,83/05/12,8305230424
- 8 Reportable occurrences, LERs & related correspondence
- B305060479 Forwards LER 83-016/03L-0 Detailed event analysis enci MAREMBUURG, D Public Service Co of Colorado B3/04/28 CDLLINS, J T Region 4, Office of Director 5pp 18348 155 24X Fiche 50-267,83/04/28,8305060479
- --8305060484 LER 83-016/03L-O on 830331, two Class 1 hydraulic shock suppressors found inoperable Caused by fully extended snubbers, due to thermal pipe movement One snubber adjusted & other replaced Public Service Co of Colorado 83/04/28 Region 1, Office of Director ip 18348 160 24X Fiche 50-267.83/04/28,

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8305270326 Forwards IE Insp Repts 50-269/83-13;50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompitance noted DANCE, H C Division of Project & Resident Programs 83/05/06 TUCKER, H B Duke Power Co 2pp 18641 142 24X Fiche 50-269,83/05/06;8305270326
- 8305270374 Forwards IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/05/06 TUCKERH B Date Power Co 2pp 18643 011 24X Fiche 50-269.83/05/06,8305270374
- --8305270397 IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas Inspected emergency preparedness exercise HUFFMAN, 9 N Region 2, Dffice of Director 83/05/03 10pp 18643,013 24X Fichs 50-269,83/05/06,8305270374
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl
 EIBENNUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fichs 50-000.83/05/11.8305110034
- J Insurance & Indemnity information
- B305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101 respectively for McOuire LAMBON.L T Duke Power Co 83/05/20 8ALT/MAN,J Office of Resource Management, Director 17pp 18626 120 24X Fiche 50-000,83/05/20,8305260261
- P Operating license stage documents & correspondence
- 8305090078 Forwards Amends 120,120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules CONNER, E. L. Operating Reactors Branch 4 83/04/15 TUCKER, H B Duke Power Co 4pp 18381 140 24X Fiche 50-267,83/04/15, 83/0590078
- --8305090111 Amends 120,120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Spec withdrawal schedule for reactor vessel surveillance capsules STOLZ, JF Operating Reactors Branch 4 83/04/15 8pp 18381

- --B305090124 Safety evaluation supporting Amends 120,120 & 117 to Licenses DPR-3B, DPR-47 & DPR-55 respectively * Office of Nuclear Reactor Regulation, Director 83/04/15 2pp 18381 152 24X Fiche 30-269.83/04/13,8305090078
- --B30507013B Notice of issuance 2 availability of Amends 120,120 & 117 to Licenses DPR-3B, DPR-47 & DPR-55, respectively STDL2.J F Operating Reactors Branch 4 B3/04/15 2pp 18281 154 24X Ficke 50-269, B3/04/15, B305050078
- 8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept. "Control of Heavy Loads (C-10), Oconbe Nuclear Power Station, Units 1,2 & 3 " Phase 1 actions acceptable per NURGG-0612
 STOLZ, J.F. Operating Reactors Branch 4 B3/04/20 TUCKER, H.B. Dute Power Co. 3pp. 18457 179 24% Fichs 50-269, 83/04/20, 8305130294
- --8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREO-0612) * Office of Nuclear Reactor Regulation, Director 83/04/20 ip 18457 182 24X Fiche 50-269,83/04/20.8305130294
- --8304070286 "Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1.2 & 3," technical evaluation rept ROBERTS, S Franklin Institute/Fianklin Research Center NRC-03-81-130 TER-C5506-374/375/37 83/03/31 CLEMENSON, F NRC No Detailed Affil(ation Oliven 20pp 18457 183 24X Fiche 50-269, 83/04/20,8305130274
- 8305020372 Forwards corrections % updates to 830418 ltr supporting 830418 application for amend to License DPR-380 postponing certain instrument surveillance requirements TUCKER.H B Duke Power Co 83/04/22 DENTON.H R Office of Nuclear Resolution, Director STOLE.JF Operating Reactors Branch 4 2pp 18276 290 24% Fiche 50-269.83/04/22.8305020372
- --8305020375 Corrected & updated proposed Tech Bpec changes re instrument surveillance requirements
 * Duke Power Co 83/04/22 t7pp t8276 292 24X
 Fiche 50-269,83/04/22,8305020372
- 8305090608 Forwards safety evaluation in support of continued PNR operation w/Dresser primary safety valves to TMI Action Item II D i EPRI data on tests of certain models of Dresser safety valves under review on generic basis BTOLZ.JF Operating Reactors Branch 4 83/04/27 TUCKER.H B Duke Power Co 2pp 18367 111 24X Fiche 30-269,83/04/27.8305090608
- --8303D90612 SER in support of continued PWR operation w/Dresser primary safety valves (TMI Action Item II D 1)

 * Operating Reactors Branch 4 83/04/27 i3pp 18367 It3 24% Fiche 50-269.83/04/27.8305070608
- B305040564 Forwards proposed App A to offsite dose calculation manual, supporting radiological efficent Tech Spec per 830209 ltr Submittal constitutes final revised offsite dose calculation manual

 TUCKER, H 9 Duke Power Co B3/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 18320 083 24X Fichs 50-269, 83/04/28, 8305040564
- --8305040568 App A to, "Otonge Nuclear Station Site Specific Info "
 * Duke Power Co 83/04/28 32pp 18320 084 24X
 Fiche 50-269,83/04/28,8305040564
- 8305200103 Forwards safety evaluation on standby shutdown facility
 Design meets requirements, except for process monitoring
 instruments for source range flux monitoring & stoam
 generator prossure indication
 BYOLZ.JF Operating Reactors Branch 4 83/04/28 TUCKER, H B
 Duke Power Co 4pg 18576 154 24X Fishe 50-269, 83/04/28,
 B305200103
- --8305200104 Safety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication * Office of Nuclear Reactor Regulation, Director 83/04/28 17pp 18576 158 24X Fiche 50-269, 83/04/28 8305200103
- 8305020455 Generic Ltr 83-19 to all gower reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc 30pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

- B303060365 Natification of B30306 meeting u/BAN Duners Group in Bethesda.MD to discuss core barrel failure at Rancho Seco & Crystal River 3. future plans for resolving problem & justification for continued operation MINER.S Operating Reactors Branch 4 B3/05/02 BTDLZ, J Operating Reactors Branch 4 2pp 18353 092 24X Fishe 30-000.B3/05/02,B305060365
- 8305180034 Forwards Amends 121,121 % [18 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage EISENHUT,D & Division of Licensing 83/05/05 TUCKER,H B Duki Power Co 3pp 18499 245 24X Fichs 50-249,83/05/05,8305180034
- --8305180045 Amends [21, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to delay certain surveillance requirements until next refueling outage STOL7, JF Operating Reactors Branch 4 83/05/05 21pp 18499 248 24X Fiche 50-249,83/05/05,8305180034
- --8305180059 Safety evaluation supporting Amends 121,121 & 118 to Licenses DPR-3B, DPR-47 & DPR-55, respectively + Office of Nuclear Reactor Regulation, Director 83/05/05 3pp 18499 269 24% Fiche 50-267,83/05/05,8305180034
- --830518006B Notice of issuance & availability of Amends 121,121 & 118 to Licenses BPR-3B, DPR-47 & DPR-55 respectively STDLZ, J F Operating Reactors Branch 4 B3/05/05 2pp 18499 274 24% Fiche 50-269, B3/05/05, B305180034
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659
- 6305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCS temp between 250 F & 223 F rather than present 200 F Preparation of proposed Tech Specs repurging in progress TUCKER.H 3 Duke Power Co B3/03/10 DENION.H R Office of Nuclear Reactor Regulation, Director STUZ.J F Operating Reactors Branch 4 2pp 18437 154 24X Fiche 30-249.83/05/10.8305130025
- 8305230499 Notification of 830608 meeting w/util in Bethesda, MB to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed SUERMANN-JF Operating Reactors Branch 4 83/05/16 STOLZ-JF Operating Reactors Branch 4 24X Fiche 50-000, 83/05/16, 8305230499
- 6303250479 Forwards responses to B30411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation.per NUREG-0737.TMI Action Item II B 4 provided Response to IE Bullotin 79-010 will be revised TUCKER.H B Duke Power Co 83/05/19 DENTON.H R Office of NUCKER.H B Duke Power Co 83/05/19 DENTON.H R Office of A 27pp 18589 005 24X Fiche 50-249.83/05/19.8305250479
- 8303270239 Application to amend License DPR-38, changing core grotection safety limits, protective sys max allowable setpoints & rod position limits
 TUCKER, H B Dute Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 App 18641 224 24X Fiche 50-269,83/05/19,8305270259
- --8309270279 Proposed Tech Spec changes re core protection safety limits, protective sys max allowable setpoints & rod position limits # Duke Power Co 83/05/19 17pp 18441 228 24% Fichs 50-249,83/05/19,8305270259
- --8305270294 "Generic Startup Physics Test Program "
 * Duke Power Co 83/03/31 22pp. 18641 245 24x
 Fiche 50-269,83/05/19,8305270259
- --8305270309 "Oconee Unit i Cycle 8 Reload Rept "

 * Babcock to Wilcox Co BAN-1774 83/02/28 46pp 18641,267.
 24X Fiche 50-269,83/05/19.8305270259

- 8305310081 Submits add1 info re safety-related environ qualification of electrical equipment, per 10CFR50 49(g) & IE Bulletin 79-018 Ejectrical isolation provided for all reactor protective sys & angineered safeguards protective sys TULKER, H B Dute Power Co 83/05/20 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 3pp 18655 123 24X Fiche 30-269,83/05/20,8305310081
- B305J100B3 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads util assessment of asymmetric loads problem acceptable STGLZ.J F Operating Reactors Branch 4 83/05/20 TUCKER.H B Dute Power Co 2pp 18662 311 24X Fiche 50-269.83/05/20, 8305310083
- ~-8305310089 Safety evaluation accepting util analysis of asymmetric LDCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided # Operating Reactors Branch 4 83/05/20 74pp 18662 313 24X Fiche 50-269.83/05/20.8305310083
- G Inspection reports: IE Bulletins & correspondence
- 8305200303 Forwards order imposing civil monetary penalties transmitted to licensee on 821012, for transmittal to Ofc of FR for publication W/o encl
 AXELRAD.J A Director's Office, Office of Inspection and Enforcement 82/10/15 Docketing & Services Branch 1p 18517 062 24X Fiche 50-269, 82/10/15, 8305200303
- 8305200544 Submits add1 response to 820625 notice of violation, per NRC 821012 request Directive 4 2 5, "Procedure for Implementing Independent Verification Requirements," will be revised Payment of civil penalty encl TUCKER, H B Duke Power Co 82/11/11 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 18515 336 24X Fiche 50-269,82/11/11.8305200544
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post B30103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 30-000.83/03/21,8212040385
- 8305270403 Forwards IE Insp Repts 50-249/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/04/05 TUCKER.H B Duts Power Co 2pp 18642 321 24X Fichs 50-267, 83/04/05, 8305270403
- --8305270411 IE Insp Repts 50-269/83-08.50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompilance noted Major areas inspected operations, surveillance testing, maint event rept review & smergency procedure review BRYANT.J. FALCONER.D Region 2. Office of Director, IONATONIS.A J Division of Project & Resident Programs 83/04/04 12pp 18642 323 24X Fiche 50-267.83/04/05.8305270403
- 8305270497 Forwards IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 Na noncompliance noted BANCE: H C Division of Project & Resident Programs 83/04/05 TUCKER, H B Dute Power Co 2pp 18446 192 24X Fiche 30-269, 83/04/05, 8305270497
- --8305270318 IE Insp Repts 50-269/83-09.50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREG-0737. Items II 8 2. "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys" COLLINS, T R , BARR, K P Region 2. Office of Director 83/04/01 7pp 18646 194 24X Fichs 50-269.83/04/03.8305270497
- 8303040021 IE Info Notice 83~21, "Defective Emergency Use Respirator" Svc 11st encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 135 24x Fiche 50-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Velve Failures "
 Svc list enc!
 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383,089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list and JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24x Fiche 50-000.83/04/25.8303040025.

- 8303040026 IE Info Notice 83-24. "Laose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment 8ys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York. Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Byo list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/03/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/03/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8305270326 Forwards IE Insp Repts 50-249/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted DANCE: HC Division of Project & Resident Programs 83/05/06 TUCKER: H B Duke Power Co 2pp 18641 142 24% Fiche 50-269,83/05/06,8305270326
- --8305270338 IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing, maint & operations & annual emergency drill BRYANT, J. FALCONER, D. Region 2, Office of Directra BROWNLEE, V. L. Division of Project & Resident Programs 83/05/06 9pp. 18641 144 24X Fiche, 50-269,83/05/06,8305270326
- B305270374 Forwards IE Insp Repts 50-269/83-10.50-270/83-10 & 50-287/83-10 on B30405-06 No noncompliance noted DANGE.H C Division of Project & Resident Programs. B3/05/06 TUCKER.H B Duke Power Co 2pp 18643 011 24X Fiche.50-269.83/05/06.8305270374
- --8305270387 IE Insp Repts 50-269/83-i0.50-270/83-i0 & 50-287/83-i0 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise

 HUFFMAN. O N Region 2. Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/03 10pp 18643 013 24X Fiche 30-269,83/05/06,8305270374
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concern re open pressurization line test valve on Unit 3 discussed O'REILLY, J P Region 2, Office of Director 83/05/11 TUCKER, H B Duke Power Co 2pp 18642 280 24X Fichs 50-269,83/05/11, 8305270425.
- --8305270435 IE Enforcement Conference Repts 50-267/83-12,50-270/83-12 & 50-287/83-12 on 830233 & 0419 Major areas discussed open pressurization line isolation valve on emergency hatch on 830317 & corrective actions DANCE, H C Division of Project & Resident Programs B3/05/10 Spp 18642-282 24X Fiche 50-269,83/05/11,8305270425
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

- 6303310081 Submits add1 info re safety-related environ qualification of electrical equipment.per 10CFR50 49(g) & IE Bulletin 79-018
 Electrical isolation provided for all reactor protective sys
 & engineered safeguards protective sys
 TUCKER.H B Duke Power Co 83/05/20 DENTON,H R Office of
 Nuclear Reactor Regulation, Director SIOLZ.JF Operating Reactors
 Branch 4 3pp 18655 123 244 Fiche 50-269.83/05/20.8305310081
- 8303040046 lE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York. Inc. 144pp 18647 007 24X Fiche 50-000.83/05/26.8303040046
- R Periodic operating reports & related correspondence
- B305170455 Forwards monthly operating repts for Apr 1983 TUCKER,H B Duke Power Co 83/05/13 Director's Office Office of Inspection and Enforcement 1p 18470 142 24X Fiche 50-269, B3/05/13, B305170455
- --8305170460 Monthly operating repts for Apr 1983 REAVIS, J A Duke Power Co 83/05/13 16pp 18470 143 24X Fiche 50-269,83/05/13,8305170455
- 8 Reportable occurrences: LERs & related correspondence
- 8107040024 PND-II-81-052A on Bi07i5, while performing reactor vessel insp w/remote video cameras, loose parts discovered in hottom of vessel Parts identified as missing from internal vessel structures Caused by corrosion fatigue BRYANT, J C Region 2, Atlanta, Office of the Director (81/03/01) BI/08/07 Ip 18326 300 24% Fiche 50-229, BI/08/07, BI07040024
- 830505034) Forwards AECD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors 2/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR.RES & IE BROWN: E J . ASHE, F S Reactor Operations Analysis Branch 83/04/13 SEYFRIT.K V Reactor Operations Analysis Branch 2pp 18352 051 24X Fiche 50-000,83/04/13.8305050341
- --8305030353 "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment: "AEOD engineering evaluation rept BRONNE J , ASHE,FS D Director's Office 83/04/13 7pp 18352 053 24X Fiche 50-000,83/04/13,8305050341
- 8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping" BROWN,E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation mept Small pipe leaks associated u/unanticipated vibration problems require addl supports or rerouting of piping BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24% Fiche 50-000,83/04/19,8305230573
- 8305170324 Forwards LER B3-012/01T-O Detailed event analysis encl TUCKER:H B Duke Power Co 83/04/22 O'REILLY, J P Region 2. Office of Director 4pp 18465 227 24X Ficha 50-267:B3/04/22. B305170324
- ---B305170338 LER B3-012/017-0 on B3040B.emergency discharge valve to Keewee Tailrace CCH-B opened w/o command.rendering condenssr circulating water emergency discharge sys inoperable Caused by shorted conductor Conductor replaced PETTY.J C Duke Power Co B3/04/22 Region 2, Office of Director 1p 18465 231 24X Fiche 50-269.83/04/22.8305170324.
- 8305110324 Part 21 rept re Type SA-1 Class IE relays Bilicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing BCR w/burn-in SCR
 DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd)
 83/04/27 STELLD,V Director's Office, Office of Inspection and Enforcement 3pp 18373 278 24% Fiche 50-000,83/04/27,8305110324
- 8305050254 RDs 269/83-10 & 287/83-04 re 821212 & 630303 loss of containment integrity Mgt audit in progress Summary list of completed & remaining activities, w/projected completion dates; encl TUCKER.H B Duke Power Co 83/04/29 Q'REILLY, J.P. Region 2, Office of Director 15pp 18338 001 24X Fiche 50-269, 83/04/29, 8305050254

- 8305170361 Forwards updated LER 83-012/017-1 Detailed event analysis encl
 - enci TUCKER,H B Dute Power Co 83/05/05 O'REILLY, J P Region 2. Office of Director 2pp 18468 125 24x Fiche 50-269,83/05/05. 8303170361
- --8305;70566 Updated LER 83-012/017-1 on 830421.emergency discharge valve to Keouse Tailrate CCM-8 opened w/o command.rendering condenser circulating water emergency discharge sys inoperable Caused by component failure PETTY.J C Duke Fower Co 83/05/05 Region 2. Uffice of Director 1p 18468 127 247 Fishe 50-269, 83/05/05.8305170561
- 8305230556 Notifies that noble gas monitor-stack high-range radiation monitor (NUREG-0737, Hem II F 1(1)) reported as being operable in 830318 orders became inoperable on 830426 Caused by moisture contamination New monitors ordered TUCKER: H D Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLE. J F Operating Reactors Branch 4 2pp 18388 185 24X Fiche 30-269,83/05/19,8305250556
- DOCKET 50-270 OCONEE NUCLEAR STATION. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8303270326 Forwards IE Insp Repts 50-269/83-13.50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted DANCELH C Division of Project & Resident Programs 83/05/06 TUCKER H B Duke Power Co 2pp 18641 142 24X Fiche 50-269.83/05/06.8305270326
- --8305270338 IC Insp Repts 50-269/83-13.50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Najor areas inspected surveillance testing maint & operations & annual emergency drill BRYANT, J Region 2, Office of Director 83/05/06 9pp 18641 144 24% Fiche 50-269.83/05/06.8305270326
- 0305270374 Forwards IE Insp Repts 50-269/83-10.50-270/83-10 & 50-287/83-10 on 830405-06 No honcompliance noted DANCE:H C Division of Project & Resident Programs 83/05/06 TUCKER:H B Duke Power Ca 2pp 18643-011 24X Fiche 50-269.83/05/06.8305270374
- --8305270387 IE Insp Repts 50-269/83-10.50-270/83-10 & 50-287/83-10 on 830403-06 No noncompliance noted Major areas inspected swergency preparedness exercise #UFFMAN.6 N Region 2, Office of Director 83/05/03 10pp 18643 013 24X Fiche 50-269/83/05/06/8305270374
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list entl EISENHUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540-095 24X Fich 50-000-83/05/11,8305110034
- J Insurance & indemnity information
- 8309260261 Forwards Endorsements 35 & 36 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 28 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101. respectively, for McOuire LAMSON, L T Duke Power Co 83/05/20 SALTZMAN, J Office of Resource Management. Director 19pp (8626 120 24X Fiche 50-000,83/05/20,8305260261
- P Operating license stage documents & correspondence
- B303090078 Forwards Amends 120, 120 \$ 117 to Licenses DPR-38, DPR-47 & DPR-35, respectively, safety evaluation 5 notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules CONNER, E.L. Operating Reactors Branch 4 B3/04/15 TUCKER, H B Duke Power Co. 4pp 18381 140 24% Fiche 50-269, 83/04/15, 830,590,078
- --8305090111 Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Spec withdrawal schedule for reactor vessel surveillance capsules STOLZ, JF Operating Reactors Branch 4 83/04/15 Bpp 18381 144 24X Fiche 50-269,83/04/15,8305090078
- ---8305090124 Safety evaluation supporting Amends 120,120 & 117 to Licenses DPR-39, DPR-47 & DPR-55, respectively • Office of Nuclear Reactor Regulation, Director 83/04/15 2pp 18381 152 24X Fiche 50-269,83/04/15,8305090078

- --8305090138 Notice of issuance & availability of Amends 120,120 & 117 to Licenses DPR-38.DPR-47 & DPR-35; respectively STOLZ, JF Derating Reactors Branch 4 83/04/15 2pp 18381 134 24% Fiche 50-269,83/04/15,8305090078
- 8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept. "Control of Heavy Loads (C-10). Ocones Nuclear Power Station. Units 1.2 & 3" Phase 1 actions acceptable per NUREO-0612 STOLZ.J F Operating Reactors Branch 4 83/04/20 TUCKER.H B Duke Power Co 3pp 18457 179 24X Fichs 30-269, 83/04/20, 8305130294
- --8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NURGO-0612) = Office of Nuclear Reactor Regulation, Director 83/04/20 1p 18437 182 24% Fiche 50-269,83/04/20,8305130294
- --8304070286 "Control of Heavy Loads (C-10), Oconee Nuclear Power Btation Units 1,2 & 3," technical evaluation rept ROBERTS.S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C3506-374/375/37 83/03/31 CLEMENSON,F NRC - No Detailed Affiliation Given 28pp 18457 183 24X Fiche 50-269,83/04/20,8305130294
- 8305090608 Forwards safety evaluation in support of continued PWR operation w/Dresser primary safety valves re TMI Action Item II D 1 EPRI data on tests of certain models of Dresser safety valves under review on generic basis STOLZ.J F Operating Reactors Branch 4 83/04/27 TUCKER.H B Dute Power Co 2pp 18367 111 24X Fiche 50-269,83/04/27,830506068
- B305040544 Forwards proposed App A to offsite dose calculation manual, supporting radiological effluent Tech Spec per 830209 ltr Submittal constitutes final revised offsite dose calculation manual TUCKER.H B Duke Power Co. 83/04/28 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 ip 18320 083 24% Fiche 50-249,83/04/28,8305040564
- --8305040368 App A to. "Oconee Nuclear Station Site Specific Info "

 * Duke Power Co 83/04/28 32pp 18320 084 24X
 Fiche 50-269.83/04/28.8305040564
- 8305200103 Forwards safety evaluation on standby shutdown facility Design meets requirements, except for process monitoring instruments for source range flux monitoring & steam generator pressure indication STOLZ, JF Operating Reactors Branch 4 83/04/28 TUCKER, H B Dute Power Co 4pp 18576 154 24X Fiche 50-269,83/04/28, 2008500000
- ~-8305200106 Bafety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication of Office of Nuclear Reactor Regulation, Director 83/04/28 17pp 18576 158 24X Fiche 50~269.83/04/28.8305200103
- 8305020455 Generic Ltr 83-19 to all power reactor % testing licensees re new procedures for providing public notice concerning issuance of emends to OLs Svc list encl EISENMUT.D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 30-000.83/05/02/8305020455
- 8305060365 Notification of 830306 mesting w/B&W Dwners Group in Bethssda: MD to discuss core barrel failure at Rencho Seco & Crystal River 3, future plans for resolving problem & Justification for continued operation MINER: 8 Operating Reactors Branch 4 83/05/02 8TDLZ, J Operating Reactors Branch 4 2p 18353 092 24X Fiche 50-000.83/05/02.8303060365
- 8305180034 Forwards Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage EISENHUT,D 0 Division of Licensing 83/05/05 TUCKER,H B Duke Power Co 3pp 18499 245 24X Fiche 50-269,83/05/05,8305180034
- --8305180045 Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-35, respectively,revising Tech Specs to delay certain surveillance requirements until next refueling outage STOLZ,J F Operating Reactors Branch 4 83/05/05 21pp 18499 248 24X Fiche, 50-269,83/05/05,8305180034
- --8305180059 Safety evaluation supporting Amends 121,121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively * Office of Nuclsar Reactor Regulation, Director 83/05/05 5pp 18499 269 24X Fichs 50-269,83/05/05.8305180034

- --8305180068 Notice of issuance & availability of Amends 121,121 \$ |18 to Licenses DPR-38, DPR-47 & DPR-55, respectively STOLZ, J F Operating Reactors Branch 4 83/05/05 2pp 18499 274 24X Fiche 50-269,83/05/05,8305180034
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 30-000, 83/05/09, 8305090659
- B305180151 Forwards request for add1 info re details on void formation during natural circulation cooldown, per 810505 Generic Ltr 81-21 Response dtd 811105 inadequate STQLZ.J F Operating Reactors Branch 4 83/05/09 TUCKER, H B Dute Power Co 4pp 18502 344 24X Fiche 50-269, 83/05/09,
- 8305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCB temp between 250 F & 225 F rather than present 200 F Preparation of proposed Tach Specs re purging in progress TUCKER.H B Duke Power Co 83/03/10 DENIGN.H R Office of Nuclear Reactor Regulation. Director STGLZ.J F Operating Reactors Branch 4 2pp 18437 154 24X Fiche 50-269.83/05/10.8305130025
- 8305230499 Notification of 830609 meeting w/util in Bethesda. MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed SUERMANN.JF Operating Reactors Dranch 4 83/05/16 STOLZ.JF Operating Reactors Branch 4 2pp 18541 274 24X Fiche 50-000.83/05/16.8305230499
- 8305250479 Forwards responses to 8304ii ltr re environ qualification of safety-related electrical equipment Justification for continued operation, per NUREG-0737.TMI Action Item II B 4 provided Response to IE Bulletin 79-018 will be revised TUCKER.H B Duke Power Co 83/057/9 DENTON.H R Office of Nuclear Reactor Regulation. Director 8702.1 J F Licensing Branch 4 27pp 18587 005 24X Fiche 50-269.83/03/19.8305250479
- 8305310081 Bubmits addl info re safety-related environ qualification of electrical equipment, per 10CFR30 49(g) & 1E Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys TUCKER.H B Duke Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18655 123 24X Fiche 50-269:83/05/20.8305310081
- 8305310083 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads Util assessment of asymmetric loads problem acceptable STOLZ, J.F. Operating Reactors Branch 4 83/05/20 TUCKER, H.B. Buke Power Co. 2pp 18662 311 24X Fiche 50~269, 83/05/20, 8305310083
- ~-8305310087 Bafety evaluation accepting util analysis of asymmetric LDCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided * Operating Reactors Branch 4 83/05/20 74pp 18662 313 24X Fiche 50~267,83/05/20,8305310083
- O Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice B3-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl. TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fichs 50-000.83/03/21.8212060385
- 8305270403 Forwards IE Insp Repts 50-269/83-08, 50-270/83-08 & 30-287/83-08 on 830211-0310 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/05 TUCKER, H B Duke Power Co 2pp 18442 321 24X Fiche 50-269, 83/04/05, 8305270403
- --83052704(1 IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted Major areas inspected operations, surveillance testing, maint, event rept review & emergency procedure review 8874NT, J. FALCONER, D. Region 2, Office of Director IONATONIGA J. Division of Project & Resident Programs 83/04/04 12pp 18642 323 24X Fiche 50-269,83/04/05.8305270403
- B305270497 Forwards IE Insp Repts 50-269/83-09.50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/05 TUCKER, H B Duke Power Co 2pp 18646 192 24X Fiche 50-269.83/04/05.8305270497

- --8305270918 IE Insp Repts 50-264/83-09, 90 270/83-09 & 50-287/83-09 on 830308-ii No noncompliance noted Major areas inspected NUREG-0737, Items II B 2, "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys" CCLLINS, I R. BARR, K.P. Region 2, Office of Director 83/04/01 7pp 18646 194 24x Fiche 30-269,83/04/03,8305270497
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator" Svr list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 [E Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 30-000,83/04/22,8303040023
- B303040025 IE Into Notice B3-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co. of New York: Inc 119pp 18381 291 24X Fiche 50-000.83/04/25,8303040029
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list enc) JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Reponse (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice B3-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/04 Consolidated Edison Co of New
 York- Inc 112pp 18382 282 24X Fiche 50-000,83/03/04,8303040030
- 830304003i IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305270326 Forwards IE Insp Repts 50-269/8J-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/06 TUCKER.H B Duke Power Co 2pp 18641 142 24X Fiche 50-269, 83/05/06,8305270326
- --8305270338 IE Insp Repts 50-269/83-13.50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveiltance testing, maint & operations & annual emergency drill BRYANT, J. FALCUNER, D. Region 2. Office of Director BROWNLEC, V. L. Division of Project & Resident Programs 83/05/06 9pp 18641 144 24X Fiche 50-269.83/05/06.8305270326
- 8305270374 Forwards IE Insp Repts 50-269/83-10.50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/06 TUCKER.H B Duke Power Co 2pp 18643 011 24X Ficke 50-267.83/05/06.8305270374
- --83052703B7 IE Insp Repts 50-267/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected amergency preparedness exercise HUFFMAN,0 N Region 2, Office of Director JENNING.G R Division of Emergency Preparedness & Materials Safety 83/05/03 10pp 18643 013 24X Fiche 50-267,82703706,8305270374

- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edisan Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concern re open pressurization line test valve on Unit 3 discussed O'REIBLY, J P Region 2. Office of Director 83/05/11 TUCKER, H 3 Duke Power Co 2pp 18442 280 24% Fiche 50-269, 83/05/11, 8305270425
- --8305270435 IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 Major areas discussed open pressuritation line isolation valve on emergency hatch on 830317 & corrective actions DANCE. H C Division of Project & Resident Programs 83/05/10 5pp 18442 282 24% Fiche 30-269,83/05/11,8305270425
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JURDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 63/05/17 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305310081 Submits add1 info re safety-related environ qualification pf electrical equipment,per 10CFR30 47(g) & IE Bulletin 79-018 Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys TUCKER.H B Duke Power Co 83/05/20 DENTON:H R Dffice of Nuclear Reactor Pagulattion, Director STOLZ.J F Querating Reactors Branch 4 Jpp 18655-123 24X Fiche 50-269.83/05/20.8305310081
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83705/26 Consolidated Edison Co of New
 York, Inc. 114pp 18647-007 24X Fiche 50-000, 83/05/26, 8303040046
- R Pariodic operating reports & related correspondence
- B305170455 Forwards monthly operating repts for Apr 1983 TUCKER.H B Duke Power Co 83/05/13 Director's Office of Inspection and Enforcement Ip 18470 142 24X Fiche 30-269, 83/05/13.8305170455
- --8305170460 Monthly operating repts for Apr 1983
 REAVIS.J A Duke Power Co 83/05/13 16pp 18470 143 24X
 Fiche 30-269,83/05/13.8305170453
- 8 Reportable occurrences, LERS & related correspondence
- 8305110324 Part 21 rapt re Tupe BA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Hestinghouse corrective action includes replacing SCR w/burn-in SCR
 DUVALL.D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.)
 83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fichs 50-000,83/04/27,8305110324.
- 8305110323 Forwards LER 83-006/03L-0 Datailed event analysis encl TUCKER:H B Dute Power Ca 83/04/29 Q'REILLY:J P Region 2, Office of Director 3pp 18406 143 24X Fiche 50-270:83/04/29, 8303110323
- --R305i10335 LER B3-006/03L-0. on B3040t, after pumping down reactor bldg normal sump level valve 2LMD-1 found cycling open & shut since work completion Caused by component malfunction Valve locked shut Valve will be disassembled for repair PETTY.J C Duke Power Co 83/04/27 Region 2, Diffice of Director ip 18406-146 24X Fiche 50-270,83/04/29,8305i10323
- 8305250536 Notifies that noble gas monitor—stack high-range radiation monitor (NUREO-0737.1tem II F I(1)) reported as being aperable in 830318 order.became inoperable on 830026 Caused by moisture contamination New monitors ordered.

 TUCKER.H B Duke Power Co 83/05/19 DENTON.H R Office of Nuclear Resulation, Director STUCZ.J F Operating Reactors Branch 4 2pp 18388 185 24X Fiche.50-269,83/05/19.8305250556

- DOCKET 50-271 VERMONT VANKEE NUCLEAR POWER STATION

 F Security, medical, smergency & fire protection plans
- 8305190310 Forwards IE Bafeguards Insp Rapt 50-271/83-08 on 830404-08 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 83/05/05 MURPHY,W P Vermont Yankae Nuclear Power Corp 3pp 18501 066 24X Fiche 30-271,83/05/05,8305190310
- --8305190311 Notice of violation from insp on 830404-08 Safeguards info deleted tref (OCFR73 21) + Region 1, Office of Director 83/05/05 1p 18501 069 24X Fiche 50-271.83/05/05.8305190310
- --B305190313 IE Safeguards Insp Rept 50-271/B3-08 on B30404-08
 Noncompliance noted vital area barrier degraded w/o
 compensatory measures in effect Bafeguards info deleted
 (ref focfR73 21)
 SMITH.O C . DUNLAP, J M . GODY, A T Region 1, Office of Director
 83/04/22 4pp 18501 070 24X Fiche 50-271,83/05/05.8305190310
- 8305200708 Responds to 830128 ltr re changes identified as Rev 7 to physical security plan Changes do not decrease effectiveness of plan. w/exception of changes on Page 9-2 & Figure 9-1 Bullet-nesistant structure requirements unclear VASSALLO, D B Operating Reactors Branch 2 83/05/09 BINCLAIR, J B. Vermont Yankee Nuclear Power Corp 2pp 18528 355 24X Fiche 50-271, 83/05/09, 8305200708
- 8305110034 Generic Ltr B3-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000, B3/05/11, 8305110034
- 8303240591 Informs that NUREO-0737. Item III A 2 1, "Emergency Preparedness. Upgrade Energency Plans to App E, 10CFR50," completed. Item closed VASBALLO, D B Operating Reactors Branch 2 83/05/18 SINGLAIR, J. B Vermont Yankee Nuclear Power Corp 3pp 18574 211 24X Fiche 50-271, 83/05/18, 8305240591
- 8305310212 Fowards errata to 830128 Rev 7 to security plan Errata withheld (ref 10CFR73 21)
 SINCLAIR.J B Varmont Yankee Nuclear Power Corp 83/05/23
 VASSALLO,D B Operating Reactors Branch 2 1p 18658 134 24X
 Fichs 50-271.83/05/23.8305310212
- P Operating license stage documents & correspondence
- B305020552 Forwards request for additinfo needed to review structural aspects of util plant-unique analysis rept for Mark I containment long-term program Response requested within 45 days.

 VASSALLO, D B Operating Reactors Branch 2 83/04/14. SINCLAIR: J B. Vermont Yankee Nuclear Power Corp Spp 18284 247 24X Fiche 50-271, B3/04/14; B305020552
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to DLs. Svc list encl EISENHUT. D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305170049 Forwards Amend 79 to License DPR-28, safety evaluation & notice of issuance & availability Amend modifies organizational placement of shift technical advisors ROONEY, V L. Operating Reactors Branch 2 83/05/02. SINCLAIR, J. B. Vermont Yankee Nuclear Power Comp. 2pp 18495 185, 24X Fiche 50-271, 83/05/02. 8305170069
- --8305170071 Amend 79 to License DPR-28.modifying organizational placement of shift technical advisors VASSALLO,D D Operating Reactors Branch 2, 83/05/02 7pp 18475.187 24X Ficha: 50-271.83/05/02;8305170049
- --8305170072 Safety evaluation supporting Amend 79 to License DPR-2B.
 # Office of Nuclear Reactor Regulation, Director 83/05/02, 29
 18495-194 24X Fiche: 50-271, 83/05/02, 8305170069
- --8305170075 Notice of issuance & availability of Amend 79 to License DPR-28 VASSALLO,D B Decrating Reactors Branch 2, 83/05/02 2pp 18495-196, 24X Fishe 30-271,83/05/02,8305170069

- 8305230068 Advises that action required by Amend 74 to License DPR-28 & Generic Ltr 83-07 complete, based on util negotiating w/DDE re disposal of high level waste or spent nuclear fuel VASSALLO, D.B. Operating Reactors Branch 2 83/05/05 SINCLAIR, J.B. Varmont Yankee Nuclear Fawer Corp. 2pp. 18543 150 24X Fiche 50-271,83/05/05,8305230068
- 8305230115 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737. Item II K 3 22.
 "Automatic Suitchover af RCIC Suction" I tem resolved VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B Varmont Yankee Nuclear Power Corp 5pp 18546 344 24X Fiche 50-271.83/05/05.8305230115
- 8305230279 Forwards safety evaluation of plant mods & design review of shielding for vital areas per NUREQ-0737. Item II B 2 2 Required mods completed & acceptable VASBALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B Varmont Yankee Nuclear Power Corp App 18543 268 24X Fiche 50-271,83/05/05,8305230279
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fishe 50-000, 83/05/09, 83005090659
- B305130103 Forwards Rev O to "Improved Dynamic Vacuum Breater Valve Response for Vermont Vankee," in response to NRC B30202 Cenemic Ltr B3-08 BINCLAIR.J B Vermont Vankee Nuclear Power Corp B3/05/11 VASBALLO.D.B Operating Reactors Branch 2 ip 18438 061 24X Fiche 30-271.B3/05/11,B305130103
- --8305130104 Rev O to "Improved Dynamic Vacuum Breaker Valve Response for Vermont Yankse " BILANIN,A J Continuum Dynamics, Inc 83/05/ii 20pp 18438 062 24% Fichs 50-271,83/05/i1.8305130103
- 8305230312 Forwards request for addi info neaded to complete review of util 810515 response to NUREG-0737. Item II K 3 28. "Qualification of ADS Accumulators" Response requested within 45 days of receipt of itr VABSALLO.D B Operating Reactors Branch 2 83/03/ii SINGLAIR. J B Vermont Yankes Nuclear Power Corp 3pg 18543 301 24X Fiche 50-271, 83/05/II. 8305230312
- B305200517 Forwards list of additions & deletions of safety-related shock suppressors installed to conform w/acceptance criteria in NUREQ-0661 Proposed change to Tach Specs will be submitted by B30601
 BINCLAIR.J B Vermont Yankee Nuclear Power Corp B3/05/17, VABSALUD, D B Operating Reactors Branch 2 Spp 18516 0B0 24X Fiche: 50-271, 83/05/17, B305200517
- 8305240195 Forwards summary of NUREO-0737 Tach Spec review to determine consistency w/guidance criteria provided in B30110 Omeric Ltr. 83-02.

 BINCLAIR-J B Vermont Yankee Nuclear Power Corp. 83/05/17 VASBALLO, D. B. Operating Reactors Branch 2 3pp. 18548-032 24X Fiche. 50-271, 83/05/17, 8305240195
- B305260296 Forwards safety evaluation of BWR Owners Group generic response to NUREO-0737. Item II K 3 45, "Depressurization M/Other Them Automatic Depressurization Sys " No mod to plant design or operations required Action complete VASSALLD, D B Operating Reactors Brench 2 83/05/18 SINGLAIR, J B Vermont Yanker Nuclear Power Comp 2pp 18629 330 24X Fiche: 50-271, 83/05/18, 8309260296
- 8305250567 Proposed Change 108 to License DPR-28.App A, revising Tech Bpecs re safety-related shock suppressors Rev makes number of snubbers installed concurrent w/completion of Mark I containment long-term program HEIDER.L H Vermont Yankee Nuclear Power Corp 83/05/20 Office of Nuclear Reactor Regulation. Director 2pp 18388 216 24X Fiche: 50-271.83/05/20,8305280569
- --8305250574 Proposed Tech Specs re safety-related shock suppressors, making number of snubbers installed concurrent w/completion of Mark I containment long-term program + Vermont Yankes Nuclear Power Corp 83/05/20 App 18588 218 24X Ficher 50-271,83/05/20,8305250569
- 8305260114 Informs that response to NUREO-0737, Item II K 3.13 re RGIG restart complete for facility, based on 830415 commitment to follow GE Owners Group conceptual design VABSALLO, D B Operating Reactors Branch 2 83/05/20 SINGLAIR, J, B Vermont Yankee Nuclear Power Corp 2pp 18649.065, 24X Fiche: 50-271,83/05/20,8305260114.

- B305270141 Requests exemption from schedular requirements of equipment qualification final rule (10CFR50 48(d)) Final submittal expected by B30610 Delay due to late roceipt of Franklin Research Ctr rept
 BINCLAIR.J B Vermont Yankee Nuclear Power Corp B3/05/20
 EISENHUT.D 9 Division of Licensing 2pp 18638 206 24X
 Fiche: 50-271,83/05/20,8305270141
- Q Inspection reports. IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction" Svc list encl
 TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000.83/03/21.8212040385
- B305120488 Add1 response to FOIA request for six categories of documents Forwards App A documents FELTON,J M Division of Rules and Records 83/03/25 HIATT,S L Ohio Citizens for Responsible Energy 2pp 18457 211 24X Fiche 50-271, 83/03/25, 8305120488
- --8207300178 Details of IE Investigation Rept 50-271/82-12 on 820606-10 No noncompliance noted Major areas investigated licenses actions in withholding inforce 820424 loss of feedwater transient Proprietary details deleted (ref 100FR2 790) * Region 1. Office of Director 82/07/20 38pp 18457 217 24X Fiche 50-271,83/03/25.83053120488
- --8305130223 Forwards chronology of Region I actions re 820424 loss of feedwater event, insp investigation; documentations, meetings w/state & liconsee officials, evaluations of appropriate enforcement action & processing civil penalty HOLODY, D J Region i, Office of Director 82/10/13 AXELRAD, J Director's Office of Pispection and Enforcement 3pp 18457 262. 24X Fishe 50-271,83/03/25,8305120488
- B30304002i IE Info Notice B3-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,83030400R1
- 83D3040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list enc!
 JORDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list enc! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000.83/04/25,8303040025
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3704/28 Consolidated Edison Co
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.
- B30304002B IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co. of New York, Inc. 122pp (8441 170 24X Fiche 30-000,83/05/03,830304002B
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp (8382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for Quaeral Emergencies" Svc list and, JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305190187 Forwards IE Insp Rept 50-271/83-06 on 830329-0401. No noncompliance noted MARTIN. T. T. Division of Engineering & Technical Programs 83/05/04 MARPHY. W. P. Vermont Yankse Nuclear Power Corp. 2pp. 18502. 260 24X Fiche 50-271, 83/05/04. 8305190187

- --8305190191 IE Insp Rept 50-271/83-06 on 830329-0401 No noncompliance noted Major areas inspected radiation protection program advanced planning & preparation, training, contaminated hydrolaser & following on previous insp findings (CLEMONS, P. SHANBAKY, M. Region I. Office of Director 83/04/25, Spp. 18502 262 24x Fiche 50-271.83/05/04.8305190187
- 8305090184 EN-83-031 on 830510 notice of violation & proposed imposition of civil penalties in amount of \$40,000 will be issued to util Action based on Tech Opec limiting condition for operation violation re-secondary containment integrity BARBER, 6, AXELARD, J Director's Office, Office of Inspection and Enforcement 83/05/05 ip 18344-001 24X Fiche 50-271,83/05/05. 8305090184
- 8305190310 Forwards IE Safeguards Insp Rept 50-271/83-08 on 830404-08 SOSITION OF Orders I Service of Inspect SUPPLIES OF SUPPLIES OF BUSINESS OF BU
- --8305190311 Notice of violation from insp on 830404-08 Safeguards info # Region 1. Office of Director 83/05/05 ip 18901 069 24X Fiche 50-271, 83/05/05, 8305190310
- ~-8305190313 IE Safeguards Insp Rept 30-271/83-08 on 830404-08
 Noncompliance noted vital area barrier degraded w/o
 compensatory measures in effect Safeguards info deleted
 (ref 10CFR73 21)
 SMITH, 0 C , DUNLAP, J K , GDDY. A T Region 1, Office of Director
 83/04/22 4pp 18501 070 24X Fiche 50-271/83/05/05/8305190310
- 8305230253 Advises that responsibility for evaluating util proposed actions in response to IE Bulletin 83-02 re recirculation sys pips cracks & restart approval transferred to Div of VASSALLO.D B Operating Reactors Branch 2 83/05/05 Vermont Yankee Nuclear Power Corp 2pp 18543 249 Fiche 50-271.83/05/05.8305230253 83/05/05 SINCLAIR, J B 8543 249 24X
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack 303040033 IE Info Notice 83-27, "Fuel Behaving Course by Behaving Course by Behaving Course by Behaving Course by Benaving Company Course by Cours
- B305250572 Discusses IE insp on B30321-25 & forwards notice of violation & proposed imposition of civil penalty ALLANJ H Region I, Office of Director 83/05/10 MURPHY, R P Vermont Yankee Nurlear Pawer Corp. 3pp 18594 347 24X Fichs 30-271, B3/05/10, B305250572
- --8305250577 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted on 830321.secondary containment integrity not maintained when irradiated fuel rods & bundles moved within fuel pool
 ALLAN. M Region I. Office of Director 83/05/10 4pp
 18594 350 24X Ficha 50-271,83/05/10.8305250572
- 8303040034 [E Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83703/11 Consolidated Edison Co of New York, Inc 114pp 18324 CO3 24x Fiche 50-000,83705/11,8303040034
- 8305250447 Forwards IE Mgt Meeting Rept 50-271/83-10 on 830417 to discuss intergranular stress corresion cracking of recirculation sys STAROSTECKI.R Division of Project & Resident Programs 83/05/ MURPHY W P Vermont Yankee Nuclear Power Core 2pp 18385 204 24% Fiche 50-271,83/05/11,8305250447 83/05/11
- --8305250450 IE Mgt Meeting Rept 50-271/83-10 on 830419 Major areas discussed intergranular stress corrosion cracking problems & response to IE Gulletin 83-02 HOLDEN.C F. GALLO.R M. Region I. Office of Director 83/04/2 4pp 18385 206 24X Ficher 50-271.83/05/11.8305250447
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Byc list encl JORDAN, E L SVC 11st energy JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc. 114pp 18697 009 24x Fiche 50-000,83/05/19,8303040040
- 8305270045 Discusses review of relief requests from inservice insprequirements per 10CFR50 55a(g) Relief granted for requirements impractical to implement SER technical evaluation te FR notice of granting of relief encl VASSALLO.D B Operating Reactors Branch 2 83/05/19 SINCLAIR Vermont Yankee Nuclear Fower Corp 3pp 18661 171 24X Fische 50-271.89/05/19.8105270045 SINCLAIR, J B Fiche 50-271,83/05/19,8305270045

- --8305270050 Safety evaluation granting in part & denying in part, requests for relief from inservice insp requirements per 10CFR50 55a(g) R3/05/19
- --8305270032 "VT Yankee Nuclear Power Station Inservice Insp Program," DUGATIONS TV. YABERS NUCLEAR FOWER STATION INSERVICE INSP. technical evaluation rept. 8 Ecience Applications. Inc. NRC-03-82-096 186-028-24 82/09/02 NRC - No Detailed Affiliation Given 62pp 18661 186 24X Fichs 30-271,83/05/19,8305270045
- --9305270055 Notice of granting of relief from ASME Code Section XI inservice insp requirements VASSALLO, D D Operating Reactors Branch 2 93/05/19 2pp 18661 249 24X Fiche 50-271, 83/05/19, 8305270045
- 8305250480 Clarifies 830324 response to util 821203 ltr ra IE Insp Rept 30-271/82-13.radirecting attention to requirement to maintain related records of maint performed by licensee on partage at licensee site as noted in IE Info Notice 83-10 NARTIN-T Division of Engineering & Technical Programs 03/05 MURPHY,W P Vermont Yankes Nuclear Power Corp Ip 18588 253 24X Fishe 50-271.83/05/20.8305250480 R3/05/20
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of 303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dif "Svc list encl JORAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18647-007 24X Fiche 30-000.83/05/26.8303040046
- R Periodic operating reports & related correspondence
- 8305170006 Forwards monthly operating rept for Apr 1983 MURPHY, H P. Vermont Yankse Nuclear Power Corp 93/0 of Resource Management, Director (p 18466-142 2 Fiche 30-271,83/05/12.8305170006 83/05/12
- --8305170007 Monthly operating rapt for Apr 1983 BURGER:F J Vermont Yankee Nuclear Power Corp 18466 143 24X Fiche 50-271, 83/05/12, 8305170006 83/05/09 700
- 8 Reportable occurrences, LERs & related correspondence
- 8305050341 Forwards AEOD/E305, "Inoperable Hotor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR.RES & IE BROHN.E J., ASHE,F S Reactor Operations Analysis Brench 83/04/13 SEYPRIT.K V Reactor Operations Analysis Branch 2pp 18352 051 24X Fiche 50-000.83/04/13,8305050341
- --8305050353 "Inoperable Motor Operated Valve Assemblies Dus to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment," AEDD engineering evaluation rept BROWNE J. ASHELFS Director's Office 83/04/13, 7pp 18352 053 24X Fiche 50-000,83/04/13,8305050341
- 8305050101 Forwards LER 83-011/03L-0 PELLETIER. J P Vermont Yankee Nuclear Power Corp B3/04/ ALLAN. J H Region 1. Office of Director 1p 18341:336 Fiche 30-271:83/04/25.8309050101 R3/04/25.
- --8305050108 LER 83-011/03L-O on 830325 during visual insp.shock suppressor M8-6 on main steam A piping found w/no visible fluid in sight glass & failed to lock up Caused by damaged lenztee Snubber cleahed & rebuilt PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/04/25. Region I. Office of Director ip 18341 337 24X Region 1, Office of Director 10 18341 337 Fichs. 50-271,83/04/25,8305050101
- V Operator Examinations
- 8305240343 Hithdraws commitment re NUREO-0737. Item I A I 3, "Licensing Exam Criteria" Recommendations to delete requirement for use of simulator exam as part of operator license exam program approved per 821012 Generic Ltr 82-18 & BECY 82-232 HEIDER.L H Vermont Yankee Nuclear Power Corp. 83/05/19 VASSALLO.D B Operating Reactors Branch 2 2pp 18572 357 24X Fiche 30-271.83/05/19.8305240343
- DOCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8303130307 Releases public version of revised emergency plan FELTON,J M Division of Rules and Records 83/05/02 Docum Management Branch ip 18456 335 24X Fiche 50-272,83/05/02, 8303130307 Mocument

- --8305130308 Forwards public version of Rev 2 to emergency plan Receipt form enci e Jersey Central Pawer & Light Co 83/04/04 VARGA: S A Operating Reactors Branch 1 1p 18456-336 24X Fiche 50-272, 83705/02, 8305130307
- --8305130309 Public version of Rev 2 to emergency plan BURGE.C A , MIDURA.K J Jersey Central Power & Light Co 83/04/04 188pp 18456 337 24X Fiche 50-272,83/05/02, 8305130307
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EIBENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.8305110034
- 8305270043 Ack receipt of 830905 itr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation resecutity access control denied STARGSTECKI, R Division of Project & Resident Programs 83/05/23 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 18638 345 24X Fiche 50-272,83/05/23,8305270043
- --8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation enc1 Encls withheld (ref locfR73 21) UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/05/05 Region 1, Office of Director 3pp 18439 347 24X Fiche 50-272,83/05/23,8305270043

O Adjudicatory correspondence

- 8305170493 Order extending time until 830527 for Commission to act to review Director's Decision DD-83-4 CHILK, 8 J Office of the Secretary of the Commission 83/05/13 Commissioners ip 18470 024 24% Fiche 50-272.83/05/13, 8305170493
- 8305310008 Order extending time until 830601 for Commission to act to review Director's Decision DD-83-6
 CHILK, B J Office of the Secretary of the Commission 83/05/27
 Commissioners ip 18653 230 24X Fichs 50-272,83/05/27,8305310008

I Financial information

- 8305200067 Forwards Annual Financial Repts for 1982 FRYLING, R Public Bervice Electric & Gas Co of New Jersey 83/05/17. Office of Nuclear Reactor Regulation, Director 19 18516 198 24X Fiche 50-000.83/05/17,8305200067
- J Insurance & indemnity information
- 8305160157 Forwards Endorsements 58 & 45 to NELIA Policy NF-230 & MAELU Policy NF-90, respectively OOLDEN, M P Marsh & McLennan, Inc. 83/05/02 SALTZMAN, J Assistant Director for State & Licensee Relations Spp. 18445 089 24X Fiche 50-272,83/05/02,8303160157
- P Operating license stage documents & correspondence
- 8305050013 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys (TMI Action Item II F 2)
 Hestinghouse reactor vessel level instrumentation sys.
 described in 801231,810206 & 1207 submittals, utilized
 LIDEN.E.A Public Bervice Electric & Oas Co of New Jersey
 83/04/22 VARQA,5 A Operating Reactors Branch i 27pp
 18339.028 24X Fiche 50-272,83/04/22,8305050013
- B305020186 Clarifies B30422 response to NRC B30420 ltr. Item 2.11 D 10CFR50 54(f), we Westinghouse treatment of undervoltage trip attachment delivered disassembled UDERITZ.R A Public Bervice Electric & Gas Co of New Jersey B3/04/27 EISENHUT.D 9. Division of Licensing 2pp 18278 192 24X Fiche 50-272,83/04/27,8305020186
- 8305110134 Forwards supplementary response to 820223 6-month response to 9eneric Ltr 81-07. NUREG-0612. "Control of Heavy Loads." to confirm & clarify items discussed in 820804 telcon LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/04/27 VARGA.S.A Operating Reactors Branch 1 Bpp 18399 007 24X Fiche 50-272.83/04/27,8305110154

- --8303110156 PSE-0108. "Maint Procedures "
 # Public Service Electric & Gas Co of New Jersey 83/04/27
 1.317pp 18399 101 24x Fiche 50-272.83/04/27.8305110154
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuence of amends to OLs Svc list enct EISENHUT.D O Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- B305090497 Application to amend Licenses DPR-70 & DPR-75 revising safety Tech Specs by raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1 LIDEM E A Public Service Electric & Oas Co. of New Jersey B3/05/04 VARGA,S A Operating Reactors Branch 1 2pp. 18360-252-24X Fiche 50-272,83/05/04.8305090457
- ---8305090459 Proposed changes to safety Tech Specs, raising trip setpoint & allowable value of steam generator water level low-low reactor brip in Table 2 2-1

 * Public Service Electric 5 Gas Co of New Jersey 83/05/04
 4pp 18360 254 24X Fiche 50-272/83/05/04/8305090457
- 8303170079 Forwards Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of Issuance & availability Amends raise trip setpoint & allowable value of steam generator water level low-low seator trip FISCHER.D Operating Reactors Branch i 83/05/05 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 3pp 18495 211 24X Fiche 50-272,63/05/05,8305170079
- --8305170084 Amends 53 & 21 to License DPR-70 & DPR-75, respectively, raising trip setpoint & allowable value of steam generator water level low-low reactor trip VAROA.S A Operating Reactors Branch 1 83/05/05 App 18495 214 24X Fiche 50-272,83/05/05,8305170079
- --B3051700B7 Safety evaluation supporting Amends 53 & 21 to Licenses DPR-70 & DPR-75 respectively + Office of Nuclear Reactor Regulation, Director B3/05/05 2pp 18495 222 24X Fiche 50-272.83/05/05.8305170079
- --B305170090 Notice of issuance & availability of Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively VAROA,S A Operating Reactors Branch 1 83/09/05 2pp 18495 224 24X Fiche 50-272,83/05/05,8305170079
- B305170117 Forwards Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amends change partial power multiplier from 0 2 to 0 3 FIECHER, D. Operating Reactors Branch 1 83/05/05 UDERITZ, R.A. Public Service Electric & Bas Co. of Naw Jersey 3pp JB496 00: 24X Fiche 50-272, B3/05/05, B305170117
- --8305;70119 Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively, changing partial power multiplier from 0 2 to 0 3 VARGA.S A Operating Reactors Branch 1 83/05/05 13pp 18496 004 24X Fichs 50-272,83/05/05,8305170117
- --8305170124 Safety evaluation supporting Amends 52 & 20 to Licenses DPR-70 & BPR-73, respectively * Office of Nuclear Reactor Regulation, Director 83/05/05 & 2pp 18476 O17. 24X Fiche 80-272,83/05/05,8305170117
- --8305170127 Notice of issuance & availability of Amends 52 & 20 to Licenses DPR-70 & DPR-75; respectively VAROA.8 A Dereting Reactors Branch 1 83/05/05 2pp 18496 019 24X Fiche 50-272,83/05/05,8305170117
- 8305090659 Openetic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305170328 Forwards schedule for qualification or replacement of unqualified equipment for Categories I B.II A.II C & IV identified in BER on environ qualification of safety-related electrical equipment
 LIDEN.E A Public Service Electric & Gas Co of New Jersey B3/05/07 VARGA: A Operating Reactors Branch i 16pp 18465 i53 24X Fiche 50-272,83/05/09,8305170328
- 8305230504 Forwards affidavit & fee for review of 830504 application to amend Licenses DPR-70 & DPR-75
 LIDEN, E A Public Service Electric & Gas Co of New Jersey
 83/05/11 VARQA, S A Operating Reactors Granch 1 2pp 18537 170
 24X Fiche 50-272, 83/05/11, 8305230504

- B305310221 Requests assessment on operability of 10-inch pressure/ vacuum relief valves used for purge or vent of containments to demonstrate that valves will operate in event of DBA-LDCA info requested within 15 days VARGA, S.A. Operating Reactors Branch 1 B3/03/19 UDERITZ.R.A. Public Service Electric & Oas Co. of New Jersey 7pp 18662 26: 24X Fsche 50-272, B3/05/19, 8305310221
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safequards & Inspection Programs (Post
 - TAYLOR, J M Division of Safaguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212050385
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83704725 Consolidated Edison Co. of New York Inc 119pp 18381 291 24X Fiche 30-000,83704725,8303040025
- 8305020258 Ack receipt of 830407 itr informing NRC of steps taken to correct violation noted in IE insp Repts 50-272/83-09 & 50-31/83-08 MARTIN.T T Division of Engineering & Technical Programs 83/04/26 UDERITI.R A Public Service Electric & Oas Co of New Jersey 1p. 18277 268 24% Fiche 50-272,83/04/26,8305020258
- --B305020267 Responds to NRC B30310 itr re violation noted in IE Insp. Repts 50-272/83-09 & 50-311/83-08 Corrective actions. Procedure RP7 004 revised to incorporate more extensive bracing for future low-specific activity box shipments. UDERITZ.R A Public Service Electric & Qas Co. of New Jersey. B3/04/07 MARTIN, T.T. Division of Engineering & Technical Programs. 2pp. 18277 269 24X Fiche 50-272.83/04/26.8305020258
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047, 24X Fiche 50-000.83/04/28.8301040026
- B303040027 IE Info Notice B3-25, "Standby Gas Treatment Sys Heater High Tamp Trip Betpoint Adjustment " Syc list and I JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York Inc 118pp 18382 165 24X Fiche 30-000.83/04/28.8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 1844(170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Flant Equipment " Svc 1ist enc! JORDANJE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 1120p 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl UORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc. 119pp. 18441 001 24X Fichs 50-000, 83/05/04/8303040031.
- 8305090397 EN-83-032 on 830505, notice of violation & proposed imposition of civil penalties in amount of \$850,000 to be issued Action based on violation of Tech Spec requirements re reactor trip breater failure XLINGLER.0 AXELRAD.7 Director's Office. Office of Inspection and Enforcement 83/05/05 ip 18363 359 24X Fiche 50-272,83/05/05,8305090397.

- B303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation" Svc list and I JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York
- 8305190163 Forwards IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/05/06 UDERITY.R A Public Service Ejectric & Oas Co of New Jersey 2pp 18502 240 24X Fiche 50-272.83/05/06.8305190163
- --8305190169 Notice of violation from insp on 830321-25 # Region 1, Office of Director 83/05/06 lp 18502 242 24X Fiche 50-272.83/05/06.8305190163
- --8305170174 IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25.
 Noncompliance noted failure to adhere to radiation protection procedures & failure to use suitable measurements of airborne radicactivity.ger 10CFR20 103(a)(3)
 NIHITZ.R L , SHANBAKY.M Region 1, Office of Director 83/05/06
 13pp 18502 243 24% Fiche 50-272,83/05/06,8305190163
- 8305160085 Forwards response to NRC 830325 itr re violations noted in IE Insp Repts 50-272/82-33 & 50-31/82-31 on 820405-1016 Corrective actions operational test group established to verify testing requirements Civil penalty fee encl UDERITZ, R A Public Service Electric & Oas Co of New Jersey. 83/05/09, DEYOUNG, R C Director's Office: Office of Inspection and Enforcement 70p 18451 027 24X Fiche 30-272.83/05/09.8305160085
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Syc list encl UDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program."
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040.
- 8303240285 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10

 MARTIN, T T Division of Engineering & Technical Programs. 83/03/19. UDERITI.R A Public Bervice Electric & Oas Co of New Jersey 2pp 18548 107 24% Fiche. 50-272, 83/05/19, 8305240285
- --8305240291 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10 Corrective actions all badges improperly issued destroyed individual responsible no longer in security mgt position UDERITZ.R A Public Service Electric & Qas Co of New Jarsey. 83/04/25 Region 1. Office of Director ip 18548 107 24X Fiche 50-272,83/05/19,8305240285
- 8305270043 Atk receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation resecurity access control denied STAROSTECKI, R Division of Project & Resident Programs 83/05/23 UDERITE, R A Public Service Electric & Cas Co of New Jersey 2pp 18638.345 24X Fiche: 50-272,83/05/23,8305270043
- --8305270053 Responds to NRC 830405 itr re-violations noted in IE Insp. Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl Encls withheld (ref 10CFR73, 21)

 UDERITZ.R A Public Service Electric & Cas Co of New Jersey 83/05/05 Region i. Office of Director 3pp 18638 347 24X Fiche 50-272,83/05/23,8305270043
- 8305270164 Ack receipt of 830509 ltr forwarding payment of proposed civil penalty Response to notice of violation & proposed imposition of civil penalty will be evaluated & corrective actions examined during future insp AXELRAD. J. A. Enforcement Staff 83/05/25 UDERITZ, R A Public Service Electric & Oss Co of New Jersey 2pp 18638 064 24X Fiche: 50-272,83/05/25,8305270164.
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp, 18647 007 24X Fichs 50-000;83/05/26;8303040046.

- R Periodic operating reports & related correspondence
- 8305170018 Forwards monthly operating rept for Apr 1783 ZUPKO, J M Public Service Electric & Oas Co of New Jersey 83/05/10 Director's Office, Office of Inspection and Enforcement ip 18466 163 24X Fiche 50-272,83/05/10,8305170018
- --8305170021 Monthly operating rept for Apr 1983 MILLER, L K Public Service Electric & Oas Co of New Jersey 83/05/10 15pp 18466 164 24X Fiche 50-272,83/05/10.8305170018
- 8 Reportable occurrences, LERs & related correspondence
- 8305200497 PND-I-83-049 all licensee commitments required for restart completed Actions to assess & mitigate svc water biofouling in support of plant heatup anticipated to occur on 830518 COMPleted NORRHOLM, L HOLM.L. COLLING.8 Region 1. Office of Director 18514 032 24x Fiche 50-272,82/05/17,8305200497 83/05/17
- 8305020150 Forwards 830414 & 26 ltrs documenting review of corrective action program re 830222 & 25 reactor trip breaker failures Ltre previously transmitted at 830414 & 26 meetings UDERITZ.R A Public Bervice Electric & Gas Co of New Jersey 83704/27 EISENHUT,D 9 Division of Licensing 2pp 18277 278 24X Fichs 50-272,83/04/27,8305020150
- --8305020160 "Preliminary Review of PSE&O Co Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station Unit 1 "
 - Basic Energy Technology Associates 83/04/14 6pp 18277 280 24X Fiche 50-272,83/04/27,8305020150
- 8305040630 Notifies of CRGR Meeting 36 on 830429 to discuss findings of Salam Reneric Implications Task Force
 of Salam Reneric Implications Task Force
 BTELLO-V Committee to Review Generic Requirements 83/04/27
 EISENHUT, D Q Office of Nuclear Reactor Regulation, Director
 JORDAN: F. L. Director's Office, Office of Inspection and Enforcement
 CUNNINGHAM, R. E. Office of Nuclear Material Safety &
 Bafeguards, Director 2pp 19396-306 24X Fiche 30-272,83/04/27,
 8305040630
- 8305030450 PNO-I-83-041 on 830425, while closing reactor trip breaker iB to test newly installed reactor manual trip switches, breaker would not latch in closed position Caused by unattached coil spring at latch mechanism end LAZARUS, W. KEIMIO, R. Region 1, Office of Director 83/04/28 ip 18306 247 24X Fiche 50-272,83/04/28,8305030450
- 8305040262 Forwards summary listing short- & long-term actions & completion schedules re 830222 & 25 reactor trip breaker events. Corrective action program will also be applied to Unit 2 currently scheduled to return to svc in June 1983 UDERITZ: RA Public Service Electric & Oas Co of New Jersey 83/04/28 EISENHUT. D 0 Division of Licensing lipp 18323 249 24% Fiche 50-272,83/04/28,8305040262
- 8303060476 Forwards LER 83-009/79X-O Detailed event analysis encl ZUPKO J M Public Bervice Electric & Cas Co of New Jersey B3/04/28 ALLAN.J Region I, Office of Director App 18348 24X Fiche 50-272,83/04/28.8303060476 1834B 1A1
- ~-8305060482 LER 83-009/99X-0 on 830130, during routine plant cooldown, inadvertent safety injection occurred due to low pressure pressure Caused by operator overlooking decreasing pressure All safety-related equipment functioned as designed FRAHM,R Public Service Electric & Gas Co of New Jersey 83/04/20. Region 1, Office of Director ip 18348 165 24X Fiche 50-272,83/04/28,8305060476
- B303090244 Responds to B30327 memo re mgt & technical issues of ATW9 events Issues to be addressed in NUREO-1000. "Generic Implications of ATW9 Events at Balem Nuclear Power Plant "RHR capability addressed in Unrasolved Safety Issue A-45 DENTON-H R. Office of Nuclear Reactor Regulation. Director 83/04/27 EPIER.E P Epler. E P 8pp 18381 084 24X Fiche: 50-272,83/04/29,8303090244.
- --8305090255 Requests comments he need for effective leadership in light of ATW8 event, failure of RHR eys & small break mitigation & failure of institutions to employ best available technology EPLER, E P Epler, E.P 83/03/27 PALLADING.N J Commissioners EBERBOLE, J C ACRB Advisory Committee on Reactor Safeguards. CULLER, F L Electric Power Research Institute 10pp 18381 09%. 24X Fiche 50-272,83/04/29,8305090244

- 8305170064 Responds to 830412 petition & 0418 amend, requesting that NRC order PSE&O to show cause why facility restant should not be restrained Petition denied based on encl Director's DENTON.H R Office of Nuclear Reactor Regulation, Dire 83/04/29 RODRIGUEZ.J H New Jersey, State of Spp 24X Fiche 50-272.83/04/29.8305170064 18494 184
- --B3051700B5 Director's Decision DD 83-6.denying Public Advocate of NJ 830412 petition & 041B amend requesting issuance of order to show cause why facility should not be restrained from restart until listed actions taken DENTON-HR Office of Nuclear Reactor Regulation, Director Office of Nuclear Reactor Regulation, Director pp 18494 187 24X Fiche 50-272,83/04/29,8305170064 äрр 83/04/29
- --BJ05170095 Safety evaluation re restart of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue * Office of Nuclear Reactor Regulation, Director BJ/04/28 45pp 18474 195 24X Fiche 50-272,83/04/29,8305170064
- --9305170106 "Evaluation of Failure to Trip of Reactor Trip Circuit
 Breakers on 830222 & 25.5alem Nuclear Generating Station
 Unit i." interim technical evaluation rept
 TDMAN.0 J Franklin Institute/Franklin Research Center
 NRC-03-81-130 83/04/07 SHEMANSKI.P NRC No Detailed
 Affiliation Given 71pp 18494 241 24X Fiche 50-272.83/04/29,
- --8305170110 Notice of issuance of Director's Decision DD 83-6 denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart CASE,E G Office of Nuclear Reactor Regulation, Director 83/04/27 2pp 18494 336 24X Fiche 50-272,83/04/29,8305170064
- 8305170674 DENERIC IMPLICATIONS OF ATMS EVENTS AT THE BALEM NUCLEAR POWER PLANT Contents Invitations UP AIMS EVENTS AT THE BALEM NUCLEAR POWER PLANT Contents Invitations # Office of Nuclear Reactor Regulation, Director NUREG-1000 Vol 83/04/30 147pp Available at NRC \$6.50 18481 183 24X Fiche 50-272.83/04/30.8305170674
- BJ05170232 Informs Commission of findings of Salem ATWS generic implications task force re overall mgt capability & performance & reactor trip sys reliability BJRCKS W J Office of the Executive Director for Operations SECY-83-158 83/05/02 157pp 18476 184 24X Fiche 50-272,83/05/02,8305170232
- 8305100004 PNS-I-83~011 on 830504, socurity officer received bomb threat on inside plant telephone line from male caller Bearch initiated No bomb found Call considered hoaz MCKEGUN, GODY, JOYNER Region 1, Office of Director 83/05/04 18377-251 24X Fiche 50-272,83/05/04.8305100004 83/05/04
- B305100258 PNO-I~B3-046 on B30428, diesel generator iC tripped off bus 405100238 PROFINES-046 on BSO0928; diesel generator iC trippec off buduring in sec water sys during i h test Caused by biofouling in sec water sys Licensee plans comprehensive program of sec water sys chlorination & insp to evaluate extent of biofouling NORRHOLM, L. TRIPPL L. KEIMIOR, Region I. Office of Director 83/05/04 2pp 18373 317 24% Fiche 50-272.83/05/04.8305100258
- 8305120434 PNS-1-83-013 on 830502. Lower Alloways Creek, NJ, police dept informed licenses of planned peaceful domonstration to protest facility restart scheduled for 830508 No press release planned
 MCKEGWN.L . 90DY.A T . JGYNER.J Region 1. Office of Director
 83/05/06 ip 18431 131 24X Fiche 50-272,83/05/06.8305120434
- B305180B30 Forwards B30506 order confirming commitment to implement #/or maintain items specified in B3042B itr re reactor trip breaker failures EISENHUT.D G Division of Licensing B3/05/06 UDERITZ, R A PUBLIC Bervice Electric & Gas Co of New Jersey 3pp 18506 001 24X Fiche 50-272,83/03/06,8305180830
- --8305180836 Order confirming licenses commitments to implement &/or maintain items specified in 830428 ltr re reactor trip breaker failures; effective immediately EISENIUT.D G Division of Licensing 83/05/06 Public Service Electric & Gas Co of New Jersey 4pp 18306 004 24X Fichm 50-272,83/05/06.8305180830
- 8305200394 Forwards supplemental LER 82-078/01X-1 Detailed event analysis encl
 ZUPRO, J M Public Service Electric & Qas Co of New Jersey
 83/05/09 ALLAN, J Region 1. Office of Director Spp 18518 110
 24X Fiche 50-272, 83/05/09, 8305200394

- --B303200397 Supplemental LER B2-078/01X-1 on B21017, during routine containment purge, abnormal decrease of radicactivity levels observed as indicated by containment plant vent monitor Caused by sample line left capped FRAHM. R Public Service Electric & Gas Co of New Jersey 83/05/04 Region 1, Office of Director ip 18518 115 24X Fiche 30-272,83/05/09,8305200394
- 8305190336 PND-I-83-050 on 830513,100 gallons of contaminated water discharged from auxiliary bldg sump onto ground between auxiliary & fuel handling bldgs Cause under investigation No offsite release occurred Contaminated soil removed BUMMERS,R - TRIPP,L Region 1, Office of Director 83/05/13 1, 18500 233 24X Fichs 50-272.83/05/13.8305190336
- 8303250238 PND-I-83-052 on 830520.plant went critical for first time since 830229 Reactor startup & required reactor trip breaker testing completed within 24 h Power ascension to 1007 expected over next several days NORRHOLM, L. JACOBS. R. GREENMAN, E. Region 1. Office of Director 83/05/23 ip 18592 358 24% Fiche 50-272,83/05/23.8305250238
- T Hearing transcripts on non-antitrust matters
- 8303020529 Unofficial transcript of Commission 830426 public meeting re-possible vote on restart in Washington. CC Pp 1-107 # Commissioners 83/04/26 127pp 18284 075 24X Fiche 30-272.83/04/26.8305020529
- 8303170087 Transcript of Commission 830512 meeting in Washington.DC to discust evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation encl * Commissioners 83705/12 Bipp 18495 226 24X Fiche 50-272.83/05/12,8305170089
- 8305830130 Transcript of Commission 830518 public meeting in Washington, DC re evaluation of implications of facility event (Part I) Pp I-62 Supporting documentation encl a Commissioners 83/05/18 97pp 18577 i10 24X Fiche 50-278,63/05/18,8305230130
- DOCKET 30-275 DIAGLO CANYON NUCLEAR FOHER PLANT, UNIT & F Security, medical, emergency & fire protection plans
- B305030160 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/22 Document Management Branch ip 18310 001 24X Fichs 50-275.83/04/22.8303030180
- --8309030188 Forwards public version of Rev O to Emergency Plan Implementing Procedures EP-RB-12. "Mid & High-Range Vent Montcors" & EP G-3. "Notification of Offsite Organizations" CRANE-P A Pacific Gas & Electric Co 83/04/06 MARTIN.J B Region 5. Office of Director Rep 18310 002 24X Fiche 50-275,83/04/22.8309030180
- ~-8303030193 Public version of Rev O to Emergency Plan Implementing Procedures EP-RB-12. "Mid & Migh-Range Vent Monitors" & EP 0-3. "Notification of Offsite Organizations " * Pacific Oas & Electric Co 83/04/06 19pg 18310 004 24X fichs 50-275,83/04/22,8305030180
- 8303040320 Forwards Amend Request 83-03 to License DPR-76 changing containment isolation valves organization & quantities of fire detection instruments
 CRANE.P A Pacific Gas & Electric Co 83/05/02 DENTON.H R
 Diffice of Nuclear Reactor Regulation, Director ip 18319 331 24X
 Fiche 50-275.83/05/02.8305040320
- --8305040328 Amend Request 83-03 to License DPR-76, changing containment isolation valve list-organization & quantities of fire detection instruments SCHUYLER, J D. CRANE. P A Pacific Gas & Electric Co 83/05/02 2pp 18319 332 24X Fiche 50-275.83/05/02.8305040320
- --8305040473 Proposed Tech Specs re containment isotation valves. administrative controls & fire detection instrumentation * Pacific Qas & Electric Co 83/05/02 19pp 18319 334 24X Fiche 50-275,83/05/02.8305040320
- 8305110034 Generic Ltr 83-21 to all licensues of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D Q. Division of Licensing 83/05/15 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche 50-000.83/05/11,8305110034

- 8305190157 Notifies that rept documenting previous exemptions & Justifying differences between existing or proposed fire protection features & features specified in Sections III G, III J.L. & D of App R will be submitted by 830610 CRANE.P A Pacific Qas & Electric Co 83/05/13 EISENHUT, D. O Division of Licensing ip 18502 256 24X Fiche 50-275,83/05/13,8305190157
- B305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKB.W J Office of the Executive Director for Operations B3/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24) Fich
- 8305310130 Forwards application for amend to License DPR-76, changing portions of Tech Specs 3 7.9 1 re fire suppression water sys & 4 7 9 4 re Halon sys CRANE, P A Pacific Gas & Electric Co B3/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18655 028 24% Ficha 50-275, 83/05/23, 8305310130
- --8305310135 Application for amend to License DPR-76, changing portions of Tech Specs 3 7 9 1 & 4 7 7 4 increasing high pressure pump capacity to 2.250 gpm & eliminating need for replacing Halon sys w/5-yr syc life remaining SCHUYLER, J 0 , CRANE, P A Pacific Gas & Electric Co 83/05/23 2pp 18655 029 24x Fiche 50-275,83/05/23,8305310130
- --B305310140 Proposed Tech Specs 3 7 9 1 re fire suppression water sys 4 4 7 9 4 re Halon sys Pacific Gas & Electric Ca 83/05/23 4pp 18655 031 24X Fiche 50-275, B3/05/23, B305310130
- G Adjudicatory correspondence
- B30504045i Advises that informant alleging PO&E/Bechtel misconduct declined to meet w/NRC, fearing PO&E/Bechtel reprisals FLEIBCHAKER, D Fleischaker, D S 83/05/03 EISENHUT, D D Division of Licensing 3pp 18343 140 24X Fiche 50-275,83/05/03,830506045i
- 8305090438 Advises that since 830423 correspondence informant contacted Joint Intervenors re allegations of Bechtel/util misconduct Fear of reprisals prevented informant from meeting or calling NRC FLEISCHAKER, D Fleischaker, D S FLEISCHAKER, D Joint Intervenors-Diable Canyon 83/05/03 EISENHUT, D 0 Division of Licensing 3pp 18342 334 24X Fiche 50-275,83/05/03,8305090438
- 8309110212 First request for document production by Governor Deukmejiam & Joint Intervenors Related correspondence STRUMMASSER, M California, State of REVNOLDS, J R Joint Intervenors-Diablo Cangon 83/05/06 Pacific Gas & Electric Co Spp 18407 100 24X Fiche 50-275.83/05/06.8305110212
- 8305110217 Certifies svc of first set of interrogatories & first document production request on listed parties on 830506 STRUMUASSER.M California. State of 83/05/06 5pp 18407 095 24X Fiche 50-275,83/05/06,8305110217
- B305110383 First set of interrogatories by Oovernor Daukmejian & Joint Intervenors Sworn response requested within 14 days Related correspondence STRUMMASSER.M California. State of REYNOLDS, J R Joint Intervenors-Diablo Canyon B3/05/06 Pacific Cas & Electric Co 26pp 18406 230 24X Fiche 30-275.83/05/06.8305110383
- 8305120285 Motion to reopen record on const QA issue to receive significant new evidence of recently established deficiencies in const QA & QC program Certificate of Svc enc!

 REYNOLOS, J. R. Joint Intervenors-Diable Canyon REYNOLDS, J. R. Center for Law in the Public Interest 83/05/10 Atomic Safety and Licensing Appeal Panel 39p 18427 159 24X

 Fiche 50-275, 83/05/10, 8305120285
- 8305160127 Advises that NRC cannot pinpoint when NRC responsibilities to Commission re independent design verification program sufficiently complete to permit discovery against NRC Final repts due by 830630 CHANDLER.L J Hearing Branch 2 83/05/13 MODRE,T S , BUCK,J H , JOHNSON,W R Atomic Safety and Licensing Appeal Panel 2pp 18448 185. 24X Fiche 30-275,83/05/13,8305160127
- 8303260182 Motion to reopen record on const GA Info discovered on util GA program design & const deficiencies & on const contractor GA program deficiencies KAUFMAN.P H California, State of 83/05/17 Atomic Sefety and Licensing Appeal Pamel 38pp 18599 024 24X Fiche 50-275, 83/05/17,8305260182

- --8305260183 Declaration of RB Hubbard re breakdown in const QA
 Describes events occurring since issuance of 830326
 supplemental affidavit demonstrating util QA/QC const
 program noncompliance Certificate of Svc encl
 HUBBARD, R B California, Btate of 83/05/06 50pp 18599 063
 24X Fiche 50-275,83/05/17.8305260182
- 8305200457 Decision ALAB-728, affirming ASLB 810717 Partial Initial Decision LBP-81-21 authorizing fuel loading & low power testing Johnson opinion, dissenting in partiencl SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/05/18 64pp 18519 340 24X Fiche 50-275,83/05/18,8305200657
- 8305270622 Answers to Governor Deukmejian & Joint Intervenors 830506 first set of Interrogatories 1(a) through (f).8(a).(c) & (d).7(a).(c) & (d).10(a) & (c) & 11(a) & (c) re independent design verification review Certificate of Svc encl CRANE.PA Pacific Oas & Electric Co 83/03/23 DEUKMEJIAN.G California. State of 200pp 18645 001 24X Fiche 50-275.83/05/23.

H General correspondence

- B305180622 Responds to B3032B itr re eight allegations by anonymous individual Preliminary evaluation of allegations underway Meeting u/util planned in near future to solicit evaluation on subj.

 EISENHUT, D 0 Division of Licensing 83/04/21 FLEISCHAKER, D Fleischaker, D B Bpp 18505 317 24X Fiche 50-275,83/04/21, B305180622
- P Operating license stage documents & correspondence
- 8305230407 Informs that backfitting math will be forwarded as soon as available, in response to 830208 ltr FURBUSH M H Pacific Oas & Electric Co 83/02/23 TOURTELLOTTE, J Requiatory Reform Task Force 1p 18543 357 24X Fiche 50-000, 83/02/23, 8305230407
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24X Ficha 50-000,83/04/11,8305230720
- 8305030191 Board Notification 83-51 forwards info re QA/QC allegations at facilities Region V currently invostigating allegations EISENHUT.D 9 Division of Licensing 83/04/15 PALLADINO.J. OILINSKY.V. AHEARNE.J. Commissioners 1p 18309 350 24X Fiche 50-275.83/04/15.8309030191
- --8305030200 Recommends QA/QC allegations be brought to attention of ARLB GREWB, J L Division of Resident, Reactor Project & Engineering Programs 83/04/13 EISENHUT, D & Division of Licensing 3pp 18309 351 24X Fichs 50-275,83/04/15,8305030191
- 8305020388 Responds to 830322 request for add1 info on instrumentation sys for detection of inadequate core couling (Generic Ltr 82-28) Installation completed & sys currently being tested Status of conformance w/NUREG-0737. Item II F 2 enc! 8CHUYLER.J O Pacific Gas & Electric Co 83/04/27 EISENHUT.D G DIVISION of Licensing 7pp 18276 329 24X Fiche 50-275.83/04/27, 8305020388
- 8305070282 Board Notification 83-54 notifies of status of activities performed under independent design verification program resafety issue on design adequacy EIBENHUT, DO DIVISION of Licensing 83/04/27 PALLADING.NJ, OILINBKY,VA, AHEARNE,JF Commissioners 4pp 18366 105 24X Fiche 50-275,83/04/27,8305070282
- 8305100422 Summary of 830419 meeting w/util in San Francisco.CA reares of review for component couling water sys VIETTI.A Licensing Branch 3 83/04/28 Licensing Branch 3 3pp 18621 200 24X Fiche 50-275.83/04/28,8305100422
- B3050305iO Application to amend License DPR-76, requesting extension of 45 days for relief from Tech Spec 3/4 9 7 for mods to fuel handling bldg per License Amend 3 Conditions & procedures applicable to Amend 3 remain in effect CRANE.P A Pacific Gas & Electric Co B3/04/29 KNIGHTON.G W Licensing Branch 3 2pp 18275 089 24X Fiche 50-275,83/04/27, B3050305iO
- 8305020455 Generic Ltr 83-17 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT.D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

- 8305040320 Forwards Amend Request 83-03 to License DPR-76, changing containment isolation valves, organization & quantities of fire detection instruments CRANE.P A Pacific Gas & Electric Co. 83/05/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 18319-331 24X Fiche 50-275, 83/05/02, 8305040320
- --B30504032B Amend Request B3-03 to License DPR-76.changing containment isolation valve list.organization > quantities of fire detection instruments
 SCHUYLER.J O. CRANE.P A Pacific Gas > Electric Co B3/05/02
 2pp 18319 332 24X Fiche 50-275.83/05/02.8305040320
- --8305040473 Proposed Tech Specs re-containment isolation valves, administrative controls & fire detection instrumentation * Pacific Gas & Electric Co. 83/05/02 19pp 18319 334 24X Fiche 50-275,83/05/02,8305040320
- 8303050198 Forwards schedule for submitting component cooling water sys info discussed at 830419 meeting in response to request for addl info at 830128 meeting GRANE, P A Pacific Gas & Electric Co 83/05/03 EISENHUT, D G Division of Licensing 3pp 18342 259 24Y Fiche 50-275, 83/05/03. 8305050198
- 8305040323 Board Notification 83-037 forwards differing prof opinions re sys interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT.D G Division of Licensing B3/05/04 PALLADIND, N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,8305040323
- 8305120611 Board Notification B3-59 forwards info re component cooling water sys discussed at 830419 meeting w/PGAE in San Francisco, CA EIBENRUT, D 0 Division of Licensing B3/05/04 PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 3pp 18440 228 24X Fiche 50-275,83/05/04,8305120611
- --8303120421 Transcript of 830417 public meeting in San Franciso.CA re review of component cooling water sys Pp 1-121 * Commissioners 83/04/19 123pp 18440 231 24X Fiche 30-275.83/05/04.8305120611
- 8305200266 Board Notification 83-061 forwards Joint Intervenors 830428
 Itr requesting meeting w/informant to discuss allegations
 re design verification program per Commission Order
 CLI-81-30
 EISENHUT.D 0 Assistant Director for Licensing 83/05/04
 PALLADIND.N OILINSKY.V AHEARNE.J Commissioners 3pp
 18340 198 24X Fishe 50-275.83/03/04.8305200266
- --8305200273 Advises of informant refusal to meet u/NRC to discuss altegations re design verification program Individual fearful or PO&E/Bechtel reprisals
 FLEISCHAKER, D Fleischaker, D 5 FLEISCHAKER, D Joint Intervenors-Dlablo Camuon 83/04/28 EISENHUT, D 9 Assistant Director for Licensing 5pp 18540 201 24X
 Fiche 30-275,83/05/04.8305200266
- B305120085 Goard Notification B3-55 forwards info on allegations reconst GA at facilities
 EISENHUT.D 0 Division of Licensing B3/05/05 PALLADING.N J ,
 OILINSKY.V , AHEARNE. J Commissioners 3pp 18422 236 24x
 Fiche 50-275
- --B305120093 Forwards sworm statements of V Tennyson & R Roam re allegations of math violations of NRC GA regulations at facilities VAN DE KAMP, J California, State of 83/04/12 EISENHUT, D & Division of Licensing 90pp 18422 239 24X Fiche 50-275,83/05/05,8305120085
- --8305120099 Transcript of 830325 interview w/VH Tennyson re alleged deficiencies in implementation of HP Foley Const Co GA program
 TENNYSON.V H Affiliation Unknown 83/03/25 73pp 18422 329 24X Fiche 50-275,83/05/05,8305120085
- 8305180024 Forwards Amend 5 to License DPR-76 & notice of issuance & availability Amend grants relief for 45 days to allow for movement of loads in excess of 2,500 lb to make mods in fuel handling bldg
 KNIGHTON.O W Licensing Branch 3 83/05/05 CRANE.P A Pacific Oas & Electric Co App 18499 276 24X Fiche 50-275,83/05/05,83/05/8005180024
- --8305180025 Amend 5 to License DPR-76.extending relief request to 45 days for mods in fuel handling bldg KNIGHTON-0 W Licensing Branch 3 83/05/05 5pp 18499 281 24X Fiche 50-275.83/05/05.8305180024

- --8305180032 Notice of issuance & availability of Amend 5 to License
 - DPR-7-0 KNIGHTON G W Licensing Dranch 3 83/05/05 2pp 18499 286 24X Fiche 50-275,83/05/05,8303180024
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D.G. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153 24X Fiche 50-000,83/05/09,8305090659
- B305120042 Responds to B30420 & 21 requests for clarification of specific items re-pressure/temp analysis for pipe break outside containment submitted in B30412 ltr CRANE, P A Pacific Qas & Electric Co 83/05/09 EISENHUT, D O Division of Licensing 5pp 18423 048 24x Fiche 50-275, 83/05/09, 8305120042
- 8305120325 Forwards response to NUREG-06;2, "Control of Heavy Loads "
 Ack of receipt of matl requested
 CRANE.P A Pacific Gas & Electric Co 83/05/09 KNIGHTON, 0 W
 Licensing Branch 3 222pp 18432 042 24% Fiche 50-275,83/05/09.
- #305120333 Forwards Rev 1 to "Pump & Valve Inservice Testing Program, Diablo Canyon Power Plant, Unit 1 " Requests for relief from ASKE Code Section XI requirements included CRANE, P A Pacific Gas & Electric Co 83/05/10 KNIGHTON, G W Licensing Branch 3 2pp 18431 317 24X Fiche 50-275, 83/05/10, 8305120333
- --8305120339 Rev 1 to "Pump & Valve Inservice Testing Program, Diabla Canyon Power Plant, Unit 1 " * Pacific Qas & Electric Co 83/05/10 83pp 18431 319 24X Fiche 50-275, 83/05/10, 8305120333
- ☑305160172 Forwards Rev 2 to Test Procedure 42 7, "Natural Circulation Boron Mixing Test" & pretest rept Receipt ack requested CRANK, P A Pacific Gas & Electric Co ■3705711 KNIGHTON.G W Licensing Branch 3 ip 18445 128 24X Fiche 50-275,83705/11,
- ~-8305160176 Rev 2 to Test Procedure 42 7, "Natural Circulation Boron Rising Test " REIS.M P Pacific Gas & Electric Co 83/04/06 59pp 18446 129 24X Fiche 50-275.83/05/11.8305160172
- #3303040044 Board Notification 83-66 forwards review of MCAP-10297(P). 303040040 Board Notification 83-66 Forwards review of WCAP-1029/1
 "Droppped Rod Methodology for Negative Flux Rate Trip
 Plants " Rod issue resolved by analysis in rept Plants
 beyond first cycle must perform analysis Comments encl
 EISCRNUTT 0 0 Division of Licensing 83/03/13 PALLADINO,N,
 OILINSKY,V, AMEARNE, J. Commissioners 21pp 18341 068, 24X Fiche 50-000, 83/05/13, 8303040044
- B305240375 Forwards info on component cooling water sys, Items 1,2 & 3 a ~ 3 e.addressing seismic qualification.basis for 64 F ocean temp & max flow/single failure analysis requested at B30419 meeting to resolve remaining issues CRANE.P A Pacific Qas & Electric Co 83/05/18 EISENHUT, D 9 Division of Licensing 34pp 18571 006 24X Fiche 50-275, 83/05/18, B305240375
- OS270296 Forwards Rev 3 to "Interface Between Independent Design Verification Program Participants, Plant & Designated Other Parties "Comments requested COOPER.H & Teledyne Engineering Services 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co. 1p 18644-339 24% Fishe 50-275,83/05/20.8308270276
- 3:305310130 Forwards application for amend to License DPR-75, changing portions of Tech Bpecs 3 7 9 1 re fire suppression water sys & 4 7 9 4 re Halon sys
 GRANELP A Pacific Qas & Electric Co 83/05/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 18655.028, 3
 Fichs 50-273, 83/05/23, 8393310130 18655, 028, 24X
- -- 2305310135 Application for amend to License DPR-74.changing portions of Yach Specs 3 7.9 i & 4 7 9 4 increasing high pressure gump capacity to 2,250 gpm & eliminating need for replacing Halon sys w/5-yr svc life remaining SCHUYLER.J 0 , CRANE,P A Pacific Cas & Electric Co 83/05/23 2pp 18655 029. 24x Fiche 50-275,83/05/23,8305310130

- --8305310140 Proposed Tech Specs 3 7 9 1 re fire suppression water sys & 4 7 9 4 me Halon sys * Pacific Gas & Electric Co 83/05/23 4pp 18455 031 24X Fiche 50-275, 83/05/23, 8305310130
- 8305270317 Notifies of 830602 meeting w/util & independent design 3052/0317 Notifies of 830602 meeting w/util & independent design verification program group in Boston.MA to followup 830512 discussions re turbine bldg.polar crane & auxiliary bldg & redistribution of moments & forces COOPER.W E. CRAOIN.J O Teledyne Engineering Services 83/05 KANEATIS.O A. DENTON.H R. HARTIN.J B NRC - No Detailed Affiliation Given 1p 18642 223 24X Fiche 50-275.83/05/27.
- Q Inspection reports, IE Bulletins & correspondence
- 8212040383 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list TAYLOR, J M TÄYLÖR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000:83/03/21,8212060385
- 830317033R Forwards IE Insp Repts 50-275/83-12 & 50-323/83-09 on B30306-0402 No noncompliance noted BISHOP: T W Region 5. Office of Director 83/04/08 CRANE, P A Pacific Oas & Electric Co 2pp 18465 133 24X Fiche 50-275,83/04/08,8305170332
- --8305170339 IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 No noncompliance noted Major areas inspected, surveillance testing, maint & TMI task action plan items CARLSDN.J D. MENDONCA.M M. KIRSCH.D F. Region 5, Office of Director 83/04/05 6pp 18465 135 24X Fiche 50-275.83/04/08.
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 303040023 is impo notice 52 2... Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 30-000,83/04/22,8303040023
- 9305170496 Forwards IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted
 BDDM.H E Region 5. Office of Director 83/04/22 CRANE.F A
 Pacific Gas & Electric Co 2pp 18470 045 24X
 Fiche 50-275.83/04/22,8305170476
- --8305f70301 IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted Major areas inspected implementation of NUREG-0737, Item II F 1. "Add1 Accident Monitoring Instrumentation"

 GARCIA, E M , WENSLAWSKI.F A , BOOK.H E Region 5, Office of Director 83/04/22 7pp 18470 047 24X Fiche 50-275,83/04/22.8305170496
- 8303040025 IE Info Notice 83-23, "Imperable Containment Atmosphere Bensing Sys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list enc! JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026.
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Résponse (fost 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Safetq/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co 18441 170 24X Fiche 50-000, 83/05/03, 8303040028. 122pp
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 30-000,83/05/04,8303040030

- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24% Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN;E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 244 Fichs 50-000.83/05/06.8303040033
- B303040034 IE Info Notice 83~30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11.8303040034
- B303040040 IE Info Notice B3-31: "Error in ADLPIPE Computer Program "
 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18497 009 24% Fiche 50-000,83/05/19,8303040040
- 8305240257 Forwards IE Insp Repts 50~275/83-13 & 50-323/83-10 on 830330-0406 & 25-27 W/o notice of violation 818H0P;T W Region 5, Office of Director 83/05/19 CRANE,P A Pacific Gas & Electric Co 2pp 18625 172 24X Fiche 50-275,83/05/19,8305240257
- --8305240242 IE Insp Repts 30-275/83-13 % 30-323/83-10 on 830330-0406 & 25-27 Noncompliance noted failure to comply w/procedural requirements for processing of nonconformance repts % to conduct welder requalification CARLSON, J D., HERNANDEZ, O H., MENDONCA, M M. Region 5, Diffice of Director 83/05/19 24pp 18425 174 24X Fichs 50-275, 83/05/19, 8305260257
- B305240390 Forwards IE Insp Rept 50-275/83-16 on B30425-0504 No noncompliance noted FAULKENBERRY, B Region 5, Office of Director 83/05/20 CRANE, P A Pacific Oas & Electric Co 3pp 18573 121 24X Fiche, 50-275, 83/05/20, 8305240390
- --8305240393 IE Insp Rept 50-275/83-16 on 830425-0504 No noncompliance noted Major areas inspected action initiated by licensee in response to gouges discovered in reactor coolant pipe Details withheld (ref 10CFR2 790)
 8CARANO,R A , BISHOP,T W , MCGUEEN,A D Region 5, Office of Director 83/05/18 2pp 18573 124 24X Fiche 50-275,63/05/20,8305240390
- 8305260270 Forwards IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 & 8ALP rept for Jul 1981 Dec 1982 MARTIN.J B Region 5, Office of Director 83/05/23 CRANE.P A Pacific Oas & Electric Co 2pp 18626 211 24X Fiche 50-275.83/05/23.8305260270
- --B305260272 IE Mgt Meeting Repts 50-275/83-18 \$ 50-323/83-14 on 830407 No noncompliance noted Major areas discussed SALP rept for Jul 1981 - Dec 1982, including design, const & operations MORRILL, P. J. KIRSCH, D. F. Region 5, Office of Director 83/05/20 2pp 18626-213 24X Fiche 50-275,83/05/23,8305260270
- --8305260274 Bubmits comments on draft BALP rept for Jul 1981 Dec 1982 discussed at B30407 meeting BALP rept will be used as guide for assigning priorities & allocating resources to maintain & improve mpt controls &/or quality of work CRANE,P A Pacific Gas & Electric Co B3/04/27 HARTIN, J B Region 5, Office of Director 2pp 18626/258 24X Fiche 50-275,83/05/23,8305260270
- B303040046 IE Info Notice B3-33. "Nonrepresentative Sampling of Contaminated Oil," Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18447 007 24% Fiche 30-000,83/05/26,8303040046
- R. Periodic operating reports & related correspondence
- B305180427 Advises that no open item repts issued 830321-0408, Individuals assigned to independent design verification program completed acceptable conflict of interest statement REEDY.R F R F Reedy, Inc 83/04/13, DENTON.H R Office of Nuclear Reactor Regulation, Director MANEATIS, Q A Pacific Qas & Electric Co ENGELKEN.R H Region 5, Office of Director 2pp 18485:298, 24X Fiche 50-275.83/04/13,8305180427

- 8305030271 Forwards Rev I to "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys' & "Verification of Mechanical/Nuclear Design of Auxiliary Feedwater Sys," Interim Technical Repts 20 & 22 W/o Rept 20 KRECHTING. J E Stone & Webster Engineering Corp 83/04/25 DENTON, H R Office of Nuclear Reactor Regulation. Director ENGELWEIN.R H Region 5. Office of Director MANEATIS. 0 A Pacific Gas & Electric Co 1p 18300 071 24X Fiche 50-275,83/04/25.
- --8305030282 "Verification of Mechanical/Nuclear Design of Auxiliary Feedwater Sys." Interim Technical Rept 22 BESTAM.F Stone & Webster Engineering Corp STRATOULY, D C Teledyne Engineering Services 83/04/20 36pp IB300 093 24X Fiche 50-275.83/04/25.8305030271
- 8305030538 Forwards Rev 1 to "Verification of Hechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 20 KRECHTING. J E Stone & Webster, Inc. 83/04/25 DENTON, H R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R H. Region 5, Office of Director MANEATIS, O A Pacific Oas & Electric Co. jp. 18305-329 24X Fiche 50-275, 83/04/23, 8305030538
- ~~8305030545 Rev 1 to "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurvation Sys," Interim Technical Rept 20 SESTAK,F, STRATOULY,P C Stone & Webster, Inc 83/04/20 34pp 18305 230 24X Fiche 50-275.83/04/25.8305030338
- 8305030573 Forwards Rev I to "Diablo Canyon Unit 1 Independent Design Verification Program Electrical Equipment Analysis:" Interim Technical Rept 33 DENISINE Robert L Cloud Associates, Inc. 83/04/29 DENION, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, O H Pacific Gas & Electric Co ip 18301.295 24% Fishe 50-275.83/04/29,8305030573
- --B3050305B1 Rev 1 to "Diable Canyon Unit 1 Independent Design Verification Program Electrical Equipment Analysis: "Interim Technical Rept 33 DENISON,E Robert L Cloud Associates, Inc P105-4-839-033 ROI B3/04/28 53pp 18301
- 8305050299 Forwards "Diable Canyon Nuclear Power Plant Unit 1.
 Independent Design Verification Program." final rept.in
 response to Commission order
 COUPER.W E Teledyne Engineering Services 83/05/02 DENTON.H R
 Office of Nuclear Reactor Regulation. Director MARTIN.J B Region
 3. Office of Director MANEATIS.O A Pacific Cas & Electric Co
 2pp 10937 001 24% Fiche 50-275.83/05/02.8305050299
- --8305050303 "Diablo Cangon Nuclear Power Plant Unit i. Independent Design Verification Program," final rept * Teledyne Engineering Services 83/05/02 126pp 18337 003 24x Fiche 50-275.83/05/02,8305050279
- B305200723 Comments on Rev O to Interim Technical Rept (ITR) 36 5 Rev 1 to ITR 36 evaluating StW audit of GF Atkinson t Wismer to Becker const GA Closing out engineering open item opposed Repts should be revised NOVAK.T M Assistant Director for Licensing B3/05/02 COOPER,W E Affiliation Unknown 3pp 18540 092 24X Fiche 50-275,83/05/02.8305200723
- BJ05230206 Board Notification B3-56 forwards "Independent Design Varification Program Semimonthly Status Rept for Apr 1983" & "Interim Technical Rept 42 RF Reedy Independent Design Varification Program Phase II Review & Audit "EIBENHUT, D. Q. Division of Licensing 83/05/03 PALLADING, N. J. QILINSKY, V. AHEARNE, J. F. Commissioners 4pp 18545 OO1 24X Fiche 50-275,83/05/03,8305230206
- 8305100173 Forwards Rev i to "Verification of Auxiliary Feedwater Sys Electrical Design," Interim Technical Rept 25 & Rev i to "Verification of Control Room Ventilation & Fressurization Sys Electrical Design," Interim Technical Rept 26 KRECHTIND. J E Stone & Webster Engineering Corp 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation. Director ENGLKEN.R H Region 5. Office of Director MANEATIS.O A Pacific Gas & Electric Co ip 18377 060 24x Fiche 50-275.83/05/04.
- --8305100179 Rev i to "Verification of Auxiliary Feedwater Sys Electrical Design." Interim Technical Rept 25
 SESTAK.F Stone & Nebster Engineering Corp 83/04/29 26pp
 18377 06R 24X Fiche 50-275,83/05/04.8305100173
- --8305100185 Rev 1 to "Verification of Control Room Ventilation & Pressurization Sys Electrical Design," Interim Technical Rept 26
 SESTAK, F. Stone & Hebster Engineering Corp. 83/05/02 25pp. 18377 087 24X Fiche 50-275,83/05/04.8305100173

- B305120203 Forwards Rev. 1 to Interim Technical Rept 21, "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Dreaks for Auxiliary Feedwater Sys. 7 Control Room. " 3 Rev. 1 to Interim Technical Rept 24, "Verification of 4,140." KRECHTING. J. E. Stone & Webster Engineering Corp. B3705709 DENTON.H R. Office of Nuclear Reactor Regulation. Director ENGELKEN.R H. Region 5. Office of Director MANEATIS.G. A. Pacific Gas & Electric Co. 1p. 18427 100. PAX Fiche 50-275.83/05/09, 830512703
- --8305120211 Rev 1 to "Verification of Effects of High Energy Line Cracks
 b Moderate Energy Line Breaks for Auxiliary Feedwater Sys &
 Control Room Ventilation b Pressuritation Sys." Interim
 Technical Rept 21
 SESTAX, F Stone & Webster Engineering Corp 83/05/03 21pp
 18427 102 24X Fiche 50-275,83/05/09,8303120203
- --8305120216 Rev 1 to "Verification of 4.160-Volt Safety-Related Electrical Distribution Sys," Interio Technical Rept 24 SESTAK: F Stame & Webster Engineering Corp 83/05/04 28pt 18427 124 24X Fiche 50-278.83/05/09,8305120203
- 8305230216 Board Notification 83-65 forwards info items re design verification program EISENHUT, D O Division of Licensing 83/05/11 PALLADINO, N J OILLINSKY, V AHEARNE, J F Commissioners 4pp 18544 001 24X Fiche 50-275,83/05/11.8305230216
- --8305230224 Forwards Rev O to "Diablo Canyon Unit ! Independent Design Verification Program MXs." Interim Technical Rept 43
 OENISON E Robert L Cloud Associates, Inc 83/04/15
 DENISON H R Office of Nuclear Reactor Regulation, Director MARTIN.J B Region 5. Office of Director MAREATIS.G H Pacific Gas & Electric Co ip 18544 163 24X Fiche 50-275,83/05/11, 8305230216
- 8305160185 Board Notification 93-68 forwards Teledyne Engineering Svcs.
 "Diable Campon Nucleat Power Plant.Unit 1.Final Rept.
 Independent Design Verification Program "Final Installment
 of rept scheduled for submittal by 830630
 EISENHUT, D 6 Division of Licensing 83/05/12 PALLADIND, N .
 OILINSKY, V. AHEARNE, J Commissioners 3pp 18474 239 24X
 Fiche 50-275,83/05/12,8305160185
- 830517051: Forwards Rev I to "Venification of Pressure.Temp.Homidity & Submargence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room ," Interim Technical Rept 14
 KRECHTING.JE Stone & Webster Engineering Corp 83/05/12
 PENTON.H R Office of Nuclear Reactor Regulation, Director ENGELKEN.R H Region 5, Office of Director MANEATIS.G A Pacific Oas & Electric Co 1p 18468 323 24x Fische 50-275.83/05/12, 8305170511
- --8305170517 Rev 1 to "Verification of Pressure, Temp. Humidity t Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auriliary Feedwater Sys & Control Room Ventilation ," Interim Technical Rept 14 SESTAK.F . STRATOULY.D C Stone & Webster Engineering Corp 83/05/09 45pp 18448 324 24Y Fiche 50-275, 83/05/12, 8305170511
- 8305180377 Advises that no open item repts issued since last semimonthly rept (RECHTING.) E Stone & Mebster Engineering Corp 83/05/13 DENTON: R Diffice of Nuclear Reactor Regulation, Director MANEATIS. 8 A Pacific Gas & Electric Co MARTIN. J B Region 5. Office of Director ip 18490 346 24% Fiche 30-275, 83/03/13, 8305180377
- B305180395 Forwards "Diable Canyon Nuclear Power Plant, Unit 1.
 Independent Design Verification Program," second Friday
 semimonthly rept for May 1983
 COUPER, M E Teledyne Engineering Services 83/05/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
 5, Office of Director MANEATIS, A Pacific Ses & Electric Co
 1p 18485 303 24X Fiche 50-275,83/05/13,8305180395
- --8305180403 "Diablo Canyon Nuclear Power Plant.Unit (, Independent Design Verification Program," second Friday semimonthly rept for May 1983 * Teledyne Engineering Services 83/05/13 28pp 18485 304 24X Fiche 50-275,83/05/13.8305180395
- B305180417 Forwards Rev O to Open Item Repts 1121 & 1122 for May 1983 Responsible individuals assigned by RL Cloud have completed acceptance statement re potential or apparent conflicts of Interest DENISON.E Robert L Cloud Associates. Inc B3/03/13 DENTON, H R Defice of Nuclear Reactor Regulation. Director MARTIN, J. B. Region 5, Office of Director MANEATIS, O H Pacific Gas & Electric Co 3pp 18485 353 24X Fichs 50-275, 83/03/13, 8305180417

- B305240238 Forwards "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period B30419-0509 Rept submitted per NRC Drder Ct.1-81-30 CRANE.P A Pacific Gas & Electric Co B3/05/13 DENTON.H R Office of Nuclear Reactor Regulation, Director MARTIN.J B Regid 5. Office of Director 1p 18548 221 24X Fichs 50-275.83/05/13,8305240238
- --8305240242 "Dieblo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509 * Pacific Gas & Electric Co 83/05/13 65pp 18548 222 24X Fiche 50-275.83/05/13.8305240238
- 8305200358 Forwards "Independent Design Verification Program Final Rept." second draft submittal Next submittal scheduled for 830530 Final submittal scheduled for 830630 CBOPER. W. E. Teledyne Engineering Services 83/05/16 DENTON. H.R. Office of Nuclea. Reactor Regulation. Director MARTIN. J. B. Region 5. Office of Pirector MANEATIS. G. A. Pacific Gas & Electric Ca 2pp 18518 016 24X Fiche 50-275.83/05/16.8305200358
- --8305200364 "Independent Design Verification Program Final Rept." second draft submittal * Teledyne Engineering Services 83/05/16 73pp 18518 018 24x Fiche 50-275,83/05/16,8305200358
- 8305230213 Forwards Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys."
 Interim Technical Rept 28
 KRECHTING, J E Stone & Medster Engineering Corp 83/05/18
 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18539/145 24% Fiche 50-275,83/05/18,8305230213
- --8305230221 Rev 1 to "Verification of Instrument & Control Design of Control Room Ventalation & Pressurization Sys," Interim Technical Rept 28 SESTAK,F Stone & Webster Engineering Corp. 83/05/13 30pp. 18539 146 24X Fiche 50-275,83/05/18,8305230213
- B305230556 Forwards Rev I to "Verification of Instrument & Control Design of Auxiliary Feedwater Sys." Interim Technical Rept 27

 KRECHTING.JE Stone & Hebster Engineering Corp. 83/05/18

 DENTON:H R Office of Nuclear Reactor Regulation, Director MARTIN:JB Region 5, Office of Director MANEATIS,G A Pacific Oas & Electric Co. 1p. 18537-102 24X Fiche 50-275,83/05/18,8305230556
- --8205230559 Rev 1. "Verification of Instrument & Control Design of Auxiliary Feedwater Sys." Interim Technical Rept 27 BESTAK.F. Stone & Webster Engineering Corp. 83/05/13 37pp 18537 103 24X Fiche 50-275,83/05/18,8305230556
- 9305250066 Beard Notification 83-67 forwards technical repts & transcript of 83054 public meeting re design verification program EISEMHULD 6 Division of Licensing 83/05/18 PALLADIND, N, OILINSKY, V, AHEARNE, J Commissioners 3pp 18575,001 24X Fichs 30-275,83/05/18,8305250066
- --8305250186 Transcript of 830504 public meeting to review design verification project in San Francisco.CA Pp 1-236
 * Commissioners 83/05/04 43pp 18595.005 24X
 Fiche 50-273,83/05/18.8305250066
- 8305250466 Forwards Rev O to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys." Interim Technical Rept 45 Meeting announcement encl RECENTING, JE Stone & Nebster Engineering Corp 83/05/20 DENTON. H R Office of Nuclear Reactor Regulation, Director MANEATIS: O A Pacific Gas & Electric Co MARTIN. J B Region 5, Office of Director 2pp 19585 228 24% Fichs 50-275, 83/05/20.
- --B305250447 Rev O to "Add1 Verification of Redundancy of Equipment & Power Supplies in Shared Bafety-Related Sys," Interim Technical Rept 45
 SESTAK: F Stone & Hebster Engineering Corp 83/05/17 17pp
 18385 230 24X Fiche 50-273, 83/05/20, 8305250466
- 8305310186 Forwards Rev i, to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Fressurization Bys, Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18.

 KRECHTING.J E Stone & Webster Engineering Corp 83/05/24

 DENTON, H R. Office of Nuclear Reactor Regulation Director MANEATIS, G.A Pacífic ofas & Electric Co MARTIN, J B Region 5, Office of Director ip. 18652 347 24X Fiche 50-275, 83/05/26, 8305310186

1

- --8305310191 Rev 1 to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Pressurization, Sys, Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18 SESTAKIF Stone & Webster Engineering Corp 83/03/24 28pp 18652 349 24% Fiche 50-275,83/03/26,8309310186
- S Reportable occurrences, LERs & related correspondence
- B305030313 PNS-V-B3-005 on B30426, region dispatched reactive insp team to review findings & status to date of licenses investigation of safety significance of recent yandalism event on B30419 involving gauges in coolant pipe MCGUEEN, A D. NORDERHAUG, L R. Region 5. Office of Director B3/04/27 Ip 18297 069 24X Fiche 50-275,83/04/27,8305030313
- B305060580 PND-V-83-019 on B30502.6 5 Richter scale earthquake occurred approx B5 miles from facility No damage identified Strong notion seismic recorder not actuated Media interest expected
 KIRBCH.D F Region 5, Office of Director 83/05/03 lp 18349 057 24X Fiche 50-275,83/05/03,8305060580
- 8305240397 LER 83-004/08T-0 on 830419, grinding wheel & rotary file gauges found on main coolant sys piping on main coolant pump 3 fischarge side Caused intentionally by unknown persons Gauges removed by grinding & blending H/830503 ltr KELLY, W J. SHIFFER, J. D. Pacific Gas & Electric Co. 83/05/03 HARTEN, J. D. Region 5. Office of Director Spp. 16549 275 24X Fiche 50-275, 83/05/03, 8305240397
- 8305160009 PND-V-83-021 on 830429, leak discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity KIRSCH. DF Region 5, Office of Director 83/05/10 ip 18456 081 24X Fiche 50-275.83/05/10.8305160009
- B305130197 PNO-V-B3-022 on B30509, while performing additultrasonic axams. RCS piping in area of one weld determined less than min wall thickness specified by code Caused by welds being ground smooth during original preservice exam KIRBCH, D F Region 5, Office of Director 83/05/11 1p 18439 347 24X Fichs 50-275, 83/05/11, 8305130187
- 9305270249 LER 93-003/03L-0 on 830414, control operator unable to achieve satisfactory check source reading on liquid radwaste discharge line radiation monitor (RE-18) Caused by missing check source from monitoring mechanism W/830513 ltr SHIFFER, J D . KELLY, W J Pacific Gas & Electric Co 83/05/13 MARTIN, J B Region 5, Office of Director 4pp 18637 152 24) Ficha 50-275,83705/13,8305270249
- T Hearing transcripts on non-antitrust matters
- 8305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at 830419 meeting w/PGVE in 8an Francisco.CA EISENHUT.D 9 Division of Licensing 83/05/04 PALLADINO,N J JOLLINSKY,V , AHEANNEJ Commissioners 3pp 18440 228 24X Fiche 50-275,83/05/04,8305120611
- --8305120621 Transcript of 830419 public meeting in San Franciso.CA ra review of component cooling water sys Pp 1-121 + Commissioners 83/04/19 123pp 18440 231 24X Fiche 50-275.83/05/04.8305120611
- 9305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re dosign verification program EISENHUT.D Q Division of Licensing 83/05/18 PALLADINO,N, QILINSKY,V, AHEARNE,J Commissioners 3pp 18595 001 24X Fiche 50-275.83/05/18,8305250066
- --8305250186 Transcript of 830504 public meeting to review design varification project in San Francisco.CA Pp 1-236
 + Commissioners 83/05/04 43pp 18595 005 24X Ficha 50-275,83/05/18,8305280066
- U Congressional/Executive Correspondence
- B305100124 Supplemental testimony of JC Keppler re GA KEPPLER, J G Region 3, Office of Director 83/03/25 6pt 18375, 197 24X Fiche 50-000, 83/03/25, 8305100124

- --8305100111 Responds to Bill13 ltr re implications of recent seismic design errors at facility Due to design errors. Util license suspended an Bill19 pending completion of independent design review & receipt of schedule for completing mods PALLADINON J Commissioners 82/02/01 DINGELL. J D House of Rep. Energy & Commerce 3pp 18375 228 24% Fiche 50-000,83/03/25,8305100124
- DOCKET 50-2/7 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- B305040716 Summary of B30405 meeting w/util in Dethesda,MD re status of App R concerning fire protection program mode at facility
 GEARS,G E Operating Reactors Branch 4 83/04/25 Operating Reactors Branch 4 3pp 18328 104 24X Fiche 50~277.83/04/25, 8300040716
- 8305100359 Describes plans for completing fire protection mods re Sections III F.III 0.(I) J & III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided BOYER, V S Philadelphia Electric Co 83/05/02 EISENRUT, D & Division of Licensing App 18379 033 24x Fiche 50-277,83/05/02. 8305100359
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list enci EISENHUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. L6pp 18540-099 24X Fiche 50-000,83/05/11,8305110034
- 8305190522 Notification of 830526 meeting w/util in Bathesda.MD to discuss alternative safe shutdown.App R GEARS.Q Operating Reactors Branch 4 83/05/17 STOLZ.J Operating Reactors Branch 4 2pp 18523 156 24X Fiche 50-2/7.83/05/17.8305170522
- G Adjudicatory correspondence
- 8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Absented dissenting views enci CHILK: 8 J Dffice of the Secretary of the Commission 83/03/31 Commissioners 3pp 17807 049 24% Fiche 50-000.83/03/31, 8304040470
- B305060250 Order extending time until 830513 for Commission to act to review ALAB-701
 HDYLE.J C Office of the Secretary of the Commission B3/05/05
 Commissioners to 18345 196 244 Fiche 50-000,83/05/05,8305060250
- B305130060 Response opposing intervehor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest PALLADINO, N J Commissioners 83/05/11 2pp 18436-228 24X Fiche 50-000,83/05/i1.8305130060
- 8305130061 Order extending time until 930520 for Commission to act to review petition for review of ALAB-701 CHILK:S J Office of the Secretary of the Commission 83/05/12 Commissioners 1p 18437 033 24% Fiche 50-000.93/05/12, 8305130061
- 8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 patition for review of ALAB-701 CHILK, S. J. Office of the Secretary of the Commission 83/05/17 Commissioners 1p 18514 283 24X Fiche 50-000,83/05/19. 8305200560
- 8303310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pite requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl CHILK/S J Office of the Secretary of the Commission 83/05/27 14pp 18653 311 24X Fiche 50-000.83/05/27.8305310017
- J Insurance & indemnity information
- 8305240307 Forwards Endorsements 1.2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection
 BRADLEY, E. J. Philadelphia Electric Co. 83/05/17 SALTZMAN. J.
 Assistant Director for State & Licenses Relations 41pp 18548 141
 24X Fiche 50-277,83/05/17.8303240307

- 8305120203 Forwards Rev 1 to Interim Technical Rept 21. "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Brasks for Auxiliary Feedwater Sys ! Control Room " & Rev 1 to Interim Technical Rept 24. "Verification of 4.60 " KRECHTING.J E Stone & Webster Engineering Corp 93/05/09 DENTON.H R Office of Nuclear Reactor Regulation. Director ENGELMEN.F H Region 5. Office or Director MANEATIS.G A Pacific Gas & Electric Go 1p 18427 100 24% Fische 50-275, 83/05/09, 8305120203
- --8305120211 Rev 1 to "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feeduater Sys & Control Room Ventilation & Pressurization Sys," Interim Technical Rept 21 SESTAX.F Stone & Webster Engineering Corp 83/05/03 21pp 18427 102 24X Fiche 30-275.83/05/09.8305120203
- --B305120216 Rev 1 to "Verification of 4,160-Volt Gafaty-Related Electrical Distribution Sys." Interim Technical Rept 24 SESTAK: F Stone & Webster Engineering Corp B3/05/04 28pp 18427 124 24X Fiche 50-279,83/05/09.8305120203
- 83032302(6 Board Notification 83-65 forwards info items re design verification program EISENNUT.D & Division of Licensing 83/05/11 PALLADINO.N J. GILINSKY.V. AHEARNE.J F Commissioners 4pp 18544 001 24X Fiche 50-275,83/05/11.8305230216
- ~~8309230324 Forwards Rev O to "Diablo Canyon Unit I Independent Design Verification Program MXs." Interim Technical Rept 43
 DENISON.E Robert L Cloud Associates: Inc 83/04/15
 DENISON.H R Office of Nuclear Reactor Regulation, Director MARTIN.J B Region 5. Office of Director MANEATIS.G H Pacific Gas & Electric Co 1p 18544 163 24% Fiche 30-275,83/05/11.
- 8305160185 Board Notification 83-48 forwards Teledyne Engineering Svcs, "Diablo Canyon Nuclear Power Plant, Unit 1.Final Rept, Independent Design Verification Program "Final Installment of rept scheduled for submittal by 830620 Fig. 10 Division of Licensing 83/05/12 PALLADINO, N. OILINSKY, V. AHEARNE, J. Commissioners 3pp 18474 239 24% Fiche 50-275,83/05/12,8305160185
- 8305170511 Forwards Rev 1 to "Verification of Pressure, Temp. Humidity & Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room ," Interim Technical Rept 14

 KRECHTING, J E Stone & Hebster Engineering Corp 83/05/12

 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R J Region 5, Office of Director MANEATIS, 0 A Pacific Gas & Electric Co ip 19468 323 24X Fiche 30-275,83/05/12,8303170511
- --B305170517 Rev 1 to "Verification of Fressure.Temp.Humidity t Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Fredwater Sys & Control Room Ventilation ," Interim Technical Rept 14 SESTAK.F. STRATOULY.D C Stone & Hebster Engineering Corp 83/05/09 ASpp 18468 324 24x Fiche S0-275.83/05/12.8305170511
- 8303180377 Advises that no open item repts issued since last semimonthly rept KRECHTING.JE Stone & Webster Engineering Corp 83/05/13 DENION.H R Office of Nuclear Reactor Regulation, Director MANGATIS.G A Pacific Gas & Electric Co MARTIN.JB Region 5. Office of Director ip 18490 346 24% Fiche 50-275.83/05/13. B30488037
- 8305180395 Forwards "Diable Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimentally rept for May 1983 COOPER, W.E. Teledyne Engineering Services 83/05/13 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director MARTIN, J.B. Region 5, Office of Director MANCATIS, G.A. Pacific Gas & Electric Co. 1p. 18485 203 24X Fiche 50-275,83/05/13,8305180395
- --8305180403 "Diablo Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimonthly rept for May 1983 * Teledyne Engineering Services 83/05/13 28pp 18485 304 24X Fiche 50-275,83/05/13,8305180395
- B305180417 Forwards Rev O to Open Item Repts 1121 \$ 1122 for May 1983 Responsible individuals assigned by RL Cloud have compileted acceptance statement re potential or apparent conflicts of interest
 DENISONIE Robert L Cloud Associates, Inc. 83/05/13 DENION,H R
 Office of Nuclear Reactor Regulation, Director MARTIN, J. B, Region
 5. Office of Director MANEATIS, 9 H Pacific Gas & Electric Co
 3pp. 18485-353 24X Fiche 50-275.83/05/13,8305180417

- 8305240238 Forwards "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509 Rept submitted per NRC Order CLI-81-30 CRANE.P A Pacific Gas & Electric Co 83/05/13 DENTON.H R Office of Nuclear Reactor Regulation. Director MARTIN.J B Region 3. Office of Director 1p 18548 221 24X Fichs 30-275.83/05/13,8305240238
- --8305240242 "Diable Canyon Verification Program." Semimonthly Status Rept 37 for period 830419-0509 * Pacific Gas & Electric Co 83/05/13 65pp 18548 222 24x Fiche 50-275,83/05/13,8305240238
- B305200358 Forwards "Independent Design Verification Program Final Rept." second draft submittal Next submittal scheduled for B30530 Final submittal scheduled for B30670 CODFER.N E Teledyne Engineering Services B3/03/16 DENTON.H R Office of Nuclear Reactor Regulation, Director MARTIN.J B Region 5. Office of Orector MANEATIS.O A Pacific Oas & Electric Co 2pp 18518 016 24X Fiche 30-275.83/05/16.8305200358
- --8305200364 "Independent Design Verification Program Final Rept,"
 second draft submittal
 * Teledyne Engineering Services 83/05/16 73pp 18518 018
 24X Fiche 50-275.83/05/16,8305200358
- 8305230213 Forwards Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys." Interior Technical Rept 28
 KRECHTING, J E Stone & Webster Engineering Corp 83/05/18
 BENTON: H R Uffice of Nuclear Reaction Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, Q A Pacific Oas & Electric Co 1p 18539 145 24X Fiche 50-275,83/05/18,830520213
- ~-8305230221 Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 28 SESTAK.F Stone & Webster Engineering Corp 83/05/13 30pp 18539 146 24X Fiche 50~275,83/05/16,8305230213
- B305230556 Forwards Rev i to "Verification of Instrument & Control Design of Auxiliary Feedwater Sys." Interim Technical Rept 27
 KRECHTING. JE Stone & Webster Engineering Corp 83/05/18
 DENTON. H R Office of Nuclear Reactor Regulation, Director MARTIN. J B Region 5. Office of Director MANEATIS. G A Pacific Gas & Electric Co ip 18537 102 24X Fiche 50-275,83/05/18,830520554
- --8305230559 Rev 1, "Verification of Instrument & Control Design of Auxiliary Feedwater Sys." Interim Technical Rept 27 SESTAK.F Stone & Webster Engineering Corp 83/05/13 37pp 18307 103 24X Fichs 50-275.83/05/18.8305230554
- 8303250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program EISENHUT.D 9 Division of Licensing 83/05/18 PALLADING.N, GILINSKY,V, AHEARNE,J Commissioners 3pp 18595 001 24X Fiche 50-275,83/05/18.8305250046
- ---B305250186 Transcript of B30504 public meeting to review design verification project in San Francisco.CA Pp 1-236
 * Commissioners B3/05/04 43pp 18575 005 24X
 Fiche 50-275,83/05/18,8305250066
- B305250466 Forwards Rev O to "Add1 Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys."
 Interfat Technical Rept 45 Meeting announcement encl
 KRECHTING, J E Stone & Webster Engineering Corp B3/05/20
 DENTON, H R Office of Nuclear Reactor Regulation. Director MANEATIS, O A Pacific Gas & Electric Co MARTIN, J B Region 5.
 Office of Director 2pp 18585 228 24X Fichs 50-275,83/05/20,8305230446
- ---8305250467 Rev O to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys," Interim Technical Rept 45
 SESTAK, F Stone & Webster Engineering Corp 83/05/17 17pp
 18585 230 24X Fiche 50-275.83/05/20.8305250466
- 8305310186 Forwards Rev I.to "Verification of Fire Protection Provided for Avxiliary Feedwater Sys, Control Room Ventilation & Pressurization Sys, Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18 KRECHTINO, J E Stone & Webster Engineering Corp 83/05/26 DENTON, H R Office of Nuclear Reactor Regulation Director HANEATIS, Q A Pacific Gas & Electric Co MARTIN, J B Region 5, Defice of Director ip 18652 347 24X Fiche 30-275,83/05/26, 83005310186

- --8305310191 Rev 1 to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys. Control Room Ventilation & Pressurization Sys. Safety-Related Portion of 4160-Volt Electric Sys, " Interim Technical Rept 18 SESTAK.F Stone & Webster Engineering Corp 83/05/24 28pp 18652 349 24X Fiche 50-275.83/05/26.8305310186
- S Reportable occurrences. LERs & related correspondence
- 8305030313 PNS-V-83-005 on 830426 region dispatched reactive insp team to review findings & status to date of licensee investigation of safety significance of recent vandalism event on 830419 involving gauges in coolant pipe MCAUSERNA D. NORDERHAUG. L R. Region 5. Office of Director 93/04/27 ip 18297 069 24X Fiche 50-275.83/04/27.8305030313
- 8305060580 PND-V-83-019 on 830502.6 5 Richter scale earthquake occurred approx 85 miles from facility No damago identified 8trong motion seismic recorder not actuated Media interest expected KIRSCH.D F Region 5, Office of Director 83/05/03 ip 18347-057 24X Fiche 50-275,83/05/03.8305060580
- B305240397 LER 83-004/08T-0 on 830419, grinding wheel & retary file gouges found on main coolant sys piping on main coolant pump 3 discharge side Caused intentionally by unknown persons gouges removed by grinding & blending W/830503 ltr KELLY, W. J. SHIFFER, J. D. Pacific Oas & Electric Co. 83/05/03 MARTIN, J. B. Region 5, Office of Director 3pp. 18549-275 24X Fiche 50-275, 83/05/03, 8305240397
- B305140009 PNO-V-83-021 on B30429, leak discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity
 KIRSCH, DF Region 5, Office of Director B3/05/10 1p
 18456 0B1 24% Fiche 50-273.83/05/10.8309160009
- B305130187 PNO-V-B3-022 on B30509, while performing addi ultrasonic axams, RCS piping in area of one wold determined less than min wall thickness specified by code Caused by welds being ground smooth during priginal preservice exam KIRECH, D.F. Region 5, Office of Director B3/05/11 ip 18439 347 24X Fiche 50-275,83/05/11,8305130187
- O305270249 LER 03-003/03L-0 on 030414, control operator unable to achieve satisfactory check source reading on liquid radwaste discharge line radiation monitor (RE-10) Caused by missing check source from monitoring mechanism W/030513 ltr 03417FER. J D . KELLY. W J Pacific Gas & Electric Co 03/05/13 MARTIN. J B . Region 5. Office of Director 4pp 18637 152 24X Piche 50-275, 83/05/13, 8305270249
- T Hearing transcripts on non-antitrust matters
- B305110073 Transcript of 830419 public meeting re component cooling water sys in San Francisco.CA Pp 1-121 ** NRC No Detailed Affiliation Given 83/04/19 124pp 18434 ii 2 24X Fiche 50-275.83/04/19.8305110093
- B305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at B30419 meeting w/862E in Ban Francisco, CA
 EIBENHUT, D Q Division of Licensing B3/05/04 PALLADIND, N J QILINBKY, V , AHEARNE, J Commissioners 3pp 18440 228 24X Fiche 30-275, B3/05/04, B305120611
- --8305120621 Transcript of 830417 public meeting in San Franciso,CA re review of component cooling water sys Pp 1-121 * Commissioners 83/04/17 123pp 18440 231 24X Fiche 50-275,83/05/04,8305120611
- #305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program #EISENHUT, D G Division of Licensing 83/05/18 PALLADING, N , QTILINSKY, V , AHEARNE, J Commissioners 3pp 18595 001 24X Fiche 50-275, 83/05/18, 8305250066
- --B305250186 Transcript of B30804 public meeting to review design verification project in San Francisco. CA Pp 1-236

 * Commissioners. B3/05/04 43pp 18595 005 24X fiche 50-275.83/05/18.8305250066
- U Congressional/Executive Correspondence

- --8305100141 Responds to Blill3 ltr re implications of recent seismic design errors at facility Due to design errors util license suspended on Blill9 pending completion of independent dasign review 7 receipt of schedule for lompleting mods PALLADIHD, N J. Commissioners 82/02/01 DINGELL, J D. House of Rep. Energy 2 Commerce 5pp 18375 228 24% Fiche 50-000, 83/03/25, 8305100124
- DOCKET 50-2/7 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- #305040716 Summary of #30405 meeting w/util in Bethesda, MD re status of App #1 concerning fire protection program mods at facility

 @EARS. @ E Operating Reactors Branch 1 #3704/25 Operating

 Reactors Branch 4 3pp 18328 106 24% Fishe 50-277, #3704/25.
- 8305100357 Describes plans for completing file protection mods re Sections III F.III G.III J. III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided BOYER.V S Philadelphia Electric Co 83/03/02 EISENRUT.D G Division of Licensing App 18379 033 24X Fiche 50-277.83/05/02.
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs is clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUF, D & Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034
- B305190522 Notification of B30526 meeting w/util in Bethesda.MD to discuss alternative safe shutdown.App R GEARS.G Operating Reactors Branch 4 83/05/17 STOLZ, J Operating Reactors Branch 4 2pp 18523 156 24X Fiche 50-277.83/05/17.8305190522
- O Adjudicatory correspondence
- B304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Abearne dissenting views ecl CHILK.8 J Office of the Secretary of the Commission 83/03/3i Commissioners 3pp 17807 049 24% Fiche 50-000,83/03/3i. B304040470
- 8303060230 Order extending time until 830513 for Commission to act to review ALAB-701
 HOYLE, J C Dffice of the Secretary of the Commission 83/05/05
 Commissioners ip 18345 196 244 Fiche 30-000,83/05/05,8305060230
- 8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss ressons why prior activities may constitute conflict of interest PALLADINGIN J Commissioners 83/05/11 2pp 18436 228 24X Fiche 30-000.63/05/11.8305130060
- 8305130061 Order extending time until 830570 for Commission to act to review petition for review of ALAB-701 CHILK, S.J. Office of the Secretary of the Commission 83/05/12 Commissioners 1p 18437 033 244 Fiche 50-000,83/05/12,8305130061
- 8303200560 Order extending time until 830527 for Commission to act to review intervenor 821227 patition for review of ALAB-701 CHICK,8 J Office of the Secretary of the Commission 83/05/19 Commissioners ip 18514 283 24% Fiche 50-000,83/05/19, 8305200560
- 8305310017 Memorandum & order to hold decision in ALAB-701 in abequance until Commission completes review of V mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl CHILK/S J Deffice of the Secretary of the Commission 83/05/27 14pp 18603 311 24X Fithe 50-000.83/05/2//8309310017
- J Insurance & indemnity information
- B305249307 Forwards Endorsements 1.2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection BRADLEY.E J Philadelphia Electric Co B3/05/17 SALTZMAN.J Assistant Director for State & Licensee Relations 41pp 18548 141 24X Fiche 50-277.83/05/17.8305240307

P Operating license stage documents & correspondence

- 8305040704 Summary of 830323 meeting w/util in Bethesda, MD re technical presentation on GE-hybrid control rods assemblies currently proposed for installation GEARS.G E Operating Reactors Branch 4 93/04/22 Operating Reactors Branch 4 93/04/22, 83/04/22,
- 8305020099 Responds to 830322 ltr re clarification of safety evaluation for environ qualification of safety-related electrical equipment Revised justifications for continued operation encl
 DALTROFF, S L Philadelphia Electric Co 83/04/27 STOLZ, J F
 Operating Reactors Branch 4 12pp 18279 241 24X
 Fiche 30-277,83/04/27,8305020099
- 8305020435 Generic Ltr 83-19 to all power reactor \$\nu\$ testing licensees rs new procedures far providing public notice concerning issuance of amends to OLs 8vc list encl EISENHUT, D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 i20 24X Fiche 50-000-83/05/02.8305020459
- B305050021 Forwards application for amend to Licenses DFR-44 & DFR-56 changing Tech Spec we limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing BRADLEY, E. J. Philadelphia Electric Co. 83/05/04 DENTON, H.R. Office of Nuclear Reactor Regulation, D(rector ip 16342 106 24X Fichs 50-277, 83/05/04, 8305050021
- --8305050027 Application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iddine concentrations in reactor coolant & coolant leak testing DALTROFF, S L., BRADLEY, E J. Philadelphia Electric Co. 83/05/04 App. 18342 107 24% Fiche 50-277.83/05/04.8305050021
- B305090459 Generic Ltr B3-20 to all operating reactor licensest & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing B3/03/09 Consolidated Edison Co of New York, Inc lapp 18627 153 24X Fishs 50-600.83/05/09.050904659
- 8303170401 Forwards scheme explaining degraded grid voltage relay circuit provided in 830310 ltr.per 830331 conference call between GE Gears & MB Ryan During surveillance test. each undervoltage relay is made to operate induvidually DALTROFF. S L Philadelphia Electric Co 83/05/13 STGLZ.J F Operating Reactors Branch 4 4pp 18469 242 24X Fiche 50-277.83/05/13.8305170401
- 8305180414 Forwards Peach Dottom procedures supplementing util 830516 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick
 BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER, A Licensing Branch 2 2pp 18482 007 24% Fiche 50-000.83/05/16, 8305180414
- --8305180426 Procedure HPD/CD-3. "Airborne Activity Survey Techniques." including techniques for constant air monitors, portable fixed filter samplers & charcual cartridges philadelphia Electric Co 83/05/16 15pp 18482-009 24X Fichs 50-000,83/05/16,8305180414
- ---8305180431 Procedure HPD/CD-65, "Field Use of Low Vol Portable Air Sampler" * Philadelphia Electric Co 83/05/16 2pp 18482 024 24X Fiche 50-000,83/05/16,8305180414
- ---8305180438 Procedure HPA-63d, "Calibr of Ventilation Sys Radiation Monitors" Philadelphia Electric Co 83/05/16 8pp. 18482 026 24X Fichs 50-000,83/05/16,8305180414
- --8305180443 Procedure HPA-77, "Determination of Max Permissible Concentration Hours" + Philadelphia Electric Co 83/05/14 5pp 18482 034 24X Fiche 50-000,83/05/14:8305180414

- 8305230318 Notification of 830520 meeting w/util in Bethesda.MD to discuss pipe cracks GEARB.0 Operating Reactors Branch 4 83/05/16 STOLZ.J Operating Reactors Branch 4 2pp 18543 304 24X Fiche 50-277.83/05/14.8305230318
- 8305240429 Forwards electric equipment mod schedule for qualification or replacement of remaining electrical equipment & qualification programs for equipment not previously described.per 830322 request
 DALTROFF.S L. Philadelphia Electric Co. 83/05/20 STOLZ, J.F. Operating Reactors Branch 4 & pp. 18574 186 24X
 Fiche 50-277.83/05/20,8305240428
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list anc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co of New York, Inc 112pp 18308 317 24X Fiche 30-000.83/03/21.8212060388
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8305030139 Forwards notice of violation from insp on 820520-0806 6TAROSTECKI.R Division of Project & Resident Programs 83/04/18 DALTROFF, 8 L Philadelphia Electric Co 2pp 18300 282 24X Fiche 50-277, 83/04/18, 6305030139
- --8305030145 Notice of violation from insp on 820520-0806 Noncompliance noted during performance of Special Procedure 518, containment penetration block valves were in closed & tagged closed condition # Region 1, Office of Director 83/04/18 ip 18300 284 24% Fiche 50-277,83/04/18,8305030139
- B305050141 Forwards IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/04/21 DALTROFF, B L Philadelphia Electric Co 2pp 18341 108 24X Ficha 50-277,83/04/21.8305050141
- --8305050147 IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted Major areas inspected induction heating stress improvement procedures used to mitigate intergranular stress corrosion cracking REYNOLDS.8 D Region 1. Office of Director DURR.J Division of Engineering & Technical Programs 83/04/21 8pp 18341 110 24X Fiche 50-277,83/04/21,8305050141
- 8303040023 IE Info Notice 83-22, "BWR Safety/Ralief Valve Failures "
 Svc list encl
 JCRDAN,C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 30-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Senting Sys " Syc list encl JDRDAM,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 1199p 18381 271 24X Piche 50-000,83/04/25,8303040025.
- 8305020343 Confirms 830506 enforcement conference in King of Prussia, PA to discuss operation in excess of limiting condition for operation for primary containment integrity & inadequate review of proposed mods
 8TAROBTECKI, R. Division of Project & Resident Programs 83/04/25, bALTROFF, 8 L. Philadelphia Electric Co. 2pp 18276-325 24X Fiche 50-277, 83/04/25, 8305020343
- 8305060313 Forwards payment in response to NRC 830927 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, fills for collection & affidavit encl

 BOYER, V 8 Philadelphia Electric Co 83/04/27, Director's Office, Office of Inspection and Enforcement 36pp 18348 167 24X Fiche: 50-277, 83/04/27, 8305060513
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28. Consolidated Edison Co. of New York, Inc 115pp 18382:047 24X Fiche 50-000,83/04/28,8303040026

- B303040027 IE Info Notice B3-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3704/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24% Fiche 50-000,83704/28.8303040027
- B305110261 Forwards IE Insp Repts 50-277/B3-07 & 50-278/B3-07 on 830315-21 & notice of violation MARTIN.T T Division of Engineering & Technical Programs B3/04/29 DALTROFF: B L Philadelphia Electric Co 3pp 18373 160 24X Fiche 50-277. B3/04/27, B305110261
- --8305110265 Notice of violation from Insp on 830315-21 + Region 1, Office of Director 83/04/29 1p 18393 163 24X Fiche 50-277,83/04/29,8305110261
- --8305110267 IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 Noncompliance noted failurs to post radiation area around reactor water cleanup skid COLLINS.D J. SHANBAKY.M M Region 1. Office of Director 83/04/28 11pp 18393 164 24X Fiche 50-277.83/04/29.8305110261
- 8305200100 Forwards safety evaluation & technical evaluation rept re util requests for relief from inservice insp requirements Partion of requests granted STOLZ, J. F. Operating Reactors Branch 4 83/05/02 BAUER, E. Q. Philadelphia Electric Co. App. 18340 154 24X Fiche: 50-277, 83/05/02, 8305200100
- --8305200107 Safety evaluation re requests for relief from inservice insp requirements

 * Office of Nuclear Reactor Regulation, Director 83/05/02 8pp i8540 158 24X Fiche, 50-277, 83/05/02, 8305200100
- --8305200110 "Inservice Insp Program," technical evaluation rept * Science Applications, Inc NRC-03-82-096 186-028-14 82/09/10 NRC - No Detailed Affiliation Given 27pp 18540 166 24X Fiche 50-277,83/05/02,8305200100
- --8305200238 Notice of granting relief from ASME Code insp requirements 8TOLZ.J F Operating Reactors Branch 4 83/05/02 2pp 18540 194 24% Fiche 50-277.83/05/02.8305200100
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Bvc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp, 1844i 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 30-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of Naw York: Inc 119pp, 18441 001 24X Fiche 50-000,83/05/04.8303040031.
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EDP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524.003 24X Fiche 50-000, B3/05/11, B303040034.
- 8303250299 Forwards IE Insp Repts 50-277/83-20 & 50-278/83-10 on 830321-25 & notice of violation MARTIN.T T Division of Engineering & Technical Programs. 83/05/13 DALTROFF, B L Philadelphia Electric Co 2pp 18592 048 24X Fiche 50-277,83/05/13,8305250299
- --8305250303 Notice of violation from insp on 830321-25 * Region I, Office of Director 83/05/13 2pp 18592.050 24X Fiche: 50-277, 83/05/13, 8305250299

- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830(03) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Natice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- *B305120473 LER 83-008/03L-0 on B30407, MPCI high steam flow isolation switch DPIS-2-23-77 setpoint found above Tech Spec limit Caused by setpoint drift of Barton Model 288 Instrument recalion, tested & returned to svc CODNEY, M J Philadelphia Electric Co B3/04/21 ALLAN, J M Region 1. Dffice of Director 1p 18431 071 24X Fiche 30-277, 83/04/21, 8305120473
- B30512035B LER B3-007/03L-D on B30324, during surveillance testing, smoke detector in drywell failed to provide audible alarm code or annunciate in control room Caused by defective detector circuit board Board replaced, tested & returned to svc CCONEY, M J Philadelphia Electric Co 83/04/22 ALLAN, J M Region 1, Office of Director 1p 18434 047 24X Fiche 50-277, B3/04/22, B305120358
- 8305060513 Forwards payment in response to NRC 830329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidevit encl.

 BOYER, V S Philadelphia Electric Co 83/04/27 Director's Office. Office of Inspection and Enforcement 36pp (8348 167 24x Fichs 50-277,83/04/27,8305060513
- B3050603B7 PNO-I-B3-045 on B30503, shutdown initiated due to containment pressure increase to 0.6 psi & unifertified containment leakage of 5.4 gpm Recirculation pump cooling water leakage noted MCCABE, E. KEIMIO, R. Region 1, Office of Director 83/05/03 ip 18343 165 24X Fiche 50-277,83/05/03,83050603B7
- 8305110316 LER 83-007/03L-0 on 830404 narrow range torus level transmitter LT 8027A determined to be out of califr Caused by instrument drift instrument recalifr & returned to svc COUNEY, M J Philadelphia Electric Co 83/05/03 ALLAN, J M Region 1, Office of Director 1p 18393 159 24X Fiche 50-277,83/05/03,8305110316
- 8305060558 PNO-I-83-045A on 830503 drywell entry identified packing leak on recirculation pump discharge header cross connect motor operated valve MO-65A Cause not stated Region I will respond to media inquiries MCCADE. KETMIQ Region 1. Office of Director 83/05/04 ip 18348 262 24X Fiche 50-277,83/05/04.8305060558
- 8305270235 LER 83-0il/DIP on 830506, ultrasonic testing indicated crack in RHR shutdown cooling suction line Caused by intergranular stress corrosion cracking Crack analysis program implemented to determine corrective actions FLEISCHMANN, R Philadelphia Electric Co 83/05/06 ALLAN, J M Region 1. Office of Director 2pp 18637 198 24X Fiche 50-277,83/05/06,8305270235
- B305120412 PND-I-83-0458 on B30503, witrasonic testing conducted on Bample 2 recirculation riser welds & one RHR weld on Unit 2 to determine if Unit 3 crack indications exist on Unit 2 RHR showed cracks on both pipe & elbow side BLOYOH, MCCABE Region 1. Office of Director B3/05/09 ip 18431 153 24X Fiche, 50-277, 83/05/09, 8305120412
- 8308270184 LER 83-012/01P on 830511.insp of fire barrier penetrations revealed inadequacies in penetration seaks Caused by const or design error & inadequate initial insp Fire watches posted & addi insps initiated FLEISCHMANN.R Philadelphia Electric Co 83/05/12 ALLAN.J M Region i, Office of Director 2pp 18637 359 24% Fiche 50-277.83/05/12.8305270184.
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8305040716 Summary of B30405 meeting w/util in Bethesda.MD re status of App R concerning fire protection program mode at facility GEARS.O E Operating Reactors Branch 4 B3/04/25 Operating Reactors Branch 4 3pp 1B328 106 24X Fiche 50-277.B3/04/25.B305040716

- 8305100357 Describes plans for completing fire protection mods re Sections (II F, III G. III J & III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided BOYER.V S Philadelphia Electric Co 83/05/02 EISENHUT, D G Division of Licensing App 18379 033 24X Fiche 50-277, 83/05/02, 8305100359
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 169p 18540-095 24X
 Fiche 30-000,83/05/11,8305110034
- 8305190522 Notification of B30526 meeting w/util in Bethesda.MD to discuss elternative safe shutdown.App R GEARS.G Operating Reactors Branch 4 83/05/17 STOLZ.J Operating Reactors Branch 4 2pp 18523 IS6 24X Fiche 50-277.83/05/17.8305190522

G Adjudicatory correspondence

- 8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Absorbe dissenting views encl CHIKK B J Office of the Secretary of the Commission 83/03/31 Commissiones 3pp 17807 049 24X Fiche 50-000.83/03/31, e20040407
- B305060250 Order extending time until 830513 for Commission to act to review ALAB-701
 HOYLE.J C Office of the Secretary of the Commission 83/05/05
 Commissioners 1p 18345 196 24% Fiche 50-000.83/05/05
- B305130060 Response apposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest PALLADING.N J. Commissioners B3/09/11 2pp 18436-228 24X Fiche 50-000.83/05/11.8305130060
- B305130061 Order extending time until B30520 for Commission to act to review petition for review of ALAB-701 CMILK.S J Office of the Secretary of the Commission B3/05/12 Commissioners ip 18437 039 24X Fiche 50-000, B3/05/12, B306130061
- 8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 patition for review of ALAB-701 CHILK:8 J Diffice of the Secretary of the Commission 83/05/19 Commissioners to 18514 283 24X Fiche 50-000.83/05/19, 8305200560
- 8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl CHILK, S J Office of the Secretary of the Commission 83/05/27 14pp 18653 3|1 24X Fithe 30-000, 83/05/27.8305310017

J Insurance & indemnity information

- 8305240307 Forwards Endorsements 1,2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection BRADLEY,E J Philadelphia Electric Co 83/05/17 SALTIMAN, J Assistant Director for State & Licensee Relations 41pp 18548 141 24X Fiche 50-277,83/05/17,8305240307
- P Operating license stage documents & correspondence
- 8305040704 Summary of 830323 meeting w/util in Bethesda, MD re technical presentation on GE-hybrid control rods assemblies currently proposed for installation OEARS, G E Operating Reactors Branch 4 83/04/22 Operating Reactors Branch 4 3pp 18336 335 24X Fichs 50-277.83/04/22, 8305040704
- 8305020099 Responds to 830322 Itr re clarification of safety evaluation for environ qualification of safety-related electrical equipment Revised justifications for continued operation and DALTROFF,S L Philadelphia Electric Co 83/04/27 STOLZ,J F Operating Reactors Branch 4 12pp 18279 241 24X Fiche 50-277.83/04/27.8305020099

- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to CLs Svc list encl EISENHUT.D & Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- B3050606B4 Notification of B30506 meeting w/util in Bethesda.MD to discuss recent crack-like indications discovered in recirculation sys

 OEARS.O Operating Reactors Branch 4 83/05/03 STOLZ.J

 Operating Reactors Branch 4 2pp 18357 311 24X

 Fiche 50-278.83/05/03.8305060684
- 8303030021 Forwards application for amend to Licenses DPR-44 & DPR-36 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing BRADLEY, E. J. Philadelphia Electric Co. 83/05/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 18342 106 24x Fichs 30-277,83/05/04,8305050021
- --8305050027 Application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing DALTROFF, S. L., BRADLEY, E. J. Philadelphia Electric Co. 83/05/04 6pp. 18342 107 24X Fiche 50-277,83/05/04,8305050021
- --8309050033 Proposed changes to Tech Specs re limitations on & monitoring requirements for iodina concentrations in reactor coolant # Philadelphia Electric Co 83/05/04 5pp i8342 113 24X Fiche 50-277.83/05/04.8305050021
- 8305180007 Forwards Amend 92 to License DPR-56, safety evaluation & notice of issuance & availability Amend revises Tech Specs for reactor operation w/Reload 5 core during Cycle 6 GEARS, G & Operating Reactors Branch 4 83/05/04 BAVER, & G Philadelphia Electric Co 4pp 18497 161 24X Fiche 50-278, 83/05/04, 8305180007
- --8305180008 Amend 92 to License DPR-56.permitting reactor operation w/Reload 5 core during Cycle 6 STOLZ.J F Operating Reactors Branch A 83/05/04 12pp 18497 165 24X Fiche 50-278,83/05/04,8305180007
- --8305180011 Safety evaluation supporting Amend 92 to License DPR-56 • Office of Nuclear Reactor Regulation Director 83/05/04 19pp 18497 177 24X Fiche 50-278.83/05/04.8305180007
- --9305180014 Notice of issuance & availability of Amend 92 to License DPR-56 STGLZ,JF Operating Reactors Branch 4 93/05/04 2pp 18497 196 24% Fiche 30-278,83/05/04,8305180007
- 8303090639 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 30-000,83/05/09,8305090659
- 8305170401 Forwards scheme explaining degraded grid voltage relay circuit provided in 830310 ltr.per 830331 conference call detween GE Grars & MB Ryam During surveillance test.rach undervoltage relay is made to aperate individually pALTROFF; S.L. Philadelphia Electric Co. 83/05/13 STDLZ, J F. Operating Reactors Branch 4 4pp 18469 242 24% Fiche 30-277.83/05/13,8305170401
- 8305180414 Forwards Peach Bottom procedures supplementing util 830516 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick URADLEY.E J Philadelphia Electric Co 83/05/16 BCHWENCER, A Licensing Branch 2 2pp 18482 007 24X Fiche 50-000, 83/05/16, 8305180414
- --8305180426 Procedure HPD/CO-3, "Airborns Activity Survey Techniques," including techniques for constant air monitors, portable fixed filter samplers & charcoal cartridges * Philadelphia Electric Co. 83/05/16 15pp 18482,009 24X Fiche 50-000,83/05/16,8305180414
- --8305180431 Procedure HPO/CO-65, "Field Use of Low Vol Portable Air Sampler " * Philadelphia Electric Co 83/05/16 2pp 18482 024, 24X Fiche 30-400,83/05/16,8305180414

- --8309180438 Procedure HPA-63d, "Calibr of Ventilation Sys Radiation
 - Philadelphia Electric Co 83/05/16 8pp 18482 026 24x Fiche 50-000, 83/05/14, 8305180414
- --8305180443 Procedure HPA-77, "Determination of Max Permissible
 - Concentration Hours " * Philadelphia Electric Co 83/05/16 Spp 18482 034 24x Fiche 50-000, 83/05/16, 8305180414
- 8305230318 Notification of 830520 meeting w/util in Bethesda. MD to
- discuss pipe cracks GEARS.O Operating Reactors Branch 4 83/05/16 Operating Reactors Branch 4 2pp 18543 304 24X Fichs 50-277.83/05/16.8305230318
- 830524042B Forwards electric equipment mod schedule for qualification or replacement of remaining electrical equipment & qualification programs for equipment not previously described, per 830322 request
 DALTROFF, B L Philadelphia Electric Co 83/05/20 SYOLZ, J F Operating Reactors Branch 4 6pp 18574 186 24X
 Fiche 50-277,83/05/20,8305240428
- Q Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc l
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emercency Use Respirator "
- SOURCE INTO NOTICE 83-21. "DEFECTIVE EMERGENCY ONE RESPIRATOR"

 JORDAN, E.L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New

 York, Inc. 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021
- B305030139 Forwards notice of violation from insp on 920520-0806 BTARDSTECKI,R Division of Project & Resident Programs B3/04/18 DALTROFF,B L Philadelphia Electric Co 2pp 18300 282 24X Fiche 30-277,83/04/18,8305030139
- --8305030145 Notice of violation from insp on 820520-0806 Noncompliance noted during performance of Special Procedure 518, containment penetration block valves were in closed & tagged closed condition

 * Region 1, Office of Director 83/04/18 ip 18300 284 24X Fiche 50-277,83/04/18,8305030137
- 8305050141 Forwards IE Insp Repts 50-277/83-08 & 50-278/83-08 on #830307-09 No noncompliance noted
 #ARTIN-T T Division of Engineering & Technical Programs 83/04/21
 DALTROFF,B L Philadelphia Electric Co 2pp 18341 108 24X
 Fiche 50-277.83/04/21,8303050141
- --8305050147 IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted, Major areas inspected induction heating stress improvement procedures used to mitigate intergranular stress corrosion cracking REYNOLDB, 8 D Region I, Office of Director DURR, J Division of Engineering & Technical Programs 83/04/21 8pp 18341 110 24 Fiche 50-277, 83/04/21, 8305050141
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures " Byc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305020343 Confirms 830506 enforcement conference in King of Prussia. PA to discuss operation in excess of limiting condition for operation for primary containment integrity & inadequate review of proposed mode

 STAROSTECKI, R Division of Project & Resident Programs 83/04/
 DALTROFF, B L Philadelphia Electric Co 2pp 18276 325 24X
 Fiche 30-277,83/04/25,8305020345,
- 8305060513 Forwards payment in response to NRC B30329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidavit encl
 BOYER, V. S. Philadelphia Electric Co B3/04/27 Director's Office, Office of Inspection and Enforcement 36pp, 18348 167 Fiche 50-277,83/04/27,8305060513,

- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Rosponse (Post 830103) 83/04/28 Consolidated Edison Co Post 830103) 83/04/28 Consolidated Edison Co of New 115pp 18382 047 24x Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice B3-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN.E L Division of Emergency Preparedness " Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc ii8pp i8382 i65 244 Fiche 50-000.B3/04/28.B303040027
- 83051i0261 Forwards IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/04/29 DALTROFF. S. Philadelphia Electric Co 3pp 18393 i60 24X Fiche 50-277.83/04/29.8305i1026i
- --8305110265 Natice of violation from insp on 830315-21 * Region 1, Office of Director 8304/27 ip 18373 163 Fiche 50-277.83/04/29,8305110261
- --8305110267 IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 Noncompliance noted failure to post radiation area around reactor water cleanup skid COLLINS, D J . SHANDAKY.M M Region 1, Office of Director 83/04/28 iipp 18393 164 24X Fiche 50-277.83/04/27.8305110261
- B305200100 Forwards safety evaluation & technical evaluation rept re util requests for relief from inservice insp requirements Portion of requests granted STOLZ.J F Operating Reactors Branch 4 83/05/02 BAUER.E G Philadelphia Electric Co 4pp iB340 154 24X Fichs 30-277.83/05/02.8305200100
- --8305200107 Bafety evaluation re requests for relief from inservice
- --8305200110 "Inservice lnsp Program," technical evaluation rept

 * Science Applications, Inc. NRC-03-82-096 186-028-14
 62/09/10 NRC No Detailed Affiliation Given 27pp
 18340 166 24x Fiche 30-277, 83/05/02.8305200100
- --B305200238 Notice of granting relief from ASME Code insp requirements STDL2.JF Operating Reactors Branch 4 83/05/02 2pp 18340 196 24X Fiche 50-277.83/05/02.8305200100
- B303040028 IE Info Notice B3-26. "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN: E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York: Inc 122pp 18441 i70 24% Fichs 50-000.83/03/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-29, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18923 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Natice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New Post 830103) 83/05/11 Consolidated Edison Co of New 114pp 18924 003 24% Fiche 50-000.83/05/11.8303040034
- B305250299 Forwards IE Insp Repts 50-277/83-20 & 50-278/83-10 on ASSISTANT Formarks of the programs of the programs B3/05/13 MARTIN.T T Division of Engineering & Technical Programs B3/05/13 DALTROFF, B L Philadelphia Electric Co 2pp 18592 048 24X Fichs 50-277, B3/05/13, B303250299
- --B305250303 Notice of violation from insp on 830321-25 , * Region i. Office of Director 83/05/13 2pp 18592 050 24X Fiche 50-277,83/05/13,8305250299

- --8305250306 IE Insp Repts 50-277/83-10 & 50-278/83-10 on 830321-25
 Noncompliance noted lack of administrative controls,
 nontraceability of instrument usage & exceeding instrument
 calibr due date in measuring & test equipment area
 SMAUBLE T , MEYER, 0 W , PRELL , J A Region 1, Defice of Director
 83/05/11 | 15pp | 18592 | 052 | 24X Fiche 50-277,83/05/13,8305250299
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 8vc list encl
 JORDANNEL Division of Emergency Preparedness & Engineering
 Response (Post 820103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18497 009 24X Fiche 50-000.83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- # Reportable occurrences, LERs & related correspondence
- B305110340 Forwards LER B3-011/01T-0 Detailed event analysis submitted COONEY, M J Philadelphia Electric Co 63/04/21 ALLAN, J M Region 1. Office of Director 3pp 1840a [54 24x Fiche 50-278, 83/04/21, 830510340
- --8305110349 LER 83-011/01T-0 on 830407.loss of control rod position indication occurred from control rods 22-47.38-31 & 34-15 Caused by improper use of jumper procedure on 830311.26 & 0402 Jumpers removed Jumper procedure suspended CGDNEY.H J Philadelphia Electric Co 83/04/21 Region 1. Office of Director 1p 18406 157 24X Fiche 50-278.83/04/21, 8305110340
- 8305030118 PNO-I-83-038.on 830425, three 1-inch long axial indications the discounterential indication in heat affected zone of recirculation pump riser discovered Caused by intergranular stress corrosion cracking 8L000M, MCCABE Region 1, Office of Director 83/04/26 1p 18308 187 24X Fiche 30-278,83/04/26,8305030118
- 8305270117 LER 83-012/01P, on 830425, analysis of radiographs & ultrasonic testing data indicated presence of four crack-like indications in O reactor recirculation sys riser of loop A Caused by intergranular stress corresion cracking FLEIBCHMANN, R Philadelphia Electric Co 83/04/26 ALLAN, J M Region 1. Office of Director 2pp 18638 166 24% Fiche 50-278,83/04/26,8305270117
- 8305020337 PND-I-83-036A on 830427, recirculation loop A riser exam completed One weld in each of two risers had crack indications Data forwarded to 0E for more detailed analysis Licensee addressing repair method & impact on outage 8LDUCH, MCCABE. E Region 1, Office of Director 83/04/27 1p 18277-134 24x Fichs 50-278,83/04/27,8305020337
- 8305060513 Forwards payment in response to NRC 830329 notice of violation k imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & effidavit encl
 80YER. V S Philadelphia Electric Co 93/04/27 Director's Office, Office of Inspection and Enforcement Jopp 18348-167 24X Fiche 50-277,83/04/27.8305060513
- 8305270184 LER 83-012/01P on 830511.insp of fire barrier genetrations revealed inadequacies in penetration seals Caused by const or design error & inadequate initial insp Fire watches posted & addi insps initiated FLEISCHHANN.R Philadelphia Electric Co 83/05/12 ALLAN, J H Region 1. Office of Director 2pp 18637 359 24% Fiche 80-277,83/05/12,8305270184

DOCKET 50-280 SURRY POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs, as stated BTEMART; N L Virginia Electric & Power Co 83/03/24 MCQUIRE, D R Division of Emergency Preparadness & Materials Safety 1p 18342:200 24X Fiche. 50-000.83/03/24.8305050126
- #305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on #30301-31 No noncompliance noted #20301-31 No noncompliance noted #20401-11 No #204

- --8305270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event followup & LERs
 BURKE,D J. DAVIS,M J. Region 2. Office of Director JULIAN,C
 Division of Project & Resident Programs 83/04/29 7pp.
 18444 289 24X Fiche 50-280,83/04/29,8305270423
- 8305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EOF) updating 820408 response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities STEMART.W L. Virginia Electric & Power Co. 83/05/06 DENTON.H R. Office of Nuclear Reactor Regulation. Director EIGENHUT.D 0 Division of Licensing 13pp 18436-215 24X Fiche 50-000.83/05/06.8305130058
- 8305110034 OPDETIC Ltr 83-21 to all licensess of operating reactors: applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUI, D 0 Division of Licensing 83/05/11 Consolidated Edigon Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034
- 8305180169 Informs that emergency plan upgrade to meet 10CFR30 App E, NUREO-0737, Item III A 2 1 requirements complete VARGA, 8 A Operating Reactors Branch 1 83/05/13 STEWART, N L Virginia Electric & Power Co 3pp 18502 351 24X Fiche 50-280,83/05/13,8305180169
- P Operating license stage documents & correspondence
- 8305060658 Forwards safety evaluation re NUREG-0737. Items II F 1 4, II F 1 5 & II F 1.6 on containment pressure, water level & hydrogen monitors Util 80(210 submittal & 830218 rev acceptable Environ qualification to be reviewed separately VARCA:8 A Operating Reactors Branch 1 83/04/22 STEHARY. W L Vinginia Electric & Power Co 2pp 18357 357 24X Fiche 30-280.83/04/22,8305040658
- --B305060603 Bafety evaluation re TMI Action Plan Items (NUREQ-0737)
 II F i 4, "Containment Pressure Monitor," II F i 5,
 "Containment Hater Level Monitor" & II F i 5, "Containment
 Hydrogen Monitor " Designs acceptable
 % Office of Nuclear Reactor Regulation, Director 83/04/22 5p
 18357 359 24X Fiche 50-280,83/04/22,8305060658
- 8305090321 Forwards Amend 87 to License DPR-32, safety evaluation & notice of issuance & availability Amend revises Tech Specs to raise control rod bank insertion limits
 NEIGHBORS: J D Operating Reactors Branch 1 83/04/26 BIEHART: W L Virginia Electric & Power Co 2pp 18367 245 24X
 Fiche 50-280:83/04/26.8305090321
- --8305090927 Amend 87 to License DPR-32, revising Tech Specs to raise control rad bank insertion limits
 VAROA,8 A Operating Reactors Branch 1 83/04/26 5ps
 18367 247 24X Fiche 30-280.83/04/26,8305090321
- --8305040331 Bafety evaluation supporting Amend 87 to License DPR-32 * Office of Nuclear Reactor Regulation, Director 83/04/26 2pp 18367 252 24% Fiche. 50-280, 83/04/26, 8305090321
- --8305090335 Notice of Issuance & availability of Amend 87 to License DPR-32 VARGA,S A Operating Reactors Branch I 83/04/26 2pp 18367-254, 24X Fichs 50-280,83/04/26,8305090321.
- 8305070045 Forwards Amend 88 to Licenses DPR-32 & DPR-37, safety evaluation & notice of issuance & availability Amends revise Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers NEIGHBURE, J D Operating Reactors Branch i 83/04/27 STEWART, W t Virginia Electric & Pawer Co 2pp 18381 184 24X Fiche 50-280,83/04/27,8305090045
- --8305090051 Amend 88 to Licenses DPR-32 & DPR-37, revising Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers VAROA & A Operating Reactors Branch 1, 83/04/27 8pp 18381 186 24X Fiche 50-280, 83/04/27, 83050900045
- --8305090062 Safety evaluation supporting Amend 89 to Licenses DPR-32 & DPR-37.

 * Office of Nuclear Reactor Regulation, Director 18391 194 24X Fichs 50-280.83/04/27,8305090045
- --8305090070 Notice of issuance & availability of Amend 88 to Licenses DPR-32 & DPR-37 VAROA:S A Operating Reactors Branch i 83/04/27 2pp 18381.196 24% Fichs 50-280.83/04/27.8305070045

DOCKETED ITEMS

- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D 9 Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche 30-000, 83/05/02/85805020455
- 8305060556 Application for amend to Licenses DPR-32 & DPR-37, changing Tach Specs to allow optimization of core loading patterns & provide addit operating flexibility by changing existing fractional power limit STEWART.W L. Virginia Electric & Power Co. 83/05/02 DENTON, H.R. Office of Nuclear Reactor Regulation. Director VARGA.S. A Operating Reactors Branch 1 8pp 18348 263 24% Fiche 50-280.83/05/02.8305060556
- --8305060361 Proposed Yech Spec pages allowing optimization of core loading patterns & providing addl operating flexibility by changing existing fractional power limit * Virginia Electric & Power Go 83/05/02 22pp 18348 271 24X Fiche 50~280.83/05/02.8305060556
- 830510010B Application to amend Licenses DPR-32 & DPR-37.revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREO-0472 "Offsite Dose Calculation Manual" also enci BTEHART.W L Virginia Electric & Power Co 83/05/04 DENTON.H R Office of Nuclear Reactor Regulation, Director VARGA.8 A Operating Reactors Branch 1 3pp 18371 346 24X Fiche 50-280,83/05/04,830510010B
- --8305100111 Proposed revs to radiological effluent Tech Specs.in accordance w/Rev 3 to NUREG-0472 * Virginia Electric & Power Ca 83/05/04 87pp 18371 347 24X Fiche 50-280,83/05/04,8305100108
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl
 EISENHUT, D 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 193 24X
 Fiche 50-000,83/05/09,8305090659
- B3051B0372 Forwards response to B30404 ltr re Category IV equipment Equipment qualification file packages submitted in support of specific identified items, Response to B30126 ltr re proposed corrective actions expected by B30520 BTEKART.W L. Virginia Electric & Power Co. B3/05/11 DENTON, H f Office of Nuclear Reactor Regulation, Director VAROA, S A Operating Reactors Branch 1 771pp 18483 120 24X Fiche 30-280, B3/05/11, B305180372
- 8305200163 Responds to 830126 & 0404 requests to review proprietary mat1 contained in Franklin Research Ctr technical avaluation repts re environ qualification of safety-related electrical equipment Info no longer requires proprietary protection SYEHART, H. Virginia Electric & Power Co 83/03/11 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 ip 18319 070 24X Fiche 50-280,83/05/11,8305200163
- 8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
 8TEMARTH L Virginia Electric & Power Co 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director. EISENHUT.D. 0
 Division of Licensing 19pp 18313 182 24X Fiche 30-000,83/05/12,8303200499
- B305260232 Submits schedule for replacement or med of safety-related equipment for environ qualification per 10CFR30 49(g) criteria Mester list of equipment encl
 BTEWART.W L. Virginia Electric & Power Co. 83/05/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director VARGA, B. A. Operating Reactors Branch 1 60pp 18622 127 24%
 Fiche. 50-280, 83/05/20, 8305260232
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J. M. Division of Bafeguards & Inspection Programs (Post 830109) 83/03/21, Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 30-000,83/03/21,8212060885
- 8305270565 Forwards IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/03/29 BTEMART.W L. Virginia Electric & Power Co. 2pg 18647-172, 24X Fiche: 50-280, 83/03/29, 8305270565

- --B305270374 IE Insp Repts 50-280/B3-06 % 50-281/B3-06 on B30222-25 No noncompliance noted Majo: areas inspected inservice testing of pumps & valves, secondary coolant chemisty program, inservice insp & LERS
 OIRARD, E H , ROSS, H J , BLAKE, J J Region 2, Office of Director B3/03/25 9pp 18647 174 24X Fichs 30-280, B3/03/27, B305270565
- #305270483 Forwards IE (nsp Repts 50-280/03-08 & 50-201/03-08 on 830201-28 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/04 STEWART, H L Virginia Electric & Power Co 2pp 18662 142 24X Fiche 30-280, 83/04/04, 8305270483
- --8305270490 IE Insp Repts 30-280/83-08 & 50-281/83-08 on 830201-28 No noncompliance noted Major areas inspected plant operations & operating records, plant maint & surveillance, plant security, followup of events & LERs

 BURKE, D J , DAVIS, M J Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 83/04/01 5pp

 18662 144 24X Fiche 50-280,83/04/04,8305270483
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc 11st encl JURDBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Eve list enel JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704722 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 50-000,83704722,8303040023
- 8305100315 Forwards response to 830324 notice of violation & proposed imposition of civil penalty Corrective actions engineering safeguards valve check list revised & added to startup procedure & sys valve lineups now required BTEMART, W.L. Virginia Electric & Power Co. 83/04/22 DEYOUNG, R.C. Director's Office. Office of Inspection and Enforcement Spp. 18370 001 24X Fiche 50-280.83/04/22,8305100315
- B305270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety
 D'REILLY.J P Region 2, Office of Director 83/04/22 STEWART.W L
 Virginia Electric & Power Co. 2pp 18646 001 24X
 Fiche 50-000.83/04/22,8305270513
- --8305270527 Forwards SALP Repts 50-280/83-02,50-281/83-02,50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1782 LENISR C Division of Project & Resident Programs 83/02/10 STEMART. W. L. Virpinia Electric & Power Co 2pp 18646 003 24X Fiche 50-000,83/04/22,8305270513
- --B305270541 SALP Repts 50-280/83-02,50-281/83-02,50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 * Region 2: Office of Director 83/02/10 45pp 18646.005 24X Fichs 50-000,63/04/22,6305270513
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 291 24X Fiche 50-000, 83/04/25 8303040025
- 8305090029 Grants 830316 request for relief from 1980 ASME Section XI requirements for inservice insp hydrostatic tests. Relief permits drain & manual isolation valve replacement in main steam sys w/o performing hydrostatic tests for entire says. VAROA: 8 A Operating Reactors Branch i 83/04/27 STEWART, W L Virginia Electric & Power Co. 3pp 18381 200 24X Fiche 50-280.83/04/27,8305090029
- --8305070037 Notice of granting of relief from ASME Code requirements for inservice insp hydrostatic tests
 VAROA.8 A Operating Reactors Branch 1 83/04/27 2pp
 18381:203 24% Fiche 50-280.83/04/27,8305070029
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list and " JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 93/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Sys Heater High Yemp Trip Setpoint Adjustment" Syc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Editon Co. of New York, Inc. 1189p. 18382 165 24X Ficher 50-000.03/04/28,8303040027

- 8305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301°31 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/29 STEMART,N L Virginia Electric & Power Co 2pp 18644 287 24) Fiche 50-280,83/04/29,8305270423
- --8305270437 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event follows & LERs
 BURKE, D. J. DAVIS, M. J. Region 2, Office of Director JULIAN, C
 Division of Project & Resident Programs 83/04/29 7pp
 18644 289 24X Fiche 50-280,83/04/29,8303270423
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Cansolidated Edison Co of New York, Inc. 1220p 18441 170 244 Fiche 50-000.83/05/03.8303040028
- B305090139 Forwards payment of civil penalty imposed for valve infraction reported in Enforcement Action EA 82-143
 STEWART, W.L. Virginia Electric & Power Co. 83/05/03 DEYOUNG, R.C. Director's Office. Office of Inspection and Enforcement 3pp 18364 049 24x Fichs 50-280.83/05/03.8305090139
- 8305270242 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-03 & 50-281/83-05 DANCE.H C Division of Project & Resident Programs 83/05/03 STEMART.W L Virginia Electric & Power Co ip 18642 025 24X Fiche 50-280/83/05/03.8303270242
- --B105270248 Responds to NRC 830311 ltr re violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05 Corrective actions Administrative Procedure ADM-B revisioned W/staff assistant & notice of violation & response posted STEMART.W L. Virginia Electric & Power Co. 83/04/08 O'RETLLY, J. P. Region 2. Office of Director. 2pp. 18642-026. 24X Fishe 50-280,83/05/03,8305270242
- --8305270252 Forwards IE Insp Repts 30-280/83-05 & 50-281/83-05 on 830207-11 & notice of vigiation DANCE: HC Division of Project & Resident Programs 83/03/11 STEMART: W L Virginia Electric & Power Co 2pp 18642 028 24x Fiche 30-280.83/05/03.8305270242
- --8305270257 Notice of vialation from insp on 830207-11 • Region 2, Office of Director 83/03/11 ip 18642 030 24X Fiche 30-280,83/05/03,8305270242
- --8305270265 IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 Noncompliance nated failure to post natice of violation & licensee response to IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821221 HOSEY, C M. BARR, K, P. Region 2, Office of Director 83/03/08 7pp 18642 031 24X Fiche 50-280/83/05/03/8305270242
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830102) 83705704 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000.83705704,8303040030
- 8303040031 IE Info Notice 83-28; "Criteria for Protective Action Recommendations for General Emergencies" Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705704 Consolidated Edison Co of New York Inc 117pp 18441 001 24X Fiche 50-000,83705704,8303040031
- 8305090224 EN-83-030 on 830509. Ratice of violation & proposed imposition of civil penalty in amount of \$40,000 issued to licensee Action based on serious weaknesses in internal & external dose monitoring & procedural compliance FLACK-E. AXELRAD. J Director's Office. Office of Inspection and Enforcement 83/05/04 ip 18363-349 24X Fiche 50-280.83/05/04.8305070224
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list ent! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 85/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 830525054f Discusses IE insp on 830321-25 & forwards notice of violation & proposed imposition of civil penalty O'REILLY.J.P. Region 2. Office of Director 83/05/09 STEWART.W L Virginia Electric & Power Co. 3pp 18595 344 24% Fiche 50-280.83/05/09.8305250541

- --8305250546 Notice of violation & proposed imposition of civil penalty in amount of \$40.000 Noncompliance noted radiation program failed to meet 10CFR20 requirements & Tech Spec provisions in area of worker protection

 O'REILLY.J P Region 1. Office of Director 83/05/09 3pp 18955 347 24X Fiche 50-280,83/05/09,8303250541
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 84X Fiche 50-000,83/05/11.8303040034,
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 12697 009 24X Fiche 50-000, B3/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/26 Consolidated Edison Co. of New York. Inc. 114pp 18647 007 24% Fiche 50-000.83/05/26.8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305100115 Forwards LERs 83-018/03L-0 & 83-019/03L-0

 HILSON, J L Virginia Electric & Power Co 83/03/03 D'REILLY, J P
 Region 2. Office of Director 1p 18375 043 24X

 Fiche 50-280.83/05/03,8305100115
- --8305100120 LER 83-018/03L-0 on B30411. Type C testing (PT-16 4 containment isolation valve leakage) performed during Spring 1983 refueling outage disclosed as-found leakage exceeding allowable rate Caused by normal wear Valves repaired WILSON.J L Virginia Electric & Power Co. 83/05/03. Region 2. Office of Director 2pp 18375-044 24X Fiche 50-280.83/05/03.8305100115
- ~-8305100127 LER 83-017/03L-0 on 83040B, performance of Periodic Test L-PT-378-2 revealed snubbers i-WFPD-MSB-15.1-RC-MSS-115, i-SI-MSS-27A, I-RH-MSS-12 & i-SI-MSB-28 inoperable. Caused by fluid leaks & loose pipe clamp 8nubbers replaced WILSON-J L Virginia Electric & Power Co 83/05/03, Region 2, Office of Director 2pp 18375-046 24X Fiche 90-280, 83/05/03, 8305100115
- 8305130198 Forwards updated LER 83-068/03X-1 WILEON,J L Virginia Electric & Power Co 83/05/06 O'REILLY,J P Region 2. Office of Director ip 18440 077 24X Fiche-50-280.83/05/06.8305130198
- --8305/30203 Updated LER 82-068/03X-1 on 8206/4, fire detection sys discovered to have lost program, rendering sys inoperable Probably caused by inadvertently reset program button Sys reprogrammed & central processing unit installed WILSON.J L Virginia Electric & Power Co 83/05/06 Region 2 Office of Director 3pp 18440 079 24X Fiche 50-280,83/05/06,8305/30/98
- 8305130228 Forwards LER 83-020/03L-0 WILSON J L Virginia Electric & Power Co 83/05/06 D'REILLY.J P Region 2. Office of Director 1p 18439 332 24X Fiche 50-280.83/05/06.8305130228
- --8305130243 LER 83-020/03L-0 on B30408.20 of 58 snubbers failed to meet acceptance criteria stipulated in periodic test Caused by seal degradation Snubbers either readjusted repaired or replaced
 HILBON.J L. Virginia Electric & Power Co. 83/05/06. Region 2. Office of Director. 3pp. 18437-333. 24X Fiche 50-280.83/05/06.8305130228
- 8303130142 PNO-II-83-03B on 830510, safety injection pumps inadvertently actuated during heatup in preparation for restart Caused by loss of vital dc electrical bus Damaged batteries replaced JENISON K M. JULIAN. CA Region 2. Office of Director 839/05/10 p 18438 131 24X Fiche 50-280.83/05/10.8305130142
- DOCKET 50-201 SURRY POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs, as stated STEWART.W L. Virginia Electric & Power Co. 83/03/24 MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety 1p 18342, 200 24X Fiche 30-000, 83/03/24, 8305050126

- 8305270423 Forwards IE Insp Repts 50~280/83-11 & 50~281/83-11 on B30301-31 Ne noncompliance noted DANCE/H C Division of Project & Resident Programs B3/04/29 STEMART.W L Virginia Electric & Power Co 2pp 18644 287 24X Fiche 50~280.83/04/29,8305270423
- --8303270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 pn 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event followup & LERs
 BURKE, D J Region 2, Office of Director 83/04/29 7pp 18644 289 24X Fiche 50-280, 83/04/29, 8305270423
- 8305060100 Requests exemption from 10CFR50 48(c)(4),allowing completion of mods to 10CFR50,App R.Section III G 3 during second refueling outage after 830517
 BTEMARTH W. L. Virginia Electric & Power Co. 83/05/03 DENTON,H R. Office of Nuclear Reactor Regulation, Director VARGA,S A. Operating Reactors Branch 1 1p. 18345 111 24X
 Fiche 50-281,83/05/03,8305060100
- 830513005B Forwards revised submittal describing preliminary plan for smergency operations facilities (EOF) updating 82040B response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities STEWART, W.L. Virginia Electric & Power Co. 83/05/06 DENTON. H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing 13pp 18436-215 24X Fiche 50-000, 83/05/06, 8305130038
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fichs 50-000.83/05/11,8305110034
- 6305180169 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREO-0737. Itam III A 2 1 requirements complete VAROA:8 A Operating Reactors Branch 1 83/05/13 STEWART. W L Virginia Electric & Power Co 3pp 18502 351 24X Fiche 50-280, 83/05/13, B305180169
- P. Operating license stage documents & correspondence
- B3Q5060638 Forwards safety evaluation re NUREQ-0737. Items II F 1 4, II F 1.5 & II F 1 6 on containment pressure, water level & hydrogen monitors Util B01210 submittal & B30218 rev acceptable Environ qualification to be reviewed separately VARQA, B A Operating Reactors Branch 1 83/04/22 STEWART, W L Virginia Electric & Power Co 2pp 18357 357 24X Fiche 50-280, 83/04/22, 8305060658
- --8305060663 Safety evaluation re TMI Action Plan Items (NUREQ-0737)
 II F i 4, "Containment Pressure Monitor," II F i 5,
 "Containment Water Level Monitor" & II F i,5, "Containment
 Hydrogen Monitor " Designs acceptable
 # Office of Nuclear Reactor Regulation, Director 89/04/22 5p
 18357 359 24X Fiche 50-280,83/04/22,8305060658
- 8303070045 Forwards Amend 88 to Licenses DPR-32 & DPR-37, safety evaluation & notice of issuance & availability Amends revise Tach Specs to change schedule requirements for functional testing of 50 KIPB & snubbors NEIOHBORS, J D Operating Reactors Branch i 83/04/27 SYEWART, W L Virginia Electric & Power Co 2pp 19381 184 24X Fiche 50-280,83/04/27.8303070045
- --8305070051 Amend 88 to Licenses DPR-32 & DPR-37.revising Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers VAROA.S A Decrating Reactors Branch 1 83/04/27 Bpp 18381 186 24X Fiche 50-280.83/04/27.8305070045
- --8305070062 Bafety evaluation supporting Amend 88 to Licenses DPR-32 & DPR-37 * Office of Nuclear Reactor Regulation, Director 83/04/27 2pp 18381:174 24X Fiche 50-280,83/04/27,8305070045
- --8305070070 Notice of issuance & availability of Amend 88 to Licenses DPR-32 & DPR-37 VARCALS A Operating Reactors Branch I 83/04/27 2pp 18381 196 24X Fiche 50-280.83/04/27.8305070045
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D.O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24% Fiche, 50-000, 83/05/02, 8305020455

- B305060836 Application for amend to Licenses DPR-32 & DPR-37.changing Tech Specs to allow optimization of core loading patterns & provide addit operating flexibility by changing risting fractional power limit
 STEWART.N L Virginia Electric & Power Co 83/05/02 DENTON.H R
 Office of Nuclear Reactor Regulation. Director VARGA.8 A
 Operating Reactors Branch 1 8pp 18348 263 24X
 Fichs 70-280.83/05/02.83008/05/56
- --8305060561 Proposed Tech Spec pages allowing optimization of core loading patterns & providing addl operating fluxibility by changing existing fractional power limit * Virginia Electric & Power Co 83/05/02 22pp 18348 271 24X Fiche 30-280,83/05/02,8305060556
- 8305100108 Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472 "Offsite Dose Calculation Manual" also encl STEWART, W L. Virginia Electric & Power Co. 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation. Director VARCA, S A Operating Reactors Branch 1 3pp 18371346 24X Fiche 50-280,83/05/04,8305100108
- --8305100111 Proposed revs to radiological efficient Tech Specs.in accordance w/Rev 3 to NUREG-0472

 * Virginia Electric & Power Co 83/05/04 87pp 18371 349 24X
 Fiche 30-280,83/05/04,8305100108
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of GPs re integrated scheduling for implementation of plant mads 8vc list encl EISENBUT, D & Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fiche 50-000.83/05/09.8305090659
- B305120244 Forwards Rev i to "Reload Safety Evaluation for Surry 2 Cycle 7 (Pattern JB2) " Tach Space approved through Amends 86 & 87; require no add1 changes Reload core design will be verified STEWART.W L. Virginia Electric & Power Co. 83/05/09 DENTON.H R Office of Nuclear Reactor Regulation, Director VARGA, S. A. Derrating Reactors Branch i 3pp 18424 183 24X Fiche 50-281.83/05/09, B305120244
- --8305120290 Rev 1 to "Reload Safety Evaluation for Surry 2 Cycle 7 (Pattern JD2)"
 SMITH.N A , SUWAL, G M , CROSS, R W Virginia Electric & Power Co 282 RO1 83/03/31 20pp 18424 185 24X Fiche 50-281, 83/05/09, 8305120244
- 8305180372 Forwards response to 830404 ltr re Category IV equipment Equipment qualification file packages submitted in support of specific identified items Response to 830126 ltr re proposed corrective actions expected by 830520 STEWART, W.L. Virginia Electric & Power Co. 83/05/11 DENTON, H.R. Office of Nuclear Reactor Regulation. Director VARGA, S.A. Operating Reactors Branch 1 771pp 18483 120 24X Fiche 50-280, 83/05/11.8305180372
- 8305200163 Responds to 830126 & 0404 requests to review proprietary mat1 contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment Info no longer requires proprietary protection STEWART, W.L. Virginia Electric & Power Co. 83/05/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director VAROA, 8 A Operating Reactors Branch i 10 18519 070 24X Fiche 50-280,83/05/11,8305200163
- B305200499 Forwards response to Generic Ltr 82-29, "Inadequate Core Cooling Instrumentation Sys," per B30310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
 BTEWART.W L Virginia Electric & Power Co 83/05/12 DENTON.W R
 Office of Nuclear Reactor Regulation, Director EISENHUT.D 0
 Division of Licensing 19pp 18513 182 24X Fiche 50-000, B3/03/12, B3083200499
- 8305240232 Submits schedule for replacement or mod of safety-related equipment for environ qualification per 10CFR30 49(g) criteria Master list of equipment encl BTEMART.W L. Virginia Electric & Power Co. B3/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director VARGA.S A Operating Reactors Branch 1 & Opp. 18622 127 24X Fiche 30-280,83/05/20.8305240232
- O Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spont Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 30-000.83/03/21,8212060385

- 8305270565 Forwards IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/03/29 STEMART.H L Virginia Electric & Power Co 2pp 18647 172 24X Fiche 50-280-83/03/29,8305270365
- --8309270574 IE insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted Major areas inspected inservice testing of pumps & valves-secondary coolant chemisty program, inservice insp & LERS GIRARD,E H. ROSS,W J., BLAKE,J J. Region 2. Office of Director 83/03/25 9pg 18647 174 24x Fiche 50-280.83/03/27,8305270565
- 8305270483 Forwards IE Insp Repts 50-280/83-08 & 50-281/83-08 on B30201-28 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/04 STEWART,W L Virginia Electric & Power Co 2pp 18662 142 24 Fiche 50-280.83/04/04,8305270483
- --8309270490 IE insp Repts 50-280/83-08 & 50-281/83-08 on 830201-28 No nonceapliance noted Major areas inspetted plant operations & perating records.plant maint & surveillance.plant security, followup of events & LERs BURKE.D J. DAVIS.H J. Region 2. Office of Director JULIAN, C A Division of Project & Resident Programs 83/04/01 3pp 18662 144 24X Fiche 50-280.83/04/04.8305270483
- 9303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435-155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 8vc list encl JORDAN,EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- B205270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety G/REILLY.J P Region 2. Office of Director 83/04/22 STEWART.W L Virginia Electric & Power Co 2pp 18646 001 24X Fiche 50-000.B3/04/22.8305270513
- --8305270527 Forwards GALP Repts 50-280/83-02,50-281/83-02,50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 LEHTS,R C Division of Project & Resident Programs 83/02/10 STEUART.H L Virginia Electric & Power Co 2pp 18646 003 24X Fiche 50-000,83/04/22,8305270513
- --8305270541 SALP Repts 50-280/83-02;50-281/83-02;50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 Region 2, Office of Director 83/02/10 45pp 18646 005 24X Fiche 50-000,83/04/22.8305270512
- 8303040025 [E Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of Naw York
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN, C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 30-000,83/04/28,8303040026
- 8303040027 IE Info Notice 63-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Go of New York, Inc 118pp 18382 145 24% Fichp 30-000,83/04/28,8303040027
- 8305270423 Forwards IE Insp Repts 50~280/83-11 & 50~281/83-11 on 830301-31 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/29 STEMART,W L Virginia Electric & Power Co 2pp 18644-287 24X Fich
- --9305270439 JE Insp Repts 50-280/83-11 & 50-281/83-11 on 830901-31 No noncompliance noted Major areas inspected plant operations & operating records maint & surveillance, security event followup & LERS
 BURKE, D J. DAVIS, M J. Region 2, Office of Director JULIAN, C. Division of Project & Resident Programs, 83/04/27 7pp 18644 289 24% Fiche 50-280,83/04/29,8305270423

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness > Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8305060061 Advises that first 10-yr inservice insp program interval artended to 841108, per ASME Section XI 1974 Edition, Summer 1975 addenda STEWART, W L Virginia Electric & Power Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 ip 18345-051 24X Fiche 50-281, 83/05/03, 8305060061
- 8305270242 Ack receipt of B30408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05 DANCE, H C Division of Project & Resident Programs B3/05/03 STEMART.H L Virginia Electric & Power Ca ip 18642 025, 24% Fichs 50-280,83/05/03,8305270242
- --B305270248 Responds to NRC B30311 ltr re violations noted in IE Insp Rapts 50-280/83-05 & 30-281/83-05 Corrective actions Administrative Procedure ADM-B reviewed w/staff assistant & notice of violation & response posted STEMART.W L Virginia Electric & Power Ca B3/04/08 O'REILLY.J P Region 2. Office of Director 2pp 18642 026 24X Ficha 50-280.83/05/03,8305270242
- --8305270252 Forwards IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 & notice of violation DANCE.H C Division of Project & Resident Programs 83/03/11 STEMART.H L Virginia Electric & Power Go 2pp 18642 028 24X Fiche.50-280,83/05/03,8305270242
- --8305270257 Notice of Violation from insp on 830207-11 = Region 2, Office of Director 83/03/11 1p 18642 030 24X Fiche 50-280, 83/05/03, 8305270242
- --B305270265 IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 Noncompliance noted failure to post notice of violation & licensee response to IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821221 HOSEY, C M , BARR, K P. Region 2, Office of Director 83/03/08 7pp 18642 031 24x Fiche 50-280,83/05/03,8305270242
- 6303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl URDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/03/04. Consolidate Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83/05/06 Consolidated Edison Co of New York, Inc 1155p 18523 248 24X Fiche 30-000,83/05/06.8303040033.
- 830525054: Discusses IE insp on 830321-25 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J.P. Region 2, Office of Director 83/05/09 STEWART, W.L., Virginia Electric & Power Co. 3pp 18595
- --8305250946 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted radiation program failed to meet 100FR20 requirements & Tech Spec provisions in area of worker protection O'REILLY.J P Region 1, Office of Director 83/05/09 5pp 18595 347 24% Fiche 50~280,83/05/09,8305250541
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list and.

 JORDANJE L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.
- 8303040040 IE Info Nutice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl.
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697.009, 24X Fiche 50-000,83/05/19,8303040040.

- 8303040046 IE Info Notice 93-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences. LERs & related correspondence
- B305050118 Forwards LER\$ 83-015/03L-0 & B3-016/03L-0
 HILBON, J L Virginia Electric & Power Co B3/04/27 O'REILLY, J P
 Region 2. Office of Director lp 18341 338 24X
 Fiche 30-281, 83/04/27, 8303050118
- --8305050121 LER 83-016/03L-0 on 830329, signal from 8 steam line pressure transmitter PT-2-485 increased approx 300 mv.rendering transmitter inoperable Cause not determined Basis adjusted & transmitter calibr & returned to svc
 WILSON.J L Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 2pp 18341 339 24X Fiche 50-281,83/04/27, 8305050118
- --8309050130 LER B3-015/03L-0 on B30402.PT-27A revealed that amp readings for heat tracing Panel 10 circuit 18 & Panel 11 circuits 2A, 4A & 6B below acceptance criteria Caused by excessive heat Defective heat tracing replaced & design change initiated WILBON, J L. Virginia Electric & Power Co. 83/04/27 Region 2, Office of Director. 2pp. 18341 341 24X Fichs 50-281,83/04/27, 8305030118
- 8305130125 Forwards LERs 83-017/03L-0 & 83-018/03L-0 HILSON.J L Virginia Electric & Power Ca 83/03/06 O'REILLY, J P Region 2. Dffice of Director 1p 18437 291 24X Fiche 50-281, 83/05/06, 8305130125
- --8305130130 LER 83-017/03L-0 on 83040B.at 100% power.amp readings for heat tracing panels 8 & 9.circuit 20B discovered below acceptable limits Caused by excessive heat Defective heat tracing replaced Design changes implemented WILSON.J L Virginia Electric & Power Ca 83/05/06 Region 2, Office of Director 2pp 18437 292 24X Fiche 50-281.83/05/06.8305130125
- --8305130136 LER 83-018/03L-0 on 830404.at 100% power.control rod 8-6 dropped to fully inserted position causing quadrant power tilt or turbine runback Cause unknown Fuses & other components operable Control rod withdrawn MILSON.J L. Virginia Electric & Power Co. 83/05/06. Region 2. Office of Director 2pp. 18437-294. 24X Ficha 50-281.83/05/06. 8305130125
- 8305230424 Forwards LERs 83-019/03L-0 & updated 80-005/01X-1 WILBON, J L Virginia Electric & Power Co 83/05/13 O'REILLY, J P Region 2. Office of Director ip 18538 188 24X Fiche: 50-281, 83/05/13, 8305230424
- --8305230432 LER 83-019/03L-0 on 830415,MOV-LCV-21150 Failed to open during performance of PTIB 4 Caused by motor leads not making contact due to loose plug in terminal strip in motor control ctr, Terminal strip properly seated WILBON.J. L. Virginia Electric & Power Co 83/05/13 Region 2, Office of Director 2pp 18538 189 24X Fiche 50-281,83/05/13,830520424
- --B30523045i Updated LER 80-005/01X-1 on 800304. Type A testing revealed leakage through recirculation spray diaphragm plate seal welds Caused by lack of fusion & slag inclusion in weld areas Defects repaired WILBON, J L Virginia Electric & Power Co 83/05/13 Region 2, Office of Director 3pp 18358 191 24X Fiche 50-281, 83/05/13, 83/05230424
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans
- B305030214 Releases public version of revised emergency plan implementing procedures FELTON, J. M. Division of Rules and Records B3/04/22 Document Management Branch 1p 18310 155 24X Fiche 50-282,83/04/22,830530214
- --8305030221 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-2 re classification of emergencies, F3-5 re emergency notification & F3-9 re emergency evacuation.

 WARD, E C Northern States Power Ca 83/04/08 Region 3, Office of Director ip 18310 156 24% Fichs 50-282,83/04/22,8305030214.

- --8305030226 Public version of revised emergency plan implementing procedures; including Procedure F3-2 re classification of emergences; F3-5 re emergency objection of F3-9 re emergency evacuation of E3-9 re emergency evacuation SCHULLKE.D A Northern States Power Co. 83/03/22 129pp 18310 157 24X Fichs 50-282,83/04/22,8305030214
- B305170657 Forwards exemption from 10CFR50, App R. Subsection III G 2 resparation, fire barrier 5 suppression requirements where both trains of redundant safe shutdown components located within same fire area, per 820630 \$ 1022 requests CLARK, R A Operating Reactors Branch 3 83/05/04 MUSQLF, D M Northern States Power CO 4pp 18481 072 24X Fiche 50-282, 83/05/04, 8305170657
- --8305170666 Exemption from iOCFR50.App R. Subsection III G 2 re separation, fire barrier & suppression requirements where both trains of redundant safe shutdown components located within same fire area EISENMUT.D G Division of Licensing 83/03/04 Northern States Power Co 7pp 18481 076 24X Fiche 50-282,83/03/04.8305170657
- --0305170403 Safety evaluation re exemptions from 10CFR50, App R. Section 151 G 2 requirement for maint of one train of equipment necessary for safe shutdown, wa fire damage Exemptions should be depied in four areas & granted in five areas 4 Office of Nuclear Reactor Regulation, Director 02/10/27 21pp 18401 003 24X Fiche 50-282.03/05/04.0305170657
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18340 095 24X Fiche 50-000,83/05/11,8305110034
- B305190343 Forwards Rev 1 to NUREG-0728, "NRC Incident Response Plan," in response to B30427 ltr requesting updated ltr of agreement W/o encl HIND, J A Division of Radiological & Materials Safety Programs B3/05/13 LARSON, C E Northern States Power Co Zpp 18500 225 24X Fishe 50-000, B3/05/13, B305190343
- B305200023 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness Upgrade Emergency Plans to App E.10CFR50." completed Item closed CLARK, F A Operating Reactors Branch 3 83/05/13 MUS0LF, D M Northern States Power Co 3pp 19540 117 24X Fiche 50-282, 83/05/13, 8305200023
- 8305230523 Forwards clarifying info in support of 830311 exemption requests for 10CFR50 48.App R re Fire Areas 58.59.73 & 74 MUSOLF.D Northern States Power 60 93/05/16 Office of Nuclear Reactor Regulation, Director 62pp 18536 329 24X Fiche 50-282.83/05/16.8305230523
- 8303240389 Advises that date for next annual emergency preparedness exercise revised to 840313, per 830128 telcon PAPERTELLO,C. J. Région 3. Défice of Director 83/05/19 LARSON,C E. Northern States Power Co. 1p. 18575-069 24X Fiche 50-282, 83/05/19, 8305240389
- P Operating license stage documents & correspondence
- 8303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1,539 MHE (summer) net HADLEY.C D Northern Btates Power Co B3/03/15 TOURTELLOTTE.J Regulatory Reform Task Force 6pp 18541 041 24X Fiche 50-000,83/03/15,8303180429
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting
 TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11
 PALLADING.N J Commissioners 2pp 18342 272 24X
 Fiche 50-000.83/04/11.8305230720
- B305020320 Forwards Rev B to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements," per 780201 submittal MUSOLF, D Northern States Power Co B3/04/19 Office of Nuclear Reactor Regulation, Director 2pp iS277 146 24X Fiche 50-282, B3/04/19, B305020320
- --8305020329 Rev 9 to "ABME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements "
 Northern States Power Co 83/04/19 21pp 18277 148 24X Fiche, 50-282, 83/04/19, 6305020320

- 8305060013 Advises that action required by 830202 Amends 61 & 55 to Licenses DPR-42 & DPR-40.respectively 5 Generic Ltr 83-07 completed, based on util actively magnitating w/DDE redisposal of high level waste or spent nuclear fuel CLARK.R A Operating Reactors Branch 3 83/04/21 MUSOLF,D M Northern States Power Co 2pp 18354 311 24X Fiche 50-282.83/04/21,8305060013
- 8305060108 Advises that requirements of NUREG-0737. TMI Action Plan Items II F 1 4.II F 1 5 & II F 1 6 met % items resolved Criteria requiring equipment to be environmentally qualified will be reviewed under environ qualification program CLARK.R A Operating Reactors Branch 3 83/04/21 MUSOLF, D M Northern States Power Co 7pp 18394 268 24X Fiche 50-282, 83/04/21, 8305060108
- 8305060023 Forwards safety evaluation & technical evaluation rept for environ qualification of safety-related electrical equipment Justification for continued operation & schedule for proposed corrective action requested by 830520 CLARKIR A Operating Reactors Branch 3 83/04/25 MUSDLF, D M Northern States Power CO 3pp 18354 322 24X Fiche 50-282.83/04/25,8305060023
- --8305060036 Safety evaluation re environ qualification of safety-related electric equipment Major qualification deficiencies identified in Franklin Research Ctr technical evaluation rept Tables 4-1,4-2,4-3 & 4-4 must be resolved # 0ffice of Nuclear Reactor Regulation. Director 83/04/25 7pp 18354 325 24% Fiche 50-282,63/04/23,6305060023
- B305020455 Generic Ltr B3-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Svc list Encl EISENHUT, D 0 Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305120389 Forwards response to NRC 830425 ltr transmitting safety evaluation for environ qualification of safety-related electrical equipment Rosemount 1153 Series A transmitters should be reclassified as Category II C equipment items MUSOLF.D Northern States Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 29pp 18433 124 24X Fiche 50~282.83/05/05.8305120389
- 8303090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT.D 0 Division of Licensing 93/05/09 Consolidated Edison Co of New York, Inc. 15pp 18627 153 24X
 Fiche 30-000.83/05/09.8305090659
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent for Exchange Resin Susceptibility to Exothermic Chemical Reaction "Svc Jist encl TAYLOR: J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B305020320 Forwards Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief From ASME Code Section XI Requirements," per 780201 submittal
 MUSDLF.D Northern States Power Co 93/04/19 Office of Nuclear Regulation, Director 2pp 18277 146 24X
 Fiche 50-282,83/04/19,8305020020
- ~-8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " # Northern States Power Co 83/04/19 21pp 18277 148 24X Fiche 50-P82,83/04/19.8305020320
- B303040023 IE Info Notice B3-22. "BWR Safety/Relief Valve Failures "
 8vc list encl
 JORDAN: E Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000, B3/04/22, B303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness >> Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-29. "Standby Gas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Byc list encl, JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- B303U40028 IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list enci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- B303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc 11st encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc 112pp 18382 282 24X Fiche 30-000,83/05/04.8303040030
- B303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/03/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 9303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305240029 Forwards IE Insp Repts 50-282/83-06 & 30-306/83-05 on 830216-0331 No nancompliance noted SHAFER.W D Region 3, Office of Director 83/05/06 LARSON,C E Northern States Power Co 2pp 18549 095 24X Fiche 50-282,83/05/06.8305240029
- --8305240061 IE Insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No noncompliance noted Major areas inspected plant operational safety, maint, surveillance, review of operating events. LERs, fire penetration soals & IE builetins FEIERADEND, C D , WILLIAMS, D L , JACKIW, I N Region 3, Office of Diractor 83/05/05 18pp 18549 097 24X Fiche 50-282,83/05/06.8305240029
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 0il " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- B305160056 Forwards monthly operating repts for Apr 1983 MUSOLF.D Northern States Power Co B3/03/11 Office of Resource Management, Director 1p 18451 036 24X Fiche 50-282, B3/05/11. 8305160056.
- --8305140076 Monthly operating repts for Apr 1983 BUGSTAD.D Northern States Power Co 83/05/04 8pp 18451 037 24X Fiche 50-282.83/05/11,8305140054
- S Reportable occurrences, LERS & related correspondence
- 8305240166 LER 83-010/03L-O on 830417, reactor coolant sample found missing after lead changing operations for turbine testing Sample taken 2 h late Caused by lack of communication Load changing procedure will be revised W/830516 ltr HUNSTAD.A A , MUSQLF, D Northern States Power Co 83/05/16 Region 3. Office of Director 2pp 18549 237 24X Fiche 50-282, 83/05/16, 8305240166

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

P305040614

0705040414

- F Security, medical, emergency & fire protection plans
- 8305100226 Revised pages to radiological emergency response plan * Dmaha Public Power District 83/03/18 180pp 18372 324 Fich* 50-285,830/33/18,8305100226
- 8305040614 Releases public version of updated radiological emergency response plan Tesponse pien FELTON, JM Division of Rules and Records 83/04/25 Docum Management Branch 1p 18335 276 24X Fiche 50-285,83/04/25,
- --8305040619 Forwards public version of updated radiological emergency response plan Receipt form encl JONEB.W C Omaha Public Power District 83/03/24 Region 4, Office of Director 1p 18335 277 24X Fiche 50-285,83/04/25,
- ---B305040624 Public version of updated radiological emergency response plan # Omaha Public Power District 83/03/04 162pp 18335 278 24X Fiche 50-285.83/04/25.8303040614
- B305030425 Responds to 830318 ltr requesting reaffirmation of 810610 ltr re-role of NRC in radiological emergency response While ltr reflects current policy, ltr of agreement not intonded SEIDLE W C Region 4. Office of Director 83/04/29 FRANCO, F F Omaha Public Power District 2pp 18306-250 24X Fiche 50-285,83/04/29,8305030425
- --8305030429 Requests reaffirmation of NRC 810610 ltr of agreement re role of NRC in radiological emergency response
 JONES, W C Omaha Public Power District 83/03/18
 Region 4, Office of Director 2pp 18306 252 24X iche 50-285,83/04/29,8305030425
- --8305030435 Responds to 810601 ltr discussing role of NRC during radiation emergency Primary role is to monitor licensee activities associated w/incident & to provide technical assistance; if requested COLLING, J T Region 4, Office of Director 81/06/10 JONES, W C Omaha Public Power District 1p 18306 254 24X Fiche 50-285, 83/04/29, 8305030425
- 8305120594 Releases public version of revised radiological emergency response plan
 FELTON.J M Division of Rules and Records 83/05/02 Docum
 Management Branch ip, 18441 339 24X Fiche 50-285.83/05/02.
 8305120594
- --8305120403 Forwards public version of revised radiological emergency rasponse plan W/o encl JONES: W C Omaha Public Power District 83/03/24 COLLINS, J T Region 4, Office of Director 1p 18441 340 24X Fiche 50-285,83/05/02:8305120594
- B305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Box list encl
 EISENHUT,D 9 Division of Licensing 83/05/11 C
 Edieon Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034 Consolidated
- 8305200060 Informs that onsite & offsite emergency preparedness JONES, M. C.
- I. Financial information
- B30506069 Forwards Annual Financial Rept 1982 JONES WC Omaha Public Power District 83/04/29 Office of Nuclear Reactor Regulation, Director ip Fiths 50-285, 83/04/29, 8305060069 DENTON, H. R. 18345 027
- --B305060091 Annual Financial Rept 1982 SPENCE, O P Omaha Public Power District 83/04 18345 028. 24% Fiche 50-285, 83/04/29, 8305060069 83/04/29 2400

- P Operating license stage documenty & correspondence
- 8305230589 Forwards backfitting % regulatory impact cost data for hardware > nonhardware-related backfits Requirement fo adding one add1 senior reactor operator to each operating shift will cost \$600,000 per yr REZNICEK.6 W Dmaha Public Power District 83/03/04 TOURTELLUTE.J Regulatory Reform Task Force 16pp 18 24X Fiche 50-285.83/03/04 8305230588 16pp 18541 322
- 8305160027 Ack receipt of Commission 830404 1tr clarifuing SER on environ qualification of safety-related electrical equipment in harsh environ Justification for continued operation of valve positioner cable & motor biake encl JONES, W.C. Dmaha Public Power District 83/04/11 Dperating Reactors Branch 3 10pp 18452 359 24: Fiche 50-283, 93/04/11, 8305160027 CLARK, R A
- 8305230720 Forwards list of utils responding to requests for cost #034072D forwards [1st of utils responding to requests figures on backfitting
 TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11
 PALLADINO.N J Commissioners 2pp 18542 272 24X
 Fiche 50-000.83/04/11.8305230720
- 8305030156 Revised amend application re heatup 4 cooldown curves Amend revises 830304 amend application to matup A coolsown curves revises 830304 amend application JDNES.W C Domaha Public Power District 83/04/28 CLARK.R A Operating Reactors Branck 3 ip 18399 101 24Y Fiche 30-285.83/04/28.8305030154
- --8305020160 Revised Tech Specs for 830304 amend application changing 103030100 Nevised Tech Spres To, 103030 194 24X Heatup & Cooldom curves a Omaha Public Power District 83/04/28 17pp 18300 194 24X Fiche 50-285,83/04/28,8305030136
- 8305060186 Forwards response to 830311 ltr requesting addl info re proposed spent fuel storage rack and New analysis indicates spent fuel coaling rack and New analysis indicates spent fuel coaling spent fuel pool cooling JONES, W C Dmaha Public Power District 83/04/29 CLARK, R A Operating Reactors Branch 3 40pp 16344 152 24X Fiche 50-285, 83/04/29, 8305060186
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Svc list encl
 EISENHUT, D O Division of Licensing 83/05/02 Constitution of Constitution of Page 11 120 24X
 Fiche 50-000,83/05/02,8305020455 Consolidated
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees \$\(\) holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT.D 0 Division of Licensing 83/03/09 Consolidated Edison Co of New York. Int 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305310240 Requests addl info for control of heavy loads review, including info open items for updated "Control of Heavy Loads " CLARK,R A Operating Reactors Branch 3 83/05/17 JONES.W C Omaha Public Power District 2pp 18662 180 24X Fiche 50-285,83/03/17,8305310240
- --8305310241 "Control of Heavy Loads (C-10). Omaha Public Power District, Fort Calhoun Station," updated draft technical evaluation rept WOBBURY, F. BOMBERGER, C. SARGENT, I H. Franklin Institute/Franklin Research Center NRC-02-81-130 TER-C5504-356 DRFT B2/11/29 CLEMENSON, F. NRC - No Detailed Affiliation Given 52pp 18662 182 24% Fiche 50-285.83/05/17.8305310240
- 8305240474 Provides 90-day response to BER & addl info per 10CFR50 49(g) & 830404 clarification ltr Position on outstanding itoms in technical evaluation rept & description of methods used to identify equipment discussed JONES, W C Omaha Public Power District 83/05/20 CLARK, R A Operating Reactors Branch 3 36pp 18549 296 24X Fiche 50-285, 03/05/20, 8305240474
- @ Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enci TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000.83/03/21,8212060385

- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator "
- Not list enc)

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 135 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 - Svc list encl JORDAN,E L | DORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383-089 24X Fithe 50-000,83/04/22,8303040023
- 8305100241 Forwards IE Insp Rept 50-285/83-09 during Mar 1983 & motice
 - of violation SEIDLE.W C Region 4. Office of Director B3/04/2. Omaha Public Power District 2pp 18374 108 24X Fiche 50-285.83/04/22.8305100241 83/04/22 JONES, W C
- --8305100242 Notice of violation from insp during Mar 1983 * Region 4. Office of Director 83/04/22 ip 18374 i10 24X Fiche 30-285.83/04/22,8305100241
- --8305100244 IE Imap Rept 50-285/83-09 during Mar 1983 Noncompliance JUDIOVZ44 IE Imap Rept 30-285/83-09 furing Mar 1983 Noncompliance hoted failure to document performance steps added by Procedure Change 10222 to Section F 3 (Pumps 81-14 & 91-18) of Surveillance Test 8T-51/68-1 YANDELL, A , JOHNSON, W D Region 4, Office of Director 83/04/21 11pp 18374 111 24X Fiche 50-285,83/04/22.8305100241
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York Inc 119pp 18381 291 24X Fiche 50-000,63/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fishe 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/0428 Consolidated Edison Co. of New York, Inc. J18pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JORDAN: EL Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/03/04 Consolidated Edison Co of New
 York: Inc | 182pp 18382 282 24X Fiche 50-000,03/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York Inc 119pp, 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "See list enc! JORDANNE L Division of Emergency Properedness & Engineering Response (Past 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115p. 18523 248 24X Fiche 50-000,83/05/06.8303040033
- 8305230464 Forwards IE Imsp Rept 50-285/83-08 on 830404-08 & motice of deviation
 SEIDLE.W C Region 4, Office of Director 83/05/06
 Omaha Public Power District 2pp 18537 151 24X
 Fiche 50-285,83/05/06,8305230464 83/05/0A
- ~-8303230467 Notice of deviation from insp on 830404-08 * Region 4, Diffice of Director 83/05/06 2pp 18537 153 24X Fiche 50-285,83/05/06,8305230464,
- --8305230475 IE Insp Rept 50-285/83-08 on 830404-08 Noncompliance noted documentation for continuing training of GA personnel not established & maintained & procedures requirement to meet audit finding 30-day response time not met MURPHY.M E. MCCRORY.S L. WESTERMAN.T Region 4. Office of Director. 83/05/02 9pp 18537 135 24X Fiche 50-283.83/05/06. 8305230464

- 8303040034 IE Info Natice 83~30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " NOSUADONU LE INTO MEETE TO THE STATE OF THE
- 8305240173 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 50-285/83-02 Corrective actions will be reviewed during future insp SEIDLE.W C Region 4, Office of Director 83/05/20 JONES.W C Omaha Public Power District ip 18548 037 24X Fiche 50-285/83/05/20,8305240173
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Di) " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New Yark, Inc 114pp 18647 007. 24X Fiche 50-000,83/05/26,8303040046
- A Periodic operating reports & related correspondence
- 8305160111 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Jan 1983 "
 JONES, W C Dmaha Public Power District 83/05/11 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 18450 161 24X Fiche 50-285.83/05/11,830516011
- --8305160116 "Reactor Containment Blds Integrated Loak Rate Test, Jan 1783 "
 * Omaha Public Power District 83/05/11 44pp 18450 162 24X
 Fiche 30-285,83/05/11,8305160111
- 8305170465 Forwards monthly operating rept for Apr 1983 JONES, H. C. Omaha Public Power District 83/05/12 DEYDUNO, R. C. Director's Office, Office of Inspection and Enforcement 1p 18470 112 24X Fiche 30-285, 83/05/12, 8305170465
- --B305170470 Mpnthly operating rept for Apr 1983 MATHEWS,T P Omaha Public Power District 83/05/12 11pp 18470 113 24X Fiche 50-285,83/05/12,8305170465
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination
 FARRELLY, T. J Consolidated Edison Co of New York, Inc 83/04/28
 LEHI8.D Atomic Safety and Licensing Board Panel 24pp 18300 3:
 24X Fiche 50-247,83/04/28,830303031
- F Security, medical, emergency & fire protection plans
- B305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions NUREG-0634-FEMA-REP-1. Rev 1 stds would place heavy resource burden on state OIUFFRIDAL D Federal Emergency Management Agency 83/04/18 PALLADINON J Commissioners ip 18342 329 24% Fiche 50-003.83/04/18,8305230670
- ---8305230676 Beeks clarification of issue re FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan PALLADINO, N J Commissioners 83/03/30 GIUFFRIDA, L O Federal Emergency Management Agency 2pp 18542 330 24X Fiche 50-003,83/04/18,8303230670
- 8305050873 Informs that licensee 830216 commitment re interim fire protection mods generally acceptable Present Tech Specs should be revised to comply w/interim mods Sample Tech Specs anc l anci VARGA,S A Operating Reactors Branch 1 83/04/21 BAYNE,J P. Power Authority of the State of New York 3pp 18352 014, 2: Fiche: 50-286, 83/04/21, 8305050073
- --8305050076 Sample Tech Specs re interim fire protection mode concerning alternate shutdown sys * Operating Reactors Branch 1 83/04/21 1pp 18352.017 24X Fiche 50-286.83/04/21.8305050073

- 8305110538 Forwards safety evaluation of util compliance w/10CFR50. App R. Sections III G 3 & IIII L Long-term compliance acceptable except for three items Spurious operation can be corrected by closing valves Response needed in 30 days VARGA.8 A Operating Reactors Branch 1 83/04/21 BAYNE, J P Power Authority of the State of New York 3pp IB419 286 24X Fiche 50-286.83/04/21.8305110538
- --8305110543 Safety evaluation of util compliance w/10CFR50. App R Proposed alternate shutdown capability performance goals of reactivity; inventory, DHR reactor pressure & process control met, subj to listed exceptions

 # Office of Nuclear Reactor Regulation, Director 83/04/21
 17pp 18419 289 248 Fiche 50-286,83/04/21,8305110538
- --8305110546 "Process Monitoring Instrumentation " * NRC - No Detailed Affiliation Given 83/04/21 3pp 18419 306 24X Fiche 50-286,83/04/21.8305110538
- 8305030284 Notification of 830429 meeting util in Bethesda.MD to discuss steam generator chemistry & fire protection interim measures POLK.P J Operating Reactors Branch 1 83/04/22 VARGA.S A Operating Reactors Branch 1 4pp 18309 330 24X Fiche 50~286,83/04/22,8305030284
- 8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning, for info Certificate of Svc encl Related correspondence GLA88,S M Federal Emergency Management Agency B3/04/25 GLEABON.J P Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247,83/04/25,8305020419
- 8303110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enc!
 EISENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 30-000,83/05/11,8305110034
- 8305160088 Advises that no basis exists to further delay facility startup per 821018 amend application re steam generator tube sleeving & 830503 order concerning emergency preparedness SINCLAIRL W Pawer Authority of the State of New York 83/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18450 357 24% Fiche 50-286.83/03/12,8305160088
- 8305240099 Submits current status of App R fire protection activities per 830518 request Installation of equipment committed to in 830216 ltr completed.820701 proposed design installad & addl Tach Specs for equipment mode will be submitted 84VNE.J P Power Authority of the State of New York 83/05/19 VAROA.S A Operating Reactors Branch i 2pp 18548 341 24X Fiche 50-286,83/05/19.8305240099
- 8305240234 Documents NRC/util tolon re seismic qualification documentation for auxiliary feedwater sys & proposed fire protection Tech Specs Tech Specs on quarterly surveillance of alternate alsocrical feed sys to be submitted BAYNE.J P Power Authority of the State of New York 83/05/20 VARGA.S A Operating Reactors Branch 1 2pp 18548 309 24X Fiche 50-286.83/05/20.8305240234
- B305240312 Informs of full cooperation between licenses & local govt in development & exercise of emergency radiological response plan, contrary to Commissioner Ahearne B30506 statement HEIMBACHL New York, State of B3/05/20 PALLADINO, N Commissioners ip 18548 184 24X Fiche 50-247, 83/05/20, 83005240312
- 8305240338 Forwards response to 830421 ltr re App R fire protection review. Section III 0 3 & III L Exemption from schedular requirements for Sections 50 48(c) & (d) for mods prior to startup from Cycle 4/5 refueling outage requested BAYNE, J P Power Authority of the State of New York 83/05/20 VARGA/8 A Operating Reactors Branch 1 4pp 18575 258 24X Fiche 50-286,83/05/20,8305240338
- 8305310049 Responds to 830523 ltr outlining specific proposals for ameliorating facility offsite preparedness situation & views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness OIUFFRIDA. L O Federal Emergency Management Agency 83/05/25 CUOMO, M N New York, 8 tate of 4pp 18633 284 24X Fiche 50-247,83/05/25,8305310049

G Adjudicatory correspondence

- B305030BB Forwards summary of thaining activities re-offsite response organizations that might be called upon to respond to onsite emergencies, per ASLB B30225 oral request Util training detailed in B30405 submittal Related correspondence BRANDEMBURG. B Office of the General Counsel B7/04/29 LEHIS, D Atomic Safety and Licensing Board Panel 7pp B303 335 24X Fiche 50-247. B3/04/29, B30503058
- 8305030608 Motion for permission to present cobuttal witnesses on subjorf prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence PDTERFIELD.A Union of Concerned Scientists PDITERFIELD.A Public Interest Research Group, New York KAPLAN,C New York, NY 83/04/19 4pp 18308 050 24X Fishe 50-247,83/04/19.8305030608
- --B305030641 Motion requesting initiation of studies on human response to radiological emergencies risks to individuals living near site & difficulty of evacuation in emergency POTTERFIELD, A Public Interest Research Group. New York POTTERFIELD, A Union of Concerned Scientists B3/04/26 Atomic Safety and Licensing Board Panel Bpp 18308 137 24X Fiche 50-247,83/04/19,8305030608
- --8303030646 Affidavit of KT Erickson & AJ Solnit re radiological emergency response plan ERICKSON, KT Public Interest Research Group, New York ERICKSON, KT Union of Concerned Scientists ERICKSON, KT Vale Univ, New Haven, CT 83/04/26 4/pp 18308 148 24X Fiche 30~247,83/04/19,8305030608
- --8305030652 Motion requesting completeness of record on NRC Questions
 3 & 4 re emergency planning issues, including capability for
 handling phone calls in emergency planning rone during
 emergency
 POTTERFIELD, A . POTTERFIELD, A Union of Concerned Scientists
 83/04/25 Atomic Safety and Licensing Board Panel 4pp
 18308 180 24X Fishe 50-247.83/04/19,8305030608
- 830502042B Motion to strike politions of 830309 emergency drill testimony under Commission Guestions 3 ½ 4 filed by witnesses for various intervenors Certificate of Svc encl Related correspondence
 RRANDENBURG.B Consolidated Edison Co of New York, Inc 83/04/22
 Atomic Safety and Licensing Board Panel 22pp 18273 075 24X
 Fiche 50-247,83/04/22,8305020428
- 8305020419 Forwards "Indian Point Plans Verification Analysis" regenergency planning, for info Certificate of Svc encl Related correspondence OLASS. S M Foderal Emergency Management Agency 83/04/25 GLEASON. J P. SHON. F J. PARIS. O H Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247.83/04/25, 8305020419
- 8305030549 Motion for subpoend to be issued to RW Krimm of FEMA Subpoend mecessary to complete record on generic nature of deficiencies cited by FEMA & FEMA change in evaluation critoria Certificate of Svc encl MORGAN.C Power Authority of the State of New York MORGAN.C Morgan Associates 83704/26 Atomic Safety and Licensing Board Panel 40pp 18306 147 24X Fiche 50-247.83/04/26,8305030549
- 8305020401 Motion to amend svc list to add SP Wasserman & delete P Chessin.LR Schwart: & M Oppel Notice of appearance & Cartificate of 8vc enc! WASSERMAN.8 P Metropoliten Transportation Authority New York, NY WASSERMAN.8 P Botein, Hays, Sklar & Herzberg 83/04/27 Atomic Safety and Licensing Board Panel &pp 18273 067 24X Fiche 50-247.83/04/27.8305020401
- 8305020451 Submits info on status of Ray Miller Inc problems affecting plantiper ASLB request
 MODRE JE Hearing Branch i 83/04/28 GLEASON JP, SHON FJ, PARIS OH Atomic Safety and Licensing Board Panel 88pp
 18283 180 24X Fiche 50-247.83/04/28.8305020451
- 8305030331 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination FARRELLY: TJ Consolidated Edison Co of New York: Inc 83/04/2B LEWISI. D Atomic Safety and Licensing Board Panet 24pp 18300 315 24X Fiche 50-247,83/04/28,8305030531
- 8305040505 Forwards util onsite emergency plans per ASLB request that documents be mailed rather than delivered BRANDENBURG.B Consolidated Edison Co of New York, Inc 83/04/28 OLEASON,J P. SHON,F J. PARIS, D H Atomic Safety and Licensing Board Panel ip 18322 110 24X Fiche 50-247.83/04/28.8305040505

- B305040464 Pequests official position to long-term operation of facilities
 OLEASON, JP , PARIS, O H , SHOW, F J Atomic Safety and Licensing Board Panel B3/05/02 CUOMO, M M New York, State of 2pp 18321 295 24% Fiche 50-247, 83/05/02, 8305040464
- 8305050035 Proposes alternative views to questions posed in SJ Chilk 830426 ltr to FEMA ro emergency planning & evacuation FLEISHER.Z S West Branch Conservation Association 83/05/02 PALLABINO, N J. OILINSKY.V. AHEARNE.J F Commissioners 3pp 18342-096 244 Fiche 50-247.83/05/02.8305050035
- 8305160304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing.Inc MILES,E 9 Administrative Contracts Branch FIN 8-8895 83/05/02 8ASSETT.H S Office of Resource Management, Director FITTI.C Atomic Safety and Licensing Board Panel 1p 18471 247 24X Fiche 50-247.83/05/02 8305160304
- --8305160312 Contract "Conversion of Profiled Testimony for Indian Point Hearings," awarded to Central Data Processing. Inc * Central Data Processing. Inc MATTIA.M J Division of Contracts FiN B-8855 83/05/02 Ppp 18471 248 24X Fiche 50-247,83/05/02,8305160304
- --B309160316 Solicitation offer % award to "Conversion of Prefiled Testimony for Indian Point Hearings." to Central Data Processing. Inc COUCH.M J Central Data Processing. Inc MATTIA.M J Administrative Contracts Dranch. FIN B-8855 B3/04/26 56ρp 18471 230 24X Fiche 50-247.83/05/02.8303160304
- 9305040500 Expresses concern that FEMA 830415 post-exercise assessment of 830309 emergency planning exercise presents incomplete picture of present status of offsite radiological emergency planning Cartificate of Svc encl
 BAYNE, J.P. Power Authority of the State of New York 83/05/03
 PALLABING, N.J. OILINSKY, V. AMEARNE, J. Commissioners 17pp
 18348 112 24x Fiche 50-286, 83/05/03, 8305060900
- 8305050037 Forwards NY State Disaster Preparedness Commission 830504 memo re State of NY commitment to continue work to ensure residents protected by best practicable emergency preparedness plan BAYNE.J P Power Authority of the State of New York 83/05/04 PALLADINO.N J. OILINSKY,V . ANEARNE.J F Commissioners 3pp 18339 105 24x Fiche 50-247,83/05/04.8305050037
- B305060496 Forwards NY State Disaster Preparedness Commission B30504 ltr providing State of NY commitment to ensure residents protected by best practicable emergency preparedness plan BAYNE. J P Power Authority of the State of New York B3/05/04 PALLADINO. N J. O!LINSKY.V, AMERINE. J F Commissioners Jpp 18348 105 24% Fiche 50-247. B3/05/04. B305060496
- 9305060505 Responds to 930426 ltr re Westchester County, NY bus driver issue. Rockland County, NY plan issue ? questions raised re FEMA briefing % status rept on offsite emergency preparedness KRIMM.R W Federal Emergency Management Agency 83/03/04 CMILK.S J Office of the Secretary of the Commission 16pp 18348 331 24X Fiche 50-247,83/03/04.8305060306
- --8303060627 Responds to request for clarification of issue on whether state emergency plan can substitute for county which does not have emergency plan State can substitute plan but NWRE0-0654 places heavy resource burden on state OIUFFRIDAL D Federal Emergency Management Agency 83/04/15 PALLABING, N J Commissioners 2pp 18348 347 24X Fiche 50-247,83/05/04.8305060506
- 3305040468 Order CLI-83-11 advising that Commission will issue order by 830609 suspending plant operation unless FEMA determines significant deficiencies no longer exist or util shows compensating actions taken or deficiencies insignificant HOYLE. J Office of the Secretary of the Commission 83/05/05 5pp 18348 075 24X Fiche 50-247.83/05/05.8303060468
- 3305090458 Memo providing citations to decisions referred to in hearing re-commitments from bus drivers needed in emergency evacuation plans
 PARIS.O H Atomic Safety and Licensing Board Panol 83/05/05 2pp
 18342 259 24X Fiche 30-247,83/05/05,8305090458
- 3305100208 Motion for extension of deadline until 830627 for all parties to submit proposed opinion, findings of fact & recommendations re enforcement action on emergency planning issues Centificate of Svc encil BRANDENBURG, I Consolidated Edison Co of New York, Inc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/05/06 PALLADINO, N J. GILINSKY, V. AHERNE, J F. Commissioners 9pp 18374 014 24% Fiche 50-247, 83/05/06, 8305100208

- 8305100204 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11, establishing procedures for decision on enforcement action on emergency planning issues Certificate of Svc encl MEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/05/09 Commissioners 6pp 18374 193 24X Fiche 50-247,83/05/09,8305100204
- B305130064 Motion for reconsideration of ruling denying licenses motion to receive DP McGuire deposition transcript into evidence Licensees entitled to place deposition in record Cartificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York, Inc MORGAN. C Power Authority of the State of New York MORGAN. C Morgan Associates B3/05/09 Atomic Safety and Licensing Board Panel 15pp 18436 230 24% Fiche 50-247.83/05/09.8305130064
- 8305120309 Order authorizing ASLB to grant relief from 830527 deadline for filing proposed findings of fact & conclusions of law since oral presentations before Commission to take place on 830526 CHILK, B. J. Office of the Secretary of the Commission 83/05/10 Atomic Safety and Licensing Board Panel 2pp 18424 100 24X Fiche 35-247.83/05/10.8305120309
- B305160024 Forwards I Levi affidavit clarifying B30211 testimony on suggested method of making sensible probability judgments described in Section 5
 HARTZMAN.R N Friends of the Earth HARTZMAN.R M Audubon Society B3/05/10 GLEASON.J P. PARIS.O H. SHON.F J Atomic Safety and Licensing Board Panel 1p 18452 353 24% Fiche 50-247,83/05/10. B305160024
- --8305160028 Affidavit of I Levi clarifying 830211 testimony re suggested method of making sensible probability judgments described in Section 5 LEVI.1 Friends of the Earth LEVI.1 Addubon Society 83/05/10 2pp 18452 354 24X Fiche 50-247.83/05/10.8305160024
- B305130030 Memorandum & order granting licensee 830506 motion for extension until B30627 to file proposed findings of fact & recommendations Date extended until B30829 for ASLB to submit recommendations to Commission
 PARIS.O H. SHIDN.F J. Atomic Bafety and Licensing Board Panel B3/05/11 Consolidated Edison Co. of New York, Inc. 2pp 18437 102 24X Fiche 50-247.83/05/11.8305130020
- 8305130071 Motion for extension of deadline (to 830615) for filing corrections to transcripts & deadline (to 830624) for filing comments Certificate of Svc enci
 BRANDENBURG. B Consolidated Edison Co of New York, Inc Morgan, C
 Power Authority of the State of New York MORGAN, C Morgan
 Associates 83/05/11 Alomic Safety and Licensing Board Panel
 7pp 18437 045 24X Fiche 50-247,83/05/11,8305130071
- 8305190342 Supports immediate plant shutdown Emergency response plan represents theory & not practicality BALEF.8 R Westchester County, NY 83/05/11 PALLADING,N J Commissioners App 18500 227 24X Fiche 50-247,83/05/11, 8305190342
- B305160133 Telecopy order granting licensee B30511 motion for extension of date to fike motions to correct transcript Motions due on B30615 GLEASON, J.P. Atomic Bafety and Licensing Board Panel B3/05/13 Consolidated Edison Co. of New York. Inc. 4pp. 18446-116 24X Fiche 30-247. B3/05/13, 8305160133
- B305140147 Order clarifying Commission B30505 order Comments from parties & general public, relevant to enforcement action. will be considered Fublic comments to be filed by B30523 Oral presentations Idmited to licensees & interested govts CHILK.8 J Office of the Secretary of the Commission B3/05/13 Commissioners 4pp 18445 152 24% Fiche 50-247, 83/05/13. 83/05/6147
- B305190220 Motion for opportunity to address issues outlined in Commission B30505 Order CLI-83-11 establishing procedures for decision on enforcement action Intervenor entitled to participate as matter of right Certificate of Svc encl RODRIGUEZ.P Parents Concerned About Indian Point B3/05/13 Commissioners 3pp 18502 143 24X Fiche 50-247,83/05/13,8305190220
- 8305200645 Advises that day of reckoning re evacuation plan issue coming on 830609 Interim compensating actions by FEMA cannot compensate for unchangeable factors of problem roads & population density TOSCANI.X Affiliation Unknown 83/05/15 Commissioners 3pp 18520 122 24X Fiche 50-247,83/05/15,8305200645

- 8303180143 Order providing time (until 830610) to parties to respond to P Amico. ASLB consultant, 830502 ltr summarizing conclusions based on review of testimony bearing transcripts re Commission (Question 1 QLEASON, J P Atomic Safety and Licensing Board Panel 83/03/16 Office of the Executive Legal Director 1p 18490 022 24% Fiche 50-247, 83/05/16, 8305180143
- --B305180146 Summarizes rept on review of testimony h hearing transcripts re Commission Question 1 Addl testimony recommended on current analytical methods for risk assessment & on issues not dealt win probabilistic safety at Study or NRC analysis AMICO,P J Applied Risk Technology Corp AMICO,P J Atomic Safety and Licensing Board Panel 63/05/02 GLEASON,J P, SHON,F J, PARIS.O H Atomic Safety and Licensing Board Panel 4pp 18470 023 24X Fiche 50-247,83/05/16.8305;80143
- B305180424 Requests time to address Commission on 830526 re Commission B30513 order ODANSKI, S. Rockland County, NY B3/05/16 CHILK Commissioners to 18485 302 24x Fiche 50-247,83/05/16,8305180424
- B305200605 Requests time to speak on B30526 State of NY claims unsubstantiated NRC should adopt policy of communicating w/public FLEISHER. Z S West Branch Conservation Association B3/05/1 PALLADINO.N J , OILINSKY, V , AHEARNE, J Commissioners 12pp 18514 090 24% Fiche 50-247, B3/03/16, B305200605
- B305240535 Citizens advisory committee progress repts re nuclear evacuation & general disaster proparedness plan

 * Rockland County: NY B3/09/16 34pp 18576 053 24%

 Fiche 50-247-83/05/16-8305240535
- B305240508 Forwards Ossining Town Board resolution expressing concerns resemble to plans Deficiencies must be corrected before plan approved WISHNELR & Ossining, NY 83/05/17 Office of the Secretary of the Commission App 185/1 260 P4X Fiche 50~247,83/05/17,83208240808
- 8305240530 Expresses concerns to adequacy & workability of evacuation plans BOOARDUB,R H Affiliation Unknown 83/05/19 NRC No Detailed Affiliation Given 2pp 18571 234 24% Fiche 50-247,83/05/19,8305240530
- 8305240546 Forwards citizen & group statements expressing concern replant safety & flawed evacuation plan, in response to Commission Order CL1-B3-1; ELLIOTT, N R Varktown, NV 83/03/19 NRC No Detailed Affiliation Given 10pp 18575 266 24X Fiche 50-247,83/05/19,8305240546
- 8305240547 Forwards board of trustees of Village of Buchanan statement that plants are safe & provide clean energy PIERCE,F W Buchanan, NY 83/05/19 PALLADINO,N J Commissioners 2pp 18578 281 24% Fiche 50-247,83/05/19.8305240547
- B305270583 Requests concrete actions re emergency evacuation plan in light of FEMA stated deficiencies, in response to Commission 830505 Order CLI-E3-11 ELLIOTT, N R Yorktown N B3/05/19 Commissioners 1p 18445 343 244 Fiche 50-247,83/05/19,8305270583
- B305240454 Motion for leave to submit written comments on NRC 830505 order to suspend facility operations Deficiencies determined to be significant by FEMA are not sufficiently deficient to require suspending operations

 JOY, J. HICKS, M. M. GALLACHER, P. J. Utility Worsers Union of America B3/05/20 Commissioners Bpp 18573 164 24X

 Fiche 30-247, 83/05/20, 8305240454
- BQ05240466 Response to Commission B30503 order establishing procedures for decision on enforcement action Emergency planning deficiencies not significant NRC enforcement action unwarranted & improper W/Certificate of Svc MCROAN.C Power Authority of the State of New York MCROAN.C Horgen Associates B3705/20 A3pp 18573 181 24X Fiche 50-247,83/05/20,8305240464
- 8305240527 Views re radiological emergency planning in response to Commission 830505 order.FEMA & NRC should rule that plants no longer have significant deficiencies based on improvement & interim compensating actions BLOCK.JD . BRANDENBURG, B. Consolidated Edison Co. of New York. Inc. 83/05/20 41pp 18971 132 24X Fiche 50-247,83/05/20.8305240527

- B30524053F Opinion on NRC B30505 order to FEbruare ton licenses emergen y planning 'prepare nens' pussible suspension of plant operations Immediate shutdown uiged KAPLANIC New York NY KAPLANIC National Emergency Civil Libertie, Committee B3/05/40 18pp 18571 218 24y Fiche 50-247 B3/05/20, B305740532
- 830525033" Submission re Commission 820705 order on intention to shut down facility on 830609 if emirgency preparedness problems not resolved Adequate protective arisum in case of radiological emergency cannot be gual intred by 830609 GOLDBERO, M. L. Public Interest Research Group, New York 17PP 18585 202 PAX Fiche 30-247, 83.05,71,8305750337
- B305240523 Order providing guidance for 430576 oral presentations to Commission re possible plant shutdown CHILK, S. J. Office of the Serretary of the Commission 83/05/23 App. 18971 119 24X Fiche 40-247,83 05 23,8305240823
- 830524053B Forwards comments on Commission Qider Cli-33-11 establishing procedures for decision on enforcement action MEISS,E R Harmon & Weiss WEISS,E R Union of Concerned Scientists 83/05/23 PALLADIND.N J AMEARNE.J F ASSELSTINE.J K Commissioners ip 189/8 093 244 Fiche 50-24/,83/05/23,8305240538
- --B305240542 Comments on Commission Order CLT-83-11 establishing procedures for decision on enforcement action Emergency planning deficiencies fundamental Adequate Interim compensating measures impossible Certificate of Svc encl WEISS.FR Union of Concerned Scientists WEISS.FR Harmon & Weiss B3/03/23 19pp 18976 094 24Y Fiche 50-247,83/05/23,8305280538
- 8305240543 Submission re Commission 830505 Order CLI-83-11 Emergency planning must be well developed & detailed w/special emphasis on health % safety of children POBNER, P parents Concerned About Indian Point 83/05/23 20pp
- 8303230223 Submission addressing Commission 830505 order on possible facility closing Requests oral presentation on 830526 re economic impact of facility shutdown Economic impact is not compelling reason for continued operation CORREN,D Greater New York Council on Energy 83/05/23 12pp 18588 083 24X fiche 50-247.83/05/23.8303250227
- B303270586 Response opposing licensee motion for reconsideration of ASLB denial of licensee motion to admit DP picGuire testimony before trial THORSEN.E D. Rockland County, NY B3/05/24 Atomic Safety and Licensing Board Panel 6pp 18649 355 24X Fiche 50-247,83/05/24,8305270586
- H General correspondence
- B30524044; Opines that decision re continued plant operation must weigh health effects of replacement by coal burning plants JAFFE.H Affiliation Unknown 83/05/16 AMEARNE. J Atomic Safety and Licensing Board Panel 2pp 18571 068 24% Fithe 50-247.83/05/16,830524044;
- B305240517 Supports continued facility operation SCHULER.R T . HCALEY.J A . IRMIN.R B Affiliation Unknown B3/03/16 PALLADING.N J Commissioners 27pp 18571 191 24x Fiche 50-247.B3/05/16,B305240517
- B305240537 Supports closing down of facility CINGUEMANI.D , CINQUEMANI.F Affiliation Unknown 83/05/19 Commissioners ip 18576 039 24% Fiche 50-247, 83/05/19 8305240537
- 8305270546 Supports shutdown of facilities on 830809 EPSTRIN.R B Affiliation Unknown 83/05/19 Commissioners 2pp 18446 114 24% fiche 30-247.83/05/19.8305270566
- 8303240541 Supports suspension of plant operation ORANNIS.A B New York, State of ELLIQTT,N R Yorktown, NY 83/03/20 NRC - No Detailed Affiliation Oiven 2pp 18576 091 24X Fiche 30-247,83/05/20,8305240541
- B305270575 Package of two citizens ltrs supporting continued facility operation
 KUNKEL, T C . WEIGANDT, J T Affiliation Unknown B3/05/20
 PALLADINO,N J Commissioners 2pp 18647 125 24X
 Fiche 50-247.83/05/20.8305270575

- 8305240433 Supports continued plant operations Plants should not be held nostage to evacuation process TODOROVICH,M H. Affiliation Unknown 83/05/23 CHILK,S J. Office of the Secretary of the Commission 3pp 18575 232 24X Fichs 50-247,83/05/23,8305240453
- J Insurance & Indemnity information
- 8305120208 Forwards Endotsement 65 to NFLIA Policy NF-208 & Endorsement 55 to MAELU Policy MF-77 GOLDEN-M P Marsh & McLennan, Inc. 83/05/03 SALF2MAN, J Assistant Director for State & Licenses Relations 3pp 18427 358 24X Fiche 30-000, 83/05/03, 8305120208
- P Operating license stage documents & correspondence
- 8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Porce effort.per 821221 itr DYSGN, J 5 Power Authority of the State of New York 83/03/02 TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18541 338 24 Fiche 50-000.83/03/02.8305230557
- 8303230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J. Regulatory Reform Task Force 83/04/II PALLADINO.N J. Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/II.8305230720
- 8305030284 Natification of 830427 meeting util in Bethesda.MD to discuss steam generator chemistry ' fire protection interim measures POLK:P J Operating Reactors Branch 1 83/04/22 VARGA.S A Operating Reactors Branch 1 4pp 18307 330 24X Fiche 50-284.83/04/22.8305030284
- 8305020381 Forwards description of mods to control room ceiling aggrate ceiling supports to be implemented prior to startup from current refueling outage BAYNE, JP Power Authority of the State of New York 83/04/28 VAROAS A Operating Reactors Branch i 5pp 18276 211 24X Fiche 50-286:83/04/28.8305020381
- B305030408 Forwards Rev 2 to "Fracture Mechanics Analysis of Indian Point Unit 3 Nuclear Generating Statton Steam Generator Oirth Held Cracks " Response re util approach requested by B30504
 BAYNE.J P Power Authority of the State of New York B3/04/28 VAROA.S A Operating Reacturs Branch I 4pp 18291 223 24X Fichs 50-286.83/04/28.3305030408
- --8305030412 Rev 2 to "Fracture Mechanics Analysis of Indian Point Unit 3 Nuclear Generating Station Steam Generator Girth Weld Cracts " COTTER.K H., PARIS,P.C. Fracture Proof Design Corp. 83-154 RO2 83/04/11 113pp 18291 227 24% Fiche 50-286.83/04/28, 8305030408
- 305170637 Clarifies 821220 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review.per encl guidelines due in 30 days VARGA-S A Operating Reactors Branch 1 83/04/28 BAYNE.J P Power Authority of the State of New York 6pp 18476 354 24X Fiche 50-286,83/04/28.8309170637
- 305020455 Generic Ltr 83-19 to all power reactor % testing licensess re new procedures for providing public natice concerning issuance of Amends to OLs Svc list enc! EISCHHUT, D o Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 30506039/ Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point: Unit 3 Nuclear Generating Station. Steam Generator Curth Wald Cracks Under Pressurized Thermal Shock Conditions " Rept withhold (ref 10CFR2 790)
 BAYNE, J P Power Authority of the State of New York 83/05/03
 VARGALS A Operating Reactors Branch 1 2pp 18348 203 24X
 Fiche 50-286,83/05/03,8305060397
- -8305060407 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point, Unit 3 Nuclear Generating Station, Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions " Rept withheld (ref 10CFR2 770) COTTER.K If Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18348 203 24X Fiche 50~286,83/03/03.8305060397

- ~~8309060417 Submits application for withholding from public disclose, "Fracture Mechanics Analysis of Indian Point, Unit 3 Nuclear Generating Station, Steam Generator Girth Wold Cracks Under Pressorized Thermal Shock Conditions "COTTER, K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 4pp 18348 206 24X Fishe 50-286, 83/05/03, 830506.0397
- 8305060427 Forwards application for amend to License DPR-64, changing Tech Specs 4 2-3.4 2-3a.6 if & Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point BAYNE.J P Power Authority of the State of New York B3/05/03 VARGA.S A Depeating Reactors Branch I 2pp 18343 227 24X Fiche 50-286.B3/05/03.B305060427
- --8305060446 Application for amend to License DPR-64 changing Tech Specs 4 2-3.4 2-3a.6 11 % Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point

 BAYNE, J P Power Authority of the State of New York 83/05/03 4pp 18343 227 24X Fiche 50-286.83/05/03,8305060427
- --8303060449 Proposed changes to Tech Specs 4 2-3, 4 2-3a, 6 ij & Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point * Power Authority of the State of New York 83/05/03 App 18343 233 24X Fiche 50-286,83/05/03,8305060427
- 830306043) Forwards application for amend to License DPR-64, changing Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 % Tables 3 6-1 % 4 4-i to reflect containment isolation valve mods % NRC & util organizational changes
 BAYNELJ P Power Authority of the State of New York 83/05/03 VAROALS A Operating Reactors Branch 1 3pp 18351 199 24X Fiche 30-286,83/05/03,8303060431
- --8303060432 Application for amend to License DPR-64, changing Tech Specs 6 7 1,6 7 1 4,6 7 1 7,6 7 1 8,6 7 2 % Tables 3 6-1 % 4 4-1 to reflect containment isoletion valve mods & NRC & util organisational changes.

 BAYNE, J P Power Authority of the State of New York 83/05/03 1p 18351 202 24% Fiche 50-286,83/05/03,8305060431
- --B305060433 Proposed changes to Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment isolation valve mode & organizational changes W/one oversize drawing Aperture card is available in PDR * Fower Authority of the State of New York 83/05/03 13pp 18351 203 24X Fiche 50-286,83/09/03,8305060431
- 8305040439 Forwards draft Rev I to Vol I of "Sys Interaction Study," incorporating organizational changes Comments requested by 830515 BAYNEIU PROBER Authority of the State of New York 83/05/03 VAROAIS A Operating Reactors Branch I 2pp 18343 303 24X Fiche 50~286,83/05/03.8300060439
- --8305060440 Draft Rev 1 to Vol 1 of "Sys Interaction Study "
 * Ebasco Services. Inc (subs of Enserch Corp) 83/05/03
 Pipp 18343 305 24% Fiche 30-286,83/05/03,8305060439
- 8305130117 Forwards Rev 2 to Procedure SDP-80-2, "Secondary Plant Chemistry Control" & Rev 2 to Procedure RE-CS-12, "Routine Chemistry Specs & Frequency," in response to NRC 830421 ltr & discussion at 830429 meeting BAYNE, JP Power Authority of the State of New York 83/05/03 VARGA; S A Operating Reactors Branch 1 ip 18438 009, 24X Fiche 30-286, 83/05/03, 8305130117
- --8305130120 Rev 2 to Procedure RE-CS-012, "Routine Chemistry Specs & Frequency "
 KERNS.H Power Authority of the State of New York 83/05/02
 18pp 18438 010 24% Fiche 50-286,83/05/03,8305130117
- --8305130123 Rev 2 to Procedure 90P-96-2, "Secondary Plant Chemistry Control " GILLEN.J Power Authority of the State of New York 83/05/02 16pp 18438 029 24% Fiche 50-286.83/05/03,8305130117
- 8305040323 Roard Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 rs Unresolved Safety Issue A-17 EISEMHUT, D 9 Division of Licensing 83/05/04 PALLADING, N Commits formers 22pp 18337 139 24X Fiche 50-000.83/05/04, 8305040323

- 8305110053 Forwards application for amend to License DPR-64, changing Tech Specs re safety limit, reactor core & control rod & power distribution limits, shutdown reactivity & deleting refs to three-loop operation
 BAYNE, J P Power Authority of the State of New York B3/05/05 VARGA, S A Dperating Reactors Branch 1 2pp 18408 003 24X Fichs 50-286, 83/05/05, 8305110053
- --8305110058 Application for amend to License DPR-64, changing Tech Specs re safety limit-reactor core & control rod & power distribution limits, shutdown reactivity & deleting refs to three-loop operation BAYNE, J P Power Authority of the State of New York 83/05/05 ip 18408 005 24% Fiche 50-284,83/05/05,8305110053
- --8305110063 Proposed Tech Spec changes re safety limit, reactor core & control rod & power distribution limits, shutdown reactivity Refs to three-loop operation deleted since facility restricted to 10% power + Power Authority of the State of New York 83/05/05 27pp 18408 006 24% Fiche 50-286.83/05/03.8305110053
- 8305090639 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT, D @ Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000, 83/03/09, 8305090659
- 8305130037 Forwards supplemental info to 821012 response re NUREG-0737. Item II B 3, "Post-Accident Sampling Sys " Response to NRC Guestion 9(6) not presently available Info will be submitted by 830615
 8AYNE.J P Power Authority of the State of New York 83/05/10 EISENHUT.D 0 Division of Licensing 16pp 18437 010 24X Fiche 50-286:83/05/10.8305130039
- 830518003B Notification of contract execution.Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ HDYLE.A Administrative Contracts Branch FIN B-8644 83/05/10 DENTON,H Office of Nuclear Reactor Regulation, Director CODELL,R NRC No Detailed Affiliation Given 1p 18499 289 24X Fiche 50-247.83/05/10.8305180038
- --8305180047 Mod 1, extending period of performance to 830630 & changing payment & general provisions, to "Consulting Svt on Indian Point Probabilistic Safety Study"

 LEMIS. J P Columbia Univ REBELLO, J E Division of Contracts 83/03/10 1p 18499 290 24X Fiche 50-247, 83/05/10, 8305180038
- 8305160088 Advises that no basis exists to further delay facility startup per 821019 amend application re steam generator tube sleeving & 830503 order concerning emergency preparedness SINCLAIR.L W Power Authority of the State of New York 83/05/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 18450 357 24X Fiche 50-286:83/05/12.8305160088
- 8305200405 Forwards Rev 3, to "Fracture Mechanics Analysis of Steam Generator Cirth Held Cracks " BAYNE, J P Power Authority of the State of New York 83/05/16 VAROA, S Operating Reactors Branch 1 1p 18317 175 24X Fiche 50-286,83/05/16,8305200405
- --B305200412 Rev 3 to "Fracture Mechanics Analysis of Steam Generator Girthweld Cracks" COTTER.K H., PARIB.P C Fracture Proof Design Carp 83-154 RO3 83/05/03 119pp 18517 176 24X Fiche 50-286.63/05/16. 8305200405
- B305240529 Responds to request for info re seismic qualification of auxiliary feedwater sys "Alarm Response Procedures Panel BCF Condensate & Boiler Feed ARP-6," revised to include listed manual actions
 BAYNE, J D Power Authority of the State of New York B3/05/18
 VAROA, 8 A Operating Reactors Branch 1 2pp 18571 123 24X
 Fichs 50-286/83/05/18/8305240529.
- B303240349 Forwards add1 info re ability of purge & vent valves to function against accident containment pressures, per B30208 ltr
 BAYNE.J P Power Authority of the State of New York B3/05/19 VAROA.S A Operating Reactors Branch 1 15pp 18574 056 24X Fiche.30-286.B3/05/19.B305240349
- B305240090 Submits varification of steam generator repair info requested in B30520 telcon Addl info re dose breakdown by major task & total dose for sleeving & girth weld repairs ancl BAYNE, J P. Power Authority of the State of New York B3/05/20 VAROA; 8 A Decrating Reactors Branch 1 6pp 18348 335, 24X Fiche 30-286:83/05/20:8305240090

- 8305240234 Documents NRC/util telcon re seismic qualification documentation for auxiliary Peedwater sys /, proposed fire protection Tech Specs Tech Specs on quarterly surveillance of alternate electrical feed sys to be submitted BAYNE, J P Power Authority of the State of New York 83/05/20 VARGA, S A Operating Reactors Branch 1 2pp 18548 307 24X Fiche 50-286, 83/05/20, 8305240234
- 8303240328 Forwards, "Identification & Listing of Electrical Equipment Important to Safety per 10CFR30 49" Nonsafety-related electric equipment w/failure that would prohibit accomplishment of safety functions not identified BAYNE.J P Power Authority of the State of New York 83/05/20 VARGA.S A Operating Reactors Dranch 1 36pp 18349 239 24% Fiche 50-286.83/05/20,8305240328
- Q Inspection reports, IE Builetins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Inn Exchange Resin Susceptibility to Exothermic Chemical Reaction" Svc list encl TAYLOR,J M. Division of Safeguards & Inspection Programs (Post 830103) B3/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21.8212060385
- B30304002! IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000.B3/04/15.8303040021
- 8305050280 Forwards request for add1 info re secondary water chemistry program concerning steam generator girth weld inservice insp NRC approval of program necessary prior to plant startup Meeting re subj requested as sonn as possible VARGA.5 A Operating Reactors Branch | 83/04/21 DAYNE.JP Power Authority of the State of New York Spp 18352 065 24X Fiche 50-286,83/04/21,8305050280
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 182pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York
- 8305100405 Forwards IE Insp Rept 50-286/83-07 on 830316-0415 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/04/25 BRONS, J C Power Authority of the State of New York 2pp 18378 046 24X Fiche 50-286/83/04/25/8305100405
- --B305100410 IE Insp Rept 50-286/83-07 on 830316-0415 No noncompliance noted Major areas inspected regular & backshift insps of operations, surveiliance, maint, monthly operating rept review, design changes & mods & repair work update KENNY,T J . ROSSBACH,L W . KISTER,H Region 1. Defice of Director B3/04/22 9pp 18378 037 24X Fiche 50-286. B3/04/25. B305100405
- 8303040024 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830403) 63/04/28 Consolidated Edison Co of New York, Inc 113pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E.L Division of Emergency fraparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York. Inc 189p 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8305020451 Submits info on status of Ray Hiller.Inc problems affecting plant, per ASLD request.

 MODRE, J E Heaping Branch 1 B3/04/28 GLEASDN, J P Atomic Safety and Licensing Board Panel 88pp 18283 180 24X

 Fiche 50-247, 83/04/28, 8305020451
- 8303040028 IE Info Notice 83-26, "Failure Discharge Line Vacuum Breakers" Svc lis JORDAN,E L Division of Emergency Prepa Response (Post 830103), 83/05/03 Co York, Inc 122pp 18441 J70 24X Fiche

- 8303040039 IE Infa Notice 83-27. Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipmen' 'Svc list encl
 JORDAN E.L. Division of Emergency Preparedness % Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co. of New
 York, Inc. 112pp 18382 282 24% Fiche 50-000,83/05/04,8303040030
- 8303040031 [E Info Notice 83-28. Criteria for Protective Action Recommendations for Ceneral Emergency Preparedness & Engineering
 JORAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 119pp 18441 001 24x Fiche 50-000.83/05/04,8303040031
- B305:10167 Advises that util util perform mid-cycle smsp of steam generator girth welds Preliminary results & corrective measures util be forwarded to MRC 5 days prior to plant startup BAYNELJ P Power Authority of the State of New York B3/05/05 VARGA: S A Operating Reactors Branch I ip 18407 121 24X Fiche 50-286.83.05/05.8305110167
- 8303040033 IE Info Notice 83-29. Fuel Binding Caused by Fuel Rack Deformation "Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post B30103) B3705/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24x Fiche 50-000,83705/06,8303040033
- \$303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list oncl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York Inc. 114pp 18524 003 24x Fiche 50-000,83/05/11.8303040034
- 8305250503 Forwards IE Insp Rept 50-286/83-09 on 830418-22 No
- noncompliance noted

 MARTIN.T T Division of Engineering & Technical Programs 83/05/12

 BRORS.U C Power Authority of the State of New York 2pp

 18584 001 24X Fiche 50-286.83/05/12.830220003
- --8305250507 IE Insp Rept 50-286/83-09 on 830418-22 No noncompliance 305≥30007 it insp Rept 30-200/83-07 on 300410-22 No monicomp₂ in noted Major areas inspected status of repeir operations for cracted upper shell to transition cone closure ueld on four REYNOLDS: S D . DURR. J Region 1. Office of Director 83/05/06 9pp 18584 003 24X Fiche 50-286.83/05/12.8305250503
- 8305250226 Forwards IE losp Rept 50-286/83-05 on 830328-31 No
- --8305250230 IE Insp Rept 30-286/83-05 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply wfrequirements of NUREG-0737, Item II B 2, "Design Review of Plant Shiplane" Plant Shelding "HAVERAMP,D R , KENNY,T J , EAPEN,P K Region 1. Dffice of Director 83'05/12 12pp 18627 019 24X Fithe 50-286,83/05/13,8305230226
- 9305250538 Notification of 830520 significant licensee meeting w/util In Buchanan NY to present results of SALP repts
 KISTER.H B Region 1. Office of Director 83/05/17 Region 1.
 Office of Director 820 18594 354 24X Fiche 50-000,83/05/17.
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " 703040040 IE Info Notice 03-31, Error in Roberts Competent Syc list enri Syc list enri JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8303040040 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 30-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & Obligge Forwards "Annual Environ Crosection Field Rep. 1982," per App B TO ULS
 10/100E.J D Consolidated Edison Co of New York. Inc 83/05/06
 ALLAN.J M Region 1. Office of Director 2pp 18392 221 24X
 Fiche 50-003.83/05/02.8305110302
- ~-8305110307 "Annual Environ Protection Plan Rept for 1982 " 305110307 "Annual environ provection man kep; for 1702 4 Consolidated Edison Co of New York, Inc 83/05/02 8pp 18392 223 24% Fiche 50-003,83/05/02,8305110302

- --8305110310 "Annual Radiological Environ Operating Rept, 1982 "

 * Consolidated Edison Co of New York, Inc 83/05/02 118
 18392 231 24X Fiche 50-003.83/05/02,8305110302
- S Reportable occurrences, LERs & related correspondence
- B305030274 PNS-I-83-008 on B30424, security officer overheard voices from storage trailer in protected area Officers apprehended four contractor employees exiting trailer rear window Search revealed marijuana cigarette Employees suspended MCKEOWN.L., GDDY.A.T., JONNER.J.H. Region I. Office of Director 83/04/25 1p 18277 144 24X Fiche 30-286, B3/04/25, B305030274
- 8305110439 PN5-1-83-012 on 830505. Licenses informed Region 1 that contract health physics employee of Inst for Resource Mgt arrested on suspected multiple federal drug-related charges Individual access to site voided as of 830505 MCKEGNN, BAILEY, GDDY Region 1, Office of Director 83/05/05 ip 18405 087 24X Fiche 50-286,83/05/05,8305110439
- T Hearing transcripts on non-antitrust matters
- 8305230001 Transcript of 830322 hearing in White Plains,NY Pp 10,737-11,117 Supporting documentation encl * Atomic Safety and Litensing Board Panel 83/03/22 418532 021 24% Fiche 50-247,63/03/22,8305230001 83/03/55 915bb
- 8305110002 Excepts from transcript of 83040/ hearing Pp 13,017-13.019.

 NRC No Detailed Affiliation Given 83/04/07 3pp 18409 007 24x Fiche 50-247,83/04/07,8305110002
- 8305030608 Mution for permission to present rebuttal witnesses on subj of prevailing winds.sample surveys b bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence POTTERFIELDA Union of Concerned Scientists PC Potterfield, A 83/04/19 4pp 18308 050 24X Fiche 50~247,83/04/19,8305030608 POTTERFIELD, A
- --8305030619 Testimony of D Outman re prevailing wind patterns
 GUTMAN.D Union of Concerned Scientists GUTMAN.D Public
 Interest Research Group, New York GUTMAN.D New York, NY
 83/04/19 4pp 18308 054 24X Fiche 50-247,83/04/19,8305030608
- --8305030629 Testimony of RR Holt re sample surveys & bystander behavior HOLT.R R Union of Concerned Scientists HOLT.R R Public Interest Research Group, New York HOLT.R R New York, NY 83/04/19 37pp 18308 058 24X Fiche 50-247,83/04/19,8305030608
- --8305030633 Reorganized testimony of JR Thornborough & D Bohning re Contention 6 2 concerning impact of shutdown on physical environ near facility FIGNER, P Parents Concerned About Indian Point 83/04/19 44pp 18308 095 24% Fithe 50-247,83/04/19,8305030608
- --B303030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site & difficulty of evacuation in emergency POTTERFIELD, A Public Interest Research Group, New York B3/04/26 Atomic Safety and Licensing Board Panel Bpp 18308 139 24X Fiche 50-247,83/04/19,8305030668
- --8305030652 Motion requesting completeness of record on NRC Questions 105030652 Motion requesting completeness or record on this S.S. 4 re emergency planning issues, including capability for handling phone calls in emergency planning zone during POTTERFIELD, A Union of Concerned Scientists Safety and Licensing Board Panel 4pp 18308 180 24x Fiche 50-247,83/04/19,8305030608 Atomic
- 8305020077 Transcript of 830426 hearing in White Plains, NY Pp 14.419-14.596 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/04/26 210pp 18278 250 24X Fiche 50-247.83/04/26.8305020077
- 8305030386 Transcript of 830427 hearing in White Plains, NY Pp 14, 397-14: Atomic Safety and Licensing Board Panel 83/ 18292 001 24X Fiche 50-247,83/04/27,8305030386 83/04/27 116pp
- 8305040172 Transcript of 830428 hearing in White Plaine, NY Pp 14, 703-15,087 Supporting documentation *ancl * Atomic Safety and Licensing Board Panel 83/04/28 524pp 18324 297 24X Fiche 50-247,83/04/28,8305040172
- 8305090425 Testimony of LA Cohen in rebuttal to testimony of D Gutman Testimony to be included w/ASLB 830420 transcript Certificate of Svc encl.
 COHEN, L. A. Consolidated Edison Co. of New York, Inc. 83/04/2B 10pp 18363

- 8303040347 Transcript of 830429 hearing in White Plains, NY Pp 15,088-15,226 Supplemental testimonies encl * Atomic Safety and Licensing Board Panel 83/04/29 149pp 18322 242 24% Fiche 30-247,83/04/29,8305040347
- 8305130327 Transcript of Commission 830505 meeting discussion & possible vote in Washington DC re status of emergency planning at facilities Pp 1-22
 Commissioners 83/05/05 27pp 18457 277 24x
 Fiche 30-247,83/05/03,8305130327
- 8305240554 Statement to be incorporated in minutes of Commission 830526 public hearing State/federal govt must force counties to devise evacuation plans Problems w/emergency plans must be resolved before 830609 pl 01AcOMO.C G Cortland. NY 83/05/18 4pp 18576 029 24% Fiche 50-247.83/05/18.8305240554
- 8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR: per 10CFR9 Commission determination statement encl CHILK, B J Office of the Secretary of the Commission 83/05/18 Public Document Branch 2pp 18593 063 24X Fiche 50-003.83/05/18, 8305240566
- --8309240570 Transcript of 821222 discussion & passible vate on emergency planning actions in Washington, DC

 Commissioners 82/12/22 15pp 18593 065 24X

 Fiche 50-003,83/05/18,8309240566
- --8309240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington.DC # Commissioners 82/12/22 59pp 18593 082 24X Fiche 50-003.83/03/18.8309240586
- 8305240531 Statement of Clergy, Religious & Laity Concerned About Indian Point Common citizens reject idea that expertise irrelevant Value of human life is supreme value * Affiliation Unknown 83/05/20 4pp 1057(105 24X Fiche 50-247,83/05/20,830524053)
- 8305240533 Forwards written testimony on efforts to address deficiencies in emergency response plan since 830505 D'RDURKE, A P Westchester County, NY 83/03/20 PALLADINO, N J. OILINSKY, V, AILGARNEJ, Commissioners ip 18976
- --8305240539 Testimony of AP O'Rourke re actions taken to improve emergency planning since Commission 830505 order Unions representing bus drivers fully support orientation course on radiological emergency response procedures 0.780URKE, A P Westchester County, NY 83/05/20 App 18576-044 24X Fiche 50-247,83/05/20,8305240539
- B305240555 Forwards statement for inclusion in special proceeding testimony HEIBS.T House of Rep. B3/05/20 PALLABINO.N Commissioners 1: 1876 025 24X Fiche 50-247.B3/05/20.B305240555
- --8305240598 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futtle Public safety should be top priority WEISET. House of Rep 83/05/19 3pp 18576-026 24% Fiche 50-247,83/05/20.8305240955
- B305310002 Testimony of RW Carlisle re potential hazards of nuclear accidents Long-range educ in nuclear radiation should be implemented Robots should be developed to dismantle plant after meltdown CARLISLE, RW Affiliation Unknown 83/05/20 Jpp 18653 240 24X Fichs 50-247, 83/05/20, 8305310002
- 8305310055 Transcript of Commission 830523 discussion of Indian Point order in Washington.DC Pp 1-17 # Commissioners 83/05/23 23pp 18663 128 24X Fiche 30-247, 83/05/23, 8305310055
- U Congressional/Executive Correspondence
- B305240555 Forwards statement for inclusion in special proceeding testimony WEISS.T House of Rep. B3/05/20 FALL. PDIND. N Commissioners ip 18576 025 24X Fiche 50-247. B3/05/20, B305240555
- ---B305240558 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile. Public safety should be top priority WEISB. T House of Rep. B3/05/19 3pp 18576 026 24X Fiche 50-247.83/05/20,8305240555

- B309310099 Commends State of NY commitment of resources & cooperation w/licensees & local govts to implement offsite coordinate preparedness plan plan pauLLADINO.N J Commissioners 83/05/25 CUONO.M New York, State of \$p 18453 280 24% Fiche 30-247, 83/05/25, 8305310059
- --8309310070 Expresses concern that additactions required to satisfy mandates per 10CFR30 54(8)(1) State of NY Disaster Preparedness Commission will work w/utils until Rockland County completes emergency preparedness plans CUDMIN M New York, State of 83/03/25 PALLADINO, N J Commissioners 3pp 18653 281 24X Fiche 90-247, 03/05/25, 82083100398
- DUCKET 50-287 OCONCE NUCLEAR STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8305270326 Forwards IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/05/06 TUCKER,H B Duke Power Co 2pp 18641 142 24X Fiche 50-269, 83/05/06, 8305270376
- --8305270338 IE Insp Repts 50-269/83-13.50-270/83-13 % 50-207/83-13 on 830311-0410 No noncompliance nuted Major areas inspected surveillance testing maint & operations & annual emergency drill BRYANT, J Region 2, Office of Director 83/05/06 9pp 19641 144 24% Fiche 50-269.83/05/06.8303270326
- B305270374 Forwards IE Insp Repts 90-269/63-10.50-2/0/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/06 TUCKER,H B Duke Power Co 2pp 18643 011 24X Fiche 50-269, B3/05/06, 8305270374
- --8305270387 IC Insp Repts 50-269/83-10,50-270/83-10 % 50-287/83-10 on 830403-06 No noncompliance noted Major areas inspected emergency preparedness exercise HUFFMAN 0 N Region 2, Office of Director 83/05/03 iOpp 18643 013 24X Fiche 50-269,83/03/06,8305270374
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for CLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl
 EISENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pe 18540 095 24X Fiche 50-000, 83/05/11, 8305110034
- J Insurance & indemnity information
- 8303260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-10i.respectively for McGure LAWGON, L T Duke Power Co 83/05/20 SALTZMAN, J Office of Resource Management, Director 19pp 18626 120 24x Fiche 50-000,83/05/20,8305260261
- P Operating license stage documents & correspondence
- 8305240247 FOIA request for three categories of documents re Reactor 8efety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802) SHOLLY, S C Union of Concerned Scientists B3/03/ii FELTON, J M Division of Rules and Records 1p 18593 178 24X Fiche 50-000, 83/03/ii, 8305240249
- 8305240234 Partial response to FDIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress FELTON.J M Division of Rules and Records 83/03/31 SHOLLY, S C Union of Concerned Scientists 2pp 18993 179 24% Fiche 50-000, 83/03/31, 8305240254
- --8305240259 Forwards comments on draft rept re Reactor Safety Study
 Methodology Applications Program for facility Changes
 indicated in areas of validity of sys criteria & correctness
 & appropriateness of assumptions in sys analysis
 PARKER, W O Duke Power Co 80/09/22 BERNERD R Probabilistic
 Analysis Staff (Pre 801119) iipp i8593 iBI 24X
 Fiche 50-000, 83/03/31,8305240254

- 8305090078 Forwards Amends (20.120 & 11° to Licenses DPR-38, DPR-47 & DPR-35, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules

 CONNER, E L Operating Reactors Branch 4 83/04/15 TUCKER, H B Dute Power Co 4pp 18381 140 24: Fichs 50-269, 83/04/15, 8383890728
- --8305070111 Amends 120,120 & 117 to Licenses DPR-38, DPR-47 & DPR-59, respectively, revising Tech Spec uithdrawal schedule for reactor vessel surveillance capsules STOLT.J F Operating Reactors Branch 4 83/04/15 8pp 18381
- --8305070124 Safaty evaluation supporting Amends 120,120 & 117 to Licenses DPR-3B DPR-47 & DPR-55, respectively • Office of Nuclear Reactor Regulation, Director 18381 152 24X Fiche 50-269,83/04/15,8303070078
- --8305070138 Notice of issuance % availability of Amends 120,120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively STDLZ.JF Derating Reactors Branch 4 83/04/19 2pp 18381 154 24X Fiche 50-269,83/04/15,8305090078
- 3305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation tept. "Control of Heavy Loads (C-10). Oconee Nuclear Power Station. Units 1,2 & 3 " Phase 1 actions acceptable per NUREG-0612 STOL2. J F Operating Reactors Branch 4 83/04/20 TUCKER. H B Duke Power Co 3pp 18457 179 24% Fiche 50-269, 83/04/20, 8305130294
- -8305130274 Safety evaluation supporting Phase I actions re control of heavy loads (MVREO-0612) * Office of Nuclear Reactor Regulation, Director 83/04/20 lp 18457 (82 24X Fiche 50-269,83/04/20,8305130294
- -8304070286 "Control of Heavy Loads (C-10). Oconee Nuclear Power Station Units 1.2 & 3." technical evaluation rept ROBERTS. 8 Franklin Institute/Franklin Research Center NRC-03-81-130 TER-0506-374/379/37 83/03/31 CLEMENSON,F NRC - No Detailed Affiliation Given 29pp 18457 183 24X Fiche 30-269,83/04/20,8305130274
- 305090508 forwards safety evaluation in support of continued PNR operation w/Dresser primary safety valves ro TMI Action Item II D i EPRI data on tests of certain models of Dresser safety valves under review on generic basis 8TOCZ. J T Operating Reactors Branch 4 83/04/27 TUCKER. H B Dute Power Co 2pp 18367 III 24X Ficha 50-269,83/04/27,830309608
- 305040544 Forwards proposed App A to offsite dose calculation manual, supporting radiological effluent Tech Spec per 830209 itr Submittal constitutes final revised offsite dose calculation manual TUCKER.H B Duke Power Co G3/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 ip 18320-083 24X Fichs 50-269.83/04/28.8305040564
- 8305040569 App A to, "Oconee Nuclear Station Site Specific Info " * Dute Power Co 83/04/28 32pp 18320 084 24X Fiche 50-269,83/04/28,8305040564
- 05200103 Forwards safety evaluation on standby shutdown facility Dasign meets requirements.except for process monitoring instruments for source range flux monitoring & steam enerator pressure indication STOLZ, J F Operating Reactors Branch 4 83/04/28 TUCKER, H B DUKE Power Co 4pp 18576 154 24X Fiche 50-269,83/04/28, 9305200103
- 3305200106 Safety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication * Office of Nuclear Reactor Regulation, Director 93/04/28 17pp 18576 158 24% Fiche 50-267,837.04/28,8305200103
- ISD20455 Generic Ltr 83-19 to all power reactor & testing licensees a new procedures for providing public notice concerning squance of amends to OLs Svc list encl ISENHUT.D G Division of Licensing B3/05/02 Consolidated dison Go of New York. Inc 50pp 18441.120 24% iche 50-000,83/05/02.8305020455
- 3060365 Notification of B30506 meeting w/B&W Owners Group in ethesda:MD to discuss core barrel failure at Rancho Seco & rystal River 3, Puture plans for resolving problem & ustification for continued operation INER.S Operating Reactors Branch 4 83/05/02 STOLZ.J ierating Reactors Branch 4 2pp 18353 092 24X he 50-900.83/05/02.8305060365

- B305090435 Forwards safety evaluation of implementation of asymmetric fault for control rod 6-3 during Cycle 7 Method for restoring normal operating flexibility can be undertaken w/o affecting plant safety THIES. A C Duke Power Cq B3/05/04 DENTON, HR Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 18363 071 24X Fiche 50-287,83/05/04,8305090435
- B305180034 Forwards Amends 121.121 & 118 to Licenses DPR-38.DPR-47 & DPR-35.respectively, safety evaluation & notice of issuence & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage EISENHUT.D 0 Division of Licensing B3/05/05 TUCKER.H B Duke Power Co 3pp 18499 245 24X Fiche 50-269.83/05/05.8305180034
- --8305180045 Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to delay certain surveillance requirements until next refueling outage STOL7, JF Operating Reactors Branch 4 83/05/05 2ipp 18479 248 24X Fiche 50-269, 83/05/05.8305180034
- --8305180059 Safety evaluation supporting Amends 121.121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively Office of Nuclear Reactor Regulation, Director 83/05/05 5pp 18499 269 24X Fiche 50-269,83/05/05,8305180034
- --8305180068 Notice of issuance & availability of Amends 121,121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively STOLZ, JF Operating Reactors Branch 4 83/05/05 2pp 18499 274 24X Fiche 50-269,83/05/05.8305180034
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fiche. 50-000. 83/05/09.8305090659
- B305180151 Forwards request for add1 info re details on void formation during natural circulation cooldown.per 810505 Generic Ltr 81-21 Response dtd 811105 imadequate
 BTOLZ.J F Operating Reactors Branch 4 83/05/09 TUCKER.H B
 Duke Power Co 4pp 18502 344 24X Fiche 50-269.83/05/09,
 B305180151
- 9305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCS temp between 250 F & 225 F rather than present 200 F Preparation of proposed Tech Specs re purging in progress TUCKER, H J Duke Power Co 83/05/10 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 19437 154 24X Fiche 50-269,83/05/10,8305130025
- 8305230499 Notafication of 830408 meeting w/util in Bethesda, MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed SUERMANN.JF Operating Reactors Branch 4 83/05/16 STOLZ.JF Operating Reactors Branch 4 2pp 18541 274 24X Fiche 50-000.83/05/16.8305230499
- 8305230479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation, per NUREG-0737. TMI Action Item II B 4 provided Response to IE Bulletin 79-018 will be revised TUCKER.H B Duke Power Co 83/05/19 DENTON.H R Dffice of NUCKER.H B 10 Duke Power Co 83/05/19 DENTON.H R Dffice of A 27pp 18589 005 24X Fiche 50-269,83/05/19,8305250479
- 8305310081 Submits add1 info re safety-related environ qualification of electrical equipment.per 10CFR50. 49(g) & IE Bulletin 79-018 Electrical isolation provided for all reactor protective sys tengineered safeguards protective sys TUCKER.H B Duke Pawer Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18655 123 24X Fiche 50-269.83/05/20.8305310081
- 8305310083 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads Util assessment of asymmetric loads problem acceptable STOLZ.J F Operating Reactors Branch 4 83/05/20 TUCKER.H B Duke Power Co 2pp 18662 311 24% Fiche 50-269,83/05/20,8305310083
- --8305310089 Safety evaluation afcepting util analysis of asymmetric LOCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided

 * Operating Reactors Branch 4 83/05/20 74pp 18462 313 24X
 Fiche 50-269, 83/05/20, 8305310083

Q Inspection reports, IE Bulletins & correspondence

- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction" Syc list encl
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212060385
- 8305270403 Forwards IE Insp Repts 50-249/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/04/05 TUCKER.H B Duke Power Co 2pp 18642 321 24X Fiche 50-269, 83/04/05, 8305270403
- --B3052704ii IE Insp Repts 50-269/83-08.50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted Major areas inspected operations, surveillance testing, maint, event rept review & emergency procedure review BRYANT.J. FALCONER.D Region 2. Office of Director IONATONIB.A J Division of Project & Resident Programs 83/04/04 12pp 18642 323 24X Fiche 50-269.83/04/05.8303270403
- 8305270497 Forwards IE Insp Repts 50-269/83-09, 90-270/83-09 & 50-287/83-09 on 830308-ii' No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/05 TUCKER, H B Duke Power Ca 2pp 18646 192 24X Fiche 50-269, 83/04/05, 8305270497
- --8305270318 IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREO-0737. Items II B 2. "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys " COLLINS, T R , BARR, W P Region 2, Office of Director 83/04/01 7pp 18646 194 24X Fiche 50-269, 83/04/05, 8305270497
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator "
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040025 IE Info Notice 83-22, "DWR Safety/Relief Valve Failures"
 Svc list encl
 JURDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Syc list enc!

 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enci JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fichs 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Banding Caused by Fuel Rack Deformation " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06.8303040033

- 8305270326 Forwards IE Insp Repts 50-269'83-13.50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/06 TUCKER, H B Duke Power Co 2pp 18641 142 24X Fiche 50-269; 83/05/06, 9305270326
- --8305270338 IE Insp Repts 50-269/83-13,50 270/83-13 & 50-287/83-13 on 83031-0410 No noncompliance noted Major areas inspected surveillance testing, maint? operations & annual emergency drill BRYANT, J. FALCONER, D. Region 2. Office of Director BROWNLEE, V. L. Division of Project & Resident Programs 83/05/06 9pp 18441 144 24X Fiche 50-269,83/05/06,8305270326
- B305270374 Forwards IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No nencompliance noted DANCE, H C Division of Project & Resident Programs 83/05/06 TUCKER, H B Duke Power Ca 2pp 18643 011 24X Fiche 50-269, 83/05/06, 8305270374
- --8305270387 IE Insp. Regts 50-249/83-10,50-270/83-10 & 50-287/83-10 on 830405-04 No noncompliance noted Major areas inspected emergency preparedness exercise
 HUFFKAN, 0 N Region 2, Office of Director JENKINS, 0 R Division of Emergency Preparedness & Naterials Safety 82/05/03 10pp 18443 013 24X Fiche 50-267,83/05/06.83052/0374
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000.83/05/11.8303040034
- 8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concein re open pressurization line test valve on Unit 3 discussed O'REILLY, J P Region 2, Office of Director 83/05/11 TUCKER, H B Duke Power Co 2pp 18442 280 244 Fichs 50-269, 83/05/11, 8305270429
- ~-8305270435 IC Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 Major areas discussed open pressurization line isolation valve on emergency hatch on 830317 & corrective actions

 DANCE, H C Division of Project & Resident Programs 83/05/10 5pp 18642 282 24X Fiche 50-269,83/05/11,8305270425
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 830531008i Submits add1 info re safety-related environ qualification of electrical equipment, per IOCFR50 49(g) & 1E Bulletin 77-01B Electrical isolation provided for all reactor protective sys t engineered safeguards protective sys TUCKER.H B Duke Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director & STOLZ, J F Operating Reactors Branch 4 3pp 18455 123 24% Fiche 30-249,83/05/20,8305310081
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Dil" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 50-000,83703/26,8303040046
- R Pariodic operating reports & related correspondence
- 8305170455 Forwards monthly operating repts for Apr 1983 TUCKER.H D Duke Power Co 83/03/13 Director's Office of Inspection and Enforcement ip 18470 142 24X Fiche 50-269.83/05/13.8305170455
- --8305170460 Monthly operating repts for Apr 1983 REAVIS-J A Duke Power Co 83/05/13 16pp 18470 143 24X Fiche 50-269,83/05/13,8305170455
- S Reportable occurrences, LERs & related correspondence

- 8305050254 RDs 269/83-10 & 287/83-04 to H21212 & 830303 loss of containment integrity Mgt audit in progress Summary list of completed & remaining activities w/projected completion dates, encl
 TUCKER.H B Duke Power Co 83/04/29 O'REILLY, J.P. Region 2, Defice of Director 15pp 18338 001 24% Fiche 50-269,83/04/29,83050254
- G305250556 Notifies that mobile gas monitor-stack high-range radiation monitor (NUREG-0737, Item II F 1(1)) reported as being operable in B30318 order-became inoperable on B30426 Caused by moisture contamination New monitors ardered TUCKER, H B Duke Pawer Co 83/05/19 DENTON, HR Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactor Branch 4 2pp 18588 185 24X Fiche 50-269, 83/05/19, 8305250556
- DOCKET 30-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8305030693 Releases public version of revito emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18309 116 24% Fiche 50-289,83/04/22,8305030693
- ---8305030695 Public version of Rev 6 to Emergency Plan Implementing Procedure 1004 6. "Addl Assistance & Notification " STANGE, S J General Public Utilities - QPU Service Corp 83/03/17 210 18307 117 24X Fiche 50-289.83/04/22,8305030693
- 8305050300 Releases public version of rev to emergency plan implementing procedure FELTON. JM Division of Rules and Records 83/04/25 Document Management Branch 1p 18352 147 24X Fiche 50-289,83/04/25.8309050300
- --8305050304 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure 1004 12, "Environ Monitoring " Receipt form encl MASH, B. General Public Utilities - GPU Service Corp. 83/02/23 DENTON-H R. Office of Nuclear Reactor Regulation, Director 1 18352 170 24X Fiche 50-289, 83/04/25, 8305030300
- ---B305050307 Public version of Rev 3 to Emergency Plan Implementing Procedure 1004 12, "Environ Monitoring" STANGE: 5 J General Public Utilities - GPU Service Corp 83/02/15 14pp 18352 171 24X Fiche 50-289.83/04/25.8305050300
- 3305100143 Submits status of offsite emergency preparedness issues re FEMA regional varifications through 830304 & data received through 830331 concerning schedule for completion of issues at facilities KRIMM,R W Foderal Emergency Management Agency 83/04/26
- RRIMM, R W Foderal Emergency Management Agency 83/04/26 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 9pp 18375 001 24X Fiche 50-289,83/04/26, 8305100143
- I305130180 Advises that emergency preparedness briefings conducted for major employers & operators in locations within emergency planning ione plume exposure pathway Partial initial decision conditions satisfied HUKILL, H D General Public Utilities GPU Service Corp 63/05/09 STOLZ, UF Operating Reactors Branch 4 1p 18440 084 24X Fiche 50-289,83/05/09,8305130180
- IBO5110034 Owneric Ltr 83-21 to all licensess of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Eve list encl EISENHUT, D © Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540-075 24X Fiche 50-000:83/05/11.8305110034
- 305190158 Clarifies 830331 ltr re reactor comlant pump trip on 25 F subcooling margin w/respect to qualification of saturation margin monitor sys Sys evaluated per Generic Ltr 82-33 & 830415 ltr Schedule for instrumentation upgrading unknown HUKILL.H D General Public Utilities CPV Service Corp 83/05/13 & EISEMHUT.D & Division of Licensing (p. 18502-239-24X Fiche 50-289, 83/05/13, 8305190158

Adjudicatory correspondence

305040054 Discusses status of BAW-GPU lawsuit document review Next rept expected within 2 wks
DIRCKS,W J Office of the Executive Director for Operations
83/04/20 PALLADINO,N , GILINSKY,V , AMEARNE,J Commissioners
2pp 18336 325 24% Fiche 50-289,83/04/20,8305040054

- --8305040068 Staff requirements memo re 830330 briefing on investigation a possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wks.

 CHILK, S. J. Office of the Secretary of the Commission 83/04/08 DIRCKS, W. J. Defice of the Executive Director for Operations HAYES, B. B. NRC No Detailed Affiliation Given CUMMINGS, J. Defice of Inspector & Auditor 2pp 18336-327 24X Fiche 50-289, 83/04/20, 8305040054
- G305230700 Requests cooperation in informing NRC of outstanding safety concerns refecilities Prompt notification re allegations of safety concerns requested PLAINE, H H Office of the General Counsel B3/04/20 DEVINE, T Government Accountability Project 2pp 18542 323 24X Fiche 50-289,83/04/20,8305230700
- 8305090504 Requests written statement under oath of affirmation as to whether or not indices discussed at 830412-14 meetings represent complete listing of all dispositions & exhibits developed for BAM-GPU lausuit
 DIRCKS.W J Office of the Executive Director for Operations
 83/04/21 ARNOLD.R C General Public Utilities GPU Service Corp
 2pp 18981 292 24X Fiche 30-289,83/04/21.830509050504
- 6305030591 Reply to NRC 830412 proposed opinion findings of fact & conclusions of law in reopened hearing Objects to nature of NRC proposed condition requiring dispatch of auxiliary operator Certificate of Svc encl
 BAXIER, T A Metropolitan Edison Co DAXIER, T A Shaw, Pittman, Potts & Trawbridge 82/04/28 6pp 18303 347 24X
 Fiche 30-289, 83/04/28, 8305030591
- 8303100406 Response opposing NRC oral motion to extend time for reply to intervenor motion to reopen restart hearing Sufficient time already provided Delay unnecessary Certificate of Svc & amended Certificate of Svc encl
 AAMODT.M M Aamodts, The 83/04/30 PALLADIND,N, AHEARNE,J,
 OILINSKY,V Commissioners 4pp 18377 352 24X
 Fiche 30-289,83/04/30,8305;00404
- 8305050033 Motion for extension until 830513 to respond to Aamodt 830416 motion to reopen record of restart proceeding Time needed so NRC response will not be filed before other parties due to manner of receipt Certificate of Svc encl HAGNER, M E Hearing Dranch 4 GDLDBERG, J R Hearing Branch 2 83/039/03 Commissioners 10pp 18342 069 24X Fiche 50-289,83/05/03,8305050053
- 8303090481 Matian for extension of time to respond to Asmodt motion to reopen record of restart proceeding HAGMER.M E Office of the General Counsel GOLDBERG, J R Hearing Branch 2 83/05/03 lp 18362 340 24X Fiche 50-289,83/05/03,8303090481
- 8305100205 Discusses selective withholding of info in 830201 memo forwarding Board Notification 83-08 re TMI-1 restart hearing Certificate of Svc encl AAMODT/N M Aamodts, The 83/05/03 EISENHUT, D @ Division of Licensing 2pp 18374 035 24X Fiche 30-289, 83/05/03, 8305100205
- 8305100212 Motion for summary disposition of B&W/OPU trial record No genuine issue of mati fact exists & TMI Alert entitled to favorable decision Svc list encl
 BRADFORD.L Three Mile Island Alert 83/05/03 Atomic Safety and Licensing Appeal Panel 5pp 18374 188 24X Fiche 50-287,83/05/03,8305100212
- 8303090431 Distribution of Rockwell rept re investigation of Hartman allegations concerning TMI-2 as part of TMI-1 restart proceeding Certificate of Svc encl TROWBRIDGE.0 F Metropolitan Edison Co TROWBRIDGE.0 F Shaw. Pittman. Potts & Troubridge 83/05/04 4pp 18342 357 24X Fiche 50-289.83/05/04.8305090431
- 8305060258 Order granting add1 time until 830601 to submit add1 comments on NRC review of OPU vs B&W trial record Trial & exhibits in NRC possession placed in PDR & LPDR Comments may be filed after 830601

 HOYLE,J C Office of the Secretary of the Commission 83/05/05 Union of Concerned Scientists App 18345 218 24X Fiche 50-289.83/05/05.8305060258
- 8305100283 Contends that planned change in reactor codiant pump trip setting b in throttling high pressure injection criteria does not affect evidence presented on performance under LOCA conditions Certificate of Svc encl BAXTER.T A Shaw, Pittman. Potts & Trombridge BAXTER.T A Metropolitan Edison Co 83/05/05 CDLES.G J. BUCK.J H. QDTCHY.R L Atomic Safety and Licensing Appeal Panel 4pp 18371 268 24X Fiche 50-289.83/05/05.8305100283

- 8305100357 Comments on ASLAP 830420 memo suggesting inter alia, that Commission exploie two concerns re facility PDRV prior to restart Resolution of PDRV corrosion issue alleady being pursued Certificate of Svc encl

 BAXTER.T A Metropolitan Edison Co BAXTER.T A Shaw. Pittman, Pitts & Troubridge 83/03/05 Spp 18379 093 24X

 Fiche 50-289,83/03/05.8305100357
- B305100310 Submits facts re personnel changes since close of lecord on mpt issues, per licensee B11001 procedures for info Resumes & svc list encl
 BAUSER,D B Shaw, Pittman, Potts & Trowbridge BAUSER,D B Metropolitan Edison Co B3/05/06 EDLES,G J , BUCK,J H , KOHL,C N Atomic Safety and Licensing Appeal Panel 13pp 18370 125 24X Fiche 50-289,83/05/06,8305100310
- 8305100163 Errata to Aamodt comments re NRC review of GPU vs B&W trial transcript & motions to reopen second of restart proceeding * Aamodts, The 83/05/09 p 18374 272 24X Fiche 50-289,83/05/09.8305100163
- B305100231 Responds to MI Lewis B3041B request for relief re leak rate issue Recommends deferring consideration of request until info relevant to concerns provided as part of NRC revalidation effort Certificate of Svc encl GOLDBERG. JR, WAGNER ME Office of the Executive Legal Director B3/05/09 Commissioners 9pp 18373 288 24X Fiche 50-289,83/05/09,830510023i
- 8305100299 Order denying People Against Nuclear Energy 820403 motion for hearing on psychological stress issue CHILK, 3 Uffice of the Secretary of the Commission 83/05/09 People Against Nuclear Energy 1p 18370 138 24X Fiche 50-289,83/05/09,8305100299
- 8305120292 Reply opposing Aamodts 830416 mution to reopen record on mgt issues Motion uncligar & fails to meet Commission & ASLAB stds Info previously available Certificate of Svc encl TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman. Potts & Trowbridge 83/09/09 Atomic Safety and Licensing Appeal Panel 14pp 18424 106 24X Fiche 50-287, 83/05/09,8305120292
- 8305160073 Petition for review of ASLB 821210 decision.ALAB-705, ruling that NRC need not publicly discipse % consider potential consequences of serious nuclear accident prior to restant authorization M/Centificate of Svc Related correspondence MEISS.E R Union of Concerned Scientists MEISS.E R Harmon & Weiss 83/05/07 U S Court of Appeals for District of Columbia Circuit 8pp 18459 035 24x Fiche 50-289,83/05/07,8305160073
- B305120319 Order referring TMI Alert B30503 motion re 0PU vs B&W trial documents to Commission Motion effectively constitutes request for mod or reconsideration of Commission B30505 order BHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel B3/05/10 2pp 18424 094 24X Fiche 30-287,83/05/10,8305120319
- B303160012 Notifies that copies of in-house 1978 mgt audit rept referred to in Aamod(B30416 motion to reopen & in licensee B30507 reply will be distributed Certificate of Svc encl TROUBRIBGE. O F Shaw. Pittman, Potts & Troubridge 83/05/12 4pp 18456 085 24% Fichs 50-289,83/05/12,8305160012
- 8305i60i30 Order granting, in part, TMI Alert motion to permit overnight removal of documents re OPU vs B5W trial transcripts Only nonindexed set of documents can be removed CHILK, S J Office of the Secretary of the Commission 83/05/13 Three Mila Island Alert 2pp 18446 114 24% Fiche 50-289. 83/05/13.8305i360i30
- 8305170039 Answer opposing Aamodt 830416 motion to reopen record 8tds for reopening record not mot Hartman allegations refalsification of leak rate data not significant info to warrant reopening record GOLDBERG. J R Hearing Branch & WACNER, M E Hearing Branch 4 83/05/13 Atomic Safety and Licensing Appeal Panel 19pp 18466 183 24X Fiche 50-289,83/05/13,8305170039
- --B305170044 Affidavit of LP Crocker that 780109-20 mgt audit does not affect testimony given on organization & mgt of TMI-1 Audit was of station mgt structure & policies in effect over 1 yr prior to TMI-2 accident CROCKER, L P Licensee Qualifications Branch 83/05/05 2pp 18466 202 24X Fiche 80-289,83/05/13,8305170039
- --8305170047 Affidavit of FR Allenspach that 780214 mgt audit does not change testimony given on Aamodt Contention 2 re upgrading performance of licensee technicians & mgt personnel ALLENSPACH.FR Licensee Qualifications Branch 83/05/04 2pp 18464 204 24x Fiche 50-287.83/05/13.8305170039

- --BJ09170051 Afridavit of RR Keimig that 780109-20 mgt audit does not change testimony on issue of util myt competency for facility operation KEIMIO.R R Division of Project & Resident Programs B3/05/05 1p 18466 206 24% Fiche 50-289,83/05/13.8305170039
- --8305170054 Affidavit of BA Boger re Admodt comments on GPU vs BbW trial transcript relationship to previous testimony BOGER, B A Division of Licensing 83/05/12 2pp 18466 207 24x Fiche 50-289, 83/05/13, 83051/0039
- --8305170038 Affidavit of F Kantor re util unsite (ethnical support ctr & nearsite emergency operations facility Both facilities found acceptable Util currently designing safety parameter displays Certificate of Svc encl
 KANTOR.F Emergency Preparedness Bianch 83/05/12 App 18466 209 24X Fichs 50-289.83/05/13.8305170039
- 8305180277 Forwards two consultant repts & Its prepared for GPU mgt remgt competence phase Ltrs clarify repts Svc list enci BLAKE.E.L. Shaw. Pittman. Potts & Trowbridge BLAKE.E.L. Metropolitan Edison Co. 83/05/16 EDLES.G.J., BUCK.J.H., KOHL.C.R. Atomic Safety and Licensing Appeal Panel 211pp 18490 071 24X Fiche 50-289.83/05/16.8305180277
- 8305240216 Advises that 830323 ltr requesting immediate halt to all work at THI-1 % 2, w/erception of maint necessary for safety, will receive consideration at request for action under 10CFR2 206 FR notice encl
 DENTON, H R Dffire of Nuclear Reactor Regulation. Director 83/05/17 KING, R Three Mile Island Public Interest Resource Center 2pp 18593 306 24% Fichs 50-289, 83/05/17, 8305240216
- --B305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at TMI-1 & 2 DENTON.H R Office of Nuclear Reautor Regulation, Director B3/05/17 p 18593 308 244 Fiche 50-289,83/05/17.8305240216
- 8305200632 Forwards NRC 830519 memo to Commission to results of NRC revalidation of NRC position on mgt integrity issues COLDBERG, J R Hearing Branch 2 83/05/19 EDLES, G J, KOHL, C N, BUCK, J H Atomic Safety and Licensing Appeal Panel 4pp 18520 (25 24x Fichs 50-287, 83/09/19, 8305200632
- B305200669 Formal demand for adjudicatory hearing on OL amend resteam generator tube repairs 2 petition to intervent Amend presents significant harands consideration Hearing required Certificate of Svc encl
 DOROSHOM, J. Three Mile Island Aleit B3/05/19 Commissioners 14pp 18519 139 24X Fiche 50-289.83/05/19.8305200669
- B305240536 Affidavit of RE Rogan confirming util commitment to activate emergency operations facility % staff facility w/emergency support director within 1 h of site area or general emergency nutification or declaration ROGAN, R E General Public Utilities GPV Service Corp 83/05/20 4pp 18576 087 24% Fiche 50~000.83/05/20,8305240536
- 8305240287 Motion for leave to file affidavit by R Rogan re testing & verification of emergency operations subsequent to Dec 1762 Affidavit needed as factual evidence before Commission for staffing plan approval W/o encl
 ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 83/05/23 Commissioners 2pp 18548 110 24X Fiche 50-287,83/05/23,8305240287
- 8305240444 Supplemental comments re immediate effectiveness of partial initial decision on mgt issues ASLR credibility / TMI-(safety questionable in light or new evidence DOROSHOM. J Three Mile I sland Alert 8705/23 Commissioners 3pp 18574 088 24% Fiche 50-289,83/05/23,8309240444
- B305240449 Motion to reopen record to remedy deficiencies relicensee mpt competency & integrity & provide right to examine relevant math evidence in context of full adjudicatory hearing DDROSHON. J. Three Mile Island Aleit 83/09/23 Atomic Safety and Licensing Appeal Panel 19pp 18573 133 24X Fiche 50-289, B3/05/23, B305240449
- --8305240457 Comments on IE Insp Rept 50-289/83-10 & review to revalidate NRC possition re Hartman allegations Conclusions on mgt integrity inconclusive due to open issues identified & not considered in revalidation program Certificate of Svc encl DIRCKS, W J Office of the Executive Director for Operations 83/03/19 PALLADING, N J . GILINSKY, V . AHEARNE, J F Commissioners App 18573 152 24% Fiche 50-289,83/05/23,8305240149

- B303240486 Forwards licensee reply opposing NRC staff brief on review of ALAB-698 per B30321 order setting forth briefing schedule on emergency planning issues in restart proceeding Cartificate of Svc enci W/o licensee reply ZAHLER.R E Shaw, Pittman, Potts & Trombridge B3/05/23 Docketing & Services Branch 49p 18572 333 24X Fichs 50-289, B3/05/23, 8305240486
- 8305240487 Reply opposing NRC brief on review of ALAB-698 re emergency planning NRC should dismiss util petition for review & affirm that part of decision being challenged by NRC TROMBRIDGE, G.F., ZAHLER, R.E., RIDGHAY, D.A. Metropolitan Edison Co. 83/05/23 Commissioners 43pp 18572 070 24X Fiche 50-289,83/05/23,8305240487
- 8305240525 Advises of change to Page 7 of NRC 830513 answer to Aamodt motion to reopen record based on mod to inspector preliminary conclusion re organization & structure OLDBERG. J R Hearing Branch 2 83/05/23 EDLES.G J , KUHL.C N . BUCK.J H Atomic Safety and Licensing Appeal Panel 1p 18571 174 24X Fiche 30-289, 83/05/23. 8305240525
- 8305250202 Forwards licensee response opposing NRC brief on review of ALAB-698, filed per Commission 830321 Ordor CLL-83-7 re briefing schedule on emergency planning Certificate of Svc encl
 ZAHLER, R & Shaw, Pittman, Potts & Trowbridge ZAHLER, R & Metropolitan Edison Co. 83/03/23 Docketing & Services Branch
 4pp 18584-012 24X Fiche 30-289,83/03/23.8305250202
- ~-8305250208 Motion to file RE Rogan affidavit, supporting licensee response opposing NRC brief on review of ALAG-698 ZAHLER.R E General Public Utilities GPU Service Corp ZAHLER.R E Shaw, Pittman. Potts & Troubridge 83705723 Commissioners 2pp 18584 016 24X Fiche 50-289,83705723,
- --8305250225 Response opposing NRC brief on review of ALAB-678 Commission should dismiss 820321 petition for review & affirm ALAB-678, authorizing licenser to organize & staff emergency response faility ZAHLER, R.E. Metropolitan Edison Co. ZAHLER, R.E. Shaw, Pittman, Potts & Trowbridge 83/05/23 Commissioners 43pp. 18584-022, 24X Fiche 50-289,83/05/23,8305250202
- 8305270604 Decision ALAB-727, permitting restart subj to Commission determination re safety of facility operation w/o endangering public SHCENARR.C J Atomic Safety and Licensing Appeal Panel 83/05/26 223pp 18643 148 24% Fiche 50-287,83/05/26,8305270604
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8305180620 Summary of ACRO Subcommittees on Metal Components & TMI-1 B30128 meeting in Mashington.DC re review of potential steam generator generic requirements & current steam generator repair program « ACRS - Advisory Committee on Reactor Safeguards 83/04/12 ACRS - Advisory Committee on Reactor Safeguards 19pp 18304 001 24X Fiche 50-289,83/04/12.6305180620
- Operating license stage documents & correspondence
- B305230402 Forwards info on costs incurred from backfitting & upgrading facilities, per B30210 request Mods categorized NRC-required. TMI-lessons learned or util-initiated DIECKAMP.H General Public Utilities GPU Service Corp 83/03/08 TOURTELLOTTE.J Regulatory Reform Task Force 9pp 18576, 319 24X Fiche 50-000:83/03/08.8305230402
- 305270022 Forwards "Rept on Mental Health Effects of TMI Accident" BROMET.E J. Pittsburgh, Univ of 83/03/08 SHANKMAN.6 F. Site Analysis Branch ip 18634 001 24X Fiche 50-320,83/03/08, 8305270022
- -8305270035 "Psychological Stress Among TMI Area Residents & Mediation of Response by Support & Coping "
 BAUMA A SCHAEFFERM A COLLINS D L Uniformed Services Univ of the Health Sciences NRC-03-82-125 83/03/08 NRC No Detailed Affiliation Civen 34pp 18634 086 24X Fiche 50-320,83/03/08,8305270022

- --B305270D40 Forwards final rept, "Reanalysis of TMI Telephone Survey Data" MOUTE,P S Pennsylvania State Univ NRC-03-82-123 83/03/01 REGAN,W NRC - No Detailed Affiliation Given ip 18634 122 24X Fiche 50-320.83/03/08.8305270022
- --8305270046 "Reanalysis of TMI Telephone Survey Data." final rept
 HDUTS,P S , MILLER,R W , LINDELL M Pennsylvania State Univ
 BJ/02/28 NRC No Detailed Affiliation Given 125pp
 18534 123 24X Fiche 50-320,83703/08,8305270022
- ---8305270048 Draft "Restarting TMI-1 Social & Psychological Impacts on Communities" Oak Ridge National Laboratory BOLIN,R New Mexica State Univ 83/03/08 NRC - No Detailed Affiliation Given 207pp 18634 248 24X Fiche 50-320,83/03/08,
- 8305090351 Forwards EH Gischel affidavit & memo re allegations on safety-related mods & tests, Invastigation underway ARNOLD.R C General Public Utilities OPU Service Corp 83/04/04 BARRETTL. General Public Utilities OPU Service Corp 25pp 18347 220 24X Ficha. 50-289, 83/04/04, 8305090351
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11 PALLADING, N. J. Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- 8305110513 Board Notification BN-83-34A provides util response to NRC 830304 ltr re resolution of TM1 Action Item II, K 3 5, "Automatic Trip of Reactor Coolant Pumps"
 EISENHUT, D 0 Division of Licensing 83/04/28 PALLADING, N , OLLINSKY, V , AHEARNE, J Commissioners 4pp 18416 345 24X Ficha 50-289, 83/04/28, 8305110513
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees renew procedures for providing public notice concerning issuance of amends to OLs Syc list enc! EISENHUT. D O Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- 8305040345 Notification of 830504 meeting w/8kM Owners Oroup in Bethesea.MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & Justification for continued operation MINER.8 Operating Reactors Branch 4 83/05/02 870LZ, J Operating Reactors Branch 4 2pp 18353 092 24X Fiche 50-000,83/05/02,8305040345
- 8303040374 Requests Data Design Lab.inc be approved as consultant to perform 2-up probationary in-depth audit of qualification & requalification training & testing program required by ASLB 82072B partial initial decision HUKILL-R D General Public Utilities OPU Service Corp 83/05/03 DENTON-H R Dffice of Nuclear Reactor Regulation, Director 1p 18343.166 24X Fiche 50-289,83/05/03,8305060394
- 8305090453 Advises that all info requested by NRC re environ qualification technical evaluation rept provided in util 820302:0324 & 0625 ltrs Addl info to resolve Category IV items will be provided upon request HUKILL:H D General Public Utilities OPU Service Corp 83/05/03 87012.J F Operating Reactors Branch 4 1p 18362 953 24X Fiche 50-289.83/05/03.8305090453
- 8305040323 Board Notification 83-057 forwards differing prof opinions resus interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
 EISENHUT.D 0 Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,8305040323
- 8303180099 Forwards Amend 85 to License DPR-50, safety evaluation & notice of issuance & availability Amend permits controlling explosive gas mixtures in waste holdup sys by limiting hydrogen to 2% by vol u/o limit on oxygen concentration STOCZ, J F Operating Reactors Branch 4 83/05/05 HUKILL, H D General Public Utilities OPU Service Corp 5pp 18503 287 24% Fiche 50-289.83/05/05,8305180099
- --8305180104 Amend 85 to License DPR-50 permitting controlling explosive gas mixtures in waste holder sys by limiting hydrogen to 2% by vol w/e limit on exygen concentration STOL7. J F Operating Reactors Branch 4 83/05/05 4pp 18503 292 24% Fiche 50-289,83/05/05,8305180099
- --8305180126 Safety evaluation supporting Amend 85 to License DPR-50
 * Office of Nuclear Reactor Regulation. Director 83/05/05 2pp
 18503 296 24X Fiche 50-289.83/05/05.8305180099

- --830518012B Notice of issuance & availability of Amend 85 to License DPR-50
 STOLZ, J F Operating Reactors Branch 4 B3/05/05 2pp 18503 29B 24X Fiche 50-289, 83/05/05, 8305180099
- 8305120055 Forwards Training Procedure 6210-ADM-2604 01, Rev 1-00, "Control of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02. Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program"

 HUKILLIH D General Public Uttlities GPU Service Corp 83705/06

 BT0LZ, JF Operating Reactors Branch 4 1p 18428 233 24X

 Ficha 30-289, 83/05/06, 8305120055
- --8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 Of. "Control of Exams for Units 1 & 2 " * General Public Utilities - GPU Solvice Corp 83/04/26 7pp 18428 234 24X Fichs 30-289,83/05/06,8305120055
- --830512006B Rev 1-00 to Training Procedure &210-ADM-2610 02, "Operator Training Instructors & Supervisors "

 * General Public Utilities GPU Service Corp 83/04/26 16pp 18428 241 24X Fiche 50-289,83/05/06,8305120055
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8 vc list encl EISENHUT, D Ø Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24x Fichs 30-000 83/05/09, 8305090659
- B305130065 Forwards application for amend to License DPR-50, including Tech Spec Change Request 125 Amend permits non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators
 HUKILLIH D General Public Utilities GPU Service Corp 83/05/09
 STOLZ.J F Operating Reactors Branch 4 2pp 18437 034 24X
 Fiche 50-287,83/05/07,8305130065

1

- --8305130070 Application to amend App A of License DPR-50, including Tech Spec Change Request 125 Amend permits non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators

 HUKILL.H D General Public Utilities GPU Service Corp 83/05/09 2pp 18437 036 24% Fiche 50-289,83/05/09,8305130065
- --8305130074 Tech Bpec Change Request 125 permitting non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators * General Public Utilities - GPU Service Corp 83/05/07 7pp 18437 038 24X Fiche 50-289.83/05/09.8305130065
- B305170105 Notification of B30517 meeting w/util & C-E in Bethesda.MD to discuss aspects of steam generator repair.including leak test results.PORV & pressurizer corrosion & third-party raview
 SILVER.H. Operating Reactors Branch 4 B3/05/13 STOLZ.J.F. Operating Reactors Branch 4 2pp 18495 345 24X
 Fiche 50-289.83/05/13.8305170105
- B305190198 Clarifies B30331 ltr re reactor coolant pump trip on 25 F subcooling margin w/respect to qualification of saturation margin monitor sys Bys evaluated per Generic Ltr 82-33 & 830415 ltr Schedule for instrumentation upgrading unknown HUKILL,H D General Public Utilities GPU Bervice Corp 83/05/13 E18ENAUT,D, Q Division of Liconsing ip 18502 239 24X Fiche 50-289,83/05/13.6305190159
- 8305180277 Forwards two consultant rapts & 1trs prepared for GPU mgt re mgt competence phase Ltrs clarify rapts Svc list enc! BLAKE,E L Shaw, Pittman, Potts & Troubildge BLAKE,E L Metropolitan Edison Co 83/05/16 EDLES,G J, BUCK,J H, KOHL,C N Atomic Safety and Licensing Appeal Panel 211pp 18470 071 24X Ficha 50-289,83/05/16.8305180277
- 8305200502 Forwards master lists & sys component evaluation worksheets for NUREG-0737 environ qualification of electrical equipment mods installed in harsh area HUKILL, H D General Public Utilities GPU Service Corp 83/05/16 870L7.J F Derrating Reactors Branch 4 83pp 18513 082 24X Fiche 50-289,83/05/16,8305200502
- B305240028 Notification of B30518 mesting w/util in Bethesda. MD to discuss steam generator repair aspects of leak test & eddy current test results & PORV & pressuriser corrosion.

 3ILVER.H Operating Reactors Branch 4 B3/05/16 STOLZ. J F. Operating Reactors Branch 4 2pp 18977 330 24X Fiche 50-289,83/05/16,8305240028
- B305200173 Forwards Rev i to "Steam Generator Tube Rupture Procedure Quidelines," technical data rept
 HUKILL,H D General Public Utilities QPU Service Corp
 B3/05/17.
 BT0LZ,J F Dperating Reactors Branch 4 1p 18519 004 24X
 Fiche: 50-289.83/05/17.8305200173

- ---8305200179 Rev 1 to Procedure 1DR 406, "Steam Generator Tube Rupture Procedure Guidelines:" technical data rept • General Public Utilities - GPU Service Corp 83/05/08 59pp 18519 005 24X Fiche 50-289.83/05/17.8305200173
- 8305200632 Forwards NRC 930519 memo to Commission re results of NRC revalidation of NRC position on mgt integrity 195005 GDLBERG, J. R. Hearing Branch 2 93/05/19 EDLES, G. J., KDHL, C. N., BUCK, J. H. Atomic Safety and Licensing Appeal Panel App. 1852D 125 24X Fiche 50-289,83/05/19.8309200632
- B305250588 Responds to 830415 starf requirements memo re schedule for decision on license amend request to permit operation of steam generators Schedule for decision contingent upon outcome of significant hazards determination DIRCKS,W J Dffice of the Executive Director for Operations B3/05/19 CHILK.B J Dffice of the Secretary of the Commission 9pp 18594 337 24% Fiche 50-209.B3/05/19.B30525058B
- --8305250590 Staff requirements memo re 830415 briefing on status of TMT-1 steam generator repairs Commission requested info on differing dates for decision on license amend request depending on significant hazards determination CHILKS J Office of the Secretary of the Commission 83/04/25 DIRCKS,W J Office of the Elecutive Director for Operations ip 18994 346 24X Fiche 50-289,83/05/19,8305230588
- 8305250269 Forwards Suppl i to. "Rept of Third-Party Review of TMI-1, Steam Generator Repair"
 HUKILL,HD General Public Utilities GPU Service Corp 83/05/20 870LZ,JF Operating Reactors Branch 4 2pp 18592 302 24X Fiche 50-289,83/05/20,8305250269
- --B305250271 Bupsi 1 to, "Rept of Third-Party Review of TMI-1.Steam Generator Repair" BROWN.S D, HOLLAND.S A, KALNINS.A General Public Utilities -GPU Bervice Corp. B3/05/16 22pp 18592 304 24X Fiche 50-289, B3/05/20. B305250269
- B305260094 Provides info identifying electrical equipment important to safety within scope of 10CFR50 49(g) already qualified Schedules for qualification of post-accident instrumentation encl
 HUKILL.H D General Public Utilities GPU Service Corp 83/05/20
 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 18399 314 24X Fiche 50-289.83/05/20,8305260094
- 8305310205 Advises that installation of two Controlotron sonic flow devices on each flow path to once-through steam generators satisfies requirements of restart SER (NUREC-0480). 811214 partial initial decision & NUREC-0737. Item II E I HUKILL.H D General Public Utilities GPU Service Corp 83/05/24 870LI.J F Operating Reactors Branch 4 ip 18438 i59 24X Fiche 30-289.83/05/24,8305310205
- G Inspection reports. If Bulletins & correspondence
- B212040385 [E Info Notice 83-14, "Dewatered Spant Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction 'Svc list enc! [TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,22/27060385
- 8303040021 IE Info Natice 83-21. "Defective Emergency Use Respirator"
 Svc list enc)
 JORDANIC L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155 24x Fiche 30-000.83/04/15,8303040021
- B303040023 IE Info Notice 83-22. "DMR Safety/Relief Valve Failures "
 Svc list encl
 JURDANAE L Division of Emergency Preparedness & Engineering
 Response (Pust 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 117pp 18381 271 24X Fiche 50-000.83/04/25,8303040025
- 8303020226 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-05
 8TARGSTECKI:R Division of Project & Resident Programs HUKILL.H D General Public Utilities GPU Service Corp 2pp 18277 276 24% Fiche 50-289.83/04/26,83050202226

- --8305020232 Responds to NRC 830314 itr re violations noted in IE Insp. Rept 50-289/83-05 Corrective actions formal action items restain generator tube repair program issued w/date extensions
 - #WKILL.H D General Public Utilities GPU Service Corp 83/04/13 Region 1. Office of Director 3pp 18277 298 24X Fiche 50-289,83/04/26,8305020226
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness ! Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Ficho 50-000.83/04/28.8303040026
- 8303040027 IE info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24% Fische 50-000.83/04/28.8303040027
- 8305110331 Forwards (E Insp Rept 50-389/83-07 on 830321-24 No noncompliance moted MARTINIT T Division of Engineering & Technical Programs 83/04/29 HUKILLIK D General Public Utilities - GPU Service Corp 2pp 18406 165 24% Ficho 50-289.83/04/29.8305110331
- --830511033B IC Insp Rept 50-289/83-07 on 930321-24 No noncompliance noted flagor areas inspected licenses actions & program to repair steam generators A & B GRAY, E , REYNOLDS, S , DURR, J P Region 1, Office of Director 83/04/22 & pp 18406 167 24X Fiche 50-289,83/04/27,8305110331
- 8305160194 Forwards IE Insp Rept 50-289/83-08 on 830228-0329 No noncompliance noted \$TARBSTFCK1,R Division of Project \$ Resident Programs 83/05/02 HUKILL-H D General Public Utilities - GPU Service Corp 2pp 18445 128 24X Fichs 50-289,83/05/02,8305160194
- --8305160199 IE Insp Rept 50-289/83-08 on B30220-0329 No noncompliance noted Major areas inspected licensee action on previous insp findings.plant operation.LERs & restart mods CONTE.R. BARR.K. 0 "MEILL.B" Region 1. Office of Director 83/04/29 11pp 16445 130 24V Fiche 50-289.83/05/02.8305160194
- 8303040028 IE Info Notice 83-26, "Failure or Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000.83/03/03.8303040028
- B303040030 IE Info Notice B3-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment: "Syc list end! JGRDAN.E L. Division of Emergency Preparedness » Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18362 282 244 Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, F. L. Division of Emergency Prepaledness & Engineering Response (Post 830103) 82/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24% Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 807/05/06 Consolidated Edison Co. of New York, Inc. 115pp. 18523 248 24% Fiche 50-000,83/03/06,8303040033
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDANLE L Division of Fmergency Preparedness & Engineering Response (Post 830103) 83703/11 Consolidated Edison Co of New York. Inc 1149p 18524 003 24X Fiche 50-000.83/03/11.8303040034
- B305250495 Forwards IE Insp Rept 50-289/03-09 on B30328-0408 & notice of violation
 MARTINIT T Division of Engineering & Technical Programs 83/05/13
 HUXICL.H D General Public Utilities GPV Service Corp 2pp
 18627 001 24X Fiche 50-289,83/05/13.8305230493
- --8305250500 Notice of violation from ones on 830328-0408 4 Region 1, Diffice of Director 83/05/13 2pp 18627 003 24) Fiche 50-289, 83/05/13, 8305250495
- ~~8309250505 IC Inso Rept 50-289/83-07 on 830328-0408 Noncompliance noted failure to reset feeder breakers to safeguards busses to failure to adequately inspect piping BISSETT.P. COGAN, N. GREGG.M. Region 1. Office of Director 83/05/11 9pp 18627 005 244 Fiche 50-289,83/05/13.8305250495

- 8305230455 Forwards 1E Insp Rept 50-289/83-10 on 830420-22 & 25-28 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/05/17 HUMILL.H D General Public Utilities - GPU Service Corp 2pp 18647
- --8305230460 IE Insp Rept 50-289/83-10 on 830420-22 % 25-28 No noncompliance noted Major areas inspected conduct of sperations procedures & training program re procedural adherence for new employees & requalification program ALLENSPACH, F.R., CAPHION, D.L., COGAN, N.J., Region 1, Dffice of Director 83/05/16 67pp 18537 200 24X Fiche 50-289, 83/05/17, 8305230455
- 6305250183 Forwards IE Insp Rept 50-289/83-10 on 830420-22 & 25-28 Joint headquarters/Region I insp initiated to evaluate effectiveness of GPU actions to ensure adherence to procedures since issuance of NUREO-0080. Suppl J REHM, T A Office of the Executive Director for Operations 83/05/18 PALLADING, N J , GLINSKY, V , AHEARNE, J Commissioners ip 18596 001 24X Fiche 50-289,83/05/18,8305250183
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19,8303040040
- 8305260085 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" No electrical primary containment penetrations mfg by Bunker Ramo Co in use at facility HUKILLIH D General Public Utilities ~ GPU Service Corp 83/05/20 Region 1, Office of Director 1p 18599 308 24X Fiche 50-289,83/05/20,8305260085
- B303040046 (E Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305020210 Forwards "TMI Aquatic Study, Monthly Rept for Mar 1983 "
 RESSLER.W C General Public Utilities GPU Service Corp 83/04/28
 HICKEY.C NRC No Detailed Affiliation Given 1p 18278 147
 24X Fiche 50-289,83/04/28,8305020210
- --8305020215 "TMI Aquatic Study, Monthly Rept for Mar 1983 "
 NARDACCI, 6 A Ichthyological Associates, Inc 83/04/28 21pp
 18278 168 24X Fichs 50-287,83/04/28,8305020210
- 8305060458 Forwards "Annual Environ Operating Rept, 1982," "Ecological Study of Susquehanna River Near TMI" & "Hydraulic Survey "
 HUKILL.H D general Public Utilities GPU Service Corp 83/04/29
 Region 1, Difice of Director 1p 18349 058 24X
 Fiche 50-289, 83/04/29, 8305060458
- --8305060464 "Hydraulir Survey," annual rept a General Public Utilities - GPU Service Corp 82/06/03 13pp 18349 078 24X Fiche 50-289-83/04/29-8305060458
- --8305060465 "Ecological Study of Susquehamna River Near TMI," annual rept for 1982 NARDACCI, O A Ichthyological Associates, Inc. 83/04/30 633pp 18349 091 24X Fiche 50-289.83/04/29.8305060458
- 8305060649 Forwards "TMI Nuclear Station Radiological Environ Monitoring Rept.1982 " W/o encl HUKILL,H D General Public Utilities - GPU Service Corp B3/04/29 Region I, Office of Director 1p 18348 250 24X Fiche 50-289,83/04/29.8305060649
- 8303270203 "Changes to Bys & Procedures Described in FSAR par 10CFR50 59 " HUKILL.H D General Public Utilities - GPU Service Corp 83/05/10 HAYNES.R C Region 1, Office of Director 17pp 18637 244 24X Fiche 50-289,83/05/10,8305270203
- 8305190240 Forwards monthly operating rept for Apr 1983 MKKILL,H D General Public Utilities - GPU Service Corp 83/05/13 MCDONALD.H C Office of Resource Management Director 1p 18501 304 24x Fiche 50-287,83/05/13,8305190240

- --B305190247 Monthly operating tept for Apr 1983 SMYTH:C W General Public Utilities - GPU Service Corp B3/05/13 10pp 18501 305 24X Fiche 50-289,83/05/13,8305190240
- 8 Reportable occurrences, LERs & related correspondence
- 8305030496 RO 83-11 on 830326. DHR in shaft bearings failed, making pump inoperable Caused by design change to pump bearing lube oil sys Sys returned to original configuration Review of existing sys in progress HUKILL, H D General Public Utilities GPU Service Corp 83/04/18 Region 1, Office of Director 2pp 18306 272 24x Fiche 50-289, 83/04/18, 8305030436
- 8305030095 Forwards LER 83-006/03L-0 HUKILL:H D General Public Utilities - GPU Service Corp B3/04/19 Region 1. Office of Director 1p 18300 344 24X Fiche 50-289, 83/04/19, 8305030095
- --8305030127 LER 83-006/03L-0 on 830320.no flow existed through hydrogen & oxygen rotameters of waste gas sys analyzer Caused by dirt blockage in regulator & flow setting Pump discharge pressure regulator setting raised 82CZECH:R A General Public Utilities GPU Service Corp 83/04/19 Region 1, Defice of Dijector 3pp 18300 345 24X Fiche 50-289,83/04/19.8305030095
- B305030102 Forwards LER B3-010/03L-0 HUKILL.H D General Public Utilities - GPU Service Corp B3/04/20 Region 1. Office of Director 1p 18300 340 24X Fiche 50-289. B3/04/20. B305030102
- --8309030112 LER 83-010/03L-0 on 830321, wasto gas sys Hays gas analyzer alarm indicated incorrect concentration of oxygen Caused by dirty amplifier low channel gain potentiometer & suitch contacts Components cleaned SYCZECH, R A General Public Utilities GPU Service Corp 83/04/20 Region 1, Office of Director 3pp 18300 341 24X Fiche 50-289, 83/04/20, 8309030102
- #305110346 Forwards LER #3-007/03L-0

 HUKILL,H D General Public Utilities GPU Service Corp #3/04/25

 Region i, Office of Director ip #406 140 24X

 Fiche 50-289,83/04/25,8305110346
- --8305i1035i LER 63-007/03t-0 on 830325, automatic termination & alarm failed to occur when dilution flow fell below min setpoint during liquid effluent release Caused by sticking of trip interlock pneumatic relay Procedures modified SICIECH:R A General Public Utilities GPU Service Corp 83/04/25 Region 1, Office of Director 2pp 18406 141 24X Fiche 50-289,83/04/25,8305110346
- 8305030534 PND-I-83-039 small fire occurred beneath auxiliary boiler A located in turbine bldg Caused by small amount of oil on concrete pad Fire extinguished using hand extinguisher CONTE.R . KEIMIO.R Region i. Office of Director 83/04/26 lp 18308 190 24X Fiche 50-289.83/04/26.8305030534
- B305030074 PNO-I-83-040 on B3042B, protesters arrived at north gate Gate closed & access established through south gate No press release planned CONTER, KEIMIGER Region 1, Office of Director 83/04/28 Lp 18300 179 24X Fiche 50-289,83/04/28,8303030094
- 8305110286 Forwards LER 83-009/03L-0 HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29 Region i, Office of Director 1p 18393 251 24X Fiche 50-289, 83/04/29, 8305110286
- --8305110287 LER 83-009/03L-0 on 830330, during surveillance/calibr of waste gas sys.Hays gas analyzer.oxygen meter failed to respond to calibr gas Cause unknown Maint checks performed & circuit components cleaned 82CZECH.R A General Public Utilities GPU Service Corp 83/04/29 Region 1. Office of Director 2pp 18373 252 24X Fiche 50-289,83/04/29.8305110286
- B305110333 Forwards LER B3-011/01Y-0 HUKILL.H D General Public Utilities - GPU Service Corp Region 1. Office of Director 1p 10406 173 24X Ficha: 50-289, B3/04/29, B305110333
- --B305110342 LER B3-011/01T-0 on B30415, while in long-term shutdown DH-P1A shaft bearings failed making pump intogerable Caused by improperly authorized mod to component & inadequate mod set up Pump repaired Maint job tickets reviewed STEPHENBON, C J General Public Utilities GPU Service Corp B3/04/29 Region 1, Office of Director 3pp 18406 174 24X Fiche 50-289, 83/04/29, 8305110333

- 8305200547 Forwards LER 83-012/03L-0 HUKILL:H D General Public Utilities - 6PU Service Corp 83/05/06 Region 1. Office of Director 1p 18515 360 24x Fiche 50-289: 83/05/04. 8305200547
- --B305200551 LER B3-012/0JL-0 or, B30406 while performing functional testing of hydraulic snubbers, snubber MS-209 failed to lock in tension direction Caused by damaged piston seal ring Snubber overhauled & tested satisfactorily SZCZECH R A General Public Utilities GPU Service Corp B3/05/06 Region 1. Office of Director 3pp 18915 361 24X Fichm 50-289, 83/05/06, 8305200547
- T Hearing transcripts on non-antitrust matters
- B309310071 Transcript or Commission 830921 briefing in Washington.DC re NRC revalidation of myt competence for restart Pp 1-57 Viougnaphs encl * Commissioners 83/05/24 73pp 18463 025 24% Fiche 80-289,83/05/24.830310071
- U Congressional, Executive Correspondence
- 8305230703 Urges resolution of remaining questions is facility restart Delay in resolving restart issue unacceptable when jobs at stake Restart issue should receive high priority this Spring BROYHILL. J. T. MODRHEAD, C. J., RITTER, D. House of Rep., Energy %. Commerce 83/03/16 PALLADINO, N. Commissioners 3pp 18542 317 247 Fiche 50-289,83/03/16.8305230703
- 8305040138 Forwards proposed Chairman testimony before Udall Subcommittee B30406 hearing re developments since Apr 1982 at TMI, responding to 1 tems in Congressman Udall B30413 ltr W/o proposed testimony DENTON, HR Office of Nuclear Reactor Rigulation, Director B3/04/20 DIRCKS, W J Office of the Executive Director for Operations 2pp 18327 01; 24X Fiche 50-289,83/04/20,8305040138
- --8309040145 Enumerator items to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982 UDALL.M K House of Rep , Interior & Insulai Affairs 83/04/13 PALLADING,N Commissioners 2pg 1832/013 24X Fiche 50-289,83/04/20,8305040138
- B305230435 Forwards response to Question 20 in 810223 ltr re NRC review of B&M/GPU trial record PALLADINO:N J Commissioners 83/04/28 UDALI,M K House of Rep , Interior % Insular Affairs 2pp 18542 05! 24X Fiche 30-289:83/04/28:8305230135
- --8305230440 Interms of dissenting opinion to Commission majority decision blocking General Counsel review of BZM/GPU trial record in TMI-1 restart proceeding Pecision will hamper ability of individual Commissioners to obtain needed info GLINSKY, V Commissioners 83/04/07 SIMPSON, A K Senate, Environment & Public Works 2pp 16542 053 24x Fiche 50-209,83/04/28,8305230435
- --- 8305230443 Responds to Chairman Palladino 830309 request for views on legality of Commission decision directing Executive Director for Operations rather than Director General Counsel. ta review B&Wd/GPU trial record Actions supported PLAINE: H H E Diffice of the General Counsel 83/03/25 PALLADIND: N J GILINSKY, V. AHEARNE, J Commissioners 5pp 18542 055 24X Fiche 50-289, 83/04/28, 8305230435
- --8305230446 Provides Commission insponse to Commissioner Gilinsty
 830407 ltr disagreeing w/Commission majority decision to
 block General Counsel review of B&H/GPU trial record in
 TMI-1 restart proceeding Commission actions justified
 PALLADINO.N J Commissioners 83/04/19 UDALLM K House of
 Rep , Interior & Insular Affairs 4pp 18542 060 24X
 Fiche 50-289,83/04/28,8309230435
- --8305230153 Disagrees w/Commission majority views in Chairman Palladino 830417 ltr justifying Commission delision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding ABBELSTINE. J K Commissioners 83/04/25 UDALL, M K House of Rep. Interior & Insular Affairs 3pp 18542 064 24X Fiche 50-289, 83/04/28, 8305230435
- B305230377 Responds to questions in 830323 Its re-steam generator tube rupture scenario at TMT-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items provided on 830325 PALLADINO.N J Commissioners 83/05/05 MARKEY.E J House of Rep. Interior & Insular Affairs Bap 18683 30/ 24X Fiche 50-289:83/05/05.8305230377

- --gJ092303BB Requests further response to issued in BJ0121 ltr re-steam generator tube degradation at TMI-1 & Subcommittee on Oversight & Investigation B21213 hearing Updated status of TMI action plan items also requested MARKEY.E J. House of Rep., Interior & Insular Affairs B3/03/23 PALLADIND,N J. Commissioners 2pp 18542-019 24X Fichs 50-289.83/03/05.8305230377
- V Operator Examinations
- B3D5120055 Forwards Training Procedure 6210-ADM-2604 01.Rev 1-00.
 "Control of Exams for Units 1 % 2." 9 Procedure
 6210-ADM-2610 02.Rev 1-00. "Operator Training Instructor
 Indoctrination/Qualification Training Program"
 HUKILLIN D General Public Utilities GPU Service Corp
 83/05/06
 81012.J F Operating Reactors Branch 4 1p 18428 233 24%
 Fiche 50-289,83/05/06,8305120055
- --8303120064 Rev 1-00 to Training Procedure 6210~ADM-2604 01. "Control of Exams for Units 1 & 2 "

 * Operal Public Utilities GPU Service Corp 83/04/26 7pp
 18428 234 24X Fiche 50-289.83/05/06.8305120055
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B3D5050144 Forwards IE Insp Rept 50-293/83-05 on 830301-04 No noncompilance noted MARTIN:TT Division of Engineering & Technical Programs 83/04/20 HARRINGTON:W D Boston Edison Co 2pp 18342 203 24X Fiche 50-293.83/04/20.8305050144
- --8305050151 lE Insp Rept 50-293/83-05 on 830301-04 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal performed on 810713-24 & public notification sys SHITHER, MILLER, M.T., CROCKER, H.W. Region 1, Office of Director 83/04/12 17pp 18342 205 24X Fiche 50-293.83/04/20.8305050144
- 3305020056 Responds to 830128 itr forwarding Rev 2 to safeguards contingency plan Rev consistent w/provisions of 10CFR30 34(p) & acceptable VASSALLO, D B Operating Reactors Branch 2 83/04/22 MORISI, A V Boston Edison Co Ip 18308 288 24% Fiche 50-293,83/04/22,830000055
- ISOS110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law unforcement visits Sve list encl
 EISENNUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc 14pp 18540 095 24X
 Fiche 50-000,83/05/11.8305110034
- 305170173 Provides schedule for changes to Tech Specs addressing fire protection issues re smoke detection. Halon sys b alternate shutdown panels HARRINGTON.W D Boston Edison Co 83/05/13 VASSALLO.D B Operating Reactors Branch 2 3pp 88466 388 24X Fichs 50-293.83/05/13.83/05/170173
- 105230450 Resubmits requests for App R tochnical 5 schedular exemptions; per 830329 meeting w/NRC W/three oversize figures Aperture cards are available in PDR HARRINOTON; H D. Boston Edison Co. 83/03/17 VASSALLD; D B Operating Reactors Branch 2 36pp 18537 267 24X Fiche 50-293, 83/05/17, 8305230450
- 05240571 Notifies that NUREG-0737, Item [II A 2 1, "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50," completed Item closed VASSALLO.D B Operating Reactors Branch 2 83/05/18 HARRINGTON.W D Boston Edison Co 3pp 18594 217 24X Fiche 30-293,83/05/18.8305240571

General correspondence

05130153 Requests that WD Harrington be primary recipient of all NRC correspondence re License DPR-35 AV Morisi should be added to list for future correspondence addressed to WD Harrington x RD Machan & CJ Mathis should be deleted from list dARRINGION, WD Doston Edison Co 83/05/09 VASSALLD, D B Jperating Reactors Granch 2 2pp 1 iche 50-293,83/05/09,8305130153

- J Insurance & indemnity information
- 8305120059 Forwards Endorsements 77 % 61 to NELIA Policy NF-188 & MAELU Policy MF-58, respectively SINISI, J H Marsh & McLennan, Inc. 83/05/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 18423 055 24X Fich 50~278,83/05/05,8305120059
- P Operating license stage documents & correspondence
- 8304180570 Forwards response to questions le single recirculation loop operation at facility MARRINGTON. W D Boston Edison Co 83/04/11 VABSALLO. D B Licensing Branch 2 3pp 17979 212 24X Fiche 50-293,83/04/11, 8304180370
- B305040295 Summary of 830414 meesting w/util re plans concerning longterm program for scheduling nacessary work items Viewgraphs enc! ECCLESTON, K T Operating Reactors Branch 2 83/04/21 VASSALLO, D B Operating Reactors Branch 2 37pp 18327 032 24X Fichs 50-293,83/04/21,8305040295
- 8303060266 Forwards Amend 68 to License DPR-35, safety evaluation & notice of issuance & availability Amend reflects installation of alarm switches on torus drywell vacuum breakers
 ECCLESTON.K T Operating Reactors Branch 2 83/04/22 MORIBI.A V Boston Edison Co. 2pp 18359 332 24X Fiche 50-293.83/04/22.8305060266
- --8309060279 Amend 68 to License DPR-35, changing Tech Specs & associated bases to reflect installation of alarm switches on torus drywell vacuum breakers
 VASSALCO, D B Operating Reactors Branch 2 83/04/22 8pp
 18359 334 24X Fiche 50-293, 83/04/22, 8305060266
- --8309060287 Safety evaluation supporting Amend 68 to License DPR-35 * Office of Nuclear Reactor Regulation, Director 83/04/22 2pp 19359 342 24% Fiche 50-293,83/04/22,8305060266
- --8305060291 Notice of issuance & availability of Amend 68 to License DPR-35 VABSALLG.D 8 Operating Reactors Branch 2 83/04/22 2pp 1839 344 24X Fiche 50-293,83/04/22.8305060266
- 8305120163 Forwards Amend 69 to License DPR~35, safety evaluation & notice of issuance & availability Amend incorporates revs to reflect organizational changes re nuclear activities, both onsite & offsite ECCLESTON.K T Operating Reactors Branch 2 83/04/26 MORISI.A V Boston Edison Co 2pp 18435 266 24X Fiche 50-293.83/04/26, 8305120163
- --8305120169 Amend 69 to License DPR-35, incorporating rows to reflect organizational changes re nuclear activities, both onsite & offsite VASSALLO, D B Operating Reactors Branch 2 63/04/26 13pp 18435 268 24x Fichs 50-293, 63/04/26, 6305120169
- --8305120180 Safety evaluation supporting Amend 69 to License DPR-35 * Office of Nuclear Reactor Regulation, Director 83/04/26 6pp 18435 281 24% Fiche 50-293,83/04/26,8305120163
- --8305120187 Notice of issuance & availability of Amend 69 to License DPR-35 VASSALLO.D B Operating Reactors Branch 2 83/04/26 2pp 18435 287 24x Fiche 50-293, 83/04/26, 8305120163
- B305090200 Forwards response to NUREO-0737 Item II K 3 13, "RCIC Automatic Restart " RCIC sys modified such that reactor high water level signal will automatically close RCIC turbine steam supply valve, should valve be open HARRINGTON. H D Boston Edison Co 83/04/29 VASSALLO, D B Operating Reactors Branch 2 1p 18363 361 24X Fiche 50-293,83/04/29,8305090200
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl ISENHUT.D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 19441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305180197 Forwards Amend 70 to License DPR-35, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to change critical power ratio limits & to increase safety relife valve summer margin ECCLESTON.K T Operating Reactors Branch 2 83/05/03 MORISI.V A Boston Edison Co 2pp 18503 333 24X Fiche 50-293,83/05/03,8305180197

- --8305180204 Amend 70 to License DPR-35, revising Tech Specs to change min critical power ratio limits 5 to increase safety relief valve simmer margin VAS9ALLD, D B Operating Reactors Branch 2 83,05/03 5pp 18503 335 24X Fiche 50-293,83/05/03,830518019/
 - 10004 555 21% 11010 40 2731 257 557 531 25031 25031 2577
- --B305180216 Safety evaluation supporting Amend 70 to License DPR-35 * Office of Nuclear Reactor Regulation, Director B3/05/03 ip 18503 340 24X Fiche 50-293, B3/05/03, B305180197
- --8305180229 Notice of issuance % availability of Amend 70 to License DPR-35 ROUNEY,V L Operating Reactors Branch 2 83/05/03 2pp 18503 341 24X Fiche 50-293.83/05/03.6305180197
- B305090659 Generic Ltr B3-20 to all operating reactor licenses % holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EIBENHUT.D 0 Division of Licensing B3/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627 153 24X Fiche 50-000, B3/05/09, B305090659
- 8305160044 Requests rescheduling of completion date for torus internal mode re torus catwalk extension support legs & ring girder/ shell weld near T-quenchers to 830221
 HARRINOTON: W D Boston Edison Co 83/05/10 VASSALLO, D B Operating Reactors Branch 2 3pp 18453 013 24x
 Fichs 50-293.83/05/10.8305160044
- B305160061 Requests that completion date for scram discharge vol mods be modified to B30223 Info to support schedular relief discussed HARRINGTON W D Boston Edison Co 83/05/10 VASSALLO D 8 Operating Reactors Branch 2 2pp 18451 045 24X Fiche 30-293, B3/05/10, 8303160061
- 8305260175 Forwards request for add1 info re NUREG-0737, Item II K 3 28 on qualification of automatic depressurfication systacconductors Response within 45 days requested VASBALLO, D B Operating Reactors Branch 2 83/05/11 MORISI, A V Boston Edison Co 3pp 18648 110 24X Fiche 50-273, 83/05/11.
- 8305170345 Notifies that response to 28 questions re "Mark I Containment Long-Term Program - Plant Unique Analysis Rept -Structural Evaluation." delayed until 830722.per 830427 & 0505 telcons HARRINGTON.W D Boston Edison Co 83/05/13 VASSALLO.D B Operating Reactors Branch 2 1p 18465 122 24X Fiche 50-293,83/05/13.8305170345
- 830517041B Responds to B3020R request for plant-unique calculations forming bases for mods to vacuum breakers on Mark I containments or justifications for as-built acceptability, per Generic Ltr 83-0B Mod schedule discussed HARRINOTON,W D Boston Edison Co 83/05/13 EISENHUT,D 9 Division of Licensing 200 16469 288 24X Fiche 50-293,83/05/13,830517041B.
- B305190147 Discusses issuance of revised policy statement re util position on NUREG-0737. Item I C 6, "Verify Performance of Operating Experience "Policy will be integrated into existing operations procedure by B3081?

 HARRINGTON:W D Boston Edison Co 63/05/13 VASEALLO, D G Operating Reactors Branch 2 ip 18902 070 24X

 Fiche: 50-293.83/05/13.8305190147
- 8305240560 Informs that NUREO-0737, Itam II F 1, "Containment High Range Radiation Monitor:" completed Item closed Safety evaluation encl VASSALLO, D II Operating Reactors Branch 2 83/05/13 MORISI.A V Botton Edison Co 4pp 18593 356 24X Fichs 30-293,83/05/13, 8305240360
- 830520044/ Provides commitment in response to final rule re environ qualification of safety-related electrical equipment Qualification plan enci HARRINGTON, W.D. Boston Edison Co. 83/05/17 VASSALLO, D.B. Operating Reactors Dranch 2 lipp 18516 092 24X Fiche 50-293,83/05/17,8305200447
- 8305200239 Submits justification for continued operation until environ qualification of equipment in Categories I b.II a & IV qualified, per 830413 request Info requested on safety evaluation items will be addressed in future itr HARRINGTON, W D Boston Edison Co 83/05/18 VASSALLO, D G Operating Reactors Aranch 2 184pp 18518 177 24X Fiche 30-293.83/05/18,8305200259

- 8305260130 Informs that NUREG-0737 Item II F 3 45 to depressurization wrother than automatic depressurization sys would not contribute to plant safety & no plant design or operation mod required Safety evaluation cncl VASSALLO.D B Operating Reactors Branch 2 83/05 19 HARRINGTON.W D Boston Edison Co 2pp 18649 052 24X Fiche 50-273,83/05/18,8305760;30
- 8305260379 Requests remittance of two class lil fees for review of 830405 application to amend ticense DPR-35, changing max critical power ratio limits & increasing safety relief valve simmer margin DIGGS:R M License Fee Management Branch 83/05/20 MORISI, A V Baston Edison Co. ip 18647 250 21% Fiche 50-293 83/05/20, 8305260179
- G Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice 83-14, 'Dewatered Spent Ion Exchange Resin Susceptibility to Exchermic Chemical Reaction "Syc list ent!

 TAYLOR, J.M. Division of Safeguards / Inspection Programs (Post B30103) B3/03/2) Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fichs 30-000, 83/03/21, 8217060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co or New York, Inc. 126pp 18435-195 24x Fiche 50-000.83/04/15,8303040021
- 8305050144 Forwards IE Insp Rept 50-293/80-05 on 830301-04 No noncompliante noted MARTIN.T T Division of Engineering & Fechnical Programs 83/04/20 HARRINGTON.W D Boston Edison Co App 18342 203 24X Fiche 50-293,83/04/20,8305050144
- --8305050151 1E Insp Rept 50-293/63-05 on 830301-04 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior applialsal performed on 810713-24 & public notification sys SMITH, R , MILLER, M T , CRUCKER, H W Rugion 1, Office of Director 83/04/12 17pp 18342 205 244 Fiche 50-293,83/04/20,8305050144
- 830304002J IE Info Notice 83-22. "BWR Sifety/Relief Valve Failures"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness % Engineering
 Response (Post 830103) 83/04/27 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24x Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN.E C. Division of Emergency Preparadness & Engineering Response (Post B30103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305050250 Updates 830310 response to II Nulletin 83-01, "Check Valve Failures in Raw Mater Cooling Sym of Diesel Generators 'No check valves located in cooling water sys at facility Failure mechanism identified in bulletin not possible MARRINGION, W D. Boston Edison Co. 83/04/2/ ALLAN, J. Region 1, Office of Director 1p 18337 334 24% Fiche 50-293, 83/04/27, 83050505050
- 8305060029 Notification of significant licensee 830510 meeting in BostoninA to discuss performance improvement program ELSASSER, F.C. Region 1. Office of Director B3/04/27 Region 1. Office of Director 1p 18354 308 24x Fiche 50 293,83/04/27. 8305060029
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary 8ide of Steam Cenerators at PWRs " Svc list encl JORDAN.E L Division of Emergenly Preparedness & Engineering Response (Post 830103) 82/04/28 Consolidated Edison Co of New York: Inc 115pp 18382 047 24X Fiche 50-000.63/04/28.6303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syr List encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 145 24X Fishe 50-000,83/04/28,8303040027
- 8305160137 Forwards IE Insp Rept 50-293/83-07 on 830322-0418 & notice of violation
 STAROSTCKI,R Division of Project & Resident Programs 83/05/02
 HARRINOTON,W D Boston Edison Co 2pp 18446 048 24%
 Fiche 50-293.83/05/02.8305140137
- --8305160137 Notice of violation from thep on 630322-0418 * Division of Project & Resident Proglams 63/05/02 1 18446 050 24X Fiche 50-293.03/05/02 6305160137

- --8305160142 IE Insp Rept 50-293'83-0/ on 830322-0418 Moncompliance noted failure to implement station procedure for insp & cleaning of standby gas treatment sys inlet plenum JOHNSON J. EICHENMOLZ.H. Region 1. Office of Director ELSASSER.T. Division of Project & Resident Programs 93/04/28 15pp 18446 051 24X Fiche 50-293.83'05/02.8305140137
- 830304002A IE Info Notice 83-26. "Fablure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidate Edison Co. of New York, Inc. 122pp 18441 170 24x Fiche 30-000,03/03/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment," Svc list end JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Past 8301031 82/05/04 Consolidated Edison Co. of New York Inc. 112pp 18382 282 247 Fishs 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 117pp 18441 001 24X Fich. 30-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 6301031 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24% Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30. "Hisapplication of Generic Emergency Operating Procedures (EGP) Guidelines "Svc list encl JORDANIC L. Division of Emergency Preparedness & Engineering Responso (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305230429 Ack receipt of 830427 ltr informing NRC or steps taken to correct violations noted in IE Insp Rept 50-293/83-03 STAROSTECKIR Division of Project *** Resident Programs B3/05/13 HARRINGTON H D Boston Edison Co ip 18538 215 24X Fiche 50-293.83/05/13,8305230429
- --B305230434 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-29J/83-03 Corrective actions personnel counseled on procedural adherence re radiation samples not taken or counted & Namo CR 83-39 issued concerning nonadherence HARRINGTON.W D Boston Edison Co B3/04/27 SYAROSTECKI.R Division of Project & Resident Programs 3pp 18538 216 24X Fiche 50-293,63/05/13.8309230429
- 8305270073 Provides clarification re-prior IF bulletin correspondence Inaccuracy due to brief review time allowed by IE Bulletin 80-01 No consequence to safety evident Expanded sampling of bulletin review being implemented HARRINGTUNIA D Boston Edison Co 83/05/13 ALLANIJ Region I. Office of Director 3pp 18638-282 24X Fiche 50-293.89/05/13, 8305270077
- 8303040040 IE Info Notice 83-31, "Eriol in ADLPIPE Computer Program "
 Svc list encl
 JORDANNF L Division of Energency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24x Fiche 50-000.83/05/19,8303040040
- 3303040044 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 0:1" Svc list encl JORDAN:E L Division of Emergency Prepairdness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- . Persodic operating reports & related correspondence
- 3305020134 Forwards photographic mit1 from 1981 & 82 annual main breakwater surveys Survey for 1983 in progress Aerial portion will be postponed while review of 830228 request in progress HARRINGTON.W D. Boston Edison Co. 83/04/26 VASSALLO, D.8 Operating Reactors Oranch 2 ip 182/8 218 24% Fiche 50-293.83/04/26.8305020134
- 1305100138 Forwards "Marine Ecology Studies re Operation of Pilgrim Station, Semiannual Rept 21, 1982" HARRINGTON, W.D. Boston Edison Co. 83/04/29 Environmental Protection Agency 2pp. 18376-004 244 Fiche 50-293, 83/04/29, 8305100138
- -8305(00144 "Marine Ecology Studies re Operation of Pilgrim Station, Semiannual Rept 21, 1982 " ANDERSON,R D., SCOTTON,L N. Boston Edison Co. NUC3-E1 83/04/30 414pp 18376 006 24X Ficho 50-293,63/04/29,8305100138

- 8305160134 Forwards "Environ Radiological Monitoring Program for 1982, Rept 15 HARRINGTON.H D Boston Edison Co 83/05/09 ALLAN,J Region 1, Defice of Director Ip 18447 231 24x Fiche 50-293,83/05/09, 8308160134
- --8305(60136 "Environ Radiological Monitoring Program 1982;" Rept 15 * Boston Edison Co 83/04/30 158pp 18447 232 24x Fiche 50-293.83/05/09.8305140134
- 8305230535 Forwards "NPDES Discharge Monitoring Rept. Jan-Mar 1983 "
 MATHIS,C J Boston Edison Co 83/03/12 Environmental Protection
 Agency MCMAHON.T C Massachusetts, Commonwealth of, 1p
 18537 062 24x Fiche 30-293,83/05/12
- --8305230537 "NPDES Discharge Monitoring Rept. Jan-Mar 1983 " MATHIS.C J Boston Edison Co B3/05/13 16pp 18537 064 24X Fiche 50-293,83/05/12,8305230535
- 8305170527 Forwards monthly operating rept for Apr 1983 HARRINGTON,W D. Boston Edison Co. 83/05/13 Director's Office, Office of Inspection and Enforcement Ip 18467 027 24X Fiche 50-293,83/05/13,8305170529
- --8305170532 Monthly operating rept for Apr 1983 HHITNEY 9 6 Boston Edison Co 83/05/13 6pp 18467 028 24X Fichs 50-273,83/05/13,8305170529
- 8 Reportable occurrences, LERs & related correspondence
- 8304110696 Forwards LER 83-010/03L-0 MATHIS.C J Boston Edison Co 83/03/24 HAYNES.R C Region 1. Office of Director 1p 17914 059 24X Fiche 50-293,83/03/24, 8304110696
- --8304110706 LER 83-010/03L-O on 830222, two of four motor operator mounting cap screws found backed out of core spray valve MDV 1400-4A Caused by sys vibration Cap screws installed w/thread compound applied Redundant MDV 1400-4B inspected WHITNEY.G G Boston Edison Co 83/03/24 Region 1. Office of Director 2pp 17914 0400 24X Ficha 50-293, 83/03/24, 8304110696
- 8305110334 Forwards LER 83-015/03L-0 HARRINGTON.W D Boston Edison Co 83/04/25 Region 1, Office of Director Ip 18406 177 24X Fiche 50-293,83/04/25,8305110334
- --8305110341 LER 83-D15/03L-O on 830331.standby gas treatment sys train opened w/o proving operability of redundant train Caused by miscommunication between inspicrew & control room Need for proper communications emphasized WHITNEY.O O Boston Edison Co 83/04/25 Region 1, Office of Director 1p 18406 178 24X Fiche 50-293.83/04/25,8305110334
- 8305110356 Forwards LER 83-014/03L-0 HARRINGTON-W D Boston Edison Co 83/04/25 Region 1, Office of Director 1p 18406-130 24X Fiche 50-273, 83/04/25, 8305110356
- --8305110365 LER 83-014/03L-O on B30329, drywell airborne leak detection sys (C-19) particulate channel found reading downscale Caused by loose connector pin fin repaired & unit returned to syc WHITMEY, 8 0 Boston Edison Co 83/04/25 Region 1, Office of Director ip 18406 i31 24X Fiche 50-293,83/04/25,8305110356
- 8305110384 Forwards LER 83-017/03L-0 HARRINGTON,W D Boston Edison Cd 83/04/25 Region 1, Office of Director 1p 18406 199 24X Fiche 50-293,83/04/25,8305110384
- --8305:10392 LER 83-017/03L-0 on 830403, drywell airborne leak detection sys (C-17) found insperable Caused by overheated sample air due to improper thermostatic control of heat tracing for sample lines Lagging on lines removed WHITNEY.9 G Boston Edison Co B3/04/25 Region 1, Office of Director ip 18406-200 24X Ficha 50-293.83/04/25,8305110384
- 8305230516 Forwards LER 83-016/03L-0 MARRINGTON W D Baston Edison Co 83/04/27 Region 1, Office of Director 1p 16537 311 24X Fichs 50-293.83/04/27,8302230516
- --B305230521 LER 83-016/03L-0 on B30402, overload annunciation received when MDV-220-2 switched open during scram recovery Probably caused by spurious annunciator from overload mechanism in Cutlei-Hammer motor control ctr Valve returned to svc WHITNEY, 6 9 Boston Edison Co B3/04/27 Region 1, Office of Director ip 18537 312 24X Fiche 50-293.63/04/27,8305230516

- B305160145 Telecopy LER B3-020/01Y-0 on B30502, daily surverilance testing per Tech Spec Section 4 11 D not performed Caused by failure to revise procedures tradvertent removal of sections from Tech Specs Procedures revised GRAHAM,E T Boston Edison Co B3/05/02 Region 1, Office of Director 1p 18446 085 24X Fiche 50-273, B3/05/02, B305160145
- 8305190024 Forwards LER 83-022/03L-0 HARRINGTON,W D Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18502 041 24X Fiche 50-293,83/05/04.8305190024
- --8305190029 LER 83-022/03L-0 on 830413, overload on valve motor 1301-17 resulted in loss of high pressure core cooling backup capability Caused by oxidation in motor end bell % motor brushes, due to humidity caused by leaking valve packing CRONDER, J D Boston Edison Co 83/05/04 Region 1, Office of Director ip 18502 042 24x Fichs 50-293,83/05/04,8305190024
- 8305230533 Forwards LER 83-018/03L-0 HARRINGTON W D Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18537 060 24% Fiche 50-293,83/05/04.8305230533
- --8305230538 LER 83-018/03L-0 on 830408, during insp standby gas treatment sys B heater contact & wiring found burnt, lendering sys inoperable Caused by high resistance due to loose wires at contactor terminal Contactor & wires replaced ORAHAM, E T Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18537 061 24X Fishe 50-273.83/05/04,8305230533
- B305190176 Forwards LER B3-021/03L-0 HARRINGTON, W D Boston Edison Co B3/05/09 Region I. Office of Director 1p 18502 257 24X Fiche 50-293,83/05/09.8305190176
- --8305190181 LER 83-021/03L-0 on 830411.during Surveillance Test 8 7 4 3.
 primary containment isolation valve A0-50338 failed to meet
 10-s closing time requirements Caused by lubicant
 infiltrating solenoid valve components Components replaced
 BRIXEY.P Boston Edison Co 83/05/09 Region 1. Office of
 Director 2pp 18502 258 24x Fiche 50-273,83/05/09,8305190176
- B305190326 Forwards updated LER B2-008/01X-1 HARRINGTON, W D Boston Edison Co 83/05/09 Region 1, Office of Director Ip 18500 318 24X Fiche 50-293,83/05/09.8305190326
- --8305190330 Updated LER 82-008/01X-i on 820331.HPCl injection valve MD-2301-8 failed to open in required manner Caused by missing wire jumper intended to bypass motor operator torque suitch Jumper installed & valve tested satisfactorily VENDER.J Boston Edison Co 83/03/09 Region 1. Office of Director 2pp 18300 319 24% Fiche 50-293.83/05/09.8305190326
- 8305230509 Forwards updated LER 83-014/03X-1 HARRINGTON, W D Boston Edison Co 83/05/09 Region 1, Office of Director 1p 18537 324 24X Fiche 50-293.83/05/09.8305230509
- --8305230515 Updated LER 83-014/03X-1 on 830329, dryweil airborne leak detection sys (C-19) particulate channel found reading downscale Caused by loose connector pin Pin repaired WHITMEY, G O Boston Edison Co 83/05/09 Region 1, Office of Director ip 18537 325 24X Fiche 50-293,83/05/09,8305230509
- DOCKET 50-295 ZION NUCLEAR POWER STATION. UNIT i
- 8305100122 Forwards post-exercise evaluation for 810729 exercise final rept of reexercise on 811007 & final exercise rept of 830118 exercise No significant deficiencies cited KRIMM.R W Foderal Emergency Management Agency 83/04/08 URDAN.E L Division of Emergency Piepaledness & Engineering Response (Post 830103) 2pp 18375 048 24% Fiche 50-295,83/04/08,8305100122
- ---8305100126 "Zion Nuclear Generating Station Small-Scale Joint Emergency Exercise, 830118, " final rept * Federal Emergency Hanagement Agency 83/03/04 7ipp 18375 050 24% Fiche 50-295,83/04/08,8305100122
- --8305100131 "Zion Nuclear Power Station Reexercise.WI/Kenosha County (Small-Scale) Bi1007," final rept * Federal Emergency Management Agency 82/04/30 32pp 18375 121 24X Fiche 50-295.83/04/08.8305100122
- --8305100136 "Post-Exercise Evaluation, Exercise of State & Local Radiological Emergency Response Plans for IL & Wi (Near Zion Nuclear Power Station) " * Federal Emergency Management Agency 81/07/29 44pp 18375 153 24X Fiche 50-295, 83/04/08, 830510012?

- 83050309%, helease, public elector or riviol chergency plan implamenting procedure FELTON. IM Division of Rules and he olds. 83,04/22 Bocument Management Branch ip 19326-103 10 Fiche 50-295-83/04/22. 83050303 %
- --830503008; Forwards public varsion of Per S to Emergency Plan Implementing Procedure LPIP -40-1, 'Emitgency Communications Sys' Operational Tests PLIML G Commonwealth Edison to 85 (4/06 NENTON H R NRC - No Detailed Affiliation Given in 18376-104 P4X Fiche 50-295,83/04/22,83050/36076
- --8309030051 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys % Operational Tests" Procedure Change Request A-B3-51 encl NYMER'J U Commonwealth Edison Co 23 39p 18325 105 24X Fiche 50-295,83/04/27,835030076
- 8305030104 Releases public /ervion of revito emergency plan implementing procedure FELTON, / M Division of Rules and Nevorts 03/04/22 Document Management Branch 1p 18309 554 34x Fichs 50-275, d3/04/22, R305030104
- --8309030114 Forwards public version of Re II to Energency Plan Implementing Procedure FPIP 390-1, "Activation of Generating Station Energency Plan Station Group"
 PLIME.G Commonwealth Edition Co 82/04/06 DENTON.H R NRC No Detailed Affiliation Given ip 100/09/355 247
 Fiche 50-295 83/04/22,83090_0104
- --830503017 Public version of Rev 11 to theregony (lon implementing Procedure EPIP 320-1, "Activation of 8 negating Station Emergency Plan Station Group "Procedure Change Request A-83-98 tool NYKIRK, J. W. Commonwealth Edison Co. 85/04/25 7pp. 18309-356-24% Fiche 50-295.83/04/22 83050301/4
- B305060673 Releases public version of levil emolgency plan implementing procedure FELTON, / M Division of Roles and Re Livis B3/04/25 Document Management Branch 1p 1835/ 326 **4* Fiche **0~295.83/04/25 R30506673
- --8305060579 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure FPIP 550-2 "Environ Emergency Kit & Emergency Operations Farility Radiological Equipment "Procedure change request end PLIML 6 Commonwealth Edison Co Detailed Aftiliation Given 3pp Fiche 50-295.83704/25.83050006/3
- --8305060686 Public version of Re 5 to fact sincy Floa Implementing Procedure EPIP 550-2, "Fristion Emergency Bit ' Emergency Operations Facility Radialingical Equipment ' * Commonwealth Edison Co B3/03/08 5pp 1835/330 24 < Fiche 50-293,83/04/22.83050606/3
- 8305060410 Forwards IC Safeguaids Insp Repts 50 295,83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld fref 10/FR/3 21) KEPPLER, J G Region 3. Office of Director 83-05/03 0'CONNOR. J J Commonwealth Edison Co. 3pp. 18341 222 244 Ficha 50-295, 8305/03,8309060410
- --B305060ilE IC Sateguards Ins., Repts in, 240,83-or 1 50 304/B3-07 on B30315 Noncompliance moted unauthorized entry into protected & vital area & failure to topl safeguards event Details withheld (ref 100/R73 1)
 BELANGERIAL, MADEDALT J. CREEL, J. R. Region 3. Office of Director B3/04/27 ip 18343 242 248 Fiche 50-295,83/05/03. B305060410
- 8305110034 Generic Lts 83-2; to all literation of epatating reactors, applicants for OLs & holders of CPs re-clusterization of access to control procedures for liw enforcement visits Svc list encl
 EISENHUT.D G Division of Livensing 83/09/11 Consolidated Edison to of New York, Inc. 16pp 18940-095 24x
 Fiche 80-000-83/09/11.8309110034
- B305240246 Advises that requirements of NUMCO O73/ Item III A 2 : "Emergency Preparedness Upditude Emity High Lot Meet App E to 100FR50," satisfied VARCA, S A Upgrating Reactors Branch 1 P3/05/16 (ARRAR, D L Commonwealth Edison Co 1pp 18593-107 244 Fiche 50-295,83/05/16,8305240246

- J learnance trindemently information
- 8305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Disson Unit 1 & Endorsement 63 to MFLIA Policy NF-201 & Endorsement 53 to MAELU Policy NF-201 & Endorsement 53 to MAELU Policy MF-44 for 2:0n Unit 1 W/o encl Quad Citics ondorsements OSTER. J Commonwealth Edison Co. 83/03/13 SALTZMAN. J Assistant Director for State & Licensee Relations 5pp 18537-174 24% Fiche 50-000.83/03/13.8305230560
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B305160246 Comments on SSMRP risk analysis Risks from seismic events should be analyzed separately from internal events w/results treated independently Unly upper limits need be estimated to determine if risks acceptable DAVIS.PR ACRS Advisory Committee on Reactor Safeguards B3/04/16 B4RENT, D ACRS Advisory Committee on Reactor Safeguards 1p 16472 001 24X Fiche 50-275-83/04/16 B305160246
- P Operating license stage documents & correspondence
- 8303300001 Forwards Amends B2 & 72 to Licanses DPR-39 & DPR-48, respectively & notice of issuance & avgiobility Amends delete nonradiological water quality-related requirements VARGA-S A Operating Reactors Branch 1 83/03/11 FARRAR D L Commonwealth Edison Co 3pp 17751 P92 P4X Fiche 50-295,83/03/11,8303300001
- --8303300002 Amends 82 % 72 to Licenses [PR-39 & DPR-48, respectively, deleting noisadiological water quality-related requirements VARGA: A Operating Reactors Branch | 83/03/11 Alpp 17751 295 24X Fiche 50-295.83/03/11, 8303300001
- ~-B30330003 Notice of issuance % availability of Amends 82 & 72 to Licentes DPR~37 % DPR~48. respectively VARGA.S A Gperating Reactors Blanch I 83/03/11 2pp 17751 356 244 Fiche 50~275, 83/03/11, B303300001
- 8304270053 Agrees w/830311 ltr demonstrating that Tech Specs indicate conditions under which protection bys channels may be bypassed during cooldown Review closed VARCA, S.A. Operating Reactors Branch 1 83/04/12 FARRAR, D.L. Commonwealth Edison Co. 2pp. 18254-150 24X Fiche 50-295,83/04/12.
- 3305180691 Forwards revised order modifying completion dates for NUREG-0737. Items II B 2. "Plant Shielding." II B 3. "Post Accident Sampling" & II F i 2. "Accident Monitoring Instrumentation "
 VAROA.S A Operating Reactors Branch 1 83/04/28 FARRAR.D L Commonwealth Edison Co. 2pp. 18505-181 24X Fiche 50-275,83/04/28. REDNINGER
- -8305180/02 Revised order modifying completion dates for NUREG-0737, Items II 8 2, "Plant Shielding." II B 3, "Post-Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation," per Generic Lits 82-05 & 82-10 EISENBULD 6 Disjeton or Licensing 83/04/28 Commonwealth Edison Co 7pp 18505 183 24* Fich: 50-295.83/04/28.8305180691
- 305020455 Generic Lti B3-19 to all power reactor & testing licensees re new procedures for providing public natice concerning issuance of amends to OLs Svc list encl ISENHUT.D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 16441 120 24% Fiche 50-000.83/05/02,8305020455
- 303040317 Responds to NRC request for add1 info re TM1 action plan items Hatl supports util position; that nonsefety-related squipment falls outside stope of Franklin Research Ctr review Justification not mecessary
 LENTING:F G Commonwealth Eduson Co 83/03/02 DENTON:H R Office of Nuclear Reactor Regulation. Director 2pp 18323 289 24X
 Fishe 50-273.83/05/02.8309040317
- 305110144 Ark receipt of 830318 ltr.providing basis for not paying addl fee for 801107 application re assurance of redundancy in DNR capability Fees include cost of prof staff hours expended & associated contractual sect Addl fee due MILLER, W.O. License Fee Management Branch 83/03/03 LENTINE, F.O. Commonwealth Edison Co. 2pp. 18421 347 24% Fiche 50-275, 83/03/03. 830510144
- 305090659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs reintegrated scheduling for implementation of plant mods Svc fist end; EISCHMUT, D G Division of Litensing 83,05/09 Consolidated Edison Co of New York, Inc 16pp 186/7/153 24% Fiche 50-000,83/05/09,8308090659

- 8303170218 Forwards response to 830208 (0317 requests for addlinfo re NUREQ-0737, Items !! F 1 4, "Containment Pressure Monitor." Il F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor "

 LENTINE: F 0 Commonwealth Edison Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 18466 332 24X Fiche 50-295,83/05/13,8305170218
- 8305240506 Forwards fee for Amends 65 & 62 to Licenses DPR-39 & DPR-48, respectively
 LENTINE, F G Commonwealth Edison Co B3/05/18 MILLER, W G License Fee Management Branch 2pp 18371 264 24X
 Fiche 30-295,83/05/18,8305240506
- 8305240473 Provides addl info re probabilistic safety study, discussed during 830331 NRC site visit Formal document verification of fan operability not previously required Procedures revised to include operability of fan coolers

 LENTINE.F G Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18549 355 24X Fiche 30-295, 83/05/19, 8305240473
- 8305250077 Forwards Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by IOCFR30 49 for Zion Units 1 & 2 " LENTINE F O Commonwealth Edison Co 83/05/19 DENTON. H R Office of Nuclear Reactor Regulation, Director 4pp 18589 042 24X Fichs 30-295, 83/05/19, 8305250077
- --8305250084 Rev 2 to "Environ Gualification of Electrical Equipment Important to Safety Covered by 10CFR50 49 for Zion Units 1 % 2" * Sargent & Lundy, Inc 83/05/200 776pp 18589 046 24X Fiche 50-295,83/05/19,8305250077
- 8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan GLBERT.R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000.83/05/26.8305310086
- Q Inspection reports: IE Bulletins & correspondence
- B212040385 IE Info Notice B3-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!

 TAYLOR. J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24x Fiche 30-000.83/03/21/8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24x Fiche 50-000,83/04/15,8303040021
- B305100262 Forwards IE Insp Repts 50-295/83-02 % 50-304/83-02 on B30118-0304 & notice of violation CHAFER, N D Region 3, Office of Director 83/04/20 REED, C Commonwealth Edison Co 2pp 18372 242 24X Fiche 50-295,83/04/20,8305100262
- --8305100266 Notice of viplation from insp on 830118-0304 SHAFER.W D Region 3. Office of Director 83/04/20 1; 18372 244 24 Fiche 50-295,83/04/20.8305100262
- --8305100271 IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 Noncompliance noted failure to notify NRC of unplanned release while purging & drawing routine sample WATERS.J R . HARTMANN.P L . DUNAWAY.F R Region 3. Office of Director 83/04/20 13pp 18372 245 24X Fichs 50-295.83/04/20.8305100262
- B303040023 IE Info Notice B3-22, "BWR Gafety/Relief Valve Failures "
 Svc list entl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fithe 50-000, B3/04/22, B303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphers Bensing Sy4" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/25 Consolidated Edison Co of New York
- 8305170337 Forwards IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311.14-17.22-23 & 0407 & notices of violation & deviation PAPERIELLO,C J Region 3, Office of Director 83/04/27 REED,C. Commonwealth Edison Co 2pp 18465 274 24X Fiche 50-295,83/04/27.8305170337

,

- ---8305170344 Notice of violation from insp on 830311.14-17.22-23 % 0407 PAPERIELLU.C J Region 3. Office of Director 83/04/27 2pp 18465 276 24X Fiche 50-295.83/04/27.8305170337
- --830517034B Notice of deviation from Insp on 830311.14-17.22-23 % 0407 * Region 3, Office of Director 83/04/27 ip 18465 278 24X Fiche 50-295.83/04/27.8305170337
- --8305170353 IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311,14-17, 22-23 & 0407 Noncompliance noted contamination surveys of transfer canal workers eithibiting hasal contamination not documented fuel pool samples not analyzed LOVENDALE.F C . MILLER.D E . GREGER.L R . Region 3. Office of Director 83/04/25 lipp 18465 279 24X Fiche 50-293,83/04/27,8305170337
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 90-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027
- 8305020252 EN-83-028 on B30503, notice of violation & proposed imposition of civil penalty in amount of \$10,000 to be issued Action based on failure to control access into protected & vital areas & unauthorized entry ROSAND, R Director's Office, Office of Inspection and Enforcement B3/04/28 1p 18277 277 24X Fichs 50-275,83/04/28,8305020252
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enci JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/03 Consolidate Edison Co. of New York, Inc. 122pp 18441 170 24x Fiche 50-000.83/05/03.8303040028
- 8305060410 Forwards IE Gafeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld (ref 10CFR73 21)
 KEPPLER.J G Region 3, Office of Director 83/05/03 O'CONNOR.J J Commonwealth Edison Co 3pp 18343 237 24X Fiche 50-295, 83/05/03.8305806410
- --8305060418 IE Safeguards Insp Repts 50-275/83-06 & 50-304/83-07 on 830315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Details withheld (ref loorR73 21)

 BELANOER.J L , MADEDA.T J , CREED.J R Region 3, Office of Director 83/04/27 ip 18343 242 24X Fiche 50-275,83/05/03,8305060410
- B303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,C L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies" Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24% Fiche 50-000, B3/05/04, B303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fichs 50-000.83/05/11.8303040034
- 830520035) Forwards results of investigation on Br-82 source & significance in containments, per 830216 committal Investigation result of IE Insp. Repts 50-295/82-30 & 50-304/82-27
 LENTINE, FO Commonwealth Edison CO 83/05/17 KEPPLER, J. Q. Region 3. Office of Director 4pp 18516 247 24X
 Fichs 50-295,83/05/17,830520035;

- 8303040040 IE toro Notice 83-31 from in Aberte? Computer Program "Sec list and Division or Emergency Preparadness & Engineering Response (Polit 830103) 83/01/19 consolidated Edison Co. of New York, Inc. 114pp 18697-009 21x Fichs 50-000/83/05/19/8303040040
- 8305310096 Forwards responses to violation // deviation noted in 1E Insp. Repts 5: 295/83-07 1 50-304/85-06 on (20311-0417 Corrective actions personnel whole body count initiated to document internal contamination.

 FARRAR, D. L. Cammonwealth Edison 10 637/95/55 REPPLER, J. Q. Region 3, Office of Director 4pp 10658-074 24X Fiche 50-295,83/05/25,83053100/95
- 8303040046 IE Into Notice 8J-33 'Nonrepresentative Sampling of Contaminated Oil ' Svc list and JORDAN E L. Division or Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 00/ 24% Fiche 50 000-83/05/26.8303040046
- R Periodic operating reports totaled currespondence
- --8305120015 Monthly operating repts for Apr 1983 AUSTIN.G Commonwealth Edison Go 83'05/07 11pp 18423 059 24X Fiche 50-295 83/05/09.8305120013
- S Reportable occurrences, LERs ' related correspondence
- 8305060440 forwards updated LER 03 004/97/ 1 canceling original rept GRAESSER.N L Commonwealth Edison Co 83/04/08 KEPPLER, J G Region 3. Office of Director 1p 18343 131 24x Fiche 50-295,83/04/08.8305060443
- --8305060444 Updated LER 83-004, 99x-1, lanceling original rept SCHULTZ. C. Commonwealth Edison Co. 23/04/08 Region 3, Office of Director 1p 18343 132 24X Fiche 50-295,83/04/08, 8305060443
- 8305060528 forwards LER 83-011/03L-0 GRAESSER,V L. Commonwealth Edison Co. 83/04/29 KEPPLER,J G Region 3. Office of Director ip 18751 088 24X Fiche 50-293,83/04/29,8305060528
- --8305060944 LER 83-011/03L-0 on 833401, steam generator bloodown monitor IRE-0019 failed low Caused by failure of high voltage power supply due to normal wear Power Supply replaced % monitor returned to svc

 JAKUBAITIS.T C Commonwealth Edison Co 83/04/27 Region 3, Office of Director ip 18351 089 P4X Fiche 50-295,83/04/27, 8305060528
- 8305060567 Forwards LER 83-010/031-0 QRAESSEN, K L Commonwealth Fdison to 83/04/27 KEPPLER, J Q Region D, Effice of Director 1p 19347-035 24 (Fiche 50-295.83/04/27.8305060567
- ---8305060572 LER 83-010/03L-0 on 830413.1A feedwater flow transmitter 1FT-510 found out-of-tolerance 3 3% low % 5 8% high on 830329 Caused by transmitter ferritt disk & coli loose from mountings Transmitters repaired & recallibr CANTMELL.P F Commonwealth Edison Co 23/04/29 Region 3, Office of Director 1p 18349 056 24/ Fiche 50-295,83/04/29,8305060547
- 8305240311 LER 83-012,031-0 on 830413.Class I pipe tunnel indine manito: IRTPRO7B failed low Caused by personnel performing calibr of IRT-PRO7B on 830412 incorrectly adjusting high voltage setting M/830513 ltr WILLIAMS.V S . GRAESSER: K L Commonwealth Edison Co 83/05/13 KEPPLER: J G Region 3. Office of Director 2pp 18548 182 24X Fiche 50-295.83/05/13.6305240311
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F Becurity, medical, emergency & tire protection plans
- 8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty facils withheld (refideFR2 /90)

 G'REFILLY, J. P. Region 2, Office of Director 83/01/13 PARRIS, H.G. Tennessee Valley Authority Capp 18363 119 24X
 Fiche 50-259, 83/01/13, 8305090191

- 8305040626 Releases public version of religed emergency plan implementing procedures
 FELTON: If Diston of Rules and Relords 83,04/26 Document Management Branch ip 18327 ODE 24x Fiche 50-259,83/04/26,8305040628
- --8305040a55 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event. IP-3 re alert & IP-4 re site area omergency 4 Tennessee Valley Authority 83/03/03 81pp 18329 008 24X Fiche 50-259, 83/04/26, 8305040628
- 8305100234 Requests that Figures B 5-48 & B 5-13B be removed from updated F3AR 'c destroyed & replaced W/encl pages since figures (untain into classified as safeguards info per 10CFR73 MILGRUM Tennessee Valley Authority B3/05/04 DENYON, H R Office ut Nucleum Reactor Regulation, Director 3pp 18373 266 24X Fich. 50 259, B3/05/04, B305100234
- 8305110031 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs % holders of CPs re clarification of access to control procedures for law enforcement visits Svc list anc; EISENHUT-D G Division of Licensing 83/05/11 Consolidated Edison to of New York, Inc. 16pp 18540-095 24% Fiche 30-000.83/05/11.8305110034
- 830526017/ Informs of NRC determination that onsite & offsite smarganty preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1 VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H Q Tennessee Valley Authority 3pp 18448 107 24X Fiche 30 257, 63/05/18, 6305260177
- J Insurance & indemnity information
- G305160007 Forwards Endorsements 65 % 34 to NELIA Folicy NF-198 & MAELU Policy Mf-66.respectively DUCK.J R Marsh & McLennan, Inc 83/05/03 SALTIMAN, J Assistant Director for State & Licensee Relations 3pp 18456-039 24X Fiche 51-259, G3/05/03, B305160005
- P Operating license stage documents 7 correspondence
- 6305040511 Application for amend to Licenses DPR-32 DPR-32 & DPR-68 revising stated isolation logic for Gloup 7 isolation valves to reflect actual logic MILLS.L M Tennesses Valley Authority 63/04/28 DENTON.H R Office of Nuclear Reactor Regulation. Director Rpp 18322 038 24X Fiche 50-239.63.04/28,8305040511
- --8305040517 Proposed changes to Yech Specs revising stated isolation logic for Group 7 isolation valves to reflect actual logic * Tennesses Valley Authority 83/04/28 5pp 18322 040 24X Fiche 50-259.83/04/28,8305040511
- 8305020455 Generic Ltr 83-17 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of anends to OLS Svc list encl EISENHUT.D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50 000.83/05/02.8305020455
- 8305090657 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D @ Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24% Fiche 50 000.83/05/09.8303090659
- B3051B0845 Advises that action required by Amends 86.83 & 57 to Licenses DPR-33.DPR-52 & DPR-68.respectively & General Let 83-07 complete, based on util negotiating w/DBE redisposal of high level waste VASSALLO, D B Operating Reactors Branch 2 83/05/09 PARRIS, H G Tennessee Valley Authority 2pp 18506 018 24X Fiche 50-259,83/05/09,8305180845

- 8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983.in response to NRC 830429 request MILLS.L M Tennessee Valley Authority 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18437 008 24x Fiche 50-259.83/05/10,8305130003
- 8303250136 Forwards request for add1 info re NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulators" Info requested within 49 days VASSALLO.D B Operating Reactors Branch 2 83/05/11 PARKIS.H G
- 49 days VASSALLO.D B Operating Reactors Branch 2 83/05/11 PARRIS.H G Tennessee Valley Authority 3pp 18596 204 24X Fiche 50-259.83/05/11,8305250136
- 8305260187 Forwards safety evaluation re BWR Owners Oroup response to NUREG-0737. Item II K 3 45, "Depressuriation WOther Than Automatic Depressuriation Sys "Action complete VASSALLO.D B Operating Reactors Branch 2 83/05/18 PARRIS, H G Tennessre Valley Authority 2pp 1848 099 24X Fiche 50-259.83/05/18,8305260187
- 8305250473 Forwards info re status of environ qualification of equipment per 10CFR50 49(g) Qualification status table, schedule for qualifying deficient equipment & addijustification for continued operation encl
 KAMMER.D S Tennessee Valley Authority 83/05/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 94pp 18595 110
 24X Fiche 50-259, 83/05/20, 8305250473
- 8305270021 Notifies that util will submit schedule for performing mods to Mark I containment drywell/wetwell vacuum breakers once calculations complete & mods identified in response to Generic Ltr 83-08 MILLS,C M Tennessee Valley Authority 83/05/23 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18638 313 24X Fiche 50-259,83/05/23.8305270021
- 8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREG-0737. Item II K 3 13, "Separate HPCI & RCIC Initiation Levels" Criteria will be met MILLS,L M Tennessee Valley Authority 83/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18638 306 24X Fiche 30-259,83/05/24.8305270030
- @ Inspection reports, IE Bulletins & correspondence
- 8305090191 Discusses IE Security Insp Repts 50~259/82-47, 30~260/82-47 & 50~296/82-47 on B21220 & forwards notice of violation & proposed imposition of civil penalty Encis withheld (ref 10CFR2 790)
 O'REILLY.J P Region 2, Office of Director 83/01/13 PARRIS.H G Tennessee Valley Authority 3pp 18363 119 24X
 Fiche 50~259, 83/01/13, 8305090191
- 8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33,50-260/82-33 & 50-276/82-33 will be delayed until 830301 MILLS,L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2. Office of Director ip 18638 071 24X Fiche 50-257.83/01/28,8305270171
- 830527017/ Forwards 830111 response to notice of violation & proposed imposition of civil penalty erroneously submitted to JP G'Reilly W/o encl MILLS,L M Tennessee Valley Authority 83/02/10 DEYBUNG,R C Director's Office. Office of Inspection and Enforcement 1p 18637 362 24X Fiche 50-259.83/02/10.8305270177
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 80-000,83/03/21,8212060385
- 8305270514 Forwards IE Insp Repts 50-259/83-06.50-260/83-06 & 50-276/83-06 on 830214-19 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/30 PARRIS,H G Tennessee Valley Authority 2pp 18646 182 24X Fiche 50-239.83/03/30.8305270514
- --8305270926 IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-276/83-06 on 830214-19 No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performance & results WHITENER, H L , JAPE, F Region 2, Office of Director 83/03/28 8pp 18646 184 24X Fiche 50-259,83/03/30,8305270514

- 8305270207 Concurs w/util 830401 request for extension of commitment dates for responding to violations noted in IE insp. Repts 50-259/82-16, 50-260/82-16 b 50-296/82-16 until 830901 LEHIS,R C Division of Project & Resident Programs 83/04/07 PARRIS,H G Tennessee Valley Authority 1p 18637 170 24X Fiche 50-259, 83/04/07, 8305270202
- --8305270206 Advises that new full compliance date of 830901 required to complete review of procedures, preparation of revs & issuance of revised instructions in response to IE Insp. Repts 50-259/82-16, 50-260/82-16, 50-296, 82-16
 MILLS, L.M. Tennessee Valley Authority 83/04/01 O'REILLY, J.P. Region 2, Office of Director ip 18637 171 24X
 Fiche 50-259,83/04/07,8305270202
- 8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 VERRELLI.D M Division of Project & Resident Programs 83/04/07 PARRIS
- --B305270652 Responds to MRC B30210 ltr re violations noted in IE Insp Repts 50-259/83-02.50-260/83-02 & 50-296/83-02 Corrective actions radiochemical lab menual Procedure 728 III 2 1 will be revised MILLS.L.M. Tennesses Valley Authority B3/03/16 O'REILLY, J P Region 2. Office of Director 3pp 18662 133 24X Fiche 50-259.83/04/07.8305270642
- --8305270658 Forwards IE Insp Repts 50-259/83-02,50-260/83-02 & 50-296/83-02 on 830117-18 & notice of violation VERRELLID M Division of Project & Resident Programs 83/02/10 PARTIS H 0 Tennessee Valley Authority 2pp 18662 136 24X Fiche 50-259,83/04/07,8305270642
- --8305270661 Notice of violation from insp on 830117-18 * Region 2. Office of Director 83/02/10 1p 18662 138 24X Fiche 50-297, 83/04/07, 8305270642
- --8305270666 IC Insp Repts 30-259/83-02.50-260/83-02 t 50-296/83-02 on 830117-19 Noncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis COLLINS.T R , BARR, k P Region 2, Office of Director 83/02/10 3pp 18662 139 24X Fiche 50-259,83/04/07,8305270642
- 8305270653 Ark receipt of 830401 itr informing NRC of steps taken to correct violations noted in 18 Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 VERRELLI, D M Division of Project & Resident Programs 83/04/13 PARRIS. H G Tennessee Valley Authority 1p 18645 201 24X Fiche 50-259, 83/04/13, 8305270653
- --8305270660 Responds to NRC 830225 ltr le violations noted in lE Insp Repts 50-259/82-44, 30-260/82-44 & 50-296/82-44 Corrective actions interim criteria for lemoval of waste oil & miscellaneous wastes from regulated areas developed MILLS.L.M. Tennessee Valley Authority 83/04/01 O'REILLY, J.P. Region 2, Defice of Director 5pp 18645 202 24X Fiche 50-259, 83/04/13, 8305270653
- --8305270664 Forwards IE Insp Repts 50-259/82-44.50-260/82-44 & 50-296/82-44 on 821115-19 & notice of violation O'REILLY, J P Region 2. Office of Director 83/02/25 PARRIS.H G Tennessee Valley Authority 2pp 18645 207 24X Fiche 50-259.83/04/13.8305270653
- --8305270665 Notice of violation from insp on 821115-19 * Region 2, Office of Director 83/02/25 2pp 18645 209 24X Fiche 50-259,83/04/13,8305270653
- --8305270668 IE Insp Repts 50-259/82-44.50-260/82-44 \$ 50-296/82-44 on 821115-19 Noncompliance noted licensee transferred licensed matt to unauthorized recipients & disposed of matt by unapproved means
 DEDS.B T , BARR.K P Region 2, Office of Director 82/12/23
 7op 18645 211 24X Fiche 50-259,83/04/13,8309270653
- 8303040021 IE Info Notice 83-21, "Defactive Emergency Use Respirator" Bvc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15,8303040021
- B305270246 Forwards IE Insp Repts 50-299/83-13,50-260/83-13 & 50-296/83-13 on B30329-30 No noncompliance noted Major areas inspected, procedures, representative records & observations of demonstrated ultrasonic methodology W/o encl VERRELLI,D M Division of Project & Resident Programs 83/04/19 PARRIS,H G. Tennessee Valley Authority 3pp 18641 326 24% Fiche 50-259,83/04/19,8305270266

- 8303040023 IF Info Notice 83-23, 'Blik Safety Relier Valve Failures "
 Svc list encl
 JORDAN, Et Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Lonsolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8305030625 Forwards additinto re masonry wall per IF Bulletin 80-11, in response to NRC 83012B its Results or wall displacement analysis will be submitted by 830715 W/three oversite drawings Aperture cards are in PDR MILLS.L M Tennessee Valley Authority 83/04/22 DENION.H R Office of Nuclear Reactor Regulation, Director 7pp 18303-001 244 Fiche 50-259,83/04/22,8305030625
- --8305030631 Rev 2 to BFN-50-D/07 "Betailed Design Criteria for Regveluation Criteria for Masonry Walls " * Tennessee Valley Authority 82/03/26 162pp 18303 008 24X Fiche 50-259,83/04/22.8305030625
- G305270510 Forwards IE Insp Repts 30-259/83-08.50-260/83-08 & 50-296/83-08 on 830329-31 No noncompliance noted VERRELLI.D M Division of Project ? Resident Programs 83/04/22 PARRISH G Tennessee Valley Authority 2pp 18646-065 24X Fiche 50-259.83/04/22.8305270510
- --8305270528 IE Insp Repts 50-259/83-08.50 260/83-08.50-296/83-08 on 830328 31 No noncompliance nated flagor areas inspected mgt is administrative controls status review of radiological environ monitoring program inspect monitoring stations CUNNINGHAM.A L., MONTGUIKERY.D M. Pregion 2, Office of Director 83/04/20 3pp 1844-06* 24X Fishe 50-259-83/04/22,8305270510
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Syc. list encl. JORDAN-C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consultdated Edison Co. of New York, Inc. 119pp 16381 291 24x Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc) 1st encl JORDAN.E L. Division of Emergency Pieparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047 244 Fiche 50-000.83/04/28.8303040026
- 830304002/ IE info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24% Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Bleakers " Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN, E.L. Division of Emergency Proparedness & Engineering
 Response (Past 830103) 83705/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3705/04 Consolidated Edison Co of New York Inc 119pp 18141 001 24x Fichc 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, 'Fuel Binding Caused by Fuel Rack Deformation " Svc [1st encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 244 Fiche 50-000,83/03/06.8303040033
- 8305270345 Ack receipt of 8304z1 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 30-259/83-05, 50-260/83-05, 50-260/83-05
 LEWIS.R C Division of Project & Resident Frograms 83/05/09 PARRIS.H G Tempessee Valley Authority 1p 18642 079 24% Fiche 50-259, 83/05/09/8305270315
- --8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-299/83-03;50-260/83-05 & 50-296/83-05 Corrective actions conduit mounting supports connected to conduits & supported per General Const Spec G-3 MILLS: L M Tennessee Valley Authority 83/04/21 O'REILLY, J P Region 2. Office of Director 4pp 19642 080 24X Fiche 50-259, 83/05/07, 8305270345

- --8303270362 Forwards IE Insp Repts 50-257/83-05.50-260/83-05 & 50-296/83-05 on 830126-3225 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/03/16 PARRIS H G Tennessee Valley Authority 2pp 18642 084 24) Fiche 50-259.83/05/07/8305270345
- --8305270J68 Notice of violation from insp on 830126-0225 4 Region 2. Office of Director 63/03/16 2pp 18642 086 24X Fiche 50-259, 83/05/09, 8305270345
- --8303270381 IE Insp Repts 50-257/83-05.50-240/83-05 & 50-294/83-05 on 830126-0225 Noncompliance noted violation of LOCFR30.App B, Criterion V in maint area & violation pf Tech Spec re Sorveillance Insp 2
 PAULK G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 63/03/14 & Pp 18642 088 24X Fiche 50-259.83/05/09.8305270345
- 8303040034 [E Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (ECP) Outdelines "Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Natice 83-31. "Error in ADLPIPE Computer Program "
 Svc list end!
 JORDANNEL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19,8303040040
- 8303040046 IE info Notice 83-33. "Nonrepresentative Sampling of Contaminated 0:1" Syc list encl JORDAN-E L Division of Emergency Prepaiedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- S Reportable occurrences. LERs & related correspondence
- 8305030266 Forward: LER 83-023/03L-0 GREEN.H J Tennessee Valley Authority 83/04/26 O'REILLY.J P Region 2. Office of Directo: Ip 18300 047 24X Fiche 50-294.83/04/26.8305030266
- --B309030272 LER 83-023/03L-O on 830330 during normal operation, while performing Surveillance Instruction 51 4 2 8-69, pressure switch PS-3-2046 had as-found setpoint of 1123 psig Caused by instrument drift Switch recallibr IRBY, 0 J Tennessee Valloy Authority 83/04/26 Region 2, Office of Director 3pp 18300 048 24X Fiche 50-276,83/04/26,8305030266
- 630510010/ Forwards LER 63-024/01T-0 GREEN,H J Tennessee Valley Authority 63/05/03 O'REILLY-J P Region 2, Office of Director 1p 183/5 026 24x Fiche 50-296.63/05/03.8305100107
- --9305100113 LER 83-024/017-0 on 830419, personnel notified that MCHGR for rod withdrawal error scenario exceeded 1% plastic strain linear heat generation rate limit for eight LTA bundles Cause not stated Procedures for reviewing work revised STILES.HA Tennessee Valley Authority 83/05/03 Region 2, Office of Director 2pp 18375 027 24% Fiche 50-296,83/05/03,8305100107
- 8305170030 Forwards LER 83-026/03L-0 GREEN.H J Tennessee Valley Authority 83/05/09 O'REILLY, J P Region 2. Office of Director 1p 18466 E80 24X Fithe 50-296.83/05/09.8305170030
- --8305170034 LCR 83-026/03L-O on 830411.while establishing EECW flow rate to emergenty dissel 3 generator cooler following modihead on HX found cracked-rendering generator inoperable Caused by mfg defect Crack in cest from head regained HOLDER/E T Tennesses Valley Authority 83/05/09 Region 2, Office of Director 2pp 18466 181 24X Fiche 30-276/83/03/09, 8305170030
- 8305290508 LER 83-025/02L-0 on 830419, during normal operation, drywell temp indicators IS-64-67, TI-64-52A & 7H 64-32 drifted out of tolerance & beyond Yach Spec Itali Instruments recallor & functional tested 4/830517 ltr

 BASS: 0 W. OREFNE: H J Tennessee Valley Authority 83/05/17
 D'REILL(Y.J P. Region 2, Office of Director Jpp 18588 294 24X
 Fiche 50-296, 83/05/17, 8305250508
- 8305310054 LER 83-027/03L-0 on 830418, offgas post-treatment rad; ation monitors (3-8M-90-265/266) rendered inoperable Caused by sample pump failure due to normal end-of-life operation

 Sample pump replaced W/830517 ltr

 GREEN.H J Temnessee Valley Authority 83/05/17

 Region 2. Office of Director 3pp 18653 183 24X 13/05/17, 8305310034

X Onsite Storage of Low Level Waste

B305030677 Requests remittance of add1 sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste MILLER.W O ticense Fee Management Branch 83/04/22 MILLB.L M Tennessee Valley Authority 2pp 18309 193 24X Fiche 50-000.83/04/22.8305030679

DOCKET 30-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

- 8305180026 Forwards Amend 82 to License DPR-46, safety evaluation & notice of issuance & availability Amend modifies fire sysclean water supply, plant staff working hours, reactor protection sys power monitoring sys & snubber listings VASBALLO, D B Operating Reactors Branch 2 83/04/29 PILANT, J M Nebraska Public Power District 2pp 18497 052 24X Fiche 50-298,83/04/29,8305180026
- --8305180039 Amend 82 to License DPR-46 modifying standby gas treatment testing requirements. App J testing scram discharge vol. fire protection sys clean water supply snubber listings & reactor power sys power monitoring sys
 VASSALLO. D B Dereating Reactors Branch 2 83/04/29 71pp
 18497 054 24X Fiche 50-298,83/04/29,8305180026
- --8305180050 Safety evaluation supporting Amend 82 to License DPR-46 * Office of Nuclear Reactor Regulation, Director 83/04/27 11pp 18497 125 24X Fiche 50-298,83/04/29,8305180026
- --8305180071 Notice of issuance & availability of Amend 82 to License PPR-46 VASSALLO.D B Operating Reactors Branch 2 83/04/29 2pp 18497 136 24X Fiche 50-298.83/04/29.8305180026
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISEMHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000,83/05/11.8305110034
- 8305250145 Informs that NUREG-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility (tem closed VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M Nebraska Public Power District 3pp 18576 195 24X Fiche 30-278.83/05/18, 8305250145
- B305260301 Forwards IE Insp Rept 50-298/83-05 on B30321-25 No noncompliance noted MADEEN.G L Region 4. Office of Director 83/05/23 PILANT, J H Nebraska Public Power District 2pp 18626-265 24X Fiche 30-298.83/05/23.8305260301
- --8305260304 IE Insp Rept 50-298/83-05 on 830321-25 No noncompliance nated Major areas inspected security plan implementing procedures security organization records & repts & access control Details withheld (ref 100FR73 21)
 EVANS.C A , KELLY, J A , WESTERMAN, T F Region 4, Office of Director 83/05/20 ip 18626 267 24X Fiche 50-298.83/05/23, 8305260301

I Financial information

- 8305060380 Forwards Annual Financial Rept 1982 FILANT, J M Nebraska Public Power District 83/05/07 Office of Nuclear Reactor Regulation, Director 1p 18344 036 24X Fiche 50-298,83/05/07,8305060380
- --8305060383 Annual Financial Rept 1982 Hitt.D W. KOSMAN.H D. HERRINGTON.F A District 83/05/03 43pp 18344 037 24% Fiche 50-298.83/05/07, 8305060380
- P Operating license stage documents & correspondence
- B305030588 Forwards response to B30215 request for add1 info re NUREC-0737. Item II B 3 re post-accident sampling sys Areas discussed include radiological & Chemical analysis capacity & reactor coolant gas analysis PILANT.M Nebraska Public Fower District B3/04/22 VASSALLO, D B Operating Reactors Branch 2 4pp (8305-354 24X Fiche 30-298, 83/04/22, 8305030588

- B305020449 Application to amend License DPR-46 changing Tech Specs to incorporate NUREO-0737 items per 830110 Generic Ltr 83-02 PILANT.J M Nebraska Public Power District 83/04/27 VASSALLO, D D Operating Reactors Branch 2 3pp 18283 173 24X Fiche 50-298.83/04/27,8305020449
- --8305020464 Proposed Tech Specs changes re Generic Ltr 83-02 concerning NUREG-0737 items * Nebraska Public Power District 83/04/27 3pp 18283 176 24% Fiche 50-298,83/04/27,8305020449
- B305030393 Confirms commitment to inform regional administrator of any changes in NPDES permit & of violations of permit PILANT, J M Nebraska Public Power District 83/04/27 VASSALLO. D B Operating Reactors Branch 2 Ip 18308 176 24X Fiche 50-278. 83/04/27, 8305030393
- B305030554 Forwards "Wetwell-Drywell Vacuum Breaker Valves Long-Term Program Structural Evaluation" PILANT.J M Nebraska Public Power District B3/04/29 VABSALLO, D B Operating Reactors Branch 2 2pp 18306 126 24X Fiche 50-298,83/04/29,8305030554
- --- 8305030564 "Hetwell-Drywell Vacuum Breaker Valves Long-Term Program Structural Evaluation" * EDS Nuclear, Inc. 04-0640-0062 ROI 83/04/30 12pp 18306 128 24X Fiche 50-298,83/04/29,8305030554
- 8305050113 Application to amend License DPR-46, extending Mark I program completion date for 90 days for weld repair Class II amend fee forwarded PILANT, J M Nebreska Public Power District 83/04/29 VASSALLO, D D Operating Reactors Branch 2 Epp 18341 334 24X Fiche 50-298, 83/04/29, 8305030113
- 8305180026 Forwards Amend 82 to License DPR-46, safety evaluation & notice of issuance & availability Amend modifies fire sysclean water supply, plant staff working hours, reactor protection sys power monitoring sys & snubber listings VASSALLO, D B Operating Reactors Branch 2 83/04/29 PILANT, J M Nebrask Public Power District 2pp 18497 052 24X Fiche 50-298,83/04/29,8305180026
- --8305180039 Amend 62 to License DPR-46.modifying standby gas treatment testing requirements. App J testing. scram discharge vol. fire protection sys clean water supply, snubber listings & reactor power sys power monitoring sys VASBALLO. D B Operating Reactors Branch 2 83/04/27 71pp 18497 054 24X Fiche 50-278, 83/04/29, 8305180026
- ---8305180050 Bafety evaluation supporting Amend 82 to License DPR-46 * Office of Nuclear Reactor Regulation, Director 83/04/29 ilpp 18497 125 24X Fiche 50-298.83/04/29.8305180026
- --8305180071 Notice of issuance & availability of Amend 82 to License PR-46 VABBALLO,D B Operating Reactors Branch 2 83/04/29 2pp 18497 136, 24X Fiche 50-298.83/04/29.8305180026
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to QLs Byc list enci EISEMHUT, D. Ø. Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 30pp. 18441 120 24X Fichs. 30-000: 83/05/02, 8305020455
- 8305160337 Forwards Amend 83 to License DPR-46, safety evaluation & notice of issuance & availability Amend lowers MSIV low reactor water isolation setpoint to Level 1 & opening & closing setpoints of two safety relief valves BIEOEL.B Operating Reactors Branch 2 83/03/04 PILANT.J M Nebrask Public Power District 2pp 18471 306 24X Fiche 30-298,83/05/04,8305160337
- --8305160340 Amend 83 to License DPR-46, revising MSIV low reactor water level isolation setpoint, opening & closing setpoints of two safety relief values & protective instrumentation section VASSALLO, D B Operating Reactors Branch 2 83/05/04. 20pp 18471-308 24X Fiche 50-298.83/05/04.8305160337
- --8305160341 Bafety evaluation supporting Amend 83 to License DPR-46 * Office of Nuclear Reactor Regulation, Director 83/05/04 5pt 18471 328 24% Fiche 50-298,83/05/04.8305160337
- --8305160342 Notice of issuance & availability of Amend 83 to License PPR-46 VASSALLO,D B Operating Reactors Branch 2 83/05/04 2pp 18471 333 24X Fiche 50-278.83/05/04.8305160337

- 830518054/ Forwards order extending completion data for installation of plant mods needed to comply w/NUREG-0661 Extension granted until 90 days after start or Fuel Cycle 9 (1983 refueling outage)
 VASSALLO.D B Operating Reactors Branch 2 83/05/05 PILANT. J M Nebraska Public Power District 2pp 18505 081 24X
 Fiche 30-298/83/05/05/8305180547
- --8305180548 Order modifying 810113 & 820915 orders, extending completion date for installation of plant mods needed to comply w/NUREQ-02661 Extension granted until 90 days after start of Fuel Cytle 9 (1983 refueling outage)
 PURPLE.R A Division of Liconsing 83/05/05 Nebreska Public Power District 4pp 18505 086 24% Fiche 50-298,83/05/05,8305180547
- B305230242 Forwards safety evaluation of util B20831 submittal reprocedure verification b design mod per NUREG-0737. Item II K 3 22, "Automatic Switchover of RCIC Switten" Requirements met VASSALLO, D B Operating Reactors Branch 2 83/05/05 PILANT, J M Nebraska Public Power District Spp 18543 232 24X Fiche 50-298.83/05/05.8305230242
- B305090659 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D G Division of Licensing B3/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 50-000.83/03/09.B305090659
- 8305260170 Forwards request for add1 info re NUREQ-0737.1tmm 11 K 3 28 on qualification of automatic depressurization sys accumulators Response requested within 45 days VASSALLO,D B Operating Reactors Branch 2 83/05/11 PILANT,J M Nebraska Public Power District 4pp 18648 113 24X Fiche 50-298.83/05/11.8305260170
- 8305250266 Forwards Draft 7 of Rev 3 to NUREG-0742. "Std Radiological Effluent Tech Specs for PWRs." as guidance in developing final submission of radiological effluent Tech Specs Tech Specs requested within 60 days W/o encl VASBALLO.D B Operating Reactors Branch 2 83/05/18 PILANT.J H Nebraska Public Power District 2pp 18595 336 24X Fiche 50-298.83/05/18.8305250266
- 8305260300 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0/37. Item II K 3 45. "Depressuritation W/Other Than Automatic Depressurization Sys " Alternative modes would not contribute to plant safety No mods lequired VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M Nebraska Public Power District 2pp 18629 316 24X Fiche 30-298.83/05/18,8305260300
- 8305270369 Responds to 10CFR50 49(g), "Environ Qualification of Electrical Equipment Important to Gafety for Nuclear Power Plants" & NRC 830408 ltr requests List of equipment important to safety encl
 PILANT, J M Nebrask Public Power District 83/05/20
 VASSALLO, D B Operating Reactors Branch 2 36pp 18642 136 24X Fiche 30-299,83/05/20,8305270369
- Q Inspection reports, JE Bulletins & correspondence
- 8212050385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Past 830103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24% Fiche 50-000,83/04/15,830/3040021
- B303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Bvc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24% Fiche 50-000,83/04/25,8303040025

DOCKETED ITEMS

- M040026 IE info Notice 83-24. "Loose Parts in Secondary Side of team Generators at PWRs " Svc list encl URDANIE L Division of Energency Preparedness > Engineering esponse (Past 830103) 83/04/28 Consolidated Edison Co of New ork, Inc 119pp 18382 047 24x Fiche 50-000.63/04/28,8303040026
- 3040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High emp Trip Setpoint Adjustment ' Svc list enc; ORQANLE L Division of Emergency Preparednoss & Englineering esponse (Post 830103) 83/04/28 Consolidated Edison Co of New ork, Inc 1189p 16382 165 24% (iche 50-000.83/04/28,8303040027
- 5170329 Forwards IE Insp Rept 50-298/83-03 on 830328-0401 No oncompliance noted office of Director 83/04/29 PILANT, J M ebraska Public Power District 2pg 18465 144 24X iche 50-278,83/04/29,8305170329
- 305170333 IE Insp Rept 50-298/83-03 on #30328-0401 No noncompliance noted Major areas inspected training % surveillance REDAND.R T, MESTERMAN.T F Region 4. Office of Director 83/04/28 7pp 18465 146 24X Fiche 30-278.83/04/29,8303170329
- 040028 [E Info Notice 83-26, "Failure of Safety/Relief Valve scharge Line Vacuum Breakers" Svc list enc!
 RDAN.E L Division of Fmergency Preparedness & Engineering sponse (Past 830103) 83/05/03 Consolidated Edison Co of New 122pp 18441 170 24x Fiche 50-000,83/05/03,8303040028
- 040030 IE Info Notice 83-27. "Operational Response to Events norming Deliberate Acts Directed Against Plant uipment " Svc list encl RDANLE L Division of Emergency Preparedness & Engineering sponse (Post 830103) 83/05/04 Consolidated Edison Co of New & Inc 112pp 18382 282 24% fiche 50-000,83/05/04,8303040030
- J4003: IE Info Notice 8J-23, "Criteria for Protective Action ommandations for General Emergencies " Svc list encl DAN.E L Division of Emergency Preparedness & Engineering yonse (Post 830103) 8J-05/04 Consolidated Edison Co of New L, Inc 119pp 16441 001 24X Fiche 50-000,83/05/04.8303040031
- 40033 If Info Notice 83-29. "Fuel Binding Caused by Fuel Rack 40033 It Info Notice 83-27, "Fuel binding caused by Foel nath ormation" Svc list encl DAM.E.L. Division of Emergency Preparedness & Engineering ponse (Post 820103) 83/05/04 Consolidated Edison Co. of New k. Int. 115pp 18523 248 24x Fiche 50-000,83/05/06.8303040033
- 40034 IE Info Notice 83-30, 'Misapplication of Generic Emergency rating Procedures (EUP) Guidelines " Svc list encl DAN.E L. Division of Emergency Preparedness & Engineering conse (Post 830103) 83/05/11 Consolidated Edison Co of New Jonse (Post 830103) 83/05/11 Consolidated Edison Co of New k, Inc. 114pp 18524 003 24x Fiche 50-000,83/05/11.8303040034
- 200328 Ack receipt of Apr 1963 mgt appraisal rept written by LRS sultants. Inc Application for withholding requested within days of ltr receipt 3EN, G. L. Region 4, Office of Director 83/05/13 Pilant. J M raska Public Power District 1p 18517 055 24% to 50-298, 83/05/13, 8305200028
- 0040 IE Info Natice 83-31, "Error in ADLPIPE Computer Program "
- Out to this heart list ent?

 AN.E L Division of Emergency Prepaiedness & Engineering onse (Post 830103) B3/05/17 Consolidated Edison Co of New Inc. 114pp 18677 007 24x Fiche 50-000, B3/05/17, B303040040
- 0301 Forwards 1E Insp Rept 50-298/83-05 on 830321-25 No USOL Forwards 1E INSP Rept 50-1476/55-05 (IL USDELL ED.)

 ENG C. Region 4. Office of Director 83/05/23 PILANT, J H
 aska Public Power District 2pp 18626 265 24X

 2 50-278.83/05/23.8305260301
- 260304 IE Insp Rept 50-298/89-05 on 830321-25 No moncompliance ted Major areas inspected security plan implementing ocadures security organization, records & repts & access throi Details withheld (ref 100cFr3) 21)

 ANB.C A . KELLY, J A . WESTERMAN, T F Region 4. Office of rector 83/03/20 ip 18626 267 24X Fiche 50-278,83/05/23,0526/30)
- 0046 IE Info Notice 83-93. "Nonrepresentative Sampling of aminated 011" Svc list encl
 N.C L Division of Emergency Preparedness & Engineering
 ones (Post 830103) 83/05/26 Consolidated Edison Co of New
 Inc 194pp 18647 007 24x Fiche 50-000,83/05/26.8303040046

- S Reportable occurrences. LERs & related correspondence
- 8305060574 Forwards LER 83-003/03L-0 Detailed event analysis submitted THOMASQN, P V Nebraska Public Power District 83/04/29 COLLINS, J T Region 4. Office of Director 2pp 18349 005 24X Fiche 50-298, 83/04/29, 8305060574
- -8305060584 LER 83-003/03L-O on 830403, indication & control power for reactor bldg exhaust valve HN-260HV failed resulting in valve not automatically closing on isolation signal Caused by burned out lamp Lamp & fuse replaced HIRE.F R Nebraska Public Power District 83/04/29 Region 4, Office of Director ip 18349 007 24X Fiche 50-298,83/04/29, 83080428-4 8305060574
- 8305120433 Forwards LER 83-004/03L-0 Detailed event analysis Submitted
 THOMASON, P. V. Nebraska Public Power District 83/04/29
 COLLINS, J. T. Region 4, Office of Director 2pp 18431 133 24X
 Fiche 30~298, 83/04/29, 8305120433
- ---8305120439 LER 83-004/03L-0 on 830409 during SP 6 1 4 contacts of relaw 917-5A-X7D Failed to open Cause not determined Relaw coil replaced & proper operation verified All ac HFA relaws on easemtial sys will be tested during Spring 1983 outage KRAUSE.R W Nebraska Public Power District 83/04/29 Region 4. Diffice of Director ip 18431 133 24X Fiche 50-298.83/04/29.8305120433
- 8305200344 PNO-IV-83-019 on 830517 indications of intergranular stress corrosion cracking in heat-affected ione of welds in RCS identified Data forwarded to GE for detailed analysis RCS loops inspected DUROIS, D IS.D. WESTERMAN.T F Region 4. Office of Director 83/05/17 18516 233 24% Fithe 50-298.83/05/17.8305200344 10
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8305030523 Requests revs to proposed mode to 100FR50 App R exemption requests re-separation requirements.per 830322 meeting & 830325 & 31 telcons Detailed discussion of revs encl FAY.C N Wisconsin Electric Power Co 83/04/28 DENION,H R Office of Nuclear Reactor Regulation, Director CLARA,R A Operating Reactors Branch 3 27pp 18300 284 24X Fiche \$0-246,83/04/28,8305030523
- 8305110540 Forwards exemption from App R in partial response to 820630 ltr & 820929 & 1011 supple Exemption permits relief from requirements to install fixed suppression sys & fire barriers to separate hydrogen lines from safety equipment CLARK.R A Derating Reactors Branch 3 83/04/28 FAY.C W Wisconsin Electric Power Co Spp 18415 104 24X Fiche \$0-266.83/04/28.8305110540
- --8305110542 Exemption from requirements of 10CFR50, App R. Section III G re fixed fire suppression sys in control room EISENHUT, D G Division of Licensing 83/04/28 Hisconsin Electric Power Co 3pp 18415 107 24% Fishe 50-266,83/04/28, 9705110540
- 8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 to 50-301/82-17 Violation 1 re fire signaling sys testing withdrawn SPESSARD, R L withorson
 BPESSARD,R L. Division of Engineering 83/05/09
 Wisconsin Electric Power Co 2pp 18464 333 24X
 Fiche 50-266.83/05/09.8305170241
- --8305170252 Responds to NRC 821130 ltr re violations noted in IE Insp. Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include add1 performance data Fire protection tests reviewed FAY.C W. Hiscansin Electric Power Co. 83/01/21 KEPPLER, J. Q. Region 3, Office of Director 42pp 18464 335 24x Fiche 50-266.83/05/09.8305170241
- --8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity FAY.C W Wisconsin Electric Power Co 83/02/24 KEPPLER.J G Region 3, Office of Director 3pp 18465 015 24X Fiche 50-266.83/05/09.8305170241
- 8305170138 Ack receipt of 830413)tr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts
 50-266/83-05 & 50-301/83-05
 HIND, J A Division of Radiological & Materials Safety Programs
 83/05/10 BURSTEINS Hisconsin Electric Power Co ip 18464 27
 24X Fiche 50-266,83/05/10.8305170138

- --8305170144 Responds to NRC B30314 ltr re violations noted in IE Safeguards Insp Repts 90-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 10CFR73 21)
 BURSTEIN S Wisconsin Electric Power Co 83/04/13 HIND, J A Division of Radiological & Materials Safety Programs Ip 18466 271 24X Fiche 30-266.83/09/10.8305170138
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law encorement visits Svc list encl
 EISENHUT, D G Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000.83/05/11,8305110034
- 8305200021 Notifies that NUREG-0737, Item III A 2). "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR50," completed Item closed CLARK, R A Operating Reactors Branch 3 83/05/12 FAY, C W Hisconsin Electric Power Co 3pp 18540 114 24X Fiche 50-266,83/05/12,8305200021
- 8305270241 Documents agreement per 83051/ conference call re timing requirements for notification of state & local agencies for unusual event or alert, per IE Insp Repts 50-266/83-01 & 30-301/83-01 Procedure to be initiated by 830701 FAY.C W Misconsin Electric Power Co 83/03/23 KEPPLER, J G Region 3. Defice of Director 1p 18637 161 24X Fiche 50-266.83/05/23.8305270241

Q Adjudicatory correspondence

- 8305020438 Brief opposing Wisconsin Environ Decade exceptions to ASLB B30204 initial decision authorizing full-scale sleeving Exceptions waived for failure to brief or arguments w/o merits CHURCHILL.B W Hisconsin Electric Power Co CHURCHILL.B W Shaw, Pittman, Potts & Trowbridgs 83/04/27 Atomic Safety and Licensing Appeal Panel 32pp 1828f 111 24X Fiche 50-266, 83/04/27.8303020438
- 8305100314 Brief in opposition to Wisconsin Environ Decade 830214 appeal of ASLB 830204 memorandum & order LBP-83-4 ASLAB should reject exceptions not briefed & affirm ASLB order resteam generator tube rupture W/Certificate of Svc BACHMANN.R Q Hearing Branch 1 83/05/09 Atomic Safety and LCCHMSING ADDRESS ASSESSED 183/05/09.8305100314
- 8305270558 Requests info re date time & location for Commission meeting on emergency operations facility location Leave to address Commission requested FAY.C W Hisconsin Electric Power Co 83/05/20 CHILK.S J Office of the Secretary of the Commission lp 18646 154 24X Ficha 50-266.83/05/20.8305270558
- P Operating license stage documents & correspondence
- 8305230724 Forwards estimated annual regulatory & nonregulatory expenditures in 830208 ltrs re cost of bacyfitting Combined capacity of facilities is 994 MMe
 BURSTEIN 8 Wisconsin Electric Power Co 83/02/25 TOURTELLOTTE.J
 Regulatory Reform Task Force 3pp 18542 269 24X
 Fiche 50-266.83/02/25.8305230724
- B305020272 Forwards Affidavit AM-80-27 in support of request to withhold proprietary info re effect of radiation on insulating matis in Westinghouse medium mator per 10CFR2 790 re encl util draft 830413 ltr WIESEMANN, R A Westinghouse Electric Corp B3/04/13 THOMAS, C G Division of Licensing 9pp 18277 196 24X Fiche 50-266,83/04/13,830800072
- --8305020272 Nonproprietary version of "Effect of Radiation on Insulating Matls Used in Westinghouse Medium Motors " BARTKO, J Hestinghouse Electric Corp 71-102-RADMC-R1 71/04/10 39pp 18277 205 24% Fiche 50-266,83/04/13,8305020272
- 8305020128 Forwards safety evaluation of util preferred ac power sys conformance to QDC 17 Power sys do not fully meet intent of QDC 17 since sys could be automatically disconnected from 4,160-volt safeguards buses in worst case accident loads NORELIUS.C. E Division of Project & Resident Programs 83/04/25 EISENHUT.D Q Division of Licensing 3pp 18278 220 24X Fiche 50-266.83/04/25.8305020128
- --8305020137 Safety evaluation of util preferred ac power sys conformance QDC 17 Proximity of low voltage transformers does not fully meet QDC 17 requirements for physical separation, but deluge sprinkler sys adequate

 W NRC No Detailed Affiliation Given 83/04/25 8pp
 18278 223 24X Fiche 50-266,83/04/25,8305020128

- 8305060001 Forwards EGCG summary of discussion re radiological effluent Tech Specs during 820602-03 plint visit Final diaft of ploposed radiological effluent Tech Specs / offsite dose calculation manual should be developed uithin 60 days CLARK, R & Operating Reactors Branch 3 83/04/25 FAY, C W Misconsin Electric Power Co 45pp 18393 263 24% Fiche 50-266.83/04/25.8305060001
- 8305090946 Lists drawings needed to review inservice testing program. Two sets of full size drawings requested CLARK.R A Operating Reactors Branch 3 83/04/2/ FAY.C W Hisconsin Electric Power Co Jpp 18381 205 24% Fiche 50-266.83/04/27,8305090546
- B305110028 Informs of Class I >> III fee classification for B30324 application for Tech Spec changes re auxiliary feedwater sys operability (Overpayment for 79026 application for administrative changes will be applied toward current fees MILLER.W O License Fee Management Branch B3/04/27 FAY.C W Wisconsin Electric Power Co 2pp 18421 313 24X Fiche 50-266.83/04/27,8305110028
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Syc list encl EISENWUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York inc 50pp 18441 120 24X Fichs 50-000,83/05/02,8305020455
- B305060408 Requests extension of deadline for environ qualification of equipment until B40330 for Unit 2.4 B41(01 for both units for smylron qualification of all 10CFR30 49(b)(3) equipment items
 BURSTEIN.8 Wisconsin Electric Power Co B3/05/04 DENTON.H R
 Office of Nuclear Reactor Regulation, Director CLARK.R A
 Operating Reactors Branch 3 3pp 1B348 210 24X
 Fiche 30-266.83/05/04.8305060408
- B305110075 Remits license amend approval fee for temporary clarification of Tech Specs re auxiliary feedwater sysoperability BURSTEIN, B. Wisconsin Electric Power Co. 83/05/04 DENTON-H R. Office of Nuclear Reactor Regulation, Director MILLER, W.O. Licen Fee Management Branch 1p. 18408-109 24X Fiche 30-266, 83/05/04, 8305110075
- 8305110181 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 91 re limiting conditions for operation requiring both RRR loops be operable unless reactor sys is in refueling shutdown condition BURSTEIN.S Wisconsin Electric Power Co 83/05/04 DENTON, H R Office or Nuclear Reactor Regulation. Director 3pp 18407 122 24X Fiche 50-266,83/05/04,8305110181
- ---8305i10187 Tech Spec Change Request 91 re limiting conditions for aperation requiring both AHR loops be operable unless reactor sys is in refueling shutdown condition # Altscensin Electric Power Ca 83/09/04 App 18407 123 24X Fiche 50-266,83/05/04,8305110181
- B3D3110201 Forwards addl fees associated w/Tech Spec Change Request 69 to allow repair of degraded steam generator tubes by sleeving BURBTEIN,S Wisconsin Electric Power Co B3/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director DIGGS,R M Licensum Fee Management Branch ip 1840/111 24X Fiche 50-266,83/05/04,8305110201
- 8305120495 Fowards 'Amends 73 % 78 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends allow temporary isolation of shared motor driven auxiliary feedwater pumps COLBURN, F G Deprating Reactors Branch 3 83/05/04 FAY.C W Hisconsin Electric Power CC 4pp 10:440 214 24X Fichs 50-266,83/05/04,8305120495
- --8305120498 Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, allowing temporary isolation of shared motor driven auxiliary feedwater pumps for unit during startup, shutdown & surveillance testing of other unit CLARK, R A Operating Reactors Branch 3 83/05/04 App 18440 218 24X Fiche 30-226.83/05/04.8305120499
- --9305120502 Safety evaluation supporting Amends 73 \$ 78 to Licenses DPR-24 & DPR-27, respectively

 * Office of Nuclear Reactol Regulation, Director 63/05/04 2pp 18440 224 24X Fitche 50-266, 83/05/04, 8305120495
- --8305120505 Notice of issuance & availability of Amends 73 & 78 to Licenses DPR-24 & DPR-27.respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/04 2pp 18440 226 24% Fiche 50-266.83/05/04.8305120495

- 8305130007 Updates progress in meeting schedular commitments per NRC 830314 order re implementation of post-TMI Action Item II F 1, "AddI Accident Monitoring Instrumentation "FAY.CR Wisconsin Electric Pawer Co 83/03/06 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 3pp 18436-341 74X Fiche 50-266.83/03/06.8305130009
- 8305090659 Generic Ltr 83-20 to all operating reactor licenses & bolders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISCNHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627 153 24% Fiche 50-000,83/05/09,8305090659
- 8305170619 Forwards approved exemption dtd 830509 for schedular requirements for installation of RCS high point gas vents allowing delay in installation of sys until 840104 CLARK,R A Operating Reactors Branch 3 83/05/09 FAY.C W Wisconsin Electric Power Co 3pp 18497 008 24X Fiche 30-301,83/05/09.8305170619
- --8303170645 Exemption from schedular requirements for installation of RCS high point gas vents allowing delay in installation of sys util 840101
 PURPLE, R A Division of Licensing 83/05/09 Wisconsin Electric Power Co 4pp 18497 011 24X Fiche 50-301,83/05/09, 8305170619
- 8305240131 Informs that piping & instrumentation diagrams requested in 830427 ltr re inservice testing program will be forwarded under separate cover FAY.C W Wisconsin Electric Power Co 83/05/19 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 ip 18549 008 24X Fiche 50-266.83/05/19.830524013i
- 8305240497 Forwards list of electric equipment important to safety to be environmentally qualified at facilities Info duplicates 811009 response per IE Builatin 79-015-w/listed exceptions FAY.C W Wisconsin Electric Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 29pp 18571 360 24X Fiche 30-266.83/05/20.83005240497
- Q Inspection reports, IE Bullatins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exchange Chemical Reaction " Svc list enc!
 TAYLOR-J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 317 24% Fishe 30-000.83/03/21,8212060385
- 8303040021 IÉ Info Notice 83-21. "Defective Emergency Use Respirator " Svc list encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 630103) 63/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 30-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 8vc list and
 JORDAN,F L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830:03) 83/04/25 Consolidated Edison Co of New York, Inc 1170p 1838: 291 24X Fishe 30-000.83/04/25.8303040025
- 8305120456 Forwards IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 & notice of violation No raply to Item 2 of notice of violation required SHAFER,W D Region 3, Office of Director 83/04/25 BURSTEIN,S Wisconsin Electric Pawer Co 2pp 18431 029 24X Fiche 50-266,83/04/25,8305120456
- --8305120463 Notice of violation from insp on B30201-0331 BHAFER:W D Region 3. Diffice of Director 83/04/25 1p 18431 031 24% Fiche 90~266.83/04/25, B30312045
- --8305i20468 IE Insp Repts 50-266/83-04 & 30-301/83-04 on 83020i-033I Noncompliance noted personnel failed to check out when exiting containment per Procedure HP 2 4 & two Eberline Model DAI-6CC area radiation monitors not labeled HAQUER L FITZPATRICK, B. JACKIN, IN Region 3, Office of Director 83/04/22 9pp 1843t 032 24% Fiche 50-266,83/04/25,8305120456

- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 30-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN.E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc #12pp 18382 282 84X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies" Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24x Fiche 50-000,83/05/04,8303040031
- 8305:20408 Submits addi response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Mechanical corrections installed w/exception of two corrections requiring welding to RHR piping BURSTEIN S Wisconsin Electric Power Co 83/05/04 KEPPLER, J Q Region J. Office of Director 2pp 18431 150 24X Fiche 50-266,83/05/04,8305120408
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303200229 Clarifies position re maint & testing program for HVAC filter units not controlled by Tech Specs & for respirator fitting program, per IE lnsp Repts 50-266/83-03 & 30-301/83-03 dtd 830216 although no noncompliance noted FAY.C W Wisconsin Electric Power Co 83/05/06 KEPPLER, J G Region 3, Dffice of Director Spp 18317 102 24X Fiche 50-266,83/05/06,8303200229
- 8305170241 Ack receipt of 830121 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation i re fire signaling sys testing withdrawn SPESSARD, R L Division of Engineering 83/05/09 BURSTEIN, S Hisconsin Electric Power Co 2pp 18464 333 24X Fiche 30-266.83/05/09.8303170241
- --8305170252 Responds to NRC 821130 itr re violations noted in IE Insp Repts 30-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include addit performance data fire protection tests reviewed FAY.C W Misconsin Electric Power Co 83/01/21 KEPPLER.J G Region 3. Office of Director 42pp 18464 335 24X Fiche 50-264,83/05/09,8305170241
- ---8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity FAV:C H Misconsin Electric Power Co 83/02/24 KEPPLER, J G Region 3, Office of Director 3pp 18465 015 24X Fiche 50-286, 83/05/09, 8305170241
- 8305170138 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Bafaguards Insp Repts 50-266/83-05 & 50-301/83-05 HIND, J A Division of Radiological & Materials Safety Programs 83/03/10 BURSTEIN, S Wisconsin Electric Power Co ip 18466/270 24X Fiche 50-266.83/05/10.8305170138
- --8305170144 Responds to NRC 830314 1tr re violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 100cR73 21) BURSTEIN/S Wisconsin Electric Pawer Co 83/04/13, HIND, J A Division of Radiological & Materials Safety Programs ip 18466 271 24X Fiche 50-266, 83/05/10.8305170138

- 8303040034 IE Info Notice 83-30, "Hisapplication of Generic Emergency Operating Procedures (EOP) Outdelines 'Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Convolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 - Save list encl

 JURDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/05/19 Consolidated Edison Co of New

 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B305240380 Confirmatory action itr re NRC B30314 order specifying certain TMI action items as complete or completion dates noted Item II F 1 1, "Noble Gas Effluent Montior," complete, however, main steam line monitors not operational KEPPLER, J @ Region 3. Office of Director 83/05/20 BURSTEIN, S Wisconsin Electric Power Co ip 18575 072 24X Fichs 50-266,83/05/20,8305240380
- B305270241 Documents agreement per B30517 conference call re timing requirements for notification of state & local agencies for unusual event or alert, per IE Insp. Repts 90-266/B3-01 & 30-301/B3-01 Procedure to be initiated by B30701 FAY, C W Misconsin Electric Power Co 83/05/23 KEPPLER, J G Region 3. Office of Director ip 18637 161 24X Fiche 50-266.83/05/23,8305270241
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDANIE L Division of Emergency Pregaredness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 90-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

- B305160169 Forwards monthly operating repts for Apr 1983 FAY.C W Wisconsin Electric Power Co B3/05/10 NF Detailed Affilation Olven tp 18446 073 24X Fiche 50-266.83/05/10,8305160169 NRC - No
- --8305160171 Monthly operating repts for Apr 1983 AY.C W Wisconsin Electric Power Co 24X Fiche 50-266,83/05/10,8305160169 83/05/09 900 18446 074
- 8 Reportable occurrences. LERs & related correspondence
- B305030275 Forwards LER B3-002/01T-0 FAY,C W Wisconsin Electric Power Co B3/04/26 R Region 3. Office of Director 1p 18300 084 24X Fiche 50-301,83/04/26,8305030275 KEPPLER, J G
- --8305030280 LER 83-002/01T-0 on 830412 during eddy current exam of steam generator tubes, 16 tubes in steam generator A & 2 tubes in steam generator B had indications greater than Tech Specs Caused by corrosion Tubes will be repaired FAY.C W Wisconsin Electric Power Co 83/04/26 Region 3. Office of Director 6pp 18300 085 24X Fiche 50-301.83/04/26.
- 8305130034 NPDES noncompliance notification on 830429, daily max pH 303130034 NPDEB noncompliance notification will include review of sampling & analysis techniques, insp of treatment equipment & review of operator logs
 FAY, C W Wisconsin Electric Power Co 83/05/05 Wisconof 2pp 18436 208 24X Fiche 50-266,83/05/05,8305130034
- 8305240331 LER 83-006/03L-0 on 830419 time delay setpoint of contact from time delay relay 2-TDRC/AO6 & 4.160-voit degraded grid voltage relay 2-275/AO6 set above Tech Spec_limit Caused by Voltage relay 2-2/3/ADA set above list have the bumping or mispositioning time set knob M/830510 ltr PAY.C W Wisconsin Electric Power Co 83/05/10 KEPPLER, J G Region 3, Office of Director 3pp 18575 [13 24X Fiche.30-301,83/05/10,830524033]
- 8305240350 LER 83-005/01T-0 on 830428, body-to-bonnet leak on A loop RTD 105240330 LER 83-005/011-0 on 830428; body-to-bonnet leak on A 1-bypass isolation valve RC-559A & boric acid wastage of four studs discovered Leakage caused stud wastage Studs & nuts replaced & valve on other loop examined M/630511 ltr FAY: C W Wisconsin Electric Power Co 83/05/11 KEPPLER: J Q Region 3. Office of Director 4pp 18574 071 24X Fiche 50-301:83/05/11,8305240350
- 8305190226 Followup to 830331 NPDES noncompliance notification On 830316 & 17, retention pond discharge (Sample Point 501) exceeded pH limit Caused by carryover of lime from water treatment sys FAY.C W Wisconsin Electric Power Co 83/05/12 Wiscons of. 2pp 18500 202 24X Fiche 50-266,83/05/12,8305190226.

- 8305240417 LER 83-003/01T-0 has been cancelled FAY,C W Wiscomain Electric Power Co 83/05/12 K Region 3, Office or Director 2pp 18573 352 24X Fiche 50-301.83/05/12.8305240412 KEPPLER, J G
- 8305240002 PNO-111-83-037 on 830509, Region 111 radiation specialist JUS240002 PNU-111-83-037 on 830509. Region [1] radiation spec learned that main steam line noble gas monitors not yet installed per 830314 commitment date Ofc of Investigation investigating failure Monitors to be installed by mid June LOVENDALE,P. PAPERIELLO. C. Region J. Office of Director 1p 18549 138 24X Fiche 50-266.83/05/18,8305240002 83/05/18
- 8305240379 NPDCs noncompliance natification on 830429.pH of retention pond discharge found above limit Caused by deminerallited makeup water treatment sys problems re undissolved line carrying through to pressure filter sys FAY.C W. Wisconsin Electric Power Co. 83/05/18 Wisconsin, State of
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3 F Security, medical, emergency & fire protection plans
- 8305270456 Forwards 1E Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted MANCE/H C Division of Project & Resident Programs 83/03/28 HANCOCK, J A Fiorida Power Corp 2pp 18644 163 24X Fiche 50-302,83/03/28,8305270436
- --8305270466 IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted Major area inspected emergency preparedness B3/03/28 | 11pp | 18644 165 | 24% Fiche 50-302,83/03/28,8305270456
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISEMNUT.D 0 Division of Cicensing B3/03/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.B305110034
- 8305270209 Forwards 1E Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted
 DANCE.H C Division of Project & Resident Programs 8
 WILQUS.W S Florida Power Corp 2pp 18637 314 24X
 Fiche 50-302.83/05/25.8305270209
- --8305270212 IE Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted Major areas inspected site orientation, review of security plan & security organization-mgt Details withheld (ref 10CFR73 21) MOORE, D.E., URYC. B. Region 2, Office of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Sofety 83/05/24 2pp 18637 314 24% Fiche 50-302.83/05/23,8305270209
- J Insurance & indemnity information
- B305040204 Forwards Encorsements 58 & 44 to NELJA Policy NF-195 & MAELU Policy MF-91, respectively DUCK, J.R. Marsh & McLennan, Inc. 83/04/29 BALTZMAN, J. Assistant Director for State & Licensee Relations 3pp. 18323 214 Fiche 50-302,83/04/27,8305040204
- 8305190022 Forwards Endorsements 59 & 45 to NELIA Policy NF-195 & MARLU Policy MF-71, respectively
 DUCK, J R Marsh & McLennan, Inc 83/05/12 SALTZMAN, J Assistant
 Director for State & Licensee Relations 3pp 18502 036 24X Fiche 50-302,83/05/12,8305190022
- P Operating license stage documents & correspondence
- 8303280319 Forwards order confirming licensee commitments on post-TMI-related issues Order based on commitments contained in util responses to NRC Generic Ltrs 82-03 & 82-10 870LZ-JF Operating Reactors Branch 4 83/03/14 HANCOCK, J A Florida Power Corp 3pp 17713 234 24x Fiche 50-302,83/03/14, H303280319
- --8303280325 Order confirming licenses commitments on gost~TMI-related PURPLE, R.A. Assistant Director for Licensing 83/03/14 Florida Power Corp. 10pp. 17713 237 24x Fiche 50-302,83/03/14, B3032B0319

- 8305230393 Forward, analysis of estimated backfitting costs per 830208 itr Estimated 4174 million spent for backfitting Backfitting expenditures will average 40% of annual expenditures from 1977 through 1985 HANCOCK J A Florida Power Corp 63/03/25 TOURTELLOTTE. J Regulatory Reform Task Force 2pp 18943 358 24% Fiche 50-302,83/03/25,8305230393
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLGTTE, J. Regulatory Reform Task Force 83/04/ll PALLADINO.N J. Commissioners 2pp 18542 272 24X Fiche 30-000.83/04/11.8305230720
- 8305120037 Forwards generic safety evaluation supporting continued operation of PWRs w/Dresser primary safety valves Safety valve ring settings acceptable STQLZ.J F Decreting Reactors Branch 4 83/04/28 WILGUS.W S Florida Power Corp 2pp 18443 24P 24X Fiche 50-302.83/04/28.8305120037
- 8305030036 Proposes mad design to fulfill monthly testing requirement of IEEE-279-1971 consistent w/testing for first & second level undervoitage relay protection sys Monthly relay bench calibr test will verify absence of relay setpoint drift HESTATEP.G R Florida Pawer Corp. 83/04/29 STDL7.J F Operating Reactors Branch 4 2pp 16300-356 24 (Fiche 50-302.83/04/27. 8309030036
- 8305030050 Advises that justification for continued operation will be included in 830520 submittal per 830223 ftr re environ qualification of electrical equipment in response to 830323 ftr Facility presently shut down for refueling WESTAFER. OR Florida Power Corp 83/04/29 STGLZ. J.F. Operating Reactors Branch 4 ip 18300-351 24% Fiche 50-302.83/04/29. 8303030050
- B305090462 Forwards BLW "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits," per 830331 commitment WESTAFER G R Florida Power Corp 83/04/29 STOLZ. J F Operating Reactors Branch 4 lp 18362 153 24X Fiche 50-302 83/04/29, 8303090462
- --8305090464 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits "

 + Batcock & Wilcor Co 77 | |40899-01 83/04/29 29pp | 18362 | 154 244 Fiche 50-302,83/04/29,8305090462
- 8305200378 Submits response to NRC 830222 ltr re stemption from 10CFR50 44(c)(3)(iii), "Reactor Vessel Head Heat" Interim elemption extending implementation deadline requested prior to restart from refueling outage scheduled for 830707 WESTAFER, G.R. Florida Power Corp. 83704/29 EISENHUT.D.G. Division of Licensing. 3pp. 18518-106. 24x Fishe 50-302,83704/29,8305200378
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensoes re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EIGENHUT.D G Division of Licensing 83/05/02 Consolidated Edicor Co of New York, Inc. 50pp 1844; 120 74X Fiche 50-000,83/05/02,8305020455
- B305040365 Notification of B30504 meeting w/B&H Duners Group in Osthosda.MD to discuss core barrel failure at Rancho Soco & Crystal River 3, future plans for resolving problem & justification for continued operation MINER.5 Operating Reactors Branch 4 B3/05/02 STOLZ, J Operating Reactors Branch 4 B3/05/02 STOLZ, J Fiche 50-000.83/05/02.8305060365
- 8305130002 Notifies of preliminary plan to implement 820104 amend to regulation re hydrogen recombiner requirement scheduled for Spring 1985 refueling outage External recombiner must be safety-grade to ensure accident survivability WESTAFER. C 8 Florida Power Corp 83,05/06 STOLZ. J F Operating Reactors Branch 4 2pp 18436-327 24% Fithe 50-302,83/05/06. 8305130002
- 8305130012 Advises that preliminary orfsite dose calculation manual (radiological effluent Tech Specs) submitted on 830427 WESTAFERICR R Florida Power Corp 87/05/06 STOLZ, J F Operating Reactors Branch 4 ip 18440 043 24X Fiche 50-302,83/05/06,8305130012
- 8305090639 Generic Ltr 83-20 to all operating reastor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 1862/ 153 24X Fiche 30-000.83/05/09.8305090659

- 8305130067 Advises that util endorses Rev 3 to BAN-10072P & BAW-10154P as response to NUREG-0737. Item II V 3 30. "Revised Small Dreak LOCA Methods to Show Compliance W/100FR50, App K " Work on item will not commence until repts approved by NRC WESTAFER, G R Florida Power Corp. 83/05/09 STOLZ, J F Operating Reactors Branch 4 ip. 18436-245 24X Fiche 50-302, 83/05/09, 2004, 2004, 2004.
- 8305190344 Forwards commitments for qualification of insp.exam & testing & audit personnel to eliminate possible conflicts & misunderstandings
 WESTAFER G R Florida Power Corp B3/05/13 EISENHUT D G
 Division of Licensing 2pp 18300 020 24% Fiche 50-302,83/05/13,8303190344
- 8305240359 Updates suatus of reactor internals bolting problem All upper core barrel bolts will be replaced b backup ultrasonic eram on «urveillance specimen holder tube bolts performed by 830520 Dasis for decisions by plans discussed BAYNARD, P Y Florida Power Corp 83/05/20 STDLZ, J F Operating Reactors Brench 4 2pp 18571 004 24Y Fiche 50-302,83/05/20.
- 8305270092 Forwards "Crystal River Unit 3 Environ Gualification Status." per 10CFR50 49 BAYNARD.P Y Florida Power Corp 83/05/20 STQLZ.J.F Operating Reactors Branch 4 2pp 18639 001 24X Fiche 50-302,83/03/20, 8305270092
- --8305270095 "Crystal River Unit 3 Environ Qualification Status" + NUS Corp 83/05/20 416pp 18639 003 24X Fiche 50-302,83/05/20,8305270092
- Q Inspection reports: JE Bulletins & correspondence
- B303270295 Provides implementation dates for policies & procedures necessary to meet commitment per requirements of ANSI N45 2 9-1974 Three-phase plan developed to resolve deficiencies identified in IE Insp Rept 30-302/82-20 BAYNARD.P Y Florida Power Corp B3/02/16 D'REILLY.J P Region 2, Office of Director 2pp 18641 185 244 Fiche 50-302,83/02/16,8303270295
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fishe 50-000,83/03/21.8212060385
- --8305270464 IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted Major area inspected emergency preparedness exercise HUFFMAN.G N . JENKINB, G R Region 2. Office of Director 83/03/28 Lipp 18644 165 24X Fiche 50-302.83/03/28.8305270456
- 8305270112 Forwards IE Insp Rept 50-302/83-08 on 830307-11 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/04/06 WILGUS.W S Florida Power Corp 2pp 18638 234 24X Fiche 50-302.83/04/06.8305270112
- --8J05270121 JE [nsp Rept 50-302/83-08 on 830307-11 No noncompliance noted Major areas inspected gaseous effluents IE info notices & somiannual effluent & waste disposal rept KAHLE, J B Region 2. Office of Director BARR.K P Division of Emergency Preparedness & Materials Safety 83/03/25 5pp 18638 236 24X Fiche 50-302,83/04/06,8303270112 .
- #305270347 Forwards 1E 1nsp Rept 50-302/83-05 on 830314-18 No noncompliance noted DANCE,H C Division of Project & Resident Programs #3704/06 WILQUE,W S florida Power Corp 2pp 18642 106 24X Fiche 50-302,83/04/06,8305270347
- --B305270354 IE Insp Rept 50-302/83-05 on 830314-18 No noncompliance noted Major areas inspected radiological environ monitoring, including mgt & administrative controls & status review of radiological environ monitoring program CUNNINGHAM, A L , KUZO, G B Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Radiological Safety Programs 83/04/06 Spp 18642 108 24x Fiche 50-302,83/04/06,8305270347

- 8305270499 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IF Insp Rcpt 50-302/82-29 LEWIS.R C Division of Project & Resident Programs 83/04/13 HILOUS.W S Florida Power Corp ip 18644 082 24X Fiche 50-302,83/04/13.8305270499
- --8305270503 Responds to NRC 830210 ltr re violations noted in 1E Insp Rept 50-302/82-29 Disagrees w/violation re log entry for action statements WESTAFER, G R Florida Power Corp 83,03/11 0'REILLY, J P Region 2, Office of Director 4pp 18646 083 24x Fiche 50-302,83/04/13,8305270499
- --8305270509 Forwards IE Insp Rept 50-302/82-29 on 821124-1217 & notice of violation LEWIS.R C Division of Project & Resident Programs B3/02/10 HANCOCK, J A Florida Power Corp 2pp 18646-087 24X Fiche 50-302, 83704/13, 8308270499
- --8305270516 Notice of violation from insp on 821124-1217 * Region 2. Diffice of Director 83/02/16 2pp 18646 089 24X Fiche 50-302.83/04/13.8305270499
- --8305270525 1E Insp Rept 50-302/82-29 on 821124-1217 Noncompliance noted failure to log entry & exit from Tech Spec action statement & failure to maintain functional test manual initiation of reactor bldg isolation function STETKA: T F Region 2, Office of Director BROWNLEE. V L Division of Praject & Resident Programs 83/01/31 11pp 18646 091 24X Fiche 30-302.83/04/13.8305270499
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 90-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enc! JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Past 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305090584 Forwards FR natice granting relief from ASME Code Section XI requirements, per util 830221 & 0314 requests STOLX.J F Operating Reactors Branch 4 83/04/27 WILGUS, W S Fjorida Power Corp 2pp 18367 350 24X Fiche 50-302.83/04/27, 8305090584
- --8305090589 Notice of granting relief from ASME Code Section XI requirements re noirle vessel inservice insp STOLZ.JF Operating Reactors Branch 4 93/04/27 2pp 18367 352 24X Fiche 50-302,83/04/27,8305090584
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Bteam Generators at PWRs " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027
- 8305270247 Ack receipt of 830207 & 0408 ltrs informing NRC of steps taken to correct violations noted in IE Imap Rept 50-302/82-22 DANCE.H C Division of Project & Resident Programs 83/04/29 WILOUS.W S Florida Power Corp ip 18641 210 24X Fiche 50-302.63/04/29.8305270247
- --8305270253 Responds to NRC 830111 ltr re violations noted in IE Insp Rept 50-302/82-32 Corrective actions welder qualification records reviewed & welder qualification status tracking program being developed WESTAFER, 0 R Florida Power Corp 83/04/08 O'REILLY, J P Region 2. Office of Director 2pp 18641 211 24X Fiche 50-302,83/04/29,8305270247

- --8305270258 Responds to NRC 830111 lti iv indiations nated in IE lnsp Rept 50-302/82-32 Corrective actions weller post-qualified on 820803 WESTAFER. G R Fiorida Power Corp 63/02/09 O'REILLY, J P Region 2. Office of Director 2pp 10641 213 24X Fiche 50-302,83/04/29,8305270247
- --8305270260 Forwards IE Insp Rept 50 302/82-32 on 821213-16 & notice of violation pance. H C Division of Project / Resident Programs 83/01/11 HANCOCK, J A Floride Power Corp Ppp 18641 215 24X Fiche 50-302, 83/04/29, 8305270247
- --8305270264 Notice of violation from insp on 821213-16 # Region 2, Office of Director d3/01/11 lp 18641 217 24X Fiche 50-302.83/04/29.8305270247
- --8305270269 IC Insp Rept 50 302/82-32 on 82)213-16 Noncompliance noted failure to meet ASME Code Section IV welder performance qualification requirements ECONOMOS: N Region 2: Office of Director BLAKE, J.J. Division of Emergency Preparedness & Materials Safety 83/01/05 App 18641 218 24X Fiche 50-302,83/04/29,8309270247
- 830304002R IE Info Notice 83-26, 'Failure of Sarety/Relief Valve Discharge Line Vacuum Breakers' Stc list encl JURDAN.E L. Division of Emergency Proparedness 2 Engineering Response (Post 830103) 83705/03 Consolidated Edison Co. of New York, Inc. 192pp 18441 170 244 Fiche 50-000.63705/03.8303040028
- 8303040030 IE Info Notice 83-2/, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co or New
 York, Inc. 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDANIE L Division of Emergency Preparadness * Engineering Response (Post B30103) B3705704 Commonly
- 8303040033 IE Info Notice 83-27, "Fuel Binding Clused by Fuel Rack Deformation " Svc list encl JORDAN E L Division of Emergency Preparadness * Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice 83-30, "Misapplication or Generic Emergency Operating Procedures (EOP) Guidelines 'Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3705/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 247 Fiche 50-000.83/05/11,8303040034
- 8303040040 IE Info Notice 83 31. "Frror in APLPIPE Computer Program "
 Svc list encl
 JORDAN, C. Division of Emergency Proposed 4dness & Engineering
 Response (Post 830103) 83/05/19 (onsolidated Edison Co. of New
 York, Inc. 114pp 18697 009 24% Fiche 50-000, 83/05/19, 8303040040
- 8305270280 Ack receipt of 830429 ltr infoining NRC of steps taken to correct violations noted in IE lnsp Rept 50-302/8J-04
 LEMIS.R C Division of Project & Rosident Programs 83/05/20
 MILOUS.M S Florida Power Corp ip 18642 038 24X
 Fiche 50-302,83/05/20,8305270280
- --8305270312 Informs that util response to NRC 830323 lt; re violations noted in IC Insp Rept 50-302/83-04 will be submitted on 830429 Addl reviews will determine if abnormal & emergency procedural review accomplished & documented WESTAFER, 0 R Florida Power Corp 83/04/25 O'REILLY, J P Region 2, Office of Director ip 18642 039 24X Fiche 50-302,83/05/20,8305270280
- --B309270318 Responds to NRC B30323 ltr re violations noted in IE Insp Rept 50-302/B3-04 Corrective actions plant operating GA manwal, abnormal & emergency pracedules, reviewed & procedure review listing in TDP-203 to be revised by B30601 WEBTAFER, G R Florida Pawer Coip B3704/27 0'REILLY, J P Region 2, Office of Director 2pp 18442 040 24X Fiche 50-302,83/05/20,8305270280
- B305270207 Forwards IF Safeguards Insp Rept 50-302/B3-12 on B30502-06 No noncompliance noted DANCE, HC Division of Project & Resident Programs 83/05/25 WILGUS W S Florida Power Corp Spp 18677 314 24X Fiche 30-302,83/05/25,8305270209

- --8305270212 IE Sareguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted Major areas inspected site orientation; review of Security plan & Security Organization-mgt Details withheld (ref 10CFR73 21) MOORE, D.E. URYC. B. Region 2. Liffice of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety 83/05/24 2pp 18537 316 24X Fiche 50-302, 83/05/25.830570209
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl URRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647 007 24x Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305;30043 Forwards monthly operating rept for Apr 1983 MESTAFER, G R Florida Power Corp 83/05/09 DEVOUND, R C Director's Dffice, Office of Inspection and Enforcement in 18437 026 24x Fishe 50-302,83/05/09.8305130043
- --8305130047 Monthly operating rept for Apr 1983 BUGART.D , CULVER,M W Florida Power Corp 83/05/02 4pp 18437 027 24X Fiche 50-302,83/05/09.8305130043
- S Reportable occurrences, LERS & related correspondence
- 8305230573 Forwards engineering evaluation rept. "Clacks & Leaks in Small Diameter Piping " BROWN.E J Heactor Operations Analysis Branch 83/04/19 SEYFRIT.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19.8305230573
- --B308230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN.E U Reactor Operations Analysis Branch B3/04/19 9pp 18541 343 24X Fiche 50-000.83/04/19.8305230573
- 8305050016 Forwards LER 83-016/01T-0 WESTAFER, G. R. Florida Power Corp. 83/04/27 O'REJLLY, J.P. Regio 2. Office of Director 1p. 18339-059 24X Fiche 50-302,83/04/27, 8305050016
- ~-8305050025 LER 83~018/01T-O on 830413, preliminary repts received from B&W indicating that 51 of 120 upper core barrel bolts ultrasonically tested may be defective Cause unknown Investigation underway Supplemental rept will be written BUFE. J. Florida Power Corp. 83/04/27 Region 2. Office of Director. 2pp. 18339-060 24% Fiche 50-302,83/04/27,8305050016
- 8305110380 Forwards LER 83-017/0}F-0 Detailed event analysis encl HENRY.P C Florida Power Corp 83/05/02 D'REILLY.J P Region 2. Office of Director 2pg 18406 223 24x Fiche 30-302,83/05/02, 8305110380
- --B305110390 LER 83-017/01T-0 on B30418, during surface & visual NDE of reactor head & internals, lifting devices revealed several indications on tripod, turnbuctle & latchblock Caused by improper mfg Indications repaired HUGHES,P G Florida Power Corp 83/05/02 Region 1, Office of Director ip 18406-225 24x Fiche 50-302,83/05/02.8305110380
- 8305130179 Forwards LER 83-019/03L-0 WESTAFER: G R Florida Power Corp 83/05/06 0'REILLY. J P Regio 2. Office of Director Ip 18440 082 24% Fiche 50-302.83/05/06, 8305130179
- --BJ051301BB LER 83-019/03L-0 on 830406, breaker in engineered safeguards (ES) motor control ctr 381 shorted rendering ES bus 38 (480-volt) & associated equipment inoperable Caused by personnel not properly aligning breaker connectors HUOHES, P G Florida Power Corp 83/09/06 Region 2, Office of Director 1p 1840-083 24% Fiche 50-302, 83/05/06, 8305130179
- 8305170399 Forwards LER 83-020/03L-0
 WESTAFER, G R Florida Power Corp 83/05/09 G'REILLY, J P Region
 2. Dffice of Director 1p 18471 221 P4X Fiche 50-302,83/05/09,8305170399
- --B305170402 LER B3-020/03L-0 on B30409, discovered that surveillance interval for fire detection instrumentation in emergency diesel generator & control rooms exceeded by 6 months Caused by procedural inadequacy Procedure SP-411 will be revised BUFE-J L Florida Power Corp B3/05/09 Region 2, Office of Director 2pp 18471 222 24X Fiche 50-302.83/05/09.8305170399

- B305260307 Interim deficiency rept re core support structure bolting Initially reported on B30419 Evaluation of corrective action in progress Next rept will be sent by B31101 CDDK. J W Consumers Power Co B3/05/19 KEPPLER, J G Region 3, Defice of Director 3pp 18625 200 24X Fiche 50-000,83/05/19, B305360309
- --8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
 TAYLOR, J H Babcock & Wilcox Co 83/04/22 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 3pp
 18623 210 24X Fiche 30-000, 83/05/17, 8305260309
- DDCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8305100122 Forwards post-exercise evaluation for Bi0729 exercise, final rept of reexercise on Bi1007 & final exercise rept of B30118 riercise No significant deficiencies cited RRIHM, R W Federal Emergency Management Agency 83/04/08 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 18375 048 24X Fiche 50-295,83/04/08,83010032
- --8305100126 "Zion Nuclear Cenerating Station Small-Scale Joint Emergency Exercise 830118," final rept Federal Emergency Management Agency 83/03/04 71pp 18375 050 24X Fiche 50~295,83/04/08.8305100122
- --9305100131 "Zion Nuclear Power Station Regretcise, WI/Kenosha County (Small-Scale) 811007: "final rept "Federal Emergency Management Agency 82/04/30 32pp 18375 121 24X Fiche 50-295.83/04/08.8305100122
- ~-8303100136 "Post-Exercise Evaluation Exercise of State & Local Radiological Emergency Response Plans for IL & WI (Near Zion Nuclear Power Station) " " Federal Emergency Management Agency 81/07/29 44pp 18375 153 24X Fiche 50-295,83/04/08,8305100122
- B305030076 Releases public version of rev to emergency plan implementing procedure FELTON.J H Davision of Rules and Records 83/04/22 Document Management Branch 1p 18326 103 24X Fiche 50-295,83/04/22
- ---8305030084 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests"
 PLIML.9 Communication Co 83/04/06 DENTON, H R NRC No Detailed Affiliation Given 1p 18326 104 24X
 Fiche 50-295, 83/04/22, 8305030076
- --B305030091 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1. "Emergency Communications Sys & Operational Tests "Procedure Change Request A-83-51 encl NYKIRKJ W Commonwealth Eduson Co 83/03/25 5pp 18326 105 24X Fiche 50-295.83/04/22.8305030076
- 8305030104 Releases public version of rev to emergency plan implementing procedure FELTON,J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18309 354 24X Fiche 50-295,83/04/22, 8305030104
- --8305030114 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure EPIP 320-1. "Activation of Generating Station Emergency Plan Station Group"
 PLIML.G Commonwealth Edison Co. 83/04/06 DENTON:H R NRC No Detailed Affiliation Qiven ip 18309 355 24X
 Fiche 50-275.83/04/22.8305030104
- --8305030117 Public version of Rev 11 to Emergency Plan Implementing Procedure EPIP 320-1. "Activation of Generating Station Emergency Plan Station Group "Procedure Change Request A-83-88 enc! NYKIRK.J W Commonwealth Edison Co 83/03/25 7pp 18309 354 24% Fich 50-295,83/04/22,8303030104
- 8305060673 Releases public version of rev to emergency plan implementing procedure FELION, U Division of Rules and Records 83/04/25 Document Management Branch 1p 18337 326 24X Fiche 50-275,83/04/25, 8305060673

- --8305060679 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 550-2. "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment" Procedure change request encl PLIML-G Commonwealth Edison Co 83/03/09 DENTON, H R NRC No Detailed Affiliation Olven 3pp 18357 327 24X Fiche 50-295,83/04/25,8305060673
- --8305060686 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP 350-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment ' * Commonwealth Edison Co 83/03/08 5pp (8397-330 24X Fichs 50-295,83/04/25,83050606/3
- g305060410 Forwards IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on g30315 & notice of violation Notice of violation withheld (ref 10CFR73 21)
 KEPPLER.J G Region 3, Office of Director g3/05/03 O'CONNOR.J J Commonwealth Edison Co 3pp 18343 239 24x Fiche 50-295, g3/05/03.8305060410
- --8305060418 IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Betails withheld (ref 10CFR73 21) BELANDER. J L Region 3. Office of Director 83/04/29 ip 18343 242 24X Fiche 50-295.83/05/03.8305060410
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D Q Division of Licensing 83/03/11 Consolidated Edison Co of New York, Inc 16pp 18340 095 24X
 Fiche 30-000,83/03/11,8305110034
- 8305240246 Advises that requirements of NUREO-0737. Item III A 2 ;,
 "Emergency Preparedness, Upgrade Emergency Plans to Meet
 App E to IOCFR50." satisfied
 VAROA, 5 A Operating Reactors Branch I 83/05/16 FARRAR, D L
 Commonwealth Edison Co 3pp 16593 303 24X Fiche 50-295, 83/05/16,
 8305240246
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B303160246 Comments on BSMRP risk analysis Risks from seismic events should be analyzed separately from internal events w/results treated independently Unly upper limits need be estimated to determine if risks acceptable

 DAVIS.P.R. Affiliation Unknown DAVIS.P.R. ACRS Advisory
 Committee on Reactor Safeguards 83/04/16 DKRENT, D. ACRS Advisory Committee on Reactor Safeguards 19 18472 001 24X

 Fiche 50-273.83/04/16.8305160246
- P Operating license stage documents & correspondence
- 8303300001 Forwards Amends 82 % 72 to Licenses DPR-39 % DPR-48, respectively & notice of issuance & availability Amends delate nonradiological water quality-related requirements VAROA, S A Decrating Reactors Branch 1 83/03/11 FARRAR, D L Commonwealth Edison Co 3pp 17751 292 24X Fiche 50-295, 83/03/11.
- --8303300002 Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively, deleting nonradiological water quality-related requirements VARQA, S A Operating Reactors Branch 1 83/03/11 61pp 17751 295 24% Fiche 50-299, 83/03/11, 8303300001
- ~~8303300003 Notice of issuance & availability of Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively VAROA, 8 A Derating Reactors Branch 1 83/03/11 2pp 17751 356 24X Fiche 50-295.83/03/11,8303300001
- 8304270053 Agrees w/830311 ltr demonstrating that Tech Specs indicate conditions under which protection sys channels may be bypased during cooldown Review closed VAROA.S A Operating Reactors Branch 1 83/04/12 FARRAR.D L Commonwealth Edison Co 2pp 18254 190 24X Fiche 50-295.83/04/12, 8304270053
- B305180691 Forwards revised order modifying completion dates for NUREO-0737. Items II 8 2. "Plant Shielding." II 8 3. "Post Accident Sampling" & II F 1 2. "Accident Monitoring Instrumentation."

 VARQA: 8 A Operating Reactors Branch 1 83/04/20 FARRAR.D L Commonwealth Edison Co 2pp 18505 181 24X Fiche 50-295.83/04/28.8305180691

- --BJ05180702 Rivised order modifying completion dates for NUREC-0737, ltems II B 2, 'Plant Shielding ' II B 3, 'Post-Accident Sampling' & II F 12, "Accident Monitoring Instrumentation," per Generic Ltrs 82-05 & 82-10 EISENNUT, D C Division of Licensing B3/04/28 Commonwealth Edison Co 9pp 18905 183 24x Fiche 50-295,83/04/28,8305180691
- 8305040317 Responds to NRC request for Jud Junfo re TMI action plan items Matl supports util position that non-afety-related equipment falls outside scope of Franklin Research (tr review Justification not nocessary LENTINE, F G Commonwealth Edison Co 83/05/02 PENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18323 289 244 Fiche 50-295,83/05/02,8305040317
- 8305110144 Ack receipt of 830318 ltr.providing basis for not paying add1 fee for 801107 application re assurance of redundancy in DMR capability Fees include cost of profits staff hours expended to associated contractual sycs Add1 fee due MILLER.W O License Fee Management Branch 83/05/03 LENTINE.F G Commonwealth Edison Co. 2pp. 18421 J47 24% Fishe 50-295.83/05/03.
- 8305090659 Generic Ltr 83-20 to all operating leactor licenses & halders of CPs re integrated scheduling for implementation of plant mode Sox list enc!
 EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000.83/05/09.8305090659
- 8305170218 Forwards response to 830208 \$\(\) 0317 requests for add1 info re NURES-0737, Items II F 1 4. "Containment Pressure Honitor." | II F 1 5. "Containment Water Level Monitor" \$\(\) II F 1 6. "Containment Hydrogen Monitor" \$\(\) II F 1 6. "Containment Hydrogen Monitor" \$\(\) LENTING: FO Commonwealth Edison Co \$\(\) \$\(
- B305240506 Forwards fee for Amends 65 # 67 to Licenses DPR-39 & DPR-48, respectively
 LENTINE, FG Commonwealth Edison Co 83'05/18 MILLER, W D
 License Fee Management Branch 2pp 185/1 264 24x
 Fiche 50-293,83/05/18,8305240506
- 8305240473 Provides addl info re probabilistic safety study, discussed during B30331 NRC site visit Formal decument verification of fan operability not previously required Procedures lovised to include apprability of fan coolers

 LENTINE.F G Commonwealth Edison Co B3/03/19 DLNTUN.H R Office of Nuclear Reactor Regulation, Directol 1p 18549 355 24x
 Fiche 30-295/83/05/19/8305240473
- 830525007/ Forwards Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by 100FR30 49 for Zion Units 1 & 2 "
 LENTINE.F G Commonwealth Edizon Co 83:05,19 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 18389 042 24% Fiche 50-295,83/05/19.830525007/
- --8305280084 Rev 2 to "Environ Qualification of Flectrical Equipment Important to Safety Covered by 10CFR50 49 For Zion Units 1 & 2 "

 * Bargent & Lundy, Inc 83/09/20 7/6pp 18989 046 24% Fiche 50-295,83/05/19.8305280077
- B305310086 Notification of 830614 meeting whitil in Dethesda,MD to discuss util DCRDR program plan OILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658 063 744 Fiche 50-000
- Q Inspection reports. IE Dulletins & currespondence
- 8212060385 IE info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000. 83/03/21.8212060385
- B303040021 IE Info Notice B3-21: "Defective Emergency Use Respirator"
 Byo list encl
 JORDAN: EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co. of New
 York: Inc. 12App. 18435 155 24X Fiche 50-000.83/04/15.8303040021
- 8305100262 Forwards IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 & notice of violation BHAFER:W D Region 3: Office of Director 83/04/20 REED:C Commonwealth Edison Co 2pp 18372 242 24% Fiche 50-295.83/04/20; 8305100262

- --830\$100271 IE Insp Repts 50-295/83-02 / 50-304/83-02 on 830118-0304 Noncompliance noted failure to notify NRC of umplanned release while purging & drawing routine sample MATERS, J. R. HARTMANN, P. L., DUNAWAY, F. R. Region 3 Office of Director 83/04/20 13pp 18372 245 24X Fiche 50-295,83/04/20, 8305100262
- 8303040023 IE Info Natice 83.22, "BWR Safety/Relief Valve Failures " Svc list encl JORDAN: F L |

JARDAN: FL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York: Inc 112pp 18383 089 24% Fiche 30-000.83/04/22.8303040023

- 8303040025 IE Info Notice 83-23. Inoperable Containment Atmosphere Sensing Sys " Svc list encl JRBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 93/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 830317033/ Forwards IE Insp Repts 50-295/83-07 & 50-304/83-04 on 830311.14-17.22-23 & 0407 & notices of violation & deviation PAPERIELLO, C J Region 3, Office of Director 83/04/27 REED. C Commonwealth Edison Co 2pp 18465 274 24% Fiche 50-295,83/04/27.
- ~-8305170344 Notice of violation from insp on 830311,14-17,22-23 & 0407 PAPERIELLO.C J Region 3 Office of Director 83/04/27 2pp 18465 276 24X Fiche 50-295,83/04/27,8305170337
- --830\$170348 Notice of deviation from insp on 830311.14-17.22-23 & 0407 4 Region 3, Office of Director 83/04/27 ip 18465 278 24% fichs 50-295.83/04/27.8305170337
- --8305170353 IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311.14-17. JOST/CUSS IE Insp Repts SU-475/83-05 & SU-304/83-05 on BUSSI:14-17.
 22-23 & 0407 Noncompliance noted contamination surveys of transfer canal workers exhibiting nasal contamination not documented Fuel pool samples not analyzed LOYENDALE.P C . MILLER.D E . GREGER.L R Region J. Office of Director 83/04/25 lipp 18465 279 24X Fiche 50-295.83/04/27.
 8305170337
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New 24% Fiche 50-000, 83/04/28, 8303040026 York, Inc 115pp 18382 047
- 8303040027 IE Info Natice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Betpoint Adjustment " Svc list encl JORDAN.E (Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24x Fiche 50-000,83/04/28.8303040027
- B305020252 EN-B3-028 on B30503 notice of violation ν proposed imposition of civil penalty in amount of \$10,000 to be issued Action based on failure to control access into protected & vital areas & unauthorized entry RDSANO.R Director's Office. Office of Inspection and Enforcement B3/04/28 lp 18277 277 24% Fiche 30-295.83/04/28.8305020252
- 8303040028 IE Info Notice 83-25, "Failure of Safety/Rollef Valve Discharge Line Vacuum Breakers" Svc list entl JURDAN.F L Division of Emergency Preparedness & Engineering Response (Post 630603) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24) Fiche 50-000.83/05/03.8303040028
- 8305040410 Forwards IE Safeguards Insp Hepts 50-299/83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld (ref 10CFR73 21)
 KEPPLERJ G Region 3. Office of Director 83/05/03 O'CONNOR.J J Commonwealth Edison Co. 3pp 18343 239 24% Fiche 50-295.
- --8305060418 |E Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 30500418 JE Safeguards Insp. Mepts 50-279/83-06 & 30-304/83-07 On 8800315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Details withheld (ref 10CFR73 21) BELANGER, J L. MADEDA, T J. CREED, J R. Region 3, Office of Director 80/04/27 lp 18343 242 24X Fiche 50-275.83/05/03, 2005/04/04 8305060410
- 8303040030 IE Info Notice 83-27. 'Operational Response to Events Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JURDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830(03) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030.

- B303040031 IE Info Notice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 90-000, B3/05/04, B303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 8301031 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06.8303040033
- 8303040034 IE Info Natice 83-30, "Misapplication of Generic Emergency
 Decrating Procedures (EOP) Guidelines " S/c list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/11 Canabidated Edison Co of New
 York, Inc 144pp 18524 003 24% Fiche 50-000,83/05/11,8303040034
- 8305200351 Forwards results of investigation on Br-92 source & significance in combinments, per 830216 committal Investigation result of IE Insp Repts 50-295/82-30 & 83/05/17 KE KEPPLER, J G
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " 303040040 It Info Notice 83-31, error in Notice Company of Service Information of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24% Fiche 50-000, 83/03/19, 8303040040
- 8305310095 Forwards responses to violation & deviation noted in IE Insp. Repts 50-295/83-07 & 50-304/83-06 on 830311-0417 Corrective actions personnel whole body count initiated to document farrant on temperature of the first of the f
- 8303040046 IE Info Notice 93-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list enci
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 114pp 18447 007 24x Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305120013 Forwards monthly operating repts for Apr 1983
 GRAEBSER.K L Commonwealth Edison Co 83/05/09 Director's
 Office, Office of Inspection and Enforcement 1p 18423 038 24X Fiche. 50-295, 83/05/09, 8305120013
- --8305120016 Monthly operating repts for Apr 1983 AUSTIN:G Commonwealth Edison Co 83/05/09 11pp 18423 059 24X Fiche 50-295.83/05/09.8305120013
- 8 Reportable occurrences. LERS & related correspondence
- 8305030440 Forwards LER 83-009/03L-0 GRAESSER: K L Commonwealth Edison Co 83/04/25 F Regian 3: Office of Director 19 18306 265 24X Fiche 50-304.83/04/25.8305030440 KEPPLER, J. G.
- --9305030445 LER 83-009/03L-0 on 830324 failed fuel letdown monitor 2RTPR27 found out of tolerance low Caused by electronic instrument drift Radiation monitor recalibr & returned to WILLIAMS.V 8 Commonwealth Edison Co 83/04/25 Region 3. Office of Director ip 18304 266 24% Fiche 50-304.83/04/25.8305030440
- 8305130196 Forwards LER 83-010/03L-0 GRAESSER, K L Commonwealth Edison Co 83/05/10 i Region 3. Dffice of Director ip 18439 353 24X Fiche 50-304.83/05/10.8305130196 KEPPLER, J O
- --8305130211 LER 83-010/03L-0 on 830411, during Purge 0-83-285 of containment, radiation monitors 2RT-PR25, 2RT-PR26 b 1RT-PR26 taken out of svc for maint to calibr instrument Caused by operator error Operator refinstructed in procedures LINDSAY, F J Commonwealth Edison Co 83/05/10 Region 3, Office of Director 1p 18439 354 24X Fiche 50-304, 83/05/10, 8305130196

- 8305240214 LER 83-011/03L-0 on 830412, while purging containment during refueling outage, recorder trace for 2RT-PR25 did not return to normal following source check Caused by sticking of print head due to oxidation on slide-wire N/830311 ltr
 JAKUBAITIST C : GRAESBERIK L Commonwealth Edison Co 83/05/11
 KEPPLER, J G Region 3. Office of Director 2pp 18548 025 24X
 Fiche 50-304, 83/05/11, 8305240214
- 8305310160 LER 83-012/03L-0 on 830426, steam generator 2A steam pressure transmitter 2PT-516 found out of tolerance Caused by instrument drift on transmitter Transmitter recalibr t returned to svc W/830325 ltr CANTWELL.PF, GRAESSER.K L Commonwealth Edison Co 83/05/25 KEPPLER,J G Region 3, Office of Director 2pp 18651 228 24X Fiche 50-304.83/05/25,8305310160

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

- F Security, medical, emergency & fire protection plans
- 830504000/ Releases public version of rev to emergency plan FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch ip 18331 008 24% Fiche 50-305,83/04/25, 8305040007
- --B305040009 Forwards public version of Rev I to emergency plan GIESLER,C W Wisconsin Public Service Corp B3/04/14 DENTON:H R Office of Nuclear Reactor Regulation, Director 18 18331 009 24X Fiche 50-305.83/04/25.8305040007
- --8305040014 Public version of Rev 1 to emergency plan * Wisconsin Public Service Corp 83/04/06 238pp 18331 010 24X Fiche 50-305,83/04/25,8305040007
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUTD O Division of Licensing 83/05/11 Consolidated Edison CD of New York, Inc Lopp 18540 095 24x
 Fiche 50-000,83/05/11,8309110034
- P Operating license stage documents & correspondence
- 8305230728 Forwards listing of regulatory-induced major plant mods & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 79-01.79-02 & 79-14 mods provided
 OIEBLER.C W Misconsin Public Service Corp 83/03/25
 TOURTELLOTTE, J Regulatory Reform Task Force 6pp 18342 263 24X
 Fiche 50-305.83/03/25.8305230728
- 8303230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24% Fiche 50-000,83/04/11,8305230720
- B305040090 Advises that Rev i to XN-NF-79-49-(P) classified proprietary.per B30222 ltr VAROA.B A Operating Reactors Branch i B3/04/22 OIEBLER.G W Wisconsin Public Service Corp 2pp 18328 240 24X Fiche 30-305.83/04/22.8305040090
- 8305030400 Application for Amend 54 to License DPR-43, revising limiting conditions for operation, surveillance requirements & administrative controls OIEBLER, C W Wisconsin Public Service Corp 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18303 182 24X Fiche 50-305,83/04/29,8305030400
- --8305030602 Proposed Tech Specs revising limiting conditions for operation, surveillance requirements 2 administrative controls

 * Wisconsin Public Service Corp 83/04/29 25pp 18303 187 24% Fiche 50-305, B3/04/29, 8305030600
- 8305110050 Forwards Amend 49 to License DPR-43, safety evaluation & notice of issuance & availability Amend changes Tech Specs we RCS leakage, condensate storage tank supply & auxiliary feedwater pump testing GROTENHUIS, M Operating Reactors Branch 1 83/04/29 OIESLER, C W Misconsin Public Service Corp 2pp 18420 324 24X Fiche. 50-305,83/04/29,8305110050
- ---B305110052 Amend 49 to License DPR-43.changing Tech Specs re RCG leakage.condensate storage tank supply & auxiliary feedwater pump testing VAROA,5 A Operating Reactors Branch 1 83/04/29 8pp 18420 326 24y Fiche 50-305.83/04/29.8305110050

- 8305110055 Sarety e aluation supporting whem 44 to License DPR-A3 * Office of Nuclear Reacts: Regulation Director 83/04/29 4p 18426-334 24% Fiche 50-305,83/04/24 8305110056
- 830504066' Forwards request for add1 info or POR"/SV railures & challenges
 VARGA,S A Operating Reactor's Branch (83'05/02 GIESLER,C Wisconsin Public Service Colp. 3pp. 18336-262 24's
 Fiche 50-305/83/05/02/8305040667
- 8305180573 Forward> SER supporting licence responses to NUREO-0737. Items II F 1 4. 'Containment Pressure Nonitor.' II F 1 5. "Containment Matel Lo el Monitor," * II F 1 6. Containment Hydrogen Monitor" VARGA, B A Operating Reactors Branch 1 83/05/02 GIESLER, C W Misconsin Public Service Corp 200 18505 308 24X Fiche 50-305.83/05/02.8305180573
- B305100102 Advises that defective under ultage trip device delivered to Franklin Research Ctr Device probably failed during preoperational testing.possibly due to bottom tripping pin occasionally sticking in downward position GIESLER.C W Misconsin Public Service Corp B3/05/06 VARGA.S A Operating Reactors Branch 1 2pp 183/7 252 24% Fiche 50-305.B3/05/06.B305100102
- 8305100114 Forwards review of existing specs to containment cooling sysoperability No mode required Revised Soction 3 3 "FSF & Auxiliary Sys." will be consistent w.NCRG-0452 % will be submitted as part of Amend 55 GIESLER.C W. Hisconsin Public Service for p. 83/05/06 VARGA 5 A Operating Reactors Branch 1 opp. 183/5 C20 247 Fiche 50-305,83/05/06,8305100114
- 830511000J Forwards evaluation of loss (r discharge back pressure on pump operability re NUREG-0737, Item II F I I 7 B3013I SER, per IE Bulletin 80-04 Operability of auxiliary feedwater pumps after extended operation at sunout flow addressed GIESLER.C W. Hisconsin Public Service Corp. 83703706 VARGA.S A Operating Reactors Branch 1 9pp. 18408 280 24X

 Fiche 50-305.83705706.8305110003
- B305090659 Generic Ltr B3-20 to all operating reactor licensees that ders of CPs re integrated scheduling for implementation of plant mode Svc list end!
 EISENHUT, D. 0 Division of licensing 83/05/09 Consolidated Edison to of New York. Inc. 16pp 18/62/153 244
 Fiche 50-000.83/05/09.8305090659
- 8305170150 Forwards addl info requested in 850902 [ii re PORV/SV failures % challenges Further ref should be made to 820625 response to NUREG-0737, item if D i GIESLER, C W Wisconsin Public Service Colp 83/05/13 VARGA, S A Operating Reactors Branch t 3pp 18/466 c*71 24% Fiche 50-305, 83/05/13, 8305/70150
- B305230300 Application for Amend 47 to License DPR-43 re RCE leakage.
 condensate storage tank supply & auxiliary feedwater pump
 testing
 OIESLER.C W Washington Public Power Supply System B7/05/13
 GROTENHUIS,M NRC No Detailed Affiliation Given 9pp 18539 120
 24X Fiche 50-305,83/05/13,8305230700
- ---8309230309 Proposed changes to Tech Specs ie RCS leakage, condensate storage tank supply & auxiliary readwater pump testing * Washington Public Power Supply System 83/05/13 6pp 18539 129 244 Fiche 50-305,03/05/13,8305230300
- 8305270009 Discusses 6004(0 ltm re use of term operable in Tach Specs which may not address multiple outages Terh Specs will be amended to incorporate STS instructions Proposed amend will be submitted within 30 days of SER.C W. Wisconsin Public Service Corp. 83/05/24 VAROA.S A Gerating Roactors Branch 1 2pp. 18478 350 24X Fiche 50-305.83/05/24.8305270009

Q Inspection reports IE Bulletine * currespondence

- 8212060395 IC Info Notice 83-14, "Dewatered Spent ion Exchange Resin Susceptibility to Eiothermic Chemical Realtion ' Svc list enc)
 - TAYLOR, J M Division of Safrguards % Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24x Fiche 50-000.83/03/21 8212060385
- 8305230723 Forwards listing of regulatory-induced major plant mode & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 77-01.79-02 & 79-14 mode provided GIESLER.C W Wisconsin Public Service Corp 83/03/25 TOURTELEOTTE.J Regulatory Reform Task Force 6pp 18542 263 24X Ficha 50-205.83/03/25.8305230728
- 8305020349 Forwards IE Insp Rept 50-305/83-0; on 830103-0302 & notice of violation NORELIUS.C E Division of Project & Resident Programs 83/04/11 GIESLER.C W Wisconsin Public Service Curp 2pp 18277 051 24X Fiche 50-305.83/04/11.8305020349
- --8305020332 Notice of violation from insp on 830103-0302 STREETER, J.F. Division of Project & Resident Programs 83/04/11 3pp 18277 053 24X Fiche 50-305,83/04/11,8305020349
- --8305020356 IE (nsp Rept 50-305/83-01 on 830103-0302 Noncompliance noted from 870422-27, temporary changes made to Maint Procedure 58-18469 w/o review or approval NELSON,R L , JACKIH, I N Region C, Office of Birector 83/04/07 8pp 18277 056 24x Fiche 50-305.83/04/11.8305020349
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/v4/15 Cansolidated Edison Co of New York, Inc. 126pp 18435 155 24x Fiche 50-000, 83/04/15, 8303040021
- 8305040f17 Discusses results of review of relief requests Relief granted in part from requirements of Section XI of ASME Code or other requirements as appropriate VAROA.S A Operating Reactors Branch 1 83/04/19 GIESLER.C W
- --8305040122 Safety evaluation supporting requests for relief from inservice insp requirements of Section XI of ASME Code for Class 1.2 & 3 components
 4 Office of Nuclear Reactor Regulation. Director 83/04/19 9pp 18328 120 24X Fiche 50-305.83/04/19.8305040117
- --8305040125 Notice of granting reliaf from ASME Code requirements VARCA:S A Uperating Reactors Branch 1 83/04/19 2pp 18328 129 24X Fiche 50-305,83/04/19.8305040117
- 8305040518 Forwards IE Insp Rept 50-305/63-05 on 830314 % 15 No noncompliance noted LITTLE.W S Region 3. Office of Director 83/04/20 GIESLER.C W Wisconsin Public Service Corp 2pp 18321 296 24X Fiche 50-305.83/04/20.8305040518
- --8305040922 IE Insp Rept 50-305/63-05 on 830314 % 15 No noncompliance nated Major areas inspected licensee action to IE Bulletin 80-1). "Masonry Wall Design " NORTON, J.F., WILLIAMS, C.C. Region 3 Office of Director 83/04/15 5pp 18321 258 24X Fiche 50-305/83/04/20/8305040518
- 8303040023 IE Info Notice 83-22, "BWR Safet4/Relief Valve Failures "
 Svc list enct
 JORBANIC L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83704/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24x Fiche 50-000 83704/22 8303040023
- B30304002" IE Info Notice 83-23, "Inoperable Containment Atmosphere Senting Sys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 271 244 Fiche 50-040.83/04/25.8303040025
- 8303040024 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PURs " Buc list end! JORDAN,E L Division of Emergency Preparedness V Engineering Response (Past 8301031 83704/28 Consolidated Edison Co of New Yark, Inc. 115pp 18382 047 247 Ficha 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list (nc) JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 247 Fiche 50-000,83/04/28,8303040027

- 8305030314 Forwards add1 info in response to IE Bulletin 80-11 re seismic qualification of masonry walls W/23 aperture cards Aperture cards are available in PDR GIESLER.C W Wisconsin Public Service Corp 83/04/29 VARGA.S A Operating Reactors Branch 1 12pp 18306 224 24X Fiche 50-305,83/04/29,8305030314
- B305050106 Forwards results of 1983 Steam generator addy current & fiber optics visual exams.per Tech Spec 4 2 b 5 a Summary of return to power SER encl Facility placed in C2 category, requiring mert insp within 24 months GIESLER.C W Wisconsin Public Service Corp B3/05/02 VARGA.S A Operating Reactors Branch 1 13pp 18342 154 24X Fiche 50-305.83/05/02.8305050106
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness % Engineering Response (Post 830103) 83705/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fische 50-000.83705/04.83033040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list anci JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Cansolidated Edison Co of New York, Inc 119pp 18441 001 24x Fiche 50-000,83/05/04,8303040031
- 8305100087 Confirms 830624 meeting in Glen Ellyn, IL to discuss SALP for facility
 NORELIUS.C E Division of Project & Resident Programs 83/05/04
 0185LER.C W Wisconsin Public Service Corp ip 18377 225 24X
 fiche 50-305.83/05/04.8305100087
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDAN E L Division of Emergency Preparadness & Enginearing Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115p 18523 248 24% Fiche 50-000.830/05/06.830/3040033
- B305270486 Forwards IE Insp Rept 50-305/83-03 on 830344-18,25,31 & 0407 & notice of violation HIND, J A Region 3. Office of Director 83/05/06 GIESLER.C W Wisconsin Public Service Corp 2pp 18644 011 24X Fiche 30-305/83/05/06
- --8305270493 Notice of Violation from insp on 830314-18 HIND.J A Region 3. Office of Director 83705705 p 18644 013 24% Fiche 50-305,83705706,8305270486
- --8305270502 IE Insp Rept 50-305/83-03 on 830314-18,25,31 & 0407
 Noncompliance noted failure to meet steam generator blowdown
 analysis sensitivity requirement of Tech Spec Table
 4 11-1 & failure to collect environ precipitation sample
 NICHOLSON,N A , ROSAK, S , SCHUMACHER,M C Region 3, Office of
 Director 83/05/04 10pp 18644 014 24% Fiche 50-305,83/05/06,8305270486
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidalines " Svc list encl JORDAN,C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000.83705/11.8303040034
- 830518026: Responds to 8304:1 notice of violation & proposed imposition of civil penalty re capped concalment pressure sensing lines NRC conclusions & actions inappropriate Violation isolated event & does not merit civil penalty ZIEMER,P D Misconsin Public Service Corp 83/05/11 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement Sipp 18490 029 24% Fiche 30-305,83/05/11,8305180261
- B305240104 Forwards clarifications % corrections to inservice insp program safety evaluation dtd 830419 Status of relief requests noted VARGA: B.A. Operating Reactors Branch 1 83/05/16 GIESLER, C. W. Wisconsin Public Service Corp. 3pp. 18593-360 24X Fiche 50-305, B3/05/16, B305240104
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18677 009 24% fiche 50-000, 83/05/19, 8303040040

- 8303040046 IE Info Notice 83-33 'Nonrepresentative Sampling of Contaminated 0:1" Svc list enr1 JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830(03) 83/05/26 Consolidated Edison Co of New York
- R Periodic operating reports & related correspondence
- 8305310164 Submits results for Filst Qualter 1983 confirmatory measurements program for liquid waste sample & NRC spiked charcoal 1 & 2 RICHMOND, J S Washington Public Power Supply System 63/04/38 ROZAK, S Region 3, Office of Directo; 2pp 18652 285 24x Fiche 30-305/83/04/30.8305310164
- 8305030106 Forwards results of 1983 steam generator eddy current % fiber optics visual exams, per Tech Spec 4 2 b 5 a Summary of return to power SER enc1 Facility placed in C2 category, requiring next insp within 24 months OIESLER, C W Wisconsin Public Service Corp 83/03/02 VAROA, S A Operating Reactors Branch 1 13pp 18342 194 21% Fiche 50-305,83/05/02,8305050106
- B305130230 Forwards monthly operating rept for Apr 1783
 OIESLER.C W Wisconsin Public Service Corp B3/05/10 Director s
 Office, Office of Inspection and Enforcement 1p 18439 214 24X
 Fiche 50-305/83/05/10/8305130250
- --8305130251 Monthly operating rept for Apr 1983 RUITER.0 H Wisconsin Public Service Corp 83/05/02 5pp 18439 215 24X Fiche 50-305.83/05/10.8305130250
- 8305310154 Forwards annual environ radioactivity monitoring repts for 1982 W/o encl MCDONNELL,L. J. Wisconsin, State of NRC-05-80-275 83/05/23 KEPPLER, J. G. Region 3, Office of Director 1p 18659 140 24X Fiche 50-000,83/05/23,8305310194
- 8 Reportable occurrences, LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Bmall Diameter Piping" BROWN.E J. Reactor Operations Analysis Branch 83/04/19 8EYPRINK V. Reactor Operations Analysis Branch 1p 18541 342 24X Fichs 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated v/bration problems require addl supports or rerouting of piping BROHN.C J Reactor Operations Analysis Blanch 83/04/19 9pp 1834 343 24X Fiche 50-000.83/04/19 8305230373
- 8305100389 Forwards updated LER 83-005/03X-1 OIESLER.C W Wisconsin Public Service Corp 83/05/03 KEPPLER.J O Region 3, Office of Director 1p 18377 326 24X Fiche 50-305.83/05/03.8305100389
- --8305100397 Updated LFR 83-005/03X-1 on 830216, during surveillance test on diesel generator 10, see water outlet CV (SM-301B) from diesel oil cooler failed to open fully when diesel started Caused by erosion of ball, causing stacking Valve replaced BERNHOFT, B L . THORGERISEN J C Wisconsin Public Service Corp 83/05/03 Region 3. Office of Director ip 18377 327 24X Fiche 50-305,83/05/03,8309100389
- B305170267 Forwards updated LER 82-030/01X-2 OIEGLER.C W Wisconsin Public Service Corp 83/05/06 KEPPLER.J G Region 3, Office of Director 1p 18465 020 247 Fiche 30-305.83/05/06.830517026/
- --B305170271 Updated LER 8P-030/01X-P on 8P1004, sensing lines on six safety-related containment pressure transmitters found capped off inside containment Caused by personnel error during maint Caps removed SCHROCK, C A Wisconsin Public Service Corp B3/05/06 Region 3, Office of Director 40pp 18465 021 24X Fiche 50-305, 83/05/06, 8305170267
- 8305170323 Forwards description of equipment failure of seismic monitoring sys, detected on 830408 Transverse motion sensor on one of three triaxial accularometers failed Sensor provides no alarm or control function bys will be upgraded OIEBLER.C W Wisconsin Public Service Corp B3/05/06 KEPPLCR.J G Region 3, 0615ce of Director 2pp 18469 189 24X Fiche 50-305.83/05/06.8305170323

- BJ05270198 LER bj-612 (Q) =0 on BJ042° c nr inment vent activity monitor (m-21) discovered out or sic capied by tradequacy in administrative procedural untrols herveling operations suspended per Tech Specs R=21 returned to -vc W/BJ0520 ltr BERNHUFT.S L. THOREGREEN.v 6 CleSter v W/BJ0520 by Director Service corp BJ70570 KEP1EBP.J 6 Region 3 Office of Director 3pp 18637 167 24% Fiche "0-30% 8 7% to 6305270158
- DOCKET 90 306 PRAIRIE ISLAND NULLIAR Limiton UNIT?

 F Security medical, emergency fire protection plans
- 8305030214 Releases public version of revised emergency plan implementing procedures FELTON. IM Division of Rules and Returns 83/04/22 Document Management Branch 1p 18310 155 24% Fiche 50-282.83/04/22.8305030714
- --8305030721 Forwards public version or to used emergency plan implementing procedures, including Procedures PG-2 reclassification of emergencies PG-5 to whet yearly notification & PG-9 is emergency execuation WARD.E C. Northern States Couet on HB/04/09 Region 3. Office of Director ip 18310 its 24% Fiche 50-282, 83/04/22, 6305030214
- --8309030626 Public version of this serving procedures including Procedure F3-3 to classification of emergencies F3-5 to emergencies F3-5 to emergencies F3-5 to emergency to F3-9 to emergency cvacuation.

 SCHULINE: D.A. Northern Gt. Les Power un 83'03/27 129pp 18310 157 244 Fiche 50-283 83/04/22, 8305030211
- 830517065/ Forwards exemption from 1001850. App R. Subsection 111 6 2 respansion, file barrier * suppression requirements where both frains of indundant salv shutdown components located within same fire area, per 820630 % 102* requests CLARK.R A Operating Reactors Branch 3 83/05/04 MUSOLF, D Northern States Power Co. 4pp 18491 0/2 24% Fiche 50-282,83/05/04,8309170657
- --8305170666 Exemption from 10/CFR50.App R Subsection III G 2 respectation.rire barries is uppression logoirements where both tights of redundant sare shotdown components located within same fire area EISEMMUT.D G Division of Licensing 33/05/04 Northerh Elate Power Co 7pp 18481-076 24% Fishe 50-282.83/05/04.8305170657
- --8309170683 Safety evaluation to exemptions from 10CFR50, App R. Section 191 G 2 requirement for maint of one train of equipment necessary for safe shutdow, w/o fire damage Exemptions should be denied in four aicas > granted in five areas # Office of Nuclear Reactor Regulation, Director B2/10/27 21pp 18481 083 24X Fiche 50-282,83/05/04,8305170657
- 8305110034 Generic Ltv 83-21 to all licthsees or operating reactors, applicants for OLs 1 holders of CPa to clarification of access to control procedures for law enforcement visits. Sec list one?

 EISENMULD 6 Division of Licensing 83-03-11 Consolidated Edison Co of New York, Inc. 16pp 10540-095 P4x Fiche 50-000-83/05/11,8305110031
- 8305190343 Forwards Rev 1 to NUREG-0720. Whit Incident Response Plansin response to 830429 ftr requesting updated ltr of agreement W/o encl
 HIND-U A Division of Radiological & Materials Safety Programs
 83/03/13 LARSON.C E Northern States Fower Co 2pp 18500 225
 24X Fiche 50-000, 83/05/13, 8305190343
- B303200023 Notifies that NUKCO-073/. Hem 111 A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR50." completed Jeom closed CLARK.R A Operating Reactors Branch } E3/05/13 MUSGLF.D M Northern States Power Co 3pp (E54L 11" 24/ Fiche 30-282,83/05/13,8305200023
- B305230523 Forwards clarifying info in support of 830311 exemption requests for 10CFR50 48.App R re Fire Areas 58,59.73 ± 74 MUSGLF: D. Morchern States Power Co. 83/05/16 Gffice of Nuclear Reactor Regulation, Director 62pp 18536 329 24x Fiche 50-282.B3/05/16.B305230523
- B305240389 Advises that date for next annual emergency preparedness exercise revised to 840313, per 830128 telcon PAPERIELLO.C J. Region 3. Office of Director 83/05/19 LARSDN.C E. Northern States Power Co. 1p. 18575 069 24X Fiche 50-282,83/05/19,8305240389

- P Operating license stage documents 5 correspondence
- 9303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1.539 MWE (summer) net HADLEYIC D Northern States Power Co 83/03/15 TOURTELLOTTE, J Regulatory Reform Task Force 6pp 18541 041 241 Fiche 30-000, 83/03/15. 8303180429
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J. Regulatory Reform Task Force B3/04/11 PALLADINO.N J. Commissioners 200 18542 272 24% Fiche 50-000.83/04/11,8305230720
- 8305020320 Forwards Rev B to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements." per 780201 submittal MUSDLF.D Northern States Power Co 83/04/19 Office of Nuclear Reactor Regulation, Director 2pp 18277 146 24X Fiche 50-282.83/04/19.8305020320
- --8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
 4 Northern States Power Co 83/04/19 21pp 18277 148 24X Fiche 50-282,83/04/19,8305020320
- 8305060013 Advises that action required by 830202 Amends 41 & 55 to Licenses DPR-42 & DPR-60, respectively & Generic Ltr 83-07 completed based on util actively negotiating w/DDE ie disposal of high level waste or spent nuclear fuel CLARK.R A Operating Reactors Branch 3 83/04/21 MUSULF.D M Northern States Power Co 2pp 18354 311 24X Ficha 50-282,83/04/21,8305060013
- 8305050108 Advises that requirements of NUREG-0737. TMI Action Plan Items II F & 4.1I F & 5 & II F & 6 met & 1 tems resolved Criteria requiring equipment to be environmentally qualified will be reviewed under environ qualification program CLARK.R A Operating Reactors Branch 3 83/04/21 MUSOLF.D M Northern States Power Co 9pp 18354 268 24% Fichs 50-282.83/04/21,8305060108
- 8305040023 Forwards safety evaluation & technical evaluation rept for environ qualification of safety-related electrical equipment Justification for continued operation & schedule for proposed corrective action requested by 930520 CLARKIR A Operating Reactors Branch 3 83/04/25 MUSDLF, D M Northern States Power Co 3pp 18354, 322 24X Fiche 50-282.83/04/25,8305060023
- --8305060036 Safety avaluation re environ qualification of safety-related electric equipment Major qualification deficiencies identified in Franklin Research Ctr technical evaluation rept Tables 4-1,4-2,4-3 & 4-4 must be resolved 4 Office of Nuclear Reactor Regulation. Director 83/04/25 7pp 18354 325 24% Fiche 50-282,83/04/25,8308060023
- 8305020459 Genoric Ltr 83-19 to all power reactor 9 testing licensees re new procedures for providing public natice concerning issuance of amends to OLS Svc list encl EISENHUT, D. G. Division of licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp. 18441-120 24X Fiche 50-000,83705/02.8305020455
- 8305120387 Forwards response to IRC 830425 ltr transmitting safety evaluation for environ qualification of safety-related electrical equipment Rosemount 1153 Senies A transmitters should be reclassified as Category II C equipment items MUSOLF.D Northern States Power Co 63/05/05 Office of Nuclear Reactor Megulation. Director 27pp 18433 124 24X Fiche 50~262,83/05/05,8305120389
- 8305090655 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D G Division of Licensing 93/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24% Fiche 50-000.83/05/09.8305090659
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice B3-14, "Devatored Spent Ion Exchange Resin Susceptibility to Erothermic Chemical Reaction " Svc list encl TAYLOR, J M Privision of Safeguards & Inspection Programs (Post B30103) 83/03/21 Consol

- 8303040021 IE info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN,C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 124pp 18435-155 24X Fiche 50-000,83/04/15,8303040021
- ---8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements"
 Northern States Power Co 83/04/19 21pp 18277 148 24X Fiche 50-282, 83/04/19, 8305020320
- 8303040023 IE Info Notice B3-22, "BWR Safety/Relief Valve Failures "
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 [E Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 30-000.83/04/28,8303040026
- 8303040027 IE info Notice 83-25. "Standby Gos Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Enc. 118pp 18382 165 24X Fiche 30-000,83/04/28,8303040027
- 8303040028 IE info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 837/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24x Fiche 30-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Past B20103) B3/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305240029 forwards 1E insp Repts 50-202/83-06 % 50-306/83-05 on 830216-0331 No noncompliance noted 814FER.W D Region 3. Office of Director 83/05/06 LARSON, C E Northern States Power Co 2pp 18549 095 24X Fiche 50-282,83/05/06.8305240029
- ---8305240061 IE insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No nancompliance noted Major areas inspected plant operational safety, maint, surveillance, review of operating events. LERs. fire penetration seals & IE bulletins
 FEIERABEND; C D : WILLIAMS, D L : JACKIW, I N Region 3, Office of Director 83/03/05 18pp 18549-097 24% Fiche 50-282,83/05/06,8305240029
- B303040034 IE info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
- B303040046 [E Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York
- R Periodic operating reports & related correspondence
- 8305160056 Forwards monthly operating repts for Apr 1983
 MUSDLF, D. Northern States Power Co. 83/05/11 Office of Resou
 Management, Director 1p 18451 036 24% Fiche 50-282,83/09/11. Office of Resource
- --8305160076 Monthly operating repts for Apr 1983 pU931A), D Northern States Power Co 83/05/04 8pp 18451 037 24% Fiche 50-2828.83/05/11.8305160036
- 8 Reportable occurrences, LERs & related correspondence
- 8305240153 LER 83-007/03L-0 on 830416, spike occurred in RCS activity up to 3 26 uci/gm dose equivalent 1-131 Caused by washout of fission products from fuel pin defects following leactor shutdown & RCS cooldown & depressurization W/830516 ltr HUN8TAD, A A . MUSCLF, D. Northern States Power Co. 83/05/16 Region 3, Dffice of Director 7pp 18547 009 24X Fiche 50-306.83/05/16,8305240153
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 8305120421 Ack receipt of FEMA 830421 ltr & "Final Exercise Rept -JOSINGULAR ACCEPT OF FEMA BJOAZI IT O FINAL Exercise Rept Joint State & Local Radiological Emergency Response Exercise "Emergency preparedness does not provide reasonable assurance that protective measures will be taken ALLAN. J M. Region I. Office of Director B3/05/04 RANDAZZA, J B. Maine Yankee Atomic Power Co. 2pp. 18433 153 24X Fiche 50-307,83/05/04,8305120421
- --8305120426 Forwards "Final Exercise Rept Joint State & Local Radiological Emergency Response Exercise for Mains Yankee Atomic Power Plant:" conducted on 821211 MCLOUGHLIN,D Federal Emergency Management Agency 83/04/21 DIRCKS,W J Office of the Executive Director for Operations 1p 18433 155 24X Fiche 50-309.83/05/04.8305120421
- --B305120427 "Final Exercise Rept Joint State & Local Rediological Emergency Response Exercise for Maine Yankee Atomic Power 83/03/31 8300
 - # Federal Emergency Management Agency 83/03/31 18433 156 24X Fiche 50~309,83/05/04,8309120421
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits SVc list onc!
 EISENHUT, D Ø Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fichs 50-000,83/05/11,8305110034
- 8305200341 Forwards description of change to tamper indication & revised security plan pages Encls withheld (ref 10CFR73 21) OARRITY. JH Maine Yankee Atomic Power Co 83/05/17 Offic Nuclear Reactor Regulation, Director 2pp 18516 230 24X Fiche 50-309,83/05/17,8305200341 Office of
- 8305230127 Forwards emergency operating procedures generation package, per NUREO-0737, Suppl I (Generic Ltr 82-33) "Requirements for Emergency Response Capability"
 OARRITY, J H Maine Yankee Atomic Power Co 83/05/17 CLARK, R A Operating Reactors Branch 3 3pp 18531 243 24X
 Fiche 50-307, 83/05/17, 8305230127
- --8305230137 Rev 5 to Procedure EOP 2-70-1. "Safety Injection "
 * Maine Yankee Atomic Power Co 83/05/17 5pp 18531 29
 Fiche 50-309,83/05/17.8305230127 18531 294
- --8305230140 Rev 12 to Procedure EQP'2-70-2, "LOCA" * Maine Yankee Atomic Power Co 83/05/17 9pp 18531 299 24X Fiche 50-309,83/05/17,8305230127

- ---8305230142 Rev 4 to Procedule FQP 2-70-3. "Steam Generator Tube Rupture ' * Maire fankee Atomic Power Co B3/05/17 7pp 18531 308 Fiche 50-309,83/05/17,8305230127
- --8305230146 Rev 14 to Procedure EDP 2-70-4, "Steam Line Break * Maine Yankee Atomic Power Ca 83/05 (7 App 1853) 3 Fiche 50-309,83/05/17,8305230127 24X 18531 315
- --8305230151 Rev 7 to Procedure 2 70-5, "Emergency Boration"

 Maine Yorkee Atomic Power Co 83,05/17 9pp 18531 321
 Fiche 50-309,83/05/17,8305230127 24 X
- --8305230154 Rev 11 to Procedure FOP 2-70-6. "Losa of Feedwater * Maine Yankee Atomic Power Co 83/05/17 5pp 18531 330 Fiche 50-309,03/05/17,8305230127 18531 330 24x
- --8305230157 Rev 5 to Procedure EOF 2-70-7, "Total Loss of Forced Reactor Coolant Flow/Natural Circulation" * Maine Yanke Atomic Power Co 83/05/17 4pp (8531 335 24X Fiche 50-309,83/05/17,8305230127
- --8305230162 Rev 8 to Procedure EOP 2-70-8; "Emergency Loop Shutdown * Maine Yankee Atomic Power Co 83/05/1/ 3pp 18531 339 2: Fiche 50-309,83/05/17,8305230127
- --B305230167 Rev 7 to Procedure EOP 2-70-9, "loss of Offsits Power "
 Maine Yankee Atomic Power Co 83/05/17 14pp 18531 342 24x
 Fiche 50-309,83/05/17.8305230127
- --8305230175 Rev 8 to Procedure EOP 2~70-10, "Control Room Evaluation " * Maine Yankee Atomic Power Co 83/05/17 5pp 18531 356 Fiche 50-309/83/05/17/8305230127
- --8305230181 "Maine Yankee Proceudre Writing Guidelines "

 # Maine Yankee Atomic Power Co #3/05/17 22pp 18531 361 24x

 Fiche 50-309,83/05/17,8305230127
- G Adjudicatory correspondence
- 8305030365 Forwards State of MC first bot of interrogatories & requests for production of documents Certificate of Svc encl STERN,P Maine, State of 83/04/29 Docksting & Services Branch 2pp 18306 001 24% Filhe 50-309.83/04/29.8305030565
- --8309030567 First set of interrogatories % requests for production of documents Certificate of Svc enc!
 AHRENS.P, STERN.P Maine. State of G3/04/29 Office of the Erecutive Legal Director 85pp 18306 003 24X
 Fiche 50-309,83/04/29,8305030565
- 8308040533 Response opposing Sensible Maint Power 830426 renewed 820827 motion for more complete A specific disclosure by applicant & for stay Thiton is not motion to compel b is founded upon erroneous assumption Certificate of Svc encl DIGNAN.T 0, OAD,R K Maine Yankee Atomic Power Co DIGNAN.T C Ropes b Gray 83/04/29 Atomic Safety and Licensing Board Panel App 18321 235 24X Fiche 50-309.83/04/29.8305040593
- 8305140097 Reply opposing applicant answer opposing Sensible Maine Power 830487 renewed motion for more complete & specific disclosure by applicant Applicant answer misleading Certificate of Sec enci MILLER, D S Sensible Maine Power MILLER, D S Miller, D S 83005/11 Atomic Safety and Licensing Board Panel App 18452 019 24X Fichs 50-309,83/09/11,8309160099
- 8305200068 Informs that 830405 methodology submittal re radiation environ for equipment qualification inside containment acceptable, per NUREG-0588 Submittal also provides ref for radiation levels outside containment CLARK.R A Operating Reactors Branch 3 83/05/13 GARRITY, J H Maine Yankes Atomic Power Co 2pp 18540 128 24X Fichs 50-309, 83/05/13, 8305200068
- 8305190255 Motion to compel answers to interrogatories & production of JOSYDERS Motion to comparansasers to interregatories & prooud occuments & request for leave to file motion Hearing cannot be conducted on basis of assertions, suppositions, similarities or generalities Certificate of Svc and MILLER, D S Sonsible Maine Power MILLER, D S Miller, D S 83/05/14 Atomic Safety and Licensing Board Panel 21pp 18301 262 24X Fiche 50-309,83/05/14.8305190255
- 8305170852 Response opposing Sensible Maine Power 830511 motion for complete & specific disclosure by util & motion for stay of proceedings Extreme relief sought before motion to compal discovery filed W/Certificate of Bvc GODDARD, R J Hearing Branch 3 B3/05/16 Atomic Gafety and Licensing Board Panel 7pp 18468 033 R4X Fiche 50-309,83/05/16.

- 83/05/17 Office of the Executive Legal Director 18575 229 24x Fiche 50-309,83/05/17,8305240493
- 8305240493 Motion for extension of discovery period until 830904 Util conduct of willful nondisclosure necessitates extension Certificate of Svc encl Hiller, D.S. Sensible Maine Power 83/05/18 Atomic Safety and Licensing Board Panel App 18372 313 24X Fiche 50-309,83/05/18,830624082
- 8305240386 Forwards second set of interingatories & requests for production of documents to NRC Certificate of Svc encl AHRENS.P., STERN.P Maine, State of 83/05/19 Atomic Safety and Licensing Board Panel 36pp 18571 070 24X Fiche 50-309,83/09/19,8305240386

H General correspondence

- 8305310238 Responds to constituent 830419 ltrs re Commission action on util performance during 821211 emergency preparadness DIRCKS H J Office of the Elecutive Director for Operations 83/05/20 COMEN.W S Sonate 5pp 18662 246 24X Fiche 50-309,83/05/20,8309310238
- --8305310239 Requests response to encl constituent ltrs re util failure to pass FEMA emergency preparedness test COHEN.W S Senate 83/04/19 KAMMERER.C C Office of Congressional Affairs 5pp 18662 250 24X Fiche 50-309, 83/05/20.8305310238

! Financial information

- 8305200314 Forwards Securities & Exchange Commission Form 10~0. Quarterly Financial Rept for Jan-Mar 1983 HDME.R S Maine Yantee Atomic Power Co 83/05/13 NRC Detailed Affiliation Given 15pp 18517 023 24X Fiche 50-309.83/05/13.8305200314 NRC - No
- 8305200578 Forwards 1981 & 82 annual financial info filed w/Becurities & Exchange Commission.per 10CFR50 71 b
 GARRITY.J H Maine Vankee Atomic Power Co 83/05/17 CLARX.R A
 Operating Reactors Branch 3 103pp 18514 143 24x
 Fiche 50-309.83/05/17.8305200578
- P Operating license stage documents & correspondence
- 8303240026 Discusses review of 820408.0601.1103 & 830216 submittals on YAEC-1276P. "DNBR Limit Methodology & Application to ME Yankee Plant " Critical heat flux correlation acceptable for application to facility reload wide14 fuel assembles CLARK, R A Operating Reactors Branch 3 83/03/09 GARRITY, J H Mains Yankee Atomic Power Co 2pp 17690 279 24X Fiche 30-309.83/03/09.8303240026
- --8303240029 Safety evaluation supporting application to reload w/14x14 fuel essemblies & min t 20 DNBR limit * Office of Nuclear Reactor Regulation, Director 83/03/09 7pp 17690 301 24X Fiche 50-309,63/03/09,6303240026
- --8301060137 "Review of YAEC-1296P DNDR Limit Methodology & Application HESSON: G M Battelle Memorial Institute, Pacific Northwest Laboratory FATE-82-114 82/12/31 NRC - No Detailed Affiliation Given 7pp 17690 308 24% Fiche 30-309,83/03/09,
- 8305020500 Forwards revised instrumentation & control concerns & positions on feedwater trip sys Meeting to discuss concerns within 45 days requested CLARK, R.A. Operating Reactors Branch 3 83/04/20 GARRITY, J.H. Maine Yankee Atomic Power Co. 7pp 18284 213 24x Fiche 50-309,83/04/20,8305020600
- 8305050220 Forwards "Mains Yankee Cycle 7 Startup Test Rept." per Tech Spec 5 9 1 2 GARRITY. J. K. Maine Yankee Atomic Power Co. 83/04/25 ALLAN, J. M. Regian I. Office of Director ip. 18338-064 24X
 Fiche 50-307,83/04/25,8305050220
- --8305050225 "Maine Yankee Cycle 7 Startug Test Rept" + Maine Yankee Atomic Power Co 83/04/25 11pp Fiche 50-309,83/04/25,8305050220 18339, 045

- 8305060042 Forwards safety evaluation supporting continued operation w/Dresser safety valve ring settings which do not allow discharge full rated flow Summary of specific info also Ent. CLARK, R A Operating Reactors Branch 3 83/04/25 Maine Yankee Atomic Powor Co 2pp 18354 334 24X Fiche 50-309, 83/04/25, 8305060042 GARRITY, J H
- --8305060049 Safety evaluation supporting continued operation by PWRs w/Dresser safety valves which do not allow discharge full
 - ** Office of Nuclear Reactor Regulation, Director 83/1
- 8305030491 Forwards response to 821210 Generic Ltr 82-28 re inadequate OSOJO491 Forwards response to B21210 Generic Let B2-20 Fe indicate core cooling instrumentation sys.including reactor coolant inventory sys description, conformance summany to NUREG-0737. Item II F 2 & proposed implementation schedule RANDAZIA.J B Maine Yankee Atomic Power Co B3/04/29 EISENHUT, D G Division of Licensing 34pp 18295 118 24X Fiche 50-309, 83/04/29, 8305030491
- --8305030496 Rev 10 to Emergency Operating Procedure EOP 2-70-0, "Emergency Shutdown From Power" * Maine Yankee Atomic Power Co 83/04/29 28pp 18295 152 24X Fichs 50-309, 83/04/29, 8305030491
- B305020455 Opnoric Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT.D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305140201 Responds to util 821007 proposed Tech Spec changes re purge 305160201 Responds to util 821007 proposed lech Spec changes he place was sus Proposed leak test interval unacceptable 61:month test interval for passive valves. w/testing after each
 use & 3-month interval for active valves recommended
 CLARK,R A Operating Reactors Branch 3 83/05/02 GARRITY, J H
 Maine Yankes Atomic Power Co 3pp 18471 339 24X
 Fiche 50-309, 83/05/02, 8305160201
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D Q Division of Licensing 83/05/09 Consolidated Edison Co of New York Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659 Consolidated
- 8305130078 Responds to request for add1 info re TMI Item II E 4 2 6, "Containment Ventilation Sys 8-Inch Qlobe Valve " Analyses to demonstrate valve qualification continuing OARRITY, J H Maine Yankee Atomic Power Co 83/05/09 CLARK, R A Operating Reactors Branch 3 2pp 18436 329 24X Fiche 50-307,83/05/09,8305130078
- 8305170612 Requests add1 info re 830218 proposed Cycle 7 supplementary changes to Tech Specs allowing operation w/YAEC-1 critical heat flux correlation CLARK, R A Operating Reactors Branch 3 83/05/09 GARRITY, J H Haine Yanter Atomic Power Co 2pp 18497 020 24X Fiche 50-309,83/05/09,8305170612
- 8305130054 Ack receipt of 821103 ltr re intention to complete Phase II of control of heavy loads issue (NVREO-0612) Final technical avaiuation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested GARRITY.J H Maine Yankee Atamic Power Co 83/05/10 CLARI Operating Reactors Branch 3 2pp 18437 031 24X Fiche 50-309, 83/05/10, 8305130054 83/05/10 CLARKIR A
- 8305130128 Responds to 10CFR50 54(f) info request re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," (Generic Ltr 83-10A) Plant-specific study applies RELAP5YA code, per 820819 & 830114 ltrs FRIZZE, C D Maine Yankee Atomic Power Co 83/05/10 EISENHUT, D 0 Division of Licensing 4pp 18437 191 24X Fiche 50-309,83/05/10,830430189 8305130128
- 8305230381 Denies request for exemption from requirements of App J to perform Type C tests w/air or nitrogen as medium for certain containment valves Uasis for conclusion contained in anci safety evaluation & tachnical evaluation rept EISENHUT.D 0 Division of Licensing 83/05/ii OARRITY, J H Maine Yankee Atomic Power Co 3pp 18377 024 24X Fiche 50~309,83/05/ii,8305230381
- --8305230397 Safety evaluation re App J review concerning containment testing program Proposed revs to Tech Spec 4 4 unacceptable * Division of Licensing 83/05/11 Spp 18577 027 24X fichs 50-309,83/05/11,8305230381

- --8206300177 "Containment Leakage Rate Testing (A-04)." technical evaluation rept
 DELGATZO.T J Franklin Institute/Franklin Research Center
 NRC-03-79-118 TER-C5257-28 82/06/28 HUANG, Y S NRC No
 Detailed Affiliation Given 36pp 18577 030 24x
 Fiche 50-309, 83/05/11.8305230381
- 8305230571 Advises that addl info required to satisfy current requirements re operational GA program Telcon on 830510 addressed general subjs to be discussed Specific questions to be provided 1 wk prior to 830525 meeting in Augusta, ME MARTIN.T T Division of Engineering & Technical Programs 83/05/11 RANDAZA.J B Maine Yankee Atomic Power Co 2pp 18537 317 24X Fiche 50-309,83/05/11,8305230371
- B305190308 Submits justification for continued operation for listed items not addressed in previous environ qualification of electrical equipment submittals including equipment qualification pending mod GARRITY. J H Maine Yankee Atomic Power Co B3/05/12 CLARK, R A Operating Reactors Branch 3 5pp 18501 074 24% Fiche 50-309, 83/05/12, 8305190308
- 8305200469 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, 820929-1001," including Type A tests performed during Cycle 6/7 refueling outage & Type B & C tests performed since last Type A test
 OARRITY, J H Maine Yankee Atomic Power Co 83/05/16 CLARK, R A Operating Reactors Branch 3 ip 18516 120 24X
 Fiche 50-309, 83/05/16, 8305200469
- --B305200473 "Reactor Cantainment Bldg Integrated Leak Rate Test, B20929-1001 " G100EY, C A Maine Yankee Atomic Power Co 83/05/16 77pp 18516 121 24X Fiche 50-309, B3/05/16, B305200469
- 8305230383 Forwards update to 801106 ltr re shielding design summary per TMI Item II 8 2 Update contains datails of results of shielding review No supplemental SER required from NRC as result of relocation & future mods
 OARRITY.J H Maine Yankee Atomic Power Co 83/05/18 CLARK,R A Operating Reactors Branch 3 8pp 18538 235 24X
 Fiche 50-309.83/05/18.8305230383
- B305240270 Proposes alternative to NRC 820903 request to upgrade auxiliary feedwater sys automatic initiation logic channel testing per TMI Item II E : 2 Monthly test of bistables actuation setpoints recommended OARRITY, J H Maine Yankee Atomic Power Co B3/05/18 CLARK, R A Operating Reactors Branch 3 2pp 18548 210 24X Fichs 50-309, B3/05/18, B305240270
- 8305240266 Forwards updated list re current status of electrical equipment important to safety within scope of 10CFR50 49 Nonqualified equipment scheduled to be qualified or replaced by end of next refueling outage OARRITY. J H Maine Yankee Atomic Power Co 83/05/20 CLARK.R A Operating Reactors Branch 3 6pp 18548 298 24X Fiche 30-309, 83/05/20.8305240266
- 0 Inspection reports, 1E Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112p 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Byc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435,155 24X Fiche 50-000,83/04/15,8303040021
- 8305030350 Forwards IE Insp Rept 50-309/83-05 on 830406-07 & notice of violation
 8TAR0STECKI, R Division of Project & Resident Programs 83/04/19
 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 18297 102 24X
 Fiche 30-309,830/04/19,8305030350
- --8305030353 IE Insp Rept 50-309/83-05 on 830406-07 Noncompliance noted inadequate control of safety-related maint of HPSI subsys & failure to maintain two operable safety injection trains per Tech Specs
 KELLY,E M Region I, Office of Director GALLO,R Division of Project & Resident Programs 83/04/13 5pp 18297 104, 24X fiche 50-309,83/04/19.8305030350

- 8303040023 IE Into Notice 83-22, "3WR Safety/Relief Valve Failures "
 5vc list encl
 JORDAN: E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24x Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24x Fiche 50-000, 83/04/25, 8303040025
- 8305020386 Ack receipt of 830412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-17
 MARTIN/T T Division of Engineering & Technical Programs 83/04/26
 RANDAZZA.J B Maine yankee Atomic Power Co 2pp 18276 244 24X
 Fiche 50-309/83/04/26/8305020386
- --8305020393 Responds to NRC 830225 ltr re violations noted in IF Insp Rept 50-309/82-17 Corrective actions prisonnel responsible for shipping radioactive mati reminded that all required insps must be documented Procedure 9 I 15 revised OARRITY, J H Haine Yankee Atomic Power Co 83/04/12 ALLAN, J H Region 1. Office of Director 4pp 18276 246 24X Fiche 50-309,83/04/26,8305020386
- 8305110314 Forwards IE Insp Rept 50-309/83-04 conducted by State of SC on 821217 No noncompliance noted, however State of SC identified violation widDT regulations
 MARTIN.T T Division of Engineering & Technical Programs 83/04/27
 RANDAIZA, J B Maine Yankee Atomic Power Co 2pp (8393 186 24X Fiche 50-309:83/04/27,8303110314
- --B305110320 IE insp Rept 50-309/B3-04 conducted by State of SC on B21217 No noncompliance noted Major areas inspected review of shipping papers placarding twarking State of SC identified violation re DDT regulations CLEMONS, P. SHANBAKY, M. Region i. Office of Director 4pp 18393 IBB 24X Fiche 50-309, B3/04/27, B305110314
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18362 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 [E Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 803103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fichs 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc. 112pp 18362 282 24X Fiche 50-000.83/05/04,8303040030
- 830304003i IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Consulidated Edison Co of New York, Inc. 119pp 18441 001 24x Fiche 50-000,83/05/04,8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Gaused by Fuel Rack Deformation " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 113pp 18523 24B 24Y Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergenty Operating Procedures (EOP) Guidelines " Svc list enci JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Connollidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B305250310 Forwards IE Insp Rept 50-309/83-02 on B30301-11 & notice of violation MARTIN.T T Division of Engineering & Technical Programs B3/05/11 RANDAZZA:J B Maine Yankee Atomic Power Co 2pp 18592 105 24Y Fiche 50-309
- --8303250312 Notice of violation from insp on 830301-11 * Region 1, Office of Director 83/05/11 5pp 18592 107 24X Fich: 50-309,83/05/11,8305250310

- --8305250314 IE Insp Rept 50-309/83-02 on 830301-11 Noncompliance noted failure to complete all design activities before declaration of sys operability EAPEN.P K . MEYER.O . NAPUDA.G . Region 1, Office of Director 83/04/27 . 39pp 18592 112 . 24X Fiche 50-309.83/05/11.8305250310
- 8305190079 EN-83-034 on 830520.notice of violation & proposed imposition of civil penalty in amount of \$40.000 to be issued Action based on violation re operating reactor w/one train of HPSI incapable of automatically starting BARBER, G. AXELRAD. J. Director's Office. Office of Inspection and Enforcement 83/05/17 ip 18502 069 24X Fiche 50-309.83/05/17,8305190079
- 8305250427 Supply response to 830324 jti & conpletes response to IE Bulletin 83-04. "Failure of Undrvoltage Trip Function of Reactor Trip Breakers "Description of reactor trip breaker incidents not previously reported encl GARRITY. J H Maine Yankee Atomic Pawer Co 83/05/18 ALLAN, J M Region 1. Office of Director 3pp 18585 271 24X Fiche 30-309.83/05/18,8305250429
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830(03) 83/05/19 Consolidated Edison Co. of New
 York, Inc. 114pp 18697 009 24x Fiche 50-000,83/05/19.8303040040
- 8305270434 Discusses IE insp on 830406-07 & forwards notice of violation & proposed imposition of civil penalty ALLAN, J H Director's Office, Office of Inspection and Enforcement 83/05/20 RANDAZZA, J B Haine Yankee Atomic Power Co 4pp 18642 235 24X Fiche 50-307.83/05/20.8305270434
- --8305270445 Notice of violation & proposed imposition of civil penalty in amount of 140,000 Noncompliance noted one of two HPSI subsys inoperable for 27 days & other HPSI subsys inoperable for 7 h during 27-day period ALLAN.J M Region i. Office of Director 83/05/20 3pp 18642 237 24X Fichs 50-309,83/05/20,8305270434
- 8303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl JORDAN,E L Division of Emergancy Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647-007 24X Fiche 50-000,83/05/26,8303040046
- 8303310067 Provides results of reevaluation of design adequacy of two masonry walls per IR Bulletin 80-11 identified in 821021 ltr Both walls located in spent fuel bidg, one adjacent to ventilation penthouse & other south of pool GARRITY, J H Maine Yantee Atomic Power Co 83/05/26 CLARK, R A Operating Reactors Branch 3 4pp 18653 174 24X Fiche 50-307.83/05/26.8305310067
- S Reportable occurrences, LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept, "Cracts & Leaks in Small Diameter Piping" BROWN,E J Reactor Operations Analysis Branch 83/04/19 SEYPRIY.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --B305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Bmall pipe leaks associated w/unanticipated vibration problems require addi supports or rerouting of piping BRONNE J Reactor Operations Analysis Branch B3/04/19 9pp 18941 343 24X Fiche 50-000,83/04/19.8309230573
- 8305060538 Forwards LER 83-009/03L-0 GARRITY, J H Maine Yankee Atomic Power Co 83/04/25 ALLAN, J M Region I. Office of Director ip 18348 327 24X Fiche 50-309, 83/04/25, 8305060538
- --8305060549 LER 83-009/03L-0 on 830405, spare HPSI pump failed to start during monthly ECCS surveillance resulting in degraded mode condition per Tech Spec 3 6 D Caused by ground racked up in pump breaker cubicle on 830307
 NELSON,R II Haine Yankee Atomic Power Co 83/04/25 Region 1, Office of Director 3pp 18348 328 24X Fiche 50-309,83/04/25, 8309060938
- 8305110344 LER B3-014/03L-0 on B30425, during steady-state full power operation. Section 207 of 115 kV incoming line decame unavailable Caused by lightning during electric strom which struct & damaged one phase of line Line repaired HOOD.E C Maine Vantee Atomic Power Co B3/04/26 Region 1. Office of Director 2pp 18406 184 24% Fiche 50-309,83/04/26, B305110344

- B305060494 Forwards updated LER 83-012/01T-1 GARRITY, J H Maine Yankee Atomic Power Co B3/04/28 ALLAN, J M Region i, Office of Director 1p 18348 101 24X Fiche 50-309, 83/04/28, 8305060494
- --8305060503 Updated LER 83-012/017-1 on 830406, drain valves opened to replace seal water supply filter FL-34B Valves opened again 5 days later to replace head gasket Caused by insufficient identification of valves in plant drawings WHITNEY, M A Mains Vankes Atomic Power Co 83/04/28 Region 1, 0ffice of Director 3pp 1834B 102 24X Fichs 50-309, 83/04/28, 8305060494
- B305110425 Forwards LER 83-010/03L-0 GARRITY, J H Maine Yantee Atomic Power Co B3/05/03 ALLAN, J M Region 1, Office of Director Lp 18405 092 24X Fiche 50-309, B3/05/03, B305110425
- --8305110433 LER 83-010/03L-0 on 830407, nonqualified RCS loop 2 resistance temp detector (RTD) input to subcooling margin monitor failed, causing erroneous monitor readings Cause unknown RTD leads disconnected & replaced MORRISON. G M Maine Yankee Atomic Power Co 83/05/03 Region 1. Office of Director 2pp 18405 093 24X Fiche 50-307, 83/05/03, 8305110425
- B305160065 Forwards LER B3-011/03L~0 GARRITY, J H Maine Yankee Atomic Power Ca B3/05/03 ALLAN, J M Region 1, Office of Director 1p 18451 001 24X Fiche 50-309, B3/05/03, B305160065
- --83051600B2 LER 83-011/03L-0 on 830404 reactor protection sys symmetric offset channel 8 found w/value less negative than other three channels Caused by failed Bell & Howell multiplier, divider module spare module installed & channel calibr TAYLOR. J M Maine Yanker Atomic Power Co 83/05/03 Region 1. Dffice of Director 2pp 18451 002 24X Fiche 50-309.83/05/03, 8305160045
- 8305200467 RO on 830408 & 15, fluctuations observed in real time computer-calculated containment weight of air & containment weight of air & containment weight of air monitoring sys Probably caused by recirculation fan failure

 GARRITY, J H Maine Yankee Atomic Power Co 83/05/03 ALLAN, J M Region 1. Office of Director 2pp 18516 118 24X

 Fiche 50-309, 83/05/03, 8305200467
- B305200529 Forwards evaluation summary rept & resolution of LER-B2-037/03L-O dtd B21115 re shock suppressor bushing failures Lab analysis revealed Torrington ball bushings mfg from brittle AISI 3160 steel Brushing replaced GARRITY, J H Maine Yankes Atomic Power Co 83/05/09 ALLAN, J M Region 1, Dffice of Director 3pp 18516 027 24X Fiche 50-309, 83/05/09, 8305200529
- 8305230472 Forwards LER 83-013/03L-0 9ARRITY.J H Maine Yankee Atomic Power Co 83/05/10 ALLAN.J M Region 1. Defice of Director in 18537 142 24X Fiche 50-309,83/05/10.8305230472
- --8305230483 LER 83-013/03L-0 on 830411.diesel fire pump failed to develop sufficient discharge pressure during fire suppression water sys test Caused by level float switch & check valve failures Valve replaced & switch cleaned LAFLANME.S J Maine Yankee Atomic Power Co 83/05/10 Region 1. Office of Director 2pp 18537 143 24X Fiche 50-309, 83/05/10, 8305230472
- 8305200360 Forwards LER B3-015/03L-0 0ARRITY.J H Maine Yankee Atomic Power Co 83/05/12 ALLAN,J M Region I. Office of Director 1p 18518 144 24X Fiche 50-309, 83/05/12, 8305200360
- --8305200374 LER 83-015/03L-0 on B30414 during maint on svc water pump P-27A pump P-27C spuriously tripped Cause unknown Pump restarted & tested satisfactorily MCCRATH.R Maine Yankes Atomic Power Co 83/05/12 Region 1, Office of Director 2pp 18518 145 24X Fiche 50-309,83/05/12, 8305200360
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8305i30307 Releases public version of revised emergency plan FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18456 335 24x Fiche 50-272, 83/05/02, 8305i30307

- --8305130308 Forwards public version of Rev 2 to emergency plan Receipt form encl * Jersey Central Power & Light Co 83/04/04 VARGA,5 A
 - Operating Reactors Branch 1 1p 18456 336 Fiche 50-272,83/05/02,8305130307
- --8305130307 Public version of Rev 2 to emergency plan BURGE.C A , MIDURA.H J Jersey Central Power & Light Co 83/04/04 188pp 18456 337 24% Fiche 50-272.83/05/02. 8305130307
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 ETSENHUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. Lopp 18340-095 24X
 Fiche 50-000,83/05/11,8305110034
- 8305270043 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 30-311/83-07 Request to further mitigate violation resecutity access control denied STAROBIECKI.R Division of Project & Resident Programs 83/05/23 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 18638 345 24X Fiche 50-272,83/05/23,8305270043
- --8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp. Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl Encls withheld (ref 10CFR73 21)

 UDERITZ, R A Public Service Electric & Cas Co of New Jersey 83/05/05 Region 1. Office of Director 3pp 18638 347 24X Fichs 50-272,83/05/23,8305270043

Q Adjudicatory correspondence

- 8305170493 Order extending time until 830527 for Commission to act to review Director's Decision DD-83-6 CHILK.B J Office of the Secretary of the Commission 83/05/13 Commissioners ip 18470 024 24X Fiche 50-272.83/05/13.
- B305310008 Order extending time until 830601 for Commission to act to review Director's Decision DD-83-6 CHILK.8 J Office of the Secretary of the Commission 83/05/27 Commissioners ip 18653 230 24X Fiche 30-272,83/05/27. 8305310008

I Financial information

- 8303200067 Forwards Annual Financial Repts for 1982
 FRYLING:R Public Service Electric & Gas Co of New Jersey
 83/05/17 Office of Nuclear Reactor Regulation: Director Ip 18516 198 24X Fiche 50-000,83/05/17,8305200067
- J Insurance & indemnity information
- 8305160157 Forwards Endorsements 58 & 45 to NELIA Policy NF-230 & MAELU 30D16013/ Forwards Endorsaments 38 2 43 to NELIA Policy NF-2 Policy MF-90, respectively OULDEN M P Marsh & McLennen, Inc B3/05/02 SALTZMAN, J Assistant Director for Btate & Licensee Relations 3pp 1 24X Fiche 30-272, B3/05/02, B305160157 18445 089
- P Operating license stage documents & correspondence
- 8305050013 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys (TMI Action Item II F 2) Westinghouse reactor vessel level instrumentation sys, described in 801231,810206 & 1207 submittals.utilized LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/04/22 VAROA.8 A Uperating Reactors Branch 1 27pp 18339 028 24X Fiche 50-272,83/04/22.8305050013
- 8305020186 Clariftes 830422 response to NRC 830420 ltr. Item 2. II D 10CFR50 54(f), re Westinghouse treatment of undervoltage trip attachment delivered disassembled UDERITZ.R A Public Service Electric & Gas Co of New Jersey 83/04/27 EISENHUT.D 0 Division of Licensing Rpp 18278 192 24X Fiche 50-272,83/04/27.8305020186
- 8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07, NUREO-0612, "Control of Heavy Loads," to confirm & Clarify Items discussed in 820804 telcon LIDEN.E A Public Bervice Electric & Gas Co of New Jersey 83/04/27 VAROA.S A Operating Reactors Branch 1 8pp 18399 007 24X Fiche 50-272,83/04/27,8305110134

- --8305110156 PSE-0108. "Maint Procedures" + Public Service Electric & Gas Co of New Jersey 83/04/27 1.317pp 18399 101 24X Fiche 50-272,83/04/27,8305110154
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OL= Svc list encl EISEMMUT. D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455
- 830509045/ Application to amend Licenses DPR-70 & DPR-75, revising safety Tech Specs by raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1

 LIDEN,E A Public Service Electric & Gas Co of New Jersey
 83/05/04 VAROA,5 A Operating Reactors Branch 1 2pp 18360 252
 24X Fiche 50-272.83/05/04,8305090457
- --B305090439 Proposed changes to safety Tech Specs, raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1

 * Public Service Electric & Oas Co of New Jersey 83/05/04

 4pp 18360 254 24X Fiche 50-272,83/05/04,8305090457
- 8305170015 Forwards Amend 19 to License DPR-75, safety evaluation & JUSI/UUIS rovarus Ameno 19 to License DMM-75, sarety evenotice of issuance & availability Amend removes cycle dependent values of Fry as function of core height & provides values by means of peaking factor limit rept FISCHER D Operating Reactors Branch 1 83/05/05 UZ Fublic Service Electric & Gas Co of New Jersey Spp 24X Fiche 30-31;83/05/05,8305170015 UDERITZ,R A 18494 155
- --8305170019 Amend 19 to License DPR-75, removing cycle dependent values of Fry as function of core height & provides values by means of peaking factor limit rept VARQA: A Operating Reactors Branch 1 83/05/05 9pp 18494 158 24X Fiche 50-311,83/05/05,8305170015
- --8305170023 Safety evaluation supporting Amend 19 to License DPR-75 Office of Nuclear Reactor Regulation, Director 18494 147 24X Fiche 50-311,83/05/05,8305170015 83/05/05
- -- 8305170028 Notice of issuance & availability of Amend 19 to License DPR-75
 VARQA: B A Dperating Reactors Branch i 83/05/0
 18494 169 24X Fiche 50~311.83/05/05.8305170015 83/05/05 2pp
- 8305170079 Forwards Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amends raise trip setpoint & allowable value of steam generator water level low-low reactor trip FISCHER.D Operating Reactors Dranch i 83/05/05 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp 18495 211 24X Fiche 50-272.83/05/05.8305170079
- --8305170084 Amends 53 & 21 to License DPR-70 & DPR-75, respectively, raising trip setpoint & allowable value of steam generator water level inw-low reactor trip VARGA. S A Operating Reactors Branch 1 83/05/05 8pp 18495 214 24X Fiche 50-272,83/05/05,8305170079
- --830517008/ Safety evaluation supporting Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively * Office of Nuclear Reactor Regulation, Director 83/05/05 2pp 18495 222 24X Fiche 50-272,83/05/05,8305170079
- --8305170090 Notice of issuance & availability of Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively VARQA, S A Operating Reactors Branch (83/05/05 2pp 18495 224 24% Fiche 35-272,83/05/05.8305170079
- 830517011/ Forwards Amends 52 & 20 to Licenses DPR-70 & DPR-75. respectively, safety evaluation & notice of issuance & availability Amends change partial power multiplier from O 2 to 0 3 TO US FISCHER, D. Operating Reactors Branch 1 83/05/05 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jorsey 3pp 1849& 001 24X Fiche 50-272,83/05/05,8305170117
- --8305170119 Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively. changing partial power multiplier from 0 2 to 0 3 VARGA: S A Operating Reactors Branch i 83/05/05 18494 004 24% Fiche 50-272,83/05/05,8305170117
- --8305170124 Safety evaluation supporting Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively * Office of Nuclear Reactor Regulation, Director B3/05/05 2, 18476 017 24% Ficha 30-272,83/05/05,8305[70117 83/05/05 2pp

- --8305170129 Notice of issuance > availability of Amends 52 & 20 to Licenses DPR-70 & DPR-75 respectively VARQA.5 A Operating Reactors Dianch | 83/05/03 2pp 1849& 019 24% Fiche 30-272, 83/05/03-8305170117
- S305110007 Forwards add) fee required for B21007 amend application L10EM.E A PUBLIC Service Electric & Gas Co of New Jersey B3/05/06 MILLER.W Q License Fee Management Branch 2pp 18409 258 24x Fichs 50-311.83/05/06.8305110007
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co
- 830517032B Forwards schedule for qualification or replacement of unqualified equipment for Categories 1 3.11 A.II C & IV identified in SER on environ qualification of safety-related alectrical equipment
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 83/05/09 VAROA.S A Operating Reactors Branch 1 16pp
 18485 153 24% Fische 50-272.83/05/09.8305170328
- 8305230504 Forwards affidavit & fee for review of 830504 application to amend Licenses DPR-70 & DPR-75 LIDEN,E A Public Service Electric & Gas Co of New Jersey 83/05/1 VARGA. S A Deprating Reactors Branch 1 2pp 18537 170 24X Fithe 50-272,83/05/11,8305230504
- 8305230094 Advises of rev to Cycle 2 reload analysis & effect on reload safety evaluation & approved amends to Tech Specs Rev due to fuel grid strap damage during Feb refueling Revised design evaluated by Wastinghouse per WGAP-9273 LIDEN E A Public Service Electric & Gas Co of New Jersey. 83/05/16 VARGA: S A Deceating Reactors Branch 1 3pp 18339 177 24X Fichs 50-311.83/05/16.8305230094
- 830531022: Requests assessment on operability of 10-inch pressure/ vacuum relief valves used for purge or vent of containments to demonstrate that valves will operate in event of DBA-LOCA info requested within 15 days VARGA: A Operating Reactors Branch 1 83/05/19 UDERITZ: R A Public Service Electric & Gas Co of New Jersey 7pp 18662 261 24X Fiche 50-272.83/05/19.8305310221
- O Inspection reports, 1E Bulletins & correspondence
- 8212060385 [E Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolle
- 9303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Svc list encl
 JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc. 126pp 18435-1855 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE info Notice 83-23, "Inoperable Containment Atmosphere 8ensing Sys " Svc list enc! JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 19381 27: 24x Fiche 50-000.83/04/25,8303040025
- York, Inc. 119pp 19381 291 24x Fiche 50-000.83/04/25,830304002t
- 8305020258 Ack receipt of 830407 ltr informing NRC of steps taken to correct violation noted in IE insp. Repts 50-222/83-09 & 50-211/83-08 MARTIN:T T Division of Engineering & Technical Programs 83/04/26 UDERITZ:R A Public Bervice Flactric & Cas Co of New Jersey 1p 18277 268 248 F4-66 90-272 2006/26, 8305020258

tion noted in IE Insp ns nsive ents New Jersey Technical 4/26,8305020258

- B303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New York, Inc | 155p | 18382 047 | 24% Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 188p 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 830304002B IE info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list enci JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 1844i 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc 112pp 18382 282 24% Fiche 50-000.83/05/04/8303040030
- B303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Cansolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031
- B303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24x Ficho 50-000, B3/05/06, B303040033
- 8305190163 Forwards IE Insp Repts 50-272/83-14 & 90-311/83-11 on 830321-25 & notice of violation MARTIN, T Division of Engineering & Technical Programs 83/03/06 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 18502 240 24X Fiche 50-272.83/05/06.8305190163
- --B305190174 IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25
 Noncompliance noted failure to adhere to radiation
 protection procedures & failure to use suitable measurements
 of airborne radioactivity.per IOCFR20 103(a)(3)
 NIMITZ,R L. SHANBAKY,M Region 1, Office of Director 83/05/06
 13pp 18502 243 24% Fiche 50-272,83/05/06,8305190163
- 8305160085 Forwards response to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/82-33 & 50-311/82-31 on 820405-1016 Corrective actions operational test group established to verify testing requirements Civil penalty fee encl UDERITZ.R A Public Service Electric & Oas Co of New Jersey 83/05/09 DEYOUNG,R C Director's Office Office of Inspection and Enforcement 7pp 18451 027 24Y Fiche 50-272.83/05/09.8305160085
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list anci
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303240285 Ack receipt of B30425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-11 & 50-31/83-10 MARTIN.7 T Division of Engineering & Technical Programs B3/05/19 UDERITY.R A Public Service Electric & Gas Co of New Jersey 2pp 18548 107 24X Fiche 50-272,83/05/19.8305240285
- --8305240291 Responds to NRC 830525 ltr re violations noted in IE Insp. Repts 50-272/83-11 & 50-311/83-10 Corrective actions all badges improperly issued destroyed Individual responsible no langer in security may position.

 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 83/04/25 Region in Office of Director ip 18548 109 24X Fiche 50-272,83/05/17,8305240285
- B305270043 Ack receipt of B30505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation resecurity access control denied STAROSTECKI.R Division of Project & Resident Programs 83/05/23. UDERITI.R A Public Service Electric & Gas Co of New Jersey 2pp 18638 345 24% Fichs 50-272,83/05/23,8305270043

- ---8305270053 Responds to NRC 830405 itr re violations noted in IE Insp.
 Repts 50-272/83-08 & 50-311/83-07 Corrective actions &
 request for reduction in severity level of violation encl
 Encls withheld (ref 100FR73 21)
 UDERITZ.R A Public Service Electric & Gas Co. of New Jersey
 B3/03/03 Region i, Office of Director 3pp 18438 347 24X
 Fiche 50-272,83/05/23 8305270043
- 8305270164 Ack receipt of 83050? Itr forwarding payment of proposed civil penalty Response to notice of violation & proposed imposition of civil penalty will be evaluated & corrective actions examined during future insp

 AXELRAD. J A Enforcement Staff 83/05/25 UDERITZ.R A Public Service Electric & Qas Co of New Jersey 2pp 18638 064 24X

 Fiche 50-272,83/05/25,8305270164
- 8303040044 IE Info Notice 83-33, "Nonsepresentative Sempling of Contaminated Oil " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18447 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

- 8305170142 Forwards monthly operating rept for Apr 1983 ZUPKO.J M Public Service Electric & Oas Co of New Jersey 83/05/10 Director's Office, Office of Inspection and Enforcement ip 18466 272 24X Fiche 50-311.63/05/10.8305170142
- --8305170147 Monthly operating rept for Apr 1983 MILLER, L. K. Public Service Electric & Gas Co. of New Jaresy 83/05/10 11pp 18466 273 24X Fiche 50-311,83/05/10.8305170142

S Reportable occurrences, LERs & related correspondence

- 8304180491 Forwards LER 83-002/03L-0 Detailed event analysis enci MIDURA:H J Public Service Electric & Gas Co of New Jersey 83/04/06 HAYNES:R C Region 1. Office of Director 3pp 1799& 353 24X Fiche 50-311.83/04/06.8304180491
- --8304180513 LER 83-002/03L-0 on B30314.discovered pressuriter code safety volves 2PR3.2PR4 & 2PR5, tested by Wylo Labs during B30224-25.lifted below 2.485 psig plus/minus 17 pressure range & displayed heavy audible & visual seat leakage DICKEY.F Public Bervice Electric & Gas Co of New Jersey 83/04/06 Region 1. Office of Director ip 17996 356 24X Fichs 50-311,83/04/06.8304180491
- B305110271 Forwards supplemental LER B3-0B3/03X-1 Detailed event analysis encl ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/04/26 ALLAN, J Region 1. Office of Director 3pp 1B393 151 24X Fiche 50-311, B3/04/26, B305110271
- --8305i10274 Supplemental LER 82-083/03X-1 on 8208i2, during routine surveillance, control room operator received low syc water flow indication on containment fan coll unit (CFCU) 25 Caused by oysters or silt restricting CFCU flow FRAMM.R., ZUPKO. J M Public Service Electric & Gas Co of New Jersey 83/04/20 Region 1, Office of Director 1p 18393 154 24X Fiche 50-311,83/04/26.8303110271
- 8303040630 Notifies of CRGR Meeting 36 on 830427 to discuss findings of Salem Generic Implications Task Force BTELLO,V Committee to Review Generic Requirements 83/04/27 EISENHUT,D O Office of Nuclear Reactor Regulation, Director JORDAN,F L Director's Office, Office of Inspection and Enforcement CUNNINOHAM,R E Office of Nuclear Material Safety & 8
- 8305040262 Forwards summary listing short- & long-term actions & completion schedules re 830222 & 25 reactor trip breaker svents Corrective action program will also be applied to Unit 2 currently scheduled to return to svc in June 1983 UDERITZ.R A Public Service Electric & Qas Co of New Jerasy 83/04/28 EISENHUT, D O Division of Licensing lipp 18323 249 24X Fiche 50-272,83/04/28,8305040262
- 8305160096 Forwards LER 83-012/03L-0 Detailed event analysis encl ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/04/28 ALLAN. J Region 1. Office of Director 3pp 18452 015 24X Fiche 50-311.83/04/28.8305160096
- --8305160102 LER 83-012/03L-0.on 830406.i0-ton Cardox sys pilot valve found in closed position & all low pressure sys declared inoperable Caused by inadequacies in sys recharging operation on 830304 Procedures revised FRAHM.R Public Service Electric & Gas Co of New Jersey 83/04/27 Region in Office of Director ip 18452 018 24X Fich 50-311.83/04/28.8305160096

- 8305060480 Forwards LER 83-011/03L-0 Detailed event analysis encl ZUPKG.J M Public Service Electric % Gas Co of New Jersey B3/04/29 ALLAN,J Region I Office of Director 3pp 18348 131 24X Fiche 50-311.63/04/29.83050.60480
- --B305060489 LER 63-011/03L-0 on 830401.disrovered that monthly testing of control room emergency will conditioning sys was overlooked Caused by insploder 645 cald requiring testing being erroneously stated Card revised FRAHM.R Public Service Electric & Gas Co. of New Jersey 83/04/27 Region i. Office of Director ip 18348 134 24X Fiche 50-311.83704/29,8305060480
- 8305090244 Responds to 830329 memp re mgt 2 technical issues of ATWS events Issues to be addressed in NUREG-1000. "Generic Implications of ATWS Events at Salem Nuclear Power Plant" RHR capability addressed in Unresolved Safety Issue A-45 DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/27 EPLERE P Epler. E P Epler
- --8303090255 Requests comments re need for effective leadership in light of ATMS event failure of RHR sys & small break mitigation & failure of institutions to employ best available technology EPLER. E. P. Epler. E. P. 83/03/27 PALLADINO. N. J. Commissioners EBERSOLE. J. C. ACRS Advisory Committee on Reactor Safeguards CULLER. F. L. Electric Power Research Institute 10pp 16381 091 24X Fiche 50-272,83/04/29,8305090244
- B305170064 Responds to B30412 petition © 0418 amend, requesting that NRC order PSE&G to show cause why facility restart should not be restrained Patition denied based on encl Director's Decision DENTON, HR Office of Nuclear Realtor Regulation, Director B3/04/29 RUDRIGUEZ. J H New Jersey, State of 3pp 18474 184 24X Fiche 50-272, 83/04/29, 8305170064
- --8305170085 Director's Decision DD 83-6, denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart until listed actions taken DENTON.H R Office of Nuclear Reactor Regulation, Director 83/04/29 8pp 18494 187 24X Fiche 30-272,83/04/29,8305170064
- --8305170075 Safety evaluation re restait of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue
 ** Office of Nuclear Reactor Regulation Director 83/04/28
 45pp 18474 195 24X Fichs 50-272-83/04/29.8305170064
- --8305170110 Notice of issuance of Director's Decision DB 83-6 denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart CASE.E G Office of Nuclear Reactor Regulation. Director 83/04/29 2pp 18474 336 24X Fiche 50-272,83/04/29.8305170064
- B305170674 GENERIC IMPLICATIONS OF ATMS EVENTS AT THE SALEM NUCLEAR POWER PLANT Generic Implications
 # Office of Nuclear Reactor Regulation, Director NUREG-1000 VOI B3/04/30 149pp Available at NRC \$4 50 18481 183 24X Fiche 50-272.83/04/30.8305170674
- 8305170232 Informs Commission of findings of Salem ATHS generic implications task force re overall mpt capability & performance & reactor trip sys reliability DIRCKS.W J Office of the Elecutive Director for Operations 8ECY-83-15B 83/05/02 1570p 18476-184 24X Fiche 50-272,83/05/02.8305170232
- 8305100004 PNS-I-83-011 on 830504, security officer received bomb threat on inside plant telephone line from maje caller Search initiated No bomb found Call considered hoax MCKEOHN, GDDY, JOYNER Region 1. Office of Director 83/05/04 ip 18377 251 24X Fiche 50-272.83/05/D4.8305100004
- B305160118 Forwards LER 83-015/03L-0 Detailed event analysis encl ZVPKO.J M Public Service Electric & Oas Co of New Jersey B3/03/05 ALLAN,J Region 1. Office of Director 3pp 18450 126 24x Fiche 50-311,83/05/05.8305160118
- --B305160123 LER B3-015/03L-0 on B30407, during routine shutdown for refueling, testing results of four mechanical snubbers revealed that devices did not meet Tech Spoc requirements Cause not stated Snubbers returned to manufacturer FRAHM.R Public Service Electric & Gas Co of New Jersey B3/05/04 Region 1, Office of Director 1p 18450 129 24X Fiche 50-311, 83/05/05.8305160118

- B305120434 PNS-1-B3-013 on B30502 Lower Alloways Creek,NJ, police dept informed licensee of planned, peaceful demonstration to protest facility restart scheduled for B30508 No press release planned MCHEGWN.L. agory,A T., JOYNER-J Region 1, Office of Director B3/05/06 ip 18431 131 24X Fiche 50-272,83/05/06.8305120434
- B305140052 Forwards LER 83-013/03L-0 Detailed event analysis encl ZUPKO, J M Public Service Electric & Gas Co of New Jersey B3/05/06 ALLAN, J Region I, Office of Director 5pp 18453 023 24X Fiche 50-311,83/05/06.8305160052
- --9305169057 LER 83-013/03L-0 on B30409, during routine shutdown, lube oil temp increases observed on charging pump 22 Caused by restricted svc water flow to pump due to oyster shells & miscellaneous mollusks Shells removed FRAHM.R Public Service Electric & Gas Co of New Jersey 83/03/04 Region 1. Office of Director ip 18453 028 24X Fiche 50-311,83/05/06.8305160052
- 8305170367 Forwards LER 83-006/04L-0 Datailed event analysis encl ZUFKO, J M Public Service Electric & Gas Co of New Jersey 83/05/06 ALLANJ Region 1. Office of Director 4pp 18466 082 24X Fiche 50-311, 83/05/06, 8305170367
- --8305170370 LER 83-006/04L-0 on 830408, decreased sensitivity of Channel 2R4(C plant vent noble gas monitor rendered waste gas discharge line automatic isolation feature inoperable Caused by leakage on monitor sample lines & internal connections FRAHM, R Public Service Electric & Gas Co of New Jersey 83/05/04 Region 1. Office of Director ip 18466 086 24X Fiche 50-311,83/05/06,8305170367
- 8305180830 Forwards 830506 order confirming commitment to implement &/or maintain items specified in 830428 itr re reactor trip breaker failures
 EISENHUT, D.G. Division of Licensing 83/05/06 UDERITZ, R.A.
 Public Service Electric & Qas Co. of New Jersey ... 3pp. 18506 001
 24X Fichs 50-272,83/05/06,8305180830
- --B305180836 Order confirming licensee commitments to implement &/or maintain items specified in B30428 ltr re reactor trip breaker failures, effective immediately EISENHUT, D.Q. Division of Licensing B3/05/06 Public Service Electric & Qas. Co. of New Jarsey App. 18506-004 24% Fiche 50-272,83/05/06,8305180830
- B305200337 Forwards LER B3-014/03L-O betailed event analysis encl ZUPKG, J M Public Service Electric & Gas Co of New Jersey B3/05/11 ALLAN, J Region I. Office of Director 3pp 18514 253 24X Fiche 50-311.83/05/11.830220537
- --B305200546 LER B3-014/03L-0 on B30413 & 19 operating loads on 2A 4-kV & 460-volt vital buses tripped Caused by spurious operation of safeguards equipment control sys RHR pump 21 restarted Contract written for further investigation FRAHM.R Public Service Electric & Gas Co. of New Jarsey B3/05/11 Region 6, Office of Director 1p 18514 256 24X Fiche 50-311,83/05/15 8305200537
- B305250501 LER 83-016/04L-O on 830418 \$ 22.small amounts of low level idquid radwaste released to util-controlled area from waste monitoring tank 21 Caused by leakage from liquid waste systemponents Valve iLHI3 flange tightened H/830518 ltr FRAMM.R . ZUPKD.J M Public Service Electric & Gas Co of New Jersey B3/05/11 ALLAN.J Region i. Office of Director Spp 18588 291 24% Fiche 50-311.83/05/11.8305250501
- T Hearing transcripts on non-antitrust matters
- B305020527 Unofficial transcript of Commission B30426 public meeting re-possible vote on restart in Washington BC Pp 1-107 * Commissioner* 83/04/26 127pp 18284-075 24X Fiche 50-272.83/04/26.8305020529
- 8305170087 Transcript of Commission 830512 meeting in Mashington.DC to discuss evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation encl # Commissioners 83/05/12 81pp 18495 226 24X Fiche 50-272,83/05/12,8305170087
- B305230130 Transcript of Commission B30518 public meeting in Washington,DC re evaluation of implications of facility event (Part I) Pp 1-82 Supporting documentation encl * Commissioners B3/05/18 97pp 18577 110 24X Fiche 50-272,83/05/18,8305230130

- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- 8305160195 Addl response to FDIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress FELTON, J M Division of Rules and Records 83/03/31 CLARK, R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312,83/03/31,8305160195
- --8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility GIBSON.J Standardization & Special Projects Branch 82/10/18 MINER.S Operating Reactors Branch 4 2pp 18462 194 24X Fiche 50-312.83/03/31.8305160195
- --8305160222 Forwards SALP evaluation input, per Sternberg 821014 memo Info consists of safeguards licensing portion MCCORKLE, G W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG.L Region 5. Office of Director 3pp 18462 235 24X Fiche 50-312,83/03/31.8305160195
- B305100099 Requests status of NRC review of Rev 4 to security training & qualifications plan Response dtd B2i012 fully responsive to Region V requirements, per NRC 821103 request HAMMOND.H J Sacramento Municipal Utility District B3/05/04 BYOLZ.JF Operating Reactors Dranch 4 ip 18377 254 24X Fiche 50-312, B3/05/04, B305100099
- 8305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EISENHUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11.8305110034
- B305240314 Forwards IE Safeguards Insg Rept 50~312/83~13 on 830503~05 No noncompliance noted Rept withheld (ref 10CFR73 21) NORDERHAUG.L R Region 5, Office of Director 83/05/18 RODRIGUEZ.R J Sacramento Municipal Utility District 2pp 18548 193 24X Fiche 50~312,83/05/18.8305240314
- 9 Adjudicatory correspondence
- 8305130099 Forwards licensee 830428 ltr re emergency feedwater instrumentation & control (EFIC) sys & upgraded auxiliary feedwater sys.NUREG-0737. Items II E 1 2 & II K 2 10 Ltr provides new info on mod completion schedule W/svc list BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Sacramento Municipal Utility District 83/05/11 ROSENTHAL.A S , BUCK.J H. KOHL.C N Atomic Safety and Licensing Appeal Panel 3pp 18437 223 24X Fiche 50-312.83/05/11.8305130099
- P Operating license stage documents & correspondence
- 8305230583 Forwards backfit cost info in response to 830208 ltr Two 3.500 kW standby diesel generators, diesel generator bldg, auxiliary bldg addition, associated electrical equipment & new computer sys added per NUREG-0737
 MATTIMOE, J Sacramento, Municipal Utility District 83/03/16
 TOURTELLOTTE, J Regulatory Reform Task Force 4pp 18541 318 24X
 Fiche, 50-312, 83/03/16, 8305230583
- 8305230720 Forwards list of utils responding to requests for cost flgures on backfitting TOURTELLOTTE. J. Regulatory Reform Task Force 83/04/11 PALLAPINO.N J. Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- 8305060419 Application for proposed Amend 93 to License DPR-54, changing titles for positions within mgt structure RDDR16UEZ.R J Sacramento Municipal Utility District 83/04/19 EISENHUT.D & Division of Licensing 1p 18343 273 24X Ficha 50-312,83/04/19.8305060419
- --8305060421 Proposed Tech Specs for Amend 93 to License DPR-54, changing titles for positions within mgt structure

 * Sacramento Municipal Utility District 83/04/19 5pp
 i8343 274 24X Fiche 50-312,83/04/19,8305060419
- 8305020592 Notifies that IAEA representatives plan to visit facility on 830505 & 06 to svc cameras & audit records

 8TOL2.JF Operating Reactors Branch 4 83/04/21 RODRIGUEZ.R J. Sacramento Municipal Utility District 2pp 18284 227 24X Fiche 50-312,83/04/2),8305020592

- B305020383 Confirms B30302 submittal date for proposed solution to three remaining open items on NRC review of upgraded auxiliary feedwater sys per NUREG-0737, Item II E 1 i Contractor requested to provide cost estimate for study RDDRIGUEZ, R J Sacramento Municipal Utility District B3/04/27 BT0LZ, J F Operating Reactors Branch 4 ip 18276 313 24x Fiche 50-312,83/04/27,8305020383
- B3050203B4 Forwards response to 821115 request for add1 info re NURGe-0737, Items II E i 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/ii oversize drawings Aperture cards are available in PDR RODRIGUEZ.R J Sacramento Municipal Utility District 83/04/28 STOLZ.J F Operating Reactors Branch 4 Jpp 18283 327 24X Fiche 50-312.83/04/28.8305020384
- --B305020372 Rev 3 to "Auxiliary Feedwater Sys Sys Description " Babcock & Hilcor Co BMNP-20004 (6-76) R3 B3/04/04 54pp 18283 332 24X Fiche 50-312.83704/28.B305020384
- B305020415 Forwards results of analysis of station electrical distribution sys voltages & comparison of test & analytical results Differences between test voltages & analytically derived voltages within 37 value RODRIOUCZ.R J Bacramento Municipal Utility District 83/04/28 BTOLZ.J F Operating Reactors Branch 4 7pp 18273 117 24X Fiche 50-312.83/04/28,8305020415
- 8305030577 Board Notification BN-83-21C forwards generic evaluation for B&W designed plants Designs maintain DHR by natural circulation through steam generators under transient & accident conditions
 EISEMHUT, D @ Division of Licensing 83/04/28 Atomic Safety and Licensing Appeal Panel 2pp 18305 335 24X Fiche 50-312.83/04/28, 8305030577
- --B305030587 Forwards generic evaluation for all D&W dosigned plants to maintain DHR by natural circulation Design acceptable MATTBON, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 83/04/18 EIBENHUT, D 9 Division of Licensing 15pp 18305 338 24x Fiche 50-312, 83/04/28, 8305030577
- B305110126 REVIEW OF THE RANCHO BECO NUCLEAR GENERATING STATION UNIT
 NO 1 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYSIS Docket
 NO 50-312 (Bacramento Municipal Utility District)
 ILBERG,D, YOUNGBLOOD,R, PAPAZOGLOU,I A Brookhaven National
 Laboratory FIN A-3393 NUREG/CR-3013 B3/04/30 Division of
 Bafety Technology 49pp Available at NRC \$4 75 18416 266 24X
 Fiche 50-312,83/04/30,8305110126
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of emends to OLs Svc list encl
 EISENMUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
 Fiche 30-000:83/05/02.8305020455
- 8303060365 Notification of 630306 meeting w/82W Dwnors Group in Bethesda.MD to discuss core barrel failure at Rancho 8eco & Crystal River 3.future plans for resolving problem & justification for continued operation MINER.G Operating Reactors Branch 4 83/05/02 STDLZ.J Operating Reactors Branch 4 29p 18353 092 24X Fiche 30-000.83/05/02.8305060365
- 8305060415 Forwards resolution of open items re NUREG-0737. Item 11 8 3. "Post-Accident Sampling Sys." per 830215 evaluation & 830314 teicon No significant radiation effects anticipated LATHAM.W K Sacramento Municipal Utility District 83/05/02 8TOLZ.J F Operating Reactors Branch 4 2pp 18343 279 24x Fiche 50-312.83/05/02.8305060415
- B305060429 Forwards response to B30405.06 & 07 ltrs & 830419 telcon requesting add1 info on spent fuel pool expansion LATHAM.H K Bacramento Municipal Utility District 89/05/02 BTOLT.J F Operating Reactors Branch 4 16pp 18343 243 24% Fiche 50-312,83/05/02.8305060429
- 8305060638 Requests remittance of fee for 830125 application re organizational changes within 15 days of receipt of htr D1005.R M License Fee Management Branch 83/05/02 RODRIQUEZ.R J Sacramento Municipal Utility District ip 18359 200 24X Fiche 30-312,83/05/02,8305060638
- B305060645 Advises that Class III fee appropriate for each listed application filed w/NRR for review Request of 830331 for exemption from order, confirming commitment to implement NUREO-0737, not exempt from fees MILLER, W O. License Fee Management Branch 83/05/02 RODRIGUEZ, R J Bacramento Municipal Utility District 2pp 18358, 362 24X Fiche 50-312, 63/05/02, 8305060645

- B305070553 Requests remittance of fee due for review of B30217 amond application re implementation of NUREG-0737 Items, ploviding justification for imposition of fees in response to B30401 ltr contesting fee MILLER, N.O. License Fee Management Bianch B3/05/02 MIDRIGUEZ, R.J. Sacramento Municipal Utility District 1p 18367-360 24X Fiche 50-312, 83/05/02, 8305070553
- 8305100344 Submits info re RURLG-0737, ltem II E i 1. 'Auxiliary Feeduate: Sys Upgrade Review." per 83040° request info resolves protection of sys from internal missiles & addi protection required foi condensate storage tank RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/02 STOLZ.J F Operating Reactors Branch 4 2pp 18378 23: 24x Fiche 50-312,83/05/02,8305100344
- 8305040323 Goard Notification 83-057 forwards differing prof opinions re sys interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Uniosolved Safety Issue A-17 EISENHUT.D & Division of Licensing 83/03/04 PALLADINO,N Commissioners 22pp 18337 139 24% Fiche 50-000,83/05/04,8305906323
- 8305100229 Forwards response to questions laised during 830422 telcon re util plans concerning NUREG-0737, Item II F 1.
 "Containment Instrumentation Upgrades" Dedicated recorder for hydrogen concentration will be provided RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/06 810LZ.J F Operating Reactors Branch 1 3pp 18374 128 24X Fiche 50-312.83/05/06.8305100229
- 8305100296 Advises that util reviewed all items in Categories I B.11 A & IV of technical evaluation rept to verify that adequate justifications for continued operation of safety-related electrical equipment exist RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/06 STOLZ.JF Operating Reactors Branch 4 2pp 18371 247 24% Fiche 50-312,83/05/06,8305100296
- B30310033B Forwards responses to 830419 questions re 830106 submittal of proposed mod for reactor cavity annular seal plate storage Three primary fission product boundaries designed to withstand concurrent LOCA 's essent loads.
 RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/06 STOLZ.J F Operating Reactors Branch 4 2pp (8378 327 24X Fiche 50-312,83/05/06.8305100338
- 8305070659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fichs 50-000,83/05/09,8305090639
- B305310171 Provides supplemental info re proposed Amend 86 to License DPR-54,per NRC B30419 verbal request Method of calculating losses in tendons 6 reduction off rejacking force of detensioned tendons discussed RODRIOUT7.R J Sacramento Municipal Utility District 83/05/11 MINOR, 5 NRC No Detailed Affiliation Given 27pp 18652 299 24X Fiche 50-312.83/05/11.8305310171
- Q Inspection reports, 1E Bulletins & correspondence
- 8305160192 FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility CLARK.R San Francisco Examiner 83/02/22 FELTON.J M Division of Rules and Records to 18462 170 24% Fiche 50-312,83/02/22,8305160192
- B212060385 IE Info Notice 83-14, "Dewatered Spent ion Exchange Resin Busceptibility to Exothermic Chemical Reaction" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 244 Fiche 30-000.83/03/21.8219060385
- B305160255 Partial response to FOIA request for all documents dtd B20101 or efter detailing or referring to SALP for facility FELTON, J M Division of Rules and Records B3/03/24 CLARK, R San Francisco Examiner 2pp 18472 241 24X Fiche 50-312, B3/03/24, B305160255
- --B21115006B Discusses performance evaluation of SALP for facility LERs contained adequate info enabling knowledgeable readers to understand events; however, LER 81-39 failed to adequately inform reader of event
 SEYFRIT.K V Reactor Operations Analysis Branch B2/11/05
 STERNBERGO D M Division of Resident Reactor Project & Engancering Programs 1p 18473 005 24x Fiche 50-312,83/03/24,8305160255

- --8305160271 Natification of 830103 neeting v/util in Sacramento.CA to discuss SALP for Jul 1981 - Sept 1982 Meeting agenda encl * Region 5. Office of Director 82/12/02 Region 5. Office of Director 3pp 18473 018 24X Fiche 50-312.83/03/24.8305160255
- 8305160195 Add1 response to FGIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress FELTON, J M Division of Rules and Records 83/03/31 CLARK, R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312, 83/03/31, 2005140195
- --9211030191 Provides results of reactor operator & senior reactor operator grams administered Jul 1981-Supt 1982, as input to SALP rept All operators passed grams
 BECKHAM.D H Operator Licensing Branch 82/10/19 MINER.S Sacramento Municipal Utility District 13pp 18462 211 24X Fiche 50-312,83/03/31,8305160195
- --B211180301 Forwards NRR input for util SALP.per 821014 memo MINER:S Operating Reactors Granch 4 82/11/16 STERNBERG, D M Region 5. Office of Director 7pp 18462 226 24X Fiche 30-312.83/03/31.8305160195
- --8305160400 Notifies that SALP board scheduled to meet 821123 Evaluation period remains Jul 1981 - Sept 1982 ENGELKEN, R H Region 5, Office of Director 82/10/04 DENTOMH R Office of Nuclear Reactor Regulation, Director DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director MICHELSON, C Director's Office 1p 18462 193 24x Fiche 50-312.83/03/31,8305160195
- --8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility
 OIBSON.J Standardization & Special Projects Branch 82/10/18
 MINER,S Operating Reactors Branch 4 2pp 18462-194 24X
 Fiche 50-312,83/03/31,8305160195
- --8305160213 Forwards draft NRR SALP input re licensing activities for Jul 1981 Espt 1982 Comments received by 821115 will be considered in final rept fineRRS Operating Reactors Branch 4 82/11/10 EISENHUT, D 0 plvision of Licensing MATTSON, R Division of Systems Integration (post 811005) VOLLHERR Division of Engineering 15pp (8462-196 24X Fiche 50-312,83/03/31,6305160195
- --8305160218 Forwards SALP for Jul 1981 Sept 1982 Overall performance of licensed activities acceptable Prof & responsive attitude in dealings w/NRC & in day-to-day conduct of safety-related activities noteworthy STERNBERG, D M Region 5. Office of Director 82/12/15 ENGELMENR H Region 5. Office of Director 2pp 18462 233 24X Fiche 50-312,83/03/31.8305160195
- --8305160222 Forwards SALP evaluation input.per Sternberg 821014 memo Info consists of safeguards licensing portion MCCORKLE.0 W Power Reactor Safeguards Licensing Branch 82/11/04 NDRDERHAUG. Region 5. Office of Director 3pp 18482 235 24X Fiche 50-312.83/03/31.8305140195
- E303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24x Fiche 50-000.83/04/15,8303040021
- 930304002J lE Info Notice 93-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 16383 989 24x Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " 8vc list enc! JORPANIE L Division of Emergency Preparedness & Engineering " Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc. 119pp 18381 271 24x Fiche 50-000.83/04/25.8303040025
- B303040026 IE Info Natice B3-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice B3-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANE L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027

- 8305020483 Forwards calculations showing that wall enclosing nuclear svc station transformer can withstand 101 mph wind & associated wind generated missiles, per IE Bulletin 80-11 Shield structure will be installed by 830901 RDDR10UEZ.R J Sacramento Municipal Utility District 83/04/28 STOLZ, JF Operating Reactors Branch 4 App 18282 337 24X Fiche 50-312.83/04/28.8305020483
- B303040028 IE Info Notice B3-26. "Failure of Safety/Relief Valve Discharge Lime Vacuum Breakers " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against flant Equipment " Bvc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030
- B303040031 IE Info Notice B3-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl URDAN.C L Division of Emergency Preparedness V Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040039 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Ract Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B305i00381 Informs that 3 months needed to assess impact upon pump operability & potential for auxiliary feedwater pump cavitation in response to IE Bulletin 80-04 Next rept will be provided by 831104
 RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/06
 BTOLL.J F Operating Reactors Branch 4 2pp 18378 214 24X
 Fiche 50-312, 83/05/06, 8305100381
- 8305230456 Forwards supplemental info to 830324 response to 1E Bulletin 83-04 re control rod drive breaker failures Commitment to in-place funtional test of breakers prior to startup ack Summary of maint history encl RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/05/09 HARTIN, J. B. Region 5. Office of Director 167pp 18538 011 24X Fiche 50-312,83/05/09,8305230456
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524.003 24X Fiche 50-000,83/05/11.8303040034
- 8305240314 Forwards IE Safeguards Insp Rept 50-312/83-13 on 830503-05 No honcompliance noted Rept withhold (ref 10CFR73 21) NORDERHAUG-L R Region 5, Office of Director 83/05/18 RODRIGUEI, R J Sacramento Municipal Utility District 2pp 18548 193 24X Fiche 50-312,83/05/18,8305240314
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/17 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303270080 Requests extension to 831015 to provide schedule for accomplishing proposed actions to close autstanding issue re IE Bulletin 79-01B items Exemptions from 10CFR50 49 & Rev 2 to Reg Guide 1 97 RODRIGUEZ.R J Sacramento Municipal Utility District 83/05/20 STOLZ.JF Operating Reactors Branch 4 2pp 18638 291 24X Fiche 50-312,83/05/20.8305270080
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Gil " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. S Northeast Utilities Service Co 114pp 18447 007 24X Fiche 50-000,83/05/26,8303040046
- R Pariodic operating reports & related correspondence
- 8305240326 Monthly operating rept for Apr 1983 W/830513 ltr COLOMBO,R , DUBRE,R.P. Sacramento Municipal Utility District 83/04/30 Director's Office. Office of Inspection and Enforcement App 18549 279 24X Fiche 50-312.83/04/30.8305240326

S Reportable occurrences, LERs & related correspondence

- 8305160255 Partial response to FOIA request for all documents dtd B20101 or after detailing or leferring to SALP for facility FELTON.V M Division of Rules and Records 83/03/24 CLARK.R San Francisco Examiner 2pp 18472 241 247 Fiche 50-312,83/03/24. B205160255
- --8211100028 Provides engineering evaluation of 810807 turbine/reactor trip Event review agrees w/licensee Event had little effect on plant safety Automatic functions occurred substantially as expected given concurrent operator actions PELLET, J. L. Reactor Operations Analysis Branch 82/10/26 SEYFRIT, K.V. Reactor Operations Analysis Branch 4pp 18472 290 24X Fiche 50-312,83/03/24,8305160255
- --8211110445 Discusses licensee reporting of Bi0807 turbine/reactor trip Proposed LER rule would require more detailed & complete event rept W/o entl ORNSTEIN.H L. Reactor Operations Analysis Branch 82/11/04 SEYFRIT.K V Reactor Operations Analysis Branch 3pp 18473 006 24X Fiche 50-312,83/03/24,8305160255
- 8305030287 Forwards LER 83-013/03L-0 Detailed event analysis submitted RODRIGUEZ.R J Sacramento Municipal Utility District 83/04/12 MARTIN.J B Region 5. Office of Director 2pp 18300 058 24X Fiche 50-312,83/04/12,8305030287
- --8305030270 LER 83-013/03L-0 on 830318 reactor bldg purge discharge fan A-336 carbon adsorber filter bank & auxiliary/spent fuel bldg filter sys A-5248 found below lech Spec for lodide removal Charchoal will be replaced by 830601 COLOMBO, R W Sacramento Municipal Utility District 83/04/12 Region 5. Office of Director ip 18300 060 24% Fiche 50-312,83/04/12,8305030287
- 8305030551 Forwards LER 83-014/01T-0 Detailed event analysis submitted RODRIGUEZ-R J Bacramento Municipal Utility District 83/04/19 MARYIN.J B Region 3. Office of Directos 2pp 18303 334 24X Fiche 50-312.83/04/19.8305030551
- --8305030561 LER 83-014/01T-0 on B30406, reactor bldg purge injet & outlet valves failed local leak rate surveillance test Caused by damaged seats for valves SFV-53504 & SFV-53605 & seats for valves SFV-53604 & SFV-53504 and instanct COLOMBO, R W Sacramento Municipal Utility District 83/04/19 Region 5, Office of Director ip 18303 336 24% Fiche 50-312,83/04/19,8305030551
- 8305130163 RD 83-016 on 830331. Listed shubbers failed acceptance criteria.per Surveillance Test SP 201 108 Shubbers reworked Burveillance Insp 201 10A will be performed prior to coming out of cold shutdown ROBRIGUEZ.R J Sacramento Municipal Utility District 83/04/28 MARTIN.J D Region 5. 0ffice of Director 2pp 18437 337 24X Fiche 30-312. 83/04/28 8305130163
- B305130219 Forwards LER 83-017/03L-O Detailed event analysis submitted RDDRIGUEZ,R J Sacramento Municipal Utility District B3/04/28 MARTIN,J B Region 5, Office of Director 2pp 18439 320 24X Fiche 50-312,83/04/28,8305130219
- ---B305130231 LER 83-017/03L-0 on 830331/testing of reactor coolant pump power relays revealed five dovices unacceptable Cause of failure unknown Relays sent to manufacturer for repair Add1 info will be provided COLOMBO.R W Bacramento Municipal Utility District 83/04/28 Region 5. Office of Director ip 18439 322 24X Fiche 30-312,83/04/28,8305130219
- 8305130105 RO 83-01 on 830408, following mgt safety review committee Fire Protection Audit 27, determined reactor coolant pump fire detectors not tested per Tech Spec requirements Caused by misapplication of Tech Spec provision ROBRIGUEZ, R J Sacramento Municipal Utility District 83/04/27 MARTIN, J B Region 5, Office of Director 2pp 18436 012, 24X Fiche 30-312,83/04/29,8305130105
- B305130160 RD B3-02 on B30326, motor driven fire pump P-440 administratively taken out of svc due to necessity to drain cooling tower circulating water basin during outage Recovery procedure established LATHAM.W K Sacramento Municipal Utility District B3/05/02 MARTIN.J B Region 5, Office of Director ip 18438 116 24X Fiche; 50-312.83/05/02,8305130140
- 8305240309 Interim deficiency rept recore support structure bolting Initially reported on 830419 Evaluation of corrective action in progress, Next rept will be sent by 831101 COOK, J W Consumers Power Co 83/05/19 KEPPLER, J O Region 3, Office of Director, 3pp 18625 200 24X Fiche 50-000,83/05/19,8303260309

- --8305260311 Deficiency tept of vitrasonic test abnormal indications in upper barrel bolting of reactor internals Initially reported on 830328 Results of internal bolt than discussed Addi info will be forwarded
 TAYLOR, J.H. Babcock & Wilcox Co. 83/04/1! DEYQUNG, R.C. Director's Office, Office of Inspection and Enforcement Spp. 18625-205 24X Fiche 50-000.83/05/17.8305260309
- --8305260313 Updated deficiency rept to core barrel bolting vitrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
 TAYLOR, J. H. Babcock & Wilcox Co. 83/04/22 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp
 18625-210 24X Fiche 30-000,83/05/19 8305260309
- 8305270115 PNS-V-83-007 on 830920, while performing security duties, upon approaching truck being officeded, security officer observed individual throwing article into cab investigation revealed cocaine in small glass container Police notified SCHAEFER, D.W. NORDERHAUG, L.R. Region 5, Office of Director 83/05/23 ip 18638 165 24% Fiche 50-312,83/05/23,8305270115

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

- 8305200324 Forwards list of emergency response open items for which no written response required Open Items lesulting from recent emergency exercise will be reflected in future rept MARSHALL. J. R. Arkansas Power & Light Gu. 83/04/08 CDLLINS. J. T. Region 4, Office of Director 2pp 16516 308 24X Fiche 50-313,83/04/08,8305200326
- 8304270424 Releases public version of recised emergency plan implementing procedures FELTON.JM Davision of Rules and Records 83/04/22 Document Management Branch ip 18244 027 24% Fiche 50-313.83/04/22. 8304270424
- ---8304270426 Forwards public version of levised emergency plan implementing procedures, including Procedures 1.2 % 6 re assignment of personnel to emergency response organization, notifications & emergency response ctis-lespectively MARSHALL, J.R. Arkansas Power & Light Co. 83/04/05 COLLINS, J.Y. Region 4. Office of Director ip 18744 028 24% Fiche 50-313,83/04/22,8304270424
- --830427042/ Public version of revised emergency plan implementing procedures including Procedures 1.2 % ore assignment of personnel to emergency response organization, notifications & emergency response ctrs.respectively # Arkansas Power & Light Co 83/03/07 86pp 18244 029 24X Fiche 30-313.83/04/22.830427042
- 8305060579 Releases public version of revised emergency plan implementing procedures FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch ip 18359 190 24X Fiche 50-313,83/04/25, 8305060575
- --8305060503 Forwards public version of revised Emergency Plan Implementing Procedures 1904 O6 reliading tall plume tracking & dose integration & 1904 O6 to protective action recommendations * Arkansas Power & Light Co 83/04/14 NRC No Detailed Affiliation Given 1p 18359 191 24X Fiche 50-313,83/04/25,8305060575
- --8305060591 Public version of revised Emergency Plan Implementing Procedures 1904 OA re radiological plume tracking & dose integration to 1904 O7 re protective action is commendations LEVING. J M. Arkansas Power & Light Co. 83/04/14 Spp 18359 192 24X Fiche 50-313,83/04/25.8305060575
- 8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Bpecs to require audit of emergency programs & security plan at frequency of at least once per 13 months CLARK.R A Operating Reactors Branch J 83/04/29 ORIFFIN, J Arkansas Power & Light Co 4pp 18434 262 24x Fiche 50-313,83/04/29.8305110193
- --8305110199 Amends 78 & 44 to Licenses UPR-51 > NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan CLARM.R A Deprating Reactors Branch 3 83/04/29 9pp 18434 266 24X Fiche 50-313.83/04/29.8305110193

- --B305110205 Notice of issuance > availability of Amends 78 & 44 to Licenses DPR-51 > NPF-6 respectively CLARK.R A Operating Reactors Branch 3 83/04/29 2pp 18434 275 24% Fithe 50-313.87/04/27.8305110193
- B305160280 Releases public version of revised nuclear contingency plan procedures
 FELTON, J M Division of Rules and Records 83/05/02 Document
 Management Branch 1p 18462 334 24% Fiche 50-313,83/05/02
- --8305160290 Forwards public version of revised Nuclear Contingency Plan Procedures 1, 2, 3, 5, 6, 7, 8, 9, 12, 13, 14 t 15 M/o encl MARSHALL, J R Ariansa's Power t Light Co 83/04/05 COLLINS, J T Region 4, Office of Director (p 18462 335 24x Fiche 50-313, 83/05/02, 8305160288
- 8305110034 Generic Ltr 83-21 to all licenseps of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law entorcement visits Svc list encl
 EISENNUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of frew York. Inc. 16pp 18540-095 24% Fiche 50-000.83/05/11.8305110034
- 8305170677 Forwards exemption from Section III L L of App R to 10CFR50 requirements to achieve cold shutdown within 72 h w/o use of affsite power SIGLZ.J F Operating Reactors Branch 4 83/05/11 GRIFFIN,J M Arkansas Power & Light Co 3pp 18496 321 24X Fiche 50-313.83/05/11.8305170677
- ~~@3051706B5 Exemption from Section III (1 to App R to (OCFRSO requirements to achieve cold shutdown within 72 h w/o use of offsite power EISE/MUT.D G Division of Licensing 83/05/11 Arkansas Power & Light Co 5pp 18496 324 24X Fiche 50-313.83/05/11.
- 8305180161 Informs that NUREG-0737.1tem III A 2 1. "Emergency Preparedness Upgrade Emergency Plans to App E. 100FR50." complete STOLZ-JF Operating Reactors Branch 4 CLARM.R A Operating Reactors Branch 3 83/05/11 GRIFFIN.JM Arkansas Power & Light Co 3pp 18502 348 24X Fiche 50-313.83/05/11.8305180161

H General correspondence

- 8305240139 Advises that correspondence distribution to Region IV will be modified to original plus three copies, per B Johnson request MARSHALL, J R Arkansas Power & Light Co 83/04/22 SEIDLE, W C Region 4, Office of Director ip 18548 334 24% Fiche 50-313,83/04/22,8305240139
- J Insurance & indemnity information
- 8305090421 Forwards NELIA & MAELU Certificates of Insurance to comply w/100FR50 54w Submittals from 830331 & 0422 misinterpreted to comply w/100FR140 & 140 15s MARSHALL.J R Ariansas Power & Light Co 83/05/03 STOLZ,J F Operating Reactors Branch A COULTINS,J T Region 4. Office of Director DINITZ,I NRC No Detailed Affiliation Given 6pp 18363 065 24X Fiche 50~313.83/05/03.8305050421
- 8305190363 Forwards NELIA & MAELU secondary financial protection Certificates of insurance 48 & 68, respectively, for CVB3, per 10CFR140 15(a)
 MARSHALL, J.R. Arkansas Power & Light Cq. 83/05/11 DINITZ, 1
 Antitrust & Economic analysis Branch (Utility Finance) 43pp
 18500 032 24X Ficha 50-313.83/05/11.8305190363
- P Operating license stage documents 5 correspondence
- 8305230364 Forwards cost info associated w/backfitting nuclear units, per JL Haulden 830224 commitment
 MARSHALL.J R Arkansas Power & Light Co 83/03/11 TOURTELLBITE, J
 Regulatory Reform Task Force 11pp 18546 234 24X
 Fiche 50-313-83/03/11,8305230364
- 8303240480 Forwards "Structural Evaluation of AR Nuclear One-Unit 1 & Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
 HARSHALL. J R Arkansas Power & Light Co 83/03/22 STOLZ, J F
 Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3 ip 17678 109 24X Fiche 50-313.83/03/22.8303240480

- --83032A0497 "Structural Evaluation of AR Nuclear One-Unit 1 Spent Fuel Storage Facility for Consolidated Fuel Storage "
 STURKEY, J J. BALLARD, T A Structural Dynamics Research Corp APL-01-014 83/01/15 74pp 17678 110 24X
 Fiche 50-313,83/03/22,8303240480
- --8303240495 "Structural Evaluation of Arkansas Nuclear One-Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage " STUBACY, J. J. DALLARD, T. A. Structural Dynamics Research Corp APL-02-013 82/11/24 75pp 17678
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting
 IDURTELLOTTE. J. Regulatory Reform Task Force 83/04/11
 PALLADIND.N. J. GELINSKY.V., AMEARNE.J.F. Commissioners 2pp
 18542 272 24X Fiche 50-000,83/04/11.8305230720
- 8305090147 Forwards Amend 77 to License DPR-51, safety evaluation & notice of issuance & availability Amend revises language for Tech Spec re inservice insp requirements for Class 1, 2 & 3 components

 870LZ.J F Operating Reactors Branch 4 83/04/18 GRIFFIN, J M Arkansas Power & Light Co 4pp 18367 266 24X

 Fiche 50-313,83/04/18,8305090147
- ~~8305090134 Amend 77 to License DPR-31, revising language of Tech Specs re inservice insp requirements for Class 1,2 & 3 components to conform w/codes & 8td Rule 10CFR30 55a STOLZ.JF Operating Reactors Branch 4 83/04/18 7pp 18367 270 24X Fiche 50-313,83/04/18,8305090147
- --8305090160 Safety evaluation supporting Amend 77 to License DPR-51 * Office of Nuclear Reactor Regulation, Director 83/04/18 10pp 18367 277 24X Fiche 50-313.83/04/18.8305090147
- --B209200375 "AR Nuclear One Unit 1 Inservice Insp Program." tachnical evaluation rept * Science Applications, Inc. NRC-03-82-096 SAI-186-028-39 B2/09/17 NRC - No Detailed Affiliation Given 16pp 18367-287 24X Fiche 50-313.83/04/18.8305090147
- --8305090179 Notice of issuance & availability of Amend 77 to License DRR-51 STOLZ: JF Operating Reactors Branch 4 83/04/18 App 18367 304 24X Fiche 50-313.83/04/18.8305090147
- 8303200541 Forwards revised schedule for completion of licensing procedures upgrade, per regulatory response & commitment control program Delay due to continuing support requirements for Unit 1 outage Upgrade to be completed by 830527 MARSHALL.JR Arkansas Power & Light Co 83/04/25 COLLINS, J T Region 4. Office of Director 2pp 18514 264 24X fiche 30-313,83/04/25,8305200541
- 8305110625 Forwards corrected Pages B & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-31 & NPF-6, respectively STDL2.J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/04/27 GRIFFIN, J M Arkansas Power & Light Co 2pp 18417 357 24% Fiche 50-313,83/04/27,8305110625
- --8305110426 Corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6: respectively * Dffice of Nuclear Reactor Regulation Director 83/04/27 2pp 18417 359 24X Fiche 50-313:83/04/27,8305110625
- 8303050125 Ack receipt of 830427 ltr w/corrections to safety evaluation for proposed spent fuel pool storage expansion Statement 15 carrected to indicate divers will not be permitted to exceed I rem whole body.per 830428 discussion w/O Vissing MARSMALL.J R Arkansas Power & Light Co 83/04/28 STOLZ, J F Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3 19 1834[347 24X Fiche 50-313,83/04/28,8303050125
- 8305050214 Advises that responses to Itoms 2 & 3 in NRC 830322 ltr re emergency feedwater sys will be submitted by 830530, per discussion w/G Vissing Response to Item 1 or schedule for response will also be provided MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J R Operating Reactors Branch 4 ip 8338 105 24X Fiche 50-313,83/04/28.8305050216
- 8305090440 Forwards response to 830329 request for add1 info re justifications for continued operation for Category I 8, II A & IV items Previous response reviewed for necessary changes per Franklin Rassarch Ctr evaluation MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J F Operating Reactors Dranch 4 128pp 18363 122 24X Fiche 50-313.83/04/28.8305090440

DOCKETED ITEMS

- 8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months CLARK, R A Operating Reactors Brench 3 83/04/29 GRIFFIN, J Arkansas Power & Light CO 4pp 18434 262 24X Fiche 50-313,83/04/29,8305110193
- --8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan CLARK, R A Operating Reactors Branch 3 83/04/29 9pp 18434 266 24X Fiche 90-313,83/04/29,8305110193
- --8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6; respectively CLARK:R A Operating Reactors Branch 3 83/04/29 2pp 18434 275 24X Fiche 50-313,83/04/29,8305110193
- 8305020455 Generic Ltr 83-19 to all power reactor 1/2 testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Evc list encl
 EIBENHUT, D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York Inc 50pp 18441 120 24X
 Fiche 50-000,83/05/02,8305020455
- 8305060365 Notification of 830506 meeting w/8&W Owners Group in Bethesde,MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & Justification for continued operation MINER,S Operating Reactors Branch 4 83/05/02 STOLZ,J Operating Reactors Branch 4 2pp 18353 092 24X Fiche 50-000.83/05/02.8305060365
- 8305120504 Forwards Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to require verification of leak testing of purge valves CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 B3705/03 0871FFIN. J Arkansas Power & Light Co 3pp 18443 141 24X Fichs 50-313.63/05/03.8309120904
- --8305120504 Amends 79 % 46 to Licenses DPR-51 & NPF-6, respectively, revising Tech Specs to require verification of leak rate testing of purge valves
 STOLZ, J F Operating Reactors Brench 4 CLARK, R A Operating Reactors Brench 3 B3/05/03 Ppp 18443 144 24X
 Fichs 50-313,83705/03,8305120504
- --8305120308 Safety evaluation supporting Amends 79 % 46 to Licenses DPR-51 & NPF-6, respectively # Office of Nuclear Reactor Regulation, Director 83/05/03 3pp 1843 153 24X Fichs 50-313.83/05/03.8305120504
- --B305120512 Notice of issuance & availability of Amends 79 & 46 to Licenses DPR-51 & NPF-6. respectively TRAMMELL.C M Operating Reactors Branch 3 B3/05/03 2pp 18443 156 24X Fiche 50-313,83/05/03,B305120504
- 8305090333 Forwards responses to NRC B30405 request for add1 info reuse of RADCAL gamma thermometer (RGT) for inadequate corecaling instrumentation RGT consists of sheathed thermocouples heater rod, core tube t jacket tube MARBHALL, J R Arkansas Power & Light Co 83705704 EISENHUT, D G Division of Licensing Bpp 18363 341 24X Fiche 50-313,83705704,8305090333
- B305100351 Corrects statement in B3032B response to NRC questions reprecautions taken to minimize personnel exposure to radiation during spent fuel storage expansion Solf-reading dosineters will be worn outside diving suits, not inside MARSHALL, J.R. Arkansas Power & Light Co. 83/05/04 ST0L2, J.F. Operating Reactors Branch & CLARK, R.A. Operating Reactors Branch 3 Ip 18379 058 24X Fiche 50-313,83/05/04,830510035!
- 8305180694 Forwards SER resolving Multi-Plant Action Item B-04.

 "Reactor Vessel Overpressure Protection," as part of low temp overpressure mitigating sys review Review of electrical instrumentation & control aspects continuing BTOLZ.JF Operating Reactors Branch 4 B3/09/05 GRIFFIN.JM Arkansas Power & Light Co 2pp 18905 192 24% Fiche 50-313,83/05/05,8305180694
- --8305180743 Safety evaluation resolving Multi-Plant Action Item B-04.
 "Reactor Vessel Overpressure Protection"
 # Office of Nuclear Reactor Regulation. Director 83/05/05
 10pp 18505 194 24X Fiche 50-313.63/05/05.8305180694

- 8305:230019 Forwards Amend BO to License DPR-51, safety evaluation & notice of issuance & availability Amends revise Tech Specs re surveillance requirements of post tensioned prestressed concrete containment tendons W/o enris
 VISSING-0 S Operating Reactors Branch 1 87:05:05 GRIFFIN, J M Ankansas Power & Light Co 1p 18541 762 24X
 Fiche 50-313,83/05/05,8305230019
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees? holders of CPs is integrated scheduling for implementation of plant mode Svc list encl
 EISENRULD G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 106/7 153 24x
 Fiche 50-000/83/05/09/8305090659
- 8305180847 Notifies of unacceptability of dolay of proposed Tech Specs re snubber surveillance in order to include ANSI Std. ANSI/ASME OM1-1982. "Exam & Performance Testing of Nuclear Power Plant Dynamics Restraints (Snubbers)." Std not adapted STOLZ. J. F. Operating Reactors Branch & CLARK.R. A. Operating Reactors Branch 3. 83/05/09 GRIFFIN.J. M. Arkansas Power & Light Co. 2pp. 18506-024, 24X Fiche 50-313,83/05/07,8305180849
- 8305170622 Forwards list of current unresulted issues for radiological effluent Tech Specs remaining as result of 820622-24 mootings final submittal requested within 30 days CLARK, A Operating Reactors Branch 3 83/05/10 ORIFFIN, J M Arkansas Power & Light Co 7pp 18497 001 24x Fiche 50-313,83/05/10,8305170622
- 8305230128 Forwards SFR supporting licensee compliance w/NUREG-073/, Item II 8 2 2. "Required Plant Mods," & design review of plant shielding requirements for access to vital areas CLARKR A Operating Reactors Branch 3 STOLZ.J F Operating Reactors Branch 4 83/05/11 GRIFFILLJ II Arkansas Power & Light Co 2pp 18546 349 24y Fiche 50-313,83/05/11.R305230128
- --8305230145 Safety evaluation supporting licensee compliance w/NUREG-0737. Hem II B 2. "Design Review of Plant Shielding Access to Vital Areas"

 * Office of Nuclear Reactor Regulation, Director 83/05/11 2pp 18546 351 24% Fiche 50~313.83/05/11.8305230128
- 8305240399 Discusses 830315 commitment to provide results of B&W supplemental FCCS calculations addressing impact or cladding models presented in NuRE9-0630. "Results of Bounding Analysis " Revised NuRE9-0630 being prepared by B&V MARSHALL, J R Arkansas Power ! Light Co 83/05/18 STOLZ, J F Operating Reactors Branch 4 2pp 18571 042 24x Fiche 50-313,83/05/18,8305240399
- 8305270065 Forwards list of electrical equipment important to safety be schedule for qualification provisions or replacement of remaining equipment, per 10CFR30 49 Agring-related maint/surveillance requirements will be addressed by NRC deadline MARSHALL. J R Arkansas Power & Light Co 83/05/20 BTOLZ. J F Operating Reactors Branch 4 CLAR.R A Operating Reactors Branch 3 27pp 18638 252 24X Fiche 30-313.81/05/20.8303270065
- Q Inspection reports, IC Bulletins & correspondence
- 8212060385 IC Info Notice 83-14, "Dewatried Spent Jun Exchange Rasin Susceptibility to Exchemic Chemical Reaction " Svc 115t enc!
 TAYLOR, It Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12pp 18308 317 24X Fiche 50-000, 03/03/21, 8212060385
- 8304150143 Forwards IE Insp Repts 50-313/87-07 & 50-368/83-03 on 830201-28 % natice of violation SEIDLE/W C Region 4. Office of Director 83/03/30 GRIFFIN, J M Arkansas Power & Light Co 2pp 1/983 226 24 (Fiche 50-313,83/03/30,8304150143
- --8304150147 Nutice of violation from insp on 830201-28 * Region 4. Office of Director 63/07/30 3py 17983 228 24x Fiche 50-313,83/03/30,8304150143
- ---B304150154 IE Insp Repts 50-313/B3-03 t 50 J6B/B3-03 on B30201-28 Noncompliance noted failure to adhere to requirements of refueling shuffle procedure.use of unapproved info sources & required verification signatures missing CALLAN.L J . CUMMINS.J E . JOHNSON, N P . Region 4. Office of Director 83/03/24 10pp 17983 231 24x Fiche 50-213,83/03/30,8304130143
- 8305100346 Forwards IE Insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18 & notice of violation EEIDLE,W C Region 4. Office of Director 83/04/14 GRIFFIN,J M Arkansas Fower & Light Co 2pp 18379 019 24X Fiche \$0-313.83/04/14.8305100348

- ~-B305100353 Notice of violation from 18.5p on B30314-18 + Region 4, Office of Director B3/04/14 2pp 18379 021 24% Fiche 50-313,83/04/14,8305100348
- --8303100361 IE insp Repts 50-313/83-04 % 50-368/83-04 on 830314-18
 Noncompliance noted failure to conduct design change reviews
 by offsite engineering group & failure to follow procedure
 re forms used in closeout of design change packages
 JAUSON, J.P., MURPHY, M.E., JOHNSON, H.D., Region 4, Office of
 Director 83/04/12 topp 18379 023 24X Fiche 50-313/83/04/14,
 8305100348
- 8303040021 IE Info Notice 83-21, "Derective Emergency Use Respirator " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021
- 830509014/ Forwards Amend 77 to License CPR-51, sarety evaluation 5 notice of issuance & availability Amend Levises language for Tech Spec re inservice insp requirements for Class 1,2 & 3 Tech Spec re liservice and components
 STOLZ, J F Operating Reactors Branch 4 83/04/18 GRIFFIN, J M
 Arkansas Power & Light Co 4pp 18367 266 24X
 Fiche 50-313.83/04/18.8305090147
- --8305070154 Amend 77 to License DPR-31, revising language of Tech Specs re inservice insp requirements for Class 1, 2 & 3 components to conform w/codes & Std Rule 10CFR50 55a STOL7.1 F Operating Reactors Branch 4 83/04/18 7pp 18367 270 24% Fiche 50-313,83/04/18,8305070147
- --8305090160 Safety evaluation supporting Amend 77 to License DPR-51

 * Office of Nuclear Reactor Regulation, Director 83/04/18
 10pp 18367 277 24X Fiche 50-313.83/04/18.8305090147
- --8209200375 "AR Nuclear One Unit 1 Intervice Insp Program," technical ## ANGULARY ONE OFFICE TIME FORCE THE PROGRAM OF CECH ## Strence Applications, Inc. MRC-03-82-096 SAI-186-028-39 82/09/17 NRC - No Detailed Affiliation diven 16pp 18367 287 248 Fiche 30-313,83/04/18,8305090147
- -- 8305090179 Notice or issuance 4 availability of Amend 77 to License DPR-51 STQLZ/J F Operating Reactors Branch 4 83/04/18 2pp 18367 304 24X Fiche 50-313.83/04/18.8365090147
- 8303040021 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures " 30304002.1E into notice of a Section of Emergency Preparedness & Engineering UGRDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383-089 24x Fiche 50-000.83/04/22,8303040023
- 8303040025 [E Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN/F I Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York
- 8305030325 Ack receipt of 830324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-01 & 50-348/83-01 SEIDLE: W C Region 4, Office of Directol 83/04/27 ORIFFIN.J M Arkansas Power & Light Co ip 18297 044 24X Fiche 50-313.83/04/27,8305030325
- --8305030331 Responds to NRC 83021/ ltr re violations noted in IE Insp Repts 50-313/83-01 & 50-368/83-01 Corrective actions revised procedure incorporating three sample requirements into Step 7 2 4 & provided proper training for applicable personnel MARSHALLJR Arkansas Power & Light Co 83/03/24 SEIDLE, W C Region 4. Office of Director 3pp 18297 045 24X Fiche 50-313,83/04/27,8305030325
- 8303040026 IE info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047 24x Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Selpoint Adjustment " Svc list enc: JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 16382 165 24x Fiche 50-000,83/04/28,8303040027
- 8305020436 Forwards IE Insp Rept 50-313/83-04 on 830301-31 & notice of Violateon KELLY, J A Region 4. Office of Director 83/04/28 Region 4 Office of Director Lp 18284 031 24x Fiche 50-313.83/04/28, Region 4,

- -8305020445 Forwards IE Insp Repts 50-313 83-06 & 50-368/83-06 on 305020443 Forwards 16 Insp Repts 30-31 83-06 & 50-36 830301-31 % notice of violation Notice of violation withheld (ref 10CFR2 770) SEIDLE: W C Region 4. Office of Director 83/04/18 Arkansas Power & Light Co 2pp 18784 032 24X Fiche 50-313,83/04/28,8305020436
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co Response (Post 830103) B3/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24% Fichs 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fishe 30-000, 83/05/04, 8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,F. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 117pp 18441 001 247 Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Natice 83-29, "Fuel Binding Caused by Fuel Rack JOSOMOSS IE Into Notice BS-24, "Fuel Binding Caused by Fuel Mack Deformation " Svc fist encl JORDAN.EL Division of Emergency Preparedness & Engineering Response (Post BSO)03) BS/05/06 Consolidated Edison Co of New York, Inc 113pp 18523 248 24X Fiche 50-000.BS/05/06.893040033
- 8305120445 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-36 & 50-348/82-37 SEIDLE N C Region 4. Office of Director 83/05/06 GRIFFIN.J M Arkansas Power & Light Co 2pp 18431 072 24X Fiche 50-313.83/05/06.8305120445
- --8305120451 Responds to NRC 830309 ltr re violations noted in IE Insp Repts 30-313/82-36 & 50-368/82-37 Corrective actions Form 1609 010A re calculation of max permissible concentration revised to require health physics supervisor signature MARSHALLJR Arkansas Power & Light Co 83/04/06 SEIDLE, W C MARSHALL.JR Arkansas Power & Light Co 83/04/06 SEIDLE.W C Region 4. Office of Director 4pp 18431 074 24X Fiche 50-313.83/05/06.8305;20445
- 8305230337 Forwards IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No noncompliance noted 8EIDLE:W C Region 4, Office of Director 83/05/06 GRIFFIN:J M Arkansas Power & Light Co 2pp 18538 256 24X Fiche 50-313,83/05/06.8305230337
- --8305230348 IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No Journal lance noted Major areas inspected test & experiment & procurement programs & receipt, storage & handling of equipment & matls program
 JAUDON, J.P., JOHNSON, W.D. Region 4. Diffice of Director 8: App. 18538-258-24X Fiche 50-313,83/05/04,8305230337
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl ORROAN,E L Division of Emergency Preparatedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of Net 114pp 18524.003 24x Fiche 50-000,83/05/11,8303040034
- 8305170591 Discusses implications of indications on upper core barrel bolts discovered during ultrasonic exams Replacement of seven affected bolts not necessary Restart of facility may groceed w/o undue risk to public MARSHALL, JR Arkansas Power & Light Co 83/05/11 STOLZ, JF Operating Reactors Branch 4 App 18467 023 24X Fishe 30-313,83/05/11,8305170351
- 8305200313 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-313/83-02 & 50-368/83-02 30-38/83-02 BEIDLE, W.C. Region 4, Office of Director 83/05/13 GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 18517 055 24X Fiche 50-313,83/05/13,8309200313
- --8305200317 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 30-313/83-02 & 50-368/83-02 Corrective actions administrative controls implemented to provide adequate procedural controls re safety-related equipment MARSHALL.JR Arkansas Power & Light Co 83/04/27 SEIDLE, W C Region 4, Office of Director 4pp 18517 058 24X Fiche 50-313,83/03/13,8305200313

- 8305230014 Supports restart of facility based on 830511 ltr re results of inep of 120 upper core barrel bolts & subsequent evaluation of upper core barrel bolt issue Responsibility for issue transferred to NRR 8TOLZ, J F Operating Reactors Branch 4 83/05/13 CAVANAU9H, W Arkenses Fower & Light Co ip 18542 231 24X Fiche. 50-313, 83/05/13, 8305230014.
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program," 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/19. Consolidated Edison-Co of New York, Inc 114pp 18697 009, 24X Fiche 30-000,83/05/19,8303040040
- 8305240049 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-03 & 30-368/83-03 Addl info re order/sequence & temporary placement of fuel assemblies requested BRIDLE.W C Region 4, Office of Director 83/05/19 GRIFFIN.J M Arkansas Power & Light Co 2pp 18549 125 24X Fiche: 50-313.83/05/19.8305240049
- ---8305240054 Responds to NRC 830330 ltr re violations noted in IE Insp Repts 50-313/83-03 & 50-368/83-03 Corrective actions: Procedure 1000, 36, "Control of Miscellaneous Info Sources," reviewed w/personnel by dept heads to establish compliance, MARSHALL, J.R. Arkaneas Power & Light Co 83/05/02 SEIDLE, H. C. Region 4, Office of Director. 6pp 18549-127 24X Fiche: 50-313,83/05/19,8305240049
- 8305310194 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-04 & 50-348/83-04.

 8EIDLE:N.C. Region 4, Office of Director 83/05/25. ORIFFIN:J.M Ankaness Power & Light Co ip. 18658.152 24X
 Fiche:50-313:83/05/25,8305310194.
- --- G205310197 Responds to NRC 830414 ltr re violations noted in IE Insp. Repts 50-313/83-04 & 50-368/83-04. Corrective actions: Rev 5 to 0A topical rept. reflecting design activity changes will be submitted for approval by B30410 HARSHALL, J. R. Arkansas Power & Light Co. 83/05/12 SEIDLE, W. C. Region 4, Office of Director. Spp. 18658, 133 24X Fiche 50-313, 83/05/25, 8305310194
- B303040046 IE Info Notice B3-33, "Nonrepresentative Bampling of Conteminated Oil " Bvc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103), B3/05/26 Consolidated Edison Co of New York: Inc. B Northeast Utilities Bervice Co 114pg 18647:007.

 24X Fiche: 50-000, B3/05/26, B303040046.
- R. Periodic operating reports & related correspondence
- B305040493 Forwards last intake impingement data for Mar 1983 ETS 4,1,2 1(2) reporting requirement deleted.per Amends 72 & 40 contained in B30311 ltr.

 MARHALL.J.R Arkenses Power & Light Co. B3/04/29 STOLY.J.F. Operating Reactors Branch 4. 1p. 18322:131, 24X Ficha: 50-313,83/04/29,8305040453.
- --8305040457 Intake impingement data for Mar 1983. * Arkansas Power & Light Co 83/04/21 11pp 18322:132. 24X Fiche: 50-313,83/04/29,8305040453
- 8. Reportable occurrences, LERs & related correspondence
- 9303200445 Forwards NPDEB noncompliance rept.per Permit AR0001392 MARSHALL, J.R. Arkaneas Power & Light Co. 83/04/04. COLLING. J.T. Region 4. Office of Director. ip 18516:109. 24X Fishe:50-313.83/04/04.8305200445.
- --8305200451 NPDES noncompliance rept: on 830323, discovered oil & grease concentrations from Outfall 003 exceeded Permit AR0001392 limits. Caused by startup activities on Unit 1. Rev of operating procedures being considered to prevent recurrence. CAVAMAUON, M. Arkensas Power & Light Co. 83/03/30. WHITTINOTON, D. Region 4, Defice of Director 2pp. 18516:110. 24X Fiche: 50-313,83/04/04,8308200445.
- B305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping." BROWN, E. J. Reactor Operations Analysis Branch, 83/04/19, 8EYPRITK, V Reactor Operations Analysis Branch, 1p. 18541-342 24X Fiche, 50-000, 83/04/19, 8305230573
- --B305230417 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept. Small pipe leaks associated w/unenticipated vibration problems require addi supports or rerouting of piping.
 BROWN.E. J. Reactor Operations Analysis Branch. 83/04/19. 7pp. 1854: 343. 24X Fiche 50-000.83/04/19, 8305230373.

- 8305260260 NPDES noncompliance notification on 830413, routine analysis revealed average oil & grease concentration of 25 mg/l & pollutant load of 27 % lb per day. Caused by bearing failure on turbine Bearing repaired W/830426 ltr ORIFFIN.J. MARBHALL.J R Arkansas Power & Light Co 83/04/20 COLLINS.J T Region 4: Defice of Director HHITTINGTON.D, Environmental Protection Agency 3pp 18529 074: 24X Fiche 30-313,83/04/20,8305260260
- B305030385 Forwards LER 83-009/03L-0 MARRHALL.J R Arkanses Power & Light Co B3/04/25. BEIDLE,W.C. Region 4. Office of Director ip 18306 259 24X Fiche: 50-313.83/04/25.8305030385
- --8305030390 LER 83-009/03L-0 on 830403 during hot shutdown after refueling outage, discovered that nonquelified disphragm was used to repair pressure switch P8-7303 in standby hydrogen purge sys Gualified pressure switch obtained & installed ROOERS,P Arkansas Power & Light Co 83/04/25 Region 4, Office of Director 2pp 18306 260 24X Fiche 50-313,83/04/25,83003038
- 8305060452 Forwards LER 83-005/03L-0 MARBHALL.J R Arkansas Power & Light Co. 83/04/25 SEIDLE,W C Region 4. Offics of Director. 1p 18348 088 24% Fichs 30-313,83/04/25,8305060452
- --8305060454 LER 83-005/03L-0 on 830328, motors for eve water pumps P-48 & P-4C observed to have upper oil reservoir piping altered Caused by installation of oil drain to facilitate draining oil from upper oil raservoir ROGERS:P Arkansas Fower & Light Co 83/04/25 Region 4, Office of Director 1p 18348 069 24X Fiche. 50-313, 83/04/25, 8305060432
- 8305200490 NPDES noncompliance notification: on 830413, sample from Outfall 003, oily water separator, revealed average oil & grease concentration of 23 mg/1 & pollutant load at 27 9 lbs per day. Caused by bearing failure on Unit 1 turbine MARBHALL. J R Ankansas Power & Light Co 83704/26 COLLING. J. T Region 4. Office of Director 3pp 18514 036 24X Fiche: 30-313, 83/04/26, 8305200490
- B305120414 Forwards LER B3-010/03L-0 MARSHALL,J R. Ankansas Power & Light Co B3/05/02 BEIDLE,W C. Region 4: Dffics of Director ip. 18434 095 24% Fiche 30-313.83/05/02.8305120414
- ---B305120418 LER 83-010/03L-0 on 830405, outboard bearing temp for steam driven emergency feedwater pump P-74 exceeded limits Caused by improperly set balance drum clearance during maint Balance drum clearances reset.

 ROGERS:P Arkansas Power & Light Co 83/05/02 Region 4, Diffice of Director. Ip 18434:074 24X Fiche, 30-313, 83/05/02, 8305120414.
- DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT: UNIT 1
 F Security, medical emergency & fire protection plans
- 8303170270 Rev 4 to PMP 2080 EPP.008, "Initiating Manning of Emergancy Response Facilities & Calling Off-Duty Plant Personnel" * Indiana & Michigan Electric Co 83/04/19, 13pp 18463'167, 24X Fiche 30-313, 83/04/19, 8303170270
- --B305170274 Replacement pages, to PMP 2081, EPP, 027, "Unit Vant Emergency Release Rate Determination" + Indiana & Michigan Electric Co 83/04/27, 7pp. 18463:180, 24X Fiche, 50-315, 83/04/17, 8305170270
- 8305040257 Releases public version of temporary change to rev to App B, hosp assistance plan FELTON.J.M. Division of Rules and Records 83/04/25. Document Management Branch 1p 18326-347 24X Fiche 50-315.83/04/25. 8305040259.
- ---B305040265 Forwards public version of Temporary Change 1 to Rev 4 to App B; hosp assistance plan.

 ** Indiana & Michigan Electric Co. 83/04/13, ORIMES; B, NRC No Detailed Affiliation Given. ip 18326-348. 24X
 Fiche: 50-315,83/04/25,8305040259
- --8305040268 Public version of Temporary Change 1 to Rev 4 to App B, hosp assistance plan # Indiana # Michigan Electric Co. 83/04/13, 4pp. 18326:349 24X Fiche:50-315,83/04/25,8305040259.

- 8305120108 Forwards fee re review of alternate safe shutdown capability per 10CFR170 22 & 830331 application
 ALEXICH: P American Electric Power Service Corp 83/05/06
 DENTON: R Office of Nuclear Reactor Regulation, Director DIGOS, R M NRC No Detailed Affiliation Given 2pp 18423 043
 24X Fiche 50-315.83/05/06.8305120108
- 8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation SHAFER: W D Region 3. Office of Director 83/05/06 DOLAN, J E American Electric Fower Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 18548 126 24X Fiche. 50-315, 83/05/06, 8305240302
- --B305240309 IE Insp Repts 50-315/83-04 & 50-316/83-09 on B30215-0331 Noncompliance noted failure to complete Tech Spec surveillance & to establish fire watch in timely manner SWANSON.E.R. DUBRY.N E , BOYD.D C Region 3, Office of Director 83/05/06 | 11pp | 18548 | 130 | 24X Fiche 50-315,83/05/06,8305240302
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT.D Q Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 093 24X Fiche: 50-000.83/05/11.8305110034
- 8303180745 Informs that NUREG-0737, Item III A 2 1, "Emergancy Preparedness, Upgrade Emergency Plans to App E, LOGFR30," completed Item closed # Operating Reactors Branch 1 83/03/13 DOLAN, J Indiana & Michigan Electric Co 2pp. 18506-045 24X Fiche: 50-315, 83/03/13, 9303180745
- 8305200458 Forwards FEMA svaluation of prompt notification sys proposed for Marren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be examined by NRC during next emergency preparedness insp HIND-J A Division of Radiological & Materials Safety Programs 83/05/20 EQUITH00D,R J Kichigan, State of, ip 18513.001 24% Fiche 30-315,83/05/20,8305200458
- --8305200465 Responds to 821213 itr repotential inadequacies of public notification sys at Harren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding sopulation ANDERSON. J T Federal Emergency Hanagement Agency 83/04/01 KEFPLER. J G Region 3, Office of Director 3pp 18513 002 24X Fiche 50-315,83/05/20,8305200458

J Insurance & indemnity information

- 8305160026 Forwards Endorsement 37 to NELIA Policy NF-206 & Endorsement 46 to MAELU Policy MF-79
 BUCKLES, J Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18452 356 24X
 Fiche 50-315.83/04/28.8305160026
- P Operating license stage documents & correspondence
- 8305230368 Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs," providing cost analysis, per 830208 request WHITE.W S American Electric Power Co , Inc 83/03/30 TOURTELLOTTE.J Regulatory Reform Task Force 7pp 18544 356 24X Fiche 50-315,83/03/30,8305230368
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADIND.N J Commissioners 2pp 18542-272 24X Fiche: 50-000.83/04/11.8305230720
- 8305040354 Forwards Amends 72 & 54 to Licenses DPR-59 & DPR-74, respectively, safety evaluation & natice of issuance & availability. Amends revise Tech Specs for oxygen content in waste decay tanks & correct 830207 Amends 69 & 51 WIGGINTON D L. Operating Reactors Branch i 83/04/25. DOLAN, J Indiana & Michigan Electric Co 2pp 18326 310 24X Fiche: 50-315-83/04/25. 8305040354
- --8305040363 Amenés 72 & 54 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs for oxygen content in waste decay tanks & correcting 830207 Amenés 69 & 51
 VAROA S A Operating Reactors Branch 1 83/04/25 16pp.
 18326 312 24x Fiche 30-315,83/04/25,8305040354
- --8305040374 Batety evaluation supporting Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively. * Office of Nuclear Reactor Regulation, Director 83/04/25 3pp 18326,328 24X Fichs 50-315,83/04/25,8305040354

- --8305040382 Notice of issuance & availability of Amends 72 & 54 to Licenses DPR-58 & DPR-74:respectively, VARDA:8 A Operating Reactors Branch I 83/04/25. 2pp. 18326-331 24% Fiche 50-315.83/04/25:8308040354
- B305030257 Responds to B21209 itr requesting comments on Bcience Applications. Inc draft final rept, "Value-Impact Analysis of Recommendation re Steam Openerator Tube Degradations & Rupture Events" (Generic Ltr 82-32)
 HERING:R F American Electric Power Service Gorp B3/04/26.
 DENTON:H R Office of Nuclear Reactor Regulation, Director, 7pp. 18300 039 24X Fiche 50-315,83/04/26,8305030257
- 8305040649 Requests review of responses to SER for environ qualification equipment items for which justification for continued operation not previously submitted, VAROA-S A Operating Reactors Branch 1 83/04/27, DOLAN, J
- B305030519 Advises that separate iodine particulate sampling sysinstelled & temporary mode performed on vent monitoring sys, per NRC 830314 order re NVREO-0737. Item II.F. i.Attachment 2. Unit I sys operational. Unit 2 sys ulil be completed shortly ALEXICH.H P American Electric Power Bervice Corp 83/04/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18295-326 24X Fiche 50-315,83/04/29,8305030519
- B305020453 Generic Ltr B3-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs. Byo list encl.

 EISENHUT. D O Division of Licensing B3/05/OR Consolidated Edison Co. of New York, Inc 50pp. 18441 120 24X Fiche 50-000, B3/05/02, B305020455.
- B305170711 Requests ref for assumptions & methodology used in astimating post-accident radiation environs to complete environ equipment qualification review. Discussion of source terms & containment type should be included VAROA.8 A Uperating Reactors Branch 1 83/05/02. DOLAN, J. Indiana & Hichigan Electric Co 2pp 18476. 256 24X Fiche 50-315.83/05/02.8305170711
- 8305090359 Requests submittal of Class I & III fees for Biiiii & B30225 applications for amend to Licenses DPR-58 & DPR-74 re Tech Spec changes to reflect revised surveillance requirements for safety-related snubbers DIOOS.R H License Fee Hanagement Branch. 83/05/04 DOLAN, J. Indiana & Michigan Electric Co ip. 18367, 219 24X Fichs. 30-315, 83/05/04, 8303090359
- 8305170076 Forwards Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability. Amends permits storage of Westinghouse 13x15 optimized fuel assemblies w/U enrichment to 4% U-225, HIOGINTON.D L. Operating Reactors Branch 1 83/05/04. DDLAN, J. Indiana & Michigan Electric Co 2pp 18475-166 24% Fiche. 50-315, 83/05/04, 8305170076
- --8305170080 Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively. permitting storage of Hestinghouse 15x13 optimized fuel assemblies w/U enrichment up to 4% U-235 VAR0A,8 A Deparating Reactors Branch 1 83/03/04 9pp. 18495 169. 24% Fiche 50-315,83/05/04,8305170076
- --B305170109 Safety evaluation supporting Amends 73 & 55 to Licenses DPR-58 & DPR-74 respectively * Office of Nuclear Reactor Regulation, Director 18495 178, 24X Fiche 50-315, B3/05/04, B305170076
- --B305170112 Notice of issuance & availability of Amends 79 & 55 to Licenses DPR-58 & DPR-74, respectively VARQA-8 A Operating Reactors Branch 1 83/05/04, 2pp, 18495 183 24X Fiche: 50-315, B3/05/04, B305170076.
- 8305180536 Advises that action required by Amends 67 & 49 to Licenses DPR-58 & DPR-74; respectively & Generic Ltr 83-07 complete, based on util negotiating w/DDE re disposal of high level waste or spent nuclear fuel VARQA,8 A Operating Reactors Branch 1 83/05/04, DOLAN, J. Indians & Michigan Electric Co 2pp 18505 076, 24X Fiche: 50-315,83/05/04,8305180536
- 8305090659 Oeneric Ltr 83-20 to all operating reactor licensees & holders of CPs rs integrated scheduling for implementation of plant mods. Svc list snc1
 EIBENHUT.D Q. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627-153 24X
 Fiche: 50-000, 83/05/09, 8305090659

- 305160121 Application to amend Licenses DPR-58 & DPR-74, adding lead 8pac Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 and HERING.R F Indiana & Michigan Electric Co 83/03/10 DENTON, H R HERING.R F Indiana & Michigan Electric Co 93/03/10 DENTON, H R 8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech MERINGER P INGLAND & PICTURE TO 150 DEFICE TO 150 DEFICE TO 150 DEFICE TO 150 DEFECT T
- --8305160126 Proposed Tech Spac Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI
 * Indiana & Michigan Electric Co 83/05/10 J2pp 18448 109 24X Ficha 50-315,83/05/10,8305160121
- 8305180838 Advises that info provided in 821115 & 1214 ltrs re TMI Items II F 1 1 & II F 1 2 on particulate monitors resolved concerns Info acceptable VAROA: 8 A Operating Reactors Branch 1 83/05/10 DC Indiana & Michigan Electric Co 2pp 18306 013 24X Ficha 50-315.83/05/10.8303180838
- 8305140104 Application for amend to License DPR-58, proposing Tech Spec changes to allow Cycle 8 operation w/Westinghouse 15x15 optimized fuel assemblies Approval requested by 830701 Class III fee transmitted by util 830207 ltr HUNTER,R 8 Indiana & Michigan Electric Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18451 080 24X Fiche 50-319,83/05/11,8305140104
- --8305160108 Proposed Tech Spec changes to allow Cycle 8 operation w/ Westinghouse 15x15 optimized fuel assemblies Supporting documentation encl * Indiana & Michigan Electric Co 24X Fiche 50-315,83/05/11,8305160104 83/05/11 285pp 18451 083
- 8305260281 Responds to NRC final rule 10CFR30 47 re electric equipment environ qualification Right to amend response reserved until meeting w/NRC scheduled to resolve environ qualification deficiencies
 HERING.R F Indiana & Michigan Electric Co 83/05/20 DE HERINO, R F Indiana & Michigan Electric Co 83/05/20 DENTUN. H Office of Nuclear Reactor Regulation, Director 16pp 18625 320 24X Fiche 50-315,83/05/20,8305260281
- 8303310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Yeledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits HUNTER, R B Indiana & Michigan Electric Co B3/05/27 DENTON. Office of Nuclear Reactor Regulation, Director 2pp (8658 060 24X Fiche 50-315,83/05/27,8305310088 DENTON, H. R.
- O Inspection reports, IE Bulletins & correspondence
- B305200294 Forwards order imposing civil monetary penalties transmitted to licensee on 821014, for transmittal to Dfc of FR for publication W/o encl.

 AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/10/15 Docketing & Services Brench ip 18516 271 24X Fiche 50-315,82/10/15,8305200294
- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Syc list BACL TAYLOR, J M. Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319, 24X F(che 50-000,83/03/21.8212040385
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator "
- 30304002) AE AFFO 1905CC SOUTH TO 1905CC SOU
- B305020347 Forwards IE Insp Repts 50-315/83-01 & 50-316/83-01 on B30117-21 & 0217, No noncompliance noted NORELIUS C E. Division of Project & Resident Programs 83/04/15 DDLAN, J E. American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 18274 094 24X Fiche. 50-315, 83/04/15, 8305020347
- --8305020348 IF Insa Rents 50-315/83-01 & 50-316/83-01 an #30117-21 & SUDJUCTURE Insp. Repts 50-313/83-01 & 50-314/83-01 on 630117-21 & 0217 No noncompliance noted Major areas inspected GA/GC organization & program work controls, design controls & control of contractor activities
 DUBRY, N. HELLER, J. HOLZHER, M. Region 3, Office of Director 83/04/14 | 11pp. 18274 076 | 24x Fiche, 50-315, 83/04/15, 8305020347
- 9303040023 IE Info Notice 93-22, "BWR Safety/Relief Valve Failures " NOORDANGE L Division of Emergency Preparedness & Engineering JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103). 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383:089 24X Fiche 50-000,83/04/22,8303040023

- 8303040025 [E Info Notice 83-23, 'Inoperable Containment Atmosphere 103040V29 IE Info Notice 83-23; Inspended Convergence Convergence (1995) Sys "Syc list end University of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24x Fiche 50-000.83/04/25,8303040025
- B303040026 IE lnfo Notice B3-24, "Laose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of York, Inc 113pp 18382 047 24x Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24x Fiche 50-000,83/04/28,8303040027
- 8303040028 IF Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Pout B30103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24x Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 244 Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 1944; 001 24x Fiche 30-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24x Fiche 50-000.83/05/06,8303040033
- 8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation SHAFER: W D Region 3, Office of Director 83/05/06 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 18548 126 24x Fiche 50-315/83/05/06/8305240302
- --8309240304 Notice of violation from insp on 830215-0331 SHAFER: W D Region 3, Office of Director 93/05/04 18548 128 24X Fiche 50-315,83/05/06,8305240302
- --B305240309 IE Insp Repts 50-315/83-04 & 50-314/83-05 on 830215-0331
 Noncompliance noted failure to complete Tech Spec
 surveillance & to establish fire watch in timely manner
 SMAMSON, E R., DUBRY, N. E., BOYD, D. C. Region 3, Office of Director
 83/05/04 11pp 18548 130 24X Fiche 50-315/83/05/06/8305240302
- 8305170485 Confirms arrangements for 830622 meeting in Clen Ellum, IL JODI/O4BD CONFirms arrangements for 830622 meeting in Q to discuss SALP for facilities
 NORELIUS.C & Division of Project & Resident Programs
 DOLAN, J E American Electric Power Service Corp DDL,
 Indiana & Michigan Electric Co Ip 18470 068 24X
 Fiche 50-315.83/05/09.8305170485 DOLAN, J E
- 8305170503 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Rapts 50-315/82-21 & 50-316/82-21 Info closes out open items to comparison limits of Sr-90 sample taken during 82115-19 insp PAPERIELLO.C J Region 3, Office of Director 83/05/09 DDLAN.J E American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co 3pp 18470 011 24% Fiche 50-315,83/05/09,8305170503
- 8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice inap & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl MERING, R F Indiana & Michigan Electric Co 83/05/10 DENTON, H (Office of Nuclear Reactor Regulation, Director 4pp 1844B 103 24X Fiche 50-313,83/05/10,8305140121
- --8305160126 Proposed Tech Sper Section 4 0 5 incorporating inservice insp & teeting requirements of ASME Code Section XI * Indiane & Michigan Electric Co 83/05/10 32pp 18448 109 24X Fiche 50-315.83/05/10,8305160121

- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidatines "Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000.83/05/11.8303040034
- 8305240078 Ack receipt of 830428 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02 GHAFER.N D Region 3 Defice of Director 83/05/17 DOLAN.J E American Electric Power Service Corp. DOLAN.JE Indiana & Michigan Electric Co 1p 18548 328 24X Fiche 50-315.83/05/17.8305240078
- --8305240085 Responds to NRC 830329 ltr re violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02 Corrective actions: ltr reemphasizing need to insure testing u/approved procedures sent to all chemical section personnel HUNTER:R S Indiana & Michigan Electric Co 83/04/28 KEPLER:J Q Region 3. Office of Director 2pp 18548 329 24X Fiche 50-315,83/05/17,8305240078
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 Yark, Inc 114pp 18697 809 24X Fiche 30-000,83/05/19,8303040040
- 830.3040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 0:1" Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fichs 50-000.83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305090363 Advises of submittal of "Annual Environ Operating Rept 1982" under separate cover HERINO, R F Indiana & Michigan Electric Co. 83/05/03 DENTON: H R Office of Nuclear Reactor Regulation, Director tp 18363-360. 24X Ficha 50-315,83/05/03,8305090363
- 8305160054 Forwards "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept, 1982" HERINO, R F Indiana & Michigan Electric Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18453 300. 24X Fichs 50-315.83/05/03,8305160054
- --8305160062 "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept.1982 " * Indiana & Michigan Electric Co * American Electric Power Co, Inc 83/05/03 535pp 18453 301 24X Fiche 50-315.83/05/03, 8305160054
- S Reportable occurrences. LERs & related correspondence
- B303280126 Forwards updated LER B2-101/01X-1 SMITH.4 G Indiana & Michigan Electric Co 83/03/17 KEPPLER, J. 0 Region 3. Office of Director 19, 17706 352 24X Fiche: 50-315, 83/03/17, 8303280126
- --8303280136 Updated LER 82-10f/01X-1 on 821123, during surveillance test, motor operated valve HMO-753 to west turbina driven auxiliary feed pump would not open Caused by valve & exhaust fan for turbine driven auxiliary feed pump room malfunction PALMER.R A Indiana & Michigan Electric Co 83/03/17 Region 3. Office of Director 2p 17706 353 24X Fiche 50-315,83/03/17,8303280128
- 8303130097 Forwards LER 83-024/03L-0 SNITH-M G Indiana & Michigan Electric Co 83/04/15 KEPPLER.J G Region 3. Office of Director in L8437 284 24X Ficha 50-315.83/04/15,8305130097
- --8305130101 LER 83-024/03L-0 on 830317, during normal operation, Fire Door 517 from contractor access control to auxiliary bldg would not close properly Caused by extended dead bolt lock preventing doors from closing Dead bolt removed JACQUES, P H Indiana & Michigan Electric Co 83/04/15 Region 3. Offsice of Director. ip 18437 285 24X Fiche 50-315,83/04/15,8305130097

- --B305020151 LER B3-025/01T-0 on B30405 cable vault helon sys failed to meet design concentrations & declared inoperable Cause unknown Review of test data & sys review continuing JACOUES.P Indiana & Michigan Electric Co B3/04/19 Region 3, Office of Director 1p 18284 045 24X Fiche 50-315,83/04/19, B305020141
- 8305230573 Forwards engineering avaluation rept, "Cracks & Leaks in Small Diameter Piping" BROWN E J Reactor Operations Analysis Branch 83/04/19 SEYFRITIK V. Reactor Operations Analysis Branch ip 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping." engineering evaluation rept Small pipe lpaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN.E J Reactor Operations Analysis Branch 83/04/19. 9pp 18341 343 24X Fiche: 50-000, 83/04/19. 8305230573.
- 8305020440 RD on B30420, waste gas holdup sys exceeded oxygen & hydrogen limits Cause not stated Proposed Tech Spec changes increasing oxygen concentration limit will be reviewed by B30422 Followup rept with be submitted within 14 days. SMITM, W G Indiana & Michigan Electric Co B3/04/20, KEPPLER, J. O Region 3, Office of Director ip 18283 091 24X Fichs 30-315,83/04/20,8305020440
- B305020299 Forwards LER B3-D27/03L-0 SMITH.N 0 Indiana & Michigan Electric Co B3/04/22 KEPPLER, J 0. Region 3, Office of Director ip 18277 112 24X Fiche 30-315, B3/04/22, B305020299
- --8305020312 LER 83-027/03L-0 on 830111.AB dissel engine removed from svc to repair minor fuel oil leak on front bank injector pump 3 Gasket replaced on pressure screw Engine returned to svc on 830112 R0BINSON.D Indiana & Michigan Electric Co 83/04/22, Region 3, Office of Director, 2pp 18277 113 24x Fiche 30-315, 83/04/22.8305020299
- 8305020317 Forwards LER 83-026/03L-0
 BMITH,W 0 Indiana & Michigan Electric Co 83/04/22, KEPFLER, J. Q. Region 3. Office of Director Ip 18277 173 24X
 Fiche 50-315,83/04/22,8305020317
- --8305020321 LER 83-026/03L-0 on 830324, during QA audit on PHI-2270, hole found in fire barrier penetration seal F-6107 Cause unknown. Beal repaired ROBINSON, D Indiana & Michigan Electric Co 83/04/22. Region 3, Office of Director ip 18277-174 24X Fiche: 50-315, 83/04/22, 8305020317
- 8305060400 Forwards LERE 83-028/03L-0,83-029/03L-0 & 83-030/03L-0 8MITH,W 9 Indiana & Michigan Electric Co 83/04/29 KEPPLER,J 9 Region 3, Office of Director 1p 18343 286. 24X Fiche 50-313,83/04/29,8305060400
- --8305060406 LER 83-028/03L-0 on 830331, after completion of surveillance test on solid state protection sys train A & review by maint supervisor, sys declared inoperable to troubleshoot possible problem w/safety injection reset time delay PALMER: R A Indiana & Michigan Electric Co. 83/04/27, Region 3, Office of Director. 2pp 18343 287. 24X Fiche 50-315, 83/04/29,8305060400
- --8305060411 LER 83-029/03L-0 on 830405, control room access Fire Door 412 would not operate properly Caused by extension rod being pulled loose from door frame since Shoe set screws replaced & extension rod reinstalled ROBINSON.D. Indiana & Michigan Electric Co 83/04/29 Region 3, Office of Director. 1p 18343.289 24X Fiche 50-315,83/04/29,8305060400
- ---8305060414 LER 83-030/03L-O on B30402, while on tour, security guard discovered Diesel Room AB cardox sys isolated w/no one in room Caused by personnel error Operator instructed on proper procedures for exiting carbon dioxide protected areas.

 KRAUBE, D. F. Indiana & Michigan Electric Co. B3/04/29 Region 3, Office of Director. Ip. 18343, 290 24X Fiche: 50-315, 83/04/29, B305060400
- 8305120376 Forwards LER 83-031/03L-0. SMITH.W.O Indiana & Michigan Electric Co 83/05/04. KEPPLER, J. Q. Region 3. Office of Director. 1p 18431 027. 24X Fiche 50-315,83/05/04.8305120396

- --8305120399 LER 83-031/03L-0 on 830407. while ottempting to entrupper containment outer door of personnel airlock would not open Caused by interlock cable being out of adjustment Cable replaced CARTEAUX, P Indiana & Michigan Electric Co 83/05/04 Region 3, Office of Director 1p 18431 028 24X Fiche 50-315,83/05/04,8305120396
- 8305170441 Forwards LER 83-032/03L-0 SMITH.W 9 Indiana & Michigan Electric Co 83/05/06 KEPPLER.J G Region 3. Office of Director 1p 18471 228 24x Fithe 50-315.83/05/06.8305170441
- --8305170444 LER 83-032/03L-0 on 830407.during normal operation, 9A insp of containment revealed several items of loose debris & inadequately restrained items Items removed or properly secured CARTEAUX.P Indiana & Michigan Electric Co 83/05/06 Region 3, Office of Director 1p 18471 229 24X Fiche 50-315,83/05/06, 8305170441
- 830513017B Forwards LER 83-033/03L-0 SMITH.W Q Indiana & Michigan Electric Co 83/05/09 KEPPLER.J Q Region 3. Office of Director 1p 18439 360 24x Fiche 30-315.83/05/09.8305130178
- ---8305130191 LER 83-033/03L-0 on 830409, during normal operation, following daily routine particulate filter change on lower containment airborne monitor, train B ERS-1400 failed to operate Cause unknown Flush channel cleared PALMER, R A Indiana & Michigan Electric Co 83/05/09 Region 3, Office of Director 2pp 18439 361 24X Fiche 50-315, 83/05/09, 8305130178
- B305130206 RO on 830506, discovered that chemical vol control sysholdup tanks not sampled in 12 h time period required when automatic gas analyzer inoperable Sample performed approx 4-5 h late
 SMITH.W Q Indiana & Michigan Electric Co 83/05/09 KEPPLER, J Q Region 3, Office of Director ip 18439 357 24X
 Fiche 50-315,83/05/09,8305130206
- 8305240327 LER 83-034/03L-0 on 830413, pyralarm detector alormed & found unplugged, rendering Fire Zone 4 detectors inoperable Caused by failure to plug in alarm after conduit installation Pyralarm reinstalled & sys verified operable W/830313 ltr PIEHL, R H , 8MITH, W G Indiana & Michigan Electric Co 83/05/13 KEPPLER, J G Region 3, Office of Director 2pp 18549 356 24X Fiche 50-315,83/05/13,8305240329
- 830524033D LER 83-035/03L-O on 830414, deluge valves for instrument room purgs exhaust 1-HV-CIPX-1 & control room cleanup sys 1-HV-ACRF-1 would not open upon activation signal Caused by failure of time delay circuit boards H/G30513 itr PALMER,R.A. SMITH.W O Indiana & Michigan Electric Co 83/05/13 KEPPLER,J G Region 3, Office of Director 3pp 18574 085 24X Fiche 30-315,83/05/13,8305240330
- 8305240345 LER 83-036/03L-0 on 830418, eight charcoal filter fill hole covers on 12-HV-AFX spent fuel storage pool exhaust ventilation sys found loose Caused by lack of procedure specifying correct math New procedure written M/830516 ltr ROBINSON.D. SMITH.W Q Indiana & Michigan Electric Co 83/05/16 KEPPLER,J Q Region 3, Office of Director 2pp 18572 361 24X Fiche 30-315,83/05/16,8305240345
- 8305240362 Forwards revised LERs 82-110/03X-1 & 82-111/03X-1 BMITH W G Indiana & Michigan Electric Co 83/05/16 KEPPLER. J G Region D. Office of Director 1p 18374 003 24X Fiche 30-315.83/05/16.8308240362
- --8305240370 Revised LER 82-110/03X-1 on 821230,while performing ice condensor tour, intermediate deck door discovered fragen shut Cause of moisture unknown Ice removed Doors operable No further problems observed CAMP,M J Indiane & Michigan Electric Co 83/05/16 Region 3 Office of Director Ip 18574 004 24X Fichs 50-315,83/05/16.8305240362
- --8305240374 Revised LER 82-111/03X-1 on 821107, during normal operation, auxiliary cable vault experienced inadvertent carbon dioxide discharge Caused by isolation of main carbon dioxide tank Valve isolating tank closed b main isolation reopened KRAUSE, D.F. Indiana & Michigan Electric Co. 83/05/16 Region 3, Office of Director 3pp. 18574-005 24X Fiche 50-315, 83/05/16.8305240342
- 8305270087 Updated LER 81-041/03x-1 on 810702, electrical ground traced to 8 train heaters from boron injection tank Caused by burned-up heater element & associated power cable Heater & power cable replaced W/830319 ltr
 UIZNER, D. G. , ShITH, W. G. Indiana & Michigan Electric Co. 83/05/19 KEPPLER, J. G. Region 3, Defice of Director 3pp. 18638 183 24X
 Fiche 50-315,83/05/19,8305270087

- B305270107 LER 83-037/01T-0 on 830416. i?-h grab sampling requirement of Tech Specs not met Caused by individual attempting to repair hydrogen monitor unable to obtain sampling at required time W/830519 [tr PALMER.R A SMITH.W G Indiana & Michigan Electric Co 83/05/19 KEPPLER J G Region 3. Office of Director Jpp 18638 241 24X Fiche 30-315.83/05/19.8305270107
- B305270444 LER 83-038/03L-0 on 830421 during normal operation design discrepancy in wiring discovered in lower containment airborne monitor Train A Caused by voltage dips in wiring Wiring corrected 5 monitor returned to svc W/B30520 ltr PALMER.R A . SHITH.N G Indiana 5 Michigan Flectric Co 83/05/20 KEPPLER.J G Region 3. Office of Director 3pp 18642 242 24X Fiche 50-315,83/05/20,8305270444
- POCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8305170270 Rev 4 to PMP 2080 EPP 008, "Initiating Manning of Emergency Response Facilities & Calling Off-Ducy Plant Personnel" 4 Indiana & Michigan Electric Co 83/04/19 13pp 18463 167 24X Fiche 50-315.83/04/19.3303170270
- --8305170274 Replacement pages to PMP 2081 FPP 027, "Unit Vent Emergency Release Rate Determination" * Indiana & Michigan Electric Co B3/04/29 7pp 18463 180 24X Fiche 50-315,83/04/19,8305170270
- 8305040259 Releases public version of temporary change to rev to App B, hosp assistance plan FELTON. J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18326 347 P4X Fiche 50-315,83/04/25,8305040259
- --8309040265 Forwards public version of Temporary Change I to Rev 4 to App B.hosp assistance plan
 # Indiana & Michigan Electric Co 83/04/13 GRIMES: 8 NRC No Detailed Affiliation Given 1p 18326 348 24X
 Fiche 50-315,83/04/25,8305040259
- --8305040768 Public version of Temporary Change I to Rev 4 to App B, hosp assistance plan * Indiana & Michigan Electric Co 83/04/13 4pp 18326 349 24X Fiche 50-315,83/04/25,8305040254
- B30312010B Forwards for re review of alternate safe shutdown capability per 10CFR170 22 & B30331 application
 ALEXICH M P American Electric Power Service Corp B3/05/06
 DENTON, HR Office of Nuclear Reactor Regulation, Director
 DIGOS,R M NRC No Detailed Affiliation Given 2pp 18423 043
 24X Fiche 50 315,83/05/06.8305120108
- 8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on B30213-0331 & notice of violation B4AFER: N D Region 3, Office of Dilector B3/05/06 DOLAN, J E American Electric Power Service Corp 7pp 18548 126 24X Fiche 50-315,810/05/06 B305240305
- --8305240306 Notice of violation from insp on 830215-0331 SHAFER, N D Region 3, Office of Director 83/05/06 200 18548 128 24% Fiche 50-315,83/05/06,8305240302
- --8309240309 IE Insp Repts 50-315/83-04 & 40-316/83-05 on 830215-0331 Noncompliance noted failure to complete lech Spec surveillance & to establish fire watch in timely manner SWANSON, E R Region 3. Office of Director 92/05/06 (1pp 18548 130 24% Fiche 50-315, 83/05/06, 8305240302
- 8305110034 Generic Ltr 83-21 to all licensees of detailing reactors, applicants for OLs % holders of CFs re clarification of access to control procedures for law enforcement visits SVC list encl
 EISENHUT, D G Division of Licensing 83/05/11 Consplidated Edison Co of New York Inc 16pp 16540-095 24X
 Fiche 50-000,83/05/(1.8305110034
- 8305180745 Informs that NUREG-0737. Itom 11I A 2 1, "Emergency Preparedness. Upgrade Emergency Plans to App E, 10CFR50," completed Item closed # Operating Reactors Branch 1 83/05/13 DULAN, J Indiana & Michigan Electric Co 2pp 18506 045 24% Fiche 50-315,83/05/13,8305180745

- E30520045B Forwards FEMA evaluation of prompt notification sys proposed for Warren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be examined by NRC during next emergency preparedness insp HIND J A Division of Radiological % Materials Safety Programs 83/05/20 SQUTHMODD.R J Michigan, State of 1p 18513 001 24% Fiche 30-315.83/05/20.8305200438
- --8305200465 Responds to 821213 ltr re potential inadequacies of public notification sys at Warren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding population ANDERSON. J T Federal Emergency Management Agency 83/04/01 KEPPLER. J G Region 3, Office of Director 3pp 18513 002 24X fiche 50-315,83/05/20,8305200458
- J Insurance & indemnity information
- B305160026 Forwards Endorsement 57 to NELIA Policy NF-206 & Endorsement 46 to MAELU Policy MF-79
 BUCKLES J Marsh & McLemnan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations Spp 18452 356 24X Fiche 50-315.03/04/28 R051516026
- P Operating license stage documents & correspondence
- B30523036B Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs," providing cost analysis.per B3020B request
 WHITE.W S American Electric Power Co , Inc B3/03/30
 TOURTELIOTTE.J Regulatory Reform Task Force 7pp 18544 356 24X
 Fichs 90-315,83/03/30.830523036B
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J. Regulatory Reform Task Force 83/04/11 PALLADINO N J Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- 8305040354 Forwards Amends 72 & 54 to Licenses DPR-38 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for otygen tontent in waste docay tanks & correct 830207 Amends 69 & 51 HIGGINTON.D & Operating Reactors Branch 1 83/04/25 DDLAN, J Indiana & Michigan Electric Co 2pp 18326 310 24X Fiche 50-315,83/04/25,8305040354
- --8305040363 Amends 72 % 54 to Licenses DPR-58 & DPR-74, respectively, rev[xing Tech Specs for oxygen content in waste decay tanks & correcting 830207 Amends 69 % 51 WARGA: S A Operating Reactors Branch | 83/04/25 16pp 18326 312 24% Fiche 50-315,83/04/25,8305040354
- --8305040374 Safety evaluation supporting Amends 72 & 54 to Licenses DPR-58 & DPR-74-respectively • Office of Nuclear Reactor Regulation, Director 83/04/25 3pp 18326 328 24X Fiche 50-315.83/04/25.8305040334
- --8305040382 Notice of issuance & availability of Amends 72 & 54 to Licenses DPR-98 & DPR-74, respectively VAROA S A Operating Reactors Branch 1 83/04/25 2pp 18326 331 24X Fiche 50-315,83/04/25,8305040354
- 8303030257 Responds to B21209 ltr requesting comments on Science Applications inc draft final rept. "Value-Impact Analysis of Recommendation re Steam Generator Tube Degradations & Rupture Events" (Generic Ltr 82-32)
 HERIMOR F American Electric Power Service Corp 83/04/26
 BENTON, R Office of Nuclear Reactor Regulation, Director 7pp 18300 039 24% Fiche 50-315,83/04/26,8305030237
- 8305040649 Requests review of responses to SER for environ qualification equipment items for which justification for continued operation not previously submitted VARGA.S A Operating Reactors Branch 1 83/04/27 DOLAN.J Indiana & Michigan Electric Co 3pp 16336-272 24X Fiche 50-315.83/04/27.8305040649
- E305030519 Advises that separate indine particulate sampling system talled & temporary mods performed on vent monitoring sysper NRC 630314 order re NUREC-0737. Item II F 1. Attachment 2 Unit 1 sysperational Unit 2 sysperation Unit 2 sysperation of Unit 1 sysperation of Unit 2 sysperation of Unit 2 sysperation of Unit 2 sysperation of Unit 2 sysperation of Service Corp 83/04/27 DENION. HR Office of Nuclear Reactor Regulation, Director 2pp 18295 326 24x Fiche 50-315.83/04/29.8305030519
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Syc list enci EISENHUT, D. G. Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441 120 24x Fiche 50-000,83/05/02,8305020455

- 8305170711 Requests ref for assumptions & methodology used in estimating post-accident radiation environs to complete environ equipment qualification review Discussion of source torms & containment type should be included VARGA-S A Operating Reactors Branch 1 83/05/02 DOLAN, J Indiana & Mithigan Electric Co 2pp 18476 256 24X Fiche 50-315,83/05/02.8305170711
- 8303180814 Requests addl info re Mercord pressure switch, including details of functional verification during testing Info requested within 45 days of receipt of ltr VARGA: A Operating Reactors Branch 1 83/05/02 DOLAN, J Indiana & Michigan Electric Co 2pp 18505 354 24X Fiche 50-316,83/05/02,8305180814
- B305090359 Requests submittal of Class I & III fees for Stilli & B30225 applications for amend to Licenses DPR-38 & DPR-74 re Tech Spec changes to reflect revised surveillance requirements for safety-related snubbers DIOGS.R M License Fee Management Branch 83/05/04 DDLAN, J Indiana & Michigan Electric Co Ip 18367 219 24X Fiche 50-315.83/05/04.8305090399
- 8305170076 Forwards Amends 73 % 55 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends permits storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment to 4% U-235 WIGGINTON, D. Operating Reactors Branch 1 83/05/04 DDLAN, J Indiana & Michigan Electric Co. 2pp. 18495 166 24% Fiche 50-315, 83/05/04, 8305170076
- ~-8305170080 Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, permitting storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment up to 4% U-235 VAROA.S A Operating Reactors Branch 1 83/05/04 9pp 18495 169 24x Fiche 30-315,83/05/04,8305170076
- --8305170109 Safety evaluation supporting Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively * Office of Nuclear Reactor Regulation, Director 83/05/04 Spp 18495 17B 24X Fiche 50-315,83/05/04,8305170076
- --8305170112 Notice of issuance & availability of Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively VARQA-S A Operating Reactors Branch I 83/05/04 2pp 18495 183 24X Fiche 50-315,83/05/04,8305170076
- 8305180536 Advises that action required by Amends 67 & 49 to Licenses DPR-58 & DPR-74.respectively & Generic Ltr 83-07 complete, based on util negotiating w/DGE re disposal of high level waste or spent nuclear fuel VARGA. S A Operating Reactors Branch 1 83/05/04 DDLAN, J Indiana & Michigan Electric Co 2pp 18503 076 24x Fiche 30-315.83/05/04.8305180536
- 8305090659 Oeneric Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24% Fiche 50-000.83/05/09.8305090657
- 8305160121 Application to amend Licenses DPR-98 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl HERIND.R F Indiana & Michigan Electric Co 83/05/10 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 18448 105. 24X Fiche 50-315, 83/05/10, 8305160121
- --8309160126 Proposed Tech Spec Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI * Indiana & Michigan Electric Co 83/05/10 32pp 18448 109 24X Fiche 50-315,83/05/10,8305160121
- 8305180838 Advises that info provided in 821115 & 1214 ltrs re TMI Items II F 1 i & II F 1 2 on particulate monitors resolved concerns Info acceptable UARGA.S A Operating Reactors Branch 1 83/05/10 DULAN, J Indiana & Michigan Electric Co 2pp 18306 013 24X Fiche 50-315,83/05/10,8305180838
- 8305260281 Responds to NRC final rule 10CFR50 49 re electric equipment environ qualification Right to amend response reserved until meeting w/NRC scheduled to resolve environ qualification deficiencies
 HERINO.R F Indiana & Michigan Electric Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 16pp 18625 320 24X Fiche 50-315,83/05/20.8305260281

- 8305310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Teledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits HUNTER:R B Indiana & Michigan Electric Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18658 065 24X Fiche 30-315.83/05/27.8305310088
- Q Inspection reports. IE Bulletins & correspondence
- B305200294 Forwards order imposing civil monetary penalties transmitted to licensee on B21014. For transmittel to Ofc of FR for publication W/o encl AXELRAD. J A Director's Office, Office of Inspection and Enforcement B2/10/15 Docketing & Services Branch 1p 18516 271 24X Fiche 50-315, 82/10/15, 8305200294
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR: J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 9303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Byc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 135 24X Fiche 50-000,83/04/13,8303040021
- 8305020347 Forwards IE Insp Repts 50-315/83-01 & 50-316/83-01 on 830117-21 & 0217 No noncompliance noted NORELIUS, C E Division of Project & Resident Programs 83/04/15 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 18274 094 24X Fiche 50-315,83/04/15,8305020347
- --B305020348 IE Insp Repts 50-315/B3-01 \(\hat{1.50-316/B3-01}\) on B30117-21 \(\hat{2.50}\)
 0217 No noncompliance noted Major areas inspected QA/QC organization \(\hat{2.50}\) program work controls, design controls \(\hat{2.50}\) control of contractor activities

 DUBRY.N \(\hat{3.50}\) HELLER.J \(\hat{3.50}\) HOLZMER.M Region 3, Office of Director B3/04/14 11pp 18274 096 24X Fiche 50-315, B3/04/15, B305020347
- 8303040023 IE Info Notice 83-22, "BWR Bafety/Relief Valve Failures" Svc list encl JORDAN.8 L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past B30103) B3/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50~000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PARs " Svc list encl JORDANEE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 117pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- 8303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list enci JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York

- 830524030° Forwards IE Insp Repts 30-315/83-04 % 50-316/83-05 on 830215-0331 % notice of violation SMAFER.W D Region 3. Office of Directol 83/05/06 DDLAN.J C American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co 2pp 18548 124 24% Fiche 50-315,83/05/06,8305240302
- --8305240306 Notice of violation from insp on 830215-0331 SHAFER U D Region 3, Office of Director 83/05/06 2pp 19548 128 24% Fiche 50-315,83/05/06,8305240302
- --8305240309 IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 Noncompliance noted failure to complete Tech Spec surveillance & to ostablish fire watch in timely mannor SWANSON, E. R. DUBRY, N. C., BOYD, D. C. Region 3, Office of Director 83/05/06 11pp 18548 130 24X Fiche 50-315,83/05/06,8305240302
- B305170485 Confirms arrangements for B30622 moeting in Glen Ellyn.lL to discuss SALP for facilities NORELIUS.C E Division of Project & Resident Programs 83/05/09 DDLAN.J E American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co ip 18470 068 24x Fiche 50-315.83/05/09.8305170485
- B305170903 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 30-315/82-21 & 50-316/82-21 Info closes out open items in comparison limits of Sr-90 sample taken during 62115-17 insp PAPERIELLO, C. J. Region 3, Office of Director B3/05/09 DDIAN, J.E. American Electric Power Service Corp. DDIAN, J.E. Indiana & Michigan Electric Go. Jpp. 18470-011 24X Fiche 30-315, B3/05/09, B305170503
- 8305160121 Application to amend licenses DPR-98 & DPR-74, adding Tech Spec Section 4 0.5 to incorporate inservice insp & testing requirements of ASME Code Section VI Class III Fee for Unit 1 & Class I fee for Unit 2 encl HERING.R F Indiana & Michigan Electric Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18440 105 24X Fiche 50-315,83/05/10,8305160121
- --8305160126 Proposed Tech Spec Section 4 0 9, incorporating inservice insp % testing requirements of ASME Code Section XI * Indiana & Michigan Electric Co 83/05/10 3/pp 18448 107 24X Fiche 50-315, 83/05/10, 8305160121
- B303040034 IE Info Notice B3-30. "Misapplication of Ceneric Emergency Operating Procedures (EQP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Proparadioss & Engineering Response (Post B30103) B3705/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305240078 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 90-315/83-02 & 50-315/83-02 & 50-315/83-02 & SIAFER, W D Region 3, Office of Director 83/05/17 BDLAN, J E American Electric Power Service Corp BDLAN, J C Indiana & Michigan Electric Co 1p 18548 328 24x fiche 50-315/83/05/17,8305240078
- --8308240086 Responds to NRC 830329 its re violations noted in IE Insp. Repts 30-315/83-02 & 50-316/83-09 Corrective actions ltr. reemphasizing need to insure testing w/approved procedures sent to all chemical section personnel. HUNTER: R B Indiana & Mithigan Electric Co. 83/04/20 KEPPLFR: J G Region 3: Office of Director. Sep. 18548-329 24X Fiche 50-315,83/05/17.8305240078
- B303040040 IE Info Notice B3-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 UDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/17 Consolidated Edison Co of New
 York, Inc 114pp 18497 009 24x Fiche 50-000, B3/05/19, B303040040
- 8303040046 IE info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl JORDAN, El Division of kerrgency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of Now York, Inc 114pp 18647 007 24x Fiche 50-000, 83/05/26, 8303040046
- R Periodic operating reports & related correspondence
- 8305090363 Advises of submittal of "Annual Environ Operating Rept 1782" under separate cover HERING.R F Indiana & Michigan Electric Co 83/05/03 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 18363 360 24x Fiche 50-315,83/05/03,8303070363
- 8305160054 Forwards "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept. 1982 " HERING, R F. Indiana & Michigan Electric Co. 83/05/03 DENTON, N () Office of Nuclear Reactor Regulation, Director ip 18453 300 24) Fiche 50-315, 83/05/03, 8305160054

- ~~8305160062 "DC Cook Nuclear Plant Units 1 ν 2 Annual Environ Operating Rept.1962 "
 - negrifous * Michigan Electric Co * American Electric Power Co .
 Inc 83/05/03 535pp (8453 301 24% Fiche 50-315,83/05/03,
 8303[40054
- S Reportable occurrences, LERs & related correspondence
- 8305130166 Forwards LER 83-035/03L-0 SMITH N 6 Indiana & Michigan Electric Co 83/04/15 KEPPLER, J G Region 3, Office of Director 1p 18438 113 24X Fiche 50-316.83/04/15.8305130166
- --8305130174 LER 83-035/03L-0 on 830312, during surveillance testing on main turbine stop valves, reset function for proximity switch on stop valve C failed to operate Trip function made inoperable for replacement on 830319 Cause unknown PALMER, R A Indiana & Michigan Electric Co 63/04/15 Region 3, Office of Director ip 18438 114 24X Fiche 50-316,83/04/15,8305130166
- B305020072 Forwards LER B3-036/01T-0 SMITH.W 0 Indiana & Michigan Electric Co 83/04/19 KEPPLER.J O Region 3. Office of Director 1p iB279 253 24X Ficha 30-316.83/04/19.8305020072
- ---8305020078 LER 83-036/01T-0 on 830414, cable vault haion sys declared inoperable after failing to meet design concentrations while performing nonroutine test Cause not determined Review of test data & testing continuing

 JACQUEG.F Indiana & Michigan Electric Co 83/04/19 Region 3, Office of Director ip 18279 254 24X Fiche 50-316, 83/04/19, 8305020072
- 8305020440 RD on 830420.waste gas holdup sys exceeded oragen & hydrogen limits Cause not stated.Proposed Tach Spec changes increasing oxagen concentration limit will be reviewed by 830422 Followup rept will be submitted within 14 days SMITM.W @ Indiana & Michigan Electric Co 83/04/20 KEPPLER, J @ Region J. Office of Director 1p 18283 091 24X Ficher 50-315,83/04/20.8305020440
- 8305020161 Forwards LERs 83-037/03L-0 & 83-038/03L-0 8NITH.W G Indiana & Michigan Electric Co 83/04/22 KEPPLER, J G Region 3. Office of Director ip 18284 068 24X Fichs 50-316.83/04/22.8305020161
- --B305020171 LER 83-037/03L-0 on B30323.Fire Door 386 found unlatched during normal operation Caused by insufficient closer mechanism force Door closer mechanism adjusted ROBINSON.D Indiana & Michigan Electric Co B3/04/22 Region 3. Office of Director ip 19284 069 24X Fiche 50-316,83/04/22,B305020161
- --B305020177 LER 83-038/03L-0 on B30405 four logic test positions tested unsatisfactorily during solid-state protection sys (train A) surveillance test Caused by failed universal card A-304 Lugic card replaced Sys operability verified PALMER.R A Indiana & Michigan Electric Co 83/04/22 Region 3. Office of Director ip 18284 070 24x Fiche 50-316,83/04/22,8305020161
- B305020192 Forwards LER B3-039/0[T-0 9MITH,W G Indiana & Michigan Electric Co 83/04/22 KEPPLER, J G Region J. Office of Director ip 18277 286 24X Fiche 50-316,83/04/22,8305020192
- --8305020198 LER 83-039/01T-0 on 830400 potential for violating RCS temp average used in DNB analysis discovered during proposed Tech Spec review Administrative temp average limit of 575 F imposed PALMER.R A Indiana & Michigan Electric Co 83/04/22 Region 3, Defice of Director 5pp 18277 267 24X Fiche 50-316, 83/04/22, 8305020192
- B3051203(B Forwards LER B3-040/03L-0 SMITH-W & Indiana & Michigan Electric Co 83/05/04 KEPPLER, J @ Region 3. Dffice of Director 1p 18431 081 24x Fiche 50-316.83/05/04.83091203(8
- --B305120324 LER B3-040/03L-0 on B30422.CCW west HX outlet to miscellaneous svc valves failed to operate within inservice insp (181) time limits.Caused by infrequent ISI testing 181 testing frequency increased from quarterly to monthly ROBINSON.D Indiana & Michigan Electric Co B3/05/04 Region 3. Office of Director ip 18431 082 24x Fiche 50-316.83/05/04.8305120318
- 8305170446 Forwards LER 83-041/03L-0 8MITH.W G Indiana & Michigan Elactric Co 83/05/06 KEPPLER, J G Region J. Office of Director ip 18469 313 24% Ficha: 50-316,83/05/06,8303170446

- --830517045: LER 83-041/03L-O on 830407.during normal operation. GA insport containment revealed several items of loose debris & inadequately restrained items Items removed on properly secured CARTEAUX.P Indiana & Michigan Electric Go 83/05/06 Region 3. Office of Director 1p 18469 314 24X Fiche 30-316.83/05/08.8305170446
- 8305130205 RD on 830506, discovered that chamical vol control sysholdup tanks not sampled in 12 h time period required when automatic gas analyzer inoperable Sample performed approx 4-5 h late
 SNITK-W & Indiana & Michigan Electric Co 83/05/09 KEPPLER. J & Region 3, Office of Director 19 18439 357 24%
 Fiche 50-315,83/05/09,8305130206
- B305240145 LER B3-042/03L-O on B30427, check valve NB-242(CCW seal water to H2 sampling pumps) found leaking Caused by dirt buildup on valve seating surfaces Valve internals cleaned Seating surfaces checked W/B30517 ltr
 R0BINSON.D. SMITH.W O Indiana & Michigan Electric Co 83/05/17.
 KEPPLER.J & Region 3. Office of Director 2pp 18549 007 24X
 Fiche 50-316.83/05/17.8305240145
- 8305270223 Forwards LERs 83-043/03L-0 & 83-044/03L-0 SNITH-W G Indiana & Michigan Electric Co 83/05/20 KEPPLER, J Q Region J, Office of Director ip 18637 236 24X Fiche 50-316, 83/05/20, 8305270223
- c-8305270227 LER 83-043/03L-0 on 830425 review of train A & B lower containment airborne monitors, ERS-2300 & 2400, revealed incorrect wiring per approved physical prints Monitors removed from svc & corrections made PALMER.R A Indiana & Michigan Electric Co 83/05/20 Region 3, Office of Director 1p 18637/234 24X Fiche 50-316,83/05/20,8305270223
- --8305270230 LER 83-044/03L-0 on 83042i.20 psig difference between pressurizer pressure channels existed Caused by pressure transmitters for NPP-152 & 153 drifting Transmitters satisfactorily calibr PALMER.R A Indiana & Michigan Electric Co 83/05/20 Region 3. Office of Director 1p 18637 235 24X Fich# 50-316.83/05/20.8405270223
- 8305310179 LER 83-045/03L-0 on 830424.upper containment normal range area & lower containment airborne monitor channels declared inoperable due to bad data in channel parameter files Caused by unverified terminal printouts W/830524 ltr PALMER.R A . SMITH, W Q Indiana & Michigan Electric Co 83/05/24 KEPPLER.J Q Region 3, Office of Director 3pp 18652 282 24X Fiche 50-316,83/05/24,8305310179
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 8305030178 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-04(2 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/04/19 LUNDVALL, A E Baltimore Qas & Electric Co 2pp 18300 243 24X Fiche 50-317,83/04/19,8305030198
- --8305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures.plant operation.radiation protection.physical security & fire protection ARCHITZEL.R E : TRIMBLE.D C : MCCABE.E C Division of Project & Resident Pragrams 83/04/18 22pp 18300 245 24X Fiche 30-317.83/04/19.8305030198
- 8305060077 Forwards exemption request for relief from requirement for installation of fixed/automatic fire suppression sys in control room complex & intake structure.per 830304 request CLARK.R A Decrating Reactors Branch 3 83/04/21 LUNDVALL.A E Rochester Gas & Electric Corp 3pp 18357 264 24X Fiche 50-317.83/04/21.8305060077
- --8305060084 Examption from requirements for installation of fixed/ automatic fire suppression sys in control room complex & instake structure EISENHUT, D Ø Division of Licensing 83/04/21 Baltimore Gas & Electric Co. 3pp 18359 267 24X Fiche 50-317.83/04/21, 8305060077
- 8305060627 Releases public version of rev to emergency plen implementing procedure FELTON.J M. Division of Rules and Records 83/04/25. Document Management Branch 1p. 18399 201 24X Fiche 50-317.83/04/25, 8305060627

- ---8305060631 Forwards public version of Rev 9.Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8.Change 1 to ERPIP 4 5 3 re guide for selection of respirators

 * Baltimore Gas & Electric Co 83/04/07 NRC No Detailed Affiliation Given 1p 18359 202 24X Fiche 50-317.83/04/25, 8305060627
- ~-8305060635 Public version of Rev 9. Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8. Change 1 to ERPIP 4 5 3 re guide for selection of respirators RUSSELL, J B Baltimore Gas & Electric Co 83/03/30 6pp 18397 203 24X Fiche 50-317, 83/04/25, 8305060627
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for ULs & holders of CPs to clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York Inc 16pp 18540 095 24% Fiche 50-000.83/05/11.8305110034
- J Insurance & indemnity information
- 8305260302 Forwards Endorsement S3 to NELIA Policy NF-216 & Endorsement 42 to MAELV Policy MF-74 QAMMIE, G B Baltimore Gas & Electric Co 83/05/23 DINITZ, I Assistant Director for State & Licensee Relations 3pp 18625 163 24X Fiche 50-317,83/05/23.8305260302
- P Operating license stage documents & correspondence
- 8305240249 FOIA request for three categories of documents re Reactor Bafety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515,2787 & 2802) SHOLLY: S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24X Fichs 50-000,83/03/11,8305240249
- 8305240254 Partial response to FOJA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress FELTON.J M Division of Rules and Records 83/03/31 SHOLLY.S C Union of Concerned Scientists 2pp 18593 179 24X Fiche 30-000.83/03/31,8305240254
- --B305240269 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RSSMAP) analysis If rept is to be published clear statement of program assumptions & limitations should be included TIERNAN, J A Baltimore Gas & Electric Co 82/03/05 BURDICK, G R Office of Nuclear Regulatory Research, Director 35pp 18593 235 24X Fiche 50-000, 83/03/31, 8305240254
- B303040783 Forwards Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to increase steam generator min pressurization temp
 JAFFE, D H Operating Reactors Branch 3 B3/04/21 LUNDVALL, A E Baltimore Oas & Electric Co 2pp 18327 204 24X
 Fiche 50-317,83/04/21,8305040783
- --8305040/89 Amends 82 t 65 to Licenses DPR-53 to DPR-69, respectively, increasing steam generator min pressurization temp, correcting typographical error & limiting overtime for personnel involved in safety-related activities CLARK:R A Operating Reactors Branch 3 83/04/21 34pp 18327 204 24X Fiche 50-317,83/04/21.8305040783
- --8305040793 Safety evaluation supporting Amends 82 & 45 to Licenses DPR-53 & DPR-69, respectively # Office of Nuclear Reactor Regulation, Director 83/04/21 3pp 18327 240, 24% Fiche 50-317,83/04/21,8305040783
- --8305040795 Notice of issuance & availability of Amends 82 & 45 to Licenses DPR-53 & DPR-69, respectively CLARK,R A Operating Reactors Branch 3 83/04/21 2pp 18327 243 24X Fiche 50-317,83/04/21,8305040789
- 8305060045 Forwards SER supporting util responses to NUREO-0737, Items II F 1 4. "Containment Pressure Monitor," II F 1 5. "Containment Hater Level Monitor" & II F 1 6. "Containment Hydrogen Monitor " Items resolved CLARK, R A Operating Reactors Branch 3 83/04/21 LUNDVALL, A E Baltimore Oas & Electric Co 9pp 18354 299 24X Fiche 50-317, 83/04/21, 8305060045

- 8305060396 Submits improvement program to decrease personnel error/ action-related events Two types of personnel awareness programs initiated Training staff increased % instructor matis upgraded TIERMAN, J. A. Baltimore Qas % Electric Co. 83/04/27 CLARK, R. A. Operating Reactors Branch 3. 3pp. 18343 174 24X Fiche 50-317.83/04/27.8305060396
- 8305060402 Application for amend to Licensos DPR-53 & DPR-69, changing Tech Spec to clarify wording of surveillance requirements for sealed souces each time reactor startup occurs Fee enci LUNDVALL.A & Baltimore Oas & Electric Co 82/04/27 CLARK.R A Operating Reactors Branch 3 5pp 18243 291 24X Fiche 50-317.83/04/27,8305060402
- --8305060405 Proposed Tech Spec changes clarifying wording of surveillance requirements for sealed sources each time reactor startup occuis

 * Baltimore Gas & Electric Co 83/04/27 7pp (8343-296-24X)
 Fichs 50-317.83/04/27
- 8305020455 Generic Ltr 83-19 to all power reactor % testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
 EISENHUT.D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc 50cp 18441 120 24X
 Fiche 30-000.83/05/02.8305020455
- B30518076B Advises that action required by Amend 61 to License DPR-69 & Amend 80 to License DPR-53 complete since util negotiating w/DDE re disposal of high level waste or spent nuclear fuel JAFFE, D H Gperating Reactors Branch 3 B3/05/04 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18306 035 24% Fiche 30-317.83/05/04.830518076B
- 8305170246 Forwards Amends 83 & 66 to Licenses DPR-93 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec requirements for equipment hatch & safety-related air filter sys

 JAFFE, D H Operating Reactors Branch 3 83/05/05 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 184// 011 24X

 Fiche 50-317,83/05/05,8305170246
- --8305170259 Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively, revising Tech Spec surveillance requirements for equipment hatch & safety-related air filter sys CLARK: A Operating Reactors Branch 3 63/09/03 64pp 18477 014 24X Fiche 50-317,83/05/05,8305170246
- --8305170266 Safety evaluation supporting Amends 83 & 66 to Licenses PPR-53 & DPR-69, respectively * Office of Nuclear Reactor Regulation, Director 83/05/05 7pp 18477 078 24X Fiche 50-317,83/05/05,8305170246
- --8305170273 Notice of issuance & availability of Amends 83 & 66 to Licensea DPR-53 & DPR-69, respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/05 2pp 18477 085 24% Ficha 30-317, 83/05/05, 8305170246
- 8305180595 Forwards Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends allow periodic testing of control element assemblies w/inoperable reed switch stack sys JAFFE.D H Derating Reactors Branch 3 83/05/05 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18505 090 24X Fiche 50-317,83/05/05,8305180594
- --B309180579 Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, allowing periodic testing of control element assemblies w/inoperable reed switch stack sys CLARK: R A Deprating Reactors Branch 3 83/05/05 17pp 18505 093 24X Fiche 50-317.83/05/05.8305180556
- --8305180614 Notice of issuance & availability of Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/05 2pp 18303 119 24X Fiche 50-317,83/05/05.8303180556
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EIGENHUT.D 0 Division of Licensing 83/05/09 Consolidated
 Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000,83/05/09.8305090659

- 8305190293 Responds to 830325 ltm re current qualification status & plans for completion of environ qualification of all safety-related electrical equipment Extension to 850430 for completion requested for Unit 1
 LUNDVALL.A.E Bultimore Gas & Electric Co 83/05/10 CLARK, R A Operating Reactors Branch 3 4pp 18501 107 24X
 Fiche 30-317,83/05/10,8305190293
- 8305200078 Forwards request for add1 info is 830504 submittal on main steam line break analysis Operation justified pending completion of revised analysis CLARK.R A Operating Reactors Branch 3 83/05/10 LUNDVALL.A E Baltimore Cas & Electric Co 3pp 1854! 038 24x Fiche 30-317.83/05/10.8305200078
- 8305260294 Forwards response to 830405 draft technical evaluation rept ra control of heavy loads Phase I review complete Util position accepted per 830518 telecon ABH.R E Baltimore Cas & Electric Co 83/05/24 EISENHUT, D G Division of Licensing 2pp (8625-161 24X Ficha 50-317,83/05/24, 8303260294
- 8305270029 Forwards marked-up proposed Tech Spec 3/4 & E & recontainment tendon surveillance
 PATTERSON.H D Baltimore Gas & Electric Co 83/05/24 JAFFE, D H
 Operating Reactors Branch 3 3pp 18638 310 24X
 Fiche 50-317.83/05/24.8305270029
- Q Inspection reports, IE Bulletine & correspondence
- B212040385 IE Info Notice 83-14. "Dewatered Spent fon Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York. Inc 112pp 18308 319 24X Fiche 50-000.83/03/21/8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Bvc (ist encl
 JURDAM: E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted 8TAROSTECKI:R Division of Project & Resident Programs 83/04/19 LUNDVALL:A E Baltimore Gas & Electric Co 2pp 18300 243 24X Fiche 50-317,83/04/19,8305030198
- --B305030208 IE Insp Repts 50-317/B3-07 % 50-318/B3-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures, plant operation, radiation protection, physical security & fire protection ARCHITZEL.R E . TRIMBLE, D C . MCCABE, E C Division of Project & Resident Programs B3/04/IB 22pp 18300 245 24X Fichs 50-317,83/04/19,8305030198
- 8303040023 IE lnfo Natice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18391 291 24X Fiche 50-000.83/04/25,8303040025
- 8305020340 Ack receipt of 830330 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-01 & 30-318/83-01 BELLAMY, R. R. Region 1. Office of Director 83/04/26 LUNDVALL, A. E. Baltimore Gas & Electric Co. 1p. 18277 065 24% Fiche 50-317,83/04/26,8305020340
- --8305020344 Responds to NRC 830303 ltr re violations noted in IE Insp. Repts 50-317/83-01 & 50-318/83-01 Corrective actions changes made to Radiation Safety Procedures 2-306 & 2-305 for max air flow & protection factor, respectively LUNDVALLA E Baltimore Gas & Electric Co 83/03/30 MARTIN.T T Division of Engineering & Technical Programs 2pp 18277 066 24X Fiche 50-317,83/04/26.8305020340
- B305110276 Forwards IE Insp Repts 50-317/83-09 & 50-318/83-09 on B30406-08 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/04/27 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 18393 237 24X Fiche.50-317.83/04/27.8305110276

- --8305110677 IC Insp Repts 50-317/83 UY % 50-318/83-09 on 830406-08 No non-unpliance noted Major areas inspected environ monitoring program for operations including mpt controls, program for QC of analytical measurements % implement/tion of program JANG, J C . PASCIAK, W J Region 1. Optice of Director 83/04/26 4pp 18373 239 24X Fiche 50-317/83/04/27/8305110276
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382-047 24x Fiche 50-000.83/04/28.8303040026
- 8303040027 IE info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JURDAN,E L. Division of Emergency Preparedness > Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24x Fiche 50-000,83704/28,8303040027
- 8303040028 IE Info Notice 83-26. "Failure or Safety/Relief Valve Discharge Line Vacuum Breakers" Suc list encl JUROAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Convolidated Edison Co. of Neu York, Int. 122pp 18441 170 24% Fiche 50-000.83/05/03.8303040028
- B303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list end I JORDAN.F L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 288 244 Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Griteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, C. L. Division of Emergency Preparedness? Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 30-000,83/05/04,8303040031
- 8305060412 Submits description or analyses of main steam line break inside containment per IE Bullatin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 CLARK, R A Operating Reactors Branch 3 Spp 18343 265 24X Fiche 50-317, 83/05/04, 8305060412
- B30304003J IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl UGRAM, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24x Ficha 50-000, B3/05/06, B303040033
- 8303040034 JE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24x Fiche 50-000.83/05/11,8303040034
- 8305200620 Forwards info in response to remaining open issues in LC Bulletin 80-04 re main steam line break inside containment, supplementing 830504 ltr Installation of main feedwater systrip scheduled for completion by 831117 LUNDVALLIA E Baltimore Gas & Electric Co 83/05/17 CLARK.R A Operating Reactors Branch 3 3pp 18320 062 24X Fiche 50-317,8305/17,6305200620
- --8305200628 Discusses analyses of potential consequences of main steam line break inside containment w/Failed-open main feedwater regulating valve & provides justification for continued operation.per IE Bulletin 80-04 Related info encl LUNDVALL.A E Baltimore Gas & Electric Co 63/05/17 CLARK.R A Operating Reactors Branch 3 30pp 18520 065 24X Fiche 30-317,83/05/17,8305200620
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN, E L Division of Emelgency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 CO9 24X Ficho 50-000.83/05/19,8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24x Fiche 50-000.83/05/26,8303040046

- R Periodic operating reports & related correspondence
- 0305200631 Forwards meteorological data for semiannual effluent repts
 - for 1982 LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 ALLAN, J M Region 1, Office of Director 1p 18519 173 24X Fiche 50-317,83/05/04,8305200631
- --8305200614 "Calvert Cliffs Nuclear Power Plant./feteorological Data." Jan-June 1982
 - Jan-June 1982 * Baltimore Gas & Electric Co 83/05/04 68pp 18519 174 24X Fiche 50-317.83/05/04/8305200631
- --8305200650 "Calvert Cliffs Nuclear Power Plant, Meteorological Data,"
 - JUI-Doc 1982 * Baitimore Gas & Electric Co 83/05/04 68pp 18519 241 24X Fiche 50-317,83/05/04,8305200631
- 8305200564 Forwards monthly operating repts for Apr 1983 LOTITO.E M Baltimore Gas & Electric Co 83/05/13 Office. Office of Inspection and Enforcement Ip 185 Fiche 50-317,83/05/13.8305200564 Director's 10 18514 128
- --8305200584 Monthly operating repts for Apr 1983 LOTITU.E Baltimore Gas & Electric Co 83/05/15 18514 127 24X Fiche 50-317.83/05/13.8305200564
 - Reportable occurrences, LERs & related correspondence
- 830504072/ Advises of intention to address AEDD/E304. "Investigation of Backflow Protection in Common Equipment 'n Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," by using NRR Ofc Ltr 40 DENTON, HR Office of Nuclear Reactor Regulation, Director 83/04/12 HCLEMESC J Director's Office 1p 18328 098 24% Fiche 50 317.83/04/12.830504072/
- 3305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping" Ginell Memitter raping "
 BROWNE J Reactor Operations Analysis Branch 83/04/19
 SEVERTIVE V Reactor Operations Analysis Branch ip it
 24% Fiche 50 000 83/04/19 8305230573 18541 342
- --8305230619 "Cracks & Leaks in Smell Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of PIPING BROWN, E J BROWN E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 34X Fiche 50-000,83/04/19,8305230573
- 3305020509 Nontoutine radiological environ operating rept During First Quarter 1993.sampling of gamma-emitting tadionutiles indicated presence of AM-110m w/higher than permitted Concentration

 FURRMAN. G R Boltimore Gas & Electric Co 83/04/21 Region 1

 Office of Director 2pp 18781 264 24X Fiche 50-317.83/04/21.
- | 305110392 Forwards LER 83-016/03L-0 | RUSSELL.I. B | Baltimore Gas & Electric Co | 80 | Region | 1 | Defice of Director | 1p | 18406 | 127 | Fiche | 50-317, 83/04/27, 8305110352 | 83/04/27 ALLAN, J. M.
- -BJ05110363 LER B3-016/03L O on BJ032B during transfer of resin from miscellameous waste ion exchanger to solid waste, hole developed in sight glass for resin transfer line Caused by attempt to open resin clog Piping mods developed JUNGE, M A. UNKLE, T J Baltimore Oas & Electric Co B3/04/27 Region 1. Office of Director 2pp 18406 L28 24X Fiche 50 317.83/04/27,8305110352
- 305270072 RD 30-317/83-19 on 830426, while raising RCS pressure to 400 psig. PGRV ERV 404 inadvertently opened Valve immediately isolated by shutting upstream valve Complete description of event & corrective actions will be submitted RUSSELL. B Baltimore Gas & Electric Co 83/04/27 ALLAN, J M Region 1, Office of Director 2pp 18638 302 24% Fishe 50-317, 83/04/27, 8305270072
- 309270609 RO 83-21 confirms operation ctr 830430 verbal notification of error in assumption used for main steam line break (MSLB) accident analysis Reanalysis performed of MSLB event assuming failure of main feed regulating valve RUSSELL.4. D Baltimore Gas & Electric Co 83/05/02 ALLAN.J M Region 1. Office of Director ip 18646 102 24X fiche 50-317.83/05/02.8305270603

- 8305040530 PND-1-83-044 on 830503, effect of continued feedwater flow due to failed open feedwater regulating valve incorporated per addit questions re licensee response to IE Bulletin 80-04, "Analysis of PMR Main Steam Line Break" ARCHITEEL MCCABE Region 1. Office of Director 83/05/03 18347 892 24X Fiche 50-317.83/05/03.8303060530 83/05/03
- B305060412 Submits description of analyses of main steam line break inside containment per IE Bulletin 80-04 resulting in B30430 LER Feedwater sys mods being initiated Continued operation justified LUNDVALL, A E Baltimore Gas & Electric Co Operating Reactors Branch 3 8pp 18343 245 24X Fiche 50-317.83/05/04.8305060412
- 8305190287 Forwards LER 83-022/04X-0 RUSSELL,L B Baltimore Gas & Electric Co 83. Region i. Office of Director in 19301 111 Fiche 50-317,83/05/05.8305190287 ALLAN, J M 83/05/05
- --8305190290 LER 83-022/04X-0 on B21118, higher than normal radioactive Ag-10m levels found in oyster samples Caused by natural tendency of oysters to biconcentrate environ silver All releases in CY82-83 within allowable ETS limits BROBST-0 E Baltimore Gas & Electric Ca 83/05/05 Region 1 Office of Director 1p 18501 112 24X Fiche 50-317,83/05/05,8305190287
- 8305230510 Forwards LER 83-019/017-0 RUSSELLL B Public Service Electric % Gas Co of New Jørsey 83/05/05 ALLAN, J M Region 1, Office of Director 1p 18 24x Fiche 50-317,83/05/05.8305230510 18536 315
- --8305230513 LER 83-019/01T-0 on 830426, PCRV ERV-404 opened while raising AUSZENDIA LER B3-0197011-0 ON B30925,PURV RRV-40 opened while raisi
 RCS pressure Caused by failure of control room opened to to
 monitor RCS pressure carefully Short circuit caused loss of
 control power to ERV-402 during troubleshooting
 MENDERLICH,R L. Baltimore Gas & Electric Co 83/05/05 Region
 1, Office of Director. 2pp 18336 316 24X Fichs 50-317,
 83/05/05,8305230510
- 8305230555 Forwards LER 83-018/03L-0 RUSBELL, L B Baltimore Gas & Electric Co 83/05/01 Region 1, Office of Director 1p 18537 331 24X Fiche 50-317,83/05/05,8305230555 83/05/05 ALLAN, J M
- --8305230560 LER 83-018/03L-0 on 830408, during maint, emergency diesel generator failed to start Probably caused by inadvertent admission of air into fuel oil sys during maint Investigation continuing

 JUNGE M A . PAVIS.O S Baltimore Gas & Electric Co 83/05/05 Region 1. Office of Director 2pa 18537 332 24X Fiche 50-317,83/05/05,8305230355
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on B30315-0412 No noncompliance noted BTAROSTECKI, R Division of Project & Resident Programs 83/0 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18300 243 Fishe 50-317,83/04/19.8305030198
- --B305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on B30315-0412 No JUSCOINED THE INSPECTOR SOFT AND CONTROL TO THE SOFT AND CONTROL TOOM, accessible plant structures plant operation radiation protection physical security & fire protection ARCHITEL, R E Division of Project & Resident Programs 22pp 18300 245 24x Fiche 50-317.83/04/19.8305030198 Ø3/04/18
- 8305040077 Forwards exemption request for rollef from requirement for installation of fixed/automatic fire suppression sys in control room complex & intake structure.per 830304 request CLARK.R A Derrating Reactors Branch 3 83/04/21 LUNDVALL.A E Rochester Gas & Electric Corp 3pp 18359 264 24% Picke 30-317.83/04/21.8303050077
- --8305060084 Exemption from requirements for installation of fixed/ automatic fire suppression sys in control room complex beintake structure
 EISENHUT, D G Division of Licensing E3/04/21 Baltim
 Electric Co Spp 18359 267 24X Fiche 50-317.83/04/21. Baltimore Gas & Electric Co 8305060077
- 8305040627 Releases public version of ray to emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/04/25 Docum Management Branch ip 18339 201 24X Fiche 50-317.83/04/25. Document 8305060627

- --8309060631 Forwards public version of Rev 9.Change 2 to Emergency Pian Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8.Change 1 to ERPIP 4 9 3 re guide for selection of respirators
 4 Baltimore Gas & Electric Co 83/04/07 NRC No Detailed Affiliation Given 1p 18359 202 24X Fiche 50-317.83/04/25. BR05066627
- --8305060635 Public version of Rev 9.Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8.Change 1 to ERPIP 4 5 3 re quide for selection of respirators RUSSELL.J B Baltimore Gas & Electric Co 83/03/30 6pp 18359 203 24X Fiche 50-317.83/04/25.8305066627
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York Inc 16pp 18540 095 24x
 Fiche 50-000,83/05/11,8305110034

J Insurance & indomnity information

- B305240302 Forwards Endorsement 53 to NELIA Policy NF-216 & Endorsement 42 to HAELU Policy NF-76 OAMHE: 0 0 Baltimore Gas & Electric Co 83/05/23 DINITZ, I Assistant Director for State & Licensee Relations 3pp 18625 163 24X Fiche 50-317:83/05/23;8305260302
- P Operating license stage documents & correspondence
- 8305240249 FOIA request for three categories of documents re Reactor Bafety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515, 2787 & 2802)
 SHCLLY,S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 19 18593 178 24X
 Fiche 50-000,83/03/11,8305240249
- B305240254 Partial response to FDIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addi documents in grogress FELYON.J M Division of Rules and Records B3/03/31 SHOLLY.B C Union of Concerned Scientists 2pp 18593 179 24% Fiche 50-000.83/03/31.8305240254
- --B3D5240269 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RSSMAP) analysis if rept is to be published clear statement of program assumptions & limitations should be included TIERNAM, J A Baltimore Gas & Electric & B2/03/05 BURDICK, G R Office of Nuclear Regulatory Research, Director 35pp 16593 255 24X Fiche 50-000.B3/03/31.B305240254
- 9305040783 Forwards Amends 82 & 45 to Licenses DPR-53 & DPR-69, respectively safety evaluation & notice of issuance & availability Amends revise Tech Specs to increase steam generator min pressurization temp

 JAFFE.D H Operating Reactors Branch 3 83/04/21 LUNDVALL.A E Baltimore 9as & Electric Co. 2pp 18327 204 24% Fiche 30-317,83/04/21,8305040783
- --8305040789 Amends 62 & 65 to Licenses DPR-53 & DPR-69, respectively, increasing steam generator min pressurization temp, correcting typographical error & limiting overtime for personnel involved in safety-related activities CLARK, R & Operating Reactors Branch 3 83/04/21 34pp 18327 206 24X Fichs 50-317,83/04/21,8305040783
- --8305040793 Safety evaluation supporting Amends 82 & 65 to Licenses DPR-53 & DPR-69 respectively * Office of Nuclear Reactor Regulation, Director 83/04/21 3pp 18327 240 24X Fichs 50-317:83/04/21:8305040783
- --8305040795 Notice of issuance & availability of Amends 82 & 65 to Licenses DPR-53 & DPR-67, respectively CLARK:R A Operating Reactors Branch 3 83/04/21 2pp 18327 243 24X Fiche, 30-317,83/04/21,8305040783
- B303060045 Forwards SER supporting util responses to NUREG-0737, Items II.F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Hater Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Items resolved CLARK, R A Operating Reactors Branch 3 83/04/21 LUNDVALL, A E Baltimore Oak & Electric Co 9p 18354 299 24X Fiche 50-317,83/04/21,8305060045

- 8305060396 Submits improvement program to decrease personnel error/ action-related events Two types of personnel awareness programs initiated Training staff increased & instructor matis upgraded TIERMAN, J. A. Baltimore Oas & Electric Co. 83/01/27 CLARK, R. A. Operating Reactors Branch 3. 3pp. 18343-1/4 24X Fiche 50-317.83/04/27.8305060396
- 8305060402 Application for amend to Licensis DPR-53 % DPR-69, changing Tech Spec to clarify wording of surveillance reductments for sealed sources each time leactor staltup occurs Fee encl LUNDVALLA E Baltimore Gas % Electric Co 82/04/27 CLARK, R A Operating Reactors Branch 3 5pp 18343 291 24X Fiche 30-317, 83/04/27, 8305060402
- --8305060405 Proposed Tech Spec changes, clarifying wording of surveillance requirements for sealed sources each time reactor startup occurs

 Baltimore Oas & Electric Co 83/04/27 7pp 18343 276 24X Fiche 50-31/.83/04/27,8305060402
- 8305020455 Generic Ltr 83~19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amonds to OLs Svc list encl EISENHUT. D G. Davision of Licensing 83/05/02 Consolidated Edison Co. of New York. Inc. Sopp. 18441 120 24X Fiche 50-000.63/05/02.8305020455
- B305180768 Advises that action required by Amend 61 to License DPR-67 b Amend 80 to License DPR-53 complete since util negotiating w/DDE red disposal of high level maste ur spent nuclear fuel JAFFE.D H Operating Reactors Branch 3 83/09/04 LUNDVALL.A & Baltimoro Gas & Electric Co 2pp 18506 055 24x Fiche 50-317.83/05/04.8305180768
- B305170246 Forwards Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec requirements for equipment batch & safety-related air filter sys JAFFE.D H Operating Reactors Branch 3 83/05/05 LUNDVALL.A E Baltimere Gas & Eloctric Co 3pp 18477 011 24X Fiche 50-317.83/05/05.8305170246
- --8305170259 Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectivelyrevising Tech Spec surveillance requirements for equipment hatch & safety-related air filter sys CLARK,R A Operating Reactors Branch 3 83/05/05 64pp 18477 014 24X Fiche 50-317,83/05/05,8305170246
- --8305170266 Bafaty evaluation supporting Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively # Affice of Nuclear Reactor Regulation, Director 83/05/05 7pp 18477 078 24X Fiche 50-317,83/05/05.8305170246
- --8305170273 Notice of issuance & availability of Amends 83 & 46 to Licenses DPR-53 & DPR-69, respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/05 2pp 18477 085 24X Fiche 50-317.83/05/05.8305170246
- B305180536 Forwards Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends allow periodic testing of control element assemblies w/inoperable reed switch stack sys NAFFE.0 H Operating Reartors Branch 3 83/09/05 LUNDVALL.A & Balt(more Gas & Electric Co 3pp 18505 090 24% Fiche 50-317,83/05/05,8305180556
- --8305180579 Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, allowing periodic testing of control element assemblies w/inoperable read switch stack sys CLARK, R A Operating Reactors Branch 3 83/05/05 17pp 18505 093 24X Fiche 50-317.83/05/05,8305180996
- --8305180607 Safety evaluation supporting Amends 84 t 67 to Licenses DPR-53 t DPR-69, respectively * Office of Nuclear Reactor Regulation, Director 83/05/05 4pp 18505 iii 24X Fiche 50-317,83/05'05,8305180556
- ---8305180614 Notice of issuance 5 availability of Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively THAMMELL.C M Operating Reactors Branch 3 83/05/05 2pp 18505 119 24X Fiche 50-317.83/05/05.8305180556
- 8305070659 Generic Ltr 83-20 to all operating reactor licensess to holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EIBENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627-153 24X Fithe 50-000.83/05/09.8305090659

DOCKETED ITEMS

- aggg190293 Responds to 830325 ltr re current qualification status & plans for completion of environ qualification of all safety-related alectrical equipment Extension to 850430 for completion requested for Unit 1 LUNDVALLA E Baltimore Gas > Electric Co 83/05/10 CLARK.R A Operating Reactors Branch 3 4pp 18501 107 24x Fiche 50-317 83/05/10.8305190293
- 8305200078 Forwards request for add1 info re 830504 submittal on main steam line break analysis Operation justified pending completion of revised analysis CLARK,R A Operating Reactors Branch 3 83/05/10 LUNDVALL.A & Baltimore Gas & Electric Co 3pp 18541 038 24X Fiche 50-317.83/05/10.8305200078
- B305260274 Forwards response to BJ0405 diant technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per B30518 telcon ASH,R E B31timore Gas & Electric Co B3/05/24 EISENHUT,D G Division of Licensing 2pp 18629 161 24X Fiche 50-317,83/05/24, R3035A0294
- B305270027 Forwards marked-up proposed Tech Spec 3/4 & 1 & recontainment tendon surveillance PATTCRSON:M D Baltimore Gas & Electric Co 83/05/24 JAFFE:D H Operating Reactors Branch 3 3pp 18638 310 24X Fiche 50-317.83/05/24.8305270029
- G Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!

 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83703/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24x Fiche 50-000:83/03/21.83120260385
- 6303040021 1E Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155 244 Fiche 90-000,83/04/15,8303040021
- 8305030198 Forwards IE Insp Repts 50-317/83-0/ % 50-318/83-07 on B30313-0412 No noncompliance noted STAROSTECKI, R Division of Ploject % Resident Programs 83/04/19 LUNDVALLIA E Baltimore Gas * Electric Co 2pp 18300 243 24% Fiche 50-317/83/04/19/8305030198
- --8305030208 IE Insp Repts 50-317/83-07 / 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control foom, accessible plant structures, plant operation, radiation protection, physical security 5 fire protection ARCHITZEL, R E . RRIMBLE, D C . MCLABLE, E C Division of Project & Resident Programs 83/04/18 22pp 18300 245 24% Fiche 50-317,83/04/19,8305030198
- 8303040023 IE Info Notice 83-22, "BWR Safety/Reliaf Valve Failures "
 Svc list encl
 JORDANIL L Division of Emergency Frepatedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24x Fiche 50-000,83/04/22,8303040023
- 8303040025 IE info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JURDAN.C L Division of Emergency Prepaisoness & Engineering Response (Post 830103) 83/04/25 Chisolidated Edison Co of Naw York, Inc 1199p 18381 291 248 Fiche 50-000,83/04/25,8303040025
- 8303020340 Ack receipt of 830340 lti informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-01 & 50-318/83-01 BELLAMY.R R Region 1. Office of Director 83/04/26 LUNDVALL.A E Baltimore Ges & Electric Co ip 18277 G65 24X Fichs 30-317.83/04/26.8308020340
- --8305020344 Responds to NRC 830303 ltr re violations noted in 1E lnsp Repts 50-317/83-01 & 50-318/83-01 Corrective actions changes made to Radiation Safety Procedures 2-306 / 2-305 for max air flow & protection Factor, respectively LUNDVALL.A E Baltimore Gas & Electric Cu 83/03/30 MARYIN.T T Division of Engineering & Technical Programs 2pp 18277 066 24X Fiche 50-317,83/04/26,8305020340
- #305110276 Forwards IE Insp Repts 50-31/f3-09 % 50-318/83-09 on #30406-08 No noncompliance noted #ARTIN.1 T Division of Engineering & Technical Programs #83/04/21 LUMBVALLA E #8161more Gas & Electric Co Rpp 18393 237 24X Fichs 50-317,03/04/27,8305110276

- --8305110277 IE Insp Ropts 50-317/83-07 & 50-318/83-07 on 830406-08 No noncompliance noted Major areas inspected environ munitoring program for operations, including mpt controls, program for GC of analytical measurements & implementation of program JANG, J C. PASCIAK. W J Region 1. Ofrice of Director 83/04/26 4pp 18393 237 24X Fiche 50-317,83/04/27,8303110276
- 8303040024 IE Info Notice 83-24, "Loose Palts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 119pp 18382 047 24X Fiche 30-000,83/04/20,8303040026
- B303040027 IE Info Notice 83-25, "Stondby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Svc list end! JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidate Edison Co of New York, Inc 118pp 18382 165 24X Fichs 30-000, 83/04/28, 8303040027
- 8303040028 IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl URBANL L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc 1(st encl JGROBA,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24% (iche 50-000,83/05/04,8303040030)
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list enci JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New Yorf, Inc 119pp 18441 001 24x Fiche 50-000.83/05/04.8303040031
- B305060412 Bubmits description of analyses of main stoom line break inside containment per IE Bulletin 80-04 resulting in B30430 LER Fredwater sys mods being initiated Continued operation justified LUNDVALL.A E Baltimore Cas & Electric Co 83/05/04 CLARK.R A Operating Reactors Branch 3 Bpp 18343 269 24X Fiche 30-317,83/05/04.8305060412
- B303040033 IE info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "Svc list encl Deformation "Svc list encl Division of Emergency Proparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York Inc 115pp 18323 24B 24X Fiche 30-000,83/03/04.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Quidelines "Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24x Fiche \$0-000,83/05/11.8303040034
- 8305200620 Forwards info in response to remaining open issues in IR Bulletin 80-04 re main steam line break inside containment, supplementing 830504 ltr Installation of main feedwater systrip scheduled for completion by 831117 LUNDVALLA C Baltimore Gas & Electric Co D3/05/1/ CLARK, R A Operating Reactore Branch 3 3pp 18520 062 24% Fiche 50-317,83/05/17,8305200620
- --8305200628 Discusses enalyses of potential consequences of main steam line break inside containment w/failed-open main feedwater regulating valve & provides justification for continued operation.per IE Builetin BO-04 Rolated (nfo encl LUNDVALL:A E Baitimore Gas & Electric Co 83/05/17 CLARK,R A Operating Reactors Branch 3 30pp 18520 065 24x Fiche 50-317,83/05/17,8305200620
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,C L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24x Fiche \$0-080,83/05/19,8303040040
- 8303040046 IE info Notice 83-03, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830(03) 83/05/26 Consolidated Editon Co of New
 York, Inc 114pp 18647 007 24x Fiche 50~000.83/03/26.8303040046

- R Periodic operating reports & related correspondence
- 9305200631 Forwards meteorological data for semiannual effluent repts for 1992. LUNOVALL.A E Baltimore Gas & Electric Co 83/05/04 ALLAN.J M Region 1. Office of Director 19 18519 173 24X Fiche 50-317.83/05/04.8305200631
- --8305200644 "Calvert Cliffe Nuclear Power Plant, Mateorological Data," Jan-June 1982 # Baltimpre Cas & Electric Co 93/05/04, 68pp 18519, 174, 24x Fiche 50-317, 83/05/04, 8305200631
- 8305200564 Forwards monthly operating repts for Apr 1983 LOTITO,E M Baltimore Ges & Electric Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p. 18514.128 24X Fiche 50-317.83/05/13,8305200564.
- --8305200584 Monthly operating repts for Apr 1983 LOTITO:E Baltimore Gas & Electric Co 83/05/15. 10pp 18514 129. 24X Fiche 50-317:83/05/13:8305200564
- 8 Reportable occurrences, LERS & related correspondence
- B305040727 Advises of intention to address AEOD/E304, "Investigation of Bactflow Protection in Common Equipment & Floor Drain Bys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," by using NRR Ofe Ler 40.

 DENTON:H R. Office of Nuclear Reactor Regulation: Director B3704/12 HELTEMES, C J Director's Office. Ip 18328,098, 24X Fichs 30-317,83/04/12,8305040727
- 8305030383 Forwards LER 83-015/03L-0 RUSSELL.L B Baltimore Oas & Electric Co 83/04/18 ALLAN, J M. Region 1, Office of Director Ip 18308:198 24X Fiche:50-318,83/04/18,8305030383
- --B305030388 LER 83-015/03L-0 on 830321, invalid in-core detector linear heat rate alarm revealed incorrect alarm setpoints entered on 830307 Gaused by improper alarm setpoint forms Setpoints corrected & forms clarified PIERINGER, P A . BOWMAN, N E. Baltimore Oas & Electric Co 83/04/19. Region i. Office of Director ip 18308 199 24X Fiche 50-319,83/04/18. 8305030383
- 8305020509 Nonroutine radiological environ operating rept During First Quarter 1983, sampling of gamma-emitting radionuclides indicated presence of AM-110m w/higher than permitted concentration FUHRMAN.0 R Baltimore Oas & Electric Co 83/04/21 Region 1, Dffice of Director 2pp 18281 264, 24X Fiche.50-317,83/04/21, 8305020509
- 8305160081 LER 83-019/03L-0 has been canceled RUSSELL.L.8 Baltimore Cas & Electric Co 83/04/22 ALLAN, J M Region 1, Office of Director Ip 18450 356. 24X Fiche 50-318,83/04/22,8305160081
- 8305040146 Forwards evaluation rept on loss of saltwater flow to avewater HXs Removal of locked open nonsafety-related HX discharge valves recommended CINTULALY G. Reactor Operations Analysis Branch. 83/04/25 SEYFRIT, K V Reactor Operations Analysis Branch (p. 18327-015-24X Fiche 50-318,83/04/23,8305040146
- --8305040150 "Loss of Balt Water Flow to Svc Water HXs." evaluation rept CINTULA:T C. Director's Office 83/04/25 7pp. 18327:016 24X Fiche 50-318,83/04/25:8305040146
- B305060530 PNO-I-83-044 on B30503, effect of continued feedwater flow due to failed upen feedwater regulating value incorporated per add1 questions re licensee response to IE Bolletin B0-04, "Analysis of PNR Main Steam Line Break ..." ARCHITIEL, MCCABE Region i, Difice of Director, B3/05/03, ip 18347.272 24X Fichs 50-317.83/05/03,8305060550,
- B3030A0412 Submits description of enalyses of main steam line break inside containment per IE Bulletin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified.

 LUNDVALL: A E Beltimore Gas & Electric Co 83/05/04. CLARK: R A. Operating Reactors Branch 3. Spp. 18343.265 24X Fiche: 80-317:83/05/04.8305060412.
- 8305190348 Forward: LER B3-023/03L-O.
 RUBSELL,L B. Baltimore Cas & Electric Co. 83/05/05 ALLAN,J.H
 Region 1: Office of Director. 10, 18500.023 24X
 Fiche 50-318.83/05/05.8305190348

- --8305190352 LER 83-023/03L-0 on 830405, control power fuse for main vant RMB panel (1622F) blew due to short circuit Caused by short when control circuit relay auxiliary contacts Jumpered. Electricians cautioned Wiring properly labeled JUNGE, M., BABBO, L.F. Baltimore Gas & Electric Co 83/05/05, Region i, Office of Director ip 18500.024, 24% Fiche 50-318.83/05/05.8305190348
- 8305230522 Forwards LER 83-022/03L-0 RUBBELL.L B Baltimore Cas & Electric Co 83/05/05 ALLAN.J H Region 1. Office of Director 1p 18536 327 24X Fiche 50-318.83/05/05.8305230522
- --8305230528 LER 83-022/03L-0 on 830411, during surveillance testing, auxiliary feedwater actuating sys channel ZF setpoint for steam generator delta pressure found out-of-spec Caused by E/I isolator output drifting low isolator replaced PIERINGER.P.A : BASSO.L F Baltimore Oas & Electric Co. 83/05/05 Region 1, Diffice of Director. 1p 18536.328 24X Fiche 50-318,83/05/05,8305230522.
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- 8303040875 Releases public version of rev to emergency preparedness procedure FELTON-J M Division of Rules and Records. 83/04/25 Document Management Branch 1p. 18351.242 24X Ficher 50-320, 83/04/25, 83053040375.
- --8305040580 Public version of Rev 4 to Emergency Preparedness Procedure 1034 8, "Callout of Oneite & Offsite Duty Roster Personnal." BEAVER, J. R. BARTON, J. General Public Utilities OPV Service Corp. 83/04/11 16pp. 18351.244. 24x Fiche 50-320.83/04/25, 8303040375.
- 8305050377 Releases public varsion of rev to emergency plan implementing procedure. FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p. 18352; 163 24X F(che: 50-920, 83/04/25, 8305050377
- --8305050381 Public version of Rev 1 to Emergency Plan Implementing Procedure 1054, 28. "Activation of Technical Support Ctr." STANDELS J General Public Utilities OPU Bervice Corp 83/03/17 5pp 18352.164 24X Fiche 50-320.83/04/25.8305050377.
- 8305100143 Submits status of offsite emergency preparedness issues re FEMA regional varifications through 830304 & data received through 830331 concerning schedule for completion of issues at facilities.

 KRIML R. Federal Emergency Management Agency, 83/04/26 JORPAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 9pp. 18375-001 24X Fiche-50-289,83/04/26,8305100143.
- B305060082 Informs of add1 mod to schedule for fire detection capability in chemical cleaming bldg. Scheduled completion date extended to B30715.

 KANOA B K General Public Utilities QPU Service Corp. B3/04/29 SNYDER, B J. TMI Program Office 1p. 18345.050 24X Ficher 50-320:83/04/29.8305060082
- 8305110034 Ceneric Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Byc list encl.

 EISENNUT, D. O. Division of Licensing 83/05/11. Consolidated Edison Co of New York. Inc. 16pp 18540-095. 24X Fichs 50-000.83/05/11.8305110034
- B305200563 Forwards clarification of security plan.per NRC 821116 request Clarification withheld (ref 10CFR2.790) KANGA.B.K. General Public Utilities QFU Barvice Gorp B3/05/16. 8NYDER.B J TMI Program Office 1p. 18514;269, 24X Fiche 50-320,83/05/16.8305200563
- 6. Adjudicatory correspondence •
- 8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Absarce dissenting views encl CHILK, S. J. Office of the Secretary of the Commission. 83/03/31. Commissioners 3pp 17807:049, 24X Fiche. 50-000, 83/03/31, 8304040470
- 8305040054 Discusses status of E&W-QPU lawsuit document review. Next rapt expected within 2 wks.
 DIRCKB/N J. Office of the Executive Director for Operations.
 83/04/20 PALLADINO, N. OILINSKY, V. AHEARNE, J. Commissioners.
 2pp. 18336: 325, 24X Fiche: 50-289, 83/04/20, 8305040054.

3

- --B303040068 Staff requirements mamo re 830330 briefing on investigation a possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wis CHILK, BJ Office of the Secretary of the Commission 83/04/08 DIRCKS, WJ Office of the Executive Director for Operations MAYES, B B NRC No Detailed Affiliation Given CUMMINOS, JJ Office of Inspector & Auditor. 2pp 18336 327 24X Fiche 50-289, 83/04/20,8305040054
- 8305230700 Requests cooperation in informing NRC of outstanding safety concerns re facilities Prompt notification re allegations of safety concerns requested PLAINE.H H Office of the General Counsel 83/04/20 DEVINE.T Government Accountability Project 2pp 18542 323 24X Fiche: 50-289, 83/04/20, 8305230700
- 8305040230 Order extending time until 830513 for Commission to act to review ALAB-701
 HQYLE, J C Office of the Secretary of the Commission 83/05/05
 Commissioners ip 18345:196 24X Fiche. 50-000. 83/05/05,
- 8305130060 Response opposing intervenor motion for recusation. Motion does not specifically discuss reasons why prior activities may constitute conflict of interest PALLADINO.N J Commissioners 83/05/11 2pp 18436 228, 24X Fiche: 50-000.83/05/11.8305130060.
- 8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701 CHILK: 8 J Office of the Secretary of the Commission 83/05/12 Commissioners ip 18437 033, 24X Fiche, 50-000, 83/05/12, 8305130061.
- B303240216 Advises that 830323 ltr requesting immediate halt to all work at TMI-1 & 2, w/exception of maint necessary for safety, will receive consideration as request for action under 10CFR2.206 FR notice encl
 DENTON.H.R Office of Nuclear Reactor Regulation, Director B3/05/17. KING,R Three Mile Island Public Interest Resource Center. 2pp. 18573 306 24X Fiche 50-289,83/05/17,8305240216
- ---8305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at TMI-1 & 2

 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 89/05/17. 1p. 18573:308. 24X Fiche 50-289.83/05/17.8305240216
- B305200540 Order extending time until 830527 for Commission to act to review intervenor B21227 petition for review of ALAB-701 CHILK, B. J Office of the Secretary of the Commission B3/05/19, Commissioners ip. 18514 283 24X Fiche 50-000, B3/05/19, B305200560.
- 8303240536 Affidavit of RE Rogan confirming util commitment to activate amergency operations facility & staff facility w/emergency support director within 1 h of site area or general emergency notification or declaration ROGAN:R E. General Public Utilities QPU Service Corp 83/05/20. 4pp. 18376:087 24% Fiche 50-000;83/05/20,8305240536
- 8305250376 Confirms T Poindexter & HN Hilcove 830527 telcon committing to discuss outstanding contentions.

 #ILCOVE.M.N. Hearing Branch 2. 83/05/23 JOHNSRUD.J H
 Environmental Coalition on Nuclear Power 1p. 18585:349 24X
 Fiche: 50-320,83/05/23,8305250376
- 8305310017 Memorandum & order to hold decision in ALAB-701 in abequace until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Beparate J Ahearne statement encl CHILK, B. J. Office of the Secretary of the Commission 83/05/27, 14pp. 18653.311. 24X Fiche.50-000.83/05/27,8305310017.

H. General correspondence

- B305120015 Requests that LP King, site operations director, be deleted from future correspondence & JJ Chwastyk, manager, plant operations be added to distribution list KANDA, B. K. General Public Utilities - QPU Service Corp. 83/05/06 BNYDER, B. J. THI Program Office 1p. 18428, 232 24X Fiche: 50-320, 83/05/06, 8305120015.
- P. Operating license stage documents & correspondence
- 8305270022 Forwards "Rept on Hental Health Effects of TMI Accident "
 BROMET, E. J. Pittsburgh, Univ of, 83/03/08, SHANKMAN, S. F. Site
 Analysis Branch, 1p. 18634 001 24X Fiche 50-320, 83/03/08, 8305270022.

- --8305270027 "Rept on Mental Health Effects of TMI Accident " BROMET, E J Pittsburgh, Univ of. 83/02/28 NRC - No Detailed Affiliation Given 77pp 18634 OO2 24X Fiche 50-320,83/03/08, 8305270022
- --8305270035 "Psychological Stress Among THI Area Residents & Mediation of Response by Support & Coping "BAUN,A , SCHAEFFER,M A , COLLINS.D L Uniformed Services Univ of the Health Sciences NRC-03-82-125 83/03/08 NRC No Detailed Affiliation Given 34pp 18634 089 24X Fiche 50-320.83/03/08.8305270022
- --B305270040 Forwards final rept, "Reanalysis of TMI Telephone Survey Data"
 HOUTS.P 8 Pennsglvania State Univ NRC-03-B2-123 83/03/01 REOAN.W NRC No Detailed Affiliation Given 1p 18634 122 24X Fiche 50-320,83/03/08.B305270022
- --B305270044 "Reanalysis of TMI Telephone Survey Data," final rept HDUT6,P B , MILLER,R W , LINDELL.M Pennsylvania State Univ B3/02/2B NRC No Detailed Affiliation Given 125pp 18834 123 24X Fiche 50-320, B3/03/08, B305270022
- --8305270048 Draft "Restarting TMI-1.Social & Psychological Impacts on Communities" SGRENSEN, J., BODERSTROM, J., Oak Ridge National Laboratory, BOLIN, R., New Mexico State Univ 83/03/08 NRC - No Detailed Affiliation Oiven 207pp 18634 248 24X Fiche 50-320,83/03/08, R303270022
- B305200101 FDIA request for name of manufacturer of fuel rods used at facility WHITED:P J Affiliation Unknown B3/03/23 FELTON.J M Division of Rules and Records 1p 18541 005 24X Fiche 50-320.83/03/23, 830520101
- B3052000B7 Responds to FOIA request for name of manufacturer of fuel rods used at facility Fuel rods mfg by B&W FELTON.J M Division of Rules and Records 83/03/31 WHITED.P J Affiliation Unknown 1p 18541 004 24X Fiche 50-320,83/03/31,8305200087
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24X Fiche 50-000,83/04/11.8305230720
- 8305020530 Presents NRC review of & recommendations on util B30131 reviewd schedule & cost info re recovery DIRCKB.W.J Office of the Executive Director for Operations 8ECY-83-140 B3/04/15 33pp 18284-261 24X Fiche 30-320, 83/04/15, 8305020930
- 8305040686 Requests responses re relief from surveillance requirements of equipment which would result in excessive exposure Tech Bpec change requests, scheduling for recovering affected sys & rev to recovery plan requested BARRETT.L.H. TMI Program Office B3/04/27 KANGA.B K General Public Utilities QPU Bervice Corp 3pp 18336-327 24X Fiche. 50-320,83/04/27,8305040686
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISE/NHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 30pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- 8305120055 Forwards Training Procedure 6210-ADM-2604 01, Rev 1-00, "Gontrol of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02, Rev 1-00, "Operator Training Instructor Indectrination/Gualification Training Program" HUKILL.H.D General Public Utilities GPU Service Corp. 83/05/06, 810LI.J. F. Operating Reactors Branch 4 1p 18428 233 24X Fiche: 50-289, 83/05/06, 8305120055
- --8305120064 Rev i-00 to Training Procedure 6210-ADM-2604 O1, "Control of Exems for Units 1 & 2."

 General Public Utilities GPU Service Corp. 83/04/26 7pp 18428-234, 24X Fiche: 50-289; 83/05/06; 8305120055
- 8305180238 Forwards Amend 21 to License DPR-73, safety evaluation & notice of issuance & availability, Amend consists of changes to radiological environ monitoring program requirements in Tech Specs.

 BNYDER, B. J. TMI Program Office 83/05/06. KANGA, B.K. General Public Utilities GPU Service Corp. 3pp 18503-001 24X Fiche 50-320,83/05/06,8305180238.

- --8305180245 Amend 21 to License DPR-73, consisting of changes to radiological environ monitoring program requirements in Tech
 - 8pecs. BNYDER, B. J. THI Program Office 83/03/04 34pp 18503 004 24X Fiche 50-320, 83/05/04, 8305180238
- --8305i80249 Safety avaluation supporting Amend 21 to License DPR-73 e Dffice of Nuclear Reactor Regulation, Director B3/05/06 iOpp. 18503;038. 24% Fichs 50-320:83/05/06/8005180238.
- --8305180253 Notice of issuance & availability of Amend 21 to License DPR-73 DPN-73 BNYDER, B. J. TMI Program Defice 83/05/06. 3pp. 18503 048 24X Fiche 50-320, 83/05/06, 8305180238
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant gods Svc list encl Edison Co of New York, Inc 16pp 18627 153 24x Fiche: 50-000, 83/05/09, 8305090659 Consolidated
- 8305170435 Provides status of activities re makeup & purification demineralizer resin sampling & Characterization Results will be available by end of May. Delay should not adversely mact commitment of mid-1983 resin removal techniques assessment KANOA, S.X. Ganeral Public Utilities OPU Service Corp. 83/05/BARRETT. L. H. TMI Program Office. 3pp. 18469-303-24X Fiche: 50-320, 83/05/12, 8305170435. 83/05/12
- 8305170448 Responds to 830427 ltr re questions on ALARA exception to Tech Spec surveillance. Several surveillances performed, w/esception of small portions in high radiation areas KANOA, B K General Public Utilities OPU Service Corp. 83/05/13 BARRETF, L H TMI Program Office. 7pp 18469 306. 24X Ficha: 50-320, 83/05/13, 8305170448
- 8305200073 Forwards list of application dates, fees paid, fees applicable & fee determination for each application. HILLER, W O Opfice of Administration. 83/05/17 ARNOLD.R C General Public Utilities GPU Service Corp 3pp 18540.131 18540, 131 24X Fiche 50-320,83/05/17,8305200073
- 8305280255 Forwards Rev O to "SER for Radiation Cheracterisation Under Reactor Vessel Head," KANOA,B.K General Public Utilities GPU Bervice Corp BARRETT.L.H TMI Program Office ip 18592:326 24X BARRETT, L. H TMI Program Office 1p 18592: 326 Fiche: 50-320, 83/05/19, 8305250255
- --- 8305250263 Rev O to "SER for Radiation Characterization Under Reactor Vessel Head. vessel ness; ... + Ceneral Public Utilities - GPU Service Corp. 83/05/17. 27pp 18592.027 24% Fiche:50-020,83/05/19.8305250255
- 8305310038 Forwards Rev Q to "SER for Radiation Characterization Under Reactor Vessel Head (Polar Grane Not Available)," for review & approval, Activity scheduled to begin mid-June KANOA, B. K. General Public Utilities - OPU Service Corp. 83/05/25. BARRETT, L. H. TMI Program Office, ip. 18655, 076 24X Fiche 50-320, 83/05/25, 8305310058,
- --B305310103 Rev 0 to "BER for Radiation Characterization Under Reactor Vessel Head (Polar Crane Not Available), " " General Public Utilities PU Service Corp B9/05/17 27pp. 16455,077, 24X Fiche: 50-920,83/05/25,8305310058.
- 8305310118 Forwards responses to NRC 830121 comments on Rev 3 to general project design criteria. Responses will be incorporated into Rev 4.19 acceptable KANGA: B K General Public Utilities OPU Service Corp 83/05/25. SNYDER.8.J. TMI Program Office 4pp 18658:087 24K Fiche: 50-320, 83/05/25, 8305310118
- B303310136 Forwards addendum to underhead characterization SER re-core topography. Document demonstrates that proposed acoustic survey of core can be accomplished w/o undux risk & should be considered addendum to previously submitted SERs KANOA:3 X. General Public Utilities QPU Service Corp. 83/05/26 BARRETT.L. H. TRI Frogram Office. Bpp. 18453.036. 24X Fiche:30-320:83/05/26.8305310136
- G. Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewetered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Syc list
- enci, TAYLDR.J.M. Division of Befeguards & Inspection Programs (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc 112pg 18308:319 24X Ficher 50-000,83/03/21,8212060385.

- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 - Bvc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fichs 30-000, 83/04/15, 8303040021
- 8305030151 Forwards IE Insp Rept 50-320/83-04 on 830227-0403 No noncompliance noted

 STAROSTECKI,R Division of Project & Resident Programs 83/04/19
 KANOA,B K General Public Utilities - GPU Service Corp 2pp
 18300 274 24% Fiche 50-320,83/04/19,8305030151
- --8305030164 IE Insp Rept 50-320/83-04 on 830227-0403 No noncompliance JUDOUDIA IE Insp Rept 50-320/83-04 on B30227-0403 No noncompliance noted Major areas inspected licenses action on previous insp findings, routine plant operations, LERs, health physics review reactor bldg entries & radioactive matt shipments WIEBE. J. BARR, K. MOSLAKT Region i. Office of Director B3/04/19 App 18300 276. 24X Fiche 50-320, 83/04/19, 8305030151
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Syst list entl.

 JORDAN, E.L. Division of Emergency Preparadness & Engineering
 Response (Post 830103). 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Stram Generators at PWRs." Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/28 Consolidated Edison Co of New
 York, Inc 115pp. 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 30-000,83/04/28,8303040027
- 8303040029 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 9303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Gaused by Fuel Rack Deformation," Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of York, Inc. 115pp. 18523:248 24X Fiche, 50-000, 83/05/06, 8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11 Consolidated Edison Co. York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." 303040040 as any November 2014 and Sec 11st encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). B3/05/19 Consolidated Edison Co. of New
 York, Inc. 114pp 18697, 009. 24X Ficher 30-000, 83/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 011. *Byc list and Jones & Engineering OpenAnkE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York: Inc 114pp 18647.007 24X Fichs 50-000.83/05/26.8303040046.

- R Periodic operating reports & related correspondence
- 8305040163 Forwards TMI Program Ofc weekly status rept for wk of B30410-16 BARRETT,L H TMI Program Office 83/04/18 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office (Opp 18327 001 24% Fiche 50-320,83/04/18,8305040163
- B305040170 Forwards TMI Program Ofc weekly status rept for wk of B30417-23
 BARREIT, L H TMI Program Office B3/04/25 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 9pp 18327 023 24X Fiche 50-320, B3/04/25, 8305040170
- 8305020210 Forwards "TMI Aquatic Study Monthly Rept for Mar 1983 "
 RESSLER.W C General Public Utilities GPU Service Corp 83/04/28
 RICKEY, C NRC No Detailed Affiliation Diven 1p 18278 167
 24% Fiche 50-289,83/04/28.8305020210
- --8305020215 "TMI Aquatic Study, Monthly Rept for Mar 1983 "
 NARDACCI, 0 A Ichthyological Associates, Inc 83/04/28 21pp
 18278 168 24X Fiche 50-289, 83/04/28, 8305020210
- 8305030462 Forwards recovery sys description & technical evaluation rept Annual updates for auxiliary bldg emorgency liquid cleanup sys (EPICOR II), solid radwaste staging modules & submerged demineralizer sys,per 820204 ltr KANGA, B K General Public Utilities GPU Service Corp 83/04/26 BNYDER, B J TMI Program Office 2pp 18293 228 24X Fiche 50-320,83/04/28,8305030462
- --8305030470 "Recovery Program Sys Description Auxiliary Bldg Emergency Liquid Clean-up Bys (EPICOR II) " + General Public Utilities - GPU Service Corp 83/03/31 52pp. 18273 230. 24X Fiche 50-320.83/04/28.8305030462
- --8305030478 "TMI-Unit 2 Sys Description of Submerged Demineralization Sys (SDS) " General Public Utilities - GPU Service Corp 83/03/31 204pp 18293 282 24% Fiche 50-320.83/04/28,8305030462
- --8305030484 Rev 1 to "TMI-Unit 2 Recovery Program, Solid Haste Staging Facility Sys Description"

 * General Public Utilities GPU Service Corp 83/04/28 21pp 18294 126 24X Fiche 50-320,83/04/28,8305030462
- 8303040458 Forwards "Annual Environ Operating Rept.1782," "Ecological Bludy of Susquehanna River Near TMI" & "Hydraulic Survey "HUKILL: HD General Public Utilities GPU Service Corp 83/04/27 Region i, Office of Director ip 18347,038 24X Fiche 50-289,83/04/27,8305040458
- --8305060460 "Annual Environ Operating Rept, 1982 "

 * General Public Utilities GPU Service Corp 82/12/31 18pp 18347 060 24X Fiche 50-289, 83/04/29, 8305060458
- --8305060464 "Hydraulic Survey," annual rept # General Public Utilities - GPU Service Corp 82/06/03. 13pp 18349.078 24X Fiche 50-289.89/04/29; 8305060458
- --8305060465 "Ecological Study of Busquehanna River Near TMI," annual rept for 1982 NARDACCI.0 A Ichthyological Associates, Inc. B3/04/30, 633pp 18349:091, 24X Fiche 50-289,83/04/29,8305060458
- 8305060649 Forwards "TMI Nuclear Station Radiological Environ Konitoring Rept.1982 " W/o and! HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29 Region 1. Office of Director 1p 18348 250, 24X Fichs.50-289,83/04/29,8305060649
- 8303060668 Forwards TMI Program Ofc waskly status rept for wk of 830424-30 BARRETT, L H TMI Program Office 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director SKYDER, B J. TMI Program Office 8pp. 18357:348 24X Fiche 50-320,83/05/02,8305060668
- B305240603 Forwards TMI Program Ofc weekly status rept for wk of B30501-07
 BARRETT, L H TMI Program Office. 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director, SHYDER, B. J TMI Program Office. 7pp. 18593-167. 24X Fiche, 50-320, 83/05/09, 8305240603
- 8305240561 Forwards TMI Program Ofc weekly status rept for wk of 830508-14.

 BARRETT.L H TMI Program Office 83/05/16 DENTON:H R. Office of Nuclear Reactor Regulation. Director SNYDER:B J TMI Program Office 9pp 18593 328, 24X Fiche.50-320.83/05/16.8305240561.

- 8305250385 "Guarterly Dose Assessment Rept, First Guarter 1983 "
 KANOA, B K General Public Utilities GPU Service Corp 83/05/18
 ALLAN, J M Region 1. Office of Director 5pp 18585 342 24X
 Fiche 50-320, 83/05/18, 8305250385
- 8305240348 Periodic groundwater monitoring program rept for Mar 1982 Apr 1983 KANQA.D K General Public Utilities - OPU Service Corp. 83/05/19 BARRETT,L H TMI Program GPFice 38pp 18574 017 24X Piche 50-320.83/05/19.8305240348
- 8 Reportable occurrences, LERs & related correspondence
- 8305030527 Forwards LER 83-010/01L-0 KANOA: B K General Public Utilities - OPU Service Corp 83/04/20 ALLAN.J M Region 1. Office of Director 1p 18275 323 24X Fiche 50-320.83/04/20.8305030327
- --8305030535 LER 83-010/01L-0 on 830322, in-core thermocouple H-3 began to exhibit erratic behavior Cause unknown To date no adverse trend in overall core thermocouple sys behavior apparent CHAPLIN-8 D General Public Utilities GPU Service Corp. 83/04/20 Region 1, Office of Director 2pp 18295-324 24X Fiche 50-320,83/04/20,8305030527
- B305110370 Forwards LER B3-011/01L-0 KANOA.B K General Public Utilities - OPU Barvice Corp B3/04/25. ALLAN.J M Region 1. Office of Director 1p 18404, 275 24X Fiche 50-320. B3/04/23, B305110370
- --8305110378 LER 83-011/011-0. on 830325, verified that 3 h reted fire damper not instelled in fire wall separating fuel handling bldg from reactor bldg annulus area Caused by AE error during const of plant Hourly firewatch posted.

 CHAPLIN:8 D General Public Utilities OPU Service Corp 83/04/25 Region 1. Office of Director 3pp 18406 276. 24X Fiche 50-320,83/04/25,8305110370
- B305110321 Forwards LER B3-012/03L-0 KANOA:B K General Public Utilities - OPU Bervice Corp. B3/04/2B ALLAN.J M Region 1. Office of Director ip 18406 071 24X Fiche 50-320.B3/04/2B.B305110321
- --8305110326 LER 83-012/03L-0 on 830329, following inadvertent discharge of one zone of air intake tunnel Halon sys.pressure of Halon bottle EI-4C discovered to be below allowable limit Caused by personnel errors Bottle repressurized WELLB.R General Public Utilities OPU Service Corp. 83/04/28, Region 1. Office of Director 3pp 18406,072 24X Fichs 30-320,83/04/28,8305110321
- B305310001 Forwards updated LERs KANOA,8 K General Public Utilities - OPU Bervice Corp B3/05/19 ALLAN,J M Region 1. Office of Director 2pp 18653 040 24X Fiche 30-320,83/05/19,8305310001
- --8305310004 Updated LER 80-001/79X-1 on 800126.60 amp molded case circuit breaker for generator auxiliaries found tripped.
 Caused by defective internal connection on A phase Breaker replaced
 CMAPLIN.8. D General Public Utilities OPU Service Corp 83/03/19 Region 1. Office of Director 2pp 18653-062. 24X Fiche 50-320,83/05/19,8305310001
- --8305310007 Updated LER 80-003/01X-1 on 800218, emergency diesel generator B out of avc for annual maintiviolating Tech Specs requiring both emergency diesel generators to be operable Gaused by change in Tech Specs,
 CHAPLIN, B D General Public Utilities GPU Service Gorg,
 83/05/19 Region 1, Office of Director 2pp. 18653-064. 24X
 Fiche 50-320,83/03/19,8305310001
- --8305310010 Updated LER 80-007/01X-1 on 800222, exhaust fan AH-E8C removed from svc for maint, violating Interim Recovery Tech Specs Caused by inability to restore unit to operable etatus within action period. Fan repaired CHAPLIN, 8 D Ceneral Public Utilities GPU Service Corp 83/05/19. Region 1, Office of Director 2pp. 18653'066, 24X Fiche 50-320,83/05/19.8305310001
- ---8305310014 Updated LER 80-012/01X-1. on 8004(3, exhaust flow of fuel handling bldg HVAC sys fell below recovery operation plan requirement Caused by either sys imbalance or flow rate requiring rev Fan lineup altered CHAPLIN,8 D General Public Utilities GPU Service Corp. 83/05/19, Region 1, Office of Director. 2pp 18453:048, 24X Fiche 50-320,83/05/19,8305310001.

- --83053;0019 Updated LER 80-049/01X-1 on 801027, discovered that valve LTB-V171 ASME Code stamped by unauthorized valve supply house Caused by unauthorized use of ASME UV code stamp by North American Safety Valve Industries, Inc CHAPLIN,8 D General Public Utilities GPU Service Corp 83/05/19 Region 1, Office of Director 3pp 18653 070 24X Fiche 50-320,83/05/19,8305310001
- --8305310024 Updated LER 80-054/03X-1 on 801117, emergency diesel generator DF-X-1R failed to start Caused by not maintaining diesel at high enough shutdown ambient temp due to heater failure Heater & contactor replaced CHAPLIN.8 D General Public Utilities GPU Service Corp 83/05/19 Region 1. Office of Director 3pp 18853 073 24 Fichs 50-320,83/05/19,8305310001
- --8305310030 Updated LER 80-055/03x-1 on 801127, emergency diesel generator DF-X-1B failed to start Caused by Failure to maintain diesel at high enough shutdown ambient temp due to heater failure Heater & contactor replaced CHAPLIN.S D General Public Utilities GFU Service Corp 83/05/19. Region 1. Office of Director 3pp 18653 076 24X Fiche 50-320,83/05/19,8305310001
- --8305310036 Upfated LER 80-056/01X-1 on 801212, core floor tank level instrumentation A inoperable Gause unknown Tach Spec 3 3 6 revised to delete core floor tank level indicators from specs
 CHAPLIN, B D General Public Utilities GPU Service Corp 83/05/19 Region 1, Office of Director. 3pp 18653 079 24X Fiche 50-320, 83/05/19, 8305310001
- --B305310041 Updated LER 80-057/03x-1 on 801217, air intake tunnel chlorine monitor declared (noperable due to failure to reapond upon exposure to chlorine vapors Caused by dirty grabe Probe cleaned & returned to svc CHAPLIN.S D General Public Utilities GPU Service Corg B3/05/19 Region i. Dffice of Director 2pp 18653 082 24X Fiche 50-320,83/05/19.8305310001
- --8305310047 Updated LER 81-004/03X-1 on 810204, emergency diesel generator DF-X-1B failed to start Caused by low diesel ambient temp Pump motor repaired on 810302 CHAPLIN, B D General Public Utilities GPU Service Corp 83/05/19 Region i, Office of Director 2pp 18653 084 24X Fiche 50-320, 83/05/19, 8305310001
- --8305310056 Updated LER 81-008/03X-1 on 810416.diesel driven fire pump failed to start Caused by failed battery Diesel switched to 8 bank.Preventive maint procedure written to replace fire ave diesel batteries A & 8 every 5 yrs CHAPLIN.8 D General Public Utilities GPU Service Corp 83/05/19 Region 1, Office of Director 2pp 18653 087 24X Fiche.50-320,83/05/19.8305310001
- ~-B305310061 Updated LER 81-010/01X-1 on B10420, shift & daily check logshest not consistent w/recovery Tech Specs in that seven instruments received daily rather than per shift checks Caused by errors in procedure logshest Procedure revised SHARTZHELDER: R General Public Utilities ~ GPU Service Corp B3/05/19 Region 1. Office of Director 3pp 18653.089 24X Fiche 50-320,83/05/19.8305310001
- --8305310066 Updated LER 81-012/03X-1 on 810422, emergency diesel generator A failed to develop output voltage Caused by corrosion & pitting of relay contacts Relay replaced Surveillance Procedure 4603-R1 revised CHAPLIN.S D. General Public Utilities GPU Service Corp 83/05/19 Region in Office of Director. 3pp 18653 092 24X Fiche.30-320.83/05/19,8305310001
- --8305310072 Updated LER 81-020/03X-1 on 810830, fuel handling bldg ventilation sys inoperable due to high pressure differential & low exhaust flow rate. Caused by excessive loading of prefitters & first bank HEPA fitters CHAPLIN.8 D General Public Utilities GPU Service Corp. 83/05/19 Region in Defice of Director 3pp, 18653 093 24X Fiche 50-320,83/05/19.8305310001
- --8305310078 Updated LER 81-022/03X-1.on 810907.channel calibr of gas partitioner performed past scheduled expiration date Caused by heavy manpower loads in conducting Unit 1 hot functional tests Instrument calibr SHARTZHELDER:R General Public Utilities OPU Service Corp 83/05/19 Region 1 Office of Director 2pp. 18653 097 24X Fiche 50-320.83/05/19.8305310001.
- --8305310080 Updatef LER 81-023/03X-1'on 810911.control bldg charcoal filters lab tested to acceptance criteria of 95% rather than 97% as required Caused by misinterpretation of Reg Quide 1.32.New filters Installed.

 SWARTZWELDER/R. General Public Utilities GPU Service Corp 83/05/19. Region 1. Office of Director. 2pp 18653 099 24% Fiche 30-320,83/05/19.8305310001

- --B305310087 updated LER 81-032/03X-1 on B11105, while reviewing operating records, discovered that exhaust flow fell below Tech Specs min on B11028 Caused by low auxiliary bldg supply flow rate & problems w/design & operation of supply damper CHAPLIN.8 D General Public Utilities OPU Service Corp 83/03/19 Region 1. Office of Director 3pp 18453 101 24X Fiche 50-320,83/05/19.8305310001
- --8305310091 Updated LER 81-034/01X-1 on 811201, in-core thermocouple F-12 inoperable Caused by polarity of thermocouple being reversed Procedures revised to prevent future occurrence CHAPLIN, B D General Public Utilities GPU Service Corp 83/05/19 Region 1, Office of Director 3pp 18693 104 24X Fiche 50-320, 83/05/19, 8305310001
- --8305310094 Updated LER 81-035/03X-1 on 811201, wind direction monitoring instrument inoperable Caused by ice formation on instrument Instrument deiced & permanent weather station heater jacket installed CHAPLIN.8 D General Public Utilities GPU Service Corp 83/05/19 Region 1, Office of Director 2pp 18453 107 24X Fiche 30-320,83/05/19,8305310001
- --8309310101 Updated t.ER 81-034/03X-1 on 811214, wind direction monitoring instrument inaperable Caused by ice formation on instrument Instrument deliced & permanent weather station heater jacket installed on instrument CHAPLIN.8 D General Public Utilities GPU Service Corp. 89/05/19 Region 1, Office of Director 2pp 18453 109 24X Fiche 50-320,83/05/19,8305310001
- --83053J0107 Updated LER 81-038/03x-1 on 811228, wind direction & wind speed monitoring instruments inoperable Caused by ice formation on instruments Instruments heat traced as temporary measure CHAPLIN, S D General Public Utilities QPU Service Corp 83/05/19 Region 1, Office of Director 2pp 18653 111 24X Fiche 50-320,83/05/19,8305310001
- --8305310114 Updated LER 82-034/01X-1 on 821021, once-through steam generator A level indication failed Caused by separated electrical connector, failed power supply & inadequate procedure Valves opened & level indicators repaired CHAPLIN-S D General Public Utilities OPU Service Corp 83/05/19 Region 1. Office of Director 2pp 18453 113 24X Fiche 50-320,83/05/19,8305310001
- T Hearing transcripts on non-antitrust matters
- B305040086 Transcript of 830422 briefing in Washington,DC re TMI-2 cleanup Pp 1-78 * Commissioners 83/04/22 124pp 18328 242 24% Fiche 30~320,83/04/22,8305040086
- 8305120312 Forwards transcripts, including corrections, re investigation by EH Stier of allegations by OPU & Bechtel KANGA, B K General Public Utilities OPU Service Corp 83/05/06 BARRETT, L H Thi Program Office ip 18433 241 24X Fiche 50-320, 83/05/06, 8305120312
- --8305120317 Testimony of JC Auger re investigation of allegations by GPU & Bechtel Pp 1-13 AUGER, J C General Public Utilities -- GPU Service Corp 83/03/31 15pp 18433 242 84X Fiche 50-320,83/05/06,8305120312
- --8905:20323 Testimony of JJ Chwastyk re investigation of allegations by OPU & Bechtel Pp 1-16 CHWASTYK, J J General Public Utilities - GPU Service Corp 83/03/31 [Spp 18433 257 24X Fiche 50-320,83/05/06,8305120312
- --8305120326 Testimony of R Gummo re investigation of allegations by GPU & Bechtel Pp 1-12 GUMMO.R General Public Utilities - OPU Service Corp 83/04/06 14pp 18433 275. 24X Fiche: 50-320.83/05/06.8305120312
- --8305120330 Testimony of EJ Kitler re investigation of allegations by GPU & Bechtel Pp 1-7 KITLER,E.J Dechtel Corp 83/04/06 9pp 18433 289 24X Fiche 50-320,83/05/06,8305120312
- --8305120335 Testimony of QA Kunder re investigation of allegations by QPU & Bechtel Pp I-15. KUNDER: © A General Public Utilities - GPU Service Corp 83/04/15 18pp. 18433 298 24X Fichs 50-320,83/05/06,8305120312
- --830512033B Testimony of WJ Marshall re investigation of allegations by GPU & Bechtel Pp i-14
 MARSHALL, W J General Public Utilities GPU Service Corp
 83704/04 i6pp 18433 316 24X Fiche 50-320,83/05/06,8305120312.

- --8305120341 Testimony of JF Perry ne investigation of allegations by GPU 1 Bcchtel Pp 1-14
 PERRY J F General Public Utilities GPU Service Corp 83/04/06
 16pp 18433 332 24Y Fiche 50-320.83 09/06.8305120312
- --8305120344 Testimony of RF Ryan re investigation of allegations by GPU
 - & Bechtel Pp 1-4 RYAN,R F Batocct & Wilcol Co 83'01'06 6pp 18433 348 24y Fiche 30-320,83/05/06,8305120312
- --B305120347 Tustimony of LC Rugers 10 investigation of allegations by GPU & Bechtel Pp 1-B RODERS.L C Babcock & Wilcox Co B3/01 01 9pp 18433 354 24X Fiche 50-320, 83/05/06, 8305120312
- --8305120350 Testimony of BC Smith re investigation of allegations by GPU & Bechlel Pp 1-5 GPU & Bechlel Pp 1-5 SMITH. B G General Public Utilities GPU Service Corp 83/04/06 7pp 18430 343 24% Fiche 50-320.83/05/06.8305120312
- ---8305120355 Testimony of JA Smith re investigation of allegations by GPU & Rechtel Pp 1-15
 SMITH.J A Gilbert/Commonwealth Cos 83/03/31 17pp 18434 007
 24% Fiche 50-320,83/05/06.8305120312
- --8305120357 Testimony of RP Harren re investigation of allegations by GPU & Dechtel Pp 1-10 HARREN.R P General Public Utilities GPU Service Corp 83/03/31 1Ppp 18434 024 244 Fiche 50-320.83/05/06.8305120312
- 8305230189 Forwards marked-up excerpt from NRC testimony from Udall 830426 hearing on facility, consisting of Pages 69-81 Memo dtd 830506 & original excerpt also cncl DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/17 KAMMCRER.C Office of Congressional Affairs 20pp 18377 249 24X Fichs 50-3F0.83/05/17,8305230189
- --8305230199 Forwards transcript of Commissioners statement before House Subcommittee on Energy & Fryiron 830426 hearing in Hashington, DC Transcript should be edited & returned by 830516 RANDERER, C Defice of Congressional Affairs 83/05/06 PALLADIND, N, GILINSKY, V, AHEARNE, J F Commissioners 18577 271 24X Fiche 50-320,83/05/17,8305230189 Commissioners ip
- --8305230209 Transcript of Commissioners statement at House Subcommittee on Energy & Environ 830426 hearing in Washington, DC Pp 68-86
 - PALLADIND, N , GILINSKY, V , AHEARNE, J F Commissioners 83/04/26 18577 272 24% Fiche 50-320,83/05/17,8305230189

U Congressional/Executive Correspondence

- B305040138 Forwards proposed Chairman testimony before Udall Subcommittee 830406 hearing to developments since Apr 1982 at TMI, responding to items in Congressman Udall 830413 ltr W/o proposed testimony BENTON. HR Office of Nuclear Reactor Regulation, Director B304/200 BIRCKS, W J Office of the Executive Director for Operations 2pp 18327 011 24% Fiche 50-289,83/04/20,8305040138
- --B305040145 Enumerates Itoms to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982 UDALL.M K House of Rep. Interior * Insular Affairs 83/04/13 PALLADING.N Commissioners 2pp 18327 013 24X Fiche 50-789,83/04/20.8305040138
- 8305230435 Forwards response to Question 20 in 030223 ltr re NRC review of BEM/OPU trial record PALLABIND.N J. Commissioners 83/04/28 UDALL,M K. House of Rep., Interior & Insular Affedra 2p. 18942 051 24X Fichs 50-289,83/04/28,8305230435
- --8305230440 Informs of dissenting apinion re Commission majority decision blocking General Counsel review of B&W/CPU trial record in TMI-1 restart proceeding Decision will hamper ability of individual Commissioners to obtain needed info GILINSKY. V Commissioners 83/04/07 GIMPSON. A K Senate, Environment & Public Works 2p. 18542 053 24X Fiche 50-289,83/04/28.8305230435
- --8305230443 Responds to Chairman Palladino 830309 request for views on legality of Commission decision directing Executive Director for Operations, rather than Dfc of General Counsel, to review BEW/OPU trial record Actions supported PLAINE.H H E Office of the General Counsel 83/03/25 PALLADIO.N J. GILINSKY,V. AHEARNE.J Commissioners 5pp 18542 055 24X Fiche 50-289,83/04/28,8305230435

- -8305230446 Provides Commission response to Commissioner Gilinsky 830407 itr disagreeing w/Cammission majority decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Commission actions justified PALLADIND, N J Commissioners 83/04/19 UDALL, M K Rep . Intrior & Insular Affairs 4pp 18542 060 & Fiche 50-289,83/04/28,8305230435 House of
- ---B305230453 Disagrees w/Commission majority views in Chairman Palladino B30419 ltr justifying Commission decision to block General Counsel review of B&N/OPU trial record in THI-1 restart Counse: review of Commissioners 83/04/25 UDALL, M proceeding
 ASSELSTINE, J K Commissioners 83/04/25 UDALL, M p
 Rep , Interior & Insular Affairs 3pp 18542 064
 Fiche 50-289, 83/04/28, 8305230435 UDALL, M K

V Operator Examinations

- B305120055 Forwards Training Procedure 6210-ADM-2604 Ol.Rev 1-00, "Control of Exams for Units 1 & 2." % Procedure 6210-ADM-2610 O2.Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program "
 HUKILL: H D General Public Utilities GPU Service Corp B3/01
 STOLZ: J F Operating Reactors Branch 4 tp 18428 233 24X
 Fiche 30-287.83/03/06.8305120055 83/05/06
- -- 8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 01, "Control of Exams for Units 1 & 2 "

 * General Public Utilities - GPU Service Corp 83/04/26 7pp
 18428 234 24% Fiche 50-289,83/05/06.8305120055
- DOCKET 50-321 EDWIN ! HATCH NUCLEAR PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8305030485 Releases public version of revised emergency plan (2003) Reference Politic Vision Co. Implementing procedures
 FELTON.J M Division of Rules and Records 83/04/25 Docum
 Management Branch 1p 18309 141 24X Fiche 50-321,83/04/25.
- --8305030687 Forwards public version of revised emergency plan implementing procedures including Procedures HNP-4734 regeneral emergency -- Savannah River Operations Ofc & HNP-4757 re alert -- security force NIX.H C Georgia Power Co 83/04/07 Office of Nuclear Reacto Regulation. Director ip 18309 142 24X Fiche 50-321,83/04/25. Office of Nuclear Reactor
- --8305030690 Public version of revised emergency plan implementing procedures including Procedures HNP-4734 re general emergency Bayannah River Operations & HNP-4527 re allert - security force
 ROGERS,W H. NIX.H. Georgia Power Co. 83/04/04
 18309 143 24X Fiche 50-321,83/04/25,8305030685
- 8305040648 Releases public version of revised pages to emergency plan FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18306 275 24X Fiche 50-321, 83/04/25, B30504064B
- -8305040654 Forwards public version of revised Pages C-3 & P-1 to emergency plan
 CLLINGER, W H Georgie Power Co 83/03/31 NRC - No Detailed
 Affiliation Given Ip 18336 276 24X Fiche 50-321,83/04/25,
- --8305040459 Public version of revised Pages C-3 & P-1 to emergency plan * Georgia Power Co 83/02/28 Ppp 18336 277 24X Fiche 50-321,83/04/25,8305040648
- 8305060469 Clarifies requests for exemptions from 10CFR50 48 & App R requirements in response to NRC request at 830330 meeting Rev to 8200510 GUCHALL T Georgia Power Co 83/04/28 STOLZ, J.F. Operating Reactors Branch 4 lipp 18351 179 24X Fiche 50-321,83/04/28,8305060469
- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits access to control processors for the second of the SVc list encl EISENHUT, D G Division of Licensing 83/03/11 (Edison Co of New York, Inc 16pp 18540 075 24X Fiche 50-000, 83/05/11, 8305110034 Consolidated

8305250530 Submits info on compliance w/Branch Technical Position 305230530 Submits info on compliance w/Branch Technical Position 9 5-1 re qualification of fire protection engineers Qualification requirements met through maint of staff at affiliated svc company, Southern Co Svcs. Inc QUCMA. L T Georgia Power Co 83/05/19 STOL2, J F Operating Reactors Branch 4 1p 16586 229 24X Fiche 90-321,83/05/19, 200888820

H General correspondence

8305030261 Requests changes in correspondence routines due to recent ngt changes

QUCHALL T Georgia Pawer Cp 83/04/28 DENTON, HR Office of

Nuclear Reactor Regulation, Director 1p 18300 046 24X

Fiche 50-000, 83/04/28, 8303030261

J Insurance & indemnity information

8305040202 Forwards Endorsement 78 to NELIA Policy NF-215 & Endorsement 303040202 Porpards Endorsement 78 to NELIA Policy NP-213 & Endorsement 63 to MAELU Policy MF-78 BUCK.J R Harsh & McLennan, Inc 83/04/28 SALTIMAN.J Assistant Director for State & Licensee Relations 3pp 18324 028 24X Fishe 50-321,83/04/28.8305040202

8305200270 Forwards Endorsement 79 to NELIA Policy NF-215 & Endorsement 3U320270 Forwards Endorsement /Y to NELLA FOILCY NF-213 & Endorsement 44 to MARLU Policy MF-78

DUCK.J R Marsh & McLennan, Inc. 83/05/16 SALTZMAN.J Assistant Director For State & Licensee Relations 3pp 18516 256 24X Fiche 50-321,83/05/16,8305200270

8305230027 Forwards Endorsement 80 to NELIA Policy NF-215 & Endorsement 66 to MAELU Policy MF-78
DUCK-J R Marsh & McLennan, Inc 83/05/16 SALTZMAN, J Assistant
Director for State & Licensee Relations 3pp 18339 180 24X
Fichs 30-321,83/05/16,8305230027

P Operating license stage documents & correspondence

8304120027 Forwards revised order confirming licensee commitments on 30412002/ Forwards revised order confirming licensee commitments (post-TMT-related issues.correcting info re implementation schedule for Item II B 3, "Post-Accident Sampling "
BTOLT.J F Operating Reactors Branch 4 B3/03/30 BECKHAM, J T Georgia Fower Co 4pp 17957 320 24X Fiche 50-321,83/03/30,8304120027

--8304120042 Order revising schedule for submittal of info re Item II 8 3, "Post-Accident Sampling," from 830401 to 830701 PURPLE, RA Division of Licensing 83/03/30 Georgia Power 10pp 17957 324 24X Fishe 30-321,83/03/30,8304120027 Ceorgia Power Co

8303040769 Forwards safety evaluation & technical evaluation rept re TMI Items I A 2 1 4 "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4 "Training for Mitigating Core Danage " Programs satisfy NUREC-0737 requirements STOLZ.J F Operating Reactors Branch 4 83/04/20 DECKHAM.J T Georgia Power Co Spp 18327 300 24X Fichs 50-321.83/04/20, 8305040769

--8207080458 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II § 4," technical

* Science Applications, Inc SAI-186-029-34 62/07/01
No Detailed Affiliation Given 14pp 18327 303 24X
Fiche 50-321.83/04/20,6305040769

8305030634 Application to amend Licenses DPR-57 & NPF-5, revising Tech Specs re TMI Action Plan Items I A (1 3.1 A (3.11 E 4 1, II E 4 2 5-7.11 K 3 3.11 K 3 13.11 K 3 22.11 K 3 15. II K 3 19.11 K 3 27.11 K 3 45 & II F 1-4 BECKHAM.J T Georgia Power Co 83/04/22 STGLZ, J F Operating Reactors Branch 4 8pp 18305 285 24X Fiche 50-321.83/04/22, 6308030524 Reactors Branch 4

--8305030465 Revised Tech Specs Te TMI Action Plan Items I A I 1 3, I A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II, K 3 15, II K 3 17, II K 3 27, II K 3 45 & II F 1-4 4 Georgia Pawer Co 83/04/22 31pp 18305 293 24X Fiche 50-321, 83/04/22, 8305030634

8305040748 Summary of 830223-24 meetings w/util & EG&G in Atlanta. GA re proposed radiological effluent Tech Specs RIVENDARK. 8 W Operating Reactors Branch 4 83/04/22 STOLZ, J F Operating Reactors Branch 4 13pp 18327 179 24X Fiche 50-321.83/04/22,8305040748

830506067! Forwards EG&G 830404 itr transmitting list of NRC comments on unresolved items from proposed radiological effluent Tech Specs Earlier scheduled date for final submittal requested STOLZ.JF Operating Reactors Branch 4 83/04/22 BECKHAM, J T Georgia Power Co 2pp 18350 001 24% Fiche 50-321,83/04/22, 8305040671

--8304220237 Forwards list of major radiological effluent Tech Spec items from licensee proposal that were not resolved at Atlanta meeting Differences between Unit 1 & Unit 2 proposals are minor Commitment date for next submittal not identified SERRANO, W EG&G, Inc 83/04/04 WILLIS.C A NRC - No Detailed Affiliation Given 3pp 18358 003 24% F; che 50-321,83/04/22, 8305040671

B305060051 Forwards Rev 1 to "Design Rept for Recirculation Sys & RHR Sys Weld Overlay Repairs & Flaw Evaluation at EI Hatch Nuclear Power Plant Unit ! " QUCMA: L T Georgia Power Co B3/04/28 STGLZ.J F Operating Reactors Branch 4 2pp 18345 226 24X Fiche 50-321, B3/04/28, #30506031

--B305060035 Rev i to "Design Rept for Recirculation Sys & RHR Sys Weld Overlay Repairs & Flaw Evalvation at EI Hatch Nuclear Power Plant: Unit I " CHARNLEY. J E , RICCARDELLA, P NUTECH Engineers, Inc 9PC-04-104 R01 B3/03/04. 100pp 18345 228 24X Fiche 50-321,63/04/28. 8305040051

8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to GLs Svc list encl EIBENNUT.D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fich: 50-000, 83/05/02, 8305020455

8305060306 Requests that portion of 830422 response to Generic Ltr 83-02 be withdrawn Portion re Item II F I, "Addl Accident Monitoring Instrumentation," will be reevaluated upon receipt of NRC guidance GUCWALL T Georgia Power Co 83/05/02 STOL7. J F Operating Reactors Branch 4 1p 18344 323 24X Fiche 50-321,83/05/02,8305060306

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche, 50-000,83/05/09,830509069

8305200453 Commits to submit results of plant-unique calculations 305R00453 Commits to submit results of plant-unique calculations acceptability of mod to torus vacuum breakers by 830615, in response to Generic Ltr 83-08
OUCHALT Georgia Power Co 83/05/16 STOLZ.JF Operating Reactors Branch 4 1p 18519 085 24X Fiche 50-321.83/05/16. 8305200453

Q Inspection reports, IE Bulletins & correspondence

8212060395 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 1830B 319 84X Fiche 50-000,83/03/21,8212060385 TAYLOR, J M

8305270471 Ack receipt of 830328 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-02 DANCE, H C Division of Project & Resident Programs 83/04/07 KELLY, H J Georgia Power Co ip 18646 072 24X Fiche 50-366-83/04/07,8305270491

~-8305270523 Forwards IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 & notice of violation DANCE: H C Division of Project & Resident Programs 83/02/25 KELLY: R J Georgia Power Co 2pp 18646 075 24X Fiche 50-366

--8305270550 IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121
Noncompliance noted failure to make 24-h telephone rept
within required time limit
CRLENDAY,R V V, HOLMES-RAY,P Region 2, Office of Director
BROWNLEE,V,L Division of Project & Resident Programs B3/02/23
4pp. 18446 078, 24% Fiche 50-366,83/04/07,8305270471

8305270570 Requests that docket number in 830322 IE Insp Rept 50-336/83-05 be changed to 50-366/83-05 due to administrative error DANCE, H C Division of Project & Resident Progra KELLY, R J Georgia Power Co ip 18646 113 2 Fithe 50-321,83/04/08,8305270570

- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" gvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 122pp 18495 155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Bvc list enc!
 JQRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18363 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- 8305270332 Ack receipt of 830418 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-321/83-04 & 30-366/83-04 DANCE,H C Division of Project & Resident Programs 83/04/27 KELLY,R J Georgia Power Co ip 18642 066 24X Fiche 50-321,83/04/27,8305270332
- --B305270336 Responds to NRC B30318 ltr re violations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04 Corrective actions training directive issued to appropriate personnel stressing prompt notification of unusual event BECKHAM.J T Georgia Power Co B3/04/18 D'REILLY.J P Region 2. Office of Director 2pp 18642 067 24X Fiche 50-321, 63/04/27,8305270332
- --8305270343 Forwards IE Imap Repts 30-321/83-04 & 50-366/83-04 on 830207-11 & notice of violation DANCE: H C Division of Project & Resident Programs 83/03/18 MELLY: R J Georgia Power Co 2pp 18642 069 24X Fichs 30-321,83/04/27,8305270332
- --8305270351 Notice of violation from insp on 830207-11
 * Region 2, Office of Director 83/03/18 Ip 18642 071 24X
 Fiche 50-321,83/04/27,8305270332
- --8305270357 IE inap Repts 50-321/83-04 & 50-366/83-04 on 830207-11 Noncompliance moted failure to make proper notification to NRC following liquid radwasts release on 821209 HRAY, J R Region 2, Office of Director DARR. K P Division of Emergency Preparedness & Materials Safety 83/03/10 7pp 18642 072 24X Fiche 50-321,83/04/27,8305270332
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary 8ide of Steam Generators at PWR4" Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000:83/04/28,8303040027
- B303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Researce (Post 830103) B3/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04,8303040030
- 8303040031 IE Info Natice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Bvc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York Inc 117pp 1844; 001 24X Fiche 50-000.83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Cansalidated Edison Co of New York Inc 115pp 18523 248 24X Fiche 50-000.83/05/06,8303040033

- 8305160144 Submits 30-day response to SER & technical evaluation rept re environ qualification of Class IE equipment (IE Bulletin 77-018) Final plans for resolving qualification of items in Categories I B. II A & II B will be transmitted by 830520 GUCHALL T Georgia Power Co 83/05/06 SYDLZ.J F Operating Reactors Branch 4 374pp 18444 044 24X Fiche 50-321,83/05/06.8305160144
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Quidelines " Svc list and JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000.83/05/11.8303040034
- 8305270350 Forwards IE Insp Repts 50-321/83-11 & 50-366/83-11 on #30411-15 No noncompliance noted DANCE:H C Division of Project & Resident Programs #83/05/11 KELLY,R J Georgia Power Co 2pp 18644 323 24X Fichs 50-321,83/05/11,8305270350
- --8305270356 IE Insp Repts 50-321/63-11 & 50-366/83-11 on 830411-15 No noncompliance noted. Major areas inspected licenses action on previous enforcement matters. OA program design mods, test & experiments program E procurement program EELIBLE.O A. DEBBAGE.A O. UPRIOHI.C M. Region 2. Office of Director 83/05/11 14pp 18644 325 24X Fiche 50-321.83/05/11, 8305270350
- 8303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/19 Consolidated Edison Co of New York, Inc. | 114pp | 18697 009 24X Fiche: 50-000, B3/05/19, B303040040
- 8305270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program (UCHA). T Occupia Power Co. 83/05/19 8fCLZ, J.F. Operating Reactors Branch 4 1p 18638 217 24X Fiche 50-321,83/05/19,8305270128
- B303040046 IE Info Notice B3-03, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York: Inc 114pp 18647 007 24X Fiche 50-000:83/05/26.8303040046
- R Periodic operating reports & related correspondence
- 8305180279 Forwards monthly operating repts for Apr 1983 NIX.H C Georgia Power Co 83/05/06 Director's Office, Office of Inspection and Enforcement 1 p 18490 282 24X Fichs 50-321,83/05/06,8305180279
- --8305180284 Monthly operating repts for Apr 1983 REDNANZ.F J Gaorgia Power Co 83/05/06 12pp 18490 295 24X Fiche 50-321,83/05/06.8305180279
- B Reportable occurrences: LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept. "Cracks & Leaks in Small Diameter Piping"
 BROWN,E J Reactor Operations Analysis Branch 83/04/19
 SEYFRIT.K V Reactor Operations Analysis Branch ip 18541-342.
 24X Fichs 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leeks in Small Diamster Piping," engineering evaluation rept Small pips leaks associated w/unanticipsted vibration problems require addl supports or rerouting of piping BROWNE J Reactor Operations Analysis Branch B3/04/19 9pp 18541 343 24% Fichs 50-000, B3/04/19, 8305230573
- 8305050030 Forwards LER 83-040/03L-0 NIX,H C Georgia Power Co 83/04/21 O'REILLY,J P Region 2: Office of Director 1p 18342 092. 24X Fich# 50-321,83/04/21; 8305050030
- --8305050040 LER 83-040/03L-0 on 830325, reactor bldg exhaust vent A radiation monitor Dii-K609A as-found data unacceptable & monitor declared inoperable Caused by instrument drift. Dii-K609A calibr & returned to svc on 830325 TIPBS 8 8 Georgia Power Co 83/04/21 Region 2, Office of Director Jpp 18342:093 24% Fiche, 50-321,83/04/21,8305050030
- 8305050083 Forwards updated LER 83-036/01X-1 NIX.H C georgie Power Co 83/04/21 0/REILLY, J.P. Region 2, Office of Director 1p. 18342 020 24X Fiche 50-321,83/04/21, 8305050083

- --8305050087 Updated LER 83-036/01X-1 on 830323, plant review board datermined lack of administrative control existed in complying w/Procedure HNP-6921 because of matl condition of cable trays Caused by lack of specific instructions TIPPS S B Opengia Power Co 83/04/21 Region 2. Office of Director 5pp 18342 021 24X Fiche 50-321,83/04/21,8305050083
- 8305110269 Forwards LER 83-043/03L-0 NIX.H C Georgia Power Co 83/04/26 E/REILLY, J P Region 2, Office of Director ip 18393 222 24X Fiche 50-321, 83/04/26, 8305110269
- --8305110272 LER 83-043/03L-0 on \$30331.RHR svc water pump B did not reach required Tech Spec pressure Caused by air release valve for loop B failing to seat off Rubber seat & float replaced & float cage realigned
 TIPPS S B Georgia Power Co 83/04/26 Region 2. Dffice of Director 3pp 18373 223 24% Fiche 50-32(.83/04/26.830310269
- 8305110270 Forwards LER 83-044/03L-0 NIX.H C Georgia Power Co 83/04/26 O'REILLY, J P Region 2, Office of Director 1p 18379 274 24X Fiche 50-321.83/04/26, 8305110270
- --8305110273 LER 83-044/03L-0 on 830404. while performing math condition inap, sys engineer found two of four bolts not installed in valve operator mount at valve bonnet on RHR loop A min flow bupass valve Replacement bolts installed & torqued TIPP9.5 D Georgia Power Co 83/04/26 Region 2. Office of Director 3pp 18393 297 24X Fichs 50-321.83/04/26.8305110270
- 8305110431 Forwards LER 83-041/03L-0 NIX: H C Georgia Power Co 83/04/26 O'REILLY, J P Region 2, Office of Director 1p 18405 088 24X Fiche 50-321,83/04/26, 8305110431
- --8305110434 LER 83-041/03L-0 on 830329, following Group 5 (solation, outboard reactor water cleanup isolation valve failed to open Caused by overheated D-C drive motor on valve operator Drive motor replaced TIPPES B Georgia Power Co 83/04/26 Region 2. Office of Director 3pp 18405 089 24X Fiche 30-321,83/04/26,8305110431
- B305110404 Forwards LER B3-042/03L-0 NIX.H C Georgia Power Co B3/04/29 D'REILLY, J P Region 2: Office of Director 1p 18392 008 24X Fiche 50-321.83/04/29, B305110404
- --8305110412 LER 83-042/03L-0 on 830330,1/2 scram received Caused by scram discharge valve high level RPS relay burning & failing in tripped condition Relay raplaced & satisfactorily tested TIPPS:S B Georgia Power Co 83/04/29 Region 2. Office of Director 3pp 18392 009 24x Fiche 50-321.83/04/29.8305110404
- \$305130138 PNO-II-83-032 on \$30501, contractor employee suffered broken arm, fractured pelvis & possible skull fracture in machine shop accident Caused by cotton glove caught by valve stem pulling person into lathe w/contaminated valve ROGGE, J F, DAKCE, H C, Region 2, Diffice of Director \$3705/02 2pp 19437 277 24X Fiche 50-321, 83705/02, 8305130138
- 8305170178 Supplemental narrative summary to Rev 5 to RO 50-321/1979-021 Updated data on tritium levels in groundwater samples during First Guarter 1983 encl No radionuclides above background identified NIX.K C Georgia Power Co 83/05/02 G'REILLY, J P Region 2, Office of Director Jpp 18466 321 24X Fiche 50-321,83/05/02,8305170178
- 8305110289 Forwards LER 83-046/03L-0 NIX.H C Georgia Power Co 83/05/03 Q'REJLLY, J P Region 2. Office of Director Ip 18373 308 24X Fiche 50-321,83/05/03. 8305110289
- --9305110293 LER 83-046/03L-0 on 830411, channel A turus water level narrow range recorder T48-R607A, operated erractically Caused by dirty control amplifier plug connection Connection cleaned Procedure HNP-1-5372 run successfully TIPPS,S B Georgia Power Co. 83/05/03 Region 2, Office of Director Spp. 18393-309 24X Fiche 50-321,83/05/03.8305110289
- B305170254 Forwards LER B3-031/03L-0 NIX, H C Georgia Power Ca 83/05/05 O'REILLY, J F Region 2, Office of Director 1p 18466 130 24X Fiche 50-321, 83/05/05, 8305170254
- --8305170262 LER 83-031/03L-O on 830409, dioxide recorder pen on primary containment atmosphere bydrogen dioxide recorder 1P33-R601A read downscale & primary containment atmosphere sample sys outlet pumps found not running Caused by component failure. TIPPS,8 B Georgia Power Co 83/03/05 Region 2, Office of Director 3pp 18466 131 24X Fiche 50-321,83/05/05,8305170254

- 8305170434 Forwards LER 93-034/03L-0 NIX, H C Oeorgia Power Co 83/03/05 O'REILLY, J P Region 2, Office of Director 1p 18467 297 24X Fiche 50-321,83/05/05, 8305170434
- --8305170438 LER 83-034/03L-0 on 830407.control room air intake isolation valve 124j-F011 closed late during Procedure HNP-1-3973 Caused by faulty operator & lack of damper shaft lubrication Shafts lubricated TIPPS:S B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp 18469 278 24X Fiche 50-321.83/05/05.8305170434
- 8305170442 Forwards updated LER 83-036/01X-2 NIX.H C Georgia Power Co 83/05/05 D'REILLY.J P Region 2-Office of Director Ip 18471 230 24X Fiche 50-321,83/05/05, 9308370442
- --8305170445 Updated LER 83-036/01X-2 on 830320,22,23 & 0405,matl condition of cable trays found out of compliance w/Procedure NPP-6921 Caused by Jack of administrative control & nonspecific procedure instructions Procedure revised SUMBER. H L Georgia Power Co 83/05/05 Region 2. Office of Director 6pp 18471 231 24X Fiche 50-321.83/05/05.8305170442
- 8305110364 RO 50-366/83-01 on 830125 & 0314, Units 2 & I, respectively, had spray/sprinkler sys taken out of svc for mods & could not be restored to operable status within 14 days per Tech Specs Continuous fire Watches maintained NIX-H C Georgia Power Co 83/05/06 O'REILLY, J P Region 2, Office of Director 3pp 18406 262 24X Fiche 50-321, 83/05/06, 8305110364
- 8305230568 Forwards LER 83-047/03L-0 NIX:H C Georgia Power Co 83/05/09 O'REILLY.J P Region 2. Office of Director 1p 18537 305 24X Fiche, 50-321, 83/05/09, 8305230558
- --8305230577 LER 83-047/03L-0 on 830412,02 recorder pens on primary containment atmosphere H202 recorders 1P33-R601A & R601LB read 17% & 3 35% respectively Caused by tubing cap missing & open sample valve in analyzer sample line A Cap replaced. TIPPS B Georgia Power Co 83/05/09 Region 2, Office of Director 3pp 18537 306 24% Fiche 50-321,83/05/09,8305230568
- B305270234 Updated LER B3-036/01X-3 on B30320, lack of administrative control existed in complying w/cable & cable tray installation Procedure HNP-6721 because of matl condition of cable trays Caused by inadequate procedures W/B30516 ltr TIPPS 6 B : NIX.H C Georgia Power Co B3/05/16 0'REILLY, J P Region 2, Office of Director 9pp 18637 186 24X Fiche 50-321.83/05/16,8305270234
- 83053:0166 LER 83-045/03L-0 on 830423, while performing MSIV trip test, D outboard MSIV (1821-F028D) found to close slower than Tech Spec limit Caused by maladjusted actuator flow control needle valve W/830516 ltr
 TIPPS, 8 B., NIX.H C Georgia Power Co 83/05/16 D'REILLY.J P Region 2, Dffice of Director 4pp 18652 335 24X
 Fiche 30-321.83/05/16.8305310166
- 8305310180 Updated LER 83-040/03X-1.on 830325, reactor bldg exhaust vent radiation monitors D11-K609A & D found inoperable Caused by instrument drift & cable failure between detector & trip unit Monitor calibr W/830316 ltr
 TIPPS 8 B . NIX.H C Georgia Power Co 83/05/16 O'REILLY, J P Region P. Dffice of D1rector 5pp 18659 135 24X
 Fiche 50-321,83/05/16,8305310180
- 8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration
 HAISLER.R K Litton Industries. Inc 83/05/20 KEPPLER.J Q Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000.63/05/20.8305270625
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- B305050144 Responds to FDIA Requests 82-455.82-471 & 82-479 re suppression pool dynamic loads Encls to Documents 3 & 4 & rept encl w/Document 7 withheld (ref FDIA Exemption 4) FELTON.J M Division of Rules and Records B3/03/17 HAFNER.B Affiliation Unknown 2pp 18364 261 24X Fiche 50-322.83/03/17, B305050144

- --8305060133 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valvo vent clearing & steam quenching phenomena Schedule coordinated W/GE & other utils WOFFORD, A W Long Island Lighting Co 75/06/03 STOLZ, J F Light Water Reactors Branch 1 4pp 18364 266 24X Fiche 50-322, 83/03/17, 8305060144
- --8305060155 Requests add1 info re suppression pool temp limit Responses to Questions 1.2.4 & 5 will be provided by GE Question 3 must be answered by util KNIEL-K Light Water Reactors Branch 2 77/08/31 WOFFORD.A W Long Island Lighting Co 2pp 18364 283 24X Fiche 50-322,83/03/17.8305060144
- --8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Remshead Condensation Stability." in response to Questions 1.2.4 & 3 Submittal date for response to Question 3 will be provided BURKE.T J Long Island Lighting Co 77/09/26 KNIEL.K Light Water Reactors Branch 2 ip 18364 287 24X Fiche 50-322,83/03/17.8305060144
- 8305t60075 Corrects serial number of 930415 ltr transmitting Rev 3 to inservice testing program Correct identifier should be SNRC-857, not SNRC-859.
 SNITH, J L Long Island Lighting Co 83/05/03 DENTON, H R Dffice of Nuclear Reactor Regulation. Director 2pp 18450 351 24X Fiche 50-322,83/05/03,8305160075
- 8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D © Division of Licensing 83/05/04 PALLADIND, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8308040923
- 8305240342 Forwards minutes of 830421 meeting w/util & S&W re clarification of addl items in independent design review KING.J P Teledyne Engineering Services 83/05/06 DENTON,H R Office of Nuclear Reactor Regulation. Director 3pp 18571 001 24X Fiche 50-322,83/05/06,8305240342
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fichs 50-000,837/05/09,8305090659
- B305190491 Notification of 830524 meeting w/8uffolk County representatives in Bechesda, MD to discuss extension of CP CARUSO, R Licensing Branch 2 83/05/16 SCHHENGER, A Licensing Branch 2 4pp 18523 159, 24x Fiche 50-322, 83/05/16, 8305190491
- 8305240447 Provides status of implementation of SER recommendations re NUREO-0737, Item II K 3 16, "Feasability Study -- Challenges & Valve Failures " Preventive maint program will be available for site review in 2 months SMITH, J L Long Island Lighting Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 18572 338 24X Fiche 30-322,83/05/20,8305240447
- 8305270001 Forwards final classification of ICR 5633-19 re pipe support design calculations from independent design review Item closed LANDERB DF Teledyne Engineering Services 83/05/20 DENTON. H R Office of Nuclear Reactor Regulation, Director 6pp 18638 327 24X Fichs 30-322.83/05/20,8305270001
- B305250373 Forwards Teledyne Engineering Svcs B30506 ltr to HR Denton w/attachment re independent design verification program BORDENICK.B M Hearing Branch 3 B3/05/24 BRENNER.L . CARPENTER.J L. MORRIG.P A Atomic Sefety and Licensing Board Panel 7pp 18592 093 24% Fiche 50-322, 83/05/24.8305250373
- 8305310050 Responds to 830324 ltr re environ qualification of GE switches (Type CR 2940).List of switch locations & summary of generic environ qualification testing encl Switch failure would not adversely affect shutdown capability EMITH.J L Long Island Lighting Co 83/05/25 DENTON.H R Office of Nuclear Reactor Regulation. Director 12pp 18693 152 24X Fiche 50-322.83/05/25,8305310050

- E NRC Safety Evaluation Report (SER), supply & correspondence
- B30504050B Forwards Rev 2 to "4;60V Metal Encl Switchgear General Maint," providing description of inservice insp & testing programs to assure seismic integrity of electrical & mechanical components (SER Issue B)
 SMITH.J L Long Island Lighting Co B3/04/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 18321 023 24X
 Fiche 50-322,83/04/22,830504050B
- --8305040514 Rev 2 to Procedure 32 050 02, "4160V Metal Encl Switchgear General Maint "
 ROSE.J J Long Island Lighting Co 83/01/31 6pp 18322 032 24% Fiche 50-322.83/04/22.8305040508
- 9305040303 Forwards monthly status of equipment summary list including balance-of-plant & NBSS equipment to assist in review of SER Issue 8 on dynamic qualification.per 98:110 & 23 itrs SMITH.J L Long Island Lighting Co 83/04/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 52pp 18323 306 24Y Fiche 50-322.83/04/29.8305040303
- 8305160070 Responds to SER Issue 48. "High Energy Line Breats (HELB)" & 830124 request to consider addl single failure within sys used to mitigate event Postulated worst-case scenarios listed Occurrence of events unlikely Issue closed SMITH.J. Long Island Lighting Co 83/05/11 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 18450 116 24X Fiche 50-322.83/05/11.8305160070
- B305270013 Forwards monthly status list of active safety-related equipment per SER Issue 8 re dynamic qualification level SMITH.J L Long Island Lighting Co 83/05/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 52pp 18633 277 24X Fiche 50-322,83/05/23,8305270013
- F Security, medical, emergency & fire protection plans
- 8305120378 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IC Emergency Preparedness Appraisal Rept 50-322/82-18 MARTIN.T T Division of Engineering & Technical Programs 83/05/05 POLLOCKIM S Long Island Cliphting Co ip 18432 303 24Y Fiche 50-322,83/05/05,8305120378
- --8305120380 Responds to NRC 820930 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18 Corractive actions permanent responsibility for emergency planning assigned to emergency planning coordinator POLLOCK.MS Long Island Lighting Co 83/04/21 MARTIN.T T Division of Engineering & Technical Programs 12pp 18432 304 24X Fiche 50-322,83/05/05,8305120378
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits gvc list encl
 EISENHUT, D @ Division of Licensing B3/05/ji Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000.83/05/11.B305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS.W J Dffice of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18973 322 24X Fiche 50-000.83/05/13.8305240213
- O Adjudicatory correspondence
- 8305100223 Forwards Teledyne Engineering Svcs 830311 itr transmitting latest classification of items from independent design review of facility BORDENICK.B M Hearing Branch 3 83/03/18 BRENNER.L., CARPENTER.J.L., MORRISIP A Atomic Safety and Licensing Board Panel App 18374 068. 24X Fiche 50-322.83/03/18.8305100223
- 8305100255 Forwards Teledyne Engineering Svcs 830315 ltr transmitting latest classification of items from independent design review of facility BORDENICK, B M Hearing Branch 3 83/03/21 BRENNER, L , CARPENIER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel App 18373 298 24X Fiche 50-322,83/03/21,8305100255
- 830510023B Forwards resolution of Suffolk County Contention 13(d) re util failure to provide sufficient GA/GC personnel during operation of facility Approval requested BORDENICK, B M Hearing Branch 3 83/04/01 BRENNER, L. CARPENIER, J. L. MORRIS, P. A. Atomic Safety and Licensing Board Panel 2pp 18373 271 24X Fiche 50-322, 83/04/01, 8305100238

- --8305100239 Resolution of Buffolk County Contention 13(d) re util failure to provide sufficient OA/OC personnel during operation Util will prepare detailed projection of QA staff requirements for 12-month period Contention withdrawn BORDENICK, B M Hearing Branch 3 EARLEY, A F Long Island Lighting Co + Suffolk County, NY 83/03/31 Atomic Safety and Licensing Board Panel 6pp 18373 273 24X Fiche 50-322,83/04/01,8305100238
- 8305100222 Second proposed opinion, findings of fact & conclusions of law in form of partial initial decision re DL application concerning GA/GC & environ qualification
 BORDENICK, B N. REPKA, D A Hearing Branch 3 83/04/18 Atomic Safety and Licensing Board Panel 119pp 18373-144 24X
 Fiche 50-382,83/04/18,8305100222
- 8305030560 Reply to Suffolk County & NRC proposed GA/GC & environ qualification opinions, findings & conclusions # Long Island Lighting Co + Hunton & Williams #3/04/25 274pp 18301 001 24% Fiche 50-322,83/04/25,8305030560
- B305020390 Memoransum & order providing for further filings on Suffolk County motion to reopen record on Contention in ASLB will rule on motion to reopen as part of initial decision on merits of Contention il BRENNER.L Atomic Safety and Licensing Board Panel B3/04/28 6pp 18276-319 24X Fich. 50-322.83/04/28.8305020390
- 8305030557 Forwards proposed stipulation re Suffolk County Contention (3(a) on QA/QC operations Util & Suffolk County agreed to stipulation NRC review incomplete but no objections anticipated EARLEY.A F Hunton & Williams 83/Q4/28 BRENNER.L Atomic Safety and Licensing Board Panel App 18305 278 24% Fiche 30-322:83/Q4/28,8303030557
- 8305100196 Response in opposition to Suffolk County 930408 motion to compel applicant to file written rept re Teledyne Engineering Svcs design review of Facility Interim meetings could result in duplicative efforts Certificate of Svc encl BORDENICK. B M Hearing Branch 3 83/04/28 Atomic Safety and Licensing Board Panel 7pp 18374 304 24X Fiche:50-322.83/04/28.8303100196
- 830510039B Forwards Teledyne Engineering Svcs 830406 ltr transmitting summary of 830330 meeting re classification of Item ICR 3633-1 concerning piping attached to horizontal beams from independent design review of facility BDRDENICK.B M Hearing Branch 3 83/04/28 PERNNER.L. CARPENTER.J L. WORRIS.P A Abomic Safety and Licensing Board Panel 4pp 18378 001 24X Fichs 30-322.83/04/28.8305100398
- 8305040461 Advises that util will serve alternative means for implementing offsite emergency plen during wk of 830516 Related correspondence CHRISTMAN, J N Hunton & Williams CHRISTMAN, J N Long Island Lighting CO 83/04/29 BRENNER, L . CARPENTER, J H . MORRIS, P A Atomic Safety and Licensing Board Panel 1p 18322 144 24X Fiche 50-322, 83/04/29, 8305040461
- 8305030488 Advises of LILCO application for rengual of License 31-17432-01 Application prepared per Reg Guide 10 5 Certificate of Svc encil BORDENICK.B H Hearing Branch 2 83/05/02 GRENNER.L , CARPENTER.J L , NORRIS.P A Atomic Safety and Licensing Soard Panel 4pp 18294 160 24% Fiche 50-322, 83/05/02, 8305030488
- 8305050001 Motion for revised schedule re contentions Three-wk time limit for submission of contentions should be deleted Parties directed to meet within 2 wks of receipt of util revised plan to agree on schedule for contention submission LANPHER.L C Buffolk County, NY LANPHER.L C Kirkpatrick, Lockhart, Hill. Christopher & Phillips 83/03/02 Atomic Safety and Licensing Board Panel 79, 18339 063 24x Fiche 50-322,83/05/02,8305050001
- --8305050005 Withdrawal of 830408 motion to compel util to file written rept re Teledyne Engineering Svc design review During 830422 talcon.util & NRC disclosed most info requested in motion Alternative relief requested Certificate of Svc encl DYNNER.A.R. Suffolk County. NY DYNNER.A.R. Kirkpatrick. Lockhart, Hill. Christopher & Phillips 83/05/02 Atomic Safety and Licensing Board Famel 13pp 18339 070 24X
 Fichs. 50-322,83/05/02,8305050001
- 8305050007 Hotion for leave to file new contention re emergency digsel generators. ASLB not required to balance lateness factors
 Certificate of Svc enci
 MILLER.M 6 Suffolk County, NV MILLER.M 9 Kirkpatrick, Lockhart,
 Hill Christopher & Phillips 83/05/02 Atomic Safety and
 Licensing Board Panel. 17pp 18339 001 24X Fiche 50-322,83/05/02,8305050007

- B305050024 Supplemental proposed transcript corrections Certificate of Svc enc1 EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Milliams B3/05/02 5pp 1B340 001 24X Fiche 50-322, B3/05/02, B305050024
- --B305050029 Revised proposed opinion findings of fact & conclusions of law in form of partial initial decision EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02 367pp 18340 006 24% Fiche 50-322, 83/05/02,8305050024
- 8305040429 Corrections to ASLO 830420 Memorandum & Order LBP-83-22, denying Soffelk County motion to terminate OL proceeding BRENNER, L Atomic Safety and Licensing Board Panel 83/05/03 2pp 18322 126 24X Fishe 50-322,83/05/03.8305040429
- B30506043? Memorandum & order ack Suffolk County B30502 withdrawal of motion to compel util to file written rept re Teledyne Engineering Svc design review Motion for util & NRC to provide infe on review denied as overly broad GRENNER. L. Atomic Safety and Licensing Board Panel B3/05/04 Suffolk County, NY 4pp 18351 174 24X Fiche 30-322,83/05/04,8305060459
- #305060518 Motion for expeditious Commission ruling on issues transferred from ABLAB re smargency planning Suffolk County motion to terminate DL proceeding is threshold issue pervading all aspects of proceeding H/Certificate of Svc #8ROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick Lockhart, Hill, Christopher & Phillips #3705704 Commissioners IBpp 18951 CO7 24X Fiche 50-922,83/05/04.8305040518
- 830510037: Forwards updated Apps B & E to util 830117 proposed partial initial decision Schedule for completion of plant continues to indicate physical readiness to load fuel by Aug 1983 REVELEY.W T Hunton & Williams 83/05/04 BRENNER.L , CARPENTER.J L , MORRIS.P A Abomic Safety and Licensing Board Panel 105pp 18378 091 24X Fiche 50-322.83/05/04.8305100391
- B303090129 Forwards executed stipulation re Suffolk County Contention 13(a) on GA/GC operation Parties intend to submit addendum to stipulation DROENICK, B M Hearing Branch 3 B3/05/05 DRENNER, L Atomic Bafety and Licensing Board Panel 1p 18363 350 24X Fiche 50-322, 83/05/05, 8305090129
- --8305090136 Stipulation resolving Suffolk County Contention 13(a) re GA/GC operations BDRDENICK, B M Hearing Branch 3 EARLEY, A F Long Island Lighting Co DYNNER, A R Suffolk County, NY 83/05/05 5pp 18363 351 24X Fithe 50-322,83/05/05,8305090129
- 8305090505 Order confirming 1-wk extension of schedule to file contentions following receipt of revised emergency plan BRENNER.L Atomic Bafety and Licensing Board Panel 83/05/05 2pp 18362 012 24X Fiche 50-322.83/05/05.8305090505
- 8305100157 Response to ASLB 830428 memorandum & order providing for further filings on Suffolk County motion to reapen record on Contention 11 Applicant response insufficient to address full scope of concern Certificate of Svc encl LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick, Lockhart, Hill. Christopher & Phillips 83/05/05 Atomic Safety and Licensing Board Panel 17pp 18374 235 24% Fiche 50-322,83/05/05,8305100157
- B305100256 Protests exclusion of North Shore Committee (NSC) from hastily convened B30504 conference call to hear ASLB decision on Buffolk County B30502 motion for rev of schedule Certificate of Svc encl
 SHAPIRO.R Cammer & Shapiro B3/05/05 BRENNER, L : MORRIS, P A , CARPENTER. J H Atomic Safety and Licensing Board Panel 3pp 18974 059 24X Fiche 50-322,83/05/05,8305100256
- B305100274 Supports Suffolk County B30502 motion for schedule rev Limited resources available to County emphasizes desirability of County proposal Interchange between parties clarify concerns & focus contentions when filed. SHAPIRDJR Cammer & Shapiro B3705705 BRENNER, L , MORRIS, P A , CARPENTER, J H Atomic Safety and Licensing Doard Panel ip 18371 241 24X Fiche 50-322,83/05/05,8305100274
- B303100380 Forwards B30421 ltm & attachments from Teledyne Engineering Bycs to NRC re independent design update program for facility Centificate of Byc encl BORDENICK, B M Office of the Executive Legal Director B3/05/05 BRENNER, L . CARPENTER, J L . MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18379 050 24X Ficha 50-322.83/05/05,8305100380

1

- 8305100201 Objects to ASLAB exclusion of Town of Southampton, NY from B30504 conference call re offsite emergency planning Town of Southampton will hold comments on offsite emergency planning until receipt of new util plan Certificate of Svc enci LATHAM.S D Twomey, Latham & Shea 83/05/06 DRENNER, L Atomic Safety and Licensing Board Panel 6pp 18374 029 24X Fiche 50-322,83/05/06,8305100201
- 8305100224 Forwards Teledyng Engineering Svcs 830419 ltr requesting verification of receipt of controlled documents re independent design review of facility BORDENICK.I M Hearing Branch 3 83/05/06 BRENNER.L., CARPENIER.J.L., MORRIS.P.A. Atomic Safety and Licensing Board Panei 4pp 18374 134 24X Fiche 50-322,83/05/06/8305100224
- ---8305i00225 Forwards transmittal forms indicating that NRC confirmation for receipt of controlled documents re independent design review of facility not yet received Verification of receipt requested KEATINGLA Teledyne Engineering Services 83/04/i9 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 18374 138 24x Fiche 50-322,83/05/06,8305100224
- 8305120297 Farwards revised proposed opinion, supplemental proposed findings of fact, revised findings of fact & conclusions of law in form of partial initial decision on Suffolk County/ Shoreham Opponents Coalition Contention 78 LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE, K J Suffolk County, NY 83/05/09 BRENNER, L , CARPENTER, J , MORRIS, P A Atomic Safety and Licensing Goard Panel 3pp 18430 178 24X Fiche 50-322,83/05/09,8305120297
- --8305120300 Revised proposed opinion, supplemental proposed findings of fact, revised findings of fact & conclusions of law in form of partial initial decision on Suffolk County/Shoreham Oppenents Coalition Contention 7B W/Certificate of Svc RROWN.H H Suffolk County, NY BROWN.H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/09 202pp 18430 181 24X Fiche 50-322,83/05/09,8305120297
- B305120329 Forwards corrected Page 59 to Suffolk County revised opinion LETSCHE.K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE.K J Suffolk County, NY B3/05/09 BRENNER,L , CARPENTER,J L, MORRIS,P A Abomic Bafety and Licensing Board Panel ip 18431 315 24X Fiche 50-322.83/05/09.8305120329
- --8305120332 Corrected Page 59 to Suffalk County revised opinion + Suffalk County, NY 83/05/09 1p 18431 316 24X Fiche 50-322,83/05/09,8305120329
- B305130069 Addendum to B30502 motion for leave to file new contention re emergency diesel generators clarifying Suffolk County views on reopening of evidentiary record Petition to reopen record not required Certificate of Svc encl MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips B3/05/10 Atomic Bafety and Licensing Board Panel Spp 18436 246 24% Fiche 50-322,83/05/10,8305130067
- 8305130072 Expresses indignation at ASLB failure to include author in 830505 telephone conference w/ASLB.util, Suffolk County & NRC Shoreham Opponents Coalition full-fledged participant in proceeding & should be included in future discussions DUGHERTY, J B Dougherty, J B DOUGHERTY, J B Shoreham Opponents Coalition 83705/10 SRENNER, L Atomic Safety and Licensing Board Panel ip 18437 052 24X fiche 30-322,63/05/10,6305130072
- 8305130077 Repts that filing of util alternate means for implementing offsite emergency planning will be unavoidably delayed until wk of 830523 CHRISTMAN.J N Hunton & Williams CHRISTMAN.J N Long Island Lighting CO 83/05/10 BRENNER.L., CARPENTER.J H, MORRIS,P A Atomic Bafety and Licensing Board Panel 1p 18436 263 24X Fiche 30-022:83/05/10.8305130077
- G305130090 Designates HJ Dircks as NRC representative on State of NY fact finding panel on facility PALLADING.N J Commissioners 83/05/10 CUDMO.M M New York, State of Ip 18437 006 24X Fiche 50-322,83/05/10.8308130090
- --B305130204 Requests designation of appropriate NRC representative to State of NY fact finding panel on facility CUDMD, M M New York, State of 83/04/22 PALLADIND, N J Commissioners ip 18437 007 24X Fiche 50-322,83/05/10,8305130090
- 8305130050 Notice of ASLB constitution JA Laurenson, chairman & JR Kline & MB Livingston, members.
 COTTER, B P Atomic Safety and Licensing Board Panel 83/05/11
 Zpp 18436 210 24X Fiche 30-382, 83/05/11, 8305130050

- 8305130068 Memorandum & Order CLI-83-13 accepting ASLAB 830426 referral of ASLB 830426 order referring ASLB 830420 order denying Suffolk County motion to terminate proceeding NRC obliged to consider util plan in absence of state/local plans CHILK.S J Office of the Secretary of the Commission 83/05/12 App 18436 298 24% Fiche 50-322,83/05/12,8305130068
- B305160006 Answer to Suffulk County B30504 motion for expeditious Commission ruling on issues transferred from ASLAP Motion should be denied except for request for briefing of certified question Certificate of Svc enci CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams B3/05/12 Commissioners 17pp 18456-062 24X Fiche 50~322.83/05/12,8305160006
- B305160131 Order directing change of svc on emergency planning submissions
 LAURENSON, J A Atomic Safety and Licensing Board Panel 83/05/12 ip 18448 141 24X Fiche 50-322,83/05/12,8305160131
- B305170545 Forwards revised NRC proposed opinion, findings of fact & conclusions of law in form of partial initial decision Error exists in pagination Page 5 omitted RAWSON.R J Hearing Branch 4 B3/05/16 BRENNER,L, MORRIS,P A, CARPENTER,J L Atomic Bafety and Licensing Board Panel 2pp 18468 121 24X Fiche 50-322,83/05/16.83/05/170545
- 8305170563 Revised proposed opinion, findings of fact & conclusions of iaw in form of partial initial decision Certificate of Byc encl REPKA. D A Hearing Branch 3 83/05/16 213pp 18467 034 24X Fiche 50-322.83/05/16.8305170563
- G30519020B Supplemental paragraphs to be included in proposed opinion & supplemental proposed findings on Suffolk County Contention if revalve failures Certificate of Svc enci FLANAGAN, D.O. Long Island Lighting Co. FLANAGAN, D.O. Hunton & Williams G3/05/16 9pp 18501 330 24X Fichs 50-322, 83/05/16, G30519020B
- 8305190271 Affidavit of EJ Youngling that portions of Suffolk County proposed contention on diesel generators unsupported by facts, insubstantial in nature or remedied Prof qualifications encl YOUNDLING, EJ Long Island Lighting Co 83/05/16 34pp 18501 113 24X Fiche 50-322,83/05/16,8305190271
- 8303190378 Forwards motion opposing Suffolk County motion to add diesel generator contention Certificate of Svc enc!
 EARLEY, A F Hunton & Hilliams EARLEY, A F Long [sland Lighting Co B3/05/16 BRENNER, L , CARPENTER, J H , MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 18500 234 24x
 Fiche 50-322,83/05/16,8305190378
- --8303190382 Response opposing Suffolk County 830302 motion to add mmérgency diesel generator contention County fails to meet stds for reopening record, for late-filed contentions & for particularity of contentions EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Hillams 83/05/16 Atomic Safety and Licensing Board Panel 34pp 18300 237 24X Fiche 50-322,83/05/16,8305190378
- B305200651 Motion for 1-day extension until 830524 to file supplemental SC/BDC 73 reply findings NRC B30516 supplemental findings not served on util counsel until 830517 EARLEY.A F Long Island Lighting Co B3/05/17 Atomic Safety and Licensing Board Panel 3pp 18519 309 24% Fiche 50-322,83/05/17, B305200651
- B305200570 Response opposing Suffolk County B30502 motion for leave to file new contention re emergency diesel generators. Interested county must observe all procedural requirements applicable to parties Certificate of Svc encl BORDENICK.B M . REPKA, D A Hearing Branch 3 63/05/18 Atomic Bafety and Licensing Board Panel 14pp 18514 058 24X Fiche 50-322,83/05/18,8305200590
- --8303200594 Final deficiency rept re failure of liquid carbon dioxide storage tank/piping & affect on operab(lity of emergency diesel generators. Issue not reportable per 100FRSO 55(e) MILLIOAN:M H Long Island Lighting Co 81/11/12 GRIER,B H Region I. Philadelphia, Office of the Director (81/03/01) 2pp 18514 074 24X Fiche 50-322,83/05/18,8305200590
- 8305240548 Advises that County will file motion for leave to respond to util 830516 & NRC 830518 response to Suffolk County motion to add emergency diesel generator contention Filing will contain important new info Related correspondence DYNNER.A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER,A R Suffolk County, NY 83/05/17 BRENNER,L J. CARPENTER,J L, MORRIS,P A Atomic Safety and Licensing Board Panel ip 18575 283 24% Fiche 50-322,83/05/19,8305240548

- 8305240432 Order granting util 830517 request for extension until 830524 to file supplemental proposed findings on Contention 78 BRENNERL Atomic Safety and Licensing Board Panel 83/05/20 Long Island Lighting Co Ip 18575 257 24X Fiche 50-322,83/05/20, 8305240432
- 8305240460 Order permitting Suffeix County to reply by 830531, to util 830516 & NRC 830518 arguments apposing County motion to admit new smergency diesel generator contention BRENNER: Atomic Safety and Licensing Board Panel 83/05/20 Suffeix County, NY App 18573 160 24X Fiche 50-322,83/05/20,8305240460
- G305270553 Forwards B20930 Torrey Pines rept.Vol II (program results).
 Vol III (potential finding repts) & environ qualification
 rept for Class [E equipment.Vols I & 1] per 630520 telcon
 W/o encis
 LANE.V M Atomic Safety and Licensing Board Panel 83/05/20
 MCCAFREY.B Long Island Lighting Co ip 18662 114 24X
 Fiche 50-322.63/05/20.6305270553
- 8305250367 Forwards ASLAB 830518 Decision ALAB-728 re Suffolk County/ Shoreham Opponents Coalition Contention 78 Areas addressed include NRC obligation re unresolved kafety issues to regulatory requirements RAHSON,R J. Hearing Branch 4 83/05/23 BRENNER,L MORRIS,P A , CARPENTER, J. L. Atomic Safety and Licensing Board Panel 66pp 18591 102 24X Fiche 50-322,83/05/23.8305250367
- 8305250334 Order approving "Resolution of Suffolk County Contention 13(a) - 0A/GC - Operations," dtd 830505 & Addendum 1.dtd 830516 BRENNER. L. Atomic Safety and Licensing Board Panel 83/05/24 Office of the Executive Legal Director 2pp 18595 359 24X Fiche 50-322,83/05/24,8305250334
- 8305250973 Forwards Teledyne Engineering Svcs 830506 ltr to HR Denton w/attachment re independent design verification program BORDENICK.B M Hearing Branch 3 83/05/24 BRENNER,L, CARPENTER,J L. MORRIS.P A Atomic Safety and Licensing Board Panel 7pp 18592 093 24% Fiche 50-322,83/05/24.8305250373
- 8305310040 Vol 3 of reply to proposed opinions, findings & conclusions of Suffolk County & NRC re safety classification & sysinteraction Certifficate of Svc encl # Long Island Lighting Co # Hunton & Williams 83/05/24 293pp 18654 092 24X Fiche 50-322,83/05/24,8305310040
- 9305310051 Vol 2 of reply to proposed opinions, findings & conclusions of Suffolk County & NRC re safety classification & sys interaction
 EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 93/05/24 127pp 18653 325 24% Fiche 50-322, 83/05/24, 8305310051
- B305260271 Supply to B30211 proposed opinion & findings of fact on Suffolk County Contention if re passive mechanical valve failures Supply to be used only if ASLG reopens record Certificate of Svc enc1
 REPKA.D A Hearing Branch 3 B3/05/25 9pp iB625 355 24X
 Fithe 50-322.83/05/25.8305260271
- 8305270595 Order approving enci proposed corrections to 830405.06 & 08 transcripts
 BRENNER: L Atomic Safety and Licensing Board Panel 83/05/25
 Long Island Lighting Co 30pp 18645 283 24X
 Piche 50-322,83/05/25,8305270595
- 8303270363 Order directing clarification by 830610 of Contention SC 11, passive mechanical valve failure & IE Gulletin 83-03, "Check Valve Failures in Raw Water Gooling Sys of Dissel Generators"

 BRENNER, L Atomic Safety and Licensing Board Panel 83/05/26 Long Island Lighting Co 8pp 18645 313 24X Fiche 50-322, 83/05/26,8305270563
- B303310063 Submission of data re cracked engine block on smergency dissel generator 103 pursuant to ALAB-143 & ALAB-291 Certificate of Svc encl DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips B3/05/26 App 18653 179 24X Fiche 50-322,83/05/26,8305310063

H General correspondence

B305190059 Urges denial of LILCD request for extension of CP, citing lack of adequate evacuation plan for Suffoix County residents
PELL:N R Southold, NY 83/05/(1 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18502 063 24X
Fishe 30-322,83/05/(1,8305)90059

- 8305180366 Responds to 830404 ltr re offsite emergency planning Commission 830512 order directed ASLB to consider any util emergency plan submitted FITZGERALD, J A Defice of the General Counsel 83/05/17 NEVEL.K Shelter Island, NY 1p 18486 359 24X Fiche 50-322, 83/05/17, 8305180346
- ---8305180367 Supports Suffolk County 830223 motion to terminate OL proceeding & motion for clarification NEVEL, M Shelter Island.NY 83/04/04 PALLADING.N J. GILINSKY.V. ANEARNE.J Commissioners 2pp 18486 360 24X Fiche 50-322, 83/05/17,8305180366
- 8305180430 Responds to 830406 ltr re offsite emergency planning Commission B30512 order directed ABLB to consider any util emergency plan submitted FITZGERALD. J A Office of the General Counsel B3/05/17 RUNCO.F Bag Harbor, NY 1p 18483 114 24X Fiche 50-322,83/05/17,8305180430
- --8305180459 Supports Suffolk County 830223 motion to terminate OL proceeding & motion for certification RUNCD, F. BRANNEN. J. KERN, P. 8ag Harbor, NY 83/04/06 PALLADINO. N. J. GILINSKY, V. AMEARNE, J. F. Commissioners 2pp 18483 115 24X Fichs 50-322, 83/05/17, 8305180430
- --B305180461 Urges denial of util request to extend CP expiration date Buffolk County determination that evacuation is impossible disposes of OL question RUNCO.F., BRANNEN.J., VAN KUVICS.J. Sag Harbor. NY 83/04/06 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp 18453 117 24X Fiche 50-322,83/05/17,8305180430
- 8305180445 Responds to 830411 ltr re offsite emergency planning Commission 830512 order directed ASLR to consider any util emergency plan submitted FITZGERALD, J. A. Office of the General Counsel 83/05/17 GREENBAUM, R. East Hampton, NY 1p 18486 062 24X Fiche 30-322, 83/05/17,8305180445
- --8305180448 Supports Suffolk County B30223 motion to terminate OL proceeding & motion for certification Portion of ltr to HR Denton entl
 GREENBAUM R Hampton, NH B3/04/11 PALLADINO, N J . OILINSKY, V . AHERNE, J Commissioners 4pp 18486 063 24X
 Fiche 50-322, B3/05/17, B305180445
- O Inspection reports, IE Bulletins & correspondence
- B212040385 IE Info Notice B3-14, "Dewatered Spant Ion Exchange Resin Susceptibility to Exchange Chemical Reaction " Svc list encl
 TAYLOR. H Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 R4X Fiche 50-000, 83/03/21, 8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc 11st encl
 JORDANIC L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc 126pp 18435 155 24X Fiche 80-000,83/04/15,8303040021
- B305050109 Responds to NRC request for add1 info on IE Bulletin B1-03 re application of hypothlorite to control growth of b10fouling organisms in ealt svc water sys NPDES permit & EPA regulations allow discharge of chlorine for 2 h POLLOCK.M S Long Island Lighting Co B3/04/21 JORDAN, E L QA Branch 3pp 18341 329. 24% Fiche 50-322,83/04/21,8305050109
- 8303040023 IE Info Notice 83-22, "BWR Sefety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- B305040508 Forwards Rev 2 to "4160V Metal Encl Switchgear General Maint: "providing description of inservice insp & tasking programs to assure seismic integrity of electrical & mechanical components (SER Issue B)
 SMITH.J L Long Island Lighting Co 83/04/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director 9pp 18321 023 24X
 Fiche 30-322,83/04/22,8305040508
- --8305040514 Rev 2 to Procedure 32 050 02, "4160V Metal Encl Ewitchgear-General Maint"
 ROSE, J Long Island Lighting Co 83/01/31 App 18322 032 24X Fiche 50-322,83/04/22,8305040508

í

- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83704/25,8303040025
- 8305040780 Goard Notification 83-053 forwards notice of violation & proposed imposition of civil penalty based upon applicant approving preoperational test results for diesel generator test even though acceptance criteria not satisfied NGVAK, T M Assistant Director for Licensing 83/04/25 Atomic Safety and Lirensing 80 Board Panel 4pp 18327 246 24X Fiche 50-322,83/04/25,8305040780
- --8305040785 Discusses IE insp on 821130-1231 & forwards notice of violation & notice of proposed imposition of civil penalty ALLAM.J M Director's Office, Office of Inspection and Enforcement 83704/12 POLLOCK.M S Long Island Lighting Co 3pp 18327 250 24X Fiche 50-322,83/04/25,8305040780
- --8303040770 Notice of violation & notice of proposed imposition of civil penalty in amount of \$40.000 Noncompliance noted applicant approved diesel generator preoperational tests results even though acceptance criteria not satisfied ALLAN.J M Director's Office. Office of Inspection and Enforcement 83/04/12 Jpp 18327 253 24X Fiche 50-322.83/04/25.8303040780
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 83/04/28 Consolidated Edison Co. of New York. Inc. 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list ancl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fishe 50-000,83/05/04,8303040030
- B303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 30-000,83/05/04,8303040031
- 8305120378 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18 MARTIN.T T Division of Engineering & Technical Programs 83/05/05 POLLOCK
- --B305120380 Responds to NRC 820930 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18
 Corrective actions permanent responsibility for emergency planning assigned to emergency planning coordinator POLLOCK.H B. Long Island Lighting Co B3/04/21 MARTIN.T T Division of Engineering & Technical Programs 12pp 18432 304 24X Fiche 50-322.83/05/05.8305120378
- 8305190031 Forwards IE Insp Rept 50-322/83-07 on 830412-15 No noncompliance noted STAROBIECKI,R Division of Project & Resident Programs 83/05/05 POLLOCK-M,S Long Island Lighting Co 2pp 18502 043 24X Fiche 50-322,83/05/05,8305190031
- --8305190038 IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted Major areas inspected NUREG-0737 items: followup on previous insp findings & review of licensee controls over portable radio transmissions in plant areas HIOGINE, J T. GALLD.R M Region 1. Office of Director 83/05/03 13pp 18502 045 24X Fichs 50-322,83/05/05,8305190031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Daformation" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc 113pp 18323 248 24X Fiche 50-000,83/05/06,8303040033

- 8305120301 Ack receipt of 830219 & 0305 ltrs informing NRC of steps taken to correct violations noted in IE Insp Ropt 50-322/83-02

 9TAROSTECKI, R Division of Project & Resident Programs B3/05/06 PULLOCK, M S Long Island Lighting Co 2pp 18424 125

 Fichs 50-322,83705/06.8305120301
- --B305120306 Responds to NRC B30121 ltr re violations noted in 1E Insp Rept 50-322/83-02 Corrective action analysis performed on welds on control rod drive piping supports to determine any necessary rework POLLOCK, M 5 Long Island Lighting Co 83/02/19 STAROSTECKI, R Division of Project & Resident Programs 16pp 18424 127 24X Fiche 50-322, 83/05/06, 8305120301
- --8305120311 Responds to NRC B30121 ltr re violations noted in IE Insp. Rept 50-0322/83-02 Corrective actions Reactor Controls.Inc to modify procedures &/or drawings to ensure specific gap requirement included for weld configurations.

 POLLOCK.M S Long Island Lighting Co B3/03/05 STAROSTECKI.R Division of Project & Resident Programs 43pp 18424 143 24X Fiche 50-322,83/05/06.8305120301
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOF) Guidelines " Svt list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 833103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303180244 Requests withdrawal or reduction of proposed civil penalty Facts & circumstances re emergency diesel generator test merit reconsideration of severity level & should be classified as lesser violation MUSELERH J Long Island Lighting Co 83/05/12 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement lipp 18486 299 24X Fiche 50-322,83/05/12,8305180244
- --8305180324 Responds to notice of violation & proposed imposition of civil penalty (EA 83-20) Addl facts discussed place circumstances noted by IE inspector in different perspective MMSELER.W J Long Island Lighting Co 83/05/12 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 23pp 18486 310 24X Fiche 50~322,83/05/12,8305180244
- --B305180331 Responds to B30224 1tr re violations noted in IE Insp Rept 30-322/82-35 on B21130-1231 Corrective actions strip chart recorder designated as primary instrument in reperformance of high load test POLLOCK.M 8 Long Island Lighting Co B3/03/16 STARDSTECKI,R Division of Project & Resident Programs 13pp 18486 333 24X Fiche 30-322,83/05/12,8305180244
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fichs 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 30-000,83/03/26,8303040046
- R Periodic operating reports & related correspondence
- 8305020541 Submits daily highlight On 83D420.ASLB issued memorandum & order denying Suffolk County motion to terminate OL proceeding In separate order.ASLB referred ruling on County motion to ASLAB for interlocutory review CARUSO.R Licensing Branch 2 83/04/22 DENTON.H R . CASE.E G . CARTER, J Office of Nuclear Reactor Regulation, Director 2pp 18284 245 24X Fiche 50-322,83/04/22,8305020361
- B Reportable occurrences. LERs & related correspondence
- 8305030274 Interim deficiency rept re apparent cracking in cylinder heads on emergency standby diesel generators Initially reported on 830308 Program to replace cylinder heads will prevent any potential impact on engine operability MILLIGAN.M H Commonwealth Edison Co 83/04/15 ALLEN.J M Region 1. Deffice of Director 4pp 18276 190 24X Fiche 50-322,83/04/15,8305030274
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported an 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000.83/04/26.8305120392

DOCKETED ITEMS

- ~-8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T Region 4, Dffice of Director 5pp 18433 074 24X Fiche 50-000.83/04/26,8305120392
- 8305120328 Final deficiency rept re failure of rocker arm assembly holddown capacraw on Transamerica Delaval emergency standby diesal generators Initially reported on 830330 Capacraws replaced Changeauts completed per E&DCR F-45462 SMITH. J. L. Long Island Lighting Co. 83/05/04 ALLAN, J. M. Region 1. Office of Director. 4pp. 18431-311 24X Fiche 50-322,83/05/04,8305120328
- 8305200549 Corrects itr identification number submitted for B30504 final deficiency rept re rocker arm assembly holddown screw SNRC-873 should be SNRC-883 BRANDI, V A Long [sland Lighting Go 83/05/12 Region 1, Office of Director 1p 18516 002 24X Fiche 50-322,83/05/12,8303200549
- T Hearing transcripts on non-antitrust matters
- 8305050024 Supplemental proposed transcript corrections Certificate of Svc encl EARLEY.A F Long Island Lighting Co EARLEY.A F Hunton & Williams 83/05/02, 5pp 18340 001 24% Fiche 50-322,83/05/02, 8305050024
- --8305050029 Revised proposed opinion, findings of fact & conclusions of law in form of partial initial decision FARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02 367pp 18340 004 24% Fiche 50-322, 83/05/02,8305050024
- 9305180082 Transcript of Commission 830512 affirmation/discussion & vote on SECY-83-157 concerning facility DL in Washington, DC Pp 1-4 commissioners 83/05/12 7pp 18503 279 24X Fiche 50-322,83/05/12,8305180082
- 8305270595 Order approving encl proposed corrections to 830405.06 & 08 transcripts
 BRENNER, L Atomic Safety and Licensing Board Panel 83/05/25
 Long Island Lighting Co. 30pp 18445 283 24X
 Fiche 50-322.03/05/25.8305270595
- U Congressional/Executive Correspondence
- 8304040391 Responds to 830321 ltr re offsite emergency planning Commission studying filings before ASLB to determine if Commission action appropriate FITZOERALD, J A Office of the General Counsel 83/03/30 SAWICKI, J New York, State of 19 17809.210 24X Fiche 50-322,83/03/30,8304040391
- --8304040394 Supports Suffoik County B30223 request for Commission decision on whether OL proceedings should be terminated BAHICKI. J New York. State of 83/03/21 PALLADINO.N J . GILINSKY. V . AHEARNE. J Commissioners ip 17809 211 24x Fiche 50-322.83/03/30.8304040391
- 8305180252 Responds to 830329 ltr re offsite emergency planning Commission 830512 order directed ABLS to consider any util emergency plan submitted FITZOERALD. J. A. Office of the General Counsel 83/05/17 BEHAN. J. L. New York, State of. 1p. 18470-027 24X Fiche: 50-322,83/05/17.8305180232
- --8305180260 Supports Suffolt County Executive P Cohslam B30223 request for Commission to assume jurisdiction over question of whether OL proceedings should be terminated BEHANJ L New York, State of B3/03/29 Commissioners ip 18490 028 24X Fiche 30-322,83/05/17,8305180252
- DOCKET 30-323 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B305230407 Informs that backfifting meth will be forwarded as soon as available, in response to B30208 ltr
 FURBUSH,M M Pacific Gas & Electric Co B3/02/23 IOURTECLOTTE, J
 Regulatory Reform Task Force 1p 18543 357 24X
 Fiche 50-000, 83/02/23, 8305230407

- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- 8305030191 Board Notification 83-51 forwards info re GA/GC allegations at facilities Region V currently investigating allegations EISENHUT.D O Division of Licensing 83/04/15 PALLADINO.J, GILINSKY,V, A-HEARNE,J Commissioners ip 18307-350 24X Fiche 50-275,83/04/15,8305030191
- --B305030200 Recommends QA/QC allegations be brought to attention of ASLB CREWS, J L Division of Resident, Reactor Project & Engineering Programs 63/04/13 EISENHUT, D G Division of Licensing 3pp 18309 351 24X Ficha 50-275
- B305020308 Responds to B30322 request for add1 info on instrumentation sys for detection of inadequate core cooling (Generic Ltr B2-28) Installation completed & sys currently being tested Status of conformance w/NUREG-0737. Item II F 2 snc1 SCHUYLER-J O Pacific Gas & Electric Co B3/04/27 EISENHUT.D G Division of Licensing 7pp 18276 329 24X Fiche 50-275.83/04/27, B305020388
- B305040323 Board Notification B3-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications B3-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D @ Division of Licensing B3/05/04 PALLADING, N Commissioners 22pp 18337 137 24X Fiche 50-000, B3/05/04, B3087040323
- B305120085 Board Notification 83-55 forwards info on allegations reconst GA at facilities
 EISENHUT.D G Division of Licensing B3/05/05 PALLADING,N J .
 GILINSKY, V . AHEARNE, J Commissioners 3pp 18422 236 24X
 Fiche 50-275,83/05/05,8305120085
- --8305120093 Forwards sworn statements of V Tennyson & R Roam re allegations of math violations of NRC GA regulations at facilities VAN DE KAMP, J California, State of 83/04/12 EISENHUT, D @ Division of Licensing 90pp 18422 239 24X Fiche 50-279, 83/05/05.8305120085
- ---9305120099 Transcript of 830325 interview w/VH Tennyson re alleged deficiencies in implementation of HP Foley Const Co GA program TENNYSON.V H Affiliation Unknown 83/03/25 73pp 18422 329 24X Fiche 50-275.83/05/05,8305120085
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fiche 50-000,83/05/09,8305090659
- 9303040044 Board Notification 93-66 forwards review of WCAP-10297(P): "Droppped Rod Methodology for Negative Flux Rate Trip Plants: "Rod issue resolved by analysis in rept Plants beyond first cycle must perform analysis Comments encl EISENHUT.D 0 Division of Licensing 83/05/13 PALLAPINO.N. GLINSKY.V. AHEARNE.J. Commissioners 21pp 18541 068 24X Fiche 50-000.83/05/13.8303040044
- B305270317 Notifies of B30602 meeting w/util & independent design verification program group in Boston, MA to followup B30512 discussions re turbine bldg, polar crane & auxiliary bldg & redistribution of moments & forces CODPER, W E , CRAGIN, J G Telsdyne Engineering Services 83/05/27 MANEATTS, G A , PENTON, H R , MARTIN, J B , NRC No Detailed Affiliation Given ip 18642:223 24X Fiche 50-275,83/05/27,8305270317.
- F Security, medical, emergency & fire protection plans
- 8305030180 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records, 83/04/22 Document Management Branch ip 18310 001 24X Fiche 50-275,83/04/22,8305030180
- --8305030168 Forwards public version of Rev O to Emergency Plan Implementing Procedures EP-RB-12. "Mid & High-Range Vent Monitors" & EP G-3, "Notification of Offsite Organizations," CRANE, P A Pacific Gas & Electric Co 83/04/06 MARTIN, J B. Region 5, Office of Director 2pp 18310 002 24X Fiche 50-275,83/04/22,8305030180

- --8305030193 Public version of Rev O to Emergency Plan Implementing Procedures EP-RB-12, "Mid & High-Range Vent Monstors" & EP O-3, "Notification of Offsite Organizations" * Pacific Gas & Electric Co 83/04/06 19pp 18310 004 24X Fiche 50-275,83/04/22,8305030180
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Gvc list encl EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11.8305110034
- 8305240213 Forwards monthly status rapt on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS:W J Office of the Executive Director for Operations 83/05/13 PALLADING.N J Commissioners 5pp 18593 322 24X Fich

@ Adjudicatory correspondence

- 8305090438 Advises that since 830423 correspondence, informant contacted Joint Intervenors re allegations of Scottel/util misconduct Fear of reprisals prevented informant from meeting or calling NRC FLEISCHAKER, D Fleischaker, D S FLEISCHAKER, D Joint Intervenors-Diablo Canyon 83/05/03 EISENHUT, D 0 Division of Licensing 3pp 18362 354 24X Fichs 50-275,83/05/03,8305090438
- 8305110212 First request for document production by Governor Daukmejian NOTICELE FIRST request for accument production of devenor bushings & Joint Intervenores Related correspondence BTRUMMASER, M California, State of REYNOLDS, J. R Joint Intervenors-Diablo Canyon 83/03/06 Pacific Gas & Electric Co 8pp 18407 100 24X Fiche 50-275,83/05/06,8305110212
- 8305110217 Certifies syc of first set of interrogatories & first document production request on listed parties on 830506 STRUMHASER.M California, State of 83/05/06 5pp 18407 095 24% Fiche 50-275,83/05/06.8305110217
- 8305110383 First set of interrogatories by Governor Deukmejian & Joint Intervenors Buorn response requested within 14 days Related correspondence
 BTRUMHASSER,M California, State of REYNDLDS,J R Joint
 Intervanors-Diablo Canyon B3/05/06 Pacific Gas & Electric Co
 26pp 18406 230 24X Fichs 30-275,83/05/06,8305110383
- 8305120285 Motion to reopen record on const QA issue to receive significant new evidence of recently established deficiencies in const QA & QC program Certificate of Svc enci REYMOLDS.J R Joint Intervenors-Diablo Canyon REYMOLDS.J R Center for Law in the Public Interest 83/05/10 Atomic Safety and Licensing Appeal Panel 39pp 18427 159 24X Fiche 90-275.83/05/10.8305120285
- 8305160127 Advises that NRC cannot pinpoint when NRC responsibilities to Commission re independent design verification program sufficiently complete to permit discovery against NRC Final repts due by 830430 CHANDLER.L J Hearing Branch 2 83/05/13 MODRE,T 8, BUCK.J H, JOHNSCN.W R Atomic Bafety and Licensing Appeal Panel 2pp 18448 185 24X Fiche 30-275,83/05/13:8305140127
- 8305260182 Motion to reopen record on const QA Info discovered on util QA program design & const deficiencies & on const contractor QA program deficiencies KAUFMAN.P H California, Btate of 83/05/17 Atomic Safety and Licensing Appeal Panyl 38pp 18599 024 24x Fiche 50-275, 83/05/17, 8305260182
- --B3052601B3 Declaration of RB Hubbard re breakdown in const GA.
 Describes events occurring since issuance of B30326
 supplemental affidavit demonstrating util GA/GC const
 program Noncompliance Certificate of Byc enci
 HUBBARD.R.B. California. State of B3/05/06 50pp 18595 2005/04 50pp 18599 063
- 8305200657 Decision ALAB-728, affirming ASLB 810717 Partial Initial Decision LBP-81-21 authorizing fuel loading & low power testing Johnson opinion dissenting in partiencl 8HOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/05/18 44pp 18519 340 24X Fiche 50-275,83/05/18,8305200657
- 8305270622 Answers to Covernor Deukmejian & Joint Intervenors B30506 first set of Interrogatories 1(a) through (f),8(a),(c) & (d),9(a),(c) & (d),10(a) & (c) & 11(a) & (c) re independent design verification review Certificate of Svc encl CRANE,P A Pacific Oas & Electric Co B3/05/23 DEUKMEJIAN,Q California, State of 200pp 18645 001 24X Fiche 50-275,83/05/23,

H General correspondence

- 8305180622 Responds to B30328 ltr re eight allegations by anonymous individual Preliminary evaluation of allegations underway meeting w/util planned in near future to solicit evaluation on subj EISENHUT.D 0 Division of Licensing 83/04/21 FLEISCHAKER.D Fleischaker, D 8 8pp 18505 317 24X Fiche 50-275.83/04/21, 8305180622
- G Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list TAYLOR, J M ,J M Division of Bafeguards & Inspection Programs (Post) 83/03/21 Consolidated Edison Co of New York, Inc 18308 319 24% Fiche 50-000.83/03/21.8212060385 R30103)
- 8305170332 Forwards IE Insp Repts 50-275/83-12 & 50-323/83-09 on BOSJO-0402 No noncompliance noted
 BISHOP,T W Region 5. Defice of Director BJ/04/08 CRANE.P A
 Pacific Oas & Electric Co 2pp 18465 133 24X
 Fiche 30-275.83/04/08,8305170332
- --8305170339 JE Insp Repts 50-275/83-12 & 50-323/83-09 on 830304-0402 No 305170339 IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 noncompliance noted Major areas inspected surveillance testing, maint & TMI task action plan items CARLBON, J D. MENDONCA, M M., KIRBCH, D F. Region 5, Office of Director 83/04/05 App 18465 135 24X Fiche 50-275,83/04/08,8305170332
- 8305060299 Advises that top cover gaskets in 12 Namco EA180 limit switches replaced per manufacturer recommendation in IE Bulletin 79-28 No further action necessary CRANE.P A Pacific Gas & Electric Co 83/04/14 MARTI Region 5, Office of Director 1p 18344 322 24X Fiche 50-323,83/04/14.8305060299
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " 103040041 In 1866 Notice 63-21, Service Commission of Emergency Proparedness & Engineering Response (Post B30103) 83/04/15 Consolidated Edison Co. of New York, Inc. 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 303040023 IE Info Notice 83-22, BMN 06.004, No. 100, No.
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Bteam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28.8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Svc list encl JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830[03) 83/04/28 Consolidated Edison Co of New York, Inc 118pp. 18382 165 24% Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 244 Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list end: JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York: Inc. 112pp 18382 282 24X Fichs 30-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031

- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/05/06 Consolidated Edison Co of New York: Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Infa Notice 83-30, "Mssapplication of Generic Emergency Operating Procedures (EOP) Ourdelines " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705711 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,837057(1,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/17 Consolidated Edison Co of New York: Inc 114pp 18697 009 24K Fiche 50-000,83/05/19,8303040040
- 8305260257 Forwards IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830530-0406 & 25-27 W/o notice of violation 8ISHDP.T W Region 5. Office of Director 83/05/19 GRANE,P A Pacific Gas & Electric Co 2pp 18625 172 24X Fiche 50-275.83/03/19,8305260257
- --8305260262 IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830330-0406 & 25-27 Noncompliance noted failure to comply w/procedural requirements for processing of nonconformance repts & to conduct weight requalification CARLSON, J D , HERNANDEZ, G H , MENDONCA, M M Region 5, Office of Director 83/05/19 24pp 18625 174 24X Fiche 50-275,83/05/19,8305240257
- 8305260270 Forwards 1E Mgt Neeting Repts 50-275/83-18 & 50-323/83-14 on 830407 & BALP rept for Jul 1981 Dec 1982 MARTIN.J B Region 5, Office of Director 83/05/23 CRANE.P A Paiffic Gas & Electric Co 2pp 18626 211 24% Fiche 50-275,83/05/23,8305260270
- --8303260272 IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 No noncompliance noted Major areas discussed SALP rept for Jul 1981 - Dec 1982, Including design, const & operations MORRILL, PJ. KIRSCH, DF Region 5. Office of Director 83/05/20 2pp 18626 213 24X Fiche 50-275,83/05/23,8305260270
- --8305260274 Submits comments on draft SALP rept for Jul 1981 Dec 1982 discussed at 830407 meeting BALP rept will be used as guide for assighing priorities & ellocating resources to maintain & improve mgt controls &/or quality of work CRANE.P A Pacific Gas & Electric Co 83/04/27 HARTIN.J B Region 5, Office of Director 2pp 18626-258 24X Fiche 30-275,83/05/23.8305260270
- 8303040046 [E Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN-E L Division of Energency Preparedness & Engineering Response (Post 830103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 30-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305060580 PNO-V-B3-019 on 830502.6 5 Richter scale earthquake occurred approx 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected KIRBCH D F Region 5. Office of Director 83/05/03 (p 18349 057 24X Fiche:50-275,83/05/03,8305060380
- U Congressional/Executive Correspondence
- 8305100124 Bupplemental testimony of JG Keppler re QA KEPPLER, J O Region 3. Office of Director 83/03/25 App 18375 197 24% Fichs 50-000, 83/03/25, 8305100124
- --8305100141 Responds to 811113 itr re implications of recent seismic design errors at facility Due to design errors util license suspended on 811119 pending completion of independent design review & receipt of schedule for completing mods PALLADINO, N J Commissioners 82/02/01 DINDELL, J D House of Rep , Emergy & Commerce 5pp 18375 228 24x Fiche 50-000,83/03/25,8305100124

- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- B305200625 Forwards Rev B to industrial security plan Changes do not decrease effectiveness of plan or level of security Encl withheld (ref 100FR73 21 & 2 790) HOME.P W Carolina Power & Light Co 83/04/20 D'REILLY, J P Region 2. Office of Director 2pp 18520 042 24X Fiche 50-324/83/04/20,8305200625
- 8303200597 Forwards change to provisions of industrial security plan Change will not decrease effectiveness of plan or level of security Encl withheld (ref 10CFR73 21)
 HDWE,P W Carolina Power & Light Co 83/04/28 D'REILLY, J P Region 2, Dffice of Director Ip 18514 106 24X
 Fiche 50-324.823/04/28, 8305200597
- 8305100100 Forwards IE Bafeguards Insp Repts 90-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted VERRELLIA Division of Project & Resident Programs 83/05/05 UTLEY, E E Carolina Power & Light Co 2pp 18375 033 24X Fiche 50-324.83/05/05,8305100100
- --B305100109 IE Safaguards Insp Repts 50-324/B3-13 & 50-325/B3-13 on 830411-15 No noncompliance noted Major areas inspected audit review.securuty plan, records, assessment aids, alarm stations & training/qualification Details withheld (ref 10CFR73 21) TOBINN D. HALL. B Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparadness & Materials Safety 83/05/04 1p 18375 035 24X Fichs 50-324,83/05/05,8305100100
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors; applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits 9vc list encl FIBENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 14pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- 8305260134 Informs that NUREO-0737, Item III A 2 1 re emergency plan upgrade to meet iOCFR50, App E requirements complete for facility Item closed VASSALLO, D B Operating Reactors Branch 2 83/05/18 UTLEY, E E Carolina Power & Light Go 3pp 18649 047 24X Fiche 50-324,83/05/18,8305260134
- J Insurance & indemnity information
- B305140135 Forwards Endorsement 48 to NELIA Policy NF-218
 BARHAN.C D Carolina Power & Light Co 83/05/02 SALTZMAN, J NRC
 No Detailed Affiliation Given 2pp 18446 066 24X
 Fiche 50-324,83/05/02,8305140135
- P Operating license stage documents & correspondence
- 8305180001 Add1 response to FQIA request for seven categories of documents re Brown & Root. Inc & South Texas project Forwards App B documents Documents also available in PDR Add1 documents undergoing review FELTON, J M Division of Rules and Records 83/03/07 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18477 219 24X Fiche 50-000, 83/03/09, 8305180001
- --B010280578 Responds to Question 4 of B00923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWB Code STELLO.V Office of Inspection & Enforcement, Office of the Director B0/09/25 AMEARNE, JF Commissioners 5pp 18497 228 24X Fiche 50-000, B3/03/09, B305180001
- 8305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
 SMITH.8 H Carolina Power & Light Co 83/03/22 TOURTELLOTTE.J Regulatory Reform Task Force 12pp 18543 277 24X Fiche. 50-000,83/03/22,8305230283
- B305230720 Forwards list of utile responding to requests for cost figures on backfitting.
 TOURTELLOTTE. J Regulatory Reform Task Force B3/04/ii
 PALLADINO. N J Commissioners 2pp 18542 272 24X
 Fiche 50-000.83/04/ii.8305230720

- 8305030288 Application for amend to License DPR-62 revising Tech Specs to delete 8 5/ MAPLHOR reduction penalty Sketches of clamp on core spray sparger, described in 820520 itr encl.per NRC request Class III license fee forwarded on 821229 HOME, P H Carolina Power & Light Co 83/04/28 VASSALLO, D B Operating Reactors Branch 2 lipp 18300 042 24X Fiche 50-324,83/04/28,8305030288
- --8305030293 Proposed changes to Tech Specs deleting 8 5% MAPLHGR reduction penalty e Carolina Power & Light Co 83/04/28 7pp 18300 073 24X Fiche 50-324,83/04/28,8305030288
- 8305030463 Application for amend to Licenses DPR-62 & DPR-71. supplementing 820616 request for miscellaneous Tech Spec revs originally scheduled for completion during 820901 refueling outage Outage & mods to be completed by 830624 HOME:P W Carolina Power & Light Co 83/04/28 VASSACLO.D B Operating Reactors Branch 2 2pp 18308 222 24X Fiche 50-324.83/04/28.8305030463
- --B3050304Bi Proposed Tech Specs re safety-related hydraulic snubbers, poet-accident monitoring instrumentation gas analyzer sys, reactor coolant leakage detection sys & remote shutdown monitoring instrumentation + Carolina Power & Light Co B3/04/20 19pp 18308 224 24X Fiche 50-324,83/04/28,8305030463
- 8305190099 Forwards safety evaluation for TMI Action Items I A 2 1 4, "Upgrading of Reactor Operator & Benior Reactor Operator Training" & II 0 4, "Training for Mitigating Core Damage" Training & requalification programs acceptable VASSALLO, D B Operating Reactors Branch 2 83/04/29 UTLEY, E E Carelina Power & Light Co 3pp 18523 175 24X Fiche 50-324.83/04/29,8305190099
- B305020455 Generic Ltr B3-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Byc list encl EISENHUT.D 0 Division of Licensing B3/05/02 Consolidated Edison Co of New York. Inc 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- B305070380 Ack receipt of B30131 ltr requesting add1 info re
 NVREG-0737. Item II K 3 20. "Gualification of ADS Accumulator
 Sys" Info requested from GE Response will be submitted by
 830630
 IMMERMAN, B R Carolina Power & Light Co 83/05/05 VASSALLO, D B
 Operating Reactors Branch 2 ip 18363 340 24X
 Fiche 50-324, 83/05/05, 8308070380
- 8305070456 Confirms 830419 responses to questions raised during 830418 telcon re spent fuel pool expansion ZIMMERMAN. B R Carolina Power & Light Co 83/05/05 VASSALLO, D B Operating Reactors Branch 2 2pp 18362 265 24X Fiche 50-324.83/05/05.8305090456
- 8305180040 Forwards Amend 80 to License DPR-62, safety evaluation & notice of issuance & availability Amend changes Tech Specs re limiting values of MAPLHOR & abrogates uniform reduction of 8 5% in limiting MAPLHOR values MACKAY.8 D Operating Reactors Branch 2 83/05/05 UTLEY, E E Carolina Power & Light Co 2pp 18499 291 24% Fiche 50-324,83/05/05,8305180040
- --8305180048 Amend 80 to License DPR-62, changing Tech Specs re limiting values of MAPLHOR & abrogating uniform reduction of 8 5% in limiting MAPLHOR values
 VAESALLO.D B Operating Reactors Branch 2 83/05/05 10pp 18499 293 24X Fiche 50-324,63/05/05.8305180040
- ~- B305180057 Safety evaluation supporting Amend 80 to License DPR-62 * Office of Nuclear Reactor Regulation, Director B3/05/05 2pp 18497 303 24X Fich 50-324, B3/05/05, B305180040
- ~-8305180061 Notice of issuance & availability of Amend 80 to License DRR-62 VASSALLO,D 8 Operating Reactors Branch 2 83/05/03 2pp 18499 305 24% Fiche 50~324,83/05/05,8305180040
- B305180563 Forwards revised order establishing 930730 completion date for implementing NUREG-0737. Items II D 3 re post-accident sampling & II F I 1 & II F 1 5 re accident monitoring VASSALLO, D 8 Operating Reactors Branch 2 83/05/05 UTLEY. E & Carolina Power & Light Co 2pp 18504 354 24X Fiche 50-324.83/05/05.8305180563
- --8305180566 Revised order confirming licensee commitments to implement NUREG-0737, Items II B 3 re post-accident sampling & II F i i & II F i 5 re accident monitoring, by 830307 PURPLE, R A Division of Licensing 83705/05 Carolina Power & Light Co 5pp 18504 356 24X Fiche 50-324,83705/05,8305180563

- 8305230178 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737. Item II K 3 22, "Automatic Switchover of RCIG Swittion " Mods acceptable VASSALLO, D B Operating Reactors Branch 2 83/05/05 UTLEY, E Carolina Power & Light Co 5pp 18546 356 24% Fiche 50-324,83/05/05,8305230178
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl
 EIGENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fichs 50-000,83/05/09,8305090659
- 8305120003 Responds to 830316 ltr requesting review of RCIC sys automatic restart per TMI Action Item II K 3 13 Acceptance criteria identified in ltr satisfied ZIMMERMAN, S R Carolina Power & Light Co 83/05/09 VASBALLO, D B Operating Reactors Branch 2 1p 18423 076 24X Fiche 50-324,83/05/09,8305120003
- B305260285 Forwards request for add1 info re 810123 response to NUREO-0737. Item II & 3 28. "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 20 days of itr receipt VASSALLO, D B Operating Reactors Branch 2 83/05/11 UTLEY, E Carolina Power & Light Co 3pp 18627 337 24X Fiche 50-324.83/05/11.8305260285
- B305240004 Informs that currently scheduled Unit 1 startup date is 830612 Outage critical path 8 days behind but recovery plan instituted to make up time Requests Tech Spec changes be issued no later than B30612 HURFORD W J Carolina Power & Light Co 83/05/17 VASSALLO, D B Operating Reactors Branch 2 lp 18549 051 24X Fiche 50-324,83/05/17,8305240004
- 8305240434 Commits to submit results of plant-unique calculations forming bases for mod program on Mark I containment vacuum breakers by 830630 in response to Generic Ltr 83-08 Calculations presented in listed documents HOME.P W Carolina Power & Light Co 83/05/19. VASSALLO,D B Operating Reactors Branch 2 2pp 18571 061 24X Fiche 50-324,83/05/19,8305240434
- B305260320 Forwards NEDO-24582, "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2" Attachment detailing pressure/temp calculations also encl ZIMMERMAN, B R Carolina Power & Light Co B3/05/24 VASSALLO, D B Operating Reactors Branch 2 jp 18623 038 24x Fiche 50-324,83/05/24,8305260320
- --8305260325 "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant.Units 1 & 2 " * General Electric Co NEDO-24392 ROI 81/10/31 61pg 18625 059 24X Fiche 50-324,83/05/24,8305260320
- O Inspection reports, IE Bulletins & correspondence
- 8303270531 Submits results of split sample taken from floor drain sample tank B for trition b radiostrontium, per IE Insp Repts 30-324/82-07 & 50-325/82-07 DIETZ.C R Carolina Power & Light Co 83/02/25 O'REILLY, J P Region 2, Office of Director Ip 18646 127 24x Fiche 30-324,83/02/25,8305270301
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exchange Chemical Reaction "Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted O'REILLY, J P Region 2, Office of Director 83/04/11 UTLEY, E Carolina Power & Light Co. 2pp 18644 138 24X Fiche 50-000:83/04/11.83052/0461
- --8305270474 IE Enforcement Conference Repts 50-261/83-10,50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of radwasty containing free liquid & inoperability of standby gas treatment deluge sys LEWIS.R.C. Division of Project & Resident Programs 83/04/07 3pp. 18644 160 24X Fiche 50-000,83/04/11,8305270461
- B303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator "
 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021.

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- 303040023 IE INTO NOVELL 1870 NOVELL 1870
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc 117pp 18381 271 24X Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83704/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Betpoint Adjustment " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 8030103) 83/04/28 Convalidated Edison Co of New York, Inc 116pp 18382 145. 24X Fiche 50-000,83/04/28,8303040027
- 8305270250 Act receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-07 & 50-325/83-07
 VERRELLI, D M Division of Project & Resident Programs
 UTLEY, E Carolina Power & Light Co 1p 1864f 187
 Fiche 30-324,83/04/29,8305270250 83/04/29
- --8305270256 Responds to NRC 830317 ltr re violations noted in IE Insp Repts 50-324/83-07 & 50-328/83-07 Corrective actions procedure revised & accepted by QA reflecting actual testing method & contractor personnel counseled DIETZ.C R Caroline Power & Light Co 83/04/15 O'REILLY, J P Region 2. Office of Director 2pp 18641 188 24X Fiche. 50-324, 83/04/29, 8303270250
- --8305270263 Forwards IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/03/17 UTLEY/E E Caroline Power & Light Co 2pp 18641 190 24X Fichs. 50-324,83/04/29,8305270250
- --8305270268 Notice of violation from insp on 830131-0203 & 07-11 * Region 2, Office of Director 83/03/17 ip 18641:192 Fiche 50-324,83/04/29,8305270250.
- --8305270276 IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 Noncompliance noted failure to foliou inservice Insp procedure for recording angle beam data COLEY, J. L. BLAKE, J. J. Region 2. Office of Director 83/03/04 8pp 18641 193 24X Ficher50-324,83/04/27,8305270250
- 8305060620 Responds to NRC 830218 ltr transmitting notice of violation & proposed imposition of civil penalties.per IE insp Repts 50-324/82-28 & 50-325/82-28 Relay tests completed 50-324/82-ec a guides/or so many satisfactorily. UTLEY.E.E. Carolina Power & Light Co. 83/05/02 DEYOUNG Director's Office, Office of Inspection and Enforcement 18349 022 24X Fiche: 50-324, 83/05/02, 8305060620 2700
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co 12200 18441 170. 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list enci.
 JORDAN: E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/04 Consolidated Edison Co of New
 York, Inc 112pp. 18382 282. 24X Fiche.50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441:001 24X Fiche 50-000,83/05/04.8303040031
- 8305100100 Forwards IE Safeguards Insp Repts 30-324/83-13 & 50-325/83-13 on 830411-15. No noncompliance noted VERRELLI, A Division of Project & Resident Programs 83/05/0 UTLEY, E. E. Carolina Pawer & Light Co. 2pp 18375 033 24X Fiche; 50-324, 83/05/05, 8305100100 83/05/05

- --8305100109 1£ Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 105100109 IE Safeguards (nsp kepts 30-324/83-13 & 30-32783-18 830411-15 No noncompliance noted Major areas inspected audit review, security plan, records, assessment aids, alarm stations & training/qualification Details withheld (ref 10CFR73 21) TOBIN, H J, HALL, B. Region 2, Office of Director MCGUIRE, I Division of Emergency Preparedness & Materials Safety 83/01 1p 18375 035 24X Fiche 50-324,83/05/03,8303100100
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/06 Consolidated Edison Co of New
 York, Inc 115p 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305270580 Ack receipt of 830318 & 0422 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-324/82-45 & 50-325/82-45 LEWIS.R C Division of Project & Resident Programs 83/05/06 UTLEV.E E Carolina Power & Light Co ip 18644 225 24X Fiche: 50-324,83/05/06,8305270580
- --8305270598 Responds to NRC B30207 ltr re violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45 Corrective actions required rev to G-list procedure will not be completed until 830527 DIETZ.C R Carolina Power & Light Co 83/05/23 O'REILLY, J P Region 2, Office of Director ip 18644 226 24X Fiche 50-324,83/05/06,8305270580
- --8305270599 Clarifies response to Violations B % C in IE Insp Repts 50-324/82-45 % 50-325/82-45 Program for determining type of alarm devices needing periodic calibr will not be completed Big 30730 DIETI, C R Carolina Power & Light Co 83/04/22 D Region 2, Office of Director 2pp 18644 227 24X Fiche 50-324.83/05/06,8305270580 O'RETLLY, J P
- --8305270410 Responds to violations noted in IE Insp Rept 50-324/82-45 & 50-323/82-45 Corrective actions engineering supervisor of discipline group responsible for performing review of tables for inconsistencies internal to procedure DIETZ, C.R. Consumers Power Co. 83/03/18 0'REILLY, J.P. Region 2, Office of Director 4pp 18644 229 24X Fiche 50-324, 83/03/06,8305270580
- --8305270617 Ack receipt of 830207 1tr transmitting IE Insp Repts 50-324/82-45 & 50-325/82-45 Util continuing evaluation of violations Response to rept will be submitted by 830318 DIETZ. C R Carolina Power & Light Co 83/03/08 O'REILLY. J Repion 2. Office of Director ip 18644 233 24X Siths 50-324 8208204 9208373890 DIETZ, C.R. Carolina Power & Light Co Region 2, Office of Director ip 188 Fiche 50-324,83/05/06,8305270580 O'REILLY, J P
- --8305270621 Forwards IE Insp Repts 30-324/82-45 & 50-325/82-45 on 821115-1215 & notice of violation LEWIS, R C Division of Project & Resident Programs 83/02/07 UTLEY, E E Carolina Power & Light Co 2pp 18644 234 24X Fiche 50-324,83/05/04,8305270580
- --830527062B Nutice of violation from insp on 821115-1215 * Region 2. Office of Director 83/02/07 2pp 18: File 50-324,83/03/06,8305270580 18644 236
- --8305270635 IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215
 Noncompliance noted failure to adequately review procedure
 changes to establish calibr procedures & to followup on
 corrective actions,
 MYERS, D. D. GARNER, L. W. BEMIS, P. Region 2, Office of Director
 83/02/02 10pp 18644 238 24X Fichs 50-324,83/05/06,8305270580
- 8305270333 Forwards 1E Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 83/05/10
 UTLEY, E E Carolina Power & Light Co 2pp 18641 123 24X Fiche 50-324, 83/05/10, 8305270333
- --8305270342 IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted Major areas inspected independent inspectors & observation of inservice inspects & work activities
 COLEY, J L , BLAKE, J J Region 2, Office of Director
 topp 18641 125 24% Fiche 50-324, 83/05/10, 8305270333 83/05/05
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524-003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " 3030404040 is after never to 1...

 Svc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/05/17 Consolidated Edison Co of New

 York, Inc 114pp 18697 009. 24X Fiche 50-000,83/05/19,8303040040

- 8303040046 IE Info Notice 83~33, "Nonrepresentative Sampling of Contaminated Dil " Bvc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705726 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 30-000,83703726,8303040046
- R Periodic operating reports & related correspondence
- 8305100412 Forwards monthly operating repts for Apr 1983 DIETZ.C R Carolina Power & Light Co 83/05/05 DEVOUNG.R C Director's Office, Defice of Inspection and Enforcement 1p 18378 066 24x Fichs 50~324.83/05/05.8305100412
- --8305100417 Monthly operating repts for Apr 1783 HARRISDN.F Carolina Power & Light Co 83/05/03 12pp 18378 067 24X Fiche 50-324,83/05/05,8305100412
- B Reportable occurrences, LERs & related correspondence
- 8305030355 Forwards LER 83-016/03L-0 DIETZ,C R Carolina Power & Light Co B3/04/20 O'REILLY, J P Region 2. Office of Director ip 18306 294 24X Firke 50-324,83/04/20,8305030355
- --8305030361 LER 83-016/03L-0 on B30323, reactor bldg exhaust ventilation high-high alarm occurred concurrent w/Group 6 primary containment isolation signal Gaused by failure of relay K2 in indication & trip unit b12-K607A Relay replaced PABTVA.M J Carolina Power & Light Co B3/04/20 Region 2, Office of Director 2pp 18306 275 24X Fiche 50-324.83/04/20, 83050330355
- 8305030497 Nonroutine radiological environ event rept Results of 830308 gamma analysis of bottom sediment revealed high Co-60 concentration Samples will be taken monthly for Oct 1982 June 1983 to determine if trends can be predicted DIETZ.C R Carolina Power & Light Co 83/04/20 O'REILLY.J P Region P. Office of Director Pap 18306 183 24X Fiche 50-324,83/04/20,8305030497
- 8305030530 RO fire barrier limiting conditions for operation issued on 830317 & 20 exceeded 7-day time frame to permit completion of mods in control diesel generator & augmented offgas bldgs Continuous stationed fire watches maintained DIETZ.C R Carolina Power & Light Co 83/04/20 O'REILLY, J P Region 2, Office of Director 1p 18306 362 24X Fiche 50-324.83/04/20,8305030530
- B305030612 Forwards supplemental LER B3-002/03L-1,
 DIETE.C R Carolina Power & Light Co B3/04/20 O'REILLY, J P
 Region 2. Defice of Director 1p 18303 343 24X
 Fiche 30-324,83/04/20,8305030612
- --8305030618 Supplemental LER 83-002/03L-1 on 830102, indicator 2-CAC-LR-2602 showed high suppression pool level Caused by Incorrect input signal to indicator due to change in trickle flow to wot ref leg of LR-2602 indicator transmitter PABTVA.M J Carolina Power & Light Co 83/04/20 Region 2, Office of Director 2pp 18303 344 24X Fiche 50-324,83/04/20,8305030612
- B303030387 Part Ri rept re pipe clamps for snubber/struts oriented in off-axis direction initially reported on B30224 & by IE Info Notice B3-13 Clamps will be replaced by end of Fall 1983 refueling outage DIETZ.C R Caroline Power & Light Co B3/04/22 O'REILLY, J P Region 2. Office of Director 2pp 18272-316 24X Fiche 50-324,83/04/22,8305030387
- B305030411 Forwards updated LER B2-124/03L-1 DIETZ.C R Caroline Power & Light Co B3/04/22 O'REILLY, J P. Hegion 2. Office of Director 1p 18293 226 24X Fiche 30-324,83/04/22,8305030411
- --8305030419 Updated LER 82-124/03L-1 on 821024 & 25, standby liquid control sys piping heat tracing on lines between sys accumulators 2-041-A003A & B & common discharge line inoperable Caused by electrical failure Mods planned PABTVA:M J Carolina Power & Light Ca 83/04/22, Region 2, Office of Director ip 18293 227 RAX Fiche 50-324, 83/04/22, 8305030411
- 8305030512 Forwards LER 83-002/03L-0.
 D1ETZ.C.R Carolina Power & Light Ga 83/04/22 O'REILLY.J P
 Region 2. Office of Director ip 18308 191 24X
 Fiche 50-324,83/04/22,8305030512

- -8305030536 LER 83-002/03L-0 on 830328, suppression pool level indicator 2-CAC-LR-2602 showed level of -31 2 inches white redundant indicators 2-CAC-LR-2601-1 & 2601-3 showed -28 5 inches Caused by change in trickle flow to wet ref leg PASTVALM J Carolina Power & Light Co 83/04/22 Region 2, Office of Director 2pp 18308 192 24X Fiche 50-324.83/04/22, 8305030512
- 8305030540 Forwards LER 83-037/03L-O DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY, J P Region 2, Office of Director 1p 18303 332 24X Fiche 30-324,83/04/22,8305030540
- --8305030547 LER 83-037/03L-0 on 830325,RHR Div II suppression gool cooling valve 2-Eii-F0248 could not be opened using either valve motor operator or manual operator Caused by losse antirotation device setscrew Setscrew tightened PASTVA,M J Carolina Power & Light Co 83/04/22 Region 2, Office of Director 2pp 18303 333 24X Fiche 50-324,83/04/22,8305030540
- 8305030291 Supplemental response to Part 21 rept re postulated pipe crack in MPCI.RCIC.reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program DIETZ.C R Carolina Power & Light Co. 83/04/26 0'REILLY, J P Region 2, Office of Director 1p 18300 061 24% Fiche 50-324,83/04/26,8305030291
- 8305050265 Forwards LER 83-038/03L-0
 DIETZ,C R Carolina Power & Light Co 83/04/28 O'REILLY, J P
 Region 2, Office of Director 1p 18338 039 24X
 Fiche 50-324,83/04/28,8305050265,
- --8305050267 LER 83-028/03L-0 on 830401 inoperative & rod block signal received from rod block monitors A & B upon selecting indicated control rods Caused by defective multiplexer cards in monitors Cards replaced & monitors returned to svc PASTVA.M J Carolina Power & Light Co 83/04/28 Region 2, Office of Director 1p 18338 040 24X Fiche 50-324.83/04/28, 8330503265
- B305050242 Forwards LER 83-042/03L-0 DIETZ.C R Carolina Power & Light Co B3/04/29 O'REILLY, J P Region 2, Office of Diractor 1p 18337 297 24X Fiche 50-324,83/04/29,8305050242
- --8303050244 LER 83-D42/03L-O on 830330, suppression pool level indicators 2-CAC-LI-2601,3 & 2-CAC-LI-3342 showed upward trend in level indication Caused by closed demineralized water root valve, preventing transmitters from sensing actual level PASTVA,M J Carolina Power & Light Co 83/04/27 Region 2, Office of Director lp 18337 278 24X Fiche 30-324,83/04/29, 8303030242
- 830313017/ Forwards LER 83-044/03L-0 DIETZ: C R Carolina Power & Light Co 83/05/04. Q'REILLY, J P Region 2. Office of Director 1p 18440 091 24X Fiche 50-324.83/05/04.8305130177
- ---8305130184 LER 83-044/03L-0 on 830408 & 07, during unit startup & power operations, control rods 02-27(02), 34-03(04), 34-23(02) & 30-11(03) had no indications for identified positions Caused by failed position reed switches. Reed switches replaced PASTVA.M J Carolina Power & Light Co. 83/05/04 Region 2, Office of Director ip 18440 092 24X Fiche 50-324,83/05/04,8305130177
- 8305130167 Forwards LER 83-045/03L-0 DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P Region 2, Office of Director ip 18437 301 24X Fiche 50-324, 83/05/05, 8305130167
- --B305130172 LER 83-045/03L-0 on 830408, routine channel check of reactor level instrumentation revealed reactor level instrument 2-B21-LT-N017D-1 indicating higher actual level Caused by leak on bypass valve N017D-1 stem packing Packing adjusted PABTVA:M J Carolina Power & Light Co 83/05/05 Region 2, Office of Director ip 18437 302 24X Fiche 50-324,83/05/05,8305130147.
- B305130170 Forwards LER 83-046/03L-0 DIETZ.C R Carolina Power & Light Co B3/05/06 D'REILLY, J P Region 2. Office of Director 1p 18439'191 24X Fiche 50-324.83/05/06.8305130170
- --8305130176 LER 83-046/03L-0 on 830410, wires to terminals 13 & 14 in terminal box for MSIV 2-821-F028A found reversed Cause undetermined Wires reterminated to proper terminals POULK, R M Carolina Fower & Light Co. 83/05/06 Region 2, Office of Director ip 18439/192 24X Fiche 50-324,83/05/06,830530170

- 8305200538 Forwards supplemental LER 83-033/03L-1 DIETZ.C R Canolina Power & Light Co 83/05/06 O'REILLY, J P Region 2. Office of Director ip 18514 260 24X Fiche 30-324,83/05/06,8305200538
- --8305200543 Supplemental LER 83-033/02L-1 on 830223 while performing high steam line radiation thannel caller & functional test, main steam line instrument channels found out of caller Gaused by instrument drift Drawers recaller FDULK: A Carolina Power & Light Co. 83/05/06 Region 2. Office of Director 3pp 18514 261 24V Fiche 50-324.83/05/06, 8303200338
- DUCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8305200625 Forwards Rev B to industrial security plan Changes do not decrease effectiveness of plan or level of security Enci withheld (ref IOCRR73 21 & 2 790) HOME.P W Carolina Power & Light Co 83/04/20 O'REILLY.J P Region 2. Office of Director 2pp 18520 042 24X Fiche 50-324.83/04/20.8305200625
- 8305200597 Forwards change to provisions of industrial security plan Change uill not decrease effectiveness of plan or level of security Encl withheld (ref 10CFR73 21) HME.P W Caralina Power & Light Co 83/04/28 0'REJLLY, J P Region 2, Office of Director 1p 18514 106 24X Fiche 50-324,83/04/28,8305200597
- 8305100100 Forwards IE Safeguards (nsp Repts 50-324/83-13 & 50-325/83-13 on B30411-15 No noncompliance noted VERRELLI.A Division of Project & Resident Programs 83/05/05 UTLEY.E E Carolina Power & Light Co 2pp 18375 033 24% Fiche 30-324,83/05/05.8305100100
- --8305100109 IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted Major areas inspected audit review security plan records assessment aids alarm stations & training/qualification Details withheld (ref 10CFR73 21) TORIN W J Region 2, Office of Director 63/05/04 ip 16375 035 24X Fiche 50-324,83/05/05,8305100100
- 8305110034 Generic Ltr 83-21 to all licensets of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D O Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000.83/05/11,8305110034
- J Insurance & indemnity information
- 8303140135 Forwards Endorsement 48 to NELIA Policy NF-218
 BARHAN.C D Carolina Power & Light Co 83/05/02 SALTZMAN.J NRC
 No Detaited Affiliation Given 2pp 18446 066 24X
 Fiche 30-324,83/05/02,8303140135
- P Operating license stage documents & correspondence
- B30518000: Add1 response to FOIA request for seven categories of documents re Brown & Root, Inc & South fexas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON.J M Division of Rules and Records B3/03/09 LINDEMAN.H N
 Lowenstein, Newman, Repis, Avelnad & Toll 6pp 18497 219 24X
 Fiche 50-000,03/03/09,8305180001
- --8010280378 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AMS Code STELLO:V Office of Inspection & Enforcement, Office of the Director 80/09/23 AMEANNE.JF Commissioners 5pp 18497 228 24X Fiche 50-000,83/03/09,8305180001
- 8303230283 Forwards capital tost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress SMITH.8 H Carolina Power & Light Co 83/03/22 TOURTELLOTTE, J Regulatory Reform Task Force 13pp 18543 277 24% Fiche 50-000,83/03/22,8305230283

- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24X Fiche 30-000.83/04/11,8305230720
- 8305030463 Application for amend to Licenses DPR-62 & DPR-71, supplementing 820616 request for miscellaneous Tech Spec revs originally scheduled for completion during 820901 refueling outage Dutage & mods to be completed by 830624 HOME: P W Carolina Power & Light Co 83/04/28 VA85ALLG, D B Operating Reactors Branch 2 2pp 18308 222 24X Fiche 50-324,83/04/28,8305030463
- --830503048i Proposed Tech Specs re safety-related hydravlic snubbers, post-accident monitoring instrumentation, gas analyzer sys, reactor coolent leakage detection sys & remote shutdown menitoring instrumentation

 « Carolina Power & Light Co 83/04/28 19pp 18308 224 24X
 Fiche 50-324,83/04/28,8305030463
- 8305190099 Forwards safety evaluation for TMI Action Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4. "Training for Mitigating Core Damage "Training & requalification programs acceptable VASSALLO. D B Operating Reactors Branch 2 83/04/29 UTLEY. E Carelina Power & Light Co 3pp 18523 175 24X Fiche 50-324.83/04/29.8305190099
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455
- 8305060176 Application to amend License DPR-71 revising Tech Specs to complete third refueling outage & begin Cycle 4 operation Proposed changes revise control rod scram insertion time requirements

 HDME.P W Carolina Power & Light Co 83/05/02 VASSALLO, D B Operating Reactors Dranch 2 2pp 18345 328 24X
 Fiche 50-325,83/05/02.8305060176
- --8305060180 Proposed Tech Spec changing control rod scram insertion tios requirements to complete third refueling outage & begin Cycle 4 operation & Carolina Power & Light Co 83/05/02 30pp 19345 330 24X Fiche 50-325,83/05/02,8305060176
- 8305090380 Ack receipt of 830131 ltr requesting add1 info re NUREO-0737. Item II K 3 26. "Gwalification of ADS Accumulator 8ys "Info requested from GE Response will be submitted by 830630 ZIMMERMAN S R Carolina Power & Light Co 83/05/05 VASSALLO.D 3 Operating Reactors Branch 2 ip 18363 340 24X Fiche 30-324.83/05/05.83035090380
- B305090456 Confirms 830419 responses to questions raised during B30418 telcon re spent fuel pool expansion
 ZIMMERMAN, 9 R carolina Power & Light Co B3/05/05 VASSALLO, D B
 Operating Reactors Branch 2 2pp 18362 265 24X
 Fich
- 8305230178 Forwards safety evaluation of util submittal re procedure verification & design mod per NURE9-0737. Item II K 3 22, "Automati. Switchover of RCIC Suction " Mods acceptable VASSALLO.D B Operating Reactors Branch 2 83/05/05 UTLEY.E & Carolina Power & Light Co. 5pp. 18546 356 24X Fiche 50-324,83/05/05.8305230178
- 8305100362 Forwards Y1003J01A53, "Supplemental Reload Licensing Bubmittal For Brunswick Steam Electric Plant: Unit 1, Reload 3(W/o Recirculation Pump Trip)," inadvertently amitted from 830502 Tech Spec rev request ZIMMERMAN, S R Carolina Power & Light Co 83/05/06 VABSALLO, D B Operating Reactors Branch 2 ip 18379 059 24X Fiche 50-325,83/05/06,8305100362
- --8305100370 "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant, Unit 1, Reload 3 (H/o Recirculation Pump Trip) "
 ZANARDI, 0 . HILL, R T . CHARNLEY, J S General Electric Co. Y1003J01A53 83/01/31. 28pp 18379 060 24X Fiche 50-325,83/05/06,8305100362
- 8305090659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 30-000,83/05/09,8305090659

- 8305[20003 Responds to 830316 ltr requesting review of RCIC sys automatic restart per TMI Action Item II K 3 13 Acceptance criteria identified in Itr satisfied ZIMMERMAN.5 R Carolina Power & Light Co 83/05/09 VASSALLO.D B Operating Reactors Branch 2 1p 18423 076 24X Fiche 50-324.83/05/09.8305120003
- 8305260285 Forwards request for add1 info re 910123 response to NUREG-0737.1tem II K 3 28. "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of itr receipt VASSALLGID B Operating Reactors Branch 2 83/05/11 UTLEY, E E Carolina Power & Light Co 3pp 18629 337 24X Fiche 50-324,83/05/11,8305260285
- 8305240004 Informs that currently scheduled Unit 1 startup date is 830612 Outage critical path 8 days behind but recovery plan instituted to make up time Requests Tech Spec changes be issued no later than 830612 HURFORD. W Caraline Power & Light Co 83/05/17 VASSALLO, D & Operating Reactors Branch 2 ip 18549 051 24X Fiche 50-324,83/05/17,8305240004
- 8305240434 Commits to submit results of plant-unique calculations forming bases for mod program on Mark I containment vacuum breakers by 830630 in response to Generic Ltr 83-08 Calculations presented in listed documents HOME, P W Carolina Power & Light Co 93/05/19 VASSALLO, D & Operating Reactors Branch 2 2pp 18571 061 24X Fiche 30-324,83/05/19,8305240434
- 8305260320 Forwards NEDO-24582, "Mark I Containment Program Plant-Unique Load Definition Brunswick Steam Electric Plant Units 1 & 2" Attachment detailing pressure/temp calculations also encl ZIMMERMAN.S R Carolina Power & Light Co 83/05/24 VASSALLO,D D Operating Reactors Branch 2 ip 18625 038 24X Fiche 50-324:83/05/24:8305260320
- --8305260323 "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 " • General Electric Cd NEDO-24582 ROI 81/10/31 6ipp t8623 059 24% Fithe 50-324,83/05/24,8305260320
- Q Inspection reports, IE Bulletine & correspondence
- 8305270331 Submits results of split sample taken from floor drain sample tank 0 for tritium & radiostrontium.per IE Insp Repts 50-324/82-09 & 50-325/82-09
 DIETZ.C R Carolina Power & Light Co 83/02/25 O'REILLY, J P Region 2, Office of Director ip 18646 129 24X
 Fiche: 50-324,83/02/25.8305270531
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Rosin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompilance noted O'REILLY, J P. Region 2. Office of Director 83/04/11 UTLEY, E Caroline Power & Light Co. 2pp. 18644 158 24X Fiche 30-000.83/04/11,8305270461
- --8305270474 IE Enforcement Conference Repts 50-261/83-10,50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of radwaste containing free liquid & inoperability of standby pas treatment doluge sys LEMIS.R C Division of Project & Resident Programs 83/04/07 3pp 18644 160 24X Fichs 50-000,83/04/11,8305270461
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" 8vc list encl JORDANNE C. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 112pp 18383 089 24X Fiche, 50-000, 83/04/22, 8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere 8ensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York. Inc 115pp 18382 047 24X Ficha 50-000:83/04/28,8303040026
- 8303040027 IE Info Natice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list anci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83704/28 Constit
- 8305270250 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-07 & 50-329/83-07
 VERRELLI.D M Division of Project & Resident Programs 83/04/29
 UTLEY, E E Carolina Power & Light Co ip 18641 187 24X
 Fiche 50-324, 83/04/29, 8305270250
- --8305270256 Responds to NRC 830317 ltr re violations noted in IE Insp Repts 30-324/83-07 & 50-325/83-07 Corrective actions procedure revised & accepted by QA reflecting actual testing method & contractor personnel counseled DIETZ.C R Caralina Power & Light Co 83/04/15 O'REILLY, J P Region 2. Office of Director 2pp 18641 188 24X Fiche 50-324.87/04/29, 8/05057/0590
- --8305270263 Forwards IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/03/17 UTLEY.E E Carolina Power & Light Co 2pp 18641 190 24X Fiche 50-324,83/04/29,8305270250
- --8305270276 IE Insp Repts 50-324/83-07 & 30-325/83-07 on 830131-0203 & 07-11 Noncompliance noted failure to foilow inservice insp procedure for recording angle beam data CCLEV, J. t. BLAKE, J. J. Region 2. Office of Director 83/03/04 8pp 18641 193 24X Fiche 50-324,83/04/29,8305270250
- 8305060620 Responds to NRC 830218 ltr transmitting notice of violation & proposed imposition of civil penalties, per IE Insp Repts 50-324/82-28 & 50-325/82-28 Relay tests completed satisfactorily
 UTLEY, E E Carolina Power & Light Co 93/05/02 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 27pp 18349 022 24X Fichs 50-324, 83/05/02, 8305060620
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705703 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-2/, "Operational Response to Events Concerning Deliborate Acts Directed Against Plant Equipment "Swc list end!
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8305100100 Forwards IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 83041i-15 No noncompliance noted VERRELLI.A Division of Project & Resident Programs 83/05/05 UTLEY, E E Carolina Power & Light Co 2pp 18375 033 24% Fiche 50-324.83/05/05.8305100100
- --B305100109 IE Bafeguerds Insp Repts 50-324/B3-13 & 50-325/B3-13 on B30411-15 No noncompliance noted Major areas inspected audit review. Becurity plan, records, assessment aids, alarm stations & training/qualification Details withheld (ref IOCFR73 21) TOBIN.W J. HALL.B Region 2. Office of Director ACCOURE.D R Division of Emergency Preparedness & Materials Safety B3/05/04 ip 18375 035 24% Fiche 50-324, B3/05/05, B305100100
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 113pp 18523 248 24X Fiche 50-000.83/05/06,8303040033
- B305270580 Ack receipt of B30318 & 0422 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-324/82-45 & 50-325/482-45 & 50-325/482-45 & EWIS,R C Division of Project & Resident Programs 83/05/06 UTLEY,E E Carolina Power & Light Co 1p 18644 225 24X Fichs 30-324.B3/05/06.B305270380

- --B305270588 Responds to NRC 830207 ltr re violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45 Corrective actions required rev to 0-list procedure will not be completed until 830527 DIETZ.CR Carolina Power & Light Co 83/05/23 O'REILLY, J P Region 2, Office of Director ip 18644 226 24X Fiche 50-324,83/05/06,8305270580
- --B303270599 Clarifies response to Violations B & C in IE Insp Repts 50-324/82-45 & 50-329/82-45 Program for determining type of alarm devices needing periodic calibr will not be completed by 820730 DIETZ.C R Carolina Power & Light Co B3/04/22 O'REILLY. J P Region 2. Office of Director 2pp 18644 227 24X Fichs 50-324,83/05/06,8305270580
- --8305270610 Responds to violations noted in IE Insp Rept 50-324/82-45 & 50-325/82-45 Corrective actions engineering supervisor of discipline group responsible for performing review of tables for inconsistencies internal to procedure DIETZ.CR Consumers Power Co 83/03/18 D'REILLY.J P Region 2, Office of Director 4pp 18644 229 24X Fiche 50-324, 83/05/06.8305270380
- --8305270617 Ack receipt of 830207 ltm transmitting IE Insp Repts 30-324/82-43 & 50-329/82-45 Util continuing evaluation of violations Response to rept will be submitted by 830318 DIETZ.C R Carolina Power & Light Co 83/03/08 G'REILLY, J P Region 2, Office of Director ip 18644 233 24X Fiche 50-324,83/05/06.8305270580
- --8305270621 Forwards IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215 & notice of violation LEHIS:R C Division of Project & Resident Programs 83/02/07 UTLEY:E E. Caroline Power & Light Co 2pp 18644.234 24X Fichs 50-324.83/05/06.8305270580
- --8305270628 Notice of violation from insp on 821115-1215

 4 Region 2: Office of Director 83/02/07 2pp 18644 236 24X

 Fiche 30-324,83/03/06.8305270580
- 8305270333 Forwards IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/10 UTLEY, E E Carolina Power & Light Co 2pp 18641-123 24X Fiche 50-324,83/05/10,8305270333
- --8305270342 IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted Major areas inspected independent insp effort & observation of inservice insp work & work activities.

 COLEY, J. L. BLAKE, J. J. Region 2. Office of Director 83/05/05 opp 18441 125 24% Fishe 50-324.83/05/10.8305270333
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 SVC list ent!
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York: Inc. 114pp 18697 009 24X Fiche. 50-000, 83/05/19, 8303040040
- 6303040046 IE Info Natice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647.007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305100412 Forwards monthly operating repts for Apr 1983 DIETZ.C R Carolina Power & Light Co 83/05/05 DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 1p 18378 066 24X Fiche 50-324,83/05/05,8305100412
- --B305100417 Monthly operating repts for Apr 1983.

 HARRISON.F Carolina Power & Light Co B3/05/03 12pp.

 18378 067 24X Fiche-50-324.83/05/05.8305100412

- S Reportable occurrences, LERs & related correspondence
- 8305030497 Nonroutine radiological environ event rept Results of 830308 gamma analysis of bottom sediment revealed high Co-60 concentration Samples will be taken monthly for Oct 1982 June 1983 to determine if trends can be predicted DIETZ.C R Garolina Power & Light Co 83/04/20 O'REILLY.J P Region 2. Office of Director 2pp 18306 183 24X Fiche 50-324,83/04/20,8305030497
- 8305030505 RD 7-day specified time frame of four fire barrier limiting conditions for operation exceeded, to permit work in augmented offgas & control bidgs for installation of two plant mods Fire watches will remain in effect DIETZ. C R Carolina Power & Light Co 83/04/20 O'REILLY, J P Region 2. Opfice of Director 1p 18308 197 24X Fiche 50-325.83/04/20,8305030505
- 8305030387 Part 21 rept re pips clamps for snubber/struts oriented in off-axis direction initially reported on 830224 % by IE Info Notice 83-13 Clamps will be replaced by end of Fall 1983 refueling outage DIETZ.C R Carolina Power & Light Co 83/04/22 O'REILLY, J. P Region 2. Office of Director 2pp 18272 316 24X Fiche 50-324,83/04/22,8305030387
- 8305030465 Forwards LER 83-017/03L-0 DIETZ, C R Carolina Power & Light Co B3/04/25 D'REILLY, J F Region 2, Defice of Director 1p 18308 243 24X Fiche 50-325,83/04/23,8305030465
- --8305030473 LER 83-017/03L-0 on 830326-28 & 0402, listed control rods had no indications for identified positions Caused by loose prototypic inlet piping connectors in each rod attributed to undervessel work Plant mods scheduled PASTVA: M J Carolina Power & Light Co 83/04/25 Region 2, Office of Director ip 18308 244 24X Fiche 50-325,83/04/25,8305030465
- 830303027i Supplemental response to Part 21 rept re postulated pipe crack in HPCI.RCIC.reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program DIETZ.C R Carolina Power & Light Co 83/04/26 O'REILLY, J P. Region 2. Office of Director ip 18300 061 24X Fiche 30-324,83/04/26,8305030291
- B305050201 RO review of fire protection sys documentation revealed 17 sys limiting conditions for operation exceeding respective time frames not reported to NRC Plant operations instructions revised & special training provided DIETZ.C R Carolina Power & Light Co 83/04/26 O'REILLY, J P Region 2, Office of Director 2pp. 18342 152 24X Fiche: 50-325,83/04/26,8305050201
- B303030143 RD on B30325, fire barrier limiting condition for operation generated to permit accessing fire door in augmented offgas bidg Caused by temporary routing of flush lines for plant mod Mod work completed on B30411

 DIETZ.C.R Carolina Power & Light Co B3/04/28 O'REILLY, J P Region 2, Office of Director ip 18341 104 24X

 Fiche 50-325, 83/04/28, 8305050143
- 8305110282 Forwards LER 83-014/03L-0 DIETZ:C R Carolina Power & Light Co 83/05/04 D'REILLY, J. P Region 2, Office of Director 1p 18373 248 24X Fiche 50-325, 83/05/04, 8305110282
- --8305110284 LER 83-014/03L-0 on 830406 & 08, during engoing refueling, control rods 46-35,22-19,14-11,42-31 & 46-31 had no indications for identified positions Caused by loose or defective prototypic inlet piping connectors
 PASTVA, M J Carolina Power & Light Co 83/05/04 Region 2, Office of Director 2pp 18373 247 24X Fiche 50-325,83/05/04.8305(10282
- 8305130108 RD on 830404, fire barrier limiting conditions for operation initiated on penetration seal CB-2-301 of Fire Door 221 Gaused by need to allow ambient air circulation due to inoperability of computer room air canditioner DIETZ.C R Carolina Power & Light Co 83/05/05 D'REILLY, J P Region 2. Office of Director. p 18437 270 24X Fiche 50-325,83/05/05,8305130108

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/03/2: PARRIB,H 9 Tennessee Valley Authority 2pp 18641 153 24X Fiche 50-327/83/03/23,8305270313
- --8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Majar areas inspected radiation protection shipment of radioactive math. IE Bulletin 80-10, IE Circular 82-47 & health physics retraining CGLLINS, T R , BARR, K P Region 2, Dffice of Director 83/03/22 7pp. 18641 155 24X Fiche 30-327,83/03/23,8305270313
- 8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan NDVAK, T. M. Assistant Director for Licensing 83/05/04 PARRIS, H. 9 Tennessee Valley Authority 5pp 18503 343 24X Fiche 30-327,83/05/04,8305180213
- --8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan
 EISENHUT, D O Division of Licensing 83/05/04 4pp 18503 348 24% Fiche 30-027, 83/05/04, 8305180213
- --8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79: respectively ADENBAM, E. O. Licensing Branch 4 83/05/04 2pp 16503 352 24x Fiche 50-327,83/05/04,8305180213
- --8305180248 Bafety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively ** Office of Nuclear Reactor Regulation, Director 83/05/04 3pp 18503 334 24% Fiche 50-327.83/05/04,8305180213
- B305100101 Responds to B30505 telcon request re review of proposed physical security plan Pian to be revised by plant operations review committee Changes have not reduced nuclear safety.

 MILLB, L M Tennessee Valley Authority B3/05/05 ADENBAM, E Licensing Brench 4 1p 18377 114 24X Fiche 50-327.83/05/05.8305100101.
- 8305130041 Withdraws 801231 request for Tech Spec change re number of fire detectors Change no longer necessary KAMMER, D 8 Tennessee Valley Authority 83/05/09 ADENSAM.E Licensing Branch 4 1p 18436.262 24X Fiche 50-327,83/05/09.8305130061.
- 8305i10034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 3vc list encl EISENHUT, D. 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fichs 50-000,83/05/11,8305110034
- B305250372 Requests remittance of balance due for review of B20721 application to amend Browns Ferry 1 Tech Space re Cycle 5 MCPR values & B20623 application re physical security plan changes for Sequoyah 1 & 2 MILLER, W O License Fee Management Branch, B3/05/20 PARRIS, H O Tennessee Valley Authority 2pp 18447 284 24X Fiche: 50-000, 83/05/20, 8305260372
- 8305310167 Forwards rev to util 830303 response to NRC 821112 request for add1 info on fire protection program Rev clarifies instrumentation loops; identified by fire shutdown logic diagram as being required for hot & cold shutdown MILLS, L.M. Tennessee Valley Authority 83/05/27 ADENSAM, E. Licensing Branch 4 App. 18652 290 24X Fiche 50-327, 83/05/27, 8305310167
- J Insurance & indomnity information
- 8303040243 Forwards Endorsements 32 & 26 to NELIA Policy NF-247 & MAELU Policy MF-102, respectively DUCK, JR Marsh & McLennan, Inc B3/04/27 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18323 244 24X Fiche 50-327, 83/04/29, 8305040243

- P Operating license stage documents & correspondence
- 8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1639, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515,2787 & 2802)
 SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24X Fiche 50-000,83/03/11,8305240249
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 30-000.83/05/02,8305020455
- 8305110246 Forwards Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs re upper head injection accumulator water level setpoint & tolerances ADENSAM, E @ Licensing Branch 4 83/03/03 PARRIS.H @ Tennessee Valley Authority 3pp 18434 298 24X Fiche 50-327, 83/05/03, 830510246
- --8305110249 Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, revising Tech Specs re upper head injection accumulator water level setpoint & tolerance ADENSAM & G Licensing Branch 4 83/05/03 8pp 18434 301 24% Ficha 50-327,83/05/03,8305110246
- --8303110250 Safety evaluation supporting Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively * Office of Nuclear Reactor Regulation, Director 83/05/03 dap 18434 309 24% Fiche 50-027, 83/05/03, 8305110246
- --8305110253 Notice of issuance & availability of Amends 28 & 17 to Licenses DPR-77 & DPR-79 respectively ADENSAM,E G Licensing Branch 4 83/05/03 3pp 18434 312 24x Fiche 50-327,83/05/03,8305110246
- 8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan NOVAK.7 M Assistant Director for Licensing 83/05/04 PARRIS:H G Tennessee Valley Authority 5pp 18503 343 24X Fiche 50-327.83/05/04.8305180213
- --8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan EISENHUT, D 0 Division of Licensing 83/05/04 4pp 18503 348 24X Fiche 50-327,83/05/04,8305180213
- ---8305180234 Notice of issuance & Availability of Amends 30 & 19 to Litenses DPR-77 & DPR-79, respectively ADENSAM.E 0 Litensing Branch 4 83/05/04 2pp 18503 352 24X Fiche 30-327.83/05/04.8305180213
- --8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively

 * Office of Nuclear Reactor Regulation, Director 83/05/04 3pp 18503 354 24X Fiche 50-327, 83/05/04, 8305180213
- B305160362 Forwards Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends change Tech Specs to reflect Class IE bus installation ADENSAM.E Q Licensing Branch 4 B3/05/05 PARRIS.H 0 Tennessee Valley Authority 2pp 18472 016 24X Fiche 50-327.83/05/05.8303160362
- --8305160366 Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs to reflect installation of second level of undervoltage protecton for Class IE buses ADENSAM.E.O Licensing Branch 4 83/05/05 24pp 18472 018 24X Fiche 50-327,83/05/05,8305160362
- --8305160368 Safety evaluation supporting Amends 29 % 18 to Licenses DPR-77 & DPR-79, respectively * Office of Nuclear Reactor Regulation, Director 83/05/05 3pp 18472 042 24% Fiche 50-327, 83/05/05, 8305160362
- --8305160369 Notice of issuance & availability of Amends 29 & 18 to Licenses PPR-77 & DPR-79, respectively ADEN8AM, E 0 Licensing Branch 4 83/05/05 4pp 18472 045 24X Fichs 50-327, 83/05/05. 8305160362

- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re-integrated scheduling for implementation of plant mods Bvc list encl EISENHUT.D Q Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627-153 24X Fiche 50-000.83/05/09.8305090659
- 8305130029 Informs that corrected Page 3/4 6-20 to Amend 20 to License DFR-77 will be reissued Page includes valve FCV-77-20 in Table 3 6-2 Valve inadventently omitted from original issuance due to clerical arror KAMMER, D S Tennessee Valley Authority 83/05/09 ADENSAM, E Licensing Branch 4 1p 18437 009 244 Fiche 50-327, B3/05/09, 8305130029
- 8305170145 Responds to 830426 ltr re SER on environ qualification of eafety-related electrical equipment Review identified no item in NRC Category II B requiring justification for continued operation
 MILLS.L.M Tonnessee Valley Authority 83/05/12 ADENSAN, E
 Licensing Branch 4 ip 18466 284 24x Fiche 50-327, 83/05/12, 8305170145
- 8305240394 Forwards into re environ qualification of electric equipment important to safety, per 10CFR50 49(g) Listing of electrical equipment a schedule for qualification or replacement of remaining equipment provided KAMMER, D S Tennessee Valley Authority 83/05/20 ADENSAM, E Licensing Branch 4 79pp 18574 197 24X Fiche 50-327, 83/05/20, 8305240394
- 8305310053 Application for amend to Licenses DPR-77 & DPR-79 requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys MTLLG-L II Tennessee Valley Authority 83/05/25 ADENSAM.E 0 Licensing Branch 4 2pp 18653 166 24X Fiche 50-327,83/05/25,8305310053
- ~-8305310057 Proposed Tech Spec requesting temporary change in Limiting Condition for Operation 3 B 2 1 a for onsite power distribution sys * Tennessee Valley Authority 83/05/25 6pp 18653 168 24x Fiche 50-327,83/05/25,8305310053
- 8305310189 Advises that Tech Sper changes authorized by Amend 29 to License DPR-77 & Amend 18 to License DPR-79 will be implemented upon completion of undervoltage mods. scheduled to accur before Unit 2 refueling outage HILLS.L M Tennessee Valley Authority 83/05/26 ADENSAM. E Licensing Branch 4 Ip 18658 151 24X Fiche 50-327.83/05/26. B305310189
- @ Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
 112pp 18308 319 24X Fiche 50-000, 83/03/21,8212050395
- 8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliancs noted VERRELLI,D M Division of Project & Resident Progrems 89/03/23 PARRIS.H 0 Tennessee Valley Authority 2pp 1841 153 24X Fiche 50-327,83/03/23,8305270313
- --8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection-shipment of radioactive math. IE Bulletin 80-10, IE Circular 82-47 & health physics retraining COLLING.T R. BARK.K P. Region R. Dffice of Director 89/03/22 Spp 18641 155 24X Fichs 50-327,83/03/23,8305270313
- 8303040021 IE Info Natice 83-21, "Defactive Emergency Use Respirator" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BHR Safety/Relief Valve Feilures."

 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 087 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L. Division of Emergency Pregaredness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York Inc 119pp 18381 271 24X Fiche 50-000,83/04/25,8303040025

- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Natice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" 8vc list encl JORDANG L Division of Emergency Preparedness & Engineering Response (Prost 830103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Ficha 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Daliberate Acts Directed Against Plant Equipment " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp (8382.282 24X Fiche 50-000,83/05/04,830304003)
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDÁN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co of New York Inc 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Evc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Byc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp 18697.009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18447 007 24X Fiche 50-000,83/03/24,8303040046
- B305310077 Advises that reinsp of low pressure turbine disks during Cycle 1 refueling outage revealed four minor indications determined to be assembly scratches or tool marks & not cracks License Condition 2 C (8) satisfied MILLS, L M Tennessee Valley Authority B3/05/26 ADENSAM.E Licensing Branch 4, ip 18655 122 24X Fiche 50-327, B3/05/26, B305310077
- R Periodic operating reports & related correspondence
- 8305240323 Monthly operating repts for Apr 1983 W/830513 ltr MABON-C C. DUPREE, D. Tennessee Valley Authority 83/05/09 NRC - No Detailed Affiliation Given 24pp 18548 040 24X Fiche 50-327.83/05/09,8305240323
- S Reportable occurrences, LERs & related correspondence
- 8304190499 Forwards LER 83-043/01T-0 OREEN.H J Tennessee Valley Authority 83/04/13 O'REILLY.J P Region 2. Office of Director 1p 18054 026 24X Fiche 50-327,83/04/13,8304190499
- --8304190937 LER 63-043/01T-0 on 830331,all four 125-volt dc vital battery channels declared inoperable due to failure to perform whekly insp surveillance within required frequency Caused by personnel error Performance test completed. ROBERS:H.R., HARDING:M.R. Tennessee Valley Authority 83/04/13 Region 2, Office of Director 2pp 18054 027 24X Fiche 50-327,83/04/13,8304190499
- 9305030176 Forwards LER 83-045/03L-0 GREEN.H J Tennesses Valley Authority 93/04/26 D'REILLY, J.P. Region 2. Office of Director. ip 18300 267 24X Fiche 50-327, 83/04/26, 8305030176

- --8305030183 LER 83-045/03L-0 on 830401.06 & 10.steam generator 1 widerrange level channel declared inoperable after failing low Caused by faulty recorder i-LR-3-43.probably due to disfective switches in connector Recorder replaced ROGERS.H R , HARDINO.M R Tennessee Vailey Authority 83/04/26 Region 2. Office of Director ip 18300 268 24X Fiche 50-327.83/04/26.8305030176
- 8305030569 Forwards LER 83-048/03L+0 QREEN.H J Tennessee Valley Authority 83/04/26 D'REILLY, J P Region 2. Office of Director tp 18303 300 24X Fichs 50-327, 83/04/26, 8305030569
- --8305030579 LER 83-048/03L-0 on B30328, discovered that on B20911 & 830108, certain main steam safety relief valves failed to meet required setpoint criteria Caused by normal aging of valve spring & ambient temp variations valves adjusted CARVER, A M . HARDING M R Tennessee Valley Authority B3/04/26 Region 2, Dffice of Director 2pp 18303 301 24X Fiche 50-327,83/04/26,8305030569
- 8305050183 Forwards LER 83-047/03L-0 QREEN.H J Tennessee Valley Authority 83/04/27 O'REILLY, J P Region 2. Office of Director 1p 18338 151 24X Fiche 30-327,83/04/27,8305050183
- ---8305050206 LER 83-047/03L-0 on 830409,RCS subcooling margin monitor declared inoperable due to failure of plant computer Computer failure caused by memory parity error Computer restarted & monitor restored ROBERS,H R , HARDING,M R Tennessee Valley Authority 83/04/27 Region 2, Office of Director (p. 18338-152 24X Fiche 50-327,83/04/27,8305050183
- 8305050123 Forwards LER 83-053/03L-0 QREEN.H J Tennessee Valley Authority 83/04/29 D'REILLY, J P Region 2. Office of Director ip 18341 037 24X Fiche 50-327,83/04/29,8305050123
- --8305050128 LER 83-053/03L-0 on 830331, during review of maint requests, discovered that on 830319 steam generator blowdown isolation valve i-FC-i-14 would not stay open & Burveillance instruction 81-166 & post-maint strake test not performed CARVER, A M , HARDINO, M R Tennessee Valley Authority 83/04/29 Region 2, Office of Director ip 18341 038 24X Fichs 50-327,83/04/29,8305050123
- B305110325 Forwards LER B3-054/03L-0 GREEN, H J Tennessee Valley Authority 83/05/05 O'REILLY, J P Region 2: Office of Director ip 18406 160 24X Fiche: 50-327, 83/05/05, 8305110325
- --8305110327 LER 83-054/03L-O on 830406, while performing Special Test 89-STEAR-INST-83-3, containment isolation valve (-FCV-1-182 failed to open Valve repaired but failed again 2 days later Caused by excessive wear Parts replaced LUBNIO, H C . HARDING, M R Tennessee Valley Authority, 83/05/05 Region 2, Office of Director, ip 18406 161 24X Fiche 50-327,83/05/05,8305110325
- B303110373 Forwards LER 83-052/03L-0 OREEN.H J Tennesse Valley Authority 83/05/05 O'REILLY,J P Region 2. Office of Director 1p 18406 256 24x Fiche: 50-327,83/05/05,8305110373
- --B3051103B2 LER 83-052/03L-0 on B30407, while running shortened interval of Burveillance Instruction 196, two of four level switches found put of tolerance Probably caused by instrument drift or calibr techniques Switches calibr LUDMIO:M C . HARDINO:M R. Tennessee Valley Authority 83/05/05 Region 2. Office of Director 2pp 18406:257 24X Fiche:30-327,83/05/05,83051103/3
- B305200577 Forwards LER B3-055/03L-0 QREEN; H J Tennesses Valley Authority 83/05/12 O'REILLY, J P Region 2. Office of Director 1p 18514 126 24X Fiche: 50-927, B3/05/12, B305200577
- --B3052005B1 LER B3-055/03L-0 on B30415, bank D movable control assembly declared inoperable due to failure to move rods after receiving rod control sys urgent alarm Caused by blown phase C ref voltage fuse FU-10 Fuse replaced R00ERB.H R , HARDINO, M R Tennessee Valley Authority 83/05/12 Region 2, Uffice of Director ip 18514 127 24X Fiche 50-327,83/05/12,8305200577
- \$305200427 Forwards LER 83-056/017-0 QREEN.H.J. Tennesses Valley Authority \$3/05/13 O'REILLY, J P Region 2, Office of Director. 1p 18517 151 24X Fishe: 50-327, 83/05/13, 8305200427,

- ---8305200432 LER 83-056/017-0 on 830503, upper containment airlock inner door discovered inoperable Caused by sheared stud & failed cam follower bearing on latthing mechanism Mechanism repaired & returned to svc LUDWIG, W C . HARDING, M R Tennessee Valley Authority 83/05/03 Region 2. Office of Director 3pp 18517 152 24% Fiche 50-327,83/05/13.8305200427
- 8305230530 Forwards LER 83-056/01T-0 OREEN.H J Tennessee Valley Authority 83/05/16 D'REILLY.JP Region 2. Office of Director 1p 18537 055 24X Fiche 50-327.83/05/16.8305230530
- --8305230536 LER 83-056/017-0 on 830503, inner door to upper containment airlock discovered inoperable Caused by sheared stud on latching mechanism & falled cam follower bearing allowing outer door to open while inner door not closed LUDHIG.N C , HARDING M R Tennessee Valley Authority 83/05/16 Region 2, Office af Director 3pp 18537 056 24X Fiche 50-327,83/05/16.8305230530
- 8305250526 LER 83-038/03L-0 on 830420.while in Mode 1.turbine bldg sump radiation monitor declared inoperable due to failure to meet surveillance requirements Caused by debris from sump blocking flow switch flow switch clasmed M/830518 1tr RODGERS.H R , HARDINO, M R , GREEN, H J Tennessee Valley Authority 83/05/18 0'REILLY, J P. Region 2. Office of Director 2pp 18383 341 24X Fiche 50-327,83/05/18.8305250526
- 8305250532 LER 83-063/03L-0 on 830421, pressurizer PORV 1-PCV-6F-340A failed to open Caused by failed coil in ASCO solenoid model LB831634 Valve will be repaired at first outage of sufficient duration M/830518 ltr HARDINO, M R. LUDWIG, N C. OREEN, H J Tennessee Valley Authority 83/05/18 0/REILLY, J P. Region 2, Office of Director 2pp 16588 227 24X Fiche 50-327,63/05/18,8303250532
- 8305260307 NPDES noncompliance nutification on 830326 & 29, temp risg between upstream ambient monitor & downstream river monitor exceeded 5 4 F limit Caused by low riverflows cooling tower & increased riverflows used to eliminate delta temp changes EL-ASHRY.M 7 Tennessee Valley Authority 83/05/23 MARLAR.J Environmental Protection Agency 8pp 18625 336 24X Fiche 50-387,83/05/23,8305260307
- X Onsite Storage of Low Level Waste
- B305030679 Requests remittance of add1 sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste HILLER.N O License Fee Management Branch 83/04/22 MILLS.L M Tennessee Valley Authority 2pp 18309 193 24X Fiche 50-000.83/04/22.8305030679
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8303270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 83/03/23 PARRIS.H 0 Tennesse Valley Authority 2pp 18641 153 24X Fiche 50-327, 83/03/23, 8305270313
- --8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-i8 No noncompliance noted Major areas inspected radiation protection shipment of radioactive math, IE Bulletin 80-10, IE Circular 82-49 & health physics retraining COLLING.T R Region 2, Office of Director 83/03/22 9pp 18641 155 24X Fichs 50-327,83/03/23,8305270313
- 8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan NOVAK.T M Assistant Director for Licensing 83/05/04 PARRIS.H G Tennesses Valley Authority 5pp 18503 343 24X Fiche 50-327.83/05/04.8305180213
- --8305180224 Amends 30 & 17 to Licenses DPR-77 & DPR-79, respectively, revising Ilcense conditions to include Commission approved guard training & qualification plan & safeguards contingency plan EIBENHUT, D 0 Division of Licensing 83/05/04 4pp 18503 348 24% Fiche 50-327, 83/05/04, 8305180213
- --8305180234 Notice of issuance & availability of Amends 30 & 19 to Licanses DPR-77 & DPR-79, respectively ADENSAM, E & Licensing Branch 4 83/05/04 2pp 18503:352 24X Fichs 50-327,83/05/04,8305180213

- --8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & PPR-79, respectively 4 Offsice of Nuclear Reactor Regulation, Director 83/05/04 3pp 18503 354. 24% Fiche 50-327,83/05/04,8305180213
- 8305100101 Responds to 830505 telcon request re review of proposed physical security plan Plan to be revised by plant operations review committee Changes have not reduced nuclear safety MILLS th Tennessee Valley Authority 83/05/05 ADENSAN, ELicensing Branch 4 ip 18377 i14 24X Fiche 30-327, 83/05/05, 8305100101
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactore, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits BVc list enc!
 EISENHUT, D 0. Division of Licensing 83/05/11 Consolidated Edison Co of New York Inc. 16pp 18540 095 24X
 Fiche. 50-000, 83/05/11, 8305110034
- 8303260372 Requests remittence of balance due for review of 820921 application to amend Browns Ferry 1 Tech Specs re Cycle 5 MCPR values & 820623 application re physical security plan changes for Sequoyah 1 & 2.

 MILLER.H.O Licanse Fee Management Branch 83/05/20 PARRIS.H 0 Tennesse Valley Authority. 2pp 18447 284 24X

 Fiche 50-000,83/05/20,8305260372
- 8305310167 Forwards rev to util 830303 response to NRC 821112 request for addl info on fire protection program. Rev clarifies instrumentation loops: identified by fire shutdown logic diagram as being required for hot & cold shutdown MILLG.L M Tennessee Valley Authority 83/05/27 ADENSAM, E. Licensing Branch 4 App 18652 290 24X Fiche 50-327.83/05/27, 8305310167
- J Insurance & indemnity information
- 8305040243 Forwards Endorsements 32 & 26 to NELIA Policy NF-247 & MAELU Policy MF-102, respectively DUCK-J R Marsh & McLennen, Inc. 83/04/29 SALTYMAN, J Assistant Director for State & Licensee Relations 3pp 18323 244 24X Fiche: 50-327, 83/04/29, 8305040243
- P. Operating license stage documents & correspondence
- 8303040084 Ack receipt of 830304 application for rev of License Condition 2.C(14) Fee exemption request denied Payment of Class II fee requested DIOGERM License Fee Management Branch 83/04/26 PARRIE, H O Tennessee Valley Authority. 1p 18336.332 24% Ficha 50-328,83/04/26,8305040084
- 8305020455 Generic Ltr 83-i9 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D Q. Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 1844f 120 24x Fiche 50-000,83/05/02,8305020455
- 8305110246 Forwards Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively eafety evaluation & notice of issuance & availability. Amends revise Tech Specs re upper head injection accumulator water level setpoint & tolerances ADENSAM. E. 9 Licensing Branch 4 83/05/03 PARRIS. H 9 Tennessee Valley Authority. 3pp. 18434 298 24x Fiche 50-327,83/05/03, 8305110246.
- --8305110247 Amends 20 & 17 to Licenses DPR-77 & DPR-79, respectively, revising Tach Specs re upper head Injection accumulator water level setpoint & tolerance.

 ADENBAM, E. Q. Licensing Branch 4 83/05/03 8pp 18434 30i. 24X Fiche 50-327,83/05/03,8305110246
- --8305110250 Safety evaluation supporting Amends 28 & 17 to Licenses PPR-77 % DPR-79 respectively * Office of Nuclear Reactor Regulation, Director 18434-309, 24X Fiche 50-327,83/05/03.8305110246
- --8305110253 Notice of issuance & availability of Amends 28 & 17 to Licenses DPR-77 & DPR-79; respectively. ADENSAMES.G. Licensing Branch 4 83/05/03 3pp 18434 312 24X Fiche. 50-327, 83/05/03, 8305110246
- B305180213 Forwards Amends 30 k 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability, Amends revise license conditions to include Commission approved guard training & qualification plan NOVAK: T & Assistant Director for Licensing. B3/03/04. PARRIS, H 0 Tennesses Valley Authority 3pp 18503.343 24X Fichs: 50-327, 83/05/04, 8305180213

- --8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan e18ENHUT, D O Division of Licensing 83/05/04 4pp 18503 348 24X Fiche: 50-327, 83/05/04, 8305180213
- --8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively ADENSAM, E G Licensing Branch 4 83/05/04 2pp 18503 352 241 Fiche 50-327, 83/05/04, 8305180213
- --8303180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively * Office of Nuclear Reactor Regulation, Director 83/05/04 3p 18503 334 24% Fiche 50-327.83/05/04.8305180213
- 8305160362 Forwards Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends change Tech Specs to reflect Class IE bus installation ADENSAM, E O Licensing Dranch 4 83/05/05 PARRIS, H Q Tennessee Valley Authority 2pp 18472 016 24X Fiche 50-327, 83/05/05, 83/05160362
- --B305160366 Amends 27 & 18 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs to reflect installation of second level of undervoltage protecton for Class IE buses ADENSAM, E Ø. Licensing Branch 4 83/05/05 24pp 18472 018 24% Fiche 50-327, 83/05/05, 8305160362
- --8305160368 Bafety evaluation supporting Amends 29 & 18 to Licenses DPR-77 & DPR-79-respectively * Office of Nuclear Reactor Regulation, Director 18472 042 24X Fichs 50-327,83/05/05,8305160362
- --8303160369 Notice of issuance & availability of Amenda 29 & 18 to Licenses DPR-77 & DPR-79, respectively ADENSAM, E 0 Licensing Branch 4 83/05/05 4pp 18472 045 24X Ficha 50-327, 83/05/05, 8305160362
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs rm integrated scheduling for implementation of plant mode Svc list encl
 EISENHUT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627,153 24X Ficha 30-000,83/05/09,8305090659
- 8305130029 Informs that corrected Page 3/4 6-20 to Amend 20 to License DPR-77 will be refsered Page includes valve FCV-77-20 in Table 3 6-2 Valve inadvertently unitted from original Issuance due to clerical error
 KAMMER.D 8 Tennessee Valley Authority 83/05/09 ADENSAM.E
 Licensing Branch 4 lp. 18437 009 24X Fiche 50-327,83/05/09,830310029
- B305170145 Responds to B30426 itr re SER on environ qualification of safety-related electrical equipment Review identified no item in NRC Category II B requiring justification for continued operation MILLG.L M Tennessee Valley Authority 83/05/12 ADENSAM.E Licansing Branch 4 Ip 18466 284 24X Fiche 50-327,83/05/12, B305170145
- 8305240394 Forwards info re environ qualification of electric equipment important to safety, per 10CFR50 49(g) Listing of electrical equipment to safety, per unalification or replacement of remaining equipment provided MAMMER.D S Tennessee Valley Authority 83/05/20 ADENBAM.E Licensing Branch 4 79pp 18574 197 24% Fiche 50-327,83/05/20,8305240394
- B305310033 Application for amend to Licenses DPR-77 & DPR-79 requesting temporary change in Limiting Condition for Operation 38 2 1 a for onsite power distribution sys MILLS:L M Tennessee Vallay Authority 83/05/25 ADENSAM
- --8308310057 Proposed Tech Spec requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys

 4 Tennessee Valley Authority 83/05/25 6pp 18653 168 24X
 Fiche 50-327,83/05/25,8305310053
- 8305310189 Advises that Tech Spec changes authorized by Amend 29 to License DPR-77 & Amend 18 to License DPR-79 will be implemented upon completion of undervoltage modes, scheduled to occur before Unit 2 refueling outage MILLS:L M Tennessee Valley Authority 83/05/26 ADENSAM. E Licensing Branch 4. 1p 18658 151 24% Fiche 30-327.83/05/26, 8305310189.

Q Inspection reports, IE Bulletins & correspondence

- 8212060385 IE Info Notice 83-14. "Dewatored Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50~000,83/03/21,8212060385
- 8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on B30214-18 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/03/23 PARRIS.H G Tennessee Valley Authority 2pp 18641 153 24% Fiche 50-327.83/03/23,8305270313
- --8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection shipment of radioactive math. IE Builetin 80-10, IE Circular 82-49 & health physics retraining COLLING, T R , BARR, K P Region 2, Office of Director 83/03/22 9pp 18641 155 24X Fiche 30-327,83/03/23,8305270313
- 8303040021 [E Info Notice 83-21, "Defective Emergency Use Respirator " Byc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 135 24X Fiche 50-000.83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list enc!
 JORDAN: C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Cansolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040029 IE Info Notice 83-23: "Inoperable Containment Atmosphere Sensing Sqs " Svc list enc! JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl. JORDAN,C L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 188pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 JE Info Notice 83-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl URDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York. Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B3D3040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04, Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- B3D3O40033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl UORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B3O103) B3/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc 11st encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/ii Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/ii,8303040034
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program."

 Svc list encl

 JORDAN:E L Division of Emergency Preparedness & Engineering

 Response (Post B30103) 83/05/17 Consolidated Edison Co of New

 York, Inc 114pp 18697 009 24X F1che 50-000,83/05/19,8303040040

- 8303040046 IE Info Notice 83~33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York: Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040046
- R Periodic operating reports & related correspondence
- B305240323 Monthly operating repts for Apr 1983 W/830513 ltr MASON.C C., DUPRES.D Tennessee Valley Authority B3/05/09 NRC - No Detailed Affiliation Given 24pp 18548 040 24X Fichs 50-327, 83/05/07, 8305240323
- 8 Reportable occurrences, LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept. "Cracks & Leeks in Small Diameter Piping" BROWN,E J Reactor Operations Analysis Branch 83/04/19 8EYFRIT.K V Reactor Operations Analysis Branch ip 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230517 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000.83/04/19,8305230573
- 8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
 MILLB.L M Tennessee Valley Authority 83/04/27 O'REILLY, J P Region 2. Office of Director 3pp 18341 083 24X
 Fiche 50-000.83/04/27,835050132
- 8305050218 Forwards LER 83-046/03L-0 OREEN.H J Tennesse Valley Authority 83/04/27 D'REILLY.JP Region 2. Office of Director ip 18338 092 24X Fiche 30-328.83/04/27.8305050218
- --8305050224 LER 83-046/03L-0 on 830401.RCS subcooling margin monitor declared inoparable due to failure of plant computer Computer failure caused by attempt to run program loaded on faulty disc Program reloaded to different area of disc ROGERS.H R . HARDINO, M R. Tennessee Valley Authority 83/04/27 Region 2. Office of Director ip 18338 093 24X Fiche 50-328.83/04/27,8305050218
- 8305050211 Forwards LER 83-051/03L-0 OREEN,H J Tennesse Valley Authority 83/04/29 O'REILLY,JP Region 2. Defice of Director 1p 18338-110 24X Fiche 50-328,83/04/29,8305050211
- ---B305050217 LER 83-051/03L-0 on B30401.safety injection sys boron injection tank inlet shutoff valve 2-FCV-63-40 would not operate Caused by dirty motor starter contactors Contactors cleaned & screw connections tightened CARVER:A M , HARDINO:M R Tennessee Valley Authority 83/04/29 Region 2, Office of Director ip 18338 iii 24X Fiche 50-328.83/04/29.83030502ii
- 8305110409 Forwards LER 83-050/03L-0 OREEN H J Tennessee Valley Authority, 83/05/06 O'REILLY, J P Region 2. Office of Director, 1p 18392 002 24X Fiche 50-328,83/05/06,8305110409
- --B305110419 LER B3-050/03L-O on B30413.control rad D-B failed to move w/rest of bank upon demand & became misaligned by more than 12 steps Caused by Inoperable lift coil due to open connection at vessel head ROGERS, H R. . HARDING, H R Tennessee Valley Authority B3/05/06 Region 2, Office of Director ip 18372 003 24X Fiche 50-328,83/05/06,8305110407
- 8305250342 LER 83-040/09L-0 on 830419, automatic control valve 2-LCV-3-154 in auxiliary feedwater sys failed to open on damand Caused by incorrect size of metering orifice Correct parts installed W/B30519 ltr OREEN,H J. RODERS,H R. HARDINO,M R. Tennessee Valley Authority 83/05/18 0'REILLY,J P. Region 2. Office of Director 4pp. 18585 355 24X Fiche 50-328,83/05/18,8305250342
- B305250380 LER B3-062/03L-0 on B3042i three of four level switches in upper head injection sys discovered out of tolerance On B30505 all four switches found out of tolerance Caused by instrument drift Switches recalibr W/B30518 ltr LUDWIO.W C . HARDING.M R Tennesses Valley Authority. B3/05/18. 0'RELLUT.J P. Region 2, Office of Director. 2pp 18585 347 24% Fiche, 50-328, 83/05/18, 8305250380

- B305250400 LER B3-064/O3L-0 on B30420.auxiliary feedwater automatic valve 2-LCV-3-148 failed to close on demand from control board Caused by failure of Backana Model B613-2098-0200 controller due to faulty voltage H/B30518 ltr ROCERS.H R , HARDING.M R , GREEN.H J Tennessee Valley Authority B3/05/15 D'REILLY.J P Region 2. Office of Director 2pp 18585 335 24X Fiche 50-328,83/05/18.8305250400
- 8305250433 LER 83-059/03L-0 on 830422.while in Mode 1.rod position indication for rod C-5 in shutdown bank D misaligned by 12 steps & declared inoperable Cause unknown Rod position indicator & cable verified W/830519 ltr HARDING M R , GREEN.M J Tennessee Valley Authority 83/05/19 0'REILL/LJ P Region 2, Office of Director 2pp 18585 287 24X Fiche 50-328,83/05/19,8305250433
- 8305260307 NPDES noncompliance notification on 830326 & 28 temp rise between upstream ambient monitor & downstream river monitor exceeded 3 4 F limit Caused by low riverflows Cooling tower & increased riverflows used to eliminate delta temp changes EL-ASHRY.N I Tennessee Valley Authority 83/05/23 MARLAR.J Environmental Protection Agency 8pp 18625 336 24X Fiche 50-327.63/05/23.8305260307

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of add1 sum to complete payment of 800731 & 1124 amend applications to permit storage of low level raduaste MILLER, W D. License Fee Management Branch 83/04/22 MILLE. M Tennessee Valley Authority 2pp 18309 193 24X Fiche 80-000-83/04/22.8308030679

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 9305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11 PALLADINO, N. J. Commissioners 2pg 18542 272 24X Fiche 50-000,83/04/t1.8305230720
- 8305060379 Notification of contract execution.Mod 6 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants i & 2" Contractor Geotechnical Engineers.Inc FIELDS.JA Division of Contracts NRC-03-82-092 83/04/12 VOLLMER.R M Division of Engineering KANE.J NRC No Detailed Affiliation Given ip 18353 086 24% Fiche 50-329.83/04/12.8300060379
- ~-8305060384 Mod 6.modifying monthly business ltr reporting requirements.
 to "Foundations & Underpinning Review of Remedial Measures
 for Structures on Fill for Midland Plants 1 & 2 "
 POULOS.8 J Geotechnical Engineers, Inc GUSTAVE.R P Division
 of Contracts NRC-03-82-092 83/04/12 3pp 18353 087 24X
 Fiche 50-329.83/04/12.8305060379
- B304220515 Forwards revised affidavits for individuals previously employed by NRC now working on independent design & const varification grogram Clarification of "providing safety evaluation" also submitted LEVIN.H A TERA Corp 83/04/21 KEPPLER.J G Region 3, Office of Director 15pp 18:33 273 24X Fiche 50-329,83/04/21,8304220515
- 8305020565 Responds to 830325 ltr re TERA Corp GA & engineering plans for independent design & const verification program for facilities NRC comments on reporting requirements proposed by TERA Corp at 830412 meeting will be provided REHM.T Office of the Executive Director for Operations 83/04/22 OCROES PP Government Accountability Project 2pp 18284 238, 24X Fiche 50-327.83/04/22,8305020565
- 8305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Topical Rept CPC-1A. "GA Manual for Midland Nuclear Plant, Vol 1" MILLER, W. G. License Fee Management Branch B3/04/25 BYRD, W. Consumers Power Co. 1p 18367-361 24V Fiche 50-329, 83/04/25, 83050900551
- 8305170131 Informs of review completion for listed activities re remedial soils work Concurrence requested MILLER, D B Consumers Power Co 83/04/28 HARRISON, J J Region 3. Office of Director 2pp 18466 265 24X Fiche 50-329,83/04/28, 8305170131
- 8305170539 Forwards Vol 5 of "Sgismic Margin Review Diesel Generator Bldg " COOK.J H Consumers Power Co 83/04/28 DENION.H R Office of Nuclear Reactor Regulation, Director 3pp 18469 036 24X Fiche 50-329.63/04/28,8305170539

- ---8305170344 Vol 5 of "Seismic Margin Review Diesel Generator Bid" WEBLEY, D A , KENNEDY, R P , KINCAID, R H Structural Hechanics Associates SMA 13701 05R003 VO 89704/30 113pp 18469 (4) 24% Fithe 50-327, 83704/28, 8305170539
- 8305170422 Forwards change specs for "Pior Wil Load Recycling Procedure." For remedial soils work, per NRC-util work authorization procedure MILLER, D.B. Consumers Power Co. 83/04/29 HARRISON, J.J. Regist 10 Office of Director 2pp. 18469-286. 24X Fiche 50-329,83/04/29 8305170422
- B305050493 Documents B30413 tolcon Util commitment to provide happing air ejector radiation monitors deleted from FBAR Chapter if 5 Potential relaxation of tritium sampling requirement discussion deferred pending effluent Tech Spec review COUK.J W Consumers Power Co 83/05/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18345,360 241 Fiche 50-329,83/05/02,8305060483
- B305170467 Requests concurrence w/proposed changes to approved vers activity to perform load test at Pier IIW MILLER, D B Consumers Power Co 83/05/02 HARRISON: J Right: 1 Office of Director 2pp 18470 075 24X Fiche 50-329.63/03/02, 8305170467
- 8303110140 Accepts TERA Corp as independent third-party to parfera review of design & const verification program re Unit 2 auxiliary feedwater sys NOVAK, 7 M Assistant Director for Licensing 83/03/03 COM, Jw Consumers Power Co 7pp 18421 351 24X Fiche 50-329, 83/03/03. 830510140
- B305170397 Requests authorization for remedial soils work to install Bulkheads E10 & W10 & to install, load & excavate Piers BE, BN, 10E & 10W MILLER, D B Consumers Power Co 83/05/03 HARRISON, J J Right, Office of Director lp 18469 231 24x Fiche 50-329, 83/05/07, 8305170397
- B305040323 Board Notification 83-057 forwards differing prof opinists we says interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D 9 Division of Licensing B3/05/04 PALLADING, N Commissioners 22pp 18337 139 24X Fichs 50-000, 83/05/04, 8305040323
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees the holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENNUT.D Q Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659
- 8303190065 Requests authorization to begin Remedial Soils Work Activities 407050400, shallow probing for Phase II & 202550104, SHPS-install & terminate cable MILLER, D B Consumers Power Co 83/05/09 HARRISON, J Region 3 Defice of Director 1p 18502 067 24X Fiche 30-329, 83/05/09
- 8305200387 Confirms 830510 telcon authorizing minor soil excavation from buried pipes outside of valve pits MILLER, D B Consumers Power Co 83/05/10 HARRISON, J Regist 1 Office of Director ip. 18518 174 24X Fiche 50-329,83/05/10,8305300389
- 8305170321 Forwards comments on review of TERA independent design (***) verification program from 830413 meeting Program scope omitted sys walk-down or turn-over & program interfaces MARNICK: R F Region 3, Office of Director 83/05/11 NOVAK: I M Assistant Director for Licensing 3pp 18465-239 24X Fiche 30-329,03/05/11,8305170321
- 8303190280 Forwards "Evaluation of Pressures in Lines of Grouting Equipment Crack Repair Borated Water Storage Tank Foundations: "In response to unresolved Item in 830118 ltr Mixing ratios for positive displacement pumps within 39808 MILLER, D B Consumers Power Co 83/09/12 HARRISON, J Regin 2 Office of Director 1p 18501 148 24X Fiche 50-329,83/05/12.8305190280.
- --B305190284 "Evaluation of Pressures in Lines of Grouting Equipant Crack Repair Borated Water Storage Tank Foundations "
 MEISENHEIMER, J., WIELAND, R.H. Consumers Power Co 83/05/05 6/1
 18501 149 24X Fiche 30-329,83/05/12

- 8305240353 Documents 830512 discussion re remedial soils work authorization Three addi shallow holes on south side of diesel generator bldg constitute only minor change MILLER,D 8 Consumers Power Ca 83/05/13 HARRISON.J J Region 3, Office of Director 1p 18573 361 24X Fiche 50-329,83/05/13,8305240353
- 8305240427 Requests work authorization for syc water pump structure underpinning program & replacement of syc water pipe Train A MILLER.D B Consumers Power Co 83/05/13 HARRISON, J Region 3. Office of Director ip 18571 057 24X Fiche 50-329,83/05/13,8305240427
- B305310190 Submits list of acceptable activities for remedial soils work authorization
 MILLERID B Consumers Power Co B3/05/13 HARRISON, J J Region 3
 Office of Director 1p 18651 001 24X Fiche 50-329,83/05/13,
 8305310190
- 8303270057 Forwards Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
 GOOK, JW Consumers Power Co 83/05/16 DENTON, HR Office of
 Nuclear Reactor Regulation, Director 1p 18640 063 24X
 Fiche 50-329,83/05/16.8305270057
- --8305270063 Amend 113 to application for CPs & GLs.consisting of Rev 48 to FBAR containing site emergency plan CDDX.J W Consumers Power Co 83/05/16 ip 18640 064 24X Fiche 50-329,83/05/16,83052/0057
- B305200553 Forwards Rev 2 to engineering program plan & Rev 3 to project GA plan re independent design & const verification program LEVIN.H TERA Corp 83/05/18 EISENHUT.D 0 Division of Licensing KEPPLER.J 9 Region 3. Office of Director COOK.J W Consumers Power Co 4pp 18514 284 24X Fiche 50~329.83/05/18.8305200553
- --8303200567 Rev 2 to "Engineering Program Plan Project Instruction PI-3201-009 Midland Independent Design & Conet Verification Program Project 3201" * TERA Corp 83/05/18 158pp 18514 288 24X Ficha 50-329,83/05/18,8305200553
- --B305200575 Rev 3 to "Project QA Plan for Midland Independent Design Const & Verification Program" LEVINH A , LEMON.C E . BECK.J W TERA Corp B3/05/02 264pp 18915 086 24X Fiche 50-329,83/05/18,8305200553
- 8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs to Disconsisting of Rev 48 to FSAR site emergency plan.

 BUD21KiD M Consumers Power Co 83/05/19 DENTON H R Office of Nuclear Reactor Regulation, Director 3pp 18548 331 24X Fiche 50~329,83/05/19,8305240137
- B305240223 Forwards SB Baranow & J Chawlo signed affidavits re potential conflict of interest in performing third-party const implementation overview HILD.F A Btone & Webster, Inc. B3/05/19 KEPPLER, J G Region 3, Office of Director 3pp 18548 012 24X Fiche 50-329,83/05/19, B300240223
- B305310143 Confirms 830720 meeting w/J Keppler to discuss various suppliers quality activities undertaken by Bechtel in support of nuclear projects.per 830520 discussion SMITH.C F Bechtel Corp 83/05/20 WARNICK.R F Region 3, Office of Director 1p, 18458 073 24X Fiche 50-327,83/05/20,8305310143
- 8305270299 Enumerates new info matl & relevant to GM/GL proceeding, as presented before ABLB on 830427 Licensee identified & reported two cracks in svc water pump structure MARNICK:R F Region 3, Office of Director 83/05/24 EIBENHUT, D O DIVIsion of Licensing 2pp 18641 356 24% Fiche 50-329,83/05/24,8305270299.
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B305020398 Forwards "B&H 177 Fuel Assembly Dwners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup nozzles.

 COOK. J W Consumers Power Co B3/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 18273 001 24X Fiche 50-329,83/04/13,8305020398
- --B305020404 "B&W 177 Fuel Assembly Owners Group Safe End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking " * Babcock & Wilcox Co. 77-1141514-00. B3/04/13 61pp 18273 005. 24X Fiche: 50-329: B3/04/13, B305020378

- 8305040336 Notification of 830511 meeting w/util & B&W in Bethesda,MD to discuss SER Open Item 7 & Confirmatory Item 7 re natural circulation & reactor vessel head vent HERNANAR W Licensing Branch 4 83704/27 ADENSAM,E 9 Licensing Branch 4 6pp 18326 335 24X Fiche 30-329,83/04/27,8305040336
- 8305110305 Suppls explanation of 820721 commitment to implement expanded cooling pond dike surveillance program including visual insps of dike turf, to resolve NRC concern re dike erosion & performance identified in May 1782 SER COOK, J W Consumers Power Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18373 229 24X Fiche 50-329,83/05/03,8305110305
- 8305070394 Comments on Open Item 2 re turbine missiles in SER Sections J 7 & 3 5 i 3 Probability of unacceptable damage to safety-related sys & components due to missiles acceptably low MOVAK.T M Assistant Director for Licensing 83/05/04 COOK.J W Consumers Power Co 3pp 18367 344 24X Fiche 50-329.83/05/04, 3705090504
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Bvc list encl. EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc. 16pp 18540-095 24X Fiche 50-000.83/05/11,8305110034
- 8305270057 Forwards Amend 113 to application for CPs & OLs.consisting of Rev 48 to FSAR containing site emergency plan CDOK. J W Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X Fiche 50-329,83/05/16,8305270057
- --8305270066 Rev 48 to FSAR containing site emergency plan * Consumers Power Co 83/05/31 264pp 18640 067 24X Fiche 50-329,83/05/16,8305270057
- **G** Adjudicatory correspondence
- 830504044\$ Notice of appearance in proceeding Certificate of Svc encl PROVENZAND, V P Consumers Power Co 83/04/28 3pp 18322 128 24X Fiche 50-329,83/04/28,8305040441
- B305040809 Renewed amended objections to interrogatories directed to util on ZACK issues & renewed motion for protective order Certificate of Svc encl Related correspondence PROVENZAND, V P Consumers Power Co 83/04/28 Sinclair, M 7pl 18321 045 24X Fiche 50-329/83/04/28/8305040509
- 8305040449 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
 BISHOP,L L Binclair, M DISHOP,L L Harmon & Weiss 83/05/02
 ip 18322 237 24X Fiche 50-329,83/05/02,8305040449
- 8305100341 Motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination at 830601 evidentiary hearings re reopened GA matters Certificate of Svc encl STEPTOE.P Consumers Power Co STEPTOE.P Isham, Lincoin & Beale 83/05/04 Atomic Safety and Licensing Board Panel 80pp 18378 233 24x Fiche 50-329,83/05/04,8305100341
- 8305100264 Advises of svc of deposition subpoents on deponents M Cient & B Marello Svc list encl PROCTOR: 8 D Isham. Lincoln & Beals PROCTOR: 8 D Consumers Power Co 83/05/06 Abomic Safety and Licensing Board Panel 2pp 18372, 296 24X Fichs 50-329, 83/05/06, 8305100764
- B30510041B Forwards unsigned subpoenss issued for L Clark T Devine. B Garde & L Hallberg depositions, for signature Witnesses intend to file motion to quash Svc list encl PROCTOR: 8 D. Isham. Lincoln & Beale B3/05/06 BECHHOEFER, C Atomic Safety and Licensing Board Panel 10pp 18378 081, 24X Fiche 50-329,83/05/06.8305100418
- 9305120273 Revised motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time inits on cross-examination Measures essential to timely development of complete record H/Certificate of Syc MILLER:M I Consumers Power Co MILLER:M J Isham Lincoln & Bale 83/05/09 Atomic Safety and Licensing Board Panel 48pp 18427 209 24X Fiche 80-329,83/05/09,8305120273

- 8305120295 Confirms 830418 telcon re disclosure of anonymous informants names Applicant counsel agreed not to disclose name if name discovered in documents HILCOVE, M N
- us in documents IN Hearing Branch 2 83/05/10 STAHL,D Isham, Lincoln 2pp 18430 176 24% Fiche 50-327,83/05/10,8305120275
- 8305240373 Confirms teleon re continuation of deposition of L Clark & T Devine, scheduled for 830516 & 23 respectively D Garde deposition acheduled for 830606 may be continued provided reconvened GA hearings attended Related correspondence PROCTOR.8 D Isham, Lincoln & Beale 83/05/13 MCCLAIN, H Karr & Lyons ip 18574 015 24X Fiche 50-329,83/05/13.8305240373
- 8305190225 Forwards insp evaluation forms filed for IE Insp Repts 50-329/82-11 & 50-330/82-11, 50-329/82-17 & 50-330/82-17, 50-329/82-19 & 50-330/82-19 & 50-330/83-03 & 50-330/83-03 HLCOVE, M N Hearing Branch 2 83/03/17 BERNADEL, L. Government Accountability Project 8pp 18500 204 24X Fiche 50-329,83/05/17, 6008/8035
- 8305190216 Motion for extension until 830524 to respond to util motion ANDIVICE MALIAN FOR EXCENSION UNTIL B-3024 to respond to Util motito limit cross-sexamination Coursel involved in 830519-24 hearing ASLD has adequate time to rule on motion before hearings resume Certificate of Syc encl

 BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability

 Project 83/05/18 Atomic Safety and Licensing Board Panel (1800) 319 24% Fichs 50-329,83/05/18.8305190216
- B305240322 Responds to B30510 ltr Areas of disagreement re documents still exist Conference call will be scheduled w/ASLB (futi) wishes to gursue matter BRUNNER, J & Consumers Power Co B3/05/18 STAMIRIS, B Stamiri B 10pp 18548 078 24X Fiche 50~329,83/05/18.8305240322
- 8305240491 Discusses schedule for appearances Deposition of S Marello will be rescheduled for Juna Deposition of C Grant scheduled for 830525 Proceedings will be instituted to enforce subposena served on M Cioni PROCTOR PROCTOR: S D (sham, Lincoln & Beale PROCTOR, S D Consumers Co 83/05/19 EECHOEFER, C Atomic Safety and Litensing Board Panel STUCKY, S W Docketing & Services Branch 2pp 18571: 24X Fiche 50-329, 83/05/19, 8305240491 PROCTOR, S D Consumers Power 18571 269
- B305240059 Proposes schedule for presenting testimony during B30601-10 hearings Proposal is joint proposal of util & NRC Rept on investigation of alleged violation of ABLB order will not be available by B30601-10 hearings WILCOVE M N Rearing Branch 2 B3/05/20 BECHHDEFER.C., COVAN, F.P. HARBOUR, J Atomic Bafety and Licensing Board Panel 2pp 18549 133 24X Fishe 50-329, 83/05/20, 8305240059
- G305240065 Response to util B30509 revised motion revising B30504 motion re procedural limitations Commission does not favor singling out issue of discretionary referral of denied parts of motion during proceeding Certificate of Svc encl HRJGMT,N A Hearing Branch 2 B3/05/20 Atomic Safety and Licensing Doard Panel 7pp 18549 055 24x Fiche 50-329,83/05/20,8305240065
- 8305240472 Order granting Stamiris motion for extension until 830524 to respond to applicant revised motion to establish limits on cross-grammination nation Atomic Safety and Licensing Board Panel, 83/05/20 Ip 18549 278 24X Fiche 30-329,83/05/20,8305240472
- 8309250215 Telecopy response to util revised motion Extensive hearing record caused by const of safety-related bidgs on faulty soil not by intervenor actions SINCLAIR.M Sinclair.M 83/05/23 Docketing & Services Branch 2pp 18592 354 24X Fiche 50-329,83/05/23,8305250215
- B305260149 Response to util revised motion to require submission of cross-examination plans, designation of lead intervenors & time limits on cross-examination Util apparent lack of concern for public safety justifies careful exam of issues SINCLAIR.M Sinclair, M 83/05/23 Atomic Befety and Licensin SINCLAIR.M Sinclair, M 83/05/23 Atomic Bafety and Licensing Board Panel 2pp 18599 284 24X Fiche 50-329,83/05/23,8305260169
- 8305270547 Forwards "Seismic Margin Review," Vols I.V & VI W/o encl. STEPTOE, P. P. Isham, Lincoln & Beale STEPTOE, P. Consumers Power Co. 83/05/23 EECHHOEFER.C. COMAN, F. P. MARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 18646, 127 24% Fiche 50-329, 83/05/23, 8305270547
- 8305260166 Response opposing util 830509 revised motion to require cross-examination plans, designation of lead intervenors & time limits on cross-examination Due process rights of full participation cannot be denied Certificate of Svc encl BERNABEIL. Stamir(s. B BERNABEIL. Quvernment Accountability Project B3/05/24 Atomic Safety and Licensing Board Panel 12pp 18599 290 24X Fiche 50-329,83/05/24,8305260166

- 8305240274 Transmittal of documents on encl list of submittals 305260276 Transmittal of documents on encl list of submittals responsive to 8 Stamiris 830407 document request Submittals designated publicly available, already submitted, privileged under atty-client privilege/proprietary WHICOVEM N Hearing Branch 2 83/05/24 BERNABEI, L Government Accountability Project 2pp 18625 143 24X Fiche 50-329,83/05/24,
- 8305270606 Order granting Stamiris 820524 discovery request for 905270506 Under granting Stamiris BXO324 discovery request for documents re implementation of quality improvement program in soils area & denying addl discovery requests re NRC/util Sept 1792 meeting. containment cracks issue & audit repts EECHHUFFER.C Atomic Safety and Licensing Board Panel 83/05/23 Stamiris, D 4pp 18644 248 24X Fiche 50~329,83/05/23.8305270606

H General correspondence

- 8305040549 Responds to 830324 ltr requesting independent plant sudit & more public meetings Three independent audits in progress or planned for site Soils compaction problem & technical & GA concerns being addressed by current hearings EISENHUT, D G Division of Licensing 83/04/22 ROMO, K B Affiliation Unknown ip 18351 232, 24X Fichs 50-329,83/04/22,8305040549
- 8305040550 Responds to 830323 ltr requesting independent audit & further public mestings Three audits in progress or planned EISENHUT, D 0 Division of Licensing 83/04/22 HAVERCAMP, M Affiliation Unknown 1p 18351 233 24X Fiche 50-329, 83/04/22, B305040550
- 8305170392 Responds to 830421 itr re reinsp & independent audits at facilities Dn 830503, TERA Corp approved to perform independent review of design & const of auxiliary feedwaters HIS SEW will perform overview

 KEPPLER, J. G Region 3. Office of Director 83/05/13 ROMO, L R

 Lone Tree Counsil 2pp 18471 202 24X Fiche 50-329, 83/05/13. 8305170392
- --8309170396 Requests assurance of independent agent to perform facility audits, per NRC 830419 reinsp order ROMO.L R Lone Tree Counsil 83/04/21 KEPPLER, J Region 3, Office of Director ip 18471 204 24x Fiche 50-327,83/05/13, 8305170392
- X Utility Final Safety Analysis Report (FSAR) & amends
- 8303270057 Forwards Amend ii3 to application for CPs & OLs.consisting of Rev 4B to FSAR containing sits emergency plan cODX, J W Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18640 063 24X Fiche 50-329, 83/05/16, 8305270057
- --8305270063 Amend 113 to application for CPs & DLs. consisting of Rev 48 to FSAR containing site emergency plan GODK.JW Consumers Power Co. 83/05/16 ip 18640 064 24X Fiche 50-329,83/05/14,8305270057
- ---8305270066 Rev 48 to F8AR containing site emergency plan * Consumers Power Co 83/05/31 264pp 18640 067, 24X Fiche 50-329,83/05/16,8305270057
- 8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & OLs.consisting of Rev 48 to FSAR site emergency BUDZIK, D.M. Consumers Power Co. 83/05/19 DENTON, H.R. Off Nuclear Reactor Regulation, Director 3pp 18548 331 24X Fiche 50-329, 83/05/19, 8305240137
- Q Inspection reports: IE Bulletins & correspondence
- 8305190005 Final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.G.D & E documents withheld (ref FDIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDERGASTIR Prendergast, N J 17pp 18506 057 24X Fiche: 50-000.83/03/11.8305190005
- --B305190045 Requests vendor insp of facilities having contracts u/Zact Co due to GA/GC problems at Midland re HVAC activities Tack Co correspondence re LaBalla & related info encl FIORELLI. G Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/04/21 PDTOPOUS. U Region 4. Dallas. Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000.83/03/11, 8208192005 Inspection Branch 8305190005

- --8305190050 Summarizes 820430 meeting w/president of Zack Co. HVAC contractor at facilities repotential allegations Zack Coplanning to terminate several employees in document control section
 HAYES, D. H. Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche 50-000,83/03/11,8305190005
- --8305170088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast + Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation given 2pp 18506 124 24X Fiche 50-000,83/03/11, 8305190005
- --8305190097 Requests investigation of Region III inadequate investigative oversight re GA breakdown & possible criminal falsification at Zack Co.HVAC contractor at facilities AT Howard & S Marello allegations discussed DEVING:T. GARDE.B Government Accountability Project 92/07/26 PALLADIMO:N J Commissioners lipp 18506 128 24X Fiche 50-000,83/03/11,8305190005
- --8305190102 Affidavit of SL Marelle re GC breakdown & criminal falsification at Zack Co. HVAC contractor at facilities MARELLO,8 L Affiliation Unknown 82/07/26 22pp 18306 139 24% Fiche 50-000,83/03/11,8305190003
- --B305190108 Affidavit of AT Howard re QC breakdown & criminal felsification at Zeck Co. HVAC contractor at facilities HOHARD.A T Affiliation Unknown B2/07/26 55pp 18506 160 24% Fichs 50-000,83/03/11,8305190005
- --8305170307 Discusses A Howard 820503 allegations re Zack Co tampering Wydocuments concerning HVAC activities at facilities Further investigation will be implemented if deemed appropriate by mgt
 SHAFER.H.D. Region 3. Office of Director 82/05/11 WARNICK.R F. Region 3. Office of Director 3pp 18507 354 24X Fiche. 50-000,83/03/11.8305190005
- --8305190394 Discusses 820624 telcon w/B Qarde of Gevt Accountability Project re allegations concerning Zack Co GA program at facilities Personally identifiable info deleted NORELIVES C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000,83/03/11,8305190005.
- 82j2060385 IE Info Notice 83-i4, "Dewatered Spent Ion Exchange Resin 8veceptibility to Exothermic Chemical Reaction " 8vc list ent! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319, 24X Fiche 50-000,83/03/21,8212060385
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 135 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Feilures "
 Bvc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- B30304002B IE Info Notice B3-23, "Inoperable Containment Atmosphere Bensing Bys " Byc list ent! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381.271 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Into Notice 83-24, "Loose Parts in Secondary Bide of Steem Cenerators at PMRs " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/26 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl, JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc. 118pp, 18382 165 24X Fiche: 50-000,83/04/28,8303040027
- B305ii0122 Forwards draft NRR BALP input for Jul 1981 Mar 1983, based on info solicited from listed personnel. Commants received by B30505 will be considered in finel rept MiLLER, M, A Licensing Branch 4 B3/05/02, MATTSON, R Division of Bystems Integration (post 811005). VOLLMER, R Division of Engineering, JORDAN, E Division of Emergency Preparedness & Engineering Response (Post 830103) 7pp 18421 316 24X Fiche, 50-327, 83/05/02, 8305110122

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakera " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830603) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svr list encl JDRDAN,E L. Division of Emergency Proparedness & Engineering Responses (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- B305190298 Forwards changes in MPGP-1.Rev 5 re QA angineering.providing insp plan to QC & removing requirement for reviewing design documents NRC approval of activity requested HILLER.D B Consumers Power Co B3/05/06 HARRISON.J J Region 3. Office of Director. 1p 18501 083 24% Fiche 50-329.83/05/06, 8305190298
- --8305190300 Draft quality plan for underpinning activities * Consumers Power Co MPGP-1 RO6 DRFT 83/05/03 23pp 18501 084 24X Fiche 50-329,83/05/06,8305190298
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8305130171 Ack receipt of 830327 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01 HARNICK,R F Region 3. Office of Director 82/05/11 COOK,J H Consumers Power Co ip 18438 104 24X Fichs 50-329,83/05/11,8305130171
- --8309130182 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01 Corrective actions valve, serial 27855, placed back in Bechtel stock B&W revising GC procedure for receiving & insp COOK, J W Consumers Power Co 83/03/29 KEPPLER, J Q Region 3, Office of Director 6pp 18439 105 24x Fiche 50-329, 83/05/11, 8305130171
- 8305200557 Advises that investigator file for IE Investigation Repts 50-329/82-13 & 50-330/82-13 reviewed.per ASLB order per intervenor request for discovery in GA hearlings Proprietary & nonproprietary documents listed W/o stated encis MARNICK.R F Region 3, Office of Director 83/05/17 PATON.W D NRC No Detailed Affiliation Given 3pp 18515 350 24X Fiche 50-329.83/05/17.8303200557
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl.
 JURDONNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 york. Inc 114pp 19697 009 24X Fiche 50-000.83/05/19.8303040040
- 8305240006 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-03 & 50-330/83-03 HARNICK.R F Region 3, Office of Director 83/05/20 CGOK, J W Consumers Power Co ip 18549 039 24X Fiche 50-329,83/05/20,8305240006
- --g305240008 Responds to NRC 830407 ltr re violations noted in IE Insp. Repts 50-329/83-03 & 50-330/83-03 Corrective actions, MPGAD Quality Action Request F-292 issued 830304 to review Bechtel procedures for proper quality classification CODK.J W Consumers Power Co 83/05/06 KEPPLER.J 0 Region 3. Office of Director 11pp 18549 040 24X Fiche 50-329,83/05/20,83/05240006.
- 8305260310 Ack receipt of 830310 ltr informing NRC of steps taken to correct violations moted in 830208 notice of violation & proposed imposition of civil penalties Revised response recraft & engineering personnel training requested KEPPLER, J. 9 Region 3, Office of Director 83/05/23 COOK, J W Consumers Power Co 2pp 18625 239 24% Fithe 50-329, 83/05/23, 8305260310.

- 8305270076 Confirms 830624 SALP meeting in Midland, MI Meeting open to other interested parties with the meeting open to other interested parties with the meeting open to other interested to the second section 83/05/24 COOK, J W Consumers Power Co. ip. 18638 301 24X Fiche 50-329, 83/05/24, 8308270076
- 8303040046 IE Info Notice 83-93, "Nonrepresentative Eampling of Conteminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 30-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305230270 "Active Mod Projects Operating PWR.1982" + Consumers Power Co 82/12/31 4pp 18576 332 24x Fiche 50-000.82/12/31,8305230270
- 8305030113 Forwards Bechtel.B&H & util monthly nonconformance repts for Mar 1983,per 730323 Memorandum & Order ALAB-1.06 & Amend 1 to CPs CPOK.J H. Consumers Power Co 83/04/25 DEYOUTO,R C Director's Office. Office of Inspection and Enforcement 1,139pp 18286 001 24X Fiche 50-329,83/04/25.8309030111
- 8305170373 Forwards "Work Activity List for May 1983," for remedial soil work per NRC-util work authorization procedure Authorization of specific work items requested NILLER,D 8 Consumers Fower Co 83/04/26 MARRISON,J J Region 3 0ffice of Director. 25pp 18466-031 24X Fiche, 50-329, 83/04/26, 8305170373
- 8305090052 Forwards addendum to "41st ALAB-106 Guarterly Rept.Apr-June 1983," convisting of resumes of recently hired employees COOK.J W Consumers Power Co 83/04/29 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 1p 18364 104 24% Ficha 30-329.83/04/29.8305090052
- --8305070060 Addendum to "41st ALAB-106 Quarterly Rept.Apr-June 1983" † Consumers Power Co 83/04/29. 82pp 18364 105 24X Fiche 50-329.83/04/29.8305090052
- 8305310198 Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept i," covering period from project inception through 830527.
 LEVIN.M A TEAA Corp 83/09/27 KEPPLER, J Q Region 3, Office of Director EISENHUT, D. Q Division of Licensing CODK, J W Consumers Power Co 4pp 18459:047 24x Fiche 50-329, 83/05/27, 8305310198
- --8303310203 "Midland Independent Design & Const Verification Program Monthly Status Rept 1." covering period from project inception through 830527.

 TULODIESKI.D.: LEVIN.H A TERA Corp 83/05/27 62pp 18659 050 24X Fiche 50-329,83/05/27,8305310198
- S Reportable occurrences, LERs & related correspondence
- B305190005 Final response to FBIA request for documents re Zact Co &/or work performed by Zack in const of facilities Forwards App A documents. Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FBIA Exemption 7) FELTON:J M Division of Roles and Records 83/03/II PRENDERGABT.R Prendergast R J 17pp 18506 059 24X Fichs 50-000.83/03/II.8305190005
- --8305190112 Deficiency rept re errors & discrepancies contained in HVAC mat1 certifications Procurement documentation will be revalidated, document & records mgt program will be developed & GA/GC personnel will be added Also reportable per Part 21 CALKINS, D.E., EICHSTAEDT, C.L., DEZUTEL, C.Z. Zack Co. 81/10/23 G10pp. 18506-215 24X Fiche 50-000,83/03/11.8305190005
- 8305170283 Ninth interim deficiency rapt re improper thrust forces used in high energy line break analysis pipe whip restraint design Initially reported on 800919 Design drawings for 83 restraints revised Next rept will be submitted by 840220 COOK.J W Consumers Power Co 83/05/06 KEPPLER.J O Region 3. Office of Director 9pp 18465-345 24% Fiche 50-329,83/05/06,8305170283
- B305170391 Final deficiency rept to nonconforming Class IE radiation monitoring sys electronic modulas mfg by Victorean Inc due to breakdown of dA program Initially reported on 820917 Vendor revised dA program reviewed & approved COOK.J.W. Consumers Power Co B3/05/06 KEPPLER.J G Region 3. Office of Director 9pp 18471.211 24% Fiche: 50-329, 83/05/06. 8305170391.

- B305170409 Interim deficiency rept re accident temp effects on containment level measurement Instrument string error exceeds alloweble steem generator ECCS control setpoints Bechtel & B&W refining existing calculations CODX.J W Consumers Power Co B3/05/06 KEPPLER.J 0 Region 3, Office of Director 2pp 18469 248 24X Fiche 50-329, 83/05/06, 8305170409
- 8305j70440 Interim deficiency rept re installation of B&W nonseismic transmitter mounting brackets forming part of RCPB Brackets will be replaced w/seismically qualified mounting brackets prior to initial fuel load Next rept expected by 830831 COOK.JW Consumers Power Co 83/05/06 KEPPLER.JO Region 3, Office of Director 2pp 18469 301 24X Fiche 50-329,83/05/06.8305170440
- 8305170489 Final deficiency rept re underrated 460-volt motor control ctr control circuit transformers supplied by Gould-Brown Boveri Initially reported on 821013 Transformers to be replaced & installation supervised by Bechtel CODK, J W Consumers Power Co 83/05/06, KEPPLER, J D Region 3, Office of Director 12pp 18470 055 24X Fiche 50-329,83/05/06,8305170489
- 8305200680 Interim deficiency rept re procured safety-related electrical equipment not meeting project requirements. Initially reported on 821230 Task force established to review purchase orders Next rept expected by 830627 COOK, J W Consumers Power Co 83/05/13 KEPPLER, J G Region 3, Defite of Director 11pp 18519; 108 24X Fiche 50-329, 83/05/13, 8306200080
- 8305200347 Interim deficiency rept re improper installation design of Class IE electrical control cabinet/panels Initially reported on 830211 Drawings will be revised Next rept will be submitted by 830819 Bechtel rept encl CODK. J W Consumers Power Co 83/05/16 KEPPLER, J, G Region 3: Office of Director 13pp 18316 235 24X Fiche 50-329, 83/05/16, 830520349
- B305240010 Interim deficiency rept re G-related equipment cooled by non-G HVAC sys Initially reported on 820625 Revs to Drawings 7220-H-550(G) will be made by B30630 Safety-grade HVAC added to listed areas Next rept by B30815 CDGK.J W Consumers Power Co B3/05/17 KEPPLER.J O Region 3. Office of Director 10pp 18549 028 24X Fiche 50-329, B3/05/17. B305240010
- 8305240218 Interim deficiency rept re design of embedments in concrete w/shear lugs located in tension zones Interim embedment design criterion being developed for use prior to testing completion Next rept expected by 831122 COOK, J. W. Concumers Power Co. 83/05/20 KEPPLER, J. O. Region 3, Office of Director 5pp 18599 317 24X Fiche 50-329,83/05/20, 6308240319
- B305260235 Finel deficiency rept re possible frazil ice formation in svc water intake structure Recirculation of svc water discharge flow near trash rack evaluated as best option to control ice at intake structure COGK. J W Consumers Power Co 83/05/20 KEPPLER. J G Region 3. Office of Director 7pp 18597 340 24X Fiche 50-327.83/05/20.830520235
- 8305240324 Final deficiency rept re auxiliary feedwater (AFW) suction piping design Initially reported on 821214 Design change issued to install pressure relief valve on four AFW pump suction lines between pump & first isolation valve CODK, J W Consumers Power Co B3/05/20 KEPPLER, J G Region 3, Office of Director 6pp. 18625 166 24X Fiche 50-329,83/05/20,830530324
- T Hearing transcripts on non-antitrust matters
- 8303100243 Forwards NRC testimony addressing Sinclair Contention 13 reastessment of severe accidents to be presented at 830328 hearing Testimony addressing Sinclair Contention 4 re-steam generator tube integrity filed on 830131 HRIGHT,N A Office of the General Counsel 83/03/18 BECHHOEFER,C. COWAN,F P. HARBOUR, J. Atonic Safety and Licensing Board Panel. 1p 18379 337 24X Fiche 50-329,83/03/19,8305100243
- --8305100245 Testimony of F Rowsome re Sinclair Contention 13 on assessment of severe accidents, RONSOME, F Assistant Director for Technology Review 83/03/18 13pp. 18373 338 24X Fiche 50-329,83/03/18,8305100243
- --8305100248 Testimony of LG Hulman & JA Mitchell re Sinclair Contention 13. HULMAN, L G , MIYCHELL, J A Accident Evaluation Branch 83/03/18 20pp 18373: 351 24X Fiche 50-329,83/03/18,8305100243

- 8305100124 Supplemental testimony of JG Keppler re GA KEPPLER, J G Region 3, Office of Director 83/03/25 6pp 18375 197 24X Fiche 50-000,83/03/25,8305100124
- --8303100141 Responds to Billi3 ltr ro implications of recent seismic design errors at facility Due to design errors util license suspended on Billi9 pending completion of independent design review & receipt of schedule for completing mods PALLADIND,N J Commissioners 82/02/01 DINORLL JD House of Rep . Energy & Commerce 5pp 18375 228 24X Fiche 50-000,83/03/25,8305100124
- B305100147 Forwards supplemental testimonies of JO Keppler RJ Cook RN Oardner RB Landsman WD Shafer & JW Gilray re GA W/o encls HILCOVE M N Office of the Executive Legal Director B3/03/25 BECHWIGEFFER C . COMAN F P . HARBOUR J Atomic Safety and Licensing Board Panel 2pp 18374 217 24X Fiche 30-329,83/03/25,8305100147
- 8305100261 Supp) beental testimony of JW Gilray, RB Landsman & WD Shafer re GA program for underpinning activities of svc water pump structure & auxiliary bldg Supporting documentation encl GILRAY, JW GA Branch LANDSMAN, R 0 , SHAFER, W D Region 3, Office of Director 83/03/29 38pp, 18372 258 24X Fiche 50-329, 83/03/25, 8305100261
- B305030457 Transcript of B30427 hearing in Midland, MI Pp 14, 272-14, 493 Supporting documentation encl * Atomic Bafety and Licensing Board Panel 83/04/27 265pp 18294 184 24X Fiche 50-327, 83/04/27, 8305030457
- 8305040191 Transcript of 830428 hearing in Midland, MI Pp 14,495-14,750 # Atomic Safety and Licensing Board Panel 83/04/28 260pp 18324 037 24% Fiche 50-329,83/04/28,8305040191
- 8305050028 Transcript of 830429 hearing in Midland.MI Pp 14,731-14,977 * Atomic Safety and Licensing Board Fanel 83/04/29 227pp 18342 262 24X Fiche 50-329,83/04/29,8305050028
- 8305050011 Transcript of 830430 hearing in Midland,MI Pp 14,978-15,096 * Atomic Safety and Licensing Board Panel 83/04/30 122pp 18338 155 24% Fiche 30-329,83/04/30,83050500011
- 8305060199 Transcript of 830502 hearing in Midland, MI Pp 15,097-15,393 Supporting documentation encl + Atomic Bafety and Licensing Board Panel 83/05/02 616pp 18346 001 24% Fiche: 90-329,83/05/02,8305060199
- 8305140033 Transcript of 830503 evidentiary hearing in Midland.Ml Pp 15, 374-15, 672 # Atomic Sefety and Licensing Board Panel 83/05/03 300pp 18455 116 24X Fiche 50-327, 83/05/03, 8305140033
- 8305110006 Transcript of 830904 evidentiary hearing in Midland,MI Pp 15,693-15,922 * Atomic Safety and Licensing Board Panel 83/05/04 232pp 18409 026 R4X Fiche 50-329,83/05/04,8305110006
- B305110092 Transcript of B30505 evidentiary hearing in Midland.MI Pp 15.923-16.219 * Atomic Bafety and Licensing Board Panel 83/05/05 302pp 18410 007 24X Fiche 50-329.83/05/05.8305110092
- 8305110001 Transcript of 830506 evidentiary hearing in Midland, MI Pp 16, 220-16, 366 a Atomic Bafety and Licensing Board Panel 83/05/06 150pp 18408 130 24X Fiche, 50-329, 83/05/06, 8305110001
- 8303310163 Transcript of 830310 proceedings in Chicago IL P 2 Subposna directed to M Cioni enci s Commissioners. 83/03/10 6pp. 18652:339 24X Fiche 30-329.83/05/10.8305310163
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8305230720 Forwards list of utils responding to requests for cost flgures on backfitting TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X Ficha 50-000.83/04/11,8305230720

- 8305060379 Notification of contract execution, Mod 6 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 " Contractor Geotechnical Engineers. Inc FIELDS, JA Division of Contracts NRC-03-62-092 83/04/12 VOLLMER, H Division of Engineering KANE, J NRC No Detailed Affiliation Given 1p 18353 086 24X Fichs 50-329, 83/04/12, 830306079
- --8305060384 Mod 6, modifying monthly business ltr reporting requirements, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2"
 POULOS,S J Geotechnical Engineers, Inc GUSTAVE,R P Division of Contracts NRC-03-82-072 83/04/12 3pp 18353 087 24X
 Fiche 50-329,83/04/12,8305060379
- 8304220515 Forwards revised affidavits for individuals previously employed by NRC now working on independent design & const verification program Clarification of "providing safety evaluation" also submitted LEVIN.H A TERA Corp 89/04/21 KEPPLER, J Q Region 3. Office of Director 15pp 18133-273 24X Fichs 50-327, 89/04/21, 8904220515
- 8305020345 Responds to 830325 ltr re TERA Corp GA & angineering plans for independent design & const varification program for facilities NRC comments on reporting requirements proposed by TERA Corp at 830413 meeting will be provided REHH. T Office of the Executive Director for Operations 83/04/22 ODRDES 8 Overnment Accountability Project 2pp 18284 238 24 Fiche 50-329,83/04/22.8305020365
- 8305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Tupical Rept CPC-1A. "GA Hanual for Hidland Nuclear Plant, Vol 1" HILLER.W O License Fee Management Branch 93/04/25 BYRD.W Consumers Power Co ip 18367 361 24X Fiche 50-329,83/04/25,8305090551
- 8305170131 Informs of review completion for listed activities re remedial soils work Concurrence requested MILLER, D.B. Consumers Power Co. 63/04/28 HARRISON, J. J. Region 3, Office of Director 2pp 18466 265 24X Fiche 50-329, 83/04/28, 8308170131
- B305170339 Forwards Vol 5 of "Seismic Margin Review Diesel Generator Bidg." COOK,J W Consumers Power Co 83/04/28 DENTON.H R. Diffice of Nuclear Reactor Regulation. Director 3pp 18469 036 24X Fiche 50-329,83/04/28,8305170539
- --8305170544 Vol 5 of "Seismic Margin Review Diesel Generator Bldg "
 MESLEY,D A , KENNEDY,R P , KINCAID,R H Structural Mechanics
 Associates SMA 13701 05R003 Vob 83/04/30 113pp 18469 040
 24X Fichs 50-329,83/04/28,8305170539
- 8305170422 Forwards change specs for "Pier Wii Load Recycling Procedure," for remedial soils work,per NRC-util work authorization procedure MILLER,D B Consumers Power Co B3/04/29 HARRISON,J J Region 3, Office of Director 2pp 18469 286 24X Fiche 30-329,83/04/29, 8305170422
- 8305060483 Documents 830413 telcon. Util commitment to provide hogging air ejector radiation monitors deleted from FSAR Chapter 11 5 Potential relaxation of tritium sampling requirement discussion deferred pending effluent Tech Spec review (CODK.) W Consumers Power Co 83/05/02 DENTON. H R. Office of Nuclear Reactor Regulation, Director 3pp 18345.360 24X Fichs 30-327.83/05/02.8305060483
- B305170467 Requests concurrence w/proposed changes to approved work activity to perform load test at Pier 11W MILLER, D.B. Consumers Power Co. 83/05/02 HARRISON, J. J. Region 3, Office of Director 2gp 18470-075 24X Fiche 50-329,83/05/02,8305170467
- 8305110140 Accepts TERA Corp as independent third-party to perform review of design & const verification program re Unit 2 auxiliary feedwater sys NDVAK.T M Assistant Director for Licensing 83/05/03 CODK.J W Consumers Power Co. 7pp 18421 351 24X Fiche 50-329.83/05/03.830510140
- 8305170397 Requests authorization for remedial soils work to install Bulkheads E10 & W10 & to install.load & excavate Piers BE. BW, 100 &

- 8305040323 Board Notification 83-037 forwards differing prof opinions re sys interaction & safety classification info relates to Board Notifications 83-17 & 63-44 re Unresolved Safety Issue A-17 EISENMUT.D 0 Division of Licensing 83/05/04 PALLADING.N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,830504023
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re-integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D. 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 59-000, 83/05/09, 8305090659
- 8303190063 Requests authorization to begin Remedial Soils Work Activities 407050400 shallow probing for Phase II & 202350104, SUPB-Install & terminate ceble HILLER, D B Consumers Power Co 83/05/09 HARRISON, J J Region 3, Office of Director ip 18502 067 24X Fichs 50-329, 83/05/09, 8303190065
- 8305200389 Confirms 830510 telcon authorizing minor soil excavation from buried pipes outside of valve pits
 MILLER, D.B. Consumers Power Co. 83/05/10 HARRISON, J.J. Region S
 Diffice of Director is 18518 174 24X Fiche 50-329.83/05/10,
 0201570099
- 8305170321 Forwards comments on review of TERA independent design const varification program from 830413 meeting Program scope omitted sys walk-down or turn-aver & program interfaces HARNICK, R F Region 3, Office of Director 83/05/11 NOVAK, T M Assistant Director for Licensing 3pp 18465 239 24X Fiche: 50-329, 83/05/11, 8305170321
- 8305190280 Forwards "Evaluation of Pressures in Lines of Grouting Equipment Crack Repair Borated Water Storage Tank Foundations." in response to unresolved item in 830118 ltr Hixing ratios for positive displacement pumps within specs HILLER, D.B. Consumers Power Co. 83/05/12 HARRISON, J.J. Region 3, Office of Director. 1p. 18501-148 24X Fiche 50-329, 83/05/12, 8305190280
- --8305190284 "Evaluation of Pressures in Lines of Grouting Equipment -Crack Repair Borated Mater Storage Tank Foundations,"
 MEISENHEIMER, J., WIELAND, R. H. Consumers Power Co. 63/05/05 8pp
 18501 149 24% Fichs 50-329,83/05/12,8305190280
- 8305240353 Documents 830512 discussion re remedial soils work authorization Three addl shallow holes on south side of dissel generator bldg constitute only minor change MILLER, D.B. Consumers Power Co. 83705763 HARRISON, J.J. Region 3, Office of Director ip 18573 361 24% Fishe 50-329, 83705713, 8305240353
- 8305240427 Requests work authorization for svc water pump structure underpinning program & replacement of svc water pipe Train A.

 MILLER, D.B. Consumers Power Co. 83/05/13 HARRISON, J. J. Region 3, Dffice of Director. 1p. 18571-057 24x Fichs 50-329, 83/05/13, 8305240427.
- B305310190 Bubmits list of acceptable activities for remadial soils work authorization
 HILLER, D B Consumers Power Co B3/05/13 HARRISON, J J Region 3, Office of Director. 1p 18651 001 24X Fiche 50-329, B3/05/13, B305310190
- 8305270057 Forwards Amend ii3 to application for CPs & DLs, consisting of Rev 48 to F5AR containing site emergency plan COOK, J. W Consumers Fower Co 83/05/16 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 18640 063 24X Fiche 30-329,83/05/16,8305270057
- --B305270063 Amend ii3 to application for CPs & OLs.consisting of Rev 48 to FBAR containing site emergency plan CODK.J W. Consumers Power Co B3/05/16 1p 18640 064 24X Fiche 50-329,83/05/16,8305270057
- B305200553 Forwards Rev 2 to angineering program plan & Rev 3 to project QA plan re independent design & const verification program LEVIN; M. TERA Corp. 83/05/18 EISENNUT. D. O. Division of Licensing. KEPPLER. J. Q. Region 3. Office of Director. CODX. J. W. Consumers Power Co. 4pp. 18514; 284 24% Fiche 50-329, 83/05/18, 8308200553
- --8305200567 Rev 2 to "Engineering Program Plan Project Instruction PI-3201-009 Midland Independent Design & Const Verification Program Project 3201" * TERA Corp. 83/05/18 158pp 18514 288 24X Fiche: 50-329,83/05/18,8305200553

- --8305200575 Rev 3 to "Project GA Plan for Midland Independent Design Const & Verification Program " LEVIN.H A , LEMON.C E , BECK.J H TERA Corp 83/05/02 264pp 18315 086 24X Fiche 50-327,83/05/18,8305200553
- 8303240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & Dis.consisting of Rev 48 to FSAR — site emergency plan BUDZIK.D M Consumers Pawer Co 83/05/19 DENTON.H R Office of Nuclear Reactor Regulation. Director Jpp 18548 331 24X Fiche 50-327.83/05/19.8303240137
- 8305240223 Forwards SB Baranow & J Chawla signed affidavits re potential conflict of interest in performing third-party const implementation overview AllD.P A Stone & Webster, Inc. 83/05/19 KEPPLER, J G Region J Office of Director 3pp 18548 012 24X Fiche 30-329,83/05/19, 820820323
- 8305310143 Confirms 830720 meeting w/J Kappler to discuss various suppliers quality activities undertaken by Bechtel in support of nuclear projects, per 830520 discussion SMITH,C F Bechtel Corp 83/05/20 WARNICK,R F Region 3, Office of Director ip 18658 073 24X Fiche 50-327,83/05/20,8305310143
- 8305270299 Enumerates new info matl & relevant to OM/OL proceeding at presented before ABLB on 830427 Licensoe identified & reported two cracks in svc water pump structure WARNICK-R F Region 3, Office of Director 83/03/24 EISENHUT.D 0 Division of Licensing 2pp 18641 356 24X Fiche 50-329,83/05/24,8305270299
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305020398 Forwards "B&W 177 Fuel Assembly Owners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup nozzles CDOK, J W Consumers Power Co 83/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18273 001 24X Fiche 50-329,83/04/13.8305020398
- 8303040334 Notification of 830511 meeting w/util & B&W in Bethesda.MD to discuss BER Open Item 7 & Confirmatory Item 7 re natural circulation & reactor vessel head veh HERNAM.R W Licensing Branch 4 83/04/27 ADENSAM.E © Licensing Branch 4 6pp 18326 335 24X Fiche 50-329,83/04/27,8305040336
- 8305110305 Supple explanation of 820921 commitment to implement expanded cooling pand dike surveillance program including visual insps of dike turf to resolve NRC concern re dike erosion & performance identified in May 1982 SER COUK, J. W. Consumers Power Co. 83/05/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp 18393 229 24X Fiche 50-329, 83/05/03, 8305110305
- 8305070574 Comments on Open Item 2 re turbine missiles in SER Sections 1.7 & 3.5 1.3 Probability of unacceptable damage to safety-related sys & components due to missiles acceptably low NOVAK:T M Assistant Director for Licensing 83/05/04 COOK:J W Consumers Power Co 3pp 18367 344 24X Fiche 50-327.83/05/04.
- F. Security, medical, emergency & fire protection plans
- 8305:10034 Generic Ltr 83-2; to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl EISENNUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18340-095 24X Fiche: 50-000.83/05/11.8305:10034
- 83052402i3 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983 DIRCKS,W J Office of the Executive Director for Operations 83/05/13, PALLADINO,N J Commissioners 5pp 18593 322 24X Fiche, 50-000, 83/05/13, 8305240213
- 8305270057 Forwards Amend 113 to application for CPs & CLs, consisting of Rev 48 to FSAR containing site emergency plan COOK.J W. Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X Ficha 30-327.83/05/16.8305270057
- --B305270066 Rev 48 to FBAR containing site emergency plan & Consumers Power Co B3/05/21 264pp IB640 067 24X Fiche 30-329, 83/05/16, 8305270057

@ Adjudicatory correspondence

- B305040444 Notice of appearance in proceeding Certificate of Svc encl PROVENZANO, V P Consumers Power Co B3/04/28 3pp 18322 128 24X Fichs 50-327, 83/04/28, 8305040441
- 8305040509 Renewed amended objections to interrogatories directed to util on ZACK issues & renewed motion for protective order Certificate of Svc encl Related correspondence PROVENZANO, V P Consumers Power Co 83/04/28 Sinclair, M 7pp 18321;045. 24X Fiche 50-329, 83/04/28,8305040509
- 9305040449 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
 BISHOP,L L Sinclair, M BISHOP,L L Harmon & Weiss 83/05/02
 Ip 18322 237 24X Fiche 50-329,83/05/02,8305040449
- 8305100341 Motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination at 830601 evidentiary hearings are reoponed GA matters Centificate of Svc encl BTEPTOE: P. Consumers Power Co STEPTOE: P. Isham, Lincoln & Beale 83/05/04 Atomic Safety and Licensing Board Panel 88pp 18378 233 24X Fiche 50-329.83/05/04.8305100341
- 8305100264 AdVises of syc of deposition subposes on deposents M Ciohi & 8 Marello Syc list and PROCTOR: 8 D Isham, Lincoln & Beale PROCTOR: 8 D Consumers Power Co 83/05/06 Atomic Safety and Licensing Board Panel 2pp 18372,276 24X Fichs 50-229,83/05/06:8305100264
- 0305100418 Forwards unsigned subposenss issued for L Clark, T Devine, B Cande & L Hallberg depositions, for signature Witnesses Intend to file motion to quash Svc list encl PROCIOR, B. D Isham, Lincoln & Beale 03/05/06 BECHHOSFER, C Atomic Sefety and Licensing Board Panel 10pp 18378 081 24X Fiche 50-329,83/05/06,8305100418
- 8305120273 Revised motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination Measures essential to time! y development of complete record M/Centificate of Syc MILLER, M I Consumers Power Ca MILLER, M J Isham, Lincoln & Deale 83/05/09 Atomic Safety and Licensing Board Panel, 48pp 18427 207 24X Fiche 50-329,83/05/09,8305120273
- 8305240373 Confirms telcon re continuation of deposition of L Clark & T Devine, scheduled for 830516 & 23, respectively B Carde deposition scheduled for 830606 may be continued provided reconvered GA hearings attended Related correspondence PROCTOR, B D Isham, Lincoln & Beale 83/05/13 MCCLAIN, W Karr & Lyans. ip 18574 015 24X Fiche 30-229/83/05/13,8305240373
- 8305190225 Forwards insp evaluation forms filed for IE Insp Repts 50-329/82-11 & 50-330/82-17, 50-329/82-17 & 50-330/82-17, 50-329/82-19 & 50-329/82-03 & 50-330/83-03 WILCOVE, M N Hearing Stanch 2 83/05/17 BERNABEI, L Qovernment Accountability Project, Bpp 18500 204 24X Fiche 50-329,83/05/17, 8305190225
- 8305190216 Motion for extension until 830524 to respond to util motion to limit cross-examination Counsel involved in 830519-24 hearing ABLB has adequate time to rule on motion before hearings resume Certificate of Svc anci BERNABELL Stampris: B DERNABELL Government Accountability Project 83/05/18 Atomic Safety and Licensing Board Panel App 18501:317 24X Fiche; 50-329,83/05/18,8305190216
- B305240322 Responds to B30510 ltr Areas of disagreement re documents still exist Conference call will be scheduled w/ABLB if ufil wishes to pursue matter BBUNNER.J E. Consumers Power to B3/05/18, B10Pp 18548 078 24X Fiche 50-329,83/05/18,8305240322
- 8305240491 Discusses schedule for appearances Deposition of 8 Marello will be rescheduled for June Deposition of C Grant scheduled for 830325. Proceedings will be instituted to enforce subposens served on M Cloni PROCTOR, 8, D. Isham, Lincoln & Beale PROCTOR, 8 D Consumers Power Co 83/05/19, BECHOEFER: C Atomic Bafety and Licensing Board Panel STUCKY, 8 H, Docketing & Services Branch 2pp 18571 269, 24X Fiche: 50-327, 83/05/19, 8305240491

- 8305240059 Proposes schedule for presenting testimony during 830601-10 hearings Proposal is joint proposal of util & NRC Rept on investigation of alleged violation of ABLB order will not be available by 830601-10 hearings MILCOVE.M N Hearing Branch 2 83/03/20 BECHHOEFER, C. COMAN.F P. HARBOUR.J Atomic 8afety and Litensing Board Panel 2pp 18547 133 24X Fiche 50-329,83/05/20,8305240059
- B305240065 Response to util B30509 revised motion revising B30504 motion re procedural limitations Commission does not favor singling out issue of discretionery referral of denied parts of motion during proceeding Certificate of Byc encl WRIGHT.N A Hearing Branch 2 B3/05/20 Atomic Bafety and Licensing Board Panel 7pp 18549 035 24X Fiche 50-329, 83/05/20, 8305240065
- 8305240472 Order granting Stamiris motion for extension until 830524 to respond to applicant revised motion to establish limits on cross-examination
 BECHHOLEFER.C Atomic Safety and Licensing Soard Panel 83/05/20
 Stamiris
- 8305250215 Telecopy response to util revised motion Extensive hearing record caused by conet of safety-related bldgs on faulty soil not by intervenor actions SINCLAIR, M. SINCLAIR, M. 83/05/23 Docketing & Services Branch 2pp 18592 354 24X Fichs 30-329.83/05/23.8305250215
- B305260169 Response to util revised motion to require submission of cross-examination plans designation of lead intervenors & time limits on cross-examination Util apparent lack of concern for public safety justifies cereful exam of issues SINCLATR.M Binclair, M B3/05/23 Atomic Safety and Licensing Board Panel 2pp 18599 284 24X Fichs 30-329,83/05/23,8305260169.
- B305270547 Forwards "Beismic Hargin Review," Vols I.V & VI W/D entl STEPTOE.P P Isham, Lincoln & Beale STEPTOE.P P Consumers Power Co. 83/05/23 BECHHOEFER:C. COWAN.F P. HARBOUR.J Atomic Safety and Licensing Board Panel 2pp 18646-127 24X Fiche 50-329.83/05/23.8305270547
- 8305260166 Response opposing util 830509 revised motion to require cross-examination plans, designation of lead intervenors & time limits on cross-examination Due process rights of full participation cannot be denied Certificate of BVc encl BERNABEI.L Stamiris, B BERNABEI.L Opvernment Accountability Project 83/05/24 Atomic Safety and Licensing Board Panel 12pp 18599 290 24X Fiche 50-329,83/05/24,8305260166
- 8305260276 Transmittal of documents on encl list of submittals responsive to B Stamiris 830407 document request Submittals designated publicly available, already submitted, privileged under atty-client privilege/proprietary
 WILCOVE.M N Hearing Branch 2 83/05/24 BERNABEI.L. Government Accountability Project. 2pp 18525 143 24X Fichs 50-329, 83/05/24, 83005260276
- B305270606 Order granting Stamiris 820524 discovery request for documents re implementation of quality improvement program in soils area & denying addi discovery requests re NRC/util Sapt 1982 meeting, containment cracks issue & audit repts BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/05/25, 8305270606

H General correspondence

- 8305040549 Responds to 830324 ltr requesting independent plant audit & more public meetings Three independent audits in progress or planned for site Soils compaction problem & technical & GA concerns being addressed by current hearings EISENHUT, D @ Division of Licensing 83/04/22 ROMO, K. \$ Affiliation Unknown is 18351 232 24X Fiche 50-327, 83/04/22, 8305040549
- 8305040550 Responds to 830323 Itr requesting independent audit & further public meetings. Three audits in progress or planned for site EISENHUT. D G. Division of Licensing. 83/04/22 HAVERCAMP.M. Affiliation Unknown Ip 18351 233 24X Fiche. 50-329, 83/04/22, 8305040550
- 8305170392 Responds to 830421 ltr re reinsp & independent audits at facilities On 830503, TERA Corp approved to perform independent review of design & const of auxiliary feedwaters says 854 will perform overview KEPPLER. J O Region 3, Office of Director 83/05/13, ROMO, L R Lone Tree Counsil 2pp 18471 202. 24X Fiche 50-329, 83/05/13, 8305170392

- --8305170376 Requests assurance of independent agent to perform facility audits, per RRC 833419 reinsp order ROMOLL R Lone Tree Counsil 83/04/21 KEPPLER, J Region 3, Office of Director 1p 18471 204 24X Fiche 90-329,83/05/13, 8305170392
- K Utzisty Final Safety Analysis Report (FSAR) & amends
- B305270057 Forwards Agend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan COOK, J W Consumers Power to B3/05/16 DENTON, H R Dffice of Nuclear Reactor Regulation, Director ip 18640 063 24X Fiche 30-327,83/05/16,8305270057
- --8305270056 Rev 48 to FSAR containing site energency plan * Conserver Rouer Co 83/05/31 264pp 18540 067 24x Fiche 50-329.83/05/16 8305270057
- 8305240137 Forwards Affidavit of Svc for Anend 113 to application for CPs & ULs consisting of Rev 49 to FEAR site emergency plan
 BUDZIK.D M Consumers Power Co 83/03/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 18548 331 24x
 Fichs 30-329.83/05/19.8305240137
- G Inspection reports. IE Bulletins & correspondence
- 8303190003 Final response to FOIA request for documents re Zack Co M/or work performed by Zack in const of facilities Forwards App A documents bocuments denoted u/esterisk available in POR App BLC, D & E documents withheld (ref FOIA Exemption 7) FELTON J H Division of Rules and Records 83/03/11 PRENDERGAST, R Prendergast, R J 17pp 18506 057 24X Fiche 30-000,83/03/11,8305190005
- --8305190045 Requests vehdor insp of facilities having contracts w/Zack Co due to OA/OC problems at Midland re HVAC activities Zack Co correspondence re LaSalie & related into encl FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/21 FOIDPOUS.U Region 4. Dallas, Vendor Inspection Branch 12pp 18506 077 24% Fiche 50-000,83/03/11,8305190005
- --8305190050 Summarites 820430 meeting w/president of Zark Co. HVAC contractor at facilities, repotential allegations Zack Co planning to terminate several employees in document control section HAYES. D W. Region 3. Diffice of Director 82/05/12 Region 3. Office of Director 82/05/12 Region 3. Office of Director 82/05/12 Region 3. Office of Director 1p 18305 089 24% Fiche 30-000.83/03/11.
- ~-B305190089 Repts ellegation re Zack Co falsified documents concerning MVAC activities at facilities per NBC Nightly News broadcast

 Redio TV Reports, Inc. 82/07/24 NBC ~ No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11, 83031490005
- --B305190102 Affidavit of SL Marello re GC breakdown & criminal falaification at Zack Co.HVAC contractor at facilities MARELLO.S L Affiliation Unknown B2/07/26 22pp 18506 139 24X Fiche 5G-000.63/03/11.8305190005
- ~~830519010B Affidavit of AT Howard rs GC breakdown & criminal falsification at Tack Co, HVAC contractor at facilities HOWARD, A T Affiliation Unknown 82/07/26 55pp 18506 160 24X Fiche 50-000.83/03/11.8305190005
- --8305190307 Discusses A Howard 820503 allegations re Zack Co tampering MyAC activities at facilities Further investigation will be implemented if deemed appropriate by mgt SHAFER. W D Region 3, Office of Director 82/05/11 WARNICK, R F Region 3, Office of Director 3pp 18507 334 24x Fiche 50-000,83/03/11,8305190005
- ~-8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re ellegations concerning Tack Co GA program at facilities Personally identifiable info deleted HORELIUS.C E Division of Engineering B2/07/12 Division of Engineering 19 18312 323 24K Fiche 30-000.83/03/11.

- 8212040385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212040385
- B30J040021 IE Info Notice B3-21, "Defective Emergency Use Respirator "
 Bvc list enel
 JURRANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures,"
 Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphers Benting Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche: 50-000,83/04/25,8303040025.
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Oenerators at PWRs " Svc list and]
 JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pg 18382 047 24X Ficher 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000.83/04/28,8303040027
- 8305110122 Forwards draft NRR BALP input for Jul 1981 Ner 1983; based on info solicited from listed personnel Comments received by 830905 will be considered in final rept MILLER, MA Licensing Branch A 83/05/02 MATTBON, R. Division of Systems Integration (post 81005) VOLLMER, R. Division of Engineering UDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 7pp 18421 318, 24X Fichs 50-329,83/05/02,8305110122
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Ralisf Valve Discharge Line Vacuum Breakers " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fichs. 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Apainst Plant Equipment "Svc list encl JORGANAE C. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04, Consolidated Edison Co. of New York, Inc. 112pp 18382 262 24X Fiche 30-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list and JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24x Fiche 50-000, 83/05/04, 8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edixon Co. of New York
- 8305190298 Forwards changes in MPOP-1. Rev 5 re GA anginearing. providing insp plan to GC & removing requirement for revisuing design documents NRC approval of activity requested MILLER.D B Consumers Power Co. 83/05/06 HARRISON, J J. Region 3, Office of Director ip 18501 083 24X Fichs 50-329:83/05/06.
- --8305190300 Braft quality plan for underpinning activities * Consumers Power Co MPGP-1 ROG DRFT 83/05/03 23pp. 18501 084 24X Fiche 50-327,83/05/06,8303190298.
- B303040034 IE Info Notice B3-30, "Misepplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc 1(4pp 18524 003 24X Fiche: 50-000, 83/05/11, B303040034

- 9305130171 Ack receipt of 930327 ltr informing NRC of staps taken to correct violations noted in IE lnsp Repts 50-329/83-01 & 50-330/83-01 WARNICK, R F. Region 3, Office of Director 93/05/11 COOK, J W Consumers Pawer Co ip 18438 104 24X Fiche 50-329,83/05/11,8305130171
- --B303130182 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01 Corrective actions valve, serial 27855.placed back in Becktel stock 8&W revising GC procedure for receiving & insp CODK.J W Consumers Power Co 83/03/29 KEPPLER.J O Region 3. Office of Director 6pp 18438 105 24X Fiche 50-329,83/05/11, 8305130171
- 8305200557 Advises that investigator file for IE Investigation Repts 50-329/82-13 & 50-330/82-13 reviewed, per ASLB order per intervenor request for discovery in QA hearings Proprietary & nonproprietary documents listed W/o stated ancis MARNICK-R. F. Region 3, Office of Director 83/05/17 PATON, W.D. NRC No Detailed Affiliation Oliven 3pp 18519 350 24X Fiche 50-329,83/05/17,8305200557
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JDRBAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp, 18697 009 24X Fiche 30-000, B3/05/19, B303040040
- B305240004 Ack receipt of B30504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-03 & 30-330/83-03 MARNICK.R F Region 3, Office of Director B3/05/20 CODK.J W Consumers Power Co ip 18549 039 24X Fiche 50-329,83/05/20,8303540004
- --B305240008 Responds to NRC B30407 ltr re violations noted in IE Insp Repts 50-329/83-03 & 50-330/83-03 Corrective actions MPGAD quality Action Request F-292 issued 830304 to revise Bechtel procedures for proper quality classification CDOX-J R Consumers Power Co B3/05/06 KEPPLER.J G Region 3. Office of Director lipp 18549 040 24X Fiche 50-329,83/05/20, 83067280004
- 8305260310 Ack receipt of 830310 ltr informing NRC of steps taken to correct violations noted in 830808 notice of violation & project disposition of civil penalties Revised response recreif & engineering personnel training requested KEPPLER.J O Region 3. Office of Director 83/05/23 CDOK.J W Consumers Power Co 2pp 18625.239 24X Fiche 50-329,83/05/23,8303260310
- 8305270076 Confirms 830624 SALP meeting in Midland, MI Meeting open to other interested parties
 WARNICK, R. F. Region 3. Office of Director 83/05/24 COOK, J W
 Consumers Power Co 1p 18638 301 24X Fichs 50-329, 83/05/24, 8305270076
- B303040046 IE Info Notice B3-33. "Nonrepresentative Sampling of Conteminated Oil " Svc list encl URDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- R Periodic operating reports & related correspondence
- 8305230270 "Active Mod Projects Operating PWR 1982 "
 # Consumers Power Co B2/12/31 4pp 18576.332 24X
 Fich* 50-000,82/12/31,8305230270
- 8305030111 Forwards Bechtel, B&W & util monthly nonconformance repts for Mar 1983, per 730323 Memorandum & Order ALAB-106 & Amend 1 to CPs CONK. J. W. Consumers Power Co. 83/04/25 DEVOLUGER C. Divertor's
- COOK: J.W. Consumers Power Co. 83/04/25 DEYDUNG, R.C. Director's Office: Office of Inspection and Enforcement 1,137pp. 18286 001 24% Fichs 50-329,83/04/25,8305030111
- 8305170373 Forwards "Work Activity List for May 1983," for remedial soil work per NRC-util work authorization procedure Authorization of specific work items requested HILLER, D.B. Consumers Power Co. 83/04/26 HARRISON, J.J. Region 3, 04/1ce of Director 25pp. 18466 031, 24X Fiche 50-327,83/04/26,8305170373
- 8305070052 Forwards addendum to "41st ALAB-106 Guarterly Rept, Apr-June 1983," consisting of resumes of recently hired employaes CDCK-J W Consumers Power Co 83/04/29 DEYOUNO, R C Director's Office, Office of Inspection and Enforcement ip 18364, 104, 24X Fiche: 50-329, 83/04/29, 8305090052

- --8305090060 Addendum to "41st ALAB-106 Guarterly Rept. Apr-June 1983 "

 * Consumers Power Co 83/04/29 82pp 18344 105 24X

 Fiche 50-329, 83/04/29, 8305090052
- B30531019B Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 1," covering period from project inception through B30527
 LEVIN, H A TERA Corp B3/05/27 KEPPLER, J 0 Region 3, Office of Director EISENHUT, D 0 Division of Licensing CDDK, J W Consumers Power Co 4pp 18659 047 24X Fichs 50-329, B3/05/27, B30531019B
- --8305310203 "Midland Independent Design & Const Verification Program Monthly Status Rept 1." covering period from project inception through 830527 TULODIESKI, D., LEVIN, H.A. TERA Corp. 83/05/27 62pp. 18657 050 24X Fiche 50-327, 83/05/27, 8305310198
- S Reportable occurrences, LERs & related correspondence
- 8305190005 Final response to FOIA request for documents re Zack Co %/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDEROAST, R Prendergask, R J 17pp 18506 059 24X Fiche 30~000,83/03/11,8305190005
- --8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated document & records mgt program will be developed & GA/GC personnel will be added Also reportable per Part 21 CALKINS.D E , EICHSTAEDT,C L , DEZUTEL.C Z Zack Co 81/10/23 310pp 18506 215 24X Fiche 50-000,83/03/11,8305190005
- 8305170283 Ninth interim deficiency rept re improper thrust forces used in high energy line break analysis pipe whip restraint design Initially reported on 800919 Design drawings for 83 restraints revised Next rept will be submitted by 640220 COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 9pp 18465 345 24X Fiche 50-329,83/05/06,8305170283
- 8305170391 Final deficiency rept re nonconforming Class IE radiation monitoring sys electronic modules mfg by Victoreen, Inc. due to breakdown of GA program Initially reported on 820917 Vendor revised GA program reviewed & approved CODK, J W Consumers Power CO 83/08/06 KEPPLER, J Q Region 3. Office af Director 9pp 18471 211 24X Fiche 50-329, 83/05/06. 8305170391
- 8305170409 Interim deficiency rept re accident temp effects on containment level measurement Instrument string error exceeds allowable steam generator ECGS control setpoints Bechtel & B&W refining existing calculations CODK, J.W. Consumers Power Co. 83/05/06 KEPPLER, J.G. Region 3, Office of Director 2pp 18469 248 24X Fiche 50-329,83/05/06.
- B305170440 Interim deficiency rept re installation of B&W nonselsmic transmitter mounting brackets forming part of RCPB Brackets will be replaced w/selsmically qualified mounting brackets prior to initial fuel load Next rept sysected by B30831 GOOK, J W Consumers Power Co B3/05/06 KEPPLER, J O Region 3, Office of Director 2pp 18467 301 24X Fiche 50-327,83/05/06,8305170440
- 8305170489 Final deficiency rept re underrated 460-volt motor control ctr control circuit transformers supplied by Govid-Brown Boveri Initially reported on 821013 Transformers to be replaced & installation supervised by Bechtel COOK, J W Consumers Power Co 83/05/06 KEPPLER, J Q Region 3, Office of Director 12pp 18470 055 24X Fiche 50-327,83/05/06,8303170489
- 8305200480 Interim deficiency rept re procured safety-related electrical equipment not meeting project requirements Initially reported on 821230 Task force established to review purchase orders Next rept expected by 830427 COOK.J W Consumers Power Co 83/05/13 KEPPLER.J G Region 3, Office of Director 11pp 18519 108 24X Fiche 50-329,83/05/13,8305200880
- B305200349 Interim deficiency rept re improper installation design of Class IE electrical control cabinet/panels Initially reported on B30211 Drawings will be revised Next rept will be submitted by 830819 Bechtel rept enc!
 COOK, J W Consumers Power Co 93/05/16 KEPPLER, J O Region 3, Office of Director 12pp 18516 235 24X Fichs 50-329, 83/05/16, 830520349.

- B305240010 Interim deficiency rept re G-related equipment couled by non-G HVAC sys Initially reported on B20625 Revs to Drawings 7220-M-560(G) will be made by B30630 Safety-grade HVAC added to listed areas Next rept by B30615 CODK.JW Consumers Power Co B3/05/17 KEPPLER.JO Region 3, Office of Director 10pp 18349 028 24X Fiche 50-329, B3/05/17, B305240010
- B305260309 Interim deficiency rept re core support structure bolting Initially reported on B30419 Evaluation of corrective action in progress Next rept will be sent by B3101 CODK.J W Consumers Power Co B3/05/19 KEPPLER,J G. Region 3, Office of Director 3pp 18625-200 24X Fiche 50-000, B3/05/19, B305260309
- --8305260311 Deficiency rept re ultrasonic test abnormal indications in upper barrel bolting of reactor internals initially reported on 830328 Results of internal bolt insp discussed AddI info will be forwarded TAYLOR.J H Babcock & Milcox Co 83/04/11 DEYDUNG, R C Director's Office. Office of Inspection and Enforcement 5pp. 18625 205 24% Fiche 50-000,83/05/19.8303260309
- --8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
 TAYLOR.J H Babcock & Wilcox Co 83/04/22 DEYOUNG.R.C
 Director's Opfice, Office of Inspection and Enforcement Spp
 18625 210 24X Fiche.50-000.83/05/19.8305260309
- 8303260218 Interim deficiency rept re design of embedments in concrete W/shear lugs located in tension zones. Interim embedment design criterion being developed for use prior to testing completion Next rept expected by 831122 COOK, J W Consumers Power Co 83/05/20 KEPPLER, J O Region 3. Office of Director 5pp 18599 317 24X Fiche 50-329,83/03/20. 8303260218
- B305240235 Final deficiency rept re possible frazil ice formation in svc water intake structure Recirculation of svc water discharge flow near trash rack evaluated as best option to control ice at intake structure COOK, J W Consumers Power Co B3/05/20 KEPPLER, J G Region 3, OFfice of Director 7pp 18599 340 24X Fiche 30-329,83/05/20,8305260255.
- 8305260324 Final deficiency rept re auxiliary feedwater (AFH) suction piping design initially reported on 821214 Design change issued to install pressure relief valve on Pour AFH pump suction lines between pump & first isolation valve COOK.J W. Consumers Power Co. 83/05/20. KEPPLER.J 9 Region 3. Office of Director. App. 18625-166. 24X Fiche 50-329.83/05/20. 8305260324
- T Hearing transcripts on non-antitrust matters
- 8305100243 Forwards NRC testimony addressing Sinclair Contention 13 re assessment of severe accidents to be presented at 830328 hearing Testimony addressing Binclair Contention 4 re steam generator tube integrity filed on 830131 MRIGHT.N A Diffice of the General Counsel 83/03/18 BECHHOUSERR, C. COMAN.F P. HARBOUR, J. Atomic Sefety and Licensing Board Penel 1p 18373.337 24X Fiche 50-329,83/03/18,8305100243
- --8305100245 Testimony of F Rousome re Binclair Contention 13 on assessment of severe accidents ROMSOME, F Assistant Director for Technology Review 83/03/18 13pp 18373 338 24X Fiche 50-327.83/03/18,8305100243.
- --8305100248 Testimony of LO Hulman & JA Mitchell re Sinclair Contention 13 HULMAN, L G , MITCHELL, J A Accident Evaluation Branch 83/03/18 20pp. 18373 351 24X Fiche: 30-329,83/03/18,8305100243
- 8305100124 Supplemental testimony of JG Keppler re GA KEPPLER.J G Region 3, Office of Director 83/03/25 App. 18375 197 24% Fiche 50-000.83/03/25.8305100124.
- B303100147 Forwards supplemental testimonies of JG Keppler, RJ Cook, RN Gardner, RB Lendsmen, ND Ghafer & JW Gilray re QA W/o encis, WILCOVE, N N Office of the Executive Legal Director B3/03/25 BECHHOEFFER, C . COMAN, F r . WARBOUR, J . Atomic Bafety and Licensing Board Panel 2pp 18374 217 24X Ficher 50-329, 83/03/25, 8305100147
- B305100217 Supplemental testimony of RJ Cook.RN Gardner.RB Landsman & WD Shafer re GA WD Shafer re GA COGK.R J. GARDNER.R N., LANDSMAN.R.B Region 9. Office of Director B3/03/25 App 18374.141. 24X Fiche 50-329.83/03/25.8305100217

- 8305100261 Supplemental testimony of JW Gilray.RB Landsman & WD Shafer re GA program for underpinning activities of svc water pump structure & auxiliary bldg Supporting documentation and GILRAY.J W GA Branch LANDSMAN.R B . SHAFER.W D Region 3, Office of Director 83/03/25 38pp 18372 258 24X Fiche 50-329, 83/03/25.8305100261
- 8305030457 Transcript of B30427 hearing in Midland, MI Pp 14, 272-14, 493 Supporting documentation encl, + Atomic Safety and Licensing Board Panel 83/04/27 265pp. 18294 184 24X Fiche 50-329, 83/04/27, 8305030457
- 8305040191 Transcript of 830428 hearing in Midland, MI, Pp 14, 495-14, 750

 * Atomic Sefety and Licensing Board Panel 83/04/28 260pp 18324 037 24% Fiche 50-329, 83/04/28, 8305040191
- 8305050028 Transcript of 830429 hearing in Midland.MI Pp 14.751-14.977 * Atomic Safety and Licensing Board Panel 83/04/29 229pp 18342 242 245 Fiche 50-329.83/04/29.830505028
- 8305050011 Transcript of 830430 hearing in Midland.MI Pp 14.978-15.096 * Atomic Safety and Licensing Board Panel. 83/04/30 122pp 18338 155 24% Fiche 50-329.83/04/30,8305050011
- B305060197 Transcript of B30502 hearing in Midland.MI Pp 15.097~15.393 Supporting documentation and + Atomic Safety and Licensing Board Panel. 83/05/02 616pp 18345 001 24% Fichs 50-329.83/05/02.8305060199.
- B305160033 Transcript of B30503 evidentiary hearing in Midland.MI Pp 15:394-15:692, a Atomic Bafety and Licensing Board Panel B3/05/03. 300pp, 18455-116 24X Fiche 50-329.B3/05/03.B305160033
- 8305110006 Transcript of 830504 evidentiary hearing in Midland, MI. Pp 15,693-15,922
 * Atomic Safety and Licensing Board Panel 83/05/04 232pp 18407 026. 24% Fiche: 50-527,83/05/04,8305110006
- 8305110092 Transcript of 830505 evidentiary hearing in Midlanf, MI Pp 15, 923-14, 219

 ** Atomic Safety and Licensing Board Panel 83/05/05 902pp 18410 007. 24X Fiche 50-329, 93/05/05, 8305110092
- B305110001 Transcript of B30506 evidentiary hearing in Midland MI Pp 16,220-16,366 * Atomic Bafety and Licensing Board Panel. B3/05/06. 150pp 18409 130 24% Fiche 50-329,83/05/06,8305110001
- 8305310163 Transcript of 830510 proceedings in Chicago, IL F 2. Subposma directed to M Cioni ancl * Commissioners 83/05/10, 6pp 18652 339, 24X Fiche 50-329, 83/05/10, 8305310163
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- Security, medical, emergency & fire protection plans
- B305090186 Forwards exemption from requirements of Section III G of App R to 10CFR50 per B20622 request re reactor bldg torus area & lower suitchgear room Remaining areas for which exemptions requested will be addressed in future action VASBALLO.D B Operating Reactors Branch 2 B3/04/26 ARNOLD.A lows Electric Light & Power Co. 2pp 18367 256. 24X Fiche 50-331,83/04/26,8303090186
- ---8305090197 Exemption from requirements of Section III G of App R. 10CFR5D re reactor bldg torus area, north & south control rod drive module areas, reactor bldg RHR valve rooms, control, lower switchgear, battery & essential switchgear rooms EISENHUT.D O Division of Licensing. 83/04/26 Iqua Electric Light & Power Co 8pp 18367-258, 24X Fiche 50-331:83/04/26-830590186
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENNUT, D. 0 Division of Licensing, 83/05/ii. Consolidated Edison Co of New York, Inc 16pp. 18540.095 24X
 Fiche: 50-000,83/05/ii,8305110034
- B305200172 Notifies of refund of Class II license amend fee re 800617 amend application Changes, per 10CFR50 54(p), do not decrease effectiveness of plan & do not require NRR approval MILLER.W O License Fee Management Branch 83/05/12 ARNOLD.D. Iawa Electric Light & Power Co. 1p 18540 234. 24X Fiche 50-331.83/05/12,8305200172

- 8305310176 Forwards IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted PAPERIELLO.C.J Region 3, Office of Director 83/05/16 LIU.L lows Electric Light & Power Co Epp 18659 118 24X Fiche 50-331,83/05/16,8305310176
- ---8305310181 IE Insp Rept 50-331/83-08 on B30411-15 No noncompliance noted Major areas inspected actions taken in response to B10722 confirmatory action ltr & emergency preparedness appraisal improvement & training PATTERSON, J. P., SNELL, W. G., AXELSON, W. L., Region 3, Office of Director B3/05/12 15pp 18659 120 24X Fiche 50-331,83/05/16,8305310176.
- 8305240564 Informs that NUREO-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50, " completed Item closed.

 VA88ALLO.D B Operating Reactors Branch 2 83/05/18 LIU.L Iowa Electric Light & Power Co 3pp 18593 348 24X

 Fithe 50-331.83/05/18.8305240564

P. Operating license stage documents & correspondence

- 8305040095 Forwards Amend 87 to License DPR-49 & notice of issuance & availability Amend incorporates revs to tables of safety-related snubbers to satisfy requirements of Mark I containment long-term 780228 order for mod WA88ALLD, D. B. Operating Reactors Branch 2 83/04/18 ARNOLD, D Iowa Electric Light & Power Co. 3pp 18328 173 24% Fiche 30-331,83/04/18,8305040095.
- --8305040108 Amend 87 to License DPR-49, incorporating revs to tables of safety-related soubsers to satisfy requirements of Mark I containment long-term 780228 order for mod of license VASSALLO.D B Operating Reactors Branch 2 83/04/18 9pp 18328 176 24X Fiche 50-331,83/04/18,8305040095
- --8305040115 Notice of issuance & availability of Amend 87 to License DPR-47
 VASSALLO,D B Operating Reactors Branch 2 83/04/18 2pp 18320 185. 24X Fiche 50-331.83/04/18.8305040095
- 8305160331 Responds to 830216 request for Tech Spec interpretation re component operability when diesel generator inoperable, stating NRR position EISENHUT, D. Q. Division of Licensing 89/04/20 NORELIUS, C E Division of Project & Resident Programs 2pp. 18472 049 24X Fiche. 50-331, 89/04/20, 8305160331
- 83031i0549 Forwards Amend 88 to License DPR-49, sefety evaluation & notice of issuance & evailability Amend revises Tech Specs to incorporate limiting conditions for operation during Fuel Cycle 7.

 APICELLA:F.L. Operating Reactors Branch 2 83/04/25 ARNOLD, D lowa Electric Light & Power Co 2pp 18415,073 24X Fiche: 50-331,83/04/25,8305110349
- --B305110536 Amend 8B to License DPR-49, revising Tech Space to incorporate limiting conditions for operation during Fuel Cycle 7. VASBALLO, D. B. Operating Reactors Branch 2 83/04/25. 20pp 18415.075 24X Fiche 50-331,83/04/25,8305110549
- --8305110560 Befety evaluation supporting Amend 8B to License DPR-49
 * Office of Nuclear Reactor Regulation, Director. 83/04/25 7p
 18415:095. 24X Fiche:50-331,83/04/25,8305110549
- --B305110566 Notice of issuance & availability of Amend 88 to License DPR-47.
 VABSALLO, D. B. Operating Reactors Branch 2 83/04/25 2pp 18415 IOR. 24X Fichs. 50-331, 83/04/25, 8305110549.
- 8305180801 Forwards request for add1 info re structural aspects of Mark I containment long-term program plant-unique analysis rapt Response requested within 45 days of receipt of ltr VABBALLO,D.B. Operating Reactors Branch 2 83/04/28 LIU.L Iowa Electric Light & Power Co 4pp 18505 346 24% Fiche.50-331,83/04/28,8305180801.
- 8305110100 Forwards Amend 87 to License DPR-49, safety evaluation & notice of issuance & availability. Amend revises Group I containment isolation signal, pressure setpoint & low-low set logic
 APICELLA: F. L. Operating Reactors Branch 2, 83/04/27 LIU, L Iowa Electric Light & Power Co. 2pp 18434:315 24X
 Fiche: 50-331, 83/04/29, 8305110100.
- --B305110234 Amend 89 to License DPR-49, revising Group I containment isolation signal, pressure setpoint from 880 psig to 850 psig a low-low set logic VABSALCO, D. B. Operating Reactors Branch 2, 83/04/29 10pp. 18434:317, 24X Fiche: 50-331, 83/04/29, 8305110100

- --8305110242 Safety evaluation supporting Amend 89 to License DPR-49 * Office of Nuclear Reactor Regulation, Director 83/04/29 5pp 18434 327 24X Fichs 50-331,83/04/29,8305110100
- --8005110243 Notice of issuance & availability of Amend 89 to License DPR-49 VABBALLO.D B Operating Reactors Branch 2 83/04/29 2pp 18434 332 24x Fiche 50-331,83/04/29,8305110100
- 8305100095 Informs of intended reporting mechanism for containment leak rate testing from Cycle 7 refueling outage.per 10CFR50, App J & Tech Spec App A LER reporting requirements do not apply Test results will be submitted in early Jul 1983 ROOT.L D lows Electric Light & Power Co 83/05/02 XEPPLER.J 9 Region 3. Office of Director 2pp 18377 216 24X Fiche 50-331,83/05/02,8305100095
- B305110037 Forwards Amend 91 to License DPR-49, safety evaluation & notice of insuance & availability Amend modifies plan for integrated scheduling of mods
 EISENHUT. D @ Division of Licensing B3/05/03 LIU.L lowa
 Electric Light & Power Co 3pp 18420 340 24X
 Fiche 30-331.83/05/03, B305110037
- --8305110037 Amend 91 to License DPR-49, revising plan for integrated scheduling of mods VASSALLO.D B Operating Reactors Branch 2 83/05/03 2pp 18420 343 24X Fiche 50-331,83/05/03,8305110037
- --8305110043 Safety evaluation supporting Amend 91 to License DPR-49
 * Office of Nuclear Reactor Regulation, Director 83/05/03
 15pp 18420 345 24X Fiche 50-331,83/05/03,8305110037
- --B305110045 Notice of issuance & availability of Amend 91 to License DPR-49
 RODNEY, V L Operating Reactors Branch 2 83/05/03 2pp 18420 360 24X Ficher 50-331, 83/05/03, 8305110037
- 8305180081 Forwards Amend 70 to License DPR-47 & notice of issuance & availability Amend deletes requirements for shift technical advisor to be on duty during refueling per TMI Action Item I A 1 I VABBALLO, D D Operating Reactors Branch 2 83/05/03 ARNOLD, D Iowa Electric Light & Power Co 3pp 18503 270 24X Fiche 50-331:83/05/03,8305180081
- --8305180091 Amend 90 to License DPR-49, deleting requirement for shift technical advisor to be on duty during refueling per TMI Action Item I A 1 1 VA89ALLO,D B Operating Reactors Branch 2 83/05/03 4pp 18503 279 24X Fiche. 30-331,83/05/03.8305180081
- --8305180093 Notice of issuance & availability of Amend 90 to License DPR-49 RBONEV, V L Operating Reactors Branch 2 83/05/03 2pp 18503 277 24X Fiche. 50-331. 83/05/03. 8305180081
- B305060060 Application to amend License DPR-49, revising App A Tech Specs re max critical power ratio operating limits for 9x8 & 8x8R/P9x8R fuel types to allow implementation of turbins control valve mod RODT.L D Iowa Electric Light & Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18345 052 24X Fichs 950-331, 83/05/04, 8305060060
- --8305060066 Proposed App A Tech Specs revising max critical power ratio operating limits for 8x8 & 8x8F/P8x8F fuel types to allow implementation of turbine control valve mod * Iowa Electric Light & Power Co 83/05/04 2pp 18345 053 24X Fiche 50-331,83/05/04.830506060
- --8305060076 Rev 1 to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr.Reload 6" WAONER.R L , ZARBIB.W A , CHARNLEY.J S General Electric Co Y10030101A6 RO1 83703/31 20pp 18345 055 24X Ficha 50-331.83/05/04.8305060060
- 8305180752 Provides clarification of SER re environ qualification of safety-related electrical equipment. All justifications for continued operation should be revised to ensure that all unqualified equipment covered Proprietary guidelines encl VASBALLO.D. B. Operating Reactors Branch 2 83/05/04 LIU.L Ioua Electric Light & Power Co. 5pp. 18506-048 24X Fiche. 50-331.83/05/04.8305180752
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D. © Division of Licensing 83/05/09. Consolidated Edison Co of New York Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659

- 8305170717 Advises that action required by 830207 Amend 81 to License DRR-47 & Generic Ltr 83-07 complete based on util negotiating w/DDE re disposal of high level waste or spent nuclear fuel VASBALLO.D B Operating Reactors Branch 2 83/05/07 LiU.L Iowa Electric Light & Power Co 2pp 18496 196 24X Fiche 50-331,83/05/09,8305170719
- B305260167 Forwards request for add1 info re NUREG-0737. Item II K 3 2B on qualification of automatic depressurization system communitors Response uithin 45 days requested VASSALLO, D B Operating Reactors Branch 2 B3/05/11 LIU,L Iowa Electric Light & Power Co 3pp 18648 117 24x Fichs 50-331.63/05/11, B305260167
- 8305230562 Informs that results of plant-unique calculations forming bases for mods to vacuum breakers will be submitted by 830731; in response to Generic Ltr 83-88 Required mods will be completed during Fall 1984 outage ROBT.L D Towa Electric Light & Power Co 83/05/16 DENTON:H R Office of Nuclear Reactor Regulation. Director 19 18537.330 24: Fiche 50-331.83/05/16.8305R305A2
- 8305240192 Forwards safety evaluation to BWR Dwhers Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization 8ys" Action complete VASSALLO,D B Operating Reactors Branch 2 83/05/18 LIU,L Iowa Electric Light & Power Co 2pp 18448 089 24X Fiche 50-331,83/05/18,8305240192
- G305240120 Forwards methodology used to address nonsafety-related equipment failures (IE Bulletin 79-01B), summary of environ qualification Action Items 40 & 41 & response for Category IV Items, per 10CFR50 49 & 830504 request ROOTL D Town Electric Light & Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 18548 349 24% Fiche 50-331,83/05/20,8305240120.
- G Inspection reports. IE Guiletins & correspondence
- B305040387 Advises that revised procedures covering adequate method to determine max permissible concentration—h from whole body counting data.per IE Insp Rept 30-331/B2~06 will be delayed due to errors discovered in computer library ROOTAL D Towa Electric Light & Power Co B2/06/30 KEPPLER, J Q Region 3. Office of Director 2pp 18323 205 24X Fiche 50-335.82/06/30.8305040389
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list and! FAYLOR, J M Division of Safeguards & Inspection Programs (Fost 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8303040021 IE Info Natice 83-21. "Defective Emergency Use Respirator "
 Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fishe 50-000.83/04/15,8303040021
- 8305020358 Forwards 1E Insp Rept 50-331/83-04 on 830216-17 & 0316-18 No nancompliance noted LITTLE.W S Region 3. Office of Director 83/04/18 ARNOLD.D fowa Electric Light & Power Co 2op 18274 046 24X Fiche 50-331.83/04/18.8305020358
- --8305020360 IE Insp Rept 50-331/83-04 on 830216-19 & 0316-18 No noncompliance noted Major areas inspected inservice insp program & procedures insp documentation & rectrculation systetathed piping followup per IE Bulletin 82-03 KEY.W J. DANIELBON.D H. Region 3, Office of Director 83/04/18 10pp 18274 048 24% Fiche 50-331.83/04/18.8305020358
- 8305100215 Forwards IE Insp Rept 50-331/83-01 on 830103-0225 & notice of violation SHAFER.W D. Region 3. Office of Director 83/04/18 ARNOLD.D Iowa Electric Light & Power Co 2pp 18374 047 24X Fiche 50-331,83/04/18.8305100215
- --8309100216 Notice of violation from insp on 830103-0225 SHAFER.W D Region 3. Office of Director 83/04/18 2pp 18374 049 24X Fichs 50-331.83/04/18.8305100215
- --B305100218 IE Insp Rept 50-331/83-01 on 830103-0225 Nancompliance noted failure to develop & adhere to detailed vessel head insulation removal procedures & to control measuring & testing equipment CLARDV.L S , JORDAN.M J . WALKER.R D Region 3. Office of Director 83/04/18 Spp 18374-051 24X Fiche 50-331/83/04/18, 8305100215

- 8305030317 Forwards finalized rept re followup insp at facility during wk of 830410 Areas included post-accident sampling, high-range containment monitors, high-range effluent monitors, training, dose assessment & in-plant survey pracedures 8TOETZEL-0 A Battelle Memorial Institute, Pacific Northwest Laboratory 83/04/21 PATTERSUNJ P Region 3, Office of Director 18pp 19297 051 24X Fiche 50-331,83/04/21,8305030317
- 8303040023 IE Info Notice 93-22, "BWR Safety/Relief Valve Failures "
 Svt list entl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "inoperable Containment Atmosphere Sensing Sys " Syc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche.50-000,83/04/25,8303040025
- B305030131 Forwards add1 response to IE Bullstin 82-03, Rev 1 re intergranular stress corrosion cracking Response suppls B21201 itr Cycle 7 refueling outage exams revealed no indication of cracking R001.L D lows Electric Light & Power Co 83/04/25 KEPPLER, J. 9 Region J. Office of Director 9pp 18300 180 24X Fiche 50-331,83/04/25,8305030131
- B305100320 Responds to NRC itr re violations noted in IE Insp Rept 50-331/83-02 Corrective actions.licensing personnel involved in development of Tech Bpec changes cautioned re necessity for care & accuracy RDOT.L D Towa Electric Light & Power Co 83/04/25 DEYOUNG.R C Director's Defice, Opfice of Inspection and Enforcement 3pp. 18370 094 24% Fichs 30-331.83/04/25.8305100320
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Bvc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice B3-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl VORDANCE L Division of Emergency Preparedness & Engineering Response (Post B330103) B3/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Ficher 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl Directed Against Plant Equipment "Svc list encl Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/03/04,830304003D
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24x Fiche 50-000,83/05/04.8303040031.
- 8305100364 Act receipt of 830425 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-331/83-02
 STREETER, JF Region 3, Defice of Director 83/05/04 LIU.L lowe Electric Light & Power Co ip 18379 088 24X
 Fiche 50-331:83/05/04,8305100364
- ~-8305100372 Responds to NRC 830324 ltr re violation noted in IE Imap Rept 50-331/83-02 Corrective actions personnel cautioned re necessity for accuracy in development of Tech Spec changes ROOT, L D lows Electric Light & Power Co 83/04/25 DEYOUNG. R. Director's Office, Office of Inapaction and Enforcement 3pp 18379 089 24X Fiche 50-331.83/05/04/83005100364
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24% Fiche 50-000,83/05/06,8303040033.
- 8305190251 Forwards IE Insp Rept 50-331/83-06 on 830328-31 No nancompliance noted STREETER, JF. Region 3, Office of Director, 83/05/06, LIU, L Iowa Electric Light & Power Co 2pp 18501;293, 24X Fiche 30-331,83/05/06,8305190251

- --8305190256 IE Insp Rept 50-331/83-06 on 830328-31 No noncompliance noted Major areas inspected general & nonlicensed training & licensed operator requalification training SUTPHINR N, HAWKINS,F C Region 3, Office of Director 83/05/05 6pp 18501 295 24X Fiche 50-331.83/05/06.8305190251
- 8305240511 Documents results of visual insp of core spray sparger during 1983 refueling outage per IE Bulletin BO-13 Insp conducted Wremote actuated TV camera Equipment resolution capability verified using one mil wire ROOT, L D Towa Electric Light & Power Co 83/05/07 KEPPLER, J O Region 3, Office of Director ip 18571 273 24X Fiche 30-231 83/05/07, 8305240511
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11,8303040034
- B305310176 Forwards IE Insp Rapt 50-331/83-08 on B30411-15 No noncompliance noted PAPERIELLD,C J Region 3. Office of Director B3/05/16 LIU,L laws Electric Light & Power Co 2pp 18659 118 24X Fichs.50-331/83/05/16/8305310176
- --8305310181 IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted, Major areas inspected actions taken in response to 810922 confirmatory action ltr & emergency preparedness appraisel improvement & training PATIERSON, J P. SNELL, W G. AXELSON, W L. Region 3, Uffice of Director 83/05/12 15pp 18659 120 24X Fiche 50-331, 83/05/16, 8305310176
- 8305240284 Forwards IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 83/05/18 LIU.L lows Electric Light & Power Co 2pp 18548 088 24X Fiche.50-331.83/05/18.8305240284
- --B305240272 IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted. Major areas inspected radiation protection program for operation & refueling including organization & staffing, staff qualifications, training & outage planning HUETER.L J., PAUL.R A , OREGER.L R Region 3, Office of Director B3/05/17 17pp. 18548.090 24X Fiche 50-331.83/05/18.8305240284
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl.
 JORDANIE L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697'009 24X Fiche 50-000,83/05/19.8303040040
- 8305240120 Forwards methodology used to address nonsafety-related equipment failures (IE Bulletin 79-01B), summary of environ qualification Action Items 40 & 41 & response for Category IV items, per 10CFR50 49 & 830504 request RDDT.L D. Iowa Electric Light & Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 19pp 18548 349 24X Fiche 50-331,83/05/20,8305240120
- 8305260315 Confirms 830621 meeting between MJ Jordan & L Root in Cedar Rapids. IA re EALP Discussion to update regulatory improvement program will be held following meeting Outside observers must notify of attendance by 830617 NORELIUG.C E. Division of Project & Resident Programs. 83/05/23 LTU.L Iowa Electric Light & Power Co Ip 18626 006 24X Fiche 50-331,8305723,8305260315
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647.007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305180346 Forwards monthly operating rept for Apr 1983
 MINECK, D.L. Imma Electric Light & Power Co 83/05/13 Director's
 Office, Office of Inspection and Enforcement 1p 18485 282 24X
 Fiche 50-331,83/05/13,8305180346.
- ~-8305180347 Honthly operating rept for Apr 1783 MILLER,W Iowa Electric Light & Power Co 83/05/13 8p; 18485 283 24X Fiche: 50-331,83/05/13,8305180346

- S Reportable occurrences, LERs & related correspondence
- 8303230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping " BROWN,E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000
- --8305230419 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leeks associated w/vnanticipated vibration problems require addl supports or rerouting of piping BROWN, E J Reactor Operations Analysis Branch B3/04/19 9pp 18341 343 24X Fiche 50-000, 83/04/19, 8305230573
- 8305030394 Forwards LER 83-008/03L-0 MINECKID L Iowa Electric Light & Power Co 83/04/25 KEPPLER, J & Region 3. Office of Director 1p 18306 236 24X Fiche 50-331.83/04/25.8305030394
- ---8308030396 LER 83-008/03L-0 on 830326, eight accessible hydraulic snubbers visually inspected & deficiencies noted Surveillance Procedure STP 46H002 revised to address mechanical aspects in addition to hydraulic mechanism REIMERS.0 A I lowa Electric Light & Power Co 83/04/25 Region 3, Office of Director 3pp 18306 237 24X Fiche 50-331, 83/04/25.8303030394
- 8305060472 RO while in cold shutdown.w/ail rods inserted, reactor mode moved from refuel position to shutdown position & A logic did not trip Caused by fallure of A sys shutdown scram reset interlock Unit maintained in cold shutdown MINECK.D L lows Electric Light & Power Co 83/04/26 KEPPLER.J Q Region 3. Office of Director 1p 18351 174 24X Fiche 50-331,83/04/26,8305060472
- 830502051i PND-III-B3-032 on 830426, scram circuitry failed to operate properly when mode switch moved from refuol position to shutdown position Caused by three loose wires in rectifier bridge
 JORDAN, M. SHAFER, W. Region 3, Office of Director 83/04/27 ip 18281 259 24X Fiche 50-331,83/04/27,8305020511
- 8305040445 PND-III-83-033 on 830428, contract health physics technician observed w/small vial containing white powdery substance Preliminary test identified substance as cocaine Individual denied access to site CHRISTOFFER,0, CREED,J, MILLER,J, Region 3, Office of Director 83/04/27, 1p 18321 297 24X Fichs 50-331,83/04/29,8305040445
- 8305130094 RO on 930212, during Type C local leak rate testing, two MBIVs exceeded Tech Specs Valves repaired MINECK.D L. Iowa Electric Light & Power Go 83/05/06 KEPPLER.J Q Region 3. Office of Director 1p 18437 201 24X Fiche 50-331.83/09/06.8305130094.
- 8305240221 LER 83-012/01T-0 on 830425, full scram should have been received when mode switch moved from refuel to shotdown, however, sys A did not trip Caused by faulty solder connection on rectifier Connections resoldered W/830510 ltr KIBLER, D R. MINECK, D L. Iowa Electric Light & Power Co. 83/05/10 KEPPLER, J O Region 3, Office of Director. 4pp. 18375 262 24X Ficha 50-331,83/05/10,8305240221
- 8305240236 LER 83-010/03L-0 on 830411.during refueling outage, one snubber found inoperable, one indeterminant; one had missing bushing & one w/bushing disengaged Caused by procedure error during previous maint W/830511 ltr
 REIMERS 0 A . MINECK, D L Towa Electric Light & Power Co 83/05/10 KEPPLER, J Q Region 3, Office of Director App 18548 322 24% Fiche 50-331,83/05/10,8305240236
- 8305270440 Forwards updated LERs 81-015/01T-1 & 81-016/01T-1 MINECK.D L. Iowa Electric Light & Pawer Co 83/05/16 KEPPLER, J G Region 3, Office of Director 1p 18642 239 24X Fiche 50-331/83/05/16,8303270440
- --8305270451 Updated LER 81-015/01T-1 on 810421, lower crankshaft 14 bearing found wiped on journal surface similar to problem identified on diesel 10-31 Caused by high temp Bearing replaced & crankshaft reiapped DONNELLY,P M I fow Electric Light & Power Co 83/05/16 Region 3. Office of Director 4pp 18642 253 24X Fiche 50-331, 83/05/16, 8305270440
- --B305270460 Updated LER 81-016/01T-1 on 910421.lower crankshaft thrust bearing 13 & adjacent bearing 12 found wiped on journal surface. Caused by high temp Crankshaft thrust bearings replaced & crankshaft relapped DONNELLY.P M Iowa Electric Light & Power Co 83/05/16 Region 3. Office of Director 3pp 18642 296 24X Fiche 50-331, 83/05/16,8305270440

8305270429 LER 83-013/017-0 on 830215, two MSIVs exceeded Tech Spec acceptance criteria Caused by wear on valve seats Valve seats reworked Reportability of event as LER established on 830505 W/830520 ltr
KIBLER, D.R., MINECK, D.L. lows Electric Light & Power Co. 83/05/20 KEPPLER, J.G. Region 3, Office an Director. 2pp. 18642 287—24X Fiche 50-331,83/05/20,8305270429

DOCKET 50-332 BARNHELL REPROCESSING PLANT

- O Inspection reports, IE Bulletins & correspondence
- 830527028B Forwards IE Insp Rept 50-332/83-01 on 830301-04 No noncompliance noted 8TOHR.J P Division of Emergency Preparedness & Materials Safety 83/03/23 BUCKHAM.J A Allied General Nuclear Services 2pp 18442 042 24X Fichs 50-332.83/03/23.8305270288
- --8305270304 IE Insp Rept 50-332/83-01 on 630301-04 No noncompliance noted Major areas inspected preoperational tests, organization safety committees, internal review & independent effort CORYELL.6 P Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/03/22, 4pp 18442 044. 24X Fiche 50-332,83/03/23.8305270288
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 830506054B Notifies that submittals re proposed alternate safe shutfown capability mods & remptions to meet Sections III 0 3,III 0 & III to 100FR50 App R. acceptable vASSALLG.D.B Operating Reactors Branch 2 83/04/26 BAYNE,J P Power Authority of the State of New York, 3pp 18359 213 24x Fiche.50-333,83/04/26,830506054B
- --8305060553 Exemption from provisions of Sections III @ 2, III @ & III L of 10CFR50 App R re alternate safe shutdown capability EISENHUT, D Q. Division of Licensing 83/04/26 Power Authority of the State of New York. 5pp 18359 216 24X Fiche 50-333,83/04/26,8305060548
- ~-8305040557 Safety evaluation supporting util request for exemption from Sections III 0 3 & III L of 10CFR50 App R re alternate safe shutdown capability = Office of Nuclear Reactor Regulation, Director 83/04/26 12pp. 18359 221 24X Fiche 30-333,83/04/26,8305060548
- 8305180572 Forwards exemption from requirements of 10CFR50, App E re annual schedule for emergency preperedness exercise Next exercise must be conducted no later than 831015 VASSALLO.D B Operating Reactors Branch 2 83/04/28 BAYNE, J P Power Authority of the State of New York 2pp 18505 298 24X Fiche 50-333.83/04/28,830580572
- ~~8305180577 Exemption granting relief from requirements of 10CFR50, App E re schedule for conducting emergency preparedness exercise Next exercise must be conducted no later than 831015 EFBERNUT.D.O Division of Licensing 83/04/28 Power Authority of the State of New York 3pp 18305 300 24% Fiche 50-533,83/04/28,8305180572
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENMUT.D @ Division of Licensing 83/05/11 Consolifated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- 8303250137 Informs that NUREC-D737 Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed VASSALLO, D B Dereating Reactors Branch 2 83/05/18 BAYNE, J P Power Authority of the State of New York 3pp. 18596 201 24X Fiche 50-333,83/05/18,8305250137.
- 8305230375 Forwards amended exemption requests to NRC 830202 draft safety evaluation of App Ridescription of proposed water sprays & ltr from fire protection consultant providing info per 830511 request 84YNE, J P. Power Authority of the State of New York, 83/05/19, DENTON, H R. Office of Nuclear Reactor Regulation, Director, 13pp 18538-243, 24X Fiche 30-333,83/05/19,8305230375.

J Insurance & indemnity information

- 8305120208 Forwards Endorsement 65 to NELIA Policy NF-208 & Endorsement 55 to MAELU Policy MF-77 GOLDEN, M P Harsh & McLennan, Inc 83/05/03 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18427 358 24X Fiche 30-000, 83/05/03, 8305120208
- P Operating license stage documents & correspondence
- 8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Force effort, per 821221 Itr
 DYSON.J 5 Power Authority of the State of New York 83/03/02, TOURTELLOTTE.J Regulatory Reform Task Force 2pp 18541 338 241 Fichs 50-000,83/03/02,8305230597
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24X Fichs 50-000,83/04/11,8305230720
- 8305030135 Forwards safety evaluation based on review of util submittals re TMI Action Item II B 1, "RCS Vents " Licensee venting capability acceptable VASSALLO.D B Operating Reactors Brench 2 83/04/18 BAYNE.J P Power Authority of the State of New York 4pp 18309 235, 24x Fiche: 50-333, 83/04/18, 8305030135
- --8303310020 "Belected Operating Reactor Issues Program II,RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept MELD-J T Energy Incorporated HELD-J T Lawrence Liverance Laboratory. FIN A-0250 B14/TER-B-7 83/03/02 ALBERTHAL, 0 NRC No Detailed Affiliation Given 4pp 18309 239 24% Fiche: 50-333, 83/04/18, 8305030135
- 8305030066 Forwards safety svaluation & technical evaluation rept re environ quelification of safety-related electrical equipment Util should reaffirm justification for continued operation Technical evaluation withheld VASSALLO, D. B. Operating Reactors Branch 2 83/04/19 BAYNE, J. P. Fower Authority of the State of New York 3pp 18326-114 24X Fiche 50-333,83/04/19,8305030066
- --B305030070 Sefety evaluation re environ qualification of safety-relatif electric equipment Four major qualification deficiencies listed * Office of Nuclear Reactor Regulation, Director. B3/04/19. 7pp 18326 117 24X Fiche 50-333,83/04/19,8305030066
- 8305020207 Forwards response to NRC 830316 ltr re NUREG-0737. Item II K 3 13, "RCIC Automatic Restart," RCIC sys modified to relocate signal for high reactor vessel water level trip from RCIC turbine trip valve to steam supply valve BAYNE, J P. Power Authority of the State of New York 83/04/28 VASSALO, D B Operating Reactors Branch 2 2pp 18278 133, 24X Fiche 50-333,83/04/28,8305020207
- 8305040424 Forwards application for smend to License DPR-59, requesting approval of proposed rediciogical effluent Tech Specs w/fixed implementation date of 840701 BAYNE, J. P. Fower Authority of the State of New York 83/04/27 VASSALLO, D. D. Operating Reactors Branch 2 2pp 18321 306 24X Fiche 50-333,83/04/29,8305040424
- --9305040434 Application for amend to License DPR-59, requesting approval of proposed radiological effluent Tech Specs w/fixed implementation date of 840701 BAYNE, J P Power Authority of the State of New York. 83/04/27 ip 18321 308 24X Fiche 50-333,83/04/29,8305040424
- --830504043B Proposed radiological effluent Tech Specs
 * Power Authority of the State of New York 83/04/29, 75pp
 18321.309. 24X Fiche.50-333.83/04/29,8305040424
- 8305020435 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuence of amends to DLs. Syc list encl EISENHUT, D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441.120, 24% Fiche 50-000,83/05/02,8305020455
- 8303040311 Forwards response to 830202 request for add1 info re NUREQ-0737.Item II F 1 4, "Containment Hydrogen Monitor." Info re water level monitors to be provided by 830419 BAYNE:J P Power Authority of the State of New York 83/05/02. VAESALLD.D B Operating Reactors Branch 2 3pp, 18323:300, 24X Fische 50-333,83/05/02.8308040311

- 8305030026 Forwards NEDO-22207. "Analysis of Scram Discharge Vol Sys Piping Integrity " No further action planned re equipment qualification & sys design mods identified in generic SER
 - RNOREG-UBO37 BAYNE, J.P., Power Authority of the State of New York 83/05/03 VASSALLO, D. B. Operating Reactors Branch 2 2pp 18339 313 24) Fiche, 50-333, 83/05/03, 8305050026
- 8305200246 Forwards safety evaluation of util submittal re procedure varification & design mod per NUREG-0737. Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved VABSALLO, D B Operating Reactors Branch 2 83/05/05 BAYNE, J P Power Authority of the State of New York 5pp 18340 206 24X Fiche, 30-333,83/05/03,8305200246
- B303090659 Owneric Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 193 24X Fichs 50-000.83/03/09, B305090659
- 8305260209 Forwards request for add1 info re 820401 response to MREO-0737.Item II K 3 29, "Gualification of Accumulators on Automatic Depressurization 8ys " Reply requested within 45 days of itr receipt WASSALLO, D B Operating Reactors Branch 2 83/05/11 BAYNE, J PROMER Authority of the State of New York 3pp 18629 354 24X Fiche.30-333,83/05/11,8305260209
- 9303160106 Forwards "Scram Instrument Vol Diverse Instrumentation for JA Fittpatrick Nuclear Plant: "supporting request that 801002 & 810107 orders re short-term mods of scram discharge vol sys be amended or lifted by 830630 BAYNE, J. P. Power Authority of the State of New York 83/05/12 DENTON: H R Office of Nuclear Reactor Regulation, Director DEYOUND, R Director's Office, Office of Inspection and Enforcement 2pp. 18430 076 24X Fiche 50-333,83/05/12,8305160106
- --8305160112 "Stram Instrument Vol Diverse Instrumentation for JA Fitzpatrick Nuclear Flant " + Power Authority of the State of New York 83/03/31 18pp 18450.098 24X Fiche 50-333,83/05/12,8305160106
- B305200265 Forwards application to amend License DPR-59, revising Tech Spec Table 3 7-1 re process pipeline penetrating primary containment
 BAYNE, J P Power Authority of the State of New York B3/05/13
 VASSALLD, D B Operating Reactors Branch 2 2pp 18516 310 24X
 Fiche: 50-333, 83/05/13, 8305200265
- --8305200268 Application to amend Tech Specs, revising Table 3 7-1 re process pipeline penetrating primary containment BAYNE, J. P. Power Authority of the Bate of New York Ip 18516 312 24X Fiche 50-333,83/05/13,8305200265
- --8305200272 Proposed Tech Spec changes re process piping penetrating primary containment

 a Power Authority of the State of New York 83/05/13 App 18316 313 24% Ficha 50-333.83/05/13 8305200265
- 8305260297 Forwards safety evaluation of BMR Owners Group generic response to NVREO-0737. Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mod to plant feeign or operations required Action complete VASGALLO.D.B Operating Reactors Branch 2 83/05/18 BAYNE, J P Power Authority of the Beate of New York 2pp 18629 323 24X Fiche 50-333,83/05/18,8305260297
- 8305240492 Forwards filing fee per 10CFR170 22 re Tech Spec changes to piping penetrating primary containment under protest pending final determination of legality of fee schedule BAYNE, J.P. Power Authority of the State of New York 83/05/19 WASSALLO, B 0 Departing Reactors Branch 2, 1p 18572 069 24X Fiche: 50-333:83/05/19.8305240492
- 8305240442 Forwards response to 10CR50 49 re equipment qualification Response to equipment qualification technical avaluation rept with his submitted separately since request from schedular exemption denied.

 BAYNELU P Power Authority of the State of New York. 83/05/20 VABSALLO, D. 8 Operating Reactors Branch 2 84pp 18573-036 24X Fiche 50-333,83/05/20,8305240442
- 8305240463 Forwards response to Generic Ltr 83-08 re results of plantunique calculations which form either bases for vacuum breaker mode or provide justification for as-built acceptability BAYNE,J.P. Power Authority of the State of New York 83/05/20 VASSALLQ,D 8 Operating Reactors Branch 2 2pp. 18573-173 24X Fiche 30-333,83/05/20.8305240463

- 8305870340 Forwards application to amend License DPR-59 & "Supplemental Reload Licensing Submittal for JA Fitzpatrick Nuclear Power Plant, Reload 5 " Amend changes std reload 11censing submittal for forthcoming Reload 3/Cycle & core BAYNE, J.P. Power Authority of the State of New York 83/05/25 VASSALD, D.B. Operating Reactors Branch 2 2pp 18643 071 24X Fiche 50-333,83/05/25,8305270340
- --8305270352 Application to amend License DPR-59, changing std reload licensing submittal for forthcoming Reload 5/Cycle 6 core BAYNE, J P Power Authority of the State of New York B3/05/25 ip 18443 073 24% Fiche 50-333, 83/05/25.8305270340
- --8305270344 Proposed Tech Specs 3 i-1.3 1-2.4 i-1.4 2-1.3 4-1.3 4-2. 3 5-6 to 3 5-10.3 6-1.4 6-1.6 i-1 & 6 2-1 re Reload 5/Cycle
 - * Power Authority of the State of New York B3/05/25 38pp 18643 074 24% Fiche 50-333/83/05/25/8305270340
- --8305270378 Rev O to "Supplemental Reload Licensing Submittal for JA Fitipatrick Nuclear Power Plant.Reload 5 " ZARBIS.W A. WAONER.R L., CHARNLEY, J. S. General Electric Co Y1003J01A56 ROI 83/03/31 25pp 18643 103 24X Fi
- Q Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin 8usceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York. Inc 112pp 18308 319 24X Fiche 30-000.83/03/21.8212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
- 8303040021 IE INFO NOTICE BUREL, BURELL, BUREL
- 8303040023 IE Info Notice 83-22, "BWR Bafety/Relisf Valve Failures "
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B3051i0501 Forwards IE Insp Rept 50-333/83-07 on B30328-31 No noncompliance noted BTAROBTECKLIR Division of Project & Resident Programs B3/04/26 MCNEIL.C A Power Authority of the Btate of New York 2pp 18393 350 24% Fiche 50-333,83/04/26,8305110501
- --8305110508 IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NURE9-0737, Item II B 2, "Design Review of Plant Shielding"

 BRIOGS.L. HAVERKAMP.D., EAPEN.P Region 1, Office of Director 83/04/22 8pp 18393 352 24% Fiche 50-333,83/04/24.8305110501
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Cenerators at PWRs " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28:8303040026
- 8303040027 IE Info Natice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Satpoint Adjustment " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28.8303040027
- ### 8305110369 Forwards IE Insp Rept 50-333/83-06 on 830301-31 & notice of violation
 ### STAROSTECKI, R Division of Project & Resident Programs
 ### MCNEILL, C A Power Authority of the State of New York
 ### 18406-299
 ### RAX Fiche 50-333,83/04/28,8305110369
- --8305110376 Notice of violation from insp on 830301-31 * Region 1, Office of Director 83/04/28 2pp 18406 301 24X Fiche 50-333,83/04/28,8305110369

- --8305110391 IE Insp Rept 50-333/83-06 on 830301-31 Noncompliance noted failure to implement radiation protection procedures failure to implement biannual procedure review & failure to maintain special procedure re ac power failures LINVILLE. J C . DOERFLEIN. L T . KISTER. H B Region 1. Office of Director 83/04/13 15pp 18406-303 24X Fiche 50-333.83/04/28, 8305110369
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83705/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18392 282 24X Fichs 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidate Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- 8303040033 [F Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/03/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830)(03) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303250838 Notification of 830520 significant licensee meeting w/util in Buchanan.NY to present results of SALP repts KISTER.H B Region 1, Office of Director 83/05/17 Region 1, Office of Director 2pp 18594 354 24X Fiche 50-000.83/05/17, 8309220838
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list enc]
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18497 009 24x Fiche 50-000-83/05/19.8303040040
- 8305270392 Ack receipt of 830511 ltr informing NRC of steps taken to correct violetions noted in IE Insp Rept 50-333/83-11
 MARTIN.T T Division of Engineering & Technical Programs 83/05/20, MCNEILL, C A Power Authority of the State of New York 2pp 18442 183 24x Fiche 50-333.83/05/20,8305270392
- ---8305270377 Responds to NRC 830413 itr re violations noted in IE Insp Rept 50-333/83-11 Corrective actions burial ground personnel resealed open box & waste package & handling Procedure F-GP-48B revised on 830330 MCNEILL, CA - Power Authority of the State of New York 83/05/11 MARTIN.T T Division of Engineering & Technical Programs 2pp 18642 185 24X Fiche 50-323,83/05/20,8305270392
- B305270274 Ark receipt of B30401 ltr informing NRC of steps taken to correct vialations noted in IE Insp Rept 50-333/82-24 Required actions to improve GA program listed MARTIN.T T Division of Engineering & Technical Programs MCNEILL.C A Power Authority of the State of New York 2pp 18643 131 24X Fichs 50-333/83/05/23.8305270274
- --8305270284 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-333/82-24 Corrective actions design verification by supervisors in Design & Analysis Procedure 3 II & 3 IB revised per insp rept.Rev to be completed by Apr 1983 BAYNE.J P Power Authority of the State of New York 83/04/01 HAYNEG.R C Region I. Office of Director 1500 18643 133 24X Fiche 50-333,83/05/23,8305270274
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Qil" Svc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp, 18647 007, 24X Fiche 30-000, 83/05/26, 8303040046
- R Periodic operating reports & related correspondence
- 8305130132 Forwards monthly operating rept for Apr 1983 MCNEfLL,C A Power Authority of the State of New York 83/05/09 Director's Office of Inspection and Enforcement 1p 18437 206 24X Fiche 50-333,83/05/09.8305130132

- --8305130134 Monthly operating rept for Apr 1983 CDOK.J Power Authority of the State of New York 83/05/09 681 18437 207 24X Fiche 50-333,83/05/09,8305130132
- 8305270189 "Annual Summary of Plant Mods, Changes & Experiments for 1982"
 MCNEILL, C. A. Power Authority of the State of New York 83/05/13 ALLAN, J. M. Region 1, Office of Director 23pp, 18638 GO1 24x Fiche 50-333,83/05/13,8305270189
- S Reportable occurrences, LERs & related correspondence
- 8305050241 Forwards AEOD/E305. "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors %/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR.RES & IE BROWN.E J. ASHE,F S Reactor Operations Analysis Branch 83/04/12 SEYFRIT.K V Reactor Operations Analysis Branch 2pp 18352 031 24X Fiche 50-000.83/04/13.8305050341
- --8305050353 "Inoperable Motor Operated Valve Assemblies Due to Frasalis Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment," AECD engineering evaluation rept BROWN.E J. ASHE.F.5 Director's Office 83/04/13, 7pp 18352 053 24X Fiche 30-000,83/04/13,8305050341
- 8305110259 Forwards LER 83-016/03L-0 MCNEILL.C A Power Authority of the State of New York 83/04/21 ALLAN,J M Region I, Office of Director ip 18393.291 24X Fiche 30-333,83/04/21.8305110259
- --8305110264 LER 83-016/03L-0 on 830412, setpoint of high-high trip four less conservative than Tech Spec limit Caused by instrument drift Setpoint adjusted & test frequency increased for trend observation
 KEITH-H N Power Authority of the State of New York 83/04/21.
 Region 1. Office of Director 1p. 18393 292 24X
 Fiche 50-333,83/04/21,8305110259
- B3D5110405 Forwards LER B3-015/03L-0 MCNEILL C A Fower Authority of the State of New York B3/04/21 ALLAN J M Region 1, Office of Director ip 18392-016, 24X Fiche 50-333 B3/04/21, B305110405
- --8305110416 LER 83-015/03L-0 on 830408, while conducting Surveillance
 Test F-S7-ID, switch 2A-S12B found out of normal position
 in Test Mode D Caused by inadequacies in implementation of
 procedural controls
 KEITH-H N Power Authority of the State of New York 83/04/21
 Region i, Office of Director 2pp 18392 017 24X
 Ficha 50-333,83/04/21,8305110405
- 8305110400 Forwards Updated LER 83-016/03L-1 MCNEILL: CA Fower Authority of the State of New York 83/04/25 ALLAN: J M Region i. Office of Director 1p 18392 012 24X Fisher 50-333, 83/04/25, 8305110400
- --B305110408 Updated LER B3-016/03L-1 on B30412 during surveillance testing on D max stillwater level high radiation monitor, setpoint of high-high trip found below Tech Spec limit Caused by instrument drift Setpoint adjusted KEITH.H N Power Authority of the State of New York B3/D4/25 Region 1, Office of Director 1p 18392 013 24X Fiche 50-333,83/04/25,8305110400
- 8305110510 Forwards LER 83-017/03L-0 MCNEILL,C A Power Authority of the State of New York 83/04/27 ALLAN,J M Region 1. Office of Director 1p 18393 361 24X Fiche 50-333,83/04/27.8305110510
- --8305110514 LER 83-017/03L-O: on 830414. Nine Mile Point-Bouth Oswego
 115kV Line 5 tripped & locked out, removing one reserve power
 supply from svc. Caused by line automatically isolating
 when tower hold down guy pulled out of ground
 LISENO, R T Power Authority of the State of New York
 Region 1. Office of Diractor 1p. 18393 362 24X
 Fiche 50-333, 83/04/27, 8305110510
- 8305230454 Forwards LER 83-014/03L-0 MCNEILL.C A Power Authority of the State of New York, 83/05/04 ALLAN.J M Region 1, Office of Director 10 18537 342 24X Fishe 50-333.83/05/04.8305230454
- --8305230459 LER 83-014/03L-0° on 830404 during normal plant operations, four cells of 8 side station battery found to have through wall cracks leaking electrolyte Caused by mishandling of cells during original installation Cells replaced PETERS, Power Authority of the State of New York 83/05/04 Region 1. Office of Director 2pp 18537 343 24X fiche 50-333,83/05/04,8305230454

- B3051003&O Advises that discrepancy due to fuel pool wall irregularities & fact that new fuel racks at high end of allowable tolerance limit Not reportable per 10CFR21 Safety factor of two precludes wall-to-wall interaction
 BAYNE, J.P. Power Authority of the State of New York 83/05/06
 VASSALUG.D B Departing Reactors Branch 2 2pp 18378 216 24;
 Fiche 50-333,83/05/06,8305100360
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list ent; EISENHUT.D Q Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000, B3/05/11, B305110034
- 8305200195 Supports util onsite emergency preparedness & upgraded plan per NUREO-0737. Item III A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E.10CFR50" Item complete VARGA.8 A Operating Reactors Branch 1 83/05/11 GAREY. J Duquesne Light Co 3pp 18540 222 24X Fiche 50-334.83/05/11, 8305200195
- 8305250426 Responds to 830207 & 0422 ltrs re changes to Revs 4 & 10 & correction of errors in Rev 9 to safeguards plan Changes consistent w/10CFR50 54(p) & acceptable for inclusion into safeguards plan
 ALLAN J K Region i, Office of Director 83/05/18 CAREY, J J Duquesne Light Co 3pp 18585 268 24X Fich# 50~334.83/05/18, 8309250426
- P Operating license stage documents & correspondence
- 8305230397 Responds to 830208 request for backfit info Total of \$281 million spent on backfitting through Jul 1982 Addl \$50 million required to complete work an NRC imposed backfits ARTHUR, J M Duquesne Light Co 83/03/09 TOURTELOTTE, J Regulatory Reform Task Force 17pp 18546 243 24X Fiche 50-334,83/03/09,8305230387
- E305230720 Forwards list of utils responding to requests for cost figures on backfitting TCURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X Fiche 50-000,83/04/11,8305230720
- B305020359 Forwards supplemental response to Generic Ltr B2-28, "Inadequate Core Cooling Instrumentation Sys" & NUREG-0737, Item II F 2 W/one oversize drawing Aperture card is available in PDR CAREY, J J Duquesne Light Co B3/04/21 VARGA, S A Derating Reactors Branch I 22pp 18273 198 24X Fiche 50-334, B3/04/21, 8305020359
- 8303040512 Discusses licensee action to initiate negotiations w/DOE re disposal of high level waste or spent nuclear fuel, per Amend in to License DPR-66 & Generic Ltr 83-07 re Nuclear Waste Policy Act of 1982 (Public Law 97-425). Section 302(b) VAR9A:8 A Operating Reactors Branch 1 83/04/25 CAREY, J Duquesne Light Co 2pp 18336 229 24X Fiche 50-334,83/04/25,8305040512
- 8305040621 Forwards revised pages to 830328 Amend &6 to License DPR-66 incorporating radioactive effluent Tech Specs into license TAM, P S Operating Reactors Branch 1 83/04/26 CAREY, J. J Duquesne Light Co 2pp 18336 308 24X Fiche 50-334.83/04/26, 8305040621
- --8305040626 Revised pages to Amend &6 to License DPR-66 incorporating liquid effluent monitoring instrumentation into Tech Bases Gerating Reactors Branch 1 83/04/26, 8pp 18336 311 24X Fiche 50-334.83/04/26,8305040621
- 8305060604 Forwards rev to Tech Spec Change Request 84, in response to Generic Ltr 82-16 Rev required to reassign section numbers to conform w/format changes incorporated in Tech Spec Amend 66 CAREY, J J Duquesne Light Co 83/04/28 VARQA, S A Operating Reactors Branch 1 2pp 18349 014 24X Fiche 50-334, 83/04/28, 8309060604
- ---8305060407 Rev to application for amend to License DPR-46, consisting of Tech Spec Change Request 84, revising Tech Specs to conform w/change in format incorporated by Amend 66 CAREY, J J. Duquesne Light Co 83/04/28 ip 18347 016 24X Fiche 50-334,83/04/28,8305060604

- --8305060614 Proposed Tech Specs re administrative controls & power distribution limits

 # Duquesne Light Co 83/04/28 5pp 18349 017 24X
 Fiche 50-334,83/04/28,8305060604
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D © Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 30pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- B305100337 Forwards Franklin Research Ctr proprietary equipment environ qualification worksheets, in response to B30329 clarification of environ qualification SER Previous submittals justified continued operation Worksheets withheld (ref 10CFR 790) CAREY, J J Duquesne Light Co B3/05/02 VARGA, S A Operating Reactors Branch 1 2pp 18379 104 24X Fiche 50-334,83/05/02, B305100337
- --B305110377 Application for withholding proprietary WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel," per 10CFR2 790 Affidavit encl WIESEMANN R A Westinghouse Electric Corp B3/04/20 VARGA, 8 A Operating Reactors Branch 1 Spp 18392 147 24X Fiche 50-334,83/05/02.8305110360
- --8305110398 Nonproprietary version of, "Second Cycle Performance of Beaver Valley Unit 1 Fuel " PRITCHETT,P A , KUNISHI,H , ROBERTS,E Westinghouse Electric Corp HGAP-10232 83/05/02 66pp 18392 156 24X Fiche 30-334.83/05/02.8305110360
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305230230 Advises that Tech Specs from Amends 47 & 36 re auxiliary faedwater sys surveillance satisfy open item noted in 820702 SER on NUREG-0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" VARGA: 8 A Operating Reactors Branch 1 83/05/16 CAREY, J J Duquesne Light Co 2pp 18543 152 24X Fiche 50-334,83/05/16,830530230
- B305240401 Forwards response to 10CFR50 49 rulemaking re environ qualification of electrical equipment When master list of equipment is coupled w/recent response to SER, more complete overview is presented CAREV, J J Duquesne Light Co B3/05/19 VARGA, B A Operating Reactors Branch 1 40pp 18574 146 24X Fishe 50-334,83/05/19,8305240401
- 8305250316 Forwards add1 info requested per 830512 telcon re util decision to replace existing control power transformers w/encapsulated-tube transformers per 10CFR50. App R Implementation planned during third refueling outage CAREY. J Duquesne Light Co 83705/20 VARGA. A Operating Reactors Branch 1 5pp 18588 273 24X Fiche 30-334,83/05/20,830520516
- 8305270187 Forwards "Reload Safety Evaluation, Beaver Valley Nuclear Plant Unit 1, Cycle 4 " Requests that change to require 50% of in-core moveable detector thimbles for full core flux map be instituted for Cycle 4 CAREY, J J Duquesne Light Co 83/05/23 VARGA, B A Operating Reactors Branch 1 2pp 1863B 107 24X Fiche 50-334, 83/05/23, 8305270187
- --8305270190 "Reload Safety Evaluation, Beaver Valley Nuclear Plant Unit 1,Cycle 4 "

 * Duquesne Light Co 83/02/28 19pp 18638 109 24X Fiche 50-334,83/05/23,8305270187
- Q Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl. TAYLOR: M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York: Inc 112pp 18308 319 24X Fiche 50~000,83/03/21,8212060385.

- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator "
- SUGGROUP IN THE NOTICE BA-21. "Defective Emergency Use Respirator" Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 185 24X Fiche 30-000,83/04/15.8303040021
- 8305050172 Forwards IE Insp Rept 50-334/83-07 on 830301-0404 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 83/04/20
 GAREY, J. J Duquesne Light Co 2pp 18341 013 24X
 Fiche 30-334-83/04/20, 8305050172
- --8305050175 Notice of violation from inep on 830301-0404 * Region 1, Office of Director 83/04/20 2pp 18341 015 24X Fiche 50-334,88/04/20,8305050172
- --8305050180 IE Insp Rept 50-334/83-07 on 830301-0404 Noncompliance noted failure to provide supplemental LER info & failure to use approved procedure for refueling preparation TROSKOSKI, #M.. TRIPP, LE Region 1. Office of Director 83/04/18 20pp 18341 017 24X Fiche 50-334,83/04/20,8305050172
- 8303040023 IE info Notice 83-22, "BWR Safety/Relief Valve Failures " 103040024 IE AFFO NOTICE NOTIC
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 117pp 18381:291 24X Fiche 30-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PNRs " Svc list encl JURDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040024
- 8303040027 IE Info Notice 83-25, "Standby Cas Treatment 8ys Heater High Temp Trip Setpoint Adjustment "Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24x Fiche 50-000.83/04/28.8303040027
- 8305100337 Forwards Franklin Research Ctr proprietary equipment environ qualification worksheets, in response to 830329 clarification of environ qualification SER Previous submittals justified continued operation Worksheets withheld (ref 10CFR2 790). CAREY, J. J. Duquesne Light Co. 83/05/02 VAROA, S. A. Operating Restors Branch i 2pp. 18379 104 24% Fiche 50-334.83/05/02, 8305100337
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441,170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl.
 JORDANAEL Bytision of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112ep 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Enginearing Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- B303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN,EL Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/06 Consolidated Edison Co of New York
- B30510026B Forwards Westinghouse Rev 1 to Procedure [SI-154, "Preservice & Inservice Insp of Reactor Vessels " Procedure meets intent of Reg Guide 1 150.Rev 1 as referenced in Generic Ltr B3-15 Generic Ltr 83-15 CAREY J J Duquesne Light Co 83/05/06, VARGA,S A Operatin Reactors Branch 1 1p 18371 160, 24X Fiche 50-334,83/05/06,
- --8305100273 Rev 1 to Procedure 181-154, "Preservice & Inservice Insp of Reactor Vessels "

 ADAMONIS, D. C., LE FEBVRE, D. J., VANO, J. A. Westinghouse Electric Corp. B3/03/16 73pp. 18371 161 24X Fiche 50-334,83/05/06,8305100268

- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Quidelines " Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11,8303040034
- 8305200436 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/82-19 Violation withdrawn per 830420 verification that records of two maint/repair activities retained MARTIN.T T Division of Engineering & Tachnical Programs 83/05/17 CAREY, J Duguesne Light Co 2pp 18517 119 24X Fiche-50-334,83/05/17,8305200436
- --8305200439 Responds to NRC 820916 & 830324 ltrs re violations noted in IE Insp Rept 50-334/82-19 Requested documentation located in files at time of insp Violation C should be withdrawn.

 CAREY, J. J. Duquesne Light Co. 83/04/25 MARTIN, T. T. Division of Engineering & Technical Programs 2pp 18517, 121 24X Flche 50-334,83/05/17,8305200436
- 8305240404 Forwards application for relief from inservice insprequirements re RHR HX nozzle Alternate exam requirements to be performed once per 40-month ARME Code period CAREY. J J Duquesne Light Co 83/05/17 VARGA, 8 A Operating Reactors Branch 1 7pp 18571 045 24X Fiche 50-334,83/05/17.83052407404
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." JOSONOVO I E 1870 NOTICE BUSSII BEFOR A MARKET SUMPTION OF BYC 11st enc)
 JORDAN, E L Division of Emergency Preparedness & Engineering
 JORDAN, E L BIVISION OF BUSSII CONSOLIDATE Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche: 50-000, 83/05/19, 8303040040,
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil" Syc list encl
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York
- R. Pariodic operating reports & related correspondence
- B305060261 Forwards Vol 2 to "Annual Environ Rept.Radiological.1982" B1EBER.J D Duquesne Light Co B3/04/25 WIGGINTON, D Operating Reactors Brench 1 lp 18344 193 24X Fiche 50-334,83/04/25.
- --8305060269 Vol 2 to "Annual Environ Rept.Radiological.1982" * Duquesna Light Co 83/04/25 124pp 18344 194 24X Ficht 50-334.83/04/25.8305060261
- 8305110424 Forwards Vol 2 to "1982 Annual Environ Rept, Radiological." CAREY, J J Doquesna Light Co 83/04/25 HAYNES, R C Region 1, Defice of Director 1p 18392 019 24X Fiche 50-334,83/04/25,
- 8305030593 Forwards NPDE8 discharge monitoring rept for Har 1983 FEITKMECHT, C Duquesne Light Co 83/04/27 REID,R W Operat Reactors Branch 4 3pp 18303 271 24X Piche 50-334,83/04/27 8305030593
- ~~8305030595 NPDES discharge monitoring rept for Mar 1983 * Duquesne Light Co. 83/04/27 13pp 18303 273 24x Fiche 50-334,83/04/27,8305030593
- S Reportable occurrences, LERs & related correspondence
- 8305030311 Forwards updated LER 79-023/03X-1 LACEY,W 9 Duquesne Light Co 83/04/13 Region 1, Office of Director 2pp. 18297:157 24X Fiche 50-334,83/04/13,8305030311
- --8305030316 Updated LER 79-023/09X-1 on 790724.dissel generator output Director 2pp 18297 159 24X Fiche 50-334.83/04/13.8305030311
- B305ii0427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices, initially reported on B30420 Attachments will be replaced w/devices w/widered grooves to accompadate new retaining rings Mfg drawings revised RAME/EP Westinghouse Electric Corp B3/04/21 DEYOUNG/R.C. Director's Dffice Of Tinspection and Enforcement 5pp 18405.095 24X Fiche 50-000.83/04/21.8305110427
- 8305110343 Forwards updated LER 83-008/03X-1 LACEY.W S Duquesne Light Co 83/04/25 ALLAN, J M Region 1, Office of Director 2pp 18406-180 24X Fiche 50-334,83/04/25,

- --B305110353 Updated LER B3-008/03X-1 on B30218.during testing of turbine driven auxiliary feedwater pump.excessive pump overheating at inboard packing follower observed Caused by packing failure (outer two rings found dry) Pump repacked BRUGA.R.J Duquesne Light Co B3/04/25 Region 1, Office of Director 2pp 18404 182 24X Fiche 50-334,83/04/25.8305110343
- B305190185 Forwards updated LER 82-052/03X-1 LACEY.W 8 Duquesne Light Co 83/04/25 ALLAN.J M Region 1, Office of Director 2pp 18500 221 24X Fiche 50-334,83/04/25, B305190185
- --8305190309 Updated LER 82-052/03X-1 on 821105.while fire hydrant was being relocated due to interference w/Unit 2 activities.leak discovered in hydrant Caused by lack of awareness & inadequate research by Unit 2 crafts personnel DRUOA,R J Duquesne Light Co 83/04/25 Region 1, Office of Director 2pp 18500 223 24X Fiche 50-334,83/04/25,8305190185
- 8305120402 Forwards LER 83-010/99X-0 LACEY, W B Duquesne Light Co 83/05/02 ALLAN, J M Region 1. Office of Director 2pp 18434 088 24X Fiche 50-334,83/05/02,
- --B305120411 LER B3-010/99X-0 on 830327 diesel driven fire pump failed operational surveillance test due to high coolant water tens Caused by casting defect in cylinder head Defective cylinder head & electrical components replaced DRUGAR J Duquesne Light Co B3/05/02 Region 1. Office of Director 2pp 18434 090 24X Fiche 50-334,83/05/02,8305120402
- 830516003B Forwards LER 83-010/99X-0 LACEY.W S Duquesne Light Co 83/05/02 ALLAN, J M Region 1. Diffice of Director 2pp 18453 123 24X Fiche 50-334, 83/05/02, 830516008B
- --8305160064 LER 83-010/97X-0 on 830327, while performing weekly diesel ungine driven fire pump operation test, water level in cooling sys expansion tank observed low Water added & high temp caused overflow Caused by defective cylinder head DRUOA, R. J. Duquesne Light Co. 83/05/02. Region i. Office of Director Rpp. 18453 125 24X Fiche 50-334,83/05/02,8305160058
- 8305230520 Forwards LER 83-011/03L-0 LACEY, W S. Duquesne Light Co 83/05/09 ALLAN, J M Region 1. Dffice of Director, 2pp 18536 323 24X Fiche 50-334,83/05/09, 8305230520
- --9305230527 LER 83-011/03L-0 on 830409, motor thermal averload relay for containment sump to 1A low head safety injection pump suction valve (H0V-91-860A) tripped, disabling motor Cause unknown. Event will be reevaluated buquesne Light Co. 63/05/09 Region 1, Office of Director 2pp. 18536: 325 24X Fiche 50-334. 83/05/09, 8305230520
- DOCKET 50-335 BT LUGIE PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- B305040563 Forwards fire hazard analysis for facility
 UHRIG.R E Fiorida Power & Light Co 83/04/12 EISENHUT, D 0
 Division of Licensing ip 18320 008 24X Fiche 50-335,83/04/12,8305040563.
- --B305040566 Fire hazard analysis for facility W/five oversize drawings Aperture cards are available in FDR * Florida Power & Light Co 83/04/12 75pp 18320.009 24X Fichel 50-535,83/04/12,8305040563
- 8303200489 Forwards safeguards info re devitalization of certain acquipment Info withheld (ref 10CFR73 21)
 UHRIG.R.E. Florida Power & Light Co 83/04/22 O'REILLY, J P
 Region 2, Office of Director ip 18513 007 24X
 Fiche. 50-335, 83/04/22, 8305200489
- B305170141 Summary of B30419-22 meetings w/util at site re physical security vital area analysis NERBEB.V. Licensing Branch 3 83/05/03 Licensing Branch 3 App. 18495:325 24X Fiche 50-335.83/05/03.8305170141
- 8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09, No noncompliance noted. DANCE: H C Division of Project & Resident Programs, 83/05/06 UHRIO,R.E. Florida Power & Light Co 2pp 18641 179 24X Fiche: 50-335, 83/05/06, 8305270287.

- --8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected emergency preparedness in technical support ctr HUFFMAN,0 N Region 2, Office of Director JENKINS,0 R Division of Emergency Preparedness & Materials Safety 83/05/03 App 18641 181 24X Fiche 50-335,83/05/06.8305270287
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for QLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540-075 24X
 Fiche 50-000,83/05/11.8305110034
- B303200090 Notifies that NUREO-0737, Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50, " completed Item closed CLARK.R A Operating Reactors Branch 3 B3/05/11 UHRIG.R E Florida Power & Light Co 3pp 18541 001 24X Fichs 50-335,83/05/11.8305200090
- 8305200346 Forwards revised Chapters 5 & 6 to security plan Chapters withheld (ref 10CFR73 21)
 UNRIO.R E Florida Power & Light Co 83/05/11 D'REILLY.J P
 Region 2. Office of Director 2pp 18516 251 24X
 Fiche 50-335.83/05/11.8305200346
- J Insurance & indemnity information
- 8305040186 Forwards Endorsements 47 & 37 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively DUCK-JR Marsh & McLennan, Inc 83/04/29 BALTZMAN, J Assistant Director for State & Licensee Relations to 18621 191 24X Fiche 50-335,83/04/29,8305040186
- 8305100182 Forwards executed Amends 8,9 & 10 to Indemnity Agreement B~76, adding Orlando Util Commission of City of Orlando,FL & Florida Municipal Power Agency & deleting Item 3 of attachment to indemnity agreement, respectively UHRIG.R E Florida Power & Light Co 83/05/05 EISENHUT.D G Division of Licensing 4pp 18374 290 24% Fiche 50-335.83/05/05,8305100182
- P Operating license stage documents & correspondence
- 8305020602 Forwards safety evaluation for environ qualification of safety-related electrical equipment & proprietary technical evaluation rept Justification for continued operation on listed items requested W/o technical evaluation rept CLARK, R A Operating Reactors Branch 3 83/04/21 UHRIG, R E Florida Power & Light Co 3pp 18284 204 24X Fiche 50-335,83/04/21,8305020602
- --8305020503 Bafety evaluation for environ qualification of safety-related electrical equipment Proprietary review guidelines and # Office of Nuclear Reactor Regulation, Director 83/04/21. 89 18284 207 24X Fiche 50-335,83/04/21.8305020602
- 8303060039 Ack receipt of 830419 ltr re resolution of thermal shield problems Schedule for submittal of repts to must commitments submitted in ltr & discussed at 830425 meeting confirmed CLARK.R. A Operating Reactors Branch 3 83/04/26 UHRIG.R E Florida Power & Light Co 2pp 18354 332 24X Fiche 30-335,83/04/26,8305060039
- B30311012B Forwards safety evaluation of upper head voiding under natural circulation cooldown conditions Util analyses acceptable Program should be reviewed to assure that TMI Action Item I C i addressed within 60 days of litr receipt CLARK: A Deerating Reactors Branch 3 B3/04/26 UHRIO.R E Florida Power & Light Co 4pp 18421 323 24X Fiche 50-335,83/04/26,830511012B
- --9305110132 9afety evaluation re upper head voiding under natural circulation cooldown conditions Consequences of upper head voiding acceptable # Office of Nuclear Reactor Regulation, Director 83/04/26 14pp. 18421.327 24X Fiche 50-335.83/04/26.8305110128
- B30502016B Forwards plant recovery plan presented at B30425 meeting re reactor vessel internals & thermal shield in response to Item C of B30419 ltr. Plan will be revised daily w/updates provided upon availability UHRIO.R E Florida Power & Light Co B3/04/27 CLARK.R A Operating Reactors Branch 3 2pp 18284 062 24X Fiche 50-335.83/04/27.8305020168.

- 8305020345 Summarizes B30425 meeting w/NRC re reactor vassel internals to thermal shield plant recovery program contenting pressurized thermal shock Plant may safely operate w/o restriction from pressurized thermal shock considerations UHRIO.R E Florida Power & Light Ca B3/04/27 CLARK.R A Operating Reactors Branch 3 13pp 18274 079 24X Fiche 50-335.83/04/27.8305020345
- 8303020519 Forwards reactor vessel internals & thermal shield plant recovery program per 830419 commitment to provide safety assessment of possible effects on fuel performance due to loose parts No fuel problems indicated at facility UHRIO.R E Florida Power & Light Co 83/04/27 CLARK, R A Operating Reactors Branch 3 2pp 19281 254 24X Fiche 50-335,83/04/27,8305020519
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees renew procedures for providing public notice concerning issuance of amends to GLs Svc list encl EISENHUT.D G Division of Licensing 83/05/02 Consolidated Edison Co of New York. Inc. 50pp 18441 120 24X Fiche 50-000.83/05/02.8305020455
- 8305090476 Advises that 10-yr pressure-temp operating limits (P-T) for plant recovery program reactor vessel internals & thermal shield valid for upcoming Cycle 6 P-T limits will be revised if necessary prior to exceeding 7 4 EFPY UHRIORR E Florids Power & Light Co 83/05/03 CLARK, R A Operating Reactors Branch 3 ip 18362 271 24X Fiche 50-335,83/05/03,8305090476
- B305100236 Advises that vendor safety analysis to support installation of mods to auxiliary sys.per util B30103 ltr re main steam line break w/continued feedwater addition.is under review Response to core reactivity question expected by B30615 UHRIGAR E Florida Power & Light Co. 83/05/03 CLARK, R A Operating Reactors Branch 3 1p. 18374 127 24X Fiche 50-335.83/05/03.8305100236
- 8305110105 Forwards Amend 57 to License DPR-67, safety evaluation & notice of issuance & availability Amend provides for removal of chlorine detectors from control room air intakes H/o encl
 SELLS, D E Operating Reactors Branch 3 83/05/03 UHRIG, R E Florida Power & Light Co 1p 18421 254 24X Fiche 50-335, 83/05/03,8305110105
- B305120146 Forwards Amend 58 to License DPR-67, safety evaluation & notice of issuance & availability Amends change Tech Specs to clarify & modify surveillance requirements & limiting operating conditions for degraded grid voltage protection SELLS, D E Operating Reactors Branch 3 B3/05/03 UHRIO.R E Florida Power & Light Co. 3pp 18435 312 24X Fiche: 50-335, 83/05/03, 8305120146
- --B305120153 Amend 5B to Livense DPR-67.revising Tech Spec surveillance requirements & limiting operating conditions re-grid voltage protection equipment & procedures
 CLARK:R A Operating Reactors Branch 3 83/05/03 11gp
 18433 315 24X Fiche 50-335,83/05/03,8305120146
- --8305120160 Safety evaluation supporting Amend 58 to License DPR-67.

 * Office of Nuclear Reactor Regulation, Director 83/05/03 3pp
 18435 326 24% Fiche 50-335.83/05/03.8305120146
- --8209020602 "Technical Evaluation Rept on Proposed Design Mods & Tech Spec Changes on Orid Voltage Degradation for St Lucie Nuclear Power Plant-Unit 1" SELAN.J.C Lawrence Livermore Laboratory FIN A-0250 UCID-19450 82/07/30 Diffice of Nuclear Reactor Regulation, Director lipp. 18435 329 24x Fiche 50-335, 83/05/03, 8305120146
- --8304060471 Rev 1.to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation," technical evaluation rept SELAN.J C Laurence Livermora Laboratory FIN A-0230 UCID-19450 R01. 83703/23 Ofvision of Licensing 10pp 18435 340 24X Fiche 50-335.83705/03.8305120146
- --8305120171 Notice of issuance & availability of Amend 58 to License DPR-67. TRAMMELL, C M Operating Reactors Branch 3 83/05/03 2pp 18435 351 24X Fiche 50-335,83/05/03,8305120146
- B305120499 Summary of 830425 meeting w/util & C-E in Bethexda, MD re schedule for resolution of thermal shield damage Thermal shield chronological sequence enco SELES, D. E. Operating Reactors Branch 3 B3/05/03 Operating Reactors Branch 3 Spp. 18443 169 24X Fiche 50-335, B3/05/03, B305120499,

- 8305120520 Summary of 830425 meeting w/util & C-E in Bethesda, MD rethermal shock to reactor pressure vassel w/removal of thermal shield from facility Viewgraphs encl SELLS, D E Operating Reactors Branch 3 83/05/03 Operating Reactors Branch 3 17pp 18441 341 24X Fiche 50-335,83/05/03,8305120320
- B303180567 Responds to 830425 ltr ve decision to remove first reactor vessel matl irradiation surveillance specimen during current outage. Info resulting from exam & evaluation of specimen requested for review of thermal & shield analysis CLARK.R A Operating Reactors Branch 3 83/05/04 UHRIO, R E Florida Power & Light Co 2pp 18504 361 24X Fiche. 30-335, 83/05/04, 8305180567
- 8305100103 Forwards info justifying continued operation w/electrical equipment in Item 114 per 830421 Itr All other items listed in Category II B of Franklin Research Ctr technical evaluation rept replaced w/qualified transmitters UHRIO.R E Florida Power & Light Co 83/05/05 CLARK.R A Operating Reactors Branch 3 2pp 18377.249 24% Fichs 50-335.83/05/05.8305100103
- 8305090559 Owneric Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods 8vc list while EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659
- 8305130121 Responds to Generic Ltr 83-108, "Resolution of TMI Action Plan Item II K 3 5. Automatic Trip of Coolant Pumps " C-E Ouners Group has chosen "trip two.leave two" strategy to resolve item Description of program expected by 830701 URRIGIR E Florida Power & Light Co 83/05/10 EISENHUT.D Q Division of Licensing 2pp 18438 091 24X Fiche 50-335,83/05/10,8305130121
- B305170103 Notification of B30520 meeting w/util & C-E in Bethesda.MD to discuss loose parts monitoring sys & ex-core instrumentation fortions of meeting may be proprietary SELLB.D E Operating Reactors Branch 3 B3/05/12 CLARK.R A Operating Reactors Branch 3 2pp 18495 340 24X Fiche 50-335,83/05/12,8305170103
- 8305240599 Notification of cancellation of 830520 meeting w/util in Bethesda.ND to discuss loose parts monitoring sys & ex-core instrumentation SELLS.D E Operating Reactors Branch 3 83/05/12 CLARK.R A Operating Reactors Branch 3 2pp 18593 165 24X Fiche 30-335.83/05/12,8305240599
- 8305170463 Forwards response to requests for add1 info re Cycle 6 reload Performance of C-E fuel examined & Tech Spec change to remove augmentation factors supported UHRIO.R E Florida Power & Light Co 83/05/13 EISENHUT, D G Assistant Director for Licensing 17pp 18469 339 24K Fiche 50-335,83/05/13,8305170463
- B305270170 Forwards "St Lucie 1 & 2 & Turkey Point 3 & 4 Detailed Control Room Design Reviews Program Plan: "fulfilling 830415 commitment per NUREG-0737, Suppl 1 UHRIO.R E Florida Power & Light Co. B3/05/14 EIBENHUT.D C. Division of Licensing Ip 18638 072 24X Fichs 50-335,83/05/14. B308270170
- B305230532 Forwards Class III fee for 830309 application for emend to Tech Specs for License DPR-67 re chlorine detection sys UHRIO:R E Florida Power & Light Co B3/05/16 DIOOS.R.M License Fee Management Branch ip 18537 059 24X Fichs 50-335:83/05/16. B308230332
- B305250397 Forwards Class III amend fee for B30309 request for proposed Tech Spec changed re chlorine detection sys UHRIO.R E Florida Power & Light Co B3/05/16 DIGOS,R M License Fee Management Branch 2pp. 18592 082 24X Fiche 50-335,83/05/16. B300250397
- B305240372 Forwards responses to NRC B30118 request for info reaccident monitoring to aid in post-implementation review of NNREO-0737. Items II F 1 4. II F, 1 5 & II F, 1, 6
 UHRIO,R E Florida Power & Light Co B3/05/19 CLARK,R A Operating Reactors Branch 3 17pp 18575 078 24X
 Fichs 50-335,83/05/19,8305240372
- 8305250462 Reschedules 830520 meeting on plant recovery program loose parts monitor & ex-core detector, for 830603, w/followup documentation to be provided by 830606 UHRIG,R E Florida Power & Light Co 83/05/19 CLARK,R A Operating Reactors Branch 3 2pp 18589 033, 24X Fiche 50-335,83/05/19,8305250462

- 8305250272 Responds to 830504 request for submittal date of exam & results for math irradiation surveillance Final rapt summarizing C-E test results expected in early Oct 1983 Rept ufil be submitted by 831101
 UHRIO-R E Florida Power & Light CO 83/05/20 CLARK,R A Operating Reactors Branch 3 ip 18592 301 24X
 Fiche 50-335-83/05/20-8305250272
- 8305250395 Forwards schedule for qualification or replacement of equipment important to safety within scope of iOCFR50 49 Add1 documentation to demonstate that equipment committed to be qualified meets specific requirements forthcoming UHRIO,R E Florida Power & Light Co 83/05/20 CLARK,R A Operating Reactors Branch 3 ilpp 18385 319 24X Fiche 50-335,83/05/20,8305250395
- 8305250472 Forwards "St Lucis Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppli to NUREQ-0737 UNRIGHT E Florida Power & Light Co 83/05/20 EISENHUT, D 0 Division of Licensing ip 18588 333 24X Fiche 50-000, 83/05/20, 8305250472
- --8305250491 "8t Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Raom Design Reviews Program Plan " * Florida Power & Light Co 83/04/30 34pp 18588 334 24X Ficha 50-000, 83/05/20,8309250472
- B339250481 Forwards "Equipment Qualification Radiation Dose Map Devalogment." In response to 830406 request Rept presents assumptions & methodology used in creating dose maps & two filustrative dose points
 URRIGAR E Florida Power & Light Co B3/05/20 EISENHUT, D G Division of Licensing, ip 18388 234 24X Fiche 50-335,83/05/20,8305250481.
- --8305250484 "Equipment Qualification Radiation Dose Map Development "
 Florids Power & Light Co 83/05/20 16pp 18588 235 24X
 Fiche 50-335,83/05/20,8305250481
- 8305270168 Forwards responses to add1 info requested in 830421 safety avaluation on environ qualification of safety-related electrical equipment UMRIO.R E Florida Power & Light Co 83/05/25 CLARK.R A Operating Reactors Branch 3 3pp 18638 056 24% Fichs 50-335,83/05/25,8305270168
- G Inspection reports, IE Bulletins & correspondence
- 8212040395 IE Info Notice 83-14, "Dewatored Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385
- 6305270561 Forwards IE Insp Repts 50-335/83-10 & 50-389/83-25 on B30316-18 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/06 UHRIG,R E Florida Pawer & Light Co 2pp 18645 321 24X Fichs 50-335,83/04/06,8305270561
- --8305270576 IE Insp Repts 50-335/83-10 & 50-389/83-25 on 630316-18 No noncompliance noted Major areas inspected Unit 1 plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items.

 WRAY.J R , BARR.K P Region 2, Defice of Director 63/04/05 8pp 18445:323 24X Fiche 50-335,83/04/06,8305270561.
- 8305270559 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-02 & 50-395/83-09 LEMIG.R C Division of Project & Resident Programs 83/04/14 UHRIG.R E Florida Power & Light Co ip 18647 127 24X Fiche 50-335,83/04/14,8305270559
- --8305270572 Responds to NRC 830301 itr re violations noted in IE Insp Rept 30-333/83-02 Corrective actions, licensed operator qualification program reviewed & will be revised by 830731 & sxam date tracking sys established. UMRIO.R.E. Florida Power & Light Co 83/03/31. O'REILLY, J P Region 2, Office of Director, 4pp 18447, 128 24X Fiche 50-335,83/04/14,8305270559
- --8305270579 Forwards IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/03/01 UMRIG.R.E. Florids Power & Light Ca 2pp 18647 133 24X Fiche 50-335,83/04/14,8305270559

- --8305270584 Notice of violation from insp on 830124-28 * Region 2. Office of Director 83/03/01 2pp 18647 135 24X Fiche 50-333-83/04/14,8305270559
- --8305270594 IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28
 Noncompliance noted failure to fallow procedures required by
 training programs & failure of licensed operators to be
 cognizant of facility design, procedures & license changes
 BELISLE.O A . SKINNER.P H . UPRIGHT.C M Region 2, Office of
 Director 83/02/24 9pp 18647 137 24X Fiche 50-335.83/04/14,
 8305270559
- 8303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 8vc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Bafaty/Relief Valve Failures "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Canadidated Edison Co of New
 York, Inc 112pp 19383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing 8ys " Svc list enct JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York
- 8305020084 Withdraws 830405 relief request for performing inservice insp Relief will not be required UHRIO.R E Florida Power & Light Co 83/04/26 EISENHUT.D O Division of Licensing ip 18279 278 24X Fithe 50-335,83/04/26,8305020084
- #305270359 Forwards IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/26 UHRIO,R E Florida Power & Light Co 2pp 18642 128 24X Fiche 50-335,83/04/26,8305270359
- --8305270367 IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted Major areas inspected local leak rate testing shubber testing & review of Unit i procedures re refueling operations WHITEMER.H L , MATHIS.J , JAPE.F Region 2. Office of Director 83/04/21 6pp 18642 130 24X Fiche 50-335.83/04/26.8305270359
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list and! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382-047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027
- 8305030340 Forwards three relief requests from certain Tech Spec 4 4 10 1 a & 10CFR50 55(g) inservice (nsp requirements Approval required during current sutage UHRIO.R E Florida Power & Light Co 83/04/29 EIBENHUT, D 0 Division of Licensing 9pp 18297 109 24X Fiche 50-335,83/04/29,8305030340
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enc! JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/04 Consolidated Edison Co of New York, Inc. 112pp. 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies," Svc list encl JDRDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fichs 50-000,83/05/06,8303040033

- 8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncomplience nated DANCE, H C Division of Project & Resident Programs 83/05/06 UHRIO: R E Florida Power & Light Co 2pp. 18641 179 24X Fichs 50-335.83/05/06,8305270287
- --8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected emergency preparedness in technical support ctr HUFFKAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Naterials Safety 83/05/03. 4pp 18641 881 24X Fiche 50-335.83/05/06.8305270287
- 8305270329 Farwards IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/06 UHRIG, R E Florida Power & Light Co 2pp 18541-131 24X Fiche 50-335,83/05/06 8305270329
- --B305270339 IE [nsp Repts 50-335/83-13 t 50-389/83-33 on 830412-15 No noncompliance noted Major areas inspected inservice (nsp (Unit 1).core barrel/thermal shield damage (Unit 1).welding type (Unit 1) typeservice (nsp (Unit 2) CROWLEY, B R. BLAKE, J J Region 2, Office of Director 83/05/02 7pp 18641 133 24X Fiche 50-335,83/05/06.8305270329
- 9303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl URBOAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.
- 8303040040 IE Jnfo Notice 83-31. "Error in ADLPIPE Computer Program "
 Evc list enci
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697.009 24X Ficher 50-000,83/05/17,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated dil " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24X Fiche. 50-000, 83/05/26, 8303040046
- R Periodic operating reports & related correspondence
- 830503034: Forwards Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept.1982" UHRIO,R E Florida Power & Light Co 83/04/28 MULLER.D R, NRC -No Detailed Affiliation Given 1p 18307 001 24X Fiche 50-335.83/04/28.8305030341
- --8305030347 Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept,1982" # Applied Biology, Inc. AB-442 83/03/31 406pp. 18207 004. 24X Fiche 50-335.83/04/88.8305030341
- A Reportable occurrences. LERs & related correspondence
- 8305050127 Forwards LER 83-021/03L-0 HILLIAMS.J W Fiorids Power & Light Co 83/04/28, O'REILLY,J P. Ragion 2. Office of Director 1p 18341 353 24X Fichs-50-335,83/04/28,8305050127
- --8305050138 LER 83-021/03L-0 on 830329, w/refueling cavity filled greater than 23 ft, two shutdown cooling hot leg suction velves closed, isolating flow to core Caused by shorting out of gover supply to control circuit.Power restored MALLINO.0 E Florida Power & Light Co 83/04/28 Region 2, Office of Director lp 18341:354 24X Fiche:50-335,83/04/28,8303030127
- B305170527 Deficiency rept re-potential significant safety hazard concerning defect in stainless steel tubing pressure boundary component initially reported on B30504. Selected tubes returned to C-E Tubes for reinsy BCHERER. A E Combustion Engineering. Inc. B3/05/06 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement. 10pp 18468 017. 24X Fiche-50-335.83/05/06.8305170327.
- 9305170244 Forwards LER 83-025/03L-0 WILLIAMS, J.W. Florida Power & Light Co 83/05/09. O'REILLY, J P Region 2: Office of Director 1p. 18466 124 24X Fiche. 50-335, 83/05/09. 8305170244.
- --8305170250 LER 83-025/03L-0 on 830419, 31-day fire station insp interval exceeded Caused by personnel overeight Personnel advised of importance of performing required insps.

 SRANNIN, J. P. Florida Power & Light Co. 83/05/09. Region 2, Office of Director, 1p. 18464-125, 24X Fiche, 50-335, 83/05/09, 8305170244

- 8305200430 PND-II-83-040 on 830515, two util employees & one forest employee arrested for cocains & marijuans possession Arrest occurred offsite Employees not involved in licensed operator activities

 LANDIS.K D. DANCE.H C. Region 2. Office of Director, 83/05/17

 19 18517 150 24X Fichs 30-335,83/05/17,8305200430
- 8305250302 LER 83-026/097-0 on 830513.67 of 264 Bergen Paterson EA-3 clamps discovered oriented improperly Caused by vendor catalog interpreted improperly Clamps will be replaced during present outage W/830518 itr
 WILLIAMS.J.W., MCLAUOHLIN,L. Florida Power & Light Co. 83/05/18 O'REILLY.J.P. Region 2. Office of Director 2pp 18572.154 241 Fiche 50-335.83/05/18.8305250302
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B305040022 Relacase public version of ravised emergency plan implementing procedures FELTON. JM Division of Rules and Records 82/04/25 Document Management Brench ip 1930 065 24X Fiche 50-245,83/04/25, B305040022.
- --8305040034 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit I reactor collent & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate COUNSIL.W. O Northeast Nuclear Energy Co (subs of Northeast Utilities). 83/04/12 EIBENNUT.D O Division of Licensing Sp. 18330 066 24X Fichs 50-245,83/04/25,8305040022
- --B305040037 Public version of revised amergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 3000p 18330 068 24X Fiche 50-245,83/04/25, 8305040022.
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.

 EIBENHUT, D. Ø Division of Licensing 83/05/11 Consolidated Edison Ca. of New York, Inc. 16pp. 18540-095 24X

 Fiche 50-000, 83/05/11, 8305110034
- 8305180833 Authorizes refund for review of 821230 & 830408 requests from revised schedule for conducting emergency exercise MILLER.H O License Fee Management Branch 83/05/11 COUNSIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities), ip 18504:030 24X Fiche 50-000,83/05/11,8305180853
- 8305160022 Advises that onsite & offsits emergency preparedness adequate & emergency plans upgraded per NUREQ-0737, Item 111.A. 2: Item complete CRUTCHFIELD.D Operating Reactors Branch 5, 83/05/13 COUNBIL: H 9 Connecticut Yankes Atomic Power Co COUNBIL: H 0. Northeast Nuclear Energy Co (subt of Northeast Utilities) 4pp 18452.349, 24X Fiche: 50-000,83/05/13,8305160022
- 1 Financial Information
- 8305020093 Forwards "Annual Rept of Electric Utils, Licensees & Others (Class A & Class B)," FERC Form 1
 BISHOP, R W Northeast Utilities 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279 109. 24X
 Fiche 30-245,83/04/26,8305020093
- J Insurance & indemnity information
- B305120156 Forwards Endorsements 87 & 78 to NELIA Policy NF-173 & MAELV Policy MF-72, respectively BINIST. J. M. Marsh & McLennan, Inc. 83/05/05 SALTZMAN, J D. Assistant Director for State & Licensee Relations 3pp 18427-153 24X Fichs 50-245, 83/05/05.8305120156.
- P. Operating license stage documents & correspondence
- 8305230616 Forwards info in response to 830208 itr requesting backfit cost data for operating nuclear units, Cost categorized according to NRC imposed, TMI & non-TMI backfits, util-initiated & hybrid backfits

 CDUNSIL, W 0, Connecticut Yankee Atomic Power Co CDUNSIL, W 0

 Northeast Nuclear Energy Co (subs of Northeast Utilities),

 CDUNSIL, W 9, Northeast Utilities 83/03/21, TOURTELLOTTE, J.

 Regulatory Reform Task Force 23pp 18543 038 24X

 Fiche 50-000,83/03/21,8305230616

- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO.N J Commissioners 2pp 19542 272 24X Fichs 50-000.83/04/11.8305230720
- 8305160188 Advises that action required by 830126 Amends 88,51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & Generic Ltr 83-07 complete based on util negotiations w/DDC re disposal of high level waste or spent nuclear fuel CLARK, R A Deprating Reactors Branch 3 83/04/20 COUNSIL, W G Connecticut Vantee Atomic Power Co 2pp 18462 355 24X Fichs. 50-000, 83/04/20, 8305160188
- 8305040058 Forwards SER supporting revs to radiological effluent Tech Specs Tech Specs acceptable CLARK,R A Operating Reactors Branch 3 83/04/21 COUNBIL,W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18344-320 24% Fiche 50-334,83/04/21.8305060058
- --8305060062 BER supporting revs to radiological effluent Tech Specs

 Office of Nuclear Reactor Regulation, Director 83/04/21 6p
 18364 322 24X Fiche 50-336.83/04/21.8305060058
- --8209210332 "Radiological Effluent Tech Spec Implementation (A-2), Millstone Nuclear Power Station Unit 2," technical evaluation rept FERNANDEZ.C., PANDEY, 8., CARFAGND, P. Franklin Institute/Franklin Research Center NRC-03-01-130 TER-03506-99 82/09/17 NRC NO Detailed Affiliation Given 26pp 18364 328 24X Fiche: 50-336,83/04/21,8305060058.
- 8303040447 Provides info justifying continued operation in light of thermal shield concerns, per request made at 830412 meeting Visual inspectod during Fall 1980 outage, uncovered no evidence of thermal shield deterioration COUNSIL. H Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. H Q Northeast Utilities 83/04/26 CLARK, R A Operating Resotors Branch 3 2pp 18319-317 24X Fiche 30-336-83/04/26,8305040447
- 8305050054 Forwards comments on Generic Ltr 82-32, "Potential Steam Generator Related Requirements" Vendor input should be sought, especially in areas of steam generator tube inservice insp. & design considerations
 COUNBIL, W.O. Connecticut Yankee Atomic Power Co. COUNBIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
 COUNBIL, W.O. Northeast Utilities 83/04/29 EIBENHUT, D.O. Division of Licensing App. 18339-085 24X Fiche 50-000,83/04/29,8305070054
- 8305030229 Bubmits progress rept re TMI Items II F 1.1 & II F 1.2 re effluent monitor mods Vendor schedular uncertainties resolved. Remaining work consists of training operators, software changes & minor wiring change.

 CDUNSIL: H 9 Northeast Nuclear Energy Co (subs of Northeast Utilities). CDUNSIL: H. 0 Northeast Utilities 83/04/29 CRUTCHFIELD. B Operating Reactors Branch 5 2pp 18338 062 24X Fichs: 50-245,83/04/29,8305050229.
- 8305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Manual," per 10CFR30, App E. Section V W/o encis.
 COUNSIL: N 0 Connecticut Yankee Atomic Power Co COUNSIL: N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities).
 COUNSIL: N 0. Northeast Utilities 83/04/29 EISENHUT, D 0 Division of Licensing 2pp 18362 256 24X Fiche 30-000, 83/04/29, 8303090453
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list enc! EIBENHUT.D 9. Division of Licensing, 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441,120 24X Fichs: 50-000,83/05/02.8305020455,
- 8303120241 Forwards proprietary & nonproprietary responses to NRC 820819 request for add1 info re measurement uncertainties & "Shape Annealing Factor Component of Axial Shape Index ." Proprietary response & rept withheld (ref 10CFR2 790) COUNSIL, H. G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H. G Northeast Utilities 83/05/03, CLARK, R. A. Operating Reactors Branch 3 16pp 18429 151 24X Fiche, 50-336, 83/05/03, 8305120241
- --8305120252 "Shape Annealing Factor Component of Axial Shape Index Uncertainty," * Combustion Engineering, Inc. CEN-247(N)-NP, 83/03/31 48pp 18429:167 24X Fiche: 50-336, 83/05/03, 8305120241

- 8305200081 Forwards SER supporting licensee 770625 & 810301 requests for relief from ASME Section XI inservice testing requirements, per 10CFR50 55(g) Relief from ASME Code requirements expires on 851225 CLARK, R. A. Operating Reactors Brench 3 83/05/04 COUNBIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 4pp 18541 006 24X Fiche 50-336, 83/05/04, 8305200081
- --8308200085 Safety evaluation supporting licensee request for relief from ASME Section XI inservice testing requirements per 100FR30 35(g) # Diffice of Nuclear Reactor Regulation. Director 83/05/04 R6pp 18541 010 24X Fiche 50-336.83/05/04.8305200081
- --B305200089 Notice of granting relief from ASME Section XI inservice testing requirements.per 100FR30 35(g)
 TRAMMELL.C M Operating Reactors Branch 3 83/05/04 2pp
 18541 036 24X Fighe 50-336,83/05/04,8305200081
- 8305090426 Forwards Amends 91 & 86 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability Amends change ownership interests in facilities CRUTCHFIELD, D. Operating Reactors Branch 3 83/05/05 COUNBIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pg 18360 236 24X Fiche 30-245, 83/05/05, 8305090426
- ---B303090460 Amend B6 to License DPR-65, reflecting merger of Connecticut Light & Power Co & Hartford Electric Light Co Pages 1 & 2 of Amend 4 to License DPR-21 snc1 CLARK, R A Operating Reactors Brench 3 83/05/05 4pp 18360 246 24X Fiche 50-245,83/05/05,8305090426
- 8305110219 Forwards Amend 85 to License DFR-65. safety evaluation & notice of issuance & availability Amend adds footnots to Tech Specs allowing use of temporary equipment hatch door LEECH,P H Operating Reactors Branch 3 83/05/05 COUNSIL. 4 O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18424 334 24x Fiche 50-336.83/05/05.8305110219
- --8305110224 Amend 85 to License DPR-65, adding footnote to Tech Specs allowing use of temporary equipment hatch door to maintain containment integrity during fuel movement or core alterations

 CLARKIR A Operating Reactors Branch 3 83/05/05 5pp 18494 340 24X Fiche 50-336, 83/05/05, 83/05110219
- --B30511022B Safety evaluation supporting Amend B5 to License DPR-65 * Office of Nuclear Reactor Regulation, Director B3/05/05 3pp 1844 345 24 Fiche 30-336.B3/05/05,B305110219
- --B305110230 Notice of issuance & availability of Amend 85 to License DPR-65
 TRAMMELL,C M Operating Reactors Branch 3 83/05/05 2pp 18434 348 24X Fiche.50-336.83/05/05.8305110219
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627:153 24X Fiche 50-000, 83/05/09, 8305090659
- B30523050B Discusses B30413 ltr re proposed revs to Tech Specs for Gycle 6 reload Current Tech Spec limits provide scceptable margin of safety GDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities B3/05/16 CLARKR A Dperating Reactors Branch 3 4pp [8537 326 24X Fiche. 50-336.83/05/16, 8305230508
- B305250510 Application to amend Licenses DPR-61, DPR-21 the DPR-65 deleting B20630 deadline date for conformance wifinal rule 100FR30 49 removing requirement for central equipment counsil. With the COUNSIL William of the COUNSIL William of C
- ~-8305250518 Proposed Tech Spec changes deleting 820530 deadline for environ qualification of electrical equipment * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/18 7pp 18588 281 24X Fiche 50-000,83/05/18,8305250510

- @ Inspection reports. IE Bulletins & correspondence
- 8212060385 lE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J N Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of Neu York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21.8212060385
- 9303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040083 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list and JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 112pp 18383 089 24X Fishe 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000.83/04/25.8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary 8ide of Steam Generators at PMRs" Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83704/28,8303040027
- 8305060424 Responds to 830316 request for plans for Cycle 6 reload outage steam generator insp Tube defect assessment & supplementary steam generator testing program tables encl CCUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) CCUNSIL.W O Northeast Utilities 83/04/29 CLARK.R A Operating Reactors Branch 3 5pp 18343 281 24% Fiche 50-336,83/04/29,8305060424
- 8303040028 IE Info Notice 83-26, "Faiture of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl UCRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 93-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fichs 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Int. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list ent! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fichs 50-000.83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Syc list and JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000,83/05/11,8303040034
- 8305250459 Forwards IE Insp Rept 50-336/83-09 on 830411-14 No noncompilance noted STAROBTECKI, R Division of Project & Resident Programs 83/05/11 COUNSILL N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588,096 24X Fiche 50-336.83/05/11,8305250459
- --0305250465 IE Insp Rept 50-336/83-D9 on 830411-14 No noncompliance noted Hajor areas inspected: licensee actions taken to comply w/requirements discussed in NURG-0737, Item II B. 2 re design review of plant shielding LAZARUS, H. J., HAVERKAMP, D. R., EAPEN, P. K. Region 1, Defice of Director 83/05/09 App. 18588 098 24X Fiche 50-336,83/05/11,8305250459.

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Progress Set list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc. 114pp 18697 009 24X Fiths 50-000,83/05/19,8303040040
- 8305270074 Forwards interim response to IE Builetin 82-02 re degradation of threaded fasteners in RCPB No linear indications found in steam generator manuay studs Five studs w/unacceptable mechanical damage replaced COUNSIL, H 0 . SEARB, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H 0 Northeast Utilities 83/05/19 MCRLEY, T E Region 1. Office of Director 3pp 18638 285 24% Fiche 30-336.83/05/19.8305270074
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040045
- R Periodic operating reports & related correspondence
- B305170010 Forwards monthly operating rept for Apr 1983
 MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast
 Utilities) MRGCZKA,E,J Northeast Utilities B3/05/12, Office
 of Resource Management, Director ip 18466 150 24X
 Fiche 50-336, 83/05/12, 8305170010
- --8305170014 Monthly operating rept for Apr 1983 GIBSON.J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/11. 5pp 18466 131 24X Fiche 50-336, 83/05/12,8305170010
- 8 Reportable occurrences. LERs & related correspondence
- 8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in 8mall Diameter Piping" BROWN,E J Reactor Operations Analysis Branch 83/04/19 8EYFRIT.K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated v/bration problems require addl supports or rerouting of piping BRONNE J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573
- B305270089 LER B3-015/03L-0 on B30421, control element assembly (CEA) 62 dropped fully into core Cause unknown Goil programmer power main & backup supplies tested & found satisfactory CEA uithdrawn & power returned to 100% W/830520 ltr. FGBTER R , MRGCKA, E J Northeast Nuclear Energy Co. (subs of Northeast Utilities) MRGCKA, E J Northeast Utilities. B3/05/20 MRGCKY, Region 1, Office of Director 2pp 18638 193 24% Fiche 50-336, B3/05/20, B305270089
- 8305270239 LER 83-017/03L-0 on 830418.during routine power operation, valve 2-81-616 taken out of svc to perform maint, Insp showed cracking in operator casing Cause under investigation by Limitorque Repairs will be made W/830520 ltr BEROIN, J M. MROCZKA, E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA, E J. Northeast Utilities 83/05/20 MURLEY, T E. Region 1. Office of Director 2pp 18637 184 24% Fiche 50-336, 83/05/20, 8305270239
- 8305270454 LER 83-016/03L-O on 830421, steam-driven auxiliary feedwater pump removed from svc for repacking Caused by natural end of life failure Pump repacked tested & returned to svc W/830320 Itr RESETAR, J. MRCCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRCCZKA, E. J. Northeast Utilities 83/05/20 MURLEY, T. E. Region 1, Office of Director 2pp 18641 329 24X Fiche 50-336, 83/05/20, 8305270434
- 8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520. Utils will measure vibration HAIBLERR K, Litton Industries, Inc. 83/05/20 KEPPLER, J Q Regian 3. Office of Director. 3pp. 18646, 212 24X Fiche 50-000, 83/05/20, 830573065

- POCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- f Security, medical, emergency & fire protection plans
- 0305050126 Informs that B30202 ltr provided changes to security plan, not personnel training & qualification programs, as stated STEMART, W L Virginia Electric & Power Co 83/03/24 MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 1p 18342 200 24% Fiche 50-000.83/03/24,8305050126
- 8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans
 CLARK, R A Decreting Reactors Branch 3 83/05/04 STEWART, W L Virginia Electric & Power Co App 18443 305 24X
 Fiche 50-338,83/05/04,8305130010
- --B305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by GA dept at least once per 12 months

 CLARK, R A Operating Reactors Branch 3 B3/05/04 10pp 18443 307 24X Fiche 50-338,83/05/04,8305130010
- --B305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7. respectively TRAMMECL.C M Operating Reactors Branch 3 83/05/04 2pp 18449 319 24X Fiche 50-038,83/05/04,8305130010
- 8305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EDF) updating 820408 response to Generic Ltr 82-33 Local EDF will be constructed adjacent or connected to existing training facilities SIEHART, H L Virginia Electric & Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 13pp 18436 215 24X Fiche 50-000, 83/05/06, 8305130058.
- 8305200094 Notifies that NUREG-0737, Item III A 2 i. "Emergency Preparedness Upgrade Emergency Plants to App E. 10CFR50." completed Item closed CLARK, R. A Operating Reactors Branch 3 83/05/10 STEHART, W L Virginia Electric & Power Co 3pp 18540 355 24X Fiche. 50-338, 83/05/10, 8305200094
- B305i10034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EIBENHUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000.83/05/11.8305110034
- Q Adjudicatory correspondence
- 8305030355 First request for production of documents & first interrogatories Certificate of Svc encl CELMAN, M R Virginia Electric & Power Co GELMAN, M R Hunton & Williams 83/04/29 Louisa County, VA 6pp 18303 303 24X Fiche 30-338, 83/04/29, 8305030555
- 8305190219 Response to request for production of documents Production will be permitted subj to encl stipulation of confidentiality Certificate of Svc encl OELMANM R Virginia Electric & Power Co 83/05/16 Louisa County, VA 8pp. 18502:180 24X Fiche 50-338,83/05/16,8305190219
- 8303200639 Response to interrogatories & request for documents
 Certificate of Svc encl Related correspondence
 ALBRECHT, V S Louisa County, VA ALBRECHT, V B Beveridge,
 Fairbanks & Diamond 93/05/16 Office of the Executive Legal
 Director 18pp 18526 024 24% Fiche 50-338,83/05/16.8305200659
- B305170223 Advises that info re operation of licensed nuclear reactors available in PDR MCOURREN,H J. Hearing Branch 1 B3/05/17 ALBRECHT,V 8 Beveridge, Fairbanks & Diamond. ip 18502 142 24X Fiche:50-338,83/05/17,8305190223
- P Operating license stage documents & correspondence
- 8305090144 Summarizes review of completed Generic Item B-24 re containment purge & vent & TMI Action Plan Item II E 4 2 BER & "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," encl CLARK, R. A. Operating Reactors Branch 3 83/04/20 STEWART, W L Virginia Electric & Power Co. 3pp 18367 072 24X Fiche: 50-338, 83/04/20, 8305090144

- --8305090149 Safety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purge isolation & other ESF sys # Office of Nuclear Reactor Regulation. Director 83/04/20 App 18367 075 24X Fiche 50-338,83/04/20.8305090144
- --8208060249 "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (8-24)." technical evaluation rept

 SARGENT, I , BTONE, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-207/208 82/08/04 CALVO, J NRC No Detailed Affiliation Given Sipp 18367 081 24X Fiche 50-338.83/04/20.8305090144
- 8305060017 Forwards 8ER re util responses to NUREG-0737. Items II F 1 4, "Containment Pressure Monitor." II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Items resolved CLARK.R A Operating Reactors Branch 3 83/04/21 STEWART,W L Virginia Electric & Power Co 8pp 18354 314 24X Fiche 50-338.83/04/21.8305060017
- B305060045 Advises that adequate justification provided for continue/ operation w/Dresser safety valves on primary side.per TMI Action Item II D I Generic safety evaluation & plantspecific info encl CLARK.R A Operating Reactors Branch 3 83/04/22 STEHART.W L Virginia filectric & Power Co 14pp 18354 346 24X Fiche 30-338.83/04/22.8305060065
- 8305060109 Forwards Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & availability Amends revise partial power multiplier & delete Unit 2 Tech Spec 4 2 2 2 g 2
 ENGLE, L. D. Operating Reactors Branch 3 83/04/22 STEWART, W.L. Virginia Electric & Power Co. 1p 18364 353 24X
 Fiche 50-338,83/04/22,8305060109
- --8309040120 Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively, revising partial power multiplier & deleting Unit 2 Tech Spec 4 2 2 2 g 2 CLARK, R A Operating Reactors Branch 3 83/04/22 26pp 18364 354 24X Fiche 50~338.83/04/22,8305060109
- --B305060136 Safety evaluation supporting Amends 46 & 27 to Licenses NPF-4 & NPF-7, respectively * Office of Nuclear Reactor Regulation, Director 18365 018 24% Fiche 50-338,83/04/22,8305060109
- --8305060140 Notice of issuance & availability of Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively CLARK, R A Operating Reactors Branch 3 83/04/22 2pp 18365 021 24X Fiche 50-338.83/04/22.8305060109
- 8305040173 Forwards 30-day response to NRC B30324 SER for environ qualification of safety-related electrical equipment, reaffirming justification for continued operation & submitting info for items in NRC Categories I B, II A & IV STEMART. H L Virginia Electric & Power Co B3/04/27 DENTON, H R Operating Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 3,014pp 18311 001 24X Fiche 50-33B,83/04/27,8305040173
- 8305040409 Responds to 830324 request to review proprietary matl contained in Franklim Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment One item identified as proprietary STEWART, W.L. Virginia Electric & Power Co. 83/04/29 DENTON, H.R. Office of Nuclear Reactor Regulation. Director CLARK, R.A. Operating Reactors Branch 3 ip. 18323 209 24X Fiche 30-338,83/04/29,8305040409
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Syr list encl EISENHUT, D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000 83/05/02/8305020455
- 8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans CLARK:R A Operating Reactors Branch 3 83/05/04 BTEWART:W L Virginia Electric & Power Co 4pp 18443 305 24X Fiche 50-338.83/05/04.8305130010
- --8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by GA dept at least once per 12 months
 CLARK.R A Deprating Reactors Branch 3, 83/05/04 10pp 18443 309 24X Fiche 50-338,83/05/04,8305130010

- --8305130023 Notice of issuance & availability of Amends 47 & 30 to ficenses UPF-4 & NPF-7, respectively TRAMMELL, C M Operating Reactors Branch 3 83/03/04 2pp 18443 319 24X Fichs 50-338.83/05/04.8305130010
- B305200709 Forwards Amends 48 & 31 to Literises NPF-4 & NPF-7, respectively safety & technical evaluations & notice of issuance & availability Amends change RETS to establish new limiting conditions for quarterly & annual release rates ENGLE.L B Operating Reactors Branch 3 83/05/05 STEWART,W L Virginia Electric & Pours Co 4pp 16539 199 244 Fiche 50-338.63/05/05,8305200709
- --8305200710 Ananda 48 k 31 to Licenses NPF-4 k NPF-7, respectively, changing REIS to establish new limiting conditions for operation for quarterly k annual average release rates CLARK, R A Gerating Reactors Branch 3 83/05/05 3pp 18599 203 24x Fiche 50-338.83/05/05,8305200709
- --R305200717 Safety evaluation supporting Amends 48 & 31 to Licenses IPF-4 & NPF-7. respectively e Office of Muclear Reactor Regulation, Director 83/05/05 7pp 18540 051 24% Fiche 50-338,83/03/03.8305200709
- --8305200720 "RETS Implementation (A-2)," technical evaluation rept CASSELL.A: CMEN.S: PANDEY,S Franklin Institute/Franklin Research Center NRC-03-91-130 TER-C5306-101/102 83/03/18 CGNOEL.F: WILLIS,C NRC - NO Detailed Affiliation Given 32pp 18340 058 24X Fiche 30-338.83/05/05,8305200709
- --8303200724 Notice of issuance & availability of Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively TRANMELL.C M Operating Reactors Branch 3 83/05/05 2pp 18540 090 24% Fighe 50-338.83/05/05.8305200709
- B305090659 Generic Ltr B3-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISEMHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc lopp 18627 153 24X
 Fichs 50-000.83/05/09,8305090659
- B305200499 Forwards response to Generic Ltr B2-28. "Inadequate Core Cooling Instrumentation Sys." per B30310 Itr During upset conditions, alarm functions provided in conjunction w/ subcooling munitors
 STEMART.H L. Virginia Electric & Power Co. B3/05/12 DENTON.H R
 Office of Nuclear Reactor Regulation. Director EISENHUT.D 0
 Division of Licensing 19pp 18313 182 24X Fiche 50-000, 83/05/12, 8303200499
- B305260323 Responds to 10CFR50 49(g) & NRC B30324 itr re electrical equipment important to safety Schedule for qualification or replacement submitted Haster list of equipment encl BTEMART; M. L. Virginia Electric & Fower Co. 63/05/20 DENTON, M.R. Office of Muclear Reactor Regulation. Director CLARK, R.A. Operating Reactors Branch 3 76pp 18626-007 24X
 Fiche 50-338,83/05/20,8305260329
- 8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Nestinghouse rept STEMART. IL Virginia Electric & Power Co 89/05/20 DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 tp 18637 325 24X Fiche 50-338,83/03/20,8305270220
- G Inspection reports, 1E Bulletins & correspondence
- B212040385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Busceptibility to Erothermic Chemical Reaction." Syc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pg 18308 319 24X Fiche.50-000.83/03/21,8212040385
- B305270517 Forwards IE Inap Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted pance. H C Division of Project & Resident Programs 83/03/29 8184ART, W L Virginia Electric & Power Co 2pp 18646 155 24% Fichs: 50-338.83/03/29,8305270517

- --8305270334 1E Insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted Major areas inspected internal & external exposures, surveys, plant tours, Unit 2 refueling outage preparation & offsite release records WRAY, J.R., BARR, R.P. Region 2, Office of Director 83/03/28 9pp 18646 157 24% Fiche 50-338,83/03/29,8305270517
- 8305270530 Forwards IE Ihsp Repts 50-338/83-05 & 50-339/83-05 on B30206-0305 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/04/01 STEMART,W L Virginia Electric & Power Co 2pp 18646-166 24X Fiche 50-338-83/04/01-8305270530
- --8305270544 IE Insp Repts 50-338/83-05 & 50-339/83-05 on 830206-0305 No noncompliance noted Major areas inspected outage activities. surveillance & maint activities. identified items. LERs & routine insps SHYMLDCK,M B Region 2, Office of Director JULIAN,C. Division of Project & Resident Programs 83/03/31 7pp 18646.168 24% Fiche 50-338,83/04/01,8305270330
- 8305270394 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in LE Insp Repts 50-338/83-01 &
- --B305270407 Responds to NRC B30204 ltr re violations noted in IE Jnsp Repts 50-338/83-01 & 50-339/83-01 Corrective actions: squipment failure trend anelysis program will be described, implemented & controlled by administrative procedure STEMART.W L Virginia Electric & Power Co B3/03/17 0'REILLY.U P Region 2. Office of Director. 4pp 18642:261, 24x Fiche 50-338,83/04/07,8305270394
- --8305270416 Confirms NRC approval to extend response time to notice of violation contained in IE Insp Repts 50-339/83-01 & 50-339/83-01 to 830318 STEHART, H L Virginia Electric & Power Co 83/03/09. D'REILLY, J P Region 2, Office of Director 1p. 18642 263 24% F(che 50-338,83/04/07.8305270394
- --8305270421 Forwards IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07 & notice of violation LEWIG.R C Division of Project & Resident Programs. 83/02/04 STEMART.W L Virginia Electric & Power Co 2pp 18642-266. 24X Fiche 50-338,83/04/07.8305270394
- --8305270430 Notice of violation from insp on 830103-07 * Region 2, Office of Director 83/02/04, 2pp 18642 268 24X Fiche 50-338,83/04/07,8305270394
- --8303270442 IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07. Noncompliance noted failure to perform all audits required by Tech Specs & to establish sys to evaluate equipment failures

 RELISLE G A . JACKBON, L H . SKINNER. P H Repion 2, Office of Director 83/01/26 10pp. 18642.270, 24X Fichs 50-338,83/04/07.8303270394
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator."
 Svc list and
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155, 24x Fichs: 50-000, 83/04/15, 8303040021
- 8305270238 Forwards IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/18, 87EWART,W.L Virginia Electric & Power Co 2pp 18637,173 R4X Fichs 50-338,83/04/18,8303270238
- --8305270244 IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted Major areas inspected inservice testing pumps & valves, data evaluation & review, corrective LER action & calibr of inservice insp tool ECONOMOS.N . BLAKE, J. J. Region 2, Office of Director. 83/04/14 Ppp 18637 175 24% Fiche 50-338,83/04/18,8305270238,
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103), 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383-087 24x Fiche 50-000,83/04/22,8303040023
- 8303270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety.

 O'RELLY-J P. Region 2, Office of Director B3/04/22, STEHART-W L. Virginia Electric & Power Co 2pp. 18646 001. 24x

 Fiche 30-000.83/04/22,8303270513

- --8305270527 Forwards 8ALP Repts 50-280/83-02,50-281/83-02,50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 LEMIS.R C Division of Project & Resident Programs 83/02/10 STEWART.W L Virginia Electric & Power Co 2pp 18646 003 24x Fiche 50-000,83/04/22,8305270513
- --8305270541 SALP Repts 50-280/83-02.50-281/83-02.50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 Region 2, Office of Director 83/02/10 45pp 18646 005 24X Fichs 50-000.83/04/22.8305270513
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Beneing Bys " Svc list encl JORDAN:E L Division of Emergency Preparadness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000:83/04/25,8303040025
- 8303040026 IE Info Notice 83-84, "Loose Parts in Secondary Side of Bteam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Ficha 50-000,83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setsoint Adjustment" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche. 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl UDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York. Inc 122pp 18441.170 24X Fiche 50-000,63/05/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " But list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Int 112pp 18382 282 24% Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Past 830103) 83/05/04 Consolidated Edison Co. of New York: Inc. 119pp 18441 001. 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18323 248 24X Fiche 50-000,83/05/04,8303040033
- B305270414 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-39 & 50-338/82-39 BANCE, H C Division of Project & Resident Programs B3/05/09 BTEMART, H L Virginia Electric & Power Co ip 18441 331 24X Fiche: 50-338, B3/05/09, B305270414
- --8305270426 Responds to NRC 830311 ltr re violations noted in IE Insp. Repts 50-338/82-39 & 50-339/82-39 Corrective actions emergency procedures revised to reflect Tech Spec 3 0 3 requirements
 SIEWART.M.L. Virginia Electric & Power Co 83/04/08
 0'REELLY.J P Region 2, Office of Director 4pp 18641 332 24X Fiche 50-338,83/05/09,8305270414
- --8305270437 Forwards IE Insp Repts 30-338/82-39 & 50-339/82-39 on 821106-1206 & notice of violation LEMIS.R.C. Division of Project & Resident Programs 83/03/11 BTEMART.W.L. Virginia Electric & Power Co. 2pp 18641 336 24% Ficher 50-338,83/05/09.8305270414
- --8305270448 Notice of violation from insp on 821104-1204 # Region 2, Office of Director 83/03/11 2pp. 18441 338 24X Fishe 50-338,83/05/07,8305270414
- ---8305270495 IE insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 Noncompliance noted failure to have EBF actuation sys operable & failure to perform required surveillance.

 SHYMLOCK.M. B Region 2. Office of Director. JULIAN.c. A Division of Project & Resident Programs 83/03/08 7pp. 18641,339 24X Fiche 30-338,83/05/09.8305270414
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003. 24X Fiche. 50-000, 83/05/11, 8303040034

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list enc!
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil" Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- S Reportable occurrences, LERs & related correspondence
- 8305230430 Forwards engineering evaluation rept. "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria ABHE, F Reactor Operations Analysis Branch 83/04/18 SEYFRIT, K V Reactor Operations Analysis Branch 2pp 18545-356 24X Fiche 30-000,83/04/18,8309230430
- --8305230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Machanisms." engineering evaluation rept LERs re safety-related battery degradation reviewed ASME.F. Reactor Operations Analysis Branch 83/04/18 5pp 18545 358 24X Fiche 50-000.83/04/18.8305230430
- 8305030158 Ferwards LER 83-016/03L-0 HARRELL-E W Virginia Electric & Power Co 83/04/20 D'REILLY, J P Region 2, Office of Director ip 16300 270 24X Fiche 50-338,83/04/20,8305030158
- --8305030165 LER 83-016/03L-0 on 830323, w/unit at 100% power, stiffener support not added to bus svc water auxiliary relay panel J per Design Change 80-8451 Caused by personnel error Stiffener support added HARRELL, E W Virginia Electric & Power Co B3/04/20 Region 2. Office of Director 3pp 16300 271 24X Fiche 50-338,83/04/20,8305030168
- B305030611 Forwards LER B3-019/03L-0 HARRELL.E W Virginia Electric & Power Co 83/04/21 O'REILLY, J P Region 2, Office of Director 1p 18306 098 24X Fiche. 50-338: B3/04/21. B305030611
- --B305030615 LER 83-019/03L-O on 830405, individual rod position indication for control bank C.rod D-12, deviated from group demand position Caused by instrument drift Instrument recalibr

 HARRELL, E H Virginia Electric & Power Co 83/04/21 Region 2, Office of Director. ip 18306 099 24X Fiche 50-338,83/04/21,8305030611
- 8305050186 Forwards LER 83-008/03L-0 HARRELL.E W Virginia Electric & Power Co 83/04/27 D'REILLY.J P Region 2, Office of Director 1p 18341 062 24X Fiche 30-328 83/04/27,8305050186
- --8305050191 LER 83-00B/03L-0 on 830410, review revealed that procedure used to restore boron injection tank concentration introduced potential unanelyzed injection flow diversions Caused by oversight Emergency procedures revised HARRELL-E W Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 3pp 18341 063 24X Fiche 30-338,83/04/27, 8305050186
- 8305110285 Forwards LER 83-020/03L-0

 HARRELL.E.W Virginia Electric & Power Co 83/05/05 O'REILLY, J P
 R**gion 2, Office of Director ip 18393.334 24X
 Fich** 50-338:83/05/05.8305110285
- --8305110288 LER 83-020/03L-0 on 830407, during surveillance testing, inside containment recirculation spray pump 1-R8-P-ID tripped Cause unknown Pump satisfactorily tested & returned to svc HARRELL, E W Virginia Electric & Power Co 83/05/05 Region 2 Office of Director 3pp 18393 335 24X Fiche 50-338,83/05/05,8305110285
- B305170406 Forwards LER B3-021/03L-0
 HARRELL.E W Virginia Electric & Power Co 83/05/10 0'REILLY, J P
 Region R. Dfrice of Director | Ip 18470: 124 24X
 Fiche: 50-338, B3/05/10, B305170406

- --B305170412 LER B3-021/03L-0 on B30411. Fire Door S-71-7 between svc bldg health physics area & auxiliary bldg would not self close Caused by removal of reclosure device for maint of closure coupling Reclosure device reinstalled HARRELL. E W Virginia Electric & Power Co B3/05/10 Region 2, Office of Director 3pp 18470 125 24X Fiche 50-338, 83/05/10.
- B305200144 RD on 830509. w/unit at 100% power, severe hydrogen leak discovered on hydrogen inner-cooled turbine generator Unit rampdown ordered & hydrogen vented to atmosphere Emergency terminated when pressure reached less than 10 psig HARRELL.E W Virginia Electric & Power Co 83/05/10 Region 2. Office of Director 2pp 18518 341 24X Fiche 50-338,83/05/10. 8303200144
- 8305200574 Forwards LER 83-022/03L-0 HARRELLE W Virginia Electric & Power Co 83/05/13 O'REILLY, J P Region 2, Office of Director 1p 18514 139 24X Fiche 50-338.83/05/13.8305200574
- --8305200583 LER 83-022/03L-0 on 830412 review of ASME XI IMV program identified 192 valves not exercised 8/or stroke timed Caused by fragmented implementation of testing program Programs upgraded HARRELL.E W Virginia Electric & Power Co 83/05/13 Region 2. Office of Director 3pp 18514 140 24X Fiche 50-338,83/05/13,8300200574.
- 8305230288 LER 83-023/03L-0 on 830423 low head safety injection pump I-SI-P-18 suction isolation valve failed to open. Caused by lack of Jubrication on valve stem to operator nut area Stem lubricated & stroled W/830518 ltr HARRELL.E W Virginia Electric & Power Co 83/05/18 D'REILLY, J P Region 2, Office of Director 3pp 18385 299 24X Fiche 50-338,83/05/18,8305250288
- 8305250417 LER 83-025/03L-O on 830429, while conducting surveillance test conditioning module TC-MM-100A to meteorological 33-ft temp chart recorder drifted 1 6 F Caused by instrument drift Module recally W/830518 ltr
 HARRELLE W Virginia Electric & Power Co 83/05/16 O'REILLY, J P Region 2, Office of Director 2pp 18583 360 24% Fiche 30-338,83/05/18,8305250417
- 8305270323 LER 83-026/03L-0 on 830426, calibr theck of delta T/TAVO protection channel I revealed erratic TAVG lead lag derivative card Cause undetermined Card replaced & channel calibr W/830920 ltr
 HARRELLE W Virginia Electric & Power Co 83/05/20 O'REJLLY, J P Region 2. Office of Director 3pp 18642 056 24X
 Fiche 50-338,83/05/20,8305270323
- DOCKET 90-339 NORTH ANNA POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- B305030126 Informs that B30202 ltr provided changes to security plan, not personnel training & qualification programs, as stated STEHART. W. L. Virginia Electric & Power Co B3/03/24 MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety ip 18342 200 24X Fiche 50-000, 83/03/24, 8305050126
- 9305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends ravise audit frequencies of station emergency & security plans
 CLARK.R A Operating Reactors Branch 3 83/05/04 STEWART.W L Virginia Electric & Power Co 490 18443 305 24X
 Fiche 50-338,83/05/04,8303130010
- --B305130017 Amends 47 & 30 to Licenses NFF-4 & NFF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by GA dept at least once per 12 months (CLARK-R A Deceating Reactors Branch 3 83/05/04, 10pp 18443 309 24X Fiche 30-336 83/05/04, 8305130010
- --8305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7-respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/04 2pp 18443 319 24% Fiche 50-338,83/05/04.8305130010.
- B305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EQF) updating B20408 response to Generic Ler 82-33 Local EOF will be constructed adjacent or connected to existing training facilities STEWART.W L Virginia Electric & Power Co B3/05/06 DENYON.H R DPPIce of Nuclear Reactor Regulation. Director 13pp 18436 215 24X Fiche 50-000,83/05/06.6305130038

- B305200074 Notifies that NUREO-0737. Item III A 2 1, "Emergency Preparedness Upgrade Emergency Plants to App E,10CFR50," completed Item Closed CLARK, R A Operating Reactors Branch 3 83/05/10 STEWART, W.L Virginia Electric & Power Co 3pp 18540 355 24X Fichs 50-338.83/05/10.8305200094
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, 8vc list encl procedures for law enforcement visits, EISENHUT, D @ Division of Licensing 83/05/11 Consolidatef Edison Co. of New York. Inc 16pp 18540 095 24X Fiche 50-000.83/05/11,8305110034

O Adjudicatory correspondence

- 8305030555 First request for production of documents & first interrogetories Certificate of Svc encl OELMAN.M R Virginia Electric & Power Co OELMAN.M R Hunton & Williams 83/04/29 Louise County, VA 6pp 18303:303 24X Fiche 50-338:83/04/29.8305030555
- B305190219 Response to request for production of documents Production will be permitted subj to encl stipulation of confidentiality. Certificate of Svc encl GELMAN/N R Virginia Electric & Power Co B3/05/16, Louise County, VA 8pp 18502,180 24X Fiche: 50-338,83/05/16,8305190219
- 8305200659 Response to interrogetories & request for documents
 Certificate of Svc encl. Related correspondence
 ALBRECHT, V B Louisa County, VA ALBRECHT, V B Baveridge,
 Feirbanks & Diamond 83/05/16 Office of the Executive Legal
 Director 18pp 18526, 024 24% Fiche 50-338, 83/05/16, 8305200659
- 8305190223 Advises that info re operation of licensed nuclear reactors available in FDR
 MCGURREN, H J Hearing Branch 1, 83/05/17, ALBRECHT, V S
 Beveridge, Fairbanks & Diamond ip 18502, 142, 24X
 Fiche 50-338,83/05/17,8305190223
- P Operating license stage documents & correspondence
- 8305090144 Summarijes review of completed Generic Item B-24 re containment gurgs & vent & TMI Action Plan Item II.E. 4 2 SSR & "Override & Reset of Control Circuitry in Ventilation/Purg Isolation & Other EGF Sys (B-24)." ancl. CLARK.R A Operating Reactors Branch 3. 83/04/20. STEMART, W L Virginia Electric & Power Co 3pp 18367 072 24X Fiche 50-338,83/04/20,8305090144
- --8303090149 Bafety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purge isolation & other ESF sys. # Office of Nuclear Reactor Regulation. Director #83/04/20 6pp 18367 075 24X Fiche. 50-938. 83/04/20. 8305090144
- --B208050249 "Override & Reset of Control Circuitry in Ventilation/Purys Isolation & Other ESF Sys (B-24)," technical evaluation rept BARGENT, I, STONE, J Franklin Institute/Pranklin Research Center NRC-03-79-118 TER-C5257-207/208, 82/08/04, CALVD, J NRC Nø Detailed Affiliation Given 31pp, 18367-081 24X 4 Fiche 50-338,83/04/20.8305090144.
- 8305060017 Forwards SER re util responses to NUREO-0737. Items II. F 1 4. "Containment Pressure Monitor," II F 1 5. "Containment Nater Level Monitor" & II F. i 6. "Containment Hydrogen Monitor" Items resolved CLARK.R A Uperating Reactors Branch 3. 83/04/21. STEWART.H L Virginia Electric & Power Co 8pp 18354;314 24X Fiche 50-338.83/04/21. 8305060017
- B305060065 Advises that adequate justification provided for continued operation w/Dresser safety valves on primary side, per TMI Action Item II D i Generic safety evaluation & plant-specific info anci CLARK.R.A Operating Reactors Branch 3 83/04/22, 81EWART.W L Virginis Electric & Power Co 14pp, 18354.346 24X Fiche 30-338.83/04/22,8305060065
- 8305040109 Forwards Amends 46 & 29 to Licenses NPF-4 & NPF-7: respectively, safety evaluation & notice of issuance & availability Amends revise partial power multiplier & delete Unit 2 fect Spec 4.2 2 2 2 EMOLE.L B Operating Reactors Branch 3 83/04/22 BTEMART; W L Virginia Electric & Power Co 1p. 18364 353, 24X Fiche 50-338,83/04/22,8305060109

- --B305060120 Amends 46 & 27 to Licenses NPF-4 & NPF-7, respectively, ravising partial power multiplier & deleting Unit 2 Tech Spec 4 2 2 2 g 2 CLARK, R A Operating Reactors Branch 3 B3/04/22 2dpp 18264 354 24X Fiche 30-338.63/04/22,8305060109
- --B305060136 Safety evaluation supporting Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively B Office of Nuclear Reactor Regulation, Director 18365 018 24X Fiche 50-338,83/04/22,8305060109 83/04/22 300
- --B305060140 Notice of issuance & availability of Amends 46 & 29 to Licenses NPF-4 & NPF-7; respectively CLARK,R A Operating Reactors Branch 3 83/04/22 2pp 18265 021 24% Fiche 50-338,83/04/22,8305060109
- 8305040409 Responds to 830324 request to review proprietary math contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment One item identified as proprietary STEMART, N. L. Virginia Electric & Power Co 83/04/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director CLARK, R.A. Operating Reactors Branch 3 ip 18323 209 24X Fiche 50-338,83/04/29,8303040409
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of Amends to D.ks Bvc list encl EISENHUT.D © Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fichs 30-000.83/05/02.8305020455
- 8305060283 Application for amend to License NPF-7, revising Tach Specs to support implementation of 2 5 F Tavg increase during current refueling outage Main steam line monoball support current refueling outage main steam line monocall support mads complete STEWART, W.L. Virginia Electric & Power Co. B3/05/03 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director CLARK, R.A. Decrating Reactors Branch 3 ip 18345-022 24X Fichs 50-339, 83/05/03, 8305060283
- 8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans CLARK,R A Operating Reactors Branch 3 83/05/04 STEWART,W L Virginia Electric & Power Co 4pp 18443 305 24X Fiche 50-338,83/05/04,8305130010
- --8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by GA dapt at least once per 12 months
 CLARK, R A. Operating Reactors Branch 3 83/05/04 10pp 18443 309. 24% Fiche.50-339,83/05/04,8305130010
- --B305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7: respectively TRAMMELL.C M Operating Reactors Branch 3 83/05/04 2pp 18443 319. R4X Fichs 50-338.83/05/04.8305130010
- 8305200709 Forwards Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, safety & technical evaluations & notice of issuence & availability Amends change RETS to establish new limiting conditions for quarterly & annual release rates ENGLE, L D Operating Reactors Branch 3 83/03/05 STEWART Virginia Electric & Power Co 4pp 18539 199 24X Fichs. 50-338, 83/05/05, 8305200709 05 STEWART, W L.
- --8305200710 Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, changing RET8 to establish new limiting conditions for operation for quarterly & annual average release rates CLARK, R A Operating Reactors Branch 3 83/05/05 3pp. 18397 203. 24X Fiche. 50-338, 83/05/05, 8305200709
- --8305200717 Bafety evaluation supporting Amends 48 & 31 to Licenses NPF-4 & NPF-7: respectively e Office of Nuclear Reactor Regulation, Director 83/05/05 7: 18340 OS1 24X Fiche. 20-338, 83/05/05, 8305200709. 83/05/05 7ga
- --8305200720 "REYS Implementation (A-2)," technical evaluation rept CABEELL A., CHEN.S., PANDEY, B. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05306-101/102 83/03/18 CONGEL, F. WILLIS, C. NRC No Detailed Affiliation Given 32p 18540 058 24X Fiche 50-338,83/05/05,8305200709
- --B305200724 Notice of issuance & availability of Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively TRAMMELL.C M. Operating Reactors Branch 3 83/05/05 Rpp 18340-090 24X Fiche 50-338,83/05/05,8305200709

- 8305120386 Submits status of License Condition 2 C(4)(c) Facility currently in second refueling outage New Rosemount resistance temp detector (RTD) Model 175K5 will be installed until redesigned RTD available STEWART.W L Virginia Electric & Power Co. 83/05/06 DENTON.F Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 2pp. 18432 269 24% Fiche 50-339.83/05/06.8305120386 DENTON, H. R.
- 8305070659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidates Edison Co of New York: Inc 14pp 18627 153 24X Fiche 50-000.83/05/09,8305070659 Consolidated
- 8305190253 Informs of status of NUREO-0737. Item II F i 3 recontainment high-range radiation monitors Qualified in-containment electrical terminations will be made per IE Bulletin 79-018 & NUREG-0388 schedule STEWART, W L Virginia Electric & Power Co 83/05/12 DEN OFFice of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 ip 18501 283 24X Fiche 50-339,83/05/12,8305190253
- 8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w' subcooling menitors
 8TEMART, W L. Virginia Electric & Power Co 83/05/12 DENTON, H R
 0ffice of Nuclear Reactor Regulation, Director 19pp 18513 182
 24X Fiche 50-000, 83/05/12, 8305200499
- 8305270130 Informs that License Conditions 2 C(15)(h)(2) & 2 C(15)(h)
 (4)re diesel generator reliability matisfied Mods will be
 completed no later than second refueling outage
 STEMART.W L Virginia Cleatric & Power Co 83/05/19 DENTON.H R
 Office of Nuclear Reactor Regulation, Director CLARK.R A
 Operating Reactors Branch 3 2pp 18638 201 24X
 Ficha 50-339.83/05/19,8305270150
- 8305260323 Responds to 10CFR50 49(g) & NRC B30324 ltm re electrical equipment important to safety Schedule for qualification or replacement submitted Master list of equipment encl STEMART.W L Virginia Electric & Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 76pp 18624 007 24X Fiche 50-338,03/05/20,0305260323
- B305270220 Requests extension until B30620 for completion of special lifting rig analysis per NUREQ-0612 Extension required due to late receipt of Westinghouse rept BTEMART,W L. Virginia Electric & Power Co B3/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A Dperating Reactors Branch 3 ip 18637 325 24% Fiche 50-338, B3/05/20, 6305270220
- 8305310099 Advises that backup overcurrent protection sys for containment electrical penetrations installed during second refueling outage Seismic design verification program in progress for containment recirculation fans STEHART, H. Virginia Electric & Power Co E3/05/24 DEN Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Unach 3 p 18655 104 24% Fiche 50-339.83/05/24,8305310099
- G Inspection reports, IE Bulletins & correspondence
- B305270143 Corrects B21124 response to violation noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Item B finding re RCS leakage removed as violation STEMART, N L Virginia Electric & Power Co B3/02/25 O'REILLY, J P Region 2. Office of Director 2pp 18638 161 24X Fiche 50-338,83/02/25,8305270143
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list Hoseepersaring to English the Burney of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison to of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212060385
- 8305270517 Forwards IE Insp Repts S0-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/03/29 STEHART, W L Virginta Electric & Power Co 2pp 18646 155 Fiche 50-338,83/03/29,8305270517
- --8305270534 IE insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted Major areas inspected internal & external exposures, surveys, plant tours, Unit 2 refueling outage preparation & offsite release records. WRAY, J. R., BARR, K. P. Region 2, Offsice of Director 83/03/28 9pp 18646 137 24X Fiche 50-338,83/03/29,8305270517

- 8305270530 Forwards IE Insp Repts 50-338/83-05 & 50-339/83-05 on B30206-0305 No noncompliance noted DAYCE H C Division of Project & Resident Programs 83/04/01 STEMART, W L. Virginia Electric & Power Co 2pp 18646 166 24X Fiche 50-336,83/04/01,8305270530
- --B305270544 IE Insp Repts 50-338/83-05 & 50-339/83-05 on B3020&-0305 No noncompliance noted Major areas inspected outage activities, surveillance & maint activities, identified items, LERs & routine insps BHYMLOCK, M B Region 2, Office of Director JULIAN, C Division of Project & Resident Programs 83/03/31 7pp 18446 168 24X Fiche 50-338,83/04/01,8305270530
- 8305270394 Act receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-338/83-01 & 30-339/93-01 LEWISIR C Division of Project & Resident Programs 83/04/07 BTEHART.H L Virginia Electric & Power Co 1p 18642.260 24X Fiche 30-338.83/04/07.8305270394
- ~~8305270407 Responds to NRC 830204 ltr re violations noted in IE Insp Repts 50~338/83~01 & 50~339/83~01 Corrective actions equipment failure trend analysis program will be described, implemented & controlled by administrative procedure STEWART.N L. Virginia Electric & Power Co 82/03/17 D'REILLY.J P Region 2. Office of Director App 18442 261 24X Fiche. 50~338,83/04/07,8305270394
- --8305270416 Confirms NRC approval to extend response time to notice of violation contained in IE Insp Repts 50-338/83-01 & 50-339/83-01 to 830318
 STEMART.N L Virginia Electric & Power Co. 83/03/08
 O'REILLY.J P Region 2. Office of Director 19 18642 265 24X
 Fichs 50-338.83/04/07.8305270394
- --8305270421 Forwards IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/02/04 STEMART.M L Virginia Electric & Power Co 2pp 18642 266 24x Fiche 50-338,83/04/07.8305270394
- --8305270430 Notice of violation from insp on 830103-07 * Region 2, Office of Director 83/02/04 2pp 18642 268 24X Fiche 50-338,83/04/07,8305270374
- --0305270442 IE (nsp Repte 50-336/83-0) & 50-337/83-0) on 830103-07 Noncompliance noted failure to perform all audits required by Tech Specs & to establish sys to evaluate equipment failures

 BELISLE: A , JACKSON, L H , SKINNER, P H Region 2, Office of Director 83/01/26 10pp 18642 270 24X Fiche 50-338,83/04/07,8305270374
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Byo list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 30-000,83/04/15,8303040021
- 8305270239 Forwards IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/18 STEMART, M L Virginia Electric & Power Co 2pp 18637-173 24% Fiche 50-338,83/04/18,8305270238
- --B305270244 IE Insp Repts 50-338/83-07 & 50-339/83-07 on 830321-30 No noncompliance noted Major areas inspected inservice testing pumps & valves data evaluation & reviews corrective LER action & calibr of inservice insp tool accommons. N. BLAKE, J. J. Region 2. Office of Director 83/04/14, Ppp 18637-175 24X Fichs 50-338,83/04/18,8305270238
- B303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list ent!
 ORRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/04/22 Consolidated Edison Co. of New
 York, Inc 112pp. 18383 089 24X Fiche 30-000,83/04/22,8303040023
- B303270513 Advises that BALP Board assessment reviewed & issuence of rept approved Nuclear activities conducted u/proper concern for nuclear safety
 O'REILLY.J P Region 2. Office of Director B3/04/22 STEWART.W L Virginia Electric & Power Co 2pp. 18646 001, 24X Fiche 30-000.839/04/22 8305270513
- --8305270527 Forwards SALP Repts 50-280/83-02.50-281/83-02.50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 LEHIS,R C Division of Project & Resident Programs 83/02/10 SIEMART,H L Virginia Electric & Power Co 2pp. 18646-003 24X Fiche 50-000.83/04/82.8305270513

- --8305270541 SALP Repts 50-280/83-02,50-281/83-02,50-338/83-03 & 50-339/83-03 for Jul 1981 Sept 1982 * Region 2, Office of Director 83/02/10 45pp 18646.005 24x Fiche 50-000.83/04/22.8305270513
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enc! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co. of New York, Inc 117pp 18381 271 24X Fiche 50-000,83704/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Denerators at PWRs " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18982 047 24X Fiche 50-000,03/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83704/28,8303040027,
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Reliaf Valve Discharge Line Vacuum Breakers " Svc list enc! JURDAN: E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York: Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382,282 24X Fiche. 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl. JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 30-000, B3/05/04, B303040031
- 8303040033 IE Info Notice 83-27. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/03/06. Consolidated Edison Co of New York
- 8305120047 Advises that inservice insp of low pressure turbing required by license condition, revealed cracks in discs at governor & generator end for low pressure turbine i & 2. Low pressure turbine rotors replaced investigation underway STEMART.W. L. Virginia Electric & Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R. A Operating Reactors Branch 3 2pp 18423 053 24X Fiche 50-337,83/05/06,8305120047
- 8305270414 Act receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-39 & 50-339/82-39 BANCE.H C Division of Project & Resident Programs 83/05/09 STEWART.W L Virginia Electric & Power Co 1p 18641/331 24X Fiche 50-338,83/05/09,8305270414
- --8305270426 Responds to NRC 830311 ltr re violations noted in IE Insp.
 Repts 50-339/82-39 & 50-339/82-39 Corrective actions'
 senergiency procedures revised to reflect Tech Spec 3.0 3
 requirements
 SIEMART.NL Virginia Electric & Power Co 83/04/08
 O'REITLLY, J P. Region 2. Office of Director 4pp 18641-332. 24X
 Fiche 50-338,83/05/09.8305270414
- --8305270437 Farwards 1E Insp Repts 50-338/82-39 & 50-339/82-39 on 821104-1206 & notice of violation LEMIS.R C Division of Project & Resident Programs. 83/03/11 STEMART.W L Virginia Electric & Power Co 2pp 18641:336 24X Fiche 50-338.83/05/07.8305270414
- --8305270448 Natice of violation from insp on 821106-1206 # Region 2, Office of Director 83/03/11. 2pp 18641 338. 24% Fishe 30-338,83/05/09,8308270414
- --8303270455 IE Insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 Noncompliance noted: failure to have ESF actuation sys operable & failure to perform required surveillance SHYMLOCK.M B Region 2: Office of Director JULIAN.C A Division of Project & Resident Fragrams. 83/03/08 7pp 18641 339 24X Fiche 30-338,83/05/09,8305270414

- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list and JARDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fichs 50-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 30-000,83/05/19,8303040040
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 011" Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/03/26 Consolidated Edison Co of New York
- S Reportable occurrences, LERs & related correspondence
- 8303030279 Forwards LER 83-025/03L-0
 HARRELL,E W Virginia Electric & Power Co 83/04/20 O'REILLY,J P
 Region 2, Office of Director ip 18300 056 24X
 Ficha: 50-339, 83/04/20, 8305030279
- --B305030283 LER 83-025/03L-0, on 83033i.w/unit in Mode 1, steam generator B water level channel 1 high-high turbine trip/feedwater isolation setpoint discovered greater than Tech Spec limit Caused by malfunctioning comparator card Card replaced HARRELL.E.W Virginia Electric & Power Co 83/04/20 Region 2, Office of Director ip 18300 057 24X Fichs 30-339,83/04/20, 8305030279
- 8305030357 Forwards LER 83-026/03L-0 HARRELL.E W Virginia Electric & Power Go 83/04/20 D'REILLY, J P Region 2, Office of Director 1 p 18291 340 24X Fiche: 50-339, 83/04/20.8303030357
- --8305030364 LER 83-026/03L-0 on 830402. Fire Doors 871-18 & 871-16 between 2H & 2J emergency diesel generator rooms & turbine bldg would not latch Causad by door strikes jammed open & bent Latches disassembled cleaned reassembled & tested HARRELL. E. W. Virginia Electric & Power Co 83/04/02 Region 2, Office of Director ip 18291 341 24X Fiche 50-339.83/04/20.8305030357
- 8305030635 Forwards LER 83-027/03L-0 HARRELL.E W Virginia Electric & Power Co 83/04/21 D'REILLY, J P Region 2, Office of Director 1p 18303 346 24X Fiche 50-339,83/04/21,8305030635
- --8303030440 LER 83-027/03L-0 on 830402,main steam safety velve pressure setpoints for valves 8V-MS-2016, 2026, 2034 & 6,2044 & 2054 found low Caused by setpoint drift Setpoints adjusted HARRELLE W Virginia Electric & Power Co 83/04/21 Region 2. Office of Director 2pp 18303 347 24X Fiche 50-339,83/04/21,8303030403
- B305050210 Forwards LER 83-027/03L-0 HARRELL.E W Virginia Electric & Power Co 83/04/27 O'REILLY, J P Region 2. Office of Director. ip 18398 106 24X Fiche: 50-339. 83/04/27. B305050210
- ---8305050215 LER 83-029/03L-0 on 830402, during Mode 4, automatic actuation of ECC8 occurred Caused by maint personnel standing on conduit resulting in loss of lo-lo pressurizer pressure safety injection block. Maint personnel reinstructed HARRELL.E W Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 3pp 18338 107 24X Fiche 50-339,83/04/27.
- 8305050271 Forwards updated LER 82-067/03X-1 HARRELLIE, W. Virginia Electric & Power Co. 83/04/27 O'REILLY, J.P. Region 2. Office of Director ip 18337.136 24X Fiche: 90-339, 83/04/27, 8305050271
- ---8305050274 Updated LER 82-067/03X-1 on 821017, steam generator C narrow range channel 2 indicated high Caused by failure of transmitter amplifier card Card replaced & loop recalibr. HARRELL, E. W. Virginia Electric & Power Co. 83/04/27. Region 2, Office of Director 2pp 18337-137. 24X Fiche 50-339.83/04/27, 8305030271.
- B305100023 Forwards LER B3-028/03L-0 HARRELL.E W Virginia Electric & Power Co B3/04/29. O'REILLY.J P Region 2. Office of Director. 1p 18377 148 24X Fiche: 50-339. B3/04/29. B305100023

- --B305100029 LER 83-028/03L-0 on B30402 amergency diesel generator 2J tripped on high crankcase pressure after emergency start signal, initiated from ECCB actuation, reset Cause unknown Generator started & tested satisfactorily Switch calibr HARRELL, E W Virginia Electric & Power Co 83/04/29 Region 2, Office of Director 2pp 18377 149 24X Fiche 50-339,83/04/29, 8305100023
- 8305100259 Forwards LER 83-030/03L-0 HARRELL,E W Virginia Electric & Power Co B3/04/29 O'REILLY,J P Region 2, Office of Director 1p 18371 335 24X Fiche 30-339,83/04/29,8305100259
- --B305100265 LER B3-030/03L-0 on B30406, pressure in nitrogen supply tank B for pressurizer PORV PCV-2435C drapped below min to consider PORV operable Caused by leak in pressurizer PORV nitrogen supply sys Mod scheduled during current outage HARRELL, E W Virginia Electric & Power Ca B3/04/29 Region 2, Office of Director 2pp 18371 336 24X Fiche 50-339,83/04/29, 8305100239
- B305110330 Forwards LER B3-023/03L-0 HARRELL.E W Virginia Electric & Power Ca B3/05/05 O'REILLY, J P Region 2. Defice of Director 10 18406 162 24X Fiche 50-339, 83/05/05, B305110330
- --8305110336 LER 83-023/03L-0 on 830414,RHR flow temporarily lost when one of two [n-series RHR suction valves closed Caused by open input breaker Breaker reclosed, vital bus restored, RHR suction valve reopened & flow restored HARRELL, E W Virginia Electric & Power Co 83/05/05 Region 2. Office of Director 2pp 18406 163 24X Fiche 50-339,83/05/05,8305110330
- 8305110453 Forwards LER 83-031/03L-0 HARRELL,E W Virginia Electric & Power Ca 83/05/05 O'REILLY, J P Region 2, Office of Director ip 18405 054 24X Fiche 50-339,83/05/05.8305110453
- ---B305110465 LER 83-031/03L-0 on B30408,w/unit in Mode 5, power lost to RNR subsystem A when 2H 4,160-volt mergency bus deenergized Caused by failure of fuses for 2H emergency bus undervoltage test circuit Fuses replaced HARRELLIE, W Virginia Electric & Power Co B3/05/05 Region 2, 07fice of Director 3pp 18405 050 24X Fiche 50-339,83/05/05, B305110453
- 8305200279 Forwards LER 83-032/03L-0 HARRELL.E.W Virginia Electric & Power Co 83/05/11 O'REILLY, J P Region 2. Office of Director ip 18516 260 24X Fiche 30-339.83/05/11.8305200279
- --8305200284 LER 83-032/03L-0. on 830412, during Mode 5, visual insp of hydraulic snubber 2-WGCB-HSS-3B revealed damaged reservoir w/o fluid Caused by personnel working in area Snubber replaced HARRELL, E W Virginia Electric & Power Co 83/05/11 Region 2 Office of Director 2pp 18516 261 24X Fichs 50-339, 83/05/11, 8305200279
- 8305250384 LER 83-036/03L-0 on 830429, while in Mode 6, loss of vital bus 2-1 resulted in loss of RHR flow for less than 1 minute when one of two RHR suction valves in series closed Caused by personnel shorting test lead Bus restored W/830518 ltr HARRELL.E W Virginia Electric & Power Co 83/05/18 0'REILLY, J P Region 2, Office of Director 4pp 18572 076 24X Fiche 50-339,83/05/18,8305250384
- B305270335 LER B3-035/03L-0 on B30423 & 24.86 lockout relay wiring omission detected while testing bus 2H charging high head safety injection pump breakers Caused by incorrect wiring Hiring properly installed H/B30520 ltr HARRELL.E W Virginia Electric & Power Co B3/05/20 O'REILLY, J P Region 2, Office of Director 4pp 18444 359 24% Fiche 50-339,83/05/20,8305270335
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8305020370 Responds to NRC 830316 itr requesting schedule for addressing unqualified electrical components in safety-related sys Issue will be addressed in environ qualification update by 830701
 TAUBER, H Detroit Edison Co 83/04/25 YOUNGBLOOD, B J Licensing Branch 1 p 18276 342 24X Fiche 50-341.83/04/25.8305020370

- 8305030171 Forwards "Independent Design Verification Program, Final Rept." Vols 1,2 & 3 Rept presents results & conclusions of review conducted per 821216 independent design verification program pian
 FERG.D A Cygne Energy Services 83/04/29 YOUNOBLOOD, B J
 Livensing Branch 1 COLSERT, W.F. Detroit Edison Co. 1p
 18287 060 24X Fiche 30-341/83/04/29, 8305030171
- --8305030178 "Independent Design Verification Program Final Rept," Vols 1.2 % 3 FERG.D A Cygna Energy Services TR-83021-1 R00 83/04/29 878pp 18289 041 24X Fiche 50-341.83/04/29.8305030171
- 8305050004 Forwards Pages 2 20-2 32 inadvertently omitted from "Independent Design Verification Program Final Rept" FERG.D A Cygna Energy Services 83/05/03 YOUNGBLOOD, B J Licensing Branch 1 1p 18338 316 24X Fiche 50-341.83/05/03,
- --8305050010 Pages 2 20-2 32 inadvertently omitted from "Independent Design Verification Program Final Rept"

 * Cygna Energy Services TR-83021-1 ROO ERR 83/05/03 12pp 1838 317 24X Fiche 50-341.83/05/03.8303050004
- 8305100119 Forwards summary of post-accident sampling analytical procedures per 820707 ltr Info describes type of analysis, equipment, suitability, range & analytical method TAUBER, H Detroit Edison Co E3/05/03 YOUNGBLOOD, B J Licensing Branch 1 2pp 18374 361 24X Fiche 50-341,83/05/03,8305100119
- 8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notification 83-17 & 83-44 re Unresolved Safety Issue A-17 EIEENKUT.D © Division of Licensing 83/05/04 PALLADINO.N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,8305040323
- B305120231 Notification of B30513 meeting w/util in Bethesda,MD to discuss general procedures followed by NRC in responding to pending Section 2 206 petition LYNCH-M D Licensing Branch 1 B3/05/06 YOUNGBLOOD,B J. Licensing Branch 1 3pp 18435 263 24X Fiche 50-341,83/05/06,8303120231
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York: Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659
- B305250207 Notification of Caseload Forecast Panel B30607~07 site visit to estimate const completion date Agenda and LYNCH, M D Licensing Branch 1 83705/12 YOUNDBLOOD, B J Licensing Branch 1 6pp 18595 352 24X Fiche 50-341.83/05/12, B305250207
- 8305230552 Summarizes 821207 conference call re-current plan for conducting induction heating stress improvement (IMSI) program on appropriate welds in recirculation sys TAUBER: H Detroit Edison Co 83/05/18 YOUNDBLOOD, 8 J Licensing Branch I 2pp 18537 090 24% Fiche 50-341.83/05/18.8305230552
- F Security, medical, emergency & fire protection plans
- 8305020264 Forwards IE Bafeguards Insp Rept 50-341/83-05 on 830101-0228 & notice of violation NGRELIUS.C E Division of Project & Resident Programs 83/04/11 WELLS.D A Detroit Edison Co 2pp 18277 095 24X Fiche 50-341.63104/11.8305020264
- --8305020274 Notice of violation from insp on 830101-0228 NORELIUS.C E Division of Project & Resident Programs 83/04/11 Rep 18277 097 24% Fiche 50-341,83/04/11,8305020264
- ---8305020285 IE Safeguards Insp Rept 50-341/83-05 on 830101-0228
 Noncompliance noted failure to follow reactor yessel flow procedures & imadequate review of procedure changes & identification & control measures
 LITTLE, B H . BYRON, P. M . WESCOTT, H M Region 3. Office of Director 83/04/04 i3pp 18277 077 24X Fiche 50-341,83/04/11,8305020284
- 8303090480 Forwards Michigan Emergency Preparadness Act MCLA 30 401, FEMA 830420 memo per ASLAP 830504 request on emergency preparadness issues. Michigan State Police 830408 ltr & Monros County GFC of Civil Preparadness 830318 ltr & LANDORAF, L.C. LeBoeuf, Lamb, Leiby & MacRae, LANDORAF, L.C. Detroit Edison Co. 83/05/05. EILPERIN, B.F., MDDRE, T.B., QDTCHY, R.L. Atomic Safety and Licensing Appeal Panel 46pp 18362 279 24X Fiche 50-341,83/05/05,8305090480.

- 8305110620 Notification of 830512 meeting w/util in Bethesda,MD to discuss fire protection of safety-related cables including adequacy of 3-h fire blankets fire stops & heat conduction LYNCH,M D Licensing Branch 1 83/05/06 YOUNGBLOOD,B J i/censing Branch 1 3pp 18416 360 24X Fiche 50-341,83/05/06, 970810620
- B305250219 Notification of postponement of B30512 meeting w/util in Bathesda.MD to discuss fire protection of safety-related cables Meeting to be rescheduled LYNCH.MD Licensing Branch 1 83/05/10 YdUNOBLOOD.BJ Licensing Branch 1 3pp 18576 359 24X Fiche 50-341,83/05/10,8305250219
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law anforcement visits Svc list encl
 EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 075 24X Fiche' 50-000, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983 DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADIND,N J Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13,8305240213
- G Inspection reports, IE Bulletins & correspondence
- B21R0603B5 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR. J M Division of Safeguerds & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 1830B 319 24% Ficher 50-000, 83/03/21, 821R060385
- 8305020264 Forwards IE Safeguards Insp Rept 50-341/83-05 on 830101-0228 & notice of violation NGRELIUS.C & Division of Project & Resident Programs 83/04/11 WELLS.D A Detroit Edison Co 2pp 18277 095 24X Fiche 50-341:83/04/11,8305020264
- --8305020274 Notice of violation from insp on 830101-0228 NORELIUS, C E Division of Project & Resident Programs 2pp 18277 097 24% Fiche 50-341.83/04/11.8305020264
- --8305020285 IE Safeguards Insp Rept 50-341/83-05 on 830101-0228
 Noncompilance noted failure to follow reactor vessel flow
 procedures & inadequate review of procedure changes &
 identification & control measures
 LITILE B H, BYRON, P M, WESCOTT, H M Region 3, Office of
 Director 83/04/04 13pp 18277 099 24X Fiche 50-341,83/04/11,8305020264,
- 8303040021 IE Info Notice 83-21: "Defective Emergency Use Respirator "
 Svc list encl.

 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Railef Valve Failures "
 Evc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- #303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sty " Svc list encl "JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) #83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025
- B305170294 Forwards IE Insp Rept 50-341/83-04 on B30214-0317 & notice of violation.

 SPESSARD: R L Division of Engineering 83/04/27 WELLS: D A Detroit Edison Co 2pp 18466 107 24X Fiche 50-341,83/04/27, 8305170294
- --8305170298 Notice of violation from insp on 890214-0317 8PE89ARD,R L Division of Engineering 83/04/27 3pp. 18466 109 24% Fiche 30-341.83/04/27,8305170294
- --8305170304 IE Insp Rept 50-341/83-04 on 830214-0317 Noncompliants noted failure to identify & segregate nonconforming cables, adequately control temporary mod in test procedure & properly control & tag lifted leads REIMANN.F W . REYES, L A Region 3. Office of Director 83/04/27 7pp 18466-112 24X Fiche 50-341.83/04/27,8305170274

- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDANLE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 9303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post #30103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305100388 Ack receipt of 830331 ltm informing NRC of steps taken to rorrect violations noted in IE Insp Rept 50-341/82-14 SPEBSARO,R L Division of Engineering 83/05/04 WELLS,D A Detroit Edison Co ip 18381 018 24X Fiche 30-341,83/05/04, ends100388
- --B305100393 Amends B30222 response to NRC B21203 ltr re violations noted in IE Insp Rept 50-341/82-14 Corrective actions GC mgt will follow Daniel Bite Administrative Procedure AP-VII-02 re deviation disposition request HELLS.D A Detroit Edison Co B3/03/31 LITTLE.W S Region 3, Office of Director 11pp 18381 019 24X Fiche 50-341.83/05/04, 8305100388
- -8305100399 Responds to NRC 821203 ltr re violations noted in IE Insp. Rept 50-341/82-14 Corrective actions Deviation Disposition Request (DDR) 1757 revised to require originator quality manager to provide copy of void DDR WELLS, D.A. Detroit Edison Co. 83/02/22 LITTLE, W.S. Region 3, Office of Director 10pp 18381 030 24% Fiche 50-341,83/05/04,8305100388
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Ficha 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORPAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/19 Consolidated Edicon Co of New
 York, Inc 114pp 18497 009 24X Fiche 30-000,83/05/19,8303040040
- 8305270261 Forwards IE Insp Rept 50-341/83-08 on 830411-13 No noncompliance noted PAPERIELLO,C. J. Region 3, Office of Director 83/05/25, WELLS,D A Detroit Edison Co 2pp 18642 816 24X Fiche 50-341,83/05/25, 8305270261
- --8305270270 IE Imap Rept 50-341/83-08 on 830411-13 No noncompliance noted Major areas inspected preoperational radiological environ monitoring program including mgt control, program implementation & results & GC GESTHANN, H J , ROZAK, S., SCHUMACHER, M Region 3, Office of Director, 83/05/25 7pp 18442.018 24X Fiche 50-341,83/05/25,8305270261
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- 8303030474 Interim deficiency rept re Fisher Control valve actuators not meeting seismic requirements Initially reported on 801231 New actuators ordered Engineering specs for Class 3 valves revised for future purchases

 WELLS, D A Detroit Edison Co 83/04/15 KEPPLER, J G Region 3, Office of Director 2pp 18308 194 24% Fiche 50-341, 83/04/15.
- 8305030585 Final deficiency rept re defective Agastat relays Initially reported on 820205 One relay mfg by Amerace Corpshipped to Pecility Relay removed on B21001 & returned to manufacturer for insp & possible replacement HELLB.D A Detroit Edison Co 83/04/15 KEPPLER.J O Region 3. Defice of Director 2pp 18306 092 24X Fiche 50-341.83/04/15.83050585
- 8305030596 Interim deficiency rept re calibr of Rosemount Model 310 DU trip units Initially reported on 820720 Potentiameters replaced u/components containing gold contacts to prevent oxidation of trip setpoint WELLS.D A Detroit Edison Co 83/04/15 KEPPLER.J 0 Region 3. Office of Director 2pp 18303 212 24X Fiche 50~341.83/04/15. 830050596
- 8305030367 Interim deficiency rept re potential failure of ITE 4,140-volt circuit breakers due to cracks in puffer piston shafts initially reported on 830321 Dne failure observed at linkage connecting pin on shaft MELLS,R A Detroit Edison Co 83/04/18 KEPPLER, J G Region 3, Office of Director ip 18306 216 24X Fiche 50~341.83/04/18, 830503030369
- 8305020085 Deficiency rept re questionable qualification of certain LK Comstock GC personnel Initially reported on 830311 Certification files updated to reflect prior work experience Const not adversely affected MELLS,D A Detroit Edison Co 83/04/20 KEPPLER, J G Region 3, Office of Director 2pp 18278 248 24X Fiche 50-341,83/04/20,8305020085
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.8 F Niggara Mohauk Power Corp 83/04/24 STARUSTECKI.R Region J. Office of Director 2pp 18433 072 24X Fiche 50-000.83/04/26,8305120392
- --B305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEC-923 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY, D C Rockwell International Corp B3/03/11 COLLINS, J T Region 4. Office of Director Spp 18433 074 24X Fiche 30-000, 83/04/26, 8305120392
- 8305100015 Interim deficiency rept re loose nuts on drywell & steam tunnel beams of structural steel sliding connection 92 Initially reported on 830028 Deviation Disposition Request MP-11006 initiated on 830406 WELLS.D A Detroit Edison Co 83/04/28 KEPPLER.J Q Region 3, Office of Director 1p 18377 153 24X Fiche 50-341.83/04/28, 8305100015
- 8303100118 Final Deficiency Rept 73 re reactor mode switch failure Initially reported on 820701 Switch handle replaced Documentation for replacement switch handle acceptable WELLS,D A Detroit Edison Co 83/04/29 KEPPLER, J O Region 3, Office of Director ip 18375 031 24% Fiche 50-341,83/04/29, 8303100118
- B3D5100154 Final Deficiency Rept B3 re overpressurization of standby liquid control sys pump II Initially reported on B21206 Caused by disconnected terminal wire on relay No sys damage sxiets Item not reportable per 10CFR50 55(e)
 HELLS.D A Detroit Edison Co B3/05/05 KEPPLER.J G Region 3, Office of Director 2pp 18374 217 24X Fiche 50-341,83/05/05,8305100154
- 8305170207 Final deficiency rept (Item 81) re arc strikes on primary containment pipe penetration bellows Initially reported on 821123 Analysis of bellows regair revealed fatigue test met ABME requirements Item not reportable per 10CFR50 55(e) WELLS,D A Detroit Edison Co 83/05/06 KEPPLER.J G, Region 3, Office of Director 2pp 18466 328 24X Fiche 50-341,83/05/06.8305170207

- 8305170535 Interim deficiency rept (Item 93) to GE error in RHR HX flow calculations Initially reported on 830406 GE gerformed evaluation of flow deficiency & concluded lower baffle plates of HXs required mod & rework HELLS, D. A. Detroit Edison Co. 83/03/06 KEPPLER, J. G. Region 3, Office of Director 2pp 18467-356 24X Fiche 50-341.83/05/06.8305170335
- 8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration HAISLER, R K Litton Industries, Inc. 83/05/20 KEPPLER, J Q Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20, 2009370255

T Hearing transcripts on non-antitrust matters

8305060188 Transcript of 830504 oral argument in Bethesda, MD Pp 1-76 a Atomic Safety and Licensing Appeal Panel B3/05/04 78pp 18345 112 24X Fiche 50-241, 83/05/04, 8305060188

DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8305040417 Requests exemption from fire protection requirements of Section III G 2 of App R to 10CFR50 per 10CFR50 12 re 45-ft elevation of fuel & auxiliary bldg Proposed mods provide adequate level of grotection HITHERS.B D Portland General Electric Co 83/04/27 CLARK.R A Operating Reactors Branch 3 5pp 18322 121 24X Fiche 50-344.83/04/27.8305040417
- 8305040666 Forwards Amend 80 to License NPF-1 & notice of Issuance & availability Amend adds License Condition 2 C (10) re implementation of IAEA safeguards at facility CLARK, R A Operating Reactors Branch 3 83/04/27 WITHERS.B D Portland General Electric Co 4pp 18357 335 24X Fiche 50-544,83/04/27.8305060666
- --8305060669 Amend BQ to License NPF-i.adding License Condition 2 C (10) (per 10CFR75 B) re implementation of IAEA safeguards at facility in response to 830323 ltr CLARK,R A Operating Reactors Branch 3 83/04/27 7pp 18357 339 24X Fiche 50-344.83/04/27.8305060666
- --8305060670 Notice of issuance & availability of Amend 80 to License NPF-1 CLARK.R A Operating Reactors Branch 3 83/04/27 2pp 18357 346 24X Fiche 50-344.83/04/27.8305060666
- 8305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs to clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D © Division of Licensing, 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fich. 50-000.83/05/11.8305(10034
- 8305200030 Notifies that NUREO-0737.Itam III A 2 1. "Emergency Preparedness.Upgrade Emergency Plans to App E. 10CFR50." completed Itam closed CLARK.R A Operating Reactors Branch 3 83/05/12 HITHERS, B D Portland General Electric Co 3pp 18540 120 24X Fiche 30-244.83/05/12.8305200030.
- P. Operating license stage documents & correspondence
- 8305230581 Forwards lists of NRC initiated & TMI-related backfit items, in response to 830208 ltr Backfitting costs resulting from utils own needs also provided.

 WITHERS B D Portland General Electric Co 83/03/24
 TOURTELLOTTE. J Regulatory Reform Task Force 4pp 18541 314 24X
 Fiche 30-344,83062/24,8308230581
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTELJ Regulatory Reform Task Force 83/04/11 PALLADING, N J Commissioners 2pp 18542 272 24X Fiche 50~000.83/04/11.8305230720
- 8305060666 Forwards Amend BO to License NPF-1 & notice of issuance & availability Amend adds License Condition 2 C (10) re implementation of IAEA safeguards at facility CLARK,R A Operating Reactors Branch 3 83/04/27 WITHERS,B D Portland General Electric Co. 4pp 18357 335 24X Fiche 50-344.83/04/27,8305060666

- --8305060669 Amend 80 to License NPF-1, adding License Condition 2 C ((0) (per 10CFR75 B) re implementation of IAEA safeguards at Facility in response to 830323 ltr CLARK, R A Operating Reactors Branch 3 83/04/27 7pp 18357 339 24X Fiche 50-344, 83/04/27, 8305060666
- --8305060670 Notice of issuance & availability of Amend 80 to License NPF-1 CLARK.R A Operating Reactors Branch 3 83/04/27 2pp 18357 346 24X Fiche 50-344.83/04/27.8305060666
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licenses; re new procedures for providing public notice concerning issuance of amends to U.S. Svc. list encl.
 EISENHUT, D.G. Division of Licensing 83/05/02 Consolidated Edison Co. of New York. Inc. 30pp. 18441 120 24X
 Fiche 30-000.83/05/02.8305020455
- 8305060600 Forwards application for amend to License NPF-1 to allow continued use of fuel assemblies modified w/stainless steel rods & partial grids Centificate of Svc for License Change Application 90 encl WITHERS, B.D. Portland General Electric Co 83/05/02 CLARK, R.A. Operating Reactors Branch 3 ip 18348 358 24X Fiche 50-344x 83/05/02, 8305060600
- --8305060604 Application for amend to License NPF-1 to allow continued use of fuel assemblies modified w/stainless steel rods & partial grids
 MITHERS.8 D Portland General Electric Co 83/05/02 9pp.
 18348 358 24X Fichs.50-344.83/05/02.8305060600
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627:153 24X Fiche 30-000.83/05/09.8305090659
- 8305130240 Advises that Cycle VI core physics data values & plot requested by Tech Spec & 9 i 10 cannot be submitted on schedule due to design delay in design of core Approval of delayed submittal requested WITHERS, B D Portland General Electric Co 83/05/09 MARTIN, J B Region 5, Office of Director 2pp 18439 193 24X Fiche: 50-344, 83/05/09, 8305130240
- 8303200013 Advises that hydrogen vent valve replacement scheduled for 1983 refueling outage postponed until 1984 refueling outage or next permissible date per operating schedule Delay caused by late valve delivery from mfg HITHERS.B D Portland General Electric Co 83/05/13 CLARK.R A Operating Reactors Branch 3 ip 18919 083 24X Fiche 50-344,83/05/13,8305200013
- 8305260275 Forwards lists identifying safety-related electric equipment subj to environ qualification.per 10CFR30 49(g) Hydrogen vent valves will not be replaced w/fully qualified valves until 1984 refueling outage
 HITHERS.8 D Portland Denemal Electric Co 83/05/20 CLARK.R A Operating Reactors Branch 3 21pp 18623 213 24X
 Fiche 50-344,83/05/20,8303260275
- 8305270182 Forwards License Change Application 92 requesting amend to License NFF-1 Amend revises manipulator crane operability load testing requirements WITHERS, B.D. Portland General Electric Co. 83/05/24 CLARK, R.A. Operating Reactors Branch 3 ip 18637 352 24X Fiche 50-344,83/05/24,8305270182
- --8305270186 Licensa Change Application 92 revising manipulator crane operability load testing requirements WITHERS.B D Portland General Electric Co 83/05/24 3pp 18637 353 24% Fiche 50-344,83/05/24,8305270182
- --8305270188 Proposed Tech Specs revising manipulator crans operability load testing requirements * Portland General Electric Co 83/05/24 2pp 18637 356 24% Fichs 50-344.83/05/24.8305270182
- 8305270205 Forwards License Change Application 91 for amend to License NPF-1: revising MSIV & pressurized code safety valve surveillance requirements WITHERS.8 D Portland General Electric Co 83/05/24 CLARK, R A Operating Reactors Branch 3 1p 18641.202 24X Fiche 50-344,83/05/24,8305270205
- --8305270211 License Change Application 91 for amend to License NPF-5; revising MBIV & pressurized code safety valve surveillence requirements HITHERS, B D Portland General Electric Co 83/05/24 4pp 18441:203 24X Fiche 50-344,83/05/24,8305270205

- --B305270282 Proposed Tech Spec revising MSIV & pressurized code safety valve surveillance requirements # Portland General Electric Co B3/05/24 3pp 18641 207 24X Fiche 50-344.83/05/24,B305270205
- @ Inspection reports, IE Bullstins & correspondence
- 8212040385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR.J H Division of Safeguards & Inspection Programs (Post
 - encl TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308-319 24X Fiche 50~000.83/03/21,8212060385
- 8305170562 Forwards IE Insp Rept 50-344/83-08 on 830323-25 No noncompliance noted BOCK, H.E. Region 5, Office of Director 83/04/08 WITHERS, B D Portland General Electric Co 2pp 18468 144 24X Fiche, 30-344, 83/04/08, 8305170562
- --B305170567 IE Insp Rept 50-344/83-08 on 830322-25 No noncompliance noted Major areas inspected radiation protection program, including procedures, surveys, general employee training, poeting & labeling & external & internal exposure control CILLIS,M , MENELAWSKI.F A , BOOK,H E Region 5, Office of Director 83/04/07 (1pp 18468-148) 24X Fiche 50-344,83/04/08,8305170562
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 Byc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15. Consolidated Edison Co of New

 York, Inc 126pp 18435 155 24X Fichs 50-000,83/04/15,8303040021
- York, Inc 126pp 18435 155 24x Fichs 30-000,83/04/15,830304002
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Volve Failures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24x Fiche 30-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JCRPAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28.8303040027
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/05/03 Consolidated Edison Co. of New York: Inc 122pp. 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New Yark, Inc 112pp 18382;282 24X Fiche 50-000.83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated,Edison Co of New York, Inc. 119pp 18441,001 24X Fiche 50-000.83/05/04,8303040031.
- B303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl.

 JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06, Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 9305130164 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of dissel generators No check valves located in sys. Sys consists of closed cooling loop for each unit, which is cooled by evc water sys.

 HITHERER D Portland General Electric Co 83/05/09 MARTIN, J B Region 5. Office of Director 2pp 18437 299 24X

 Fichs: 50-344, 83/05/09, 8305130164

- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidate Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- #303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"

 Byc list encl

 JORDAN: E. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New

 York, Inc. 114pp 18697 009 24X Fichd 50-000,83/05/19.8303040040
- B303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Pust B30103) 83/05/26 Consolidated Edison Co. of New York, Inc. 144pp 18647 007 24X Ficha 50-000.83/05/26.8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305130224 Forwards updated LER 63-001/01X-1 Detailed event enalysis encl WITHERS, B D Portland General Electric Co 83/04/22 MARTIN, J B Region 5, Office of Director 3pp 18439 323 24X Fiche 50-344,83/04/22,8305130224
- --B305130292 Updated LER 83-001/Q1X-1 on B30106, as-built conditions in masonry walls differed from conditions in previous seisoic response analyses Cause not stated Further investigations in progrems
 BUSHNELL-T E Portland General Electric Co B3/04/21 Region
 5, Office of Director ip 18439 326 24X Fiche 50-344,83/04/22,8305130224
- 8305130143 Forwards LER 83-003/03L-O Detailed event analysis encl YUNDT.C P Fortland General Electric Co 83/04/27 MARTIN, J B Region 5, Office of Director 3pp 18438 127 24X Fiche 50-344, 83/04/27, 8305130143
- --B305130132 LER 83-003/03L-0 on B30327, plant did not have emergency power source to boric acid transfer pump used in flowpath from boric acid storage tank during core alterations Caused by personnel error Procedure will be clarified BAIR.0 G Portland General Electric Co 83/04/27 Region 5, Office of Director 1p 18438 130 24X Fiche 50-344,83/04/27,8305130143
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8305100011 Forwards final rept of BNWL participants at 830413-14 emergency preparedness exercise Areas covered include technical support ctr, control roum, operations support ctr & offsite monitoring teams
 MARTIN.J B. THOMAS.W V Battelle Memorial Institute, Pacific Northwest Laboratory 83/04/22, PLOSKI, 1 Region 3, Office of Director 24pp 18377 137 24X Fiche 30-346,83/04/22,8305100011
- 8305100080 Ferwards IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted Notices of deficiencies & deviations encl. PAPERIELLO,C J Region 3, Office of Director 83/04/22 CROUSE,R P Toledo Edison Co 2pp. 18377 230 24X Fiche 50-346-83/04/22-8305100080
- --8305100082 Notice of deficiencies from insp on B30315-18 * Region 3, Office of Director, 83/04/22 3pp 18377 232 24X Fiche 50-346,83/04/22,8305100080
- --8303100084 Notice of deviation from insp on 830315-18
 * Region 3, Office of Director 83/04/22 2pp 18377 235 24X
 Fiche 50-346.83/04/22,8305100080
- ---8305100090 IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted, Major areas inspected followup insp of items identified during emergency preparedness implementation appraisal on 830208-19.
 PLOSKI, T. J., AXELSON, W. L. Region 3. Office of Director 83/04/20 12pp 18377 237. 24X Fiche 50-346, 83/04/22,8305100080
- 8305060595 Releases public version of temporary mod request to emergency plan implementing procedure FELTON.J.M Division of Rules and Records 83/04/25 Document Management Branch 19. 18359 185 24X Fiche 50-346.83/04/25, 8305060595

- --9305060601 Forwards public version of Temporary Mod Request T-7104 to Emergency Plan Implementing Procedure El 1300 07,
 "Technical Support Ctr Activation " Receipt form encl
 4 Toledo Edison Co 83/04/1t NRC No Detailed Affiliation
 Given ip 18359 186 24X Fiche 50-346,83/04/25,8305060595
- --B305060608 Public version of Temporary Mod Request T-7104 to Emergency Plan Implementing Procedure EI 1300 O7. "Technical Support Ctr Activation" Rev 27 to Index encl DURDELR FARIS, JA N MURRAY, T D Toledo Edison Co 83/04/05 3pp 18359 187 24% Fiche 50-346.83/04/25.8305060595
- 8305060692 Releases public version of rev to emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18358 156 24% Fiche 50-346,83/04/25, 8305060692
- --8305060699 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure El 1300 OI, "Emergency Plan Activation" * Toledo Edison Co 83/03/31 NRC - No Detailed Affiliation Given 3pp 18358 157 24X Fiche 50-346
- --8305060702 Public version of Rev 5 to Emergency Plan Implementing Procedure EI 1300 Oi. "Emergency Plan Activation " Rev 26 to index enc)
 HURRAY,T D. BEYER,B R. BRIDEN,D W. Toledo Edison Co. 83/03/28
 40pp 18358 140 24X Fichs 30-346.83/04/25.8305060692
- 8305030389 Ack receipt of 821206 proposed changes to industrial security plan Change B acceptable Comments on Change A, which decreases security plan effectiveness, encl Encls withheld (ref 10CFR73 21)
 STGLZ.J F Operating Reactors Branch 4 83/04/26 CROUSE.R F Toledo Edison Co 1p 18304 306 24X Fiche 50-346,83/04/26,8305030389
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Go of New York, Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.8305110034
- B305270605 Forwards IE Insp Rept 50-346/83-07 on B304(2-15 No violations or deviations identified Weaknesses w/emergency exercise identified which will require corrective action PAPERIELLO.C. J. Region 3, Office of Director B3/05/12 CROUSE.R P. Toledo Edison Co. 3pg 18644 252 24x Fiche 50-346.83/05/12,8305270605
- --8305270614 IE Insp Rept 50-346/83-07 on 830412-19 Weaknesses identified in draft exercise scenario PLOSKI.T J., PHILLIPS.M P., GLOERSEN.W B. Region 3, Office of Director 83/05/12 13pp 18644 255 24X fiche 50-346,83/05/12,8305270608
- 8303240251 Advises that App B to Industrial security plan, transmitted in Amend 56 to License NPF-3, contains no proprietary info CROUSE, R P Toledo Edison Co 83/05/13 STOLZ, J F Operating Reactors Branch 4 ip 18548 308 24X Fiche 50-346,83/05/13, 8305240251
- 8305260241 Forwards application for amend to License NPF-3, reflecting change in audit frequency of security & emergency plans to 12 months CRUUEE.R P Toledo Edison Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18599-332 24X Fiche 50-346,83/05/19.
- --8305260245 Application for amend to License NPF-3 reflecting change in audit frequency of security & emergency plans to 12 months CROUSE.R P Toledo Edison Co 83/05/19 3pp 18599.333 24X Fiche 50-346.83/05/19.8305260241
- --8305260248 Marked-up proposed Tech Spec changes reflecting change in audit fraquency of security & emergency plans to 12 months * Toledo Edison Co. 83/05/19 ip 18579 336 24X Fichs 50-346.83/05/19.6303260241
- B303260303 Responds to NRC B30422 ltr re deficiencies noted in 1E Emergency Preparedness Appraisal Rept 50-346/83-03 Corrective actions, procedures revised, training conducted & sample lines shielded w/lead bricks & lead blankets CROUSE,R P Toledo Edison Co B3/05/20 MEPPLER,J G Region 3/04fice of Director 7pp 18625 344 24X Fiche 50-346,83/05/20,8305260303

- J Insurance & indemnity information
- 8305140105 Forwards Endorsement 44 to NELIA Policy NF-236 & Endorsement 34 to MAELU Policy MF-92 GDLDEN.M P Marsh & McLennen. Inc 83/05/02 SALTZMAN.J Assistant Director for State & Licensee Relations 3pp 18451 053 24X Fiche 50-346.83/05/02.8305160105
- P. Operating license stage documents & correspondence
- B305230716 Responds to B3020B request for backfitting expenditures.
 Actual cost at DL date was \$583 million Projected add1
 future cost for NRC imposed mods conservatively estimated at
 \$26,500,000
 CROUBE,R P Toledo Edison Co B3/02/IB TOURTELLOTTE,J
 Regulatory Reform Task Force 10pp 18542 294 24X
 Fithe 50-346,83/02/18,8305230716
- 8303230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J. Regulatory Reform Yask Force 83/04/11 PALLADINO.N J. Commissioners 2pp 18342 272 24X Fiche 50-000.83/04/11.8305230720
- 8305040305 Responds to NRC 830325 ltr re safety-related electrical equipment Justification for continued operation exists for all equipment which may not be qualified Response submitted B30310 contains no changes or proprietary info CROUSE, R P Toledo Edison Co 83/04/29 STOLZ, J F, Operating Reactors Branch 4 28pp 18323 260 24X Fiche 50-346,83/04/29,3300402035
- 8303170462 Discusses results of analysis performed to determine probability of postulated tornado generated missile contacting gratings covering ventilation openings Probability acceptably small Condition not RO CROUSE, R P Toledo Edison Co 83/04/29 KEPPLER, J 0 Region 3, Office of Director. 2pp 18470 136 24X Fiche 50-346,83/04/29,8305170462
- B3D5D20455 Generic Ltr B3-17 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to DLs Svc list encl EISENHUT, D © Division of Licensing 83/05/02 Consolidated Edison Co of New York: Inc 50pp 18441 120 24X Fiche, 50-000, 83/05/02, 8305020455
- 8305040472 Application to amend License NPF-3 revising App A to Tach Spec Tables 4 3-6 & 4 3-10 re extension of surveillance interval for steam generator outlet pressure instrumentation CROUSER P Toledo Edison Co 83/05/02 STOL2, JF Operating Reactors Branch 4 2pp 18322 137 24X Fiche 50-346/83/05/02.
- --8305040480 Proposed changes to App A to Tech Specs revising Tables 4.3-6 & 4.3-10 re extension of surveillance interval for steam generator outlet pressure instrumentation * Toledo Edison Co. 83/05/02 4pp 18322 159 24X Fiche 50-346.83/05/02.8305040472
- 8303040491 Forwards application for amend to License NPF-3 revising Tech Spec Section 4 8 1.2. Tables 4 3-11 & 3 6-2 resurveillance requirements for automatic load sequencer amonthly testing of auxiliary feedwater sys logic CROUSER P Toledo Edison Co 83/05/02 870LZ, J F Operating Reactors Branch 4 ip 18322 145 24X Fiche 50-346,83/05/02.
- --8305040497 Application for amend to License NPF-3 revising Tech Space Section 4 B 1 2, Tables 4 3-11 & 3 6-2 re surveillance requirements for automatic load sequencer & monthly testing of auxiliary feedwater sys logic CROUSE, R P. Toledo Edison Co 83/05/02, 3pp 18322 146 24X Fiche 50-344,83/05/02,8305040491
- --B305040503 Proposed changes to Tech Spec revising Section 4 8 1.2. Tables 4 3-11 & 3 6-2 re surveillance requirements for automatic load sequencer & monthly testing of auxiliary feedwater sys logic.

 * Toledo Edison Co B3/05/03 Bpp 18322.149 24% Fiche 50-346,83/05/02,8305040491
- 8305060365 Notification of 830506 meeting w/B&W Dwners Group in Bethesda:MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & justification for continued operation MINER: B Operating Reactors Brench 4 83/05/02 STOLZ: J Dperating Reactors Branch 4. 2pp 18353 092 24X Fiche. 50-000, 83/05/02, 8305060365

- B305060395 Forwards response to B20923 ltr re open items in NUREG-0612.

 "Control of Heavy Loads at Nuclear Power Plants " Dynamic load effects, inservice insp & exam frequency reviewed Phase II results expected by B30601 CRDUSE.R P Toledo Edison Co B3/05/02 STDLZ.J F Operating Reactors Branch 4 7pp iB349 167 24X Fiche 50-346.83/05/02.

 B305060395
- 8305;70869 Forwards Amend 58 to License NPF-3, safety evaluation & notice of issuance & availability Amend modifies Tech Spectable to incorporate revised trip setpoints for borated water storage tank DE ADAZIC, A H Operating Reactors Branch 4 83/05/05 CROUSE, R P Tojedo Edison Co 3pp 18496 327 24X Fiche 50-346,83/05/05,83/05/2049
- --8305170673 Amend 38 to License NPF-3, revising trip setpoints for borated water storage tank & bus feeder broaker trip delay STGL2.J F Operating Reactors Branch 4 B3/05/05 9pp 18495 332 24X Fithe 50-346, B3/05/05, B305170669
- --B305170678 Safety evaluation supporting Amend 58 to License NPF-3 * Office of Nuclear Reactor Regulation. Director 83/05/05 3pp 18494.341 24% Fiche 30-346.83/05/05.8303170669
- ~-B305170682 Notice of issuance & availability of Amend 38 to License NPF-3 STOLI, J F Uperating Reactors Branch 4 83/05/05 2pp 18496 344 24X Fiche 50-346,83/05/05,8305170669
- p305180102 Forwards Amend 57 to License NPF-3, safety evaluation & notice of issuance & availability Amend modifies specs to provide addit protection to minimize potential for low temp overpressure transients
 STOLZ.J F. Operating Reactors Branch 4 83/05/05 CROUSE, R F Toledo Edison Co 4pp 18503 300 24X Fiche 50-346,83/05/05,8305180102.
- --8305180114 Amend 57 to License NPF-3, modifying specs to provide add1 protection to minimize potential for low temp overpressure transients 8701.7.J F. Operating Reactors Branch 4 83/05/05 10pp 18503 304. 24X Fiche 50-346,83/05/05.8305180102
- --8305180135 Bafety evaluation supporting Amend 57 to License NPF-3 ** Office of Nuclear Reactor Regulation, Director 83/05/05 4pp 18503 314 24% Fiche 50~346,83/05/05,8305180102
- --B305180187 Notice of issuance & availability of Amend 57 to License NPF-3 STGLI, J.F. Operating Reactors Branch 4 83/05/05 2pp EB503 318, 24X Fiche 50-346,83/05/05,8305180102
- B305110385 Forwards response to open item on safe load paths contained in NRC 820923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREO-0612) GROUSE: R P. Toledo Edison Co. B3/05/06 STOLZ, J F. Operating Reactors Branch 4 11pp 18406 201 24X Fiche 50-346,83/05/06, D208110308
- 8305110437 Forwards "Bounding Analytical Assessment of NUREQ-0630 on LOCA & Operating tW/FT Limits," per 830405 ltr CROV8E,R.P Toledo Edison Co. 83/05/06 STOLZ,J F Operating Reactors Branch 4 ip 18404 320 24X Fiche 50-346,83/05/06,8305110437
- --8305110443 "Bounding Analytical Assessment of NUREO-0630 on LOCA & Operating kW/FT Limits "

 Babcock & Wilcox Co 77-1142162-00 83/05/06 28pp 18404 32:. 24X Fiche 50-346/83/05/06/8300110437
- 8305070657 Ceneric Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods, 8vc list encl EISENHUT, D 9 Division of Licensing 83/05/07 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153 24X Fiche 50-000, 83/05/09, 8305070659.
- 8305130032 Responds to 830429 ltr re proposed changes to Tech Specs 3 D 3 & 4.0.3 Check in payment of fee transmitted CRDUBER P. Toledo Edison Co 83/05/09. MILLER, W D License Fee Management Branch. 1p 18437·101 24X Fiche 50-346.83/05/09, 8305130032
- OBJOSIBO411 Provides status rept on implementation of integrated living schedule program.per 830412 ltr Internal task force & standing committees, charged w/various living schedule activities, created & utilized CROUBER.P. Toledo Edison Co 83/05/10 8TOLZ, J. F Operating Reactors Branch 4. App. 18485 356 24X Fishe 50-346,83/05/10, 8305180411

- 8305200592 Advises that due to difficulties w/rev, license amend request re DHR capability redundancy will be submitted by 8306f3 CROUSE, P. Toledo Edison Co. 83/05/13 STOLZ-J F. Operating Reactors Branch 4 1p 18514 120 24X Fiche 30-346.83/05/13, 830520692
- 8305240351 Forwards response to B30411 request for add1 info redeletion of surveillance requirements for auxiliary reduator pump turbine speed switches Water level in steam generator controlled at 35 inches CROUSE.R P Toledo Edison Co 83/05/17 STOLZ, J F Operating Reactors Branch 4 4pp 18574 075 24X Fiche 50-346.83/05/17, 8305240351
- 8305260241 Forwards application for amend to License NPF-3 reflecting change in audit frequency of security & emergency plans to 12 months

 CROUSE: R P Toledo Edison Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18599 332 24X Fiche 50-346,83/05/19,83059.034
- --8305260245 Application for amond to License NPF-3 reflecting change in audit frequency of security & emergency plans to 12 months CROUSE.R P Toledo Edison Co 83/05/19 3pp 18599 333 24X Fiche 50-346,83/05/19,8305260241
- --8305260248 Marked-up proposed Tech Spec changes reflecting change in audit frequency of security & emergency plans to 12 months * Toledo Edison Co 83/05/19 ip 18579 336 24X Fiche 50-346.83/05/19.830526024i
- B305240423 Forwards info re environ qualification of electrical equipment important to safety, per 10CFR50 49 List of activities to resolve technical svaluation rept open items encl Namco limit switches scheduled for replacement listed CROUSE, R P Toledo Edison Co 63/05/20 STOLZ, J F Operating Reactors Branch 4 29pp 18573 006 24X Fiche 50~346.83/05/20, R305240423
- Q Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J II Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edizon Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 8vc list encl
 JORDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Bafaty/Relief Valve Failures"

 Bvc list encl

 JORDAN.E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/22 Consolidated Edison Co of New

 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8305100080 Forwards IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted Notices of deficiencies & deviations encl
 PAPERIELLO, C. J. Region 3, Office of Director 83/04/22 GROUGE, R. P. Toledo Edison Co. 2pp 18377
- --8305100082 Notice of deficiencies from insp on 830315-18 * Region 3, Office of Director 83/04/22 3pp 18377 232 24X Fichs 50-946,83/04/22,8305100080
- --8305100084 Notice of deviation from insp on 830315-18 * Region 3, Office of Director 83/04/22 2pp 18377 235 24X Fiche 50-346.83/04/22,8305100080
- --B305100090 IE Insp Rept 50-346/B3-03 on B30315-18 No noncompliance noted Major areas inspected followup insp of items identified during emergency preparadness implementation appraisal on B30208-19. PLDSMI,T J., AXELSON,W L. Region 3, Office of Director B3/04/20 12pp 16377 237 24X Fiche 50-346,83/04/22,8305100080
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Bensing Sys " Svc tist encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

- 8303170303 Forwards IE Insp Rept 50-346/83-04 on 830301-04 & 09-11 & notice of violation STREETER.J F Region 3, Office of Director 83/04/27 CROUSE,R P. Toledo Edison Co 2pp 18466 015 24X Fiche 50-346,83/04/27, 8305170303
- --8305170308 Notice of violation from insp on 830301-04 & 09-11 STREETER, J F Region 3, Office of Director 83/04/27 lp 18466 017 24X Fiche 50-346,83/04/27,8305170303
- --8305170315 IE Insp Rept 50-346/83-04 on 830301-04 & 09-11 Noncompliance noted waivers not prepared & exams not given to two individuals not attending required radiological control requalification training SUTPHIN,R N, MAHKINS,F C Region 3, Office of Director 83/04/27 &pp 18466 018 24X Fiche 50-346.83/04/27,8305170303
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382-047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York Inc 118pp 18382 145 24% Fiche 50-000.83/04/28,8303040027
- 8305060519 Forwards revised "Inservice Insp Pump & Valve Program." reflecting results discussed at 830329 meeting CROUSER P Toledo Edison Co 83/04/29 STOLZ.JF Operating Reactors Branch 4 2pp 18351 113 24X Fiche 50-346.83/04/29.8305060519
- --8305060523 "Inservice Insp Pump & Valve Program" * Toledo Edison Co 83/04/29 23pp 18351 115 24X Fiche 50-346.83/04/29.8305040519
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Bvc list encl JORDAN.E L Division of Energency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co of New York. Inc 122pp 18441 170 24X Fiche 30-000.83/05/03.8303040028
- BJ03040030 IE info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fishe 50-000.83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3705704 Consolidated Edison Co of New York, Inc. 1199p 18441 001 24X Fiche: 50-000,83/05/04,8303040031.
- 8305100076 Confirms 830627 meeting in Olen Ellyn, IL to discuss SALP NORELIUS,C E Division of Project & Resident Programs 83/05/04 CROUSE,R P Toledo Edison Co ip 18377 274 24X Fiche 50-346,83/05/04,8305100076
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11 Consolidate Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305270605 Forwards IE Insp Rept 50-346/83-07 on 830412-19 No violations or deviations identified Weaknesses w/emergency exercise identified which will require corrective action PAPERIELLO, C. J. Region 3. Office of Director 83/03/12 CROUSE, R. P. Toledo Edison Co. 3pp. 18644-252 24X Fiche. 50-346, 83/05/12, 8305270605
- --8305270614 IE Insp Rept 50-346/83-07 on 830412-15 Weaknesses identified in draft exercise scenario.
 PLOSKI,T J, PHILLIPS,M P., GLOERSEN,W B Region 3, Office of Director 83/05/12 13pp. 18644 255. 24X Fiche 50-346,83/05/12,8305270605

- 8305200509 Ack receipt of 830118 & 0203 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-25 SPEB8ARD.R L Division of Engineering 83/05/17 CROUSE.R P Toledo Edison Co ip 18516 075 24X Fiche 50-346,83/05/17, 8305200509
- --8305200514 Responds to NRC 821221 ltr re violations noted in IE inp Rept 50-346/82-25 Advises that response will be submitted by 830301 Delay due to number of organizations involved in preparation of response CROUSE:R P Toledo Edison Co 83/01/18 NORELIUS.C E Division of Engineering ip 18516 076 24X Fiche 50-346,83/05/17.
- --8305200520 Responds to NRC 821221 ltr re violations noted in IE Insp Rept 50-346/82-25 Reload pattern did not entail unreviewed safety questions for reason stated CROUSE.R P Toledo Edison Co 83/02/03 NORELIUS.C E Division of Engineering 2pp 18516 077 24X Fiche 50-346,83/05/17, 8305200509
- --8305200527 Responds to NRC B21221 ltr re violations noted in IE Insp. Rept 50-346/82-25 Corrective actions cross-shuffle appropriately considered & proper safety evaluation performed Retraction of notice of violation requested CROUSE, R.P. Toledo Edison Co. 83/04/13 NORELIUS, C.E. Division of Engineering ip 18516-079 24X Fiche 50-346,83/05/17,8303500509
- 8305240067 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-01 Responsibilities to promptly determine, evaluate & rept causes of malfunctions of asfety-related equipment stressed SHAFER, W D Region 3, Office of Director 83/05/17 CROUSE, R P Toledo Edison Co 1p 18549 062 24X Fiche, 50-346, 83/05/17, 8305340067
- --B305240072 Responds to NRC B30308 ltr re violations noted in IE Insp Rept 50-346/B3-01 Corrective actions statusing of facility change requests initiated to assure that drawings reflect as-built condition Radowste panel drawing stick updated CROUSE.R P Taledo Edison Co 83/04/29 NORELIUS.C.E Division of Engineering 15pp 18547 063 24X Fiche 50-346,83/05/17, 8305240067
- B305200330 Ack receipt of B30429 ltr Concurs w/decision to extend completion of first 10-yr inservice insp interval to end of scheduled Bpring 1987 refueling outage SPEBBARD.R L Division of Engineering B3/05/18 CROUSE.R P Toledo Edison Co 1p 18516 218 24X Fiche 30-346.83/05/18.8305200330
- --8305200337 Informs of intention to extend completion of first 10-yr Inservice insp interval to end of scheduled Epring 1789 refueling outage to coincide w/other planned outages CRUSE.R P Toledo Edison Co 83/04/29 KEPPLER.J O Region 3, Office of Director 1p 18516 217 24X Fiche 50-346,83/05/16, 8305200330
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Progress "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/17 Consolidated Edison Co. of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305260303 Responds to NRC 830422 ltr re deficiencies noted in 1E Emergency Preparedness Appraisal Rept 50-346/83-03 Corrective actions procedures revised, training conducted & sample lines shielded w/lead bricks & lead blankets CROUSER P Toledo Edison Co 83/05/20 KEPPLER J 0 Region 3. Office of Director 7pp 18625 344 24X Fiche 50-346.83/05/20, 8305260303
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list and JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Int 114pp 18647 OO7 24X Fiche 50-000.83/05/26,8303040046
- R Periodic operating reports & related correspondence
- B305190149 Forwards "Effluent & Waste Disposal Semiannual Rept. Bolid Waste & Irradiated Fuel Shipments, Jul-Dec 1980 "MURRAY, TD Toledo Edison Co. 83/05/11 KEPPLER, J. Q. Region G. Office of Director ip 18502 071 24x Fiche 50-346, 83/05/11, 8305190149
- --8305190154 "Effluent & Waste Disposel Semiannual Rept. Solid Waste & Irradiated Fuel Shipments. Jul-Dec 1780 "
 * Toledo Edison Co 83/05/11 2pp 18502,072 24X Fiche. 50-346.83/05/11,8305190149

- B Reportable occurrences, LERs & related correspondence
- 8305130093 Forwards revised LER 83-012/01X-2 MURRAY, T D Toledo Edison Co 83/05/05 KEPPLER, J G Region 3, Office of Director 1p 18437 195 24X Fichs 50-346,83/05/05, 8305130093
- --8305130095 Revised LER 83-012/01X-2 on B30303.operating practice of requiring one ECCB room cooler to be valved into svc in each ECCB room less conservative than updated FSAR assumptions Caused by lack of procedural control FSAR reviewed RICHTER, L Toledo Edison Co 83/05/05 Region 3, Office of Director 3pp 18437 196 24X Fiche 50-346.83/05/05.8305130093
- 8305130190 Forwards revised LERs 82-020/03X-2,81-032/03X-1 & 81-058/01X-1. Previous LER forms should be replaced & respective supplemental info sheets retained MURRAY.T D Toledo Edison Co 83/05/05 KEPPLER.J Q Region 3, 07fice of Director ip 18437 348 24X Fiche 50-346,83/05/05,8305130190
- --8305130195 Revised LER 82-020/03X-2 on 620409, loss of 120 volt alternating current Distribution Panel Y2 experienced while in Mode 6 Safety feature actuation signal Channel 2 actuated Caused by blown YV2 inverter fuse Fuse replaced MATHENV. D. C., STOTZ. J. Toledo Edison Co. 83/05/05 Region 3. Office of Director ip 16439 349 24X Fiche 50-346,83/05/05,8305130190
- --B305130201 Revised LER 81-032/03X-1 on 810404, relay status lamp 302A did not change when trip signal applied rendering trip output to AF 579 from steam & feedwater rupture control sys Chennel 2 inoperable. Caused by failed relay driver card TRAUTHAN, D. J. Toledo Edison Co. 83/05/05 Region 3, Office of Director. 1p. 18439 350 24X Fichs 50-346,83/05/05,8305130190
- --B305130205 Revised LER 81-058/01X-1 on 811001, very little air flow through chlorine detectors AE5338A & B observed On 811009, detectors declared inoperable Caused by design error Detector discharge routed back to ventilation duct IBLEY.T Toledo Edison Co. 83/05/05 Region 3, Office of Director, 1p. 18439 351 24X Fichs 30-346:83/05/05.8305130190
- 8305170162 Forwards revised LER 83-002/03X-1, MMRRAY: T D Totado Edison Co 83/05/05. KEPPLER: J Q Region 3, Office of Director 1p. 18466.299 24X Fiche 50-346,83/05/05, 8305170162
- --8305170171 Revised LER 83-002/03X-1 on 830115,RC8 dose equivalent I-131 exceeded Tech Spec limit of 1.0 uCi/gm Caused by leakage of fission products through fuel cladding I-131 monitored until level dropped ROMENT Toledo Edison Co 83/05/05. Region 3. Diffice of Birector Bpp 18466 300 24X Fiche 50-246,83/05/05,8305170162
- B305170201 Forwards LER 83-016/03L-0 MURRAY.T D. Toledo Edison Co 83/05/05 KEPPLER.J 0 Region 3, Office of Director 1p, 18466-351 24X Fiche 50-346,83/05/05, 8305170201
- --B305170205 LER B3-016/03L-0 on B30407, determined that amplifier of startup level transmitter LY-BP7A3 for steam generator 1-2 failed. Caused by component failure within amplifier Amplifier replaced YARDER: K Toledo Edison Co. B3/05/05 Region 3, Office of Director 3pp 18466, 332 24X Fiche 50-346, 83/05/05, B305170201
- B305240219 LER 83-017/09L-0 on B30411, spent fuel pool (SFP) level verification surveillance test ordered later than Tech Spec requirement Caused by personnal error SFP level verified Mean on schedules planned W/830309 ltr
 MMRAY.T. D Toledo Edison Co 83/05/09 KEPPLER.J G Region 3, Office of Director 3pp. 18548 019 24X Fiche 50-346,83/05/09, B305240219
- 8305240341 LER 83-018/03L-0. on 830417, safety features actuation systhematically addition admitted RE2007 found reading below normal Gaussed by equipment failure Detector replaced & failed detector sent to vendor for repair W/830516 ltr ISLEY.T, MURRAY.T D. Toledo Edison Co. 83/03/16 KEPPLER, J. O. Region 3, Office of Director Spp. 18571 356 24X Fiche: 30-346, 83/05/16, 8305240341.
- 8303260293 Revised LER 83-016/03X-1. on 830407, amplifier of startup level transmitter LT-8P9A3 for steam generator 1-2 failed Caused by component failure within amplifier. Amplifier replaced W/830517 ltr.
 YARQER,K. HURRAY.T D Toledo Edison Co 83/05/17 KEPPLER, J. G Region 3. Office of Director 2pp. 18625 318 24X Fiche: 50-346, 83/05/17, 8305260293

- B30531003B LER B3-019/03L-O on B3042L steam & feedwater rupture control sys Channel 3 tripped Caused by failed +15-volt dc power supply. On B30427, Channel 3 tripped Power supply returned to vendor Failed supplies replaced W/B30520 ltr YARGER,K. STOTZ, J. MURRAY,T D Toledo Edison Co B3/05/20 KEPPLER,J G Region 3, Office of Director App 18653 131 24X Fiche 50-346, B3/05/20, 830531003B
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8305060616 Releases public version of revised svc bldg telephone directory FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch ip 18359 116 24X Fiche 50-348.83/04/26.8305060616
- --8303060621 Forwards public version of revised svc bldg telephone directory to be filed w/Administrative Procedure FNP-0-EIP-B HUDSPETH.J B Alabama Power Co 83/04/05 Office of Nuclear Reactor Regulation, Director 2pp 18359 117 24X Fiche 50-348.83/04/26.8305060616
- --8305060626 Public version of revised svc bldg telephone directory * Alabama Power Co 83/03/17 66pp 18359 119 24X Fiche 50-340:83/04/26:8305060616
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl.
 EIBENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034
- B303240191 Forwards Rey & to security plan Rev establishes upper limit of 120 days on interim clearance, per Varga B30105 ltr Rev withheld (ref 10CFR2 790) CLAYTON, F L Alabama Power Co B3/05/12 O'REILLY, J P Region 2, Office of Director ip 18548 031 24X Fiche 50-34B, 83/05/12, 8305240191
- 8305250285 Forwards response to 830204 SERs & NRC 830412 ltr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included CLAYTON.F L Alabama Power Co 83/05/20 VAROA.S A Office of Nuclear Reactor Regulation, Director 118 p 18496 251 24X Fichs 50-348,83/05/20,8305250285
- 8305250391 Responds to NRC request to evaluate adding RCS cold leg temp indication & source range neutron monitor to hot shutdown panels per 100FR50, App R Addition of RCS appropriate mod Source range neutron monitor too costly CLAYTON, FL Alabama Power Co 83/05/20 VARGA, S A Office of Nuclear Reactor Regulation. Director 5pp 18585, 337. 24X Fiche 50-348, 83/05/20, 8305250391
- I Financial information
- B303240481 Forwards Annual Financial Rept 1982 & related financial info to satisfy retrospective premium guarantee required under Price-Andersen Act BOMDEN, T J Alabama Power Co B3/05/20 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 16pp 18572 113 24X Fiche 50-348, B3/05/20, B305240481
- --8305240484 Annual Financial Rept 1982 FARLEY: J M Alabama Power Co 83/03/04 40pp 18572 127 24X Fiche 50-348, 83/05/20,8305240481
- J Insurance & indemnity information
- 8305040180 Forwards Endorsements 52 & 43 to NELIA Policy NF-238 & MAELU Policy MF-23, respectively DUCK.J.R Marsh & McLennan, Inc. 83/04/28 SALTZMAN.J Assistant Director for State & Licensee Relations 3pp. 18324 034 24X Fiche 50-348, 83/04/28, 8305040180
- P Operating license stage documents & correspondence
- B305090016 Forwards Amend 31 to License NPF-2, safety evaluation & notice of issuance & availability Amend allows increase in storage capacity of spent fuel pool from 675 to 1.407 storage locations REEVES, E. A. Operating Reactors Branch 1 83/04/15 CLAYTON, F. L. Alabama Power Co 2pp 18369 288 24X Fiche 30-348, 83/04/13, 830986014.68

- ---8305090019 Amend 31 to License NPF-2, revising Tech Specs to increase storage capacity of spent fuel pool from 675 to 1.407 storage locations
 VARGALS A Deprating Reactors Branch 1 83/09/15 4pp, 18369 290 24X Fiche 50-348,83/04/15,8305090016
- --8305090023 Safety evaluation supporting Amend 31 to License NPF-2

 * Office of Nuclear Reactor Regulation, Director 83/04/15
 15pp 18369 294 24X Fiche 50-348.83/04/15.8305090016
- --8305090027 ElA supporting Amend 31 to License NPF-2
 # Office of Nuclear Reactor Regulation, Director 83/04/15
 11pp 18369 309 29X Fiche 50-348,83/04/15,8305090016
- --B305090032 Notice of issuance & availability of Amend 31 to License NPF-2 VARQA.S A Operating Reactors Branch 1 83/04/15 2pp 18369 320 24X Fiche 50-348,83/04/15,8305090016
- 6303020436 Advises of active negotiation w/DDE on agreement for disposal of spent nuclear fuel tw/or high level radwaste per generic Ltr 83-07 Comments on draft std disposal contract typroposed disposal rulemaking encl CLAYTON,F L Alabama Power Co E3/04/25 VARQA,S A Office of Nuclear Reactior Regulation, Director 12pp 18282 347 24X Fiche 50-348,83/04/25,8305020456
- 8303020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public natice concerning issuance of amends to OLs Svc list encl EISENHUT.D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 1844[120 24X Fiche 50-000.83/05/02.8305020455
- 8305180712 Forwards safety evaluation re requests for relief from ABME Code Section XI inservice testing requirements Some relief granted & some alternate testing authorized.

 VARGA: B A Operating Reactors Branch 1 83/05/02 CLAYTON.F L Alabama Power Co 4pp 18504 172 24X Fiche 50-348,83/05/02.

 B305180712
- --8305180721 Safety evaluation re requests for relief from ASME Code Section XI inservice testing requirements Relief from exercising requirements for svc water check valves denied per IE Bulletin 83-03

 * Office of Nuclear Reactor Regulation, Director 83/05/02 14pp 18504 176 24X Fiche 50-348.83/05/02,8305180712
- --8305180725 Supplementary safety evaluation of inservice testing program • NRC - No Detailed Affiliation Given 83/05/02 13pp 18504 287 24X Fiche 50-348,83/05/02.8305180712
- --8305180731 Natice of granting of relief to util from ASME Section XI inservice testing requirements VARGA.B A Operating Reactors Branch 1 83/05/02 2pp 18504 300 24X Fiche 50-248.83/05/02.8305180712
- 8305110308 Application for amend to DLs revising Tech Specs 3/4 8 2 3, 3/4 8 2 4 4 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions CLAYTON.F L. Alabama Power Co. 83/05/03 VARQA,S A. Office of Nuclear Reactor Regulation, Director. 5pp. 18393 198 24X Fichs 50-348.83/05/03.8305110308
- --8305110311 Proposed changes to Tech Specs 3/4 8 2 3,3/4 8 2 4 & 3/4.8 2 5 increasing confidence of battery operability & providing time to correct certain battery conditions w/o undwe plant shutdown

 * Alabama Power Co
- B305090639 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list enci EISENHUT.D 0 Division of Licensing B3/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 133 24% Fiche 50-000.83/05/09.8305090659
- 8305240440 Advises that operator training program procedures re natural circulation cooldown (Generic Ltr 81-21), based on Westinghouse Owners Group guidelines, will be incorporated by 830615 Training will be completed by 830519 CLAYTON, F. L. Alabama Power Co. 83/05/18 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 2pp 18573 131 24X fiche 50-348,83/05/18,8305240440

- Q Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fichs 30-000/83/03/21,8212060385
- 8305270358 Forwards IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/03/30 MCDDNALD, R P Alabama Power Co 2pp 18642 096 24X Fiche 50-348, 83/03/30, 8305270358
- --8305270370 IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No suncompliance noted Major areas inspected monthly maint & surveillance operational safety independent insp effort, refueling & IE Bulletin 82-04 followup BRADFORD. H H . RULAND. W H Region 2. Office of Director CANTRELL.F. B Division of Project & Resident Programs 83/03/29 8pp 18642 098 24% Fiche 50-348,83/03/30,8305270358
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator' Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc. 125pp 18435 155 24x Fichs 50-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JURPANJE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co., of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list and JORDANIE L Division of Emergancy Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24% Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 30-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Int 112pp 18382 282 24X Fichs 50-000,83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl. JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York. Int. 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York
- 8305140074 Discusses actions taken to identify & resolve potential DS-416 reactor trip breaker problems per IE Bulletin 83-01 Schedule. w/finalized implementation dates, to be submitted by 830531. Emergency operating procedures encl CLAYTON.F L Alabama Power Co 83/05/10 VARGA, S A Office of Nuclear Reactor Regulation. Director 7pp 18450 206 24X Fiche 50-348,83/05/10,8305160074
- --8305160100 Rev 6 to Emergency Operating Procedure FNP-1-E0P-5 O.
 "Reactor Trip"

 * Alabama Pawer Co 83/05/09 6pp 18450 213, 24X
 Fiche 50-348,83/05/10.8305160094

1 1

DOCKETED ITEMS

- --8905160107 Rev 6 to Emergency Operating Procedure FNP-1-E0P-15 0. "Anticipated Transients W/o Trip (ATWT) "
 + Alabama Power Co 83/05/10 5pp 18450 219 24X
 Ficas 30-348,83/09/10,8305160994 .
- B303040034 IE Info Natice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOF) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Bvc 11st encl
 JORDANN.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fichs 50-000,83/05/19,8303040040
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JDRDANE L Division of Emergency Preparadness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305200306 Forwards monthly operating rept for Apr 1983 CLAYTON,F L Alabama Power Co 83/05/12 Office of Resource Hanagement, Director ip 18516 274 24X Fiche 50-348,83/05/12, 8305200306
- --8305200327 Monthly operating rept for Apr 1983 HAIRSTON.W. @ Alabama Power Co 83/05/02, 5pp 18516 275 24X Fiche 50-348, 83/05/12, 8305200306
- 8303200379 Forwards monthly status of licensing items, requiring NRC approval, identified in 830113 ltr
 CLAYTON,F L. Alabama Power Co 83/05/13 VARGA, 6 A Office of Nuclear Reactor Regulation, Director App 18514 114 24X
 Fiche 50-348, 83/05/13, 8305200579
- B Reportable occurrences, LERs & related correspondence
- B305110427 Part 21 & deficiency repts re misoperation of D8-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHE, E.P. Westinghouse Electric Corp. B3/04/21 DEYDUNG, R C Director's Dffice, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, B3/04/21, B305110427
- B305050148 Forwards LERs B3-012/03L-0 & B3-015/03L-0 CLAYTON; F L. Alabama Power Co B3/04/27 O'REILLY, J P Region 2. Office of Director ip 18341 355 24X Fiche 50-348, 83/04/27, B305050148
- ---8305050154 LER 83-015/03L-0 on 830328, instrumentation channel associated w/steem generator iC flow transmitter FT-497 declared inoparable due to erronsous high indication Caused by obstruction of low pressure sensing line Line cleared HAIRSTON.H. O Alabama Power Co 83/04/27 Region 2, Office of Director 1p 18341 356 24X Fiche 50-348.83/04/27,8305050148
- --B305050158 LER B3-012/03L-0 on B30402, overtemp-delta temp loop 2 Channel II declared inoperable when bistables 422Cl-2 tripped Caused by power supply failure of comparator card Card replaced & loop calibr HAIRBYON, H. O Alabama Power Co 83/04/27 Region 2, Office of Director ip 18341 357 24X Fiche 50-348,83/04/27,8305050148
- B305050195 Forwards LER B3-014/03L-0 CLAYTON,F L Alabama Power Co 83/04/29 Region 2, Office of Director. 1p 18338,149 24% Fiche: 50-348,83/04/29,8305050195
- --B305050203 LER B3-014/03L-0. on B30330. during surveillance test of main feedwater pump turbine iA:RCS Tavg decreased below 341 F.
 Caused by overfeeding of steam generators due to excessive leak past main feedwater pump discharge valve HAIRBTON:W Q. Alabama Power Co. B3/04/29 Region 2. Office of Director. ip 18338.150 24X Fiche 50-348.B3/04/29.B305050195
- B305230540 Forwards LERs 83-018/03L-0 & 83-019/03L-0 CLAYTON, F L. Alabama Power Co B3/05/13 Region 2, Office of Director. 1p 18537 079. 24X Fiche: 50-348, 89/05/13, 8305230540
- ---B305230544 LER 83-018/03L-0, on 830413,RCB temp average fell below Tech Spec limit. Caused by excessive leakby on 1A main feedwater regulating bypass valve Stroke on 1A main feedwater regulating bypass valve adjusted & verified HAIRSTON,W G Alebama Power Co 83/05/13 Region 2, Office of Director. 1p. 18537-080, 24X Fiche 50-348,83/05/13,8305230540

- --8305230550 LER 83-019/03L-0 on 830415, pressurizer pressure fell below Tech Spac limits during performance of FNP-1-STP-201 18 Caused by personnel failure to verify instrumentation channel selector switches prior to initiating test HAIRSTON, M G Alabama Pawer Co 83/09/13 Region 2, Office of Director 2pp 18537 081 24X Fiche 50-34B,83/05/13,8305230540
- 8305250353 LER 83-017/03L-0 on 830417, specific gravity of train A syc water battery bank cells 34 & 43 less than 1 170 Cause undetermined Cells replaced & battery bank returned to syc W/830517 ltr HAIRBYON, N O , CLAYTON, F L Alabama Power Co 83/05/17 Region 2, Office of Director 2pp 18592 080 24X Fiche 50-348,83/05/17,8305250353
- 8305290581 LER 83-020/03L-0 on B30420.overtemp Delta temp instrumentation loop B associated w/T1422C declared inoperable due to reading out of tolerance w/other channels Caused by drift of summing amplified card W/830520 ltr HAIRBTON,W G , CLAYTON,F L Alabama Power Co B3/05/20 Region 2, Office of Director 2pp 18588 205 24X Fiche 50-348.83/05/20, 8303250581
- 8305310201 Comments on adequacy of current facility DB-416 reactor trip breakers Breaker configuration modified based on dimensional alignment & extensive testing Safe operation not adversely impacted by breakers
 CLAYTON,F L Alabama Power Co 83/05/26 VARGA,S A Office of Nuclear Reactor Regulation, Director 2pp 18658 197 24X Fiche 50-348,83/05/26,8305310201
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

 A Application/construction stage documents A correspondence
- 8305060507 Responds to concerns expressed in Encl 1 to NRC 820812 1tr ra dynamic qualification of safety-related equipment for seismic & hydrodynamic loads Gualification program revs will be completed by Fourth Quarter 1983 KEMPER.J S Philadelphia Electric Co 83/03/31 8CHWENCER,A Licensing Branch 2 7pp 18351 147 24X Fiche 50-352,83/03/31.8305060507
- B305040527 Forwards request for add1 info needed for review of auxiliary sys issues SCHMENCER, A Licensing Branch 2 B3/04/22 BAUER, E O Philadelphia Electric Co 4pp 18351 227 24X Fichs 50-352.83/04/22.8305040527
- B305060529 Forwards "Environ Assessment Rept & Findings, Point Pleasant Water Supply Project," per NRC request HESTON, R.T. Pennsylvania, Commonwealth of, B3/04/26 LEHR, J.C. Environmental & Hydrologic Engineering Branch of 18347 309 24X Fishe 50-352, B3/04/26, B305060529
- --8305040536 "Environ Assessment Rept & Findings, Point Pleasant Water Supply Project"

 MIDDENDORF, W.D., WESTON, R.T., DUNCAN, P.S. Pennsylvania, Commonwealth of, 62/08/31 118pp 18347 310 24X Fiche 50-352,83/04/26,8305040529
- B305020335 Responds to B20405 request for add1 info re control rod drive sys hydrodynamic loads Loads caused by operation of scram valves incorporated into sys support design KEMPER. J B Philadelphia Electric Co 83/04/27 SCHWENCER. A Licensing Branch 2 5pp 18277 135 24X Fiche 50-352,83/04/29,8305020335
- 8305030299 Forwards application for Amend 48 to OL application, revising FSAR & design assessment rapt BRADLEY.E J Philadelphia Electric Co 83/04/29 DENYON, H R Office of Nuclear Reactor Regulation, Director 3pp 18297 147 24X Fiche 50-352, 83/04/29, 8305030299
- --8309030307 Application for Amend 48 to OL application, revising FSAR & design assessment rept Certificate of 8vc sncl BAVER, E g , BRADLEY, E J Philadelphia Electric Co B3/04/27 7pp 18297 150 24% Fiche 30-332,83/04/29,8305030299
- #305060437 Forwards draft responses to NUREG-0737. Items I C i, I C 6, I D i, i D 2, I G i & III, A i 2 Responses will be incorporated into FBAR by June 1983.

 BRADLEY,E J Philadelphia Electric Co B3/05/04 SCHWENCER, A Licensing Branch 2 9pp 18351 160 24% Fiche 50-352, 83/05/04, 8305060457
- 8305100275 Forwards Rev O to "Study Calculation for E-Sys Clamp on Elbows." KEMPER: J S Philadelphia Electric Co 83/05/04 PURPLE:R A Division of Licensing 2pp 18370 175 24X Fiche 50-352,83/05/04, 8305100275

- --8305100281 Rev O to "Study Calculation for E-Sys Clamp on Elbows " One oversize drawing encl Aperture card available in PDR HU, C K. HUANG, A Y., KHLAFALLAH, M Z Bechtel Corp SR B031-SS10 R0O 83/04/18 76pp 18370 177 24X Fiche 50-352.83/05/04, 8305100275
- 8305110079 Summary of 830322-24 meetings w/util, Bechtel & GE in San Jose, CA re applicant response to NRC requests for addl info re machanical engineering review MARTIN, R E Licensing Branch 2 83/05/05 Licensing Branch 2 16pp 18419 337 24X Fiche 50-352.83/05/05,8305110079
- 8305190012 Notification of 830517 & 18 meetings w/util in Bethesda,MD to discuss resolution of remaining outstanding issues
 MARTIN.R E Licensing Branch 2 83/05/06 SCHWENCER.A Licensing Branch 2 4pp 18523 207 24X Fiche 50-352:83/05/06:8305190012
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fichs: 50-000,83/05/09,8305090659
- 8305130024 Notification of 830511 meeting w/wtil in Bethesda.MD to discuss requirements for resolution of geotechnical issues identified in NRC 830311 itm MARTIN.R E Licensing Branch 2 83/05/09 SCHWENCER, A Licensing Branch 2 4pp 18457 175 24X Fiche 30-352,83/05/09,8305130024
- 8305120320 Forwards draft proposed changes in response to 830407 discussions re Items 1.3a.3b.4.7.8.10-13.15-16 & 18 Braft changes will be incorporated into FSAR rev scheduled for June 1983 & into design assessment rept RRADLEY.E J Philadelphia Electric Co 83/05/10 SCHWENCER.A Licensing Branch 2 138pp 18431 170 24X Fichs 50-352.83/05/10.8305120320
- B305200170 Notification of cancellation of B30511 meeting w/util in Bethesda. MD to discuss requirements for resolution of geotechnical issues MARTIN.R E Licensing Branch 2 B3/05/10 SCHWENCER, A Licensing Branch 2 App 18540 235 24X Ficha 50-352,83/05/10,8305200170
- B305170187 Forwards draft responses & FSAR page changes re Instrumentation & Control Sys Branch Requests for Addl Info 421 5, 421 6, 421 7, 421 16, 421 30 & 421 50 in NRC B20825 ltr W/seven oversize drawings Aperture cards in PDR BRADLEY.E & Philadelphia Electric Co B3/05/12 SCHHENCER, A Licensing Branch 2 150pp 18463 017 24% Fiche 50-352, 83/05/12, B305170187
- 8305180343 Forwards draft responses & FBAR page changes in response to Mechanical Engineering Branch 830411 request for add1 info re non-straight main steam line & independent design verification program BRADLEY.E J Philadelphia Electric Co 83/05/13, SCHWENCER, A Licensing Branch 2 42pp 18485 171 24X Fiche 50-352,83/05/13,8305180343
- 8305180402 Forwards draft change to FSAR Section 9 2 6.4 2 2 re spray pond natural evaporation per 830420 teleon Change to be formally incorporated into FSAR rev scheduled for June 1983 BRADLEY: E J Philadelphia Electric Co 83/05/13 SCHWENCER, A Licensing Branch 2. 3pp. 18486 009. 24X Fiche 50-332,83/05/13,8305180402
- 8305180419 Forwards draft revs to responses to Guestions 430.68,430 72, 430 75 & 430 114 rs diesel generator auxiliary sys Changes will be formally incorporated into FBAR rev scheduled for June 1983 BRADLEY.E J Philadelphia Electric Co 83/05/13 SCHWENCER, A Licensing Branch 2 21pp. 18485 332. 24X Fiche 50-352,83/05/13,8305180419
- 8305180432 Forwards draft responses to Radiological Assessment Branch request for add1 info & draft FSAR changes resulting from B30428 telecom w/MRC Schedule for formally incorporating changes into future FSAR revs noted BRADLEY, E.J. Philadelphia Electric Co. 83/05/16 SCHMENCER, A Licensing Branch 2 55pp 18486 126 24X Fiche: 50-352, 83/05/16, 8305180432
- 8305230496 Forwards draft revs to GA Branch Questions 260.1 through 260 55 & related FBAR changes per 830329 meeting Info will be incorporated into FBAR in June 1983 BRADLEY,E J Philadelphia Electric Co 83/05/19 BCHWENCER,A Licensing Branch 2 315pp. 18535 358 24% Fiche 50-352,83/05/19,8309230496

- 8305230133 Forwards Amend 50 to GL application, substituting revised version of physical security plan Rev withheld (ref. 100FR2 790)

 BRADLEV.E J Philadelphia Electric Co. 83/05/20 DENTON.H R. Office of Nuclear Reactor Regulation. Director 3pp 18584 065 24X Ficha 50-382.83/05/20.8303250133
- --8305250135 Amend 50 to OL application, substituting revised version of physical security plan W/Certificate of Svc KEUPER, J S Philadelphia Electric Co 83/05/20 7pp 18584.069 24X Fiche 50-352,83/05/20,8305250133
- B305270375 Forwards revised draft change to Hydrologic & Geotechnical Engineering Branch open item re FBAR Section 9 2 & 4 2 2 Change will be formelly incorporated into FBAR rev in June 1983 BRADLEY, E.J. Philadelphia Electric Co. B3/05/25 SCHHENCER, A. Licensing Branch 2 3pp 19644 296 24X Fiche 50-352, 83/05/25, B305270375
- C Utility Environmental Report (ER), amends & correspondence
- B305160001 Rev 12 to environ rept OL stage One oversize drawing entl Aperture card available in PDR # Philadelphia Electric Co 93/04/30 72pp 18448.030 24X fiche 50-352.83/04/30.8305160001
- 8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept.per DG Eisenbut 810706 ltr

 BRADLEY.E J Philadelphia Electric Co 83/05/13 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 5pp 18500-027,

 24% Fiche 50-352,83/05/13,8305190359
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305020255 Forwards draft responses to Questions 440 3,440 4,440 5 k 440 32 Responses also address Item 1 of draft SER Series 440 Reactor Bys Branch, "ODYN Analysis of Pressurization Transients" & Item 3 of 820716 1tr re SER Section 4 4 BRADLEY,E J Philadelphia Electric Co 83/04/27 SCHWENCER, A Licensing Branch 2 15pp 18277 080 24X Fiche 50-352,83/04/27. 8305020255
- 8305020454 Forwards draft responses to Reactor Sys Branch draft SER to TMI Items II K 3 13, II K 3 15, II K 3 16, II K 3 16, II K 3 21, II K 3 22, II K 3 24, II K 3 25, II K 3 30, II K 3 31 & II K 3 45 Response will be incorporated into FGAR revs BRADLEY,E J Philadelphia Electric Ca 83/04/27 SCHWENCER, A Licensing Branch 2 13pp 18283 287 24X Fiche 50-352,83/04/27,8305020454
- B305170228 Forwards dreft responses to Reactor Sys Branch draft SER, Items 4 & 5 re TMI Action Items II K 1 5 & II K 1 10
 Responses will be formally incorporated into FSAR rev scheduled for June 1983
 BRADLEY,E J. Philadelphia Electric Co B3/05/11 BCHWENCER, A Licensing Branch R App 18466/342 24X Fiche 50-352, 83/05/11, 8305170228
- B303180387 Forwards draft FSAR page changes re open items for Chemical Technology Section draft SER re reactor coolant & suppression pool & secondary containment atmosphere Changes to be incorporated into Rev 20 to FSAR in May 1983 BRADLEY.E.J Philadelphia Electric Co 83/05/13 SCHWENCER.A Licensing Branch 2 10pp 18486-347 24X Fiche 50-352,83/05/13,8305180389,
- 8305180451 Forwards draft responses to SER open items re draft fire protection section.per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings

 BRADLEY.E J Philadelphia Electric Co 83/05/13 SCHWENCER.A Licensing Branch 2 67pp 18486 201 24X Fiche 50-352.83/05/13.8305180451
- 8305180414 Forwards Peach Bottom procedures supplementing util 830316 response to Item 5 of Radiological Assessment Branch draft BER Similar or improved procedures will be developed for Limerick BRADLEY.E J Philadelphia Electric Co 83/05/16 SCHWENCER.A Licensing Branch 2 2pp 18482-007 24X Fiche, 50-000, 83/05/16, 8305180414
- ---B305180426 Procedure HPO/CO-3, "Airborne Activity Survey Techniques," including techniques for constant air monitors, portable fixed filter samplers & charcoal cartridges * Philadelphia Electric Co B3/05/16 15pp 18482,009. 24X Fiche 50-000,83/05/16,8305180414

- --8305180431 Procedure HPO/CO-65, "Field Use of Low Vol Portable Air Bampler" + Philadelphia Electric Co 83/05/16 2pp 18482 024 24X Fiche 50-000,83/05/16,8305180414
- --8305180438 Procedure HPA-636, "Calibr of Ventilation Sys Radiation Monitors"

 Philadelphia Electric Co 83/05/16 8pp 18482 026 24X
 Fiche 50-000,83/05/16,8305180414
- --8305180443 Procedure HPA-77, "Determination of Max Permissible Concentration Hours" Philadelphia Electric Co 83/05/16 5pp 18482 034 24X Fiche 50-000,83/05/16,8305180414
- 8305200615 Forwards FSAR page changes & draft responses prepared per Procedures & Test Review Branch draft SER open items Responses & FSAR page changes will be formally incorporated into FSAR rev scheduled for June 1983

 BRADLEY:E J Philadelphia Electric Co 83/05/18 SCHWENCER, A Licensing Branch 2 26pp 18520 075 24X Fiche 50-352,83/05/18,8305200615
- 8305310009 Forwards draft responses to personnel qualification SER ltems 1-3. mgt technology Items 1 & 2 & draft rev to FSAR Section I3 2 2 1 7 re performance review program Changes will be incorporated into June 1983 FSAR rev SAADLEY,E. J Philadelphia Electric Co 83/05/25 SCHHENCER,A Licensing Branch 2 20pp 18653 243 24X Fiche 50-352,83/05/25,8305310009
- 8305310045 Forwards draft responses to Core Performance Branch draft EER Items 1 through 4 & 6 through 11 FSAR Chapters 4,5,6 & 15 will be revised to incorporate latest approved revs to GESTAR II in June 1989
 BRADLEY.E J Philadelphia Electric Co 83/05/25 SCHWENCER,A Licensing Branch 2 16pp 18653 288 24X Fiche 50-352,83/05/25,8305310045
- F. Security, medical, emergency & fire protection plans
- 8304290013 Forwards draft fire protection section of SER based on review of util 830128 submittal of fire protection program through Amend 45 of DL application Thirty-four open items require resolution.

 8CHWENCER.A Licensing Branch 2 83/04/19. BAUER, E 0 Philadelphia Electric Co 31pp 18266 053 24X
 Fiche: 50-332, 83/04/19, 8304290013
- B305110072 Notification of B30518-19 meetings w/util in Bethesda.MD to discuss fire protection issues MARTIN,R E Licensing Branch 2. B3/05/05 BCHWENGER.A Licensing Branch 2 3pp 18419 360 24X Fiche 50-352.83/05/05.8305110072
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISEANUT, D 0 Division of Licensing 83/05/11, Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche: 50-0009 83/05/11,8305110034
- 8305180451 Forwards draft responses to SER open items re draft fire protection section.per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
 BRADLEY,E J Philadelphia Electric Co 83/05/13 8CHWENCER,A Licensing Branch 2 67pp 18486 201 24X Fichs 50-352,83/05/13.8305180451.
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKE,M J. Office of the Executive Director for Operations. 83/05/13 PALLADING.N.J. Commissioners 5pp 18593-322 24) Fiche: 50-000.83/05/13,8305240213
- 8305250133 Forwards Amend 50 to OL application; substituting revised version of physical security plan Rev withheld (ref 10CFR2 790).

 BRADLEY, E. J. Philadelphia Electric Co. 83/05/20 DENTON, H.R. Office of Nuclear Reactor Regulation; Director. 3pp. 18584 045, 24X Fiche: 50-352,83/05/20,8305250133
- --8305250135 Amend 30 to DL application; substituting revised version of physical security plan. W/Certificate of Svc KEUPER, J. S. Philadelphia Electric Co 83/05/20 7pp 18584.068, 24X:Fiche 50-352,83/05/20,8305250133

G Adjudicatory correspondence

- 8305020441 Answer opposing Limerick Ecology Action, F. Romano & M. Lewis further particularization of conditionally admitted contentions Neither specificity nor bases provided for contentions Certificate of Svc encl
 WETTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn B.704/27 Atomic Bafety and Licensing Board Panel
 48pp 18283 092 24X Fiche 30-352,83/04/27.8305020441
- 8305040470 New info contention re inadequate util mgt Repeated carelessness.malfunctioning safety-related equipment & util response adversely reflect on mgt capability ROMAND.FR Air and Hater Pollution Patrol 83/04/27 Commissioners ip 18322 236 24X Fiche 50-352,83/04/27, 8305040470
- 8305020405 Notice of ASLAS reconstitution CN Kohl, chairman & OJ Edles & RL Outchy, members
 TOMPKING, 0 A Atomic Safety and Licensing Appeal Panel 83/04/28
 ip 18273 046 24X Fiche 50-352,83/04/28,8305020405
- 8305030563 Forwards joint repts on status of emergency planning reviews & schedule re-onsite & offsite emergency planning contentions; status of discovery & suggested items for discoversion at 830509 prehearing conference HETTERHAHN, M J Conner & Wetterhahn METTERHAHN, M J Philadelphia Electric Co 83/04/29 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 7pp 18306-118 24X Fiche: 50-352,83/04/29,8305030563
- 8305030550 Memorandum & order ALAB-726, reversing ASLB 830427 Decision LBP-83-25 & remanding Del-Aware 830308 request for late-filed Contention V-26 to ASLB for disposition on merits
 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/05/02 Atomic Safety and Licensing Board Panel 7pp 18306 140 24X Fiche 30-352, 83/05/02,8305030550
- 8303060478 Provides update of status of conditionally admitted non-PRA contentions
 WETTERHAMN,M J Conner & Wetterhamn WETTERHAMN,M J Philadelphia Electric Co 83/03/03 BRENNER.L. COLE.R F. COLE.R F. Atomic Safety and Licensing Board Parel 7pp 18348 238 24X Fiche 30-332,83/05/03,8305060478
- B305060339 Response to Limerick Ecology Action/Air & Water Pollution Patrol spec of conditionally admitted contentions Contentions I-B, I-15 & I-30 admissible PRA contentions should be denied Certificate of Svc encl HODODON, A P Hearing Branch 2 B3/05/04 Atomic Safety and Licensing Board Panel 23pp 18344 085 24X Fiche 50-352, 83/05/04, B305060339
- B305090478 Advises of change of address Svc list should be amended accordingly ELLIOTT, C W Brose & Poswistillo 83/05/06 NRC No Detailed Affiliation Given 1p 18360 235 24X Fiche 50-352,83/05/06,8305090478
- B30512027B Forwards status rept on draft emergency plan preparation AV,T Y Pennsylvania, Commonwealth of, 83/05/09 RRENNER,L. COLE,R F. MORRIS,P.A. Atomic Bafety and Licensing Board Panel 19 18427 257 24% Fiche 30-352,83/05/09,8305120278
- --8305120280 Status rept re preparation of draft emergency plans Centificate of Svc encl AU.T.Y Pennsylvania, Commonwealth of. 83/05/09 4pp 18427:238 24X Fiche 50-352.83/05/09.8305120278
- 8305120296 Forwards JI Ruttenberg notice of appearance & AJ Noges notice of withdrawal of appearance Certificats of Svc encl RUTTENBERG, J I Keystone Alliance 83/05/09 BRENNER, L, MORRIS, P A, COLE, R F A tomic Safety and Licensing Board Panel 5pp 18430 171 24% Fichs 50-352.83/05/09.8305120296
- 8305160174 Notice of appearance in proceeding Certificate of Syc encl BUSH,M,W Philadelphia, PA 83/05/09 5pp 18446 068 24X Ficha 50-352,83/05/09,8305160174
- 8303160177 Notice of appearance in proceeding LENIS,K 8 Philadelphia, PA 83/05/09 2pp 18444 034 24X Fiche 30-352,83/05/09.8305160177,
- 8305170533 Response to ASLB 830321 order advising that Commonwealth of PA.Ofc of Consumer Advocate intends to participate in proceeding WERBAN.D Pennsylvania, Commonwealth of, 83/05/10 BRENNER, L Atomic Safety and Licensing Board Panel ip 18467 355 24X Fiche 30-352,83/05/10.8305170533

- 8305170536 Order directing util.NRC & Air & Mater Pollution Patrol to jointly supply ASLB w/IE Insp Rept 50-353/76-06, notice of violation, util response & other documents re scope of reesam of welds by particular inspector BRENNER, L Atomic Safety and Licensing Board Panel 83/05/13 Philadelphia Electric Co 3pp 18469 025 24X Fiche 30-352,63/09/13,8305170538
- 8305180136 Mamprandum & order confirming schedules established at 830507-ii special prehearing conference NRC ordered to rept on FEMA schedule for reviewing plans & NRC schedule for issuing SER. first SER suppl.PRA.DES & FES BRENNER.L Atomic Safety and Licensing Goard Panel B3/05/16 10pp 18470 012 24x Fichs 50-328.83/05/16.8305180136
- 8305240516 First set of interrogetories on pressurized thermal shock contention Certificate of Svc encl Related correspondence LEMIS, N J Lewis, M 83/05/19 Office of the Executive Lagai Director Ip 18571 175 R4X Fiche 50-352.83/05/19,8305240516
- 8305260181 Forwards IE Inap Rept 50-353/76-06, notice of violation & util response, per ASLB 830513 order re GA documents Comments on Inap repts, notices of violation & interrogatories received on 830518 W/o encl ROMANO, FR Air and Mater Pollution Patrol 83/05/17 BRENNER, L Atomic Safety and Licensing Board Panel 1p 18599 261 24X Fiche 50-332, 83/05/17, 8305260181
- 8305230239 Advises that FEMA is discussing time needed to review Pannsylvania Emergency Mgt Agency emergency plan w/FEMA regional oft NFC schedules for issuance of SER SER suppl. PRA.DES & FES unchanged VOCLER.B H Hearing Branch 2 83/05/20 BRENNER.L, MORRIS.P A, CDLC.R Atomic Safety and Licensing Board Panel 2pp 18539:004 24X Fiche 50-352.83/05/20.8305230239
- 8305240489 Forwards, in response to ASLB 830513 order for QA documents, IE Insp. Rept 50-353/76-06 & related documents WETTERNAHN, N J Conner & Hetterhahn HETTERNAHN, M J Philadelphia Electric Co 83/05/20 DRENNER, L , MORRIS, P A , COLE, R. F Atomic Safety and Licensing Board Panel 87pp 18572 166 24X Fiche 50-352,83/05/20,8305240489
- 8305260322 Response to ASLB 830516 scheduling order Add1 statement re NRC use of PRA & rept on NUREG-0737. Item II K 3 iB encl Schedules for NRC issuance of documents discussed at second special prehearing conference valid W/Certificate of Svc HODGDON.A P Hearing Branch 2 83/05/24 9pp 18625 019. 24X Fiche 50-352.83/05/24.8305260322
- --8305260327 Forwards evaluation of BMR Dwners Group generic response to NUREO-0737. Item JI K 3 18. "Mod of Automatic Depressurization Sys Logic Feasibility for Increased Diversity of Some Event Sequences " Response requested SCHMENCER.A Licensing Branch 2 83/05/23 BAUER.E G Philadelphia Electric Co 9pp 18625 028 24X Fiche 50-352,83/05/24,8305260322
- --8304140161 Forwards safety evaluation of mods proposed by BHR Owners Group re NUREG-0737. Item II K 3 18. "Mad of ADS Logic "
 Two options proposed acceptable W/o encl
 HOUSTON.R W Assistant Director for Reactor Safety 83/04/01
 LAINAS.O C Assistant Director for Safety Assessment 2pp
 18625 037 24X Fiche 50-332,83/05/24,8305260322
- B3053i0013 Supplemental motion to reopen &/or to admit new Contentions V-27 & V-28 re feasibility of providing water to plant by startup Certificate of Svc encl SUGARMAN, R J Dei-Aware Unlimited, Inc SUGARMAN, R J Sugarman, R J B3/05/24 Atomic Safety and Licensing Board Panel 17pp 18653 265 24x Fiche 50-352,087/05/24,8005310013
- H General correspondence
- 8305240316 Requests MH Bush & K Lewis be added to GL proceeding syc list for City of Philadelphia Byc will replace former managing director. W Goode BUSH, M H Philadelphia, PA 83/05/19 GRENNER, L, COLE, R F, MORRIG. P A Atomic Safety and Licensing Board Panel, 4pp 18548 197 24X Fishe 50-352,83/05/19,8305240316
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8301310260 Forwards Rev 16 to FBAR BRADLEY:E J Philadelphia Electric Co 83/01/28 DENTON:H R. Office of Nuclear Reactor Regulation. Director. 2pp 16967 246 24X Fiche 50-352:83/01/28:8301310260
- --8301310274 Rev 16 to Limerick Generating Station.Units 1 & 2 FSAR * Philadelphia Electric Co 83/01/31 442pp. 16967-333 24X Fiche 50-352,83/01/28,8301310260

- 8305140117 Rev 19 to FSAR * Philadelphia Electric Co 83/04/30 626pp 18448 187 24% Fiche 50-352.83/04/30.8305160117
- 8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FBAR & Rev 12 to environ rept.per DG Eisenhut Bl0706 ltr BRADLEY,E J Philadelphia Electric Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18500 027 24X Fiche 50-352,83/05/13,8305190359
- @ Inspection reports. IE Bulletins & correspondence
- 82120603B5 IF Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Conspil
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator' Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/04/13 Consolidated Edison Co. of New York, Inc 126pp 18435 135 24X Fiche 50-000,83/04/15,8303040021,
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDANNE L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of Naw
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83~23, "Inoperable Containment Atmosphere Sensing Sys " 8vc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp. 18381 291 24X Fiche 50~000.83/04/25,8303040025
- B303050202 Informs that changes to Rosemount transmitters will be completed by B40701 for Unit 1 & prior to fuel load for Unit 2 Info completes response to IE Bulletin B0-16 KEMPER, J S Philadelphia Electric Co B3/04/25 HAYNES, R C Region 1. Office of Director 3pp 18341 078 24X Fiche 50-352,83/04/25,8305050202
- 8305040057 Notification of significant licensee 830502 meeting in Philadelphia,PA to discuss results of SALP TRIPP.L E Region I. Office of Director 83/04/27 Division of Project & Resident Programs. ip 18354 362 24X Fiche 50-352,83/04/27,8305060057
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/2B Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice B3-25, "Stradby Gas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 93/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B303040029 IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl
 URDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 288 24X Fichs 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Syc list encl. JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

- p303040034 [E Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list and URBOAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18924 003 24X Fiche 50-000,83/05/11.8303040034 York, Inc 114pp
- 0303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering lost 830103) 63/05/19 Consolidated Edison Co of New 114pp 18697 009 24% Fiche 50-000,83/05/19,8303040040 Response (Post
- \$\textit{\rightarrow} 0.305240489 \textit{Forwards, in response to ASLB 830513 order for QA documents, IE Insp Rept 50-353/76-06 & related documents
 HETTERHAHN, M J Conner & Hetterhahn HETTERHAHN, M J Philadelphia
 Electric Co 83/05/20 BRENNER, L , MORRIS, P A , COLE, R F Atomic
 Safety and Licensing Board Panel
 87pp 18572 166 24X
 Ficha, 50-352, 83/05/20, 8305240489
- 9303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JQRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/03/26 Consolidated Edison Co. of New York, Inc. 184pp 18647-007 24X Fiche 50-000,83/05/26,8303040046
- 1 Hearing transcripts on non-antitrust matters
- 8303160035 Transcript of 830509 prehearing conference in Philadelphia. PA Pp 4.039-4.167

 * Atomic Bafety and Licensing Board Panel 83/05/09 132pp 18456-094 24X Fiche 30-332.83/05/09.8303160035
- p305160173 Transcript of 830510 hearing in Philadelphia.PA
 - 19910173 (paisers for 65 55510 hearing in Filtrately (1897) 1897 4 Atomic Safety and Licensing Board Panel 83/05/10 R28pp 18445 180 R4X Fichs 50-352,83/05/10,8305160173
- @305160016 Transcript of 830511 prehearing conference in Philadelphia:PA Pp. 4,396-4,389 # Atomic Bafety and Licensing Board Panel 83/05/11 135pp 1845 165 24X Fiche 50-352:83/05/11;8305160016
- DOCKET 50-053 LIMERICK GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- #305040507 Responds to concerns expressed in Encl 1 to NRC 820812 1tm austraction responds to concerns expressed in Ent. 1 to NRC BENDLE 1 re dynamic qualification of safety-related equipment for seismic & hydrodynamic loads Gualification program revs will be completed by Fourth Quarter 1788
 REMPER.J 8 Philadelphia Electric Co 83/03/31 8CHMENCER, A Licensing Branch 2 7pp 18351 147 24% Fiche 50-352,83/03/31,
- B303040527 Forwards request for addl info needed for review of autiliary sys issues
 SCHMENCER.A. Licensing Branch 2 B3/04/22 BAI
 Philadelphia Electric Co 4pp 18351 227 24X
 Fichs 50-352.83/04/22.8305040527
- 3305060529 Forwards "Environ Assessment Rept & Findings Point Pleasant Water Supply Project," per NRC request WEBTON R T Pennsylvania Commonwealth of, 83/04/26 LEKR, J C Environmental & Hydrologic Engineering Branch ip 18347 309 24X Fichs 50-352,83/04/26,8305060529
- ~8305060536 "Environ Assessment Rept & Findings, Point Pleasant Water Supply Project "
 HIDDENDORF, H B , WESTON.R T , DUNCAN, P S Penns
 Commonwealth of, 82/08/31 | 118pp | 18347 310
 Fichs 36-352,83/04/26,8305060529
- 305020335 Responds to 820405 request for add1 info re control rod drive sign hydrodynamic loads Loads caused by operation of acrea valves incorporated into sys support design KEPPER J B Philadelphia Electric Co. 83/04/29 8CHWENCER, A Licensing Branch 2 3pp 18277 135 24X Fiche 50-352,83/04/29, 8305020335
- 305030299 Forwards application for Amend 48 to OL application, revising PAR & design assessment rept

 RADLEY.E J. Philadelphia Electric Co 83/04/29 DENTON.H.R

 Office of Nuclear Reactor Regulation, Director 3pp. 18297 147

 RAY Fiche 50-332,83/04/29:8305030299
- \$305030307 Application for Amend 48 to OL application, revising FSAR & design assessment rept Certificate of Svc encl
 BAUER, E O . BRADLEY, E J Philadelphia Electric Co 83/04/29
 7pp 18297 150, 24X Fiche 50-352,83/04/29,8305030299

- 8305060457 Forwards draft responses to NUREG-0737, Items I C 1, I C 6, I D 1, I D 2, I G 1 & III A 1 2 Responses will be incorporated into FBAR by June 1983
 BRADLEY,E J Philadelphia Electric Co 83/05/04 SCHWENCER, A Licensing Branch 2 9pp 18351 160 24% Fiche 50-352,83/05/04,8305060437
- 8305100275 Forwards Rev O to "Study Calculation for E-Sys Clamp on EXPOSE. J S Philadelphia Electric Co. 83/05/04 PURPLE.R A Division of Licensing 2pp 18370 175 24X Fiche 50-352.83/05/04. B305100275
- ---8305100281 Rev O to "Study Calculation for E-Sys Clamp on Elbows " One overtize drawing encl Aperture card available in PDR HU.C K , HUANG, A Y , KHLAFALLAH, M Z Bechtel Corp SR 6031-5810 ROD 83/04/18 76pp 18370 177 24X Fixhe 50-352,83/05/04, 8305100275
- 8305110079 Summary of B30322-24 meetings w/util.Bechtel & GE in Ban Jose, CA re applicant response to NRC requests for add1 info re mechanical engineering review MARTIN, R E Licensing Branch 2 83/05/05 Licensing Branch 2 16pp 18419 337 24X Fiche 50-352,83/05/05,8305110079
- 8305190012 Notification of 630517 & 18 meetings w/util in Bethesda,MD to discuss resolution of remaining outstanding issues
 MARTIN.R E Licensing Branch 2 83/05/04 SCHHENCER.A Licensing
 Branch 2 4pp 18523 209 24X Fichs 30-
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list excl ETERNHUT,D 0 Division of Licensing 83/05/09 Edison Co of New York, Inc 16pp 18627 153 24X Fiche 90-000,83/05/09,8305070659 Consplidated
- 8305130026 Notification of 830511 meeting w/util in Bethesda.MD to discuss requirements for resolution of geotechnical issues identified in NRC 830311 ltr MARTIN.R C Licensing Branch 2 83/05/07 SCHMENCER.A Licens Branch 2 4pp 18457 175 24X Fichs 50-352.83/05/09.8305130026
- 9305130096 Forwards draft responses to Auxiliary Sys Branch Guestions
 410 00 410 104 Info discusses Rev 14 to FBAR re detection
 of leakage through spent fuel pool timer & continuous
 occupational exposure during normal operations
 BRADLEY:E J Philadelphia Electric Co 83/05/09 SCHMENCER, A
 Licensing Branch 2 12pp 18438 045 24X Fiche 50-353,83/05/09, Licensing Branch 2 8305130076
- 8305120320 Forwards draft proposed changes in response to 830407 discussions re Items 1,3a,3b,47,78,10-13,15-16 & f8 Draft changes will be incorporated into FSAR rev scheduled for June 1783 & into design assessment rept BRADLEY, E. J. Philadelphia Electric Co. 83/05/10 SCHWENCER, A Licensing Branch 2 138pp 18431 170 24X Fiche 50-352, 83/05/10,
- 8305200170 Notification of cancellation of 830511 meeting w/wtil in Bethesda: MD to discuss requirements for resolution of geotechnical issues
 MARTIN: R E Licensing Branch 2 83/05/10 SCHWENCER; A Licens Branch 2 4pp 18340 235 24X Fiche 50-352; 83/05/10; 8305200170 Licensing
- 8305170187 Forwards draft responses & FSAR page changes re
 Instrumentation & Control Sys Branch Requests for Addl Info
 421 5,421 6,421 7,421 16,421 30 & 421 30 in NRC 820825 ltr
 Wisoven oversize drawings Aperture cards in PDR
 BRADLEY.E J Philadelphia Electric Co B3/03/12 SCHWENCER.A
 Licensing Branch 2 150pp 18463 017 24X Fiche 50-352,83/05/18.
 REQD: 170187 BRADLEY, E J Philad Licensing Branch 2 8305170187
- 8305180343 Forwards draft responses & FSAR page changes in response suprouses rowards grant responses & PSAK page changes in response to Mechanical Engineering Branch 830411 request for addlinfo re non-straight main steam line & independent design verification program

 BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER, A Licensing Branch 2 42pp 18485,171 24X Fiche 50-352,83/05/13,8305180343
- 8305180402 Forwards draft change to FBAR Section 9 2 6 4 2 2 re spray pend natural evaporation per 830420 telcon Change to be formally incorporated into FBAR rev scheduled for June 1983 BRADLEY, E J Philadelphia Electric Co 83/05/13 SCHWENCER, A Licensing Branch 2 3pp 18486 009 24X Fiche 50-392,83/05/13,

- 8305180419 Forwards draft revs to responses to Quastions 430 68.430 72, 430 73 & 430 114 re diesel generator auxiliary sys Changes will be formally incorporated into FSAR rev scheduled for June 1983 2RADLEY.E J Philadelphia Electric Co 83/05/13 SCHWENCER.A Licensing Branch 2 21pp 18485 332 24% Fiche 50-352,83/05/13, 8305180419
- 9305160432 Forwards draft responses to Radiological Assessment Branch request for add1 info & draft FSAR changes resulting from 830428 telcon w/NRC Schedule for formally incorporating changes into future FSAR revs noted BRADLEY.E J Philadelphia Electric Co 83/05/16 SCHWENCER.A Licensing Branch 2 55pp 18486-126 24X Fiche 50-352,83/05/16.
- 8305230496 Forwards draft revs to QA Branch Questions 260 1 through 260 55 & related FSAR changes per 830329 meeting Info will be incomponated into FSAR in June 1983 BRADLEY.E J Philadelphia Electric Co 83/05/19 SCHWENCER.A Licensing Branch 2 315pp 18535 358 24X Fiche 50-352.83/05/19.8305230496
- 8305230133 Forwards Amend 50 to OL application, substituting revised version of physical security plan Rev withheld (ref 10CFR2 790)
 BRADLEY, E. J. Philadelphia Electric Co. 83/05/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 18584 045 24X Fiche 50-352,83/05/20,8305250133
- --8305250135 Amend 30 to OL application, substituting revised version of physical security plan W/Certificate of 8vc KEUPER.J S Philadelphia Electric CD 83/05/20 7pp 18584 068 24X Fiche 30-352,83/05/20,839250133
- 8305270375 Forwards revised draft change to Hydrologic & Geotechnical Engineering Branch open item re FSAR Section 9 2 4 4 2 2 Change will be formally incorporated into FSAR rev in June 1983
 BRADLEY, E J Philadelphia Electric Co. 83/05/25 SCHWENGER, A Licensing Branch 2 Jpp 18644 296 24X Fiche 50-352,83/05/25,8305270375
- C Utility Environmental Report (ER), amends & correspondence
- B305160001 Rev 12 to environ rept OL stage One oversize drawing encl. Aperture card available in PDR # Philadelphia Electric Co 83/04/30 72pp 18448 030 24X Fiche 30-352,83/04/30,8305160001
- 8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept.per DO Eisenhut 810704 ltr 8RADLEY.E J Philadelphia Electric Co 83/05/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 18500 027 24X Fiche 50-352,83/05/13.8305190359
- E NRC Bafety Evaluation Report (BER), supply & correspondence
- 8304270013 Forwards draft fire protection section of SER based on review of util 830128 submittal of fire protection program through Amend 45 of UL application Thirty-four open items require resolution

 SCHMENCER, A Licensing Branch 2 83/04/19 BAUER, E 0 Philadelphia Electric Co 31pp 18266-053 24X Fiche 50-352,83/04/19,8304290013
- B305020235 Forwards draft responses to Questions 440 3,440 4,440 5 & 440 32 Responses also address Item 1 of draft SER Series 440 Reactor Bys Branch. "ODYN Analysis of Prissurization Transients" & Item 3 of 820716 Itr re SER Section 4 4 BRADLEY.E J Philadelphia Electric Co B3/04/27 BCHWENCER.A Licensing Branch 2. i5pp 18277 080 24X Fiche 50-352,83/04/27,8305020285
- 8305020454 Forwards draft responses to Reactor Sys Branch draft SER re
 TMI Items II K 3 13.II.K 3 15.II K 3 16.II K 3 18.II K 3 21.
 II K 3 22.II K 3 24.II K 3 25.II K 3 30.II K 3 31 &
 II K 3.45 Response will be incorporated into FBAR revs
 BRADLEY.E J Philadelphia Electric Co 83/04/27 SCHMENCER.A
 Licensing Branch 2 13pp 18283 287 24X Fiche 50-352.83/04/27.
- B303170228 Forwards draft responses to Reactor Sys Branch draft SER.

 Items 4 & 5 re THI Action Items II K I 5 & II.X 1.10
 Responses will be formally incorporated into FSAR rev
 scheduled for June 1933
 BRADLEY.E.J Philadelphia Electric Co 83/05/II, 8CHWENCER, A
 Licensing Branch 2 4pp 18466 342 24X Fiche 50-352,83/05/II,
 B303170228

- 8305180389 Forwards draft FSAR page changes re open items for Chemical Technology Section draft SER re reactor coolant & suppression pool & secondary containment atmosphere Changes to be incorporated into Rev 20 to FSAR in May 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/05/13 BCHMENCER, A Licensing Branch 2 10pp 18486-347 24X Fiche 50-352,83/03/13,8303180389
- 8305180451 Forwards draft responses to BER open items re draft first protection section, per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
 BRADLEY, E. J. Philadelphia Electric Co. 83/05/13 8CHWENCER, A Licensing Branch 2 67pp 18486 201 24% Fiche 50-352,83/05/13.8305180451
- 8305180414 Forwards Peach Bottom procedures supplementing util 800316 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick.

 BRADLEY, E. J. Philadelphia Electric Go. 83/05/16 SCHWENCER, A. Licensing Branch 2 2pp. 18482 007 24% Fiche: 50-000, 83/05/16, 8305180414
- 8305200615 Forwards FBAR page changes & draft responses prepared par Procedures & Test Review Branch draft SER open items. Responses & EBAR page changes will be formally incorporated into FBAR rev scheduled for June 1983
 BRADLEY, E J Philadelphia Electric Co 83/05/18 SCHMENCER, A Licensing Branch 2 26pp 18520 095 24X Fiche 50-352,83/05/18,8305200615
- 8305310009 Forwards draft responses to personnel qualification BER Itams 1-3, mgt technology Itams 1 & 2 & draft rev to FSAR Section 13 2 2 1 7 re performance review program Changes will be incorporated into June 1983 FSAR rev BRADLEY.E J Philadelphia Electric Co 83/05/25, 8CHHENCER.A Licensing Branch 2 20pp 18653 243 24X Fiche: 50-352,83/05/25,8305310009.
- 8305310045 Forwards draft responses to Core Performance Branch draft EER Items 1 through 4 & 6 through 11 FBAR Chapters 4.5.6 & 15 will be revised to incorporate latest approved reve to DESTAR II in June 1983.

 BRADLEY, E J Philadelphia Electric Co 83/05/25, SCHMENCER: A Licensing Branch 2, 16pp 18653 288, 24X Fiche, 50-352:83/05/25, 8305310045
- F. Security, medical, emergency & fire protection plans
- B305110072 Notification of 830518-19 meetings w/util in Bethesda:H0 to discuss fire protection issues MARTIN, RE Licensing Branch 2 B3/03/05 BCHWENCER, A. Licensing Branch 2 3pp 18419 360 24x Ficha, 30-352, 83/05/05, 8305110072
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors applicants for DLs & holders of CPs re clarification of access to control procedures for lew enforcement visits Bvc list encl
 EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.8305110034
- 830518045: Forwards draft responses to SER open items re draft fire protection section: per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
 BRADLEY, E.J. Philadelphia Electric Co. 83/05/13 SCHMENCER: A Licensing Branch 2 67pp 18486 201 24X Fiche. 50-352: 83/05/13. 8305180451
- 8305250133 Forwards Amend 30 to QL application; substituting revised version of physical security plan Rev withheld (ref 10CR2 790)

 BRADLEY, E. J. Philadelphia Electric Co., 83/05/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 3pp. 18364-065 24X Fiche 50-352,83/05/20,8305250133
- ---8305250135 Amend 50 to OL application, substituting revised version of physical security plan M/Certificate of Svc KEUPER, J B Philadelphia Electric Co. 83/05/20 7pp 18584 088 24X Fichs 30-352,83/05/20,8305250133
- O Adjudicatory correspondence
- B305020441 Answer opposing Limsrick Ecology Action, F. Romano & H. Lewis further particularization of conditionally admitted contentions Neither specificity nor bases provided for contentions Certificate of Syc encl MCTICHMANN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn 83/04/27 Atomic Safety and Licensing Board Panel. 48pp 18283.072. 24X Fiche 50-352,83/04/27,8305020441

- B303040470 New info contention re inadequate util mgt Repeated carelyeaness, malfunctioning safety-related equipment & util response adversely reflect on mgt capability RDMANO,F R Air and Water Pollution Patrol B3/04/27 Commissioners ip 18322 236 24X Fiche 50-352,83/04/27,8305040470
- B305020405 Notice of ASLAB reconstitution CN Kohl, chairman & 9J Edles & RL Gotchy, members
 TOMPKINS, B A Atomic Bafety and Licensing Appeal Panel 83/04/28
 ip 18273 066 24X Fiche 30-352:83/04/28.8305020405
- 8305030363 Forwards joint repts on status of emergency planning reviews & schedule re onsite & offsite emergency planning contentions, status of discovery & suggested items for discussion at 830509 prehearing conference HETTERHAHN, M J Conner & Wetterhahn HETTERHAHN, M J Philadelphia Elactric Co 83/04/29 BRENNER, L, MORRIS, P A, COLE, R F Atomic 84fety and Licensing Board Panel 7pp 18306 118 24X Fiche: 50-352, 83/04/29, 8305030363
- 8305030550 Memorandum & order ALAB-726, reversing ABLB 830427 Decision LBP-83-25 & remanding Del-Awarr B30308 request for labe-filed Contention V-26 to ABLB for disposition on merits.

 BHOEMAKER: C J Atomic Bafety and Licensing Appeal Panel 83/05/02 Atomic Bafety and Licensing Board Panel 7pp 18306 140 24X Fiche 50-352, 83/05/02, 8305030550
- 8305060478 Provides update of status of conditionally admitted non-pRA contentions
 HETTERMANN.M J Conner & Wetterhahn WETTERHAHN.M J Philadelphia
 Elactric Co 83/05/03 BRENNER.L , COLE,R F , COLE,R F Atomic
 Safety and Licensing Board Panel 7pp 18348 238 24X
 Fiche 50-332,83/05/03,8305060478
- 8305060339 Response to Limerick Ecology Action/Air & Water Pollution Patrol spec of conditionally admitted contentions Contentions I-B, I-15 & I-30 admissible PRA contentions should be denied Certificate of Svc encl HODODON: A P Hearing Branch 2 83/05/04 Atomic Safety and Licensing Board Panel 23pp 18344 085 24X Fiche 50-352,83/05/04.8305060339
- 8305090478 Advises of change of address Svc list should be amended accordingly ELLIOTF, C. H Brose & Poswistillo 83/05/06 NRC No Detailed Affiliation Given ip 18360 235 24X Fiche 50-352,83/05/06,8303090478
- 8305120278 Forwards status rept on draft emergency plan preparation AU,T Y Pennsylvania, Commonwealth of, 83/05/09 BRENNER,L., COLE,R F. MORRIS,P A Atomic Safety and Licensing Board Panel 1p 18427 257, 24X Fiche. 50-352, 83/05/09, 830120278
- --B305120280 Status rept re preparation of draft emergency plans Certificate of Svc encl AU,T Y Pennsylvania, Commonwealth of, 83/05/09 App. 18427 258 24X Fiche 50-352,83/05/09,8305120278
- B305120296 Forwards JI Ruttenberg notice of appearance & AJ Nogee notice of withdrawal of appearance Certificate of Svc encl RUTTENBERO, J I Keystone Alliance B3/05/09 BRENNER, L , MORRIS,F A , COLE,R F A tonic Safety and Licensing Board Panel 5pp 18430-171 24X Fiche 50-352,83/05/09.8305120296
- 8305160174 Notice of appearance in proceeding Certificate of Svc encl BUSH, M W Philadelphia, PA 83/05/09 5pp 18446 068 24X Fiche. 50-352, 83/05/09, 8305160174
- 8305160177 Notice of Appearance in proceeding LEWIS:KS Philadelphia: PA 83/05/07 2pp 18444 034 24X Fiche 50-352:83/05/07:8305160177,
- 8305170533 Response to ASLB 830321 order advising that Commonwealth of PA.Ofc of Consumer Advocate intends to participate in proceeding MERSAN.D. Pennsylvania. Commonwealth of, 83/05/10 BRENNER,L Atomic Bafety and Licensing Board Panel 1p 18467 355 24X Fiche 50-352.83/05/10.8305170533
- 8305170538 Order directing util,NRC & Air & Water Pollution Patrol to jointly supply ASLB w/IE Insp Rept 50-353/76-06, notice of violation, util response & other documents re scope of reexam of welds by particular inspector BRENNER.L. Atomic Bafety and Licensing Board Panel, 83/05/13 Philadelphia Electric Co 3pp 18469 025 24X Fiche: 50-352,83/05/13,8305170538

- 8305180136 Memorandum & order confirming schedules established at 830509-11 special prehearing conference NRC ordered to rept on FEMA schedule for reviewing plans & NRC schedule for issuing SER, first SER suppl.PRA.055 & FES BRENNER, L Atomic Safety and Licensing Board Panel 83/05/16 10pp 18490 012 24X Fiche 50-352,83/05/16,8305180136
- 8305240516 First set of interrogatories on pressurized thermal shock contention Certificate of Svc encl Related correspondence LEWIS.M I Lewis. M 83/05/19 Office of the Executive Legal Director ip 18571 175 24% fiche 50-352.83/05/19.8305240516
- 8305260181 Forwards IE Insp Rept 50-253/76-06, notice of violation & util response, per ABLB 830513 order re GA documents Comments on insp repts, notices of violation & interrogatories received on 830518 W/o encl ROMANO.F R Air and Water Pollution Patrol 83/05/19 BRENNER, L Atomic Safety and Licensing Board Panel ip 18599 261 24X Fiche 50-352,83/05/19,8305260181
- 8305230239 Advises that FEMA is discussing time needed to review Pannsylvania Emergency Mgt Agency emergency plan w/FEMA regional ofc NRC schedules for issuance of BER. SER suppl, PRA. DEB & FEB unchanged VDQLER.B H Hearing Branch 2 83/05/20 BRENNER.L, MORRIB, P. A. CQLE.R F Atomic Safety and Licensing Board Panel 2pp 18537 004 24X Fiche 30-352,83/05/20,8305230239
- 8305240489 Forwards, in response to ASLB 830513 order for GA documents, IE Insp Rapt 50-353/76-06 & related documents WETTERHAHN, M J Conner & Wetterhahn, WETTERHAHN, M J Philadelphia Electric Co 93/05/20 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 87pp 18572 166 24X Fiche 50-352,83/05/20,8305240489
- 8305260322 Response to ASLB 830516 scheduling order Addl statement re NRC use of PRA & rept on NUREG-0737. Item II K 3 18 encl Schedules for NRC issuance of documents discussed at second special prehearing conference valid M/Certificate of Svc HODGDON, A P Hearing Branch 2 83/05/24 9pp 18625 019 24X Fiche 50-352.83/05/24.8305260322
- --8309240327 Forwards evaluation of BWR Owners Group generic response to NUREG-0737. Item II K 3 18. "Mod of Automatic Depressurization Sys Logic Feasibility for Increased Diversity of Bome Event Sequences "Response requested SCHMENCER. A Licensing Branch 2 63/03/23 BAUER. E 0 Philadelphia Electric Co 9pp 18625 028 24X Fichs 50-352, 83/05/24, 8305260322
- --8304140161 Forwards safety evaluation of mods proposed by BWR Owners
 Group re NUREG-0737, Item II K 3 18, "Mod of ADS Logic"
 Two options proposed acceptable W/a entl
 HOUSTON, R W Assistant Director for Reactor Safety 83/04/01
 LAINAS, G C Assistant Director for Safety Assessment 2pp
 18625 037 24X Fiche 50-352,83/05/24,8305260322
- B305310013 Supplemental motion to reopen &/or to admit new Contentions V-27 & V-28 re feasibility of providing water to plant by startup Certificate of Svc encil SUGARMAN, R J Del-Aware Unlimited, Inc. SUGARMAN, R J Bugarman, R J. B3/05/24 Atomic Safety and Licensing Board Panel 17pp 18653 263 264 Fiche 50-352,08705/24,0305310013
- H General correspondence
- 8305240316 Requests MW Bush & K Lewis be added to DL proceeding svc list for City of Philadelphia Svc Will replace former managing director, W Goode BUSH, M W Philadelphia, PA 83/05/19 BRENNER, L, GOLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18548 197 24x Fichs 50-352,83/05/19,8305240316
- K Utility Final Sefety Analysis Report (FSAR) & amends
- 8301310240 Forwards Rev 16 to FSAR BRADLEY: E J Philadelphia Electric Ca 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16967 246 24X Fiche, 30-352, 83/01/28, 8301310260
- --8301310274 Rev 16 to Limerick Generating Station, Units 1 % 2 FSAR. * Philadelphia Electric Co 83/01/31 442pp 16967 333 24X Fiche 50-352,83/01/28,8301310260
- 8305160117 Rev 19 to FBAR * Philadelphia Electric Co B3/04/30 626pp 18448 187 24X Fiche, 50-352, 83/04/30, 8305160117

- 8303190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR SOSTINGED TO THE STATE OF THE SECOND STATE OF THE STATE O
- Q Inspection reports. IE Bullatins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spant Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list
 - enci TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24% Fiche 50-000.83/03/21.8212040385
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator "
- Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- 103040023 te for a first notice as action of the second of
- 8303040023 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing 8ys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305050202 Informs that changes to Resemount transmitters will be suppowed informs that changes to Resemblic transmitters completed by 840701 for Unit 1 & prior to fuel load for Unit 2 Info completes response to JE Bulletin 80-14 KEMPER.J 8 Philadelphia Electric Co 83/04/25 HAYNE Region 1. Office of Director 3pp 18341 078 24X Fiche.50-352.83/04/25,8305050202
- B305060057 Notification of significant licensee B30502 meeting in Philadelphia.PA to discuss results of SALP TRIPP.L E Region is Office of Director B3/04/27 Division Project & Resident Programs ip 18054 362 24X Fiche 50-352.83/04/27.8305060057 Division of
- 8303040025 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co 18382 047 24x Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 11889 18382 165 24X Fiche 50-000,83/04/28,8303040027 110pp
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enc! JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidates Edison Co of New York, Inc 122pp. 18441 170 24X Fichs 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030
- 8303040031 [E Info Notice 82-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list and I JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York Inc. 117pp 18441.001 24X Ficha 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Syc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24x Fiche: 50-000, 83/05/11, 8303040034

- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program 1
- 8305240489 Forwards, in response to ASLB B30513 order for QA documents.
 IE Insp Rept 50-353/76-06 & related documents
 WETTERHAHN, M J Conner & Wetterhahn 83/05/20 BRENNER, L. Atomic
 Safety and Licensing Board Panel 87pp 18572 166 24X
 Fiche 50-352,83/05/20,8305240489
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sempling of Contaminated 011" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040048
- T Hearing transcripts on non-antitrust matters
- 8305160035 Transcript of 830509 prehearing conference in Philadelphia. PA Pp 4,037-4,167 • Atomic Bafety and Licensing Board Panel 83/4 18456 074 24X Fiche 50-352,83/05/09,8305160035 83/05/09, 132pp.
- 8305160173 Transcript of 830510 hearing in Philadelphia, PA * Atomic Safety and Licensing Board Panel 83/05/10 228ee 24X Fiche 50-352, 83/05/10, 8305160173
- 8305160016 Transcript of 830511 prehearing conference in Philadelphia PA Pp 4,376-4,529 * Atomic Sefety and Licensing Board Panel 83/05/11 18453 165 24% Fiche 50-352,83/05/11,8305160016 83/05/11 13500
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8305130074 Forwards draft responses to Auxiliary Sys Branch Guestians 410 00 410 104 Info discusses Rev 14 to FBAR re detection of leakage through spent fuel pool liner & continuous accupational exposure during normal operations.

 BRADLEY,E J Philadelphia Electric Co B3/05/07 SCHKENCER, A Licensing Branch 2 12pp 18438 045 24X Fiche 50-353, 83/05/09. 6305130076
- O Adjudicatory correspondence
- 8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl. CHILKS J Office of the Secretary of the Commission 83/03/31 Commissioners 3pp 17807 049 24X Fiche 50-000.83/03/31. 8304040470
- 8305060250 Order extending time until 830513 for Commission to act to review ALAB~701 HDYLE.J C Office of the Secretary of the Commission 83/ Commissioners 1p 18345 196 24X Fiche 50-000,83/05/05,8305060230
- 8305130060 Response opposing intervenor motion for recusation. Motion does not specifically discuss reasons why prior activities may constitute conflict of interest PALLADINO.N J. Commissioners 83/05/11 2pp 18436-RR8 24X Fichs 50-000.83/05/11.8305130060
- B305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701 CHILKS J Defice of the Secretary of the Commission B3/05/12 Commissioners ip 18437 033 24X Fichs 50-000.B3/05/12. 8305130061
- 8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 patition for review of ALAB-701 CHILK.8 J Defice of the Secretary of the Commission 83/05/19. Commissioners ip 18514:283 24X Fiche, 50-000, 83/05/19.
- 8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EFA stds Beparate J Ahearne statement encl. CHILK, S J Office of the Secretary of the Commission 83, 14pp 18653 311 24x Fiche 50-000,83/05/27,8305310017 83/05/27

I Financial information

8305200067 Forwards Annual Financial Repts for 1982 FAYLING,R Public Service Electric & Oas Co of New Jersey 83/05/17 Office of Nuclear Reactor Regulation, Director 1 8516,198 24X Fichs 50-000,83/05/17.8305200067

Q Inspection reports. IE Bulletins & correspondence

- 8305160083 Forwards IE Insp Rept 50-354/83-05 on 830301-0417 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 83/05/02 MARTIN, T J Public Service Electric & Oas Co of New Jersey 2pp 18451 007 24X Fichs 50-354,83/05/02,8305160083
- --8305160087 Notice of violation from insp on 830301-0417

 Division of Project & Resident Programs 83/05/02 i 18451 009 24X Fiche 50-354.83/05/02.8305160083
- --8305160091 IE Insp Rept 50-354/83-05 on 830301-0417 Noncompliance noted failure of QC insp to identify HVAC ductwork support discrepancies
 BATEMAN,W H , TRIPP.L E Region 1, Office of Director 63/04/2. 1449. 18451 010 24X Fiche 50-354,83/05/02.8305160083
- 8305170487 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/83-02 STAROBIECKIR Division of Project & Resident Programs 83/05/11 MARTIN, T J Public Bervice Electric & Gas Co of New Jersey ip 18469, 358 24X Fiche 50-334,83/05/11,8305170487
- --8305170490 Responds to NRC 830311 ltr re violations noted in IE Insp Rept 50-354/83-02 Corrective actions concrete placements in question covered w/moistened burlap Curing period extended add: 4 days MARTIN.T J Public Service Electric & Oas Co of New Jersey 83/04/08 HAYNES,R C Region 1, Office of Director 2pp 18469 359. 24X Fiche 50-034/83/05/11,8305170487

R. Periodic operating reports & related correspondence

83/05250387 "Monthly Status Completion Rept for Apr 1983 " Fuel load scheduled for Jan 1986 Const progress approx 67 85% complete at end of Apr 1983 LANDRIEU, PR H Public Service Electric & Gas Co of New Jersey 83/05/19 TRIPP, L E Region 1. Office of Director ip 18585 351 24% Fiche 30-354,83/05/19,8305250387

9 Reportable occurrences, LERs & related correspondence

- 8303030459 PNS-1-B3-010 on 830427. Bechtel safety representative received telephone call that bomb located in reactor Search of reactor bldg conducted w/negative results Police notified No press release planned MCKEONNL , KUSHNER.W. JOYNER, J. Region 1, Office of Director 83/04/28 1p 18294 150 24X Fiche 50-354, 83/04/28, 8305030459
- 8303040470 Deficiency rept re scribed lines on small bore piping resulting in sharp discontinuities Initially reported on 830124 Repairs will involve replacing pipe, blending out scribe line or welding Completion expected by 830530 MARTIN.T J Public Service Electric & Oas Co of New Jersey 83/04/28 ALAN, J M Region 1. Office of Director 3pp 18348 080 24X Fichs. 50-354.83/04/28,8305040470
- 8305110255 Significant const deficiency rept re weld defects in Class IE cabinets. Initially reported on B30125, Bailey Controls Coreworked all affected cabinets.

 MARTIN.T J. Public Service Electric & Oas Co. of New Jersey B3/05/02 ALLAN.J M. Region 1. Office of Director 2pp 18393.175. 24X Fiche 50-354/83/05/02, B305110255
- 8305120384 Interim significant const deficiency rept re mechanical shock arrest or brackets supplied by ITT Orinnell w/ potential interference problems Initially reported on 830413 Affected parts returned to ITT Orinnell for rework MARTIN Public Bervice Electric & Cas Co of New Jersey 83/05/05 ALLANJ M. Region i, Office of Director 2pp, 18433 079, 24X Fiche: 50-354.83/05/05,8305120384

♥ Operator Exeminations

E303310185 Informs that initial licensing exams will be given to 28 senior reactor operators & 20 reactor operator candidates in Nov 1985, per Generic Ltr 83-01 Instructor certification exams scheduled for Jul 1985 for eight candidates HITTL-R L. Public Service Electric & Gas Co. of New Jersey 83/05/13 SCHMENCER, A. Licensing Branch 2 ip. 18658 150 24% Fiche: 50-354, 83/05/13, 8305310185.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

- G Adjudicatory correspondence
- 8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views shall CHILK.S J Office of the Secretary of the Commission 83/03/31 Commissioners 3pp 17807 049 24X Fiche 50-000,83/03/31,8304040470
- 8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
 HOYLE.J C Office of the Secretary of the Commission 83/05/05 Commissioners ip 18345 196 24X Fiche 50-000, 83/05/05.
 8305060250
- 8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of Interest PALLADINO. N J Commissioners 83/05/11 2pp 18436 228 24x Fiche 50-000.83/05/11.8305130060
- B305130061 Order extending time until B30520 for Commission to act to review petition for review of ALAB-701 CHILK 8 J Diffice of the Secretary of the Commission B3/05/12 Commissioners ip 18437 033 24X Fiche 50~000.B3/05/12, B305130061
- 8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701 CHILK.S J Office of the Secretary of the Commission 83/05/19 Commissioners ip 18514 283 24X Fiche 50-000,83/05/19,8305200540
- 8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl CHILK, S J Office of the Secretary of the Commission 83/05/27 14pp 18653 311 24X Fiche 50-000, 83/05/27, 8305310017

8 Reportable occurrences, LERs & related correspondence

- B305040470 Deficiency rept re-scribed lines on small bore piping resulting in sharp discontinuities. Initially reported on B30124. Repairs will involve replacing pipe blending out scribe line or welding Completion expected by B30530 MARTIN, T J Public Service Electric & Oas Co of New Jersey B3/04/28 ALLAN, J M Region I, Office of Director 3pp 18348-080 24X Fiche 50-354.83/04/28.8305060470
- 8305110255 Significant const deficiency rept re wold defects in Class IE cabinets Initially reported on 830125 Bailey Controls Coreworked all affected cabinets MARTIN.T J Public Service Electric & Qas Co of New Jersey 83/05/02 ALLAN.J M Region i. Office of Director 2pp 18393 175 24X Fiche 50-354.83/05/02.8305110255
- 8305120384 Interim significant const deficiency rept re mechanical shock arrest or brackets supplied by ITT Orinnell w/ potential interference problems Initially reported on B30413 Affected parts returned to ITT Orinnell for rework MARTIN Public Service Electric & Qas Co of New Jersey, B3/05/05 ALLAN, JM Region 1. Office of Director 2pp 18433 079 24X Fiche 50-354,83/05/05,8305120384

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

- 830519016B Forwards draft rev to organization (Criterion I) section of FBAR Chapter 17 1. "OA Program for Design & Const Phase "Draft reflects current commitments for remainder of ZPS-1 Quidance written per SRP.Rev 2
 80R0MANN.E A Cincinnati Oas & Electric Co 82/10/15
 KEPPLER.J G. HUNTER.D Region 3, Office of Director 16pp 18502 219 24X Fiche 50-359,82/10/15,830519016B
- 8305190190 Responds to 821228 itr requesting supplemental info to 821126 ltr requesting approval for Bechtel to conduct independent review of plant mgt Assessment program includes issues covered in 82112 order to show cause DICKHONERN H Cincinnati Gas & Electric Co 83/01/03 KEPPLER. J & Region 3, Office of Director 67pp 18502-074 24X Ficha: 50-358, 83/01/03, 8305190190

- 8305090542 Partial response to FOIA request for transcript of Commission meetings discussing 821112 order 4 documents supporting NRC recommendations to Commission re issuance of order Forwards App B documents App A documents in PDR FELTON.J M Division of Rules and Records 83/03/17 8AMF Shaw. Pittmen. Potts & Troubridgs 4pp 18365 136 24% Fiche 50-358,83/03/17,8305090942 SAMP, R A
- --8305090545 Submits interim rept of Natl Board Notification ABME Code related const at facility.per State of CH, Div of Boiler Insp
 - MCDONALD.D G Ohio, State of 82/05/12 MILAN.D M Ohio. of 76pp 18365 140 24x Fiche 50-358,83/03/17.8305090542 76pp
- --B305090561 Submite Natl Board Audit Interim Rept 3 re ASME Code related const at facility,per State of GH Div of Boiler Insp Rept covers activities from 820807-0930
 MCDDNALD,D J , ALLISON.C W , BULLIVAN.M F Ghio, State of 82/09/30 MILAN.D M Dhio, State of 18pp 18365 361 24X Fiche 50-358,83/09/17,8305090542
- B305260397 Add1 response to FDIA request for transcripts of Commission B21028,1108 & 12 meetings re issuance of B21112 show cause order & supporting documentation Forwards App A documents App A documents withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records B3/03/28 SAMP.R A Shaw. Pittman. Potts & Trombridge 4pp 18647 294 24X Fiche 50-358.83/03/28.8305260397
- -- 8305260401 Forwards press release, witness list & J Keppler final 30520401 Forwards press release without it to deppte testimony for 820914 hearing on status of NRC review of const activities at facility KAMMERER, C. Diffice of Congressional Affairs 82/09/13 FALLADIND, N. GILINSKY, V. AHERNE, J. Commissioners 18647 298 24X Fiche 50~358,83/03/28,8305260397
- 8305190278 Amend 147 to application for DL, consisting of Rev 93 to COMMANN,E A Cincinnati Gas & Electric Co 83/03/3t Office of Nuclear Reactor Regulation, Director 2pp 16 24X Fiche 50-358,83/03/31,8305190278
- --8309190281 Rev 93 to FSAR
 * Cincinnati Gas & Electric Co
 Fiche 50-358.83/03/31.8305190278 83/03/3£ 79pp 18501 159 24X
- 8305020432 Responds to questions raised in NRC 830404 ltr re contacts w/Bechtel on Zimmer project List of Bechtel revenues to GA Technologies encl NEYLAN.A J Torrey Pines Technology 83/04/05 DICKHONER, W H Cincinnati Gas & Electric Co 4pp 18281 218 24X NEYLAN.A J Torrey Pines Technolog Cincinnati Gas & Electric Co 4pp Fiche 50-358.83/04/05.8305020432
- 8305020435 Requests 1trs & documents referenced in NRC transcript of 830328 public meeting NEYLAN A J CA Technologies, Inc /General Atomic Cc 83/04/15 DICKHOMER H H Cincinnati Oas & Electric Co 1p 18281 252 24X Fichs 50-358/83/04/15,8305020435
- 8305020367 Forwards advance copy of "Program Plan for Independent Review of Zimmer Project Mgt " Plan will be discussed at 830425 public meeting in Cincinnati.OH NEYLAN.A J Torrey Pines Technology 83/04/21 DICKHONER.W H Cincinnati Gas & Electric Co ip 18276 250 24X Fiche 30-358,83/04/21.8305020367
- --B305020368 GA-C17044. "Program Plan for Independent Review of Zimmer 83/03/31 39pp 18276 251 24%
- 8305030528 Application for Amend 148 to OL application consisting of NOTIONAL PROPERTY OF THE PROPE
- 8305110118 REPORT OF THE EVALUATION TEAM ON THE QUALITY OF CONSTRUCTION AT THE IIIMMER NUCLEAR POWER STATION
 # NRC No Detailed Affiliation Ofven NUREG-0769 83/04/30
 391pp 18418 001 24% Fishe 50-358.83/04/30,8305110118
- 8305120022 Notification of 830401-03 meetings w/util in Moscow, OH for site audit of environ qualification of safety-related electrical equipment KINTNERL L Licensing Branch 1 83/05/03 YOUNGEL KINTNERLL Licensing Branch 1 83/05/03 YOUNOBLODD, B J Licensing Branch 1 4pp 18443 278 24X Fiche.50-358,83/05/03. 8305120022

- 8305040323 Board Notification 83-057 forwards differing prof opinions re sus interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issus EISENHUT, D. G. Division of Licensing 83/05/04 PALLADING, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04,
- 8305170550 Responds to 830107 ltr requesting concurrence in performing JUSI/UJOSU NEJADORS to BSOIO/ IT requesting conturrance in pe addi work activities not in violation of 821112 show cause order & order immediately suspending const Listed activities not safety-related & may be undertaken MARNICK.R F Region 3. Office of Director 83/05/06 BURG Cincinnati Gas & Electric Co 5pp 18469 153 24X Fiche 50-358. B3/05/06/8305170550 BORGMANN E A
- --8305170553 Requests that work activities not in violation of B2[i]2 order to show cause & order to immediately suspend essential const be allowed to continue Activities to be performed DGROMANN, E A Cincinnati Oas & Electric Co 83/01/07 KEPPLER, J O Region 3. Office of Director 5pp. 18469.138 24X Fiche. 50-358.83/05/06,8303170550
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659.
- 8305130111 Forwards Certificate of Svc for License Amend 148 in form of Rev 94 to FBAR WILLIAMS.J Cincinnati Gas & Electric Go 93/05/09
 Diffice of Nuclear Reactor Regulation, Director 2pp
 24X Fiche 50-358,83/05/09,8305130111
- 8305170093 Board Notification 83-62 forwards NRC evaluation team independent assessment of installed safety-related equipment W/o rept aguspment w/o rept NGYAK,T M Division of Licensing 83/05/10 Atomic Bafety and Licensing Appeal Panel 7pp 18495 317 24X Fiche: 50-358,83/05/10. Licensing Appeal Panel 8305170093
- --8305170098 Forwards NRC evaluation team rept (NUREC-0969) we onsite hardware evaluation conducted 830124-0304 W/o encl DIRCKS.W J Office of the Executive Director for Operations 83/05/04 PALLADING,N, GILINBKY,V, AHEARNEJ, Commissioners ip 18495.323 24X Fiche 50-358,83/05/10.8305170093
- 8303230630 Requests rev of GA program description in FSAR Section 17 I to incorporate changes resulting from util response to 821112 order suspending const of safety-related equipment YOUNGBLDDD, B. J. Licensing Branch i 83/05/11 WILLIAMS, J. Cincinnati Gas & Electric Co. 4pp. 18543-025 24X Fiche 50-358,83/05/11,8305230630
- 8303230658 Forwards Containment Sys Branch request for add1 info re performance of wetwell-to-drywell vacuum breakers during LOCA pool swell phase for Mark II containments OL application should be amended by ref NEDE-22178(F) YOUNGSLOOD. B J Licensing Branch 1 83/05/13 WILLIAMS. J Cincinnati Gas & Electric Co 4pp 18542 337 24X Fiche 50-358.83/05/13,8305230658
- 8305190312 Ack receipt of 820830 ltr re understanding of 801224 immediate action ltr & associated stop work order concerning Reactor Controls Inc Hork performance will be examined following lifting of Commission 821112 order WARNICK.R F. Region 3, Office of Director 83/05/16 WILLIA Cincinnati Gas & Electric Co. 2pp 18501 062 24X Fiche. 50-358, 83/05/16, 8305190312
- ---8305190314 Documents 820818 telcon re Stop Work Order 82-01. Immediate action itr issued on 801224 Stop Work Order 80-14 applies only to matl.equipment & labor supplied by Reactor Controls, inc Catalytic, Inc released to perform new work BDROMANN.E. A Cincinnati Gas & Electric Co 82/08/30. KEPPLER.J J. Region 3. Dffice of Director 2pp 18501 064, 24% Fiche 50-358,83/05/16,8305190312
- 8305200454 Requests addl info re time required to recertify welfers employed at plant from Jul-Nov 1982 during special welfer qualification program Detailed accounting of time for each individual welfer should be provided KEPPLER. J G Region 3, Office of Director 93/05/17 WILLIAMS. Cincinnati Gas & Electric Co 3pp 18513 011 24X Fiche 50-358 83/05/17,8305200454. WILLIAMS, J

- 8305200558 Confirms followup 830526 meeting in Cincinnati, OH to discuss details of planned independent mgt review, including 6A & quality verification programs Meeting will be open to public.

 KEPPLER: J G Region 3. Office of Director 83/05/17 NEYLAN: A J Torrey Pines Technology 2pp 18515 353 24X Fiche 50-358, 83/05/17.8305200558
- 8305260336 Responds to 830506 request for NRC review & acceptance of results & conclusions of quality confirmation program, Task V (radiography) Review & disposition of identified nonconforming conditions will be performed during next insp HARNICK, R F Region 3, Office of Director 83/05/23 MILLIAMS, J Cincinnati Qas & Electric Co 2pp 18625 044 24X Fiche 30-358.63/05/23,8305260336
- --B305260337 Forwards Rev i to "Task V Radiographic Confirmation Rept," demonstrating adequacy of AW Kellogs Co.radiograph technique for piping subassembly shop welds HILLIAMS. J Cincinnati Gas & Electric Co B3/05/06 KEPPLER. J C Region 3. Office of Director 2pp 18625 046 24X Fichs 50-238, 83/05/26, 830362036
- ---8305260338 Rev 1 to "Task V Radiographic Confirmation Rept " # Cincinnati Gas & Electric Co 83/03/24 10pp 18625 048 24X Fiche 50-358,83/05/23,8305260336
- E NRC Safaty Evaluation Report (SER), supply & correspondence
- B30507048b Forwards response to Suppl 3 of SER (NUREG-052B).
 Section 3 10, "Seismic & Dynamic Qualification of Seismic Category 1 Mechanical & Electrical Equipment "FLYNN, J D Cincinnati Gas & Electric Co 83/05/05 DENTON, H Office of Nuclear Reactor Regulation, Director 4pp 18360 223 24% Fiche 50-358,83/05/05,8305070486
- F Security, medical, emergency & fire protection plans
- B305ii0034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EIGENHUT. D. Q Division of Licensing B3/05/ii Consolidated Edison Co of New York: Inc 16pp 18540 075 24X Fichs, 50-000, 83/05/ii, B305ii0034
- 8305180458 Forwards "Ohio River Valley Wind Field Characterization Within WH Zimmer Nuclear Power Station Emergency Planning Zone," in response to NRC Guestion 322 18 WILLIAMS, J Cincinnati Qas & Electric Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18482 163 24X Fiche 50-358,63/05/13,8305180458
- --8305180463 "Ohio River Valley Wind Field Characterization Hithin WH Zimmer Nuclear Power Station Energency Planning Zone "

 * Stone & Webster Engineering Corp 89/04/30 28ipp 18482 165 24% Fiche. 30-358,83/05/13.8305180458
- B303240213 Forwards monthly status rept on offsite emergency preparedness for QL reviews for Apr 1983
 DIRCKS,W.J Office of the Executive Director for Operations
 B3/05/13 PALLADINO,N J. Commissioners 5pp 18593 322 24X
 Fiche 50-000.83/05/13,8305240213.
- O Adjudicatory correspondence
- 8305110290 Clarifies Contention 5 re ion exchange resin reactor coolant polishing sys.per IOCFR2.206
 01LLMAN,D. Affiliation Unknown 83/04/28 Office of Nuclear Reactor Regulation, Director 3pp 18393 304 24X Fiche: 50-338,83/04/28,8305110290
- 8305040436 Order extending time until 830520 for Commission to act to review Director's decision
 CHILK, 8 J. Office of the Secretary of the Commission 89/05/02
 Commissioners ip. 18321.305 24X Fiche 50-358,83/05/02,8305040436.
- 8305040504 Decision ALAB-727.modifying ASLB 820621 decision As modified decision is affirmed Emergency response plans need not be final when OL application noticed for hearing.
 SHOEMAKER.C J Atomic Bafety and Licensing Appeal Panel. 83/05/02 28pp. 18319:236. 24X Fiche 50-358.83/05/02.8305040504
- 8305110350 Memorandum & order dismissing D Gillman 830317 & 0408 appeals re ABLB denial of intervention. Content of appeals appears to constitute challenge to ABLB application of factors governing late filed intervention potitions GHOEMAKER.C J. Atomic Bafety and Licensing Appeal Panel GILLMAN.D. Affiliation Unknown. Bpp 18406 132 24X Fiche 50-358,83/05/10,8305110350.

- 8305200525 Order extending time until 830527 for Commission to act to review Director's decision dtd 830210 CHILK, 8 J Office of the Sacretary of the Commission 83/05/19 Commissioners 1p 18516 074 24X Fiche 50-358,83/05/19, e20820023
- B305240171 Requests recommendations on proceeding w/remaining offsite emergency planning issues in light of ALAB-727 FRYE.J H Atomic Safety and Licensing Board Panel B3/05/25 BARTH.C A Hearing Branch I CONNER.T B. NETTERHAHN.H J Conner & Wetterhahn Ip 18597 289 24X Fiche 50-358.83/05/25.8305260171
- 8305310018 Order extending time until B30606 for Commission to act to review B30210 Director's decision CHILK, S.J. Office of the Secretary of the Commission B3/05/27 Commissions ip 18653 125 24X Fiche 30-358,83/05/27, e305310018
- H General correspondence
- 8305160202 Ack receipt of 830413 ltr re selection of Torrey Pines Technology (TPT) to conduct mgt review of facility TPT to meet w/NRC to consider final review plan MENCZER: W B Region 3, Office of Director 83/05/02 WESTBROOK, J Cleveland, OH 2pp 18462 339 24X Fiche 50-358.83/05/02, 8305160202
- J Insurance & indemnity information
- 8305270539 Responds to 830422 ltr re American Nuclear Insurers activity at facility No ASME Code work in process due to stop work order HJ Kaiser continuing to resolve existing nonconformances & verification of resolutions
 DDBEL.H F Hartford Insurance Group 83/05/19 HARRISON 9 F
 National Board of Boiler & Pressure Vessel Inspectors 2pp
 18646 137 24% Fiche 30-358.83/05/19.8303270539
- K Utility Final Safety Analysis Report (FBAR) & amends
- B30519027B Amend 147 to application for QL.consisting of Rev 93 to FBAR BORGMANN,E A Cincinnati Gas & Electric Co 83/03/31 DENYON, E Office of Nuclear Reactor Regulation, Director 2pp 18501 157 24X Fichs 50-358, 83/03/31, 830519027B
- --8305190281 Rev 93 to FSAR

 * Cincinnati Gas & Electric Co 83/03/3J 79pp 18501 159 24X
 Fiche 50-358.83/03/3I.8305190278
- B303030528 Application for Amend 148 to CL application, consisting of Rev 94 to FSAR BDRGMANN.E A Cincinnati Gas & Electric Co 83/04/27 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 18292 356 24X Fichs 50-358,83/04/29,8305030528
- --8305030533 Rev 94 to FBAR * Cincinnati Gas & Electric Co 83/04/30 228pp 18292 358 24x Fiche 30-358,83/04/29,8305030528
- 8305130111 Forwards Certificate of Svc for License Amend 148 in form of Rev 94 to FSAR WILLIAMS, J. Cincinnati Gas & Electric Co. 83/05/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 18438 087 24X Fiche 50-358,83/05/09,8305130111
- Q Inspection reports. IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8305;20070 Add1 response to FOIA request for IE Insp Rept 50-358/81-13 Portions of documents listed on app withheld (ref FOIA Examption 4) FELTON, J M Division of Rules and Records 83/03/21 DEVINE, T, ROBENTHAL Government Accountability Project 3pp 18443 173 24X FIGHS 50-358.83/03/21.8305120070
- --8305120074 Forwards Electrical Drafting 8td EDSB-126 revised on 791005, Pages 2-43 through 2-48 of Electrical Installation Spec H-2173 & Pages 8 3-29.8 3-30 & 8 3-65 of FSAR, per request re tray loading criteria. Related info encl COTTA, R E Sargent & Lundy, Inc. 81/02/18 BARRETT, P Region 3. Chicago, Office of the Director 36pp 18443 196 24X Fiche 50-338,83/03/21.8305120070

- 8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies Alt NRC ofcs will comply wi/FOIA request Request Requests will be coordinated w/Ofc of General Counsel PALLADIND, N J Commissioners B3/04/14 UDAtL, M K House of Rep Interior & Insular Affairs 7pp 18594 131 24X Fiche 50-358-83/04/14,8305240252
- --8305240256 Responds to 830302 ltr re processing of T Applegate FDIA request for documents on investigation into alleged const deficiencies All FOIA requests will be coordinated w/Ofc of General Counsel Commissioners views encl PALLADINO, N J Commissioners 83/04/14 SEIBERLING, J F House of Rep. Interior & Insular Affairs 12pp 18374 130 24X Fiche 50-258.83/04/14.8305240252
- --8305240263 Discusses investigation of Applegate allegations, "Adequacy of IE Investigation 50-358/80-09 at WH Zismer Nuclear Fower Station." per Udali 821207 itr IE investigation found unsatisfactory in Aug 1981 T Harpster interview encl CUMMINGS. J J Office of Inspector & Audstor 83/01/05 BICKNIT, L Office of the General Counsel 8pp 18594 153 24% Fiche 50-358.83/04/14.8305240252
- --8305240267 Forwards add1 info re NRC withholding of T Harpster interview w/Govt Accountability Project 811123 FOIA request. per Commission 830207 instructions CUMMINOS.J Office of Inspector & Auditor 83/02/14 MALSCH.M G Office of the General Counsel App 18594 163 24X Fiche 50-358,83/04/14.8305240232
- --B305240272 Requests info re Dfc of inspector & Auditor (GIA) inquiry into Zimmer matter Reasons for removal of documents from DIA ofcs questioned Hithholding of documents contributed to delay in public recognition of true status of project UDALL-M K House of Rep . Interior & Insular Affairs 82/12/07 PALLADING. N J Commissioners ip 18594 169 24X Fiche 50-358.83/04/14.8305240252
- --8305240275 Requests add1 info re 821207 ltr seeking explanation of circumstances currounding compliance w/FDIA request for documents pertaining to facility Adequacy of Cummings reply questioned UDALL.M. SIEBERLING.J House of Rep., Interior & Insular Affairs 83/03/02 PALLADING.N Commissioners 2pp 18594 170 24X Fiche 30-358.83/04/14.8305240252
- 8303040021 [E Info Notice 83-21, "Defective Emergency Use Respirator" Evc list enc)
 JURDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consulidated Edison Co of New
 York, Inc 112pp 18383 087 24X Fiche 30-000,83/04/22,8303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphers Bensing Sys " Svc list encl JORDAN.E L pivision of Emergency Proparedness & Engineering Response (Post B30103). B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 50-000, 83/04/25, 8303040025
- B303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl. JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pg 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 6303040030 IE Info Notice 63-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc. 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030

- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York Inc 119pp 18441 OOI 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Ract Deformation " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergenty Operating Procedures (EOP) Quidelines " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305170447 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-10 Request for extension until 830609 for response to noncompliance granted WARNICK: R Region 3, Office of Director 83/05/13 WILLIAMS.J Cincinnati Oas & Electric Co 2pp 18471 224 24X Fiche 50-358.83/05/13.8305170447
- --B305170454 Responds to NRC 830325 ltr re noncompliances noted in IE
 Insp Rept 50-338/62-10 Extension to 830607 for responding to
 noncompliances due to extensiveness of rept requested
 BQROMANN.E A Cincinnati Gas & Electric Co B3/04/20
 KEPPLER.J Ø Region 3, Office of Director 2pp 18471 226 24K
 Fiche 50-358,83/05/19.8305170447
- B305260223 Forwards IE Insp Rept 50-358/82-11 on 820505 & 0726-0930 & notice of violation WARNICK: R F Region 3. Office of Director 83/05/13 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 18622 087 24X Fiche 50-358, 83/05/13, 8305260223
- --8305260223 Notice of violation from insp on 820505 & 0726-0930 WARNICK, R F Region 3, Office of Director 83/05/13 4pp 18622 089 24% Fiche 50-358.83/05/13,8305260223
- --8305260231 IE Insp Rept 50-358/82-11 on 820505 & 0726-0930
 Noncompliance noted failure to follow procedures to document nonconforming welds on piping matl & to provide adequate design control measures
 CHRISTIANSON, W. OWYNN, T.P. NIGHTINGALE, E. Region 3, Office of Director 83/04/14 27pp 18622 093 24X Fiche 50-358.83/05/13, 8305240223
- 9305190269 Ack receipt of 821115 ltr in response to NRC 821027 request for info re allegations concerning welder qualification NRC will examine matters during subsequent inspecting the subsequent inspection of Region 3. Office of Director 93/05/16 WILLIAMS. J. Cincinnati Gas & Electric Co. ip. 18501 238 24X Fiche 50-358, 83/05/16.8305190269
- --8305190273 Responds to 821027 ltr re allegations concerning withholding of relevant documentation on welders from 820709 meeting w/NRC List of documents used at 820708 mgt meeting w/HJ Kaiser t/or 820709 meeting provided SYLVIA:8 R Cincinnati Gas & Electric Co 82/11/15 KEPPLER:J 9 Region 3. Office of Director 3pp. 18501 239 24X Fiche 50-358.83/05/14.8305190269
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"

 Byc list encl
 JURDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 30-000, B3/05/19, 8303040040
- 8305240001 Ack receipt of 830125 & 0223 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-338/82-01 HARNICK, R F Region 3, Office of Director 83/05/20 WILLIAMS, J Cincinnati Gas & Electric Co ip 18549 135 24X Fiche 50-358, 83/05/20,8305240001
- --8305240012 Supple 820804 & 830104 ltrs in response to NRC 020624 itr reviolations noted in IE-Intp Rept 50-358/82-01. Cable grip installation will be verified for cable installed on vertical risers
 BORGMANN,E A Cincinnati Gas & Electric Co 83/01/25
 KEPPLER, J G Region 3, Office of Director ip 18549 136 24X
 Fiche 50-358,83/05/20,8305240001

- --8305240016 Suppls 830125 response to violations noted in IE Insp Rept 50-358/82-01 Design changes require mods to as-built condition Const work authorization request prepared Followup rept will be sent by 830504
 80R0MANN.E A Cincinnati Gas & Electric Co 83/02/23
 KEPPLER.J Q Region 3, Office of Director ip 18549 137 24X
 Fiche 50-358,83/05/20.8305240001
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York

R Periodic operating reports & related correspondence

- 8305250162 Monthly status rept for Apr 1983 W/830319 ltr + Region 3, Office of Director DIRCKS,W J Office of the Executive Director for Operations 83/04/30 PALLADINO,N Commissioners 69pp 18596 071 24X Fiche 50-358.83/04/30, 8305250162
- B Reportable occurrences, LERs & related correspondence
- 8305120342 Interim deficiency rept re masking of radiography by inadequate surface preparation initially reported on 820520 Const work authorization request processed to blond grind & reradiograph welds Next rept expected by 830815 HILLIAMS. J Cincinnati Gas & Electric Co 83/04/29 KEPPLER, J G Region 3. Office of Director 2pp 18432 267 24X Fiche 50-358,83/04/29,8305120342
- 8305120410 Interim deficiency rept re Item M-72 on lack of QA program for fire protection sys installation Sargent & Lundy developing sampling program to assure as-designed sys installed & functional Next rept to be submitted by 830801 WILLIAMS. J Cincinnati Gas & Electric Co 83/04/29 KEPPLER. J G Region 3. Office of Director 20 p 18434 092 24X Fiche: 50-358.83/04/27.8305120410
- 830512042? Interim deficiency rept re Brown Boveri 125-volt dc control device failure on 6 9 kV & 4 16 kV switchgear Initially reported on B30202 All Brown Boveri circuit breakers will be inspected & adjusted Followup rept by B30815 WILLIAMS: J Cincinnati Gas & Electric Co B3/04/27 KEPPLER, J G Region 3, Office of Director 5pp 18431 161 24X Fiche 50-358.83/04/29,8305120429
- --8305120437 "Instructions for Inspecting, Adjusting &/or Replacement of Farts for Obtaining Limit Switch Adjustments on Brown Boveri 75 & V Through 15 kV,500 Through 750 MVAI5HK350, 3000; All HKV Breakers "

 * Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/25 App. 18431 164 24K Fiche 50-358,83/04/29,8305120429
- 8305120432 Interim deficiency rept re failure of essential HVAC turning Vanes (Item M-46) Initially reported on 820510 Scheduling & implementation of test procedure clarifying design adequacy contingent upon release of NRC 821112 order to show cause HILLIAMS. J Cincinnati Gas & Electric Co 83/04/29 KEPPLER, J Q Region 3. Office of Director 2pp 18431 194 24X Fiche 50-358,83/04/29,8305120432
- 8305120446 Interim deficiency rept re Item M-27 concerning lack of weld procedure qualification & Item M-73 concerning possibly altered welding procedures Initially reported on 81:103 & 82:217.respectively HILLIAMS. J Cincinnati Oas & Electric Co 83/04/29 KEPPLER, J G Region J. Office of Director 2pp 18431 078 24X Fiche 50-358,83/04/29,8305120446
- B305120487 Interim deficiency rept re inadequate cable tray hanger insp (Item E-20) Initially reported on 820303 Alternate method for cable tray hanger reinsp developed for galvanised cables Next rept will be submitted by 830620 WILLIAMS, J Cincinnati Cas & Electric Co 83/04/29 KEPPLER, J G Region 3. Office of Director 2pp 18431 055 24X Fiche 50-358, 83/04/29, 8305120487
- B305170524 Interim deficiency rept to Item G-3 concerning lack of inspections not all files of the personnel qualifications Review of work packages to identify any Inspections have qualifications a certification not documented continuing Next rept expected by B3080B WILLIAMS. J Cincinnati Gas & Electric Co B3/05/06 KEPPLER. J G Region 3. Office of Director 20p 18467 249 24X Ficher 50-358.83/05/06.8305170524
- 8305190228 Deficiency rapt ra Item M-84 concerning spent fuel rack spacing Initially reported on 830415 GE evaluation determined condition not reportable per 10CFR30-55(e) WILLIAMS.J. Cincinnati Gas & Electric Co 83/05/10 KEPPLER.J G Region 3. Dffice of Director 2pp 18500-200 24X Fishe 50-338,83/05/10,8305190228

- 8303200534 Interim deficiency rept re seismic qualification of 13 essential damper operator mounting brackets Initially reported on 801014 Vendor approved American Warming & Ventilating Co design mods Next rept by B30810 WILLIAMS. J Cincinnati Gas & Electric Co 83/05/13 KEPPLER, J G Region J. Office of Director 2pp 18516 019 24X Fithe 50-358,83/05/13,8305200536
- 8305190316 Ack receipt of 820929 ltr informing NRC of exception to correction notice to document deficiencies during document review & use of generic nanconformance regist to document deficiencies to comply w/previous commitments WARNICK.R F Region 3, Office of Director 83/05/16 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 18301 039 24% Fiche 50-358,83/05/16,8305190316
- 8305260227 Final deficiency rept re essential instruments attached to nonessential/nonseismic piping Initially reported on 830420 Condition determined not reportable per 10CFR50 55(e) WILLIAMS. J Cincinnati Gas & Electric Co 83/05/19 KEPPLER, J G Region 3, Office of Director 2pp 18599 330 24X Fiche 50-358,83705/19,8305260227

T Hearing transcripts on non-antitrust matters

- B305090537 FOIA request for transcript of Commission meetings discussing B21112 order CLI-B2-33 & documents supporting NRC recommendation to Commission re issuance of order SAMP.R A Shaw. Pittman. Potts & Trowbridge B3/02/09 GRIMSLEY.D H Division of Rules and Records 2pp 18365 134 24X Fiche 50-358.83/02/09.8305070537
- 8305090542 Partial response to FOIA request for transcript of Commission meetings discussing 821112 order & documents supporting NRC recommendations to Commission re issuance of order Forwards App B documents App A documents in PDR FELTON.J M Division of Rules and Records 83/03/17 SAMP,R A Shaw, Pittman, Potts & Trowbridge 4pp 18365 136 24X Fiche 50-358,83/03/17,8305090542
- --B305090549 Testimony of JQ Keppler before US House of Representatives.

 Committee on Interior & Insular Affairs, Bubcommittee on
 Energy & Environ on B20610 re GA problems & related
 activites at facility Pp 1-12

 KEPPLER.J G NRC No Detailed Affiliation Given B2/06/10
 12pp 18365 216 24X Fiche 50-358,83/03/17,8305090542
- 8305260397 Addl response to FOIA request for transcripts of Commission 821028.1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/03/28 SAMP.R A Shaw. Pittman, Potts & Troubridge App 18647 294 24X Fiche 50-358.83/03/28,8305260397
- --8305240405 Testimony of JC Keppler (Region III) before Subcommittee on Energy & Environ of Committee on Interior & Insular Affairs on 830914 re quality confirmation program in Washington, DC KEPPLER, J G Region 2. Defice of Director 82/09/14 62pp 18647 302 24X Fiche 30-358,83/03/28,8305260397

U Congressional/Executive Correspondence

- B303260397 Addl response to FDIA request for transcripts of Commission B21028,1108 & 12 meetings re issuance of B21112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records B3/03/28 SAMP,R A Shaw. Pittman, Potts & Troubridge App 18647 294 24X Fiche 50-358,83/03/28,8305260397
- 8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All NRC ofcs will comply w/FOIA request Request Requests will be coordinated w/Ofc of General Counsel PALLADINO:N J Commissioners 83/04/14 UDALL:M K House of Rep Interior & Insular Affairs 7pp 18594 131 24X Fiche 50-358.83/04/14.8305240252
- --B305240256 Responds to B30302 ltr re processing of I Applegate FDIA request for documents on investigation into alleged const deficiencies All FOIA requests will be controlled W/Ofc of General Counsel Commissioners views encl PALLADINO,N J Commissioners B3/04/14 SEIBERLING.JF House of Rep. Interior & Insolar Affairs 12pp 18594 13B 24X Fiche 50-358,83/04/14,8305240252

- --8303240272 Requests into re Ofc of Inspector & Auditor (OIA) inquiry into Zimmer metter Reasons for removal of documents from OIA ofc: questioned Withholding of documents contributed to delay in public recognition of true status of project UDALL: M.K. Nouse of Rep., Interior & Insular Affairs 82/12/07 PALLADINO.N. J. Commissioners ip 18594 169 24X Fiche 50-358,83/04/14,8305240232
- --8305240275 Requests add1 info re 821207 itr seeking explanation of circumstances surrounding compliance w/FOIA request for documents pertaining to facility Adequacy of Cummings reply Questioned
 UDALL.M., SIEBERLING, J. House of Rep. Interior & Insular Affairs
 83/03/02 PALLADINO, N. Commissioners 2pp 18594 170 24X Fiche 50-358, 83/04/14, 8305240252

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans

- 8305040683 Forwards Amends i8 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness licenser conditions imposed by ASLAB 830304 decision KNIGHTON, O W Licensing Branch 3 83/04/27 DIETCH, R Southern California Edison Co COTTON, O D, BERNATH, L San Diego Gas & Electric Co 5pp. 18357 314 24% Fiche 50-361,83/04/27,8305060683
- --8305060674 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively. modifying emergency preparedness license conditions imposed by ASLAB B30304 decision EISENHUT, D @ Division of Licensing 83/04/27 4pp [8357 318 24X Fichs 50-361, 83/04/27, 8305060683
- --8305060703 Notice of issuance & availability of Amends 18 & 4 to Licenses NPF-10 & NPF-15, respectively NRC No Detailed Affiliation Oiven, 83/04/27 ip 18357 322 24% Fiche 50-361,83/04/27,8305060683
- 8305110034 Generic Ltr 83-2% to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enc!
 EISENNUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York Inc. 16pp 18540 093 24% Fiche: 50-000, 83/05/11, 8305110034
- 8305260242 Forwards IE Gafeguards Insp Repts 50-206/83-11.50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 100FR73 21).

 NORDERHAUG, L. R. Region 5. Office of Director 83/05/12 PAPAY, L. T. Bauthern California Edison Ca. 2pp 18399 322 24X Fiche 50-206.83/05/12,8305260242
- 8303170471 Responds to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re emergency response capability requirements Progress in areas of safety parameter display systematical control room design revieus & emergency response facilities summarized BASKIN,K P Southern California Edison Co. 83/05/13 EISENHU Office of Nuclear Reactor Regulation, Director Rep 18470 CDAX Fiche 50-361,83/05/13,8305170471 18470 077

Q Adjudicatory correspondence

8305190212

- 8305100199 Discusses Memorandum & Order CLI-83-10 re arrangements required under regulations for medical svc for contaminated-injured individuals No further evidentiary hearing required CHANDLER.L.J. Office of the Executive Legal Director 83/04/25 880WN.H.F. Celifornia, Univ. of. San Francisco 1p 18374·199 24X Fiche:50-361,83/04/25,8305100199.
- B305100220 Advises that no further evidentiary hearing required to determine compliance w/Commission regulations re medical sycs for contaminated injured individuals Issue can be resolved on basis of written submission CHANDLER.L.J. Habrings Division B3/04/25, NEBBITT.W Affilia Unknown 10 18373 319. 24X Ficha 50-361.83/04/25,8305100220 Affiliation
- 8305190195 Proposed findings of fact & conclusions of law Declaration of SVC encs PIGOTT,D R Southern California Edison Co PIGOTT,D R Herrington & Sutcliffe, 83/05/16 5pp 18500 001 24X Fiche 50-361,83/05/16,8305190195.
- 8305190212 Motion to augment record to include various revised county emergency plans & other documents re emergency planning.

 Dagisions should reflect current info Declaration of Syc PIOOTT, D. R. Bouthern California Edison Co. Pioott, D. R. Orrick, Herrington & Sutcliffe, 83/05/16 Atomic Safety and Licensing Board Panel 33pp, 18502:146 24X Fichs 50-361,83/05/16.

- 8305190252 Position re Commission 830405 Memorandum & Order CLI-83-(0 on offsite medical sycs Util provided necessary level of medical sycs for general public Declaration of Syc encl. PIGOTY.D R Southern California Edison Co. 83/05/16 9pp 18501 284 24X Fichs 50-361.83/05/16.8305190252
- 8305240522 Order extending time until 830607 for Commission to act to review petitions for review of ALAB-717 CHILKS J Office of the Secretary of the Commission 83/05/20 Commissioners ip 18571 il8 24X Ficha 50-341 83/05/20
- H General correscondence
- 8305090024 Add1 response to FDIA request for documents re 821130 special insp rept Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FDIA Exemption 5) Documents 3 & 4 withheld (ref FDIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/21 GARDE.B Government Accountability Project 4pp 18381 158 24% Fiche 50-206,83/03/21.8305090024 GARDE, B
- B30512017B Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcombe replaces GD Cotton as representative authorized to sign NRC licensing documents HOLCOMBE, J C Ban Diego Qas & Electric Co B3/05/06 E1BENHUT, D & Division of Licensing ip. 18427 156 24X Fiche 30-206, 83/05/06, 830512017B
- P Operating license stage documents & correspondence
- 8305110179 Forwards Amend 1A to License NPF-10, safety evaluation & 305110179 Forwards Amend 16 to License NPF-10; safety evaluation & notice of issuance & availability Amend updates Unit 2
 Tech Specs for consistency w/Unit 3 Tech Specs
 KNIGHTON, Of United States of Security States of Security S
- --8305110182 Amend 16 to License NPF-10, updating Tech Specs for consistency w/Unit 3 Tech Specs KNIGHTON, 0 W Licensing Branch 3 83/04/25 81pp 18434:361, 24% Fichs 30-361,83/04/25,8305110179
- --8303110186 Bafety evaluation supporting Amend 16 to License NPF-10 # Office of Nuclear Reactor Regulation, Director 83/04/25 19 18435 152 24X Fiche: 50-361,83/04/25,8305110179
- --8305110188 Notice of issuance & availability of Amend 16 to License KNTOHTON, G. W. Licensing Branch 3, 83/04/25 2pp. 18435-153 24% Ficha 50-361,83/04/25,8305110179,
- 8305060689 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision
 XNIGHTON, G W Licensing Branch 3 83/04/27 DIETCH, R Southern California Edison Co COTTON, G D, BERNATH, L Ban Diego Gas & Electric Co 5pp 18357 314 24X Fiche 50-361,83/04/27,8305060883
- --8305060694 Amends 18 & b to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ASLAB 830504 decision EISENHUT, D 0 Division of Licensing, 83/04/27 4pp. 18357 338 24X Fiche 50-361,83/04/27,8305060683.
- --B305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively. # NRC No Detailed Affiliation Given B3/04/27. Ip 18357 322 24X Fiche 50-361,83/04/27,8305060683,
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re-new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
 EISENHUT, D. Q Division of Licensing. 83/05/02 Consolidated Edison Co of New York: Inc. 50pp. 18441 120. 24X
 Fiche 50-000, 83/05/02, 8305020455
- 8305040323 Board Notification 83-057 forwards differing prof opinions ra sys interaction & safety classification. Info relates to Board Notifications 83-17 & 83-44 re Unresolved Bafety Issue A-17 EIBENHUT, D. G. Division of Licensing 83/05/04. PALLADING, N. Commissioners. 22pp 18337 139 24X Fiche, 50-000, 83/05/04. B305040323.

- B305170229 Forwards Amends 19 & 7 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability Amends modify Tech Specs re radioactive liquid seffluents & effluent monitoring instrumentation KNIGHTON.0 W Licensing Branch 3 B3/05/04 DIETCH,R Bouthern California Edison Co CATTON.0 D . BERNATH,L San Diego Gas & Electric Co 3pp 18476 349 24X Fiche 50-361.83/05/04.8305170229
- --8305170233 Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation to add steam generator blowdown pass line as alternative release path EISEN-UT, D G Division of Licensing 83/04/29 10pp 18476-352 24% Fiche 50-361.83/03/04.8305170229
- --B303170234 Safety evaluation supporting Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively Pffice of Nuclear Reactor Regulation, Director 83/04/29 8pp 18476 362 24X Fiche 50-361,83/05/04,8305170229
- --8305170236 Notice of issuance & availability of Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively KNIOMATON, 0 W Licensing Breach 3 83/04/29 2pp 18477 008 24X Fiche: 50-361, 83/05/04, 8305170229
- 8303090639 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659
- 8305260122 Comments on 830106 proposal to delete integral test of core protection calculator functional capability from natural circulation test Alternate demonstration of functional capability requested NOVAK.T.N Assistant Director for Licensing 83/05/12 DIETCH.R Southern California Edison Co HOLCOMBE.J C San Diego Oas & Electric Co. 6pp 18649-039 R4X Fiche 30-361.83/05/12.8305260122
- 8305190028 Responds to Generic Ltr 83-10A re resolution of TMI Itam II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Util, as member of C-E Owners Group.has chosen "trip two.leave two" strategy to resolve item

 8ASKIN.K P Southern California Edison Co 83/05/13, KNIGHTON, 0 Licensing Branch 3 2pp 18502.039 24X Fiche 50-361,83/05/13,8305190028
- 8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants; w/emphasis on need for PDRVs in current C-E designs NOVAN, T.M Assistant Director for Licensing 83/05/18. Atomic Bafety and Licensing Board Panel. 7pp 18627 107 24X Fiche: 50-000, 83/05/18, 8305250209
- --8305230221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ABLAB HATTBON, R. J. Division of Systems Integration (post 811005) 83/04/2B. EISENHUT, D.O. Division of Licensing ip 18627 113 24% Fichs 50-000, 83/05/18, 8305250209
- --8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630, DIRCKS, W. J. Office of the Executive Director for Operations 83/04/25. CHILK, S. J. Dffice of the Secretary of the Commission, ip. 18627, 113. 24X Ficher 50-000, 83/05/18, 8305250209
- 8305240458 Forwards status of environ qualification of electrical equipment per 10CFR50 49(g). All equipment except auxiliary feedwater pump motors, meets NUREO-0388 guidelines for Category II plant BASKIN, K.P. Southern California Edison Co 83/05/20, KNIGHTON, G. H. Licensing Branch 3 5pp 18549: 286 24X Fiche 50-361, 83/05/20, 8305240458.
- G Inspection reports, IE Bulletins & correspondence
- B212040385 IE Info Notice B3-14, "Dawatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post B30103). B3/03/21 Consolidated Edison Co of New York, 112pp. 18308,319 24x Fiche 50-000,83/03/21.8212040385

- 8305030075 Comments on Mgt Analysis Co 830404 visit to Region V re recent licensee regulatory performance & circumstances which led to proposed issuance of civil penalties against util CREMB.J L Division of Resident.Reactor Project & Engineering Programs 83/04/13 Division of Resident.Reactor Project & Engineering Programs ip 18300 178 24X Fiche 50-361,83/04/13, 8305030075
- 8303170417 Forwards IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 & notice of violation 818HDP.T W Region 5. Office of Director 83/04/14 PAPAY, L T Southern California Edison Co 2pp 18469 253 24X Fiche 50-361,83/04/14,8305170417
- --8305170420 Notice of violation from insp on 830312-25 KIRSCH,D F Region 5, Office of Director 83/04/14 3pp 18469 255 24X Fiche 50-361,83/04/14,8305170417
- --B305170421 IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 Noncompliance noted failure to rept reactor trip breaker inoperability & to implement vendor svc builetin info STERNDERO, D M, KIRSCH, D F, CHAFFEE, A E Region 5, Office of Director 83/04/13 28pp 18467 258 24X Fiche 50-361, 83/04/14, 8305170417
- 8305170474 Forwards IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No noncompliance noted 818HOP.T.W Region 5. Office of Director 83/04/14 PAPAY, L T Southern California Edison Co. 2pp 18470:086 24X Fiche. 50-361.83/04/14,8305170474
- --8305170480 IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No moncompliance noted Major areas inspected operational safety verification, monthly surveillance, LER review & independent insp effort PATE.R.J. MENDONCA, M.M., D'BRIEN, J.P. Region 5, Office of Director. 83/04/14 App. 18470 088 24X Fiche 50-361, 83/04/14, 8305170474.
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator" Evc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15, Consolidated Edison Co. of New York, Inc. 126pp 18435-155 24X Fiche 50-000,83/04/15,8303040021
- B305170515 Forwards IE Insp Repts 50-361/83-14 & 50-362/83-14 on B30321-30 & notice of violation BCARANO, R A. Division of Radiological Bafety & Bafeguards Program B3/04/18. PAPAY, L T. Bouthern California Edison Co 2pp 18467.260 24X Ficha 50-361,83/04/18,8305170515
- --B305170521 Notice of violation from insp on B30321-30 WENBLAWSKI,F A Region 3, Office of Director B3/04/18 2pp 18467 262 24X Ficher 50-361, B3/04/18, B305170515
- --8305170530 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 Noncompliance noted failure to perform surveys.inform workers & properly monitor liquid radioactive effluent release YUMAS.GP. MENSLAMSKI.FA. BOOK.HE Region 5, Office of Director 83/04/14 10pp 18467 264 24X Fiche 50-361.83/04/18, 8305170515
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 8vc list enc1
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383,089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305170359 Forwards IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08. No noncompliance noted 818H0P, T. M. Region 5. Office of Director 83/04/26 PAPAY, L T Southern California Edison Co 2pp 18466:098 24X Fichs. 50-361:83/04/26, 8305170359
- --8305170361 IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08 No noncompliance noted, Major areas inspected; corrective & preventative maint programs ECKHARDT, JH , KIRSKI,D F Region 5, Office of Director 83/04/22 4pp, 18466 100, 24X Fiche: 50-361,83/04/26,8305170359
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103), 83/04/28, Consolidated Edison Co of New
 York, Inc. 115pp. 18382 047 24X Fiche 50-000,83/04/28,8303040026

- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Divisson of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28,8303040027
- 8303070278 Forwards response to notice of violation & proposed imposition of civil penalties based on IE Insp Repts 50-361/83-06 & 50-361/83-08 Generic procedure will be revised by 830430 to detail key plant sys Paument encl PARAY.C T Southern California Edison Co 83/03/02 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 18364 002 24X Fiche 30-361,83/05/02,8305090278
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24x Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24% Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JOHDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24% Fiche 50-000,83705/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Quidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fichs 50-000,83/05/11,8303040034
- B305260242 Forwards IE Bafeguards Insp Repts 50-206/83-11,50-361/83-20 t 50-362/83-18 an B30425-29 No noncompliance noted Details withheld (ref loteFR73 21) NORDERHAUGL R Region 5, Office of Director 83/05/12 PAPAY.L T Southern California Edison Co 2pp 18399 322 24x Fiche 50-206.83/05/12,8305260242
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list enc!
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 820103) 83/05/19 Consolidated £dison Co of New
 York, Inc 114pp 18697 009. 24X Fiche 50-000,83/05/19,8303040040
- 8305260264 Advises that util 830502 response to notice of violation & proposed imposition of civil penalties acceptable w/one exception re interim measures for analysis of radioactive iodines MARTIN.J B Region 5. Office of Director 83/05/20 PAPAY,L T Southern California Edison Go 2pp 18626 001 24% Fiche.50-361.83/05/20.8305260264
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list enc.)
 JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/26 Consolidated Edison Co of New York: Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8304150372 Monthly operating repts for Feb 1983 MAYWEATHER, L Southern California Edison Co 83/03/15 iipp 17981 359 24X Fiche 50-361.83/03/15.8304150368
- 8. Reportable occurrences, LERs & related correspondence
- 9305030492 RD 50-361/82-176 on 830329, review of monconformance repts revealed less than conservative limiting conditions for operation Caused by failure to verify undervoltage trip mechanism operability following 820710 maint RAY, M.B. Sputhern California Edison Co. 83/03/30 ENGELKEN, R H Region 5. Office of Director 26p 18306 274 24X Fiche 30-361.83/03/30,8305030432

- B305060505 Forwards LER B3-036/01T-0 RAY, H B Bouthern California Edison Co B3/04/08 MARTIN, J & Region 5. Dffice of Director 2pp 18351 143 24X Fiche 30-361, 83/04/08, 8305060505
- --8305060514 LER 83-036/01T-Q on 830321, discharge isolation valva on common liquid radwaste effluent radiation monitor 2/3 RT-7813 discovered shut Caused by personnel error Valve left shut during quarterly channel functional test RAY, H B Southern California Edison Co 83/04/08 Region 3, Office of Director 2pp 18351 145 24X Fichs 50-361,83/04/08,830506505
- B305050341 Forwards AEGD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR.RES & IE BROWN E J Reactor Operations Analysis Branch B3/04/13 SEYFRIT.K V Reactor Operations Analysis Branch 2pp 18352:051 24X Fiche 50-000:83/04/13,8305050341
- --B305050353 "Inoperable Motor Operated Valve Assemblies Due to Primitira
 Degradation of Motors &/or Improper Limit Switch/Torque
 Switch Adjustment: "AEOD engineering svaluation rept
 BROWNE J Director's Office B3/04/13 7pp 18352 053 24X
 Fiths 50-000,83/04/13,8305050341
- 8305030356 Forwards LER 83-026/017-0 Datailed event analysis submitted RAY, H B Southern California Edison Co 83/04/18 MARTIN, J B Region 5, Office of Director 3pp 18306 219 24X Fiche 50-361.83/04/18.8305030356
- --8305030359 LER 83-026/01T-0 on 830404 containment isolation valve 2HV8248 indicated mid-position following both open & closed signals Caused by faulty magnetic reed switch assembly Assembly replaced Valve declared operable RAY.H B Southern California Edison Co 83/04/18 Region 5, Office of Director 2pp 18306-222 24X Fiche 50-361,83/04/18,830530354
- B305230573 Forwards engineering evaluation rept, "Cracks & Leats in Small Diemeter Piping"
 BROWN, E J Reactor Operations Analysis Branch 83/04/19
 SEYRIT.K V Reactor Operations Analysis Branch ip 18541 342
 24X Fiche 50-000
- --B305230519 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require add1 supports or rerouting of piping BROWN/E J Reactor Operations Analysis Branch B3/04/19 9pp 18541 343 24X Fiche 50-000/83/04/19,8305230573
- 8305030340 RD high steam generator differential pressure trip function operability requirements exceeded for Modos 1, 2 & 3 Setpoints will be corrected before reentry into Mode 3 & will be reported in LER by 830505 RAY, H B Southern California Edison Co 83/04/22 MARTIN. J B, Region 5, Office of Director 2pp 18291 361 24X Fiche 50-361, 83/04/22, 83093030360
- 8305020183 PND-V-83-018 on 830421.util received ltr from C-E informing of error in equivalent voltages corresponding to setpoints associated w/steam generator high delta pressure trip function Corrective action being developed BISHOP.T W Region 5. Office of Director 83/04/25 lp 18277 295 24X Fiche 50-361,83/04/25,8305020183
- B305040467 RO B3-D38 on B30426, motor operated valves 2HVB150, 2HVB152 & 2HVB153 could not be opened during testing in preparation to proceed to Mode 3 operation Investigation continuing Followup rept to be submitted by 830512
 RAY, H B Southern California Edison Co 83/04/27 MARTIN, J B Region 5, Office of Director 2pp 18351 190 24X
 Fiche 30-361, B3/04/27, B305060467
- 8305180790 Forwards SER on reactor trip breakers Licensee proposed actions provide acceptable basis for restart & operation EISENHUT, O Division of Licensing 83/05/02 DIETCH, R Southern California Edison Co COTTON, O D. BERNATH, L San Diego Cas & Electric Co 3pp 18505 QQ1 24X Fiche 50-361,83/05/02,8305180790
- --B303180804 BER lifting restrictions on exceeding power documented in confirmation of action ltrs dtd B30311 & 0427 based on corrective actions re reactor trip breaker fellure.

 * Office of Nuclear Reactor Regulation, Director B3/04/30
 58pp 18505 004 24X Fiche 50-361.83/05/02.8305180790
- 8305160011 Forwards LER 83-035/03L-0 RAY, H B Southern California Edison Co 83/05/05, MARTIN.J.B Region 5, Office of Director 1p 18456 083 24X Fiche 50-361,83/05/05,8305160011

- --8305160014 LER 83-035/03L-0 on 830405, pin hole leaks discovered in miniflow line for auxiliary feedwater pump P141, downstream from flow orifice F0-4711 P141 delcared inoperable Caused by cavitation downstream of flow orifice Pipe section replaced RAY, H B Southern California Edison Co 83/05/05 Region 5, Office of Director ip 18456 084 24X Fiche 50-361,83/05/05,8305160011
- 8305160055 Forwards LERs 83-037/01T-0 for Units 1 & 2 RAY, H B Sauthern California Edison Co 83/05/05 MARTIN. J B Region 5. Office of Director 2pp 18451 047 24X Fiche 50-361.83/05/05.8305160055
- --B305160069 LER 83-037/01T-0 on 830421.high steam generator differential pressure setpoint used in PPS emergency feedwater sys logic circultry resulted in actual trip setpoint of 300 psid, higher than assumed in FSAR Caused by conversion error RAY.H B. Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 049 24X Fiche 50-361,83/05/05, 8305160055
- --B305160101 LER B3-037/01T-0 on 830421, high steam generator differential pressure satpoint used in PPS emergency feedwater sys logic circuitry resulted in actual trip setpoint 300 paid higher than assumed in FSAR Caused by voltage conversion error RAY. H B Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 051 24X Fiche 50-361, B3/05/05, B3/05/60055
- B305270321 RB B3-040 on B30426, while filling safety injection tank T-007, valves 2HV9334 & MU-099 inadvertently left open Procedure BD23-3-2 7 revised to include positive steps to close valves. Followup rept will be submitted by B30523 RAY. H B Southern California Edison Co B3/05/09 MARTIN, J B Region 5, Office of Director 3pp 18641 164 24X Fiche 50-361,83/05/09,8305270321
- B305270243 LER B3-038/03L-O on B30426 shutdown cooling sys HX (solation valves 2HVB150,52 & 53 could not be remotely opense from control room Mode 3 restraint imposed Caused by Incorrect sequence torque satting W/B30512 ltr
 RAY.H B Southern California Edison Co. 83/05/12 MARTIN, J B Region 5. 0 Ffice of Director 4pp 18637 157 24X
 Fiche 50-361,83/05/12,8305270243
- B305170278 Confirms no safety-related applications of integral underwoltage trip devices exist other than in reactor trip switchgear, in response to NRC request for info re 830415 reactor trip breaker rept BASKIN, K P Bouthern California Edison Co 83/05/13 KNIGHTON, Q W Licensing Branch 3 ip 18465, 326, 24X Fiche 50-361, 83/05/13, 8305170278
- B305270408 LER B3-039/03L-0 on B30419, diesel generator starting time exceeded surveillance requirement Caused by relay K-8 not reset Relay manually cycled W/B30519 ltr RAY. H B Southern California Edison Co B3/05/19 MARTIN, J B Region 5, Office of Director App 18642 317 24X Fiche 50-361, B3/05/19, B305270408
- B305270131 LER 83-042/03L-0 on 830422, during operability testing, emergency chiller E-335 (train B) stalled Caused by valve closed on surge line due to low compressor suction pressure Valve opened. M/830520 ltr
 RAY. H B Southern California Edison Co 83/05/20 MARTIN, J B Region 5. Office of Director 4pp 18638 210 24X
 Fiche 50-361,83/05/20,8305270131

DOCKET 50-362 BAN ONOFRE NUCLEAR STATION, UNIT 3

- F. Security, medical, emergency & fire protection plans
- 8305060683 Forwards Amends 18 & 6 to Licenses NFF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision KNIGHTON.6 W Licensing Branch 3 83/04/27 DIETCH, R Southern California Edison Co 5pp 18357 314 24X Fiche 50-361,83/04/27,8305060683
- --B305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ASLAB B30304 decision.

 EIBENNUT.D 0 Division of Licensing 83/04/27 4pp 18357 318 24X Fiche 50-361,83/04/27,8305060683
- ---9305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively. • NRC No Detailed Affiliation Given 83/04/27 ip 18357 322 24X Fiche 50-361,83/04/27,8305060683

- B305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT.D G Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540-075 24X Fiche 50-000,83/05/11.83051(0034
- 9303240242 Forwards IE Safeguards Insp Repts 50-204/83-11.30-361/83-20 & 30-362/83-19 on 830425-29 No noncompliance noted Details withheld (ref 100FR73 21)
 NORDERHAUG.L R Region 3, Office of Director 83/05/12 PAPAY,L T Southern California Edison Co 2pp 18399 322 24X
 Fiche 50-204.83/05/12,8308260242
- B305170471 Responds to Generic Ltr 82-33 (NUREO-0737, Suppl 1) re amergency response capability requirements Progress in areas of safety parameter display sys, detailed control room design reviews & emergency response facilities summarized BASKIN:K P Southern California Edison Co B3/05/13 EIGENHUT, D 0 Office of Nuclear Reactor Regulation, Director App 18470 077 24X Fiche 50-361,83/05/13,8305170471

G Adjudicatory correspondence

- B305100197 Discusses Memorandum & Order CLI-83-10 re arrangements required under regulations for medical svc for contaminated-injured individuals No further evidentiary hearing required CHANDLER, L. J. Office of the Executive Legal Director B3/04/25 BROWN, R. F. California, Univ. of, San Francisco ip 18374 199 24X Fiche 50-361, 63/04/25, B305100199
- B305100220 Advises that no further evidentiary hearing required to determine compliance w/Commission regulations re medical sycs for contaminated injured individuals Issue can be resolved on basis of written submission CHANDLER.L J Hearings Division B3/04/25 NEBBITT.W Affiliation Unknown 1p 18373 319 24% Fichs 30-361,83/04/25,8305100220
- 8305190195 Proposed findings of fact & conclusions of law Declaration of Svc encl
 PIGOTT, D R Southern California Edison Co PIGOTT, D R Orrick,
 Herrington & Sutcliffe 83/05/16 Spp 18500 001 24X
 Fiche 50-361,83/05/16,8305190195
- 8303190212 Motion to augment record to include various revised county emergency plans & other documents re emergency planning Decisions should reflect current info Declaration of Svc enci PIGOTT, D R Southern California Edison Co PIGOTT, D R Orrick, Herrington & Sutcliffe 83/05/16 Atomic Safety and Licensing Board Panel 33pp 18502 146 24X Fiche 50-361,83/05/16,8305190212
- B305190252 Position re Commission B30405 Memorandum & Order CLI-83-10 on offsite medical sycs Util provided necessary level of medical sycs for general public Declaration of Syc encl P100TT, DR Bauthern California Edison Co B3/05/16 7pp 18501 284 24X Fiche 50-361,83/05/16,8305190252
- B305240522 Order extending time until B30507 for Commission to act to review petitions for review of ALAB-717 CHILK:S J Office of the Secretary of the Commission B3/05/20 Commissioners ip 18571 118 24X Fiche 50-361.83/05/20.8305240522

H General correspondence

- 8305070024 Add1 response to FOIA request for documents re 821130 special insp rept Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6). Documents 3 & 4 withheld (ref FOIA Exemption 7) FELTON, J M Division of Rules and Records 83/03/21 GARDE, B Government Accountability Project 4pp 18381 158 24X Fiche 50-206.83/03/21,8305090024
- 830312017B Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcombe replaces GD Cotton as representative authorized to sign NRC licensing documents ADLCOMBE.J C. San Diego Gas & Electric Co B3/05/06 EISENHUT, D G Division of Licensing | Ip 18427 156 24X Fiche 50-206.83/05/06.

- P Operating license stage documents & correspondence
- B305060683 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ABLAB 830304 decision MNIGHTON, 0 W Licensing Branch 3 83/04/27 DIETCH, R Southern California Edison Co COTTON, 0 D, BERNATH, L San Diego 9ss & Electric Co 5pp 18357 314 24X Fiche 50-361, 83/04/27, 8305060583
- --8305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ABLAB 830304 decision EISENHUT.D 0 Division of Licensing 83/04/27 4pp 18357 318 24X Fiche 50-361.83/04/27.8305060683
- --8305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively + NRC - No Detailed Affiliation Given 83/04/27 1p 18357 322 24X Fiche 50-361,83/04/27,8305060683
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to CLs 8vc list encl EISENHUT, D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche: 50-000.83/05/02.8305020455
- 8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D © Division of Licensing. 83/09/04 PALLADINO, N Commissioners 22pp. 18337 139 24% Fichs 50-000,83/05/04,8308040323
- 8305170229 Forwards Amends 19 & 7 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability, Amends modify Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation KNIGHTON.0 W Licensing Branch J. 83/05/04 DIETCH.R. Bouthern California Edison Co CATTON.0 D. BERNATH, L. San Diego Oas & Electric Co 3pp 18476 349 24% Fiche 50-361.83/05/04.8305170229
- --8305170233 Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation to add steam generator blowdown pass line as alternative release path EISENHUT, D @ Division of Licensing 83/04/29 10pp 18476 352 24X Fiche 50-361.83/05/04.8305170229
- --8305170234 Safety evaluation supporting Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively * Office of Nuclear Reactor Regulation. Director 18476 362 24% Fiche 50-361,83/05/04.8305170229
- --8305170236 Notice of issuance & availability of Amends 17 & 5 to Licentes NPF-10 & NPF-15, respectively KNIOMTON,0.4 Licensing Branch 3 83/04/27 2pp 18477 008 24X Fiche 50-361,83/05/04,8305170229
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list enci EISENHUT, D. G. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305260122 Comments on 830106 proposal to delete integral test of core protection calculator Functional capability from natural circulation test Alternate damonstration of functional capability requested.

 NOVAK, T M Assistant Director for Licensing 83/05/12 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Cas & Electric Co 6pp 18647-059 24% Fiche-50-361.83/05/12, 8305260122
- 8305190028 Responds to Generic Ltr 83-10A re resolution of TMI Item II K 3.5. "Automatic Trip of Reactor Coolant Pumps " Util, at member of C-E Guners Group, has chosen "trip two, leave two" atrategy to resolve item BASKIN, K.P. Boutharn California Edison Co. 83/05/13 KNIGHTON, C W Licensing Branch 3 2pp 18502.039 24X Fiche 50-361, 83/05/13, 8305190028
- 8305250207 Board Notification 83-063 transmits memos re status of BHR studies for C-E plants, w/amphasis on need for PORVs in current C-E designs.

 NOVAKITM Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X Fiche 50-000,83/05/18,8305250209

- --B305250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PDRVs in current C-E designs be provided to ASLB & ASLAB MATTBON, R. J Division of Systems Integration (post 811005) B3704/28 EIBENHUT, D Q Division of Licensing 1p 18427 113 24X Fishe 30-000, B3705/18, 8305250207
- --8305250228 Responds to Commission 830404 request that study of need fire controlled depressurization capability in C-E plants be accelerated & that ACR8 views be solicited on issue prior to reporting back to Commission Study to be concluded 830630 DIRCKS-W J. Office of the Executive Director for Operations 83/04/25 CHILK, 8 J Office of the Secretary of the Commission ip. 18627.115 24X Fiche 50-000,83/05/18,8305250209
- B305240438 Forwards status of environ qualification of electrical equipment per 10CFR50 49(g) All equipment, except auxiliary feedwater pump motors, meets NUREO-0388 guidelines for Category II plant
 BASKIN.K P Southern California Edison Co B3/05/20 KNIGHTCN.0 p
 Licensing Branch 3 5pp 18549 286 24K Fichs, 50-361.83/05/20,
- Q Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction," Svc list encl.

 TAVLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212060385
- 8305030075 Comments on Mgt Analysis Co 830404 visit to Region V retreast licenses regulatory performance & circumstances which led to proposed issuance of civil penalties against util CREMS.J L Division of Resident Reactor Project & Engineering Programs 83/04/13 Division of Resident.Reactor Project & Engineering Programs 19 18300 178 24X Fiche.50-361,93/04/13.830503075
- B305170417 Forwards IE Insp Repts 50-361/B3-13 & 50-362/B3-12 on B30312-25 & notice of violation BISHOP, T W Region 5. Office of Director B3/04/14. PAPAY, L T Southern California Edison Co. 2pp 18469 253 24X Fiche 50-361, B3/04/14, B305170417.
- ~-830517042i IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 Noncompliance noted failure to rept reactor trip breaker inoperability & to implement vendor syx bulletin infa. BYERNBERG D M , KIRSCH, D.F , CHAFFEE, A E Region 5, Office of Director 83/04/13 28pp 18469, 258 24X Fiche 50-361, 83/04/14, 8305170417.
- 8305170474 Forwards IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No moncompliance noted BISHDP.T W Region 5. Office of Director 83/04/14 PAPAY.L T. Bouthern California Edison Co 2pp 18470 086 24X Fiche 50-361,83/04/14,8305170474
- --8305170480 IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 He noncompliance noted Major areas inspected operational safety verification, monthly surveillance, LER review & independent insp effort PATE,R J , MENDONCA, M M , O'BRIEN, J P. Region 5, Office of Director 83/04/14 App 18470 088 24X Fiche. 50-361, 83/04/14, 8305170474
- 830304002(IE Info Notice 83-2), "Defective Emergency Use Respirator" Evc list encl JORDAN,E L. Division of Emergency Preperedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 185 24X Fiche 50-000,83/04/15,830304002(
- 8305170515 Forwards IE Insp Rapts 50-361/83-14 & 50-362/83-14 on 830321-30 & notice of violation. 8CARAND.R A. Division of Radiological Safety & Safeguards Program 83/04/18 PAPAY.L T. Southern California Edison Co 2pp 18467 260 R4X Fiche 50-361.83/04/19.8305170515
- --B305170521 Notice of violation from insp on 830321-30 MEMSLAMSKI,F A Region 3, Office of Director, 83/04/18. 2pp 18467 262 24X Fiche 30-361.83/04/18.8305170515
- --B305170530 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30
 Nancompliance noted failure to perform surveys, inform workers & properly monitor liquid radioactive affluent release
 YUHAS.O.P. HENSLAWSKI, F.A. BOOK. H.E. Region 5, Office of Director B3/04/14 10pp 18467 264 24X Fiche 50-361, B3/04/18, B305170515

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305170359 Forwards IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08.No noncompliance noted 830404-08.No noncompliance noted BIBHOP.7 W Region 5, Office of Director 83/04/26 PAPAY.L T Sauthern California Edison Co 2pp 18466 078 24X Fiche 50-361,83/04/26,8305170359
- --8305170361 IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08 No noncompliance noted Major areas inspected corrective & preventative maint programs. ECKHARDI, J H . KIRSCH, D F . Region 5, Office of Director 83/04/22 4pp. 18466:100 24X Fiche 50-361,83/04/26,8305170359
- 8303040025 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E, L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- B303040027 IE Info Notice 83~25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50~000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co 18441 170 24X Fiche 50-000,83/05/03,8303040028 York, Inc. 122pp
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24% Fiche, 50-000, 83/05/04, 8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp. 18523 248 24X Fiche 50-000,83/05/04,8303040033
- B303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034
- 8305260242 Forwards IE Bafaguards Insp Repts 50-204/83-11.50-341/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref lOCFR73 21).
 NORDERHAUGLER. Region 5. Office of Director 83/05/12 PAPAY.L T Bouthern California Edison Co 2pp 18599.322. 24X
 Fiche 50-206.83/05/12.8309260242.
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " 8vc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697-007. 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl. JCROAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647-007 24X Fiche. 50-000, 83/05/26, 8303040046.
- R Periodic operating reports & related correspondence
- 8304150372 Monthly operating rapts for Feb 1983, MAYMEATHER, L Southern California Edison Co 83/03/15, 11pp 17981 359 24X Fiche, 50-361, 83/03/15, 8304150368

- 8 Reportable occurrences, LERs & related correspondence
- G30506044B Forwards revised LER B3-005/01X-1 RAY, H B Southern California Edison Co G3/03/31 ENGELKEN, R H Region 5, Office of Director 2pp 18343 135 24X Fiche 50-362,83/03/31,8305060448
- --8305060450 Revised LER 83-005/01X-1 on B30222, observed loose snubbers & hangers associated w/two sampling valves (3HV508 & 3HV517) of RCS Caused by removal for maint performed on associated components Snubbers reconnected RAY:H B Southern Callfornia Edison Co 83/03/31 Region 5. Office of Director 3pp 18343 137 24X Fiche 50~362.83/03/31. 8305060448
- 8305030360 RU high steam generator differential pressure trip function operability requirements exceeded for Modes 1,2 & 3
 Satpoints will be corrected before reentry into Mode 3 & will be reported in LER by 830505
 RAY.H B Southern California Edison Co 83/04/22 MARTIN.J B Region 5. Diffice of Director 2pp 18271 361 24X
 Fishs 30-361.R9/04/29.R905030360 Fiche 50-361, 83/04/22, 8305030360.
- 8305020183 PNO-V-83-018 on 830421, util received ltr from C-E informing of error in equivalent voltages corresponding to setpoints associated w/steam generator high delta pressure trip function Corrective action being developed BISHOP.T W Region 5, Diffice of Director 83/04/25 ip 18277 275 24X Fiche 50-361,83/04/25,8305020183
- 8305180790 Forwards SER on reactor trip breakers Licensee proposed actions provide acceptable basis for restart & operation EISENHUT.D 0 Division of Licensing 83/05/02 DIETCH.R Souther California Edison Co COTTON.O D. BERNATH.L San Diego Cas & Electric Co 3pp 18505 001 24X Fich# 50-361.83/05/02.8305180790 DIETCH,R Southern
- ---B305180B04 SER lifting restrictions on exceeding power documented in confirmation of action itre dtd B30311 & 0427 based on corrective actions re reactor trip breaker failure # Office of Nuclear Reactor Regulation, Director B3/04/30 18505 004 24X Fiche 50-361,83/05/02,8305180770
- 8305160047 Forwards LER 83-035/03L-0 RAY, H B Southern California Edison Co 83/05/03 MARTIN, J B Region 5. Office of Director 2pp 18453 020 24X Fiche 30-362,83/05/03,8305160047
- ---8305160051 LER 83-035/03L-0 on 830404, fire spray sys spuriously actuated Fire detectors inoperable Causo unknown Compensatory measures remained in place until fire spray sys returned to syc on 830416. RAY, H B Bouthern California Edison Co 83/05/03 Region 5, Office of Director ip 18453 022 24X Fiche 50-362,83/05/03,8305160047
- 8305160110 Forwards LER 83-033/03L-0 RAY, H B. Bouthern California Edison Co 83/05/ Ragion 5, Office of Director 2pp 18450 093 Fiche 30-362,83/05/03,8305160110 O3 MARTIN, J B 83/05/03
- --8305160115 LER 83-033/03L-0 on 830331. Fire spraq sys that protects control bldg cable riser elevator 30 ft spuriously activated Cause unidentified Corrective action re proper resetting technique to be provided to personnel RAY.H B Southern California Edison Co 83/03/03 Region 5, Office of Director 1p 18450 095 24X Fiche 30-362,83/05/03,8305160110
- 8305160120 Forwards LER 83-036/03L-0 RAY, H B Bouthern California Edison Co 83/05/03 MARTIN, J B Region 5, Office of Director 2pp 18448 143 24X Fiche 50-362,83/05/03,8305160120
- --8305160125 LER 83-036/03L-0 on 830308 & O401.early warning fire detectors in zones 41 & 5.respectively, found inopenable Cause unknown. Detector inopenability under evaluation RAY.H B Southern California Edison Co 83/05/03 Region 5. Office of Director ip 18448 145 24X Fiche 50-362,83/05/03. 8305160120
- B305140055 Forwards LERs B3-037/01T-0 for Units 1 % 2 RAY,H B Southern California Edison Co B3/05/05, MARTIN,J B, Region 5, Office of Director 2pp 18451 047 24X Fiche 50-341, B3/05/05, B305160055
- --8305160101 LER 83-037/01T-O on 830421, high steam generator differential pressure setpoint used in PPS emergency feeduator sys logic circuitry resulted in actual trip setpoint 300 psid higher than assumed in FSAR Caused by voltage conversion error RAY, H B Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 051 24X Fiche 50-361, B3/05/05, B305160055

- 8305170278 Confirms no safety-related applications of integral undervoltage trip devices exist other than in reactor trip switchgear in response to NRC request for info re 830415 reactor trip breaker rept

 8ASKIN.K P Southern California Edison Co 83/05/13 KNIGHTON G W Licensing Branch 3 ip 18465 326 24X Fiche 50-361,83/05/13,8305170278
- 8305270157 LER 83-036/03L-0 on 830420, possible problems in source insp.

 mfg & configuration control of reactor trip circuit breaker
 supplier identified in GA audit Caused by inadequate
 supplier OA program for subcontractors W/830320 ltr
 RAY.H B Southern California Edison Co 83/05/20 MARTIN.J B
 Region 5. Office of Director 3pp 18638 067 24X
 Fiche 50-362.83/05/20.8305270157
- DUCKEY 50-364 JUSEPH M FARLEY NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- B305060616 Releases public version of revised svc bldg telephone directory
 FELTON-J M Division of Rules and Records B3/04/26 Document Management Branch 1p 18359 116 24x Fiche 50-34B,83/04/26, B305060616
- --030505052: Forwards public version of revised svc bldg telephone directory to be filed w/Administrative Procedure FNP-0-EIP-8

 HUDGPETH. J B Alabama Power Co 83/04/05 Office of Nuclear Reactor Regulation. Director 2pp 18359 117 24X Fiche 50-348.83/04/26.8303060616
- --8305060426 Public version of revised svc bldg telephone directory * Alabama Power Co 83/03/17 66pp 18359 119 24X Fiche 50-348,83/04/26,8305060616
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EISENNUT.D © Division of Licensing 83/05/II Consolidated Edison Co of New York Inc 16pp 18540 095 24X Fiche 50-000,83/05/II,8305110034
- B305240191 Forwards Rev 6 to security plan Rev establishes upper limit of 120 days on interim clearance, per Varga B30:05 ltr Rev withheld (ref 10CFR2 790)
 CLAYTON F L Alabama Power Co 83/05/12 D'REILLY, J P Region 2, Office of Director 1p (8548 031 24X Fiche 30-348,83/05/12, 8303240191
- 8305290285 Forwards response to 830204 SERs & NRC 830412 itr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included CLAYTON: F L Alabama Power Co 83/05/20 VAROA, S A Office of Nuclear Reactor Regulation, Director 118 p 18696 251 24X Fiche 50-348,83/05/20,8303250285
- B305250391 Responds to NRC request to evaluate adding RCS cold leg temp indication & source range neutron monitor to hot shutdown panels per IOCFR50.App R Addition of RCS appropriate mod Source range neutron monitor too costly CLAYTON.FL Alabama Power Co B3/05/20 VARGA.S A Dffice of Nuclear Reactor Regulation. Director Spp 18585-337 24X Fiche 50-348.83/05/20.8305250391
- I Financial information
- 8305240481 Forwards Annual Financial Rept 1982 & related financial info to satisfy retrospective premium guarantee required under Price-Andersen Act BONJEN.T J Alabama Power Co 83/05/20 SALTZMAN.J Antitrust & Economic analysis Branch (Utility Finance) 16pp 18572 113 24X Fiche 50-348.83/05/20.8305240481
- --8305240484 Annual Financial Rept 1982 FARLEY, J M Alabama Power Co 83/03/04 40pp 10572 129 24x Fiche 50-348,83/05/20,8305240481
- J Insurance & indemnity information
- 8305040180 Forwards Endorsements 52 & 43 to NELIA Policy NF-238 & MAELV Policy MF-93, respectively DUCK.J R Marsh & Malennan Inc 83/04/28 SALTZMAN.J Assistant Director for State & Licensee Relations 3pp 18324 034 24X Fiche 50-348,83/04/28,8305040180.

- P Operating license stage documents & correspondence
- 8305020456 Advises of active negotiation w/DDE on agreement for disposal of spent nuclear fuel 2/or high level radwaste per Generic Ltr 83-07 Comments on draft std disposal contract k proposed disposal rulemaking entl CLAYTON.F L. Alabama Power Co. 83/04/25 VARGA,S A. Office of Nuclear Reactor Regulation, Director 12pp 18282 347 24X Fiche 50-348,83/04/25,8305020454
- 8305170659 Forwards supplemental BER input re turbine valve testing Interval between periodic turbine valve tests can be increased from weekly to monthly on interim basis, pending establishment of new probabilistic turbine missile position VAROA. S A Operating Reactors Branch i 83/04/29 CLAYTON, F L Alabam Power Co 9pp 18481 063 24X Fiche 50-364,83/04/29,8305170659
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of Amends to OLs Svc list encl EISENRUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fichs 50-GOD, 83/05/02, 8305020455
- B30511030B Application for amend to OLs revising Tech Bpecs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions CLAYTON, F. L. Alabama Power Co. B3/05/03 VARGA, 8 A. Office of Nuclear Reactor Regulation, Director. 5pp. 18393 178 24X Fiche 50-348, 83/05/03, 8305110308
- ---8305il03il Proposed changes to Tech Specs 3/4 8 2 3,3/4 8 2 4 & 3/4 8 2 5 increasing confidence of battery operability & providing time to correct certain battery conditions w/o undue plant shutdown # Alabama Pawer Co 83/05/03 19pp 18393 203 24X Fiche 50-348,83/05/03,8305110308
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D O Division of Licensing 83/05/09, Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 30-000,83/05/09,8305090659
- B303240440 Advises that operator training program procedures re natural circulation cooldown (Generic Ltr 81-21), based on Westinghouse Owners Group guidelines, will be incorporated by B30415 Training will be completed by B30519 CLAYTON, F. L. Alabama Power Co. B3/05/18 VAROA, S.A. Office of Nuclear Reactor Regulation, Director 2pp 18573 (31 24X Fiche 50-348, 83/05/18, 8305240440
- G Inspection reports, IE Bulletine & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svt list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consulidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 30-000,83/03/21.8212060385
- 8305270358 Forwards IE Insp Repts 50-348/83-10 & 50-344/83-08 on 830216-0305 No noncompliance noted VERRELLID M Division of Project & Resident Programs 83/03/30 MCDDNALD R P Alabama Power Co 2pp 18642 096 24X Fiche. 50-348, 83/03/30, 8305270358
- --8305270370 lE Insp Rapts 50-348/83-10 & 50-364/83-08 on 830214-0305 No nancompliance noted Major areas inspected monthly maint & surveillance, operational safety, independent insp effort, refueling & IE Bulletin 82-04 followup BRADFORD.W H . RULAND.W H Rayion 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 83/03/29 8pp 18642 098 24X Fiche, 50-348, 83/03/30, 8305270358
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator"

 8vc list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Natice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 83/04/22 Consolidated Edison Co of New
 York: Inc 112pp 18383 087 24X Fiche 50-000,83/04/22.8303040023

- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc. 110pp 16382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp, 18441 170 84X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Daliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp. 18382 282 R4X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " 8vc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp. 18523 248 24X Fiche 30-000,83/05/06,8303040033
- 8303160094 Discusses actions taken to identify & resolve potential DS-416 reactor trip breaker problems per IE Bulletin 83-01 Scheduls. W/finalized implementation dates, to be submitted by 830331 Emergency operating procedures encl CLAYTON.F L Alabama Power Co 83/05/10 VARGA, S A Office of Nuclear Reactor Regulation, Director 7pp 18450 206 24X Fiche 50-348,83/05/10,8305160094
- --8305160100 Rev 6 to Emergency Operating Procedure FNP-1-EDP-5 0. "Reactor Trip." # Alabama Power Co 83/05/09 6pp 18450 213 24x Fiche 50-348,83/05/10,8305160094
- --B305160107 Rev 6 to Emergency Operating Procedure FNP-1-EQP-15 0, "Anticipated Transients W/a Trip (ATWT) " + A186ame Power Co 83/05/10 5pp 18450 217 24X F1che. 30-388, 83/05/10, 8305160094
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program," Byc list encl.
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Conteminated Oil" Svc list encl VGRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Fost B30103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp, 18647 007 24% Fiche 30-000, B3/05/26, B303040046
- R Periodic operating reports & related correspondence
- 8305200357 Forwards monthly operating rept for Apr 1983 CLAYTON-F.L. Alabama Power Co. 83/05/12 Division of Data Automation & Management Information 2pp 18518,096, 24X Fichet 50-364-83/05/12,8305200357
- --8305200362 Monthly operating rept for Apr 1983 HAIRSTON: M Q. Alabama Power Co. 83/05/02 4pp 18518 098 24X F1che 50-364,83/05/12,8305200357

- 8305200579 Forwards monthly status of licensing items, requiring NRC approval, identified in 830113 ltr
 CLAYTON F L Alabama Power Co 83/05/13 VAROA, S A Office of Nuclear Reactor Regulation, Director 6pp 18514 114 24X
 Fiche 50-348,83/05/13,8305200579
- S Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of D6-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME.E.P. Westinghouse Electric Corp. 83/04/21 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 5pp 18405 095 24x Fiche 50-000.83/04/21,8305110427
- 8305030580 Forwards LER 83-018/03L-0 CLAYTON, F L. Alabama Power Co. 83/04/22 Region 2, Office of Director 1p. 18305-358 24% Fiche 50-364,83/04/22,8305030580
- --8305030589 LER B3-018/03L-0 on 830326, pressurizer heater group 2A declared inaperable when heaters failed to energize Caused by discharge breaker closing springs & out of adjustment microswitch Switch adjusted & breaker cycled HAIRSTON.W Q Alabama Power Co 83/04/22 Region 2, Office of Director 1p 18305 359 24X Fiche 50-364, 83/04/22, 8305030580
- 8305100132 Forwards LER 83-019/03L-0 CLAYTON: FL Alabama Power Co 83/05/03 Region 2, Office of Director 1p 18374 358 24% Fiche 50-364,83/05/03.8305100132
- --8305100139 LER 83-019/03L-0 on 830404 & 19, rod control sys declared inoperable upon receipt of failure alerm on power cabinet 2AC Following second occurrence, phase control card \$2 replaced HAIRSTON,W Q Alabama Power Co 83/05/03 Region 2, Office of Director 2pp 18374 359 24% Fiche 50-364,83/05/03,8305100132
- B305110257 Forwards LER B3-021/03L-0 CLAYTON.F L Alabama Power Co B3/05/05 Region 2. Dffice of Director ip 18393 179 24% Fiche 30-364, B3/05/05, B305110257
- ---8305110260 LER 83-021/03L-O on 830411.instrumentation channel associated w/refueling water storage tank water level indicater LI-4075A declared inoperable due to low indication Cause not determined HAIRSTON.W G Alabama Power Co 83/05/05 Region 2. Office of Director ip 8839 180 24X Fiche 50-364.83/05/05,8305110257
- 8305310201 Comments on adequacy of current facility DB-414 reactor trip breakers Breaker configuration modified based on dimensional alignment & extensive testing Safe operation not adversely impacted by breakers
 CLAYTON-F L Alabama Power Co 83/05/24 VAR9A.S A Office of Nuclear Reactor Regulation, Director 2pp 18658 157 24X
 Fiche 50-348,83/05/26,8305310201
- DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8305030685 Releases public version of revised omergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/25 Document Management Branch ip. 18309 141 24X Fiche 50-321,83/04/25,8305030685
- --8308030487 Forwards public version of revised emergency plan implementing procedures, including Procedures HNF-4734 regeneral emergency Sevannah River Operations Ofc & HNF-4527 re alert security force NIX.H C Georgia Power Co 82/04/07 Office of Nuclear Reactor Regulation, Director ip 18309 142 24X Fiche 50-321,83/04/25.
- --8305030490 Public version of revised emergency plan implementing procedures, including Procedures HNP-4734 re general emergency Savennah River Operations & HNP-4527 re alert security force RUGERB.W H , NIX, H Georgia Power Co 83/04/04 50pp 18309 143 24X Fiche 50-521.83/04/25.8303030685
- 8305040648 Releases public version of revised pages to emergency plan FELTON.J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18336 275 24X Fiche 50-321.83/04/25, 8305040648

- --8305040654 Forwards public version of revised Pages C-3 & P-1 to emorgency plan
 OLLINGER,W H Georgia Power Co 83/03/31 NRC No Detailed Affiliation Given 1p 18336 276 24% Fiche 50-321,83/04/25.
- --8305040659 Public version of revised Pages C-3 & P-1 to emergency plan * Georgia Power Co 83/02/28 2pp 18336 277 24% Fiche 30-321,83/04/25,8305040648
- 8305060467 Clarifies requests for exemptions from 10CFR50 48 & App R requirements in response to NRC request at 830330 meeting Rev to 820701 response to be submitted by 830530 GUCWALL T Georgia Four Co 83704728 STOLZ, J F Operating Reactors Branch 4 11pp. 18351 179 24X Fiche 50-321,83704728,8330604469
- 8305;10034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISENHUT.D.O Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc. 16pp 18540 095 24X Fiche 30-000,83/05/11,8305110034.
- 8305250530 Submits info on compliance w/Branch Technical Position 9 5-1 re qualification of fire protection engineers Gualification requirements met through maint of staff at affiliated svc company, Southern Co Svcx. Inc GUCHALL T Georgia Power Co 83/05/19 STOL 2, J F Operating Reactors Branch 4 lp 18388 229 24X Fiche 50-321, 83/05/19.

H General correspondence

- 8305030261 Requests changes in correspondence routines due to recent mgt changes GUCHA-L T Georgia Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 19 18300 046 24X Fiche 50-000.83/04/28,8305030261
- J Insurance & indemnity information
- B305040202 Forwards Endorsement 78 to NELIA Policy NF-215 & Endorsement 63 to MAELU Policy MF-78

 DUCK, J. R. Marsh & Milennan: Inc. B3/04/28 SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 18324-028
- 8305200270 Forwards Endorsement 79 to NELIA Policy NF-215 & Endorsement 64 to MAELU Policy MF-78 DUCK:JR Mersh & McLennan, Inc. 83/03/16 SALTZMAN,J Assistant Director for State & Licensee Relations 3pp 18516 256 24X Fiche, 50-321,83/05/16,8305200270
- 8305230027 Forwards Endorsement 80 to NELIA Policy NF-215 & Endorsement 66 to MAELU Policy MF-78 DUCK, J.R. Marsh & McLennan, Inc. 83/05/16 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp. 18539 180 24X Fiche: 30-321,83/05/16,8305230027

P. Operating license stage documents & correspondence

- 8304120027 Forwards revised order confirming licenses commitments on post-TMI-related issues, correcting into re implementation schedule for Item II B 3. "Post-Accident Sampling " STOLZ.J F Operating Reactors Branch 4. 83/03/30 BECKHAM.J T Cacrois Power Co 4pp. 17957 320 24% Fiche 50-321,83/03/30. 8304120027
- --8304120042 Order revising schedule for submittal of info re Item II. B 3, "Post-Accident Bampling," from 830401 to 830701 PURPLE R A Division of Licensing 83/03/30 Georgia Power Co 10pg 17957, 324 24X Fiche 30-321, 83/03/30, 8304120027.

technical evaluation rept re tar Operator & Sanior vaining for Mitigating '37 requirements. | #3/04/20 BECKHAN, J T | #50-321,83/04/20,

on Programs as

07/01 NRC -

- 8305030634 Application to amend Licenses DPR-57 & NPF-5, revising Tech Bases re TMI Action Flan Items 1 A 1 1 3, I A 1 3, I I E 4, 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4 BECKHAH, J T Georgia Power Co 83/04/22 STOLZ, J F Operating Reactors Branch 4, 8pp 18305 285 24X Fiche 30-321, 83/04/22, 8305030694
- --8305030665 Revised Tech Specs re TMI Action Plan Items I A. 1 i. 3, 1 A i 3, II E 4 i. II E 4 2 5-7, II K 3 3. II K 3 i3, II K 3 22, II K 3 i5, II K 3 i9, II K 3 27, II K 3 45 & II F 1-4 \$ 0eorgia Power Co 83/04/22 3ipp 18305 293 24X Fichs 50-321, 83/04/22, 8305030634
- 8303040748 Summary of 830223-24 meetings w/util & E080 in Atlants, 0A reproposed radiological effluent Tech Specs RIVENBARK, 0 W Operating Reactors Branch 4 83/04/22. STOLT, J.F. Operating Reactors Branch 4 15pp 18327 179 24X Fiche, 30-321, 83/04/22, 8305040748
- 8305040671 Forwards EQ&C 830404 ltr transmitting list of NRC comments on unresolved items from proposed radiological effluent Tech Specs Earlier scheduled date for final submittal requested BTOLZ.J.F Operating Reactors Branch 4 83/04/22 BECKHAM.J T. Georgia Power Co 2pp 18358 001 24X Fiche 50-321.83/04/22, 8305060671
- --8304220257 Forwards list of major radiological effluent Tech Spec less from licensee proposal that were not resolved at Atlanta mesting Differences between Unit 1 & Unit 2 proposals are minor Commitment date for next submittal not identified.

 BERRAND, W EG&G, Inc. 83/04/04 WILLIS, C.A. NRC No Detailed Affiliation Given 3pp 18358,003 24X Fiche 50-321.83/04/22.
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensess re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT, D & Division of Licensing 83/05/02. Consolidated Edison Co of New York, Inc. 30pp 1844: 120 24% Fichs. 50-000.83/05/02.8305020455
- 8305060306 Requests that portion of 830422 response to Ceneric Ltr 83-02 be withdrawn Portion re Item II F 1. "Add1 Accident Monitoring Instrumentation." will be reevaluated upon receipt of NRC guidence, OUCMALL T Georgie Power Co 83/05/02 STDLZ.J F Operating Reactors Branch 4 1p 18344 323 24X Fiche 50-321.83/05/02, 8305060306
- B305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods 8yc list encl.
 EIGENHUT,D Q Division of Licensing, 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X
 Fiche 30-000,83/05/09,8305090659
- B305160157 Amends B30330 submittal re extension of MALPHQR limits. ECCS analysis results justify operation of all facility fuel types at exposures greater than 30,000 MHd/st types at exposures greater than 30,000 MHd/st Georgia Power Co. B3/05/10 ST0LZ, J.F. Operating Reactors Branch 4 2pp. 18446;083 24X Fiche. 50-366, E3/05/10. 8303160159
- 8305200453 Commits to submit results of plant-unique calculations re acceptability of mod to torus vacuum breakers by 830615, in response to Generic Ltr 83-08 OUCHA, L T Georgia Power Co 83/05/16 STOLX, J F Operating Reactors Breach 4, 1p 18519 085 24X Fiche 50-321,83/05/16,0000082
- 8305240250 Advises that startup expected to occur between 830607-14 assuming resolution of outstanding licensing issues, Unknowns still exist in schedule due to existence of pipe flaw indications Draft rept on weld repairs expected by 830530, OUCHALLT Georgia Power Co. 83/05/19, 870LI, J.F. Operating Reactors Branch 4 ip 18548-307 24X Fiche-50-366,83/05/19, 8305240250.
- 8305260298 Submits QE info assuring that crud-induced local corrosion failures will not occur during Cycle 4. In response to NRC 830519 request OUCHA, L.T. Qeorgia Power Co. 83/05/20, STDLZ; J.F. Operating Reactors Branch 4. 1p. 18626-264. 24X Fiche 50-366, 83/05/20, 8305260298

- @ Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000.83/03/21.8812060385
- 8305270491 Ack receipt of 830328 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-02 DANCE, H C Division of Project & Resident Programs 83/04/07 KELLY, R J Georgia Power Co ip 18646 072 24X Fichs 50-366,83/04/07,8305270491
- --8305270508 Responds to NRC 830225 ltr re violations noted in IE Insp Rept 50-364/83-02 Corrective actions personnel to evaluate actions taken for both units if event affects shared equipment & shift HEAD, 0 F Georgia Power Co 83/03/28 O'REILLY, J P Region 2, Office of Director, 2pp 18646 073 24X Fiche 50-366,83/04/07, 8305270491
- --B305270523 Forwards IE Insp Repts 50-321/83-02 & 50-346/83-02 on B21220-B30121 & notice of violation DANCE.H C Division of Project & Resident Programs B3/02/25 KELLY,R J Georgia Power Co 2pp 18646 075 24X Fiche 50-366,
- --B305270550 IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 Noncompliance noted failure to make 24-h telephone rept within required time limit CRLENJAK.R V , HOLMES-RAY.P Region 2, Office of Director BROWNLEE.V L Division of Project & Resident Programs 63/02/23 4pp 18848 078 24X Fiche 50-366/83/04/07/8303270491
- 8305270570 Requests that docket number in 830322 IE Insp Rept 50-336/83-05 be changed to 50-366/83-05 due to administrative error DANCE.H C Division of Project & Resident Programs 83/04/08 KELLY.R J Georgia Power Co ip 18646 ii3 24X Fichs. 50-321,83/04/08,8305270570
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Velve Failures" 8vc list entl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383-089, 24X Fiche 50-000,83/04/22,8303040023
- 8303040023 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys " Eve list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 271 24X Fiche 50-000.83/04/25,8303040025
- B305270332 Ack receipt of B30418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-04 & 50-364/83-04. DANCE.H C. Division of Project & Resident Programs B3/04/27 KELLY.R.J Georgie Power Co ip 18642.066 24X Piche: 50-321, B3/04/27, 8305270332
- --8305270336 Responds to NRC 830318 ltr re viglations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04 Corrective actions training directive issued to appropriate personnel stressing prompt notification of unusual event BECKHAMAJ.T. Georgie Power Co 83/04/18 O'REILLY, J.P. Region 2. Diffice of Director. 2pp 18642 067 24X Fiche 50-321. 83/04/27,8305270332.
- --8305270343 Forwards IE Insp Repts 50-321/83-04 & 50-366/83-04 on B30207-11 & notice of violation.

 DANCE,H.C. Division of Project & Resident Programs 83/03/18 KELLY,R.J. Georgia Power Co. 2pp 18642:069 24X Fichs:50-321,83/04/27.8305270332.
- --8305270351 Notice of violation from insp on 830207-11 * Region 2, Office of Director. 83/03/18, ip 18642 071. 24X Fiche: 50-321,83/04/27,8305270332

- --8305270357 IE Insp Repts 50-321/83-04 & 50-366/83-04 on 830207-il Noncompliance noted failure to make proper notification to NRC following liquid radwaste release on 821207 MRAY. J R Region 2. Office of Director BARR.K P Division of Emergency Preparedness & Materials Safety 83/03/10 7pp 18642 072 24X Fiche 50-321.83/04/27,8305270332
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B305040711 Notification of B30429 meeting w/util in Atlanta, GA to discuss results of ongoing ultrasonic insp of pipes, details of crack length & depth determinations, proposed repairs & bases for repairs
 RIVENBARK, GW Operating Reactors Branch 4 B3/04/28. STGLZ, J F Operating Reactors Branch 4 2pp 18328 109 24X
 Fiche 50-366,83/04/28,8305040711
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl UDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 830304003] IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305140144 Submits 30-day response to SER & technical evaluation rept re environ qualification of Class IE equipment (IE Bulletin 79-018) Final plans for resolving qualification of items in Categories I D. II A & II B will be transmitted by 830520 QUCMA.L T Georgia Power Co B3/05/06 BTOLZ, J F Operating Reactors Branch 4 374pp 18444 044 24% Fithe 50-321,83/05/06, B305140144
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, B3/05/11, B303040034
- 8305270350 Forwards IE Insp Repts 50-321/83-11 & 50-366/83-11 on B30411-15 No noncompliance nated DANCE:H C Division of Project & Resident Programs 83/05/11 KELLYR J Georgia Pawer Co 2pp 18644 323 24X Fiche 50-321,83/05/11,8305270350
- --8305270356 IE Insp Repts 50-321/83-11 & 50-366/83-11 on 830411-15 No noncompliance noted Major areas inspected licensee action on pravious enforcement matters, 64 program design mods.test & experiments program & procurement program BELISLE, 6 A , DEBBAGE, A 0 , UPRIGHT, C M Region 2, Office of Director 83/05/11 14pp 18644 325 24X Fichs 50-321,83/05/11,8305270350
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 30-000,83/05/19,8303040040
- 8305270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program GUCHALL T Georgia Power Co 83/05/19 870LZ, J.F. Operating Reactors Branch 4 ip 18638 217 24X Fichs 50-321, 83/05/19, 8305270128

- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- 8305310073 Submits info re analyses & repairs of large-diameter stainless steel piping welds per inservice insp conducted during 1983 maint/refueling outage identifying Unacceptable uttrasonic indications in refireulation & RMR sys BECKMAM, J T Georgia Power Co 83/05/26 STOLZ, J F Deerating Reactors Branch 4 9pp 18655 345 24X Fiche 50-366,83/05/26, 8305310073
- ---B3D5310084 Provides response to IE Builetin 83-02 re stress corrosion cracking in large-diameter stainless steel recirculation syspiping at BWR plants
 BECKHAM, J Georgia Power Co B3/05/26 O'REILLY, J P Region
 2. Dffice of Director 37pp 18655 334 24X
 Fiche 30-366, B3/05/26, B305310073
- --B305310092 Discusses possible imposition of augmented leak detection requirements for RCS due to discovery of unacceptable pipe flaw indications in recirculation & RHR sys Util commitments to incorporate NUREC-0313, Rev 1 Section IV B 1 a 2 BECKHAN, J T Georgia Power Co B3/05/25 STOLZ, J F Operating Reactors Branch 4 2pp 18656 032 24% Fiche 50-366, 83/05/26, 83/05/207.
- --8305310097 Draft Rev A to "Design Rept for Weld Overlay Repairs & Flaw Evaluation in Recirculation & RHR Sys." preliminary rept GUSTIN.H L NUTECH Engineers. Inc. GPC-07-102 RA DRFT 83/05/31 91pp 18556 034 24X Fiche.50-366.83/05/26.8305310073
- R Periodic operating reports & related correspondence
- 8305180279 Forwards monthly operating repts for Apr 1983 NIX.H C Georgia Power Co 83/05/06 Director's Office of Inspection and Enforcement ip 18490 282 24X Fiche 30-321,83/05/06.8305180279
- --8305180284 Monthly operating repts for Apr 1983 REDWANZ,F J Georgia Power Co 83/05/06 129p 18490 295 24X Fiche 30-321,83/05/06,8305180279
- S Reportable occurrences, LERs & related correspondence
- 8305110375 Forwards revised LER 82-100/03X-1 NIX,H C Georgia Power Co 83/04/26 D'REILLY,J P Region 2: Office of Director ip 18406 226 24X Fiche 50-366,83/04/26, 8305110375
- ~-8305110389 Revised LER 82-t00/03X-i on 820828, RCIC sys declared inoperable upon discovery of inoperative switches Caused by failure of switch components due to corrosion & water damage Switches replaced
 TIPPS-S B Georgia Power Co 83/04/26 Region 2, Office of Director 3pp 18406:227 24X Fiche 50-366, 83/04/26, 8305110375
- 8305120392 Interim deficiency rept re misapplication of ITE Gowld circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Inti Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO, 9 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region I. Office of Director 2pp 18493 072 24% Fiche 50-000,83/04/26,8305120392
- --9305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-322 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation

 EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T, Region 4, Office of Director 5pp 18433:074 24X

 Fiche 50-000,83/04/26,8305120392
- 8305110410 Forwards LER 83-023/01T-0 NIX.H.C Georgia Power Co 83/04/28 O'REILLY, J.P. Region 2, Office of Director 1p 18392 004 24X Fiche 50-366,83/04/28, 8305110410
- --8305110417 LER 83-023/017-0 on 830418, cracklike indications noted on recirculation sys 2831 endcap-to-manifold wald heat affected rone of weld 2831-228M-4 Caused undetermined Followup rept to be submitted upon completion of repair TIPPS:S 8 Georgia Power Co 83/04/28 Region 2, Office of Director 3pp 18392 005 24X Fiche 50-346,83/04/28,8305110410
- 8305110429 Forwards LER 83-007/03L-0 NIX.H.C Georgia Power Co 83/04/28 O'REILLY.J.P Region 2: Office of Director ip 18404 352 24% Fiche 50-366,83/04/28, 8305110429

- --8305110436 LER 83-007/03L-0 on 830401.RHR flow indicator 2082-8004 in remote shotdown panel found to be reading inaccurately, rendering instrument loop inoperable Caused by component failure Defective amplifier card replaced TIPPS: 8 B Georgia Power Co 83/04/28 Region 2: Office of Director 3pp 18404 353 24X Fiche 50-366.83/04/28.8305110429
- 8305130235 Forwards LER 83-019/03L-0 NIX.H C Georgia Power Co 83/04/28 O'REILLY, J P Region 2, Office of Director ip 18440 094 24X Fiche 50-366 83/04/28, 8308190335
- --8305130242 LER 83-019/03L-0 on B30127, during fire protection isolation valve position & lube check Procedure HNP-2-3358, lube oil room deluge sys isolation valve 2043-F101 found locked closed Cause unknown Valve locked open TIPPS S II Georgia Power Co B3/04/28 Region 2, Office of Director 3pp 18440 095 24X Fiche 50-346, 83/04/28, 830513023\$
- 8305170276 Forwards LER 83-027/03L-0 NIX.H C Georgia Power Co 83/05/05 O'REILLY.J P Region 2. Office of Director 1p 18465 270 24X Fiche 50-366.83/05/03,
- --B305170284 LER B3-027/03L-O on B30420, during performance of Protesure hNP-2-3752; primary containment RHR valves found leaking in excess of Tech Spec limit Cause under investigation Corrective maint to be performed TIPPS S B Georgia Power Co B3/05/05 Region 2, Office of Director 3pp 18465 291 24X Fichs, 50-366, 83/05/05, 8305170276
- --B305170394 LER 83-017/03L-0 on 830406, during HNP-2-3322, w/unit in cell shutdown. HPC1 pump discharge valve 2E41-F006 failed to open Caused by loose wire on terminal block inside valve operator Wire tightened Valva cycled TIPPS. 8 B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp. 18469, 228 24X Fiche 50-366, 83/05/05, 8305170389
- 8305170491 Forwards LER 83-016/03L-0 NIX.H C Georgia Power Co. 83/05/05 O'REILLY, J P Region 2. Office of Director 1p 18470.001 24X Fiche 50-366.83/05/05. 8305170491
- --B305170499 LER 83-016/03L-0 on 830405, MBIV drain valve 2821-F016 would not close. Caused by dirty torque switch contacts Contacts disconnected. cleaned & retightened Valve cycled properly SUNNER. H L. Georgia Power Co. 83/05/05 Region 2. Office of Director 3pp 18470 002 24X Fiche 50-366.83/05/05.8305170481.
- 8305170502 Forwards LER 83-018/03L-0 NIX.H C Georgia Power Co 83/05/05 O'REILLY, J P Region 2. Office of Director 1p 18470 018 24X Fiche 50-366,83/05/05. 8305170502
- --8305170506 LER 83-018/03L-0 on 830406. while performing quarterly (see spray pump operability Procedure HNP-2-3201, core spray pump min flow bypass valve 2621-F0138 would not close automatically Caused by bent fingers on torque switch.

 TIPPS, S B Georgia Power Co 83/05/05 Region 2, Office of Director. 3pp 18470 019 24X Fiche. 50-366. 83/05/05. 8305170502
- B305110364 RD 50-366/B3-01 on B30125 & 0314, Units 2 & 1, respectively, had spray/sprinkler sys taken out of svc for mods & could not be restored to operable status within 14 days per Tech Specs. Continuous fire watches maintained NIX.H C Beorgia Power Co B3/05/06 UREILLY.J P. Region 2, Office of Director 3pp 18406.262 24X Fiche 50-321, 63/05/06, 8305110364
- 8305230463 Forwards LER 83-015/01T-0 NIX.H C Georgia Power Co 83/05/09 O'REILLY.J P Region 2, Office of Director 1p 18537 345 24X Ficha.50-366.83/05/09, 8305230463
- --830523046B LER 83-015/01T-0 on 830427, during visual exam, damaged pijs supports found on HPCI pump discharge line Cause not determined Discharge pipe & pipe supports being analyzed Pipe supports will be repaired TIPPS 8 B Georgia Power Co 83/05/09 Region 2: Diffice of Director 3pp 18537:346 24X Fiche 50-366,83/05/09,8305230463
- 8305230486 Forwards LER 83-022/03L-0 NIX,H.C Georgia Power Co 83/05/09 0'REILLY,J P Region 2 Office of Director 1p 18537:145 24X Fiche 50-366.83/05/09, 8308230486

- --8303230490 LER 83-022/03L-0 on 830413.MSIV leakage bleed valve 2532-F007 failed to close as required Caused by dirty torque switch inside valve operator 2532-F007 Torque switch cleaned & valve stroked during maint TIPPS.8.B Georgia Power Co 83/05/09 Region 2. Office of Director 3pp 18537 146 24X Fiche 50-366.83/05/09.8305230486
- 8305230495 Forwards LER 83-025/03L-0 NIX,H C. Georgia Power Co 83/05/09 D'REILLY, J P Region 2, Gffice of Director ip 18537 179 24X Fiche 50-366,83/05/09, 8305230495
- --8303230498 LER 93-025/03L-0 on 830414 during turbine bldg area temp functional test & calibr monitor 2U61-R002 found out of calibr Caused by estpoint drift of five temp switches & inoperability of one switch Monitor replaced TIPPS.S.B Georgia Power Co 83/05/07 Region 2, Office of Director, 3pp 18527 180 24X Fiche 50-366,83/05/09,8305230495
- 8305310124 LER 83-020/03L-0 on 830423. discovered main bearing 11 on upper crank shaft wiped, Caused by lack of lubricating oil at upper crankshaft main bearing 11 Design change (DCR-82-239) completed to improve oil supply W/830517 ltr TIPPS, 8 B, NIX.H C Georgie Power Co 83/05/17 D'REILLY, J P Region 2, Office of Director 4pp 18658 078 24X Fiche 50-366,63/05/17,8305310124
- 8305310206 LER 83-030/017-0 on 830503, during performance of main steam relief valve maint by Myle Lab, 10 steam relief valves found unacceptable Caused by setpoint drift, pilot tube leakage & long delay time W/830517 ltr
 TIPPB, B. B., NIX, H. C. Deorgia Power Co. 83/05/17 D'REILLY, J. P. Ragion 2. OPfice of Director 4pp 18651 010 24X
 Fiche 50-366,83/05/17,8305310206
- 8305270123 LER 83-029/03L-0 on 830428, safety/relief valve position primary indicators 2821-N301A & C found to actuate at 91 & 90 5 psig, respectively, contrary to Tech Specs Caused by setpeint drieft. Indicators will be replaced W/830519 ltr TIPPS, 8 B . NIX.H C Georgia Power Co 83/05/19 O'REILLY, J P Regian 2, GPfice of Director 4pp 18638 221 24X Fiche 50-366,83/05/19,8305270123
- 8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utile will measure vibration HAIBLERIR K. Litton Industries, Inc. 83/05/20 KEPPLER, J. Q. Region 3. Defice of Director 3pp. 18646-212 24X Fiche 50-000,83/05/20,8305270625

DOCKET 50-367 BAILLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 830516031B Notification of contract execution, Mod 1 to "Div of Engineering Review Support on Bailly Nuclear Plant I "
 Contractor MT Davisson FIELDB. J A Tachnical Assistance Contracts Branch FIN B-7505 83/05/06 VOLLMER, R, H Division of Engineering LEAR, 9 NRC No Detailed Affiliation Olven. 1p 18472-051 24X Fiche: 50-367, 83/05/06, 830516031B
- --8305160332 Mod 1, terminating contract & deepligating funds, to "Div of Engineering Review Support on Bailly Nuclear Plant I " DAVISEON.M T. Darisson. M.Y GUSTAVE.R P Division of Contracts FIN B-7505 83/05/06 2pp 18472 052 24X Fiche 50-367,83/05/06,8305160318
- DOCKET 50-268 ARKANSAS NUCLEAR ONE, UNIT 2
- F Security, medical, emergency & fire protection plans
- B305200326 Forwards list of emergency response open items for which no written response required Dpan items resulting from recent emergency exercise will be reflected in future rept MARSHMLLJR Arkaness Power & Light Co B3/04/08 COLLINS, J T Region 4, Office of Director 2pp. 18516 308 24X Fiche: 50-313, 83/04/08,8305200326
- 8304270424 Releases public version of revised emergency plan implementing procedures.
 FELTON, J. N. Division of Rules and Records. 83/04/22 Document Management Branch 1p. 18244 027 24X Fichs 50-313,83/04/22,8304270424

- --8304270426 Forwards public version of revised emergency plan implementing procedures, including Procedures 1,2 & 6 re assignment of personnel to emergency response organization, notifications & emergency response ctrs, respectively MARSHALL, JR Arkansas Power & Light Co 83/04/05 COLLINS, J T Region 4, Office of Director 1p 18244 028 24X Fiche 50-313,83/04/22,8304270424
- --8304270427 Public version of revised emergency plan implementing procedures including Procedures 1,2 & & re assignment of personnel to emergency response organization notifications & emergency response ctrs.respectively * Arkanses Power & Light Co 83/03/07 86pp 18244 029 24X Fiche 50-313,83/04/22.8304270424
- 8305060575 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18357 170 24X Fiche 50-313,83/04/25. 8305060575
- ---8305060583 Forwards public version of revised Emergency Plan Implementing Procedures 1904 O6 re radiological plume tracking & dose integration & 1904 O6 re protective action recommendations

 * Ankansas Power & Light Co 83/04/14 NRC No Detailed Affiliation Given ip 18359 191 24X Fiche 50-313.83/04/25.
- --8305060591 Public version of revised Emergency Plan Implementing Procedures 1904 06 re radiological plume tracking & dose integration & 1904 07 re protective action recommendations LEVINE, J M Arkansas Power & Light Co
- 8303110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months CLARK, R A Operating Reactors Branch 3 83/04/27 GRIFFIN. J Arkansas Power & Light Co 4pp 18434 262 24X Fiche 30-313,83/04/27,8305110193
- --8305110199 Amenda 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan CLARK, R A Operating Reactors Branch 3 83/04/29 9pp 18434 266 24X Fichs 50-313.83/04/29.8305110193
- --8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-4 respectively CLARK, R A Operating Reactors Branch 3 83/04/29 2pp 18434 275 24X Fiche 50-313,83/04/29,8305110193
- 8305160288 Releases public version of revised nuclear contingency plan procedures FELTON.J M Division of Rules and Records 83/05/02 Document Management Branch lp 18462 334 24% Fiche 50-313,83/05/02, 8305160289
- --8305160290 Forwards public version of revised Nuclear Contingency Plan Procedures 1:2,3,5,6,7,8,9,12,13,14 & 15 W/o encl MARSHALLJ R. Arkansas Power & Light Co 83/04/05 COLLINS.J T Region 4: Office of Director. 1p 18462 335 24X Fiche 50-313,83/03/02,8305160288
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EISENHUT, D G Division of Licensing 83/05/11 Consolidated Eisen Co of New York, Inc 16pp 18540 075 24X Fiche 30-000,83/05/11,8305110034
- 8305180161 Informs that NUREO-0737. Item III A 2 1, "Emergency Praparadness. Upgrade Emergency Plans to App E. 10GFR50." complete STOLZ.J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/05/11 GRIFFIN.J M Arkansas Power & Light Co 3pp 18502 348 24% Fiche 50-313.83/05/11.830318016
- H General correspondence
- B305240139 Advises that correspondence distribution to Region IV will be modified to original plus three copies, per B Johnson request MARSHALL, J R Arkansas Power & Light Co B3/04/22 SEIDLE, W C Region 4, Office of Director ip 1854B 334 24X Fiche 50-313, B3/04/22, B305240139

J Insurance & indemnity information

- 8305090421 Forwards NELIA & MAELU Certificates of Insurance to comply w/10CFR50 34w Submittals from 830331 & 0422 misinterpreted to comply w/10CFR140 & 140 15a MARSHALL.JR Arkansas Power & Light Co 83/05/03 STQLZ.JF Operating Reactors Branch 4 COLLINB.JT Region 4, Office of Director DINITZ.I NRC No Detailed Affiliation Given App 18363 Q65 24X Fichr 50-313,83/05/03,8305090421
- 8305190363 Forwards NELIA & MAELU secondary financial protection Cartificates of Insurance 48 & 48, respectively, for CY83, per 10CFR140 15(a) MARSHALL, J.R. Arkansas Power & Light Co. 83/05/11 DINITZ. I Antitrust & Economic analysis Dranch (Utility Finance) 41pp 18500 032 24X Fiche 50-313,83/05/11,8305190363
- P Operating license stage documents & correspondence
- 8305230364 Forwards cost info associated w/backfitting nuclear units, per JL Maulden 830224 commitment MARSHALL, J R Arkansas Power & Light Co 83/03/11, TOURTELLOTTE, J Regulatory Reform Task Force 11pp 18546 234 24X Fiche 50-313,83/03/11,8305230364
- 8303240480 Forwards "Structural Evaluation of AR Nuclear One-Unit 1 & Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
 MARSHALL, J.R. Arkensas Power & Light Co. 83/03/22 870LZ, J.F.
 Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 1p 17678 109, 24X Fiche 50-313,83/03/22,8303240480
- --8303240495 "Structural Evaluation of Arkansas Nuclear One-Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage " STURKEY.J J. BALLARD.T. A Structural Dynamics Research Corp AFL-02-013 82/11/24 75pp 17678 191 24X Ficha 50-313,83/03/22,8303240480
- 8303230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO, N J., GILINSKY,V. AMEARNE.J F. Commissioners 2pp 18342 272 24x Fichs 50-000.83/04/11.8305230720
- B305200580 Forwards list of add1 procedures controlling QA measures for threaded fastener lubricants to minimize fastener susceptibility to stress corrosion cracking MARSHALL. J R Arkansas Power & Light Co B3/04/21 BEIDLE, W. C Region 4, Opfice of Director 3pp 18514 250 24X Fiche 50-388, B3/04/21, B305200580
- B305200541 Forwards revised schedule for completion of licensing procedures upgrade, per regulatory response & commitment control program Delay due to continuing support requirements for Unit i butage Upgrade to be completed by 830527 MARSHALL, J.R. Arkansas Power & Light Co. B3/04/25 COLLINS, J.T. Region 4. Defice of Director 2pp 18514.264 24X Fiche 50-313,83/04/25,8305200541
- 8305110625 Forwards corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively STOLZ, JF Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/04/27 ORIFFIN, J H Arkansas Power & Light Co 2pp 18417 357. 24X Fichs 50-313,83/04/27,8305110625
- --8305110626 Corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively * Office of Nuclear Reactor Regulation, Director 83/04/27 2pp 18417 359 24X Fichs 50-313,83/04/27,8303110625
- 8303050125 Ack receipt of 830427 ltr w/corrections to safety evaluation for proposed spent fuel gool storage expansion Statement 15 corrected to indicate divers will not be permitted to exceed I rem whole body, per 830428 discussion w/0 Vissing MARSHALLJR Arkansas Power & Light Co 83/04/28 STOLZ, J.F. Operating Reactors Branch 4 CLARK, RA Operating Reactors Branch 3 1p 18341 347 24X Fiche: 50-313.83/04/28,8305050125
- 8305020416 Acks receipt of 630415 SER & technical evaluation rept re environ qualification of safety-related electrical equipment Category II B items acceptable MARSHALLJR. Arkenses Power & Light Co 83/04/29 CLARK.R A Operating Reactors Branch 3 2pp 18279 190 24X Fichs. 50-368.83/04/29, 8305020416

- 8303110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Fach Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months CLARK, R A Decrating Reactors Branch 3 83/04/29 ORIFFIN, J Arkansas Power & Light Co 4pp 18434 262 24X Fiche 50-313,83/04/29,8305110193
- --8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan
 CLARK,R A Operating Reactors Branch 3 83/04/29 9pp
 18434 266 24X Fiche 30-313,83/04/29,8305110193
- --8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6: respectively CLARK, R A Deerating Reactors Branch 3 83/04/29 2pp 18434 275 24% Fiche 50-313,83/04/29,8305110193
- 8305020455 Generic Ltr 83-i9 to all power reactor & testing licenses re new procedures for providing public notice concerning issuance of amends to DLs 8vc list encl EISENHUT, D & Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441,120 24X Fiche 50-000,83/05/02,8305020455
- 8305110165 Forwards Amend 45 to License NPF-6, safety evaluation & notice of issuance & availability Amend clarifies & modifies emergency diesel generator load block application timing criteria TOURIGNY.E O Operating Reactors Branch 3 83/05/03 QRIFFIN.J Ariansas Power & Light Co 3pp 18494 244 24X Fiche 30-368.83/05/03.8305110165
- --B305110169 Amend 45 to License NPF-6, revising Tech Specs for sergency diesel generator load block application tinding criteria-CLARK, R A Operating Reactors Branch 3 83/05/03 5pp 18434 247 24% Fiche 50-368,83/05/03,8305110165
- --8305110173 Bafety evaluation supporting Amend 45 to License NPF-b * Office of Nuclear Reactor Regulation, Director, 83/05/03 3_{jj} 18434 252 24X Fiche 50-368,83/05/03,8305110165
- --B305110176 Notice of Issuance & aveilability of Amend 45 to Licenia NPF-6 TRAMMELL, C. M. Operating Reactors Branch 3 83/05/03 2pp 18434 255 24x Fiche 50-348,83/05/03,8305110165
- 8305120504 Forwards Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Bases to require verification of lask testing of purge valves GLARK:R A Operating Reactors Branch 3 STOLZ, J.F. Operating Reactors Branch 3 STOLZ, J.F. Operating Reactors Branch 4 89/05/03 GRIFFIN.J Arkansas Power & Light C: 3pp 18443 141 24X Fiche 50-313.89/05/03.6305120504
- --830512050& Amends 79 & 46 to Licenses DPR-51 & NPF-6.respectively, revising Tech Specs to require varification of leak rate testing of purge valves
 STOLZ.J F Operating Reactors Brench 4 CLARK, R A. Operating Reactors Branch 3 83/05/03 9pp 18443 144 24X
 Fiche 50-343,83/05/03.8305120504
- --8305120508 Safety evaluation supporting Amends 79 & 46 to Licenset DPR-51 & NPF-6: respectively * Office of Nuclear Reactor Regulation, Director 83/05/03 39 18443 153 24X Fiche 50-313.83/05/03.8305120504
- --B303120512 Notice of issuance & availability of Amends 79 & 46 to Licenses DFR-51 & NPF-6, respectively TRAMMELL.C. M Operating Reactors Branch 3 83/05/03 2pp 18443 156. 24X Fiche 50-313,83/05/03.8305120504
- 8305090333 Forwards responses to NRC 830406 request for add1 info reuse of RADCAL gamma thermometer (ROT) for inadequate corecooling instrumentation ROT consists of sheathed thermocouples, heater rod, core tube & Jackst tube MARSHALL, J. R. Arkansas Power & Light Co. 83/05/04 EISENHUT, D. 0. Division of Licensing 8pp 18363;341 24% Fiche 50-313,83/05/04,8303.090373.
- 8305100351 Corrects statement in 830328 response to NRC questions reprecautions taken to minimize personnel exposure to radiation during spent fuel storage expansion Self-reading documeters will be worn outside diving suits not inside MARSHALL. J. R. Arkansas Power & Light Co. 83/05/04 STOLZ. J. F. Operating Reactors Branch 4 CLARK. R. Operating Reactors Branch 3. 1p 18377 038 24X Fiche 50-319.83/05/04.8305100351.

- 8305;80030 Forwards Amend 47 to License NPF-6. EIA & notice of issuance & negative declaration Amend deletes requirements for remote merial surveillance monitoring & bird impaction event studies.

 LYNCH. 0. D. Operating Reactors Branch 3 83/05/05 GRIFFIN, J Arkaneas Power & Light Co 4pp 18497 203 24X Fiche 50-368, 83/05/05, 8305180030
- --B305180036 Amend 47 to License NPF-6, deleting Tech Specs for remote aerial surveillance monitoring & bird impaction event studies

 CLARK,R A Operating Reactors Branch 3 83/05/05 7pp
 18497 207 24X Fiche, 50-368, 83/05/05, 8305180030
- ---8305180049 Notice of issuance & negative declaration re Amend 47 to License NPF-6 TRAMMELL, C. M. Operating Reactors Branch 3 83/05/05 29p 18497 217 24X Fiche 50-368,83/05/05.8305180030
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods. Svc list encl.
 EISENHUT, D. Q. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153 24X
 Fiche 30-000, 83/05/09, 8305090659
- 8305180849 Notifies of unacceptability of delay of proposed Tech Specs re snubber surveillance in order to include ANSI Std. ANSI/ASKC 0M4-1982. "Eram & Performance Testing of Nuclear Power Plant Dynamics Restraints (Snubbers) "Std not adopted STGLZ.JF Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3, 83/05/09 GRIFFIN.JM Arkansas Power & Light Co. 2pp. 18506.024, 24X Fiche 50-313,83/05/09,8305180849
- B305170622 Forwards list of current unresolved issues for radiological affluent Tech Specs remaining as result of 820622-24 asetings Final submittal requested within 30 days CLARK, R. A. Operating Reactors Branch 3 BTGLZ, J.F. Operating Reactors Branch 4 B3/05/10 ORIFFIN. J.M. Arkansas Power & Light Co. 7pp. 18497 001 24X Fichs 50-313,83/05/10.8305170622
- B303230128 Forwards SER supporting licensee compliance w/NUREO-0737, Itsm II B B 2, "Required Flant Mods," & design review of plant shielding requirements for access to vital areas CLARK, R A. Operating Reactors Branch 3 STGLZ, J F Operating Reactors Branch 4, B3/05/11, GRIFFIN, J, M Arkansas Pomba & Light Co. 2pp. 18546, 349, 24X Fichs 50-313, B3/05/11, B305290128
- --8305230145 Bafety evaluation supporting licensee compliance w/kVRE0-0737. Item II.B.2. "Design Review of Plant Shielding Access to Vital Areas"

 Office of Nuclear Reactor Regulation, Director 83/05/11 2pp 18546.351. 24X Fiche: 50-313,83/05/11.8305230128
- 8305180467 Forwards 15 revised oversize drawings Aperture cards are available in PDR. Drawing transmittal list encl
 8HIVELY.C Arkansas Power & Light Co 83/05/12 NRC ~ No
 85tatied Applitation Given. 2pp 18482 129, 24X
 Fiche: 50-368, 83/05/12, 8305180467
- 8305230723 Forwards "Arkanses Nuclear I Steam Electric Station, Unit 2, Gycls Three Startup Rept," summarizing pracritical, low power & power escalation testing for period ending 830104 MARSHALL, J. R. Arkanses Fower & Light Co 83/05/12 GLARK, R A Operating Reactors Branch 3 ip 18541 096 24X Fiche: 50-368, 83/05/12, 8305230723
- --8303230723 "Arkansas Nuclear i Steam Electric Station. Unit 2. Cycle Three Startup Rept." for period ending 830104 * Arkansas Power & Light Co. WP-0576 B3/05/12 34pp 18541: 097 24X Fiche: 50-368, B3/05/12, 8305230723
- B305240360 Informs that response to NUREO-0737. Item IJ E i 2.

 "Emergency Feedwater Bys Automatic Initiation & Flow Indication," per 830411 request will be provided by 830614 Change discussed w/E Tourigny MARSHALL.J R. Arkansas Power & Light Co. 83/05/17 CLARK,R A Operating Reactors Branch 3. ip 18574.002 24X Fiche: 50-268.83/05/17,8305240360
- 8305270065 Forwards list of electrical equipment important to safety & schedule for qualification provisions or replacement of remaining equipment.per 10CFR50 49. Aging-related maint/ survaillance requirements will be addressed by NRC deadline MARSHALL, J R. Arkenses Power & Light Co. 83/05/20 870LZ, J F. Operating Reactors Branch 4 CLARK, R A. Operating Reactors Branch J 27pp. 18638 252, 24X Fiche.50-313,83/05/20,8305270065

- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Gvc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 317 24X Fiche 50-000, B3/03/21, B212040385
- 8304190143 Forwards IE Insp Repts 50-313/83-03 & 50-368/83-03 on 830201-28 & notice of violation 8EIDLE.W C Region 4. Office of Director 83/03/30 GRIFFIN.J M Arkansak Power & Light Co 2pp 17983 226 24X Fiche 50-313,83/03/30,8304150143
- --8304150154 IE Insp Repts 50-313/83-03 & 50-368/83-03 on 830201-28
 Noncompliance noted failure to adhere to requirements of refusiting shuffle procedure, use of unapproved info sources & required verification signatures missing
 CALLAN. L J . CUMMINS, J E . JOHNSON, H D Region 4. Office of Director 83/03/24 10pp 17983 231 24X Fichs 50-313,83/03/30,8304150143
- B30510034B Forwards IE Insp Repts 50-313/B3-04 & 50-368/B3-04 on B30314-18 & motice of violation BEIDLE.N C Region 4: Office of Director B3/04/14 GRIFFIN.J M Arkansas Power & Light Co 2pp 18379 019 24X Fiche 50-313, B3/04/14: 830510034B
- --8305100353 Notice of violation from insp on 830314-18 * Region 4, Office of Director 83/04/14 2pp 18379 021 24X Fiche 50-313,83/04/14.8305100348
- --8305100361 IE insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18
 Noncompliance noted failure to conduct design change reviews
 by offsite engineering group & failure to follow procedure
 re forms used in closeout of design change packages
 JAUDON: J P , MURPHY: M E , JOHNSON: W D Region 4: Dffice of
 Director 83/04/12 10pp 18379 023 24X Fiche 50-313,83/04/14,
 8305100348
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" 8vc list encl JORDAN, EL Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000/83/04/15/8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fithe 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025.
- 8305030325 Ack receipt of 830324 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~313/83-01 & 50~368/83-01 8EIDLE,W C Region 4. Office of Director 83/04/27 QRIFFIN, J M Arkansas Power & Light Co Ip. 18297 044 24X Fiche 50~313.83/04/27.8305030325
- --8305030331 Responds to NRC 830217 ltr re violations noted in IE Insp Repts 50-313/83-01 & 50-368/83-01 Corrective actions revised procedure incorporating three sample requirements into Stap 72 4 & provided proper training for applicable personnel MARGHALL.J R Arkansas Power & Light Co 83/03/24 SEIDLE, H C Region 4. Office of Director 3pp 18297, 045 24X Fiche 50-313,83/04/27.8305030325
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary 8ide of Steam Denerators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Bys Heater High Temp Trip Betpoint Adjustment." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8305020436 Forwards IE Insp Rept 50-313/83-06 on 830301-31 & notice of violation. KELLY, J A Region 4. Office of Director 83/04/28 Region 4. Office of Director 1p 18284 031 24X Fichs 50-313.83/04/28. 8305020436

- --8305020445 Forwards IE Insp Repts 50-313/83-06 & 50-368/83-06 on 830301-31 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 SEIDLE, W C Region 4. Office of Director 83/04/18 QRIFFIN, J M Arkansas Power & Light Co 2pp 18284 032 24%
 Fiche 50-313,83/04/28,8305020436
- 8303040028 IE Info Notice 83-24. "Failure of Safety/Relief Valve Discharge Line Vacuum Broakers " Svt list oncl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Natice 83-27. "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list end!
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/04 Consolidated Edison Co of New
 York: Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- B303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc!

 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83705706 Consolidated Edison Co of New York
- 8305120445 Act receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-36 & 50-368/82-37
 SEIDLE,W C Region 4, Office of Director 83/05/06 GRIFFIN, J M Arkansas Power & Light Co 2pp 18431 072 24X
 Ficke 50-313,83/05/06/8305120445
- --8305120451 Responds to NRC 830309 ltr re violations noted in IE Insp. Repts 50-313/82-36 & 50-368/82-37 Corrective actions Form 1609 010A re calculation of max permissible concentration revised to require health physics supervisor signature MARSHALLJR Arkansas Power & Light Co 83/04/06 SEIDLE, W C Region 4, Office of Director 4pp 18431 074 24% Fiche 50-313,83/05/06,8305120445
- 830523037 Forwards IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No noncompliance noted SEIDLE.W C Region 4. Diffice of Director 83/05/06 @RIFFIN.J M Arkansas Power & Light Co 2pp 18538 256 24% Fiche 50-310,80705/06,9305230337
- --8305230348 IE Insp Repts 50-913/83-07 & 50-268/83-07 on 830418-22 No moncompliance nated Major areas inspected test & experiment & programs & receipt storage & handling of equipment & matts program

 JAUDON, J P., JOHNSON, W D. Region 4, Office of Director 83/D5/03 &pp 18538 258 24X Fiche 50-313.83/05/06.8305230337
- 0303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Outdelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 9305200313 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-313/83-02 & 50-346/83-02 SEIDLE,W C Region 4. Office of Director 83/05/13 QRIFFIN, J M Artansas Power & Light Co 2pp, 18517 056 24X Fiche 50-313,83/05/13.8305200313
- --8305200319 Responds to NRC 830325 ltr re violations noted in 1E Insp Repts 50-313/83-02 & 50-369/83-02 Corrective actions administrative controls implemented to provide adequate procedural controls re safety-related equipment MARSHALL, JR Arkansas Power & Light Co 83,04/27 SEIDLE, W C Region 4, Office of Director 4pp 18517 058 24x Fiche 50-313,83/05/13,8305200313
- 8303040040 lE Info Notice 83-31: "Error in ADLPIPE Computer Program " &vc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/17 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 30-000.83/05/19.8303040040

- 8305240049 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-313/83-03 & 50-368/83-03 Add inforce order/sequence & temporary placement of fuel assemblies requested SEIDLE. W.C. Region 4. Office of Director 83/05/19 GRIFFIN, J. H. Arkansas Power & Light Co. 2pp 18549 125 24X Fiche 50-313,83/05/19,8305240049
- --B305240054 Responds to NRC B30330 ltr re violations noted in IE lnsp Repts 30-313/83-03 & 50-368/83-03 Corrective actions: Pracedure 1000 36, "Control of Miscellaneous Info Bources," reviewed w/personnel by dept heads to establish compliance MARSHALL.J R Arkansas Power & Light Co B3/05/02 SEIDLE, W C Region 4. Office of Director App 18549 127 24X Fiche 50-313,83/05/19,8303240047
- 8309310194 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-04 & 50-369/83-04 SEIDLE,W C Region 4, Office of Director 83/05/25 QRIFFIN,J N Arkanses Power & Light Co ip 18658 152 24X Fiche 30-313.83/05/25.8305310194
- --8305310199 Responds to NRC 830414 ltr re violations noted in IE Insp. Repts 50-313/83-04 & 50-368/83-04 Corrective actions Rev 5 to GA topical rept. replecting design activity changes, will be submitted for approval by 830610 MARSHALLJ R Arransas Power & Light Co. 83/05/12 SEIDLE.K C Region 4, Office of Director 3pp 18658 153 24X Fiche 50-313,83/05/25,8305310194
- 8303040046 IE lnfo Notice 83-33, "Nonrepresentative Sampling of Contaminated Gil" Bvc list encl
 JDRDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- R. Periodic operating reports & related correspondence
- B303200573 Submits third monthly status rept re regulatory response & commitment control program Info consists of programs made in areas of verification of implementation of commitments since 750101 & procedure rev tracking MARSHALL, J R Arkansas Power & Light Co B3/04/14 COLLING, J T Region 4. Defice of Director 3pp 18514.274 24X Fiche 50-368, 83/04/14, 8305200573
- S Reportable occurrences, LERs & related correspondence
- 8305200445 Forwards NPDES noncompliance rept per Permit AR0001392 MARSHALL.JR Arkansas Power & Light Co 83/04/04. COLLING.J T Region 4. Office of Director 1p 18516 109 24X Fiche 50-313, 83/04/04.8305200450
- ---830520045i NPDES noncompliance rept on 830323.discovered oil & greate concentrations from Outrall 003 exceeded Permit AR0001392 limits Caused by startup activities on Unit 1 Rev of operating procedures being considered to prevent recurrence CAVANAUGH.W Arkansas Power & Light Co 83/03/30 WHITTINGTON.D Region 4. Defice of Director 2pp 18516 IIO 24% Fichs 50-313.83/04/04.8305200445
- B305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping" BROWN,E J Reactor Operations Analysis Branch, 83/04/19, SEYFRIT-K V Reactor Operations Analysis Branch ip 18541:342 24X Fiche 50-000,83/04/19,8305230573
- --8305230617 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN E J Reactor Operations Analysis Branch 83/04/19 9pp 18341 343 24% Fiche 50-000,83/04/19,8305230573.
- 9308260260 NPDES noncompliance notification on 830413 routine analysis revealed average oil & grease concentration of 25 mg/l & pollutant load of 27 9 lb per day Caused by bearing failure on turbine Bearing repaired H/830426 ltr ORIFFIN.J., MARSHALL, J. A Arkansas Power & Light Co B3/04/20 COLLING.J T Region 4. Office of Director HHITT/NOTON.D Environmental Protection Agency 3pp 18627 074 24X Fiche 50-313, 83/04/20,8305260260
- 8305020373 Forwards LER 83-014/01T-0
 MARSHALL, J R Arkansas Power & Light Co 83/04/25 SEIDLE, W C
 Region 4. Office of Director. Jp 18276 309 24X
 Fiche: 50-368, 83/04/25, 8305020373

- --8305020378 LER 83-014/01T-0 on 830411, response times of two RCS resistance temp detectors found badly degraded Caused by degradation of couplant (Never-Seer) used in mating resistance temp detectors into thermowells ROGERS.P Arkansas Power & Light Co 83/04/25 Region 4. Office of Director 2pp 18276 310 24X Fiche 50-368.83/04/25, 8305020373
- 8305200490 NPDES noncompliance notification on 830413, sample from Outfall 003, oily water separator, revealed average oil & greese concentration of 25 mg/l & pollutant load at 27 9 lbs per day Caused by bearing failure on Unit i turbine MARSHALL, J R Arkansas Power & Light Co 83/04/26 COLLINS, J T Region 4, Office of Director 3pp 18514 036 24X Fichs 50-313, 83/04/26,8305200490
- B305260249 Telecapy LER 83-020/01T-0 on 830519, fire watch posted in wrong location for period exceeding Tech Spec limit Further details will be provided LEVING.J.M Arkaness Power & Light Co 83/05/19 COLLINS.J Region 4, Office of Director ip 18626 323 24X Fiche 50-368,83/05/19,8305260249
- DOCKET 30-369 HILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1 F. Becurity, medical, emergency & fire protection plans
- B303040384 Releases public version of rev to emergency plan implementing procedures
 FELTON, J.M. Division of Rules and Records B3/04/24 Document Management Brench ip 18336 137 24X Fiche 50-369,83/04/26, 8305040384
- --9305040597 Forwards public version of revised emergency plan implementing procedures including Procedures RP/D/A/5700/01 re notification of unusual event, RP/O/A/5700/02 re alert & RP/O/A/5700/04 re general emergency
 TUCKER: H B Duke Power Co BS/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENGAM, E G Licensing Branch 4 2pp 18336 140 24% Fiche 50-369,83/04/26.8305040584
- --B305040606 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual events RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general emergency QLOVER.M B Duke Power Co. B3/02/24 77pp 18336 142 24X Ficha 50-369,83/04/26,8305040584
- B305050135 Forwards Rev 15 to security plan, including implementation of Unit 2 vital access, safe shutdown facility & deletion of interim vital areas Rev withheld (ref 10CFR73 21) TUCKER.H B Duke Power Ca 83/04/26 O'REILLY, J P Region 2, Dffice of Director ip, 18342 239 24x Fiche 50-369,83/04/26, B305050135
- B305160283 Releases public version of revised emergency plan implementing procedures FELTON-J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18472 079 24X Fiche 50-369,83/05/02, 8305160283
- --B305i60285 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/O/A/5700/01 re notification of unusual event.RP/O/A/5700/02 re elert & RP/O/A/5700/03 re site area emergency TUCKER, H B. Duke Power Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18472:080 24X Fiche 50-369,83/05/02,8305160283
- --9305160286 Public version of revised amergency plan implementing procedures, including Procedures RP/D/A/5700/01 re natification of unusual syent.RP/D/A/5700/02 re alert & RP/D/A/5700/03 re site area emergency LEDNARD.J R., MCCONNELL,T Duke Power Co 83/02/04 159pp 18472.082 24X Fiche 50-369,83/05/02,8305160283
- B305130192 Advises of plan to use public address sys for local fire alarms in reactor bldg.Plan meets intent of NFPA 72D-1975 as committed in Section E ((a) of fire protection review plan NRC epproval requested by B30701

 TUCKER.H B Duke Power Co B3/05/06 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch 4. 2pp 18439:358, 24X Fiche 50-349,83/05/06,8305130192
- B305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D. G. Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X Fiche.50-000,83/05/11,8305110034

- 8305200556 Forwards IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/17 TUCKER.H B Duke Power Co 2pp 18514 264 24X Fiche 50-369.83/05/17.8305200556
- --8305200545 IE Safeguards Insp Repts 50-349/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation, review of security organization & security program audit Datails withheld (ref 100FR73 21) TILLMAN, A. URYC. B. Region 2. Office of Director MCGUIRE, D. R. Division of Emergency Preparadness & Materials Safety 83/05/17 p. 18514 268 24% Fiche 50-369, 83/05/17, 8305200556
- B305250278 Forwards Rev 7 to spent fuel transportation plan Rev withheld (ref jQCFR73 21) TUCKER.H B Duke Power Co B3/05/18 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 18592 362 24X Fiche 50-369.B3/05/18.
- J Insurance & indemnity information
- B305260261 Forwards Endorsements 95 % 36 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-82 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101, respectively, for McGuire LAWSON, L T Duke Power Co B3/05/20 SALTZMAN, J Office of Resource Management, Director 19pp 18A26 120 24X Fiche 50-000,83/05/20,8305260261
- P Operating license stage documents & correspondence
- 8303300370 Notification of 830329 meeting w/util in Bethesda.MD to discuss equipment qualification BIRKEL.R A Licensing Branch 4 83/03/22 ADENSAM.E G Licensing Branch 4 3pp 17754 286 24X Fiche 50-369.83/03/22,8303300370
- 8305050283 Forwards proprietary & nonproprietary versions of attachment to 830314 ltr re Tech Spec change to reduce measurement uncertainty for RCS flow rate Proprietary version withheld (ref 10CFR2 790)
 TUCKER: H B Duke Power Co 83/04/26 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 28pp 18337 261 24X Fiche 50-369.83/04/26.8305050283
- --8303050288 Application for withholding proprietary info re Westinghouse reactor protection sys/ESF actuation sys Setpoint methodology (ref 10cFR2 790) HIESEMANN, R A Westinghouse Electric Corp 83/04/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 8pp 18337 289 24X Fiche 30-369,83/04/26,83/05050283
- B305060224 Application for amend to License NPF-9 revising B21123 application re reduced measurement uncertainty for RCS flow rate Amend should also be applied to Unit 2 Tech Specs withheld (ref 10CFR2 790) Class I amend fee encl TUCKER.H B Duke Power Co B3/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAME G Licensing Branch 4 3pp 18345 024 24X Fiche 50-369,83/04/27,8305060224
- 8305060413 Forwards add1 info re monitoring & testing program for steam generators concerning preheater mod Installation of mod on Unit 2 currently scheduled to begin in mid-June Date tentative depending on Westinghouse schedule
 TUCKER.H B Duke Power Co 83/04/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch
 4 3pp 18343 259 24X Fiche 50-369,83/04/28.8305060413
- 8305020455 Generic Ltr 83-19 to all power reactor t testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
 EISENHUT.D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York Inc 50pp 18441 120 24X
 Fiche 50-000,83/05/02,8305020455
- B305100383 Requests that B30418 proposed amend to Tech Specs to revise setpoint for upper head injection accumulator automatic isolation be changed to incorporate revised setpoint calculation
 TUCKER.H B Dute Power Co B3/05/04 DENTUN.H R Office of Nuclear Reactor Regulation, Director ADENBAN.E Q Licensing Branch
 4. 2pp 18377 323 24X Fiche 50-369,83/03/04,8305100383

- B305100007 Requests approval of revised test method & acceptance criteria for dynamic rod drop test Reply requested by B30511, scheduled date of test TUCKER.H B Duke Power Co B3/05/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18377 257 24% Fische 50-369, 83/05/05,83091000007
- B305100347 Forwards addl justification supporting adequacy of test of electrical load to satisfy License Condition 2 C & WCAP-B921. "Setpoint Study Duke Power, William B McGuire Muclear Plant, Units i & 2 " Rept withheld (ref 10CFR2 790) TUCKER, H D Duke Power Co B3/05/05 DENTON H R Office of Nuclear Reactor Regulation. Director ADENGANE 0 Licensing Branch 4 2pp 18378 325 84X Fiche 50-369,83/05/05.8303100347
- 8305180053 Forwards Amend 21 to License NPF-9, safety evaluation & notice of issuance & availability Amend adds condition for verifying acceptability of Model D2 steam generator mods ADENSAM E Q Licensing Branch 4 83/05/05 TUCKER.H 8 Duke Power Co 3pp 18499 307 24X Fiche 50-349.83/05/05.8305180053
- --8305180058 Amend 21 to License NPF-9, adding condition for verifying acceptability of model D2 steam generator design mods EISENHUT, D Ø Division of Licensing B3/05/05 4pp 18499 309 24% Fiche 50-369, 83/05/05, 8305180053
- --8305180066 Safety evaluation supporting Amend 21 to License NPF-9

 Office of Nuclear Reactor Regulation, Director 83/05/05
 13pp 18499 313 24% Fiche 30-367.83/03/05/8305180053
- ---8305180072 Notice of issuance & availability of Amend 21 to Lacense NPF-9 ADENSAM,E 0 Licensing Branch 4 83/05/05 3pp 18499 326 24X Fiche 50-369,83/05/05,8305180053
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D 9 Division of Licensing 89/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627 153 24X Fiche 50-000.83/05/04.8303090659
- 8305170723 Responds to B30311 request for relief from ASME Code Section XI requirements re-performing hydrostatic tests after mods by welding on both units associated w/steam generator D Approach acceptable
 NDVAK.T M Assistant Director for Licensing B3/05/09 TUCKER.H B
 Duke Power Co 4pp 18496-1845 24X Fiche 50-369.83/05/09.
 B305170723
- --B305170726 SER supporting B30311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mode by welding on both units associated w/steam generator D

 4 Division of Licensing B3/05/09 3pp 18476 170 24X fiche 50-369, 83/05/09 805170723
- --B305170730 Notice of granting of ralief from certain requirements of ABME Code Section XI inservice testing requirements ADENSAM.E G Licensing Branch 4 B3/05/10 2pp 18496 193 24X Fiche 50-369,83/05/09.8305170723
- B305170277 Forwards response to open items identified in Franklin Research Ctr technical evaluation rept re environ qualification of electrical equipment TUCKER.H B Duke Power Co B3/05/11 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAK, E G Licensing Branch 4 29pp 18465 297 24X Fiche 50-369,83/05/11.8305170277
- 8305180791 Requests add1 Class I fee for 830311 application for relief from ASME Code Section XI requirements Requirements impractical DIGGS.R M License Fee Management Branch. 83/05/11 TUCKER.H B Duke Power Co ip 18505 345 24X Fiche 50-369.83/05/11, 8305180791
- 8305200438 Forwards Rev 1 to "Offsite Dose Calculation Manual"
 TUCKER.H B Duke Power Co 83/05/17 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAME © Litensing Branch
 4 ip, 18517-124 24X Fiche 50-369,83/05/17,8305200438
- 8309240097 Informs that License Condition 2 C (!!)g on NUREG-0737.
 Item II K 3 10. "Anticipatory Reactor Trip." satisfied
 Bafety evaluation bnc1.
 NOVAK: T M Assistant Director for Licensing 83/05/17 TUCKER.H 1
 Duke Power Co App 18594 125 24X Fiche 30-369.83/05/17.
 8305240097

- 8305230247 Approves util 830505 requested changes to dynamic rod drep test purpose method & acceptance criteria Change alters test to record data on dynamic reactor response to simultansous drop of two rods into core NDVAK.T M Assistant Director for Licensing 83/05/17. TUCKER.H B Duke Power Co 3pp 18595 333 24X Fiche 30-369.83/05/17. R308250247
- B3052502B1 Clarifies commitment to modify automatic shunt trip design per Salem Tast Force generic study Implementation schedule for independent fusing scheme for breaker closing circuits & auxiliary relays will be submitted

 TUCKER-H B Duke Power Co B3705/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Branch

 4 ip 18592 361 24X Fiche 50-369,89/05/20,8305250281
- B305250287 Informs of control scheme reevaluation for hydrogen mitigation sys Switches allowing manual actuation will be added during first refueling shutdown TUCKER.H B Dute Power Co 83/05/20 DENTON.H R Defice of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Stanck 1p 18592 075 24X Fiche 50-369.83/05/20.8305250287
- 8305250442 Advises that info submitted 830223 & 0512 re environ qualification of electric equipment in Unit 2 applies equally to Unit 1
 TUCKER, H B Dute Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branca 4 ip 18688 095 24X Fiche 50-369,83/05/20,8305250442.
- @ Inspection reports, IE Bulletins & carrespondence
- 8212040985 IE Info Notice 83-14, "Dewatered Spant Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc liet enc!

 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York. Inc 112pp 18308 319 24X Fichs 50-000, 63703/21, 8212040385
- 8305270146 Forwards IE Insp Repts 50-369/83-14 & 50-370/83-21 en 830307-10 No nencompliance noted DANCE,H C Division of Project & Resident Programs. 83/03/25 TUCKER:H R Duke Power Co 2pp 18638 195 24X Fiche 50-369,83/03/25,8305270146
- --B305270151 IE Insp Repts 50-369/B3-14 & 50-370/B3-21 on B30307-10 & moncompliance noted Major areas inspected Unit 2 initial fuel loading, preoperational test results review & followup an previous inspector-identified itams
 THOMAS.M Region 2. Office of Director JAPE.F Division of Emergency Preparedness & Materials Safety B3/03/24. 4pp 18638 197 24X Fiche 50-369,83/03/25,8305270146
- 8305270154 Forwards IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/03/27 TUCKER,H D Duke Power Co 2pp 18638 034 24X Fichs 50-369,63/03/29,8305270154
- --8305270i60 IE Insp Repts 50-369/83-i3 & 50-370/83-i9 on 830i20-0302 ks honcompliance noted Major areas inspected operations, surveillance testing, maint, procedures review. TMI requirement verification & provious outstanding items
 ORDERS, W. ROGOE, J. Region 2, Defice of Director IONATONIE, A
 Division of Project & Resident Programs 83/03/28 19pp
 18630 036 24X Fiche 50-369,83/03/29,8305270134
- 8305270385 Forwards IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted DANCE, HC Division of Project & Resident Programs 83/03/27 TUCKER, H B Duke Power Co 2pp 18643 037 24X Fiche 50-369, 83/03/29, 8305270385
- --8305270402 IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted Major areas inspected steam generator mod.NDE & preservice insp. observation of work & work activities KLEINSOROEL, W P. BLAKE, J J Region 2, Office of Director 83/03/29 11pp 18443-039 24X Fiche 50-369.83/03/29.8305270385
- 8305270327 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08

 DANCE,H C Division of Project & Resident Programs 83/04/04 TUCKER,H B Duke Power Co 1p 18642,224 24X
 Fiche 50-369/83/04/04/8305270327

- --B305270366 Responds to NRC B30224 ltr re violations noted in IF Insp Repts 50-369/83-05 & 50-370/83-08 Corrective actions procedures will be modified by B30401 to verify quantity of radisactive math per App C & 100FR20 203 TUCKER.H B Duke Power Co B3/03/25 O'REILLY, J P Region 2, Office of Director 2pp 18642 225 24X Fiche 50-369,83/04/04, 8305270327
- --8305270382 Forwards 1E Insp Repts 30-349/83-05 & 50-370/83-08 on 830131-0204 & notice of violation DANCE H C Division of Project & Resident Programs 83/02/24 TUCKER H B Duke Power Co 2pp 18642 227 24X Fiche 50-369, 83/04/04, 8305270327
- --8305270405 Notice of violation from insp on 830131-0204 e Region 2, Office of Director 83/02/24 ip 18642 229 24X Fiche 50-369,83/04/04,8305270327
- ---B305270428 IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204 Noncompliance noted trailer containing more than 10 times App C quantity of Ca-60 not pasted per 10CFR20 2038 ALBRIGHT.R H . CULLING.T R Region 2. Office of Director BARR.K P Division of Engineering & Radiological Safety Programs B3/02/22 3pp 1842 230 24% Fiche 30-369.83/04/04,8305270327
- 8303040021 IE Info Notice 83-21: "Defective Emergency Use Respirator"

 Byr list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) 83/04/15 Consolidated Edison Co of New
 York: Inc 126pp 18435 155 24X Fichs 30-000:83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BMR Bafety/Relimf Valve Failures " Svc limit and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- G303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sansing Sys " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp. 18381 291 24X Fichs 50-000,83/04/25,8303040025
- 8303270511 Forwards IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted DANCS: H C Division of Project & Resident Programs 83/04/27 TUCKER: H B, Duke Power Co 2pp 18645 248 24X Fichs 50-369,83/04/27,8305270511
- --B305270521 IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted Major areas inspected startup programs & closeout of outstanding items
 BURNETT-P.T., JAPE.F Region 2, Office of Director 83/04/25 opp 18645 250 24X Fichs 50-369.83/04/27.8305270511
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list and! JORDANIE L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/04/28 Consolidated Edison Co of New York, Inc listpp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Evc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 189p. 18382 165, 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " 8vc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp. 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Syc list enci.
 JORDANIE L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp, 18382.282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/05/04. Consolidated Edison Co. of New York, Inc. 117pp 18441 001. 24X Ficha 50-000.83/05/04.8303040031
- 8305500148 Forwards revised info re steam generator insp program Following preheater mod installation Attachment replaces Page 2 of encl to 830428 ltr
 TUCKER, H B. Duke Power Co. 83/05/05 DENTON, H R. Office of Nuclear Reactor Regulation, Director / ADENBAM, E G. Licensing Branch 4. 2pp 18374; 221, 24% Ficher 50-369, 83/05/05, 8305100148

- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc) JORDAN,C L Division of Emergency Preparadness & Engineering Response (Post 830103) B3/05/06 Consolidated Edison Co of New York
- 8303040034 IE info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305190462 Discusses NDE support to Task Order 4-83,which L Frank requested CV Dodd to undertake Meeting of eddy-current specialists to discuss exam of preheater tube wear defects will be scheduled FARMX.L Materials Engineering Branch FIN B-0779-3 83/05/13 MCCLUNG.R W Dak Ridge National Laboratory 1p 18523 166 24X Fiche 50-369, 83/05/13,8305190462
- 8305200556 Forwards IE Sefeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/17 TUCKER,H B Duke Power Co 2pp 18514 266 24X Fiche 50-369,83/05/17,8305200556
- ---B305200565 IE Safeguards insp Repts 50-369/83-18 & 50-370/83-25 on B30418-22 No noncompliance moted Major areas inspected site orientation; review of security organization & security program audit Details withheld (ref 10CFR73 21)
 TILLMAN, A. VRYC, B. Region 2, Office of Director MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety B3/05/17 p. 18514 268 24X Fiche 50-369.83/05/17,8305200556
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 19697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Dil " Syc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305170536 Forwards monthly operating repts for Apr 1983 TUCKER:H B Duke Power Co 83/05/13 Director's Office Office of Inspection and Enforcement 1p 18469 028 24X Fiche 50-367.83/05/13,8305170536
- --8305170540 Monthly operating repts for Apr 1983
 REAVIS.J A Duke Power Co 83/05/13 7pp 18469 029 24X
 F(che 50-349.83/05/13.8305170534
- 8 Reportable occurrences, LERs & related correspondence
- B305310052 Updated LER B3-014/03X-1 on B30303.conventional waste water sys radiation monitor iEMF-31 channel found out of the tolerance Caused by cracking detector crystal due to excessive temp change Crystal replaced W/B30518 ltr NARDOCI.P.B , TUCKER.H B Duke Power Co B3/04/15 O'REILLY, J P Region 2, Office of Director 2pp 18633 164 24% Fiche 50-369.83/04/15,8305310052
- 8305230573 Forwards engineering evaluation rept. "Cracks & Leaks in Small Diameter Piping " BROWN, E J Reactor Operations Analysis Branch, 83/04/19 SEYFRIT.K V. Reactor Operations Analysis Branch 19 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping.

 BROWN: E J Reactor Operations Analysis Branch 83/04/19 7pp 18541 343. 24X Fichs. 50-000, 83/04/19, 8305230573
- 8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices. Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mg drawlings revised RAME, E P Westinghouse Electric Corp 83/04/21 DEYOUNO, R C Director's Offices of Fitze of Inspection and Enforcement 5pp 18405 095 24% Fiche: 50-000, 83/04/21, 8305(10427

- 8305030673 Summary of 830419 meeting w/util.Bechtel & Westinghouse in Bathesda,MD re failures of undervoltage trip devices in reactor trip breakers (Westinghouse Model DS-416) BIRKEL,R A Licensing Branch 4 83/04/25 Licensing Branch 4 34pp 18309 195 24X Fiche 50-369.83/04/25,8305030675
- 8305100002 Forwards LER 83-016/03L-0 TUCKER.H B Duke Power Co 83/04/26 O'REILLY, J P Region 2. Office of Director 1p 18377 213 24X Piche 50-369.83/04/26. B305100002
- --8305100003 LER 83-016/03L-0 on 830327, hanger IMCA-ND-H260 discovered pulled loose from wall anchors & snubbers IMCA-ND-H177 \$ H317 found locked up during subsequent full-stroking Caused by water hammer event resulting in void formation NARDOCI,P B Duke Power Co B3/04/26 Region 2, Office of Director ip 18377 214 24X Fiche 50-369,83/04/26,8305100002
- 8305040273 Clarifies info re reactor trip breakers reported in 830228, 0301 & 22 ltrs Five consecutive failures to trip reactor trip breakers via undervoltage attachment considered single failure
 TUCKER.H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director NOVAK.T H NRC No Detailed Affiliation Given 2pp 18323 242 24X Fiche 50-369,83/04/28, 820504023
- B305060403 Submits add1 info requested by B30426-27 telcons re problems w/D8-416 breaker undervoltage devices Undervoltage devices replaced w/new corrected devices & installation checks to verify proper alignment initiated TUCKER.H II Duke Power Co B3/04/28 DENTON.H II Office of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 10pp 18343 177 24K Fiche 50-369,83/04/28,8305060403
- 8305100364 Forwards radial peaking factor limit rept.in response to RO 369/83-it re removal of burnable poison rod assemblies Requirement to submit rept 60 days prior to effective date of limits does not apply TUCKER: B Duke Power Co 83/04/28 O'REILLY.J P Region 2. Office of Director 3pp 18379 101 24X Fiche 50-369.83/04/28.8705100366
- 8305110201 Forwards LER 83-013/03L-0. Detailed event analysis encl TUCKER, H B Duke Power Co 83/04/29 D'REILLY, J F Region 2, Office of Director 4pp 18393 243 24X Fiche 50-369,83/04/29,
- ~-8305110283 LER 83-013/03L-0 on 830315, during upperhead imjection level suitch calibr, suitches found out of tolerance Caused by design deficiency Rev to Tech Specs changing switch setpoint submitted MARDDC1,P B Duke Power Co 83/04/29 Region 2, Office of Director ip 18393 247 24X Fiche 50-369,83/04/29,8305110281
- 8305040227 Forwards "Investigation of Unit Trips," "Unit Fast Recovery," "Actions Required for ATHB Event," "Reactor Trip:" & evaluation re mod to provide automatic reactor trip breaker actuation.per NRC request TUCKER.H B Duke Power Co 83/05/02 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 3pp, 18323 217 24% Fiche 50-369,83/05/02.8305040229
- --8305040240 Procedure OP/1/A/6100/05, "Unit Fast Recovery "
 * Duke Power CO 83/05/02 7pp 18323 222 24X
 Fitche 50-264.83/05/02.8305340227
- --8305040246 Procedure AP/O/A/5500/34, "Actions Required for ATMS Event " FIREBAUGHLL, REESIDE:W O Duke Power Co 82/04/22 3pp 18323 231 24X Fiche 50-369;83/05/02,8305040229
- --8305040260 Change O to Procedure AP/1/A/5500/01. "Reactor Trip "
 REESIDE,B , FIREBAUGH,L. Duke Power Co 82/05/29 8pp
 18323 234 24X Fiche.50-369.83/05/02,8305040229
- 8305070472 Discusses 830418 rept re reactor trip breakers (RTB) for facility RTB found w/no gap between undervoltage device trip arm & breaker trip shaft pin on 830331 Problem inadvertently emitted in 830418 rept Proper gaps verified TUCKER.H B Duke Power Co 83/05/05 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAN.E © Licensing Branch 4 lp. 18362 341, 24X Fiche 50-369.83/05/03.8305090472
- B305110085 Submits add1 info requested in B30427 telcon re failure of D8-416 breaker undervoltage devices Westinghouse recommendations implemented Add1 testing will be performed & amend to Tech Spec will be added.

 TUCKER.H B Duke Power Co B3/03/03 DENTON.H R. Office of Nuclear Reactor Regulation, Director ABENBAM.E 0 Licensing Branch 4 4pp 18398 062 24% Fiche 50-367, B3/03/03, B305110085

- B305100327 Clarifies B30331 incident involving problem w/train B reactor trip breaker Problem resulted in failure of breaker to trip upon undervoltage TUCKER,H B Duke Power Co B3/05/05 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18378 321 24X Fiche 50-369, B3/05/05, B305100327
- 8305170355 Forwards LER 83-017/03L-0 TUCKER.H B Duke Power Co 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18466 105 24X Fiche 50-369,83/05/05, 8305170355
- ~-B305170358 LER B3-017/03L-O on B30405, during draining of refueling cavity RHR (ND) pumps began to cavitate & eventually both ND pumps stopped Caused by level gauge isolation Cavity refilled ND sys ventsd Procedures revised NARDOCI,P B Duke Power Co 83/05/05 Region 2, Office of Director ip 18466 106 24X Fiche 50-369,83/05/05,8305170355
- 8305170507 Advises that all info re RO 369/83-18 on 830407 on enubly operability unaveilable Complete rept will be submitted by 830520 TUCKER: H B Duke Power Co 83/05/06 O'REILLY, J. P Region 2, Office of Director 1p 18470 014 24X Fiche 50-369, 83/05/06, 830517057
- 8305170649 Ack receipt of 830428 response to NRC concerns re reactor trip breakers Facility may be returned to operation Detailed schematic diagrams, describing approved reactor protection sys shunt modirequested EIBENHUT, D 0 Division of Licensing 83/05/06 TUCKER, H B Dule Power Co 2pp 18496 244 24% Fiche 50-369,83/05/06,8305170649
- 8305130158 Provides add1 info updating 830428 & 0503 ltrs re recent problems w/D8-416 breaker undervoltage devices.per NRC request Actions & commitments provide sufficient basis for operation Util intends to proceed w/startup per schedule TUCKER.H B Duke Power Co 83/05/10 DENION.H R Office of Nuclear Reactor Regulation, Director ADENIAM.E Q Licensing Branth 4 4pp 18437 172 24X Fiche 50-369, 83/05/10,8305130158.
- 8305250404 LER 83-019/03L-0 on 830413, representative fuel pool ventilation sys carbon filter sample analysis indicated sample failed to mest methyl indide penetration criteria Bample analyses made to determine cause W/830512 ltr NARDOCI,P B , TUCKER,H B Duke Power Co 83/05/12 0'REILLY,J F, Region 2, Dffice of Director 2pp 18592 091 24% Fiche 50-369,83/05/12.8305250404
- B305230717 Forwards SER of util actions in response to DB-416 reactor trip breaker failures Unit may be returned to svc NOVAK.T M Assistant Director for Licensing 83/05/18 TUCKER.K B Duke Power Co 2pp 18542 274 24X Fiche 50-349.83/05/18, 8305230717
- --8305230719 Safety evaluation re util actions taken in response to reactor trip brasker failures Unit may be returned to svc * Assistant Director for Licensing 83/05/18 18pp 18542 276 24X Fiche 50-369, 83/05/18, 8305230717.
- B305230549 Submits list of procedures changed to require independent engineering analysis on reactor trips Analysis will use reactor trip checklist to ensure appropriate parameters considered Performance engineer to document review TUCKER.H B Duke Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director A DEENSAME G Licensing Branta 4 2pp 18588 224 24X Fiche 50-369,83/05/20,8305250549
- 8305310174 PND-II-83-042 on 830521 employee injured while pressuriting inflatable bladder—like pipe plug Rupture of bladder caused employee left hand to hit adjacent piping resulting in cuts to broten bones Hand decontaminated iGNATONIS, A. GIDSUN, A.F. Region 2. Office of Director 83/05/23 2pp 18652-277 24X Fiche 30-367, 83/05/23, 8305310174
- DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305190032 Forwards response to outstanding environ qualification items identified in Section 7 8 of Suppl 6 to SER & technical evaluation rept Info supports full power licensing TUCKER.H B Duke Power Co 83/05/12 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAME 9 Licensing Branch 4 5pp 18502 058 24X Fiche 50-370.83/05/12.8305190032

- F Becurity, medical, emergency & fire protection plans
- B305040584 Releases public version of rev to emergency plan implementing procedures FELTON.J M Division of Rules and Records B3/04/26 Document Management Branch ip 18336 137 24X Fiche 50-369.83/04/26, 8305040584
- --B305040597 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/U/A/5700/01 re notification of unusual event, RP/U/A/5700/02 re alert & RP/U/A/5700/04 re general emergency TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18336 140 24X Fiche 50-369,83/04/26,8305040584
- --8305040606 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general smargency Qt.0VER, M S Duke Power Co 83/02/24 77pp 18336 i42 24x Fiche 50-369, 83/04/26, 8303040584
- B305050135 Forwards Rev 15 to security plan, including implementation of Unit 2 vitel access, safe shutdown facility & deletion of interim vital areas Rev Withheld (ref 10CFR73 21)

 YUCKER, H B. Duke Power Co 83/04/26 0'REILLY, J P Region 2.

 Office of Director ip. 18342 239 24% Fiche 90-367,83/04/26,830505135
- 8305160283 Releases public version of revised emergency plan implementing procedures FELTON. If Division of Rules and Records 83/05/02 Document Management Branch ip 18472 079 24X Fiche 30-369.83/05/02. 8305160283
- --8305160285 Forwards public version of revised emergency plan implementing procedures including Procedures RP/O/A/3700/01 re notification of unusual event, RP/D/A/5700/02 re alert & RP/O/A/5700/03 re site area emergency TUCKER. H B Duke Power Co 83/02/25 DENYON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 2pp 18472 080 24X Fiche 50-369.83/05/02,8305160283
- --8305160286 Public version of revised amangency plan implementing procedures, including Procedures RP/O/A/5700/01 re notification of unusual event.RP/D/A/5700/02 re alert & RP/D/A/5700/03 re site area emergency LEONARD.JR , MCCONNELL.T Duke Power Co 83/02/04 159pp 18472 082 24X Fiche 50-369,83/05/02.8305160283
- G305130192 Advises of plan to use public address sys for local fire alarms in reactor bldg Plan meets intent of NFPA 720-1975 as committed in Section E I(a) of fire protection review plan NPC approval requested by S30701

 TUCKER, H B. Duke Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAN, E C Licensing Branch 4 2pp 18439:338 24% Ficher 50-369, 83/05/06, 8305130192
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EIBENHUTD O Division of Licensing 83/03/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fichs 30-000,83/05/11,8305110034
- B305170020 Bubmits schedule for installation of RCB cold leg temp monitors as integral part of standby shutdown sys Mod will be implemented no later than startup following second refueling outage Exemption may be needed TUCKER.H B. Duke Power Co 83/05/13 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBARM.E O Licensing Branch 4 App 18502 017 24X Fiche 50-370.83/05/13.8305190020
- 8305200556 Forwards IE Bafeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/17 TUCKER,K II Duke Power Co 2pp 18514 266 24X Fiche: 50-369, 83/05/17, 8305200556
- --8303200545 IE Bafeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation.review of security organization & security program audit Details withheld (ref 10CFR73 21)
 TILLHAN, A Region 2, Office of Director 83/05/17 ip 18514 268 24X Fichs 50-369,83/05/17,8305200556
- B305250278 Forwards Rev 7 to spent fuel transportation plan Rev withheld (ref 10CFR73 21) TUCKER, H B Duke Fower Co B3/05/18, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18592 362 24X Fiche: 50-349, 83/05/18, 8305250278

- J Insurance & indomnity information
- 9305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101, respectively, for McGuire LAWSON, L T Duke Power Co 83/05/20 SALIZMAN, J Office of Resource Management, Director 19pp 18626 120 24% Fiche 50-000, 83/05/20, 8305260261
- P Operating license stage documents & correspondence
- B303300370 Notification of B30327 meeting w/util in Bethesda, MD to discuss equipment qualification BIRKELR A Liconsing Branch 4 B3/03/22 ADENSAM, & O Licensing Branch 4 B3/03/24 ADENSAM, & O Licensing Branch 4 B3/03/24, B303300370
- 8305060224 Application for amend to License NPF-9 revising 821123 application re reduces measurement uncertainty for RCS flow rate Amend should also be applied to Unit 2 Tech Spocs withheld (ref 10CR2 790) Class I amend fee encl TVCKER.H B Duke Power Co 83704/27 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Dranch 4 3pp 18345 024 24% Fiche 50-369.83/04/27,8305060224
- 8305040449 Discusses util intentions re performance of requirements placed on Westinghouse for physics testing & surveillance of hybrid control rods Estimated critical positions will be used thoughout Cycle i TUCKER.H B Duke Power Co 83/04/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 2pp 18321 297 24X Fiche 50-370.83/04/28.8305040469
- 8305060413 Forwards add1 info re monitoring % testing program for steam generators concerning preheater mod Installation of mod on Unit 2 currently scheduled to begin in mid-June Date tentative depending on Westinghouse schedule TUCKER, H B Duke Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 18343 239 24% Fiche 50-369, 83/04/28, 8305060413
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to CLs Svc list encl
 EISENHUT, D @ Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
 Fiche 50-000.83/03/02.8305020495
- B305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications B3-17 & B3-44 re Unresolved Bafety Issue A-17 EISENKUT, D Q Division of Licensing 83/05/04 PALLADING, N Commissioners 22pp 18337 139 24X Fiche 50-000, B3/05/04, B305040323
- 8305100383 Requests that 830418 proposed amend to Tech Specs to revise setpoint for upper head injection accumulator automatic isolation be changed to incorporate revised setpoint calculation
 TUCKER.H B Duke Power Co 83/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 18377 323 24x Fiche 50-369,83/05/04,8305100383
- --8305100390 Revised proposed Tech Specs changing upper head injection accumulator automatic isolation setpoints to incorporate revised setpoint calculation # Duke Power Co 83/05/04 ip 19377 325 24X Fiche 50~349,83/05/04.8305100383
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT. D. G Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- B305170723 Responds to B30311 request for relief from ABME Code Section XI requirements re performing hydrostatic tests after mods by welding on both units associated w/steam generator D Approach acceptable
 NOVAK.T M Assistant Director for Licensing B3/05/09 TUCKER.H B Dute Power Co 4pp 18476 186 24X Fiche 50-369, 83/05/09, 83/05/079.
- --B305170726 SER supporting B30311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mode by welding on both units associated w/steam generator D

 * Division of Licensing B3/05/07 3pp 18496 190 24X Fiche 50-369, B3/05/09, B305170723

- --8305170730 Notice of granting of relief from certain requirements of ASME Code Section XI inservice testing requirements ADENSAM.E G Licensing Branch 4 83/05/10 2pp 18496 [93 24X Fiche 50-369,83/05/09,8305170723
- 8303170277 Forwards response to open items identified in Franklin Research Ctr technical evaluation rept re environ qualification of electrical equipment TUCKER. H B Duke Power Co. 83/05/11 DENTON. H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 29pp 18465 297 24% Fiche 50-369, 83/05/11, 8305170277
- 8303180791 Requests add1 Class I fee for 830311 application for relief from ABME Code Section XI requirements Requirements impractical. DICOB,R M License Fee Hanagement Branch 83/05/11 TUCKER,H B Duks Power Co Ip 18505 345 24X Fiche 50-369,83/05/11, 8303180791
- 8303040044 Board Notification 83-66 forwards review of NCAP-10297(P), "Broppped Rod Methodology for Negative Flux Rate Trip Plants "Rod issue resolved by analysis in rept Plants beyond first cycle must perform analysis Comments encl EISENHUT, D G Division of Licensing 83/05/13 PALLADINO, N , GILINSKY, V , AMEARNE, J Commissioners 21pg 18546:068 24X Fichs 50-000, 83/05/13.8303040044
- B305230499 Notification of B3060B meeting w/util in BethesdarHD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments 4 source range flux monitors to be addressed SUERMANN.JF Operating Reactors Branch 4 83/05/16 STDLZ.JF Operating Reactors Branch 4 220 18341 274 24x Fichs. 50-000.83/05/16.8305230499
- B30520043B Forwards Rev 1 to "Offsite Dose Calculation Manual"
 TUCKER:H B. Duke Power Co B3/05/17 DENTON H R Office of
 Nuclear Reactor Regulation, Director ADENSAME 0 Licensing Branch
 4 Lp. 18517 124 24X Fiche 50-369, 83/05/17, 830520049B.
- --8305200440 Rev 1 to "Offsite Dose Calculation Manual "
 BIRCH.M L , MCINTOSH,M D , STEWART,J M Duke Power Co 83/04/15
 8pp 18517 125 24X Fiche.50-369,83/05/17.8305200438
- 8305250281 Clarifies commitment to modify automatic shunt trip design per Salem Task Force generic study Implementation schedule for independent fusing scheme for breaker closing circuits & auxiliary relays will be submitted TUCKER.H B Duke Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E Q Licensing Branch 1p 18592 361 24% Fiche 50-369, 83/05/20,8305250281
- G305250287 Informs of control scheme reevaluation for hydrogen mitigation sys Buitches allowing manual actuation will be added during first refueling shutdown TUCKER.H B Duke Pawer Co 83/05/20 DENTON.H R Office of Nuclear Reacture Regulation. Director ADENSAM, E Q Licensing Branch 4. 1p. 18592 075 24X Fiche 50-369.83/05/20.8305250287
- 8305250290 Clarifies statements made in 830516 & 12 ltrs re environ qualification of electrical equipment All outstanding stams will be resolved & will be consistent w/IOCR50 49(g) requirements
 TUCKER.H B Duke Power Co. 83/05/20 DENTON.R Office of Nuclear Reactor Regulation, Director ADENSAM, E C. Licensing Branch 4 2pp 18592 136 24X Fiche 50-370, 83/05/20, 8305250290
- Q Inspection reports, IE Bulletins & correspondence
- B212060365 IE Info Notice 83-14, "Dewatered Spent ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list and TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21. Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385
- 8303270144 Forwards IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/03/25 TUCKER,H R Dute Power Co. 2pp 18638 175 24X Fichs 50-369,83/03/25,8305270146
- --B305270151 IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted Hajor areas inspected Unit 2 initial fuel loading preoperational test results review & followup on previous inspector-identified items

 THOMAS M Region 2: Office of Director JAPE, F Division of Emergency Preparadness & Materials Safety. 83/03/24. 4pp 18638 197 24X Fiche 50-369.83/03/25.8305270146.

- 8305270154 Forwards IE Insp Repts 50-369/83-13 & 30-370/83-19 on 830120-0302 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/03/27 TUCKER.H B Duke Power Co 2pp 18638 034 24X Fichs 50-369.83/03/29.8305270154
- --B305270160 IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 noncompliance noted Major areas inspected operations, surveillance testing, maint, procedures neview. TMI requirement varification & previous outstanding items

 ORDERS.W., ROGOE, J. Region 2. Office of Director IONATONIS.A. Division of Project & Resident Programs, 83/03/28 19pp

 18638 036 24X Fiche. 50-369, 83/03/29, 8305270154
- 8305270385 Forwards IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/03/29 TUCKER.H B Duke Power Co 2pp 18643 037 24X Fichs 50-369
- --8305270402 IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 to 0301-04 No noncompliance noted Major areas inspected steam generator mod, NDE & preservice insp. observation of work & work activities
 KLEINSCRGE, W P , BLAKE, J J Ragion 2, Office of Director 83/03/28 iipp 18443 039 24X Fichs 50-369, 83/03/29, 830527006;
- 8305270327 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08

 BANCE, H C Division of Project & Resident Programs, 63/04/04 TUCKER, H B Duke Power Co ip 18642-224 24X

 Fichs 50-369,83/04/04,8305270327
- --8305270366 Responds to NRC 830224 ltr re violations noted in IE Insp. Repts 50-369/83-05 & 50-370/83-08 Corrective actions procedures will be modified by 830401 to verify quantity of radioactive matl per App C & 10CFR20 203
 TUCKER.H B Dute Power Co 83/03/25 O'REILLY, J.P. Region 2. Office of Director, 2pp 18642,225 24X Fiche: 50-369,83/04/Q4.8305270327
- --8305270382 Forwards IE Insp Repts 50-369/83-05 & 50-370/83-08 en 830131-0204 & notice of violation. DANCE, H C Division of Project & Resident Programs, 83/02/24 TUCKER, H B Duke Power Co 2pp. 18642, 227 24X Fichs 50-369, 83/04/04, 8305270327
- --8305270428 IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204 Noncompliance noted trailer containing more than 10 times App C quantity of Co-40 not posted per 10CFR20 203e ALBRIGHT.R. H. COLLINS.T R Region 2. Office of Director BARR.K P Division of Engineering & Radiological Bafety Programs 83/02/22 5pp 18642 230 24X Fiche 50-369.83/04/04.8305270327
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator *
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fichs 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 8vc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of Ne
 York, Inc 112pp 18383.089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/25 Consolidated Edison Co. of Mee York, Inc 119pp 18381 291 24X Fiche 30-000.83/04/25.830304023
- 8305270511 Forwards IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No poncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/27 TUCKER.H B Dute Power Co. 2pp 18645.248 24X Fiche 50-369,83/04/27,8305270511
- --8305270521 IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-09 No noncompliance noted Major areas inspected startup programs & closeout of outstanding items BURNETY.P T. JAPE.F Region 2. Office of Director. 83/04/25 6pp 18645 250 24X Fichs 50-369.83/04/27.8305270511
- 830304002å IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382,047, 24X Fiche 50-000,83/04/28,8303040028

- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E 4. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Piche 50-000,83/04/28,8303040027
- B303040028 IE Into Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl URDAN,E L. Division of Emergency Preparedness & Engineering Response (fost 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03.8303040028
- 9303040030 IE Info Notice 93-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment," See list and USRDANIE 1. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp. 18382, 282 24X Fiche 50-000, 83/05/04/8303040030
- 8303040031 IE Into Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc. 119pp 18441.001 24X Fiche 50-000,83/05/04,8303040031
- 830510014B Forwards revised info re steam generator insp program following preheater mod installation Attachment replaces
 Page 2 of encl to 83042B ltr
 TUCKER, H B. Duke Power Co 83/05/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp. 18374 221 24X Fiche 50-369,83/05/05,830510014B.
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Eye list entl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp. 18523.248 24X Fichs 50-000,83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Evc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp. 18524:003 24X Fiche 50-000,83/05/11,8303040034
- B305200556 Forwards IE Bafeguards Insp Repts 50-369/83-18 & 50-370/83-25 on B30418-22. No noncompliance noted DANCE: H C Division of Project & Resident Programs, 83/05/17 TUCKER: H B Duke Power Co 2pp 18514 266 24X Fiche: 50-349, 83/05/17, 8305200556
- --8305200545 IE Bafeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation, review of security prognization & security program audit, Details withheld (ref 10CFR73 21) TILLMAN, A., VRYC, B. Region 2. Office of Director MCGUIRE, D.R. Dlvision of Emergency Preparadores & Materials Safety 83/05/17 1p. 18314: 268 24X Fiche 50-369, 83/05/17,8305200556
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Bvc list encl
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp, 18697:009, 24X Fichs 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-39, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046
- A Periodic operating reports & related correspondence
- B305170536 Forwards monthly operating repts for Apr 1983 TUCKER.H.B. Duke Power Co. 83/05/13 Director's Office, Office of Inspection and Enforcement 1p. 18469.028 24X Fiche: 50-369,83/05/13,8305170536
- --9303170540 Monthly operating repts for Apr 1983. REAVIS.J.A. Duke Power Co 83/05/13 7pp 18469 029 24X Fiche: 50-369, 83/05/13, 8305170536
- 8. Reportable occurrences, LERs & related correspondence
- 8305110427 Part 2: % deficiency repts re misoperation of D8-416 reactor trip undervoltage devices. Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME, E P Hestinghouse Electric Corp 83/04/21, DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 3pp 18405-095. 24% Fiche: 50-000, 83/04/21, 8305110427

- B305030675 Summary of B30419 meeting w/util.Bechtel & Westinghouse in Bethesda.MD re failures of undervaltage trip devices in reactor trip breakers (Westinghouse Model DS-416)
 BIRKEL.R A Licensing Branch 4 B3/04/25 Licensing Branch 4 B3/04/25 168305030675
- 8305040273 Clarifies info re reactor trip breakers reported in 830228, O301 & 22 ltrs Five consecutive failures to trip reactor trip breakers via undervoltage attachment considered single failure
 TUCKER, H B Duke Power Co. 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director NOVAK, T H NRC No Detailed Affiliation Given 2pp 18323:242 24X Ficha 50-369,83/04/28,8305040273
- 8305050153 Interim deficiency rept re ITT Barton Class IE transmitters exhibiting thermal nonrepeatability Initially reported on B21210 Bincs errors within safety analysis limits.no setpoint changes required TUCKER.H B Duke Power Co 83/04/28 O'REILLY, J P Region 2, Office of Director 2pp 18341 358 24X Fiche 50-370,83/04/28, B305050153
- 8305060403 Submits addi info requested by 830426-27 telcons re problems w/D8-416 breaker undervoltage devices Undervoltage devices replaced w/new corrected devices & installation checks to verify proper alignment initiated TUCKER.H B Dute Power to 83/04/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4. 10pp 18343 177 24% Fiche 50-369.83/04/28,8305060403
- 8305040227 Forwards "Investigation of Unit Trips," "Unit Fast
 Recovery," "Actions Required for ATMS Event," "Reactor
 Trip," & evaluation re mod to provide automatic reactor
 trip breaker actuation.per NRC request
 TUCKER,H B Duke Power Co 83/05/02 DENTON,H R Office of
 Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch
 4 3pp 18323 217 24X Fiche 50-369.83/05/02,8305040229
- --8305040246 Procedure AP/D/A/5500/34, "Actions Required for ATWS Event" FIREBAUGH.L., REESIDE.W O Duke Power Co 82/04/22 3pp 18323 231 24% Fiche 50-369, 83/05/02, 8305040229
- --8305040260 Change O to Procedure AP/1/A/5500/01. "Reactor Trip " REESIDE,B , FIREBAUGH,L Duke Power Co 82/04/29 Bpp 18323 234 24X Fiche 50-369,83/05/02,8305040229
- B305130184 PNO-II-B3-033 on B30501, inadvertent safety injection occurred Gaused by spurious signal during tests of steam generator D Low power OL received on 830303 & initial criticality planned during wk
 NEJFELT, 0, IGNATONIBA. Region 2, Office of Director B3/05/01
 19 18440 049 24X Piche 50-370,83/05/02,8305130186
- 8305090472 Discusses 830418 rept re reactor trip breakers (RTB) for facility RTB found w/no gap between undervoltage device trip arm & breaker trip shaft pin on 830331 Problem inadvertently omitted in 830418 rept. Proper gaps verified TUCKER.H B Duke Power Co 83/05/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 ip 18362 341 24X Fiche 50-369,83/05/03,8305090472
- B305110085 Bubmits add1 info requested in B30427 telcon re failure of DB-416 breaker undervoltage devices Westinghouse recommendations implemented Add1 testing will be parformed & amend to Tech Spec will be added TUCKER: H B Duke Power Co B3/05/03, DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 App 18398 062 24X Ficher 50-369, 83/05/03, 8305110085
- 830517025B Forwards LER 83-004/03L-0 TUCKER: H B Duke Power Co 89/05/06 O'REILLY, J P Region 2, Office of Director, ip 18465 06B 24X Fiche 50-370,83/05/06, 830517025B
- ---B3Q5170267 LER 83-004/03L-0 on B30406, ventilation unit condensate drain tank released while composite sampler inoperable for more than 30 days Caused by personnel error Tank red tagged, sampler installed & operation procedure will be modified NARDQCI.F B Duke Power Co B3/05/06 Region 2, Office of Director ip 18465 069 24X Fiche 50-370.83/05/06,8305170258
- 8305110262 PND-II-83-036. on 830508, unit achieved initial criticality w/o incident Actual parameters in close agreement w/ predicted conditions NEJFELT, G M., IGNATONIE, A. Region 2, Office of Director 83/05/09. ip 18393

- 8305130138 Provides add1 info updating 830428 & 0503 Itrs re recent problems w/DS-416 breaker undervoltage devices, per NRC request Actions & commitments provide sufficient basis for operation. Util intends to proceed w/startup per schedule TUCKER, H B Dute Power Co B3/03/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ABENSAM, E G Licensing Branch 4 4pp 18437 172 24X Fiche 50-369,83/05/10.8305130158
- 8305250439 LER 83-005/03L-0 on 830413, procedure review revealed that area temp monitoring surveillance not performed within 12 h limit Gaused by mess to Tech Spors Surveillance interval not recorded Procedures revised H/830512 ltr
 NARDOCI,P B , TUCKER,H B Duke fower Co 83/05/12 O'REILLY, J P Region 2, Office of Director 2pp 18585 287 24x
 Fiche 50-370,83/05/12,8305250439
- 8303250499 LER 83-006/03L-0 on B30413, while in Made 5, control room wide range reactor coolant loop D pressure indicator found low & declared inoperable Caused by air trapped in pressure transmitter Transmitter bled & loop recalibr WB303512 ltr NARD3C1,P B , TUCKER,H B Duke Power Co 83/05/12 D'REILLY, J P Region 2. Office of Director 20p 18588 266 24X Fiche 50-370,83/05/12,8305250499
- 8305250525 Interam deficiency rept re Tech Spec 3 & 1 3 concerning operability of containment air lock investigation continuing Complete rept will be provided by 830603 TUCKER. H B Duke Pawer Co 83705/IB D'REILLY. J P Region 2. Office of Director ip 18583 340 24X Fiche 50-370, 83/05/IB, 8305255535
- 8305250507 Notifies that commitment to limit operation of Unit 2 to zero power physics testing as result of recent problems w/DB-416 reactor trip breakers met w/issuance of safety evaluation for Unit 1 breakers

 TUCKER.H B Duke Power Co 83/05/19 DENTON.H R Office of NUCKER.H B Duke Power Co 83/05/19 DENTON.H R Office of Nucker Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 ip 18588 254 24X Fiche 50-370.83/05/19.8305250507
- B305290549 Submits list of procedures changed to require independent angineering analysis on reactor trips Analysis will use reactor trip checklist to ensure appropriate parameters considered Performance angineer to document review TUCKER: H B Dute Power Co B3/05/20 DENTON: N R Office of Nuclear Reactor Regulation, Director ADENSAM: C Licensing Branch 2pp 18588 224 24X Fiche 50-369,83/05/20.8305230549

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- B305240087 Addi response to FDIA request for draft inspleyaluation repts & comments on J Keppler 820719 ltr re special safety insploy facility during May-Jul 1982 Forwards App C documents
 FELTON, J M Division of Rules and Records 83/03/31 GARDE, B Oovernment Accountability Praject 2pp 18393 015 24X Fiche 30-373, 83/03/31.8305240087
- --8305250144 Recommends unesorted access to protected areas for R Lipinski & S Chan Ragifac sheet transmitting evaluation of technical rept, "Assessment of Effects of Nicked Reinforcing Steel," encl KEPPLER, J O Region 3, Office of Director 82/06/14 REED, C Commonwealth Edison Co 7pp 18593 056 24X Ficha 50-373,83/03/31,8305240087
- B305050402 Forwards request for add1 info re Pire protection for safe shutdown, based on review of Amend 62 to FSAR SCHWENCER: A Licensing Branch 2 B3/04/28 FARRAR, D L Commonwealth Edison Co. Spp 18352 046 24X Fiche 50-373,83/04/28, B305050402
- 8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124.26.29.1201.14 & 830414 & notice of violation SPESSARD.R L Division of Engineering 83/04/28 REED.C Commonwealth Edison Ca 2pp 18431 107 24X Fiche 50-373.83/04/28.8305120438
- --8305120443 Notice of violation from insp on 831124,26,27,1201.14 & 8265444 844 84554444 8455444 84554444 8455444 8455444 8455444 84554444 8455444 84554444 8455444484644 8455444484 845544484 84554444 8455444484 8455444484 8456444
- --B305120447 IE Insp Repts 50-373/B2-54 & 50-374/B2-22 on B21124,26,29, 1201,14 & B30414 Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices RAMSEY.C., ULIE.J., HABSE.R. Region 3, Office of Director B3/04/27 19pp 18431-112 24X Fiche 50-373,83/04/2B,830512043B

- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for CLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT.D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 075 24X Fiche 50-000.83/05/11,8305110034
- --8305130195 Forwards list of objectives, scope of participation, scenaric outline & narrative summary for emergency exercise scheduled for 830712

 BLACKHON.T O Commonwealth Edison Co 83/04/19 HIND.J Division of Emergency Preparedness & Operational Bupport 15pp 14437 157 24X Fiche: 50-373, 83/05/11,8305130149
- 8305170423 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Rept 50-373/83-03
 MILLER.J R Region 3, Office of Director 83/05/12 REED.C Commonwealth Edison Co 1p 18469 290 24X Fiche 50-373.83/05/12,
- --B305170425 Responds to NRC B30329 ltr re violations noted in IE Safeguards Insp Rept 50-373/B3-03 Corrective actions. procedures used to test metal detectors & proposed change in description of metal detectors addressed Details withheld FARRAR.D L Commonwealth Edison Co B3/04/19 KEPPLER, J O. Region 3. OPfice of Director ip 18469 291 24X Fiche 50-373,83/05/12,8305170423

Q Adjudicatory correspondence

- 8303200481 Advises that time for Commission to review Director's Decision DD-83-1 expired Commission declined review Decision became final agency action on 830506 CHILK, 8 J Office of the Secretary of the Commission 83/05/19 HARTIGAN.N Illinois, State of ROREM, B L Friends of the Earth 06/00L.E M Citizens Against Nuclear Power ip 18513:014 24X Fiche 50-373,83/05/19,8305200481
- P Operating license stage documents & correspondence
- 8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FOIA Examption 7) FELTON.J M Division of Rules and Records 83/03/11, PRENDERGAST.R Prendergast. R J. 17pp 18306-059 24X Fiche 50-000.83/03/11,8305190005
- --8208250506 Trip rept of 820802 audit, reviewing seismic & qualification file for Zack Co equipment, at Sargent & Lundy Engineers ofc in Chicago. IL.
 RGSITOC2V, Z R Equipment Qualification Branch, 82/08/06
 SCHWENCER, A Licensing Branch 2 8pp 16507 201 24X
 Fichs 50-000, 83/03/11, 8305170005
- --B305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removal welds Certain welds on Unit 2.Div II switchgear heat removal sys may not meet applicable code requirements HOLYDAK:R H Commonwealth Edison Co B2/08/06 Region 3, Office of Director 1p 18507 200 24X Fichs 50-000:83/03/11.
- --8305190302 Forwards Rev Q to "Assessment of Stitch Weld Strength in HVAC Ductwork Const.LeBalle County Station Units 1 & 2." GC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired. POLLOCK,R H Sargent & Lundy, Inc 82/08/27 SHELTON.B.R Commonwealth Edison Co ip 18507 317 24X Fiche 50-000, 83/03/11.8305190005
- --8305170303 Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const.LaSalle County Station Units 1 % 2 "
 CHO.F L , KISISELI T , MELIGI.A V Sargent & Lundy, Inc CGD-003490 ROO 82/08/27 27pp 18507 318 24X
 Fichs 50-000,83/03/11.8305190005
- --8305190332 Forwards "LaSalle County Station Independent HVAC Review," interim rept Rept also sent to JG Keppler KEMPIAK, A J C F Braun & Co 82/09/15 SHELYON, B R Commonwealth Editar Co 1p 18507 359 24X Fiche 50-000, 83/03/11,8305190005

- --BOOS190333 Forwards TE Watts B21019 & 25 memos to CW Schroeder responding to R Lanksbury questions he HVAC ductwork design & transmitting Rev O to Project Instruction PI-LS-42. "Review of GC Documentation for LaBails County Station "SCHROEDER,C W Commonwealth Edison Co B2/10/27 KEPPLER,J G Region J. Office of Director 90p 18508 093 24% Fiche 50~000.83/03/11.8305190005.
- --8305190357 Rev O to Project Instruction PI-L8-42, "Review of QC Occumentation for Lagalle County Station Units i & 2" a Sargent & Lundy, Inc 82/10/21 9pp 18508 102 24X Fiche: 50-000, 83/03/11, 8305190005
- --8305190365 Forwards Vols 1-4 to "Independent HVAC Review.LaBalle County Nuclear Plant," final rept KEMPfAK: A J C F Braun & Co 82/10/27 SHELTON. B R Commonwealth Edison Co 1p 18508 111 24X Fiche 50-000. 83/03/11,8305190005
- ~-8305190367 Ack receipt of CF Braun final rept of independent HVAC review at facilities PHILLIPS,R.W. Region 3, Office of Director 82/10/27 Region 3, Office of Director 82/10/27 Region 3, Office of Director 1p 18508 112 244 Fiche 50-000,83/03/11,8305190005
- ~-8305190379 Requests list of results of detailed calculations on rebar damage for 647 toncrete elements affecting Unit 1 operation & approved CF Braun proposal for independent HVAC review Zack Co Ehronology enci.

 QUODIE. J S Illinois. State of 82/09/07 KEPPLER. J 9 Region 3, Office of Director 5pp 18311 278 24X Fiche 50-000.

 RS/03/11.830519005
- ---B305190390 P Donahue show Transcript 08302 re nuclear power safety info re facilities & Zack Co enc! Multimedia Program Production. Inc. 83/03/11 128pp 18512 189 24X Fiche 50-000,83/03/11,8305190005
- 8304290034 Requests documented acceptance of General Motors Electro-Motive Div (EMD) MI 9644 mod as acceptable alternative to diesel generator prelube qil pump EMD clarification of prelube requirements and 1 SCHROEDER, C W Commonwealth Edison Co 83/04/26 SCHWENCER, A Licensing Branch 2 3pp 18265 274 24X Fiche 50-373,83/04/26, 8304290034
- 8303030161 Confirms discussion w/A Bournia changing effective date for proposed Tech Spec re radiation chemistry technician qualification requirements to 830305
 8CHROEDER: C W Communwealth Edison Co 83/04/27 8CHWENCER: A Licensing Branch 2 ip 18300 269 24X Fiche 50-373, 83/04/27, 8303030161.
- 8305020455 Ceneric Ltr 83-19 to all power reactor & testing licensees re new precedures for providing public notice concerning issuance of amends to OLs Svc list encl EISENHUT.D 0 Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455
- B303110082 Forwards "Test Rept on Verification Testing of Beparation Between Class IE & Non-Class IE Power Cables in Raceways "Written confirmation of closure of License Condition 2 C (24) requested BCHROEDER: C W Commonwealth Edison Co 83/05/03 BCHWENCER: A Licensing Branch 2 2pp 18397 239 24X Fiche 50-373,83/05/03,8303110082.
- --RIGG1100B9 "Test Rept on Verification Testing of Beparation Between Class IE & Non-Class IE Power Cables in Raceways "
 HAZELTINE, J. JOHNSON F., ROBERTS, W. Wyle Laboratories 46511-3
 83/03/28 181pp 16397 241 24X Fiche 50-373,83/03/03,
 83051100B2
- 8305110171 Forwards safety evaluation on drywell to wetwell vacuum breaker valve mods to withstand suppression pool swell phase of LOCA Mods acceptable
 BCHMENGER.A Licensing Branch 2 83/05/03 FARRAR,D L.
 Commonwealth Edison Co 2pp 18434 236 24X Fiche 50-373,83/05/03,83/03/10171
- --B305110175 Bafety evaluation on drywell to watwell vacuum breaker valve mods to withstand suppression pool swell phase of LOCA Mods acceptable * NRC - No Detailed Affiliation Given B3/05/03 3pp 18434 236 24X Fiche; 50-373, 83/05/03, 8305110171

- 8305120580 Forwards Amend 14 to License NPF-11, safety evaluation & notice of 1ssuance & availability Amend deletes License Condition R C (26) & incorporates licensee approved alternative to Rad/Chem technical qualifications SCHWENCER, A Licensing Branch 2 83/05/05 FARRAR, D L Commonwealth Edison Co 3pp 18441 319 24X Fiche 50~373,83/05/05,8305120580
- --8305120585 Amend 14 to License NPF-11 deleting License Condition 2 C (26) & changing Tech Specs to incorporate licensee approved alternative to Rad/Chem technical qualifications RIBERNUT. D © Division of Licensing 83/05/05 6pp 18441 322 24X Fiche 50~373.83/05/05.8305120580
- ~~8305120589 Safety evaluation supporting Amend 14 to Licanse NFF-11 * Office of Nuclear Reactor Regulation, Director 83/05/05 2pp 18441 328 24% Fichs 90-373.83/05/05,8305180580
- --8305120593 Notice of issuance 2 availability of Amend 14 to License NPF-11 SCHWENCER, A Licensing Branch 2 83/05/05 3pp 18441 330 24X Ficha 50-373,83/05/05,8305120580
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enr!
 EISENHUT, D 0 Division of Licensing 83/05/07 Consolidated Edison Co of New York, Inc 16pp. 18627 153 24X Fichs 50-000.83/05/09/3830590659
- 8305170477 Confirms 830512 enforcement conference in Olen Ellyn IL w/util to discuss programmatic deficiencies identified in surveillance testing program NORELIUS, C E Division of Project & Resident Programs 83/05/09 REED. C Commonwealth Edison Co ip 18470 085 24X Fiche 50-373,83/05/09.6305170477
- B305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0874) Supporting documentation encl REED.C Commonwealth Edison Go 83/05/11 DENTON, H R Office of Nuclear Restor Regulation, Director 10pp 18521 085 24X Fiche 50-000.83/05/11.8303200621
- --B305200637 "Energy, Inc/Fergusan, Inc. Audit Rept of Sargent & Lundy for Comm Ed" CURRAN, R N. HARRIS, R J Energy Incorporated FEROUSON, R N Fergusan, Inc. B2/07/06 65pp 18521 095 244 Fiche 50~000,83/05/11.8305200621
- --8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects" * Commonwealth Edison Co 82/11/17 350pp 18521 160 24X Fiche 50-000.83/05/11.8305200621
- --8305200555 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment MARCUS.Q F Commonwealth Edison Co 81/10/06 6pp 18522 150 24X Fich# 50-000.83/05/11.8305200621
- --8305200665 Rept of B30307-15 audit to evaluate Sargent & Lundy GA program implementation & afequacy of facility design SUMMERFIELD.T. MARCUS.G.F. Commonwealth Edison Co. 83/03/23 18pp 18582 156 24% Fiche 50-000.B3/05/11
- --8305200675 Rept of 820607-ii audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
 MARCUS.O F Commonwealth Edison Co 82/06/17 48pp 18522 174
 24% Fiche 50-000.83/05/11.8305200621
- ---8305200681 Rev 3 to "Interface Control Agreement, Westinghouse Piping & Structural Evaluation Program for Byron Station Unit 1 "

 * Westinghouse Electric Corp * Commonwealth Edison Co *
 Sargent & Lundy, Inc. 82/10/27 19pp 18527 221 24x
 Fichs 50-000:83/05/11.8305200621
- --B3052004B3 Rev C to Procedure 3 0 4. "Design Control New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl WHITAKER, W A Nuclear Power Services. Inc B2/11/23 iBpp 18522 241 24X Fiche 50-000,83/05/11,8305200621
- --8305200A84 Advises that Wastinghouse GA program implementation described in WCAP-8370. Rev 9A, satisfactory SEYFRIT. K V Region 4. Dallas, Office of the Director (81/03/01) 81/04/30 SLEMBER, R J Westinghouse Electric Corp 2pp 18522 259 24X Fiche 50-373,83/05/11,8305200621

- --8305200688 Rev O to "Auxiliary Feeduater Sys Design Review Rept " Util GA statement re verification of adequacy of design & const of Byron Unit 1 enc! HATTELET.P L , MEISTER.J R , BRAEGER.C B Sargent & Lundy, Inc DRR-AF-001-88 ROO 80/07/16 84pp 18522 303 24X Fiche 50-000, 83/05/11, 8305200621.
- --830520049: "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed " BIGBEE, D : CURRAN, R N : FARMAN, R F Energy Incorporated, 83/04/04 127pp 18523 027 24X Fiche 50-000, 83/05/11; 8305200621
- 8305200015 Responds to util 830407 request to change Tech Specs allowing dilution flow blowdown determination by position of regulating valve Request unacceptable Flow rate estimate still vulnerable to uncertainties NOVAK.T H Division of Licensing 83/05/17 FARRAR.D L Commonwealth Edison Co 3pp 18528 360 24x Fiche 50-373.83/05/17.830550015
- 8305230584 Submits editorial rev to Specific Action 10 per 821228 response to Generic Ltr 81-04 re measures to minimize intergranular stress corrosion cracking General & specific corrective actions discussed NUREC-0913 compilance achieved SCHROEDER.C W Commonwealth Edison Co 83/05/19 LAINAG.C Licensing Branch 2 4pp 18537.313 24X Fiche 50-373,83/05/19,8305230584
- 8305240110 Forwards Tables 3 9 4 & 3 9-4A comparing NRC fuel assembly load combinations in horizontal plans vertical plans & design basis loads Encl tables will be included in FSAR Amend 63 to be submitted by 830630 SCHROEDER.C W Commonwealth Edison Co 83/05/19 SCHWENCER.A Licensing Branch 2 App 18548 343 24X Fiche 50-373,83/05/19,8305240110
- B305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in EE Insp Repts 30-434/83-06 & 30-453/83-0D Actions will be decided during pipe whip restraint energy absorbing mati tests.

 SPESSARD.R L Division of Engineering. 83/05/24 REED, C Commonwealth Edison Co. ip 18644 087 24X Fichs 50-000, 83/05/24, 8305270476
- --8305270501 Rev 1 to "Evaluation of Three Legged Pipe Whip Restraint Sys" "AAJ S , YANO.M S , AMIN.M Sargent & Lundy, Inc 8 15 1-0 RO1 82/09/21 47pp 18644 099 24X Fiche 50-000,83/05/24,8305270476
- 8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util BCRDR program plan OTLBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 244 Fiche 50-000, 83/05/26, 8305310086.
- Q Inspection reports, IE Bulletins & correspondence
- 8305170005 Final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/aster(st available in PDR. App B.C.D & E documents withheld (ref FDIA Elemption 7) FELTON, J M Division of Rules and Records 83/03/11 PRENDERGAST.R Prendergast.R J 17pp 18506 059 24X Fiche. 50-000,83/03/11.8305170005
- --8305190045 Requests vendor insplot facilities having contracts w/Zack Co due to GA/GC problems at Midland re HVAC activities Zack Co correspondence re LaBalle & related info enci FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/04/21 POTOPOUS.V Region 4. Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000,83/03/21. 8305190005
- --8305190050 Summarizes 820430 mesting w/president of Zack Co. HVAC contractor at facilities; ra potential allegations, Zack Co planning to terminate several employees in document control section
 HAYES, D. H. Region 3, Office of Director 82/05/12 Region 3
 Office of Director. ip 18505,089 24x Fiche 30-000,83/03/11.8305190005
- -8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast * Radio TV Reports. Inc 82/07/24. NRC No Detailed Affiliation Given 2pp 18506-124 24X Fiche 50-000.83/03/11.8303190005

- --8305190097 Requests investigation of Region III inadequate investigative oversight re GA breakdown & possible criminal falsification at Zack Co.HVAC contractor at facilities AY Howard & S Marello allegations discussed DEVINE, T Government Accountability Project 82/07/26 PALLADINO, N. Commissioners 11pp 18506:128 24% Fiche 50-000,83/03/11,8305190005
- --8305170102 Affidavit of SL Marello re GC breakdown & criminal falsification at Zack Co. MVAC contractor at facilities MARELLO, SL Affiliation Unknown 82/07/26 22pp 18306 J3g 24X Fiche 50-000, 83/03/11.8305190005
- --8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zeck Co. MVAC contractor at facilities HOHARD. A T Affiliation Unknown 82/07/26 55pp 18306,160 24% Fiche: 50-000,83/03/11,8305190005.
- --8305190119 Repts investigation re-possible flawed equipment at facilities, per Eyewitness News broadcast + Radio TV Reports: Inc 82/07/26 NRC No Detailed Affiliation Oliven 2pp 18507-145 24X Ficher 30-000, 83/03/11, 8305190005
- --8305170124 Offers assistance & cooperation in investigating Tack Co Suggestions discussed DEVINE, T : QARDE, 8 P Government Accountability Project 82/07/27. PALLADING, N J Commissioners 2pp 18507-167 241 Fiche 50-000,83703/11,8305190005
- --8305190128 Forwards outline of investigation rept re Zack documintation concerning HVAC activities Discussion of mall spac & mechanical properties for galvanized sheet steel & stiffener hanger & support steel & L DelOeorge handwritten notes enci NORELIUS, C & Region 3, Office of Director 82/07/28. KEPPLER, J Q , DAVIS, A B , FOBTER, J Region 3, Office of Director, 25pp 18507 169 24X Fiche 50-000,83/03/11,8305190005
- --B305190151 Informs of atty general of Btate of IL intention to eliens NRC 820811 meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations
 VAN VRANKEN, J. Illinois, State of 82/08/09, KEPPLER, J. 0 Region 3, Office of Director ip. 18507.209 24X Fiche 50-000,83/03/11,8305190005
- --B305170162 Introduction of 820811 public meeting to discuss util plant re employment of third party contractor to conduct independent review of HVAC sys at facilities. A NRC - No Datailed Affiliation Given. 82/08/11 2pp 18507 214 24X Fiche 50-000,83/03/11,8305170005.
- --8305190167 Requests that all interested parties be furnished propositic contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized VAN VRANKEN, J. Illinois, State of 82/08/12, KEPPLER, J. 9 Region 3. Office of Director 20p 18507-215, 24% Fichs 50-000.83/03/11.8305190005
- --8305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & B Marello experience & knowledge be utilized in review process Util BZ0913 ltr to CF Braun & Go enci HONARD. A. T Affiliation Unknown. 82/08/13 KEPPLER. J. 9. Region 3. Office of Director lipp 18507;216 24X Fiche 50-000,83/09/11.8305190003
- --8305190184 Confirms 820812 telcon re telephone cell from M Cherry concerning Zack investigation & circumstences surrounding termination of Zack enployees DAVIG.A 8 Region 3. Office of Director 82/08/16 FITZGERALD./ Office of Investigation 2pp 18507 230 24X Fiche 50-000,83/03/j1,8305190005
- --8305190189 Notification of 820824 meeting w/util in Olen Ellyn, IL to discuss status of licensee independent HVAC review Region 3, Office of Director 82/08/18. Region 3, Office of Director 62/08/18. 86300 3/03/11, 8303190005
- --8305190283 Introduction of 820824 public meeting to discurs util preliminary plans re independent review of HVAC sys at facilities Meeting will focus on GF Breun technical proposals.

 a NRC No Detailed Affiliation Given 83/08/24, ip 18507-266 24X Fichm. 50-000/83/03/11.8305190005

- --8305190292 Advises that AT Howard & 88 Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co, subj to listed conditions Related info encl.

 DEVINE.T. Government Accountability Project 82/08/13

 XEPPLER.J. Region 3, Office of Director 16pp 18507 294 24X Fiche 50-000,83/03/11.8305190003
- --8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities CF Braun should rept directly to NRC & should audit all critical areas at facilities MARELLO, B L. Affiliation Unknown 82/08/16 KEPPLER. J Region 3, Office of Director 3pp 18507 313 24X Ficha 50-000. 83/03/11,8305190005.
- --8305190304 Discusses concerns on behalf of AT Howard & B Marello, for NRC consideration in review of CF Braun final proposal to conduct independent review of HVAC sys at facilities.per 820824 meeting.

 DEVINE.T. Government Accountability Project 82/09/04
 KEPPLER.J.Q Region 3, Office of Director 6pp 18307 345 24X
 Fiche 30-000,83/03/11,8305190005
- --8305190329 Responds to 820904 1tr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taken into consideration in NRR review of proposal KEPPLER, J 9 Region 3, Office of Director 82/09/13 DEVINE, T Government Accountability Project 1p 18507 357 24X Fiche: 50-000, 83/03/11, 8305190005.
- --8305190384 Advises that field insp of HVAC sys at facility completed, including review of Oovt Accountability Project allegations against Zack Co No technical basis exists for further restriction of facility power level. W/related info KEPPLER. J Q Region 3. Office of Director 82/12/03 DENYON H R Office of Nuclear Reactor Regulation, Director. 11pp 18512 038 24% Fiche 50-000,83/03/11,8305190005
- --8303190387 Rev 1 to "LeSalle County Station Technical Proposal," including scope of work, work plan to accomplish independent HVAC review, organization chart & resumes of personnel assigned to project List of matl specs for HVAC const encl e C F Braun & Co 82/08/25, 34pp, 18512:155 24X Fiche 50-000,83/03/11.8305190005
- --8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co GA program at facilities. Personally identifiable info deleted MORELIUB. C. E Division of Engineering 82/07/12 Division of Engineering. Ip 18512-323 24X Fiche 50-000, 83/03/11, 8305190005
- --8303190399 Handwritten notes re meeting w/util on allegations concerning Zack Co activities at facilities.
 DAVIS:A.B. NRC No Details Affiliation Given 82/07/16. 9pp 18512.335. 24X Fiche: 50-000.83/03/11.8305190005
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc).

 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Constidated Edison Co of New York, Inc 112pp 18308, 319 24X Fiche, 50-000, 83/03/21, 8212060385
- 8305090306 Add1 response to FOIA request for all records prepared at Region III, all invastigators involved in investigation of T Novard & B Morella allegations & all internal records reproblems distavered at facility Forwards App B documents FELTON.J M. Division of Rules and Records 83/03/22 GARDE, B Government Accountability Project. 2pp 18381:216 24X Fiche: 50-373, 83/03/22, 8305090306
- --8305090313 IE Investigation Repts 50-373/82-51 & 50-374/82-15 on B20721-1001. No noncompliance noted Major areas investigated followup on allegations re mail proceurement & GA deficiencies of HVAC sys installed by Zach Co LANKABURY, R. D., HEBTCOTT-H. M. Region 3, Office of Director 82/08/16 4pp, 18381;219, 24X Fiche 50-373,83/03/22,8305090306.
- 8304120409 Forwards IE Insp Rept 50-373/83-07 on 830215-0311.No noncompliance noted UTTLE:N. 8. Region 3. Office of Director. 83/03/23 REED.C. Commonwealth Edison Co. 2pp. 17932.150. 24X Fiche 50-373.83/03/23.8304120409.

- --8304120412 IE Insp Rept 50-373/83-07 on 830215-0311 No noncompliance noted Major areas inspected startup test results & previously opened items MAURA, F.A., REYEB, L.A. Region 3, Office of Director 83/03/23 4pp 17932 152 24X Fiche 50-373,83/03/23,8304120409
- 8305240087 Addi response to FDIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents

 FELTON, J M Division of Rules and Records 83/03/31 GARDE, B Government Accountability Project 2pp 18593 015 24X

 Fiche 50-373, 83/03/31, 8305240087
- --B30524009B Five draft summaries of affidavits & statements.draft comments on followup of allegations.minutes of Region III 820329,0419,0503 & 0706 staff meetings & draft investigation schedule Personally identifiable info deleted NRC No Detailed Affiliation Given 83/03/25 36pp 18593 018 24% Fische 50-373,83/03/31,8305240087
- --8305240125 Discusses actions planned during add1 insp to resolve concerns re adequacy of workmanship during const of masonry walls R Lipinski assistance requested to resolve issues starting wk of 820815

 8PE68ARD.R L Division of Project & Resident Programs 82/08/17
 EIEENHUT.D Q Division of Licensing 2pp 18573 054 24X
 Fiche 50-373.83/03/31.8305240087
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 135 24X Fiche 50-000, B3/04/15, B303040021
- 8303040023 IE Info Notice 63-22, "BWR Safety/Relief Valve Failures " 8vc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl \ JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B305020094 Confirms B30513 enforcement conference at Region III ofc in Olen Ellyn. IL to discuss programmatic deficiencies identified in surveillance testing program, per B30414 telcon NORRELIUS, C E Division of Project & Resident Programs B3/04/25 REED. C Commonwealth Edison Co ip 18278 247 24X Fiche 50-373,83/04/25,8305020094
- 8305120415 Forwards IE 1nsp Repts 80-373/83-13 & 50-374/83-03 on B30131-0421 No noncompliance noted LITTLE:W 5 Region 3, Office of Director 83/04/27 REED.C Commonwealth Edison Co 2pp 18434.080 24X Fiche 50-373,83/04/27, 8305120415
- --8305120420 IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncomptiance noted Major areas inspected as-built walkdown & review of procedures for structural steel items & socket weld cracks in main steam drain lines
 KEATINO, D E , CILIMBERO, R L , DANIELSON, D H Region 3, Office of Director 83/04/27, 6pp. 18434 082 24X Fiche 50-373, 83/04/27, 8305120415
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 30-000,83/04/28,8303040026
- 8303040027 IE Info Notice 33-25, "Standby Gas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,89/04/28,8303040027
- 830512043B Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124.26, 29, 1201.14 & 830414 & notice of violation SPESSARD.R L Division of Engineering 83/04/28 REED, C Commonwealth Edison Co 2pp 18431: 107 24X Fichs 50-373, 83/04/28, 830512043B
- --8305120443 Notice of violation from insp on 921124,26,29,1201,14 & 830414 SPESBARD, R L Division of Engineering, 83/04/28 3pp 19431 109 24X Fiche 50-373,83/04/28,8305120438.

- ~~8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29, 1201.14 & 830414 Noncompliance noted failure to unite nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices
 RAMSEY,C , ULIS, J , HASSG, R Region 3, Office of Director 83/04/27 19pp 18431 112 24X Fiche 50-373,83/04/20,8305120438
- 8305170398 Forwards IE Insp Repts 50-373/83-11 & 50-374/83-06 on R30307-0408 & notice of violation STREETER.JF Region 3. Office of Director 83/04/28 REED.C Commonwealth Edison Co 2pp 18469 232 24X Fiche 50-373,83/04/28,8305170398
- --8305170400 Notice of violation from these on 830307-0408. STREETER, J F Region 3. Office of Director 83/04/28 ip 18459 234 24% Fiche 50-373,83/04/28,8305170398
- --8305170403 IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 Noncompliance noted failure to have adequate preoperational test procedure to determine end-of-cycle recirculation pump trip sys response time LANKSBURY, R D., DUPONT, S O., REYES, L. A. Region 3, Office of Director 83/04/28, 5pp 18469 235 24X Fiche 50-373,83/04/28, 8305170398
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list and JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 839103) 83/05/03 Consolidated Edison Co. of New York. Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- ### 8305060542 Ack receipt of ### 830404 & 08 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10 ### 8305060542 ###
- --9305060554 Responds to NRC 830214 1tr re violations noted in JE Insp Repts 50-373/82-40 & 50-374/82-10 Corrective actions meetings & discussions held between GA general mgt & dept lead auditors General ofcs audited REED.C Commonwealth Edison Co 83/04/04 KEPPLER.J Ø Region 3. Office of Director. 17pp 16348 307 24X Ficher 50-373, 83/05/03, 8305060542
- --8305060569 Forwards revised Page 2 to response to moncompliance noted in IE Insp Repts 50-373/82-40 & 50-374/82-10.per NRC 830214
 ltr
 SCHROEDER.C W Commonwealth Edison Co 83/04/08 KEPPLER.J G
 Region 3. Office of Director 2pp 18348 325 24X
 Fiche 50-373,83/05/02.8303060542
- 8303040030 IE Info Natice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
 JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche. 30-200, 837057048303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDANIE L. Division of Emergency Freparedness & Engineering Response (Post 830103) 83705/04 Constit
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl. JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York Inc 115pp. 18523 248. 24X Fiche 50-000.83/05/06.8303040033
- 3305240241 Forwards IE Insp Rept 50-373/83-14 on 830329-0415 & notice of violation NORELIUS, C. E. Division of Project & Resident Programs 83/05/06 REED: C. Commonwealth Edison Co., 2pp 18548 287 24X Fiche 50-373,83/05/06,8305240241
- -8305240244 Notice of violation from insp on 830324-0415 NORELIUS.C E Division of Project & Resident Programs 83/05/06 2pp. 18548-289 24X Fiche 30-373,83/05/06,8305240241
- -8305240247 IE Insp Rept 50-373/83-14 on 830329-0415 Noncompliance noted failure to have adequate surveillance procedures & failure to perform required surveillance test within periodic time interval LANKSBURY, R D , GULDEMOND, W G , WALKER, R. D Region 3, Office of Director 83/05/06. 7pp. 18548 291. 24X Fichs 50-373,83/05/06,8305240241.

- 8305130139 Ack receipt of 830504 Itr informing NRC of steps talents correct violations noted in IE Insp Rept 50-373/82-47 Based on info supplied, second item of noncompliance remains violation

 SPESSARD. R L Region 3, Office of Director 83/05/10 REED, C Commonwealth Edison Co 1p 18436 001 24X Fiche. 50-373.83/05/13.8305130139
- --8305130144 Responds to NRC 830401 ltr re violations noted in lE [hij]
 Rept 50-373/82-47 Corrective actions instruction/review
 session by site project const superintendent stressed
 importance of procedure adherence
 FARRAR.D L Commonwealth Edison Co 83/05/04 KEPPLER,J 0
 Region 3, Office of Director 9pp 18436-002 24X
 Fiche 50-373,83/05/10,8305130139
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Ouidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of Mary York, Inc 114pp, 18524 003 24X Fiche 50-000,63/05/11,6303040034
- 8305170423 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Inep Rept 50-373/83-03
 MILLER.J R Region 3, Office of Director 83/05/12 REED.C Commonwealth Edison Co 1p 18469 290 24X Fiche 50-373.83/03/12.
- --8305170425 Responds to NRC 830389 ltr re violations noted in [E Safeguards Insp Rept 50-373/83-03 Corrective actions procedures used to test metal detectors & proposed change in description of metal detectors address & proposed change in description of metal detectors address & Datails withheld. FARRARS, D L. Commonwealth Edison Co. 83/04/19 KEPPLER, J @ Region 3. Office of Director ip 18469 291 24X Fiche 50-373,83/03/12,8305170423
- 8305260327 Forwards IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 & notice of violation STREETER.J.F Region 3. Office of Director 83/05/12 REED.C Commonwealth Edison Co 2pp 18625 120 24X Fiche 50-373.83/05/12.8305260329
- --8305260331 Notice of violation from insp on 830309-30. STREETER, J F Ragion 3, Office of Director 83/05/12 Ip 18625 122 24X Fiche 50-373,83/05/12,8305260329
- --8305260334 IE Insp Repts 30-373/83-15 & 50-374/83-13 on 830309-30 Noncompliance noted failure to follow mod package procedures HASSE,R A, CHOULES,N C, FARRELL,R E Region 3, Office of Director 83/05/11 14pp 18625 123 24X Fiche 30-373,83/05/12, 8305260329
- 8305240301 Ack receipt of 830404 & 26 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-55 & 30-378/82-33 Due to improvement of internal communications, smoother communication w/resident inspector expected NORELIUS, C E Division of Project & Resident Programs 83/05/17 REED. C Commonwealth Edison Co ip 18348 115 24% Fiche 30-373,83/05/17,8305240301
- --830524030B Responds to NRC 830223 ltr re violations noted in IE Insp. Repts 50-373/82-35 & 50-374/82-33 Corrective actions onsite review conducted on 830316 & included discussion of possible broad implications of noncompliance FARRAR, D i. Commonwealth Edison Co. 83/04/04 KEPPLER, J O. Region 3. Office of Director 8pp 18548 116 24X Fichs 50-373/83/05/17,8305240301
- --8305240315 Supple response to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions: dept heads to prepare memo to station superintendent summerizing any potential noncompliance FARRAR, D L Commonwealth Edison Co. 83/04/26 KEPPLER, J & Region 3, Office of Director 2pp 18548 124 24% Fichs 50-373, 83/05/17, 8305240301
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "

 Bya list encl

 JGRDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103), B3/05/17 Consolidated Edison Co of New

 York, Inc 114pp 18697 009 24X Fiche.50-000.83/05/19.8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated U11 " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co. of New York, Inc. 114pp. 18647 007 24X Fiche 30-000,83/05/26,8303040048

- R Periodic operating reports & related correspondence
- 8303040365 Forwards errata to Part 2 of "Operating Rept of Radioactive Effluents for Jul-Dec 1982"
 DIEDERICH 9 J Commonwealth Edison Co 83/04/19 KEPPLER, J G Region 3, Office of Director 1p 18323 198 24X
 Fiche 50-373,83/04/19,8303040365
- --B305040371 Errata to Part 2 of "Operating Rept of Radioactive Effluents for Jul-Dec 1982" -- Commonwealth Edison Co 83/04/19 App 18323 199 24X Fiche 50-373,83/04/19.8305040365
- 8305110447 Forwards monthly operating rept for Apr 1983 DIEDERICH O J Commonwealth Edison Co 83/05/05 Office of Resource Management, Director 1p 18405 073 24X Fiche 50-373,83/05/05,8305110447
- --9305110452 Monthly operating rept for Apr 1783 LIN.D L Gommonwealth Edison Co 83/05/05 13pp 18405 074 24X Ficha 50-373,83/05/05,8305110447
- S Reportable occurrences, LERs & related correspondence
- 8305190005 Final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FDIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDERGAST.R Frendergast, R J 17pp 18506 059 24X Fiche. 50-000.83/03/11,8305190005
- --B305190084 RD fire dampers supplied by American Warming & Ventilation, Inc declared inoperative Caused by discrepancy in fuse link assembly size Fuse assemblies will be replaced JV Winkle Itr re news telecast & J Dierbeck note encl HOCLYOAK, R H. Commonwealth Edison Co B2/07/01 KEPPLER, J G Replon 3. Office of Director 33pp 18506 091 24X Fiche 50-000.83/03/11,8305190005
- --8305190112 Deficiency rept re errors & discrepancies contained in HVAC mat1 certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21 CALKINS, D. E. Zack Co. 81/10/23 310pp 18506 215 24X Ficha 50-000, 83/03/11, 8305190005
- --BS05190393 Discusses Zack Co Part 21 rept re duel traveler record sys for fabrication of duct work & hangers at facility.per B20729 telcon w/L DelDeorge & C Reed AT Howard resume encl HILLIAMB.C. C NRC - No Detailed Affiliation Givon B3/03/11 LANKBBURY.R D NRC - No Detailed Affiliation Given 6pp 18512-317 24X Fiche 50-000.83/03/11.8305190005
- 9305020351 Forwards LER 93-026/03L-0 DIEDERICH.G J Commonweelth Edison Co 83/04/13 KEPPLER, J 0 Region 3. Office of Director to 18274 120 24X Fiche: 50-373, 83/04/13, 8305020351,
- --8305020353 LER 83-026/03L-0 on 830321, radwaste discharge process radiation monitor declared inoperable. Caused by high fixed level of background radiation Task force formed to resolve problems Equipment design under investigation ARAMD, J Commonwealth Edison Co. 83/04/13 Region 3, Office of Director 2pp 18274 121 24x Fiche 50-373, 83/04/13, 8305020351.
- B305020205 Forwards LER B3-027/03L-0 DIEDERICH, G. J. Commonwealth Edison Co B3/04/15 KEPPLER, J Q Region 3. Office of Director 1p. 18278 189 24X Fiche 50-373, B3/04/15, B305020205
- --8305020234 LER 83-027/03L-0 on 830320, steam leak on main turbine control valve i stem seel leakoff line ITD20AA 1-/2 inches discovered Caused by overlap of weldments Welds repaired. SPENCER.D. Commonwealth Edison Co 83/04/15 Region 3, Office of Director 2pp 18278 190 24X Fiche. 50-373, 83/04/15, 8305020205
- 8305020241 Forwards LER 83-028/03L-0 DIEDERICH 9 J Commonwealth Edison Co 83/04/15 KEPPLER, J 9 Region 9, UPfice of Director 1p 18277, 274 24X Fiche: 50-373, 83/04/15, 8305020241
- --8305020251 LER 83-028/03L-0 on 830320, steam leak discovered on offgas steam jet mir ejector 1A drain line to turbine bldg aquigment drains Caused by defective weldment Work Request L2380 generated to repair weldment SPENCER, D. Commonwealth Edison Co 83/04/15 Region 3, Office of Director, 2pp 18277-275 24x Fiche: 50-373, 83/04/15, 830502041.

- 8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping " BROWN, E J Reactor Operations Analysis Dranch 83/04/19 SEYFRIT, K V Reactor Operations Analysis Dranch ip 18541 342 24X Fiche 50-000,83/04/19,8305230573
- --8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWNE J Reactor Operations Analysis Branch 83/04/19 9pp 18541 349 24X Fiche 50-000.83/04/19,8305230573
- 8305020086 Forwards LER 83-030/03L-0 DIEDERICH: G J. Commonwealth Edison Co 83/04/21 KEPPLER: J 9 Region 3: Office of Director ip 18279 106 24X Fiche 50-373,83/04/21,8305020086
- --8305020090 LER 83-030/03L-0 on 830324, local leak rate test on CRD removal hatch double gasket seals incorrectly performed prior to startup Caused by personnel error Leak rate test reperformed & new Procedure LTS 100-8 initiated HOUSTON.R W Commonwealth Edison Co 83/04/21 Region 3, Office of Director 2pp 18279 107 24X Fiche 50-373,83/04/21, 8305020086
- \$305020109 Forwards LER 83-031/03L-0 DIEDERICH.0 J Commonwealth Edison Go 83/04/21 KEPPLER.J G Region 3. Office of Director in 18278 199 24X Fichs 50-373,83/04/21.8305020109
- --8305020114 LER 83-031/03L-0 on 830324, Validyne P232 flow transmitters installed near standby gas treatment failed environ qualification testing Caused by inappropriate location near high radiation levels Instruments will be relocated MARTINDVICH, M Commonwealth Edison Cb 83/04/21 Region 3, Office of Director 3pp 18278 200 24X Fiche 50-373,83/04/21,8303020109
- B305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LDCA hydrogen recombiners supplied by Rockwell Intl Initially reported on B30328 Matter under investigation Final rept by B30808 Reported per Part 21 MANNO.5 F Niagara Mohawk Power Corp B3/04/26 STAROSTECKI, R Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY. D C Rockwell International Corp 83/03/11 COLLINS, J T Region 4, Office of Director 3pp 18433 074 24X Fiche 50-000.83/04/28,8305120392
- B305040493 Forwards LER B3-031/03L-0 DIEDERICH: 0 J Commonwealth Edison Co 83/04/27 KEPPLER, J G Region 3: Office of Director ip 18348 096 24x Fiche 30-373, B3/04/27, B305040493
- ---B305040509 LER 83-031/03L-0 on 830331, turbine stop valve limit switch for reactor protection sys found out of spec Caused by improper alignment on initial installation Limit switch repositioned & new adjustable actuating arm installed MASTERSON.V V Commonwealth Edison Co 83/04/27 Region 3, Office of Director App 19348 097 24% Fiche 50-373,83/04/27. 8305060493
- 8305060398 Forwards LER 83-033/03L-0 DIEDERICH: 0 J Commonwealth Edison Co 83/04/28 KEPPLER. J 0 Region 3. Office of Director ip 18343 160 24x Fiche 50-373. 83/04/28, 8305560398
- --8305060401 LER 83-033/03L-0.on 830402, during hot shutdown radwaste effluent monitor declared inoperable Caused by high fixed level of background radiation Liquid radwaste PRM inner chamber coated w/acrylic resin to prevent radiation buildup ARAND. J Commonwealth Edison Co 83/04/28 Region 3. Office of Director 2pp 18343 161 24X Fiche 50-373,83/04/28,8305060398
- B305170374 Forwards LER B3-034/03L-0
 DIEDERICH: G J. Commonwealth Edison Co B3/05/03 KEPPLER, J G Region G. Office of Director ip 18469 208 24X
 Fithe 50-373, B3/05/03, B305170374
- --8305170378 LER 83-034/03L-0 on 83040B, during LIS-HP-10, level indicating switch IB21-M100A as-found setpoint exceeded Tech Spec value Caused by setpoint drift Switch setpoint recalibr HOUSTON,R W Commonwealth Edison Co 83/05/03 Region 3, Office of Director 2pp 18469 209 24% Fiche 50-373,83/05/03,8305170374

- 8305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attacked hold tags to 13 HVAC control panels w/defect Evaluation being conducted HALL-D P Illinois Power Co 83/05/04 KEPPLER, J G Region 3. Office of Director 2pp 18431 049 24X Fiche 50-000.83/05/04.8305120475
- --8305120484 Part 21 rept to defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformance rept will be issued for applicable sites
 FAUCONNEAU.0 Mark Controls Corp. 83/04/18 Director's Office. Office of Inspection and Enforcement 2pp 18431 051 24X Fichs 50-000.83/05/04.8305120475
- 8305170383 Forwards LER 83-035/03L-0 DIEDERICH 0 J Commonwealth Edison Co 83/05/04 KEPPLER. J 0 Region 3. Office of Director 1p 18469 213 24X Fiche 50-373,83/05/04,8305170383
- ~~8305170388 LER 83-035/03L-0 on 830406, offgas hydrogen analyzer 1A not maintaining proper vacuum & analyzer 1B not wired properly. Caused by dirty flame arrestor on analyzer A Flame arrestor cleaned Analyzer B rewired HOUSTON, R H Commonwealth Edison Co 83/05/04 Region 3, Office of Director. 2pp 18469 214 24X Fiche 50-373,83/05/04,8305170383
- 8305240229 LER 83-038/03L-0 on 830207, during performance of LIB-HP-09, head correction omitted from calibr test pressure, leaving instrument 1822-N013 out of tolerance Caused by misunderstanding of procedures W/830504 ltr
 TAYLOR, R, DIEDERICH, G.J. Commonwealth Edison Co 83/05/04.
 KEPPLER, J & Region 3, Office of Director 4pp 18348 311. 24X
 Fichs. 50-373, 83/05/04, 8305240229
- 8305240007 RG on B20715, ultraviolet fire detectors taken out of svc Due to continued const work, fire detectors to be out of svc until Fall 1983 fuel load DIEDERICH, G J Commonwealth Edison Co. 83/05/10 KEPPLER, J O Region 3. Office of Director 1p 18549 038 24X Fiche: 50-373, 83/05/10, 8305240007
- 8305240318 LER 83-036/03L-0 on 830414, welding Procedure: MP8 1-5-A & 5-5-A discovered in conflict w/ASME Code. Repairs to main steam drain line welds made using subg procedures Evaluation of procedures in process M/830504 itr SPENCER:D A DIEDERICH. 0. J Commonwealth Edison Co 83/05/10 REPPLER:J & Region 3, Office of Director 3pp 18548 075 24X Fiche 50-373.83/05/10.8305240318
- 8305240354 LER 83-037/03L-0 on 830421, while in cold shutdown liquid radwaste effluent process radiation monitor declared inoperable Caused by not performing acceptable source check due to high level of internal contamination th/830510 ltr.

 ARAND, J. DIEDERICH, G. J. Commonwealth Edison Co. 83/05/10 KEPPLER, J. G. Region 3, Office of Director. 3pp. 18575: 104 24: Fiche: 50-373, 83/05/10, 8305240354
- B305240381 LER B3-040/03L-0 on B30412, stack wide-range gas monitor mid-range noble gas recorder OD18-R521 produced unusual readings Caused by electronic noise Original power supply reinstabled in mid-range recorder W/B30511 ltr MASTERSON V DIEDERICH: G J Commonwealth Edison Co B3/05/10 KEPFLER: J. G. Region J. Office of Director 4pp 18549 341 24X Fiche 30-373.83/05/10.8305240381
- 8305240025 LER 83-041/03L-0 on 830414.steam leak in weld fittings on instrument line IMB798A-1 inch discovered Caused by insufficient weld matl Weld ground out & connections rewelded W/830511 ltr MATFORD.P 5 DIEDERICH.Q.J Commonwealth Edison Co 83/05/11 KEPPLER.J 0 Region 3, Office of Director 2pp 18549 052 24X Fiche 50-373,83/05/11,8305240025.
- 8305240334 NPDES noncompliance notification between 830411-17.composite sample k analysis not performed Caused by personnel error Personnel to be intructed on proper setup of composite sampler H/830512 ltr DIEDERICHO J Commonwealth Edison Co 83/05/12 KEPPLER, J & Region J. Office of Director 3pp. 18549 358 24X Fiche: 50-373,63/05/12,8305240334
- 8305240073 RO on 830424, during surveillance, smote observed coming out of dissel fire pump GA valve covers Pump shipped to manufacturer to determine cause of failure New dissel pump installed k testef DIEDERICH.0 J Commonwealth Edison Co. 83/05/13 KEPPLER, J G. Region 3, Office of Director. 1p. 18549 093. 24X Fiche 50-373,83/05/13,8305240073

- 8305240425 LER 83-039/03L-0 on 830418, during visual insp.mechanical snubbers found locked between hot & cold settings Causad by movement in excess of snubber travel range or defective snubber Snubber replaced W/830517 itr

 8PENCER.D A . DIEDERICH.Q J Commonwealth Edison Co 83/05/17

 KEPPLER.J O Region 3. Office of Director 3pp 18571 058 24X

 Fiche 50-373.83/05/17,8305240425
- B305270237 RO on B30322, scram occurred on low reactor water level. MPCS & RCIC sys auto initiated due to low reactor water level Caused by receiving rept of B flow control velve remping open on spurious signal DIEDERICH 0 J Commonwealth Edison Co B3/05/17 KEPPLER, J Q Region 3, Office of Director ip 19637 156 24X Fiche 30-373, 83/05/17, 8305270237
- 8305270195 LER 83-042/03L-0 on 830423, during MSIV bocal leak rats test. inboard MSIV found exceeding allowable leak rate of 25 SCFH Caused by less than perfect seating of disc & seat surfaces. Inboard MSIVs.discs & seats lapped & machined W/890320 Itr MASTERSON, V. DIEDERICH, O.J. Commonwealth Edison Co. 83/05/20 KEPPLER, J. Q. Region 3, Office of Director 4pp 18537;339 24% Ficks 50-373,83/05/20,8305270195
- DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8303190005 Final response to FOIA request for documents re Zack Co b/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C.D & E documents withheld (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11. PRENDEROAST.R Prendergast. R J 17pp 18506 059, 24X Fiche 50-000,83/03/11,8305190005
- --8208250505 Trip rept of 820802 audit reviewing saismic & qualification file for Zack Co equipment, at Sargent & Lundy Engineers ofc in Chicago, IL ROSETOCZY, Z R Equipment Qualification Branch 82/08/06 SCHWENCER, A Licensing Branch 2 8pp 18507, 201. 24X Fiche 50-000, 83/03/11, 8305190005
- --B305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removat welds Certain welds on Unit 2.Div II switchgear heat removal sys may not meet applicable code requirements HOLYOAX.R H Commonwealth Edison Co. B2/08/06. Region 3. Office of Director 1p 18507 200 24X Ficher 50-000.83/03/11: 8305199005
- --8305190302 Forwards Rev O to "Assessment of Stitch Weld Strength in HVAC Ductwork Const.LaSelle County Station Units 1 & 2 " QC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired POLLOCK, R H Sargent & Lundy, Inc 82/08/27 SHELTON, B R Commonwealth Edison Co 1p 18507 317 24X Fiche 50-000, 83/03/11,8305190005
- ---B305190303 Rev O to "Assessment of Stitch Weld Strength in HVAC Ductwork ConstituSalle County Station Units 1 & 2 " CHO.F.L., KIBISELIT T, MELIGI.A V Sargent & Lundy, Inc CGD-003490 ROO B2/0B/27 27pp 18307 318 24X Fiche 50-000,83/03/11,8303190003
- ---9305190332 Forwards "LaSalle County Station Independent HVAC Reviews" interim rept Rept also sent to JG Keppler KEMPIAK, A J. C F Braun & Co 82/09/15 BHELTON, B R Commonwealth Edison Co 1p 18507 359 24X Fichs 50-000. 83/03/11.8305190005
- --B303190353 Forwards TE Netts B21019 & 25 memos to CH Schroeder responding to R Lanksbury questions re HVAC ductwork design & transmitting Rev O to Project Instruction PI-L8-21, "Review of GC Documentation for LaSe11e County Station." SCHROEDER.C W Commonwealth Edison Co B2/10/27 KEPPLER, J G Region 3, Office of Director 7pp 18508 093 24X Fiche 50-000,83/03/11,8305190005
- --8305170357 Rev O to Project Instruction PI-LS-42, "Review of QC Documentation for LaBaila County Station Units 1 & 2 "
 Sargent & Lundy, Inc 82/10/21 9pp 18508 102 24X Fiche 50-000,83/03/11,8305190005
- --8305170365 Forwards Vols 1-4 to "Independent HVAC Review, LaBalle County Nuclear Plant," final rept KEMPIAK.A J C F. Braun & Co 82/10/27 SHELTON, B R Commonwealth Edison Co 1p 18508'111 24X Fiche, 50-000, 83/03/11, 8305190005

- --8305190367 Act receipt of CF Braun final rept of independent HVAC review at facilities PHILLIPS:R W Region 3, Office of Director 82/10/27 Region 3, Office of Director 1p 18308 112 24X Fiche 30-000,83/03/11,8305190005
- --B305i90379 Requests list of results of detailed calculations on rebar damage for 647 concrete elements affecting Unit 1 operation & approved CF Breun proposal for independent HVAC review Zact Co chronology encl
 QOODIE, J 8 Illinois, State of 82/09/07 KEPPLER, J Q Region 3. Office of Director 5pp 18511 278 24X Fiche 50-000, 83/03/11,8305190005
- --8305190390 P Donahue show Transcript 08302 re nuclear power safety Info re facilities & Zack Co encl e Multimedia Program Production, Inc 83/03/11 128pp 18912-189 24X Fiche 50-000.83/03/11.8305190005
- 8304290034 Requests documented acceptance of General Motors Electro-Motive Div (EMD) MI 9644 mod as acceptable alternative to diesel generator presube oil pump EMD clarification of presube requirements encl SCHROEDER: C W Commonwealth Edison Co 83/04/26 SCHWENCER, A Licensing Branch 2 3pp 18265 274 24X Fiche 50-373.83/04/26, 8304270034
- 8305110082 Forwards "Test Rapt on Verification Testing of Baparation Between Class IE & Non-Class IE Power Cables in Raceways " Written confirmation of closure of License Condition 2 C (24) requested, 6CHROEDER, C W Commonwealth Edison Co 83/05/03 SCHWENCER, A Licensing Branch 2 2pp 18397 239 24X Fiche 50-373,83/05/03,8305116082.
- --8305110089 "Test Rept on Verification Testing of Separation Between Class IE & Non-Class IE Power Cables in Receways " HAZELTINE.J., JOHNSON.F., ROBERTS, W Wyle Laboratories 46511-3 83703/28. 181pp. 18397: 241 24X Fiche 50-273, 83/05/03, 8305110082
- 8303070657 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list enci EISEMMUT.D. 9. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp. 18627 153 24X Fichs. 50-000, 83/05/09, 8305090659
- B305200621 Decuments review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FBAR & SER 4MRCO-0876). Supporting documentation encl REED.C. Commonwealth Edison Co. 83/05/11 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 10pp 18521 085 24% Fichs. 50-000, 83/05/11, 8305200621
- --B305200637 *Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed ** CARRAN, R N , HARRIS, R. J Energy Incorporated FEROUSON, R. N Farguson, Inc. B2/07/06 63pp 18521 095 24X Fiche. 30-000, 83/05/11, 8305200621
- --B305200665 Rept of B30307-15 audit to evaluate Sargent & Lundy GA program implementation & adequacy of facility design SUMMERFIELD.T., MARCUS, 0 F Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fichs 30-000.83/03/11,8305200621.
- --- B305200675 Rept of B20607-11 audit re Bargent & Lundy GA program implementation is evaluation of adequacy of mechanical, electrical & atructural design of facilities Related info sncl.

 MARCUS, G. F. Commonwealth Edison Co. B2/06/17 48pp 18522 174 24X Fichs: 30-000, 83/05/11, 8305200621
- -8305200691 *Design Evaluation (Audit) Rept of Bargent & Lundy for Comm Ed. ** B109EE.D., CURRAN,R.N., FARMAN,R.F. Energy Incorporated, 83/04/04 127pp. 18523.027 24X Fiche 50-000,83/05/11, 8305200621
- 305230584 Bubmits editorial rev to Specific Action 10 per 821228 response to Generic Ltr 81-04 re measures to minimize intergranular stress corrosion cracking General & specific corrective actions discussed NUREO-0313 compliance achieved. SCHROEDER.C.W. Commonwealth Edison Co 83/05/19. LAINAS.O.C. Licensing Branch 2 4pp. 18537-313 24X Fiche-50-373.83/05/19. 8303230584.

- B305240110 Forwards Tables 3 9 4 & 3 9-4A comparing NRC fuel assembly load combinations in horizontal plane, vertical plane & design basis loads Encl tables will be included in FSAR Amend 63 to be submitted by B30630 SCHROEDER, C H Commonwealth Edison Co B3/05/19 SCHWENCER, A Licensing Branch 2 4pp 18548 343 24X Fichp 50-373, B3/05/19, B305240110
- 8305240111 Confirms 830513 telcon re schedule for installation of instrumentation for automatic scram to shut down reactor in event of low pressure scram in control rod drive sys
 SCHROEDER, C W Commonwealth Edison Co 83/05/19 SCHWENCER, A Licensing Branch 2 2pp 19548 347 24X Fiche 50-374, 83/05/19, 8305240111
- 8305270476 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing math tests

 SPESSARD.R L Division of Engineering 83/05/24 REED, C
 Commonwealth Edison Co. 1p 18644 OB7 24X Fiche. 50-000, 83/05/24, 8303270476
- ---8305270501 Rev i to "Evaluation of Three Legged Pipe Whip Restraint 84s" HAJS: YANO.M 8: AMIN.M Sargent & Lundy. Inc. 8: 15: 1-0: R01 82/09/21 47pp 18644 099 24% Fiche 50-000.83/05/24.8305270476
- 8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan GLBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 30-000, 83/05/26, 8305310086
- F Security, medical, emergency & fire protection plans
- 8305240087 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 itr re special safety insp of facility during May-Jul 1982 Forwards App C documents
 FELTON, J M Division of Rules and Records 83/03/31 OARDE, 8
 Oovernment Accountability Project 2pp 18593 015 24X
 Fiche 50-373,83/03/31,8305240087
- --8309230144 Recommends Unesorted access to protected areas for R Lipinski & 8 Chan Rapifac sheet transmitting evaluation of technical rapt. "Assessment of Effects of Nicked Rainforcing Steel." And the Effects of Proceedings Steel." And Effice of Director 82/06/14 REED, C Commonwealth Edison Co 7pp 18573 056 24X Fiche 50-373,83/03/31,8305240087
- 8305050402 Forwards request for add1 info re fire protection for safe shutdown, based on review of Amend 42 to FSAR
 SCHWENCER, A Licensing Branch 2 83/04/28 FARRAR, D L
 Commonwealth Edison Co 3pp 18352 046 24% Fiche. 50-373,83/04/28,8305050402
- 8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on B21124.26,29,1201,14 & 830414 & notice of violation BPESSARD,R L Division of Engineering 83/04/28 REED,C Commonwealth Edison Co 2pp 18431,107 24X Ficher 50-373,83/04/28,8305120338
- --8305120443 Notice of violation from insp on 821124,26,29,1201,14 & 830414

 SPESBARD,R L. Division of Engineering 83/04/28 3pp 18431 109 24X Fiche 50-373,83/04/28,8305120439
- --8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,27, 1201/14 & 830414. Noncompliance noted failure to write noncomformance repts & failure to comply w/10CFR50, App B. Criterion II re housekeeping practices RAMSEY.C.: WILLIAMS.C.C. Region 3. Office of Director 83/04/27 19pp 18431,112 24X Fiche 50-373,83/04/28,8305120438
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl
 EISENHUT,D 9. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034,
- B305130149 Ack receipt of B30419 ltr informing NRC of objectives & providing scenario outline for B30712 exercise PAPERIELLO,C,J Region 3. Office of Director, B3/05/11 REED,C Commonwealth Edison Co ip 18437-196 24X Fiche 50-373,83/05/11,8305130149

8305130155 Forwards list of objectives, scope of participation scenario outline & narrative summary for emergency exercise scheduled for 830712

BLACKMON.T G Commonwealth Edison Co 83/04/19 HIND.J

for B30712 BLACKMON.T G Commonwealth Edison Co B3/04/19 HIND.J Division of Emergency Preparedness & Operational Support 15pp 18437 157 24X Fiche 50-373.83/05/11.8305130149

Adjudicatory correspondence

305200481 Advises that time for Commission to review Director's Decision DD-83-1 expired Commission declined review Decision became final agency action on \$30506 CHILLS J Office of the Servetary of the Commission 83/05/19 HARTIGAN.N Illinois. State of HOREM.B t Friends of the Earth \$05001.E M Cititens Against Nuclear Power ip 18513 014 24X Fiche 50-373,83/05/19.8305200481

Inspection reports, IE Bulletins & correspondence

- 305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDERGAST.R Prendergast. R J 17pp 18506 059 24X Ficha 50-900.83/03/11.8305190005
- --8305190045 Requests vendor insplaf facilities having contracts w/Zack Co due to GA/GC problems at Midland re HVAC activities Zack Co correspondence re LaBalle & related info encl FIGRELLI.9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/21 POTOPOUS, U Region 4. Dallas. Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000.83/03/11.
- --8305170050 Summarizes 820430 meeting w/president of Zack Co. HVAC contractor at fecilities, re-potential allegations Zack Co-planning to terminate several employees in document control section
 HAYES, D.W. Region 3, Office of Director 82/05/12 Region 3
 Office of Director 1p 18506-089 24x Fiche 30-000, 83/03/11, 8305170005
- --8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast ** Radio TV Reports. Inc 82/07/24 NRC No Detailed Affiliation Given 2pp 18504 124 24X Fiche 50-000,83/03/11.8305190005
- ---8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co. HVAC contractor at facilities AT Howard & S Marello allegations discussed DEVINE. T Covernment Accountability Project 82/07/26 PALLADING, N J Commissioners lipp 18506 128 24X Fithe 50~000.83/03/11.8305190005
- ---8305190102 Affidavit of St. Marello re GC breakdown & criminal falsification at Zack Co. MVAC contractor at facilities MARELLO.S L Affiliation Unknown 82/07/26 22pp 18506 139. 24x Fichs 50-000.83/03/11.8305190005
- --8205190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co.HVAC contractor at facilities HOMARD.A T Affiliation Unknown 82/07/26 55pp 18506 160 24% Fiche 30-000,83/03/11,8305190005
- --8305190128 Forwards outline of investigation rept re Zack documentation concerning HVAC activities Discussion of matl spec & mechanical properties for galvanized sheat steel & stiffener hanger & support steel & L DelGeorge handwritten notes encl MORELIUB, C E Region 3, Office of Director 82/07/28 KEPPLER, J 9, DAVIS, A B, FOSTER, J Region 3, Office of Director 25pp 18507-149 24X Fiche 50-000,83/03/11.8305190005
- ~-B305190151 Informs of atty general of State of IL intention to attend NRC B20B1; meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations

 VAN VRANKEN, J Illinois, State of B2/08/09 KEPPLER, J G Region 3, Office of Director ip 18507 209 24X Fiche 50-000, B3/03/11, 8305190005

- --8305190162 Introduction of 820811 public meeting to discuss util plans re employment of third party contractor to conduct independent review of HVAC sys at facilities * NRC - No Detailed Affiliation Given 82/08/11 2pp 18507 214 24X Fiche 50-000,83/03/11,8305190005
- --8305190167 Requests that all interested parties be furnished proposed contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized VAN VRANKEN. J Illinois. State of 82/08/12 KEPPLER. J Q Region 3. Office of Director 2pp 18507 215 24X Fiche 50-000.83/03/11.8305190005
- --B305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & S Marello experience & knowledge be utilized in review process Util 820813 ltr to CF Braun & Co encl HOMARD, A T Affiliation Unknown 82/08/13 KEPPLER, J Q Region 3, Office of Director 11pp 18507 216 24X Fiche 50-000.83/03/11,8305190005
- ---B3051901B4 Confirms B20B12 telcon re telephone call from M Cherry concerning Tack investigation & circumstances surrounding termination of Tack employees DAVIS. A B Region 3. Office of Director B2/0B/16 FITZGERALD. J. Office of Investigation 2pp 18507 230 24X Fiche 50-000.83/03/11.8305190005
- --B3051902B9 Forwards T Devine B20B13 ltr.AT Howard B20B13 ltr & 88 Marello 820B16 ltr for NRR consideration in assessment of util proposal on third party review of HVAC sys at facilities

 SPESSARD.R L Division of Project & Resident Programs 82/08/25 EISENHUT.D G Division of Licensing 1p 18507 273 24X Fiche 50-000,83/03/11.8305190005
- ---B305190292 Advises that AT Howard & 88 Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co. subj to listed conditions Related info encl
 DEVINE, T Government Accountability Project B2/08/13
 KEPPLER, J Region 3, Office of Director 16pp 18507 294 24X
 Ficas 50-000, 83/03/11, 8305190009
- --8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities CF Braun should rept directly to NRC & should audit all critical areas at facilities MARELLO.S L. Affiliation Unknown 82/08/16 KEPPLER.J Region 3. Office of Director 3pp 18507 319 24X Fiche 50-000, 83/03/11.8305190005
- ---B305190304 Discusses concerns on behalf of AT Howard & 8 Marello, for NRC consideration in review of CF Braun final proposal to conduct independent review of HVAC sys at facilities, per B20824 meeting
 DEVINE.T Government Accountability Project B2/09/04
 KEPPLER.J G Region 3, Office of Director 6pp 18507 345 24X
 Fiche 50-000, 83/03/11, 8305190005
- --8305190327 Responds to 820904 ltr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taken into consideration in NRR review of proposal KEPPLER. J G Region 3. Office of Director 82/09/13 DEVINE. T Government Accountability Project ip. 18507 357 24X Fiche 50-000,83/03/11,8305190005

- --8305170399 Handwritten notes re meeting w/util on allegations concerning Zack Co activities at facilities DAVIE.A B NRC No Detailed Affiliation Olven 82/07/16 9pp. 18512 335 24X Fiche 50-000, 83/03/11, 8305190005

- 8305120346 Forwards IE Insp Rept 50-374/83-07 on 830224-25 No noncompliance noted PAPERIELLO: O J Region 3, Office of Director 83/03/16 REED,C Commonwealth Edison Co 2pp 18433 064 24X Fiche 50-374,83/03/16, 8305120346
- --B305120353 IE Insp Rept 50-374/83-07 on B30224-25 No noncompliance noted Major areas inspected organization radiation protection procedures, facilities, instruments & equipment & progress of certain sys demonstrations & tests MILLER.D E , GREGER, L R. Region 3, Office of Director B3/03/14 5pp. 18433 066 24X Fiche 50-374.83/03/16,8305120346
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83703/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fichs 30-000,83/03/21,8218060385
- 8305090306 Addl response to FOIA request for all records prepared at Region III.all investigators involved in investigation of T Howard & B Morella allegations & all internal records reproblems discovered at facility Forwards App B documents. FELTON, J M Division of Rules and Records 83/03/22 QARDE, B Government Accountability Project 2pp 18381 216 24X Fiche 50-373,83/03/22,8305090306
- --8305090313 IE Investigation Repts 50-373/82-51 & 50-374/82-15 on 820721-1001 No noncompliance noted Major areas investigated followup on allegations re mat1 proceurement & GA deficiencies of HVAC sys installed by Zach Co LANKSBURY, R D , WESTCOTT, H M Region 3, Office of Director 82/08/16 4pp 18381-219 24X Fiche 50-373,83/03/22,8305090306
- 8305240087 Add1 response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
 FELTON, J M Division of Rules and Records 83/03/31 GARDE, 8 Government Accountability Project 2pp 18593 015 24X
 Fiche 50-373,83/03/31,8305240087
- ---B303240098 Five draft summaries of affidavits & statements, draft comments on followup of allegations, minutes of Region III 820329, 0419, 0503 & 0706 staff meetings & draft investigation schedule Personally identifiable info deleted NRC No Detailed Affiliation Given 83/03/25 36pp 18593 018 24X Fiche 50-373, 83/03/31, 8303240087.
- --8305240i25 Discusses actions planned during add1 insp to resolve concerns re adequacy of workmanship during const of mesonry walls R Lipinski assistance requested to resolve issues starting wk of 820815
 SPESBARD, R L Division of Project & Resident Programs 82/08/17 EISENHUT, D 0 Division of Licensing 2pp. 18593:054 24X Fiche, 50-373, 83/03/31, 8305240087
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"

 Bvc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435.155 24X Fiche 50-000,83/04/13,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Bafety/Relief Valve Failures."
 8vc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- B30304002P IE Info Notice B3-23, "Inoperable Containment Atmosphere Sansing Bys " Svc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/04/25 Consolidated Edison Co of New York, Inc. 119pp. 18381 291 24X Fiche 30-000, B3/04/25, B303040025
- 8305120341 Forwards IE Insp Rept 50-374/83-ii on 830322-25 & 29 & 30 & notice of violation.
 LITTLE.W. 8 Region 3, Office of Director 83/04/26 REED.C
 Commonwealth Edison Co 2pp 18431:136. 24X Fiche 50-374.83/04/26, 8305120
- --8305120364 Notice of violation from insp on 830322-25 & 27 & 30 LITTLE, W. 8 Region 3, Office of Director 83/04/26 ip 18431.138 24% Fiche.50-374,83/04/26,8305120361.
- --8305120368 IE Insp Rept 50-074/83-11 on 830322-25 & 29 & 30 Noncompliance noted, failure to translate FBAR requirements into instructions & procedures to establish separation of cables belonging to different reactor protection sys. NAIDU.K R., AHMEDI., WILLIAMS, C.C. Region 3, Office of Director 83/04/22, 7pp 18431 139, 24% Ficha.50-374,83/04/26,8305120361

- B305120415 Forwards IE Insp Repts 50-373/B3-13 & 50-374/B3-03 on B30131-0421 No noncompliance noted LITTLE, W S Region 3, Office of Director Commonwealth Edison Co 2pp 18434 080 24X Fiche 50-373,83/04/27,8703120415
- --8305120420 IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncompliance noted Major areas inspected as-built walkdown & review of procedures for structural steel items & socket weld cracks in main stram drain lines KEATING.D E . CILIMBERG.R L . DANIELSON,D H Region 3, Office of Director 83/04/27 App 18434 082 24X Fiche 50-379.83/04/27, 8305120415
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Bide of Bteam Generators at PWRs " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDÁN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/2B Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/2B,8303040027
- 830512043B Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,27,1201,14 & 830414 & notice of violation SPESSARD,R L Division of Engineering 83/04/28 REED,C Commonwealth Edison Co 2pp 18431 107 24X Fichs 50-373,83/04/28,830512043B
- --8305120443 Notice of violation from insp on 821124,24,29,1201,14 & 830414
 SPESSARD,R L Division of Engineering 83/04/28 3pp 18431 109 24X Fiche 50-373,83/04/28,8305120438
- --8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124.26,29, 1201.14 & 830414 Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50.App B. Criterion II re housekeeping practices RAMSEY, C. ULIE, J. HABSE, R Region 3. Office of Director 83/04/27 19pp 18431 112 24X Fiche 50-373,83/04/28,8305120438
- 830517039B Forwards IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 & notice of violation 8TREETER, J F Region 3, Office of Director 83/04/28 REED, C Commonwealth Edison Co 2pp 18469 232 24X Fiche 50-373,83/04/28,8305170398
- --8305170403 IE Insp Repts 50-373/83-11 & 50-374/83-04 on 830307-0408 Nancompliance noted failure to have adequate preoperational test procedure to determine end-of-cycle recirculation pump trip sys response time

 LANK8DURY.R D , DUPDNT.8 G , REYES.L A Region 3, Office of Director 83/04/28 Spp 18467 235 24X Fiche 50-373.83/04/28, 8305170398
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York; Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- B305060542 Ack receipt of B30404 & 08 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/B2-40 & 50-374/B2-10 BPESSARD,R L Division of Engineering B3/05/03 REED,C Commonwealth Edison Co ip 18349 304 24X Fiche 50-373,83/05/034,8305060542
- --8305060554 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10 Corrective actions meetings & discussions held between OA general mgt & dept lead auditors General ofcs audited REED.C Commonwealth Edison Co 83/04/04 KEPPLER, J O Region 3, Office of Director 17pp 18348 307 24X Fiche 50-373,83/05/03,8305060542
- --8305060569 Forwards revised Page 2 to response to noncompliance noted in IE Insp Repts 50-373/82-40 & 50-374/82-10, per NRC 830214 ltr SCHROEDER, C H Commonwealth Edison Co 83/04/08 KEPPLER, J, G Region 3, Office of Director 2pp 18348 325 24X Fiche 50-373,83/05/03,8305060042
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York. Inc. 112pp 18382 282 24X Fiche 50-000-83/05/04,8303040030.

- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E. L. Divisson of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B301031 B3/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24% Fiche.50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list enc!
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303170322 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-374/83-05 SPESSARD.R L Division of Engineering 83/05/11 REED, C Commonwealth Edison Co 1p 18465 232 24X Fiche 50-374,83/05/11,8305170322
- --8305170331 Responds to NRC 830405 ltr re violations noted in IE Insp Rept 50-374/83-05.Corrective actions requirement for tasting LPCS sys excess flow check valve incorporated into nuclear boiler Preparational Test PT-NB-201. FARRAR.D L Commonwealth Edison Co 83/05/04 KEPPLER.J 0 Region 3. Defice of Director 6pp 18465 233 24X Fiche 50-374.83/05/11.8305170322
- 8305260327 Forwards IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 & notice of violation 8TREETER.J F Region 3. Office of Director 83/05/12 REED.C Commonwealth Edison Co 2pp 18825 120 24% Fiche 50-373.83/05/12. 8305260329
- --8305260334 IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 Noncompliance noted failure to follow mod package procedures HASSE.R A , CHQULES.N C , FARRELL.R E Region 3. Office of Director. 83/05/11 16pp 18625 123 24X Fichs.50-373.83/05/12, 8303260327
- B305240301 Act receipt of B30404 & 24 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-35 & 50-378/82-33 Due to improvement of internal communications, smoother communication w/resident inspector spected NORELIUS.C E Division of Project & Resident Programs. B3/03/17 REED.C Commonwealth Edison Co ip 18548 ii5 24X Fiche 30-373.83/05/17.830524030!
- --8305240308 Responds to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions onsite review conducted on B30316 & included discussion of possible broad implications of noncompliance PARRAR.D L Commonwealth Edison Ca 83/04/04 KEPPLER.J G Region 3. Office of Director 8pp 18548 116 24X Fiche 50-373,83/05/17,8305240301
- --8305240315 Supple response to NRC B3D223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions dept heads to prepare memo to station superintendent summarizing any potential honcompliance FARRAR, D L. Commonwealth Edison Co. B3/04/26 KEPPLER, J G Region 3. Office of Director 2pp 18548 124 24X Fiche, 50-373, 83/05/17, 8305240301
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18677 009 24X Fiche 50-000, B3/05/19, B303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Gil." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26.8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305190005 Final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents documents documents with a facilities forwards PDR App B.C.D & E documents withheld (ref FDIA Exemption 7) FELTON.J M Division of Rules and Records. 83/03/11 PRENDEROASTAR Prendergast, RJ 17pp. 18506 059 24X Fiche 30-000,83/03/11,8305190005

- ---8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/GC personnel will be added Also reportable per Part 21 CALKINS, D E Zack Co 81/10/23 310pp 18506 215 24X Fiche 50-000.83/03/11.8305190005
- 6305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LUCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI.R Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000.83/04/26.8305120392
- --8305120404 Part 21 rapt re failure of post-LDCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T. Region 4, Office of Director 3pp 18433 074 24X Fiche 50-000.83/04/26,8305120392
- 8305100018 Interim Deficiency Rept 83-01 re temp offset problems experienced w/Riley temp switches installed in leak detection sys Calibr procedure modified & switches recalibr Final rept will be submitted by 830601.

 * Commonwealth Edison Co 83/05/02 KEPPLER, J G, Region 3, Office of Director ip 18377 152 24X Fiche 50-374,83/05/02,8305100018
- 8305100352 Updated interim deficiency rept re offset & module problems of Riley temp indicating switches in leak detection sys Calibr procedure modified Final resolution of module problem (hardware mod) in progress Final rept expected by 830601 SCHROEDER.C W Commonwealth Edison Co 83/05/03 KEPPLER.J O. Region J. Office of Director ip 18379 092 24X Fiche 50-374.83/05/03.8305100352
- 8305240007 RO on 820715, ultraviolet fire detectors taken out of syc Due to continued const work, fire detectors to be out of syc until Fall 1983 fuel load DIEDERICH, O J Commonwealth Edison Co 83/05/10 KEPPLER, J O Region 3, Office of Director 1p 19547 038 24X Fiche 50-373, 83/05/10, 8305240007
- DOCKET 50-382 WATERFORD GENERATING STATION: UNIT 3
- A Application/construction stage documents & correspondence
- 8305020502 Forwards comments on C-E Owners Group calculations redepressurization & DHR capability of C-E plants w/o pressurizer PORVs, discussed at 830112 meeting w/C-E Owners Group in Bethesda.MD NOVAK,T M Assistant Director for Licensing 83/04/19 MAURIN,L V Louisiana Power & Light Co 4pp. 18284 333 24X Fiche 50-382,83/04/19.8305020502
- 8305020341 Requests extension of commitment re athropemetric concurn w/highest row of meters on remote shutdown panel LCP-43 by providing permanent metal deck in front panel per human factors audit findings
 MAURIN,L V Louisians Power & Light Co. 83/04/25 KNIGHTON, 9
 Licensing Branch 3 2pp 18277'115 24X Fiche 50-382,83/04/25,8305020341
- 8305040323 Board Notification 83-057 forwards differing prof opinions resussinteraction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D 9 Division of Licensing, 83/05/04, PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323
- B305090659 Generic Ltr B3-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Byc list encl
 EISENHUT, D 9. Division of Licensing, B3/05/09 Consolidated
 Edison Co of New York, Inc 16pp 18627-153 24X
 Fiche 30-000, B3/05/09, B305090659.
- 8305130343 Forwards Board Novirication 83-64 re issuance of 40-yr OL EISENNUT, D 0 Division of Licensing 83/05/10. NOVAK, T. M. Assistant Director for Licensing. 2pp 18456 227 24X Fiche 50-382,83/05/10,8305130343
- --8305130344 Board Notification 83-64 forwards util 830318 request for 40-yr OL NOVAK.T M Assistant Director for Licensing, 83/05/10 Atomic Safety and Licensing Board Panel, 8pp. 18456 228 24X Fiche 50-382,83/05/10,8305130343

- 8305240258 Notification of 830523 site visit to conduct control room audit & discuss revs to amergency operating procedures WILBON.J H Licensing Branch 3 83/05/10 KNIGHTON.G W Licensing Branch 3 3pp 18573 297 24X Fiche 30-382.83/05/10.8305240258
- 8305180468 Forwards responses to NRC concerns raised at 830218 meeting w/util to close out open items re emargency feedwater control ays, per NUREG-0787, Suppl 1 W/23 oversize drawings Aperture cards are available in PDR MAURIN.L. V Louisians Power & Light Co 83/05/13 KNIGHTON.C W Licensing Branch 3 31pp 18482 131 24X Fiche 50-382,83/05/13,8305180468
- 8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants: w/emphasis on need for PDRVs in current C-E designs.

 NGVAK:T M Assistant Director for Licensing #3705/18 Atomic Bafety and Licensing Board Penel 7pp 18627 107 24X Fiche 50-000: 83705/18, 8305250209
- --8305250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ASLAB.

 MATTSON, R. J. Division of Systems Integration (post 811005)
 83/04/28 EISENHUT. D Q Division of Licensing 1p 18627 113, 24X Fiche 50-000, 83/05/18, 8305250209
- --8303250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issua prior to reporting back to Commission Study to be concluded 830630 DIRCKS,W J. Office of the Executive Director for Operations 83/04/25 CHILK,S J. Office of the Secretary of the Commission ip. 18627 115 24X Ficha 30-000.83/05/18.8305250209
- 8305310094 Forwards revised description of NUREO-0737, Item II F 2, "Inadequate Core Cooling Instrumentation," providing sufficient info to close item & corresponding requirement in 8ER.

 DRUMMOND, F J Louisians Power & Light Co 83/05/23 KNIOHION, O W Licensing Brench 3 34pp. 18655 039 24X Fiche 50-382,83/05/23,8305310094
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B305310094 Forwards revised description of NUREG-0737. Item II.F 2.
 "Inadequate Core Cooling Instrumentation." providing
 sufficient info to close item & corresponding requirement
 in SER
 DRUMMOND.F.J Louisiana Power & Light Co B3/05/23 KNIGHTON. Q W
 Licensing Branch 3. 34pp 18655:039 24X Fiche 50-382,83/05/23,
 8305310094
- F. Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl.
 EISEMHUT, D 9. Division of Licensing 83/05/ii. Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X Fiche: 50-000, 83/05/ii. 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS,W.J. Office of the Executive Director for Operations, 83/05/13. PALLADINO,N.J. Commissioners 5pp 18593 322, 24X Fiche 50-000, 83/05/13, 8305240213.
- 8305200285 Forwards list of NRC emergency preparedness insp team personnel requiring unescorted & unrestricted access to facility on 830523-27. Site orientation on issuance of badges, excort duties & amergency evacuation requested COLLINS, J. T. Region 4, Office of Director 83/05/16 MAURIN, L. V. Luuisiana Power & Light Co. 2pp. 18517.065 24X Fiche: 50-382, 83/05/16, 8305200285
- 9. Adjudicatory correspondence
- B305120322 Order granting NRC B30415 motion to correct B30208-11 hearing transcript.

 MOLFE:8 J. Atomic Safety and Licensing Board Panel B3/05/11 Office of the Executive Legal Director tp 18432:266 24% Fiche: 50-382:83/05/11:8305120322.
- 8305180429 Advises that all sirens within emergency planning zone will be tested by parish officials for rotational function, output & audibility at perimeter of each siren effective range 8vc list encl.
 RIDGMAY, D. A. Shaw, Pittman, Potts & Trowbridge, RIDGMAY, D. A. Louisians Power & Light Co. 83/05/16 TURK, S. E. Hearing Branch 1 4ps. 18485:274 24X Fiche, 50-382,83/05/16,8305180429

- B305200642 Corrects statements made at 830419 oral argument Neither NRC nor FEMA will independently verify accuracy of siren measurements NRC method for verifying siren coverage adequacy delineated

 TURK 8 E Hearing Branch 1 83/05/18 EILPERIN.8 F , KOHL.C & , JOHNBON.W R Atomic Safety and Licensing Appeal Panel 6pp 18520 129 24X Fiche 30-382, B3/05/18. B305200642
- 8305270634 Second partial initial decision in OL hearing Requests that NRC ascertain that changes &/or mode to preemergency public info brochure implemented JORDAN, W. H., FOREMAN, H., WOLFE, S. J. Atomic Safety and Licensing Board Panel 83/05/26 34pp 18646-264 24% Fiche 50-382, 83/05/26, 8305270624
- H General correspondence
- 8305170270 Informs that correspondence signed by FJ Drummend, RP Barkhurst & TF Gerrets should be accepted as valid submittals CAVANAUGH. W Louisiana Power & Light Co 83/05/13 KNIGHTON, O W Licensing Branch 3 lp 18465 358 24X Fiche 50-382, 83/05/13, 8305170270
- G Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction" Svc list encl.

 TAYLOR, J. H. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 112pp 18308,319 24% Ficha 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24x Fiche 50-000,83/04/15,8303040021
- 8305200190 Informs that 830316 order imposing civil penalty & accompanying info should be transmitted to ASLB & parties, per Ofc Ltr 19 procedures EIBENHUT.D G Division of Licensing B3/04/19 NOVAK.T Assistant Director for Licensing ip 18576/133 24X Fiche 50-382,83/04/19,8305200190
- --8305200199 Board Notification 83-52 notifies that order imposing civil penalty issued to util on 830316 resulting from breakdown in GA/GC program NOVAK, T M Assistant Director for Licensing 83/04/19. Atomic Safety and Licensing Board Panel. 4pp 18576-134 24X Ficha 50-382,83/04/19,8305200190
- 8303040023 IE Info Notice B3-22, "BWR Bafety/Relief Valve Failures "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383,089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Bys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 8330103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25.8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Bide of Bleam Generators at PWRs." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York Inc 113pp 18382 047 24% Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 163 24X Fiche 50-000.83/04/28.8303040027
- B305170004 Forwards IE Insp Rept 50-382/83-16 on 830328-31 No noncompliance noted MADBEN: G. Region 4. Office of Director 83/04/27 MAURIN, L. V. Louisiana Power & Light Co. 2pp. 18466 242 24X Fiche: 50-382, 83/04/27, 8305170004
- --8305170009 IE Insp Rept 50-382/83-16 on 830328-31 No noncompliance noted. Major areas inspected safety-related records, site-related design activities & potential const deficiency resmergency feedwater turbine-driven pump OBERO, C R , CROSSMAN, H A Region 4, Office of Director. 83/04/25. Ppp 18466 244. 24X Fiche 50-382, 83/04/29, 8305170004

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list and I JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fichs 50-000.83/03/04.8303040030
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/05/04 Consolidated Edison Co of New York. Inc 119pp 18441 001 24X Fiche 80-000,83/05/04.8303040031
- 8305200251 Forwards IE Investigation Rept 50-382/82-09 on 820329-0516 & notice of violation MADSEN.O L Region 4. Office of Director 83/05/04 MAURIN.L V Louisiana Power & Light Co 2pp 18517 067 24X Fiche: 50-382,83/05/04,8305200251
- --8309200253 Notice of violation from investigation on 820329-0516 * Region 4. Office of Director 83/05/04 ip 18517-049 24 Fiche 50-382,83/05/04,8305200251
- --8305200256 IE Investigation Rept 50-382/82-09 on 820329-0516 Noncompliance noted individual in plant metrology leb gerformed equipment calibr w/o being properly qualified DRISKILL, D D , JUHNSON,E H Region 4, Office of Director 83/03/10 12pp 19517 070 24X Fiche 50-382.83/05/04.8305200251
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (ECP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11.8303040034
- 8303200285 Forwards list of NRC emergency preparedness inspiteam personnel requiring unescorted & unrestricted access to facility on 830323-27 Site orientation on issuance of badges, escort duties & emergency evacuation requested COLLINS.J T Region 4. Defice of Director 83/05/16 MAURIN,L V Lovisiane Power & Light Co 2pp 18517.065 24X Fiche 50-382,83/05/16.8305200285
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Svc list enc!
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co. of New
 York, Inc. 114pp 18697 007 24X Fiche 30-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 8305050017 Forwards nuclear organization staffing status rept as of 830415 & status rept of personnel commitments contained in 810420 ltr MAURIN.L V Louisiana Power & Light Co 83/04/20 WILSON, J NRC No Detailed Affiliation Given 3pp 18338 331 24X Fiche 50-382.83/04/20.8305050017
- 8 Reportable occurrences, LERs & related correspondence
- B30504000B Board Notification 83-40 notifies of applicant commitment to periodically survey industrial & transportation activities in plant area to maintain awareness of significant product changes.per preliminary notification dtd 830322 NDVAK.I M Assistant Director for Licensing B3/04/22 Atomic Safety and Licensing Board Panel 4pp 18354 272 24X Fiche 50-382.83/04/22,8305040008

- 8305020411 Final Significant Const Deficiency 64 re low safety injection tanks, discharge flow rates during preoperational testing C-E analysis performed per Nonconformance Rept W3-4636 Flow rates acceptable MAURIN.L V Louisiana Power & Light Co 83/04/25 COLLINS, J. T. Region 4, Office of Director 3pp 18273 097 24X Fiche 50-382,83/04/25,8305020411
- 8305020450 Final Bignificant Const Deficiency Rept 49 re failure of Crosby Valve & Gauge Co Stellite Alloy 6B discs to meet ASHE requirements Solid Stellite 6B valve discs meet all ASHE Code Saction 3 requirements MAURIN.L V Louisiana Power & Light Co 83/04/25 COLLINB.J T Region 4. Office of Director ip 18281 247 24X Fiche 50-382.83/04/25.8305020450
- 8305020479 First interim rept of Bignificant Const Deficiency 76 redamage to pressurizer heaters during precore hot functional testing Initially reported on 830311 Unacceptable heaters will be replaced/reworked Next rept expected by 830715 MAURINAL V Louisians Power & Light Co 83/04/25 COLLING.J T Region 4. Office of Director 2pp 18283 268 24X Fiche 50-382,83/04/25,8305020479
- B305060425 Forwards rev to seismic qualification completion schedule, MAURIN.C. V. Louisiana Power & Light Co. 83/04/27. KNIGHTON, 0 W. Licensing Branch 3 32pp 18343 193 24X Fiche 50-382, 83/04/27, 8305060425
- 8305060566 Final Deficiency Rept 110 re dàmage to main steam piping supports Initially reported on 830325 Evaluation completed Condition determined not reportable Hydraulic transient attributed to improper operation of sys MAURIN.L V. Louisians Power & Light Co 83/04/27 COLLINB, J T Region 4. Office of Director 2pp. 18349:053 24X Fiche 50-382,83/04/27,8305060566
- 8303040367 First Interim Significant Deficiency Rept 78 re insufficien documentation from American Bridge for reactor auxiliary & fuel handling bldgs bolting & welding Nonconformance repts issued Next rept by 830630 MAURINL V Louisians Power & Light Co 83/04/28, COLLINS: J T Region 4, Office of Director 3pp. 18344 148 24X Fiche 50-382,83/04/28,8305060367
- 8305060587 Third Interim Bignificant Const Deficiency Rept 53 re possible failure of GE Type HFA relays. Bubmittal of final rapt delayed until 830615 due to plant testing MAURIN.L V Louisiana Power & Light Co. 83/04/29 COLLINS, J T Region 4. Office of Director. Ip 18349 010 24X Fiche 50-382,83/04/29,8305060587
- 8305130019 NPDES noncompliance notification on 830317-19, approx 200,000 gallons of condenser hotwell water released from NPDES outfall Number 002 Caused by necessity to drain secondary sys & Units 1 & 2 waste treatment ponds full.
 MAURIN.L V Louisiana Power & Light Ca 83/05/06 KNIOHTON, C W Licensing Branch 3 App 18437 149 24X Fiche 50-382,83/05/06,8305130019
- 8305170223 Second Intgrim Const Deficiency Rept 72 re radiation monitoring sys RN-23 control modules Initially reported on 830321 Corrective action scheduled for completion by 830615 Final rept will be submitted by 830630.

 MAURIN.L V Louisiana Power & Light Co 83/05/11 COLLINS, J T Region 4. Office of Director ip 18466 340 24X Fichs 50-382,83/05/11,8305170223
- 8305170265 Secund interim Significant Const Deficiency Rept SCD 71 re failure to properly review condition identification & work authorization for reportability Initially reported on 830211 Forms being reviewed Final rept expected by 830815 MAURINL V Louisiana Power & Light Co 83/05/11 COLLING. J. T Region 4. Office of Director 2pp 18465-018 24X Fiche 50-382.83/05/11,8305170265.
- 8303170327 First Interim Const Deficiency Rept 79 re unqualified components in hydrogen analyzers Initially reported on 830413 Field insp by Ebasco determined that pump bearings contained grease qualified for LOCA environ MAURIN, L V Louisiana Power & Light Co 83/05/11, COLLINS, J T Region 4. Office of Director . 4pp 18465 169, 24X Ficha 50-382,83/05/11,8305170327.
- 8305170351 Sixth interim rept of Significant Const Deficiency Rept 35 re matl properties of tube track & welding fittings JC White fittings tested by Lucious Pitkins, Inc Corrective actions will be completed 830630. Final rept by 830720 MAURINL V Louisiana Power & Light Co 83/05/11. COLLINS, J. T. Region 4. Office of Director 1p 18465 266. 24% Fiche 50-382, 83/05/11, 8305170341

- 8305170484 Third Interim Const Deficiency Rept 60 re turnover documentation & imadequate hanger weld problems initially reported on 830214 Conrective actions 95% complete Final rept will be submitted by 830715 MAURINI. V Louisians Power & Light Ca 83/05/11 0'REILLY, J P Region 2. Office of Director 1p 18470 067 24% Fiche 50-382,83/05/11,8305170484
- 8305170492 Second Interim Const Deficiency Rept 70 re OE 480-voit trip coils not dropping out after tripping Initially reported on 830321 Corrective actions scheduled for completion by 830601. Final rept will be submitted by 830622 MAURIN, L. V. Louisiane Power & Light Co. 83/05/11 COLLINS, J. T. Region 4, Defice of Director 1p 18470 054 24X Fiche; 50-382, 83/05/11, 8305170492
- 8305170500 Sixth Interim Const Deficiency Rept 33 re chilled water piping supports Initially reported on 830307 Handware mods complete Review of supporting documentation underway Final rept will be submitted by 830630 MAURIN, L. V. Louisiana Fower & Light Co. 83/05/11 COLLINS, J T Region 4, Defice of Director 1p 18470 035 24X Fiche 50-362,83/05/11,8305170500
- 8305200542 Sixth interim rept re Significant Const Deficiency Rept 54 on tube steel (HT-166) lamination Corrective action completed by replacing 240 ft of tube steel installed in safety-related sys Final rept delayed until 830623 DRUMMOND, F. J. Louisians Power & Light Co. 83/05/16 COLLINS, J. T. Region 4, Office of Director 1p 18515-355 24X Fiche. 50-382, 83/05/16, 8305200542
- 8305270138 Interim Significant Deficiency Rept 80 re unsatisfactory straking of emergency feedwater pump turbine steam shutoff valves initially reported on 830420 Vendor rept submitted on 830427 & springs replaced Next rept by 830729 DRUMMOND, F. J. Louisiana Power & Light Co. 83/05/20 COLLINS, J T Region 4, Office of Director 2pp 18638 163 24X Fiche 50-382,83/05/20,8305270138
- 8305270147 Sixth interim deficiency rept re incorrect structural calculations for holdup & boric acid make up tanks
 Corrective action scheduled for completion by 830531 Final rept will be delayed until 830621
 DRUMMOND, F J Louisiana Fower & Light Co 83/05/20 COLLINS, J T Region 4, Office of Director ip 18638 160 24X
 Fiche: 50-382,83/05/20,8305270147
- 8305270194 Second interim Significant Const Deficiency Rept 77 re inadequate containment purga valve closure time & flow rate. Hardware corrective action complete Final rept will be submitted by 830630, DRMMOND,F J Louisiana Power & Light Co 83/05/20 COLLINS, J. T Region 4. Office of Director 1p. 18637, 349 24X Fiche 50-382,83/05/20,8305270194.
- 8305270373 Bignificant Const Deficiency Rept 73 re American Bridge reactor containment bldg structural steel welding defects. Reinap scheduled Corrective action rework will be completed. Next rept will be provided by 830815. DRUMMOND. F. J. Louisiana Power & Light Co. 83/05/20 COLLINS, J 7 Region 4, Office of Director 1p. 18642 336 24X Fiche: 50-382, 83/05/20, 8305270373
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION. UNIT 1 F. Security, medical, emergency & fire protection plans
- 8305050285 Releases public version of temporary change to emergency plan procedure FELTON.J. M Division of Rules and Records 83/04/25 Document Management Branch. 1p. 18352.070 24X Fiche 50-387.83/04/25, 8305050285
- --B305050289 Forwards public version of Temporary Change 83-575 to Emergency Plan Procedure EP-IP-044, "Emergency Environ Sampling," Receipt form and the Pennsylvania Power & Light Co. B3/04/14 BCHWENGER, A NRC No Detailed Affiliation Given 3pp 18352:071 24X Ficher 30-387,83/04/25,8305050285
- B305030144 Forwards application for proposed Amend 23 to License NPF-14, changing License Condition 2.C (28)(g)(1) to extend completion date for safety parameter display sys to B31230, as part of NURED-0737, Item III. A. 1.2 (Generic Ltr 82-33). GURTIG: N. W Pennsylvania Power & Light Co B3/04/29 BCHWENCER: A. Licensing Branch 2. 1p 18306-328 24X Fiche 50-387, B3/04/29, 8305030144.

- --8305030153 Application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(i) to extend completion date for safety parameter display sys to 831230, as part of NUREO-0737. Item III A 1 2 CURTIS, N W Pennsylvania Power & Light Co 83/04/29 2pp 18306 329 24X Fiche 50-387, 83/04/29, 8305030444
- 8305130310 Releases public Version of rev to emergency plan implementing procedure FELTON.J H Division of Rules and Records 83/05/02 Document Management Branch ip 18456 237 24X Fiche 50-387,83/05/02. 8305130310
- ---8305130311 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030. "Activation & Functional Operation of Emergency Deparations Facility & Transfer of Control From Technical Support Ctr "

 * Pennsylvania Power & Light Co 83/04/20 SCHWENCER, A NRC No Detailed Affiliation Given ip 18454 238 24X Fiche, 50-087, 83/05/02, 8305130310
- --8305130314 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr " # Pennsylvania Power & Light Co. 83/04/20 96pp 18456 239 24X Fichs 50-387, 83/05/02,8305130310
- 8305200091 Forwards request for add1 info re Rev 6 to emergency plan, needed to complete review Info requested by 830520 8CHMENCER.A Licensing Branch 2 83/05/07 CURTIS,N W Pennsylvania Fower & Light Co 5pp 18540 358 24X Fiche 50-387,83/05/09,8305200091
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D Q Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540-095. 24X Fich 50-000,83/05/11,8305110034
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8305110097 Forwards application for Amend 54 to GLs containing Rev 33 to FBAR CURTIS.N W Pennsylvania Power & Light Co 83/05/03 SCHWENCER, A Licensing Brench 2 6pp 18405 100 24X Fiche 50-387, 83/05/05, 83/0510097
- --8305110104 Application for Amend 54 to OLs containing Rev 33 to FSAR # Pannsylvania Power & Light Co B3/05/05 1p 18405 107 24X Fiche 30-387,83/05/05,8305110097
- --8305110108 Rev 33 to FSAR * Pennsylvania Power & Light Co 83/04/30 323pp 18405 108 24X Ficha 50-387,83/05/05,8305110097
- P Operating license stage documents & correspondence
- B303300772 Forwards add1 guidance re reporting offsite radiation doses to public SCHMENGER,A Licensing Branch 2 B3/03/24 CURTIS,N w Pennsylvania Power & Light Co 4pp 17745 244 24X Fiche 50-387,83/03/24,8303300772
- 8305040669 Forwards SER on BMR Dwners Group generic response to NUREQ-0737. Item II K 3 18. "Mod of Automatic Depressurization Sys (ADB) Logic " Response acceptable w/ stipulated conditions Response requested expediently SCHMENCER. A Licensing Branch 2 83/04/25 CURTIS,N W Pennsylvania Power & Light Co 10pp 18336 338 24X Fiche 50-387,83/04/25,8305040669
- B305110160 Forwards 467 oversize drawings, per Reg Quide 1, 70 Drawing transmittal list encl Aperture cards are available in PDR MOLCHANY, W J Pennsylvania Power & Light Co B3/04/25, BCHWENCER, A Licensing Branch 2 20pp 18406 318 24X Fiche 50-387, 83/04/25, B305110160
- 8305040546 Requests remittance of Class III fee for 821110 application re nonconformance w/NOREO-0737, Item II E 4 2 an containment isolation dependability DIO95.R M License Fee Management Branch 89/04/27 CURTIS.N. W Pennsylvania Power & Light Co ip, 18351 230 24X Fiche 50-387.83/04/27, 8305040346

- 8305020387 Responds to NRC B30203 & 0330 questions re proposed SRP Amend 19 No need exists to arbitrarily increase initial power to account for uncertainty in power level Errats sheet & transient summary of feedwater controller failure and. CURTIS,N W Pennsylvania Power & Light Co B3/04/28 SCHMENCER, A Licensing Branch 2 App 18276 314 24X Fiche 30-387,83/04/28,8305020387.
- 8303030144 Forwards application for proposed Amend 23 to License NFF-14, changing License Condition 2 C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737. Item III A 1.2 (Generic Ltr 82-33) CURIIS.N W Pennsylvania Power & Light Co 83/04/27 SCHWENCER.A Licensing Branch 2 1p 18206-328 24X Fiche 50-387.83/04/27, 8305030144
- --8305030153 Application for proposed Amend 23 to License NPF-14. changing License Condition 2 C (28)(g)(i) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737. Item III A I 2 CURTIS.N W Pennsylvania Power & Light Co 83/04/29 2pp 18306 329 24X Fiche 50-387.83/04/29,8305030144
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLS Svc list enci EISEMHUT.D 0. Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp. 18441.120 24X Fiche 80-000.83/05/02.8305020455
- 8303040616 Ack completion of action required by Amend 7 to License NPF-14:Peragraph 3 by initiating DDE negotiations concerning disposal of high level waste or spent nuclear fuel.

 8CHMENCER: A Licensing Branch 2 83/05/02 CURTIS: N W Pennsylvania Power & Light Co 2pp 18351 225 24X Fiche. 50-387,83/05/02,8305040616
- 8305100016 Forwards proposed Amend 24 to License NPF-14, changing App A Tach Specs re circuit breaker location, gaseous release type, bypass damper leakage & reactor vessel level instrumentation KENYON.B D Pennsylvania Power & Light Co 83/05/04 SCHMENCER, A Licensing Branch 2 4pp 18377 126 24X Fiche 50-387,83/05/04,8305100016
- --- 9305100019 Proposed Amend 24 to License NPF-14, changing App A Tech Specs re circuit breaker location-gaseous release type. bypass damper leakage & reactor vessel level instrumentation KENYON, B.D. Pennsylvania Power & Light Co. 83/05/04 1p 18377 130 24X Fiche 50-387,83/05/04,8305100016
- B30510030B Forwards "Offsite Dose Calculation Manual." CURTIS:N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER, A Licensing Brench 2 1p 18370 004 24X Fiche 50-387, 83/05/05, 8305100308
- --8305100317 "Dffsite Dose Calculation Manual "
 # Pennsylvania Power & Light Co 83/04/27 76pp, 18370:005
 24% Fiche 50-387,83/05/05,8305100308
- 9305110097 Forwards application for Amend 54 to DLs containing Rev 33 to FSAR
 CURTIS:N W Pennsylvania Power & Light Co 83/05/05. SCHWENCER, A Licensing Branch 2 App. 18405 100 24X Fiche 50-387,83/05/05,8305110097
- --8305110104 Application for Amend 54 to OLs containing Rev 33 to FBAR # Pennsylvania Power & Light Co 83/05/05 1p 18405 107 24X Fiche 50-387,83/05/05,8305110097
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Syc list enci.
 EISENHUT.D Q. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627,153 24X
 Fiche: 50-000, 83/05/09, 8205090659
- 3305130114 Forwards responses to questions re ultimate heat sink test plan Calibr temp measuring device will be used to measure temp in main stilling well in pumphouse Tests will be performed during Jul or Aug 1983.
 CURTIS:N W Pennsylvanta Fower & Light Co 83/05/10, SCHWENCER, A Licensing Branch 2, 7pp, 18438 082 24X Fiche 50-387,83/05/10, 8305130114

- 8305200175 Approves licensee B30225 submittal w/description of permanent mods to 12-inch gas pipeline near facility, limiting flow & precluding flammable mixture at facility air intakes

 SCHMENCER. A Licensing Branch 2 B3/05/10 CURTIS.N W Pennsylvania Power & Light Co 2pp 18540-232 24X Fiche 30-387-83/05/10. B305200176
- 8305190285 Advises that util participating in BMR Owners Group Committee to address fast scram issues Due to delays caused by additesting BMR rept will not be received in time for response in Second Guarter 1933 CURTISIN W Pennsylvania Power & Light Co 83/05/16 BCHMENCER, A. Licensing Branch 2 Ip 18501 147 24X Fiche 50-387, 83/05/16, 8305190285
- 8305190295 Forwards drawing of mod to resolve essential svc water single failure issue Mod Allows manual shutoff valves in RHR room & corrects loss of both RHR pumps in one div CURTIES NN Pennsylvania Power & Light Co B3/05/16 SCHWENCER, A. Licensing Branch 2, 3pp 18500 218 24X Fiche: 50-387, 83/05/16.
- 8305230541 Advises that util andorses BWR Owners Group rept NEDO-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity "Proposed amend to License NPF-14 will be submitted to reflect position.

 CURTISIN W Pennsylvania Power & Light Co 83/05/19 SCHWENCER, A. Licensing Branch 2, 2pp 18537-335 24X Fichs 50-387, 83/05/19, 8305230541
- 8305270064 Forwards equipment qualification summary rept Summary info submitted complete for Unit 1 but only partially complete for Unit 2 Next rev of rept will contain complete info for Unit 2.

 CURTIS.N W Pennsylvania Power & Light Co 83/05/20 BCHWENCER.A. Licensing Branch 2 766pp. 18635-095. 24X Fiche. 50-387. 83/05/20. 8305270064.
- 8305310208 Fowards check in payment of review re nonconformance w/ NUREO-0737. Item II E. 4 2. par 830427 request CURTIS. N. W. Pennsylvania Power & Light Co. 83/05/25 SCHWENCER, A Licensing Branch 2. ip. 18658 133 24X Fiche 50-387, 83/05/25, 8305310208
- G Inspection reports, IE Bullstins & correspondence
- B212040385 IE Info Notice 83-14, "Dewatered Spant Ion Exchange Resin Susceptability to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J.N Division of Sefeguards & Inspection Programs (Post B30103). B3/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308-319 24% Ficher-50-000.83/03/21.8212040385.
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator," Bvc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche.50-000,83/04/15,8303040021.
- 8303040023 IE Info Natice 83-22, "BWR Bafety/Relief Valve Failures "
 8vc list encl
 JORDAN E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sansing Sys " Syc list enc! JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp. 18381, 291 24X Fiche, 50-000, 83/04/25, 8303040025
- 8305030366 Orants util 830303 preservice inspirelief requests. Encl technical evaluation will be incorporated into future suppl to SER 8CHMENCER, A Licensing Branch 2 83/04/25 CURTIS, N W Pennsylvania Power & Light Co 2pp 18352:026, 24X Fiche, 50-367,83/04/25,8305050366.
- --8305050373 Supplemental SER, supporting preservice insp relief request * NRC No Datailad Affiliation Given 83/04/25, 17pp 18352-028, 24X Fiche 50-387, 88/04/25, 8305050506
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Btsam Generators at PWRs " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103), B3/04/28. Consolidated Edison Co. of New York, Inc 115pp. 18382-047. 24X Fiche. 50-000, B3/04/28, 8303040026.

- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8305110149 Notification of 830517 meeting w/util onsite to discuss results of SALP MCCABE,E C Region 1, Office of Director 83/04/29 Region 1, Office of Director 83/04/29, 8305110149
- 8305060543 Bubmits addi info re IE Bulletin 82-01, Rev 1, Suppl 1, "Alterations of Radiographs of Welds in Piping Bubassemblies," per B30330 request Three radiographs dispositioned per PSI ultrasonic exam. ABME Code Section XI CURTIB, N W. Penneylvania Power & Light Co 83/05/02 ALLAN, J M Region 1. Office of Director 3pp 18347 306 24X Fiche 50-987, 83/05/02, 8305060543
- 8303040028 IE Info Notice 83-25, "Failure of Bafety/Relief Vaive Discharge Line Vacuum Breakers " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03, Consolidated Edison Co. of New York, Inc. 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L. Davision of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp. 18382;282, 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Fost 830103), 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp. 18441 001 24X Fiche 50-000,83/05/04,8303040031.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation," Syc list encl WRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06, Consolidated Edison Co. of New York, Inc. 115pp. 18523 248 24X Fiche. 50-000, 83/05/06, 8303040033.
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11. Consolidated Edison Co of New York, Inc. 114pp, 18324-003, 24X Fiche 50-000,83/05/11,8303040034.
- 9305250571 Forwards IE Insp Rept 50-387/83-10 on 830314-15 No noncompliance noted, MARTIN, T. Davision of Engineering & Technical Programs 83/05/13 KENYON, B, D Pennsylvania Power & Light Co. 2pp 18588, 211 24X Fiche: 50-387, 83/05/13, 8305250571.
- --8305250575 IE Insp Rept 50-387/83-10 on 830314-15 No noncompliance noted Major areas inspected open items from IE Insp Rept 50-387/82-36 re radiographic documentation & NDE, KERCH-H Region i, Office of Director. 83/04/20 3pp. 18588: 213 24X Fiche: 50-387, 83/05/13, 8305250571
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Byc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/17, Consolidated Edison Co. of New
 York: Inc. 114pp. 18697:007, 24X Fiche 50-000,83/05/19,8303040040,
- 8305270255 Forwards response to Enforcement Action 83-26 & payment of civil penalty, Supervisor of operations conducted training sessions w/each shift to ensure all significant aspects of event understood KENYON, B. D. Pennsylvania Power & Light Co. 83/05/20. DEYOUNG, R C, Director's Office, Office of Inspection and Enforcement 8pp. 18637:141. 24X Fiche: 50-387, 83/05/20, 8305270255
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list enci. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), B3/05/26. Consolidated Edison Co. of New York, Inc. 114pp. 18647-007. 24X Fiche: 50-000.83/05/26,8303040046.
- 8. Reportable occurrences, LERs & related correspondence
- 8305030334 Forwards LER 83-051/03L-0. MEISER: H. W. Fennsylvania Fower & Light Co. 83/04/21 ALLAN, J. M. Region J. Dffice of Director. 19. 18277: 141. 24X Fiche: 50-387, 83/04/21, 8305030334.

- --B305030338 LER 83-051/03L-0 on 830322.RCIC turbine tripped on electrical overspeed signal Caused by slow operation of governor valve RCIC quick testing frequency increased to monthly KUCZYNSKI, L. A Pennsylvania Power & Light Co. 83/04/2I. Region 1, Office of Director 2pp 18297 142 24X Fiche 50-387, 83/04/21.8303030334
- 8305120422 Forwards updated LER 82-001/01X-1 KEISER:H W Pennsylvania Power & Light Co 83/04/21 ALLAN, J M Region 1, Office of Director 1p 18433 238 24X Fiche 50-387,83/04/21,8305120422
- --8305120430 Updated LER B2-001/01X-1 on 820718, linear indications found on recirculation riser weld A-11M Caused by slag inclusion in A-11M weld & partial cold lap on 1/4 inch A-13 weld Weld areas excavated & repaired
 TODD.J T Pennsylvania Power & Light Co 83/04/21 Region 1, Office of Director 2pp 18433 237 24X Fiche 50-387,83/04/21, 8305120422.
- 8305i1024i Forwards LER 83-052/03L-0 KEIBER:H W Fennsylvania Power & Light Co 83/04/22 ALLAN, J M Regian I, Office of Director. Ip 18406 340 24X Fiche: 50-387, 83/04/22, 830511024i
- --8305i10247 LER 83-052/03L-0: on 830325, during surveillance test, CREDASS train A tripped Caused by fan bults coming off fan pullay Belts replaced & bearings & fan pulley realigned KUCZYNBKI, A Pennsylvania Power & Light Co 83/04/22 Region 1, Office of Director 1p. 18406: 341 24X Fiche 50-387, 83/04/22, 8305110241
- 8305110348 Ferwards LER 83-053/03L-0 KEISER:H W Pennsylvania Power & Light Co. 83/04/25 ALLAN.J M. Region 1. Office of Director. 1p. 18404.349 24X Fiche 50-387.83/04/25.8305110348
- --8305110358 LER 83-053/03L-0 on 830326 & 30, containment hydrogen & oxygen analyzer 8 declared inoperable due to erratic readings Investigation underway. Air in-leakage suspected KUCYNSKI, L A Pennsylvania Power & Light Co. 83/04/25 Region in Office of Director 2pp 18404 350 24X Fiche 50-387, 83/04/25,8305110348
- 8305110421 Forwards LER 83-054/03L-0 KEIBER:H W Pennsylvania Power & Light Co 83/04/28 ALLAN.J.M. Ragion 1. Office of Director ip 18404 356. 24X Fiche: 50-387: 83/04/28, 8305110421
- --8305110430 LER B3-054/03L-0 on B30401.one hydraulic control unit found w/prassure below aliquable limit. Caused by leaking connections Procedural changes instituted to recharge any accumulator w/iow pressure, but above alarm point PIEMONTEBE, A P Pennsylvania Power & Light Co. 83/04/28 Region i, Office of Director 1p. 18404 357 24X Fiche 50-387, 83/04/28, 83031042i
- 8305060442 LER 83-057/DIP-0 confirms 830428 telcon re incident concerning bypass leakage calculations for feedwater following DBA LOCA
 KEISER:H W Pennsylvania Power & Light Co 83/04/29. ALLAN, J. M Region i, Dffice of Director ip, 18343 146 24X Fiche, 90-387:83/04/29, 8305060442
- 8305040592 Forwards LER 83-055/03L-0, KEISER:H H Pannsylvanta Power & Light Co, 83/04/29. ALLAN:J.M Region 1. Office of Director ip 18349 008 24X Fiche 30-387:83/04/29.8305060392
- --8305060598 LER 83-055/03L-0 on 830405, while calibr safety relief valve acoustic monitoring sys, one monitor did not indicate that respective valve open Faulty indication caused by broken pin on accelerometer connector Connector replaced.

 KUCZYNSKI: A Pennsylvania Power & Light Co 83/04/29. Region i. Office of Director ip 18349-009. 24% Fiche 50-387.83/04/29, 8305060592
- 8305i60140 Corrected RO on 821221.actual total activity released was 14 uCi at concentration of 1 37E-5 uCi/m1 instead of 4 82 uCi at concentration of 4.7E-6 uCi/m1 Release figures well below required reporting limits.

 KEISER.H N. Pannsylvania Power & Light Co. 83/04/29. ALLAN.J.M Region 1. Office of Director. 1p. 18446-104 24X

 Fiche. 50-387.83/04/29.8305160140
- 8305160132 RO. on 830212,ECCS actuated, resulting in reactor scram on main turbine control valve fast closure Event occurred again on 830322 when reactor scrammed due to main steam line high radiation Planned HPCI injections initiated 821227-830404. KEISER, H W. Pennsulvania Power & Light Co 83/05/04. ALLAN, J. M Region 1, Office of Director 2pp 18446, 188 24X Fiche 50-387,83/05/04,8305160132

- 8305230471 Forwards LER 83-059/03L-0 KEISER:H W Pennsylvania Power & Light Co 83/05/04 ALLAN, J M Region 1. Office of Director 1p 18537 L94 24X Fiche 50-397,8705/04.8305230471
- --9305230477 LER B3-059/03L-0 on B30404, fullowing full M81V isolation, test data showed Level 1 acceptance criteria for one valve not met Event under investigation Updated LER to be forwarded shortly PIEMONTESE. A P Pennsylvania Power & Light Co B3/05/04 Region 1, Dffice of Dfirector 2pp 18537 175 24X Fiche 50-387.83/05/04,8305230471
- 8305160124 Forwards LER 83-059/03L-0 KEISER,H W Pennsylvania Power & Light Co 83/05/06 ALLAN,J M Region 1. Office of Director 1p 18448 183 24X Fiche 50-387,83/05/06,8305160124
- --8305160151 LER 82-058/03L-O on 830409.during scheduled surveillance tests, but reactor pressure vessel water level switches found out of tolerance Caused by setpoint drift Engineering evaluation re use of analog transmitters underway KUCZYNSKI.L A Pennsylvania Power & Light Co 83/05/06 Region 1. Office of Director ip 18448 184 24X Fiche 50-387,83/05/06.8305160124
- 8305190319 Interim deficiency rept re failure of GE reactor mode switch to actuate reactor protection sys channel Initially reported on 830407 Franklin Inst test & analysis rept on 830322 switch failure sncl Final rept for Unit 2 by 831001 CURTIS.N W Pannsylvania Power & Light Co 83/05/06 ALLAN.J M Region 1. Dffice of Director 2pp 18301 025 24X Fiche 50-387.83/05/06.8305190319
- --8305190322 "Sysquehanna Unit 1 Reactor Mode Switch Failure Modes & Mechanisms," final rept
 * Franklin Institute/Franklin Research Center F-A5818-1
 83/04/27 30pp 18301 027 24% Fiche 30-387,83/05/06.8305190319
- 8309200555 Forwards LER 83-063/03L-0 KEIBER: H W Pennsylvania Power & Light Co 83/05/11 ALLAN, J M Region 1, Office of Director 1p 18514 257 24X Fiche 50-387,83/05/11,8305200555
- --B305200561 LER B3-063/03L-0 on B30411.main steam line drain valve leakage exceeded Tech Spec limit Cause not stated Stal ring replaced outboard valve lapped & valves reassembled TODD.J T Pennsylvania Power & Light Co B3/03/11 Region 1. Office of Director 1p 18514 238 24X Fiche 50-387,83/05/11,8305200555
- 8305200640 Forwards LER 83-060/03L-0 KEISER:H W Pennsylvania Power & Light Co 83/05/11 ALLAN:J M Region I. Office of Director ip 18520 150 24X Fiche 50-387:83/05/11.8305200640
- --8305200646 LER 83-060/03L-0 on 830411 reactor protection sys actuation caused Div II of RHR to (solate while in shotdown cooling mode Caused by const worker burgists breaker handle for 4kV safeguard LC X-fmr Cause unknown LER will be updated KUCZYNSKI.L A Pennsylvania Power & Light Co 83/05/11 Region & Office of Director 10 18320 131 24X Fiche 50-387.83/05/11, 8303200640
- DOCKET 50-388 SUSQUEMANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8305040669 Forwards SER on BMR Owners Group generic response to NUREG-0737. Item II K 3, 18. "Mod of Automatic Depressurization Bys (ADS) Logic "Response acceptable w/ stipulated conditions Response requested expediently SCHWENCER, A Licensing Branch 2 83/04/25 CURTIS, N W Pennsylvania Power & Light Co 10pp 18336 338 24X Fiche 50-387.83/04/25.8305040669
- #305110160 Forwards 467 oversize drawings.per Reg Guide 1 70 Drawing transmittal list encl Aperture cards are available in FDR MDLCHANY.W J Pennsqivania Power & Light Co #3704/25 ECHMENCER, A Licensing Branch 2 20pp 18406 318 24X Fiche 50-387.83/04/25,8005110160
- 8305100426 Notification of 830525-27 meetings w/util in Luserne County, PA to assess status of const & completion schedules Meeting on 830525 open to public Agenda encl PERCH.R Licensing Branch 2 83/05/05 SCHWENCER, A Licensing Branch 2 1p 18621 194. 24X Fiche 50-388.83/05/05.8305100426

- 8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FBAR CURTIS,N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER, A Licensing Brench 2. App 18405 100 24% Fiche 50-387, 83/05/05, 8305110097,
- --B305110104 Application for Amend 54 to OLs containing Rev 33 to FBAR = Pennsylvania Power & Light Co B3/05/05 ip 18405 107 24X Ficha 50-387, B3/05/05, B305110097
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENRUT.D 0 Division of Licensing. 83/05/09 Consolidated Edison Co of New York. Inc. 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659
- 8305130114 Forwards responses to questions re-ultimate heat sink test plan Calibr temp measuring device will be used to measure temp in main stilling well in pumphouse Tests will be performed furing Julior Aug 1983 CURTIB,N W Pennsylvania Power & Light Co 83/05/10 SCHWENCER, A. Licensing Branch 2 7pp. 18438-082 24X Fichs 50-387,83/05/10,8305130114
- 8305190285 Advises that util participating in BHR Owners Group Committee to address fast scram issues Due to delays caused by addl testing BHR rept will not be received in time for response in Second Quarter 1783 CURTIS,N W Pennsylvania Power & Light Co 83/05/16 SCHMENCER, A Licensing Branch 2 1p 18501 147 24X Fichs 50-387,83/05/16.
- 8305230541 Advises that util endorses BWR Owners Group rept NEDD-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity "Proposed amend to License NPF-14 will be submitted to reflect position, CURTIS.N W Pennsylvania Power & Light Co 83/05/19 SCHWENCER, A Licensing Sranch 2 2pp 18537 335 24X Fiche 50-387, 83/05/19, 8305230541
- 8303270064 Forwards equipment qualification summary rept Bummary info submitted complete for Unit 1 but only partially complete for Unit 2 Next rev of rept will contain complete info for Unit 2 CURTIS.N W Pennsylvania Power & Light Co 83/05/20 SCHWENCER.A Licensing Branch 2 766pp 18635.095 24X Fiche 50-387.83/05/20, 8305270064
- F Security, medical, emergency & fire protection plans
- B305050285 Releases public version of temporary change to emergency plan procedure. FELTON.J M Division of Rules and Records 83/04/25 Document Management Branch, Ip. 18352 070 24X Fiche 50-387,83/04/25, B305050285
- --8305050289 Forwards public version of Temporary Change 83-575 to Emergency Plan Procedure EP-IP-044, "Emergency Environ Sampling." Receipt form encl + Pennsylvania Power & Light Co 83/04/14 SCHWENCER, A NRC No Detailed Affiliation Given 3pp 18352 071 24X Fiche 50-387,83/04/25,8305050285
- B305130310 Releases public version of rev to emergency plan implementing procedure FELTON.7 M Division of Rules and Records 83/05/02 Document Management Branch ip 18454*237 24% Fiche 50-387.83/05/02. B305130310
- --8305130311 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr # Pennsylvania fower & Light Co 83/04/20 SCHWENCER, A NRC No Detailed Affiliation Given ip 18456 238 24X Fiche 50-387,83/05/02,8305130310
- --8305130314 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr "
 * Pennsylvania Power & Light Co 83/04/20 98pp. 18456 239 24X Fiche 50-387,83/05/02,8305130310
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list enci EIBENNUT. D. O Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095. 24X Fiche. 50-000, 83/05/11, 8305110034

X Utility Final Bafety Analysis Report (FSAR) & amends

- 8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FBAR
 CURTIS.N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER.A
 Licensing Branch 2 6pp 18405 100 24X Fiche 50-387.83/05/05,
 B305110097
- --8305110104 Application for Amend 54 to OLs containing Rev 33 to FBAR $\,$
 - * Pennsylvania Power & Light Co 83/05/05 ip 18405 107 24X Fiche 50-387,83/05/05,8305110097
- --8305110108 Rev 33 to F8AR * Pennsylvania Power & Light Co 83/04/30 323pp 18405 108 24% Fiche 50-387,83/05/05,8305110097
- @ Inspection reports, IE Bulletins & correspondence
- B2120603B5 IE Info Notice B3-14, "Dematered Spent Ion Exchange Resin Susceptability to Evothermic Chemical Reaction "Svc list enc!
 TAYLOR, J.M Division of Bafeguards & Inspection Programs (Post B30103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 1830B-319 24X Fiche 30-000.83/03/21,82120603B5
- 8303040021 IE Info Notice 83-21: "Defective Emergency Use Respirator"
 Evc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22, "BWR Bafety/Relief Valve Failures "
 Bvc list encl
 JORDAN,E i Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co. of New
 York Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing 8ys " 8vc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 117pp 18381 271 24X Fiche 30-000,83/04/25,8303040025
- B303040026 IE Info Notice B3-24: "Loose Parts in Secondary Side of Bteam Generators at PWRs " Evc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047, 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382,165, 24X Fiche 50-000,83/04/29,8303040027
- 8305110149 Notification of 830517 meeting w/util onsite to discuss results of BALP MCCABE, EC Region i, Office of Director 83/04/29 Region i, Office of Director 83/04/29 Region i, Office of Director ip 18421 346 24X Fiche 50-387,83/04/29, 830510149
- 8303060543 Submits addl info re IE Bulletin 82-01.Rev 1.Euppl 1.
 "Alterations of Radiographs of Halds in Piping
 Subassemblies." per B3030 request Three radiographs
 dispositioned per P8I ultrasonic exam, ABME Code Section XI
 CURTIS,N W Pennsylvania Power & Light Co 83/05/02 ALLAN, J M
 Region 1. Office of Director 3pp 18347 306 24X
 Fiche: 50-387, 83/05/02, 8305040343
- B303040028 IE Info Notice B3-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- B303040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." But list end JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382-282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl. JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 117pp. 18441:001. 24X Fiche.50-000,83/05/04.8303040031

- 6303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consulidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/04.8303040033
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of New York. Inc 114pp 18324 003 24X Fichs 50-000,83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18447 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- B305160140 Corrected RO on B21221, actual total activity released was 14 uCf at concentration of 1 37E-5 uCf/ml instead of 4 82 uCf at concentration of 4 7E-6 uCi/ml Release figures well below required reporting limits

 XEISER: H W Pennsylvania Power & Light Co 83/04/29 ALLAN. J M Region 1, Office of Director ip 18446 104 24X

 Fiche 50-387.83/04/29.8305160140
- 8305110258 PNO-1-83-047 on 830504, contractor employee entered roped-off area for radiographic exams of pipe welds & received approx 40 mrem dose No overexposure identified Industrial radiography suspended pending completion of evaluation MCCANN, MCCARE Region 1. Office of Director 83/05/05 ip 18393 290 24X Fiche 50-388,83/05/05,8305110258
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305020590 Forwards Suppl 3 to SER W/o encl KNIGHTON.0 W Licensing Branch 3 83/04/20 UHRIO.R E Florida Power & Light Co 2pp 18284 230 24X Fichs 50-389,83/04/20, 8308020590
- F Security, medical, emergency & fire protection plans
- 8305270289 Forwards 1E Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/03/29 UHR10,R E Florida Power & Light Co 2pp 18638 352 24X Fichs 30-389:83/03/29,8305270289
- --8305270293 IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted Major areas inspected fire protection MILLER.W H. CONLON.Y E Region 2. Office of Director 93/03/2 7pp 19638 354 24X Fiche 50-389, 83/03/29,8305270289
- 8305270098 Forwards IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted. DANCE:H C Division of Project & Resident Programs 83/04/19 UHRT0:R E Florida Power & Light Co 2pp 18662 125 24X Fiche. 50-389:83/04/19
- --8305270101 IE Insp Rept 50-389/83-30 on 830327-0402 No noncompliance noted Major areas inspected cable fire stops, radiation monitors, relay coordination study. IE bulletins & GA audits HUNT, M.D. Region 2. Office of Director CONLON, T.E. Division of Engineering & Radiological Safety Programs 83/04/15 5pp 18662 127 24X Fiche 50-389,83/04/19,8305270098
- 8305030231 Releases public version of revised offnormal & smargancy operating procedures
 FELTON.J M Division of Rules and Records 83/04/22 Document Managament Branch 1p. 18310 077, 24X Fiche 50-389,83/04/22,
- --8305030240 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0120035 repressurizer pressure & level & 2-0760030 re dc ground isolation

 METHY, C M Florida Power & Light Co 83/04/06 Director's Office, Office of Inspection and Enforcement, ip, 18310:078 24X Fichs 50-389, 83/04/22, 8305030231

- ~-8305030244 Public version of revised offnormal & emergency operating procedures, including Procedures 2~0120035 re pressurizer pressure & level & 2~0960030 re dc ground isolation & Florida Power & Light Co. 83/04/05 78pp 18310 079 24X Fiche 50~389,83/04/22,8305030231
- 8305200489 Forwards safequards info re devitalization of certain equipment Info withheld (ref iOCFR73 21) URRIO,R E Florida Power & Light Co 83/04/22. O'REILLY, J P. Region 2. Office of Director ip 18513 007 24X Fichs 50-335,83/04/22,8305200489
- 8305160279 Releases public version of revised emergency plan implementing procedures
 FELTION.JM Division of Rules and Records 83/05/02 Document
 Management Branch 1p 18475.011 24X Fiche 50-389.83/05/02,
 8305160279
- --8305160282 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 2-0030143, "Total Loss of AC Power" & Rev 1 to 2-0120037, "Reactor Coolant Gas Vent Sys Off-Normal Operation."

 WETHY.C M Florida Power & Light Co 83/04/19 Director's Office, Office of Inspection and Enforcement 1p 18475 012 24X Fiche 50-387,83/05/02:8305160279
- --8305160284 Public version of Rev 1 to Emergency Plan Implementing Procedure 2-0030143, "Total Loss of AC Power" & Rev 1 to 2-0120037, "Reactor Coolant Gas Vent Sys Off-Normal Operation"
 4 Florida Power & Light Co 83/04/14 25pp 18475 013 24X Fiche 50-389,83/05/02,8305160279.
- 8305170141 Summary of B30419-22 maetings w/util at site re physical security vital area analysis NERSES, V Licensing Branch 3 69p 18475.325 24% Fichs 50-335.83/05/03,8305170141
- 8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/05/06 UMRIOR E Florida Power & Light Co 2pp. 18641 179 24X Fiche 50-335,83/05/06,8305270287
- --8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected, emergency preparadness in technical support ctr.
 HUFFMAN, O. N. Region 2. Office of Director. 83/05/03 App
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D. 9 Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp 18540-095. 24X Fiche 30-000.83/05/11.8305110034.
- 8305170356 Informs that changes to security plan.per 830405 & 06 ltrs & 830418-22 security meeting commitments, transmitted on 830511 Reevaluation of vital areas for safety-safeguards interface performed.

 URRIGIRE Florida Power & Light Co 83/05/11 EISENHUT, D 0 Division of Licensing ip 18466-104 24X Fiche 50-389, 83/05/11.
- 8305200346 Forwards revised Chapters 5 & 6 to security plan Chapters withheld (ref 10CFR73 21)
 URRIO.R E Florida Power & Light Co 83/05/11 O'REILLY, J P
 Region P. Defice of Director. 2pp 18516 251. 24X
 Fichs 50-335.83/05/11.8305200346
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS, W.J. Office of the Executive Director for Operations, 83/05/13 PALLADINO, N.J. Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13,8305240213
- J Insurance & indemnity information
- 8303030016 Forwards License NPF-16 authorizing operation at 5% power, FR notice. Amends 8.9 & 10 to Indomnity Agreement 8-76 & assessment of license duration EIGENHUT. D 0 Division of Licensing 83/04/06 UHRIO, R. E Florida Power & Light Co. 5pp. 18310 290 24% Fiche 50-389,83/04/06,830030016
- 8305030379 Forwards Endorsement I to NELIA Certificate N-89 & MAELU Certificate M-89 DUCK.U.R Marsh & McLennan, Inc. 83/04/25 SALTZMAN, J Assistant Director for State & Licenses Relations 16pp 18308 200. 24X Fiche. 50-389

- 8305040186 Forwards Endorsements 47 & 37 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively DUCK.JR Marsh & McLennan, Inc. 83/04/29 BALTZMAN, J. Assistant Director for State & Licensee Relations ip 18621 191. 24X Fiche 50-335,83/04/29,8305040186.
- B305100182 Forwards executed Amends 8, 9 & 10 to Indemnity Agreement B-76, adding Orlando Util Commission of City of Orlando,FL & Florida Hunicipal Power Agency & deleting Item 3 of attachment to indemnity agreement, respectively UHRIGAR E Florida Power & Light Co 83/05/05 EIBENHUT,D 0. Division of Licensing 4pp 18374 290 24X Fiche 30-335,83/05/05,8305100182
- P Operating license stage documents & correspondence
- 8305030016 Forwards License NPF-16 authorizing operation at 5% power. FR notice, Amends 8, 9 & 10 to Indemnity Agreement 8-76 & assessment of license duration EISENHUT. D 0 Division of Licensing 83/04/06 UHRIQ.R.E Florid. Power & Light Co 5pp 18310-290 24% Ficher 50-389, 83/04/06, 830507016
- --8305030019 License NPF-16.authorizing operation at 5% power DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/06 45pp 18310 275 24% Fiche 50-389.83/04/06.8305030016
- --8303030022 Notice of issuance of License NPF-16 KNIGHTON.9 W Licensing Branch 3 83/04/06 3pp. 18310-340 24X Fichs.50-389,83/04/06,8305030016
- 8305060278 Forwards Amend 1 to License NPF-16. safety evaluation & notice of issuence & availability. Amend changes channel functional test surveillance requirements for wide-range logarithmic neutron flux monitor KNIONTON. 9. W Licensing Branch 3 83/04/22 UHRIO. R E Florid. Power & Light Co. 2pp 18353 068 24X Fiche 50-389.83/04/22. 8305060278
- --B303060303 Amend 1 to License NPF-16, changing channel functional test surveillance requirements for wide-range logarithmic neutron flux monitor
 KNIGHTON, 9 W Licensing Branch 3 83/04/22, 7pp 18353.070.
 24x Fiche 50-389,83/04/22,8305060298
- --8305060308 Safety evaluation supporting Amend 1 to License NPF-16.

 Office of Nuclear Reactor Regulation, Director, 83/04/22. 1p 18353 077 24X Fiche 50-389,83/04/22,8305060298
- --8305060312 Notice of issuance & availability of Amend 1 to Licanse NPF-16 BUCKLEY-B. Licensing Branch 3. 83/04/22 3pp. 18353'078 24X Fiche 50-389,83/04/22,8305060298.
- 8305020455 Generic Ltr 83-i9 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list enci.
 EISENHUT, D Ø Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441.120 24X
 Fiche 50-000.83/05/02.8305020455
- B303040323 Board Notification B3-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications B3-17 & B3-44 re Unrasolved Safety Issue A-17.

 EIGENHUT, D Ø Division of Licensing, B3/05/04 PALLADINO, N. Commissioners 22pp 18337.139 24X Fiche 50-000, B3/05/04, B305040323
- 8305070659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mode Sec list enci EISENRUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153. 24X Fiche: 50-000.83/05/09.8303090659
- 8305130118 Advises that mode to purge sys not required, Sufficient margin exists to allow check valve to perform intended safety Function I time closes out 5% of rated thermal power portion of License Condition 2 C B
 URRIGIR E, Florida Power & Light Co 83/05/10 EISENHUT, D Ø
 Division of Licensing 2pp. 18438.057, 24% Fiche 50-389,83/05/10,8305130118
- 8305270251 Forwards revised FSAR Table 7.3-9 indicating effects EBF actuation sys devices have on plant operation Table will be incorporated into Amend 14 to FSAR scheduled for 830808. UHRIO:R E Florida Power & Light Co 83/05/14. EISENHUT, D. O Division of Licensing. 3pp. 18637.149 24X Fiche 50-389,83/05/14,8305270251

- 8305250455 Confirms that OE AK-2 scram breakers used at San Unofre also in use at facility UHR10.R E Florida Power & Light Co 83/05/20 EISENHUT.D G Division of Licensing 1p 18585 210 24x Fiche 50-389,83/05/20, 8305250455
- 8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4
 Detailed Control Room Design Reviews Program Plan," per
 630415 commitment re Suppl 1 to NNREO-0737
 UHR10,R E Florida Power & Light Co 83/05/20 EISENHUT,D Q
 Division of Licensing ip 18588 333 24X Fiche 50-000,83/05/20,
 6305250472
- --8305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan " + Floride Power & Light Co 83/04/30 34pp 18588: 334 24X Fiche 50-000.83/05/20,8305250472
- 8305260381 Requests remittance of two Class III fees for review of 830422 application to amend License NPF-i6.changing requirements for principle secondary coolants & requirements for wide-range logarithmic neutron flux monitor DIOOS,R M License Fee Menagement Branch 83/05/20 UHRIG.R F Florida Power & Light Co. 1p 18647 247 24X Fiche 50-389, 83/05/20,8305260381
- 8305270104 Forwards summary of calculations performed to determine flood level inside containment, in response to NRC request for add1 info re util 830510 ltr UHRIG.R E Florida Power & Light Co 83/05/25 EISENHUT, D G Division of Licensing 6pp 18638 244 24X Fiche 50-387,83/05/25,8305270104.
- 8305270125 Forwards resolution of Item I C re remote shutdown damonstration prior to initial criticality.per Region II request Item closed Requests Region II be notified of concurrence following review UHRTO, R E. Florida Power & Light Co. 83/05/25 EIBENHUT, D O Division of Licensing 3pp 18638-218 24X Fiche 50-389,83/05/25,8306370125
- 8305270153 Forwards add1 info re turbine trip circuitry at facility Turbine manual trip initiated in control room by depressing pushbutton PB/170 located on RTQ board 201 UHRIO.R E Florida Power & Light Co 83/05/25 EISENHUT, D G Division of Licensing. 3pp 18638.156 24X Fiche 50-389,83/05/25,8305270153
- 8305310184 Forwards list of resolved license conditions for initial criticality Post-fuel load initial test program initiated, including criticality & low power testing described in Chapter 14 to FSAR
 UHRIO.R E Florida Power & Light Co 83/05/26 EISENHUT, D. Q.
 Division of Licensing opp 18658 162 24X Fiche 30-389,83/05/26,8305310184
- Q. Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.U.M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8305270289 Forwards IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/03/29 UHRID,R E Florida Power & Light Co 2pp 18638 352 24X Fiche. 50-389,83/03/29,8305270289
- --8305270293 IE Insp Rept 50-389/83-17 on 830301-04 No honcompliance noted Major areas inspected fire protection.
 MILLER, N. H., CONLON, T. E. Region 2, Office of Director 83/03/28 7pp. 18638, 354 24X Fiche: 50-389, 83/03/29, 8305270289.
- 8305270310 Forwards IE Insp Rept 50-389/83-18 on 830308-11 No noncompliance noted DANCE,H.C. Division of Project & Resident Programs *83/03/30 UHRIO,R E. Florida Power & Light Co 2pp 18641*167 24X Fiche: 50-389, 83/03/30, 8305270310
- --8305270315 IE Insp Rept 50-389/83-18 on 830308-11 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys. AMO,W P., BLAKE,J J Region 2, Office of Director, 83/03/29 App. 18641-169 24X Fiche 50-389,83/03/30,8305270310

- 8305270447 Forwards IE Insp Rept 50-389/83-19 on 830307-11 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/04/04
 UHRIO, R E Florida Power & Light Co 2pp 18642 245 24X
 Fiche 50-389,83/04/04,8305270447
- --8305270453 IE Insp Rept 50-389/83-19 on 830307-11 No noncompliance noted Major areas inspected plant & maint procedure review, evaluation of integrated hot functional test results & reactor protection sys test results evaluation TAYLOR.P A Region 2. Office of Director JAPE.F Division of Engineering & Radiological Bafety Programs 83/03/30 App 18842 247 24X Fiche 50-389, 83/04/04/8305270447
- 8305270361 Forwards IE Insp Repts 30-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted DANEE, H C Division of Project & Resident Programs 83/04/06 UHRIO, R E Florida Power & Light Co 2pp 18645 321 24X Fiche 30-335.83704/06.8305270561
- --B305270576 IE Insp Repts 50-335/B3-10 & 50-389/B3-25 on B30316-18 No noncompliance noted Major areas inspected Unit 1 plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items HRAY, J R , BARR.K P Region 2, Office of Director 83/04/05 Bpp 18645 323 24X Fiche 50-335,B3/04/06,B305270561
- 8305270559 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-02 & 50-389/03-09

 LEWIS.R C Division of Project & Resident Programs 83/04/14

 UHRIO.R E Florida Power & Light Co 1p 18647 127 24X

 Fiche 50-335.83/04/14,8305270359.
- --8305270579 Forwards IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 & notice of violation LEHIE,R C Division of Project & Resident Programs 83/03/01, URIO,R E Florida Power & Light Co 2pp 18647 133 24X Fiche 50-335,83/04/14,8305270559
- --8305270594 IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 Noncompliance noted failure to follow procedures required by training programs & failure of licensed operators to be cognizant of facility design, procedures & license changes BELIBLE, G A., BKINNER, P H., UPRIGHT, C M. Region 2, Office of Director 83/02/24 9pp 18647 137 24X Fiche 50-335.83/04/14, 8305270559
- B303040021 IE info Notice B3-21. "Defective Emergency Use Respirator "
 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co. of New
 York, Inc. 124pp 18435 155 24X Fiche: 50-000, B3/04/15, B303040021
- B305270240 Forwards IE Insp Rept 50-389/B3-24 on B30321-24 No noncompliance noted DANCE:H C Division of Project & Resident Programs B3/04/15 UHRIO:R E Florida Power & Light Co 2pp 18637 162 24X Fiche. 50-389:83/04/15:8305270240
- --B305270245 IE Insp Rept 50-389/83-24 on 830321-24 No noncompliance noted Major areas inspected test results for integrated ESF test.RCS leakage monitoring test & plant tour TAYLOR.P A Region 2, Office of Director JAPE.F Division of Project & Resident Programs B3/04/15 3pp 19637 164 24X Fiche 50-389,83/04/15,8305270240
- 8305270098 Forwards IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/04/19 UHRTO:R E Florida Power & Light Co 2pp 18462 125 24X Fichs 50-389:83/04/19:8305270098
- --8305270101 IE Insp Rept 50-389/83-30 on B30329-0402 No noncompliance noted Mejor areas inspected, cable fire stops, radiation monitors, relay coordination study, IE bulletins & QA audits HUNT.M D Region 2, Office of Director CONLON.T.E. Division of Engineering & Radiological Sefety Programs 83/04/15 5pp 18662 127 24% Fiche.50-389,83/04/19,8305270098
- 8305270349 Ack receipt of 830330 ltr informing NRC of steps teken to correct violations noted in IE Insp Rept 50-389/83-06 LEWIS,R C. Division of Project & Resident Programs 83/04/19 UHRIG,R E Floride Power & Light Co 1p 18642 113 24X Fiche.50-389,83/04/19,8305270349
- ---8305270360 Responds to NRC 830301 itr re violations noted in IE Insp. Rept 50-389/83-06 Corrective actions bolting repts from inception of const completion group to 830218 being reviewed & civil const activity QA insps reviewed UHRIO.R E. Florida Power & Light Co. 83/03/30 O'REILLY, J. P. Region 2. Office of Director, 4pp 18642-114 24X Fiche 50-389, 83/04/19, 8305270349

- --8305270363 Forwards IE Insp Rept 50-389/83-06 on 830110-27 & notice of violation
 LEWIS,R C Division of Project & Resident Programs 83/03/01
 UHRIO,R E Fiorida Power & Light Co 3pp 18842 118 24X
 Fiche 50-389,83/04/19,8305270349
- --8305270371 Notice of violation from insp on 830110-27 * Region 2, Office of Director 83/03/01 2pp. 18442 120 24x Fiche 50-389,83/04/19,8305270349
- --8305270379 IE Insp Rept 50-389/83-06 on 830110-27 Noncompliance noted inadequate procedure for accomplishing final civil structural turnover & failure to fullow procedures for insp of structural steel.

 LENAHAN, J , CONLON, T E Region 2. Office of Director 83/02/18 App 18642 122 24X Fichs 50-389.83/04/19.8305270349
- B303040023 IE Info Notice B3-22. "BWR Bafety/Relief Valve Failures "
 Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp. 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B305270359 Forwards IE Insp Repts 50-335/83-07 & 50-389/83-21 on B30314-18 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/04/26 UHRIO,R E Florida Power & Light Co 2pp 18642 128 24X Fiche 50-335,83/04/26,8305270359
- ---8305270367 IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No nancompliance noted Major areas inspected local leak rate testing, snubber testing & review of Unit 1 procedures re refueling aperations
 HHTTENER, H L . MATHIS, J . JAPE, F Region 2, Office of Director 83/04/21 &pp 18642 130 24X Fiche 50-335,83/04/26,8305270359
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice B3-25, "Standby Gas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8305270507 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/83-13 LEMIS,R C Division of Project & Resident Programs 83/05/02, UKRIG,R E Florida Power & Light Co 1p 18645 256 24X Fiche 30-389,83/05/02,8305270507
- --8305270520 Responds to violations noted in IE Insp Rept 50-389/83-13 Corrective actions GC inspector given verbal & written reprimend & need for strict compliance discussed at weekly electrical inspectors meeting
 URRIO, RE Florida Power & Light Co 83/04/08 O'REILLY, J P Region 2, Office of Director 2pp 18645 257 24X Fiche 50-389,83/05/02.8305270507
- ---8305270527 Forwards IE Insp Rept 50-387/83-13 on 830201-04 & notice of violation LEMIS, RC Division of Project & Resident Programs 83/03/08 URRIO, RE Florida Power & Light Co 2pp 18645 259 24X Fiche 50-387,83/05/02,8305270507
- --8305270535 Notice of violation from insp on 830201-04
 * Region 2, Office of Director 83/03/08 ip 18645 261 24X
 Fich 50-389,83/05/02,8305270507
- --B305270542 IE Insp Rept 50-387/83-13 on B30201-04 Noncompliance noted failure to follow procedures for insp of safety-related cables

 HERRIHEATHER, N. OIBBONS, T.D. Region 2, Office of Director CONLON, T.E. Division of Project & Resident Programs 83/03/03

 -- 18645 262 24X Fichs 50-389, B3/05/02, B305270507
 - E Info Notice 83-26, "Failure of Safety/Relief Valve line Vacuum Breakers " Bvc list enc1 Division of Emergency Preparedness & Engineering "Dat 8301033. 83/05/03 Consolidated Edison Co. of New 122pp 18441.170 24% Fiche 50-000.83/05/03,8303040028

- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305270176 Forwards IE Insp Rept 50-389/83-28 on 830405-08 No noncompliance nated DANCE, H C Division of Project & Resident Programs, 83/05/05 UHRIO, R E Florida Power & Light Co 2pp 18638 024 24X Fiche 50-389,83/05/03,8305270176
- --8305270179 IE Insp Rept 50-389/83-28 on 830405-08 No noncompliance noted Major areas inspected nonconformance control sys & review of as-built drawings COLEY, J. L. WRIGHT, R. W. HERDT, A. R. Region 2, Office of Director, 83/05/02 5pp 18638 026 24X Fiche 50-389,83/05/05,8305270176
- B305270232 Forwards IE Insp Rept 50-387/83-31 on 830309-10 & 0402 & 07 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/05 URKIG, R E Florida Power & Light Co 2pp 18637,200 24X Fichs 50-389,83/05/05,8305270232
- --8305270236 IE Insp Rept 50-389/83-31 on 830309-10 & 0402 & 07.No noncompliance noted Major areas inspected civil turnover program, piping analysis & cable tray bolting requirements LENAMAN, J J. CONLON T E. Region 2. O
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24% Fiche 50-000,83/05/06,8303040033
- B305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/06 UHRIG: R E Florida Power & Light Co 2pp 18641 179 24X Fiche 50-335.89/05/06/8305270287
- --8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected emergency preparedness in technical support ctr HUFFMAN, 0 N Region 2, Office of Director JENKINB, 0 R Division of Emergency Preparedness & Materials Safety 83/05/03, 4pp. 18641 181 24X Fiche 50-335,83/05/04,8305270287
- 8305270329 Forwards IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/06 UHRIO.R E Florida Power & Light Co 2pp 18641 131, 24X Fiche 50-335,83/05/06,8305270329
- --B305270339 IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted Major areas inspected inservice insp (Unit 1):core barrel/thermal shield demage (Unit 1):welding & NDE (Unit 1) & preservice insp (Unit 2)
 CROWLEY, B R , BLAKE, J J Region 2. Office of Director 83/05/02 9pp 18641 133 24% Fiche 50-335,83/05/06,8305270329
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Praparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, B3/05/11, 8303040034
- 9303040040 IE Info Natice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 93/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Conteminated Oil " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 114pp 18447 007 24X Fiche, 50-000, 83/05/26, 8303040046

- R Períodic operating reports & related correspondence
- 830503034i Forwards Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept,1982" UHRIGAR E Florida Power & Light Co 83/04/28 MULLER, D.R. NRC -No Detailed Affiliation Olven 1p 18307 OO1 24X Fiche 50-335,83/04/28,830503034i
- --B305030347 Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept.1982" * Applied Biology, Inc. AB-442 83/03/31 406pp 18307 004 24% Fiche 50-335,83/04/28,8305030341
- 8 Reportable occurrences, LERs & related correspondence
- 8305030304 Final Deficiency Rept B3-007 re condensate storage tank damage Initially reported on B30322 Caused by condensation of steam creating local vacuum conditions Double butt welded plates installed, cracks sealed & designs improved UHRIO.R E Florida Power & Light Co 83/04/21 O'REILLY, J P Region 2. Office of Director App 18296 194 24X Fiche 50-389.83/04/21,8305030306.
- B303030604 Interim deficiency rept re Westinghouse gate valve premature indication of valve closure Initially reported on B30223. Util evaluating condition & will submit final rept by B20504

 URRIGAR E Florida Power & Light Co B3/04/25 O'REILLY, J P Region 2, Office of Director 1p 18303 342 24X

 Fichs 50-389, 83/04/25, 8305030604
- 8305100088 Interim deficiency rept re failure of two safety-related Agastat relays to time out properly & installation of incorrect Agastat relay on diesel generator Initially reported on 83030 Investigation angoing URRIQ:RE Florida Power & Light Co 83/04/27 D'REILLY:JP Region 2. Office of Director 2pp 18377 223 24% Fiche 50-369.83/04/29.8305100088
- 8305100227 Final deficiency rept re loss of continuity on mineral insulated cable assemblies Initially reported on 830330 Twantu-three cable assemblias w/defective connectors repaired Deficiencies not reportable per iOCFR50 55(e) UHRIG.R E Florida Power & Light Co 83/04/29 0'REILLY, J P Ragion 2. Office of Director 2pp 18373 286 24X Fiche 50-389,83/04/29,8303100227
- 8305100269 Forwards LER 83-001/01T-0 WILLIAMS, J W. Florida Power & Light Co 83/05/02 O'REILLY, J P Region 2. Office of Director 1p 18371 331 24X Fiche: 50-389, 83/05/02, 8305100269
- --B305100278 LER 83-001/01T-0 on 830416.during fuel movement.both amergency generators discovered out-of-svc Caused by personnel error in establishing out of svc log Logs reviewed & periodic surveillance procedure revised WALLING.0 E. Florida Pawer Corp 83/05/02 Region 2. Office of Director 3pp. 18371 332 24X Fiche 50-389.83/05/02.8305100269
- 8305170191 Forwards LER 83-003/03L-0 WILLIAMS J W. Florida Power & Light Co 83/05/09 O'REILLY J P Region 2. Office of Director ip 18466'326 24X Fiche 50-389,83/05/09,8305170191
- --8305170197 LER 83-003/03L-0 on 830412, following initial core load, low pressure safety injection pump A tripped off Condition resulted in loss of operation of shutdown cooling loop A Caused by personnel error Technician reinstructed VALDES A florida Power & Light Co 83/05/09. Region 2, Office of Director 1p 18466 327 24X Fiche. 50-389, 83/05/09, 83005170191
- B305170310 R0 389-83-005 on B30507, safety injection tank isolation valves closed w/plant in Mode 4 above 276 psia Gaused by personnel error. Procedural step overlooked during plant heatup Valves immediately opened WETHY.C.M Florida Power & Light Co 83/05/09. © REILLY, J P Region R. Office of Director ip 18463 187 24X Fiche: 30-369, 83/05/09, 8305170310
- 8303200181 Final deficiency rapt re premature indication of valve closure of Westinghouse gate valves Initially reported on 830223. Configuration represents normal design condition Condition not reportable per 10CFR80 55(4)

 UHRIQ.R.E Florida Power & Light Co. 83/05/11 O'REILLY, J P Region 2. Dffice of Director 3pp 18517 064 24X
 Fiche: 50-389, 83/05/11, 8305200181

- B305200430 PNU-II-83-040 on B30515, two util employees & one former employee arrested for cocaine & marijuana possession arrest occurred offsite Employees not involved in licensed operator activities

 LANDIS, K D. DANCE, H C. Region 2. Office of Director 19 18517 150 24X Fiche 50-335, B3/05/17, B305200430
- 8305290416 Clarifies B30418 final deficiency rept re diesel generator start relay defect Addl indication provided to indicate to control room when master control switch, located in diesel generator bldg, is in stop position
 UHRIG.R E Florida Power & Light Co 83/05/19 O'REILLY, J P Region 2, Office of Director ip 18583 359 24X
 Fiche 50~389,83/05/19,8305250416
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B305030121 Forwards three oversize flow diagrams illustrating mods to chemical feed lines, in response to NRC request MILLS.L M Tennessee Valley Authority B3/04/22 ADENSAM, E Licensing Branch 4 2pp 18298 138 24X Fiche 50-370, 83/04/22, 8305030121
- 8305030A0A Forwards response to Oeneric Ltr 83-10C re program for resolution of NUREO-0737. Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps " Pump trip can be achieved safely & reliably by operator, when required MILLS.L M Tennessee Valley Authority 83704/22 ADENSAM.E Licensing Branch 4 Bpp 18303 172 24X Fiche 50-390.83/04/22,8305030604
- B305030041 Forwards responses to 821201 request for add1 info re Items 1 b.1 g.5 a & 5 c of Branch Technical Position CBD 6-4. Info includes opening supply & exhaust lines & seismic design category of debris screens MILLS.L M Tennessee Valley Authority B3/04/26 ADENBAM, E Licensing Branch 4 4pp 18300 352 24X Fiche 50-390, B3/04/26. B305030041
- 8305030434 Forwards comments on LLL preliminary sys interaction results from diagram matrix analysis of safety injection sys Terminology used in rept not common to industry & should be defined at first ref MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM, E Licensing Branch 4 3pp 19292 151 24X Fiche 50-390,83/04/26,8305030434
- 8305040253 Informs that consequences of unmitigated boron dilution event meets acceptance criteria for postulated accidents. Control room contains adequate audible & discrete info to determine boron dilution event MILLS.L.M Tennessee Valley Authority 83/04/29 ADENSAM.E Licensing Branch 4 2pp 18323 247 24X Fiche 50-390.83/04/29, 8305040253
- B305090659 Opneric Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mode Bvc list encl EISENHUT, D 0 Division of Licensing B3/05/09 Consolidated Edison Co of New York, Inc 16pp 18627-153 24X Fiche 30-000,83/05/09,8303090659
- B305200325 forwards evaluation results re-potential for liquefaction of soils beneath essential raw cooling water pipelines
 Bite-specific ground motion & modified seed & Idriss (1981)
 procedure discussed Proposed 830520 meeting agenda encl
 MILBIL M Tennessee Valley Authority 83/05/17 ADENSAM.E
 Licensing Branch 4 3pp 18517 043 24X Fiche 50-390,83/05/17,
 B305200325
- 8305240660 Notification of 830519 meeting w/util in Silver Spring.MD to discuss proposed application of watch tower power block concept KENYON.T J Licensing Branch 4 83/05/17 ADENBAM.E & Licensing Branch 4 4pp. 18593 174 24X Fiche 50-390.83/05/17.8305240660
- B305230624 Recommends meeting, within 30 days receipt of ltr, to discuss util plans for completing environ qualification program NOVAK,T M. Assistant Director for Licensing B3/05/18 PARRIS,H Q Tennessee Valley Authority 3pp 18543 035 24X Fiche 30-390, B3/05/18, B305230624
- 8305250425 Responds to 830401 ltr re environ qualification of safety-related mechanical equipment located in harsh environ areas. Schedule proposed by NRC for list of mechanical equipment i month prior to site audit cannot be supported MILLS, L M Tennessee Valley Authority 83/05/19 ADENSAM, E Licensing Branch 4 3pp 18585 265 24X Fiche 50-390, 83/05/19, 8305250425



- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B305030543 Forwards list of safety-related electrical components, respective functions & summery of data used to establish satpoints for balance-of-plant equipment, per BER Section 7 i 3 i Info completes action per SER Confirmatory Item 21 KAMMER, D S Tennesse Vallay Authority 83/04/25 ADENBAM, E Operating Reactors Branch 4 326pp 18302 001 24x Fiche: 50-390, 83/04/25, 8305030543
- 8305130020 Forwards add1 justification required by SER (NUREO-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities MILLS.L M Tennesses Valley Authority 83/05/10 ADENSAM.E Licensing Branch 4 4pp 18437.129 24X Fiche 50-390.83/05/10.8305130020
- 8305310039 Forwards info reschedule for steam generator mods, per SER (NUREG-0847) design changes.

 MILLS.L M Tennessee Valley Authority 83/05/27 ADENSAM, E Licensing Branch 4 2pp 18653 307 24X Fiche 30-390.83/05/27, 8305310039
- F Security, medical, emergency & fire protection plans
- 8305090409 Forwards IE Safeguards Insp Rept 50-390/83-12 on 830418-22 No noncompliance noted VERRELLID Division of Project & Resident Programs 83/05/06 PARRIS, H G Tennessee Valley Authority 2pg 18363 062 24x Fiche 50-390,83/05/06,8305090409
- --8305090418 IE Safeguerds Insp Rept 50-390/83-12 on 830418-R2 No noncompliance noted, Major areas inspected, security plan requirements re barrier between facilities & proposed watchtowers Details withheld (ref 10CFR73 21)
 MOORE D E. Region 2, Office of Director. MGCURE, D R Division of Emergency Preparadness & Materials Safety, 83/05/06 ip 18363 064. 24X Fichs 50-390,83/05/06.8305070409.
- 8303110034 Operatic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EIBENHUT.D 9. Division of Licensing 83/05/11 Consolidated Edison Co of New York Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for CL reviews for Apr 1983 DIRCKS M. J. Office of the Executive Director for Operations 83/05/13. PALLADING, N. J. Commissioners 5pp 18593 322 24X Fiche 30-000, 83/05/13, 8305240213
- B305270228 Ack receipt of B30509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 VERRELLI, D M Division of Project & Resident Programs. B3/05/19 PARRIS, H G Tennessee Valley Authority ip 18637 193 24X Fiche: 50-390, 83/05/19, 8300370228
- --8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp. Repts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance KAMMER.D 8. Tennessee Valley Authority. 83/05/09 D'REILLY, J. P. Region 2. Office of Director 2pp 18637 196 24X Fiche 50-390,83/05/19.8305270228
- 83053(0187 Forwards physical security plan Plan withheld (ref 100F873 21) Revs requested within 40 days of ltr receipt ADENSAME 0 Licensing Branch 4 83/05/24 PARRIS. H 0 Tennessee Valley Authority. 2pp. 18651:002. 24X Fiche:50-390,83/05/24,83053(0187
- O. Advisory Committee on Reactor Befeguards reports & correspondence
- 8303130270 Summary of 248th ACRS meetings on 820812-14 in Nashington,DC was ACRS Advisory Committee on Reactor Safeguards, 83/05/05 ACRS Advisory Committee on Reactor Safeguards, 527pp. 18438,225 24% Fiche: 50-000,83/05/05,8305190270

- Q Inspection reports, IE Bulletins & correspondence
- 8305270133 Suppls 830117 response to notice of violation contained in IE Insp Repts 50-390/82-35 & 50-391/82-32 Corrective actions any necessary revs to operating div instructions will be made as appropriate MILLS,L H Tennessee Valley Authority 83/03/18 O'REILLY, J P Region 2. Office of Director 2pp 18638 208 24X Fiche 50-390,83/03/18,8309270133
- 8212060385 IE Info Natice 83-14, "Dewatered Spent Ion Exchange Resin 80sceptibility to Exothermic Chemical Reaction " Syc list ancl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8305270290 Forwards IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/03/23 PARRIS,H & Tennesses Valley Authority 2pp 18445 344 24X Fiche 50-390,83/03/23,8305270290
- --B305270303 IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted Major areas inspected followup on licensee identified items, licensee action on previous enforcement matters & independent insp effort HEATHERLY, T L., SMAN, W. Region 2, Office of Director. QUICK, D Division of Project & Resident Programs 83/03/22 9pp 18645 346 24X Fiche 50-390,83/03/23,8305270290
- 8305270651 Forwards IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs. 83/04/11 PARRIS, H G Tennessee Valley Authority 2pp 18646; 344 24X Fiche 50-390, 83/04/11, 8305270651
- --8305270457 IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No moncompliance noted Major areas inspected licensee action on previous enforcement matters independent inspeforts; preservice insp & safety-related structure; COLEY, J. L. BLAKE, J. Region 2, Office of Director 83/04/06 12pp 18446-346 24X Fiche 50-390,83/04/11,8305270651
- B303040021 IE Info Natice B3-21, "Defective Emergency Use Respirator" Bvc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/15 Consolidated Edison Co of New Yerk, Inc 126pp 18435 135 24X Fiche 50-000, B3/04/15, B303040021
- 8305270540 Forwards IE Insp Rept 50-390/83-09 on 830329-0401 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/04/15 PARRIS,H G Tennessee Valley Authority 2pp 18646 332 24X Fiche 50-390,83/04/15,8305270540
- --B305270562 IE Insp Rept 50-390/83-09 on 830329-0401 No noncompliance noted Major areas inspected, preoperational test procedure review preoperational test witnessing & followup on previous enforcement matter THOMAS, M., MATHIS, J.L., JAPE, F. Region 2, Office of Director B3/04/14 4pp 18446 334 24X Fiche 50-390,83/04/15,8305270540
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list entl
 JORDANNE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24x Fiche 50-000,83/04/22,8303040023
- B303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York
- 8303040024 IE Info Notice 83-24. "Loose Parts in Secondary Side of Bteam Generators at PHRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp, 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28. Consolidated Edison Co of New York, Inc 118pp 18382 165 24x Fiche 50-000,83/04/28,8303040027

- 8305270557 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
 VERRELLI.D M Division of Project & Resident Programs 83/05/02 PARRIS.H 9 Tennessee Valley Authority in 18646-116 24X Fiche 50-390/83/05/02,8305270557
- --R305270547 Second supplemental response to NRC B21216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions drawings will be revised to reflect mark numbers of ae-installed dampers by B30430 MILLS.L M Tennessee Valley Authority B3/04/11 0'REILLY, J P Region 2. Office of Director ip 18646 117 24X Fiche 50-390, B3/05/02, B305270557
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Reponse (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8302040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 30-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN:E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fichs 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Bvc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305070409 Forwards IE Safeguards Insp Rept 50-370/83-12 on 830418-22 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 83/05/06 PARRIS, H 0 Tennessee Valley Authority 2pp 18363 062 24X Fiche. 50-370, 83/05/04, 8305090409
- --8303090418 IE Safeguards Insp Rept 50-370/83-12 on 830418-22 No noncompliance noted Major areas inspected security plan requirements re barrier between facilities & proposed watchtowers Details withheld (ref 10CPR73 21)

 MOORE D E Region 2, Office of Director MCOUIRE, D R Division of Emergency Preparedness & Materials Safety 83/03/06 ip 18363.064 24X Fiche.50-390,83/03/06,8305090407.
- 8305270413 Forwards IE Insp Repts 50-390/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted, VERRELLI,D M Division of Project & Resident Programs 83/05/09. PARRIS,H G. Tennessee Valley Authority, 2pp. 18642,279 24X Fiche 50-390,83/05/09,8305270413
- --B305270420 IE Insp Repts 50-390/83-10 & 50-391/83-08 on B30411-15 No noncompliance noted Major areas inspected licensee action on previous enforcement matters licensee identified items, inspector followup items & independent insp effort QIBBONS.T.D., CONLON.T.E., Region 2, Office of Director B3/05/06, 4pp 18642,301 24X Fiche.50-390,83/05/09,8305270413
- 8303040034 IE Info Natice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Ouidelines " Bvc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Cansolidated Edison Co of New York, Inc. 114pp. 18524.003 24X Fiche. 50-000, 83/05/11, 8303040034
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Svc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103), B3/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009, 24X Fiche: 50-000, B3/05/19, B303040040.
- 8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 UERRELLI, D. M. Division of Project & Resident Programs. 83/05/19. PARRIS.H Q. Tennessee Valley Authority ip 18637.195. 24X Fiche: 50-390/83/05/19, 8305270228.
- --B305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20, Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance KAMMER, D. B Tennessee Valley Authority B3/05/09 D'REILLY, J. P Region 2, Office of Director 2pp 18637, 196, 24X Fiche, 50-390, 83/05/19, 8305270228

- B303040046 IE Info Notice B3-33. "Nonrepresentative Sampling of Contaminated Dil" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York
- 8 Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of D9-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME, E.P. Westinghouse Electric Corp. 83/04/21 DEYOUNG, R.C. Director's Dffice. Dffice of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427
- 9305030072 First interim deficiency rept re toose matl in steam generator Initially reported on 830325 All loose items & matl determined detrimental removed from generators Next rept expected by 830808
 MILLS,L M Tennessee Valley Authority 83/04/25 0'REILLY, J P Region 2. Office of Director 2pp 18300 349 24X
 Fiche 50-390.83/04/25,8305030072
- 8305030082 Becond interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 GA documents being prepared to substantiate insulation data Next rept expected by 830921 MILLBL. M Tennessee Valley Authority 83704/25 O'REILLY, J P Region 2, Office of Director 2pp 18397 237 24X Fiche 50-370,83/04/25,8305030082
- B305030578 First interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on B30327 Program being modified to automatically calculate direction cosines Next rept to be submitted by B30923 MILLS,L M Tennessee Valley Authority B3/04/26 D'REILLY, J P Region 2, Office of Director 2pp 18303 309 24X Fiche 50-370.83/04/26.8305030578
- B305050067 Ninth interim deficiency rept re seismic qualification for chillers/coolers & deficient piping of HVAC sys & improper classification of ERCH sys piping & components Initially reported on Bi0324 & 0507. respectively Next rept due B30829 MILLELL M Tennessee Valley Authority B3/04/27 D'REILLY, J P Region 2. Office of Director 4pp 18342 042 24X Fiche 30-390,83/04/27,8305050067
- 8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
 MILLS,L H Tennessee Valley Authority 83/04/27 D'REILLY,J P. Region P. Office of Director 3pp 18341 083 24X
 Fiche 50-000,83/04/27,8303050152
- 8303050232 Second combined interim deficiency rept re alternate analysis piping program Significant breakdown of program requires reverification of alternate analysis Full review program underway Next rept expected by 830930 MILLS, L. M Tennessee Valley Authority 83/04/27 O'REILLY, J P Region 2. Office of Director 5pp 18337 329 24% Fiche 50-390,83/04/27,8305050232
- 8305050078 First interim deficiency rept re spacing & clearance in high pressure fire protection sprinkler sys in auxiliary bldg Initially reported on B3031 Evaluation in progress Next rept will be sent by 830624 MILLS.L.M Tennessee Valley Authority 83/04/28 O'REILLY, J. P. Region 2. Office of Director 2pp 18342, 150 24X Fiche 50-390, 83/04/28, 8305050078
- B30505018B First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per QA program Initially regorted on B30327 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by B30706 MILLS,L M Tennessee Valley Authority B3/04/28 D'REILLY, J P Region 2, Office of Director 2pp 18341 076 24X Fichs. 30-000,83/04/28,830505018B
- 8305050243 Third interim deficiency rept re high point venting in ERCW sys Initially reported on 820930 Performance evaluation ongoing. Nest rept will be submitted by 830729 MILLS,L M Tennessee Valley Authority 83/04/28 O'REILLY, J P Region 2. Office of Director ip 18338 036 24X Fiche. 50-390.83/04/28.8303050243
- 8305030047 Fourth interim deficiency rept re questionable patches of plastic cement morter. Initially reported on 820429 Three of 50 supports determined to be in violation of Const Bpec G-32. Next rept will be submitted by 830805 MILLS.L M Tennessee Valley Authority 83/04/29 O'REILLY, J P Region 2. Diffice of Director 1p 18339 330 24X Fiche 50-390.83/04/29.8305050047.

- 8305110317 Seventh interim deficiency rept re lack of documentation for rock supported structures for 1-inch differential settlement. Initially reported on 810707 Design criteria being prepared Next rept by 830922 MILLS, L M, Tennessee Valley Authority 83/05/04 O'REILLY, J P Region 2, Office of Director 3pp 18393 183 24X Fiche 50-390.83/05/04.8305110317
- 8305110319 First interim rept re Deficiencies 1.2 & 3 GA program per TVA Personal Svcs Contract TV-49510A w/011bert Assoc Written instructions & procedures not provided to contractor in performing/documenting prining analysis Review underway MILLS.L M Tennesses Valley Authority 83/05/05 0'REILLY, J P Region 2. Office of Director 3pp 18393 181 24X Fiche 50-000,83/05/05,8305110319
- B305130133 Supplemental info to final deficiency rept re insufficient dacumentation for protective devices Initially reported on B10313 Completion date for corrective actions delayed until B30531 One field change request remains MILLS.L M Tennessee Valley Authority 83/05/06 O'REILLY, J P Region 2, Office of Director ip 18437 279 24X Fiche 50-390.83/05/06.8305130133
- 8305i302i7 Addl info to final deficiency rept re nonconservative calculation method for general Const Spec 6-32 Initially reported on BR0528 Rev to Design Std DS-C6 i will be issued by 830630 MILLS.L M Tennessee Valley Authority 83/05/06 O'REILLY.J.P Region 2, Office of Director ip 18440 089 24X Fiche 50-390, 83/05/06, 8305i302i7
- 8305170288 Second interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 Scope of investigation synamode to include generic implications Next rept expected by 830922 MILLS:L M Tennessee Valley Authority 83/05/07 D'REILLY, J P Region 2. Defice of Director 2pp 18465 071 24X Fiche 50-390,83/05/09,8305170288
- 8305170299 Final deficiency rept re lack of support for reactor bldg annulus floor drain sump Initially reported on 821207 Fipes analyzed & appropriate seismic supports designed under Engineering Change Notice ECN 3234 MILLS.L M Tennessee Valley Authority 83/05/07 D'REILLY, J P. Region 2. Office of Director 2pp. 18465 066 24X Fiche 50-390,83/05/09,8305170299
- 8303200274 Revised final deficiency rept re unqualified control aquipment Initially reported on 800922 Control equipment seismic qualification test requirements will be reviewed MILLS.L M Tennessee Valley Authority 83/05/11 O'REILLY, J P. Region 2. Office of Director 2pp 18518 074 24X Fiche. 50-390.83/05/11,620200274
- 8305200275 Eighth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 New Engineering Procedure SWP-EP 43 22 written Drawings containing reviewed & updated quality issued, MILLGLL, M Tennesse Valley Authority 83/05/11 0'REILLY, J P. Region 2, Office of Director ip 18516 318 24K Fiche 50-390.83/05/11.8305200275
- 6305200343 Suppl to final deficiency repts to Class IE electrical components for ERCM traveling screens Initially reported on Bi051B Qualified motor search continues Corrections to be completed by 831001 MILLBIL M Tennessee Valley Authority, 83/05/11 O'REILLY, J P. Region 2, Office of Director 1p 18516 232 24X Fithe 50-390,83/05/11,8305200343
- 8303230575 Final deficiency rept re missing seismic design documentation for auxiliary bldg platform. Initially reported on 820426 Required drawing revs completed. Field mods will be completed by 830801 & 840214 for Units 1 & 2, respectively MILLERL M Tennesses Valley Authority 83/05/13 0'REILLY, J P. Region 2. Office of Director 20p 18537 307 24X Fiche: 50-390, 83/05/13,8305230575,
- 8305200387 Second revised final deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Previous decision re nonapplicability of IOCFRSO 55(e) sustained MILLSIL M Tennesses Valley Authority 83/05/16 D'REILLY, J.P. Region 2. Office of Director. 2pp 18517.086, 24X Fiche. 50-390, 83/05/16, 8305200387
- 8305230482 Third interim deficiency rept re incorrect supports in analysis of 3-inch chemical vol & control sys line Initially reported on 830505 Addi problems identified Field mode required. Next rept will be submitted by 830922 MILLSIL. M Tennessee Valley Authority 83/05/17 0'REILLY, J. P. Region 2. Office of Director 2pp 18537 149 24X Fiche 50-390, 83/05/17, 8305230482

- 8305230493 Final deficiency rept re inadequate freeze protection Initially reported on 810413 Piping to ERCW pump motor cooler redesigned to be self-draining MILLS:L M Tennessee Valley Authority 83/05/18 O'REILLY, J P Region 2. Office of Director 2pp 18538 212 24X Fichs 50-390:83/05/18.8305230433
- 8305230447 Second interim deficiency rept re auxiliary instrument room fire door failure Initially reported on 821229 Lower flush bolt not engaged in strike plete at floor Acceptance criteria established for mex room pressures MILLS:L M Tannesse Valley Authority 83/05/18 0'REILLY,JP. Region 2. Office of Director 2pp 18538 194 24X Fiche 50-390.83/05/18.8305230447
- B305230569 Fifth interim deficiency rept re excessive movement of containment penetration bellows initially reported on B11204 Analysis Problems N3-63-74 & N3-74-14 reanelyzed Support mods required Next rept due by B30930 MILLS.L.M. Tennasses Valley Authority B3/05/18. D'REILLY, J. P. Region 2. Office of Director 1p 18536-318 24X Fiche 50-390,83/05/18,8305230569
- 830525042i First interim deficiency rept re qualification of nozzle loads in reactor coolant loop Initially reported on 83042i, Review of analysis problems in progress, Next rept by 83092i, MILLSI, M TEDRILLY Valley Authority 83/05/19 0'REILLY, J.P. Region 2, Office of Director 2pp 18585 263 24X Fiche 50-390,83/05/19,830525042i.
- B305250435 Final rept re deficiencies in Ameron cement mortar lining. Initially reported on 820521 Corrections to each deviation listed Also reportable per 100FR21. MILLS.L.H Tennessee Valley Authority B3/05/20 D'REILLY, J P Region 2, Office of Director App 18585 273 24X Fiche 50-390,83/05/20,8305250435
- 8305310172 Second interim deficiency rapt re failure of curtain-type fire dampers to close Initially reported on 821025 Engineering change notice issued to add negator closure springs & positive latches MILLS.L M Tennessee Valley Authority. 83/05/23 O'REILLY, J. P Region 3. Office of Director ip. 18658-147 24X Fiche 50-390,83/05/23,8305310172

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8305030121 Forwards three oversize flow diagrams illustrating mode to chemical feed lines, in response to NRC request, MILLS,L M Tennessee Valley Authority 83/04/22, ADENBAM,E Licensing Brench 4 2pp. 18298-138 24X Fiche-50-390,83/04/22, 8305030121.
- B303030606 Forwards response to Generic Ltr 83-10C re program for resolution of NUREQ-0737, Item II K 3, 5, "Automatic Trip of Reactor Coolant Pumps." Pump trip can be achieved safely k reliably by operator, when required.

 MILLS, L M Tennessee Valley Authority 83/04/22 ADENSAM, E, Licensing Branch 4. Bpp 18303:172 24X Fiche. 50-390, 83/04/22, 8305030606
- 8305030041 Forwards responses to 821201 request for add1 info re Items 1.5.1 g.5 a & 5 c of Brench Technical Position CSB 6-4 Info includes opening supply & exhaust lines & seismic design category of debris screens MILLS/L M Tennessee Valley Authority 83/04/26 ADENBAM, E. Licensing Brench 4, 4pp 18300,352, 24X Fiche,50-390,83/04/26,8305030041
- 8305030434 Forwards comments on LLL preliminary sys interaction results from diagram metrix analysis of safety injection sys.

 Terminology used in rept not common to industry & should be defined at first ref
 MILLS,L M Tennesses Valley Authority, 83/04/26, ADENBAM,E.

 Licensing Branch 4 3pp 18292:151 24X Fiche: 50-390,83/04/26,8305030434
- 8305040253 Informs that consequences of unmitigated boron dilution event meets acceptance criteria for postulated accidents. Gontrol room conteins adequate audible & discrete info to determine boron dilution event MILLS: L.M. Tennesses Valley Authority B3/04/29. ADENSAM. E Licensing Branch 4. 2pp 18323 247. 24X Fiche. 50-390. 83/04/29. 8305040253
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci ETBENHUTD, 0 Division of Licensing, 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153, 24X Fiche 50-000,83/05/09,8305090659

- 8305200325 Forwards evaluation results re potential for liquefaction of soils beneath essential raw cooling water pipelines Site-specific ground motion & modified seed & Idriss (1981) procedure discussed Proposed 830520 meeting agenda encl MILLS, L M Tennessee Valley Authority 83/05/17 ADENSAM. E Litensing Branch 4 3pp 18517 043 24X Fiche 50-390,83/05/17,8305200325
- B305240660 Notification of B30519 meeting w/util in Silver Spring.MD to discuss proposed application of watch tower power block concept KENYON.T J Licensing Branch 4 B3/05/17 ADENSAM.E 0 Licensing Branch 4 4pp 18593 174 24X Fiche 50-390.83/05/17.8305240660
- 8305230624 Recommends meeting, within 30 days receipt of ltr, to discuss util plans for completing environ qualification program NOVAK.T M 'Assistant Director for Licensing 83/05/18 PARRIS.H G Tennessee Valley Authority 3pp 18543:035 24X Fiche 50~370,83/05/18.8305230624
- 8305250425 Responds to 830401 ltr re environ qualification of safety-related mechanical equipment located in harsh environ areas. Schedule proposed by NRC for list of mechanical equipment 1 month prior to site audit; cannot be supported HILLS, L M Tennessee Valley Authority 83/05/19 ADEMSAM. ELicansing Branch 4. 3pp 18585 265 24X Fiche 50-390,83/05/19,8305250425
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305030543 Forwards list of safety-related electrical components, respective functions & summary of data used to establish setpoints for balance-of-plant equipment, per SER Section 7 1.3 1.1nfo completes action per SER Confirmatory Item 21 KAMMER, D 9 Tennessee Valley Authority 83/04/25 ADENSAM, E Operating Reactors Branch 4 32/4pp 18302 001 24X Fiche 50-390,83/04/25,8305030543
- 8305130020 Forwards addl justification required by SER (NUREO-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities MILLB, L M Tennessee Valley Authority 83/05/10 ADENSAM. E Licensing Branch 4 4pp 18437 129 24X Fiche 50-390,83/05/10.8305130020
- B305310039 Forwards info re schedule for steam generator mods, per SER (NUREG-0847) design changes MILLS, L.M Tennessee Valley Authority B3/05/27 ADENSAM, E Licensing Branch 4 2pp 18653 307 24X Fiche 50-390, 83/05/27, 8305310039.
- F. Sacurity, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EIBENHUT, D. G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 15pp 18540 075 24X Fiche 50-000,83/05/11,8305110034
- 8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 UERRELLI, D M Division of Project & Resident Programs 83/05/19 PARRIS, H Q Tennessee Valley Authority ip. 18637:195. 24X Fiche: 50-390.83/05/19,8305270228
- --8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Rapts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adaquate. Two dampers not in compliance KAMMER, D S Tennessee Valley Authority 83/05/07 O'REILLY, J. P. Region 2, Office of Director 2pp. 18637-196 24X Ficha 50-390,83/05/19,8305270228
- 8305310187 Forwards physical security plan, Plan withheld (ref 10CFR73 21) Revs requested within 40 days of ltr receipt. ADENSAM: E. & Licensing Branch 4 B3/05/24. PARRIS, H. @ Tennessee Valley Authority 2pp 18651 002 24X Fiche 50-390, 83/05/24. 8305310187
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington.DC

 * ACRS - Advisory Committee on Reactor Safeguards 83/05/05 ACRS - Advisory Committee on Reactor Safeguards 529pp, 18458:223 24% Fiche: 50-000, 83/05/05,8303130290.

- O Inspection reports, IE Builetins & correspondence
- B305270133 Supple B30117 response to notice of violation contained in IE Insp Repts 50-390/82-33 & 50-391/82-32 Corrective actions any necessary reve to operating div instructions will be made as appropriate MILLS,L M Tennessee Valley Authority B3/03/18 D'REILLY,J P Region 2. Office of Director 2pp 18638 208 24X Fiche 50-390.03/03/18.0305270133
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000,83/03/21,8212060385
- 8305270290 Forwards 1E Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/03/23 PARRIS,H 0 Tennessee Valley Authority 2pp 18645 344 24X Fiche 50-390,83/03/23,8305270290
- --B305270303 IE Insp Repts 50-390/B3-06 & 50-391/B3-05 on B30122-0222 No noncompliance noted Major areas inspected followup on licensee identified items, licensee action on previous enforcement matters & independent insp effort HEATHERLY, T. L., SWAN, W. Region 2, Office of Director GUICK, D Division of Project & Resident Programs B3/03/22 9pp 18645 346 24% Fiche 30-390, B3/03/23, B305270290
- 8305270651 Forwards IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/04/11 PARRIS,H 0 Tennesses Valley Authority 2pp 18646 344 24X Fiche 50-390,83/04/11.8305270651
- --B305270639 IE Insp Repts 50-390/83-05 & 50-391/83-04 on B30228-0304 & 15-18 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent insp efforts, preservice insp & safety-related structures COLEY.J L : BLAKE.J J Region 2, Office of Director 83/04/06 12pp 18646 346 24X Fiche 50-390.83/04/11.8305270651
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Bteam Generators at PWRs " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/2B Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8305270557 Ack receipt of 830411 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 UERRELLI.D M Division of Project & Resident Programs. 83/05/02 PARRIS.H G Tennessee Valley Authority 1p. 18646-114 24X Fiche 50-390.83/05/02.8305270557
- --8305270567 Second supplemental response to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions drawings will be revised to reflect mark numbers of as-installed dampers by 830430.

 MILLS.L M Tennessee Valley Authority 83/04/11 O'REILLY.J P Region 2. Office of Director 1p 18446:117 24X Fiche 50-390.83/05/02.8305270557

- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 30-000,83/03/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New Yort, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Nutice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06.8303040033
- 8305270413 Forwards IE Insp Repts 50-370/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/09 PARRIS:H G Tennessee Valley Authority 2pp 18642 299 24X Fiche 50-390/83/05/09/8305270413
- --8305270420 IE Insp Repts 50-370/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, licensee identified items, inspector followup items & independent inspector followup items & independent inspector B3/05/06 App 1842 301 24% Fiche 50-390.83/05/09/8305270413
- 8303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN:E L D(vision of Emergency Preparedness & EngineFring Response (Post 830)03) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JURDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 VERRELLIO M Division of Project & Resident Programs 63/05/19 PARRIS.H 0 Tennessee Valley Authority ip 18637.195 24X Fiche 50-390.83/05/19.8305270228
- --B305270233 Responds to NRC B21216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance KAMMER.D S Tennessee Valley Authority B3/05/09 O'REILLY.J P Region 2. Office of Director 2pp 18637 176 24X Fiche 50-390,83/05/19.8305270228
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Byc list enc!
 JURDAN/E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York
- S Reportable occurrences: LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices u/widented grooves to accommodate new retaining rings Mfg drawings revised RAHE, E. P. Westinghouse Electric Corp. 83/04/21 DEYQUNO, R. C. Director's Office, Dffice of Inspection and Enforcement, 5pp 18405 095 24X Fiche 30-000,83/04/21,8305110427
- 8305030072 First interim deficiency rept re loase matl in steam generator Initially reported on 830325 All loase items & matl determined detrimental removed from generators Next rept expected by 830808 MILLS.L M Tennessee Valley Authority, 83/04/25 0'REILLY.J P Region 2. Defice of Director 2pp 18300,349 24X Fiche 50-390,83/04/25,8305030072

- B305030082 Second interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 OA documents being prepared to substantiate insulation data Next rept expected by B30921 MILLS.L M Tennessee Valley Authority B3/04/25 O'REILLY, J P Region 2. OFfice of Director 2pp 18397 239 24X Fiche 30-390.83/04/25.8305030082
- 8305030378 First interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830329 Program being modified to automatically calculate direction cosines Next rept to be submitted by 830783 MILLS,L H Tennessee Valley Authority 83/04/26 O'REILLY,J P. Region 2. Office of Director Rpp 18303 309 24X Fiche 50-390,83/04/26,8305030578
- B305050067 Ninth interim deficiency rept re seismic qualification for chillers/coolers & deficient piping of HVAC sus & improper classification of ERCH sus piping & components Initially reported on B10324 & 0507, respectively Next rept due B30829, MILLS,L M Tennessee Valley Authority B3/04/27 O'REILLY,J P Region 2, Office of Director 4pp 18342 062 24X Fiche 50-390,83/04/27,8305050067
- 8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on B10316
 MILLB,L H Tennessee Valley Authority 83/04/27 D'REILLY, J P Region 2, Office of Director. 3pp 18341 083 24X Fiche 50-000,83/04/27,8305050132
- 8305050232 Second combined interim deficiency rept re alternate analysis piping program Significant breakdown of program requires reverification of alternate analysis. Full review program underway Next rept expected by 830930.

 MILLS.L M Tennassee Valley Authority 83/04/27 D'REILLY, J. P. Region 2. Office of Director 3pp 18337 329 24X Fiche 50-390.83/04/27.8305050232
- 8305050078 First interim deficiency rept re spacing & clearance in high pressure fire protection sprinkler sys in auxiliary bidg. Initially reported on 830331 Evaluation in progress Next rept will be sent by 830624 MILLS.L M Tennessee Valley Authority 83/04/28. O'REILLY, J. P. Region 2. Dffice of Director 2pp 18342 150 24X Fiche 50-390,83/04/28.8305050078
- B305050188 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per GA program Initially reported on B30329 Investigation of involved carbon stael fittings & flanges continuing Next rept expected by B30706.
 MILLE,L M Tennessee Valley Authority B3/04/28 O'REILLY, J. P. Region 2. Dffice of Director 2pp. 18341 076 24X Fiche 50-000, B3/04/28, 8305050188
- B305050243 Third interim deficiency rept re high point venting in ERCH sys. Initially reported on 820730 Performance evaluation ongoing Next rept will be submitted by 830729.

 MILLS,L M Tennesse Valley Authority 83/04/28 O'REILLY, J P Region 2. Office of Director 1p 18338 056 24X Fiche 50-390.83/04/28,8305050843.
- 8305050047 Fourth interim deficiency rept re questionable patches of plastic cament mortar Initially reported on 820429 Three of 50 supports determined to be in violation of Const Spec G-32 Next rept will be submitted by 830805.

 MILLS.L M. Tennessee Valley Authority, 83/04/29, 0'REILLY, J P. Region 2. Dffice of Director. ip 18338,330 24X Fiche 50-390.83/04/29,8305050047.
- 8305110505 Final deficiency rept re incorrectly wired ERCW flow control valves. Initially reported on 830405 Event determined isolated condition caused by misinterpretation of conduit drawings Operators rewired & personnel reinstructed MILLS,L M Tennessee Valley Authority 83/05/03 0'REILLY, J. P. Region 2, Office of Director 2pp 18405, 046 24X Fiche: 50-391, 83/05/03, 8305110505
- B305110317 Seventh interim deficiency rept re lack of documentation for rock supported structures for i-inch differential settlement Initially reported on B10707, Design criteria being prepared Next rept by B30722 MILLS,L M Tennessee Valley Authority B3/05/04, O'REILLY, J P Region 2, Office of Director 3pp 18373:183 24X Fiche: 50-370, B3/05/04, B305110317.
- 8305110319 First interim rept re Deficiencies 1,2 & 3 GA program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc.Written instructions & procedures not provided to contractor in performing/documenting piping analysis.Review underway MILLS.L M Tennessee Vallay Authority 83/05/05 D'REILLY, J P Region 2, Office of Director. 3pp 1839:181. 24X Fiche 50-000,83/05/05,8305110319.

- 8305130133 Supplemental info to final deficiency rept re insufficient documentation for protective devices Initially reported on 810313 Completion date for corrective actions delayed until 830531 One field change request remains MILLS, L M Tennessee Valley Authority 83/05/06 O'REILLY, J P Region 2, Office of Director ip 18437 279 24X Fiche 50-390,83/05/06,8305130133
- 8305130217 Add1 info to final deficiency rept re nonconservative calculation method for general Const Spec G-32 Initially reported on 820528 Rev to Design Btd D3-C4 1 will be issued by 830630 MILLS.L M Tennessee Valley Authority 83/05/06 D'REILLY.J P Region 2, Office of Director ip 18440 089 24X Fiche 50-390.83/05/06.8305130217
- 830517028B Second interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on B30117 Bcope of investigation expanded to include generic implications Next rept expected by 830922 MILLS.L M Tennessee Valley Authority B3/05/09 0'REILLY.J P Region 2. Office of Director 2pp 18465 071 24X Fiche 50-390.83/05/09.8305170288
- B305170299 Final deficiency rept re lack of support for reactor bldg annulus floor drain sump Initially reported on 821207 Pipes analyzed & appropriate seismic supports designed under Engineering Change Notice ECN 3234
 MILLB.L H Tennessee Valley Authority 83/05/09 O'REILLY, J P Region 2. Office of Director 2pp 18465 066 24X
 Fiche 50-390,83/05/09,8305170299
- 8305200274 Revised final deficiency rept re unqualified control equipment Initially reported on 800722 Control equipment , seismic qualification test requirements will be reviewed MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P Region 2. Office of Director 2pp 18518 094 24X Fiche 50-390,83/05/11,8305200274
- 8305200275 Eighth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 New Engineering Procedure BHP-EP 43 22 written Drawings containing reviewed & updated quality issued MILLB,L M Tennessee Valley Authority 83/03/11 D'REILLY,J P Region 2, Office of Director 1p 18516 318 24X Fiche 50-390,83/05/11,8305200275
- 8305200343 Suppl to final deficiency repts re Class IC electrical components for ERCW traveling screens Initially reported on 810518 Qualified motor search continues Corrections to be completed by 831001 MILLS.L M Tennessee Valley Authority 83/05/11 O'REILLY.J P Region 2. Defice of Director 1p 18516 232 24X Fiche 50-370.83/05/11.8305200346
- B305230575 Final deficiency rept re missing seismic design documentation for auxiliary bldg platform Initially reported on B20426 Required drawing revs completed Field mods will be completed by B30801 & 840214 for Units 1 & 2, respectively MILLS, L M Tennessee Valley Authority B3/05/13 0'REILLY, J P Region 2, Dffice of Director 2pp 18537 309 24X Fiche 50-390,83/05/13,8305230575.
- B305200387 Second revised final deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on B20607 Previous decision re nonapplicability of 10CFR30 55(e) sustained MILLS,L M Tennesses Valley Authority B3/05/16 D'REILLY,J P Region 2, Office of Director. 2pp 1B519 086 24X Fiche 50-390,B3/05/16,B305200387
- 8305230482 Third interim deficiency rept re incorrect supports in analysis of 3-inch chemical vol & control sys line Initially reported on 830505 Addl problems identified Field mods required. Next rept will be submitted by 830722 MILLS.L M Tennessee Valley Authority. 83/05/17 O'REILLY, J P Region 2. Defice of Director 2pp. 18537 147 24X Fiche, 50-390, 83/05/17, 8305230482
- 8305230493 Final deficiency rept re inadequate freeze protection Initially reported on 810413 Piping to ERCW pump motor cooler redesigned to be self-draining MILLS.L M Tennessee Valley Authority 83/05/18 O'REILLY.J.P. Region 2. Diffice of Director , 2pp 18538 212 24% Fiche.50-390,83/05/18.8305230433
- B305230447 Second interim deficiency rept re auxiliary instrument room fire door failure Initially reported on B21227 Lower flush bolt not engaged in strike plats at floor Acceptance criteria established for max room pressures
 MILLB,L H Tennessee Valley Authority B3/05/18 O'REILLY,J,P
 Region 2. Office of Director 2pp 18538'174. 24X
 Fiche 50-390,B3/05/18,B305230447

- 8305230569 Fifth Interim deficiency rept re excessive movement of containment penetration belious Initially reported on 811204 Analysis Problems N3-63-74 & N3-74-1A reanalysed Support mods required Next rept due by 830930 MILLS.L M Tennessee Valley Authority 83/05/18 0'REILLY.J P Region 2. Office of Director 1p 18536-318 24X Fiche 50-390,83/05/18,8305230569
- 8305250421 First interim deficiency rept re qualification of nazzle loads in reactor coolant loop [Initially reported on 830421 Review of analysis problems in progress Next rept by 830921 MILLS,L M Tennessee Valley Authority 83/05/19 O'REILLY, J P Region 2. Office of Director 2pp 18585 263 24X Fiche 50-390/83/05/19,8305250421
- B305230435 Final rept re deficiencies in Ameron cement mortar lining Initially reported on B20521 Corrections to each deviation listed Also reportable per 10CFR21 MILLS,L M Tennessee Valley Authority 83/05/20 O'REILLY, J P Region 2. Office of Director 6pp 18585 273 24X Fiche 50-390.83/05/20,8305250435
- 8305310172 Second interim deficiency rept re failure of curtain-type fire dampers to close Initially reported on 821025 Engineering change notice issued to add negator closure springs & positive latches MILLS,L M Tennessee Valley Authority 83/05/23 D'REILLY, J P Region 3, Office of Director 1p 18658 149 24X Fiche 50-390,83/05/23,8305310172
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

 E NRC Safety Evaluation Report (SER), supple & correspondence
- B305200513 Summarizes B30510 telcon, clarifying SER description of feedwater mod isolation logic Reverse flush valves provided W/Class IE Trains A & B closure signals DIXON, O W Gouth Carolina Electric & Gas Co B3/05/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 18516 086 24X Fiche 50-395,83/05/12,8305200513
- F Security, medical, emergency & fire protection plans
- B303030010 Advises that position concerning nonestablishment of backup emergency operations facility (EUF) unacceptable Flans to establish EOF by B30601 must be submitted & must meet NUREG-0737, Buppl 1 (Generic Ltr 82-33) criteria EIBENRUT.D 0 Division of Licensing B3/04/25 DIXON,O W South Carolina Electric & Gas Co 3pp 18310 353 24X Ficho 50-395,83/04/25,8305030010
- B305050311 Releases public version of rev to emergency plan implementing procedures FELTON.J M Division of Rules and Records B3/04/25 Document Management Branch 1p 18352 185 24X Ficho 50-395,83/04/25.
- --B305050317 Forwards public version of Rev 5 to Emergency Plan
 Implementing Procedure EPP-002, "Communication &
 Notification" & Change I to Rev 1 of EPP-020, "Emergency
 Personnel Exposure Control "
 DIXON.O W South Carolina Electric & Oas Co 83/03/25
 DENTON.H R. Diffice of Nuclear Reactor Regulation, Director 2pp
 18352 186 24X Fiche 50-395,83/04/25.8305050311
- --8305030321 Public version of Rev 5 to Emergency Plan Implementing Procedure EPP-002, "Communication & Notification" & Change 1 to Rev 1 of EPP-020, "Emergency Personnel Exposure Control "CCUNTS, M , BRADHAM, A & Bouth Carolina Electric & Qes Co 89/09/15. 40pp 18352 188 24X Fiche 50-375,83/04/25,8305050311
- B305270436 Forwards IE Insp Rept 50-395/B3-07 on B30314-17 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/04/25 DIXON,O W South Carolina Electric & Gas Co 2pp 18662 115 24X Fiche:50-395/B3/04/25/B305270436
- --8305270446 IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted Major areas inspected coordinated emergency response exercise

 CLINE, W.E., STANSBERRY, W.W. Region 2. Office of Director JENKINS, O.R. Division of Emergency Preparedness & Materials Safety 83/04/14. 8pp 18462 117 24X Fiche 50-395,83/04/25,8305270436
- 830506013D Forwards Amend 15 to License NPF-12, safety evaluation & notice of issuance & availability Amend changes Tech Bpec to reflect add1 fire protection equipment Installed & actual location & number of fire detectors.

 ADENSAM.E 0 Licensing Branch 4 83/04/27 DIXON.O W South Carolina Electric & Oas Co 2pp 18359 310 24X

 Fiche 50-395.83/04/27,8305060130

- --8305060282 Amend 15 to License NPF-12.changing Tech Spec to reflect add1 fire protection equipment installed actual location & number of fire detectors & location of water spray & sprinkler sys
 ADENBAM.E Q Licensing Branch 4 83/04/27 15pp 18359 312 24X Fiche 30-395.83/04/27,8305040130
- ---8305060288 Safety evaluation supporting Amend 15 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 18359 327 24X Fiche 30-395,83/04/27,8305060130
- --B305060P95 Notice of issuance & availability of Amend 15 to License NPF-12 ADENSAM,E G. Licensing Branch 4 B3/04/27 3pp 18359 329 24X Fiche 50-395,83/04/27,8305060130
- 8305090454 Forwards IE Safeguards Insp Rept 50-395/83-13 on B20903-B30406 No noncompliance noted O'REILLY, J.P. Region 2. Office of Director B3/05/06 DIXON, O W Bouth Carolina Electric & Gas Co. 2pp 18362 261 24X Fiche: 50-395, 83/05/06, 8305090454
- --B305090461 IE Safeguards Insp Rept 30-375/83-13 on 820703-830406. No noncompliance noted Hajor areas inspected licensee revalidation of preemployment screening records Details withheld (ref 10CFR73 21)
 TOBINN J. PERNY.C. LANKFORD.J. Region 2, Office of Director 83/05/04 ip 18362 263 24X Fiche 50-375,83/05/06.8305070454
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034
- 8305180373 Requests exemption from Generic Ltr 82-33 requiring backup emergency operations facility to be located within 10 to 20 miles of plant site Approval requested to have backup emergency operations facility at corporate ofc DIXON.O W South Carolina Electric & Gas Co 83/05/16 DENTON.H F Office of Nuclear Reactor Regulation, Director 2pp 18486 357 24X Fiche 50-395,83/05/16,8305180373
- P Operating license stage documents & correspondence
- 8305040010 Informs that relief from preservice hydrostatic tests required by ASME Code Section IX justifiable Alternative program incorporating NRC evaluation will provide acceptable level of structural integrity SER & FR notice forwarded NOVAK.T M Assistant Director for Licensing 83/04/22 DIXON.O W South Carolina Electric & Gas Co 2pp 18351 216 24X Fiche 30-375, 83/04/22.8305040010
- --8305040016 Safety evaluation supporting util request for relief from preservice hydrostatic test required by ASME Code Section IX

 NRC NRC** NRC** NRC** NRC** Affiliation Given 83/04/22 4pp
 18351 218 24X Fiche 50-395.83/04/22,8305040010
- --8305040021 Notice of granting of relief from certain requirements of ASME Code Section IX inservice (testing) requirements ADENSAM.E O Licensing Branch & 83/04/22. 3pp 18351:222 24X Fiche 50-395,83/04/22.8305040010
- 8305030014 Requests remittants of Class III fees for 830127 & 0218 applications requesting relief from requirements of ASME Code Section XI re hydrostatic testing of feedwater sys DIOGS R M License Fee Management Branch 83/04/26 DIXON, O W Bouth Carolina Electric & Gas Co ip 18310:348 24X Fiche 30-395,83/04/26,8305030014
- 8305040130 Forwards Amend 15 to License NPF-12, safety evaluation 2 notice of issuance & availability Amend changes Tech Spec to reflect add1 fire protection equipment installed & actual location & number of fire detectors ADENSAN.E G Licensing Branch 4 83/04/27 DIXON.O W South Carolina Electric & Oas Co 2pp 18357 310 24X Ficher 50-395.83/04/27,8305040130
- --8305060282 Amend 15 to License NPF-12 changing Tech Spec to reflect add1 fire protection equipment installed actual location & number of fire detectors & location of water spray & sprinkler sys ADENSAM.E Q Licensing Branch 4 83/04/27 15pp 18359 312 24X Fiche 50-395,63/04/27,8305060130
- --8305060288 Bafety evaluation supporting Amend 15 to License NPF-12
 * Office of Muclear Reactor Regulation, Director 83/04/27 Rp;
 18359 327. 24% Fiche.50-395.83/04/27,8305060130

- --8305060295 Notice of issuance & availability of Amend 15 to License NPF-12 ADENBAM.E G Licensing Branch 4 83/04/27 3pp 18359 329 24X Fiche 50-395,83/04/27,8305060130
- B305020455 Generic Ltr B3-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Bvc list encl EISENHUT, D G Division of Licensing B3/05/02 Consolidated Edison Co of New York, Inc 50pp 18441/120 24% Piche 50-000, B3/05/02. B305020455
- B305040619 Discusses steam generator mod to OL Conditions 2 C(14) & 2 C(32) Loose parts monitoring program & monitoring of feedwater inlet pressure oscillations clarified, per B30413 & O214 ltrs, respectively DIXON.O W South Carolina Electric & Oas Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16348 355. 24X Fiche 50-395, B3/05/03, B305060619
- 8305110136 Advises that action required by 830203 on Amend 9.Paragraph 3.to License NPF-12 & Generic Ltr 83-07 completed based on util negotiating u/DDE re disposal of high level waste or spent nuclear fuel ADENSAM.E G Licensing Branch 4 83/05/03 DIXON.O W South Carolina Electric & Oas Co · 2pp 18421 255 24X Fiche 50-395.83/05/03.8305110136
- B305100301 Informs of completion of evaluation of piping associated w/ feadwater mod.piping break blowdown, pipe whip. jet impingement & reactive forces to assure FSAR commitments unchanged DIXON.O N South Carolina Electric & Oas Co. B3/05/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18971.249 24X Fiche 50-395.83/05/04.8305100301
- B303200113 Forwards request for add1 info on util rept. "Beismic Confirmatory Program for Equipment & Components for VC Bummer Nuclear Station Feb 1983, "submitted in response to OL Condition 2 C(2)

 ADENSAME 9 Licensing Branch 4 83/05/04, DIXON, O W South Carolina Electric & Oas Co 3pp 18540 318 24X

 Fiche 50-395,83/05/04,8303200113
- B305180012 Forwards Amend 16 to License NPF-12, safety evaluation & notice of issuance & availability Amend permits operation of modified Model D-3 steam generators

 ADENSAM; E. G. Licensing Branch 4 B3/05/05 DIXON, D. W. Bouth Carolina Electric & Gas Co. 4pp 18497, 138 24X

 Fiche 50-395, 83/05/05, 8305180012
- ---B3051B0015 Amend 1& to License NPF-12.permitting operation of modified Model D-3 steam generators
 EIBENHUT, D O Division of Licensing B3/05/05 Spp. 18497 142.
 24% Fiche 50-395,83/05/05,83051B0012
- --8305180020 Bafety evaluation supporting Amend 16 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 83/05/05 10ap 18497 147 24X Ficha 50-395,83/05/05,8305180012
- --8305180023 Notice of issuance & availability of Amend 16 to License NPF-12 ADENSAM, E 0. Licensing Branch 4 89/05/05 3pp 18497 157. 24X Fiche 50-395,83/05/05,8305180012
- B305070657 Generic Ltr B3-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mode. Svc list encl EISENRUT, D 0 Division of Licensing. B3/05/09, Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000.83/05/09,8305070659
- 8305180442 Forwards fees for reviews of two separate requests for relief from ASME Code Section XI requirements DIXON.O W South Carolina Electric & Gas Co 83/05/12 DIQQ8,R W License Fee Management Branch 2pp 18486 181 24X Fiche 50-395,83/05/12.8305180442
- 8305250492 Formards list of Class IE electric equipment important to safety, per 10CFR50. 49. Schedule for environ qualification of remaining equipment encl DIXON.O H South Carolina Electric & Oas Co 83/05/17 DENTON.H R D
- 8305310224 Requests add1 fee based on Class III determination for Amend 16 to License NPF-12, permitting operation of modified Model D-3 steam generators. DIGOS,R M License Fee Management Branch 83/05/24 DIXON, D, W Bouth Carolina Electric & Oas Co 1p 18662 260 24X Fiche: 50-395, 83/05/24, 8305310224,

- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent ton Exchange Resin Busceptibility to Exothermic Chemical Reaction " Bvc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post

TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% Fiche 50-000.83/03/21.8212040385

- 8305270412 Ack receipt of 830329 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-01 LEWIS/R C Region 2, Office of Director 83/04/11 DIXON.D W Bouth Carolina Electric & Gas Co 1p 18642 OO1 24X Fiche 50-395/83/04/11,8305270412
- --B205270422 Responds to NRC B30301 ltr re violations noted in IE Insp Rept 50-395/83-01 Corrective actions cross-ref table being prepared identifying reactor trip & ESF actuation sys instrumentation test procedures DIXON.O W Bouth Carolina Electric & Oas Co 83/03/29 O'REILLVIJ P. Region 2. Office of Director 3pp 18642-002 24X Fiche 50-395,83/04/11.8303270412
- --8305270433 Forwards IE lnsp Rept 50-395/83-01 on 830105-31 & notice of violation
 LEWIS,R C Division of Project & Resident Programs 83/03/01
 DIXON,D W South Carolina Electric & Gas Co 2pp 18642 005
 24X Fiche 50-395,83/04/11,8305270412
- --8305270443 Notice of violation from insp on 830105-31 * Region 2, Office of Director 83/03/01 ip 18642 007 24X Fiche 50-375.83/04/11.8305270412
- --8305270462 IE Insp Rept 50-395/83-01 on 830105-31 Noncompliance noted failure to comply w/action statement for ESF actuation SKOLDS, J L Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 63/02/18 8pp 18642 008 24X Fiche 50-395,83/04/11,8305270412
- 8305270431 Ack receipt of 830314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-04 VERRELLI.D M Division of Project & Resident Programs 83/04/13 DIXUN.O W South Carolina Electric & Gas Co 1p 18641 346 24) Fichs.50-395,83/04/13,8305270431
- --8305270441 Responds to NRC 830214 violations noted in IE Insp Rept 50-395/83-04 Corrective actions containment equipment hatch area will be posted w/rigid sign DIXON.O W Bouth Caroline Electric & Gas Co 83/03/14 D'REILLY, J.P. Region 2. Office of Director 2pp 18641 347 24X Fiche 30-395,83/04/13,8305270431
- --8305270449 Forwards IE Insp Rept 50-395/83-04 on 830118-20 & notice of violation
 DANCE, H C Division of Project & Resident Programs 83/02/14
 DIXON, O W Bouth Carolina Electric & Gas Co 2pp 18641-349
 24X Fiche, 50-395, 83/04/13, 8305270431
- --8305270452 Notice of violation from insp on 830118-20 * Region 2, Office of Director 83/02/14 ip 18641 351 24X Fiche 50-395,83/04/13,8305270431
- ---8305270458 IE Insp Rept 50-395/83-04 on 830118-20 Noncompliance noted failure to properly post radiation area PEERY. W W , BARR. K P Region 2, Office of Director 83/02/09 4pp 18641 352 24X Fiche 50-395.83/04/13,8305270431
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Bvc 11st encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15.8303040021
- B305270091 Forwards IE Insp Rept 50-395/83-12 on B30322-25 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/04/18 DIXON, D W, South Carolina Electric & Gas Co 2pp 18638-186, 24X Fiche, 50-395, 83/04/18, 8305270091
- --8305270094 IE Insp Rept 80-395/83-12 on 830322-25 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14) & Yech Bpec compliance.

 ANG.W.P. Region 2. Office of Director BLAKE.J.J. Division of Emergency Preparedness & Materials Safety 83/04/14 5pp. 18638:188 24X Fiche 50-395.83/04/18,8305270091

- 8305270093 Forwards IE Insp Rept 50-395/83-11 on 830329-31 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/04/20 DIXON, W O South Carolina Electric & Gas Co 2pp 18638 171 24) Fichs 50-395
- --8305270086 IE Insp Rept 50-395/83-11 on 830329-31 No noncompliance noted Major areas inspected radiochemical instrument calibr, GC program & records & capability tests for measurement of radioactive effluents
 EVANS.C D Region 2. Office of Director MONTGOMERY, D Division of Emergency Preparedness & Materials Safety 83/04/19 Bpp 18638 173 24X Fiche 50-395/83/04/20.8305270083
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valva Failures "
 Svc liet encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sansing Sys " Syc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000.83/04/25,8303040025
- 8305270436 Forwards IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted VERRELLI,D H Division of Project & Resident Programs 83/04/25 DIXON,O W South Carolina Electric & Gas Co 2pp 18662 115 24X Fiche 50-395,83/04/25,8305270436
- --8305270446 IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted Major areas inspected coordinated emergency response exercise CLINE, W. E., STANSBERRY, W. W. Region 2, Office of Director JENKINS, O. R. Division of Emergency Preparedness & Materials 84fety 83/04/14 Bpp 18662 117 24X Fiche 50-395,83/04/25,8305270436
- 6303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Bteam Generators at PWRs " 8vc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fichs 50-000,83/04/28,8303040024
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305270464 Forwards IE Insp Rept 50-395/83-14 on 830412-15 No noncompliance noted VERRELLI,D M Region 2, Office of Director 83/05/05 DIXON,O W 80uth Carolina Electric & Gas Co 2pp 18644 D57 24X Fiche 30-395,83/05/05,8305270464
- --8305270478 IE Insp Rept 50-395/83-i4 on 8304i2-i5 No noncompliance noted Major areas inspected steam generator mod.welding program & NDE program K.EINSGROE, W.P. Region 2. Office of Director BLAKE.J. J. Division of Engineering & Radiological Safety Programs 83/05/04 15pp 18644 039 24% Fiche 30-395.83/05/05,8305270464
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24% Fiche 50-000,83/05/06,8303040033

- 8305090454 Forwards IE Safeguards Insp Rept 50-395/83-13 on 820903~830406 No noncompliance noted O'REILLY, J P Region 2, Office of Director 83/05/06 DIXON, O W South Carolina Electric & Oas Co 2pp 18362 261 24X Fiche 50-395,83/05/06,8305090454
- --8305090461 IE Safeguards Insp Rept 50-395/83-13 on 820903-830406 No noncompliance noted Major areas inspected licenses revalidation of preemployment screening records Details withheld (ref 10CFR73 21)
 TOBIN.W J., PERNY.C , LANKFORD, J. Region 2, Office of Director B3/05/04 ip 18362 263 24X Fiche 50-395.83/05/06.8305090454
- 8305270512 Ack receipt of 830504 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-05 LEWIS,R C Division of Project & Resident Programs 83/05/10 DIXGN.O H South Carolina Electric & Gas Co 1p 18646 050 24X Fiche 50-395,83/05/10.8305270512
- --B305270519 Forwards IE Insp Rept 50-395/B3-05 on B30201-0304 & notice of violation
 LEWIS, RC Division of Project & Resident Programs B3/04/04
 DIXON, D W South Carolina Electric & Gas Co 2pp 18646 051
 24X Fiche: 50-395
- --8305270522 Notice of violation from insp on 830201-0304 * Region 2, Office of Director 83/04/04 2pp 18646-053 24X Fich* 50-395,83/05/10,8305270512
- --8305270532 JE Insp Rept 50-395/83-05 on 830201-0304 Noncompliance noted failure to follow procedures for waste monitor tank by not flushing discharge line & control room fan inoperable

 BKCLDS.J L. Region 2. Office of Director CANTRELL.F B. Division of Project & Resident Programs 83/03/30 10pp 18646 055 24X Fiche 30-395.83/05/10.8305270512
- 8303040034 IE Info Notice 83-3D, "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11, Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.
- 8305180465 Forwards 830117 divers rept on svc water intake structure & Gibert Commonwealth Assocs engineering evaluation of divers insp.in response to NRC 830324 ltr Svc water intake structure essentially stabilized
 DIXON.O W South Caroline Electric & Gas Co 83/05/11 DENTON.H Office of Nuclear Reactor Regulation, Director 4pp 18483 086
 24X Fiche 50-395.83/05/11.8305180465
- --B3051B0466 "Divers Rept Svc Water Intake Tunnel Insp "
 EAGDN.T D. Easen Diving & Marine Contractors, Inc B3/01/17
 Ilpp 1B483 090 24X Fich# 50-395,83/05/11,83051B0465
- 8305200311 Porwards Rev 5 to Emergency Operating Procedure EOP-5.

 "Recovery From Reactor Trip." in response to IE Bulletins
 83-01 & 83-04 Procedure revised to require manual reactor
 trip upon automatic reactor trip condition
 DIXON.O W Bouth Carolina Electric & Gas Co 83/05/12 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 5pp 18516 199
 24X Fiche 50-095.83/05/12.8303200311
- --8305200352 Rev 5 to Emergency Operating Procedure EOP-5, "Recovery From Reactor Trip "
 POULE.J W South Carolina Electric & Gas Co 83/04/27 14pp 18516 204 24X Fiche. 50-395. 83/05/12:8305200311
- 8303040040 IE Info Notice 83-31, "Error in ADLPIFE Computer Program "
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Byo list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York: Inc 114pp 18647 007 24X Ficha 50-000,83/05/26,8303040046.
- B. Reportable occurrences: LERs & related correspondence
- B305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Hfg drawings revised RAHE.E P Westinghouse Electric Corp B3/04/21, DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement Spg 18409:095, 24% Fiche 30-000/83/04/21,830510427

- 8305030627 Forwards LER 83-031/03L-0 Detailed event analysis enc1 DIXON.0 H South Carolina Electric & Oas Co 83/04/22 O'REILLY,J P Region 2, Defice of Director 3pp 18303.328 24X Fiche 30-395.83/04/22.8305030627
- --B305030637 LER 83-031/03L-0 on B30325.ECCS mechanical water chiller XKX-001B tripped Caused by intermittently failing valve control switch Switch repaired FIELDS,H C South Carolina Electric & Gas Co B3/04/22. Region 2, Office of Director ip 18303 331 24X Fiche 50-395.83/04/22, 8305030627
- 8305050057 Forwards LER 83-033/03L-0 Detailed event analysis encl DIXON.0 W South Carolina Electric & Oas Co 83/04/29 O'REILLY, J P Region 2. Office of Director 2pp 18342 066 24X Fiche 50-395.83/04/29,8305050057
- --8305050061 LER 83-033/03L-0. on 830331, while in Mode 5, source range detectors N-31 & N-32 lost for approx 5 minutes Caused by maint personnel error in placing trains of solid state protection sys in wrong position Personnel cautioned FIELDS, H C South Carolina Electric & Gas Co 83/04/29. Region 2, Office of Director ip 18342 069 24X Fiche 50-395, 83/04/29. 8305050057
- B305050233 Forwards LER B3-032/03L-0, Datailed event analysis encl, DIXON,O W Bouth Caroline Electric & Gas Co, B3/04/29 O'REILLY,J P. Region 2, Office of Director 2pp 18338-057, 24X Fiche 50-395,83/04/29,8305050233
- ---B305050239 LER 83-032/03L-0 on B30331, detection Zone NNN in control bldg failed to respond to simulated smoke condition during investigation of alarm Alarm previously received on 830329 Caused by short in smoke detector Dectector reinstalled. MCKINNEY, C. J. South Carolina Electric & Qas Co B3/04/29. Region 2. Office of Director, ip. 1838-059. 24X Fiche 50-395, 83/04/29,8305050333
- 8303100089 Forwards LER 83-034/03L-0 Detailed event analysis encl. DIXON,O W Bouth Carolina Electric & Oas Co 83/05/02 O'REILLY,J.P. Region 2, Office of Director 2pp 18377:220 24X Fiche 80-395.83/05/02.8303100089.
- --8305100091 LER 83-034/03L-0. on 830409; motor junction box cover on RHR pump B found w/burned area. Caused by electrical short to ground resulting from insulation failure Termination retaped & pump returned to operable status MCKINNEY.C J Bouth Carolina Electric & Gas Co. 83/05/02, Region 2, Dffice of Director ip 18377-222, 24X Fichs 50-395,83/05/02,8305100089.
- 8305110313 Part 21 rept re blow-out panel in east & west penetration areas. Initially reported on 830506. Structural framing sys designed to protect flow transmitter & related instrument tubing.

 BARKER, N. R. Gilbert/Commonwealth Cos. 83/05/07. DEYOUNG, R. C. Director's Office. Defice of Inspection and Enforcement 2pp 18393 196 24% Fiche. 50-395, 83/05/07. 8305110313
- 8305110322 Part 21 rept re ring duct stiffener failure Initially reported on 830506, Design change to eliminate airflow-induced vibration & redesign of ring stiffener submitted to util.

 BARKER,N R Gilbert/Commonwealth Cos 83/05/09 DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 2pp. 18393.177. 24X Fiche 30-395,83/05/09.8305110322.
- B305110397 PNO-II-B3-035 on B30507, fire detected in circuitry of one of three component cooling water pumps. Licensee declared alert Coused by faulty relay. Relay replaced & pump restored to operability BUTCHER, R C , CANTRELL, F, B, Region 2, Office of Director. B3/05/09. ip. 18406, 189 24X Fiche: 50-395, 83/05/09, 8305110379.
- 8305200626 Forwards LER 83-038/03L-0 Detailed event enalysis encl. DIXON: 0 W. South Carolina Electric & Oas Co. 83/05/12. O'REILLY.J.P. Region 2. Office of Director. 2pp. 18519:326 24X Fiche 50-395,83/05/12.8305200626.
- --8305200633 LER 83-038/03L-0. on 830413, pressurizer pressure transmitter IPT-457 found out of tolerance Caused by zero & span shift of teet instrument used in calibr of transmitter. Transmitter recalibr BOWKNIGHT, R. J. Bouth Carolina Electric & Gas Co 83/05/12. Region 2, Office of Director ip 18519 328. 24X Fichs. 50-393,83/05/12,8305200626

- 8305250349 LER BJ-035/03L-0 on 830420, horizontal fire barrier above svc water booster pump A found damaged Caused by maint activities in immediate area of fire barrier Damaged barrier replaced H/830520 itr
 DIXON, D W. BOUKNIGHT, R J South Carolina Electric & Gas Co 63/05/20 D'REILLY, J P Region 2, Office of Director 2pp 18592 102 24% Fiche 50-395,83/05/20,8305250349

DOCKET 50-396 UNIV OF VIROINIA CAVALIER REACTOR P Operating license stage documents & correspondence

B30523054B Application for amend to License R-123 changing Tech Specs to remove Item 3 2 b re subcriticallty w/single rod inserted & to modify Section 5 ir e fuel elements

BRENIZER J S Virginta. Univ of Charlottesville. VA 63/05/10 THOMAS.C.0 Standardization & Special Projects Branch 2pp 18537 083 24X Fiche 50-396.83/05/10.830523054B

DOCKET 50-397 HPP88 NUCLEAR PROJECT, UNIT 2

- A Application/construction stage documents & correspondence
- B305130262 Notification of B30524 meeting w/util in Walnut Creek.CA to review program status of engineering licensing construction, understanding the status of engineering licensing construction (environ & seismic) & energency planning # Region 5. Office of Director B3/04/09 Region 5. Office of Director Rpp 18439 242 24X Fiche 50-397.83/04/09.8305130262
- 8303030324 Forwards summary review of actions taken to assure quality of safety-related const & to meet commitments made to Commission in 800717 ltr.per 10CFR30 34(f) Actions included in restart & quality verification programs GARLIBLE; C S Washington Public Power Supply System 83/04/18 MARTIN, J B Region 5, Office of Director 20pp 18297 163 24X Fiche 50-397,83/04/18,8305030324
- 8305040289 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
 NOVAK.T M Assistant Director for Licensing 83/04/26
 HOLTZBCHER.D L Illinois Power Co 2pp 18326 343 24X
 Fiche: 50-000.83/04/26,8305040289
- B305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT.D @ Division of Licensing B3/05/03 EDELMAN, M R Clave
- --8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Oroup II for efforts in resolving issues generic to BWR/6 DL applicants EIBENHUT.D.Q Division of Licensing. B3/05/03. HALE,D P Illinois Power Co. 2pp 18523 200 24X Fiche 50-000.83/05/03, B305170046
- --8305170060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 GL applicants EIBENHUT.D.Q Division of Licensing. 83/05/03 FERQUBON.M R Washington Public Power Supply System 2pp 18523.202 24X Fiche 50-000.83/05/03.8305170046
- --8305170068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
 EIBENNUTID 0 Division of Licensing, 83/05/03, MCGAUGHY, J.P.
 Mississippi Power & Light Co 2pp 18523-204 24X
 Fithe 50-000, 83/05/03, 8305190046
- --8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants.

 EIBENHUT, D. G. Division of Licensing. 83/05/03 CAHILL, J. Gulf States Utilities Co. 2pp 18523:206 24X Fiche: 50-000,83/05/03,8305190046.

- 8305100110 Responds to 830413 ltr re TMI Action Item 11 K 3 18, "Mods to ADS Sys Logic " One of two options (2 or 4) will be implemented Choice based on benefit to design impact on schedule, availability of hardware & analysis & total cost BOUCHEY, © D Washington Public Power Supply System 83/05/04 SCHMENCER, A Licensing Branch 2 1p 18375 032 24X Fiche 50-397, 83/05/04 8305100110
- 8305090659 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fithe 50-000. B3/05/09/08305090659
- 8305170156 Forwards Burns & Roe Drawing H501 defining jurisdictional boundary between NF & AISC for supports W/o encl BOUCHEY: 0 D Washington Public Power Supply System 83/05/11 BCHMENCER, A Licensing Branch 2 ip 18466 341 24X Fiche 50-397, 83/05/11, 8305170156
- 8305250261 Notification of 830606-09 meetings w/util & LASL onsite to discuss control room human factors reviews AULUCK, R Licensing Branch 2 83/05/18 SCHHENCER, A Licensing Branch 2 5pp 18595 338 24X Fiche 30-397,83/05/18,8305250261
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND. J Licensing Brench i 83/05/02 HOLTZSCHER, D L Illinois Fower Co 2pp 18443 173 24X Fiche 50-000.83/05/02,
- ---8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO, J J Licensing Branch I 83/05/02 POWELL, P Washington Public Power Supply System ip 18443 174 24X
 Fiche 50-000,83/05/02,8305120460
- --8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND. J J Licensing Branch 1 83/05/02 REED. W J Gulf States Utilities Co Ip 18443 175 24X Fiche 50-000,83/05/02,8303120460
- --B3051204B5 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue

 STEFAND, J Licensing Branch 1 83/05/02 RICHARDSON, J D Mississippi Power & Light Co 1p 18443 176 24X
 Fiche 50-000, 83/05/02, 8305120460
- --8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental BERs. Info needed to document evaluation on each Licensing Review Group II generic issue

 STEFAND. J. Licensing Branch i 83/05/02 BUZZELLI.E M
 Cleveland Ejecthic Illuminating Co ip 18443 177 24X
 Fichs 50-000.83/05/02.8305120460
- B305160041 Forwards marked-up FSAR pages describing equipment for sampling & monitoring process & effluent streams during postulated accidents Submittal closes out commitment in Bectian 11 5 2 (Page 11-14) of SER. NUREO-0892
 BBUCHEY, O D Washington Public Power Supply System 83/05/10 BCHWENGER, A Licensing Branch 2, 20pp. 18444 009 24X
 Fichs 50-397.83/05/10,8305160041
- 8305250082 Forwards Suppl 3 to SER (NUREG-0892) H/o encl 8CHWENCER. A Licensing Branch 2 83/05/19 FERGUSDN. R L Washington Fublic Power Supply System 2pp 1895/ 307 24X Fiche 50-397,83/05/19,8305250082
- F Security, medical, emergency & fire protection plans
- 8305130262 Notification of B30524 meeting w/util in Walnut Creek, CA to review program status of engineering, licensing, const, startup, quality verification, equipment qualification (environ & seismic) & smergency planning # Region 5, Office of Director 83/04/09 Region 5, Office of Director 2pp, 18439:242 24X Fiche 50-397,83/04/09,8305130262.

- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list ent!
 EISENHUT, D 0 Division of Licensing 83/09/11 Consolidated Edison Co of New York, Inc 16spp 18540 095 24X
 Fiche 50-000,83/05/11.8305110034
- 8305240213 Forwards monthly status rept on offsite emergency greparedness for QL reviews for Apr 1983 DIRCKS:W J Office of the Executive Director for Operations 83/05/13 PALLADIND.N J Commissioners 5pp 18593 322 24X Fiche 50-000.83/05/13,8305240213

G Adjudicatory correspondence

- 83032903B2 Brisf in opposition to Coalition for Safe Power appeal from ABLB 830222 memorandum & order dismissing 820223 petition to intervene Petitioner failed to particularize & support contentions Certificate of Svc encl REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman B3/03/25 Atomic Safety and Licensing Appeal Panel 25pp 17724 021 24X Fiche 50-397,83/03/25, B303290382
- 8305260174 Advises that time for Commission to review ALAB-722 expired Commission declined review Decision became final agency action on 830523.

 CHILK: B J Office of the Secretary of the Commission 83/05/25 Atomic Safety and Licensing Board Panel 1p 18599 272 24X Fiche 50-397.83/05/25.8305260174
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8305120233 Forwards Amend 29 to FSAR
 BOUCHEY: 0 D Washington Fublic Power Supply System 83/03/15
 BCHWENCER: A Licensing Branch 2 2pp 18424 226 24X
 Fiche 30-397,83/03/15,8305120233
- --8305120236 Amend 29 to FBAR * Washington Public Power Supply System 83/03/31 952pp 18424 228 24X Fiche 50-397, 93/03/15, 8305120233
- O Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svr list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212040385
- 9303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
- SOCIO-CONTROL TO THE CONTROL OF THE SOCIETY OF THE
- B305170375 Forwards IE Insp Rept 50-397/83-10 on 830301-31 No noncompliance noted STERNBERGO DM Region 5, Office of Director 83/04/18, CARLISLE, C B Washington Public Power Supply System 2pp 18469 191 24x Fiche 50-397,83/04/18,8305170375
- --B305170381 IE Insp Rept 50-397/83-10 on 830301-31 No noncompliance noted Major areas inspected pipe support records.const quality reverification activities & const mgt topics TOTH.A D . D0005.R T Region 5. Office of Director 82/04/15 14pp 18469 193 24X Fiche 50-397.83/04/16.8305170375.
- 8305170346 Forwards IE Insp Rept 50-397/83-13 on 830404-00 No noncompliance noted. ETERNBERO, D M Region 5, Office of Director 83/04/19 CARLISLESC 8 Washington Public Power Supply System 2pp 18465 268 24X Fiche 50-397.83/04/19.8305170346
- --8305170349 IE Insp Rept 50-397/83-13 on 830404-08. No noncompliance noted Major areas inspected preoperational test program, open items: IE bulletin/circular response TMI (NUREG-0737) activities & independent insp Willett, D. J. DODDS, R. T. Region 5, Office of Director 83/04/19, 3pp 18465-270 24X Fiche: 50-397, 83/04/19, 8305170346
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp, 18383 089 24X Fiche 50-000.83/04/22,8303040023

- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B305130245 Forwards "HNP-2 Project Review of Completed Safety-Related Work," fourteenth progress rept for Jan-Mar 1983, per util 800717 commitments in response to notice of violation & addl info in accordance w/10CFR50, 54(f) CARLIBLE, C S Washington Public Power Supply System B3/04/26, MARTIN, J D Region 5, Office of Director 17pp 18439 195 24% Fiche 50-397, 83/04/26, 8305130245
- B305170436 Forwards IE Insp Rept 50-397/83-12 on B30301-31 No noncompliance noted STERNBERG.D M Region 5, Office of Director. B3/04/26 CARLISLE.C S Washington Public Power Supply System 2pp 18469 177 24X Fiche 50-397,83/04/26,8305170436
- --B305170439 IE Insp Rept 50-397/B3-12 on 830301-31 No noncompliance noted Major areas inspected preoperational test procedure review. Witnessing & independent insp effort FEIL.R A , TOTH.A D , DDDDB.R T Region 5, Office of Director 83/04/24 7pp 18469 179 24X Fiche 50-397.83/04/26.8305170436
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Bvc list ancl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fichs 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027.
- B303040028 IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103), 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.
- 8305050159 Forwards Vol 4 to "HPPSS Nuclear Project 2 Preservice Insp Program Plan: Summary Rept: "documenting completion of approx 98% of volumetric & surface exams, repairs & replacements & including Request for Relief PSI-2-001 BOUCHEY, 0 D Washington Public Power Supply System 83/05/03 SCHWENGER, A Licensing Branch 2 2pp 18341, 121, 24X Fichs 50-397,83/05/03,8305050159
- --8305050164 Vol 4 to "MPPSS Nuclear Project 2 Preservice Insp Program Plan, Summary Rept" PORTER, D W., MARTIN, J. Washington Public Power Supply System 83/04/27 196pp 18341 123 24% Fiche 50-397, 83/05/03, 8305050159
- B303040030 IE Info Notice B3-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" By 11st encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/04 Consolidated Edison Co. of New
 York, Inc 112pp 18382 282 24X Fiche 50-000, B3/05/04, B303040030.
- B30304003i IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost B30103). B3705/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000,83705/04,8303040031.
- 8303170335 Forwards IE Insp Rept 50-397/83-16 on 830418-22 No noncompliance noted BODK: HE Region 5, Office of Director, 83/05/05, CARLISLE, C. 8 Washington Public Power Supply Bystem 2pp 18465, 126 24X Fiche 30-397:83/05/05, 8303170335
- --8305170343 IE Insp Rept 50-397/83-16 on B30418-22. No noncompliance noted Major areas inspected radwasts mgt sys. including review of preoperational test program & status of gas.liquid & solid wasts treatment sys.

 YUMAS, G P , WENSLAWSKI.F A , BOOK, H E Region 5, Office of Director B3/05/04 5pp 18465 128 24X Fiche 50-397,83/05/05,8305170335
- 8305260252 Requests unrestricted access for team members to site during NRC const assessment team insp scheduled for 830516-27 & 0506-16 STERNBERO, D. M. Region 5, Office of Director. 83/05/05. CARLISLE, C. S. Washington Public Power Supply System. 2pp 18526-108 24X Fiche 30-397,83/05/05,8305260252

- --B305240255 Lists team members & areas of assignment for NRC const assessment insp scheduled for B30516-27 & 0606-16 HEIBHMAN:R F Reactor Construction Branch B3/04/26 Reactor Construction Branch ip 18626 110 24X Fichs 50-397,83/05/05.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83703706 Consolidated Edison Co 115pp 18523 248 24% Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Enginearing Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Bvc list encl
 UGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl UCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040046
- R. Periodic operating reports & related correspondence
- 8305130245 Forwards "WNP-2 Project Review of Completed Safety-Related Hork," fourteenth progress rept for Jan-Mar 1983, per util 800717 commitments in response to notice of violation & addl info in accordance w/10CFR30 54(f) ANTO AN MECOPONIC WINDOWS 34177

 CARLISLE, C S Washington Public Power Supply System 83/04/26

 MARTIN, J D Region 5, Office of Director 17pp 18439 193 24X

 Fiche 50-397,83/04/26,8305130245
- 8 Reportable occurrences, LERs & related correspondence
- B305030300 Part 21 rept re linear indications identified in 8A 106 grade pipe Initially reported on B30413 Caused by mfg process error & ultrasonic exam inadequacies All seamless pipe put on hold & magnetic particle examined CARLIBLE, C 9 Washington Public Power Supply System B3/04/15 MARTINJ B Region 5, Office of Director 18pp 18297 070 24 Fiche: 50-397,83/04/15,8305030300
- B305030507 Final & interim deficiency repts re Class IE cables in Baismic Category i raceways & standby gas treatment sys damper Next rept by B30718 CARLIBLE.C 8 Washington Public Power Supply System B3/04/18 MARTIN.J B Region 5. Office of Director 11pp 18295 098 2 Fiche 50-397.83/04/18.8305030507
- B305030500 Interim deficiency repts re IE Circuler Bi-05. "Sway Strut/ Snubber End Bushings" & Anaconda flexible conduit Initially reported on B21202 & B30321, respectively Guarterly updates will continue to be provided Next rept expected by B30720 GARLIBLE, C. S. Washington Public Power Supply System B3/04/20 MARTIN, J. B. Region 5. Office of Director 5pp 18306 345 24X Fiche 50-397,83/04/20,8305030500
- B305130106 Interim deficiency repts on Condition 221 re NAMCO EA-180 & EA-740 limit switches & Condition 226 re 125-volt dc motor operator connected to 250-volt dc power source Next rept operator connected to 200-voit of power source next r by 830726 CARLISLE, C. S Washington Public Power Supply System MARTIN, J. B Region 5, Office of Director App 184 Fiche 20-397,83704/26,8305130106. 18438.093
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
 BMITH,8 H Carolina Power & Light Co B3/03/22 TOURTELLOTTE, J
 Regulatory Reform Task Force 13pp 18543 277 24X
 Fiche: 50-000,83/03/22,8305230283.
- 8305020506 Forwards request for addl info re personnel training to aid in review performed by Licensee Guelifications Branch.
 KNIGHTON, G. W. Licensing Branch 3 83/04/11 UTLEY, E. E. Carolina
 Power & Light Co. 4pp 18284 325 24X Fiche 50-400,83/04/11,
 8305020504

- 8305230720 Forwards list of utile responding to requests for cost figures on backfitting
 TOURTELLOTTE. J Regulatory Reform Task Force 83/04/11
 PALLADINO.N J Commissioners 2pp 18542 272 24X
 Fiche 30-000.83/04/11.8305230720
- 8305170577 Forwards request for design documents to continue NRC review KNICHTON.OW Licensing Branch 3 83/04/21 UTLEY,EE Ca Power & Light Co 3pp 18496 117 24% Fiche 30-400,83/04/2 8305170577 Carolina
- 8305070659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000,83/05/09,8305070659 Consolidated
- 8305120467 Forwards "Conformance W/Title 10 of CFR Parts 20,50 & 100," per 811125 request & 820630 schedule Requirements of applicable regulations met Add1 verification provided by independent NRC review
 MCDUFFIE.M A Carolina Power & Light Co 83/05/09 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 13pp 18431 05
 24X Fiche 50-400, 83/05/09, 8305120467 18431 058
- 8305170282 Forwards changes to corporate QA program, currently provided In Section 1 8 of PBAR

 In Section 1 8 of PBAR

 MCDUFFIE,M A Carolina Power & Light Co B3/05/09 DENTON,H R

 Office of Nuclear Reactor Regulation, Director 1p. 18465 329

 Fiche 30-400,83/05/09.8305170282
- --8305170285 Changes to Section 1 8 (QA program) of PSAR # Carolina Power & Light Co 83/05/09 14pp 18465 330 Fiche 50-400,83/05/09,8305170282
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8305170149 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1 AND 2 Docket Nos STN 50-400 And STN 50-401 (Carolina Power And Light Company) * Office of Nuclear Reactor Regulation, Director NUREG-0972 83/04/30 220pp 18477 216 24X Fiche 50-400,83/04/30,8305170149
- 8305200122 Forwards DES & FR notice W/o DES KNIOHTON,O W Licensing Branch 3 83/05/12 UTLEY,E E Carc Power & Light Co 2pp 18528 346 24X Fiche 50-400.83/05/12, 8305200122
- --8305200125 Notice of availability of DES
 KNIGHTON, 0 W Licensing Branch 3 83/05/12 2pp 18528 348
 24% Fiche 50-400,83/05/12,8305200122
- B305200197 Forwards draft EIB & FR notice W/o encl KNIGHTON, Q W Licensing Branch 3 B3/05/12 Butzel & Kess EBERT, P Affiliation Unknown 3pp 19576 151 24X Fiche 30-400.83/05/12.8305200197
- 8305200205 Forwards for comments DES & notice of availability W/o encl KNIONTON, G W Licensing Branch 3 83/05/12 WILSON K Environmental Protection Agency 2pp 18540 215 24X Fiche 30-400 83/05/12 8305200205
- 8305200209 Forwards, for review & comment. DEB Comments due within 45 days after FR publication W/o encl
 KNIGHTON.0 W Licensing Branch 9 83/05/12 NODD, J M Commerce,
 Dept of, Natl Oceanographic & Atmospheric Administration 4pp
 18340 211 24X Fiche 50-400,83/05/12,8305200209
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8303020124 Forwards responses to draft BER Open Items 8 & 9 for Metsorological & Effluent Treatment Branch Wind loads for winds faster than 117 mph considered in svc load combinations for containment design (FSAR Table 3.8 1-2) MCDUFFIE,M. A Carolina Power & Light Co 83/04/27 DENTON.H R Defice of Nuclear Reactor Regulation. Director 4pp. 18278 231 24X Fiche 50-400;83/04/27,8305020124,
- 8305230296 Forwards OA Branch & Matls Engineering Branch requests for addl info not addressed in Feb 1983 draft SER Info requested by 830701
 KNIGHTON, G H Licensing Branch 3 83/05/03 UTLEY, E E. Card
 Power & Light Co 7pp 18543 292 24X Fiche 50-400,83/05/03,

- 8305040555 Forwards responses to draft SER Open Items 34, 35, 40, 42 & 44 MCDUFFIE,M A Carolina Power & Light Co B3/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 9pp 18348 293 24% Fiche 50-400,83/05/04,8305060555
- 8305;10248 Informs that draft SER Open Item 67 re design of normal containment surge sys closed Sys adequate Issue of time sys allowed to operate to be addressed during Tech Spec preparation

 KCDUFFIE.M A Carolina Power & Light Co 83/05/07

 Office of Nuclear Reactor Regulation, Director Ip

 Fiche 50-400,83/05/09,8305110248 DENTON-H R 18406 339

- 8305110274 Confirms 830428 telcon closing out draft SER Open Items 278 & 277 per Generic Ltr 82-14 Responses to other open items will be submitted shortly MCDUFFIE;M A Carolina Power & Light Co 83/05/07 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18393 307 Fiche 50-400.83/05/07.8305110274.
- 8305160017 Forwards response to draft SER Open Item 59 re containment Sys Reactor cavity subcompantment analysis conservative
 MCDUFFIE M A Carolina Power & Light Co 83/05/11 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 18453 163
 24% Fiche 50-400.83/05/11,8305160017
- 8305160021 Forwards response to draft SER Open Item 274 concerning refueling water storage tank (RHST) Two RHST vent lines are protected from freezing by redundant ambient sensing heat prosected from Freezing by Federhadic amounts behing head fracing on each vent line HCDUFFIE.M A Carolina Power & Light Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18432 347, 24X Fiche 50-400,83/05/11.8305160021 18452 347
- 8305160109 Advises that draft SER Open Items 48 & 74 closed per Generic Ltr B2-14 No anticipatory reactor trip mod proposed MCDUFFIE. M A Carolina Power & Light Co B3/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18444 029 Fiche 30-400, B3/05/11, B305140109
- 8305180400 Forwards response to draft SER Open Item 191 re closing of cooling water surge tank vent valve upon radiation alarm annunclation Vent valve automatically closes upon receipt of signal from cooling water monitor
 MCDUFFIEM A Carolina Power & Light Co 83/05/16 DENTON.H R.
 Dffice of Nuclear Reactor Regulation. Director 2pp 18486 012
 24X Fichs 50-400,83/05/16.8305180400
- 8305200442 Advises that draft BER Open Item 128 closed per 830329 telcon Description of new fuel paol antisiphon sycs will be provided in response to Open Item 130 MCDUFFIE.N A Carolina Power & Light Co. 83/05/16 DENYON, H R. Office of Nuclear Reactor Regulation, Director 1p 18517 123 Fiche 50-400.83/05/16.8305200442
- 8303200329 Forwards responses to Procedures & Sys Review Branch draft SER on Open Items 200,205 & 206 re proposed method for measuring process-to-sensor response time MCDUFFIE,M A Carolina Power & Light Co B3/05/18 DENTON, H.R Office of Nuclear Reactor Regulation, Director 9pp 18517 046, 24X Fiche 50-400,83/05/18.8303200329
- 8305200384 Forwards response to draft SER Open Items 32 & 33 re irradiation-strengthened Zircalov yield strengths & predicted cladding collapse time exceeding lifetime of fuel. prespectively

 MCDUFFIG.M A Carolina Power & Light Co 83/05/18 DENTON,H,R

 Dffice of Nuclear Reactor Regulation, Director App 18518 160

 24% Fiche 50-400,83/05/18.8305200284
- 8305250494 Documents 830421 telcon re draft SER Open Items 12,15 & 16 JUDICIONA DOCUMENTE BLORZI TEICON TE GRAFT BER Upen Items 12:15 & 1 concerning environ & hydrologic englineering; per Generic Ltr 82-14 Items considered closed as result of info submitted in 82:104 ltr
 MCDUFFIE.M A Carolina Power & Light Co 83/05/22 DENTON, H. R. Dffice af Nuclear Reactor Regulation, Director 1p. 18583 334 Fichs. 30-400,83/05/22, 8305250494
- 8305270023 Forwards responses to draft Chemical Engineering Branch SER Open Items 145 & 148 re TMI Item II.B 3, "Post-Accident Bampling Bys" & operator training requirements for post-accident sampling systrespectively.

 MUDUFFIE:M A Carolina Power & Light Co. 83/05/23 DENTON.H. R. Office of Nuclear Reactor Regulation. Director 3pp. 18633:347. 24X Ficha 50-400,83/05/23,8305270023.
- 8305260234 Informs that draft Radiological Assessment Branch SER Dpen Item 168 closed per 830510 telcon on FBAR Question 471 21. Responses to other open item in draft SER expected shortly MCDUFFIE.M A Caroline Power & Light Co 83/05/24 DENTION, H.R. Office of Nuclear Reactor Regulation, Director 1p 18599 339 24 Fiche: 50-400, 83/05/24, 8305260234.

- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Consplidated
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS:W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J. Commissioners 5pp 18573 322 Fichs 50-000,83/05/13,8305240213

G Adjudicatory correspondence

- 8303040477 Requests extension by 1-wk of deadline re briefs on proposed security plan experts Time needed due to large number of depositions & late scheduling of depositions Related correspondence CORROW, H Carolina Power & Light Co 83/04/28 KELLEY, J L., BRIGHT, G O., CARPENTER, J H Atomic Gafety and Licensing Board Panel. 2pp 18322 163 24X Ficha 50-400, 83/04/28, 8305040479
- --8305040485 Answers to general interrogetories & interrogetories on Contentions 22A, 22B, 75, 80, 83, 84 & 132, first set Related correspondence, CARROW.H Caroline Power & Light Co 83/04/28 EDDLEMAN, Eddleman, W. 63pp 18322 165 24X Fiche 50-400,83/04/28, EDDI.EMAN. U 8305040479
- -8305040492 Response to request for production of documents Certificate of Svc encl CARROW-H Carolina Power & Light Co 83/04/28 EDDLEMAN Eddleman, W 4pp 18322 228 24x Fiche 50-400,83/04/28, FOR FMAN, U
- --8305040498 Response to first request for admission re Eddleman Contention 22-B Certificate of Bvc encl CARROW.H Carolina Power & Light Co 83/04/28 Eddleman 4pp. 18322 232 24X Fichs 50-400,83/04/28,8305040479
- 830506047f Forwards LI Loflin affidavit to be included in util 830428 answers to W Eddleman first set of interrogatories on Contentions 224, 228, 75, 80, 83, 84 & 132 Svc list encl. CARROW, H Carolina Power & Light Co 83/05/02 KELLEY, J L., BRIGHT, Ø O , CARRENTER, J H Atomic Bafety and Licensing Board Panel. 4pp. 18351 175 24X Fiche 50-400, 83/05/02, 8305060471.
- 8305040485 Contentions based on util site emergency plan Cartificate of EDDLEMAN W Eddlemen, W 83/05/02 Atomic Safety and Licensing Board Panel App 18348 135 24X Fiche: 50~400, 83/05/02, 8305060485.
- 8305040532 Answer to NRC 830420 motion to compel Conservation Council 305060532 Answer to NRC 830420 motion to compa! Conservation C of North Carolina to respond to discovery Council is willing to nagotiate Council unable to answer all NRC discovery requests H/Certificate of Svc Related correspondence RUNKLE, J Conservation Council of North Carolina RUNKLE, J Runkle, J D 83/05/02, 10pp 18347 273 24X Fiche 50-400,83/05/02,8305040532
- 8305040412 Memorandum & order confirming withdrawal of Citizens Against Nuclear Power as formal party KECLEY.J.L. Atomic Safety and Licensing Board Panel Citizens Against Nuclear Power ip 18319,358 24X Fiche. 50-400.83/05/03,8305040412,
- --8305040421 Advises of Citizens Against Nuclear Power withdrawal as NEWMAN, P.T., NEWMAN, S.E. Citizens Against Nuclear Power, 83/04/28. KELLEY, J.L. Atomic Safety and Licensing Board Panel ip 18319 359. 24X Fiche: 50-400.83/05/03.8305040412
- 8305090475 Hotion to compel applicant to respond to Conservation Council of North Carolina Interrogatories 4-1 through 4-5 & 4-14 (first set) re Contention 4 concerning cumulative effects of transshipments Certificate of Svc encl. RUNKLE, J Conservation Council of North Caroline 83/05/03, 18360:229 24X Fiche 50-400.83/05/03,8305090475. 83/05/03, épp.
- B305110145 Affidavit of W Eddleman certifying negotations w/NRC re response to NRC first set of interrogatories, EDDLEMAN W Eddleman W B3/05/06. 2pp. 18393.342 24X Fiche:50-400.83/05/06.8305110145.

DOCKETED ITEMS

- 8305110222 Responds to NRC first set of interrogatories Related correspondence
 EDDLEMAN, W Eddleman, W 83/05/06 Atomic Safety and Licensing
 Board Panel 19pp 18407 076 24X Fiche 50-400,83/05/06,
- 8305110361 Response to applicant third set of first round interrogatories Certificate of Syc encl Related correspondence Eddleman, W 83/05/06 Caroling Power & 287 24X Fiche 50~400,83/05/06,8305110361 Carolina Power & Light Co
- 12pp. 18406 287 8305110366 First set of interrogatories Reply requested before 830525
- Related correspondence
 EDDLEMAN, W Eddleman, W 83/05/06 7/05/06 Office of the Executive Legal 24% Fiche 50-400,83/05/06,8305110366 10pp 18406 265
- 8305120288 Bubmission of Contention 161 re D8-416 circuit breakers for safe shutdown defects & possible malfunction Documents from which basis derived unavailable until 830420 Certificate of Svc encl
 - Svc encl EDDLEMAN, W Eddleman, W 83/05/07 Atomic Safety and Licensing Board Panel 2pp 18424 120 24X Fiche 50-400,83/05/07,8305120289
- B305130075 Responds to R Wilson interrogatories Certificate of Svc & affidavit encl Related correspondence CARROW-H Carolina Power & Light Co 83/05/10 Wilson, R 19: 18436:279 24X Fiche 50-400.83/05/10.8305130075 Wilson, R 19np
- 8305130088 Response to R Wilson request for production of documents as contained in interrogatories to applicant Documents will be made Awailable at mutually agreeable time Certificate of Svc encl Related correspondence GARROW M Carolina Power & Light Co 83/05/10 WILSON, R Wilson, R 4pp 18437 090 24% Fiche 50-400, 83/05/10, 8305130088
- 8305170497 Responses to first set of general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc BAXTER, T A Carolina Power & Light Co. BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/12 EDDLEMAN, W Eddleman, W 36pp Trowbridge 83/05/12 EDDLEMAN, W Edd: 95 24X Fiche 50-400,83/05/12,8305170497. 18467 295
- 8305170450 Response to first set of requests for production of documents on Contentions 41 & 65
 8AKTER: T.A. Carolina Power & Light Co. BAXTER: T.A. Shaw, Pittman, Potts & Trowbridge. 83/05/13 EDDLEMAN, W. Eddleman, W. 3pp 18469:315 24X Fiche 50-400.83/05/13,8305170450.
- 8305170456 Response to 830318 interrogatories Related correspondence WILSON, R. Wilson, R 83/05/13 Office of the Executive Legal Director 5pp 18467:285 24X Fiche 50-400,83/05/13,8305170456
- 8305170486 Clarification & supplementation of 830303 responses to 830131 interrogatories & request for production of documents Certificate of Svc encl Related correspondence WILSDN:R Wilson, R. 83705/13 Carolina Power & Light Co 18470:069 24X Fiche 50-400.83/05/13.8305170486
- 8305170491 Becond set of interrogatories Related correspondence, WILBON, R. Wilson, R. 83/05/13 Carolina Power & Light Co. 18470.006. 24% Fiche:50-400,83/05/13,8305170491
- 8305170528 Suppl to Contentions 150 161 re five factors for late filing of contentions Balancing of factors not required since contentions based on previously unavailable info Certificate of Svc encl EDDLEMAN, W Eddleman, W 83/05/14 Atomic Safety and Licensing Board Panel 3pp 18467 352 24X Fiche 50-400,83/05/14 8305170528
- 8305240500 Response to first set of interrogatories on Joint Contention II, Certificate of Svc encl. Related correspondence B3/05/16. Carolina Power & Light Co 21pp 18575 208 24X Fichs 50-400,83/05/16. 8305240500
- 8305240507 First set of interrogatories on Contentions III, IV & V. GOSZ4000/ First set of interrugatories on Contentions []]] V & V. Certificate of Svc encl.Related correspondence PAYNE, M T Kudzu Alliance PAYNE, M.T. Edelstein & Payne. 83/05/16. Carolina Power & Light Co. 13pp. 18571 244. 24X Fiche. 30-400,83/05/16,8305240507.
- B305190231 Brief on qualifications of witnesses proffered as expert in security planning: 10CFR73, Parts of plans re expertise of BJ Tuggle-JR Maples-LW Stevens & ER Bleacher should be made awailable to experts W/Certificate of Svc, BARTH: C. A Hearing Branch 1 B3/05/17, 13pp 18500 187, 24X Fiche: 30-400,83/05/17,8305190201

- 8305200430 Request for extension until 830403 to respond to W Eddl B30502 contentions on util site emergency plan Counsel has numerous conflicting obligations Certificate of Svc encl D'NEILL, J H Carolina Power & Light Co D'NEILL, J H Shaw, Pittman. Potts & Trawbridge 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18520 153 24X fiche 50-400,83/05, 8305200430
- 8305240446 Brief re qualifications of persons proffered by interver as experts to evaluate facility security plan All five intervenor witnesses fail to display sufficient expertise & should be withdrawn Certificate of Svc onci FLYNN, 8 F. CARROW, H. Carolina Power & Light Co. 83/05/17 29; 18574 091 24X Fiche 50-400,83/05/17,8305240446
- 8305240551 Motion requesting J Mackie be withdrawn as proposed exp: witness Applicant deprived of right to depose Mackie Benefit of having conducted cross-examination not afforded Certificate of Svc encl Related correspondence FLYNN-S F . CARROW.H Carolina Power & Light Co 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18575 276 24X Fiche 50-400,83/05/17,8305240551
- 8305240550 Response opposing Conservation Council of North Carolina 830503 motion to compel applicant to respond to discovery Contention 4 does not encompass cumulative effects of fuel shipment W/Certification of Counsel & Certificate of Svc. D'NEIL, J H Carolina Power & Light Co O'NEIL, J H Shaw, Pitte Potts & Trowbridge 83/05/18 Atomic Sefety and Licensing Boa Panel 12pp 18575 284 24x Fiche 50-400,83/05/18,8305240550
- K Utility Final Safety Analysis Report (FSAR) & amends
- B305200676 Forwards Amend 6 to FSAR Amend revises positions re reg guides in Section 1 8 & GA organization & responsibility revs in Sections 13 1 & 17 2 per 830311 final rule MCDUFFIEM A Carolina Power & Light Co B3/05/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18519-119 24X Fiche 50-400.83/05/13.8305200676
- --8305200679 Amend 6 to FSAR * Caroline Power & Light Co 83 Fiche 50-400,83/05/13,8305200676 83/05/13 23pp 18519 121 24)
- B305240417 Forwards revised distribution list reflecting changes in title name & address of persons receiving copies of Amend & to FBAR; per request ZIMMERMAN. 8 R Carolina Power & Light Co B3/05/20 EISENHUT, D Division of Licensing 4pp. 18571 032 24X Fiche 50-400.83/05/28305240417
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 LE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Syc list enc1 TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319, 24X Fiche 50-000,83/03/21,8212060385
- 8305270341 Forwards IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 No noncompliance noted
 VERRELLI.D M Division of Project & Resident Programs 83/03/31
 UTLEY.E E Carolina Power & Light Co Ip 18641-355 24X
 Fiche 30-400,83/03/31,8305270341
- --8305270348 IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 noncompliance noted Major areas inspected structural design activities & IE Bulletin 79-02 & 79-14 followup LENAHAN, J Region R. Office of Director CONLON, T E. Divisi of Engineering & Radiological Safety Programs 83/03/30, 4pp 18641 359 24% Fiche 50-400,83/03/31,8305270341
- 8305270546 Forwards IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 No noncompliance noted VERRELLI,D.M Division of Project & Resident Programs 83/04/05 UTLEY,E.E Caralina Power & Light Co 2pp 18645 276 24X Fich e: 50-400, 83/04/05, 8305270546
- --8305270551 IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 h noncompliance noted Major Areas inspected structural concrete & steel HARRIS-J R.; CONLON.T.E. Region 2: Office of Director, 83/04/04 5pp 18645 278. 24X Fichs 50-400,83/04/05,8305270546,
- 8305270377 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-03 & correct violations noted in it inspires sur-routed-us a 50-401/83-03
 VERRELLI.D M Division of Project & Resident Programs.
 UTLEY, E E Carolina Power & Light Co ip 18642 187
 Fiche 30-400,83/04/14,8305270377 83/04/14 PAY

- --B3052703B3 Responds to NRC 830302 ltr re violations noted in IE Insp Rept 50-400/83-03 Corrective actions preservice insp Procedure NES-B0A5035 revised to include surface magnetic particle insp for Weld i-SH-RV-01B PARSONS-R M Carolina Power & Light Co 83/03/31 O'REILLY, J P Region 2. Office of Director 2pp 18642 188 24X Fiche 50-400.83/04/14,8305270377
- --8305270391 Forwards 1E Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/03/02 UTLEY.E E Carolina Power & Light Co 2pp 18642 190 24X Fiche 50-400.83/04/14.8305270377
- --8305270397 Notice of violation from insp on 830124-27
 * Region 2, Office of Director 83/03/02 ip 18642 192 24X
 Fiche 50-400.83/04/14.8305270377
- --8305270406 IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 Noncompliance noted failure to establish adequate measures to control purchased svcs KLEINSORGE, W P , BLAKE, J J Region 2, Office of Director 83/02/28 11pp 18442 193 24X Fiche 50-400,83/04/14,8305270377
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 Svc list mnc1
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co. of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28.8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " 8vc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- * 8305270423 Forwards IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted.

 VERRELLI, D M Division of Project & Resident Programs. 83/05/03 UTLEY, E E Carolina Power & Light Co 2pp 18645 269. 24X Fiche 50-400,83/05/03,8305270623
 - --B305270622 IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted Major areas inspected geotechnical design activities, lakes dens & canals, quality records & safety-related dem/dike operational insp program LENAHAN, J J , CONLON, T E Region 2, Office of Director 83/04/29 4pp 18445:271. 24X Fichs 50-400.83/05/03.8305270623
 - 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04. Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
 - B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001. 24X Fiche. 50-000, 83/05/04, 8303040031
 - 8305270484 Forwards IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/04. UTLEY.E E Caroling Power & Light Co 2pp 18644-024 24X Fiche 50-400.83/05/04.8305270484

- --8305270492 IE Insp Repts 50-400/83-i3 & 50-401/83-i3 on 8304ii-i5. No noncompliance noted Major areas inspected containment steel: reactor vassel & safety-related structures YORK, J W. LIU.W C. Region 2, Office of Director. BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/03. opp 18644 026 24X Fiche 50-400,83/05/04.8305270484
- 8303040033 IE Info Notice 83×29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305270609 Ack receipt of 830426 ltr informing NRC of steps taken to correct viplations noted in IE Insp Repts 50-400/83-06 & 50-401/83-06 WERRELLI: D M Division of Project & Resident Programs 83/05/10. UTLEY, E E Carolina Power & Light Co 1p 18647 146 24X Fiche 30-400/83/05/10, 8305270609
- --8305270415 Responds to NRC 830401 ltr re violations noted in IE Insp Rept 50-400/83-06 Corrective actions add1 supports added to two svc water piping spool pieces to comply w/procedural requirements, WP-102, App A PARSONS, R M Carolina Power & Light Co 83/04/26 O'REILLY, J.P. Region 2, Office of Director 2pp 18647 147 24X Fiche 50-400, 83/05/10, 8305270609
- ---8305270620 Forwards IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220 & notice of violation VERRELLID M Division of Project & Resident Programs 83/04/01 UTLEY, E E Caroline Power & Light Co 2pp 18647-149 24X Fichs 50-400,83/05/10,8305270609
- --B305270626 Notice of viplation from insp on B30120-0220 * Region 2, Office of Director 83/04/01 2pp 18647,151 24X Fiche 50-400,83/05/10,8305270609
- --8305270631 IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220. Nancompliance noted failure to support piping per procedural requirements MAXWELL, 0 F Region 2, Office of Director BEMIS, P. Division of Project & Resident Programs 83/04/01 App 18647 153 24X Fiche 50-400,83/05/10,8305270609
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003, 24X Fiche 50-000,83/05/11,8303040034
- B30527027i Ack receipt of B30503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12 VERRELLI, D M Division of Project & Resident Programs. B3/09/16. UTLEY, E & Carolina Power & Light Co 1p 18641.313 24X Fiche 50-400, B3/05/16, B305270271.
- --8305270281 Responds to NRC 830404 ltr re violations noted in 1E Insp. Repts 50-400/83-12 & 50-401/83-12. Corrective actions: Procedure CGC-2 re absconformance control revised on 830327 to provide guidelines for deficiency rept issuance PARSONS, R M Carolina Power & Light Co 83/05/03. 0 (REILLY, J P Region 2. Office 40 Director 2pp. 18641 314 24X Fiche 50-400,83/05/16.8305270271
- --8305270292 Forwards IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 & notice of violation VERRELLID M Division of Project & Resident Programs, 83/04/04. UTLEY.E.E. Caroline Power & Light Co 2pp 18641:316 24X Fiche 50-400.83/05/16.8305270271
- --8305270301 Notice of violation from inep on 830220-0320 * Region 2, Office of Director. 83/04/04 ip 18641;318, 24X Fiche 50-400.83/05/16,8305270271
- --830527030B IE Insp Repts 50-400/83-12 & 50-401/83-12 on B30220-0320. Noncompliance noted Deficiency Disposition Rept 1301 not evaluated during 14-day period MAXMELL OF Region 2, Office of Director BEMIS, P. Division of Project & Resident Programs 83/04/04, 7pp 18641'319 24X Fichs. 50-400, B3/05/16, 8305270271.
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program."
 8vc list ancl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), B3/05/19 Consolidated Edison Co. of New
 York, Inc. 114pp 18697.009 24X Fiche 30-000,83/05/19,8303040040.

- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 800103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
 - 114pp
- R. Periodic operating reports & related correspondence
- 8305020165 Forwards "Quarterly Seismic Monitoring Rept for Jan-Mar
- 1983 "
 ZIMMERMAN, B R Carolina Power & Light Co 83/04/27 DENTON, H R
 Diffice of Nuclear Reactor Regulation, Director 1p 18284 060 24X
 Fiche 50-400,83/04/27,8305020165
- --8305020172 "Seismic Monitoring Program Quarterly Data Rept Jan-Mar 1983 "
 - Carolina Power & Light Co 83/04/27 ip 18284 061 24X
 - Reportable occurrences, LERs & related correspondence
- 3304280299 PNB-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law anfoncement agencies notified.

 HALL, B L , MCQUIRE, D Region 2, Atlanta, Office of the Director 80/11/04 1p 18255 330 24X Fiche 50-400, 80/11/04, 8304280299
- 3305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices initially reported on 830420 Attachments will be replaced w/devices w/widened grouves to accommodate new retaining rings Mfg drawings revised RAHE, E.P. Hestinghouse Electric Corp. 83/04/21 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement Spp. 18405,095 24X Fiche, 50-000,83/04/21,8305110427
- 305030à0i Final deficiency rept re weld deficiencies in Class IC transfer panels Initially reported on 830401 Deficiency not reportable per 100FR50 55(e) CHIANGI,N J Carolina Power & Light Co 83/04/25 D'REILLY,J P Region 2. Office of Director ip 18306 088 24X Fiche, 50-400, 83/04/25, 8305030601.
- 305050124 Final deficiency & Part 21 repts re pressure boundary math supplied by Tube Line Corp failing to meet Tech Blacs, Item £23 Initially reported on 830330 Items returned to vendor. New fittings purchased PARBONS.R M Caroline Power & Light Co 83/04/28 O'REILLY, J P Region 2. Dffice of Director 4pp 18341.343 24X Fiche 50-400,83/04/28,8305050124
- 303030185 Interim deficiency & Part 21 repts re base metal defect in spool piece supplied by Bouthwest Fabricating & Welding Co Initfally reported on 830182 Vendor directed to show preventive measures Final rept by 830801
 PARBONG:R M. Caroline Power & Light Co 83/04/27 O'REILLY, J P Region 2. Office of Director 4pp 18342 240. 24X Fiche, 50-400, 83/04/29, 8305050185
- 305050259 Final deficiency & Part 21 repts re 480-volt switchgear design defect in secondary disconnects Initially reported on 821102. Brown-Boveri completed change-out of all old style stationary secondary disconnects
 PARBONG.R M Carolina Power & Light Co 83/04/27 D'REILLY, J P
 Ragion 2, Dffice of Director 4pp 18338 016 24X
 Ficha 50-400,83/04/29,8305050259
- 105130027 Part 21 & final deficiency repts (Item 106) re incorrect design of 480-voit switchgear on secondary disconnects Disconnects installed in breaker cradle will be replaced PARSONS,R.M. Carolina Power & Light Co 83/04/29, 0'REILLY, J P Region 2, Office of Director 4pp 18437'125 24X Fiche: 50-400,83/04/29,8305130027
- O5110252 Interim deficiency rept re conduit installed in structural concrete not in accordance w/AGI-318 Initially reported on 830401. Evaluation determined item not reportable per GOCRESO, 55(e),
 CHIANGI, N. J. Caroline Power & Light Co. 83/05/03 O'REILLY, J. P.
 Region 2, Office of Director ip. 18406 338 24X
 Fiche: 50-400, 83/05/03, 8305110252
- O5130080 Deficiency rept re Class IE motor control ctrs from ITT O001d containing weld defects Initially reported on 830408. Vendor svaluation to be completed by Jul 1983, Extension until 830713 requested Also reported per Part 21 PARSONS.R. M. Carolina Power & Light Co. 83705/06 O'REILLY, J. P Region 2. Office of Director. 1p. 18436 264. 24X Fiche: 50-400,83/05/06.8305130080.

- 8305130216 Interim rept re deficient wolds on emergency svc water self-cleaning strainers Initially reported on 830408 Evaluation of pressure boundary welds not expected to be completed until June 1983 Next rept will be submitted by 830617 7/06 G'REILLY, J P PARSONS, R M Carolina Power & Light Co 83/0 Region 2, Office of Director 1p 18439 329 Fiche 50-400,83/05/06,8305130216 83/05/06
- 8305130113 Part 21 rept re low natural frequency of counterbalance assembly, resulting in unacceptable stresses on bactdraft damper counterbalance arm Solsmic qualification critoria not fully met Investigation & testing underway HILL. TD Ruskin Manufacturing Co 83/03/10 Director's Office of Inspection and Enforcement 7pp 18438 001 24X Fiche 30-400,83/03/10,8305130113 Director's Office,
- 8305230442 Final deficiency rept, Item 67, re omission of protective coating behind pad attachment inside containment dome liner Initially reported on 811228 Work on weepholes completed using Keeler & Long 6548-5 epoxy surfacer PARSONB, R M Carolina Power & Light Co 83/03/13 0'REILLY, J. R Region 2, Office of Director App 18538 196 24X Fiche 50-400,83/05/13,8305230442 D'RETLLY, J. P
- T Hearing transcripts on non-antitrust matters
- 8305240077 Forwards transcript of Tuggle, Maples, Mackie, Bleacher & Stevens depositions as experts of W Eddleman on security, per 830520 telcon W/o encl BARTH, C A Hea 1p 18549 094 on w/o ent. Hearing Branch 1 83/05/20 EDDLEMAN,W Eddleman, W. D74 24x Fiche 50-400,83/05/20,8305240077
- DOCKET 50-401 BHEARON HARRIS NUCLEAR POWER PLANT: UNIT 2
- A Application/construction stage documents & correspondence
- 8305020504 Forwards request for add1 info re personnel training to aid in review performed by Licensee Qualifications Branch. RMIGHTON.6 W Licensing Branch 3 83704/11. UTLEY.E E Carolina Power & Light Co 4pp 18284 325 24X Fichs 50-400.83/04/11. Power & Light Co 8305020506
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11. PALLADINO, N J Commissioners 2ep 18542 272 24X Fiche 50-000,83/04/11,8305230720
- 8305170577 Forwards request for design documents to continue NRC review
 KN10HTON.O W Licensing Branch 3 83/04/21 UTLEY.E E Caro
 Power & Light Co. 3pp 18496 117 24X Fiche 50-400.83/04/21,
 8305170577 Carolina
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EIBENHVI.D Q Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
 Fichs 50-000,83/05/09,8305090659
- 8305120467 Forwards "Conformance H/Title 10 of CFR Parts 20,50 & 100," per 811125 request & 820630 schedule Requirements of applicable regulations met Addl verification provided by independent NRC review MCDUFFIE,M A Carolina Power & Light Co 83/05/09 DENTON,H R Office of Nuclear Reactor Regulation, Director 13pp 1843/058 24X Fiche 50-400, 83/05/09, 8305120467.
- 8305170282 Forwards changes to corporate QA program, currently provided in Section 1 B of P8AR MCDUFFIEM A Carolina Power & Light Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 19 18465-329 24 Fich
- 14pp 18465 330 24X
- D NRC Draft/Final Environmental Statements, supple & correspondence
- B305170149 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1 AND 2. Docket Nos STN 30-400 And STN 50-401 (Carolina Power And Light Company) * Office of Nuclear Reactor Regulation, Director NUREO-0572.
 B3/04/30 220pp 18477 216 24X Fiche 50-400.93/04/30.8305170149.

- 8305200122 Forwards DES & FR notice W/o DES KNIOHTON, G W Licensing Branch 3 83/03/12 UTLEY, E E Carolina Power & Light Co 2pp 18528 346 24X Fich # 50-400.83/05/12, 8305200122
- --8305200125 Notice of availability of DES KN10HTON,0 W Licensing Branch 3 83/05/12 2pp 18528 348 24% Fiche 50-400,83/05/12,8303200122
- 8305200197 Forwards draft EIS & FR notice 4/0 encl KNIGHTON. G W Licensing Branch S 83/05/12 Butsel & Kass EBERT. P Affiliation Unknown Spp 18576 151 24X Fishe 50-400.83/05/12.8305200197
- 8305200205 Forwards, for comments, DES & notice of availability W/o encl KNIGHTON, 0 W Licensing Branch 3 83/05/12 WILSON, K Environmental Protection Agency 2pp 18540 215 24X Fiche. 50-400.83/05/12,8305200205
- 8305200209 Forwards, for review & comment, DES Comments due within 45 days after FR publication W/o encl
 KNIGHTORN, G W Licensing Branch 3 83/05/12 WOOD, J M Commerce,
 Dept of, Natl Decanographic & Atmospheric Administration 4pp
 18540:211 24X Fiche 50-400, 83/05/12, 8305200209
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305020124 Forwards responses to draft SER Open Items 8 & 9 for Meteorological & Effluent Treatment Branch Hind loads for winds fester than 117 mph considered in svc load combinations for containment design (FSAR Table 3 B 1-2) MCDUFFIE.M. A Carolina Power & Light Co. 83/04/27, DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp. 18278 231. 24X Fiche 50-400.83/04/27.8305020124
- 8305230296 Forwards GA Branch & Matls Engineering Branch requests for add! inFo not addressed in Feb 1983 dreft BER Info requested by 803701 KNIGHTON,0 W Licensing Branch 3 83/05/03 UTLEY.E.E. Carolina Power & Light Co 7pp 18543-272 24% Fiche 50-400,83/05/03,8305230294.
- 8305060555 Forwards responses to draft SER Open Items 34,35,40,42 & 44 MCDUFFIE.M.A Caroline Power & Light Co 83/05/04 DENTON,H R Qffice of Nuclear Reactor Regulation, Director 9pp 18348-293 24% Fiche 50-400,83/03/04,8305060555.
- 8305110248 Informs that draft BER Open Item 67 re design of normal containment purge sys closed Sys adequate Issue of time sys allowed to operate to be addressed during Tech Spac preparation
 MCDUFFIE.M A Carolina Power & Light Co 83/05/09 DENTON, H R
 Office of Nuclear Reactor Regulation, Director, 19 18406, 337 24X
 Fiche 50-400, 83/05/09, 8305110248
- B305110294 Confirms 830428 telcon closing out draft SER Open Items 298 & 299 per Generic Ltr 82-14 Responses to other open items will be submitted shortly MCDUFFIE,M A Carolina Power & Light Co 83/05/09 DENTON,H R Defice of Nuclear Reactor Regulation, Director ip 18393 307 24X Fiche 50-400,83/05/09,8305110294.
- B305160017 Forwards response to draft BER Open Item 39 re containment sys Reactor cavity subcompartment analysis conservative MCDUFFIE:M A. Carolina Power & Light Co. B3/03/11. DENTON,H R Dffice of Nuclear Reactor Regulation, Director. 2pp. 18453:163 24X Fiche: 50-400.83/05/11.8305140017.
- 8305160021 Forwards response to draft SER Open Item 274 concerning refueling water storage tank (RMST). Two RMST vant lines are protected from freezing by redundant ambient sensing heat tracing on each vent line MCDUFFIE.M A Carolina Power & Light Co. 83/05/11. DENTON.H.R Office of Nuclear Reactor Regulation. Director 2pp. 18452.347. 24X Fiche: 50-400, 83/05/11.8305160021
- 8305160109 Advises that draft SER Open Items 48 % 74 closed per Generic Ltr 82-14. No anticipatory reactor trip mod proposed MCDUFFIE.M A Carolina Power & Light Co. 83/05/11. DENTON, H R Office of Nuclear Reactor Regulation. Director 1p. 18444:029. 24X Fiche: 50-400, 83/05/11, 8305160109
- 8305180400 Forwards response to draft SER Open Item 191 re closing of cooling water surge tank vent valve upon radiation alarm annunciation Vent valve automatically closes upon receipt of signal from cooling water monitor.

 MCDUFFIEM A. Carolina Power & Light Co. 83/05/16. DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp. 18486,012, 24X Fiche.30~400,83/05/16.8305180400

- 8305200442 Advises that draft SER Open Item 128 closed per 830329 talcon Description of new fuel pool antisiphon svcs will be provided in response to Open Item 130 MCDUFFIE,M A Carolina Power & Light Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18517,123 24x Fichs 30-400,83/05/16,8305200442
- 8305200327 Forwards responses to Procedures & Sys Review Branch draft BER on Open Items 200,205 & 206 re proposed method for measuring process-to-sensor response time MCDUFFIE.M A Carolina Power & Light Co 83/05/18 DENTON,H R. Office of Nuclear Reactor Regulation. Director 9pp 18517,046 24X Fichs 50-400.83/05/18.8305200329
- 8305200394 Forwards response to draft SER Open Items 92 & 33 reirradiation-atrengthened Zircalov yield strengths & pradicted cladding collapse time exceeding lifetime of fuel, respectively MCDUFFIE:M A Carolina Power & Light Co 83/05/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp 18518 160 24X Fiche 50~400,83/05/18,8305200384
- 9305250494 Documents 830421 telcon re draft SER Open Items 12,15 & 16 concerning environ & hydrologic engineering, per Oeneric Ltr 82-14 Items considered closed as result of info submitted in 821104 Itr.

 MCDUFFIE.M A Carolina Power & Light Co 83/05/22. DENTON, H R. Office of Nurlear Reactor Regulation, Director 1p. 18583-354. 24x Fiche:50-400.83/05/22,8305250494
- 9305270023 Forwards responses to draft Chemical Engineering Branch SER Open Items 145 & 148 re TMI Item II B 3, "Post-Accident Sampling Sys" & operator training requirements for post-accident sampling sys; respectively.

 MUDUFFIE,M.A Carolina Power & Light Co 83/05/23 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp. 18633, 349, 24X Fiche 50~400,83/05/23, 8305270023
- B305260234 Informs that draft Radiological Assessment Branch BER Open Item 168 closed per B30510 telcon on FBAR Question 471 21. Responses to other open items in draft BER expected shortly, MCDUFFIE,M.A. Carolina Power & Light Co. B3/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p. 18599 339, 24x Fichs 50-400.83/05/24/830526023
- F. Becurity, medical, emergency & fire protection plans
- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control proceduras for law enforcement visits Syc list enci Syc list enci EISENHUT,D 0 Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 14pp 18540 095 24x Fiche: 50-000, 83/05/11, 8305110034
- Q. Adjudicatory correspondence
- 9305040479 Requests extension by 1-wk of deadline re briefs on proposed security plan experts Time needed due to large number of depositions & late scheduling of depositions Related correspondence
 CARRON,H Carolina Power & Light Co 83/04/29 KELLEY, J. L.,
 BRIGHT, G CJ. CARPENTER, J. H. Atomic Bafety and Licensing Board Panel.
 2pp 18322-163 24% Fiche. 50-400, 83/04/28, 8305040479.
- --8305040485 Answers to general interrogatories & interrogatories on Contentions 22A: 22B: 75:80:83:84 & 132; first set Related correspondence.
 CARROW: H Carolina Power & Light Co 83/04/28. EDDLEMAN; H, Eddleman; H 63pp 18322:165 24X Fiche. 50-400; 83/04/28; 2308040479.
- --8305040492 Response to request for production of documents, Cartificate of 8vc encl.

 CARRON, H. Carolina Power & Light Co 83/04/28. EDDLEMAN, H Eddleman, H 4pp 18322, 228 24X Fiche 50-400, 83/04/28, 8305040479.
- --8305040498 Response to first request for admission re Eddleman Contention 22-8 Certificate of Svc ancl. CARROH-H Caroline Power & Light Co 83/04/28. Eddleman: W. 4pp 18322-232. 24X Fiche. 50-400: 83/04/28, 8305040479.
- \$305060471 Forwards LI Loflin affidavit to be included in util B30428 answers to W Eddleman first set of interrogatories on Contentions 224:228,75.80,83.84 & 102.8v. list encl CARROW,H. Carolina Power & Light CO B3/05/02, KELLEY,J,L., BRIGHT,G.O. CARPENTER,J H. Atomic Safety and Licensing Board Panel. 4pp. 18351.173. 24X Fiche.50-400.83/05/02,8305060471.

- 8305060485 Contantions based on util site emergency plan Certificate of 8vc encl EDDLEMAN, W Eddleman, W 83/05/02 Atomic Safety and Licensing Board Panel 4pp 18348 135 24X Fiche 50-400,83/05/02,8305060485
- 8305060532 Answer to NRC B30420 motion to compel Conservation Council of North Carolina to respond to discovery Council is willing to negotiate Council unable to answer all NRC discovery requests W/Certificate of Svc Related correspondence RUNKLE. J Conservation Council of North Carolina. RUNKLE. J RUNKLE. J B3/05/02 10pp 18347 293 24X Fiche: 50-400.83/05/02,8305060532
- B305040412 Memorandum & order confirming withdrawal of Citizans Against Nuclear Power as formal party KELLEY, J. Atomic Safety and Licensing Board Panel B3/05/03 Citizens Against Nuclear Power ip 18319-358 24X Fiche 50-400,83/05/03,8305040412
- ---B305040421 Advises of Citizens Against Nuclear Power withdrawal as formal party NEWHAN, P T , NEWHAN, B E Citizens Against Nuclear Power B3/04/28 KELLEY, J L Atomic Bafety and Licensing Board Panel 1p 18319: 359 24X Fichs 50-400, 83/05/03, 8305040412
- 83Q5090475 Motion to compel applicant to respond to Conservation Council of North Caroline Interrogetories 4-1 through 4-5 & 4-14 (first set) re Contention 4 concerning cumulative effects of transshipments Certificate of Svc encl RUNKLE, J Conservation Council of North Carolina 83/05/03, 6pp 18360:227 Z4X Fiche 50-400,83/05/03,8305090475
- 8305110145 Affidavit of W Eddleman certifying negotations w/NRC re response to NRC first set of interrogatories EDDLEMAN, W Eddleman, W 83/05/06 2pp 18393,342 24X Fiche:50-400,83/05/06,8305110145
- 8305110222 Responds to NRC first set of interrogatories Related correspondence EDDLEMAN. W Eddleman, W 83/05/06 Atomic Safety and Licensing Board Panel 17pp. 18407 076 24X Fiche 50-400,83/05/06.830510222
- 830510361 Response to applicant third set of first round interrogatories Certificate of Svc encl Related correspondence EDDLEMAN. W Eddleman, W 83/05/06. Carolina Power & Light Co 12pp 18406 287 24x Fiche 30-400.83/05/06.8305110361.
- B305110366 First set of interrogatories. Reply requested before 830525 Related correspondence EDDLEMAN, H Eddleman, W 83/05/06 Office of the Executive Lega Director 10pp 18406:265 24X Fiche: 50-400,83/05/06,8305110366
- 8305120288 Submission of Contention 161 re DS-416 circuit breakers for safe shutdown defects & possible malfunction. Documents from which basis derived unavailable until 830420 Certificate of Svc encl.

 EDDLEHAN: W Eddleman, W 83/05/07 Atomic Safety and Licensing Board Panel. 2pp 18424 120 24X Fichs 50-400.83/05/07.8305120288
- B305130075 Responds to R Wilson interrugatories Certificate of Byc & affidavit encl Related correspondence GARROW, H Carolina Power & Light Co. 83/05/10. Wilson, R 19pp 18436:279 R4X Fiche 50-400,83/05/10,8305130075
- 8305130088 Response to R Wilson request for production of documents as contained in interrogatories to applicant Documents will be made available at mutually agreeable time Certificate of Syc encl Related correspondence GARRCM, H Carolina Power & Light Co 83/05/10 WILSON, R Wilson, R. 4pp. 18437.070. 24X Fiche 50-400, 83/05/10, 8305130088
- 8305170497 Responses to first set of general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc encl Related correspondence
 BAXTER.T.A Carolina Power & Light Co BAXTER.T.A Shaw, Pittman, Potts & Trowbridge 83/05/12, EDDLEMAN.H, Eddleman. H 56pp 18467 295. 24X Fiche: 50-400.83/05/12, B305170497
- 8303170430 Response to first set of requests for production of documents on Contentions 41 & 65
 BAXTER.T A. Carolina Power & Light Co. BAXTER.T A. Shaw, Pittman, Potts & Trowbridge 83/05/13, EDDLEMAN,W Eddleman, W. 3pp 18469-315 24X Fiche 50-400,83/05/13,8305170450
- B305170456 Response to B3031B interrogatories. Related correspondence. WILBON,R. Wilson, R 83/05/13 Office of the Executive Legal Director 5pp 18467: 285. 24X Fiche. 50-400. B3/05/13. 8305170456

- 8305170486 Clarification & supplementation of 830303 responses to 830131 interrogatories & request for production of documents Certificate of Svc encl Related correspondence WILSON: R Wilson, R 83/05/13 Carolina Power & Light Co 4pp 18470 049 24X Fiche. 50-400.83/05/13.8305170486
- 8305190209 Package of seven requests to make limited appearance statement at OL hearings OAGE.J. HUUBARD, K S. OREENBAUM, R L. Affiliation Unknown B3/05/13 NRC No Detailed Affiliation Given 7pp 18502 188 24X Fiche 50-440,83/05/13,8305190209
- 8305170528 Suppl to Contentions 150 -- 161 re five factors for late filing of contentions Balancing of factors not required since contentions based on previously unavailable info Certificate of Svc encl EDDLEMAN, W Eddieman, W 83/05/14 Atomic Safety and Licensing Board Panel 3pp 18467 352 24X Fiche 50-400.83/05/14,8305170528
- 8305240500 Response to first set of interrogatories on Joint Contention II Certificate of Svc encl Related correspondence. PAYNE,H T Kudzu Allience PAYNE,H T. Edelstein & Payne 83/05/16 Carolina Power & Light Co. 2ipp 18575 208 24X Fiche 30~400,83/05/16.8305240500
- 8303240307 First set of interrogatories on Contentions III, IV & V Certificate of Svc encl, Related correspondence. PAYNE, M T Kudzu Alliance PAYNE, M T Edelstein & Payne 83/05/16 Cerolina Power & Light Co. 15pp 18571 244 24X Fiche 50-400,83/05/16,8305240507
- B305190231 Brief on qualifications of witnesses proffered as expert in security planning, 10CFR73 Parts of plans re expertise of BJ Tuggle-JR Maples, LH Btevens & ER Bleacher should be made available to experts H/Certificate of Svc BARTH.C A Hearing Branch 1 83/05/17 13pp 18500 187 24X Fichs 30-400,82/05/17, 1805190231
- 8305200630 Request for extension until 830603 to respond to W Eddleman 830502 contentions on util site emergency plan Counsel has numerous conflicting obligations Certificate of 8vc encl U'NEILL, J H Carolina Power & Light Co. D'NEILL, J H Shaw, Pittman. Potts & Trowbridge. B3/05/17 Atomic Safety and Licensing Board Panel 5pp 18520.153 24X Fiche 50-400.83/05/17, 8305200630
- 8305240446 Brief re qualifications of persons proffered by intervenors as experts to evaluate fac(lity security plan All five intervenor witnesses fail to display sufficient expertise & should be withdraum Certificate of Byc encl FLYNN.8 F. CARROH, H. Carolina Power & Light Co. B3/05/17 29pp 18574 091 24% Fiche 50-400.83/05/17.8305240446
- B305240551 Motion requesting J Mackie be withdrawn as proposed expert witness, Applicant deprived of right to depose Mackie Benefit of having conducted cross-examination not afforded Certificate of Bvc encl. Related correspondence FLYNN, B F . CARROW, H Carolina Power & Light Co B3/05/17 Atomic Safety and Licensing Board Panel 3pp 18575 276 24X Fiche 50-400.83/05/17,8305240551.
- 8305240550 Response opposing Conservation Council of North Carolina 830503 motion to compel applicant to respond to discovery Contention 4 does not encompass cumulative effects of fuel shipment M/Certification of Counsel & Certificate of Svc O'NEIL.J H Carolina Power & Light Co O'NEIL.J H Shew. Pittman. Potts & Trowbridge 83/05/18 Atomic Safety and Licensing Board Panel 12pp 18575 284 24X Fiche 50-400.83/05/18.8305240550
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8305200676 Forwards Amend 6 to FBAR. Amend revises positions re reg guides in Bection 1,8 & GA organization & responsibility revs in Sections 13,1 & 17 2.per 830311 final rule HCDUFFIE.M A. Carolina Pawer & Light Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18519-119 24X Fiche 50-400.83/05/13,8305200676
- --8305200679 Amend & to FBAR * Carolina Power & Light Co B3/05/13 23pp 18519 121 24X Fiche 30-400,83/05/13, B305200674

- 8305240417 Forwards revised distribution list, reflecting changes in title name & address of persons receiving copies of Amend & to FRAR per request IMMERNAN-SR Carolina Power & Light Co 83/05/20 EIS ZIMMERMAN.S R Carolina Power & Light Co 83/05/20 EISENHUT.D G Division of Licensing 4pp 18571 052 24X Fiche 50-400,83/05/20,8305240417
- Q Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 16308-317 24% Fiche 50-000,83/03/21,8212060385
- 8303270341 Forwards IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/31 UTLEY, E.E. Carolina Power & Light Co. 1p 18641 358 24X Fiche 50-400:83/03/31.8305270341
- --8305270348 IE Insp Repts 50~400/83-11 & 50~401/83-11 on 830308-11 No augustusen in insp. Repts 30-400/83-11 & 30-401/83-11 on augustus no noncompliance noted Major areas inspected structural design activities & IE Bulletin 79-02 & 79-14 followup LENAHAN, J Regions 2. Office of Director CONLON, T.E. Division of Engineering & Radiological Safety Programs 83/03/30 4pp 18441 359 24X Fiche 50-400,83/03/31.8305270341
- 8305270544 Forwards IE Insp Repts 50-400/83-09 & 50-401/83-09 on SUBSIDER FOR THE NO NONCOMPLIANCE NOTED TO SUBSIDER OF SUBSIDER OF SUBSIDER OF PROJECT & Resident Programs B3/04/05 UTLEY, E E Carolina Power & Light Co 2pp 18645 276 24X Fiche 30-400. B3/04/05, B309270346
- --9305270551 IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 No noncompliance noted Major areas inspected structural CONCrete & steel
 HARRIS, J R , CONLON, T E Region 2, Office of Director 83/04/04
 5pp 18645 278 24% Fiche 50-400,83/04/05,8305270546
- 8305270377 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-03 & 50-401/83-03 50-401/63-03 VERRELLI,D M Division of Project & Resident Programs UTLEY.E E Carolina Power & Light Co 1p 18642 187 Fiche 50-400,83/04/14.8305270377 83/04/14
- --8305270391 Forwards IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/03/02 UTLEY.E E Carolina Power & Light Ca 2pp 18642 190 24X Ficha 50-400,83/04/14,8305270377
- --8305270406 IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 Noncompliance noted failure to establish adequate measures to control purchased sycs KLEINSGRGE, W.P., BLAKE, J.J. Region 2. Office of Director 83/02/28 (1pp. 18642 193 24X Fiche 50-400.83/04/14,8305270377
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
- JOSPANUEL SEARCE SEARCE
- 8303040023 IE Info Notice 83-22, "BWR Bafety/Relief Valve Failures,"
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enc1
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/25 Consolidated Edison Co of New
 York, Inc 119pp. 18381 291 24X Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/04/28 Consolidated Edison Co of New
 York, Inc 113pp. 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Syc list encl JORDANIE L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/04/28 Consolidated Edizon Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027

- 83D304002B IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Bvc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New 103) 83/05/03 Consolidated Edison Co of New 18441 170 24X Fiche 50-000,83/05/03,8303040028, York. Inc 122pp
- 8305270623 Forwards IE Insp Repts 50-400/63-14 & 50-401/83-14 on 830413-15 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs. 83/05/03 UTLEY, E E Caroling Power & Light Co 2pp 18645'269 24X Fiche 50-400,83/05/03,8305270623
- --B305270632 IE Insp Repts 50-400/83-14 & 50-401/83-14 on B30413-15 No noncompliance noted Major areas inspected geotechnical design activities: lakes, dams & canals, quality records & safety-related dam/diks operational insp program LENAHAN, J J. CONLON, T E Region 2. OFfice of Director, B3/04/29, 4pp 18645 271 24X Fiche 30-400, B3/05/03, B305270623
- 8303040030 IE Info Notice 83-27, "Operational Response to Events 103040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Ageinst Plant Equipment " Svc list encl JURDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co York, Inc 117pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.
- 8305270484 Forwards IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/04 UTLEY, E E Carolina Power & Light Co 2pp 18644 024 24X Fiche 50-400,83/05/04,8305270484
- --8305270492 IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted Major areas inspected containment steel, reactor vessel & safety-related structures VQRK.J W , LIU, H C Region 2, Office of Director. DLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/03 6pp 18644 026 24X Fiche 50-400,83/05/04,8305270484
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18323 248 24X Fiche 50-000.83/05/06.8303040033
- 8305270609 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-06 & 50-401/83-06 VERRELLI,D M Division of Project & Resident Programs B3/05/10 UTLEY,E E Carolina Power & Light Co. 1p 18647-146 24X Fiche: 50-400, 83/05/10, 8305270609
- --8305270620 Forwards IE Insp Repts 50-400/83-06 & 50-401/83-06 on Fiche 50-400, 83/03/10, 8303270609
- --8305270631 IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220 Noncompliance noted failure to support piping per procedural requirements
 MAXHELL, O F Region 2, Office of Director BEMIS, P. Division of
 Project & Resident Programs 83/04/01, 6pp 18647-153 24X Fich = 50-400, 83/05/10, 8305270409
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EDP) Quidelines." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003, 24X Fiche 50-000,83/05/11,8303040034
- 8305270271 Ack receipt of 830503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12 VERRELLI, D.M. Division of Project & Resident Programs. B3/05/16 UTLEY, E.E. Carolina Power & Light Co. ip 18641-313 24X Fiche 50-400.83/05/16.8305270271
- --8305270281 Responds to NRC 830404 ltr re violations noted in IE Insp. Repts 50-400/83-12 & 50-401/83-12 Corrective actions. Procedure CQC-2 re nonconformance control revised on 830329 to provide guidelines for deficiency rept issuance. PARSONS.R M Carolina Power & Light Co 83/05/03 O'REILLY.J P. Repion 2. Office of Director 2pp. 18641 314 24X Fiche 50-400.83/05/16.8305270271

- --8305270292 Forwards IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 & natice of violation VERRELLI,D M Division of Project & Resident Programs 83/04/04 UTLEY,E E Caroline Power & Light Co 2pp 18641 316 24X Fiche 50-400,83705716,8305270271
- --8305270308 1E Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 Noncompliance noted Deficiency Disposition Rept 1301 not evaluated during 14-day period MAXHELL, G F Region 2, Office of Director BEMIS, P Division of Project & Resident Programs 83/04/04 7pp 18441 319 24X Fiche 50-400,83/05/16,8305270271
- 8303040040 IE Info Notice B3-3i. "Error in ADLPIPE Computer Program "
 Syc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19.8303040040
- 8303040044 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- R. Periodic operating reports & related correspondence
- B3D5020165 Forwards "Quarterly Seismic Monitoring Rept for Jan-Mar 1983"

 ZIMMERMAN, S.R. Carolina Power & Light Co B3/04/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 18284 060 24X Ficha 50-400, B3/04/27, B305020165
- --8305020172 "Seismic Monitoring Program Quarterly Data Rept Jan-Mar 1983 " # Carolina Power & Light Co 83/04/27 ip 18284 061 24X Fichs 50-400,83/04/27,8305020165
- 8 Reportable occurrences, LERs & related correspondence
- B304280299 PNS-11-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified HALL, B L , MCGUIRE, D Region 2, Atlanta, Office of the Director BD/11/04 ip. 18255-330 24X Fiche 50-400, 80/11/04, 8304280299
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor frip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R.C Director's Office. Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427
- 8305030601 Finel deficiency rept re weld deficiencies in Class IE transfer panels Initially reported on 830401. Deficiency not reportable per iOCFRSO 55(e) CHIANOI.N J Carolina Power & Light Co 83/04/25 O'REILLY, J P Region 2, Office of Director 1p 18306 088 24X Fiche 50-400. B3/04/25, 8305030601
- B305i10252 Interim deficiency rept re conduit installed in structural concrete not in accordance w/ACI-318 Initially reported on B30401.Evaluation determined item not reportable per 10CFR50 55(e) CHIANGI, N. J. Carolina Power & Light Co. 83/05/03, D'REILLY, J. P. Region 2, Dffice of Director 1, 18406 338 24X Fiche' 50-400, B3/05/03, B305i10252
- 8305130080 Deficiency rept re Class IE motor control ctrs from ITT Quild containing weld defects Initially reported on 830408 Vendor evaluation to be completed by Jul 1983 Extension until 830713 requested Also reported per Part 21 PARSONS.R M Carolina Power & Light Co 83/05/06 D'REILLY.J P Region 2. OPfice of Director. ip. 18436-264 24X Fiche: 50-400, 83/05/06, 8305130080
- B305130216 Interim rept re deficient welds on emergency svc water selfcleaning strainers. Initially reported on 830408 Evaluation of pressure boundary welds not expected to be completed until June 1983, Next rept will be submitted by 830617 PARBONS, R M Caroline Power & Light Co 83/05/06 D'REILLY, J. P Region 2. DPfice of Director. ip 18439 329. 24X Fiche: 50-400, 83/05/06, 8305130216
- B305130113 Part 21 rept re low natural frequency of counterbalance assembly, resulting in unacceptable stresses on backdraft damper counterbalance arm Beismic qualification criteria not fully met Investigation & testing underway
 HILL, T.D. Ruskin Manufacturing Co. B3/05/10. Director's Office.
 Office of Inspection and Enforcement. 7pp. 18438-001 24X
 Fiche 50-400, 83/05/10, 8305130113

T Hearing transcripts on non-antitrust matters

8303240077 Forwards transcript of Tuggle-Maples, Mackie, Bleacher & Stevens depositions as experts of W Eddleman on security, per 830320 telcan W/o encl
BARTH,C A Hearing Branch 1 83/03/20 EDDLEMAN,W Eddleman, W 1p 18349 094 24X Fiche 30-400,83/03/20,8305240077

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A Application/construction stage documents & correspondence

8308230720 Forwards list of utils responding to requeste for cost figures on backfitting TOURTELLOTTE. J. Regulatory Reform Task Force 83/04/11 PALLADING.N.J. Commissioners 2pp 18542 272 24X Fiche 30-000.83/04/11.83305230720

S Reportable occurrences, LERs & related correspondence

8304280299 PNS-II-80-030 on B01104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified HALL, B L Region 2, Atlanta, Office of the Director B0/11/04 ip 24X Fiche 50-400,80/11/04,8304280299

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 8 Reportable occurrences, LERs & related correspondence

8304280279 PNS-II-80-030 on 80i104 bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified HALL, BL Region 2, Atlanta, Office of the Director 80/11/04 P24X Fiche 30-400,80/11/04,8304280279

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

C Utility Environmental Report (ER), amends & correspondence

8305190349 Application for renewal of License R-126 including financial inforrevised Tech Specs.environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in meil BROPHY.J J Utah. Univ of 83/05/12 Diffice of Nuclear Reactor Regulation. Director 20pp 18500 321 24X Fiche 50-407.83/05/12.8305190349

--8305190349 Environ rept * Utah, Univ of 83/03/07 4pp 18501 015 24X Fiche 50-407,83/05/12,8305190349

I Financial information

8305190349 Application for renewal of License R-126 including financial info, revised Tech Specs, environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail BROPHY, J J Utah, Univ of 83/05/12 Office of Nuclear Reactor Regulation, Director 20pp 19500 321 24X Fiche 50-407,83/05/12,8305190349

P Operating license stage documents & correspondence

8305060660 Advises that License R-126 for TRIGA reactor not considered expired as renewal application dtd 830308 apparently lost in mails
EIBENHUT.D 0 Division of Licensing 83/05/03 BROPHY.J J Utah.
Univ of 1p 18357-356 24X Fiche 50-407.83/05/03.8305060660

8305190349 Application for renewal of License R-126 including financial inforrevised Tech Specs environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail BRUPHY, J J Utish Univ. of 83/05/12 Office of Nuclear Reactor Regulation, Director, 20pp 18300 321, 24X Fiche. 50-407.83/05/12, 8305190349

--8305190360 Proposed Tech Specs & bases for TRIGA reactor * Utah, Univ of 83/05/12 37pp 18500 341 24X Fiche 50-407,83/05/12,8305190349

--8305190369 Environ rept * Utah, Univ of 83/03/07 4pp 18501 015 24X Fiche 50-407,83/05/12,8305190349 --8305190380 Revised reactor operator requalification program SANDQUIST,0 M Utah, Univ of 83/01/31 4pp 18501 019 24X Fiche 50-407.83/05/12.8305190349

V Operator Examinations

8305190349 Application for renewal of License R-126 including financial info, revised Tech Specs, environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail BROPHY, J. J. Utah, Univ. of 83/05/12 Office of Nuclear Reactor Regulation, Director 20pp. 18500-321 24X Fiche. 50-407, 83/05/12, 8305190349

--8305190380 Revised reactor operator requalification program
SANDQUIST. 6 M Utah, Univ of 83/01/31 4pp 18301 019. 24x
Fiche 50-407.83/05/12.8305190349

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8305:10298 Forwards LACBWR onsite meteorological data from Mar 1982 - Feb 1983 WE18S.D Dairyland Power Cooperative 83/05/02 FAIROBENT, J. Division of Systems Integration (post 811005) 159pp 18392 343 24X Fiche 50-409,83/05/02,8305110298

B305i60050 Responds to B30428 telcon requesting writter confirmation of B30419 verbal agreement to Install free-standing metal barrier between HPSH/fire protection diesel driven pumps in cribhouse, to act as radiant shield LINDER, F Dairyland Power Cooperative B3/05/05 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18453 018 24X Fiche 50-409.83/05/05,8305i60050

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl EISENHUT.D. 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X Fiche 50-000,83/05/11.8305110034

8305240327 Forwards response to unresolved item identified during 820920-24 insp Response withheld (ref 10CFR73 21)
LINDER:F Dairyland Power Cooperative 83/05/13 CRUTCHFIELD.D Operating Reactors Branch 5 1p 18573 172 24X
Fichs 50-409.83/05/13.8305240327

8305170416 Notifies that ansite & offsite emergency preparedness adequate NUREG-0737. Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CRR50, "Complete, CRUICHFIELD,D Operating Reactors Branch 5 83/05/16 LINDER,F Dairyland Power Cooperative 3pp. 18469, 250. 24X Fichs. 50-409, 83/05/16, 8305170416

8305190016 Responds to 821020 ltr to changes to physical security, safeguards contingency & guard training & qualification plans Certain proposed changes unacceptable Encl comments withheld (ref 100FR73 21) CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/17 LINDER, F. Dainyland Power Copparative 1p. 18501-358. 24X Fichs. 30-409, 83/05/17, 8305190016

8305310169 Forwards listed changes to EPP-2. Issue 9. "Organization & Operations During Emergencies" Ack of receipt requested. W/o encl.
LINDER: F. Dairyland Power Cooperative 83/05/23 Region 3. Office of Director ip. 18652:296 24X Fichs 30-409:83/05/23. 8308310169

Q Adjudicatory correspondence

BB05100214 Discusses ABLB 830421 initial decision deciding show cause proceeding re lique/action potential at facility. SBE of 0 12 g assequate & conservative description, Dawatering systemed not be installed to preclude liquefaction CUNNINGHAM. OH Office of the Executive Legal Director 83/04/28, DENTON, HR Office of Nuclear Reactor Regulation, Director DEYQUNG.R. Director's Office Office of Inspection and Enforcement, 3pp 18374:185 24X Fiche 50-409, 83/04/28, 8305100214

8305200452 Forwards ASLP Initial Decision 80-445-01 SC re liquefaction potential at LACBHR Util neither required to submit detailed design proposal for nor make operational site dewatering sys, CRUTCHFIELD, D Operating Reactors Branch 5. 63/05/19 LINDER, F. Dainyland Power Cooperative. 3pp 16513.023. 24X Fiche 50-409,83/05/19,8305200452

J Insurance & indemnity information

8305230027 Forwards Endorsements 50 & 51 to NELIA Policy NF-217 DEVINE:H F Dairyland Power Cooperative 83/05/16 DINITZ, I Office of Nuclear Reactor Regulation, Director 2pp 18539:197, 24X Fichs 50-409,83/05/16,8305230027

P. Operating license stage documents & correspondence

8305040682 INTEGRATED PLANT SAFETY ASSESSMENT REPORT, SYSTEMATIC EVALUATION PROGRAM - LACROSSE BOILING WATER REACTOR Dockst No. 50-409 (Dairyland Power Cooperative)

* Division of Licansing NURS-0827 83/04/30 494pp 18334-142 24X Fichs 50-409,83/04/30,8305040682

8305020455 Gengric Ltp 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Syc list encl EISENHUT.D O Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

8305;00025 Forwards Class II fee for 820607 application to amend License DPR-45, in response to NRC 830118,0314 & 0412 ltrs Util maintains that fee not appropriate, as described in util 830315 ltr LINDER, F Dairyland Power Cooperative 83/05/02 MILLER, H G License Fee Management Branch. 1p 18377 115 24X Fiche 50-409,83/05/02.8305100025.

8305120066 Confirms pumping time/fuel consumption of emergency sycurater supply sys pumps using flooding bases similar to alternate core spray sys.per Dudley 830420 telcon Specific cases discussed LINDER, F Dairyland Power Cooperative, 83/05/02 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18431.024 24X Fiche 30-409,83/05/02,8305120066

8305070657 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl.
EISENHUT, D @ Division of Licensing, 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153 24X Fiche-30-000, 83/05/07, 8305070659

8305230398 Forwards response to 830330 request for clarification of items identified in SER on environ qualification of safety-related electrical equipment Request for extension to 1984 refueling outage schedule repeated per 830311 ltr LINDER: Dairyland Power Cooperative. 83/05/16 CRUYCHFIELD, D. Operating Reactors Branch 5 4pp. 18538 228. 24X Fiche 80-409, 83/05/16, 8305230398

8305260082 Advises that facility design acceptable TMI Action Item II K.3 28, "Gualification of Accumulators on Automatic Depressurization Bys Valves," resolved Bafety evaluation enci.

CRUTCHFIELD,D Operating Reactors Branch 5 83/05/24 LINDER,F Dairyland Power Cooperative 5pp 16599,302 24X
Fiche 30-409,83/05/24,8305260082.

8305270002 Forwards SER accepting licenses actions in response to TMI Action Plan Item II K 3 25. Effect of Loss of AC Power on Pump Seels "Seel injection will continue even if offsite power lost CRUTCHFIELD.D Operating Reactors Branch 5 83/05/25 LINDER,F. Dairyland Power Cooperative. 3pp. 18633 346 24X Fichs 50-409.83/05/25.8305270002

Q Inspection reports. IE Bulletine & correspondence

8212060383 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list and.
TAYLOR.J M. Division of Safeguerds & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co. of New York: Inc 112pp 18308 319 24X Ficher 50-000.83/03/21.8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator."

8vc list encl
JDRDAN,E L. Division of Emergency Preparadness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New
York, Inc. 126pp 18435:133 24X Fiche: 30-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Sefety/Relief Valve Failures." Bvc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22, Consolidated Edison Co. of New York, Inc 112pp, 18383'089 24X Fiche 30-000,83/04/22,8303040023

- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fithe 50-000.83/04/25.8303040025
- 8303040026 IE Info Notice 93-24, "Loose Parts in Secondary Side of 8team Generators at PWRs " 8vc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24% Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 18982 165 24X Ficha 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list and URDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) B3/05/03 Consolidated Edison Co. of New York, Inc. 122pp 1844i 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Fost 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305130258 Informs that draft "Regulatory Improvement Program," submitted W/util 830404 ltr.responsive to NRC concerns Program implementation will be monitored Info re changes to program milestones requested KRPPLER.J & Region 3. Office of Director 83/05/05 LINDER, F W Dairyland Power Cooperative 1p 18437 220 24X Fiche 50-407.83/05/05.8305130258
- --8305130267 Forwards draft "Regulatory Improvement Program" Draft derived from meetings w/Region III & reviewed by M Brach, resident inspector TAYLOR.J H Dairyland Power Cooperative 83/04/04 KEPPLER.J Q Region 3. Office of Director ip 18439 222 24X Fichs.50-409,83/05/05.8305130258
- --8305130271 Draft Procedure 032483JWT: "Regulatory Improvement Program"

 * Dairyland Power Cooperative. 83/04/04 15pp 18437 223 24X
 Fiche 50-409,83/05/05,8305130258
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " 8vc list enc! JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New Y
- 8305130109 Atk receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-02 BHAFER.W.D Region 3. Office of Director 83/05/10. LINDER,F W. Dairylland Power Cooperative 1p. 18437 360 24X Fiche. 50-409, 83/05/10, 8305130109.
- --8305130112 Responds to NRC B30330 ltr re violations noted in IE Insp Rept 50-409/83-02. Corrective actions contract issued to Nuclear Energy Svcs. Inc for svcs including applicable 10CFR30, App 8 & Part 21 requirements LINDER, F Dairyland Power Cooperative 83/04/19 STREETER, J. E Region 3. Diffice of Director 2pp 18437; 361 24X Fiche 50-409, 83/05/10, 8305130109
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Syc list encl UGRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11. Consolidated Edison Co. of New York, Inc. 144pp. 18524.003 24X Piche.50-000.83/05/11,8303040034
- 8303260286 Forwards 1E Insp Rept 50-409/83-04 on 830411-15 No noncompliance noted BYREETER, J. F Region 3, Office of Director, 83/05/12 LINDER, F W Dairyland Power Cooperative 2pp 18626; 111 24X Fiche' 50-409, 83/05/12, 8303260256.

- --B305260258 IE Insp Rept 50-409/83-04 on B30411-15 No noncompliance noted Major areas inspected licensed & unlicensed employee training, licensed operator requalification training & GA audits of training program SUTPHIN.R N , HAWKINS,F C B3/05/12 7pp 18626 113 24X Fiche 50-409, B3/05/12, B305260256
- 8305240327 Forwards response to unresolved item identified during B20920-24 insp Response withheld (ref 10CFR73 21) LINDER,F Dairyland Power Cooperative 83/05/13 CRUTCHFIELD,D Operating Reactors Branch 5 ip 18573 172 24X Fiche 50-409,83/05/13.8305840327
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Byc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- R Periodic operating reports & related correspondence
- 830511029B Forwards LACBUR onsite meteorological data from Mar 1982 ~ Feb 1983 WE198.D Dairyland Power Cooperative 83/05/02 FAIROBENT, J Division of Bystems Integration (post 811005) 199pp 18392 343 24X Fiche 50-409,83/05/02,8305110278
- 8305310154 Forwards annual environ radioactivity monitoring repts for 1992 H/o encl
 MCDONNELL,L J Wisconsin, State of NRC-05-B0-275 83/05/23
 KEPPLER,J G Region 3, Office of Director ip 18459 140 24X
 Fiche 50-000,83/05/23
- B Reportable occurrences, LERs & related correspondence
- B305020144 Forwards LER 83-001/03L-0 & updated LER 82-020/03X-1 Detailed event analysis encl LINDER,F Dairyland Power Cooperative B3/04/21 KEPPLER, J 0 Ragion 3, Office of Director 3pp 19278 194 24X Fiche 30-409,83/04/21
- --8305020170 LER 83-001/03L-0 on 830325, following low reactor water level scram, iB HPCS pump observed not running. Caused by backward installation of current transformer in HPCS pump breaker ground fault trip device GOODMAN.L 8 Dairyland Power Cooperative 83/04/21 Region 3. Office of Director 1p 18278 197 24X Ficha 50-409, 83/04/21.
- --8305020182 Updated LER 82-020/03X-1 on 921119-20, on three occasions vacuum pump which maintains isokinetic flow rate to stack activity monitors tripped Caused by pump & motor overheating Motor thermal overload fuses upgraded GODMAN, L. S. Dajryland Power Cooperative 83/04/21 Region 3, Office of Director ip 18278 198 24X Fiche 50-409, 83/04/21, 8305020146
- T Hearing transcripts on non-antitrust matters
- 8305100164 Transcript of ACRS LACBUR SEP Subcommittee 830506 hearing in Washington, DC Pp 1-166 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/05/06 227pp 18370 265 24% Fiche 50-407,83/05/06,8305100164
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UN1: 2

 A Application/construction stage documents & correspondence
- B305090633 Forwards FR notices of receipt of OL application, notice of availability of environ rept.notice of consideration of issuance of OL & notice of opportunity for hearing BCHMENCER, A Licensing Branch 2 83/05/02 RHDDE, G K Niagara Mohawk Power Corp 4pp 18367 307 24% Fiche 50-410.83/05/02, 830590633
- --8303090648 Notice of receipt of application for OL, notice of availability of environ rept.notice of consideration of issuance of OL & notice of opportunity for hearing SCHMENCER, A. Licensing Branch 2 83/05/02 7pp 18367 311 24% Fiche. 50-410,83/05/02.8305090633

- --8305090452 Notice of opportunity for public participation in proposed NRC licensing application by Niagara Mohawk Power Corp. et al. for Nine Mile Point Station Unit 2

 NRC - No Detailed Affiliation Given 83/05/02 4pp 10367 318 24X Fiche 50-410, 83/05/02, 8305090633
- 8305110315 Application for Amend 2 to OL application (filed in PDR Category A).consisting of Amend 2 to FSAR (filed in PDR Category K) & Suppl 1 to environ rept OL stage (filed in PDR Category C) Affidavit of Svc encl.

 MANGAN, C V Niagara Mohawk Power Corp 83/05/05 EISENHUT. D Q
 Division of Licensing 6pg 18394 001 24X Fiche 50-410,83/05/05, 8305110315
- B305180054 Summary of B30428 meeting w/util, GE & AE in Bethesda.MD re licensing review of GL application & specific review issues HAUOHEY.M F Licensing Branch 2 83/05/05 Licensing Branch 2 13pp 18499 330 24% Fiche 50-410
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D @ Division of Licensing 83/05/09 (Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09.8305090659 Consolidated
- 8305230574 Forwards repts in response to FSAR & environ rept OL stage acceptance review questions per NRC request for add1 info to 830419 submittal re OL application List of repts submitted enci MANGAN,C V Niagara Mohawk Power Corp 89/05/13 EISENHUT,D G Division of Licensing 3pp 18600 001 24X Fiche 50-410,83/05/13, 8305230574
- --9305230582 Forwards add1 info re FSAR & environ rept GL stage per NRC 830329 request List of repts submitted encl RHODE 6 % Niagara Mohawk Power Corp 83/04/19 EISENHUT, D 6 Division of Licensing 3pp 18600 004 24Y Fiche 50-410, 83/05/13, 8305230574
- --8305230585 "316(a) Demonstration Submission. NPDES Permit NY 0001015 "
 * Niagara Mohawk Power Corp 83/05/13 224pp 18600 007 24X
 Fich 50-410, 83/05/13, 8305230574
- --8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Dawego Steam Station Unit 6." interim rept 4 Lawler: Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 B2pp 18600 231 24% Fiche 50-410.83/05/13.8305230574
- --8305230592 "316(a) Demonstration Submission Permit NY 0020109 " * Power Authority of the State of New York 83/05/13 217pp 18600 308 24X Fiche 50-410/83/05/13/8305230574
- ---8305230569 "316(b) Demonstration Submission Permit NY 0020109 "
 * Power Authority of the State of New York 83/05/13 325pp
 18601 165 24X Fiche: 50-410, 83/05/13, 8305230574
- --8305230603 "Fish Tag Rept Summary 1972-76 " STORR.J F Storr. J F 76/12/31 95pp 18602 130 24X Fiche 50-410,83/05/13,8305230574
- --8305230607 Vol (to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish, 1973 " 4 Quirk, Lawler & Matusky Engineers 74/08/31 59ipp 18602 225 24X Fiche 30-410, 83/05/13, 8305230374
- --8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies. Fish Impingement, Water Quality, 1973 "
 # Quirk, Lawier & Matusky Engineers 74/08/31 268pp
 18604 094 244 Fische 50-410, 83/05/13, 8305230374
- --B305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 1, Apps I~III (a-d) Methods & Matls, Statistical Procedures, Plankton: 1973 " * Guirk, Lawler & Matusky Engineers 83/05/13 508pp, 18605 001 24X Fiche 50-410.83/05/13.8305230574
- --8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 2, App III (=-p),Plankton.1973 " Quirk, Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24X Fiche 50-410.83/05/13.8305230574
- --8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV. V. VI Benthos, Fish, Fish Impingement, 1973 " 4 Gulfk, Lewler & Hatusky Engineers 83/05/13 396pp. 18608:006 24X Fiche: 50-410,83/05/13,8305230574.

- --8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4, App VII Hater Quality, 1973 " * Quirk, Lawler & Matusky Engineers 83/05/13 291pp 18610 015 24X Fiche 50-410,83/05/13,8305230574
- --8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I~IV. 1974 Lawier, Matusky & Skelly Engineers 75/12/31 993pp 507 042 24X Fiche 50-410, 89/05/13, 8305230574
- --- 8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters 703=31053 vs. 11 vs. 12 vs. 13 vs. 13 vs. 14 vs. 14 vs. 15 vs. 15 vs. 16 vs. 16
- --8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975." * Lawler-Matusky & Skelly Engineers LMSE-76/0081&191-033 76/03/31 497pp 18611 226 24X Fiche 50-410.83/05/13, 8305230574
- --8305830466 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1978 *

 * Lawler, Matusky & Skelly Engineers 77/05/31 489pp
 18613 001 24X Fiche 50-410,83/05/13,8305230574
- --8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies, App I-1%, Lawler, Matusky & Skelly Engineers. 77/05/31 514 130 24X Fiche 50-410, 83/05/13, 8305230574
- --8305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 " * Texas Instruments, Inc 78/05/31 875pp 18616 061, 24X * Taxas Instruments, Inc 78/09
- --8305230681 "316(a) Demonstration Bubmission, NPDE8 Parmit 070 0X2 2 000632 NY (0003212) " Niagara Mohauk Power Corp 83/05/13 150pp 18618 216 24) Fiche 50-410,83/05/13,8305230574 89/05/13 150pp 18618 216 24X
- --8305230684 "Intake Considerations: NPDES Permit 070 0X2 2 00632 NY (0003212) " TOUGHER | 1 Niagara Mohawk Power Corp | 83/05/13 | 50pp | 18619.006, 24X | Fich | 50-410.83/05/13.8305230574
- -8305230687 "316(a) Demonstration Submission NPDES Parmit 070 0X2 2 000633 NY (000321) "

 * Niagara Mohawk Power Corp LMSE-75/0363&191/029, 93/05/13
 192pp 18619 053 24X Fiche 50-410,83/05/13,8305230574
- --8305230691 "Intake Considerations NPDES Permit 070 0X2 2 000633 NY (0003221) " * Niagara Mohawk Power Corp 8: Fiche 50-410,83/05/13,8305230574 83/05/13 50pp 18619:205. 24X
- --8305230494 "3}6(A) Demonstration Submission NPDES Permit NY 0002186." * Nlagara Mohawk Power Corp 83/05/13 460pp 18619 249 24K Fich# 50-410,83/05/13,8305230574
- --8305230699 "Intake Considerations NPDES Permit NY 0002186 "
 * Niagara Mohawi Power Comp 83/05/13 149pp 18620 3
 Fiche 50-410.83/05/13.830523074 18620 349 24X
- --8305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 6 Gamego Steam Station "

 # Stone & Webster Engineering Corp 77/05/31. 52pp 18681'138 24% Fichs 50-410.83/05/13.8305230574
- 6305240498 Responds to 830419 Generic Ltr 83-18 requesting addl info re review of BWR Coners Group control room survey program Info addressed in 830414 ltr to NRC. MANGAN.C V Niagara Mohawk Power Corp 83/05/18 EISENHUT, D. G. Licensing 1p 18572 068 24X Fiche 50-410,83/05/18, Division of Licensing 8305240498
- C Utility Environmental Report (ER), amends & correspondence
- 8305090633 Forwards FR notices of receipt of OL application, notice of avolvoous Forwards FR notices of receipt of OL application.notice availability of environ rept.notice of consideration of issuance of OL & notice of opportunity for hearing SCHMENCER.A Licensing Branch 2 83/05/02, RHODE,0 K Niagar Mohawk Power Corp 4pp 18367 307 24X Fiche 50-410,83/05/02,8305090633
- --8305090648 Notice of receipt of application for OL, notice of availability of environ rept.notice of consideration of issuance of OL & notice of opportunity for hearing SCHMENCER.A. Licensing Branch 2 83/05/02 7pp 18367;311. 24X Fiche 50-410.83/05/02.8305090633

- B305110315 Forwards Buppl 1 to environ rept OL stage (filed in PBR Category C)
 MANGAN,C V Niagara Mohawk Power Corp B3/05/05 E19ENHUT,D G
 Division of Licensing 6pp 18374 001 24X Fiche 50-410,83/05/05.
 B305110315
- --8305110359 Suppl I to environ rept QL stage + Niagara Mohawk Power Corp 83/05/31 79pp 18394 007 24X Fiche 50-410,83/05/05,8305110315
- 9305230574 Forwards repts in response to FBAR & environ rept OL stage acceptance review questions per NRC request for addl info to 930419 submitted re OL application List of repts submitted encl MANGAN.C V. Nisaara Mahawk Bayan Corp. 93408449 STERRANDER D.
- MANGAN, C V Niagara Mohawk Power Corp 83/05/13 EISENHUT, D G Division of Licensing 3pp 18600 001 24X Fiche 50-410,83/05/13,8305230374
- --8305230585 "316(a) Demonstration Submission NPDES Permit NY 0001015 "
 * Niagara Mohawk Power Corp 83/05/13 224pp 18600 007 24x
 Fiche 50-410,83/05/13,8305230574
- --8305230587 "Evaluation of Angeled Screan Fish Divers Sys at Oswego Steam Station Unit 6." interim rept * Lawier, Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 82pp 18600 231 24X Fiche 50-410, 83/05/13, 8305230574
- ~-8305230592 "316(a) Demonstration Submission Permit NY 0020109 "
 # Power Authority of the State of New York 83/03/13 217pp
 18600 308 24X Fiche 50-410,83/05/13,8305230574
- --8305230599 "316(b) Demonstration Submission Permit NY 0020109 "
 # Power Authority of the State of New York 83/05/13 325pp 18601 165 24X Fiche 50-410,83/05/13,8305230574
- ~-8305230603 "Fish Tag Rept Summary 1972-76" STORR.J F Storr, J F 76/12/31 95pp 18602 130 24X Fiche: 50-410,83/05/13,8305230574
- ~~8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish, 1973 " * Quirk, Lawler & Matusky Engineers 74/08/31 591pp 18602 225 24X Fiche 50-410, 83/05/13, 8305230574
- --8305230614 Vol II to "Nins Mile Point Aquatic Ecology Studies:Fish Impingement, Water Quality, 1973 "
 # Guirk, Lawler & Maturky Engineers 74/08/31 268pp 18604:096 24X Fichs 50-410,83/05/13,8305230574
- ~-8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 1. Apps 1-III (a-d) Methods & Matls, Statistical Procedures, Plankton, 1973 " # Guirk, Lawler & Matusky Engineers 83/05/13 508pp 18605: 001 24X Fiche 50-410, 83/05/13, 8305230574
- --8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (=-p) Plankton, 1973 " * Quink, Lawler & Matusky Engineers 83/05/13 377pp 18606 149 24X Fiche 50-410, 83/05/13, 8305230574
- ~-8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV. V. VI Benthos, Pish, Fish Impingement, 1973 " * Quirk, Lawler & Matusky Engineers 83/05/13 396pp 18608 006 24X Fiche 50-410, 83/05/13, 8305230574
- -8305230444 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4. App VII. Hater Quality, 1973" # Quirk, Lauler & Hatusky Engineers 83/05/13 291pp 18510:015 24X Fiche 50-410.83/05/13.8305230574
- ~-8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV, 1974" "Lewler, Matusky & Skelly Engineers 75/12/31, 933pp, 18609:042 24X Fiche 50-410,83/05/13,8305230574,
- --8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters VII-X), 1974 "

 * Lewier: Matusky & Skelly Engineers, 75/12/31 280pp
 18610-306 24X Fiche 50-410,83/05/13,8305230574
- --8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975 "

 * Lawler, Matusky & Skelly Engineers, LMSE-76/00818191-033
 76/05/31 497pp 18611 226 24X Fiche 50-410, 83/05/13,
 8305230574.
- --9305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
 # Lawler Matusky & Skelly Engineers. 77/05/31 489pp
 18613 OOI 24X Fiche. 50-410, 83/05/13, 8305230574

- ~-8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies.App I-IX, 1976" * Lawler, Matusky & Skelly Engineers 77/05/31 65ipp 18614 130 24X Fiche 50-410,83/05/13,8305230574
- --8309230480 "Nine Mile Point Aquatic Ecology Studies, 1977 " * Texas Instruments, Inc 78/05/31 875pp 18616 061 24X Fiche 50-410,83/05/13,8305230574
- --B305230681 "3i6(a) Demonstration Submission NPDES Permit 070 0X2 2 000632 NY (0003212) " * Niagara Mohawk Power Corp 83/03/13 150pp 18618 216 24X Fichs 30-410,83/03/13.8305230574
- ~-8305230684 "Intake Considerations, NPDES Permit 070 0X2 2 00632 NY (0003212) "

 * Niagara Mohawk Power Corp 83/05/13 50pp 18619 006 24X
- Fiche 50-410.83/05/13.8305230574
 --8305230AB7 "316(a) Demonstration Submission NPDES Permit 070 0X2 2
- * Niagara Mohawk Power Corp LMSE-75/0363&191/029 83/05/13 1520p 18619 053 24% Fiche 50-410,83/05/13,8309230574

000933 NA (0003551) 4

- --B305230691 "Intake Considerations NPDES Permit 070 0X2 2 000633 NY (0003221) "

 * Niagara Mohawk Power Corp 83/05/13 50pp 18619 205 24X Fiche 50-410,83/05/13,8305230574
- --8305230696 "316(A) Demonstration Submission NPDES Permit NY 0002186 "
 * Niagara Mohawk Power Corp 83/05/13 460pp 18619 249 24X Fiche 50-410,83/05/13,8305230574
- --8305230499 "Intake Considerations NPDES Permit NY 0002186" * Niagara Mohauk Power Corp. 83/05/13 149pp 18620 349 24X Fiche 50-410, 83/05/13, 8305230574
- --B305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 6 Owengo Steam Station "

 * Stone & Webster Engineering Corp 77/05/31 52pp 18621 138 24% Fiche 50-410, 83/05/13, 8309230574
- 8305260086 Forwards Affidavit of 9vc indicating that Amend 2 to FSAR & Suppl 1 to environ rept OL stage, provided to appropriate parties delineated in 830329 ltr Distribution lists encl MANOAN, C V Niagara Mohawk Power Corp 83/05/23 EISENHUT, D G Division of Licensing 5pp 18579 309 24% Fichs 50-410,83/05/23,830536086
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8305110296 Distusses draft EIS received on B30415 which indicated no known historic significant sites will be directly affected by plant operation Gouncil must be afforded opportunity to comment prior to granting license or permit KLIMA: D.L. Advisory Council on Historic Preservation 83/05/09 84KOSKI,L. Siting Analysis Branch 17pp 18393 256 24X Fiche 50-410.83/05/09.8305110296
- F Security, medical, emergency & fire protection plans
- 8305030515 Forwards revised meteorological data tape for facility Physical specs of data taps unchanged from previous submittal Taps will be included in next FSAR amend W/o encl MANOAN.C V Niagara Mohawk Power Corp 83/04/29 SCHWENCER.A Licensing Branch 2 ip 18300.337 24X Fichs 50-410.83/04/29,8305030515
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18940 095 24X Fiche 50-000, 83/05/11, 8305110034
- O. Adjudicatory correspondence
- 8305090633 Forwards FR notices of receipt of OL application.notice of availability of environ reptinctics of consideration of issuance of OL & notice of opportunity for hearing BCHMENGER, A Licensing Branch 2 B3/05/02 RHODE, G K Niagara Mohawk Power Corp 4pp 18367 307 24% Fiche. 50-410, 83/05/02, 830506663

- --8305090648 Notice of receipt of application for OL, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing SCHMENCER, A Licensing Branch 2 83/05/02 7pp 18367 311 24X Fiche 50-410,83/05/02,8305090633
- K Utility Final Safety Analysis Report (FBAR) & amends
- B30421023B Forwards Amend 1 to FSAR, consisting of SRP deviation statements, page changes & 1,470 oversize drawings MANOAN.C V Niagara Mohawk Power Corp B3/04/13 £18ENHUT.D O Division of Licensing 2pp 18090 272 24X Fiche 50-410,83/04/13.B30421023B
- --8304210240 Amend 1 to FSAR W/1.216 oversize drawings & 254 oversize figures Aperture cards are available in PDR * Niagara Mohawk Power Corp 83/04/30 387pp 18090.274 24X Fiche 50-410.83/04/13.8304210238
- B305:103:5 Forwards Amend 2 to FSAR (filed in PDR Category K)
 W/21 oversize drawings Aperture cards are available in
 PDR
 MANOAN.C V Niagara Mohawk Power Corp. B3/05/05 EISENHUT, D Q
 Division of Licensing App 18394 001 24X Fiche 50-410,83/05/05,8305:103:15
- --8305110372 Amend 2 to FSAR W/21 oversize drawings Aperture cards are available in PDR * Niagara Mohawk Power Corp 83/05/31 136pp 18394 085 24X Fiche 30-410.83/05/05.8305110315
- 8303240086 Forwards Affidavit of Svc indicating that Amend 2 to FSAR & Suppl 1 to environ rept ~ OL stage, provided to appropriate parties delineated in 830329 ltr Distribution lists encl MANOAN.C V Niagara Mohawk Power Corp. 83/05/23 EISENHUT.D 0 Division of Licensing 5pp 18599 309 24X Fiche 50-410,83/05/23,8303240086
- M Antitrust correspondence
- 830313002B Forwards add info requested on 830321 re antitrust review of OL application
 MANGAN,C V Niagara Mohawk Fower Corp. 83/05/07 REOAN,W H Bite
 Analysis Brench 21pp 18437 104 24X Fiche 50-410,83/05/07,
 830513002B
- G Inspection reports, IE Bulletins & correspondence
- 8212040305 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction "Svc list encl TAYLOR.J M Division of Safequards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York. Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8305230527 Forwards expurgated statements not previously submitted w/IE Investigation Rept 50-410/82-078 re improper use of GC inspector trainess by S&V STAROSTECKI.R Division of Project & Resident Programs. 83/03/24 RHODE, 0 K Niagara Mohawk Power Corp 26pp. 18537:029. 24X Fichs 30-410.83/03/24.8305230527
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 8vc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103). 83/04/15 Consolidated Edison Co of New

 York, Inc 126pp. 18435:153 24X Fiche 50-000;83/04/15;8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures."
 Syc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). B3/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche: 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list and I JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382'047 24X Fiche: 50-000,83/04/28,8303040026

- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Empresscy Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028.
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Syc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282, 24X Fichs 50-000, 83/05/04, 8303040030,
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Bvc list enc] JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441.001 24X Fiche 50-000,83/05/04,8303040031
- 8305160093 Responds to request for add1 info re IE Bulletin 82-01, Rev 1, Suppl 1. Three welds inaccessible for reradiography currently under evaluation Two add1 welds w/enhanced radiographs found satisfactory MANNO, 8 F Niagara Mohewk Power Corp 83/05/04 STAROSTECKI, R Division of Project & Resident Programs 2pp 18452 013 24X Fiche 30-410, 83/05/04, 8305160093
- 8305190331 Forwards IE Insp Rept 50-410/83-04 on 830314-0415.No noncompliance noted BTARD8TECKI.R Division of Project & Resident Programs 83/05/04 RHDBE, O. K. Niagara Mohawk Power Corp 2pp 18500-305. 24X Fiche 50-410.83/05/04,8305190331
- --8305190334 IE Insp Rept 50-410/83-04 on 830314-0415 No noncompliance noted Major areas inspected, safety-related piping, licensee surveillance, contractor audits, instrumentation tubing supports & structural steel SCHUZ-R D, KISTER-M.B. Region 1, Offics of Director, 83/05/02 iipp. 18500:307 24X Fiche 50-410,83/05/04,8305190331
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl. JORDAN.E.L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/05/06. Consolidated Edison Co. of New York, Inc. 115pp. 18323 248 24X Fiche, 50-000, 83/05/06, 8303040033
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines," Svc list encl URDAN.E.L Division of Emergency Preparedness & Engineering Response (Post B30103), B3/05/11. Consolidated Edison Co of New York. Inc 114pp 18524.003 24x Fiche, 80-000, 83/05/11, B303040034.
- 8303040040 IE Info Notice 83-31: "Error in ADLPIPE Computer Program," Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/19 Consolidated Edison Co of New York: Inc. 114pp. 18497.009 24X Fiche 50-000,83/05/19,8303040040.
- 8305270638 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/83-02 STARDSTECKI, R. Division of Project & Resident Programs 83/05/19 RHODE, 0 K Niagara Mohawk Power Corp 1p 18646-207. 24X Fiche: 50-410,83/05/19,8305270438
- --8305270645 Responds to NRC 830328 ltr re violations noted in IE Insp. Rept 50-410/83-02 Corrective actions correct process planner was obtained before restarting work & foremen & superintendent retrained MANNO, S. F. Niagara Mohawk Power Corp. 83/04/26 STAROBTECKI, R. Region i, Office of Director 3pp 18646, 208 24X Fiche 50-410, 83/05/17, 8305270638.
- 8303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Gil " Svc list encl JORDAN:E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26, Consolidated Edison Co. of New York, Inc. 114pp, 18647:007 24X Fichs. 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305230574 Forwards repts in response to FBAR & environ rept - OL stage acceptance review questions per NRC request for addit info to 830419 submittal re OL application List of repts submitted entl.

MANQAN,C V Niagara Mohawk Power Corp 83/05/13 EISENHUT,D G Division of Licensing 3pp 18600 001 24% Fiche 50-410,83/05/13,8305230574

- --8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6." interim rept + Lawler: Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 B2pp 18600 231 24X Fiche 50-410.83/05/13.8305230574
- --8305230603 "Fish Tag Rept Summary 1972-76" BTDRR: J F Storr, J F 76/12/31 93pp 18602 130 24X Fiche: 50-410, 83/05/13,8305230574
- --8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish. 1973 " • Guirk, Lawler & Matusky Engineers 74/08/31 59ipp 18602. 225 24x Fiche 50-410. 83/05/13, 8305230574
- ---8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies, Fish Impingement, Water Quality, 1973"

 ** Quirk, Lawler & Matusky Engineers 74/08/31 268pp
 18604 096 24% Fiche, 50-410, 83/05/13, 8305230574
- --8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 1, Apps I-III (a-d), Methods & Matls, Statistical Procedures, Plankton, 1973." • Quirk, Lawler & Matusky Engineers 83/05/13 508pp 18605:001 24X Fiche 50-410, 83/05/13, 8305230574
- --B30523062B Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (=-p) Plankton, 1973 " duirk, Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24X Fiche 50-410,83/05/13,8305230574
- --8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV. V. VI Benthos, Fish, Fish Impingement, 1973" * Quirk, Lawler & Matusky Engineers 63/05/13 376pp 18608:006 24% Fiche 50-410, 83/05/13, 8305230574
- ---8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Pert 4, App VII: Mater Guality, 1973 "

 # Guirk, Lawler & Matusky Engineers 83/05/13 291pp
 18610:015. 24X Fiche, 50-410,83/05/13,8305230574
- --8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV, 1974 " + Lawler, Matusky & Skelly Engineers 75/12/31 333pp 18609, 042. 24% Fiche 50-410, 83/05/13, 8305230574.
- ---8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters VII-X), 1974 "

 * Lawler, Matusky & Skelly Engineers 75/12/31 280pp 18610 306 24X Fiche: 50-410, 83/05/13, 8305230574
- --8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975,"

 * Lawler, Matusky & Skelly Engineers LMSE-76/0061&191-033.
 76/05/31. 497pp 18611, 226 24X Fiche, 50-410, 83/05/13, 8305230574.
- --8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
 # Lawler, Matusky & Skelly Engineers 77/05/31 489pp
 18613.001 24X Fiche: 50-410, 83/05/13, 8305230574
- --8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies: App I-IX: 1976."

 * Lawler: Matusky & Skelly Engineers. 77/05/31. 651pp. 18614: 130. 24% Fiche: 50-410: 83/05/13. 8305230574
- --8305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 "

 * Texas Instruments, Inc., 78/05/31, 875pp 18616.061 24X
 Fiche: 30-410, 83/05/13, 8305230574
- 8. Reportable occurrences, LERs & related correspondence
- 8305120372 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328. Matter under investigation Final rept by 830808 Reported per Part 21.

 MANNO, 8.F. Niagera Mohawk Power Corp 83/04/26. BTAROBTECKI, R Region I, Office of Director. 2pp 18433:072. 24X
 Fiche: 50-000.83/04/26.8305120392.

- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83/03/11 CGLLINS.J T Region 4. Office of Director 5pp 18433 074 24X Fiche 50-000.83/04/26,8305120392
- 8305120334 Interim deficiency rept re GE control rod drive sys clamps Initially reported on 830405 Clamps not ASME qualified Final rept will be submitted by 830829 MANNO.6 F Niagara Mohawk Power Corp 83/05/04 STAROSTECKI, R Division of Project & Resident Programs 2pp 18432 292 24X Fiche 50~410,83/05/04.8305120334
- 8309250430 Suppls 820402 final deficiency rept re Power Strut spring nuts Corrective actions completed Nuts from Field Purchase Order 12113 returned to vendor S&W GA Insp Plan N20006AFA008 revised to ensure use of proper spring nut MANNO.8 F Niagara Mohawk Power Corp 83/05/16 STAROSTECKI.R Division of Project & Resident Programs 1p 18585 286 24X Fiche 30-410.89/05/16.8303250430
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J Regulatory Reform Task Force B3/04/11 PALLADINO.N J Commissioners 2pp 18542 272 24X Fiche: 50-000, 83/04/11, 8305230720
- 8305230263 Informs of NRC determination that probability of unacceptable damage due to turbine missites acceptably low, provided turbine missite generation probability maintained as specified **MIGHTON.O W Licensing Branch 3 83/04/28 WGOLEVER.E J Duqueene Light Co 3pp 18543 258 24X Fiche 50-412.83/04/28, 830320263
- B305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EIBENHUT.D G Division of Licensing B3/05/09 Consolidated Edison Co of New York. Inc 16pp 18627-153 24X Fiche 50-000.83/05/09.8305090659
- C Utility Environmental Report (ER), amends & correspondence
- 8305170199 Summary of 830322 meeting w/util & 5kW in Bethesda, MD reenviron rept OL stage LAZO, L. Licensing Branch 3 83/05/10 Licensing Branch 3 24pp 18496-144 24X Fiche: 30-412, 83/05/10, 8305170199
- 8305180559 Forwards environ rept for Beaver Valley Power Station.Unit 2. HODLEVER,E J Duquesne Light Co 83/05/16. DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18550 001 24X Fiche 50-412.83/05/16.8305180559
- --8305180576 Environ rept OL Stage for Beaver Vailey Power Station, Unit 2 Errata enci * Duquesne Light Co 83/05/16 7819p 18568 119 24X Fiche 50-412:83/05/16.8305180559
- F Security, medical, emergency & fire protection plans
- B3D5020426 Informs of mod to Unit 1 emergency preparadness plan to include Unit 2 Units will have one emergency plan & separate sats of implementing procedures HOOLEVER.E J Duquesne Light Co B3/04/28 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp. 18273 192 24X Fichs 50-412.83/04/28.8305020426
- 8305170186 Summary of 830317 meeting w/util in Bethesda,MD re physical security plan Plan required by 830731 LAZO,L Licensing Branch 3. 83/05/10 Licensing Branch 3 App 18496 140 24X Fiche 80-412,83/05/10,8305170186
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits BVc list snel EISEMHUT. D. O Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540:095, 24X Fiche 50-000.83/05/11.8305110034

- B305310234 Summary of B30411 meeting w/util in Bethesda.MD re schedule for completing items in Generic Ltr B2-33.Suppl 1 to NUREG-0737 requirements for emergency response capability LAZO,L Licensing Branch 3 83/05/11 Licensing Branch 3 12pp 18642 234 24X Fiche 50-412.B3/05/11.B305310234
- B303180256 Forwards "Beaver Valley Power Station Unit 2 Fire Protection Evaluation Rept " Ack of receipt requested MODLEVER.E J Duquesne Light Co B3/05/16 DENTON.H R. Office of Nuclear Reactor Regulation, Director 2pp 18490 355 24X Fiche 30-412.83/05/16.8305180256
- --8305180257 "Beaver Valley Power Station Unit 2 Fire Protection Evaluation Rept " * Duquesne Light Co 83/05/16 576pp 18490 357 24X Fichs 50-412.83/05/16,8305180256
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8305180283 Forwards Amend 1 to FBAR WODLEVER,E J Duquesne Light Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18487 225 24X Fichs 50-412,83/05/16,8305180283
- --8305180287 Amend 1 to FBAR W/seven oversize figures Aperture cards are available in PDR * Duquesne Light Co 83/05/31 862pp 18487 230 24X Fiche 50-412.83/05/16,8305180283
- 8305180559 Forwards FBAR & environ rept (filed in PDR Category C) for Beaver Valley Power Station, Unit 2
 HODLEVER, E J Duquesne Light Co 83/05/16
 DENTON, H R Dffice of Nuclear Reactor Regulation, Director. 2pp 18550 001 24X
 Fiche 50-412,83/05/16,8305180559
- --8305180569 FBAR for Beaver Valley Power Station. Unit 2 Errate encl * Duquesne Light Co. 83/05/16 2:877pp 18550 003. 24X Fiche 50-412,83/05/16:8305180559
- --8305180585 Chapter 1 to Beaver Valley Unit 2 FSAR. "Introduction & General Description of Plant" # Duquesne Light Co 83/05/16 269pp 18550 014 24X Fiche 50-412.83/05/16-8305180559
- --8303180592 Chapter 2 to Beaver Valley Unit 2 FSAR, "Site Characteristics" * Duquesne Light Co. 83/05/16 230pp 18350 283 24X Fiche 50-412.83/05/16.8305180559
- --8305180598 App 2.3A to Beaver Valley Unit 2 FSAR, "Salt & Water Drift"

 * Duquesne Light Co 83/05/16 15pp 18551 153, 24X
 Fiche 50-412.83/05/16.8305180559
- ---8305180604 App 2 38 to Beaver Valley Unit 2 FBAR. "Visible Plume Model "
 - * Duquesne Light Co. 83/05/16 Spp. 18551 167. 24X Fiche 30-412.83/05/16.8305180559
- --8305180613 App 2 3C to Beaver Valley Unit 2 FBAR, "Beaver Valley Power Station Joint Frequency Distribution at 35-Ft Level (Jan 1976 Dec 1980)"

 Doquesne Light Co. 83/05/16 117pp 18551 174 24X Fiche 50-412,83/05/16
- --8305180625 App 2 3D to Beaver Valley Unit 2 FSAR, "Beaver Valley Power Station Joint Frequency Distribution at 500-Ft Level (Jan 1976 Dec 1980)."

 * Duquesne Light Co. 83/05/16 183pp 18551 291 24X Fiche 50-412.83/05180559
- --8305180634 App 2 4A to Beaver Valley Unit 2 FBAR, "Analysis of Flood Heights, Ohio River at Shippingport, PA Hydrologic Engineering Investigation " Aperture card available in PDR. " Duquesne Light Co. 83/05/16 185pp 18552 114 24X Fiche 50-412,83/05/16,8305180559
- --8305180441 App 2 5A to Beaver Valley Unit 2 FSAR, "Ohio River Elevations & Piezometer Data" • Duquesne Light Co 83/05/16 44pp 18552 297 24X Fiche 50-412,83/05/16,8305180559
- ---8305180650 App 2.58 to Beaver Valley Unit 2 FSAR, "Boring Logs." Aparture cards available in FDR 8 Duquesne Light Co 83/05/16 48pp. 18552 347, 24X Fiche 50-412.83/05/16,8305180559

- --8305180655 App 2 5C to Beaver Valley Unit 2 FSAR, "Relative Density Plots for Verification Borings, Terra Probe Densification Hain Intake Structure" * Duquesne Light Co 83/05/16 51pp. 18553 035 24X Fichs 50-412,83/05/16,8305180539
- --8305180661 App 2 5D to Beaver Valley Unit 2 FBAR, "Lab Test Data in Situ Soils " Buquesne Light Co 83/05/16 138pp 18553 085 24x Fichs 50-412,83/05/16,8305180559
- --8305180666 Chapter 3 to Beaver Valley Unit 2 FSAR, "Design of Structures: Components: Equipment & Sys " * Duquesne Light Co 83/05/16 1, 147pp 18553 223, 24X Fiche 50-412,83/05/16,8305180559
- --8305180673 App 3A to Beaver Valley Unit 2 F8AR. "Computer Program for Dynamic & Static Analysis of Beismic Category I Structures, Equipment & Components "

 Duquesme Light Co. 83/05/16 157pp 18556 290, 24X Fiche.50-412,83/05/16.8305180559
- --8305180681 App 38 to Beaver Valley Unit 2 FSAR. "Study of Probability of Aircraft Collision W/Beaver Valley Power Station -- Unit 2 "

 * Duquesna Light Co. 83/05/16 559 18557.087 24X
 Ficha. 50-412,83/05/16,8305180559
- --8305180685 Chapter 4 to Beaver Valley Unit 2 FSAR. "Reactor" * Duquesne Light Co 83/05/16 231pp 18357 170 24x Fiche 50-412.83/05/16.8305180539
- --8305180693 Chapter 5 to Beaver Valley Unit 2 FBAR, "RCS & Connected Bys " Four aperture cards available in PDR * Duquesne Light Co 63/05/16 252pp, 18558 041 24X Fiche 50-412.83/05/16,8305180559
- --B305180695 App 5A to Beaver Valley Unit 2 FBAR, "Cold Shutdown Capability" * Duquesne Light Co B3/05/16 12pp 18558 293 24X Ficha 50-412.83/05/16,8305180559
- --8305180697 Chapter 6 to Beaver Valley Unit 2 FSAR, "ESF," Aperture cards available in PDR.

 e Duquesne Light Co 83/05/16 460pp 18558 332 24X Fichs' 50-412,83/05/16,8305180559
- --8305180705 Chapter 7 to Beaver Valley Unit 2 FSAR, "Instrumentation L Controls," * Duquesne Light Co 83/05/14 682pp 18560 072, 24X Fichs 50-412,83/05/16,8305180559
- --8305180708 Chapter 8 to Beaver Valley Unit 2 FBAR, "Electric Pauer" * Duquesne Light Co. 83/05/16 180pp 18562:034. 24X Fiche. 50-412, 83/05/16, 8305180559
- ---8305180715 Chapter 9 to Beaver Vallay Unit 2 F8AR, "Auxiliary Sys of Aperture cards available in PDR, a Duquesne Light Co 83/05/16 480pp 18562;214 24X Fiche 50-412,83/05/16,8305180559
- --8305180720 Chapter 10 to Beaver Valley Unit 2 FSAR. "Steam & Power Conversion Sys." Aperture cards available in PDR * Duquesne Light Co 83/05/16 114pp 18563-334. 24% Fiche 50-412,83/05/16,8305180559
- --B3051B072B App 10A to Beaver Valley Unit 2 FSAR, "Auxiliary Feedwater Sys Simplified Reliability Analysis"

 * Duquesne Light Co. B3/05/14. 77pp 18564,088, 24X
 Fiche 50-412,83/05/14.8305180559
- --8305180735 Chapter 11 to Beaver Valley Unit 2 F8AR, "Radwaste Mpt." Aperture cards available in PDR * Duquesne Light Co 83/05/16 143pp 18564 176 24X Fiche 50-412,83/05/16,8305180559
- --8305180740 App 11A to Beaver Valley Unit 2 FBAR, "Summary of Annual Radiation Doses,"

 + Duquesne Light Co. 83/05/16, 26pp 18564-319, 24X
 Fiche: 50-412, 83/05/16, 8305180559,
- --8305180746 Chapter 12 to Beaver Valley Unit 2 F8AR, "Radiation Protection"

 # Duquesne Light Co. 83/05/16 192pp. 18564,352. 24X
 Fiche: 50-412,83/05/16,8305180559

- --8305180749 Chapter 13 to Beaver Valley Unit 2 FSAR, "Conduct of Operations "
- --8305180755 Chapter 14 to Beaver Valley Unit 2 FSAR, "Initial Test Program" Four aperture cards available in PDR Buquesne Light Co 83/05/16 183pp 18565 301 24X Fiche 30-412,83/05/16,8305180559
- --8303180760 Chapter 15 to Beaver Valley Unit 2 FSAR, "Accident
 - # Duquesna Light Co 83/05/16 461pp 18566 124 24X Ficha 50~412,83/05/16,8305180559
- --8305180764 App 15A to Beaver Valley Unit 2 FSAR, "Dose Methodology "
 # Duquesne Light Co 83/05/16 8pp 18567 225 24X
 Fiche 50-412.83/05/16,8305180559
- --8305180767 Chapter 16 to Beaver Valley Unit 2 FSAR, "Tech Specs" * Duquesne Light Co 83/05/16 7pp 18567 234 24X Fiche 50-412.83/05/16.8305180559
- --B305180767 Chapter 17 to Beaver Valley Unit 2 FSAR, "GA " Errata = Duquesne Light Co. 83/05/16 31pp 18567 240 24X Fichs. 50-412, 83/05/16, 8305180559
- 8305240248 Forwards affidavit certifying distribution of FSAR Amend i HOCLEVER, E J. Duquesne Light Co. 63/05/19 DENTON H R Office o Nuclear Reactor Regulation, Director 3pp 18548 304 24X Fiche: 50-412.83/05/19.8305240248 Office of
- Q Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice 83-14, "Dewatered Spent for Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list
 - encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Ca of New York, Inc 112pp. 18308 319 24X Fichs 50-000.83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Bvc list encl
 JCRDAN,E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys "Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 800103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381.291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of BEeam Generators at PWRs " Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382;047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice B3-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp, 18382,165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 93-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl UGRDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/03. Consolidated Edison Co. of New York, Inc. 122pp 18441,170, 24% Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103), 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382-282, 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441.001, 24% Fiche 50-000.83/05/04.8303040031

- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New-Yark, Inc 113pp 18523 248 24% Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (ECP) Guidelines "Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19,8303040040
- 8305280488 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-01 MARTIN.T T Division of Engineering & Technical Programs 83/05/20 WOOLEVER, E J Duquesne Light Co ip 18589 035 24X Fiche 50-412,83/05/20,8305250488
- --8305250498 Responds to NRC 830210 ltr re violations noted in IE Insp Rept 50-412/83-01 Corrective actions three steam generator cold leg notice wolds will be repaired by end of Dec 1983 Steam generator technical manual will be revised MODLEVER.E J Duquesne Light Co 83/05/04 STAROSTECKI,R Division of Project & Resident Programs 6pp 18589 036 24X Fiche 50-412,83/05/20.8305230488
- 8305270656 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/81-09
 STAROSIECKI,R Division of Project & Resident Programs 83/05/24
 MODLEVER,E J Duquesne Light Co 1p 18646 358 24X
 Fiche 30-412,83/05/24,8305270656
- --8305270662 Revises B20310 response to NRC B20207 ltr re violations noted in IE Insp Rept 50-412/B1-09 Corrective actions nuts & boits in duct connection will be replaced w/new nuts/boits & flat washers to ensure proper bearing surface area MODLEVER: J Duquesne Light Co 83/04/04 STAROSTECKI.R Division of Project & Resident Programs 3pp 18646 359 24X Fiche 50-412,83/05/24,8305270656
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated 011 " Byc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/03/26 Consolidated Edison Co of New
 York, Inc 114pp. 18647 007 24X Fiche 50-000.83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- 8303100104 Interim Significant Deficiency Rept 83-02 re GC acceptance of conditions in nonconformance w/insp plan attributes Initially reported on 830318 GC supervisor & lead inspectors reinstructed Next rept will be submitted by 830801 HOOLEVER, E J Duquesne Light Co 83/04/29 HAYNES, R C Region 1: Office of Director 4pp 18374 330 24X Fiche 50-412,83/04/29, 8305100104 HAYNES R C Region I
- 8305110275 Interim Bignificant Deficiency Rept 83-01 re incorrect Westinghouse EMD gate valve position indication Initially reported on 830112, Rept of results of evaluation will be submitted by 830531

 WOOLEVER, E J Duquesne Light Ca B3/04/29 HAYNEB, R C Region Office of Director 5pp 18393 273 24X Fichs 50-412,83/04/29,8305110295
- 8305200429 Final Significant Deficiency Rept 82-06 re failed sheared pinion keys in Limitorque motor operators supplied by Westinghouse All deficient keys replaced Also reportable Per Part 21

 WOOLEVER: E J Duquesne Light Ca B3/05/10 ALLAN. J Region 1.
 Office of Director 5pp 18517 145 24X Fiche 50-412,83/05/10.
 B305200429
- DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B305020326 Forwards add1 info re containment pressure boundary fracture toughness, in response to NRC B20504 Itr W/four oversize drawings Aperture cards are available in PDR PARKER, W O Duke Power Co B2/06/03 DENTON, H R, Office of Nuclear Reactor Regulation, Director ADENBAN, E O Licensing Branch 4 2pp 18276, 220 24% Fiche 30-413, B2/06/03, 8305020326

- B305050008 Forwards "Const Project Evaluation for Gatawba Nuclear Btation" OMEN.W H Duke Power Co B2/12/30 O'REILLY, J P Region 2, Office of Director. 19 18339 110 24X Fiche 50-413.82/12/30.8305050008
- --B305050014 "Const Project Evaluation for Catauba Nuclear Station " # Duke Power Co 82/10/31 202pp 18339 111 24X Fiche 50-413,82/12/30,8305050008
- 8305020554 Approves request to withhold "Reactor Cavity Asymmetric Loads" from public disclosure per 100FR2 790 ADENSAM: 6 Licensing Branch 4 83/04/26 TUCKER, H 8 Duke Power Co 2pp 18284, 247 24% Fiche 50-413, 83/04/26, 8305020556
- 8305090659 Generic Ltr 83-20 to all operating reactor licensmes & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D O Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc. 16ps 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305270005 Forwards proposed Tech Specs in form of marked-up Ray 4 to NUREQ-0452, "8T8 for Westinghouse PWRs "
 TUCKER-H B Duke Power Co B3/05/20. DENTON,H.R Office of Nuclear Reactor Regulation, Director ADENSAMSE 0 Licensing Branch 4 741pp 18630 001 24X Fiche 50-413.83/05/20.8305270005
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B303020020 Forwards comments on SER Section 9.5 1 re fire protection program issued by NRC on B30222. W/four oversize drawings.

 List of room descriptions also encl. Aperture cards are available in PDR.

 TUCKER.H B. Dute Power Co. B3/04/14, DENTON.H R. Diffice of Nuclear Reactor Regulation, Director ADENBAM.E C. Licensing Branch 4 14pp. 18276 222 24% Fiche 50-413.83/04/14.8305020020
- 8305020028 Notification of 830504 meeting w/util in Bethasda, MD to discuss SER Confirmatory Item 17 re Type C leak rate testing of certain isolation valves.

 JABBOUR: K N Licensing Branch 4 83/04/25 ADENSAM, E. Q Licensin Branch 4. 3pp 18308 302 24X Fiche: 50-413, 83/04/25, 8305020028
- B305170712 SAFETY EVALUATION REPORT RELAYED TO THE OPERATION OF CATAMBA NUCLEAR STATION, UNITS I AND 2 Docket Nos 50-413 And 50-414 (Duke Power Company.et al) # Division of Licensing NUREG-0954 801 B3/04/30, 54pp. Available at NRC 84 75 18481,126 24X Fiche 50-413.83/04/30, B305/70712
- 8305160196 Forwards Hydrologic Engineering Section request for add1 info re SER Confirmatory Item 1 on local flooding analysis Response requested by 830610 ADENBAME 6 Licensing Branch 4 83/05/06 TUCKER, H B Duke Power Co 4pp. 18471 335. 24X Fiche 50-413,83/05/06,8305160196
- 8305170615 Forwards Suppl 1 to SER.W/o encl. NOVAK; TM Division of Licensing 83/05/13 TUCKER, H B Duke Power Co. 3pp 18497/017, 24% Fiche 50-413:83/05/13,8305170615.
- 8305240021 Notification of 830525 meeting w/util & Westinghouse in Bethesds:MD to discuss resolution of SER Open Item 9 re conformance to RBS 5-1 & steam generator tube rupture. JABBOURK N Licensing Branch 4 83/05/13 ADENSAME 9 Licensing Branch 4 3pp 18577 311. 24X Fiche 50-413.83/05/13.8305240021
- 8305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sus at facility Emergency lighting portion of Open Item I3 should be closed based on encl discussion TUCKER.H B Duke Power Co 83/05/16. DENTON.H.R Office of Nuclear Reactor Regulation, Director, ADENBAM.E 0 Licensing Branch 4 4pp 18517 297. 24X Fiche. 50-413.83/05/16.8305200401.
- 8305200476 Forwards revised pages to FBAR addressing Open Item 15, Confirmatory Items 2.5 & 10 & License Condition 4, per SER. Revised pages will be included in Rev B. TUCKER.R B Duke Power Co 83/05/16 DENTON.H R. Office of Nuclear Reactor Regulation, Director ADENBAM.E.Q Licensing Branch 4 11pp 18512 347 24X Fiche: 50-413, 83/05/16.8305200476
- 8305310200 Informs of plans to perform mods to Hestinghouse Model D2/D3 steam generators per SER (NURE-0966) issued on 830316.Plant-specific mod details encl TUCKER.H B. Duke Power Co. 83/05/18 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENBAN.E. G. Licensing Branch 7pp. 18651 014 24% Fiche: 50-413,83/05/18,8305310200.

- F Security, medical, emergency & fire protection plans
- 8305020020 Forwards comments on BER Section 9 5 i re fire protection program, issued by NRC on 830222 H/four oversize drawings List of room descriptions also encl Aperture cards are available in PDR TUCKER, H B Duke Power Co 83/04/14 DENTON, H R Dffice of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Branch 4. 14pp 18276 222 24X Fiche 50-413,83/04/14,8305020020
- 8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/21 TUCKER,H B Duke Power Co 2pp 18642 175 24X Fichs 50-413,83/04/21
- --8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08,Ne noncompliance noted Major area inspected fire protection. MILLER, H. H. CONLON, T. E. Region 2, Office of Director 83/04/19 opp 18642 177 24% Fichs 50-413,83/04/21,8305270393.
- 8305160292 Releases public version of evacuation time estimates.
 FELTON.J M Division of Rules and Records 83/05/02 Document
 Management Branch ip 18462 238 24X Fiche 50-413,83/05/02,
 8305160292.
- --8305160293 Forwards public version of "Evacuation Time Estimates"
 TUCKER.H B Duke Power Co 83/04/20 DENTON.H.R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing
 Branch 4 ip 19462, 239 24X Fiche. 50-413, 83/05/02, 8305160292,
- --8305160295 Public version of "Evacuation Time Estimates " # Planning Research Corp 83/04/30. 94pp 18462:240 24X Fiche 50-419.83/05/02,8305160292
- 8303170296 Forwards storage & in-transit security plan for BNM of low strategic significance Plan withheld (ref 10CFR73 80). TUCKER.H. B Duke Power Co 83/05/10 DENTON.H.R. Office of Nuclear Reactor Regulation, Director, 1p 18465:078, 24X Fiche 50-413,83/05/10,8305170296
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for QLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Bvc list ancl EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 C95 24X Fish 80-000, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKB:N J Office of the Executive Director for Operations 83/05/13 PALLADINO,N, J, Commissioners 5pp 18593;322, 24% Fiche: 50-000,83/05/13,8305240213
- 8305200401 Requests BER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion TUCKER.H B Duke Power Co. 83/05/16 DENTON,H R, Office of Nuclear Reactor Regulation, Director ADENBAM,E O. Licensing Branch 4 4pp 18517-297, 24X Fiche-50-413.83/05/16.8305200401

O. Adjudicatory correspondence

- 8305030504 Advises that NRC will not serve responsive pleading to Palmetto Alliance 830411 motion to compel discovery from applicants, NRC is not party to discovery dispute.

 JOHNSON, G E Hearing Branch 4 83/04/29, KELLEY, J. L., FOSTER, R. F., CALLIHAN, D Atomic Bafety and Licensing Board Panel, ip 18295: 304 24% Fiche 50-413,83/04/29,8305030504.
- 8305040538 Motion to compel Palmetto Alliance response to util interrogatories t requests to produce re Palmetto Alliance Contentions 6.7.8.16 & 44. Responses inadequate to date.
 Certificate of Evc encl. Related correspondence.
 MCGARRY.J M. Duke Power Co. MCGARRY.J M. Debeyoise & Liberman 83/04/29 Atomic 884ety and Licensing Board Panel. 65pp. 18321:132 24X Fiche 50-413.83/04/29,8305040538
- 8305030576 Followup interrogetories & related document requests on Contentions 6.8.16,27 & 44. Certificate of Svc encl.
 JOHNSON, G. E. Hearing Branch 4. 83/05/02 Palestto Alliance.
 10pp 18306.100. 24X Fiche: 50-413.83/05/02, 8305030376
- 8305060252 Responses to 830418 interrogatories & requests to produce Fe DES Contentions 11:17 & 19. Related correspondence, QUILD, R Palmetto Alliance, RILEY, J L. Carolina Environmental Study Group, QUILD, R. Quild, R 83/05/02 Duke Power Co 21pp 18345.197. 24X Fiche: 50-413.83/05/02.8305060252.

- B3050500B0 Renewed motion to compel Palmetto Alliance full answers to interrogatories on Contention 7 Answers & supplemental answers evasive Certificate of Svc encl JOHNSON.0 E Hearing Branch 4 B3/05/04 Atomic Safety and Licensing Board Panel 13pp 18342 135 24X Fiche 50-413.83/05/04, 8305000B0
- 8305070468 Advises that emergency operating procedures mailed to intervenors per ABLB 820305 & 1201 orders Thirty-day period for filing contentions should start on 830507 CARR.A V Dute Power Co 83/05/04 KELLEV.J L . CALLIMAN.A D . FORTER.R F Atomic Safety and Licensing Board Panel ip 18362 258 24X Fiche 50-413.83/05/04.8303070468
- 8303100282 Forwards notices of deposition for M McAfee, NR Hoopingarner & M Lowe re Palmetto Alliance contentions Related correspondence CARR. A V Duke Power Co 83/05/04 QUILD.R Quild, R ip 18371 261 24X Fiche 50-413,83/05/04,8305100282
- --8305100287 Notice of W McAfee deposition in Columbia:80 re Palmetto Alliance Contention & & B10722 affidavit HCGARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman 83/05/04 ip 18371 262 24% Fiche 50-413.83/05/04,8305100282
- --8305100297 Notice of NR Hoopingarner deposition in Columbia,8C re Palmetto Alliance Contention 6 & B10722 affidavit HCGARRY.J M Duke Power Co MCGARRY,J M Debevoise & Liberman B3/05/04 1p 18371.263 24X Fiche 50-413,83/05/04,8305100282
- --8305100305 Notice of M Lowe deposition in Columbia,8C re Palmetto Alliance Contentions 6,7.8,16,27 & 44. HCCARRY,J M Duke Power Co MCCARRY,J M Debevoise & Liberman 83/05/04 1p 18371 264 24X Fiche 50-413,83/05/04,8305100282
- 8305100342 Followup interrogatories to Palmetto Alliance Contentions 6, 7, 8,16 & 27 Answer must be filed by 830520 Certificate of 8vc encl Related correspondence CARR.A.V. Dute Power Co 83/05/04 Atomic 8afety and Licensing 80ard Panel 16pp 18378 196 24X Ficha 50-413,83/05/04, 8300100342
- B305100415 Advises of filing of followup interrogatories on Palmetto Alliance Contentions 4,7,8,16 & 27 Applicant has received no answers from Palmetto Alliance to interrogatories on Contention 44, so no followup available at present time CARR.A V Duke Power Co B3/03/04 KELLEY, J L Atomic Safety and Licensing Board Panel CALLHAN, A D Union Carbide Corp FOSTER, R F Affiliation Unknown ip 18378 080 24X Fichs. 30-413, 83/05/04, 8305100415
- B305090511 Discusses B30502 telcon re recording of applicant & Palmetto Alliance depositions on Contentions 27,14,8,44,6 & 7 Draft stipulation and MCGARRY, J M Debevoise & Liberman B3/05/05 GUILD, R Guild, R, 7pp. 18362
- 8305100232 Responds to Duke Power Co motion to establish deadline for control room design review contentions NRC does not appose motion to extent contentions filed by 830531 Certificate of Svc encl
 JOHNSON 0 E Office of the Executive Legal Director 83/05/09.
 Atomic Befety and Licensing Board Panel 5pp 18374 122 24X
 Fiche 50-413,83/05/09,8305100232
- B305110462 Response to Carolina Environ Study Group (CEBO) Contention IB & DEB Contention 17 Interrogatory 10 of Contention 17 Irrelevant. Affidavits, Certificate of Counsel & Certificate of Evc encl
 JOHNBON, O E. Hearing Branch 4 B3/05/10 Atomic Bafety and Licensing Board Panel 27pp 18405.017 24X Fiche 50-413,83/05/10,8305110462
- B303130036 Advises that NRC will make NRC technical staff members available for deposition on B30516-18 in Bethesda, MD No written notice of deposition received JOHNBON, 9 E Hearing Branch 4 83/05/11 QUILD, R. Guild, R Q
- 8305170472 Memorandum & order ruling on util 830427 motion to compel Palmetto Alliance further responses to util interrogatories & requests to produce re Palmetto Contentions 6,7,8,16 & 44 Listed requests granted KELLEY, J L Atomic Safety and Licensing Board Panel 83/05/13, Duke Power Co 13pp 18470.099 24X Fiche 50-413,83/05/13, 8305170472.
- 8305170556 Forwards SER Buppl 1 (NUREG-0934) W/o smc1
 JOHNSON.0 E. Hearing Branch 4 83/05/16, KELLEY, J L., FOBTER, R F.,
 CALLIHAN.D Atomic Safety and Licensing Board Panel 1p
 18468:140. 24X Fiche 50-413,83/05/16,8305170556

- 8305240489 Followup interragatories re DES Contentions II, 17 & 19 Certificate of Svc encl Related correspondence MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 83/05/18 Palmetto Alliance 16pp 18572 317 24X Fiche 50-413.83/05/18.8305240485
- 8305230055 Forwards add1 documentation ro util welding insp task force rept Documents may fall within scope of General Interrogatory 4 (First set) Documents identified in response to FOIA request W/o encl
 JOHNSON.0 E Hearing Branch 4 83/05/19 GUILD.R Palmetto Alliance GUILD.R Guitd.R ip 18339 176 24X
 Fiche 50-413.63/05/19.8305230055
- 8305310025 Forwards 830517 & 20 ltrs from HD Tucker to JO Dayis & HR Denton, respectively, per request W/o encl CARR, A V Duke Power Co 83/05/24 GUILD, R Guild, R 1p 18653 310 24X Fiche 50-413,83/05/24,8305310025
- 8305310035 Lists post-discovery administrative matters requiring resolution Remaining documents should be identified in response to A8LB 830513 order. by 830531 01BBON.R L Duke Power Co 83/05/24 GUILD.R Palmetto Alliance GUILD.R Guild R 2pp 18653 211 24X Ficho 50-413.B3/05/24, 8305310035
- B305310155 Motion to establish discovery schedule on GA Contention G Certificate of Svc encl GUILD: R Palmetto Alliance B3/05/25 Atomic Safety and Licensing Board Panel 2ipp 18653 015 24X Fiche 50-413,83/05/25, B305310155

H General correspondence

- 8305040455 Forwards documents identified in 830414 ltr per 830428 telcon W/o encis Related correspondence OIBBON,R L Consumers Power Co 83/04/29 QUILD,R Palmetto Alliance ip 18322 143 24X Fichs 50-413,83/04/29,8305040455
- G Inspection reports, IE Bulletins & correspondence
- 82:2060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Safeguards & Inspection Programs (Post 630103) 63/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fithe 50-000.83/03/21.8212060385
- 8305270324 Forwards IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/03/25 TUCKER, H B Duke Power Co 2pp 18642 059 24X Fiche 50-413,83/03/25,8305270324
- --8305270334 IE Insp Repts 50-413/83-03 & 50-414/83-03 on B30126-0225 No noncompliance noted Major areas inspected IE Bulletin 82-04 followup, electrical component & sys nonconformance items, pips welding & electrical cables & terminations VANDOORN.P. K. Region 2. Office of Director IGNATONIS, A J Division of Project & Resident Programs 83/03/22 3pp. 18442 061 24X Fiche 50-413,83/03/25,8305270324
- 8305270590 Forwards IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/04/13 TUCKER.H. B Dute Power Co 2pp 18646 103 24X Fiche 50-413
- --8305270602 IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted Major areas inspected reviews of license GA surveillance repts & authorized nuclear inspector problem repts VANDORN.P.K. IGNATONIS.A J Region 2. Office of Director 83/04/12 3pp 18446 105 24X Fiche 50-413.83/04/13,8305270990
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator"
 Svc 11st encl
 JDRDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8309270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/04/21 TUCKER:H B. Dute Power Co 2pp 18642 175, 24X Fiche: 50-413, 83/04/21, 8305270393
- --B305270404 IE Insp Repts 50-413/B3-06 & 50-414/B3-06 on B30405-0B No noncompliance noted Major area inspected fire protection MILLER, H H. CONLON, T E Region 2. Office of Director 83/04/19 6pp 18642 177 24% Fichs 50-413, B3/04/21, B30527039

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " 303040023 Ik into Notice 35 --- Seven Head of the Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24% Fiche 50-000, 83/04/22, 8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc 119pp 18381 291. 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice B3-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Syc list encl JJRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 30-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list entl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consoildated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fichs 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705706 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30. "Misapplication of Genetic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8305250211 Requests comments on encl draft NRR SALP input for June 1982 Apr 1983 Comments received by 830523 will be considered in final rept JABBOUR.K N Licensing Brench 4 83/03/18 EISENHUT.D & Division of Licensing MATTSON.R Division of Systems Integration (post 8)1005) VOLLMER.R Division of Engineering & Opp. 18627 117 24X Fiche 50-413, 83/05/18, 8305250211
- 8303040040 IE Info Notice 83-31, "Error in ADLFIFE Computer Program " 303040040 It among the Color of Emergency Preparedness & Engineering
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 820103) 83/05/19 Cansol(dated Edison Co of New
 York, Inc. 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 CO7 24X Fiche 50-000,83/05/26.8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor 3UD:110427 Part 21 & deficiency repts re misoperation of Di trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHE.E P Hestinghouse Electric Corp 83/04/21 DEYOU! Director's Office. Office of Inspection and Enforcement 18405 095 PAX Fiche 50-000,83/04/21.8305110427 DEVOUNG, R C
- 8305170292 Final Significant Deficiency Rept SD 413-414/82-23 re 9051/0242 Final Significant Deficiency Rept SD 413-414/82-23 reviolation of const procedures for mixing & placing SikaTop 122 during drill hole repair Initially reported on 821208 Test program concluded SikaTop 122 acceptable FUCKER-N B Duke Power Co 83/05/06 O'REILLY,J.P Region 2: Office of Director 3pp 18465 359, 24X Fiche 50-413-83/05/06. 8305170292

- 8305250282 Significant Deficiency Rept 8D 413/83-07 re vent valve 30320282 Significant Deficiency Rept 80 413/83-0/ re vent valve LND105 not installed in accordance w/design & const criteria Initially reported on 830414 Valve will be corrected to conform w/drawing in June 1983 TUCKER.H B Duke Power Co 83/05/13 D'REILLY.J P Region 2. Offfice of Director 2pp 18592 359 24X Fiche 50-413,83/05/13. 8305250282
- 8305270069 Final Significant Deficiency Rept SD 413-414/82-27 re cracks in cell containers of nickel cadmium batteries mfg by Transamerica Delaval Initially reported on 821220 Caused by contact w/unknown solvent used for cleaning TUCKER. HB Duke Power Co 83/05/17 O'REILLY. J P Region 2, Office of Director 3pp 18638 279 24X Fiche 50-413,83/05/17, 2208370659 B305270049

DOCKET 50-414 CATAURA NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence

- 8305020326 Forwards add1 info re containment pressure boundary fracture toughness, in response to NRC 820504 ltr W/four oversize drawings Aperture cards are available in PDR PARKER, W O Duke Power Co 82/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 2pp 18276 220 24% Fithe 50-413,82/06/03,8305020326.
- 8305050008 Forwards "Const Project Evaluation for Catawba Nuclear Station "
 OWEN, W H Duke Power Co 82/12/30 O'REILLY, J P Region 2: Office of Director 1p 18339.110 24X Fiche 50-413,82/12/30,8305050008.
- --8305050014 "Const Project Evaluation for Catamba Nuclear Station." * Duke Power Co 82/10/31 202pp 18339*111 24X Fichs 50-413, 82012/30, 8305050008
- 8305020556 Approves request to withhold "Reactor Cavity Asymmetric Loads" from public disclosure per 10CFR2 790 ADENBAM, E 0 Licensing Branch 4 B3/04/26 TUCKER, H B. Duke Power Co. 2pp 18284 247 24X Fiche 50-413.83/04/26,8305020556.
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl 93/05/07. 93/05/07. EISENRUT, D G Division of Licensing 83/05/0' Edison Co of New York, Inc 16pp 18627, 153 Fiche 50-000, 83/05/09, 8305090659 Consolidated
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8303020020 Forwards comments on SER Section 9.5 1 re fire protection program, issued by NRC on 830222 H/four oversize drawings.

 List of room descriptions also encl Aperture cards are available in PDR available in PDR TUCKER,H B Duke Power Co 83/04/14 DENTON,H R Office Nuclear Reactor Regulation, Director ADENBAM,E G Licensi 4 14pp 18276 222 24X Fiche 50-413,83/04/14,8305020020. Licensing Brench
- B30502002B Notification of B30504 meeting w/util in Bethesda, MD to discuss SER Confirmatory Item 17 re Type C leak rate testing of certain isolation valves
 JABBOURK N Licensing Branch 4 B3/04/25, ADENBAM, E. 9 Licensing Branch 4 Bp. 18308 302 24X Fiche 50-413,83/04/25,8305020028
- 8309170712 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAMBA 305170712 SAPETY EVALUATION REPORT RELATED TO THE UPERATION OF GAT NUCLEAR STATION UNITS 1 AND 2 Docket Nos. 50-413 And 50-414 (Duke Pawer Company.et al.) # Division of Licensing NUREO-0954 BOL 83/04/30 56pp. Available at NRC \$4.75 18481 126 24X Fiche.50-413.83/04/30, 8305170712
- 8305160196 Forwards Hydrologic Engineering Section request for add1 info re SER Confirmatory Item 1 on local flooding analysis Response requested by 830610 ADENSAME G Licensing Branch 4 83/05/06. TUCKER, H. B Duke PC CO 4pp 18471:335 24X Fiche 50-413,83/05/06.8305160196
- 8305170615 Forwards Suppl 1 to SER W/o encl.
 NDVAK.7 M Division of Licensing 83/05/13 TUCKER, H. B Duke
 Power Co. 3pp 18497 017 24X Fiche: 50-413, 83/05/13: 8305170615. 305170613 renwerd NOVAK, T.M. Divi Power Co. 3pp
- 8305240021 Notification of 830525 meeting w/util & Wastinghouse in Bethesda, MD to discuse resolution of SER Open Item 9 re-conformance to RSB 5-1 & steam generator tube rupture JABBOUR, K, N Licensing Branch 4 83/05/13 ADENSAM, E 9 Licen: Branch 4 3pp 18577 311 24X Fiche 50-413, 83/05/13, 8305240021

- B305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion
 TUCKER,H B Duke Power Co 83/05/16 DENTON,H R Office of
 - enci discussion
 TUCKER, H D Duke Power Co 83/05/16 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch
 4 4pp 18517 297 24X Fiche 30-413,83/05/16,8303200401
- 8305200476 Forwards revised pages to FSAR addressing Open Item 15.
 Confirmatory Items 2,3 & 10 & License Condition 4,per SER
 Revised pages will be included in Rev 8
 TUCKER, H B Duke Power Co 83/05/16 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 lipp 18312 347 24X Fiche 50-413,83/05/16,8305200476
- B305310200 Informs of plans to perform mods to Westinghouse Model DA/D3 steam generators per SER (NVRE-0966) issued on B30316 Plant-specific mod details enci TUCKER: H B Duke Power Co B3/03/18 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4 7pp 18651 014 24X Fiche 50-413, 83/03/18. 8305310200

F Security, medical, emergency & fire protection plans

- B305020020 Forwards comments on SER Section 9 5 1 re fire protection program, issued by NRC on B30222 W/four oversize drawings List of room descriptions also encl Aperture cards are available in PDR TUCKER.H B Duke Power Ca B3/04/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 14pp 18276 222 24X Fiche 50-413, B3/04/14, B305020020
- B305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompilance noted DANCE, H C Division of Project & Resident Programs 83/04/21 TUCKER, H B Duke Power Co 2pp 18642 175 24X Fiche 50-413,83/04/21,8305270393
- --8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted Major area inspected fire protection. MILLER, W. H. Region 2, Office of Director 83/04/17 6pp 18642 177 24X Fiche 50-413,83/04/21,8305270393
- 8305160292 Releases public version of evacuation time estimates FELTON.J.M Division of Rules and Records 83/05/02 Document Management Branch 1p 18462 238 24X Fiche 50-413,83/05/02,8305160292
- --B305160293 Forwards public version of "Evacuation Time Estimates "
 TUCKER, M B. Duke Power Co B3/04/20 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E O Licensing
 Branch 4 ip 18462 239 24X Fiche 50-413,83/05/02.8303160292
- --8305160295 Public version of "Evacuation Time Estimates" * Flanning Research Corp 83/04/30 94pp 18462 240 24X Ficha 50-413,83/05/02,8305160292
- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
 EISENHUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 093 24X Fiche: 50-000.83/05/11,8305110034
- B305200401 Requests BER Section 9 5 3 be revised to accurately reflect dusign of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on enci discussion

 TUCKER, H D Duke Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18517 297 24X

 Fiche: 50-413, 83/05/16, 8305200401

O Adjudicatory correspondence

- B305030504 Advises that NRC will not serve responsive pleading to Palmetto Alliance B304i1 motion to compel discovery from applicants NRC is not party to discovery dispute JOHNSON.0.E. Hearing Branch 4 83/04/27 KELLEY.J.L., FOSTER,R.F. CALLIMAN.D. Atomic Safety and Licensing Board Panel ip 18275 304 24X Fiche 50-413,83/04/27.8305030504
- B305040538 Motion to comps! Palmetto Alliance response to util interrogatories & requests to produce re Palmetto Alliance Contentions 6.7.8.16 & 44 Responses inadequate to date Certificate of Svc encl Related correspondence MCGARRY.J M Duke Power Co. MCCARRY.J M Debevoise & Liberman B3704/29 Atomic Barety and Licensing Board Panel 65pp. 18921.152 24X Fichs 50-413.83/04/29,8305040538

- B305030576 Followup interrogatories & related document requests on Contentions 6.8.16.27 & 44 Certificate of Svc encl JOHNSON, © E Hearing Branch 4 B3/03/02 Palmette Alliance 10pp 18306 100 24x Fiche 50-413.83/05/02.8305030576
- 8305040252 Responses to 830418 interrogatories & requests to produce re DES Contentions (1,17 & 19 Related correspondence OUILD, R Palmetto Alliance RILEY, J Carolina Environmental Study Group OUILD, R Guild, R 83/05/02 Duke Power Co 21pp 18345 197 24X Fiche 50-413,83/05/02.8305060252
- B3050500B0 Renewed motion to compel Palmetto Alliance full answers to interrogatories on Contention 7 Answers & supplemental answers evasive Certificate of Svc enci
 JOHNSON.0 E Hearing Branch 4 B3/05/04 Atomic Safety and
 Licensing Board Panel 13pp 18342 135 24X Fiche 50-413.83/05/04.
- B303090468 Advises that emergency operating procedures mailed to intervenors per ASLB 820305 & 1201 orders Thirty-day period for filing contentions should start on 830509 CARR.A V Duke Power Co 83/05/04 KELLEY, J L , CALLIHAN, A D , FOSTER, R F Atomic Safety and Licensing Board Panel ip 18362 258 24X Fiche 50-413,83/05/04,8305090468
- 8305100282 Forwards notices of deposition for W McAfes, NR Hoopingarner & M Lowe re Palmetto Alliance contentions Related correspondence CARS, A V Duke Power Ca 83/05/04 GUILD, R Guild, R 1p 18371 261 24X Fiche 50-413, 83/05/04, 8305100282
- --8305100289 Notice of W McAfee deposition in Columbia,8C re Palmetto Alliance Contention & & Bi0722 affidavit MCGARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman 83/05/04 Ip 18371 262 24X Fiche 50-413,83/05/04,8305100282
- ~~8309100297 Notice of NR Hoopingarner deposition in Columbia, 8C re Palmetto Alliance Contention & & 810722 affidavit HCOARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman 83/05/04 ip 18371 263 24% Fiche 50-413,83/05/04,8305100282
- --8305100305 Notice of M Lowe deposition in Columbia. SC re Palmetto Ailiance Contentions 6.7.8.16,27 & 44 MCOARRY.J M Duke Power Co MCOARRY.J M Debevoise & Liberman 83/05/04 ip 18371 264 24X Fiche 50-413.83/05/04.8305100282
- 8305100342 Followup interrogatories to Palmetto Alliance Contentions 6, 7, 8, 16 & 27 Answer must be filed by 830520 Certificate of 8vc encl Related correspondence CARR.A V Duke Power Co 83/05/04 Atomic Safety and Licensing 8board Panel 16pp 18378 196 24X Fiche 30-413,83/05/04,8305100342
- 8305100415 Advises of filing of followup interragatories on Palmetto Alliance Contentions 6.7.8.16 & 27 Applicant has received no answers from Palmetto Alliance to interrogatories on Contention 44.so no followup available at present time CARR.A V Duke Power Co 83/05/04 KELLEY, J L Atomic Safety and Licensing Board Panel CALLIHAN, A D Union Carbide Corp FOSTER, R F Affiliation Unknown 1p 18378 080 24X Fiche 30-413, 83/05/04,8305100415
- B305070511 Discusses 830502 telcon re recording of applicant & Palmetto Alliance depositions on Contentions 27,16,8,44,6 & 7 Draft stipulation oncl MCGARRY.J M Debavoise & Liberman 83/03/05 GUILD,R Guild, R 7pp 18362:146 24% Ficha 50-413,83/05/05,8305070511
- 8305100232 Responds to Duke Power Co motion to establish deadline for control room design review contentions NRC does not oppose motion to extent contentions filed by 830531 Certificate of Svc encl
 JOHNSON.0 E Office of the Executive Legal Director 83/05/07
 Atomic Safety and Licensing Board Panel 5pp 18374 122 24X
 Fiche 50-413.83/05/09.8305100232
- 8305110462 Response to Carolina Environ Study Group (CESG) Contention 18 & DES Contention 17 Interrogatory 10 of Contention 17 irrelevant Affidavits, Certificate of Counsel & Certificate of Svc enci
 JOHNSON-Q E Hearing Branch 4 83/05/10 Atomic Safety and Licensing Board Panel 29pp 18405 017 24X Fiche 50-413, 83/05/10, 8305110462
- 8303130056 Advises that NRC will make NRC technical staff members available for deposition on 830516-18 in Bathesda, MD No written notice of deposition received JOHNSON.0 E Hearing Branch 4 83/05/11 QUILD, R Guild, R QUILD, R Palmetto Alliance 2pp 18436 333 24X Fiche 50-413,83/05/11,8305130056

- 8305170472 Memorandum & order ruling on util 830429 motion to compel Palmetto Alliance further responses to util interrogatories & requests to produce re Palmetto Contentions 4.7,8,16 & 44 Listed requests granted KELLEY, J.C. Atomic Safety and Licensing Board Panel 83/05/13 Duke Power Co. 13pp. 18470 099 247 Fiche 50-413,83/05/13,8305170472
- B305170556 Forwards SER Suppl 1 (NUREO-0954) W/o encl JOHNSON C E Hearing Branch 4 B3/05/16 KELLEY, J L , FOSTER, R F , CALLIHAN D Atomic Safety and Licensing Board Panel 1p 18468 160 24x Fiche 50-413, 83/05/16. B305170556
- 8305240485 Followup interrogatories re DES Contentions 11.17 & 19 Certificate of Svc encl Related correspondence MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman B3/05/18 Palmetto Alliance 16pp 18572 317 24X Fiche 30-413,83/05/18,8305240485
- 8305230055 Forwards add) documentation re-util welding insp task force rept Documents may fall within scope of General Interrogatory 4 (first set) Documents identified in response to FDIA request W/o sncl JORNSON, & E Hearing Branch 4 83/05/19 GUILD, R Palmetto Alliance GUILD, R Guild, R ip 18539 176 24X Fichs 50-413,83/05/19,8305230055
- B305310025 Forwards B30517 & 20 ltrs from HB Tucker to JO Davis & HR Denton, respectively, per request W/o encl CARR, A V Duke Power Co B3/05/24 GUILD, R Guild, R 1p 1B453 310 24% Fichs 50-415, B3/05/24, B305310025
- 8305310035 Lists post-discovery administrative matters requiring resolution Remaining documents should be identified in response to ASLB 830513 order, by 830531 GIBSON.R L Duia Power Co 83/03/24 GUILD.R Palmetto Alliance GUILD.R Ouild, R 2pp 18653 211. 24X Fiche 50-413,83/05/24. 8305310035
- B305310155 Motion to establish discovery schedule on GA Contention G Certificate of Svc encl GVILD.R Palmetto Alliance 83/05/25 Atomic Safety and Licensing Board Panel. 21pp 18653 015 24X Fiche: 30-413,83/05/25, 8305310155

H General correspondence

- 8305040455 Forwards documents identified in 830414 ltr per 830428 telcon W/o encls Related correspondence OIBSON,R L Consumers Power Co 83/04/29. GUILD.R Palmetto Alliance ip 18322 143 24X Fiche 30-413,83/04/29,8305040455
- @ Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice B3-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24% Fiche 50-000.83/03/21.8212060385
- B305270324 Forwards IE Insp Repts 50-413/B3-03 & 50-414/B3-03 on B30126-0225 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/03/25 TUCKER,H B. Duke Power Co 2pp 18642.059 24X Fichs 50-413,83/03/25,B305270324
- --8305270334 IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No nancompliance noted Major areas inspected IE Bulletin 82-04 followup, electrical component & sys nonconformance items, pipe welding & electrical cables & terminations VANDOURN.P K Region 2, Office of Director IONATONIB, A J Division of Project & Resident Programs. 83/03/22 5pp 18642 061 24X Fiche 50-413,83/03/25,8305270324.
- 8305270590 Forwards IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/13, TUCKER.H B. Duke Power Co 2pp 18646 103 24X Fiche 50-413,83/04/13,8305270590
- --8305270602 IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226.0326 No noncompliance noted Major areas inspected reviews of licenses 9A surveillance repts & authorized nuclear inspector problem repts VANDOURN.P.K.; IGNATONIS.A.J. Region 2. Office of Director 83/04/12 5pp 18646.105. 24X Fichs.50-413.83/04/13.8305270590.

- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator," Svt list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/15 Consolidated Edison Co. of New York, Inc. 126pp 18435-155 24X Fiche 50-000, 83/04/15, 8303040021,
- 8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/04/21, TUCKER:H B Duke Power Co Zpp 18442 175 24X Fiche 50-413,83/04/21,8305270393
- --8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08, No noncompliance noted Major area inspected fire protection MILLER, W H , CONLON. T E Region 2, Office of Director 83/04/19, 6pp 18642 177 24% Fiche 50-413, 83/04/21, 8305270393
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures," Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383.089 24X Fiche 50-000,83/04/22,8303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Sensing Bys." Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3704/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche. 50-000, 83/04/25, 8303040025
- 8303040026 IE Info Notice 83-24, "Laose Parts in Secondary Side of Steam Generators at PHRs," Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp. 18382:047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28,8303040027.
- 8303040028 IE Info Notice 83-24, "Failure of Bafety/Relief Valve Discharge Line Vacuum Braakers," Svc list encl JORDAN: E. Division of Emergency Preparadness & Engineering Rasponse (Post B30103) 83/05/03 Consolidated Edison Co. of New York: Inc 122pp. 18441.170. 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04. Consolidated Edison Co. of New York, Inc. 112pp. 18382; 282 24X Fiche 50-000; 83/05/04, 8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl, JURDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl. JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co. of New York, Inc 115pp. 18523 248 24X Fiche 50-000,83/05/06,8303040033.
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list enct.

 JORDANIE L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305250211 Requests comments on encl draft NRR BALP input for June 1982 Apr 1983. Comments received by 830523 will be considered in final rept.
 JABBOURK N Licensing Branch 4, 83/05/18 EISENHUT, D. G. Division of Licensing MATTSON:R Division of Systems Integration (post 81005). VOLLMER:R Division of Engineering App. 18627:117. 241 Fiche 50-413,83/05/18,8305250211.
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Ewe list encl
 JORDANIE L. Division of Emergency Preparadness & Engineering
 Response (Post 830103), 83/05/19, Consolidated Edison Co. of New
 York, Inc. 114pp 18697 009 24X Fiche: 30-000, 83/05/19, 8303040040.
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl URDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York: Inc. 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- B305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME, E P Westinghouse Electric Corp B3/04/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 03/04/21, 8305110427
- 8305170292 Final Significant Deficiency Rept 9D 413-414/82-23 revialation of const procedures for mixing & placing BikATop 122 during drill hole repair Initially reported on 821208 Test program concluded SixaTop 122 acceptable TUCKER.H B Duke Power Co 83/05/06 O'REILLY.J P Region 2, 04fice of Director 3pp 18465 359 24X Fiche 50-413,83/05/06,8305170292
- B305250449 Significant Deficiency Rept SD 414/B3-08 re tack weld found on shaft/rotor assembly of Limitorque operator motor Institutelly reported on B30415 Shaft rotor/assembly to be repaired or replaced Final rept expected by B30603 TUCKER, H B Duke Power Co B3/05/13 O'REILLY, J P Region 2, Dffice of Director 2pp 18585 284 24X Fiche 50-414,83/05/13, B305280449
- 8305270069 Final Significant Deficiency Rept 8D 413-414/82-27 re cracks in cell containers of nickel cadmium batteries mfg by Transamerica Delaval Initially reported on 821220 Caused by contact w/unknown solvent used for cleaning TUCKER. H B Duke Power Co 83/05/17 G'REILLY, J P Region 2, Office of Director, Spp 18638 279 24X Fiche 50-413,83/05/17,8305270067

DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT I

- A Application/construction stage documents & correspondence
- 8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress FELTON.J M Division of Rules and Records 83/03/31 8HOLLY, 8 C Union of Concerned Scientists 2pp 18593 179 24X Fiche. 50-000.83/03/31,8305240254.
- --BiO3300276 Comments on draft "Reactor Safety Bludy Methodology Applications Program Results for Orand Gulf 1 BMR Power Plant " Omissions & simplifications overstate risk of facility operation. HGD068.W Reactor Bystems Branch B1/03/24 CURRY, J Office of Nuclear Regulatory Research, Director Spp 18593, 252 24X Fiche, 50-000, 83/03/31, 8305240254
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 8305120460 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO, J J Licensing Branch 1 83/05/02, HOLTISCHER, D. L. Illinois Power Co. 2pp 18443 173 24X Fiche 50-000,83/05/02, 3305120460.
- --B305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental BERs, Info needed to document evaluation on each Licensing Review Group II generic issue,
 BTEFANGUU Licensing Branch 1 83/05/02 PCHELL,P Washington Public Power Bupply Bystem. 1p 18443 174 24X
 Fische 50-000,83/05/02.8305120460
- --8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs. Info needed to document evaluation on each Licensing Review Oroup II generic issue STEFANG.J J Licensing Branch 1 83/05/02 REED, W. J. Gulf States Utilities Co ip. 18443.175 24X Fiche 50-000,83/05/02,8305120460
- --B305120485 Requests into relissue solutions accepted by NRC which have a have not been addressed in BER/supplemental SERs Infoneeded to document evaluation on each Licensing Review Group II generic issue.

 STEFANO, J J Licensing Branch I B3/05/02 RICHARDBON, J. D. Mississippi Power & Light Co 1p 18443:176, 24X Fiche: 30-000, 83/05/02, 8305120460

- --8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licansing Review Group II generic issue
 STEFAND, J Licensing Branch 1 83/05/02 BUZZELLI, E M
 Cleveland Electric Illuminating Co ip 18443 177 24X
 Fiche 50-000,83/05/02,8305120460
- F Security, medical, emergency & fire protection plans
- 8305050075 Forwards Rev & to physical security plan Rev withheld (ref 10CRR2 790)
 MCGAUGHY, J P Mississippi Power & Light Co 83/02/21
 O'REILLY, J P Region 2, Office of Director 2pp 18342 052 24X
 Fiche 50-416-83/02/21.8305050075
- B305050077 Forwards revised pages & response to NRC comments re
 physical security plan, Revs 7 & 5, respectively Encis
 withheld (ref 100FR2 790)
 MC0AUGHY, J P Mississippi Power & Light Co B3/03/15
 O'RETLLY, J P Region 2, Office of Director 2pp 18342 148 24X
 Fiche 50-416,83/03/15,8305050077
- 8305270409 Notifies that IE Insp Rept 50-416/83-03 was insdvertently assigned wrong number Correct number is 50-416/83-07 Reissued IE Insp Rept 50-416/83-07 enci
 VERRELLI, D M Division of Project & Resident Programs 83/03/28 RICHARD, J B. Mississippi Power & Light Co ip 18642 305 24X Fiche 50-416.83/03/28,8305270409
- --8305270417 Forwards IE Insp Rept 50-416/83-07 on 830124-27 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/03/28 RICHARD.J B Mississippi Power & Light Co 2pp 18642 306. 24X Fiche 50-416,83/03/28,8305270409
- --8305270427 Corrected IE Insp Rept 50-416/83-07 on 830124-27. No noncompliance noted Major areas inspected emergency preparedness exercise CLING.W E. Region 2, Office of Director JENKINS.O R Division of Emergency Preparedness & Materials Safety 83/03/25 9pp 18642 308 24X Fiche 50-416,83/03/28,8305270409
- 8304280037 Application for amend to License NPF-13 re sealed source contamination reporting, fire protection & trip setpoints MCGAUGHY, P Mississippi Power & Light Co 83/04/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 18251 152 24X Fiche 50-416.83/04/25.8304280037
- --8304280049 Proposed Tech Specs re smaled source contamination, reporting fire protection & trip setpoints * Mississippi Power & Light Co 80/04/25 14pp 18251 161 24X Fiche 50-416/83/04/25,8304280037
- 8305110034 Ceneric Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits.

 Svc list encl
 EISENHUI, D © Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche 50-000, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKB, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X Fiche: 50-000, 83/05/13, 8305240213
- B305270028 Confirms NRC position re use of manually-entered codes & anti-passback features for control of access to vital areas Devices may unduly restrict movement during safety-related emergencies Response requested by 830630 SCHMENCER.A. Licensing Branch 2 83/05/23 MCOAUGHY, J P Mississippi Power & Light Co 2pp 18662 105 24X Fiche: 50-416, 83/05/23, 8305270028
- J. Insurance & indemnity information
- 8305190015 Forwards ANI Certificate N-79 & MAELU Certificate M-79 for secondary finencial coverage DALE, L.F. Mississippi Power & Light Co B3/05/11 KERR. 0 W Office of State Programs, Director 18pp 18501.340 24X Fiche 50-416.83/05/11,8305190015
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington.DC, # ACRS - Advisory Committee on Reactor Safeguards. 83/05/05 ACRS - Advisory Committee on Reactor Safeguards 527pp 18458:225 24X Fiche 50-000.83/05/05

P Operating license stage documents & correspondence

- 8305230608 Provides lump sum number representing direct cost impact of regulatory proliferation during approx period from NRC CP to low-gower OL.in response to 830208 request re backfitting COSES LUTKEN,D C Mississippi Power & Light Co 83 TOURTELLDTIE, J Regulatory Reform Task Force Fiche 50-416, 83/03/04, 8305230608 83/03/04 18541 340 P4X
- B305240249 FDIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515, 2787 & 2802) SHOLLY, B C Union of Concerned Scientists B3/03/11 FELTON, J M Division of Rules and Records ip 18593 178 24X Fiche 50-000, 83/03/11, 8305240249
- 8305240260 Forwards util comments on Reactor Safety Study Methodology Applications Program results Risks associated w/BWR/6 plant design misrepresented CESARE, O NRC No Detailed Affiliation Given 81/02/17 CURRY, J NRC No Detailed Affiliation Given 5pp 16573 175 24X Fiche 50-000.83/03/31,8305240854 17 CURRY, J
- --8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RSSMAP) evaluation conducted by Sandia Natl Labs Excessively conservative calculations used Related Correspondence enci

 DALE, L.F. Mississippi Power & Light Co. 81/01/23 BERNERD, R M
 Office of Nuclean Regulatory Research, Director 49pp. 18573 200
 24X Fiche 50-000,83/03/31.8305240254
- 8304(1032) Forwards application to amend License NPF-13 Amend revises surveillance procedure review - Package 2 & miscellaneous Tech Specs re responsibility for auditing station MCCAUCHY, J P Mississippi Power & Light Co 83/04/07 DENTON. I Office of Nuclear Reactor Regulation, Director 2pp 17911 031 24X Fiche 30-416.83/04/07.8304110321 DENTON, H R
- --8304110328 Application for amend to License NPF-13, revising survaillance procedure review Package 2 & miscellaneous Tech Specs re responsibility for auditing station activities MCGAUGHY-J P Mississippi Power & Light Co 83/ 17911 033 24X Fight 50-416,83/04/07,8304110321. 83/04/07 12pp
- --8304i10335 Proposed Tech Specs re prompt notification w/written followp:reactor protection sys instrumentation & RCS surveillance requirements, reactor vessel matl surveillance program-withdrawal schadule & area temp monitoring + Mississippi Power & Light Co 83/04/07 34pp 17911 045 Fiche 50-416.83/04/07.8304110321
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J. Regulatory Reform Task Force, 83/04/11 PALLADINO, N.J. Commissioners 2pp 18342 272 24X Fiche 50-000.83/04/11,8305230720
- 8304190378 Forwards corrected 830413 ltr providing update to 830128 & 820610 ltrs re Category I masonry walls & temp monitoring in HPCS dissel generator room PALE: F Mississippi Power & Light Co 83/04/13 DENTAN, H R Defice of Nuclear Reactor Regulation, Director 6pp 18056 063 24X Fichs. 50-416, 83/04/13, 8304190378
- 8304280037 Application for amend to License NPF-13 re sealed source contamination, reporting, fire protection & trip setpoints MCGAUGHY, J. P. Mississippi Power & Light Co. 83/04/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 9pp 18251 152 24X Fiche 50-416,83/04/25,8304280037
- --8304280049 Proposed Tech Specs re sealed source contamination, reporting, fire protection & brip setpoints * Mississippi Power & Light Co 83/04/25 14pp 18251 161 24X Fiche 50-416,83/04/25,8304280037.
- 8305040287 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues

 NOVAK.T.M Assistant Director for Licensing

 HOLTZECHER.D L Illinois Power Co 2pp 18

 Fiche 30-000.83/04/26.8303040289 83/04/26 18326-343
- 8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
 EISENHUT.D 0 Division of Licensing. 83/05/02 Consolidated Edison Co. of New York, Inc. 30pp. 18441 120 24X
 Fiche 50-000,83/05/02,8305020455

- 8305240496 Forwards "Safety Relief Valve Discharge Test," final rept for Kuosheng Nuclear Power Station, including Apps A-T Rept withheld (ref 100FR2 790) Info submitted per DL Condition QC(45)

 DALE, L. F. Mississippi Power & Light Co. 83/05/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 96189-286
 24% Fiche 30-000, 83/05/02, 8305240495
- 8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
 EISENHUT, D.G. Division of Licensing 83/05/03 EDELMAN, M.R. Gleveland Electric Illuminating Co. 2pp. 18523 198 24X
 Fiche 50-000,83/05/03,8305190046
- --8305190054 Commends representatives of BWR/b utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/b OL applicants EISENIUT. D O Division of Licensing 83/05/03 HALE.D P Illinois Power Co 2pp 18523 200 24X Fiche 50-000:83/05/03. 8305190044
- --8305190060 Commends representatives of BMR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 QL applicants
 EISENHUT, D G Division of Licensing 83/05/03 FEROUSON, M, R
 Washington Public Power Supply System 2pp. 18523 202 24X
 Fiche 50-000, 83/05/03, 8305190046
- --8305190068 Commends representatives of BWR/6 utils participating in SUSTINUOUS Commends representatives of BMR/A utils participating Licensing Review Group II for efforts in resolving issues generic to BMR/A OL applicants.

 EISENHUT.D 0 Division of Licensing 83/05/03 MCGAUGHY.J P Mississippi Power & Light Co 2pp 18323 204 24X

 Fiche 50-000.83/05/03.830517004A
- --8305190077 Commends representatives of BMR/6 utils participating in Licensing Review Group II for afforts in resolving issues generic to BMR/6 OL applicants ETBENUT.D O Division of Licensing. 83/05/03 CAHILL.J 0v1f Btates Utilities Co 2pp 18523 206 24X Fiche 50-000.83/05/03.
- 8305070639 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
 EISENHUT, D @ Div(sion of Licensing 83/05/09. Consolidated Edison Co. of New York, Inc 16pp 18627 153 24X
 Fiche 50-000,83/05/09,8305090659. Consulidated
- 8305130124 Forwards response to questions included in 830203 ltr re
 Hydrogen Control Owners Group program Questions 8 & 9 must
 be addressed on plant-specific basis Tentative errangements
 made for meeting w/Containment 8ys Branch on 830402
 RICHARDSON.J D Hydrogen Control Owners Group, BHR-6 Mark III
 RICHARDSON.J D Mississippi Fower & Light Co 83/05/11
 HOUSTON.R W Division of Bystems Integration (post 811005), 25pp
 18437 231 24X Fiche 50-416,83/05/11,8305130126
- B305250150 Notification of B30603 meeting w/BWR-Hydrogen Control Owners Oroup in Bethesda, MD to discuss hydrogen control program & emergency procedure guidelines HOUBTON.D Licensing Branch 2, B3/05/17 SCHWENCER, A Licensing Branch 2, 4pp 18596.191, 24X Fiche, 50-416, 83/05/17, 8305250150
- 8305240143 Forwards qualification status & compliance summary per 10CFR50 47 re environ qualification of electrical aquipment important to safety. Updated aquipment list & qualification status for relevant components encl. DALE: L F Mississippi Power & Light Co 83/05/20, DENTON: H R Office of Nuclear Reactor Regulation, Director. 61pp 18349:12 24X Fiche 50-416,83/05/20,8305240143
- O Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction." Svc list TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp. 18308 319. 24X Fiche 50-000,83/03/21,8212040385
- 8305270409 Notifies that IE Insp Rept 50-416/83-03 was inadvertently assigned wrong number. Correct number is 30-416/83-07. Reissued IE Insp Rept 50-416/83-07 encl. VERRELLI, D.M. Division of Project & Resident Programs 83/03/28. RICHARD, J. E. Mississippi Power & Light Co. ip 18642,305 24% Fiche 50-416,83/03/28.8305270409.

- --8305270417 Forwards IE Insp Rept 50-416/83-07 on 830124-27 No noncompliance noted VERRELLID M Division of Project & Resident Programs 83/03/28 RICMARD, J B Mississippi Power & Light Co 2pp 18642 306 24: Fiche 50-416,83/03/28,8305270409
- ---B305270427 Corrected IE Insp Rept 50-416/83-07 on B30124-27 No noncompliance noted Major areas inspected emergency preparedness exercise

 CLINE, W E Region 2, Office of Director JENKINB, O R Division of Emergency Preparedness & Materials Safety B3/03/25 7pp 18642 308 24% Fiche 50-416, B3/03/28, B305270409
- --8305270306 IE Insp Rept 50-416/83-11 on 830310-13 No noncompliance noted Major area inspected drywell suppression pool bypass leakage testing BROOKS,E H. JAPE,F Region 2, Office of Director 83/03/28 4pp 18641 175 24X Fiche 50-416,83/03/30,8305270300
- 8305270463 Forwards IE Insp Rept 50-416/83-09 on 830314-18 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/04/05 RICHARD.J B Mississippi Power & Light Co 2pp 18644 074 24X Fiche 50-416/83/04/05/8305270463
- --8305270470 IE Insp Rept 50-416/83-09 on B30314-18 No noncompliance noted. Major areas inspected review of startup procedures & acceptable test packages
 BURNETT: P T , JAPE.F. Region 2, Office of Director 83/03/30
 3pp. 18444 076 24X Fiche 50-416,83/04/05,8305270463
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435-155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relimf Valve Failures,"
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000/83/04/22,8303040023
- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphera Bensing Bys " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103), B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, B3/04/25, B303040025
- 8305270585 Approves issuance of SALP Rept 50-416/82-45 for Jul 1981 Aug 1982 Discussion of comment submitted in util 830302 ltr provided.

 O'REILLY: J P Region 2, Office of Director 83/04/25 LUTKIN, D C Mississippi Power & Light Co 3pp 18644 187 24X Fiche: 30-416, 83/04/25, 8305270585.
- ---8305270593 Comments on SALP Board Assessment 50-416/82-45 for Jul 1981 - Aug 1982, Plans to upgrade performance will be submitted in Mar 1983 MCQAUQHY, J P Mississippl Power & Light Co 83/03/02 O'REILLY, J P Region 2, Office of Director, 8pp. 18644 190 24X Fiche 50-416,83/04/25,8305270585
- --8305270396 Forwards SALP Board Assessment 50-416/82-45 for Jul 1981 Aug 1982. LEWIS.R C Division of Project & Resident Programs 83/02/03 STAMPLEY:N L Mississippi Power & Light Co 2pp 18644.178 24X Fiche 50-416.83/04/25.8305270585
- ---8305270637 BALP Board Assessment 50-416/82-45 for Jul 1981 Aug 1982 * Region 2, Office of Director 83/04/25 25pp 18644.200 24X Fiche 50-416.83/04/25.8305270585
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp. 18382:047 24X Fiche: 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Btandby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl. UGRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382 165 24X Fiche.50-000.83/04/28,8303040027

- B303040028 IE Info Notice B3-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN:E L Division of Emergency Preparadhess & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303120369 Discusses guidelines developed to aid in review of [E Bulletin 79-15] re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NGVAK. T M Assistant Director for Licensing 83/03/03 HOLTZSCHER, D L Cicensing Review Group II HOLTZSCHER, D L III incis Power Co 6pp 18440 356 24X Fiche 50-000, 83/05/03, 8305120549
- 8303040030 IE Info Notice B3-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list end!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Dinding Caused by Fuel Rack Deformation" Svc list encl
 JDRDANE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/06 Consolidated Edison Co of New
 York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- B303040034 IE Info Notice B3-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B305270275 Forwards IE Enforcement Conference Rept 50-416/83-15 on B30420 O'REILLY, J P Region 2. Office of Director 83/05/12 RICHARD, J B Mississippi Power & Light Co 2pp 18644 277 24X Ficha 50-416,83/05/12,8305270275
- --B305270283 IE Enforcement Conference Rept 50-416/83-15 on 830420 Major areas discussed enforcement issues resulting from inadequate control of mods & maint & inadequate corrective actions
 VERRELLI, D M Division of Project & Resident Programs 83/05/12
 4pp 18644 301 24X Fiche 50-416, 83/05/12, 8305270275
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list end!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 830327038B Ack receipt of 830401 & 0510 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-416/83-04 VERRELLI,D M Division of Project & Resident Programs 83/05/19 RICHARD,J B Mississippi Power & Light Co ip 18643 023 24X Fiche 50-416,83/05/19,8305270388
- --8305270400 Responds to NRC 830304 ltr re violations noted in IE Insp Rept 50-416/83-04 Corrective actions personnel informed of significance of correct positioning of handswitches MCGAUGHY.J P Mississippi Power & Light Co 83/05/10 O'REILLY.J P Region 2. Office of Director 2pp 94207 303 24X Fiche 50-416,83/05/19,8305270388
- --83052704iO Responds to NRC 830304 ltr re violations noted in IE Insp Rept 50-416/83-04 Corrective actions DOT label covered & correct label posted, add1 training seminar on posting held on 830128 & handswitches moved to standby MCOAUGHY, J P Mississippi Power & Light Co 83/04/01 O'REILLY, J, P Region 2, Office of Director 3pp 18643 026 24X Fiche 50-416.83/05/19,8305270388
- --8305270418 Forwards IE Insp Rept 50-416/83-04 on 830117-0215 & notice of violation
 VERRELLI.D.M Division of Project & Resident Programs 83/03/04
 STAMPLEY.N L Mississippi Power & Light Co 2pp 18643'029. 24X
 Fiche 50-416
- --8305270424 Notice of violation from insp on 830117-0215 * Region 2, Office of Director 83/03/04 ip 18643-031 24x Fiche 50-416,83/05/19,8305270388

- --8305270438 IE Insp Rept 50-416/83-04 on 830117-0215 Nancompliance noted failure to make Part 20 posting & to follow procedure re handswitches

 HAONER.A 0 , SCOTT.D E , CANTRELL, F S Region 2, Office of Director 83/03/02 5pp 18643 032 24X Fichs 50-416,83/05/19,8305270388
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated OII " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24x Fiche 50-000.83/05/26.8303040046

R Periodic operating reports & related correspondence

- 8305250072 Monthly operating rept for Apr 1983 W/830513 ltr RICHARDSON, J D , MCGAUGHY, J P Mississippi Power & Light Co, 83/03/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp 18385 103 24X Fiche 50-416,83/05/13,8305250072
- S Reportable occurrences, LERs & related correspondence
- B305270515 Interim deficiency rapt re defective contact button in Liberty Control telephone relays. Initially reported on B30217 Investigation of applicability to Unit 2 underway beficiency not reportable for Unit 1 Final rept by 830418 MCGAUGHY. J P Mississippi Power & Light Co. 83/03/18. 0'REILLY.J P Region 2. Office of Director. 6pp. 18646.121 24X Fiche 50-416.83/03/18.8305270515
- 8305030553 RD 83-024/O on 830319 & 30, several smoke detectors in control room Zones 1-18 & auxiliary bldg corridors, elevation 139 ft.respectively, covered to prevent actuation during welding fire watches established MCOAUGHY.J P Mississippi Power & Light Co 83/04/25 O'REILLY,J P. Region 2. Office of Director 2pp. 18303-337 24X Fiche:50-416.83/04/25,8305030553
- 8305030562 RO 83-023/0 on 830312; two smoke detectors in standby gas treatment filter train room. Zone 2-19 covered during welding activities to prevent actuation. Similar evant occurred on 830315. Detector operability to be restored by 830315. MCGAUCHY.JP Mississippi Power & Light Co 83/04/25 0'REILLY.JP Region 2. Office of Director. ip. 18304:125, 24X Fiche 30-416.83/04/25, 8305030562
- 8305050256 Forwards LER 83-061/03L-0 RICHARDS, J Mississippi Power & Light Co 83/04/27. O'REILLY, J P Region 2: Office of Director ip 18338 020 24X Fiche, 50-416, 83/04/27, 8305050256
- --B305030261 LER B3-061/03L-0 an B3032B, one solenoid operated Freon valve found w/blown gasket. Caused by defective ALCO Controls solenoid operated gasket Valve reworked w/valve repeir kit & new gasket installed ROHRER, N V., SHINOLETON, E. B. Mississippi Power & Light Co. B3/04/27 Region 2, Office of Director Ip (833B:021 24X Fichs. 30-416, 83/04/27, 8305050256
- 8303050[3] RO 83-026/0 on 830327, security access card reader to fire door (ASI8, Elevation 166 ft. in auxiliary bldg malfunctioned Caused by fire door blocked to allow personnel access. Card reader reworked & returned to svc 830405 MCQAUOHY. JP Mississippi Power & Light Co 83/04/28 G'REILLY. JP Region 2. Office of Director. ip 18342.201. 24X Fiche 50-416,83/04/28,8303050131
- B305050167 Forwards LER B3-060/03L-0 MCGAUGHY.J P Mississippi Power & Light Co 83/04/28. D'REILLY.J P Region P: Office of Director ip 18341.Q86 24X Fiche: 50-416.B3/04/28.B305050167.
- --B30505017B LER B3-060/03L-0 on B30329, during cold shutdown; load shedding & Div I LSB sequencing panel failure alarm actuated Caused by failure of 15-volt do power supply used to power sulf state electronics for sys logic.

 BYRD.R. Mississippi Power & Light Co. 83/04/28, Region 2, Office of Director 2pp. 18341.087, 24% Fiche: 50-416,83/04/28,8305050167
- 8305050227 RO BJ-025/0 on 830322, fire rated penetrations opened to implement design change peckages Hourly fire watches established within 1 h & will be maintained for duration of plenned maint activities. Work to be completed by 830610 MCGAUGHY-J P. Mississippi Power & Light Co 83/04/28 G'REILLY-J.P. Region 2. Office af Director 2pp. 18338:094, 24X Ficha 50-416.83/04/28.8305050227.
- B305110275 Forwards LER 83-051/03L-0

 DALELL F Mississippi Power & Light Co. 83/04/29. D'REILLY, J. P. Region 2. Office of Director. Bp 18393:148 24X
 Fiche: 50-416: B3/04/29, B305110275.

- --8305110279 LER 83-051/03L-0 on 830401, control room emergency filtration subsystem taken out of svc to ellow performance of corrective maint Task completed & subsystem energized on 830404
 ROHRER: M V , BHINOLETON, E B Mississippi Power & Light Co 83/04/29 Region 2, Office of Director 2pp 18393 149 24x Fiche 50-416,83/04/29,8305110275
- 8305110418 RD 83-027/O on 830321, during performance of seismic monitoring sys functional test, operation of chart recorders & spectrum anelyser determined unacceptable Ceuse not stated finvestigation underwey Next rept expected by 830615 DALE; L F Mississippi Power & Light Co 83/04/29, O'REILLY, J P Region 2, Office of Director ip 18392 001 24X Fiche 30-416,83/04/29,8305110418
- 8305110291 Special Rept 83-028/O on 830329, firs penetrations opened to implement design change packages Fire watches assablished, Work tasks expected to be completed by 830701 MCGAUGHY. J Mississippi Power & Light Co 83/05/04 O'REILLY, J. P. Region 2. Office of Director 3pp 18393 142 24X Fiche 30-416, 83/05/04, 8305110291
- 8305130194 Forwards updated LER 82-175/99X-1 MCGAUGHY.J P Mississippi Power & Light Co B3/05/06 O'REILLY.J P Region 2. Dffice of Director. ip 18440:071. 24X Fiche 50-416,83/05/06.8305130194
- --8305i30200 Updated LER 82-i75/99X-i on 82i2i3, fire barriers in control room panel discovered open Caused by breaking fire barriers to accompadate design change in panel Berriers restored on 8304i2

 BYRD, R. Mississippi Power & Light Co 83/05/06 Region 2, Office of Director ip 18440,072 24X Fiche 50-416,83/05/06,
- 8305170424 Forwards LER 83-048/01T-0 MCGAUGHY, J P Hississippi Power & Light Co 83/05/09. J'REILLY, J P Region R. Office of Director 1p. 18469.295 24) Fiche 50-416.83/05/09.8305170424
- --8305170426 LER 83-048/01T-0 on 830423, suppression pool level instrumentation discovered not functionally tested since 830407 Cause under investigation Instrumentation tested satisfactorily within 8 h ROHRER: M V . SHINOLETON. E B Hississippi Power & Light Co. 83/05/07 Region 2, Defice of Director. 1p. 18469 296 24 Fichs. 50-416: 83/05/09, 8305170424
- 8305170427 Forwards updated LER 83-031/79X-1. MCGAUGHY.J.P Mississippi Power & Light Co. B3/05/09. B765LLV.J.P Region 2: Office of Director. Piche: 50-416, 83/05/09. 3005170427.
- --8305170431 Updated LER 83-031/99X-1.on 830113, fire rated Door DC104 blocked open to route temporary discharge hose from hot machine shop sump to turbine bldg floor drain sys Caused by inadequacy of present sys Mod to be completed by Bept 1983. BYRDLR Mississippi Power & Light Co 83/05/09 Region 2, Office of Director ip. 18469 274, 24X Fiche.50-416,83/05/09,8305170427
- 8305170430 Forwards updated LER 83-004/01T-0. MCGAUCHY.J P Mississippi Power & Light Co. 83/05/09. G'REILLY.J P Region 2. Office of Director. 2pp 18467; 291. 24% Fichs 50-416,83/05/09,8305170430.
- --B305170433 Updated LER 83-004/01T-1 on 830110, penetration AP-728 found open & had been open since 821213 Caused by planned maint work & personnel error Hourly fire watch established. Penetration to be resealed by 830630.

 BYRD, R. Mississippi Power & Light Co. 83/05/09 Region 2, Office of Director, 2pp 18467:273 24X Fiche: 50-416.83/05/09, 8305170430.
- 8305200280 Forwards LER 83-049/03L-0, MCGAUGHY, J. P. Mississippi Power & Light Co., 83/05/09, O'REILLY, J. P. Region 2, Defice of Director, 1p. 18516 263, 24X Fichs: 30-416,83/05/09,8305200280
- --8305200286 LER 83-049/03L-0 on 830409; during cold shutdown, diesel generator 12 auto start not available when elerm actuated. Caused by condensate drain valve downstream of tank C not fully closed. Compresors reworked.

 BYRD, R Mississippi Power & Light Co. B3/05/09 Region 2. Office of Director 3pp 18516.264 24X Fiche. 50-416.83/05/09.8303200280

- B305200604 RD 83-029/O on B30422,50-meter wind direction reading did not agree w/10-meter reading Caused by Incorrectly wired new sensors located in Design Change Package 82-502 Wiring diagram corrected MCGAUGHY.J P Mississippi Power & Light Co B3/05/09 O'REILLY.J P Region 2. Office of Director 1p 18514 089 24X Fiche 30-416,83/05/09,8305200404
- 8305200523 Forwards LER 83-052/03L-0 MCGAUGHY,J P Mississippi Power & Light Co 83/05/11 O'REILLY,J P Region 2. Office of Director 1p 18516 043 24) Fiche 50-416, 83/05/11, 8305200523
- --83052005G2 LER 83-058/O3L-O on 8304i1, while reviewing vessel head installation work package, discovered head flange/vessel flange thermocouples not physically reinstalled during insulation installation Cause under evaluation ROHRER, M V Mississippi Power & Light Co 83/05/11 Region 2. Office of Director ip 18516-044 24X Fiche 50-416,83/05/11.8305200523
- 8305200484 Forwards LER 83-046/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/05/12 O'REILLY, J P Region 2. Office of Director 1p 18513 008 24X Fiche 50-416, 83/05/12, 8305200484
- --B305200493 LER B3-046/03L-0 on B30412, monthly functional surveillance for Div I chlorine detection sys not performed by B30410 Caused by personnel error ROMBER, M V Mississippi Pawer & Light Co 83/05/12 Region 2, Office of Director 2pp 18513 009 24X Fiche 50-416,83/05/12, B305200484
- 0305250365 RO B3-032/O on B30415, smoke detectors in control room covered to prevent alarm candition while welding performed Detectors uncovered on B30501 & sys returned to normal operation MCGAUGHY. J P Mississippi Power & Light Co B3/05/17 O'REILLY, J P Region 2. Office of Director ip 18585 350 24X Fiche 50-416, 83/05/17, 8305250365
- 8305250405 Final RO 83-002/i on 830201, smoks detectors on Elevation 119 ft of auxiliary bidg covered to perform planned maint Hourly fire watch established Detectors restored to svc on 830507.

 MCGAUGHY, J. P. Mississippi Power & Light Co 83/05/17 O'REILLY, J. P. Region 2, Office of Director 1p 18585 332 24X Fiche. 30-416, 83/05/17, 8305250405
- B305250434 RD B3-031/O on B30415, fire doors blocked open for 21 days, exceeding 7-day time limit Doors closed & restored to operation MCGAUGHY, J P Mississippi Power & Light Co B3/05/17 U'REILLY, J P Region 2, Office of Director 2pp 18585 291 24X Fichs; 50-416, 83/05/17, B309250434
- 8305250513 RO 83-033/0 on 830411, fire-rated penetrations opened to implement design change packages Hourly fire watches established within 1 h & will be maintained for duration of planned maint activities MCOAUGHY, J P Mississippi Power & Light Co 83/05/17 G'REILLY, J P. Region 2, Office of Director 2pp 18583 352 24X Fiche 50-414, 83/05/17, 8305250513
- 8305310146 Updated RO 83-006/1 on 830210, fire penetrations AE-382C & AE-384C opened to permit planned maint work Initially reported on 830318 Maint work order not completed Restoration data estimated for 830614 MCOAUCHY. J P Mississippi Power & Light Co 83/05/17 O'REILLY. J P. Region 2. Office of Director 1p 18651 208, 24X Fichs 50-416,83/05/17,8305310146
- 8305310207 Updated LER 82-027/79X-3 on 820727, seal AV-8D discovered not installed in spare HVAC penetration to containment exhaust filter train room due to current drawings not requiring penetrations to be scaled M/830517 ltr
 ROHRER,M V., SHINOLETON,E B. MCGAUGHY, J.P. Mississippi Power & Light Co. 83/05/17 0/REILLY,J.P. Region 2. Office of Director 2pp 18651:008 24X Fiche 50-416.83/05/17.8305310207
- 8305250487 Updated LER 83-048/01X-1 on 830425, surveillance coordinator found that suppression pool level instrumentation not functionally tested before exceeding Tech Spec late date Caused by personnel error W/830518 ltr ROHRER.M.V., MCCAUCHY.J.P. Mississippi Power & Light Co. 83/05/18 C'REILLY.J.P. Region 2. Office of Director 3pp 18588.288. 24X Fiche: 50-414,83/05/18,8305250487

- 8303250377 Updated LER 83-001/01x-1 on 830107, two wall penetrations (auxiliory hidg to turbine bldg) not previously opened Caused by personnel error Hourly fire watch established & personnel reinstructed re Tech Specs W/830318 ltr BYRD.R. MCOAUCHY.J P Mississippi Power & Light Co 83/05/18 O'REILLY.J P Region 2. Office of Director 4pp 18588 207 24X Fiche 50-416.83/05/18.8305230379
- 8305270473 RO on 830418, smake detectors N504 A, B & C at elevation 139 ft in auxiliary bldg covered to prevent continuous alarm condition from welding performed for planned maint activity Detectors uncovered & returned to svc on 830509 MCGAUGHY, J P Mississippi Power & Light Co 83/05/18 O'REILLY, J P Region 3, Office of Director 1p 18644 146 24X Fiche 50-416, 83/05/18, 8305270473
- 8305310065 Updated LER 82-080/01X-2 on 821004, cap screw, securing rear crankcase cover to engine block found cracked & breaking during torque check Caused by fatigue during engine operation W/830518 1tr
 ROMRER.M V. SHINGLETON, E B., MCGAUGHY.J P. Mississippi Power & Light Co. 83/04/18 0'REILLY.J P. Region 2. Office of Director 5pp. 18653 206 24% Fiche 30-416,83/05/18,8305310065
- 8305310204 Updated LER 82-138/99X-1 on 821112 several duct covers could not be installed while performing approved maint work on control room floor grid seals & duct covers Caused by cables extending through ducts H/830518 ltr BYRD.R. MCGAUCHY, JP Mississippi Power & Light Co 83/05/18 D'REILLY, JP Region 2, Office of Director 2pp 18651 006 24X Fichs 50-416,03/05/18,8305310204
- 8305310069 Updated RO 83-015/1 on 830311.during special insp of fire-rated assemblies, three open penetrations identified Correct mati nonconformance rept numbers should be 00162-83, 00163-83 & 00165-83 Restoration set for 830530 MCOAUGHY.JP Mississippi Power & Light Co 83/05/17, 0'REILLY.JP Region 2, Office of Director 2pp 18653 204 24X Fiche 30-416,83/05/17,8305310069
- 8305310196 RD 83-034/O on 830413, Fire Door 1A312 alarmed & would not reset Cause unknown Door functionally tested & returned to svc MCGAUGHY, J P Mississippi Power & Light Co 83/05/20 O'REILLY, J P Region 2, Office of Director 2pp 18658 160 24) Fiche 50-416, 83/05/20, 8305310196
- DOCKET 50-417 GRAND OULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305240254 Partial response to FDIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addi documents in progress FELTON.J M Division of Rules and Records 83/03/31 SHOLLY.8 C Union of Concerned Scientists 2pp 18593 179 24X Fiche 50-000.83/03/31.8305240254
- --8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RBSMAP) evaluation conducted by Sandia Natl Labs Ercessively conservative calculations used Related correspondence encl
 DALE.L F Mississippi Power & Light Co 81/01/23 BERNERO,R M Office of Nuclear Regulatory Research, Director 49pp 18593 200 24X Fiche 50-000,83/03/31,8303240294
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting
 TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11
 PALLADING, N. J. Commissioners 2pp 18542 272 24X
 Fiche 50-000,83/04/11,8305230720
- 8304190378 Forwards corrected 830413 ltr providing update to 830128 & 820610 ltrs re Category I masonry walls & temp monitoring in HPCS diesel generator room DALE/L F Mississippi Power & Light Co 83/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18056 063 24X Fiche 30-416/83/04/13, 8304190378
- B305040289 Advises that effective B30418.JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues NOVAK.F M Assistant Director for Licensing B3/04/24 HOLTSCHER.D L Illinois Power Co 2pp 18326 343 24X Fiche 30-000.B3/04/26.B305040289

- 8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EJSENHUT,D 0 Division of Licensing 83/05/03 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 18523 198 24K Fiche 50-000,83/05/03.8305190046
- --8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving Issues generic to SWR/6 DL applicants EISENHUT.D @ Division of Licensing 83/05/03 HALE.D P Illinois Power Co 2pp 18523 200 24X Fiche: 50-000.83/05/03. 8305190046
- --8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 GL applicants EISENHUT, D 6 Division of Licensing 83/05/03 FERGUSON, M R Washington Public Power Supply Bystem 2pp 18523 202 24X Fiche 50-000,83/05/03,8305190046
- --83051900AB Commends representatives of BNR/A utils participating in Licensing Review Group II for afforts in resolving issues generic to BNR/A OL applicants
 EISENHUT,D G Division of Licensing. 83/05/03 MCGAUGHY, J P Mississippi Power & Light Co 2pp 18523 204 24K Ficha 50-000.83/05/03.8305190046
- --8305190077 Commends representatives of BMR/A utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/A OL applicants EISENHUT, D G Division of Licensing. 83/05/03 CAHILL, J Gulf States Utilities Co 2pp 18323 206 24% Fiche 50-000,83/05/03,8305190046
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D © Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659
- B305130126 Forwards response to questions included in B30203 ltr re
 Hydrogen Control Owners Group program Guestions 8 & 9 must
 be addressed on plant-specific basis. Tentative arrangements
 made for meeting w/Conteniment Sys Branch on B30602
 RICHARDSON.J D Hydrogen Control Owners Group, BHR-6 Mark III
 RICHARDSON,J D Mississippi Power & Light Co. B3/05/11.
 HOUSTON,R W Division of Systems Integration (post B11005), 25pp
 18437 231 24X Fiche. 30-416, 83/05/11, 8305130126
- 8305240143 Forwards qualification status & compliance summary per 10CFR50 49 Te environ qualification of electrical equipment important to sefety Updated equipment list & qualification status for relevant components enci DALE, L.F. Mississippi Power & Light Co. 83/05/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 61pp. 18549 17. 24X Fiche 50-416,83/05/20,8305240143
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B305120460 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental EERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND.J J Licensing Branch i 83/05/02. HOLTZBCHER, D L Illinois Power Co 2pp 18443 173 24x Fiche. 30~000, 83/05/02, 8305120460
- --8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental BERs Info needed to document evaluation on each Licensing Review Group II generic issue

 STEFAND.J J Licensing Branch 1 83/05/02 POMELL, P Washington Public Power Supply System ip. 18443 174 24X
 Fichs 50-000.83/05/02.8305120460
- --8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFAND, J Licensing Branch & 83/05/02 REED, W J Qulf States Utilities Co lp 18443 175 24x Fiche 50-000, 83/05/02, 8305120460
- ~-8305120485 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 SYEFANO, J J Licensing Branch | 83/05/02 RICHARDSON, J D Missiesippi Power & Light Co ip 18443 176 24X
 Fich 50-000,83/05/02.8305120460

- --B305120491 Requests info re issue solutions accepted by NRC which have A have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFAND, J Licensing Branch 1 B3/05/02 BUZZELLI, E M. Cleveland Electric Illuminating Co 1p 18443 177, 24% Fiche 50-000, 83/05/02, 8305120460
- F Security, medical, emergency & fire protection plans
- 8305050075 Forwards Rev & to physical security plan Rev withheld (ref 10CFR2 790)

 MCGAUGHY, J P Mississippi Power & Light Co 83/02/21

 G'REILLY, J P Region 2. Office of Director 2pp 18342 052 24X

 Fiche 50-416.83/02/21.8305050075
- 8305050077 Forwards revised pages & response to NRC comments rephysical security plan.Revs 7 & 3.respectively Encls withheld (ref 10CRR2 790)
 MCGAUOHY, J P Mississippi Power & Light Co 83/03/15
 O'REILLY, J P Region 2, Office of Director 2pp 18342 148, 24X
 Fiche 50-416,83/03/15,8305050077
- 8305i10034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 075 24X Fich 30-000/83/05/11,8305110034
- 8305270028 Confirms NRC position re use of manually-entered codes & anti-passback features for control of access to vital areas Davices may unduly restrict movement during safety-related emergencies Response requested by 830630 SCHMENCER.A Licensing Branch 2 93/05/23 MCOAUGHY, J P Missistppi Four & Light Co 2pp 18662 105 24X Fiche 50-416,83/05/23.8305270028
- J Insurance & indemnity information
- 8303190015 Forwards ANI Certificate N-79 & MAELU Certificate M-79 for secondary financial coverage DALE: L F Mississippi Power & Light Co 83/05/11 KERR,O. W Office of State Programs, Director 18pp 18501.340 24X Fiche 50-416,83/05/11,8305190015
- Q Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212040385
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Bvc 1ist encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- B303040023 IE Info Notice 83-22: "BHR Safety/Relief Valve Failures." Bvc list encl JURDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 112pp 18383 089, 24% Fiche 50-000, 83/04/22, 8303040023
- B303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN E L Division of Emergency Preparadness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381.291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list encl UDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24% Fiche 50-000,83/04/28,83030400%
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment," Syc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fishe 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/03, Consolidated Edison Co. of New York, Inc. 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028

- 8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NOVAK, T M Assistant Director for Licensing 83/05/03 ROLTZSCHER, D L Licensing Review Group II HOLTZSCHER, D L IIlinois Power Co 6pp 18440 356 24X Fiche 50-000, 83/05/03, 8205120569
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc. 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- B303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list mcl,
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19,8303040040
- 8303040044 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Gil " Svc list sncl JURDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- B305270515 Interim deficiency rept re defective contact button in Liberty Control telephone relays Initially reported on 830217 Investigation of applicability to Unit 2 underway Deficiency not reportable for Unit 1 Final rept by 830418 MCGAUGHY.JP Mississippi Power & Light Co 83/03/18 0'REILLY.JP Region 2. Office of Director App 18646 121 24X Fiche 50-416.83/03/18.8305270515
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- B30506064B Forwards request for add1 info to complete evaluation of application for OL FBAR should be amended to include info requested Response requested by B30801 YOUNDBLOOD, B J Licensing Branch 1 B3/05/03 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 31pp 18358 006 24X Fiche 50-423, B3/05/03, B30506064B
- --8303170105 Forwards Div of Engineering proposed program to address US98 clarification re seismic design sarthquakes on eastern US seaboard. Proposed program will complete ongoing FRA reviews VOLLMER.R.H. Division of Engineering 83/03/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 91pp 18358 037 24X Fiche 30-423,83/03/03.8305060648.
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing 83/03/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8303090659
- B305250185 Summary of B30412 meeting w/util & Day,Berry & Howard in Bathesda: MD re licensing review items Viewgraphs encl DOOLITTLE: E. Licensing Branch 1 83/05/12 Licensing Branch 1 7pp 18626 348. 24% Fiche 50-423,83/05/12,8305250185

- 8305200587 Requests info re NRC contingencies built into current OL application review schedule to support fuel load date, per 830412 meeting COUNSIL.W 9 Northeast Utilities 83/05/13 YOUNGBLODD, B J Licensing Branch 1 1p 18514 246 24X Fiche 50-423,83/05/13,830520857
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 50-000.83/05/11.8305110034
- B305240213 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983
 DIRCKS,N J Diffice of the Executive Director for Operations 83/05/13 PALLADINO.N J Commissioners 5pp 18593 322 24X Fiche 50-000.83/05/13, B305240213
- I Financial information
- B305020093 Forwards "Annual Rept of Electric Utils, Licensees & Others (Class A & Class B)," FERC Form 1
 BISHOP,R W Northeast Utilities 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279 109 24X
 Fiche 50-245.83/04/26.8305020093
- K Utility Final Safety Analysis Report (FSAR) & amends
- B305030069 Forwards receipt ack form & corrected pages inadvertently omitted from FBAR Amend 2 package
 EMERSON.W Stone & Nebster Engineering Corp B3/04/20 NRC N
 Detailed Affiliation Given Bpp 18342 054 24X
 Fich = 50-423,83/04/20,8305050069
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction" Svc list encl
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator" Bvc list encl
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Bvc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 9303040025 IE Info Notice 93-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN/E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York: Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs" Bvc list encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83/04/28 Consolidated Edison Co
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Betpoint Adjustment " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-25. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York: Inc 122pp 18441 170 24x Fiche 50~000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche, 50-000, 83/05/04, 8303040030

- B303040031 IE Info Notice B3-28. "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/03/04 Consulidated Edison Co of New York, Inc 119pp 18441 001 24% Fiche 50-000, B3/03/04,B303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation "Svc list end. JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/17 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8305270033 Act receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-423/83-04

 MARTIN, T T Division of Engineering & Technical Programs B3/05/20

 COUNSIL-W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) Ip 18638 341 24% Fiche 50-423,83/05/20.8305270033
- ---B305270037 Responds to NRC B30328 ltr re violations noted in IE Insp Rept 50-423/B3-04 Corrective actions equipment storage history tards updated to reflect vendor requirements on spraying electrical contacts w/CRC 2-26 every 2 yrs COUNSIL,N G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,N G Northeast Utilities B3704/27 MARTIN,TT Division of Engineering & Technical Programs 3pp 18638 342 24X Fiche 50-423,83/05/20,8305270033
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences. LERs & related correspondence
- 8309110427 Part 21 & deficiency repts re misuperation of D8-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME, EP Westinghouse Electric Corp 83/04/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp (8405 095 24X Fiche 50-000,83/04/21.8303110427
- 8305060455 Interim deficiency rept re imadvertent uncoupling of pullapart terminal blocks in Gould motor control ctrs Initially reported on 830329 Development of prototype brackets underway Final rept expected by 830701 COUNBIL.W C , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W Q Northeast Utilities 83/04/28 ALLAN.J M Region I, Office of Director (p 1835) 198 24X Fiche: 50-423,83/04/28,8305040455
- 8305200533 Interim Significant Deficiency Rept SD-36 re design & const in main cantrol board welds Initially reported on 830413 Meeting w/util & engineer scheduled for 830517 to discuss necessary corrective actions COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities. 83/05/13 ALLAN.U M Region I. Office of Director 2pp 18016-025 24X Fiche 50-423.83/05/13.8305200333
- 8305270036 Final Deficiency Rept SD-37 re possible misoperation of Hestinghouse DS-416 reactor trip switchgear undervoltage attachments initially reported on 830420 Undervoltage attachments will be replaced w/new design CDUNSIL.H 6. SEARS.C F. Northeast Nuclear Energy Co. (subs of Northeast Utilities) CDUNSIL.H 6. Nartheast Utilities 83/05/20 ALLAN.J M. Region in Office of Director 2pp 18638 308 24X Fiche 50-423,83/05/20.8305270036
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8305030084 Notifies that update to PSAR Chapter 17 outlining GA organizational change will be provided by June 1983 per 10CFRSO 54
 DUTTON.D E Georgia Power Co 83/04/21 EIGENHUT.D 0 Office of Nuclear Reactor Regulation. Director 1p 18342 026, 24X
 Fiche 50-424,83/04/21,8305050086

- 8305090659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT, D © Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fichs 50-000,83/05/09,8305090659
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl
 EIBENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 14pp 18540 095 24X Fiche 50-000,83/05/11.8305110034
- H General correspondence
- 8308030261 Requests changes in correspondence routines due to recent mgt changes QUCHALL T Georgia Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18300 046 24X Fiche 50-000, 83/04/28, 8305030261
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin 8usceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Bafeguerds & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 30-000,83/03/21.8212060385
- 8305270330 Forwards IE Insp Repts 50~424/83-07 & 50-425/83-07 on B30115-0308 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/03/28 KELLY,R J Georgia Power Co 2pp 18641 112 24X Fiche 50~424,83/03/28,8305270330
- --8305270937 IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 % nencompliance noted Major areas inspected lifting & installation of NSSS components, automatic welding of pipe & electrical control terminations SANDERS.H F Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/03/28. 6pp 18641 114 24X Fiche:50-424,83/03/28,8305270330
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator."
 Svc 1(st encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000, B3/04/15, B303040021.
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list enc!

 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fichs 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381:291 24% Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Cenerators at PMRs" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co., of New York, Inc 115pp 18382,047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl. JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382 165 24% Fiche 50-000,83/04/28,8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441,170 24X Fiche 50-000, 83/05/03,8303040028.
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc 11st encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp, 18382,282 24X Fiche 50-000,83/05/04,8303040030

- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- B303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Bvc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305270320 Forwards IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted DANCE: H C Division of Project & Resident Programs 83/05/10 KELLY: R J Georgia Power Co 2pp 18642 217 24X Fichs 50-424, 83/05/10, 8305270320
- --B30527032B IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted Major areas inspected general observations of work in progress, observations of primary pips walding & preparations for heavy lifts BANDERS.W F Region 2. Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/05/09 4pp 18642 219 24% Fiche 50-424,83/05/10.8305270320
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000,83/05/11,8303040034
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 30-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- B. Reportable occurrences, LERs & related correspondence
- B305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830426 Attachments will be replaced widevices windened grooves to accommodate new retaining rings Mfg drawings revised RAME, E P Westinghouse Electric Corp B3/04/21 DEYGUNO, R C. Director's Office Office of Inspection and Enforcement 5pp 18405:095 24X Fiche 50-000, 83/04/21, 8305110427
- 8305100161 Interim deficiency rept re pipe support design calculations Initially reported on 830325 Engineering evaluation will not be completed until and of yr Schedule for completion of evaluation expected by 831201 FOSTER.D O Georgia Power Co 83/04/29 O'REILLY, J P Region 2. Office of Director ip 18374 271 24X Fiche 50-424.83/04/29, 8305100161
- 8305250452 Advises that final rept re sheared pinion keys in Limitorque motor operators will be submitted by 830610 FOBTER.D O. Georgia Power Co 83/05/16 D'REILLY, J. P. Region 2, Office of Director 1p 18585 211 24X Fiche 50-424.83/05/16, 8305250452
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8305050086 Notifies that update to PBAR Chapter 17 outlining GA organizational change will be provided by June 1983 per 100FR80 54.

 DUTTON D E. Georgia Fower Co. 83/04/21 EISENHUT, D G. Office of Nuclear Reactor Regulation, Director, 1p 18342 026 24X Fiche 50-424,83/04/21,8305050086
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode 8vc list encl EIBENHUT, D 9 Division of Licensing, 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Ficher 50-000.83/05/09,8305090659

- F Security, medical, emorgency & fire protection plans
- B305ii0034 Generic Ltr B3-2i to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D G Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18940 095 24X Fiche 50-000. B3/05/11, B305i10034
- H General correspondence
- 8305030261 Requests changes in correspondence routines due to recent mgt changes OUCHA.E.T Georgia Power Co 83/04/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 18300 046 24X Fiche 50-000.83/04/28.8305030261
- Q Inspection reports, IE Builetins & correspondence
- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exchermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Sefeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 317 24X Fichs 50-000.83/03/21,8212060385
- 8305270330 Forwards IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted DANCE, H C Division of Project & Resident Programs B3/03/28 KELLY, R J Georgia Power Co 2pp 18641 112 24X Fiche 50-424,83/03/28,8305270330
- --B305270337 IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted Major areas inspected lifting & installation of NSSB components, automatic welding of pipe & electrical control terminations

 SANDERS, W F Region 2. Office of Director BRDWNLEE, V L
 Division of Project & Resident Programs 83/03/28 App 18641 114 24X Fiche 50-424,83/03/28,8305270330
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Eve list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Bafety/Relief Valve Failures"
 Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 1129p 18383 089 24X Fiche 30-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JURDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fichs 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oos Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18392 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83705703 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83705703,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Evants Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830102) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382,282 24X Fiche: 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche: 50-000, 83/05/04, 8303040031

- B303040033 IE Info Notice B3-29, "Fuel Binding Caused by Fuel Rack Deformation' Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3705/06 Consolidated Edison Co of New York, Inc | 115pp 18323 248 24% Fiche 50-000.83705/06.8303040033
- B305270320 Forwards IE Insp Repts 50-424/83-08 & 50-425/83-08 on B30309-0412 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/10 KELLYR J Georgia Power Co 2pp 18642 217 24X Fiche 50-424-83/05/10,8305270320
- --8305270328 IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No nancompliance noted Major areas inspected general observations of work in progress observations of primary pipe welding & preparations for heavy lifts SANDERS H F Region 2, Office of Director BROWNLEE, V L. Division of Project & Resident Programs 83/05/09 App 18442 219 24X Fichs 50-424,83/05/10,8305270320
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8303040040 lE Info Notice 83-31, "Error in ADLPIPE Computer Program" Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc. 114pp 18697-009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 JE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences. LERs & related correspondence
- 8305110427 Part 2: & deficiency repts re misoperation of DS-414 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widered groupeds to accommodate new retaining rings Mfg drawings revised RAME.E P Westinghouse Electric Corp 83/04/21 DEVOUNG.R C Director's Office, Office of Inspection and Enforcement Spp 18405 095 24X Fiche 50-000.83/04/21.8305110427
- 8305100161 Interim deficiency rept re pipe support design calculations initially reported on 830325 Engineering evaluation will not be completed until and of yr Schedule for completion of evaluation expected by 831201 FOSTER.D D Opergia Power Co 83/04/29 O'REILLY, J P Region 2, Office of Director 1p 18374 271 24X Fiche 50-424.83/04/29, 8305100164
- 8303250452 Advises that final rept re sheared pinion keys in Limitorque motor operators will be submitted by 830610 FOSTER.D O Georgia Power Co 83/05/16 O'REILLY.J P Region 2, Office of Director 1p 18585 211 24X Fiche 50~424.83/05/16, 8305250452
- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- 8305040323 Board Notification 83-057 forwards differing prof opinions resys interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D Q Division of Licensing 83/05/04 PALLADINO, N COmmissioners 22pp 18337 139 24% Fiche 50-000,83/05/04,8305040323
- F Security, medical, emergency & fire protection plans
- B305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT,D C Division of Licensing 83/05/11 Consolidated EISENHUT,D C Division of Licensing 83/05/11 Consolidated Eisen Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B30503053B Advises that applicable recommendations contained in BMN Topical Rept BAM-1564, "Integrated Control Sys Reliability Analysis," will be implemented prior to fuel loading to fulfill requirements of NUREG-0737, Item II K 2 9 MILLS, L M Tennessee Valley Authority 83/04/26 ADENSAM, E Licensing Branch 4 1p 18303 297 24X Fiche 50-438,83/04/26,8305030558
- 8305100398 Forwards add1 documentation re Code Case N-192 for use of flexible metal instrumentation hose W/one oversize proprietary drawing Drawing withheld (may contain company sensitive info) Aperture card in Central Files MILLB.L M Tennessee Valley Authority 83/05/04 ADENBAN.E Licensing Branch 4 ip 18377 275 24X Fiche 50-438,83/05/04,8303100358
- --8305100349 "Design Spec BNP-DS-1940-4809-R0 Flexible Metal Instrumentation Hoses for Instrumentation & Control Sge ** BELTZ, I L Tennessee Valley Authority 80/09/03 7pp 18377 277 24X Fiths 50-438,83/05/04,8305100358
- --8305100382 Rev A to "Documentation of Compliance for MBC Part 78153 to Requirements of ASME Section III NC-3649 & Code Case N-92 & N-188-1 " NYSTROM.R H Metal Bellows Corp. CR 730 RA 80/10/17 Spp 18377 284 24X Fiche 50-438.83/05/04.8305100358
- --8305100395 Rev A to "Design Rept for Hose Assembly Flexible Metal Pr ABME Boiler & Pressure Vessel Code Section III, Subsection NC, Class 2 " NYSTROM, R H Metal Bellows Corp CR 729 RA 80/10/17 Jipp 18377 292 24X Fiche 50-438, 83/05/04, 8305100358
- 8305100240 Forwards response to Unresolved Safety Issues A-1, A-5, A-1i, A-12, A-17, A-40, A-43, A-44, A-45, A-46, A-47, A-48 & A-49 Responses support position that plant can be operated safely until resolution of open items MICLS, L M Tennesses Valley Authority 93/05/05 ADENSAN, E Licensing Branch 4 26pp 18372 298 24X Fichs 50-438, 83/05/05, 8305100240
- 8303070639 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153, 24X Fiche 50-000,83/05/09.8305090659
- F Becurity, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for CLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list enci EIEENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-00b, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS W J Office of the Executive Director for Operations 83/05/13 PALLADININ N J. Commissioners 5pp 18593 322. 24X Fiche 30-000/83/05/13.8305240213
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE lnfo Notice 83-14, "Dewatered Bpent Ion Exchange Resin Susceptibility to Exchange Chamical Reaction " Svc list enc!
 TAYLOR, J. M. Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidate Edison Co. of New York, Inc. 112pp 18308 319 24X Ficher 50-000, 83/03/21, 8212060385
- 8305270524 Forwards IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17 No noncompliance noted VERRELLID M Division of Project & Resident Programs 83/04/11, PARRISH 6, Tennessee Valley Authority, 2pp. 18646:175, 24X Fichs 50-438,83/04/11,8305270524
- --8305270537 IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830316-17 No noncompliance noted Major areas inspected item reported by licansee under locfr30 55(e) re excessive vibration of ERCH pump/mator
 LIU/N C , BLAKE, J. J. Region 2, Office of Director 83/04/07 5pp 18446 177 24X Fiche 50-438,83/04/11,8305270524.

- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator "
 - 90:004004: 12 1,...
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- 303040023 is anno notes. See list encl.

 JORDAN, E. L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040024
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8305270589 Ack receipt of 830331 & 0418 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-438/83-02 & 50-439/83-02 VERRELLI, D M Division of Project & Resident Programs 83/04/29 PARRIS, H 9 Tennessee Valley Authority 2pp 18646 215 24X Fiche 50-438,83/04/29,8303270589
- --8303270397 Add1 response to NRC 830223 ltr re violations noted in IE Insp Repts 30-438/83-02 & 30-439/83-02 Item 8 of noncompliance in area of flushing & hydrostatic testing & related procedures disputed
 MILLS,L M Tennessee Valley Authority 83/04/18 O'REILLY,J P
 Region 2, Office of Director 3pp 18646 217 24X
 Fiche 50-438,83/04/29,8305270589
- --8305270608 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Corrective actions document control unit performing review of craft drawings & will resolve discrepancies MILLS: LM Tennessee Valley Authority 83/03/31 D'REILLY, J P Region 2, Office of Director 4pp 18646 220 24X Fiche 50-438,83/04/29,8305270589
- --8305270616 Forwards IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 & notice of violation VERRELLI, D. M Division of Project & Resident Programs 83/02/25 PARRISH Q Tennessee Valley Authority 2pp 18646 224 24X Fiche 50-438,83/04/29,8305270589
- --8305270619 Notice of violation from insp on 830101-31 * Region 2, Office of Director 83/02/25 2pp 18646 226 24X Fiche 50-438,83/04/29,8303270589
- --8305270629 IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 Noncompliance noted failure to control installation of supports for remote valve operators inadequate drawing control & inadequate const operating instructions WILCOX, J D Region 2, Dffice of Director FREDRICKBON, P Division of Project & Resident Programs B3/02/25 14pp, 18644 228, 24% Ficher 50-438,83/04/29,8305270589
- 8303040028 IE Info Notice 83-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York: Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Byo list encl. UORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp. 18382 282 24X Fiche 50-000:83/05/04.8303040030
- B303040031 IE Info Notice B3-2B, "Criteria for Protective Action Recommendations for General Emergencies" Eve list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

- 8305270372 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03 VERRELLI.D M Division of Project & Resident Programs 83/05/04 PARRIS. H G Tennessee Valley Authority 1p 18642 337 24X Fiche 50-438, 83/05/04, 8305270372
- --8305270386 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03 Corrective actions inspector reinstructed to verify concrete patch curing record completion MILLS,L M Tennessee Valley Authority 83/04/22 (
 Region 2. Office of Director 5pp 18642 338 24X
 Fiche 50-438,83/05/04,8305270372
- --8305270396 Forwards IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 & motice of violation VERRELLI,D M Division of Project & Resident Programs 83/03/ PARRISH 0 Tennessee Valley Authority 2pp 18442 343 24) Fiche 50-438,83/05/04,8305270372
- ---8309270398 Notice of violation from insp on 830207-18 * Region 2, Office of Director 83/03/25 2pp 18442 345 24x Fiche 50-438,83/05/04,8305270372
- --8305270415 IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 aud2/0413 it insp kepts 30-43/83-03 on 83020/Noncompliance noted failure to properly cure concrete repair
 patch & failure to train electrical craft foremen in
 procedure for structural steel installations
 HARRIS, J. R. Region 2, Office of Director CONLON, T. E. Divi
 of Project & Resident Programs 83/03/23 lipp 19642 347
 Fiche 50-438,83/03/04.8305270372
- B305270582 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04 50-437/83-04 VERRELLI.D M Division of Project & Resident Programs 83/05/05 PARRISH O Tennesse Valley Authority 1p 18646 301 24X Fiche 30-438,83/05/05,8305270582
- -8308270592 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04 Corrective actions cable reconfigured to produce acceptable band radius & proper returning to produce acceptable and realist proper torque values for side bolting obtained from vendor KAMMER: D B Tennessee Valley Authority B3/04/25 O'REILLY, J P Region 2. Office of Director 5pp 18446:302 24X Fiche 50-438,83/05/05.8305270582
- --8305270601 Forwards IE Insp Repts 30-438/89-04 & 50-439/89-04 on B30207-18 & notice of violation
 VERRELLI,D M Division of Project & Resident Programs 83/03/2
 PARRIS,H C Tannessee Valley Authority 2pp 18646 307, 24X
 Fiche 30-438,83/05/05,8305270582 B3/03/25
- --8305270407 Notice of violation from insp on 830207-18 * Region 2. Office of Director 83/03/25 ip 18446 309 24X Fiche 50-438,83/05/05,8305270582
- --8305270618 IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18 Noncompliance noted bend at trays TY3-A647-A; TY3A54:-8 & TY4A491-A Bxceeded Openral Const Spec G-38 min radius RUFF,A B Region 2, Office of Director CONLON,T E Division of Project & Resident Programs 83/03/23 14pp 18646-310 24X Fiche 50-438, 83/03/05,8305270582
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Ouidelines " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fich 50-000,83/05/11,8303040034
- 8303040040 JE Info Notice 83-31. "Error in ADLPIPE Computer Program " SUC list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc. 114pp 18497 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Di1 " Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- 8305030252 Final Deficiency Rept NCR 1690 re nonconforming seismic support lugs on 2-inch or less steel pipe Initially reported on 811225 Designs & procedures modified & fabrication techniques changed to reduce welding MILLS, L M Tennessee Valley Authority 83/04/25 O'REILLY, J P Region 2, Office of Director 3pp 18300 051 24% Fiche 50-438.83704/25.8305030282
- 8305030370 Seventh interim deficiency rept re failure of bolts & nuts to meet ASTM specs Initially reported on 810924 Results of analysis of bolting mat! will be evaluated Next rept will be submitted by 830707 Also reported per 100FR2! MILLS,L M Tennessee Valley Authority 83/04/25 O'REILLY,J P Region 2. Office of Director 2pp 18306 217 24X Fiche 50-438,83/04/25,8305030370
- 8305050120 Second interim deficiency rept re improperly qualified norrie loads Initially reported an 830124 Fifty-five problems identified & 62 problems remain to be investigated Next rept expected by 831017 MILLS.L M Tennessee Valley Authority 83/04/27 O'REILLY.J P Region 2. Office of Director 2pp 18337 133 24X Fiche 30-438.83/04/27.8305050120
- 8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
 MILLS, L M Tonnessee Valley Authority 83/04/27 D'REILLY, J P Region 2, Office of Director 3pp 18341 083 24X
 Fiche 50-000,83/04/27,8305050152
- 8305050122 Second interim deficiency rept re unqualified flex-hose connections Initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21 MKLL9,L M Tennessee Valley Authority 83/04/28 O'REILLY, J P Region 2. Defice of Director 2pp 18342 178 24X Fiche 30-438,83/04/28,8305050122
- 8305050188 First interim deficiency regt re tubeline matls supplied by Capital Pipe not mfg per GA program Initially reported on 830327 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706 MILLS.L N Tennessee Valley Authority 83/04/28 0'REILLY, J P Region 2. Dffice of Director 2pp 18341 074 24% Fiche 50-000.83/04/28.8305050188
- 8305110304 First interim deficiency rept re outdated design criteria for DHR & core flooding sys Initially reported on 830405 Latest approved BMH descriptions reviewed to determine adequacy of latest util design Next rept by 831123 MILL9,L M Tennessee Valley Authority 83/05/02 O'REILLY, J P Region 2, Office of Director 2pp 18393 235 24X Fiche 50-438,83/05/02,8305110304
- 8305110406 Third interim deficiency rept re undersized fillet welds made before mid-1780 Initially reported on 820722 Craftsmen & inspectors not in possession of fillet gauges to determine proper weld size Insp continuing Next rept by 831205 MILLS.L M Tennessee Valley Authority 83/05/02 O'REILLY, J P Region 2. Office of Director 2pp 18406 187 24X Fiche 50-438,83/05/02,8305110406
- 8305110317 First interim rept re Deficiencies 1,2 & 3 @A program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc Written instructions & procedures not provided to contractor in performing/documenting plping analysis Review underway MILLS,L H Tennessee Valley Authority 83/05/05 D'REILLY, J P Region 2, Defice of Director 3pp 18373 181 24X Fiche 50-000,83/05/05,8305110319
- B305130147 Second interim deficiency rept re backflow not considered for ERCM booster pump shutoff Initially reported on 821230 Design criteria diagram for ERCM modified to include check valves Next rept will be submitted by 840719 HILLS.L M Tennessee Valley Authority 83/05/06 O'REILLY, J P. Region 2. Office of Director 2pp 18438 122 24X Fiche 30-438,83/05/06.8305130147
- 8303130154 First interim deficiency rept re defects in pipe clamps mfg by ITT Grinnell Initially reported on 830406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21 MILLS.L M Tennessee Valley Authority 83/05/06 O'REILLY, J P Region 2. Office of Director Spp. 18437 182 24X Fiche 30-438,83/05/06,8305130154

- 8305200569 Fourth interim deficiency rept re implementation of GA test documentation on radiation monitoring equipment Initially reported on 820824 GA Technologies will field test monitor & rewrite test travelers Next rept by 831228
 MILLS,L M Tennessee Valley Authority 83/05/11 0'REILLY,J P Region 2. Office of Director ip 18514 277 24X
 Fiche 50-438.83/05/11.8305200569
- 8305200187 Final deficiency rept re unauthorized use of QC stamp Initially reported on 821216 Identification markings on items cited by rept have been obliterated & items scrapped QC personnel trained on proper use & security MILLS.L M Tennessee Valley Authority 83/05/16 0'REILLY, J P Region 2. Office of Director 2pp 18519 001 24X Fiche 50-438,83/05/16,8305200187
- 8303200519 First interim deficiency rept re inadequate Calculation TI-ECS-47, "Common Zone & Fuel Handling Area Tornado Depressurization Analysis " Initially reported on 830414 Initial review indicated walls & floors maintain integrity MILLS,L M Tennessee Valley Authority 83/05/16 O'REILLY,J P Region 2, Office of Director 2pp. 18516 083 24X Fiche 50-438,83/05/16,8305200519
- 8305230545 Second interim rept re generic deficiencies at Consolidated Controls Corp Initially reported on 820916 Evaluation Indicates GC problems corrected & equipment Pailures random Also reported per Part 21 Next rept by 831117 MILLS.L M Tennessee Valley Authority 83/05/18 O'REILLY, J P. Region 2. Dffice of Director 2pp 18337 085 24X Fiche 30-438,83/05/18,8305230545
- G305230551 Third interim deficiency rept re lack of environ qualification for equipment in auxiliary bidg due to potential failure of startup & reirculation sys Initially reported on B20422 Design work ongoing Next rept by B40217 MILLS,L M Tennessee Valley Authority B3/05/18 O'REILLY, J P Region 2, Office of Director 2pp 18537 333 24X Fiche, 50-438, 83/05/18, 8305230551
- 8305230565 Final deficiency rept re use of unqualified TVA-designed fillet welds on piping lugs Initially reported on 820819. Calculation package for lugs complete Procedures for designing fillet-welded lugs incorporated MILLS,L M Tennessee Valley Authority 83/05/18, 0'REILLY, J. P. Region 2. Office of Director 2pp 18537 072 24X Fiche 50-438,83/05/18,8305230565
- 8305310138 Seventh interim deficiency rept re inconsistency between assumptions for pipe break in LOCA & structural analyses for connecting pipes in affected loop Initially reported on 801121 Next rept by 831118 Also reported par Part 21, MILLS.L M Tennesse Valley Authority 83/05/23 0'REILLY, J. P Region 2: Defice of Director 2pp 18656 125 24X Fiche 50-438,83/05/23.8305310138
- 8305310193 First interim deficiency rept re power cable bend radii in vertical to horisontal trays Initially reported on 830422 Vendor assistance will be requested to determine min acceptable bend radius
 MILLS,L M Tennessee Valley Authority 83/05/23 0'REILLY, J P
 Region 2. Office of Director 2pp 18651.004 24X
 Fiche 30-438.82/05/23,8305310193
- B305310214 Eighth interim deficiency rept re B&W nonconservative analysis of neutron flux. Initially reported on B01105, Also reportable per Part 21 Util awaiting results of B&W analysis Next rept will be submitted by B31024 MILLS,L.M Tannessee Valley Authority B3/05/23 O'REILLY,J.P Region 2. Office of Director 2pp 18658 146 24X Fiche: 50-438,83/05/23,8305310214
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8305030558 Advises that applicable recommendations contained in B&W Topical Rept BAW-1364, "Integrated Control Sys Reliability Analysis," will be implemented prior to fuel loading to fulfill requirements of NVREG-0737, Item II K 2.9.
 HILLE,L M Tennessee Valley Authority 83/04/26 ADENBAM.E Licensing Branch 4 ip. 18303 299 24X Fiche. 50-438.83/04/26, 8305030558
- 8305100358 Forwards add1 documentation re Code Case N-192 for use of flexible metal instrumentation hose M/one oversize proprietary drawing Drawing withheld (may contain company sensitive info) Aperture card in Central Files MYLLSLL M Tennesse Valley Authority 93/05/04 ADENSAM.£ Licensing Branch 4 1p 18377.275 24X Fiche. 30~438,83/05/04.8305100358

- --8305100367 "Design Spec BNP-DS-1940-4809-R0 Flexible Metal Instrumentation Hoses for Instrumentation & Control Sys " BELTZ,I L Tennessee Valley Authority 80/09703 7pp 18377 277 24X Fiche 50-438,83/05/04.8305100358
- --8305100382 Rev A to "Documentation of Compliance for MBC Part 78153 to Requirements of ASME Section III NC-3647 & Code Case N-92 & N-188-1 " NY8TROM.R H Metal Bellows Corp CR 730 RA 80/10/17 8pp 18377 284 24X Fiche 50-438.83/05/04.8305100358
- 18377 284 24X Fiche 50-438,83/05/04,8305100358
- --B305100395 Rev A to "Design Rept for Hose Assembly Flexible Metal Per ASME Boiler & Pressure Vessel Code Section III. Bubsection NC. Class 2 " NYSTROM.R H Metal Bellows Corp. CR 729 RA 80/10/17 31pp 18377 292 24X Fiche 50-438.83/05/04.8305100358
- 8303100240 Forwards response to Unresolved Safety Issues A-1,A-5,A-11.A-12.A-17,A-40,A-43,A-44,A-45,A-46,A-47,A-48 & A-49
 Responses support position that plant can be operated safely until resolution of open items
 MILLS.1. M Tennessee Valley Authority 83/05/05 ADENSAM.E
 Licensing Brench 4 26pp 18372 298 24X Fiche 50-438,83/05/05,8305100240
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl.
 EISENHUT, D 0. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X
 Fiche: 50-000, 83/05/09, 8305090659
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr B3-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl
 EISEMMUT.D 9 Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche. 50-000,83/05/11,8305110034
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent for Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Bafeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8305270524 Forwards IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17. No noncompliance noted VERRELLI,D M Division of Project & Resident Programs, 83/04/11, PARRIS,H 9 Tennessee Valley Authority 2pp 18646:175 24X Fiche. 50-438,83/04/11,8305270524
- --8305270537 IE Insp Repts 50-438/83-07 & 50-439/83-09 on 830316-17 No noncompliance noted Major areas inspected item reported by licensee under 10CFR50 55(e) re excessive vibration of ERCW pump/motor LIU, M.C., BLAKE, J J Region 2, Office of Director, 83/04/07 5pp. 18446 177. 24X Fichs 50-438,83/04/11.8305270524
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/15 Consolidated Edison Co. of New York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Feilures "
 8vc 1ist enci.
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp. 18383 089 24X Fiche 50-000,83/04/22,8303040023,
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list encl JORDAN, E. L. - Division of Emergency Preparedness & Engineering Response (Post 830103). B3/04/25 Consolidated Edison Co. of New York: Inc 119pp. 18381 291, 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8305270589 Ack receipt of 830331 & 0418 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 VERRELLI.D M Division of Project & Resident Programs 83/04/29 PARRIE.H G Tennessee Valley Authority 2pp 18646 215 24X Fiche 50-438/83/04/29.8305270589
- --8305270597 Add1 response to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-437/83-02 Item 8 of noncompliance in area of flushing & hydrostatic testing & related procedures disputed MILLB.L M Tennessee Valley Authority B3/04/18 0'REJLLY.J P Region 2. Office of Director 3pp 18646 217 24X Fiche 50-438,83/04/29,8305270589
- --8305270608 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Corrective actions document control unit performing review of craft drawings & will resolve discrepancies MILLS: L M Tennesser Valley Authority 83/03/31 D'REILLY, J P Region 2. Office of Director 4pp 18646 220 24X Fiche 50-438,83/04/29,8305270589
- ---8305270616 Forwards IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 & notice of violation VERRELLID M Division of Project & Resident Programs 83/02/25. PARTS, H Q Tennesses Valley Authority 2pp 18646 224 24X Fiche 50-438,83/04/29.8305270589
- --8305270619 Notice of violation from insp on 830101-31 * Region 2. Office of Director 83/02/23 2pp 18646 226 24X Fiche 50-438,83/04/29,8305270589
- --B305270629 IE Insp Repts 50-438/83-02 & 50-439/83-02 on B30101-31 Noncompliance noted failure to control installation of supports for remote valve operators, inadequate drawing control & inadequate const operating instructions WILCOX, J D Region 2, Office of Director FREDRICKSON, P Division of Project & Resident Programs 83/02/25 14pp. 18646 228 24X Fiche 50-438,83/04/29,8303270589
- B303040028 IE Info Notice B3-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3705703 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, B3/05/03, B303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche 30-000-83/05/04.8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fichs 50-000.83/05/04,8303040031
- 8305270372 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-438/83-03 & 50-439/83-03 VERRELLI, D M Division of Project & Resident Programs. 83/05/04 PARRIE, H 0 Tennessee Valley Authority ip 18642 337. 24X Fiche 50-438,83/05/04,8305270372
- --8305270386 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03 Corrective actions inspector reinstructed to verify concrete patch curing record completion MILLB.L M. Tennessee Valley Authority 83/04/22 D'REILLY, J. P Region 2, Office of Director 5pp 18642 338 24X Fichs 50-438,83/05/04,8305270372
- --8305270396 Forwards IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 & notice of violation. VERRELLID M Division of Project & Resident Programs 83/03/25 PARRIB H Q. Tennessee Valley Authority 2pp 18642:343 24X Fiche 50-438,83/05/04,8305270372.
- --8305270398 Notice of violation from insp on 830207-18 * Region 2, Office of Director 83/03/25 2pp 18642:345 24X Fiche 50-438,83/05/04,8305270372.

- --8305270415 IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 Moncompliance noted failure to properly cure concrete repair patch & failure to train electrical craft foremen in procedure for structural steel installations
 MARRIG.J R Region 2. Diffice of Director CONLON.T E
 of Project & Resident Programs 83/03/23 11pp 1864
 Fiche 50-438,83/05/04.8305270372 % TE Division 18642 347 24
- 8305270582 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04 50-439/83-04
 VERRELLI,D M Division of Project & Resident Programs
 PARRIS,H G Tennestee Valley Authority ip 18646 301
 Fiche 50-438,83/05/05,8305270582 83/05/05
- --B305270592 Responds to NRC B30325 ltr re violations noted in IE Insp Repts 30-438/83-04 & 50-439/83-04 Corrective actions cable reconfigurad to produce acceptable bend radius & proper torque values for side bulting obtained from vendor KAMMER: D S Tennessee Valley Authority B3/04/25 O'REILLY, J P Region 2. Office of Director Spp 18644 302 24X Fiche 50-438,83/05/05,8305270582
- --8305270601 Forwards IE Insp Repts 50-438/83-04 & 50-439/83-04 on B30207-18 & notice of violation VERRELLID M Division of Project & Resident Programs 83/03, PARRIS.H O Tennessee Valley Authority 2pp 18646 307 24) Fiche 50-438,83/05/05,8305270582 83/03/25
- --8305270407 Notice of violation from insp on 830207-18 * Region 2. Office of Director 83/03/25 ip 16 Fiche 30-438.83/05/05.8305270582 18646 309 24X
- --8305270618 IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18
 Noncompliance noted bend at trays TY5-A649-A, TY3A561-B &
 TY4AA71-A proceeded General Const Spec G-38 min radius
 RUFF, A B Region 2, Office of Director CONLON, T E Division of
 Project & Resident Programs 83/03/23 14pp 18646 310 24X
 Fiche 50-438,83/03/05,8305270582
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18323 248 24% Fiche 50-000,83/05/06,8303040033
- B303040034 IE Info Notice B3-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl URDAN EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000, 83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " JOSOPOUTO IN INTO NUMBER 2015
 SVC list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 011" Svc list enc?
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- B Reportable occurrences, LERs & related correspondence
- 8305030252 Final Deficiency Rept NCR 1690 re nonconforming seismic support lugs on 2-inch or less steel pipe Initially reported on 811225 Designs & procedures modified & fabrication on diseaso signs & protestory modeling techniques changed to reduce usiding MILLERL M Tennessee Valley Authority 83/04/25 O'REILLY, J P Region 2. Office of Director 3pp 18300 051 24X Fichs 50-438.83/04/25.8305030252
- 8305030370 Seventh interim deficiency rept re failure of bolts & nuts to meet ASTM specs. Initially reported on 810924 Results of analysis of bolting mati will be evaluated Next rept will be submitted by 830707 Also reported per 100FR21 MILLS.L M Tennessee Valley Authority 83/04/25 O'REILLY, J P Region 2. Office of Director 2pp 18306 217 24X Fiche 50-438.83/04/25.8305030370
- 8305050120 Second interim deficiency rept re improperly qualified notite loads Initially reported on 830124 Fifty-five problems identified & 62 problems remain to be investigated. Next rept expected by 831017 MILLS,L M Tennessee Valley Authority 83/04/27 D'REILLY, J R Region 2, Office of Director 2pp 18337 133 24X Fiche 50-438,83/04/27,8305050120 D'RETLLY, J P

- B305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316 MILLS, L M On Stylin MILLS,L M Tennessee Valley Authority 83/04/2 Region 2, Office of Director 3pp 18341 083 Fiche 50-000,83/04/27,8305050152 83/04/27 ... 24 X
- 8305050122 Second interim deficiency rept re unqualified flex-hose connections Initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21
 MILLS.L M Tennessee Valley Authority 83/04/28
 Region 2, Office of Director 2pp 18342 198 2
 Fiche 50-438.83/04/28,8305050122 O'REILLY, J P
- 8305050188 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per GA program Initially reported on 830329 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706 MILLS.L M Tennessee Valley Authority 83/04/28 D'REILLY, J P Region 2. Office of Director 2pp 18341 076 24X Fiche 30-000.83/04/28,8305050188
- 8303110292 Third interim deficiency rept re linear indications in Natl Valve & Mfg Co spool pieces Initially reported on 820924. Vendor requested to supply list of spool pieces w/Heat Code L63687 Util awaiting reply Also reportable per Part 21. MILLS.L M Tennessee Valley Authority 83/05/02. O'REILLY, J. P. Region 2, Office of Director 2pp 18393 254 24X Fiche 50-439.83/05/02.830310292 Fiche 50-439, 83/05/02, 8305110292
- 8305110304 First interim deficiency rept re outdated design criteria for DHR & core flooding sys Initially reported on 830405. Latest approved BMN descriptions reviewed to determine adequacy of latest util design Next rept by 831123. MILLS.L M Tennessee Valley Authority 83/05/02 D'REILLY, J. P Region 2. Office of Director 2pp 18393 235 24X Fiche 50-438,83/05/02,8305110304
- 8303i10406 Third interim deficiency rept re undersized fillet welds made before mid-1980 Initially reported on 820722 Craftsmen & inspectors not in possession of fillet gauges to determine proper weld size Insp continuing Next rept by 831205 MILLS.L M Tennessee Valley Authority 83/05/02 0'REILLY.J P. Region 2. Office of Director 2pp 18406 187. 24X Fiche 50-438.83/05/02.8305110406
- 8305110441 Final deficiency rept re faulty relays mfg by Brown Boveri Electric in auxiliary power distribution sys Initially reported on 820528 Four relays returned to vendor for repair & reinstalled at facility Also reported per 10CFR21. MILLS.L H Tennessee Valley Authority. 83/05/02. 0'REJLLY, J. P Region 2. Office of Director 2pp 18393 348 24X Fiche 50-439,83/05/02,8305110441
- 8305130089 First interim deficiency rept re drawing discrepancy for in-core monitor tank sleeves Initially reported on 830405. Use of tank sleeves in present configuration under investigation Next rept will be submitted by 831222. MILLS,L M. Tennessee Valley Authority 83/05/04. 0'REILLY,J P. Region 2. Office of Director 2pp. 18437-256-24X Fiche 50-439,83/05/04.8305130089
- 8305110319 First interim rept rs Deficiencies 1,2 & 3,0A program per TVA Personal Svcs Contract TV-47510A w/011bert Assoc Written instructions & procedures not provided to contractor in performing/documenting piping analysis Review underway MILLS,L M Tennesses Valley Authority 83/05/05, D'REILLY, J P Region 2, Dffice of Director 3pp 18373 181 24X Fiche 50-000,83/05/05,8305110319
- 8305130147 Second interim deficiency rept re backflow not considered for ERGW booster pump shutoff Initially reported on B21230. Design criteria diagram for ERGW modified to include check valves Next rept will be submitted by 840719 MILLS, L M Tennessee Valley Authority 83/05/06 D'REILLY, J P Region 2. Office of Director. 2pp 18438-122. 24X Fiche 50-438,83/05/06,8305130147
- B305i30i54 First interim deficiency rept ra defects in pipe clemps afg | by ITT Orinnell Initially reported on B30406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21 MILLS,L M Tennessee Valley Authority B3/05/06, D'REILLY,JP Region 2, Dffice of Director 3pp. 18437 182 24X Fiche 50-438.83/05/06.8305130154
- B305200569 Fourth interim deficiency rept re implementation of GA test of documentation on radiation monitoring equipment Initially reported on B20824. GA Technologies will field test monitor & rewrite test travelers Next rept by B31228.
 MILLS,L M Tennesse Vallay Authority B3/05/11. 0'REILLY, J. P. Region 2. Defice of Director in 18514 277 24X
 Fiche 50-438,83/05/11,8305200569

- 8305200187 Final deficiency rept re unauthorized use of QC stamp Initially reported on 821216 Identification markings on items cited by rept have been oblitorated & items scrapped QC personnel trained on proper use & security MILLS, L M Tennessee Valley Authority 83/05/16 O'REILLY, J P Region 2. Office of Director 2pp 18519 001 24X Fiche 50-438.83/05/16,8305200187
- 8305200519 First interim deficiency rept re inadequate Calculation TI-ECS-47; "Common Zone & Fuel Handling Area Tornado Depressurization Analysis "Initially reported on 830414 Initial review indicated walls & floors maintain integrity MILLS.L M Tennessee Valley Authority 83/05/16 D'REILLY:J P Region 2. Office of Director 2pp 18516 083 24X Fiche 50-438.83/05/16.8305200519
- 8305230545 Second interim rept re generic deficiencies at Consolidated Controls Corp Initially reported an 820716 Evaluation indicates GC problems corrected & equipment failures random Also reported per Part 21 Next rept by 831117 MILLB.L M Tennessee Valley Authority 83/05/18 O'REILLY, J P Region 2. Defice of Director 2pp 18537 085 24X Fiche 50-438,83/05/18,8305230545
- 8305230551 Third interim deficiency rept re lack of environ qualification for equipment in auxiliary bldg due to potential failure of startup & retriculation sys Initially reported on 820422 Design work ongoing Next rept by 840217 MILLE.L M Tennessee Valley Authority 83/05/18 O'REILLY.J P Region 2, Office of Director 2pp 18537 333 24% Fichs 50-438,83/05/18,8305230551
- 8305230365 Final deficiency rept re use of unqualified TVA-designed fillet welds on piping lugs Initially reported on 820819 Calculation package for lugs complete Procedures for dasigning fillet-welded lugs incorporated MILLS.L M Tennessee Valley Authority 83/05/18 0'REILLY,J P Region 2. Office of Director 2pp 18537 092 24X Fiche 50-438,83/05/18,8305230565
- 8305310138 Seventh interim deficiency rept re inconsistency between assumptions for pips break in LOCA & structural analyses for connecting pipss in affectsed loop Initially reported on 301121, Next rept by 831118 Also reported per Part 21 HILLS, L. M. Tennesses Valley Authority 83/05/23 O'REILLY, J. P. Region 2, Office of Director 2pp 18656 125 24X Fiche 50-438,83/05/23,8305310138
- 8305310193 First interim deficiency rept re power cable bend radii in vertical to horizontal trays Initially reported on 830422 Vandor assistance will be requested to determine min acceptable bend radius MILLB.L M Tennessee Valley Authority 83/05/23 O'REILLY, J P Region 2, Office of Director 2pp 18651 004 24X Fiche: 50-438.83/05/23,8305310193
- 8309310214 Eighth interim deficiency rept re 8&W nonconservative analysis of neutron flux Initially reported on 801105 Also reportable per Part 21 Util awaiting results of 8&W analysis. Next rept will be submitted by 831024 MILLS.L M Tennessee Valley Authority 83/05/23 O'REILLY.J P Region 2. Office of Director 2pp 18658 146 24X Fiche. 50-438.83/05/23.8305310214

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8303280059 Forwards seismic qualification & pump valve operability info.per B30203 request Repts on floor response spectra, seismic summary listing, revised FVORT & seismic qualification review team forms included EDELMAN.MR Cleveland Electric Illuminating Co 83/03/16 YOUNDBLOOD, B J Licensing Branch i 1.704pp 17701 001 24X Ficher 50-440,83/03/16,8303280059
- 8303040289 Advises that effective 830418, JJ Stefano designated Licensing Review Oroup II program project manager Change will help expedite reviews on disposition of remaining generic issues NOVAK, T M Assistant Director for Licensing. 83/04/26, HGLTISCHER, D L. Illinois Power Co. 2pp. 18326-343 24X Fiche: 50-000, 83/04/26, 8305040289
- 830519009A Advises of NRC evaluation findings of automatic depressurization sys logic mod options in response to TMI Action Item II K.3 18 Util should advise NRC of which action will be implemented & furnish necessary design & info YOUNOBLOOD. B. J. Licensing Branch 1 83/04/27 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 194 24X Fiche 50-440,83/04/27,8305190096

- 8303090277 Forwards Board Notification (BN) 83-58 previously transmitted as BN 83-13 forwarding EG&G draft rept.
 "Identification & Ranking of Nuclear Plant Structures, Bys & Components & Graded GA Guidelines" W/o BN 83-58 NDVAK.T M Assistant Director for Licensing 83/05/02 Atomic Safety and Licensing Board Panel 6pp 18366 275 24X Fiche 50-440.83/05/02,8305090277
- 8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 DL applicants EISENHUT.D G Division of Licensing B3/03/03 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 18523 198 24X Fiche 50-000.83/03/03,8305190046
- --B305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 CL applicants EISENHUT.D 0 Division of Licensing B3/05/03 HALE.D P Illinois Power Co 2pp 18523 200 24% Fiche 50-000,83/05/03,8305190046
- --8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving Issues generic to BWR/6 DL applicants EISENHUT.D G Division of Licensing 83/05/03 FEROUSON,M R Washington Public Power Supply 8ystem 2pp 18323 202 24X Fiche 50-000,83/05/03,8305190046
- --B305190068 Commends representatives of BWR/4 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT, D Q Division of Licensing 83/05/03 MCGAUGHY, J P Mississippi Power & Light Co 2pp 18523 204 24X Fiche 50-000,83/05/03,8305190046
- --8305190077 Commends representatives of BWR/A utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/A OL applicants
 EISENHUT, D Q Division of Licensing 83/05/03 CAHILL, J Gulf States Utslities Co 2pp 18523 206 24X Fiche 50-000, 83/05/03, 8305190046
- B305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & B3-44 re Unresolved Safety Issue A-17
 EISENHUT, D G Division of Licensing 83/05/04 PALLADING, N Commissioners 22pp 18337 139 24X Fichs 50-000.83/05/04.8305040323
- 8305090699 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D G Division of Licensing B3/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 30-000,83/03/09,8305090659
- 8305230143 Responds to 821214 & 830401 requests for add1 info re safety relief valve piping & quencher device & safety-related piping supports Info will be provided 830430 for Questions 210 10 & 210 ii & 840430 for Question 210 9 EDELMAN.M R Cleveland Electric Illuminating Co 83/05/16 YQU/081000.B J Licensing Branch 1 ip 18539 187 24X Fiche 50-440.83/05/16.8305230143
- B305250189 Notification of B30526 meeting w/util & Gilbert Assocs in Bethesds,MD to discuss design for containment purge STEFAND,J J Licensing Branch i B3/05/16 YOUNGBLOOD,B J Licensing Branch i 3pp 16395 359 24X Fichs 50-440.83/05/16.
- B303230270 Forwards addl info re environ equipment qualification program & plant readiness for audit, in response to 830323 Questions 270 1-270 i3 Safety-related equipment, per TMI Items II 0.3 & II F i, will be added prior to fuel load EDELMAN, M R Cleveland Electric Illuminating Co 93/05/17. YOUNGBLODD, B J Licensing Branch 1 23Bpp 18529 001 24X Fiche 50-440.83/05/17,8305230390
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B304060126 NUS-4336: "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations" HILKENSON NUS Corp B3/04/30 44pp 17858 021 24X Fiche 30-440.83/04/04,8304060118.
- B305040664 Forwards Suppl 3 to SER (NUREO-0B97).W/o encl YOUNOBLOOD, B J Licensing Branch 1 B3/04/27 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18336 266 24X Fiche 50-440, B3/04/27, B305040664

- 8305170096 SAFETY EVALUATION REPORT RELATED TO OPERATION OF THE PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company) e Office of Nuclear Reactor Regulation, Director Nure0-0807 503 83/04/30 75p 18492 303 24X Fiche 50-440,83/04/30,8305170096
- 8305120460 Requests into re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO.J J Licensing Dranch I 83/05/02 HOLT25CHER.D L Illinois Power Cp 2pp 18443 173 24X Fiche 50~000.83/05/02.
- --8305120470 Requests info re issue solutions accepted by NRC which have to have not been addressed in SER/supplemental SERs. Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO. J J Licensing Branch i 83/05/02 POWELL, P Washington Public Power Supply System ip. 18443 174 24X
 Fiche 50-000,83/05/02,8305120460
- --B305120477 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO, J. J. Licensing Branch 1 83/05/02 REED, N. J. Quif States Utilities Co. 1p 18443 175 24X Fiche 50-000, 83/05/02, 8303120440
- --8305120485 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO.J J. Licensing Branch 1 83/05/02 RICHARDSON.J D. Mississippi Power & Light Co ip 18443 176. 24X Fiche 30-000.83/05/02.8305120460
- --8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO.J J. Licensing Branch I 83/05/02 BUZZELLI.E M
 Cleveland Electric Illuminating Co Ip 18443 177 24X
 Fiche 30-000.B3/03/02.8305120460
- B305110300 Forwards response to Human Factors B21112 in-progress audit rept re BER Outstanding Issue 7, control room design review EDELMAN.H R Cleyeland Electric Illuminating Co 83/05/04 YOUNOBLOOD.B.J Licensing Branch I 21pp 18393 312 24X Fiche 50-440.83/05/04.8308110300
- 8303230649 Forwards request for add1 info re SER Section i3 5 2 2. "Reanalysis of Transients & Accidents Development of Emergency Operating Procedures " Schedule requested within 7 days of receipt of 1tr.
 YOUNOBLOOD. B J. Licensing Branch I 83/05/06 EDELMAN, M. R Cleveland Electric Illuminating Co 6pp 18542:354 24X Fichs 50-440, 83/05/06, 8305230649
- 8305230645 Forward: NUREQ-0887; Suppl 3 to SER W/o encl YOUNGBLOOD, B J Licensing Branch 1 83/05/07. EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18542 360. 24X Fiche 50-440,83/05/07:8305230645
- 8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re SER Outstanding Issue 19 Curves dependent on amount of fuel inventory released Revised response to Round 2 Guestion 1 2 submitted on 830404. EDELMAN.M R Cleveland Electric Illuminating Co 83/05/13 YOUNOBLOOD,B J. Licensing Branch 1 4pp 18539 188. 24X Fiche 50-440.83/05/13,8305230106.
- 8303240267 Forwards response to 830307 request for clarifications & addl info re FSAR Table 3 2-1 Suppl 3 to SER issued in Apr referenced same questions as outstanding Issue 23. Info should resolve Outstanding Issue 23 in next SER suppl, EDELMAN.H R Cleveland Electric Illuminating Co 83/05/19. YOUNDBLOOD,B J Licensing Branch 1. Ifpp 18626 200 24X Ficha 50-440.83/05/19.8305260267
- F. Security, medical, emergency & fire protection plans
- B303230649 Forwards request for add1 info re BER Section 13,5 2.2. "Reanalysis of Transients & Accidents.Development of Emergency Deresting Procedures." Schedule requested within 7 days of receipt of itr YOUNOBLOOD.B. J. Licensing Branch 1 83/05/06 EDELMAN, M.R. Cleveland Electric Illuminating Co. dpp 18542-354, 24X Fiche.30-440.83/05/06.B309230649

- 8305110034 Generic Ltr 83-21 to all licenses of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT. D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fich 50~000.83/05/11.8305110034
- 8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re BER Outstanding Issue 19 Curves dependent on amount of fuel inventory released Revised response to Round 2 Question I 2 submitted on 830404 EDELMAN M R Cleveland Electric Illuminating Co 83/05/13 YOUNDBLOOD, B. J. Licensing Branch 1 4pp 18539 188 24X Fichs 50-440,83/05/13,8305230106
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS:W J Office of the Executive Director for Operations, 83/05/13 PALLADING,N J Commissioners 5pp 18593 322 24% Fich

O Adjudicatory correspondence

- B305020470 Answer opposing Ohio Citizens for Responsible Energy B30418 motion to hold record open on QA issue Motion based on mere speculation that intervenor witnesses may become evailable Certificate of Svc encl
 SILBERO, J E Commonwealth Edison Co SILBERO, J E Shaw, Pittman, Potts & Troubridge B3/04/27 Atomic Safety and Licensing Board Panel 7pp 18283 300 24% Fiche 50-440,83/04/27,8305020470
- 8303040528 Motion for summary disposition of DL application on grounds of matl false statement in amend to environ rept Certificate of Svc encl Related correspondence HIATT.S L. Ohio Citizens for Responsible Energy 83/04/28. Atomic Safety and Licensing Board Fanel 18pp 18321.217 24% Fiche 50-440,83/04/28,8305040528
- 8303040541 Motion to stay proceeding pending ruling on OH Citizens for Responsible Energy 830428 motion for summary disposition of OL application Certificate of Svc encl Related correspondence HIATT, 8 L. Ohio Citizens for Responsible Energy 83/04/28, Atomic Sefety and Licensing Board Panel, 3pp 18321, 276 24X Fiche, 50-440, 83/04/28, 8303040541
- 8305040544 Response opposing unmeritable motion for reconsideration by clarification of ASLB 830330 memorandum & order granting NRC motion for summary disposition of Issue 9 on polymer degradation W/Certificate of Svc Related correspondence HIATT,S L Ohio Citizene for Responsible Energy 83/04/28 Atomic Safety and Licensing Board Panel 4pp 18321-272 24X Fiche 50-440,83/04/28,8305040544
- 8305020477 Answer opposing Ohio Citizens for Responsible Energy 830418 motion to hold record open on QA issue Motion premature & grounded on sheer speculation Cartificate of Svc encl CUTCHIN.J M Hearing Brench 4 83/04/29 Atomic Safety and Licensing Board Panel 4pp 18282 359 24X Fiche.50-440,83/04/29-8305020477
- B305040325 Brief supporting Ohio Citizens for Responsible Energy motion to hold record open on GA issue Applicant is moving back const completion date of own volition MILT.D D Sunflower Alifance B3/04/27 Atomic Safety and Licensing Board Panel. 2pp 18323-293 24X Fiche 50-440, 83/04/29, 8305040325
- 8305040487 Application for subposes directed to CM Shuster.of util & to J Keppler.NRC Region III administrator Proof of Svc encl. WILT, D D. Sunflower Alliance WILT, D D Wilt, D, D 83/04/29. Atomic Safety and Licensing Board Panel 3pp 18319.270 24X Fiche.50~440.83/04/29.8305040487
- 830504054B Request for NRC & util to stipulate to authenticity of documents to be identified by 830518 & request to admit documents as evidence Proof of Bvc encl HILT, D D Sunflower Alliance HILT, D D Hilt, D D 83/04/29. Atomic Safety and Licensing Board Panel. Ip 18321 271 24X Fiche 50-440,83/04/29,8305040548
- 8305040307 Response opposing Bunflower Alliance, Inc. et al 830427 action which requests applicant to stipulate to authenticity of unidentified documents & requests admission of documents as evidence Centificate of Evc encl
 BILBERG, J.E. Cleveland Electric Illuminating Co. BILBERG, J.E. Shaw, Pittman, Potts & Troubridge 83/05/02, Atomic Bafety and Licensing Board Panel 3pp. 18323, 303, 24X Fiche: 50-440, 83/05/02, 8305040307

- 8305090487 Informs ASLB that requested documents re matters mentioned in NRC prefiled testimony on Issue 3 will be provided CE Norelius 820910 ltr re special const insp forwarded GA insprest forthcoming Evaluation encl CUTCHIN.J M Hearing Branch 4 83/05/06 BLOCH,P B, BRIGHT,G D, KLINE,J R Atomic Safety and Licensing Board Panel 2pp 18361 153 24X Fiche 50-440,83/05/06.8305090487
- --8305090490 Forwards "Belf-Initiated Evaluation," assessing project & committing to maintaining highest quality stds
 EDELMAN, M R Cleveland Electric Illuminating Co 82/12/07
 KEPPLER, J G Region 3, Office of Director ip 18361 156 24X
 Ficha 50-440,83/05/06.8305090487
- ---8305090493 "Belf-Initiated Evaluation"

 * Cleveland Electric Illuminating Co 82/10/31 213pp 18361 157 24X Fichs 50-440, 83/05/06, 83050990487
- 8303100294 Amended application for subpeona directing attendance of CM Shuster & JO Keppler at 830503 hearings on Issue 3 re nonconformance trand analysis sys Proof of Svc encl WILT.D.D Bunflower Alliance WILT.D.D Wilt. D.D 83/05/06 SHUSTER.C M Cleveland Electric Illuminating Co KEPPLER.J 9 Region 3, OPFice of Director 3pp 18370 139 24X Fiche 50-440,83/05/06,8305100294
- 8305100367 Brief in support of Ohio Citizons for Responsible Energy B30428 Motion for summary disposition of OL application & motion for stay of proceedings Appropriate sanctions should be imposed on applicant Proof of Svc encl WILT.D D Sunflower Alliance WILT.D D Wilt, D D 63/05/06 Atomic Safety and Licensing Board Panel 7pp 18379 042 24% Fiche 50-440,83/05/06,8305100367
- B305160156 Requests to make limited appearance statement at OL hearings RCCLUSKEY, a Affiliation Unknown 83/05/08 NRC No Detailed Affiliation Given ip 18446-086 24X Fiche 50-440,83/05/08,8305160156
- 8305100169 Forwards SER, Suppl 3 (NUREO-0887) W/o enci CUTCHIN.J M Hearing Branch 4 83/05/08 BLOCH.P B , BRIGHT, G D., KLINE, J R. Atomic Safety and Licensing Board Panel ip 18374 273 24X Fichs 50-440, 83/05/09, 8305100168
- 8305120304 Requests to make limited appearance statement at 830523 OL hearings RENNER, A E Affiliation Unknown 83/05/07 NRC No Datailed Affiliation Given ip 18424 206 24X Fiche 50-440,83/05/07,8305120304
- 8305160122 Requests to make limited appearance statement at DL hearings CDOK: 9 S Affiliation Unknown 83/05/10 NRC No Detailed Affiliation Given ip 18450 130 24X Fiche 50-440,83/05/10,83005160122.
- 8305160153 Requests to make limited appearance statement at GL hearings. QLEIBERNA Affiliation Unknown 83/05/10 NRC - No Detailed Affiliation Given 1p. 18446-087 24X Fiche 50-440.83/05/10, 8205160183
- 8305170305 Objects to characterization of Ohio Citizens for Responsible Energy members as persons advocating disruption, demonstration & disrespect for law, as stated in Sunflower Alliance 830506 brief in support of motion HIATT, 8 L. Ohio Citizens for Responsible Energy 83/05/10 HIATT, D. Wilt, D.D. 1p 18465-075. 24X Fiche-50-440,83/05/10,8305170305
- 8305170341 Motion to file contentions objecting to BNM license issuence unless & until OL granted & facility ready to load fuel Certificate of 8vc encl.
 HIATT.S.L. Ohio Citizens for Responsible Energy 83/05/10
 Atomic Bafety and Licensing Board Panel. 2ipp 18465 076. 24X
 Fiche: 30-440,83/05/10.8305170341.
- B305170457 Requests opportunity for staff member to make limited appearance statement at B30523 hearing ECKART.D.E. House of Rep B3/05/11 STUCKY,B Office of the Becretary of the Commission 1p. 18470 141. 24X Fiche. 50-440
- 8305170461 Requests to make limited appearance statement at 830523 & 31 hearings in Painesville MALDDRF.E.J Affiliation Unknown. 83/05/11 Office of the Secretary of the Commission ip 18469-318 24X Fiche 50-440.83/05/11,8305170461

- 8305170464 Requests to make limited appearance statement at DL hearings
 BIMBER,R M Affiliation Unknown 83/05/12 NRC No Detailed Affiliation Given ip 18469 361 24X Fiche 50-440,83/05/12, 8305170444
- B305170452 Requests to make limited appearance statement at CL hearings RAJKI/S Affiliation Unknown B3/05/13 Docketing & Bervices Branch 1p 18469 207 24X Fiche 50-440, B3/05/13, B305170452
- 8305190207 Package of seven requests to make limited appearance statement at DL hearings GAGE, J. HUBBARD, K. S. GREENDAUM, R. L. Affiliation Unknown 83/05/13 NRC - No Detailed Affiliation Given 7pp 18302 188 24X Fiche 50-440.83/05/13.8305190207
- 8305190214 Requests to make limited appearance statement at DL hearings RUDD, C C Affiliation Unknown 83/05/14 NRC No Datailed Affiliation Given ip 18502 237 24X Fiche 50-440,83/05/14,8305190214
- 8305240512 Requests to make limited appearance statement at DL hearings
 O'NEILL,K Affiliation Unknown 83/05/15 NRC No Detailed Affiliation Given 1p 18571 109 24X Fiche 50~440,83/05/15,8305240512
- 8305200656 Requests to make limited appearance statement at OL.
 hearings
 ZIVKOVICH,E A , HANDBOY,L . WARCLOUD, J Affiliation Unknown
 83/05/17 Office of the Secretary of the Commission App
 18519 312 24X Fiche 50-440,83/05/17,8305200656
- 8305200598 Requests to make limited appearance statement at OL hearings DEVINE.A.: THOMPSON,D.: MAST,L. Affiliation Unknown 83/05/19 Docketing & Services Branch 2pp 18514 104 24X Fiche 50-440,83/05/19,8305200598
- B305240515 Update to util B30205 answer to Interrogatory 3 of Sunflower Alilance B11202 first set of interrogatories Ali three counties have submitted draft plans to Chio Disaster Bycs Agency Syc list encl Related correspondence BMIGER.M A Shaw, Pittman, Potts & Trowbridge SMIGER.M A Cleveland Electric Illuminating Co B3/05/19 MILT.D.D Synflower Alliance WILT.D D Wilt. D D 7pp 18571 125 24X Fichs 50-440,83/05/19,8305240515
- B305240944 Requests to make limited appearance statement at OL hearings
 FLAGO, D M , FINK. J , REED, J R Affiliation Unknown B3/05/19,
 Office of the Secretary of the Commission 3pp 18376 040 24X
 Fiche 50-440, B3/05/19, B305240544

H General correspondence

- 8305310031 Notifies that DD Wilt no longer represents Sunflower Ailtance, Inc due to irreconcilable differences & prof responsibility WILT.D 7 Wilt. D D 83/05/23 BLOCH.F. KLINE.J.R., BRIGHT.G O Atomic Safety and Licensing Board Panel 1p 18653 130 24x Fiche 50-440.83/05/23,8305310031
- G Inspection reports, IE Bulletins & correspondence
- B212060385 IR Info Notice B3-14, "Dewatered Spent Ion Exchange Resin Succeptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR. J M Division of SePaguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24% Fiche 50-000.83/03/21.8212060385
- 8304150362 Forwards IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted LITTLE, N S Region 3. Office of Director 83/04/01 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17782 127. 24X Fiche 50-440,83/04/01,8304150362
- --8304150364 IE Insp Repts 50~440/83-07 & 50~441/83-08 on 830314-17 No noncompliance noted Major areas inspected licensee actions on 10CFR50 55(e) items
 WARD.K D . CILIMBERG.R.L . DANIELSON,D H Region 3. Office of Director 83/04/01 9pp. 17982 131 24X Fiche.50~440.83/04/01,8304150362

- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator,"
- 103040021 IE info muces and Seve list encl Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- 0000400x3 IE INTO NOTICE COMMISSION OF Emergency Preparadness & Engineering
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 087 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 271 24X Fichs 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Betpoint Adjustment" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 93/04/28. Consolidated Edison Co. of New York, Inc. 118pp 19382 145 24X Fiche 30-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep deaft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl.

 NDVAK.T M Assistant Director for Licensing 83/05/03

 HOLTZSCHER.D L Licensing Review Group II. HOLTZSCHER.D L Illinois Power Co 6pp. 18440 354 24X Fiche 50-000,83/05/03.
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441-001 24x Fiche 50-000, B3/05/04, B303040031.
- 8305120130 Summary of 830426 meeting w/util in Perry,OH re containment weld deficiencies addressed in IE insp reps Acceptability study ongoing BTEFANG.J J Licensing Branch 1 B3/05/04 YOUNGBLOOD, B J Licensing Branch 1 3pp 18435 353 24X Fichs 50-440.83/05/04,
- #305170203 Advises that liquid penetrant testing utilized as alternative to magnetic testing on containment vessel penetration welds per IE Dullettin 80-08 response EDELMAN.M R Cleveland Electric Illuminating Co #3703/05 EPPLER.J O Region 3. Office of Director ip 18466 350 24x Fiche 30-440,83/03/03,8305170203
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Evo list encl UORDAN.E.L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305260236 Forwards IE insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 & notice of violation LITTLE; N 5 Region 3, Office of Director 83/05/09 EDELMAN, M R Cleveland Electric Illuminating Co 2pp. 18599 347 24X Fiche 50-440.83/05/09,8305260236
- -8305240239 Notice of violation from insp on 830328-0401 LITTLE:W 9 Region 3, Office of Director. 83/05/10 18599 349. 24% Fiche 50-440.83/05/09.8305260236.

.

- --8305260243 IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 Nancompliance noted turnover reviews of purchase orders & installation/fabrication packages performed w/o controlling procedure
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305260221 Forwards IE Insp Rept 50-440/83-07 on 830215-18 & 0414-15 No nancampliance noted
 STREETER, J F Region 3, Office of Director 83/05/12 EDELMANH A
 Cleveland Electric Illuminating Co 2pp 18622'120 24X
 Fiche 30-440.83/05/12,8305260221
- --8305260224 IE Insp Rept 50-440/83-07 on 830215-18 & 0414-15.No nancampliance noted Major areas inspected procedures for control of preoperational testing turnover controls & jurisdictional control of equipment REIMANN.FW, LANKSBURY.RD, REVES,LA Region 3, Office of Director 83/05/12 5pp 18622 122 24X Fiche 30-440,83/05/12,8305260221
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Progres" 30340404 It into Rette 30 511 Class Communication of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 OO7 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305020500 Second interim deficiency rept re linear indications on pipe whip restraint bracket welds for B21/B33 sys Initially reported on B21/28, Brackets will be removed & structural steel brackets reworked Next rept by B30701 EDELHAN.M R Cleveland Electric Illuminating Co B3/04/15, KEPPLER.J G Region 3, Defice of Director 2pp 18281 245 24% Fichs 50-440,83/04/15,8305020500
- 8305;30222 Part 2: rept re potential ASME Section III & V violation Initially reported on 8304:2 Scope & condition of nonconformance under investigation MHEATONN R Borg-Marner Corp 83/04/15 MARTIN, J B Region 5. Office of Director 4pp 18439 336 24X Fiche 50-440,83/04/15,820312022
- 830502030B Revised final deficiency rept re incomplete fill detected in biological whield wall concrete of reactor bldgs Due to const scheduling. Unit 1 & 2 repairs will be completed by 830831 & 1231 respectively EDELMAN H & Cleveland Electric Illuminating Co. 83/04/19. KEPPLER. J O Region 3, Office of Director ip 18277. 175. 24X Fiche 50-440.83/04/19.830502030B
- 8305040486 Interim deficiency rept re nonconforming condition on Class IE low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222 Welding fix planned for cubicie EF2C05 Final rept will be submitted by 831130 EDELMAN. M R Cieveland Electric Illuminating Co 83/04/27. KEPPLER. J G Region 3. Office of Director 2pp 18319 353 Fichs 50-440,83/04/27,8305040486 Q Co 83/04/27. 2pp 18319 353 24X
- 8305040496 Final deficiency rept re potential breach of seal integrity of hydrogen igniter Model 6043 glow plug component supplied by Fower Sys Initially reported on 830207 Igniters repaired. Also reportable per Part 21 EDELMAN.M R. Cleveland Electric Illuminating Co 83/04/27 KEPPLER.J G. Region 3, Defice of Director 2pp 18319:356 24X Fiche 50-440.83/04/27,8305040496.
- B305100394 Interim deficiency rept me failure of Johnson Controls, Int to adequately verify acceptability of Unistrut Corp GA program implementation Initially reported on B30329. Carrective action request & nonconformance rept issued. EDELMAN.M R Cleveland Electric Illuminating Co. B3/04/28. EDEPLERJ.O Region 3, Office of Director 2pp 18377 357. 24% Fiche: 50-440,83/04/28,8305100394

1

- 8305040465 Interim deficiency rept re incorrectly sized reactor pressure vpssel water level transmitters Replacement of transmitters expected by 830501 Final rept will be submitted upon work completion EDELMAN.M R Cleveland Electric Illuminating Co 83/04/29 KEFPLER.J G Region 3, Defice of Director ip 18319 355 24X Piche 50-440,83/04/29,8305040465
- B305100013 Second interim deficiency rept we defective Bailey 720 util station devices installed in GE supplied balance-of-plant panels. Initially reported B10626 Seventy of 71 devices returned to GE for rework Final rept due by B31201 EDELMAN, M R Cleveland Electric Illuminating Co B3/04/29 MEPPLER.J G Region 3, Office of Director 2pp 18421 244 24X Fiche 50-440,83/04/29,8305100013
- 8305100333 Becond interim deficiency rept re ASME Code Section III.
 Class 3 piping supports supplied by Transamerica Delaval.
 Inc w/o mat1 certification initially reported on 830325
 Supports reanalyzed Next rept by 830701
 EDELMAN.N R Cleveland Electric Illuminating Co 83/04/29
 KEPPLER,J G Region 3, Office of Director 2pp 18377 005 24X
 Fiche 50-440.83/04/29.8305100333
- 8305130234 Final Deficiency Rept RDC 71(83) re breakdown in GA program of Carboline.Co Initially reported on 830408 Program inadequate to meet requirement of iOCFR50.App B Carboline Co initiated new changes to GA program EDELMAN.M R Cleveland Electric Illuminating Co 83/05/06 KEPPLER.J C. Region 3, Office of Director 2pp 18439 318 24X Fiche 50-440.83/05/06.8305130236
- B305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LDCA Initially reported on 830407 Final rept expected by 830815 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 83/05/06 KEPPLER.J Q Region 3, Office of Director 2pp 18439 212 24X Fiche 50-440,83/05/06,8305130248
- T Hearing transcripts on non-antitrust matters
- B305030526 Forwards Region III testimony re GA issues of fact contained in ASLB B21222 order CUTCHIN.J.M Hearing Branch 4 83/05/02 BLDCH,P B , BRIGHT,O D , KLINE.J R Atomic Safety and Licensing Board Panel 1p 18292 117 24X Fiche: 50-440,83/05/02,8305030526
- --B305030537 Testimony of Region III panel consisting of JE Konklin, CC Williams, OF Maxwell & ML Olldner he GA issues of fact contained in ASLB B21222 order. Discusses constactivities & implementation of GA program W/prof qualifications KONKLIN, J. E., WILLIAMS, C. C., MAXMELL, QF Region 3, Office of Director 83/05/02 33pp 18272 118 24X Fiche 50-440, 83/05/02, 8305030526
- B305040506 Forwards testimony of MR Edelman & QR Leidich re QA program for control of safety-related contractors (Issue 3)
 STLBERG. J E , OLASBPIEGEL, H Bhaw, Pittman. Potts & Trowbridge
 03/05/02 BLOCH, P B , KLINE, J R , BRIGHT. O O Atomic Safety and
 Licensing Board Panel 2pp 18322-069 24X Fiche 50-440.83/05/02.
 8305040506
- --B305040516 Testimony of MR Edelman & GR Leidich re util GA program for control of safety-related contractors (Issue 3).
 EDELMAN.M R, LEIDICH.O R Cleveland Electric Illuminating Co
 B3/05/02 3Bpp 18322,071 24X Fiche 50-440,83/05/02.8305040506
- 8305110004 Transcript of 830509 telephone conference in Bethesda.MD Pp 805-883
 # Atomic Befety and Licensing Board Panel 83/05/09 78pp 18408 289
 24X Fiche 50-440.83/05/09.8305110004
- 8305260093 Transcript of 830523 hearing in Paine4ville, DH. Pp 884-994 Bupporting documentation encl 4 Atomic Safety and Licensing Board Panel. 83/05/23 128pp. 18622.182 24X Fiche 50-440.83/05/23.8305260093
- B305310137 Transcript of B30524 hearing in Painesville:OH Pp 996-1,226 Bupporting documentation encl + Atomic Bafety and Licensing Board Panel B3/05/24 272pp 18657:128 24X Fiche 50-440.83/05/24,8305310137

- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8303280099 Forwards seismic qualification & pump valve operability info.per 830203 request Repts on floor response spectra, seismic summary listing.revised PVORT & seismic qualification review team forms included EDELMAN.M R Cleveland Electric Illuminating Co 83/03/16 YOUNOBLOOD, B J Licensing Branch 1 1,704pp 17701 001 24% Fiche 50-440,83/03/16,8303280099
- 8305040289 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues

 NOVAK.T M Assistant Director for Licensing 83/04/26
 HOLTZGEHER.D L. Illinois Power Co 2pp 18326 343 24X

 Fiche 50-000, 83/04/26, 8305040289
- B305190096 Advises of NRC evaluation findings of automatic depressurization sys logic mod options in response to TMI Action Item II K 3 iB Util should advise NRC of which action will be implemented & furnish necessary design & info YGUNOBLCODD B J Licensing Branch i B3/04/27 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 18523 174 24X Fiche 50-440, B3/04/27, B305190096
- 8305090277 Forwards Board Notification (BN) 83-58 previously transmitted as BN 83-13, forwarding EG&G draft rept.
 "Identification & Hanking of Nuclear Plant Structures, 8ys & Components & Graded GA Guidelines " W/o BN 83-58
 NOVAK.Y M Assistant Director for Licensing 83/05/02 Atomic 84fety and Licensing Board Panel 6pp 18366 275 24X
 Fiche 50-440,83/05/02,8305090277
- 8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 QL applicants
 EISENHUT.D G Division of Licensing 83/05/03 EDELMAN.M R
 Claveland Electric Illuminating Co 2pp 18523 198 24X
 Fiche 50-000.83/05/03.8305190046
- --B305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 OL applicants EIBENHUT.D Q Division of Licensing 63/05/03 HALE.D P Illinois Power Co 2pp 18523 200 24X Fishe 50-000.83/05/03, B305170046
- ---8305190040 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 OL applicants EISENHUT.D Q Division of Licensing 83/05/02 FERGUSON,M R Washington Public Power Supply System 2pp 18523 202 24X Ficher 30-000, 83/05/03.8305190046
- --B305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EIBENHUT.D Q Division of Licensing 83/05/03 MCGAUCHY.J P Mississippi Power & Light Co 2pp 18323 204 24K Fiche 50-000.83/05/03,8305190046
- --8305190077 Commends representatives of BMR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 CL applicants EISENHUT, D O Division of Licensing 83/05/03 CAHILL, J Gulf States Utilities Co 2pp 18523 206 24X Fiche, 50-000, 83/05/03, 8305190046
- 8305040923 Board Notification 83-057 forwards differing prof opinions results interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D 0 Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,8305040323
- B305090699 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing B3/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fichs. 50-000, 83/05/09 305090659
- 8305230143 Responds to 821214 & 830401 requests for add1 info re safety relief valve piping & quencher device & safety-related piping supports Info will be provided 830630 for Questions 210 10 & 210 11 & 840630 for Question 210 9 EDELMAN.M R Cleveland Electric Illuminating Co. 83/05/16 YOUNDBLOOD, B J Licensing Dranch i ip 18539 187 24X Fiche 50-440,83/05/16,8305230143

- 8305250189 Notification of 830526 meeting w/util & Gilbert Assocs in Bethesda,MD to discuss design for containment purge STEFAND. J Licensing Branch 1 83/05/16 YOUNGBLOOD, B J Licensing Branch 1 3pp 18395 359 24X Fiche 50-440,83/05/16,8204350.89
- 8305230290 Forwards add1 info re environ equipment qualification program & plant readiness for audit in response to 830323 Guestions 270 i-270 i3 Safety-related equipment,per TMI Items II 0 3 & II F i, will be added prior to fuel load EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/05/17 YDUN0810DD, B.J. Licensing Branch i 239pp 18529 001 24% Fiche 50-440,83/05/17,8305230290
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305040664 Forwards Suppl 3 to SER (NUREG-0897) H/a encl YOUNDBLOOD.B J Licensing Branch I 83/04/27 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 18336 266 24X Fiche 30-440.83/04/27.8305040664
- B305170096 BAFETY EVALUATION REPORT RELATED 10 OPERATION OF THE PERRY NUCLEAR POWER PLANT, UNITE 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)

 * Office of Nuclear Resultor Regulation, Director NuREQ-0887 803. B3/04/30 75pp 18492 303 24X Ficha 50-440,83/04/30,8305170096
- 8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO.J J Licensing Brench 1 83/05/02 HOLTZSCHER, D L Illinois Power Co 2pp 18443 173 24X Fishs 50-000,83/05/02,0204120AAO
- --B305120970 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document avaluation on each Licensing Review Group II generic issue
 STEFANO. J Licensing Branch I 83/05/02 POHELL, P Hashington Public flower Supply System Ip 18443 174 24X
 Fiche 50-000.83/05/02.8303120460
- --8305120477 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND.J J Licensing Branch 1 83/05/02 REED, W J Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000, 83/05/02, 8305120460
- --8303120485 Requeste into re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND, J J Licensing Branch i 83/05/02 RICHARDSON, J D Mississippi Fower & Light Co 1p 18443-176 24X
 Fichs 50-000,83/05/02,8305120460
- --830512049] Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND. J Licensing Branch 1 B3/05/02 BUZZELLI.E M Cleveland Electric III winating Co 1p 18443 177, 24X fiche 50-000.83/05/02.8305120460
- 8305110300 Forwards response to Human Pactors 821112 in-progress audit rept re SER Outstanding Issue 7, control room design review EDELMANN M R Cleveland Electric Illuminating Co 83/05/04 YOUN08L0DU.B J Licensing Branch 1 21pp 18393 312. 24X Fiche 50-440.83/05/04.8305110300
- 8305230649 Forwards request for add1 info to SER Section 13 5 2 2.

 "Reanalysis of Yransients & Accidents Development of
 Emergency Operating Procedures "Schedula requested within
 7 days of receipt of itr
 YOUNGBLOOD, B J Licensing Branch 1 83/05/06 EDELMAN, M R.
 Cleveland Electric 111uminating co App 18542 354 24X
 Fiche 30-440,83/05/06.8305230649
- 8305230645 Forwards NUREO-0887, Suppl 3 to SER W/o encl YOUNGBLOOD, B J Licensing Branch 1 83/05/07 EDELMAN, M. R Claveland Electric Illuminating Co 3pp 18542 360 24X Fiche: 50-440, 83/05/09, 8305230645
- 8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re BER Outstanding Issue 19 Curves dependent on amount of fuel inventory released. Revised response to Round 2 Question I 2 submitted on 830404 EDELMAN.M R Cleveland Electric Illuminating Co 83/05/13/90UNGBLOOD, B J Licensing Branch 1. 4pp 18539 108 24) Fiche 50-440-83/05/13/8305230106

- 930526D267 Forwards response to 830307 request for clarification; 4 add1 info re FSAR Table 3 2-1 Suppl 3 to SER issued in Apr referenced same questions as outstending Issue 23 Info should resolve Gutstanding Issue 23 in next SER suppl EDELMAN.M R Cleveland Electric Illuminating Co B3/05/19, VOUNOBLOOD.B J Licensing Branch 1 lipp 18626 200 24X Fiche: 50-440,83/05/19,8305260267
- F Security, medical, emergency & fire protection plans
- 8304060124 NUS-4336, "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations " MILKENSON NUS Corp 83/04/30 44pp 17858; O21 24X Fiche 50-440:83/04/04.8304060118.
- 8305230649 Forwards request for add1 info re SER Section 13.5 2 2, "Reanalysis of Transients & Accidents Development of Emergency Operating Procedures " Schedule requested within 7 days of receipt of 1tr YOUNOBLOOD, B. J. Licensing Branch 1. B3/05/06 EDELMAN, M.R. Cleveland Electric Illuminating Co. 6pp 18542 354 24X Fichs 50-440,83/05/06,8305230649
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc 11st encl.
 EISENHUT.D 9 Division of Licensing, 83/05/11. Consolidated Edison Co of New York, Inc. 14pp. 18540-095 24X Ficher 50-000, 83/05/11, 8305110034
- B305230106 Forwards curves showing gamma dose rate vs time & instructions for use re BER Outstanding Issue 19. Curves dependent on amount of fuel inventory released Revised response to Round 2 Guestion I 2 submitted on B30404 EDELMAN M R Cleveland Electric Illuminating Co. 83/05/13 YUUN08LDOD.B J Licensing Branch 1 4pp 18539 188. 24x Fiche 50-440.83/05/13.8305230106

9 Adjudicatory correspondence

- 8305020470 Answer opposing Dhio Citizens for Responsible Energy 830418 motion to hold record open on GA issue Motion based on mere speculation that intervenor witnesses may become available. Certificate of Svc encl
 SILBERG, J. E. Commonwealth Edison Co. SILBERG, J. E. Bhaw, Pittsan. Potts & Trowbridge. 83/04/27. Atomic Safety and Licensing Board Panel 7pp 18283 300. 24X Fiche 50-440, 83/04/27, 8305020470.
- 8305040528 Motion for summary disposition of DL application on grounds of matl false statement in amend to environ rept Certificate of Svc encl Related correspondence.

 HIATT'R L Ohio Citizens for Responsible Energy 83/04/28

 Atomic Safety and Licensing Board Panel 18pp. 18321 217 24X

 Piche 30-440:83/04/28.8305040528
- B30504054i Motion to stay proceeding pending ruling on OH Citizens for Responsible Energy B30428 motion for summary disposition of OL application Certificate of Svc encl Related correspondence
 HIATT-8 L Ohio Citizens for Responsible Energy B3/04/28.
 Atomic Safety and Licensing Board Panel 3pp 18321 276 24X
 Fiche 50-440-83/04/28.8300040541
- 8305040544 Response upposing unmeritable motion for reconsideration & clerification of ASLB 830330 memorandum & order granting NRC motion for summary disposition of issue 9 on polymer degradation W/Certificate of Svc Related correspondence. HIATT.8 L Ohio Citizens for Responsible Energy 83/04/28. Atomic Safety and Licensing Board Penel 4pp. 18321 272 24X Fiche 50-440,83/04/28,8305040544
- 8305020477 Answer opposing Dhio Citizens for Responsible Energy 830418 motion to hold record open on GA issue Motion premature & grounded on sheer speculation Certificate of Svc encl. CUTCHIN. J. M Hearing Branch 4 83/04/27 Atomic Safety and Licensing Board Panel. 4pp 18282 359. 24X Fiche 50-440, 83/04/278 8305020477
- 8305040325 Brief supporting Ohio Citizens for Responsible Energy motion to hold record open on GA issue. Applicant is moving back const completion date of own volition HILT, D.D. Sunflower Alliance, 83/04/29. Atomic Safety and Licensing Board Panel 2pp. 18323 293 24X Fiche 50-440,83/04/29,8305040325
- B305040407 Application for subposess directed to CM Shuster of util to J Kappler, NRC Region III administrator Proof of Svc encl WILT, D.D. Sunflower Alliance WILT, D.D. Wilt, D.D. B3/04/29. Atomic Safety and Licensing Board Panel Spp. 18317: 270 24X Fiche 50-440, 83/04/29, 8305040487

- 830504054B Request for NRC & util to etipulate to authenticity of documents to be identified by 83051B & request to admit documents as evidence Proof of Svc enci HILT.D D Sunflower Alliance WILT.D D Wilt. D D 83/04/29 Atomic Sefety and Licensing Board Panel 1p 18321 271 24X Fiche 50-440.83/04/27.830304054B
- 8305040307 Response opposing Sunflower Alliance. Inc. et al 830429 motion which requests applicant to stipulate to authenticity of unidentified documents & requests admission of documents as evidence. Certificate of Svc encl
 BILBERG. J. E. Claveland Electric Illuminating Co SILBERG. J E. Rhaw. Pittman. Potts & Troubridge 83/05/02 Atomic Safety and Licensing Board Panel 3pp 18323 303 24X Fiche 50-440.83/05/02.
- 8305090487 Informs ABLB that requested documents re matters mentioned in NRC prefiled testimony on Issue 3 will be provided CE Norwius 820910 itr re special const insp forwarded GA insp rept forthcoming Evaluation encl CUTCHIN.J M Hearing Branch 4 83/05/06 BLOCH.P B , BRIGHT, 9 O , KLINE, J R Atomic Bafety and Licensing Board Panel 2pp, 18361.153 24X Fiche 50-440,83/05/06.8305090487
- --8305090490 Forwards "Belf-Initiated Evaluation," assessing project & committing to maintaining highest quality stds
 EDELMAN,M.R. Cleveland Electric Illuminating Co 82/12/07
 KEPPLER.J 9 Region 3, Office of Director 19 18361,156 24X
 Ficha 50-440,83/05/06,8305090487
- --8305090493 "Self-Initiated Evaluation "
 # Cleveland Electric Illuminating Co 82/10/31, 213pp.
 18361 157. 24X Fiche: 50-440, 83/05/06, 8305090487
- 8303100294 Amended application for subpeona directing attendance of CM Shuster & JG Keppler at 830503 hearings on Issue 3 renonconformance trend analysis sys Proof of Svc snc1 MILT.D D. Sunflower Alliance WILT.D D Wilt. D D 83/05/06 SHUSTER, C M Cleveland Elactric Illuminating Co KEPPLER, J G Ragion 3. Office of Director 3pp 18370 139 24% Fiche: 50-440, 83/05/06, 8305100294
- 8305100367 Brisf in support of Chio Citizens for Responsible Energy B30428 motion for summary disposition of DL application & motion for stay of proceedings Appropriate sanctions should to imposed on applicant.Proof of Bvc encl HILT.D D Bunflower Alliance, WILT.D D Wilt, D D 83/05/06, Atomic Bafety and Licensing Board Panel, 7pp 18379.042 24X Fiche.50~440,83/05/06,8305100367
- B305160156 Requests to make limited appearance statement at OL hearings MCCLUSKEY, O Affiliation Unknown B3/05/08, NRC ~ No Detailed Affiliation Given ip 18446.086 247 Fiche: 50-440.83/05/08, B305160136
- 8305100168 Forwards 8ER, Suppl 3 (NUREO-0887). H/o encl CUTCHIN.J M Hearing Branch 4 83/05/08 BLOCK: P B., BRIGHT, Q D., KLINE, J R Atomic Safety and Licensing Board Panel. 1p 18374 273 24X Fiche 50-440, 83/05/09, 8305100168
- B305120304 Requests to make limited appearance statement at B30523 GL hearings RENNER, A E Affiliation Unknown B3/05/09 NRC No Detailed Affiliation Given 1p 18424 206 24X Fiche 50-440,83/05/09, B305120304
- B305160122 Requests to make limited appearance statement at OL hearings CDOK, 0 B Affiliation Unknown 83/05/10 NRC No Detailed Affiliation Given 1p 18450 130, 24X Fiche 50-440,83/05/10,8305160122
- 8305160153 Requests to make limited appearance statement at DL hearings OLEIBSEN.A. Affiliation Unknown B3/05/10, NRC No Detailed Affiliation Given, 1p. 18446 OB7 24X Fiche: 50-440, B3/05/10, B3/05160153
- 8305170305 Objects to characterization of Ohio Citizens for Responsible Energy members as persons advocating disruption, demonstration is disrespect for law, as stated in Sunflower Alliance 830506 brief in support of motion.

 HIATT: B L. Ohio Citizens for Responsible Energy 83/05/10, HILT.D D Wilt, D.D 1p. 18465,075 24X Fiche 50-440,83/05/10, 8305170305
- 8305170341 Motion to file contentions, objecting to SNM license issuance unless & until DL granted & facility ready to load fuel Certificate of Svc encl HIATT, S. L. Ohio Citizens for Responsible Energy. 83/05/10. Atomic Safety and Licensing Board Panel. 21pp 18465,096 24X Fiche 50-440,83/05/10,8305170341.

- 8305170457 Requests opportunity for staff member to make limited appearance statement at 830523 hearing ECKART, DE House of Rep. 83705/11 STUCKY, S. Office of the Secretary of the Commission ip 18470 141 24X Fiche 50-440
- 8305170461 Requests to make limited appearance statement at 830523 & 31 hearings in Painesville WALDORF.E J Affiliation Unknown 83/09/11 Office of the Becretary of the Commission 10 18469 318 24X Fiche 50-440.83/05/11.8305170461
- 8305170464 Requests to make limited appearance statement at OL hearings
 BIMBER, R M Affiliation Uninown 83/05/12 NRC No Detailed Affiliation Given Lp 18467 361 24% Fiche 50-440,83/05/12,
- B305170452 Requests to make limited appearance statement at OL hearings
 RAJKI,S Affiliation Unknown 83/05/13 Docketing & Services
 Branch lp 18469 207 24X Fiche 50-440,83/05/13,8305170452
- 8305190214 Requests to make limited appearance statement at DL hearings RUDD.C C Affiliation Unknown 83/05/14 NRG No Detailed Affiliation Given ip 18502 237 24X Fiche 50-440,83/05/14,8305190214
- B305240512 Requests to make limited appearance statement at OL hearings
 O'NEILL, K Affiliation Unknown B3/05/15 NRC No Detailed Affiliation Given ip 18571 107 24X Fiche. 50~440, B3/05/15,
- B303200656 Requests to make limited appearance statement at OL hearings
 ZIVKOVICH.E A , HANDBOY,L , WARCLOUD, J Affiliation Unknown
 83/05/17 Office of the Secretary of the Commission 6pp
 18319 312 24X Fiche 30-440,B3/05/17,8305200656
- 830520039B Requests to make limited appearance statement at DL hearings DEVING.A , THOMPSON,D , MAST.L Affiliation Unknown 83/05/19 Docketing & Services Branch 2pp 18514 104 24X Fiche 50-440.83/05/19,8305200598
- B305240315 Update to util B30205 answer to Interrogatory 3 of Sunflower Alliance B11202 first set of interrogatories All three counties have submitted draft plans to Ohio Disaster Svcs Agency Svc list encl Related correspondence SWIGER, H A Shaw, Pittman, Potts & Trowbridge SWIGER, H A Cleveland Electric Illuminating Co B3/05/19 WILT, D D Sunflower Alliance WILT, D D Witt, D D 7pp 18571 125 24X Fiche 50-440,83/05/19,8305240515
- 8305240544 Requests to make limited appearance statement at OL hearings FLAGG.D M . FINK.J. REED.J R Affiliation Unknown 93/05/19 Office of the Secretary of the Commission 3pp 18576.040 24X Fiche 50-440,83/05/19,8305240544.
- H General correspondence
- 8305310031 Notifies that DD Wilt no longer represents Sunflower Alliance, Inc due to irreconcilable differences & prof responsibility WILT.D D Wilt. D D 83/05/23 BLOCH.P. KLINE.JR, BRIGHT.Q O Atomic Bafety and Licensing Board Panel ip 18653 130 24X Fiche 50-440,83/05/23,8305310031
- O Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list and! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319. 24X Fich - 50-000,83/03/21.8212060385
- 8304150362 Forwards IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted LITTLE, W 8 Region 3, Dffice of Director 83/04/01 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17982 129 24X Fiche 50-440,83/04/01,8304150362

- --8304150344 IE Imag Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted Major areas inspected licensee actions on 10CFR50 55(e) items WARD, K D, CILIMBERG, R L, DANIELSON, D H Region 3, Office of Director 83/04/01 9pp 17982 131 24% Fiche 50-440,83/04/01.
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 - 303040021 IE into Rotite 83-21, Celetaria Baraine Sec list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Int 126pp 18435 155 24X Fiche 50-000 83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
- 303040025 to 10.0 No. 10.0 No.
- 8303040025 IE Info Notice 83~23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 6303040026 IE Info Notice 63-24, "Loose Parts in Secondary Side of 2000-002A IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs " Suc list encl JORRAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New Yori, Inc. 113pp 18382 047 24X Fiche 50-000,83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Gys Heater High Temp Trip Setpoint Adjustment "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830)03) 83/04/28 Consolidated Edison Co of New York: Inc 1:8pp 18382 165 24% Fiche 50-000,83/04/20,8303040027
- B303040028 IE Info Notice B3-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 30-000,83/05/03.8303040028
- B305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NOVAN-T M Assistant Director for Licensing B3/05/03 HOLTZSCHER.D L Licensing Review Group II 6pp 18440 356 Fichs 50-000, B3/05/03, 8305120569 18440 356 24X
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 803063) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04,8303040030
- 830304003(IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list enci JORDAN.E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 CO1 24X Fiche 50-000,83/03/04,8303046031
- 8305120130 Summary of 830426 meeting w/util in Perry,OH re containment weld deficiencies addressed in IE insp reps Acceptability weto certifiencies addressed in IE insp reps Acceptability study ongoing
 BTEFAND.J J Licensing Branch 1 B3/05/04 YDUNGBLDOD.D J
 Licensing Branch | Spp 18435-353 24X Fiche 50-440,83/05/04,8305120130
- 8305170203 Advises that liquid penetrant testing utilized as alternative to magnetic testing an containment vessel penetration welds per IE Bulletin 80-08 response EBELMAN.M R Clevetand Electric Illuminating Co 83/05/05 KEPPLER, J O Region 3, Office of Director ip 18466.350 24X Fiche 50~440,83/05/05,8305170203
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Byo list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,89/05/06,8303040033.
- 8305260236 Forwards IE Insp Repts 50-440/83-11 & 50-441/83-10 on B30328-0401 & notice of violation LITLE.W S Region 3, Office of Director 83/05/09 EDELMAN,M R. Cleveland Electric Illuminating Co 2pp 16599 347 24X Fiche 30-440,83/05/09,8305260236

- --8305260243 IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-842 Noncompliance noted turnover reviews of purchase orders & Installation/fabrication packages performed w/o controlling Procedure
 MERRIWEATHER, N , CONLON. T E Region 2, Office of Director
 MERRIWEATHER, N , CONLON. T E 24X Fiche 50-440, 83/05/09, 03032473
- 8303040034 IE Info Notice 83-30. "Misapplication of Quartit Entril" Deterating Procedures (EOP) Quidalines " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co 45 Mayork, Inc 114pp 18524 003 24x Fiche 50-000,83/05/11,80334X3
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Pracesa" JOGOGODGO IE 1870 Notice 83-31, "Error in ADLPIPE Computer Prayers" Svc 1(st encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co s/R York: Inc 114pp 18697 009 24X Fiche 30-000.83/03/1/19.89334%(4
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Syc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co York, Inc 114pp 18647 007 24X Fiche 50-000 83/05/28,800 03) 83/05/26 Consolidated Edison Co #/ Pa 18647 007 24X Fiche 50-000, 83/03/26, 83030434 114pp
- 8 Reportable occurrences, LERs & related correspondence
- 8305070500 Becond interim deficiency rept re linear indications ess.3 whip restraint bracket welds for B21/B33 sys Initially reported on B21278 Brackets will be removed & structural steel brackets reworked Next rept by 830701 EDELMAN.H R Cleveland Electric Illuminating Co 87/04/15 KEPPLER.J Q Region 3. Office of Director 2pp 18281 243 311 Fichs 50-440,83/04/15,8305020500
- B305130222 Part 21 rept re potential ABME Bection III & V violalist Initially reported on B30412 Scope & condition of nonconformance under investigation WHEATON W R Borg-Harner Corp B3/04/15 MARTIN J B Rigles & Office of Director 4pp 18439 336 24X Fiche 50-440, B3/04/13. 8305130222
- 8305020308 Revised final deficiency rept re incomplete fill faththia biological shield wall concrete of reactor bldgs Bue to const scheduling. Unit i & 2 repairs will be completed by 830831 & 1231 respectively EDELMAN, M R. Cleveland Electric Illuminating Co 83/04/19, KEPPLER, J G Region 3, Office of Director 1p 18277-175 fill Fiche 30-440,83/04/19,8305020308
- 8303040486 Interim deficiency rept re nonconforming condition on Class IE low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222. Helding fix planned for cubicle EF2005 final rept will be submitted by 83100 EDELMAN, M R Cleveland Electric Illuminating Co 03/04/27. REPPLER, J G Region 3, Office of Director 2pp 18319 331 24 Fiche 30-440.63/04/27.8305040486.
- 8305040496 Final deficiency rept re-potential breach of seal inlights of hydrogen igniter Model 6043 glow plug component supplied by Power Bys Initially reported on 830207 Igniters repaired Also reporteable per Part 21 EDELMANIM R Cleveland Electric Illuminating Co 83/04/27 KEPPLER, J G Region 3, Office of Director 2pp 18319.3% 31 Fiche 30-440.83/04/27,8305040496
- 8305100374 Interim deficiency rept re failure of Johnson Controls. In to adequately verify acceptability of Unistrut Corp GA program implementation Initially reported on 830327 Corrective action request & nonconformance rept issued EDELMAN. M R Claveland Electric Illuminating Co 83/04/FB. KEPPLER. J O Region 3, Office of Director 2pp 18377 337 241 Fiche 30-440.83/04/28.8305100394
- 8305040465 Interim deficiency rept re incorrectly sized resitor pressure vessel water level transmitters Replacement of transmitters expected by 830501 Final rept will be submitted upon work completion
 EDELMAN, M R Cleveland Electric Illuminating Co 83/04/29
 KEPPLER, J G Region 3, Office of Director 1p 18319:335 241 Fiche 50-440, 83/04/29, 8305040465.
- 8305100013 Second interim deficiency rept re defective Bailey 720 while station devices installed in OE supplied balance-of-plant panels Initially reported 810626, Seventy of 71 devices returned to OE for rework. Final rept due by 831201 EDELMAN.N.R. Cleveland Electric Illuminating Co. 83/04/29. KEPPLER, J. O. Region 3. Office of Director. 2pp 1842; 244 Ficha 50-440, 83/04/29, 8305100013.

- B303100333 Second interim deficiency rept re ASME Code Section III.
 Class 3 piping supports supplied by Transamerica Delaval.
 Inc w/o matl certification Initially reported on B30325
 Supports reanalyzed Next rept by 830701
 EDELMAN,M R Cleveland Electric Illuminating Co B3/04/29
 KEPPLER.J 9 Region 3. Office of Director 2pp 18379 005 24)
 Fiche 30-440.83/04/29, 8305100333
- 8303130236 Final Deficiency Rept RDC 71(83) re breakdown in GA program of Carboline. Co Initially reported on 830408 Program inadequate to meet requirement of 10CFR50. App B Carboline Co initiated new changes to GA program EDELMAN. M R Cleveland Electric Illuminating Ca 83/05/06 KEPPLER, J G Region 3, Office of Director 2pp 18437 318 24X Fiche 50-440.83/05/06.8305130236
- 8305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LOCA Initially reported on 830407 Final rept expected by 830815 Also repurted per Pert 21 EDELMAN M R Cleveland Electric Illuminating Co 83/05/06 KEPPLER.J O Region 3, Office of Director 2pp 18439 212 24X Fiche 50-440,83/05/06,8305130248

T Hearing transcripts on non-antitrust matters

- B305030526 Forwards Region III testimony re GA issues of fact contained in ASLB 821222 order CUTCHIN.J.H Hearing Branch 4 83/05/02 BLOCH.P.B., BRIGHT.G O., KLINE, J.R. Atomic Safety and Licensing Board Panel ip 18292 117 24X Fiche 50~440,83/05/02.8305030526
- --8305030537 Testimony of Region III panel consisting of JE Konklin, CC Williams, OF Maxwell & ML Olldner re QA issues of fact contained in ASLB 821222 order Discusses const activities & implementation of QA program W/prof qualifications KONKLIN, JE, WILLIAMS, C.C., MAXWELL, Q.F. Region 3, Office of Director 83/05/02 33pp 18292 118. 24X Fiche 50-440, 83/05/02, 8305030536
- 8305040504 Forwards testimony of MR Edelman & GR Leidich re QA program for control of safety-related contractors (Issue 3) SILBERG.J.E. (QLASBPIEGEL.H Shaw, Pittman, Potts & Trombridge 83/05/02 BLOCH,PB. KLINE.JR. RRIGHT,Q D Atomic Safety and Licensing Board Panel 2pp 18322 067 24X Fiche 50-440,83/05/02,8305040506
- --8305040516 Testimony of MR Edelman & QR Leidich re util QA program for control of safety-related contractors (Issue 3) EDELMAN, M R. LEIDICH, Q R. Cleveland Electric Illuminating Co 83/05/02 38pp. 18322 071 24X Fiche 50-440.83/05/02,8305040506
- 8305110004 Transcript of 830509 telephone conference in Bethesda, MD Pp 805-8851 **
 * Atomic Sefety and Licensing Board Panel 83/05/09 78pp 18408 289. 24X Fiche 50-440, 83/05/09, 8305110004
- 8305260073 Transcript of 830523 hearing in Painesville, OH. Pp 884-994 844-994 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/23 128pp 18622. 182. 24X Fiche 50-440,83/05/23,8305260093
- 8305310137 Transcript of 830524 hearing in Painesville,OH Pp 976-1,226 Supporting documentation encl # Atomic Safety and Licensing Doard Panel, 83/05/24 272pp 18657,126. 24X Fiche 50-440,83/05/24,8305310137
- DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B305130335 Forwards ACRE B30419 ltr re review of application for OL, reporting on low power operation KNIOHTON, G W Licensing Brench 3 83/04/25 HARRISON, R. J. Public Service Co. of New Hampshire 3pp 18457, 328 24X Fiche
- --8303130339 Comments on lower power operation review of QL application Operation reasonably assured at core power levels up to 5% full power w/a undue risk to public health & safety EBERBOLE,J.C. ACRS Advisory Committee on Reactor Safeguards 83/04/19. PALLADINO,N J Commissioners 3pp. 18457.331 24% Fiche. 50-443,83/04/25,8305130335.
- 8305110016 Notification of 830511 meeting w/util in Bethesda, MD to discuss projected const completion date, WHEELER, L. L. Licensing Branch 3. 83/04/28 KNIGHTON, 9 W Licensing Branch 3 4pp 18421: 238 24X Fiche. 50-443, 83/04/28, 8305110016.

- B303040323 Board Notification 83-097 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
 EISENHUT.D 0 Division of Licensing 83/05/04 PALLADING.N Commissioners 22pp 18337 139 24X Fiche 50-000.83/05/04, p30-9040327
- B305130332 Requests description of environ qualification program including listed items Scope of submittal to include all electrical equipment important to safety located in harsh environ KNIGHTON O W Licensing Branch 3 83/05/05 HARRISON R J Public Service Co of New Hampshire 4pp 18457 334 24X Fiche 50~443.83/05/05.8305130332
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fiche 50-000.83/05/09.8305090659
- 8305270019 Requests extension of CP completion dates for Units 1 t 2 to June 1986 & Oct 1988, respectively, per Amend 40 to CPPR-135 & CPPR-136
 DEVINCENTIS, J Vankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18662 107 24X Fiche 30-443, 83/05/16, 8305270019
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- ## Division of Licensing | NUREG-0896 | S0/04/30 | S0/0
- 8305260038 Forwards Suppl 1 to SER re application for OL W/o encl KNIGHTON: 0 W Licensing Branch 3 83/05/12 HARRISON: R J Public Service Co of New Hampshire 4pp. 18649 088 24X Fiche 30-443.83/05/12.8305260038
- F Security, medical, emergency & fire protection plans
- 8303090523 FOIA request for add1 info re sarlier request on Pilgrim dtd 821105 concerning similar documentation for Seabrook facilities SHOTHELL, J.A. Massachusetts, Commonwealth of, 83/01/05, FELTON, J.H. Division of Rules and Rocords 2pp 18368 001 24X Fiche 50-443,83/01/05,8303090523
- 8305090527 Partial response to FOIA request for add1 info re 821105 request pertaining to facility. Forwards App A documents Documents also available in FDR App B documents completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records, \$3/03/10 SHOTHELL, J A Massachusetts, Commonwealth of, 5pp 18368 003 24X Fiche 50-449, 83/03/10, 8305090529
- --8203150073 Forwards branch review comments of facility emergency plan, performed against NUREO-0534 criteria Addl info & commitments required prior to acceptance PAOANG.F 0 EP Licensing Dranch 82/03/03 MIRAGLIA.F J Licensing Branch 3 20pp 18368 014 24X Fiche 50-443,83/03/10,8305070329
- --B20819007B Requests findings on prompt protective action decisionmaking in States of VT,NH & MA Bignificant problem may exist w/offsite preparedness in listed states "Site & Environ Interface." Chapter 2 encl.

 QRIMES.B K Division of Emergency Preparedness (Pre 830103)
 B2/04/27 KRIMM.R M Federal Emergency Management Agency 6pp 18368 034 24% Fiche 50-443,83/03/10.8305090529
- --9305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station" * HMM Associates, Inc. 83/03/10 56pp 18368 155 24X Fiche 50-443, 83/03/10, 8305090529
- B303030006 Forwards United Engineers & Constructors General Arrangemen'
 Drawing 9736-F-805062 re fire protection of primary
 component cooling water pumps, per util 830121 ltr W/o encl
 DEVINCENTIS, J Yantee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/05/02 KNIGHTON, 6 W. Licensing
 Branch 3 2pp 18337 083 24X Fiche 50-443,83/05/02.8305050006

- B305110034 Oeneric Ltr B3-21 to all licensees of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT.D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York. Inc 16pp 18540 095 24X Fiche 30-000, B3/05/11, B305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24) Fich
- Q Adjudicatory correspondence
- B305100356 Forwards responses to New England Coalition on Nuclear Poliution fourth-sirth eighth twelfth fourteenth & fifteenth motions for summary disposition
 LESSY, R P Hearing Branch 3 B3/03/21. HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Bafety and Licensing Board Panel 2pp
 18411 001 24X Fiche 50-443, B3/03/21, B305100356
- --B305100375 Response to twelfth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 1 NRC cannot agree or disagree w/statement of mati fact until receipt of preservice & inservice insp programs LEBSY.R P. PERLIS.R G. Hearing Branch 3 83/03/18 Atomic Bafety and Licensing Board Panel 28pp. 18411 003 24X Fiche 50-443,83/03/21,8305100356
- --8305100392 Response to fourteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) No genuine issue of math fact exists & NECNP entitled to favorable fecision PATTERSON, W.F., LESBY, R.P., Hearing Branch 3 83/03/10 Atomic Safety and Licensing Board Panel 5pp 18411 032 24X Fiche 50-443,83/03/21,8305100356
- --8305100400 Affidavit of RK Anand on New England Coalition on Nuclear Pollution Contention 1.0 3 Requirements of QDC 30 satisfied. AMAND.R K. Auxiliary Systems Branch. 83/03/18 App 18411 037 24X Fiche: 50~443,83/03/21,8305100354.
- --8305100411 Response to fifteenth motion for summary disposition of New England Comittion on Nuclear Pollution (NECNP) Contention I G No genuine issue of matl fact exists & NECNP entitled to favorable decision PATTERSON.W.F. LESSY,R P Hearing Branch 3 89/03/18. Atomic Safety and Licensing Board Panel App 18411 043, 24X Fithe 50-443.89/03/21.8305100356
- --9305100419 Affidavit of R9 LaGrange on util commitment to qualify wide-range pressure transmitters per NUREG-0588 requirements Commitment acceptable LAGRANGE.R 0 Equipment Qualification Branch 83/03/18 3pp 18411 047 24X Fiche-50-443.83/03/21.8305100356
- --B305100425 Response to fourth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention

 I Requirement to qualify path to cold shutdown not needed Contention must be dismissed
 PERLIS.R Q , LESBY.R P. Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 2pp 18411 050 24X
 Fiche 30-443.83/03/21,8305100356
- --B305100430 Response to sixth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention NH-13 No genuine issue of matl fact exists & NECNP entitled to favorable decision PATTERSON. H F. LESSY.R.P Hearing Branch 3 B3/03/18 Atomic Bafety and Licensing Board Panel 5pp. 18411 052, 24X Fithe 50-443.83/03/21.8305100356
- ---8305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREO-0737, Item I A 1 I requirements re shift technical advisor position Proposal acceptable WIGGINS, J T Division of Project & Resident Programs 83/03/17. 2pp 18411 057 24X Fiche 50-443.83/03/21,8305100356.
- --B305100432 Response to eighth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNF) Contention I A 2 No genuine issue of matl fact exists & NECNF entitled to favorable decision PATTERSON.W F. LESSY, R.P. Hearing Branch 3 83/03/18. Atomic Safety and Licensing Board Panel. 4pp 18411:059 24X Fithe 50-443,83/03/21,8305100335

- --8305100424 Affidavit of RO LaGrange on qualification of Class [E electric valve operators installed inside containment. Util committed to qualification per NUREO-0588 LAGRANGE. R G Equipment Qualification Branch 83/03/18, 3pp, 18411 044 24X Fiche 50-443,83/03/21.8305100356
- 8305100138 Forwards CY Liang. WT LeFave & SS Kirslis joint affidavit reviewing & commenting on Table I A 2-3 which includes listing of all electric valve operators inside containment, per ASLB request LESSY. R P Hearings Division PATTERSON. W F Office of the Executive Legal Director 83/04/20 HOYT. H, LUEBKE. E A, HARBOUR. J Atomic Safety and Licensing Board Panel 3pp 18374 252 24X Fiche 50-443,83/04/20,8308100138
- --8305100166 Affidavit of CY Liang.WT Lefave & 88 Kirslis providing results of NRC review of Table I A 2-3 concerning environ qualification of electric valve operators installed inside containment Prof qualifications encl
 LIANG.C Y Reactor Systems Branch LEFAVE,W T Auxiliary Systems Branch KRRSLIS,8 S Chemical Engineering Branch 83/04/19
 16974-255 24X Fiche 50-443,83/04/20.8305100159,
- 8305100219 forwards supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-B re Contention I A.2 in NRC 821228 response to first set of interrogatories Waffidavits re review of Table I A 2-3 LESSY, R P. Office of the Executive Legal Director 83/04/20, CURRAN, D. Harmon & Welss. 2pp. 18374 145 24X Fische 50-443,83/04/20,8305100219
- --8305100221 Supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I.A 2 in NRC 82128 response to first set of interrogatories Affidavits re Table I A.2-3 encl LESSY.R P , PATTERSON.W.F Diffice of the Executive Legal Director 82704/20 Atomic Safety and Licensing Soard Panel. 14pp. 18374 147 24X Fishe 50-443,83/04/20,8305100219
- 8305020425 Forwards Town of Seabrook request to participate as interested municipality Interests lie in areas of emergency planning insurance & accidents & precautionary evacuation. FELCH.F B , RANDALL.W I., FALCONER, J C Seabrook, NH. 83/04/22 HOYT.H F Atomic Bafety and Licensing Board Panel ip 18273 (% 24X Fiche 50-443, 83/04/22, 8305020425
- --8305020429 Request to participate as interested municipality per 10CFR2.715(c) PELCH.F D , RANDALL.W I , FALCONER.J C Seabrook, NH. 83/04/22 Atomic Sefety and Licensing Board Panel 1p 18273 197. 24% Fichs. 50-443, 83/04/22.8305020425
- 8305020482 Forwards Town of Exeter request to participate as interself municipality
 MUNICIPALITY
 MINICIPALITY
 MINICIPALITY
- ---8303020486 Request to participate as interested municipality per 10CFR2 715(c)
 CHICK, DE Exeter, NH. 83/04/24 Atomic Safety and Licensing Board Panel 1p 18282 297, 24X Ficher 50-443,83/04/26,
- 8305030541 Motion to reconsider ASLB 830425 memorandum & order in response to New England Coalition on Nuclear Pollution objection to B30414 conference call Complexity of issue justifies 20-day response period Certificate of 8vc encl. CURRAN.D. BISHOP.L.L. New England Coalition on Nuclear Pollution BISHOP.L.L. Harmon & Weiss. 83/04/29. Atomic Safety and Licensing Board Panel 5pp 18301.357. 24X Fiche.50-449.83/04/29.
- 8305030570 Order admitting Town of Exeter, NH as interested municipality Exeter must observe procedural requirements & take proceeding as found HOYT. H. F. Atomic Safety and Licensing Board Panel. 83/04/29. Exeter, NH 7pp 18306:110 24X Fiche 50-443,83/04/29,8305030370
- 8305040300 Response to New England Coalition on Nuclear Pollution motion to amend petition to intervene. Additionation should be denied on grounds of timeliness or partially denied on grounds of vaguaness Certificate of Svc sncl DIGNAN, T 9, GAD.R.K. Fublic Service Co of New Hampshire, DIGNAN, T 9 Ropes & Gray 83/04/29 Atomic Safety and Licensing Board Panel 16pp 18324 OD1 24X Ficher 50-443, 63/04/29, 83305040300.

- 9305040316 Response to Town of Seabrook, NH request to participate as interested municipality Emergency planning exercise & public insurance coverage issues may not be litigated in present proceeding Certificate of Svc encl
 DIONAN.T G . DIONANT G . Fiche, 50-443, 83/04/29, 8305040316
- 8305090501 Forwards request to participate as interested municipality proceedings
 proceedings
 QENT.A V Salisbury, MA 83/05/02 HOYT, H F Atomic Safety and
 censing Board Panel 2pp 18362 138 24X Fiche 50-443, 83/05/02, Licensing Board Panel 0305070501
- ~-8305090502 Request to participate as interested municipality in NOOVYCHOCK Request to participate as interested municipality in proceedings

 BARGENT.A V Balisbury, MA 83/05/02 Atomic Safety and Licensing Board Panel 1p 18362 139 24X Fiche 50-443,83/05/02.

 B305090801
- 8305040329 Responds to New England Coalition on Nuclear Pollution & State of NH submittals subsequent to 830407-08 prehearing conference Objects to word "omission" in reworded Coalition Contention in 2, Coalition Contention I D 2, LESBY, R P. Hearing Branch 3 83/05/04 HOYT, H , LUEBKE, E A , HARBOUR, J. Atomic Safety and Licensing Board Panel App 18344 OBL 24X Fiche 50-443, 83/05/04, 8305040329
- 8305040463 Order denying New England Coalition on Nuclear Pollution B30429 mation for reconsideration of ASLB B30425 memorandum & order No basis exists to reconsider order HOYT, H F Atomic Safety and Licensing Board Panel B2/05/04 England Coalition on Nuclear Pollution 3pp 18348 072 24X Fiche 50-443.83/05/04.8305060463 New
- B305090508 Order admitting Town of Beabrook.NH as interested municipality All procedural requirements must be observed HOYT-H F Atomic Safety and Licensing Board Panel 83/05/06 6pp 18362.140 24X Fithe 30-443.83/05/06.83050
- 8305100200 Order admitting Town of Balisbury, MA as interested municipality List of Beabrook contentions remaining as of 830414 encl. HOVT.H.F. Atomic Safety and Licensing Board Panel 83/05/0 Atomic Safety and Licensing Board Fanel 6pp 18374 023. Fiche: 50-443, 83/05/06, 8305100200
- 8305270573 Requests inclusion as intervenor in upcoming hearings re evacuation planning for facility NOMLES 8 W Northampton County, PA 83/05/07 Atomic Safety and Licensing Board Panel. 3pp 18646 112 24X Fiche 50-443,83/05/07, Atomic Safety and 8305270573
- 8305100334 Response opposing New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene Motion should be rejected as untimely filed Certificate of Byc encl PERLIS, R. Q : LESSY.R P Hearing Branch 3 83/05/09. Safety and Licensing Board Panel 8pp 18378,329 Fiche 50-443,83/05/09,8305100334 241
- 8303130087 Informs that Strafford County Superior Court will be available for ASLB hearings during part of Jul & all of Aug 1983 in response to request for hearing D'AMOURS NE House of Rep 83/05/09 HOYT. H Atomic Safety a Atomic Safetu and 8305130087.
- 8305:30:81 Memorandum & order memorializing 830407-08 prehearing conference in Boston, MA Rulings made on filing of contentions re Newburyport, MA emergency plan & re motions for summary disposition
 HOYTH F. Atomic Safety and Licensing Board Panel 83/05/11.
 Public Service Co of New Hampshire 36pp 18440.001 24X
 Fiche: 30-443.83/05/11.8305130181
- B30516006B Affidavit of GC Minor responding to NRC B30420 affidavit on qualification of electric valve operators at plant Operators must be considered important to safety & environmentally qualified Certificate of Svc encl.Related correspondence MINOR.0 C. New England Coalition on Nuclear Pollution B3/05/11, 13pp 18453 105 24X Fiche 30-443,83/05/11,830516006B
- 8305160002 Motion to file out-of-time answer to NRC affidavit re-CURRAN.D. Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel 3pp. 18456 056 24X Fichs 50-443.83/05/12.8305160002

- 8305160019 Response opposing NRC 830420 affidavit supporting assertion that none of unqualified electric valve operators inside containment are important to safety Failure to operate could prevent successful cooling of reactor CURRAN.B . JURDAN.W S New England Coolition on Nuclear Pollution CURRAN.D Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel App 18452 341 24X Fiche 50-443.83/05/12.8305140019
- 830317047B Memorandum & order denying New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene to admit new Contention NECNP VII on environ qualification of Admix new Contention meets of the state of t Fiche 50-443, 83/05/13, 8305170478
- B30519034A Requests public meeting be held to receive public input for preparation of Town of Hampton radiological emergency mgt plan WALKER, J. R. Hampton, NH. B3/05/13. Affiliation Unknown. 1p
 - MALKER, J.R. Hampton, NH B3/05/13 Affiliat: 18500 022 24X Fiche 50-443,83/05/13,8305190346
- 8305190197 Motion to amend petition to intervene by adding Contention SAPL Suppl 7. "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate Game Gooling of Svc encl
 gACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Backus,
 Shea & Meyer 83/05/16 Atomic Safety and Licensing Board Panel
 Spp 18502 205 24% Fiche 50-443,83/05/16,8305190199
- 8305250327 Requests MB Pearson be placed on avoist as Town of Amesbury, MA representative, per ASLB 830328 itr STUART, D L Amesbury, MA 83/05/16 H0YT, H F Atomic Safety and Licensing Doard Panel ip 18585 361 24X Fiche 50-443,83/05/16. 8305250327
- B305240451 Order promulgating schedules for proceeding, including schedules for technical safety & onsite & offsite emergency planning contentions
 HDYT.H F Atomic Safety and Licensing Board Panel B3/05/23 HDVT, N F Atomic Safety and Licensing Board Panel 83/05/23 4pp 18574 120 24X Fiche 50-443,83/05/23,8305240451
- 8305310147 Response to SAPL motion to amend petition to intervene re 30531014/ Response to SAPL motion to amend petition to interven SER open items Motion should be denied on grounds of timeliness Certificate of Bvc encl DIGNAN.TO Public Service Co of New Hampshire DIGNAN.TO & Gray 93/03/24 Atomic Safety and Licensing Board Panel 18651 209 24% Fiche 30-443,83/05/24,8305310147 Boo
- 8305270598 Order granting Town of North Hampton, NH 830507 petition to intervene re evacuation planning & admitting town as intervene re evacuation planning & admitting town as interested municipality in proceeding per IOCFR2 715(c) HDVT:HF Atomic Safety and Licensing Board Panel 83/05/25 Public Service Co of New Hampshire 2pp 18645 361 24X Fiche 50-443,83/05/25,8305270598

H General correspondence

- 8305250331 Offers use of junior high school auditorium for Aug 1783 licensing hearings Auditorium seats 500 people % has adjacent nurses room & bathroom for personal use NADEAU.JP. YOUNG, M.L. HQLWAY, F.I. Rye, NH. 83/05/20 HOYT, H. Atomic Safety and Licensing Board Panel 1p 18572 104 24X Fich# 50-443, 83/05/20, 8305250331
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8303130352 Informs of uneasiness on selection of 1755 Cape Ann earthquake as facility std for design response spectra Critical safety-related components should be designed to withstand larger Charleston event POMEROY, P W Rondout Associates PDMERDY, P W ACRS - Advisory 83/04/05 KERR, W ACRS - Adv 2pp 18443 333 24X Committee on Reactor Safeguards Committee on Reactor Safeguards Fiche 50-443, 83/04/05, 8305130352
- 8305130235 Forwards ACRB 830419 ltr re review of application for OL. resorting on low power operation
 KNIGHTON, G W Licensing Branch 3 83/04/25 HARRISON, R J Public
 Service Co of New Hampshire 3pp 18437 328 24x Fiche 50-443,83/04/25,8305130335
- --8305130339 Comments on lower power operation review of OL application Operation reasonably assured at core power levels up to 5% full power w/o undue risk to public health & safety EBERSOLE. J. C. ACRS Advisory Committee on Reactor Safeguards 83/04/19 PALLADING.N J. Commissioners 3pp 18497 331, 24X Fiche 50-443,83/04/25,8305130335

- B305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities Supporting documentation encl MAXMELL, J C Maxwell, J C MAXMELL, J C ACRS Advisory Committee on Reactor Safeguards B3/05/05 KERR, W ACRS Advisory Committee on Reactor Safeguards Spp 18443 335 24X Fiche 50-443,83/05/05, B305130347
- G Inspection reports. IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Esothermic Chemical Reaction " Svc list encl
 - TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York. Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8303050114 Forwards IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted 8TAROSTECKIR Division of Project & Resident Programs 83/04/01 HARRISON.R J Public Service Co of New Hampshire 2pp 18342 244 24X Fiche 80-443/83/04/01/8305050116
- --8305050119 IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted Major areas inspected work activities, procedures & records re sys & component installation & structural steel erection CERNE, A C., GRAMM, R.A., NARROW, L.M. Region 1, Office of Director B3/04/20 12pp 18342 246 24X Fiche 50-443,83/04/01.8305050116
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 135 24X Fiche 50-000.83/04/15.83030440021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 82/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000.83/04/25.8303040025
- B303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Bys Heater High Temp Trip Setpoint Adjustment" Svc list enci JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.
- 8303040028 IE Info Notice 83-26. "Failure of Bafety/Relief Valve
 Discharge Line Vacuum Breakers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/03 Consolidated Edison Co of New
 York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list and JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 820103). 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04.8303040030.
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies," Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 82/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524-003 24X Fiche 50-000,83/05/11,8303040034.

- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/17 Consolidated Edison Co of New
 York, Inc 114pp 18497 007 24X Fiche 50-000,83/03/19,8303040040.
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York: Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.
- 9 Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices. Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME.E.P. Westinghouse Electric Corp 83/04/21 DEYOUNO.R C Director's Dffice. Dffice of Inspection and Enforcement 5pp 18405 095 24X Ficha 50-000.83/04/21.8305110427.
- 8305200495 Supplementary Part 21 rept re adequacy of ever water cooling towar structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630 SARBTEN. O.E United Engineers & Constructors, Inc. (subs of Raythson Co) 83/04/29 Region i. Office of Director 3pp 18514 033 24X Fiche 50-443,83/04/29,8305200495
- 6305160039 Final deficiency rept re sheared pinion keys on six Limitarque motor operators Initially reported on 820805 Westinghouse will replace pinion keys on all 58-0 motor operators for Westinghouse valves DEVINCENTIS, J Public Service Co of New Hampshire 83/05/04 8TAROBETECKI, R Division of Project & Resident Programs 3pp 18453 127 24X Fiche 50-443,83/05/04,8305160039.
- 8305110299 PND-I-B3-048 on 830429, potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds involving procedural violations during magnetic perticle exam. CERNE. A GALLO. R. Region 1. Office of Director 83/05/06. 1p. 18393 333 24X Fiche 50-443.83/05/06.8305110299
- 8305190164 Second interim deficiency rept re Westinghouse EMD gate valve position indication Initially reported on 830110
 Investigation continuing Detailed description, enalysis of safety implications & corrective actions expected by 830610.
 DEVINCENTIS, J Yankse Atomic Electric Co DEVINCENTIB, J Public Bervice Co of New Hampshire 83/05/09 BTAROBIECKI, R Division of Project & Resident Programs 2pp 18502 235 24X
 Fiche 50-443,83/05/09,8305190164
- 8305200353 Final deficiency rept to D8-416 reactor trip switchgear malfunction initially reported on 830422 Caused by deviations from breaker internal recommended clearances. Manufacturer drawings modified. DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Hampshire 83/05/16 STAROBTECKI, R Division of Project & Resident Programs 3pp 18518-091 24X Fiche 50-443,83/05/16.8305200355
- B305200402 Interim deficiency rept re-svc water & circulating water pump house structural inadequacy Initially reported on B30419 Detailed engineering evaluation scheduled for completion by 830722

 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hempshire B3/05/16 STAROSTECKI.R. Division of Project & Resident Programs 2pp 18517 295. 24X

 Fiche. 50-443. 83/05/16. 8305200402
- 8305250244 Second interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 Series process instrumentation & control sys cabinets Initially reported on 830318 Evaluation rept expected by 830630 DEVINCENTIS. J. Yankee Atomic Electric Co DEVINCENTIS. J. Public Service Co of New Hampshire 83/05/20 STAROSTECKI, R Division of Project & Resident Programs. 1p 18572 297. 24X Ficha. 50-443, 83/05/20, 8305250244
- U Congressional/Executive Correspondence
- B304250241 Requests suggestions for appropriate facility to accommodate licensing proceeding in reasonable space & comfort & w/o unnecessary handicaps
 HOYT.H.F. Atomic Bafety and Licensing Board Panel. B3/04/20, D'AMOURS.N E. House of Rep. ip 18178 111, 24X
 Fiche 30-445.83/04/20,8304250241.

- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305130335 Forwards ACRS B30419 ltr re review of application for OL, reporting on low power operation KNIGHTON, G W Licensing Branch 3 83/04/25 HARRISON, R J Public Service Co of New Hampshire. 3pp 18457 328 24X Fiche 50-443,83/04/25,8305130335
- B305110016 Notification of B30511 meeting w/util in Bethesda, MD to discuss projected const completion date WHEELER: L Licensing Branch 3 83/04/28 KNIGHTON, 0 W Licensing Branch 3 4pp 18421 238 24X Fiche 50-443,83/04/28,
- B305040323 Board Notification B3-057 forwards differing prof opinions re sys interaction & sefety classification Info relates to Board Notifications B3-17 & B3-44 re Unresolved Safety Issue A-17
 EIBENHUT, D 0 Division of Licensing B3/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, B305040323
- 8305130332 Requests description of environ qualification program including listed items Scope of submittal to include all electrical equipment important to safety located in harsh environ
 KNIGHTON.O W Licensing Branch 3 83/05/05 . HARRISON,R J Public Barvice Co of New Hampshire 4pp 18457 334 24X
 Fiche 50-443,83/05/03.8305130332
- 8305070659 Generic Ltr 83~20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EIBENHUT.D 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 50~000.83/05/09.8303070659
- 8305270019 Requests extension of CP completion dates for Units 1 & 2 to June 1986 & Oct 1988, respectively, per Amend 40 to CPPR-135 & CPPR-136
 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 18662 107 24X Fiche 50-443, 83/05/16, 8305270019
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B305170668 SAFETY EVALUATION REPORT RELATED TO THE DPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos 50-443 And 50-444 (Public Service Company of New Hampshire, et al) # Division of Licensing NUREO-0876 S01 83/04/30 32pp Available at NRC \$4 50. 18481:332 24X Fiche 50-443,83/04/30,8305170668
- B30526003B Forwards Suppl 1 to SER re application for DL W/o encl MM10HTON.g W Licensing Branch 3 83/05/12 HARRISON.R.J Public Service Co of New Hampshire 4pp Fiche: 50-443, 83/05/12, 830526003B
- F Security, medical, emergency & fire protection plans
- 8305090523 FDIA request for add1 info re earlier request on Pilgrim dtd 821105 concerning similar documentation for Seabrook facilities 8HOTMELL, J A Massachusetts, Commonwealth of, 83/01/05, FELTON.J.M Division of Rules and Records 2pp 18368 601 24X Fiche 30-443,83/01/05,8305090523
- 8305070527 Partial response to FOIA request for add1 info re 821105 request pertaining to facility Forwards App A documents Documents also available in FDR App B documents completely withheld (ref FOIA Exemption 5)
 FELTON.J.M Division of Rules and Records 83/03/10 SHOTHELL, J. A. Massachusetts, Commonwealth of, 5pp 18368 003 24X
 Fiche 50-443,83/03/10,8305070527
- --8203150093 Forwards branch review comments of facility emergency plan, performed against NUREG-0654 criteria Addi info & commitments required prior to acceptance, PAGAND.F 0. EP Licensing Branch 82/03/03, MIRAGLIA,F J Licensing Branch 3 20pp, 18368 014 24X Fiche.50-443,83/03/10,8308900329

- --8208190078 Requests findings on prompt protective action decisionmaking in States of VT. NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface." Chapter 2 encl GRIMES, B K Division of Energency Preparedness (Pre 830103) 82/04/27 KRIMM, R M Federal Emergency Management Agency opp 18368 034 24X Fiche 50-443,83/03/10.83050900329
- --B305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station " * HMM Associates, Inc B3/03/10 Fiche 50-443,83/03/10,8305090529
- B305050006 Forwards United Engineers & Constructors General Arrangement Drawing 9736-F-805062 re fire protection of primary component cooling water pumps, per util 830121 ltn Wo encl DEVINCENTIS, J Vankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire B3/05/02 KNIGHTON, 0 W Licensing Branch 3 2pp 18339 083 24% Fiche 50-443,83/05/02,83050500006
- 8305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 E18ENHUT.D 0 Division of Licensing B3/05/11 Consolidated Edison Co of New York. Inc 16pp 18340 095 24X
 Fiche 50-000,83/05/11,8305110034
- G Adjudicatory correspondence
- B305100356 Forwards responses to New England Coalition on Nuclear Pollution Fourth, sixth, eighth, twelfth, fourteenth & fifteenth motions for summary disposition LEGBY, RP Hearing Branch 3 83/03/21 HOVT, H., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 18411 001 24x Fiche 30-443,83/03/21,8305100356
- --8305100375 Response to twolfth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 1 NRC cannot agree or disagree w/statement of matl fact until receipt of preservice & inservice insp programs
 LESSY, R P. PERLIS.R Q Hearing Branch 3 B3/03/18 Atomic Safety and Licensing Board Panel 28pp 18411 003 24x
 Fiche 50-443,83/03/21.8305100356
- --8305100392 Response to fourteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) No genuine issue of matl fact exists & NECNP entitled to favorable decision PATTERGON, W F , LESBY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel Spp 18411 032 24X Fiche 50-443,83/03/21,8305100356
- ----8305100400 Affidavit of RK Anand on New England Coalition on Nuclear Pollution Contention I D 3 Requirements of GDC 30 satisfied ANAND, R K Auxiliary Systems Branch 83/03/18 App 18411 037 24X Fiche 50-443,83/03/21,8305100355
- --B3051004ii Response to Fiftmenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I Q No genuine issue of mati fact exists & NECNP entitled to favorable decision PATTERSON, W F , LESBY, R P Hearing Branch 3 B3/03/18 Atomic Safety and Licensing Board Panel 4pp 18411 043 24X Fiche 30-443,83/03/21.8305100356
- ---8305100419 Affidavit of RQ LaGrange on util commitment to qualify wide-range pressure transmitters per NUREG-0588 requirements Commitment acceptable LAGRANGE, R. Q Equipment Gualification Branch 83/03/18 3pp 18411 047 24X Fiche 50-443,83/03/21,8305100356
- ---8305100425 Response to fourth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention

 I 1 Requirement to qualify path to cold shutdown not needed Contention must be dismissed.

 PERLIS.R 0 . LESSY.R P Hearing Branch 3 B3/03/18 Atomic Safety and Licensing Board Panel 2pp 18411 030 24% Fiche 30-443,83/03/21.8305100356
- --8305100430 Response to sixth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention NH-13 No genuine issue of matl fact exists & NECNP entitled to favorable decision PATTERSON, M.F., LESBY, R.P. Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 5pp 18411 052 24X Fiche 50-443,83/03/21,8305100354

- --B305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREG-0737. Item I A 1 1 requirements re shift technical advisor position Proposal acceptable WIGGINS. J T Division of Project & Resident Programs 83/03/17 2p 18411 057 24X Fiche 50-443,83/03/21,8305100356
- --B305100432 Response to eighth motion for summery disposition of New England Coalition on Nuclear Pollution (NECNP) Contention
 I A 2 No genuine issue of mati fact exists & NECNP entitled to favorable decision
 PATTERSON,W F , LESSY,R P Hearing Branch 3 B3/03/18 Atomic Sefety and Licensing Board Panel App 18411 059 24X Fiche 50-443, B3/03/21, B305100356
- --8305100424 Affidavit of RG Lagrange on qualification of Class IE electric valve operators installed inside containment, Util committed to qualification per NUREO-0588 LAGRANGE, R G Equipment Qualification Branch 83/03/18 3pp 18411 064 24X Fiche 30-443,83/03/21.8305100356.
- 8305100158 Forwards CY Liang.WT LeFave & 88 Kirslis joint affidavit reviewing & commenting on Table I A 2-3 which includes listing of all electric valve operators inside containment, per ASLB request LEBSY.R P Hearings Division PATTERSON.W F Office of the Executive Legal Director 83/04/20 HOYT.H , LUEDKE.E A , HARBOUR.J Atomic Safety and Licensing Board Fanel. 3pp 18374 252 24X Fichs 50-443.83/04/20,8305100158
- --8305100166 Affidavit of CY Liang, HT LeFave & S5 Kirslis providing results of NRC review of Table I A 2-3 concerning environ qualification of ejectric valve operators installed inside conteinment Prof qualifications encl
 LIANO: C Y Reactor Systems Branch LEFAVE, W T Auxiliery Systems
 Branch KIRSLIS, S S Chemical Engineering Branch 83/04/19
 16pp 18374 255 24X Fiche 50-443, 83/04/20,8305100158
- 8305100219 Forwards supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I A 2 in NRC 62122B response to first set of interrogatories W/affidavits re review of Table I A 2-3 LESSY.R P Office of the Executive Legal Director B3/04/20 CURRAN.D Harmon & Weiss 2pp 18374 145 24X Fiche 50~443.83/04/20,8305100219
- --8305100221 Supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I A 2 in NRC 821228 response to first set of interrogatories Affidavits re Table I A 2-3 encl Defice of the Executive Legal Director 83/04/20 Atomic Safety and Licensing Board Panel 1420 18374 147 24X Fiche. 50-443:83/04/20,8305100219
- 8305020425 Forwards Town of Beabrook request to participate as interested municipality interests lie in areas of emergency planning. Insurance & accidents & precautionary evacuation. FELCH, F B , RANDALL, H I , FALCONER, J C Seabrook, NH 83/04/22 HOYT, H F. Atomic Bafety and Licensing Board Panel Ep. 18273 176 24X Fiche 50-443,83/04/22,8305020425
- --8305020429 Request to participate as interested municipality per 100F82 715(c)
 FELCH, F B : RANDALL, W I : FALCONER, J. C. Seabrook, NH 83/04/22
 Atomic Safety and Licensing Board Penel. 1p 18273-197 24X
 Fichs 50-443,83/04/22,8305020425
- 8305020482 Forwards Town of Exeter request to participate as interested municipality CHICK, D.E. Exeter, NH 83/04/26 HOYT, H.F. Atomic Safety and Licensing Board Penel 1p. 18282-298. 24X Fiche 50-443,83/04/26,8305020482
- --8305020486 Request to perticipate as interested municipality per 10CFR2 715(c)
 CHICK, D E Exeter, NH 83/04/26 Atomic Safety and Licensing Board Panel ip 18282 299 24X Ficha 50-443,83/04/26,8305020482
- B305030541 Motion to reconsider ASLB B30425 memorandum & order in response to New England Coalition on Nuclear Pollution objection to B30414 conference call Complexity of issue justifies 20-dey response period Cartificate of Svc encl CURRAN.D. BISHOP.L L. New England Coalition on Nuclear Pollution BISHOP.L L. Hermon & Weiss 83/04/29 Atomic Sefety and Licensing Board Panel Spp 18301.357 24X Fiche.50-443.83/04/29, B305030541
- 8305030570 Order admitting Town of Exeter, NH as interested municipality Exeter must observe procedural requirements & take proceeding as found.
 HOY1.H F. Atomic Safety and Licensing Board Penal 83/04/29-Exeter, NH 7pp 18306-110 24X Fiche 50-443,83/04/29.8305030570

- B305040300 Response to New England Coalition on Nuclear Pollution motion to amend petition to intervene Additionation should be denied on grounds of timeliness or partially denied on grounds of vagueness Certificate of Bvc encl
 DIONANT 0 QADJR K Public Service Co of New Hampshire
 DIONANT 0 Ropes & Oray B3/04/29 Atomic Bafety and Licensing
 Board Panel 16pp 18324 001 24X Fiche 30-443, B3/04/29,
 B305040300
- 8305040316 Response to Town of Beabrook, NH request to participate as interested municipality Emergency plenning exercise & public insurance coverage issues may not be litigated in present proceeding Certificate of Svc encl
 DIONAN, T 0. DIONAN, T 0 Public Bervice Co of New Hampshire OAD, R K Ropes & Orey 83/04/29 5pp 18323 295 24X
 Fichs 30-443,83/04/29,8305040316
- 8305090501 Forwards request to participate as interested municipality in proceedings
 BARGENT.A V Selisbury, MA 83/05/02 HOYT, H F Atomic Sefety and Licensing Board Panel 2pp 18362 138 24X Fiche 50-443, 83/05/02, 8305090501
- --8305090502 Request to participate as interested municipality in proceedings SARCENT.A V Salisbury, MA 83/05/02 Atomic Safety and Licensing Board Panel 1p 18362,139 24X Fiche: 50-443,83/05/02,8305090501.
- B305050329 Responds to New England Coalition on Nuclear Pollution & State of NH submittels subsequent to B30407-08 prehearing conference Objects to word "omission" in reworded Coalition Contention I.D 2
 LEBSY.R P Hearing Branch 3 B3/05/04 H0YT.H., LUEBKE.E A., HARBOUR.J Abonic Safety and Licensing Board Panel. 4pp 18044.081 24X Fiche 50-443,83/05/04.8305060329
- B305060463 Order denying New England Coalition on Nuclear Pollution 830429 motion for reconsideration of ASLB B30425 memorandum & order. No basis exists to reconsider order. HGYT, HF Atomic Bafety and Licensing Board Panel 82/05/04. Net England Coalition on Nuclear Pollution 3pp 18348,072, 24X Fiche 50-443,83/05/04,8303060463.
- B30307050B Order admitting Town of Bashrook, NH as interested municipality All procedural requirements must be observed. HOYT-H F Atomic Safety and Licensing Board Panel. 83/05/06. App. 18362 140 24X Ficher 50-443, 83/05/06. 8305070308
- 8303100200 Order admitting Town of Salisbury, MA as interested municipality List of Beabrook contentions remaining as of 830414 encl HOYTH F. Atomic Bafety and Licensing Board Penel. 83/05/06. Atomic Safety and Licensing Board Penel. 83/05/06. Atomic Safety and Licensing Board Panel 6pp 18374 023, 24X Fiche. 50-443, 83/05/06. 8305100200
- 8305270573 Requests inclusion as intervenor in upcoming hearings re evacuation planning for facility NONLES:3 W. Northampton County, PA 83/05/07 Atomic Sefety and Licensing Board Panel 3pp. 18646 112 24X Fiche. 50-449, 83/05/07, 8305270573
- 8305100334 Response opposing New England Coalition on Nuclear Pollution 830421 motion to amend patition to intervene Motion should be rejected as untimely filed, Certificate of Bvc encl.

 PERLIS,R G., LESSY,R P. Hearing Branch 3 83/05/09 Atomic Bafety and Licensing Board Panel Bpp 18378'329, 24X Fiche 50-443,83/05/09,8305100334.
- 8305130087 Informs that Strefford County Buperior Court will be available for ABLB hearings during part of Jul & all of Aug 1993; in response to request for hearing D'AMOURS.N.E. House of Rep 83/05/09. HOYT.H.F. Atomic Safety and Licensing Board Panel 1p. 18440 044 24X Fiche: 50-443,83/05/09. 8305130087
- 8305130181 Memorendum & order memorializing 830407-08 prehearing conference in Boston MA Rulings mede on filing of contentions re Newburyport MA emergency plan & re motions for symmary disposition HOYT.H F Atomic Safety and Licensing Board Panel 83/05/11. Public Service Co of New Hempshire 36pp. 18440 001 24X Fiche: 50-443,83/05/11,8305130181
- B30516006B Affidavit of GC Minor responding to NRC B30420 affidavit on qualification of electric velve operators at plant Operators must be considered important to safety & environmentally qualified. Certificate of Bvc encl. Related correspondence. MINOR, G C. New England Comittion on Nuclear Pollution, 83/05/11 13pp. 18453 105, 24X Fichs: 50-443, 83/05/11, 830516006B

- B305160002 Motion to file out-of-time answer to NRC affidavit re Contention I A 2 concerning environ qualification of electric valve operators inside containment Intervenor unable to complete review within 10-day period set by ASLB CURRAN, D , JORDAN, M, S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss B3/05/12 Atomic Safety and Licensing Board Panel 3pp 18456 056 24X Fiche 50-443,83/05/12,8305160002
- 8305160019 Response opposing NRC B30420 affidavit supporting assertion that none of unqualified electric valve operators inside containment are important to safety Failure to operate could prevent successful cooling of reactor CURRANID , JORDANIM S New England Coolition on Nuclear Pollution CURRANID Harmon & Weiss 83/05/12 Atomic 8afety and Licensing Board Panel 4pp 18452 341 24X Fiche 50-443.83/05/12,8305160019
- 8305170478 Memorandum & order denying New England Coalition on Nuclear Pollution 830421 motion to emend patition to intervene to admit new Contention NECNP VII on environ qualification of electrical equipment important to safety MOYT. H F Atomic Safety and Licensing Board Panel 83/05/13 New England Coalition on Nuclear Pollution 6pp 18470 092 24X Fiche. 50-443, 83/05/13, 8305170478
- B305190346 Requests public meeting be held to receive public input for preparation of Town of Hampton radiological emergency mgt plan
 HALKER, J. R Hampton, NH B3/05/13 Affiliation Unknown ip
 18500 022 24X Fiche 50-443,83/05/13,8305190346
- 8305190199 Motion to amend petition to intervene by adding Contention SAPL Suppl 7, "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate of Svc encl BACKUS, R A Seacoest Anti-Pollution League BACKUS, R A Backus, Sheak Mayer 83/05/16 Atomic Safety and Licensing Board Panel 5pp. 18502.205 24X Fiche 30-443,83/05/16,8305190199
- 8305250327 Requests MB Pearson be placed on svc list as Town of Amesbury, MA representative, per ABLB 830328 ltr STUART, D L Amesbury, MA 83/05/16 HOYT, H F Atomic Safety and Licensing Board Panel ip 18585 361 24% Fiche 50-443,83/05/16,8305250327
- 8305240451 Order promulgating schedules for proceeding, including schedules for technical safety & onsite & offsite emergency planning contentions
 HOYT.B F Atomic Safety and Licensing Board Panel 83/05/23 4pp 18574:120 24X Fiche 50-443,83/05/23,8305240451
- 8305310147 Response to SAPL motion to amend petition to intervene re BER open items Motion should be denied on grounds of timeliness Certificate of Svc enci DIQNAN,T Q Public Service Co of New Hampshire DIQNAN,T.Q. Ropes & Gray, B3/05/24 Atomic Safety and Licensing Board Panel Bpp 18431 209. 24% Fiche 50-449,83/03/24.8305310147
- 8305270598 Order granting Town of North Hampton, NH 830507 petition to intervene re evacuation planning & admitting town as intervene municipality in proceeding per 10CFR2 715(c) HOYT, H F Atomic Bafety and Licensing Board Panel. 83/05/25 Public Service Co of New Hampshire 2pp 18645:361 24X Fiche: 50-443, 83/05/25, 8305270578
- H General correspondence
- B305250331 Offers use of junior high school auditorium for Aug 1983 licensing hearings. Auditorium seats 500 people & has adjacent nurses room & bathroom for personal use NADEAU, J.P., YOUNG, M.L., HOLHAY, F.1 Rue, NH 83/05/20 HOYT, H.F. Atomic Bafety and Licensing Board Panel ip 18592 104 24X Fiche: 50-443,83/05/20,8303250331
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 9309130332 Informs of uneasiness on selection of 1755 Cape Annearthquake as facility std for design response spectra Critical safety-related components should be designed to withstand larger Charleston event POMERGY, PW. Rondout Associates. PUMERGY, PW. ACRS Advisory Committee on Reactor Safequards 83/04/05 KERR, W. ACRS Advisory Committee on Reactor Safequards 2pp 18443 333 24X Fiche 50-443,83/04/05,8305130332
- 8305130335 Forwards ACRS 830419 ltr re review of application for CL, reporting on low power operation KNIGHTON, G. W Licensing Branch 3, 83/04/25, HARRISON, R J Public Service Co. of New Hampshire 3pp 18457 328 24X Fiche: 50-443/83/04/25.8305130335

- --B305i30339 Comments on lower power operation review of DL application Operation reasonably assured at core power levels up to 5% full power w/o undue risk to public health & safety EBERSOLE; J C ACRS Advisory Committee on Reactor Bafeguards B3/04/19 PALLADINO, N J Commissioners 3pp 18457 331 24% Fiche 50-443,83/04/25,8305i30335
- 8305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities Supporting documentation and MAXWELL.J C ACRS Advisory Committee on Reactor Safeguards 83/05/05 KERR.H ACRS Advisory Committee on Reactor Safeguards 5pp 18443 335 24X Fiche 50-443,83/05/05,8305130347
- G Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enci TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21,8212040385
- 8305050116 Forwards IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted 87AR08TECKI,R Division of Project & Resident Programs 83/04/01 HARRISON.R J Public Bervice Co of New Hampshire 2pp 18342 244 24X Fiche: 50-443,83/04/01,8305050116
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Bvc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- B303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Bys." 8vt list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3704/25, Consolidated Edison Co of New
 York, Inc 117pp. 18381.271 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382.047 24% Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment 8ys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co. of New Verk, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment," Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382.282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Buc list encl JURDAN.E.L. Division of Emergency Properedness & Engineering Resgonse (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 117pp 18441.001 24X Fichs 50-000.83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). B3/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

- 9303040034 IE Info Notice 93-30. "Misapplication of Generic Emergency Operating Procedures (EUP) Guidelines "Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 93/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 247 Fiche 50-000.83/05/11.8303040034
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list ser!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 50-000.83/05/26,8303040046
- S Reportable occurrences. LERs & related correspondence
- B305110427 Part 21 & deficiency repts re misuperation of DS-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME.E P Westinghouse Electric Corp B3/04/21 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000.83/04/21,8305110427
- 8305200495 Supplementary Part 21 rept re adequacy of svc water cooling tower structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630
 8ARSTEN.G E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/04/29 Region 1, Office of Director 3pp 18514 033 24X Fiche 50-443,83/04/29,8305200495
- 8305160039 Final deficiency rept re sheared pinion keys on six Limitarque motor operators initially reported on 820805 Hestinghouse will replace pinion keys on all SB-O motor operators for Mestinghouse valves DEVINCENTIS, J Public Service Co of New Hampshire 83/05/04 STAROSTECKLIR Division of Project & Resident Programs 3pp 18453:127 24X Fichs 50-443,83/05/04,8305160039.
- B305110279 PNO-1-83-048 on B30429.potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds.involving procedural violations during magnetic particle eram

 CERNE, A. GALLO, R. Region i. Office of Director B3/05/06 ip 18393 333 24X Fiche 50-443,83/05/06,8305110299
- 8305190164 Second interim deficiency rept re Westinghouss EMD gate valve position indication initially reported on 830110 investigation continuing Detailed description, analysis of safety implications & corrective actions expected by 830610. DEVINCENTIS, J Yantee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/09 STAROSTECKI.R Division of Project & Resident Programs 2pp 18502 235 24X Fiche 50-443,83/05/09,8305190164
- 8305200353 Final deficiency regt re DS-416 reactor trip switchgear malfunction Initially reported on 830482 Caused by deviations from breaker internal recommended clearances Manufacturer drawings modified DEVINCENTIS, J Yantee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 STARDSTECKI.R Division of Project & Resident Programs 3pp 18518 091. 24X
- 8305200402 Interim deficiency rept re-svc water & circulating water gump house structural inadequacy Initially reported on 830419 Detailed engineering evaluation scheduled for completion by 830722
 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 83/05/16 STAROSTECKI.R Division of Project & Resident Programs 2pp 18517 275 24X
 Ficher 50-443,83/05/16,8305200402
- B305250244 Second interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 Series process instrumentation & control sys cabinets. Initially reported on 83038 Evaluation rept spected by 830630 DEVINCENTIS.J Vantee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 83/05/20 STAROSTECKI.R Division of Project & Resident Programs ip 18592 297 24X Fiche 50-443,83/05/20,8305250244

- U Congressional/Executive Correspondence
- B304250241 Requests suggestions for appropriate facility to accommodate licensing proceeding in reasonable space & comfort & w/o unnecessary handicaps
 HOYT.H F Atomic Bafety and Licensing Board Panel B3/04/20
 D'AMDURS.N E House of Rep ip 18178 111 24X
 Fiche 30-443.83/04/20.8304250241
- DOCKET 30-445 COMANCHE PEAK STEAM ELECTRIC STA ,UNIT 1

 A Application/construction stage documents & correspondence
- B305180001 Add1 response to FOIA request for seven categories of documents re Brown & Root, Inc & Both Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON, J M Division of Rules and Records B3/03/09 LINDEMAN, H N
 Lowenstein, Newman, Reis, Axelad & Toll App 18497 219 24X
 Fiche 50-000, 83/03/09, 8305180001
- --8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will compliete visual insp & comply w/corrective actions in encl AWB Code STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE, J F Commissioners , 5pp 18497 228 24X Fiche 50-000,83/03/09.8305180001
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE.J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272, 24X Fiche. 50-000. 83/04/11, 8305230720
- 8303090722 Board Notification 63-12 forwards rept, "Design & Const Salf-Initiated Evaluation," to facilitate general upgrading of plant & industry
 NOVAK.T M Assistant Director for Licensing AS BNB3-12 83/05/02, Atomic Safety and Licensing Board Panel 3pp 18368 291 24X Fiche 30-445,83/05/02,8305090722
- --8305090726 "Design & Const Belf-Initiated Evaluation, Comanche Peak Steam Electric Station " " Texas Utilities Generating Co 92/10/31 354pp 18368 294 24X Fiche 50-445,83/05/02,8305090722
- B305040323 Board Notification 83-057 forwards differing prof opinions results interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT, D © Division of Licensing 83/05/04 PALLADING, N Commissioners 22pp 18337 139 24X Fichs 50-000,83/05/04,
- B3D5120107 Summary of B30413 meeting w/util in Bethesda. MD re added assurance program to assure independent verification program requirements met
 BURWELL, S B Licensing Branch 1 83/05/04 Licensing Branch 1,
 7pp 18443 177 24% Fichs 50-445,83/05/04,8305120107
- B305100125 Forwards comments on environ qualification correlation between installed & qualified components as followup to B21014 audit trip rept on Item II.a. "Auxiliary Bldg Modular Train Filter"

 SCHMIDT: H C Texas Utilities Services, Inc B3/05/05, YOUNGBLOOD, B J Licensing Branch i 2pp 18375 029, 24X Fiche 30-445, 83/05/05, 8305100125
- B305090659 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list ancl EISENHUT, D 9 Division of Licensing B3/05/09 Consolidated Edison Co of New York, Inc 16p 1B627 153 24X Fiche 30-000, B3/05/09, B305090659
- 8305230627 Forwards request for procedures generation package needed to complete OL application evaluation YOUNOBLOOD. B J Licensing Branch 1 83/05/12 GARY.R J Texas Utilities Generating Co App 18543 029 24X Fiche 50-445, 83/05/12.8305230627.
- B3053i0151 Comments on alternate shutdown reactor heat removal Direct readings of process variables necessary to perform & control reactor heat removal provided at hot shutdown panel as part of alternate shutdown design SCHMIDT.H C Texas Utilities Services, Inc 83/05/20, YOUNGBLOOD, B J Licensing Branch i 3pp 18651.221 24X Fiche 50-445.83/05/20,8305310151

F Security, medical, emergency & fire protection plans

- 8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness MIZUNG, 0 S Hearing Branch 1 83/04/27 BLOCH, P B , JORDAN, W H , MCCOLLUM, K A Atomic Safety and Licensing Board Panel Spp 18292 163 24X Fiche 30-445
- B305240213 Forwards monthly status rept on offsite emergency preparedness for QL reviews for Apr 1983 DIRCKS:H U Office of the Executive Director for Operations B3/05/13 PALLADINO,N U Commissioners 5pp 18593 322 24X Fich

Q Adjudicatory correspondence

- 8212300007 Brief in opposition to NRC exceptions to ASLB 820730 order denying reconsideration of orders to produce info Affidavit & Certificate of 8vc encl ELLIS.J Citizens Association for Bound Energy 82/12/21 Atomic 84fety and Licensing Appeal Panel 175pp 16597 036 24X Fiche 80-445,82/12/21,821300009
- 8303020422 Motion to allow Citizens Assoc for Sound Energy to file written argument on issue in lieu of presenting oral argument at 83019 hearing Citizens do not have finances to come to Bethesda: MD for 40-minute argument ELLIB: J Citizens Association for Sound Energy 83/01/11 Atomic Bafety and Licensing Appeal Panel 2pp 18283 001 24X Fiche 50-445.83/01/11.8305020422
- --8305020430 Written argument on issues to be argued orally on 830117 in Bethesda, MD Citizens Assoc for Sound Energy unable to attend or find representative Whistleblower protection discussed ELLIB.J Citizens Association for Sound Energy 83/01/11 Atomic Bafety and Licensing Appeal Panel 65pp 18283 003 24X Fiche 50-445,83/01/11,8305020422
- --8305020437 Forwards Citizens Assoc for Sound Energy witness J Doyle affidavit re blacklisting due to testimony at hearings ELLIB.J Citizens Association for Sound Energy 83/01/18 ROBENTHAL.A S Atomic Safety and Licensing Appeal Panel 1p 18283 068 24X Fiche 50-445.83/01/11.8305020422
- --8305020444 Affidavit of J Doyle re blacklisting due to testimony at hearings NRC should take immediate & stringent measures to stop insidious practice NRC current protoction for whistleblowers is farce & charade Certificate of Svc encl DDYLE. J Affiliation Unknown 83/01/17 4pp 18283 069 24X Fiche 50-445,83/01/11,8305020422
- 8305040529 Affidavit of MA Walsh re computer program in J Doyle 830426 surrebuttal testimony BTRUDL program utilized w/sufficient similarities to assure results will be accurate MALSH.M A Citizens Association for Sound Energy 83/04/26 ip 18320 001 24X Fiche 50-445.83/04/26.8305040529
- 8305040296 Motion for discovery re applicant & NRC interrogetories on const appraisal team Insp Repts 50-445/83-18 & 30-446/83-12 Related correspondence ELLIS, U. Citizens Association for Sound Energy 83/04/28. Atomic Bafety and Licensing Board Panel 3pp 18324.025 24X Fiche 30-445.83/04/28,8305040296
- 8305040497 Fourteenth set of interrogatories & requests to produce, Related correspondence ELLIG. J Citizens Association for Sound Energy 83/04/28 Tex. Utilities Generating Co 10pp 18322 111 24X Fichs. 50-445.83/04/28,8305040479
- 8305040513 Fourth set of interrogatories & requests to produce Related correspondence ELLIB, J Citizens Association for Sound Energy 83/04/28, Office of the Executive Legal Director 7pp. 18321 249 24X Fiche 50-445,83/04/28,8305040513
- 8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness MIZUNO,0 8 Hearing Branch 1 83/04/27 BLOCH.P B . JORDAN,W H., MCCOLLOM,K A. Atomic Bafety and Licensing Board Panel 3pp 18272 163 24X Fiche 50-445.83/04/29.8303030464
- 8305030514 Motion for protective order that discovery not be had redraft notice of violation on calculation of deflection of rigid support CC-1-107-008-E23R Draft is not final NRC document Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 83/04/29 Atomic Safety and Licensing Board Panel 7pp 18306 350 24X Fiche 50-445,83/04/29,8303030514

- 8305030522 Order extending time until 830503 for Commission to act to review ALAB-714
 CHILK 8 J Diffice of the Secretary of the Commission 83/04/29
 Commissioners Ip 18306 357 24X Fiche 50-445,83/04/29,
- B30504053i Advises of NRC agreement to voluntarily release one paragraph designated by Judge Bloch as containing factual info possibly relevant to litigation, from draft B21229 notice of violation Paragraph set forth TREBY, S A Hearing Branch 1 B3/05/03 CASE, J Citizens Association for Sound Energy ip 18321 241 24X Fiche 30-445, 83/05/03, 8305040531
- B305040557 Reply to State of TX brief on collateral estoppel State of TX erred in concluding Dept of Labor decision should be given collateral estoppel effect Decision not sufficiently firm to be accorded preclusive effect
 RUTHSCHILD.N U Hearing Branch 1 83/05/03 4pp 18321 282 24X Fiche 30-443.83/05/03.8305040557
- --8305040560 Reply to Citizens Assoc for Sound Energy brief re consideration of LOCA in design criteria for pipe supports Operability of pipe supports not necessary to assure safety-rolated component operability N/Certificate of Svc HIZUND, 0 S Hearing Brench i 83/03/03 9pp 18321 286 24X Fiche 30-445,83/05/03,8303040557
- B305050015 Order extending time until 830320 for Commission to act to review ALAB-714 CHILKS J Office of the Secretary of the Commission B3/05/03 Commissioners ip 18339 055 24X Fiche 50-445,83/05/03, 8303030015
- B30905001B Reply brief to Citizens Assoc for Sound Energy 830420 brief re consideration of effects of LOCA on pipe support design Citizens erroneously applied provisions of ASME Code not applicable to design Certificate of Svc oncl REVNOLDS.N S . HORIN.W A Texas Utilities Generating Co REVNOLDS.N S . Debevois & Liberman 83/05/03 2ipp 18338 334 24X Fiche 50-445,83/05/03.830505001B
- 8305090443 Response in opposition to NRC 830420 response to ASLB question re LOCA-induced thermal expansion in linear supports & applicant 830421 brief on consideration of pipe support design thermal stresses W/Certificate of Svc ELLIS.J Citizens Association for Sound Energy 83/05/03 Atomic Safety and Licensing Board Panel 25pp 18363 001 24X Fiche 50-445.83/05/03,8305090443
- B305110137 Responds to B30504 request to review proposed protective agreement between Citizens Assoc for Sound Energy & ITT-Crimel re design criteria for pipe supports Warding too restrictive Revised proposal enci for review ELLIS.J Citizens Association for Sound Energy B3/05/04 HORIN.W Debevoise & Liberman App 18373 344 24% Fiche 50-445,83/05/04.B30510137
- B305090507 Forwards testimony of LJ Skiles. AB Armstrong & CL Born reemergency planning recommendations. A Vega testimony reconstappraisal team rept & JS Marshall. DH Wader JC Finneran & DR Hoodlan affidavits Related correspondence REYNOLDS. N S Debevoise & Liberman REYNOLDS. N S Taxas Utilities Cenerating Co B3/05/05 BLOCH.PB. MCCOLLOM.KA. JORDAN.W H Atomic Safety and Licensing Board Panel 2pp 18362 014 24X Fiche S0-445.83/05/05.8305090307
- --8305090517 Affidavit of JS Marshall in response to ASLB inquiry re classification of equipment for application of 100FR50.App II requirements & relationship of Board Notification 83-13 to HR Denton Bili20 memo on classification MARSHALL J S Texas Utilities Cenerating Co 83/05/05 7pp 18362 026 24X Fichs 50-445.83/05/05.8305090507
- --8305090521 Affidavit of DH Wade re Midland-Ross superstrut math (Board Notifications 83-02 & 83-14) & welds in main control beard panels (Board Notifications 82-90, 90A & 116) HADE, DH Texas Utilities Generating Co 83/05/05 90pp 18342 033 24% Fiche 50-445,83/05/05,8305090507
- ---8305090525 Affidavit of JC Finneran on applicant response to Doard Notification 82-105 re pipe clamps employed on ASME Code Class I piping FINNERAN J C Texas Utilities Generating Co 83/05/05 3pp 18362 123 24X Fiche 50-445,83/05/05.8305090507

- --8305090530 Affidavit of DR Woodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl WOODLAN.D R Teras Utilities Generating Co 83/05/05 12p 18362 126 24% Fiche 50-445.83/05/03.8305090507
- 8305090548 Forwards direct testimony & affidavits in response to questions posed by ABLB during 830407 telcon TREBY,S A. ROTHSCHILD, M.U. MIZUND,Q S. Hearing Branch 1 83705705 BLOCH,P B. JDRDAN,W H. MCCOLLOM,K A. Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445,83705705,8305090568
- --8305070578 Supplemental testimony of S Burwell, WP Chem, JI Tapia, J Rajan & RO Taylor re concerns raised by MA Walsh & J Doyle & NRC const appraisal insp rept Prof qualifications encl BURWELL, S Division of Licensing CHEN, WP Energy, Dept of. TAPIA, J I Division of Resident, Reactor Project & Engineering Programs 83/05/05 14pp 18360 004 24% Fiche 50-445,83/05/05,8305070548
- --8305070586 Suppismental testimony of DM Rohrer & T Urbanik re emergency preparedness ROHRER, D M Emergency Preparedness Branch URBANIK, T Texas A&M Univ . College Station, TX 83/05/05 20pp 18360 018 24X Fiche 50-445, 83/05/05, 8303090568
- --8305090592 Supplemental testimony of A Lookabaugh & J Benton re emergency preparedness LOOKABAUGHA . JENTON.J Federal Emergency Management Agency 83/05/05 15pp 18360 038 24X Fiche 50-445.83/05/05,8305090568
- --8303090600 Affidavit of SB Burwell re questions posed during ASLB 830407 telcon on implemented procedures concerning maint of scram breakers as result of Board Notifications 83-26 & 83-38 Prof qualifications encl BURNECLL'S B Licensing Branch 1 83/05/05 5pp 18360 053 24X Fiche 30-443, 83/05/05.8303090368
- --8305090607 Affidavit of FD Coffman on Unresolved Safety Issue A-17,
 "Sys Interaction in Nuclear Power Plants," per ASLB 830407
 telcon request Frof qualifications encl
 COFFMAN.F D Reliability & Risk Assessment Branch 83/05/05
 9pp 18360 058 24X Fiche 50-445,83/05/05,8305070568
- --830509061B Affidavit of S Diab re semiscale feed & bleed Experiment S-9R-2 & related subsequent RELAP-5 analyses.per ASLB 830407 telcon request Prof qualifications encl DIAB. S Reactor Systems Branch 83/05/05 5pp 18360 067 24X Fiche 50-445, 83/05/05.8305070558
- --8305090625 Affidavit of TO Dunning re ASLB 830407 telcon question on reactor trip (scram) sys & conformance w/IEEE-279 Prof qualifications enci
 DUNNING: TO Instrumentation & Control Systems Branch 83/05/05
 6pp 18360 072 24X Fiche 50-445,83/05/05,8305090568
- --8305090632 Affidavit of WP Haase re ASLB 830407 telcon questions on NRC interpretation of 10CFR30, App B Prof qualifications enci HA885 W P GA Branch. 83/05/05 3pp 18360 078 24X Fiche 50-445,83/05/05,8305090568
- --8305090640 Affidavit of CE Rossi re ASLB 830407 telcon questions concerning status of NRC position on Unresolved Bafety Issue A-9, "ATHS " Prof qualifications encl ROSBI.C E Instrumentation & Control Systems Branch 83/05/05 5pp 18360 083 24% Fiche 50-445.83/05/05.8305090568
- --8305090646 Affidavit of AJ Szukiewicz & TG Dunning re ABLB 830407 questions on Unresolved Safety Issue A-47. "Safety Implications of Control Sys " Praf qualifications enci SZUKIEHICZ: A J Generic Issues Branch DUNNING: T O Instrumentation & Control Systems Branch 63/05/05 9pp 18360 093 24X Fichs 50-445.83/05/05.8305070568
- --8305090650 Affidavit of RQ Yaylor re ASLD 830407 telcon questions on use of superstrut matl
 TAYLOR.R.G Region 4: Office of Director 83/05/05 2pp
 18360 102 24X Fiche 30-445.83/05/05,8305090568

ao re ASLB 830407 telcon questions on "Alleged Dasign Deficiency "

.earing Branch 83/05/05 5pp 15,83/05/05,8305090568

- --8305090460 Testimony of AB Beach re const appraisal team insp concerning pipe support const a pipe support design interfaces w/const Prof qualifications encl BEACH.A B Director's Office. Office of Inspection and Enforcement 83/05/05 4pp 18360 109 24X Fiche 50-445,83/05/05.8305090568
- 8305090560 Notice of 830612-17 evidentiary hearings re const appraisal tram QA study Limited appearance statements will be disallowed BLOCH P 8 Atomic Safety and Licensing Board Panel 83/05/06 1p 18360 153 24X Fichs 50-445
- 8305100270 Confirms ABLB response to util question re delegation of authority to county judges to make decisions concerning radiological emergency protective action notification & recommendations
 REYNOLDS:N S Debevoise & Liberman REYNOLDS:N B Taxas Utilities
 Generating Co 83/05/06 BLOCH.P B Atomic Safety and Licensing
 Board Panel 1p 18371 338 24X Fiche 50-445.83/05/06.8305100270
- 8305100321 Forwards drawing of upper lateral restraint ref in J Doyle
 830426 rebuttal testimony
 REYNDLDS,N S Debevoise & Liberman REYNDLDS,N S Texas Utilities
 Generating Co 83/05/06 BLDCH,P B Atomic Safety and Licensing
 Board Panel 2pp 18370 071 24X Fiche 50-445,83/05/06,8305100321
- 8305110332 Requests info re introduction into evidence of const & appreisal team insp & investigation repts by NRC ELLIS, J Citizens Association for Sound Energy 83/05/06 ROTHECHILD, M U Office of the Executive Legal Director 1p, 18406 147 24X Fiche 50-445,83/05/06.8305110332
- 830511036B Discusses proposed stipulation re listed Citizens Assoc for Bound Energy discovery matters ELLIS.J Citizens Association for Sound Energy 83/05/06 ROTHSCHILD, N U Office of the Executive Legal Director. 2pp 18406 077 24x Fiche 50-445.83/05/06.830511036B
- 8305ii0377 Submits list of stipulations re Citizens Assoc for Sound Energy exhibits for verification of authenticity & possible admission into evidence ELLIS.J Citizens Association for Sound Energy 83/05/06. HORIN.N Pabevoise & Liberman 2pp 18406 195 24X Fiche 50-445,83/05/06, 8305ii0397
- B305110357 Response opposing NRC B30505 motion to withdraw Bept 1982 prefiled testimony Certificate of Svc encl.
 ELLIS.J Citizens Association for Bound Energy B3/05/07. Atomic Safety and Licensing Board Panel 4pp 18406 082 24X Fiche 30-445.83/05/07.8305110357
- 8305100267 Forwards original signed pages to JB Marshall, DH Wade, JC Finneran & DR Woolan affidavits filed on 830505.

 HORIN, W A Debevo(se & Liberman HORIN, W A Texas Utilities Generating Co 83/05/09 BTUCKY, S W Docketing & Services Branch 5pp 18371 236 24X Fiche 50-445, 83/05/09, 8305100267.
- 8305100295 Answer opposing Citizens Assoc for Sound Energy motion for discovery re-const appraisal team rept Discovery requests unnecessary.cumulative.undusly burdensome & untimely. Certificate of Svc encl.
 REYNOLDS,N S Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 83/03/09 Atomic Safety and Licensing Board Panel. App 18371-235 24X Fiche 50-445,83/03/09,8305100295.
- 8305130066 Motion to allow addi supplementary surrebuttal testimony of J Doyle, witness for intervenor Receipt of drawing creates need to revise previous testimony ELLIS. J Citizens Association for Sound Energy 83/05/09. Atomic 8sfety and Licensing Board Panel 2pp 18436.331 24X Fiche 50-445,83/05/09.8305130066
- B305130175 Response to ABLB B30506 request for discussion of interrelationship of ASME App XVII. Section 2271 3, to rest of ASME Code App is mandatory & integral part of ASME Code & is applicable to pipe supports Certificate of Svc encl ELLER. J Citizens Association for Sound Energy B3/05/09 34pp. 18437 303 24x Fichs 50-445,83/05/09,8305130170.
- 8305130013 Answer to Citizens Assoc for Sound Energy B30428 motion for discovery Answers to interrogatories filed as limited discovery on IE Const Appraisal Insp Repts 50-445/83-12 & 50-445/83-12 relevant ROTHSCHILD, M U Hearing Branch i 83/05/11 Atomic Safety and Licensing Board Panel Spp 18437 133 24X Fiche 50-445,83/05/11, 8305130013
- --8305130021 Answers to fourth set of interrogatories & requests to produce BEACH.A B Director's Office, Office of Inspection and Enforcement 83/05/11 Citizens Association for Sound Energy. 12pp. 18437 136 24X Fiche 50-445,83/05/11,8305130013

- B305130033 Response to ABLB inquiry re ASME Boiler & Pressure Vessel Code App XVII App delineates requirements & stress limits for analysis of linear pipe supports MIZUNO, 6 Shearing Branch 1 B3/05/11 3pp 18437 094 24X Fiche 50-445.83/05/11,8305130033
- --B305130040 Affidavit of RJ Bosnak re App XVII-2000 requirements & stress limits for linear elastic analysis of linear pipe supports Article XVII-2271 3 requires appropriate design consideration be given Certificate of Svc encl BOSNAK.R J Dffice of Nuclear Reactor Regulation, Director 83/05/11 4pp 18437 097 24X Fiche 50-445,83/05/11,8305130033
- 8305130260 Supplemental reply brief re pipe support design
 Consideration of thermal expansion of supports not required
 in design of linear-type pipe supports Certificate of Svc
 encl
 REYNOLDS.N S , HORIN, W A Texas Utilities Generating Co
 REYNOLDS.N S Debevoise & Liberman B3/03/11 Atomic Safety and
 Licensing Board Panel 7pp 18439 244 24X Fiche 50-445,83/05/11,
 B305130260
- B305170287 Forwards improved drawing received from applicant in response to request re Citizens Assoc for Sound Energy Exhibit 763 (J Doyle B30504 supplemental surrebuttal testimony) ELLIB, J Citizens Association for Sound Energy B3/05/11 BLOCH, PB, MCCOLLOM, KA, JORDAN, WH Atomic Safety and Licensing Board Panel 3p 18463 354 24X Fiche 50-445, B3/05/11, B305170287
- 8305170513 Forwards add1 exhibits to assist in reaching stipulations prior to hearings W/o encl ELLIB. J Citizens Association for Sound Energy 83/05/11 ROTHBCHILD, M U Hearing Branch 1 REYNOLDS, N S Debevoise & Liberman 2pp 18470 009 24X Fichs 50-445,83/05/11,8305170513
- 8305160147 Forwards AB Beach 830511 signed affidevit & prof qualifications to NRC 830511 answers to Citizens Assoc for Bound Energy fourth set of Interrogatories ROTHBCHILD.H U Hearing Branch 1 83/03/12 ELLIB.J Citizens Association for Bound Energy 3pp 18446 101 24X Fiche 30-445.83/05/12.8305160147
- B305200504 Forwards B30513 ltr transmitted to Region IV & util in response to ASLB directive re cross-examination document delivery. ELLIS, J. Citizens Association for Sound Energy B3/05/16 BLOCH, P B , JORDAN, W H , MCCOLLOM.K A Atomic Bafety and Licensing Board Panel 1p 18514 086 24X Fiche 30-445,83/05/16,8305200504
- 8305200554 Order extending time until 830527 for Commission to act to review ALAB-714
 CHILK, B. J. Office of the Secretary of the Commission 83/05/19
 Commissioners 1p 18519 091 24X Fiche 50-445,83/05/19,
- B305270015 Forwards NB Le.DC Ford,P Keshishian,RM Compton,GC Gower, HW Phillips & HA Hansen prof qualifications Individuals listed in NRC answer to Interrogatory 1 (fourth set) & requests to produce ROTHBCHILD,N.U Hearing Branch 1 83/05/26 ELLIS,J Citizens Association for Sound Energy 10pp 18633 352 24X Fiche: 50-445, 83/05/26, 8305270015
- 8305310011 Order extending time until 830606 for Commission to act to review ALAB-714
 CHILKS J. Diffice of the Secretary of the Commission 83/05/27
 Commissioners ip 18653 237 24X Fiche 50-445,83/05/27,8305310011
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B305160138 Forwards Amend 40 to FBAR

 QARY,R J Texas Utilities Generating Co 83/05/09 DENTON;H R

 Office of Nuclear Reactor Regulation, Director 2pp 18446.190

 24% Fichs. 50-445; 83/05/07; 8305160138
- --8305160141 Amend 40 to FBAR * Texas Utilities Generating Co 83/05/09 397pp 18446:194 24X Fiche, 50-445, 83/05/09, 8305160138
- O, Inspection reports, IE Bulletins & correspondence
- 8212060395 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin 80sceptibility to Exothermic Chemical Reaction " 8vc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp. 18308 319 24X Fiche 50-000-83/03/21,8212060885.

- 8305100093 Confirms plan to perform independent verification insp on 830429-0906 Addl info to required documentation packages for 47 welds selected for independent verification requested by 830411 GAGLIARDD. J.E. Division of Resident, Reactor Project & Engineering
- B305120145 Forwards IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Executive summary of results & list of pokential enforcement actions encl Region IV will address findings at later date DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 83/04/11 OARY,R J Texas Utilities Generating Co 10pp 18427 262 24X Fiche 50-445,83/04/11,8305120145
- ---8305120155 IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on B30124-0204 & 0214-0303 Major areas inspected electrical & instrumentation const.mechanical const.welding & NDE & civil & structural const
 BEACH.A B . KESHISHIAN.P I . GOMER.O C Reactor Construction Branch 83/04/08 89pp 18427 270 24X Fiche 30-445,83/04/11. 8305120145
- 8305100247 Forwards IE Insp Rept 50-445/83-13 on 830307-11 No noncompliance noted MADSEN.G L. Region 4. Office of Director 83/04/13 GARY,R J Texas Utilities Generating Co 2pp 18373 279 24X Fiche 50-445.83/04/13.8305100247
- --B305100249 IE Insp Rept 50-445/83-13 on B30307-11 No noncompliance noted Major areas inspected review of electrical instrumentation cable quality records k review of QA audits of electrical instrumentation & cables HULKIKIN,R P. HUNNICUTT,D M. WESTERMAN,T F. Region 4, Office of Director 83/04/07 5pp 18373 281 24X Fiche 50-445.83/04/13.8305100247
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Int 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice B3-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDANNE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Natice 83-23, "Inoperable Containment Atmosphere 8ensing Sys " Svc list encl JORDAN: EL Division of Emergency Preparadness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 30-000.83/04/25,8303040025
- B305120610 Informs that commitments resistent & method of siam of preservice insp program consistent winservice exams, based on Reg Guide I 150 Preservice siam plan described in B30301 itr acceptable provided plan completed before B40115 YOUNOBLOOD, B J Licensing Branch I B3/04/27 GARY, R J Texas Utilities Generating Co 2pp 18440 354 24X Fiche 30-445, B3/04/27, B305120610
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18392 047, 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JDROAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8305170309 Forwards IE lnsp Rept 50-445/83-08 on 830301-31 & notice of violation MADSEN,O L. Region 4. Office of Director 83/04/29 GARY,R J Taxas Utilities Generating Co 2pp 18466 001 24X Fichs 50-445,83/04/29.8305170309
- --B305170313 Natice of violation from insp on 830301-31 * Region 4, Office of Director 82/04/27 ip 18466 003 24X Fiche 50-4450-83704/29,8305170309
- --8305170318 IE Insp Rept 50-445/83-08 on 830301-31 Noncompliance noted failure to review change to Rev O to Procedure IPO-001A, "Plant Stantup from Cold Shutdown"

 KELLEY,D L , MCCRORY,B L , WESTERMAN,T F Region 4, Office of Director 83/04/28 lipp 18466 004 24X Fiche 50-445,83/04/29,8305170309

- 830304002B IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24x Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50~000.83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list enct JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305160240 Board Notification 83-290 provides 830413 meeting summary describing continuing discussion between NRC & util on need for program to assure adequate plant design & const.as result of const appraisal team insp NOVAK.T M Assistant Director for Licensing 83/05/04 Atomic Safety and Licensing 80ard Pamel 4pp 18471 351 24X Fiche 50-445.83/05/04.8305160240
- --8305160244 Summary of 830413 meeting w/util in Bethesda,MD re misunderstanding between util & NRC on need for added assumance that plant designed & contructed in accordance w/ application Results of const appraisal team insp discussed BURNELLS B Licensing Branch 1 83/05/04 Licensing Branch 1 6pp 18471 354 24X Fiche 50-445.83/05/04.8305160240
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8305120373 Informs that IE Insp Rept 50-455/83-05 canceled No rept will be issued under subj number MADSEN.G L. Region 4, Office of Director 83/05/09 GARY.R J Teras Utilities Generating Co. Ip 18432 280 24X Fiche 50-445,83/05/09,8305120373
- B303040034 IE Info Notice B3~30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305230445 Forwards IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted MADSEN.9 L Region 4, Office of Director 83/05/13 GARY,R J Teras Utilities Generating Co 2pp 18538 178 24X Fiche 50-445,83/05/13,8305230445
- --8305230449 IE Insp Repts 50-445/83-12 & 30-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted Major areas inspected followup of unresolved items in IE Insp Repts 50-445/82-26, 50-446/82-14 & 50-445/82-22
 TAPIA, J I CHEN, N P , HUNNICUTT, D M Region 4, Office of Director 83/05/03 8pp 18538 180 24X Fiche 50-445/83/05/13, 8305230445
- 8305200416 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-03 & 50-445/83-01 MADSEN, 0 L. Region 4, Office of Director 83/05/18 GARY, R. J. Teras Willities Generating Co. 1p 185/8 124 24X Fiche 50-445,83/05/18,8305200416
- --8305200419 Responds to NRC B30328 ltr re violations noted in IE Insp. Repts 50-445/83-01 Corrective actions light poles will be inspected & Items designated non-nuclear safety-related reviewed & upgraded GARY.R J Teras Utilities Generating Co B3/04/25. MADSEN. Region 4. Office of Director 3pp 18518 125 24X Fiche 50-445,83/05/18,8305200416
- B305200666 Ark receipt of B30415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 MADBEN.C L Region 4. Office of Director B3/05/18 QARY.R J Texas Utilities Generating Ca 1p 18519 Q95 24X Fire- 90-445,83705/18,8305200666

- --8305200674 Responds to NRC 830314 ltr re violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 Corrective actions const personnel will be reinstructed in necessity for rigid compliance w/design & procedural requirements GARY,R J Texas Utilities Generating Co 83/04/15 MADBEN, 0 L Region 4, Office of Director 3pp 18519 096 24X Fiche 50-445,83/05/18,8305200666
- B303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040
- 8303240003 Forwards IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted MADSEN,G L Region 4, Office of Director 83/05/20 9ARY,R J Texas Utilities Generating Co 2pp 18549 139 24X Fiche 50-445,83/05/20,8305240003
- ---8305240005 IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted Major areas inspected radwaste program & transportation activities, including organization, training, radwaste sys mgt.effluent release controls & procedures BAER,R E . MURRAY,B , WESTERMAN,T F Region 4, Dffice of Director. 83/05/19 34pp 18549 141 24X Fiche 50-445,83/05/20,8305240003
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, B3/05/26, B303040046
- R. Periodic operating reports & related correspondence
- B305100130 Forwards "Reactor Containment Bldg Unit 1 Preoperational Integrated Leak Rate Test. 1983 " Electrical penetrations leaked excessively during testing Further testing to determine cause of leakage in progress SCHMIDT.H C Texas Utilities Services, Inc B3/05/06, DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18370:145 247 Fichs 50-445,83/05/06,8305100130
- --B305i00135 "Reactor Containment Bldg Unit 1 Preoperational Integrated Leak Test: 1783 "
 * Texas Utilities Services, Inc B3/12/31 33pp. 18970 146. 24X Fiche 50-445: 83/05/06: 8305100130
- S Reportable occurrences: LERs & related correspondence
- B30520029B Interim Deficiency Rept SDAR-106 re HVAC hangers fabricated at variance w/design Initially reported on B30301. Completion of evaluation anticipated by B30705 GARY, R J Texas Utilities Generating Co B3/05/11 MADSEN, G L. Region 4. Office of Director ip 18516.273. 24X Fiche 50-445, B3/05/11, B305200298
- 8305240356 Part 21 rept re bolting parts for ABME III NF Class i pipe supports on rigid struts or pipe clamps for struts or snubbars Initially reported on 830513. Boiting parts greater than 2-inch size not examined HOVI.L NPB Industries: Inc 83/05/16 DEYOUNG.R C Director's Office: Office of Inspection and Enforcement 1p 18574'001 24% Fiche 50-000.83/05/16.8305240356
- T Hearing transcripts on non-antitrust matters
- 8305020156 Corrected transcript of 830407 telephone conference in Bethesda:MD Pp 1-132 * Abomic Safety and Licensing Board Panel 83/04/07, 135pp 18272 228 24X Fiche 50-445,83/04/07,8305020156
- B305040507 Forwards J Doyle surrebuttal testimony.

 ELLIS, J Citizens Association for Sound Energy. B3/04/26
 BLOCH, P B , JORDAN, H, H, MCCOLLUM, K, A Atomic Safety and Licensing Board Panel ip 18319 146 24X Fiche 50-445,83/04/26,8303040507

DOCKETED ITEMS

- --8305040515 Burrebuttal testimony of J Doyle re consideration of LOCA in design criteria for pipe supports Results of hand calculations supported by computer analysis indicate gross error in fundamental approach Certificate of Svc encl DOVLE-J Citizens Association for Sound Energy 83/04/26 89pp 18319 147 24X Fiche 50-445.83/04/26.8303040507
- B305040535 Supplemental surrebuttal testimony of J Doyle re severe minor & offsetting errors in computer analysis Certificate of Svc encl DDYLE, J Citizens Association for Sound Energy 83/04/28 Bpp 18321 263 24X Fiche 50-445.83/04/28,8305040535
- 8305110157 Surrebuttal testimony of MA Walsh Certificate of Svc encl Related correspondence HALSH-H A Citiems Association for Sound Energy 83/05/04 7pp 18407 ii2 24X Fiche 50-445.83/05/04.8305110157
- B305110354 Supplemental surrebuttal testimony of J Doyle re special insp team Insp Repts 50-445/B2-26 & 50-446/B2-14 Related correspondence DOYLE, J Citizens Association for Sound Energy B3/05/04 42pp 18406 086 24X Fiche 50-445/B3/05/04.B305110354
- 8305070507 Forwards testimony of LJ Skiles.AB Armstrong & CL Born re emergency planning recommendations.A Vega testimony re const appraisal team rept & JS Marshall.DH Wade, JC Finneran & DR Woodlan affidavits Related correspondence REYNOLOS.N S Debevoise & Liberman REYNOLDS.N S Texas Utilities Generating Co 83/05/05 BLOCH.P.B. MCCGLLOM, K A , JGRDAN.W H Atomic Safety and Licensing Board Panel 2pp 18362 014 24X Fiche. 50-445,83/05/05,8305090507
- --8305090510 Testimony of LJ Skiles: AB Armstrong & CL Born on ASLB 830425 telcon questions re adequacy of county judge as emergency plan coordinator SKILES, LJ, ARMSTRONG, AB, BORN, CL Texas, State of 83/05/05 7pp 18362 016 24X Fichs 50-445:83/05/05:8305090507
- --8305070513 Testimony of A Vega re applicant response to 830411 Const Appraisal Team Insp Repts 30-445/83-18 & 50-446/83-12 VEOA.A Texas Utilities Generating Co 83/05/05 3pp 18362 023 24X Fiche 50-445.83/05/05.8305090507
- --B305090517 Affidavit of JB Marshall in response to ASLB inquiry re classification of aquipment for application of IOGR350.App B requirements & relationship of Board Notification 83-13 to HR Denton B11120 memo on classification MARBHALL.J S Texas Utilities Generating Co 83/05/05 7pp 18362 026 24X Fichs 50-445.83/05/05.8305090307
- --8305090521 Affidavit of DH Wade re Midland-Ross superstrut matl (Board Notifications 83-02 & 83-14) & welds in main control board panels (Board Notifications 82-90, 790 & 116) WADE, D H Texas Utilities Generating Co 83/05/05 70pp 18362 033 24X Fichs 50-445,83/05/05,8305090507
- --8305090525 Affidavit of JC Finneran on applicant response to Board Notification 82-105 re pipe clamps employed on ASME Code Class I piping, FINNERAN, J C Texas Utilities Generating Co 83/05/05 3pp 18362 123 24X Fiche 50-445,83/05/05,8305090507
- --8305090530 Affidavit of DR Woodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl WOODLAN.DR Texas Utilities Generating Co. 83/05/05, 12pp 18362 126 24X Fiche 50-445,83/05/05,8305090507
- B305070568 Forwards direct testimony & affidavits in response to questions posed by ASLB during B30407 telcon TREBY, 8 A , ROTHBCHILD, M, U , MIZUNG, G S Hearing Branch 1 83/05/05 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Beard Panel 2pp 18360 001 24X Fiche 50-445,83/05/05,8320500546
- --8305090578 Supplemental testimony of S Burwell, MP Chen, JI Tapia, J Rajan & RO Taylor re concerns raised by MA Walsh & J Doyle & NRC const appraisal insprept Prof qualifications encl BURWELL, S Division of Licensing CHEN.W P Energy, Dept of TAPIA, J. Division of Resident, Reactor Project & Engineering Programs. 83/05/05 14pp 18360 004 24X Fiche 50-445,83/05/05,8305090568
- ---8305090586 Supplemental testimony of DM Rohrer & T Urbanik re emergency preparedness ROHRER, D M Emergency Preparedness Branch URBANIK, T Texas A&M Univ., College Station, TX 83/05/05 20pp 18360.018 24X Fiche 50-445,83/05/05,8305090568

- --B305090592 Supplemental testimony of A Lookabaugh & J Benton re emergency preparedness LOOKABAUGH, A · BENTON, J Federal Emergency Management Agency 83/05/05 | 15pp | 18360 | 038 | 24% Fiche 50-445,83/05/05,8305090568
- --8305090660 Testimony of AB Beach re const appraisal team insp concerning pipe support const & pipe support design interfaces w/const Prof qualifications encl BEACH.A B Director's Office. Office of Inspection and Enforcement 83/05/05 4pp 18360 109 24X Fiche 50-445.83/05/05,8305090568
- B305i30157 Supplementary surrebuttal testimony of J Doyle Error in fundamentals used in calculations for upper lateral restraint compounded by errors in stiffness used in Gibbs & Hill calculations Related correspondence DDYLE.J Citizens Association for Sound Energy 83/05/09 2pp 18437 269 24X Fiche 50-445.83/05/09.8305130157
- 8305230138 Transcript of 830516 hearing in Fort Worth, TX re CL application Pp 5,855-6,169 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/16 408pp 18530 215 24X Fiche 50-445.83/05/16.8305230138
- 8305230147 Transcript of 830517 hearing in Fort Worth, TX Pp 6.287-6.471 Supporting Socumentation encl # Atomic Bafety and Licensing Board Panel 83/05/17 334pp 18529 239 24X Fiche. 30-445.83/05/17.8305930147
- ### 8305250010 Transcript of ### 830518 hearing in Fort Worth.TX Pp 6,472-6,817 Supporting documentation encl ### Atomic Safety and Licensing Board Panel ### 83/05/18 388pp 18384 075 24% Fiche \$0-445.83/05/18.8305250010
- 8305260079 Transcript of 830520 hearing in Fort Worth,TX Pp 7.273-7.485 Supporting documentation encl 83/05/20 319pp * Atomic Bafety and Licensing Board Panel 83/05/20 319pp 18624 046 24X Fiche 50-445.83/05/20.8305260079
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA .UNIT 2

 A Application/construction stage documents & correspondence
- 8305180001 Add1 response to FDIA request for seven categories of documents re Brown & Root. Inc & South Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON.J M Division of Rules and Records 83/03/09 LINDEMAN.H N
 Lowenstein, Neuman, Reis, Axelrad & Toll 6pp 18497 219 24X
 Fiche 50-000.83/03/09.8303180001
- ---8010280578 Responds to Gusstion 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AMS Code STELLO. V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNS. J F Commissioners Spp 18497 228 24% Fiche 50-000, 83/03/09, 8305180001
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting. TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11 PALLADINO, N. J. Commissioners 2pp 18542 272 24X Fiche 50-000.83/04/11.8305230720
- B305090722 Board Notification B3-12 forwards rept. "Design & Const -Belf-Initiated Evaluation," to facilitate general upgrading of plant & industry NDVAK.T M Assistant Director for Licensing, AS BNB3-12 B3/05/02 Atomic Safety and Licensing Board Panel 3pp 18368 291 24X Fiche 30-443.B3/05/02,8305090722
- ---8305090726 "Design & Const Self-Initiated Evaluation,Comanche Peak Steam Electric Station" * Texas Utilities Generating Co 82/10/31 354pp 18368 274 24X Fiche 50-445,83/05/02.8305090722

!

- B305040323 Board Notification B3-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications B3-17 & B3-44 re Unresolved Safety Issue A-17 EISENHUT, D G Division of Licensing B3/05/04 PALLADINO.N Commissioners 22pp 18337 139 24X Fiche 50-000.83/05/04, B305040323
- B305120109 Summary of B30413 meeting w/util in Bethesda, MD re added assurance program to assure independent verification program requirements met BURNELL.S B Licensing Branch 1 83/05/04 Licensing Branch 1 7pp 18443 179 24X Fiche 50-443.83/05/04.8305120109
- 8305100125 Forwards comments on environ qualification correlation between installed & qualified components as followup to 821014 audit trip rept on Item II a, "Auxiliary Bldg Modular Train Filter"

 SCHMIDT: H C Texas Utilities Services, Inc 83/03/05
 YOUNOBLOOD, B J Licensing Branch 1 2pp 18375-029 24X
 Fiche 80-445,83/05/05.8303100125
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 153 24X Fiche 30-000.83/05/09.8305090659
- 8305230627 Forwards request for procedures generation package needed to complete DL application evaluation YCUN08LCOD. B J Licensing Branch 1 83/05/12 GARY, R J Texas Utilities Generating Co App 18543.029 24X Fiche 50-445. 83/05/12,8305230627
- 8303310151 Comments on alternate shutdown reactor heat removal Direct readings of Process variables necessary to perform & control reactor heat removal provided at hot shutdown panel as part of alternate shutdown design 8CHMIDT, H C Texas Utilities Services, Inc 83/05/20 YOUNDBLOOD, B J Licensing Branch i 3pp 18651 221. 24X Fiche 50-445,83/05/20,8305310151
- F Security, medical, emergency & fire protection plans
- 8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness.
 MIZUNG, 6 S Hearing Branch 1 83/04/27 BLOCH, F B Atomic Safety
 and Licensing Board Panel 3pp. 18292 163 24X
 Fiche 30-445, 83/04/29, 8305030464

G Adjudicatory correspondence

- 8305020422 Motion to allow Citizens Assoc for Sound Energy to file written argument on issue in lieu of presenting oral argument at 83019 hearing Citizens do not have finances to come to Bethesda. MD for 40-minute argument ELLIS.J Citizens Association for Sound Energy 83/01/ii, Atomic Safety and Licensing Appeal Panel 2pp 18283 001 24X Fiche 30-445.83/01/ii.8303020422
- --8303020430 Written argument on issues to be argued orally on 830119 in Bethesda.MD Citizens Assoc for Sound Energy unable to attend or find representative Whistleblower protection discussed ELLIS, J Citizens Association for Sound Energy 83/01/11 Atomic Safety and Licensing Appeal Panel 65pp 18283 003 24X Fiche 50-445,83/01/11,8305020422
- ---8305020437 Forwards Citizens Assoc for Sound Energy witness J Doyle affidavit re blacklisting due to testimony at hearings.
 ELLIE, J Citizens Association for Sound Energy 83/01/18
 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel ip 18283 068 24x Fiche: 50-445, 83/01/11, 8305020422
- --8305020444 Affidavit of J Doyle re blacklisting due to testimony at hearings NRC should take immediate & stringent measures to stop insidious practice NRC current protection for whistleblowers is farce & charade Certificate of Svc encl DOYLE. J Affiliation Unknown 83/01/17 4pp 18283-069. 24X Fiche 50-445.83/01/11.8305020422
- 8305040529 Affidavit of MA Walsh re computer program in J Dayle 830426 surrebuttal testimony STRUDL program utilized w/sufficient similarities to assure results will be accurate WALSH.M A Citizens Association for Sound Energy 83/04/26 1p 18320 001 24X Fichs 50-445,83/04/26,8305040529
- B305040276 Motion for discovery re applicant & NRC interrogatories on const appraisal team Insp Repts 50-445/83-18 & 50-446/83-12. Related correspondence ELLIS.J Citizens Association for Sound Energy 83/04/28. Atomic Safety and Licensing Board Panel 3pp 18324 025 24X Fiche 50-445,83/04/28.8305040276

- 8305040499 Fourteenth set of interrogatories & requests to produce Related correspondence ELLIS,J Citizens Association for Sound Energy 83/04/28 Texas Utilities Generating Co 10pp 18322 111 24X Fiche 50-445,83/04/28,8305040499
- B305040513 Fourth set of interrogatories & requests to produce, Related correspondence
 ELLIB, J Citizens Association for Bound Energy B3/04/28 Dffic of the Executive Legal Director 7pp 18321 249 24X
 Fiche 50-445,83/04/28,8305040513
- 8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness, MIIUND,G S Hearing Branch 1 83/04/27 BLOCH,P B . JORDAN W H . MCCOLLOW,K A Atomic Safety and Licensing Board Panel 3pp. 18272 163 24X Fiche 50-445.83/04/29.8305030464
- B303030314 Hotion for protective order that discovery not be had redraft notice of violation on calculation of deflection of rigid support CC-1-107-008-E23R Draft is not final NRC document Certificate of Byc encl ROTHSCHILD: M U Hearing Branch i 83/04/29 Atomic Safety and Licensing Board Panel 7pp 18306 350 24X Fiche. 50-445, 83/04/29, 8305030514
- 8305030522 Order extending time until 830503 for Commission to act to review ALAB-714 CHILK, 8 J Office of the Secretary of the Commission. 83/04/29 Commissioners ip 18306-357 24X Fiche: 50-445, 83/04/29, H308030522
- 8305040531 Advises of NRC agreement to volunterily release one paragraph designated by Judge Bloch as containing factual info possibly relevant to litigation, from draft 821227 notice of violation Paragraph set forth TREBY,8 A Hearing Branch 1 83/05/03 CABE,J Citizens Association for Sound Energy 1p. 18321 241, 24X Fiche 50-445,83/05/03.8305040531
- B305040557 Reply to State of TX brief on collateral estoppel State of TX erred in concluding Dapt of Labor decision should be given collateral estoppel effect Decision not sufficiently firm to be accorded preclusive effect ROTHSCHILD, M U Hearing Branch 1 83/05/03 4pp. 18321 282, 24X Fiche 50-445, 83/05/03, 8305040557
- --8305040560 Reply to Citizens Assoc for Sound Energy brief re consideration of LOCA in design criteria for pipe supports Operability of pipe supports not necessary to assure safety-related component operability W/Certificate of Bvc, MIZUNO.6 9 Hearing Branch 1 83/05/03 9pp. 18321 286, 24X Fiche 50-445,83/05/03,8305040557
- B305050015 Order extending time until 830520 for Commission to act to review ALAB-714 CHILK,8 J. Diffice of the Becretary of the Commission. 83/05/03 Commissioners, ip 18339 055 24X Fiche 50-445,83/05/03,8305050015
- B3050500iB Reply brief to Citizens Assoc for Sound Energy 830420 brief re consideration of effects of LDCA on pipe support design. Citizens erronsously applied provisions of ASME Code not applicable to design Certificate of Svc encl. REVNOLDS.N S , HORIN,W A Texas Utilities Cenerating Co. REVNOLDS.N S Debevoise & Liberman. B3/05/03 2ipp. 18398 334. 24X Fiche: 50-445, 83/05/03, 8305050018,
- B305090443 Response in opposition to NRC B30420 response to ABLB question re L0CA-induced thermal expansion in linear supports & applicant B30421 brief on consideration of pipe support design thermal stresses W/Certificate of Bvc. ELLIB.J Citizens Association for Sound Energy, B3/03/03. Atomic Bafety and Licensing Board Panel, 25pp. 18363-001 24X Fiche 30-445,83/05/03,8305090443.
- 8305110137 Responds to 830504 request to review proposed protective agreement between Citizens Assoc for Sound Energy & ITT-Orinnel re design criteria for pipe supports Wording too restrictive. Revised proposel anci for review, ELLIS.J Citizens Association for Sound Energy 83/05/04, HORIN.W Debryotes & Liberman. 4pp 18393-344 24X Fiche: 50-445,83/05/04,8305110137
- 8305110347 Certifies svc of J Doyle 830504 supplemental surrebuttal testimony.
 ELLIBJ. Citizens Association for Sound Energy. 83/05/04 2pp. 18404.158 24X Fiche 50-445.83/05/04,8305110347

- 8305090507 Forwards testimony of LJ Skiles, AB Armstrong & CL Born re amergency planning recommendations, A Vega testimony re const appraisal team rept & JS Marshall, DH Wade, JC Finneran & DR Hoodlan affidavits Related correspondence REVNOLDS, N B Debevoise & Liberman B3/05/05 BLOCH, P B Atomic 84fety and Licensing Board Panel 2pp 18362 014 24X Fiche 50-445,83/05/05,8305090507
- --8305090517 Affidavit of JS Marshail in response to ASLB inquiry re classification of equipment for application of 10CFR50.App B requirements & relationship of Board Notification 83-13 to HR Denton 811120 memo on classification MARFIALL.J S Texas Utilities Generating Co 83/05/05 7pp 18342 026 24X Fiche 50-445.83/05/05.8305090507
- --8305090521 Affidavit of DH Wade re Midland-Ross superstrut matl (Board Notifications 83-02 & 83-14) & welds in main control board panels (Board Notifications 82-90, 90A & 116) HADE, DH Texas Utilities Generating Co 83/05/05 90pp 18362 033 24X Fiche 50-445, 83/05/05, 8305090507
- --8305090525 Affidavit of JC Finneran on applicant response to Board Notification 82-105 re pipe clamps employed on ASME Code Class I piping FINNERAN.J C Texas Utilities Generating Co 83/05/05 3pp 18362 123 24X Fiche 50-445,83/05/05,8305090507
- --B305070530 Affidavit of DR Hoodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl HOODLAN,D R Texas Utilities Generating Co 83/05/05 12pp 18362 126 24X Fiche 50-445,83/05/05,8305070507
- 8303090368 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon TREBY.8 A . ROTHSCHILD, M U . MIZUND, G S Hearing Branch 1 83/03/05 BLOCH, P B . JORDAN, W H . MCCOLLDM. K A Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445,83/05/05,830300058
- --8305090600 Affidavit of 8B Burwell re questions posed during ASLB 830407 telcon on implemented procedures concerning maint of scram breakers as result of Board Notifications 83~26 & 83-38 Prof qualifications encl BURNELLE B Licensing Branch i 83/05/05 5pp 18360 053 24X Fiche 50~449.83/05/05.8305090568
- --B305090607 Affidavit of FD Coffman on Unresolved Bafety Issue A-17, "Sys Interaction in Nuclear Power Plants." per ASLB 830407 telcon request Prof qualifications encl COFFMAN.F D Reliability & Risk Assessment Branch 83/03/05 9pp 18360 058 24X Fiche 50-445,83/03/05,8305090568
- --8305090618 Affidavit of 8 Diab re semiscale feed & bleed Experiment 8-8R-2 & related subsequent RELAP-5 analyses, per ABLB 830407 telcon request Prof qualifications encl DIAB.S. Reactor Systems Branch 83/05/05 5pp. 18360 067 24X Fiche 50-445,83/05/05,8305090568
- --8305090625 Affidavit of TO Dunning re ASLB 830407 telcon question on reactor trip (scram) sys & conformance w/IEEE-279 Prof qualifications encl DUNNING.T 9 Instrumentation & Control Systems Branch 6pp 18360 072 24X Fiche 50-445,83/05/05,8305090568
- --8305070632 Affidavit of WP Haass re ASLB 830407 telcon questions on NRC interpretation of IOCFR50, App B Prof qualifications encl HAASS, W P QA Branch 83/05/05 5pp 18360 078 24X Fiche 50-445, 83/05/05, 8303090568
- --8305090640 Affidavit of CE Rossi re ASLB 830407 telcon questions concerning status of NRC position on Unresolved Safety Issue A-9. "ATMS " Prof qualifications encl ROSSI C E Instrumentation & Control Systems Branch. 83/05/05 3pp 18360 083. 24X Fiche 50-445,83/05/05.8305090568
- --8303070646 Affidevit of AJ Siukiswicz & TO Dunning re ASLB 830407 questions on Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Prof qualifications encl SZUKIEWICZ: A J Generic Issues Branch DUNNING, T G Instrumentation & Control Systems Branch 83/05/05, 9pp 18360 093 24X Fiche 50-445,83/05/05,8305090568
- --8305090650 Affidavit of RG Taylor re ASLB 830407 telcon questions on use of superstrut matl
 TAYLOR,R O Region 4. Office of Director 83/05/05 2pp
 18360 102 24X Fichs 50-445,83/05/05,8305090368

- --8305090654 Affidavit of D Terao re ASLB 830407 telcon questions on Board Notification 82-105, "Alleged Design Deficiency" Prof qualifications encl
 TERAO, D Mechanical Engineering Branch 83/05/05 5pp
 18360 104 24X Fiche 30-445,83/05/05,8305090568
- 8305090360 Notice of 830612-17 evidentiary hearings re const appraisal team GA study Limited appearance statements will be disallowed BLOCH.P B Atomic Safety and Licensing Board Panel 83/03/06 Ip 18360 153 24% Fiche 50-445.83/05/06,8305090360
- B305100270 Confirms ABLB response to util question re delegation of authority to county judges to make decisions concerning radiological emergency protective action notification 5 recommendations
 REYNOLDS.N S Debevoise & Liberman REYNOLDS,N S Texas Utilities Generating Co 83/05/06 BLOCH-P B Atomic Safety and Licensing Board Panel 1p 18371 338 24X Fiche 50-445,83/05/06,8305100270
- B305100321 Forwards drawing of upper lateral restraint ref in J Doyle B30426 rebuttal testimony REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Texas Utilities Generating Co B3/05/06 BLOCH,P B Atomic Safety and Licensing Board Panel 2pp 18370 091 24X Fichø 50-445,83/05/06.8305100321
- 8305110332 Requests info re introduction into evidence of const & appraisal team insp & investigation repts by NRC ELLIS. J Citizens Association for Sound Energy 83/05/06 ROTHSCHILD, M U Office of the Executive Legal Director ip 18406 147 24% Fiche 50-445,83/05/06,8305110332
- 8305110368 Discusses proposed stipulation re listed Citizens Assoc for Sound Energy discovery matters ELLIS.J Citizens Association for Sound Energy 83/05/06 ROTHSCHILD.M U Office of the Executive Legal Director 2pp 18406 077 24X Fiche 50-445.83/05/06.8303110368
- 8305110397 Submits list of stipulations re Citizens Assoc for Sound Energy exhibits for verification of authenticity & possible admission into evidence ELLIS. J Citizens Association for Sound Energy 83/05/06 HORIN, N Debevoise & Liberman 2pp 18406 195 24X Fiche 50-445, 83/05/06, 0301510307
- 8305110357 Response opposing NRC 830505 motion to withdraw Sept 1982 prefiled testimony Certificate of Svc encl ELLIS.J Citizens Association for Sound Energy B3/05/07 Atomic Safety and Licensing Board Panel 4pp 18405 082 24X Fiche 50-445,83/05/07.8305110357
- B305100267 Forwards original signed pages to JS Morshall, DH Wade, JC Finneran & DR Woolan affidavits filed on 830505 HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co B3/05/09 STUCKY, S W Docketing & Services Branch 5pp 18371 236 24X Fiche 50-443, 83/05/09, 8305100267
- 8305100295 Answer opposing Citizens Assoc for Sound Energy motion for discovery re const appraisal team rept Discovery requests unnecessary.cumulative.unduly burdensome & untimely Certificate of Svc encl REYNOLDS:N S Texas Utilities Generating Co REYNOLDS:N S Debevoise & Liberman 83/05/09 Atomic Safety and Licensing Board Panel App 18371 255 24X Fiche 50-445.83/05/09.8305100295
- 8305130066 Motion to allow add1 supplementary surrebuttal testimony of J Doyle, witness for intervenor Receipt of drawing creates need to revise previous testimony ELLIS, J Citizens Association for Sound Energy 83/05/09, Atomic Safety and Licensing Beard Panel 2pp 18436 331 24X Fiche 50-445,83/05/09,8305130066
- 8305130175 Response to ASLB 830506 request for discussion of interrelationship of ASME App XVII, Section 2271 3, to rest of ASME Code App is mandatory & integral part of ASME Code & is applicable to pipe supports Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 83/05/09 34pp 18437 303 24X Fiche 50-445,83/05/09.8305130175
- 8305130013 Answer to Citizens Assoc for Sound Energy 830428 motion for discovery Answers to interrogatories filed as limited discovery on IE Const Appraisal Insp Repts 50-445/83-18 & 30-446/83-12 relevant ROTHECHILD: M U Hearing Branch 1 83/05/11 Atomic Safety and Licensing Board Panel 3pp 18437 133 24X Fiche 50-445/83/05/11, 8305130013
- --8305130021 Answers to fourth set of interrogatories & requests to produce BEACH.A B Director's Office. Office of Inspection and Enforcement 83/05/11 Citizens Association for Sound Energy 12pp 18437 13A 24X Fichs 50-445,83/05/11,8305130013

- 8305130033 Response to ASLB inquiry re ASME Doiler & Pressure Vessel Code App XVII App delineates requirements & stress limits for analysis of linear pipe supports MIZUNO.6 S Hearing Branch I 83/05/11 3pp 18437 094 24X Fiche 50-445.83/05/11.8305130033
- --8305130040 Affidavit of RJ Bosnak re App XVII-2000 requirements & stress limits for linear elastic analysis of linear pipe supports Article XVII-2271 3 requires appropriate design consideration be given Certificate of Svc encl BOSNAK, R J Office of Nuclear Reactor Regulation, Director 83/05/11 4pp 18437 097 24X Fiche 50-445, 83/05/11, 8305130033
- B305130260 Supplemental reply brief re pipe support design.
 Consideration of thermal expansion of supports not required in design of linear-tupe pipe supports Certificate of Svc enc.
 REYNOLDS,N S . HORIN,N A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman B3/03/11. Atomic Safety and Licensing Board Panel 7pp 18439 244 24% Fiche 50-445,83/05/11,8305130260
- 8305170287 Forwards improved drawing received from applicant in response to request re Citizens Assoc for Sound Energy Exhibit 763 (J Doyle 830504 supplemental surrebuttal testimony)
 ELLIS.J Citizens Association for Sound Energy 63/09/11
 BLOCH,P B. MCGULOM,K A., JORDANNH H. Atomic Safety and Licensing Board Panel 3pp 18465 354 24X Fiche 30-445.83/05/11.8305170287
- B305170513 Forwards add] exhibits to assist in reaching stipulations prior to hearings H/o encl.
 ELLIS.J Citizens Association for Sound Energy 83/05/11
 RQTHSCHILD.M U Hearing Branch 1 REYNOLDS.N S Debevoise & Liberman 2pp 18470 009 24X Fiche 50-445.83/05/11.8305170513
- 8305160147 Forwards AB Beach 830511 signed affidavit & prof qualifications to NRC 830511 answers to Citizens Assoc for Sound Energy fourth set of interrugatories ROTHSCHILD.M U Hearing Branch I 83/03/12 ELLIB.J Citizens Association for Sound Energy 3pp 18446 101 24X Fiche: 30-445, 83/03/12, 8305160147
- 8305200504 Forwards B30513 ltr transmitted to Region IV & util in response to ASLB directive re cross-examination document delivery
 ELLIS.J Citizens Association for Sound Energy 83/05/16
 BLOCH.P B . JORDAN.H H . MCCOLLOM.K A Atomic Safety and Licensing Board Panel ip 18314 086 24X Fiche 50-445,83/05/16,8305200504
- 8305200694 Order extending time until 830527 for Commission to act to review ALAB-714
 CHILK, S. Office of the Sacretary of the Commission 83/05/19
 Commissioners ip 18519 091 24X Fiche 50-445,83/05/19,
- B305270015 Forwards NB Le.DC Ford.P Keshishian.RM Compton.GC Gower.
 HW Philips & WA Mansen prof qualifications individuals
 listed in NRC answer to Interrogatory 1 (fourth set) &
 requests to produce
 RUTHSCHILD.M U Hearing Branch 1 B3/05/26 ELLIS.J Citizens
 Association for Sound Energy 10pp 18633 352 24X
 Fiche 50-445,83/05/26,8305270015
- B305310011 Order extending time until B30606 for Commission to act to review ALAB-714 (HILK, 8 J Office of the Secretary of the Commission B3/05/27 Commissions ip 18653 239 24X Fiche 50-445, B3/05/27, 3705310011
- K Utility Final Safety Analysis Report (FSAR) & amends
- B30516013B Forwards Amend 40 to FSAR GARY.R J Texas Utilities Generating Co B3/05/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18446 170 24X Fichs 50-445.83/05/09,830516013B
- --8305160141 Amend 40 to FSAR

 * Texas Utilities Operating Co 83/05/09 397pp. 18446'194
 24% Fiche 50-445,83/05/09,8305160138
- Q. Inspection reports, IE Bulletins & correspondence
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exchangic Chemical Reaction " Svc list encl TAYLOR, J M Division of Sefeguards & Inspection Programs (Post 830103), 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

- 8305100093 Confirms plan to perform independent verification insp on 830425-0306 Add1 info re required documentation packages for 47 welds selected for independent verification requested by 830411 GACLIARDD. J E Division of Resident, Reactor Project & Engineering Programs 83/04/11 GARY, R J Texas Utilities Generating Co 8pp 18377 266 24X Fiche 30-445,83/04/11,8305100093
- 8305120145 Forwards IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Executive summary of results & list of potential enforcement actions encl Region IV will address findings at later date DEVOUNO.R C Director's Office, Office of Inspection and Enforcement 83/04/11 GARY.R J Texas Utilities Generating Co 10pp 18427 262 24X Fiche 50-445.83/04/11.8305120145
- --8305120155 IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Major areas inspected electrical & instrumentation const, mechanical const, welding & NDE & civil & structural const BEACH, A B , KESHISHIAN, P I , OUMER, O C Reactor Construction Branch 83/04/08 B9pp 18427 270 24X Fiche 50-445, 83/04/11, 8305120145
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Evc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures."

 8vc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidate Edison Co. of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoparable Containment Atmosphere Bensing Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York
- 8305120610 Informs that commitments relextent & method of exam of preservice insplangements consistent w/inservice exams, based on Reg Quide I 150. Preservice exam plan described in 830301 Itracceptable provided plan completed before 840115 YOUNGBLOOD, B. J. Licensing Branch I 83/04/27 GARY, R. J. Texas Utilities Generating Cd. 2pp 18440 354 24X Fiche 50-445, 83/04/27.8303120610
- 6303040026 IE Info Notice 83-24, "Loose Parts in Becondary 8ide of Steam Generators at PWRs " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441·170 24X Fichs 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl UDRDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/03/04 Consolidated Edison Co. of New York, Inc. i12pp 18382 282, 24X Fichs. 50-000, 83/05/04, 8303040030.
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001, 24X Fiche 50-000,83/05/04,8303040031
- 8305160240 Board Notification 83-29C provides 830413 meeting summary describing continuing discussion between NRC & util on need for program to assure adequate plant design & const.as result of const appreisal team insp NDVAK.T M. Assistant Director for Licensing, 83/05/04. Atomic Safety and Licensing Board Panel 4pp 18471 351 24X Fiche 30-445.83/05/04.8305160240

- --8305160244 Summary of B30413 meeting w/util in Bethesda.MD re misunderstanding between util & NRC on need for added assurance that plant designed & contructed in accordance w/ application Results of const appraisal team insp discussed BURWELL,S B Licensing Branch 1 B3/05/04 Licensing Branch 1 Gpp 18471 354 24X Fiche 50-445.83/05/04,8305160240
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Evc list enc! JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Cansolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305230445 Forwards IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted MADSEN.9 L Region 4, Office of Director 83/05/13 GARY, R J Texas Utilities Generating Co 2pp 18528 178 24X Fiche: 50-445/83/05/13,8305230445
- --8305230449 IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted Major areas inspected followup of unresolved items in IE Insp Repts 50-445/82-26, 50-446/82-14 & 50-445/82-22 TAPIA, J I CHEN, W P , HUNNICUTT, D M Region 4, Office of Director 83/05/03 8pp 18538 180 24X Fiche 50-445,83/05/13, 8305230445
- 83052004i6 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-03 & 50-446/83-01 MADSEN, 0 L Region 4, Office of Director 83/05/18 GARY, R J Texas Utilities Generating Co ip 18518 124 24X Fiche 50-445,83/05/18,8305200416
- --8305200419 Responds to NRC 830928 ltr re violations noted in IE Insp. Repts 50-445/83-03 & 50-446/83-01 Corrective actions light poles will be inspected & items designated non-nuclear safety-related reviewed & upgraded GARY,R J Texas Utilities Generating Co 83/04/25 MADSEN, Region 4, Office of Director 3pp 18518 125 24X Fiche 50-445,83/05/16,8305200416
- 8305200666 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 MADSEN,G L Region 4, Office of Director 83/05/18 GARY,R J Texas Utilities Generating Co ip 18519 095 24X Fiche, 50-445, 83/05/18, 8305200666
- --8305200674 Responds to NRC B30314 ltr re violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 Corrective actions const personnel will be reinstructed in necessity for rigid compliance w/design & procedural requirements OARY,R J Texas Utilities Generating Co B3/04/15 MADSEN, O. L Region 4, Office of Director 3pp 18519 076 24X Fiche 50-445, 83/05/18, 8305200666
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305240003 Forwards IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted MADBEN.0 L. Region 4. Office of Director 83/05/20 GARY.R J Texas Utilities Generating Co. 2pp 18549 139 24X Fichs 50-445,83/05/20,8305240003
- --8305240005 IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted Major areas inspected radwaste program & transportation activities, including organization, training, radwaste sys mpt, effluent release controls & procedures BAER.R.E. MURRAY, B., WEBTERMAN, T.F. Region 4, Office of Director 83/05/19 34pp 18549 141 24X Fiche 50-445, 83/05/20, 8305240003
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.

 JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- B305110427 Part 2: & deficiency repts re misoperation of D8-416 reactor trip undervoltage devices Initially reported on B30420
 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME.E P Westinghouse Electric Corp B3/04/21 DEYGUNO,R C Director's Dffice of Dispection and Enforcement 5pp 18405 095 24X Fichs 50-000.83/04/21.8305110427
- B305200298 Interim Deficiency Rept SDAR-106 re HVAC hangers fabricated at variance w/design Initially reported on B30301 Completion of evaluation anticipated by 830705 GARY.R J Teras Utilities Generating Co 83/05/11 MADSEN, 0 L Region 4. Office of Director 1p 18516 273 24X Fiche 50-445.83/05/11,8305200298
- 8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or anubbers initially reported on 830513 Bolting parts greater than 2-inch size not examined HOVI.L NPS Industries, Inc 83/05/16 DEYOUNO,R C Director's Office Office of Inspection and Enforcement 1p 18574 001 24X Fiche 30-000.83/05/16.8305240336
- T Hearing transcripts on non-antitrust matters
- 8305020156 Corrected transcript of 830407 telephone conference in Bethesda, MD Pp 1-132 * About Safety and Licensing Board Panel 83/04/07 135pp 18272 228 24% Fiche 50-445,83/04/07.8305020156
- B305040507 Forwards J Doyle surrebuttal testimony
 ELLIG.J Citizens Association for Sound Energy B3/04/26
 BLOCH.P B , JDRDAN.W H , MCCOLLOM.K A Atomic Safety and Licensing
 Board Panel ip 18319 146 24x Fiche 50-445.83/04/26.8305040507
- --B303040915 Surrebuttal testimony of J Doyle re consideration of LOCA in design criteria for pipe supports Results of hand calculations supported by computer analysis indicate gross arror in fundamental approach Certificate of Svc encl DOYLE.J Citizens Association for Sound Energy B3/04/26 89pp 18319 147 247 Fishe 50-445.83/04/26.8305040507
- B305040535 Supplemental surrebuttal testimony of J Doyle re severe minor & offsetting errors in computer analysis Certificate of Svc encl
 DUYLE.J Citizens Association for Sound Energy B3/04/28 Spp 18321 Z43 24x Fiche 50-445, B3/04/28, B305040335
- B305110157 Surrebuttal testimony of MA Walsh Certificate of Svc encl Related correspondence MALSH.M A Citizens Association for Sound Energy 83/05/04 9pp 18407 112 24X Fiche 50-445,83/05/04.8305110157
- 83031i0334 Supplemental surrebuttal testimony of J Doyle re special inspiteam Insp Repts 50-443/82-24 & 50-4446/82-14 Related correspondence BDYLE. J Citizens Association for Sound Energy 83/05/04 42pp 18406 086 24X Fichs 50-443,83/05/04,83/05110334
- 8305090507 Forwards testimony of LJ Skiles, AB Armstrong & CL Born re emergency planning recommendations, A Vega testimony reconst appraisal team rept & JS Marshall, DH Wade, JC Finneran & DR Woodlan affidavits Related correspondence REYNOLDS, N 9 Debevoise & Liberman REYNOLDS, N 8 Texas Utilities Generating Co 83/05/05 BLOCH, PB, MCCOLLOM, KA, JORDAN, WH Atomic Safety and Licensing Board Panel 2pp 18362 014 24X Fiche 30-445,83/05/05,8305090507
- --8305070510 Testimony of LJ Skiles, AB Armstrong & CL Born on ASLB 830425 telcon questions re adequacy of county judge as emergency plan coordinator SKILES, LJ, ARMSTRONG, AB, BORN, CL Texas, State of 83/05/05 7pp 18362 016 24% Fiche 30-445,83/05/05,8305070507
- --8305090513 Testimony of A Vega re applicant response to B30411 Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 VEOA.A Texas Utilities Generating Ca B3/05/05 3pp 18362 023 24X Fiche 50-445,83/05/05.8305090507
- B303090548 Forwards direct testimony & affidavits in response to questions posed by ASLB during B30407 telcon
 TREBY, B A Hearing Branch 1 83/05/05 BLOCH, P B Atomic Safety and Licensing Board Panel 2pg 18340 001 24X
 Fiche 50-445, B3/05/05, B305090548

- --8305090578 Supplemental tastimony of S Burwell, WP Chen, Jl Tapia, J Rajan & RG Taylor re concerns raised by MA Waish & J Doyle & NRC const appraisal insp rept Prof qualifications encl BURWELL, S Division of Licensing CHEN, W P Energy, Dept of TAPIA, J I Division of Resident, Reactur Project & Engineering Programs 83/05/05 14pp 18360 004 24x Fiche 50-445,83/05/05,8305090568
- --8305090596 Supplemental testimony of DM Rohrer & T Urbanik re emergency preparedness RCMRER, D M Emergency Preparedness Branch URBANIK, T Texas A&M Univ , College Station, TX 83/05/05 20pp 18360 018 24X Fiche 50-445,83/05/05,8305090568
- ---8305090592 Supplemental testimony of A Lookabaugh & J Benton re emergency preparedness LOOKABAUGH, A. BENTON, J Federal Emergency Management Agency B3/05/05 15pp 18360 038 24% Fiche 50-445,83/05/05,8305090568
- --B305070660 Testimony of AB Beach re const appraisal team insp concerning pipe support const & pipe support design interfaces wiconst Prof qualifications encl BEACH:A B Director's Dffice. Office of Inspection and Enforcement B3/05/05 4pp 18360 109 24X Fiche 50-445,83/05/05,830507036
- 8305130157 Supplementary surrebuttal testimony of J Doyle Error in fundamentals used in calculations for upper lateral restraint compounded by errors in stiffness used in Gibbs & Hill calculations Related correspondence DOYLE, J Citizens Association for Sound Energy 83/05/09 2pp 18437 269 24X Fiche 50-445,83/05/09.8305130157
- 8305230138 Transcript of 830516 hearing in Fort Worth TX re QL application Pp 5.855-6.169 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/16 408pp 18530 215 24X Fiche 50-445.83/05/16.8305230138
- 8305230100 Transcript of 830517 hearing in Fort Worth, TX Pp 6,170-6,226 Supporting documentation encl * Atomic Safety and Licensing Roard Panel 83/05/17, 268pp 18534 282 24X Fiche 50-445,83/05/17,8305230100
- 8305230147 Transcript of 830517 hearing in Fort Worth TX Pp 6.287-6.471 Supporting documentation encl

 * Atomic Safety and Licensing Board Panel 83/05/17 336pp
 18529 239 24X Fiche 50-445,83/05/17,8305230147
- 8305250010 Transcript of 830518 hearing in Fort Worth TX Pp 6.472-6.817 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/18 388pp 18584 075 24X Fichs 30-445,83/05/18.8305250010
- 8305260099 Transcript of 830519 hearing in Fort Worth, TX Pp 6,818— 7,272 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/19 743pp 18597 001 24X Fiche 50-445,83/05/19,8305260099
- 8305260079 Transcript of 830520 hearing in Fort Worth, TX Pp 7,273-7,485 Supporting documentation encl * Atomic Eafety and Licensing Board Panel 83/05/20 319pp 18624 046 24X Fiche 50-445,83/05/20,8305260079

DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- B30324033B Forwards revised draft responses to discussion items & questions from NRC Power Sys Branch. Containment Sys Branch. Instrumentation & Control Sys Branch & OA Bys Granch re OESSAR-II
 SHERN000.9 0 General Electric Co 83/03/23 EISENNUT, D 0 Division of Licensing 59pp 17681 251 24% Fiche 50-447,83/03/23,8303240338
- 8305020573 Responds to 821001.830309,0414 & 19 ltrs re GE request for final design approval for GESSAR-II nuclear island design Approval can be granted if listed requirements met DENTON.H R Office of Nuclear Reactor Regulation, Director 83/04/21 SHERHOOD,0 O General Electric Co 3pp 18284 233 24X Fiche 50-447.83/04/21,8305020573
- 8305030403 Provides statement of GE objectives for final design approval in light of current Commission proposed policy statement on severe accidents ACRS review of GESBAR II SER (NUREO-0979) recommended BHERWOOD.0 9 General Electric Co B3/04/29 DENTON.H R Office of Nuclear Reactor Regulation, Director, 2pp. 18306 240 24X Fiche 30-447.83/04/29,8305030403

- B30518Q060 Notification of ACRS B30513 meeting w/GE in Washington, DC to discuss GESSAR-II BWR/6 nuclear island design Marked-up agenda encl
 THOMAS.C O Standardization & Special Projects Branch B3/05/09 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post B30201) HOUSTON, R W Assistant Director for Reactor Safety 3pp 18499 345 24X Fiche 50-447, B3/05/09, B305180040
- 8305200197 Forwards marked-up revised response to Guestion 460 09 of NRC 820825 request re GEBBAR-II std BAR SHERMODO, 0 G Deneral Electric Co 83/05/18 EISENHUT, D Q Division of Licensing 6pp 18519 071 24X Fiche 50-447,83/05/18, 8305200157
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B305020355 Forwards proposed resolution to GESBAR-II BER outstanding issue re-post-accident monitoring instrumentation SHERNOOD, G General Electric Co 83/04/28 EISENHUT, D O Division of Licensing 48pp 18277 003 24X Fiche 50-447,83/04/28,830502035
- 8305050379 Forwards SER for GESSAR-II BWR/6 Nuclear Island Design Outstanding issues identified in Section 1 8 expected to be resolved prior to May 1783 ACRS meeting W/a encl THOMAS.C O Standardization & Special Projects Branch 83/04/28 RAY.J J ACRS Advisory Committee on Reactor Safeguards ip 18352 045 24X Fiche 50-447.83/04/28.8305050379
- 8303060562 Forwards SER (NUREO-0979) re application for final design approval for GESSAR II & FR notice W/o NUREQ THOMAS.C D Standardization & Special Projects Branch 83/04/28 SKERMOOD.G Q General Electric Co 2pp 18359 210 24X Fiche 50-447,83/04/28,8305060562
- --B30506056B Notice of availability of SER (NUREO-0979) on proposed final design approval for GESGAR II BRINKHAN.D & Standardisation & Special Projects Brench B3/04/28 ip 18359 212 24X Fiche 50-447,83/04/28,8305060562
- B305030403 Provides statement of GE objectives for final design approval in light of current Commission proposed policy statement on severe accidents. ACRS review of GEBBAR II SER (NUREG-0979) recommended SHERWODD. 0 General Electric Co 83/04/29, DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 18306 240 24% Fichs 30-447.83/04/29,8303030403
- 8305100278 Forwards proposed resolution of Containment Sys & Instrumentation & Control Sys Branches outstanding SER issues re GESAR II SHERMOOD GO General Electric Co 83/05/05. EISENHUT, D. Q Division of Licensing 6pp 19370 085 24X Fiche 50-447, 83/05/05, 8305100278
- 8305260037 Forwards supplemental responses to Power Sys Branch questions re OEBSAR-II ac/dc power sys/balance-of-plant interfaces Responses will be included w/Amend 15 to SER SHERNOOD, 0 0 Oeneral Electric Co 83/05/24 EISENHUT, D Q Division of Licensing 10pp 18622 310 24x Fiche. 50-447, 83/05/24, 83092260037
- --83052&0048 Forwards draft Amend 15 to DESSAR-II Amend resolves selected outstanding & confirmatory issues identified in SER (NUREG-0979) & completes Subsection 1 9 i pn GEBSAR-II/F8AR interfaces
 SHERWOOD, 0 G General Electric Co 83/05/24 EISENHUT, D. G. Division of Licensing 446pp 18622, 320 24X
 Fiche 50-447, 83/05/24, 83032&0037
- T Hearing transcripts on non-antitrust matters
- 8305020174 Transcript of ACRS Subcommittee on GE Water Reactors, OEBSAR-II 830422 meeting in Santa Monica, CA, Pp. 361-609, Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 83/04/22 357pp. 18281 299 24X Fiche 50-447, 83/04/22, 8305020174
- DOCKET STN-50-494 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8305120552 Informs that ASME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III.Div 1, Classes 1,2 MC & CS." not acceptable for generic use & not listed in reg guide series.per 830302 submittel. YOUNOBLOOD,B J Licensing Branch 1. 83/05/03 FARRAR,D.L. Commonwealth Edison Co 2pp 18443 120. 24X Fichs 50-000,83/05/03,8305120552

- 8305040323 Board Notification 83-057 forwards differing prof opinions re my interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EISENHUT.D @ Division of Licensing 83/05/04 PALLADINO.N Commissioners 22pp 18337 139 24X Fiche 50-000.83/05/04, 8305040323
- B305100237 Forwards response to FSAR question re crushable pipe whip restraint matl, per B30330 request for add1 info Confirmation test to verify angularity of load results will be completed by B30801 Info will be included in FSAR amend SHARTI.E D Commonwealth Edison Co B3/05/04 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 18373 269 24X Fiche 50-000, B3/05/04, 8305100237
- 8305110216 Notification of 830513 meeting w/C-E & Westinghouse in Bethesda. MD to discuss seismic & qualification review team results & pump & valve operability DLSHAM, L N Licensing Branch i 83/05/05 YOUNGBLODD, B J Licensing Branch i 3pp 18434 354 24X Fiche 50-454,83/05/05,830510216
- 8305130051 Forwards revised response to Question 270 9.Part C resolving qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev
 BWARTZ.E D Commonwealth Edison Co 83/05/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18436-313 24X
 Fiche 50-000.83/05/06.8305130051
- 8305070657 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plent mods 8vc list encl EIBENHUT, D. 9 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000.83/05/09.8305070659
- 8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review, "Supply I & II SMARTZ.E D Commonwealth Edison Co 83/05/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18487 001 24X Fiche 50-000.83/05/09.8305180385
- --8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review." Supply 1 & 11 * Commonwealth Edison Co 83/04/30 22ipp 18487 002 24X Ficha 30-000,83/05/07,8305180385
- 8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & BER (NUREG-0876) Supporting documentation enc. REED, C Commonwealth Edison Co 83/05/11 DENTON-HR Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche 50-000,83/05/11.8305200621
- --8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed " CURRAN, R N , HARRIS, R J Energy Incorporated FERGUSON, R N Ferguson, Inc 82/07/06 65pp 18521 095 24X Fiche 50-000, 83/05/11, 8305200621
- --8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Comet Projects"

 * Commonwealth Edison Co 82/11/17, 350pp 18521 160 24X Fiche 50-000,83/05/11,8305200621
- --8305200655 Rept of 810927-30 audit to verify Sargent & Lundy conformance to NUREG-0388 re environ qualification of Class IE electrical equipment MARCUS.0 F Commonwealth Edison Co 81/10/06 &pp 18522 130 24X Fichs 50-000.83/05/11.8305200621
- --8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy GA program implementation & adequacy of facility design SUMMERFIELD, T. MARCUB.0 F Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fichs 50-000.83/05/11.8305200621.
- --8305200675 Rept of 820607-11 audit re Sargent & Lundy GA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
 ARCUS, G F Commonwealth Edison Go 82/06/17 48pp 18522 174
 24X Fiche.50-000.83/05/11.8305200621
- --8305200691 Rev 3 to "Interface Control Agreement, Westinghouse Piping & Structural Evaluation Program for Byron Station Unit 1 "

 * Wastinghouse Electric Corp * Commonwealth Edison Co *
 8ergent & Lundy, Inc. 82/10/29 19pp 18522 221 24X
 Fiche 30-000,83/05/11,8305200621

- --8305200683 Rev C to Procedure 3 0 4, "Design Control New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl WHITAKER, W A Nuclear Power Services, Inc. 82/11/23 18pp 18522 241 24X Fiche 50-000,83/05/11,8305200621
- --8303200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util GA statement re verification of adequacy of design & const of Byron Unit 1 encl WATTELET.P L , MEISTER, J R , BRAEGER, C B Sargent & Lundy, Inc DRR-AF-001-BB ROO 80/07/16 84pp 18522 303 24X Fiche 50-900,83/05/11,8305200621
- ---8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed " BIOBEE, D : CURRAN, R N : FARMAN, R F Energy Incorporated B3/04/04 127pp 18523 027 24X Fiche 50-000.B3/05/11; B305200621
- B305310086 Notification of B30614 meeting w/util in Bethesda.MD to discuss util DCRDR program plan GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 30-000
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305160059 Clarifies commitments re timing for completion of preoperational testing of auxiliary bldg ventilation sys Review of SER, NUREG-0876, indicates misunderstanding may exist
 TRAMM, T R Commonwealth Edison Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18453 118 24X Fiche 30-484,83/05/11,8305160059
- F Security, medical, emergency & fire protection plans
- 8305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability YOUNGBLOOD, B J Licensing Branch 1 83/04/11 FARRAR, D L Commonwealth Edison Co 3pp 18336 219 24X Fiche 30-000, 83/04/11, 8305040062
- --8304150458 Forwards revised position accepting use of exit core thermocouples as alternative to use of hot leg temp resistance temp detectors Use of thermocouples unil comply w/10CFR30.App R
 RUBENSTEIN.L S Assistant Director for Core & Plant Systems 83/03/18 MATTSON.R J Division of Systems Integration (post 811005) 4pp 18334 224 24X Fiche 50-454.83/04/11.8305040062
- 8305040069 Releases public version of rev to emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18329 092 24X Fiche 50-454,83/04/22, 8305040069
- --8305040074 Forwards public version of rev to emergency plan implementing procedures, including Procedures BZP 100-1 restation manager & BZP 310-4 reassembly & evacuation of personnel
 TRAMH.TR Commonwealth Edison Co 83/02/25 DENTON.HR Office of Nuclear Reactor Regulation, Director 1p 18329 093 24X Fiche 50-454.83/04/22.8305040069
- --8305040080 Public version of rev to emergency plan implementing procedures including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel ** Commonwealth Edison Co 83/02/10 331pp 18329 074 24X Fiche 50-454,83/04/22.8305040069
- B305060184 Forwards Rev 8 to security plan Rev withheld (ref 10CFR73 21) FARRAR.D L Commonwealth Edison Co 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18345 090 24X Fiche 50-434,83/04/29,8305060184
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enci EIBENHUT. D 9 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000,83/05/11,8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS W J Office of the Executive Director for Operations. 83/05/13 PALLADING, N J Commissioners 5pp 18593,322 24X Fiche 50-000,83/05/13,8305240213

G Adjudicatory correspondence

- B305040405 Memorandum & order denying intervenor B30428 oral motion to keep record upen on steam tube integrity subissues Record contains sufficient info to make decision re Unresolved Safety Issue A-3
 SMITH, I W Atomic Safety and Licensing Board Panel B3/05/03
 League of Homen Voters of Rockford, IL 2pp 18323 208 24X
 Fiche 30-454, 83/05/03, 8305040405
- 8305100286 Application for issuance of encl unsigned subpoenss directing attendance & testimony of I Souders & J Ogsbury at ASLB 830523 session in Rockford, IL Certificate of Svc encl WHICHER, J M League of Homen Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinnisaippi Alliance for the Environment (SAFE) 83/05/06 SOUDERS, I. GOSBURY, J. Affiliation Unknown 7pp 18371 134 24X Fiche 50-454,83/05/06,8305100286
- B305100172 NRC response to joint intervenor motion to reopen record raised under Contention IA concerning J Hughes testimony on GC/GA Staff apposes further hearing on subj matters YOUND, M A Atomic Safety and Licensing Board Panel 83/05/09 7pp 1B374 323 24X Fiche 50-454.83/05/09.8305100172
- --8305100176 Affidavit of DW Hayes & KA Connaughton re statement by J Hughes supporting intervenor motion to reogen record HAYES, D W . CONMAUGHTON.K Region 3. Office of Director 83/05/09 15pp 18374 330 24X Fiche 50-454,83/05/09.8305100172
- 8305110215 Response in apposition to Rockford League of Homen Voters & Dekalb Area Alliance for Responsible Energy/Safe Alternatives for Future Energy motion to allow testimony of J Hughes on OA/GC Certificate of Evc encl
 BECKER.B D Commonwealth Edison Co BECKER.B D Isham, Lincoln & Beale 83/05/09 Atomic Safety and Licensing Board Panel 13pp 18407 039 24X Fiche 50-454,83/05/09.8305110215
- 8305120277 Discusses order of witness presentation for hearings resuming on 830523 NRC will present witnesses on liquid pathway contention first.followed by util.Rockford League of Homen Voters & util rebuttal witnesses GALLO.J Commonwealth Edison Co 83/05/10 SMITH.I W. COLLER F. CALLIMAN.A D Atomic Bafety and Licensing Board Panel 2pp 18430 1457 24X Fiche 50-454.83/05/10.8306130299
- B305160060 Affidevit of RP Tuetken on J Hughes allegations re welding Melding of brace to pressure pipe proper. If performed per design specs Util conducting refinsp of work performed by contractor GC inspectors
 TUETKEN. R P Commonwealth Edison Co 83/05/11 3pp 18453 120 24X Fiche 30-434,83/05/11.8303160060
- B305170314 Confirms mailing of proprietary version of Pages 4691,4692 & 4697 from B30415 transcript.per terms of Mestinghouse nondisclosure agreement Method for circulating nonproprietary portion to PDRs being worked out DAVIS.F X Westinghouse Electric Corp 83/05/11 THOMAS.D Affiliation Unknown 2pg 18465 076 24X Fiche 50-454.83/05/11, 8305170314
- 8303170319 Forwards nondisclosure agreement signed on 830427 Terms of agreement should be used to handle Westinghouse proprietary info contained in 830415 transcript Method for circulating nonproprietary portion to PDRs being worked out H/o encl DAVIS.F X Westinghouse Electric Corp 83/05/11 CHAVEZ.D DeKalb Area Alliance for Responsible Energy CHAVEZ.D Sinnissippi Alliance for the Environment (SAFE) 1p 18465 362 24X Fiche 50-454.83/05/11.8305170319
- 8305170334 Forwards application for withholding from public disclosure Westinghouse proprietary info discussed in 830415 meeting Method for circulating nonproprietary portions of 830415 transcript to PDRs being worked out W/a encl DAVIB,F X Westinghouse Electric Corp 83/05/11 8MITH,I W., CDLE,R F. CALLIHAN,A D. Atomic Bafety and Licensing Board Panel 2pp 18469 006 24X Fiche 50-454.83/05/11,8305170334
- 8305170522 Forwards nondisclosure agreement signed on 830426 & proprietary version of Pages 4691,4692 & 4699 from 830415 transcript M/o proprietary pages
 DAVIS:F X Westinghouse Electric Corp 83/05/11. BRIDENBAUGH,D, JOHNSON.B, BUNCM:R League of Women Voters of Rockford, 1L ip 18467 251 24% Fiche 30-434.83/05/11.8305170522
- 8305160162 Memorandum & order scheduling special deposition session for 830526 in Rockford, IL to take deposition of J Hughes & possibly of Souders & Ogsbury SKITH, I W Atomic Safety and Licensing Board Panel 83/05/12 8pp

- 8305170297 Forwards stipulation w/affidavits & ambulance survey re admission of certain evidence offered by intervenors on emergency planning issues Upon admission of evidence, hearing record should be closed Svc list encl W/o stated encl BIELAWSKI.A P Isham, Lincoln & Beals BIELAWSKI.A P Commonwealth Edison Co 83/05/12 SMITH.I W COLE.R F . CALLIMAN.A D Atomic Safety and Licensing Board Panel 3pp 18465 063 24X Fiche 50-454.83/05/12.8305170297
- B305170565 Mution to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unexecuted stipulation BIELAMBKI, A P Commonwealth Edison Co BIELAMBKI, A P Isham, Lincoln & Beale 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18468 168 24X Fiche 30-454.83/05/12.8305170565
- --8305170569 Testimony of P Holmbeck re investigation into adequacy of emergency plans re emergency planning contentions Util made no attempt to study protective value of sheltering populations around plant HOLMBECK.P DeKalb Area Alliance for Responsible Energy HOLMBECK.P Sinnissippi Alliance for the Environment (8AFE) HOLMBECK.P League of Momen Voters of Rockford. IL 83/05/12 73pp 18468 170 24X Fiche 50-454.83/05/12.8305170565
- --8305170572 Testimony of 9 Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable MONTEL.0 DeKalb Area Alliance for Responsible Energy MONTEL.Q. Sinnissippi Alliance for the Environment (SAFE) MONTEL.G League of Women Voters of Rockford, IL B3/02/16 12pp 18468 245 24% Fichs 50-434,83/03/12,8305170565
- --8305170976 Testimony of JM Maloney on emergency preparedness contentions Util emergency plan cannot be implemented until questions on notification, transportation, communication & liability answered MALONEY, J M DeKalb Area Alliance for Responsible Energy MALONEY, J M Sinnissippi Alliance for the Environment (SAFE). MALONEY, J M League of Women Voters of Rockford, IL 83/02/17, 12pp 18468 257 24X Fiche 30-454,83/05/12,8305170565
- --8305170581 Testimony of C Lamb re emergency preparedness contentions LAMB.C DeKalb Area Alliance for Responsible Energy LAMB.C. Sinnissippi Alliance for the Environment (BAFE) LAMB.C. League of Women Voters of Rockford. IL 83/02/16 11pp 18468 271 24X Fiche 50-454.83/05/12.8305170565
- --8305170388 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications, transportation difficulties & school liability

 YURNER, D DeKalb Area Alliance for Responsible Energy TURNER, D Sinnissippi Alliance for the Environment (SAFE) TURNER, D, League of Women Voters of Rockford, 1L 83/02/10, 12pp 18468 282 24X Fiche 50-454,83/05/12,8305170565
- --8305170590 Testimony of D Miller ru emergency preparedness contentions Concerns include procedures for & modes of emergency communications, transportation difficulties & school liability MILLER, D DeKalb Area Alliance for Responsible Energy MILLER, D Sintistippi Alliance for the Environment (BAFE) MILLER, D League of Homon Voters of Rockford, IL 83/02/28 12pp. 18468 275. 24X Fiche 50-454,83/05/12,8305170565
- --8305170593 Testimony of JL Murphy on Contentions 3 & 13 Listed problems inherent in any radiological accident & should be resolved to provide reasonable degree of safety to citizens MURPHY, J L DeKalb Area Alliance for Responsible Energy MURPHY, J L Binnissippi Alliance for the Environment (BAFE). MURPHY, J L League of Women Voters of Rockford, IL, 83/02/28 16pp 18468 307 24X Fiche 50-454,83/05/12,8305170565
- 8305200521 Memorandum & order approving stipulation to offer into evidence Joint Intervenors Exhibits 13 20 Stipulation will be bound into 830523 transcript Proposed findings & conclusions on amergency planning issues due 830620 SMITH.I W Atomic Safety and Licensing Board Panel 83/05/17 Office of the Executive Legal Director ip 18516 085 24X Fiche.50-454,83/05/19,8305200521
- G Inspection reports. IE Bulletins & correspondence
- 8212050385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308/319 24X Fiche 30-000, 83/03/21, 8212060385

- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
- 93304021 It into Notice 83-21, "Derective Emergency Use Respirator" Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 193 24X Fiche 50-000,83/04/15,8303040021
- 9303040023 IE Info Notice 93-22, "BWR Safety/Relief Valve Failures "
- Bvc list encl JORDAN,E L SVC list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere 303040U20 IE INTO NOTICE B3-83, INSPERIOR CONSTITUTION OF THE SENSING BYS "SVC list encl JORDAN,E L Division of Emergency Preparedness & Engineering Acesponse (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305170238 Forwards IE Insp Repts 50-454/83-14 & 50-455/83-12 on B30316-18 & 31 No noncompilance noted PAPERIELLO.C J Region 3, Office of Director B3/04/26 REED.C Commonwealth Edison Co 2pp 18465.087 24X Fiche 50-454,83/04/26,
- --B305170248 IE Insp Repts 50-454/83-14 & 50-455/83-12 on B30316-18 & 31 No noncompliance noted Major areas inspected environ protection including preoperational radiological environ monitoring implementation & results & mgt controls GEBTMANN, M J , SCHUMACHER, M C Region 3, Office of Director B3/04/25 7pp 18465 089 24X Fiche 50-454,B3/04/26,B30517023B
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc I (st encl JORDAN: L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/29 Consolidated Edison Co of New York: Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 830304002B IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list ancl JURDAN:E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co. of New York: Inc 122pp 18441 170 24X Fiche 50-000,83/03/03,83030400R8
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAM: E L. Division of Emergency Preparedness & Engineering Equipment - Decline which of Emergency Proparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" 8vc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Rinding Caused by Fuel Rack JOSOVANAE L DIVISION of Emergency Preparadness & Engineering
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/06 Consolidated Edison Co of New
 York, Inc. 115pp 18523 24B 24X Fiche 50-000, 83/05/06, 8303040033
- 8305190019 Forwards IE Insp Repts 50-454/83-15 & 50-459/83-13 on 830321 & 28-31 No noncompilance noted LITTLEN 8 Region 3, Office of Director 83/05/06 REED, C Commonwealth Edison Co 2pp. 18502 004 24X Fichs 50-454,83/05/06 B305190019
- --8305170027 IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted Major areas inspected evaluation of NDE results for pool liner welds & review of quality records MARD,K O , DANIELBON.D H Region 3, Office of Director 83/04/27 11pp 18502 004 24X Fiche 30-454,83/05/06,8305190019
- 8305130129 Ack receipt of 830103 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 BPEBBARD.R.L Region 3. Office of Director 83/05/10 REED, C Commonweelth Edison Co 1p 18437 280 24X Fiche 50-454.83/05/10, 83015/30150

- --9305130135 Responds to NRC 820624 ltr re-violations noted in IE Insp. Repts 50-454/82-05 & 50-455/82-04 Welding procedures & instructions need not be at each location where actual welding performed per ASME Code STIEDE.W L Commonwealth Edison Co Region 3. Office of Director Spp Region 3. Office of Director 3pp 18437 281 24X Fiche 50-454,83/05/10.8305130129 KEPPLER, J. G.
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11. 8303040034
- 8303170458 Confirmatory action ltr re insp of pipe whip restraints in safety-related high energy piping sys on 830503-04 & 09-10 Restarting installation of whip restraints contingent upon transmittal of as-built drawings to Sargent & Lundy KEPPLER, J O Region 3, Office of Director 83/05/13 REED, C Commonwealth Edizon Co 2pp 18467 319 24X Fiche 50-454, 83/05/13, 2303570480
- 8305200508 Ack receipt of 830210 & 0504 ltrs informing NRC of steps 305200508 Ack receipt of 830210 & 0504 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12
 8PESSARD.R L. Region 3. Office of Director 83/05/17 REED.C Commonwealth Edison Co. 1p 18516 060 24X Fiche 50-454,83/05/17,8305200508
- --9305200522 Responds to 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions repts 30-434/82-17 & 30-433/82-12 Corrective actions contractor placed hold tags on 50 panels & notified electrical const dept per Procedure 6
 FARRAR D L Commonwealth Edison Co B3/05/04 KEPPLER, J Q Region 3. Office of Director 6pp 18516 061 24X
 Fiche 50-454.83/05/17.8305200508
- --8309200540 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 30-454/82-17 & 50-455/82-12 Corrective actions contractor instructed to identify panels which contained cable separation problems & hold tags placed on panels FARRAR, D L Commonwealth Edison Co 83/02/10 KEPPLER, J G Region 3. Office of Director 7pp 18516 067 24X Fiche 30-454.83/05/17,8303200508
- 8305200586 Confirms enforcement conference on 830523 in Chicago, IL per 830516 telcon Conference concerns deficiencies identified in preoperational test program

 SPESSARD,R L Division of Engineering 83/05/18 REED,C

 Commonwealth Edison Co 1p 18514 121 24X Fiche 50-454,83/05/18, 8305200584
- 8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers NORELIUS, C E Division of Project & Resident Programs 83/05/18 REED. C Commonwealth Edison Co ip 18571 181 24X Fiche 50-000.83/05/18,8305240524
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
- 8305260278 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Finding only 10 rejectable welds out of 1,067 not proper indication of inspector performance NORELIUS, C E. Division of Project & Resident Programs 83/05/20 REED, C Commonwealth Edison Co 1p 18625 156 24X Fiche 50-454.83/05/20,8305260278
- ---8905260282 Responds to NRC B30324 ltr re violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Corrective actions,welds reinspected New onsite contractor GA/GC qualification procedures implemented FARRAR, D L. Commonwealth Edison Co. 83/04/19 KEPPLER, J G Region 3, Opfice of Director 3pp 18625 137 24X Fiche 50-454,83/05/20,8309260278
- 8305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing matl tests

 SPESSARD.R L. Division of Engineering 83/05/24 REED.C Commonwealth Edison Co. 1p. 18644 0B7 24X Fiche 50-000,83/05/24. 8305270476

- --8305270487 Responds to NRC 830331 ltr re violations noted in IE Insp Repts 50-434/83-06 & 50-455/83-05 Corrective actions site design procedures compiled into manual by Westinghouse & issued to facility for site use on 830415 FARRAR, D L Commonwealth Edison Co 83/04/29 KEPPLER, J G Region 3, Office of Director lipp 18644 088 R4X Fiche 50-000,83/05/24,8305270476
- --8305270501 Rev 1 to "Evaluation of Three Legged Pipe Whip Restraint 84 s" MAIJ S , YANG,M S , AMIN,M Sargent & Lundy, Inc 8 15 I-O ROI 82/09/21 47pp 18644 099 24X Fiche 50-000,83/05/24,8305270476
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 0:1" Svc list encl JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York
- S Reportable occurrences, LERs & related correspondence
- 8303110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHE.E P Hestinghouse Electric Corp 83/04/21 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 5pp 18405 075 24X Fichs 50-000.83/04/21.8305110427
- 6305030270 Final deficiency rept re reactor coolant pump & steam generator support columns not installed within tolerances specified on Sargent & Lundy Design Drawing S-1105 Initially reported on B303287 Revised tolerances will be verified SHARTZ.E D Commonwealth Edison Co 83/04/25 KEPPLER.J Q Region 3, Office of Director 3pp 18300 087 24% Fiche 30-454.83/04/25.830500270
- B305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on B30328 Matter under investigation Final rept by B30808 Reported per Part 21 MANNO.5 F Niagara Mohawk Power Corp 83/04/26 STARDSTECKI.R. Region 1. Office of Director. 2pp 18433 072 24X Fiche 50-000.83/04/26.8305120392
- ~-8305120404 Part 21 rept re failure of post-LUCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83/03/11 CULLINS, J T Region 4. Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392
- 8305190233 PNO-III-83-035 on 830511, licensee stopped work on new installation of pipe-whip restraints on safety-related piping per 830513 confirmatory action itr Restraints installed w/o adequate procedures or GC insp program DANIELBON, D H. LITTLE, W S Region 3. Office of Director 83/05/13 p 18501 318 24X Fiche 50-454,83/05/13,8305190233
- T Hearing transcripts on non-antitrust matters
- 8305040349 Transcript of B30415 hearing in Rockford, IL Pp 4, 671-4, B30 Supporting documentation encl * NRC - No Detailed Affiliation Given B3/04/15 163pp 18323 031 24X Fiche 50-454, 83/04/15, 8305040349
- 8305020163 Transcript of 830426 hearing in Rockford, IL Pp 5,964-6,156 * NRC - No Detailed Affiliation Given 83/04/26 192pp. 18277 301 24X Fiche 50-454,83/04/26,8305020163
- 8305170408 Forwards proprietary & nonproprietary versions of statements made by NRC witness re Westinghouse Model D4/D5 steam generators Proprietary info withheld (ref 10CFR2 790) RAHE, E P Westinghouse Electric Corp 83/04/26 EISENHUT, D O Division of Licensing ip 18469 326 24X Fiche 50-454,83/04/26,8305170408
- --B3051704i1 Forwards application for withholding proprietary version of statements made by NRC witness re Hestinghouse Model D4/D5 steam generators per 10CFR2 790 HIESEMANN.R A Hestinghouse Electric Corp 83/04/26 EIBENHUT, D C Division of Licensing 9pp 18469.327 24X Fiche 50-454,83/04/26.8305170408
 - Nonproprietary version of statements made by Rajan reuse Model D4/D5 steam generators. Pp 4.691-4.692 &
 - RC No Detailed Affiliation Given 83/04/24 3pp 36 24X Fiche: 50-454, 83/04/26, 8305170408

- 8305030305 Transcript of 830427 hearing in Rockford, IL Pp 6.157-6.400 • NRC - No Detailed Affiliation Given 83/04/27 204pp 18294 200 24X Fiche 50-454.83/04/27.8305030305
- 830503050B Motion to permit J Hughes testimony re GA/GC at facility & to shorten time for responses by util & NRC Matters of testing documentation & welding constitute significant safety issues MHICHER.J M League of Women Voters of Rockford, IL WHICHER.J M DeKalb Area Alliance for Responsible Energy WHICHER.J.M Safe Energy for New Haven B3/04/27 Atomic Safety and Licensing Board Panel 4pp 18275 071 24% Fiche 50-454.83/04/27.8305030508
- --8305030516 Handwritten testimony of J Hughes re GA/GC at facility HUGHEB, J League of Homen Voters of Rockford, IL HUGHEB, J DeKalb Area Alliance for Responsible Energy HUGHEB, J Safe Energy for New Haven 83/04/25 3pp 18275 075 24X Fiche 50-454,83/04/27,8305030508
- 8305030391 Transcript of 830428 hearing in Rockford, IL Pp 6.401-6.540 Supporting documentation encl * NRC - No Detailed Affiliation Given 83/04/28 221pp 18295 329 24% Fiche 50-454,83/04/28,8305030371
- 8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters Wunescotted stipulation
 BIELAMSKI.A P Commonwealth Edison Co BIELAMSKI.A P Isham, Lincola & Beale 83/05/12 Atomic Safety and Licensing Spard Panel 2pp 18468 168 24X Fiche 50-454.83/05/12.8305170565
- --B305170569 Testimony of P Holmbeck re investigation into adequacy of emergency plans re emergency planning contentions. Util made no attempt to study protective value of sheltering papulations around plant HOLMBECK,P DeKalb Area Alliance for Responsible Energy HOLMBECK,P Sinnissippi Alliance for the Environment (SAFE) HOLMBECK,P League of Wamen Voters of Rockford, IL 83/05/12, 73pp 18468 170 24X Fiche 50-454,83/05/12,8305170565
- --8305170572 Testimony of 0 Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable MONTEL.G. Dekalb Area Alliance for Responsible Energy. MONTEL.G. Sinnissippi Alliance for the Environment (SAFE) MONTEL.G. League of Women Voters of Rockford, IL 83/02/16 12pp 18468 245 24X Fiche 50-454.83/05/12.8305170565
- --B305170376 Testimony of JM Maloney on emergency preparadness contentians Util emergency plan cannot be implemented until questions on notification, transportation, communication & liability answered MALONEY. J M DeKalb Area Alliance for Responsible Energy, MALONEY, J M Sinnissippi Alliance for the Environment (BAFE) MALONEY, J M League of Momen Voters of Rockford, IL. 83/02/17, 12pp 18468 257 24X Fiche 30-454,83/05/12,8305170565.
- --8305170581 Testimony of C Lamb re emergency preparedness contentions LAMB,C Dexalb Area Alliance for Responsible Energy LAMB,C, Sinnissippi Alliance for the Environment (SAFE) LAMB,C. League of Homen Voters of Rockford, IL 83/02/16 11pp 18468.271, 24X Fiche 50-454,83/05/12,8305170565
- --8305170588 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications, transportation difficulties & school liability
 TURNER,D Dekalb Area Alliance for Responsible Energy, TURNER,D Sinnissippi Alliance for the Environment (SAFE). TURNER,D, League of Women Voters of Rockford, IL 83/02/10 12pp 18468-282 24X Fichs 50-454,83/05/12.8305170545
- --8305170590 Testimony of D Miller re emergency preparedness contentions Concerns include procedures for & modes of emergency communications, transportation difficulties & school liability MILLER, D DeKalb Area Allience for Responsible Energy MILLER, D. Sinnissippi Allience for the Environment (SAFE) MILLER, D. League of Women Voters of Rockford, IL 83/02/28, 12pp 18468 295, 24% Fiche. 50-454, 83/05/12, 8305170565.
- ---B305170593 Testimony of JL Murphy on Contentions 3 & 13.Listed problems inherent in any radiological accident & should be resolved to provide reasonable degree of safety to ritizens MURPHY.J L. DeKaib Area Alliance for Responsible Energy.

 MURPHY.J L. Sinnissippi Alliance for the Environment (BAFE)

 MURPHY.J L. League of Homen Voters of Rockford, IL 83/02/28

 16pp. 18468 307 24X Fiche 50-454,83/05/12,8305170565.

- 8305310093 Transcript of 830523 hearing in Rockford, IL Pp 6,541-6.675

 * Atomic Safety and Licensing Board Panel 83/05/23 147pp 18655 129 24X Fiche 50-454,83/05/23,8305310093
- 8305310116 Transcript of 830524 hearing in Rockford, IL Pp 6,676-6,951 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/24 359pp 18454 129 24X Fichs 50-454,83/05/24,8305310116

DOCKET STN-50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8305120552 Informs that ABME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III.Div i.Classes 1.2.MC & CB," not acceptable for generic use & not listed in reg guide series, per 830302 submittal YOUNGBLOOD, B J Licensing Branch 1 83/05/03 FARRAR, D L Commonwealth Edison Co 2pp 18443 120. 24X Fiche 50-000, 83/05/03, 8305120552
- B305040323 Board Notification B3-037 forwards differing prof opinions resus interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
 EISENHUT, D. Q Division of Licensing 83/05/04 PALLADING, N Commissioners 22pp 18337 139 24x Fiche 50-000,83/05/04, 8305040323
- 8305100237 Forwards response to FSAR question re crushable pipe whip restraint mati, per 830330 request for add1 info Confirmation test to verify angularity of load results will be completed by 830801 info will be included in F8AR amend SMARTZ.E D Commonwealth Edison Co 83/05/04 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18373 267 24X Fiche 50-000, 83/05/04,8305100237
- 8305110216 Notification of 830513 meeting w/C-E & Westinghouse in Bethesda: MD to discuss seismic & qualification review team results & pump & valve operability OLSHAM: L N Licensing Branch 1 83/05/05 YOUNGBLOOD: B J Licensing Branch 1 3pp 18434 354 24X Fichs 50-454,83/05/05,830510216
- 8305130051 Forwards revised response to Question 270 9.Part C reenviron qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev
 8WARTZ.E D Commonwealth Edison Go 83/05/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18436 313 24X Fiche 50-000,83/05/06,8305130051
- 8305090659 Generic Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods Svc list enc; EIBENHUT, D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627-153 24X Fiche 50-000,83/05/09.8305090659
- 8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Oenerating Station & Control Room Human Factors Engineering Review," Suppls I & II BHARTZ: E D Commonwealth Edison Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation. Director in 18487:001 24X Fiche. 50-000, 83/05/09, 8305180385
- --8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review,"

 Buppls 1 & II

 * Commonwealth Edison Co 83/04/30 22ipp 18487 002 24X
 Fiche: 50-000, 83/05/09, 8305180385
- 8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREO-0874) Supporting documentation encl REED, C. Commonwealth Edison Co. 83/05/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 10pp. 18521:085, 24X Fichs: 50-000, 83/05/11, 8305200621.
- --8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed " CURRAN, R N Energy Incorporated 82/07/06 65pp 18521 095 24x Fiche; 50-000, 83/05/11, 8305200621
- --8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects " * Commonwealth Edison Co 82/11/17, 350pp, 18521 160 24X Fiche: 50-000;83/03/11:8305200621

- --8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment MARCUS GF Commonwealth Edison Co. 81/10/06 App. 18522-150-24X Fiche 50-000
- --B305R00665 Rept of B30307-15 audit to evaluate Sargent & Lundy GA program implementation & adequacy of fecility design SUMMERFIELD.I Commonwealth Edison Co B3/03/23 18pp 18522 136 24x Fiche 30-000.B3/05/11,8305200621
- --8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info enc!

 MARCUS: GF Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche 50-000.83/05/11.8305200621
- --8305200683 Rev C to Procedure 3 0 4, "Design Control New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Draidwood enci WHITAKER,W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fiche 50-000,83/05/11,8305200621
- --83052006B8 Rev O to "Auxiliary Fredwater Sys Design Review Rept " Util GA statement re verification of adequacy of design & const of Byron Unit 1 encl WATTELET.P L. MEISTER, J.R., BRAEGER, C.B. Sargent & Lundy, Inc DRR-AF-001-BB ROO 80/07/16 84pp 18522 303 24X Fiche 50-000,83/05/11,8305200621
- --8305200491 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed " BIOBEE, D Energy Incorporated 93/04/04 127pp 18523-027 24X Fiche 50-000,83/05/11,8305200421
- 8305310086 Notification of 830614 meeting w/util in Bethesda.MD to discuss util DCRDR program plan OLBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305160059 Clarifies commitments retiming for completion of preoperational testing of auxiliary bldg ventilation says Review of SER, NURCG-0876, indicates misunderstanding may exist TRAMM.TR Commonwealth Edison Co. 83/05/11 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 18453 118 24X Fiche 50-454,83/05/11,8305160059
- F Security, medical, emergency & fire protection plans
- 8305040062 Requests that response to NRC position re source range nautron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability YOUNOBLOOD.B J Licensing Branch ! 83/04/11 FARRAR,D L Commonwealth Edison Co 3pp 18336 219 24X Fiche 50-000.83/04/11, 8305040062
- 8305040069 Releases public version of rev to emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/04/22 Document Management Branch ip 16329 092 24X Fiche 50-454,83/04/22, 8305040069
- --B305040074 Forwards public version of rev to emergency plan implementing procedures including Procedures BZP 100-1 restation manager & BZP 310-4 reassembly & evecuation of personnel
 TRAMM.TR Commonwealth Edison Co B3/02/25 DENTON.HR Office of Nuclear Reactor Regulation, Director 1p 18327.093 24X Fiche 50-454.83/04/22.8305040069
- ~-8305040080 Public version of rev to emergency plan implementing procedures, including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel & Commonwealth Edison Co 83/02/10 331pp 18329 094 24X Fiche 50-454.83/04/22.8305040069
- 8305060184 Forwards Rev 8 to security plan Rev withheld (ref 10CFR73 21) FARRAR,D L Commonwealth Edison Co 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18345 090 24X Fiche,50-434,83/04/29,8305060184

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D @ Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

9 Adjudicatory correspondence

- 8303040403 Hemorandum & order denying intervenor 830428 oral motion to keep record open on stram tube integrity subissues Record contains sufficient info to make decision re Unresolved Safety Issue A-3 EMITH, I W Atomic Safety and Licensing Board Panel 83/05/03 League of Women Voters of Rockford, IL 2pp 18323 208 24X Fithe 50-454-83/05/03.8305040403
- B305100286 Application for issuance of encl unsigned subposmas directing attendance & testimony of I Souders & J Ogsbury at ABLB B30523 session in Rockford, IL Certificate of Svc enc; HHICHER, J M League of Homen Voters of Rockford, IL HHICHER, J M DeKalb Area Alliance for Responsible Energy HHICHER, J M Sinnissippi Alliance for the Environment (SAFE) B3/05/06 SUDERS, I OGSBURY, J Affiliation Unknown 7pp 18371 134 24X Fiche 30-454,83/05/06,8305100286
- 8305100172 NRC response to joint intervenor motion to reopen record raised under Contention IA concerning J Hughes testimony on GC/GA Staff opposes further hearing on subj matters 70UNO, M A Atomic Safety and Licensing Board Panel 83/05/09, 7pp 18374,323 24X Fiche 30~454.83/05/09,8305100172
- --8305100176 Affidavit of DW Hayes & KA Connaughton re statement by J Hughes supporting intervenor motion to reopen record HAYES, D W. CONNAUGHTON, K. Region S. Office of Director 83/05/09 13pp 18374 330 24X Fiche 50-454,83/05/09,8305100172
- 8305110213 Response in apposition to Rockford League of Women Voters & Dekelb Area Alliance for Responsible Energy/Safe Alternatives for Future Energy motion to allow testimony of J Hughes on GA/GC Certificate of Svc encl
 BECKER, B D Commonwealth Edison Co BECKER, B D Isham, Lincoln & Beale 83/05/07 About 58/644 and Licensing Board Panel 13pp 18407.039 24X Fiche 30-454,83/05/07,8305110213
- 8305120279 Discusses order of witness presentation for hearings resuming on 830523 NRC will present witnesses an liquid pathway contention first, followed by wtil, Rockford League of Homen Voters & util rebuttal witnesses GALLD, J Isham, Lincoln & Beale GALLD, J Commonwealth Edison Co. 63/05/10 6MITH. I W. COLE.R F. CALLIMAN, A D. Atomic Bafety and Licensing Board Panel. 2pp 18430 169 24X Fiche 50-434,83/05/10,8305120299
- 8305160040 Affidavit of RP Tuetken on J Hughes allegations re welding Welding of brace to pressure pipe proper. If performed per design specs Util conducting reinsp of work performed by contractor GC inspectors
 TUETKEN.R P Commonwealth Edison Co 83/05/11 3pp 18453 120 24X Fiche 50-454.83/05/11,8305160060
- 8305170314 Confirms mailing of proprietary version of Pages 4691.4692 & 4699 from 830415 transcript, per terms of Westinghouse nandisclosure agreement Method for circulating nanproprietary portion to PDRs being worked out.

 DAVIS.F X Westinghouse Electric Corp 83/05/11 THOMAS.D Affiliation Unknown 2pp 18465 076 24X Fiche 50-434,83/05/11,8305170314
- B305170319 Forwards nondisclasure agreement signed on B30427 Terms of agreement should be used to handle Westinghouse proprietary info contained in B30415 transcript Nethod for circulating nonproprietary partion to PDRs being worked out M/o enci DAVIS.F X Westinghouse Electric Corp 83/05/11 CHAVEZ.D DeKalb Area Alliance for Responsible Energy CHAVEZ.D Simissippi Alliance for the Environment (SAFE) ip. 18465 362, 24X Fiche 30-404.83/05/11,8305170319.
- B305170334 Forwards application for withholding from public disclosure Hestinghouse proprietary info discussed in B30415 meeting. Method for circulating nonproprietary portions of B30415 transcript to PDRs being worked out H/o encl DAVIB,F X Hestinghouse Electric Corp B3/05/11 SMITH,I H: COLE,R F, CALLIHAN,A D Atomic Safety and Licensing Board Panel 2pp 18469 006 24X Fiche, 50-454,83/05/11,8305170334
- B305170522 Forwards nondisclosure agreement signed on B30426 & proprietary version of Pages 4691,4692 & 4699 from 830415 transcript W/o proprietary pages DAVIS.F X Hestinghouse Electric Corp B3/05/11 BRIDENBAUGH, D JOHNSON, B , BUNCH, R. League of Homen Voters of Rockford, IL ip 18467 251 24X Fichs 50-454.83/05/11,8305170522

- 8305160162 Memorandum & order scheduling special deposition session for 830526 in Rockford. IL to take deposition of J Hughes A possibly of Rouders & Ogsbury 8MTH, I W About Bafety and Licensing Board Panel 83/05/12 8pp 18444 036 24X Fiche 50-454.83/05/12,8305160162
- 8305170297 Forwards stipulation w/affidavits & ambulance survey readmission of certain evidence offered by intervenors on emergency planning issues Upon admission of evidence-hearing record should be closed 8vc list enc! W/o stated enc! BIELAWBKI.A P Isham, Lincoln & Beale BIELAWBKI.A P Commonwealth Edison Ca 83/05/12 SMITH.I W CULE.R F , CALLIHAN.A D Atomic Safety and Licensing Spard Pane! Spp 18455 063 24X Fiche 50-454,83/05/12,8305170297
- 8303:70565 Motion to receive into evidence stipulation & portions of grefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters Munexecuted stipulation DIELAMBKI.A P. Commonwealth Edison Co. BIELAMBKI.A P. Isham, Lincoln & Reale 83/05/12. Atomic Safety and Licensing Board Panel 2pp 18468:168 24X Fiche 50-456,83/05/12.8305170565
- 8305200521 Hemorandum & order approving stipulation to offer into evidence Joint Intervenors Exhibits 13 20 Bipulation will be bound into 830523 transcript Proposed findings & conclusions on emergency planning issues due 830620 BNITH. I W Atomic Bafety and Licensing Board Panel 83/05/17 Office of the Executive Legal Director. 1p. 18516 085, 24% Fiche 30-454,83/05/19,8305200521
- @ Inapaction reports. IE Bulletine & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Syc list encl TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 317 24% Fishe 50-000:83/03/21.8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator' Svc 11st encl JUPRANNEL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of Heavyork, Inc. 126pp. 18435-155 24X Fiche, 30-000, 83/04/13, 8303040021.
- 8303040023 IE Info Notice 83-22, "BWR Bafety/Relief Valve Failures *
 Bvc 1(st encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp. 18383:089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IC Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys." Byc list encl. JORDAN: E L. Division of Emergency Properedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291, 24X Fiche. 50-000, 83/04/25, 8303040025
- 8303170238 Forwards IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 & 31, No noncompliance noted. PAPERIELLO, G. J. Region 3. Defice of Director. 83/04/26. REED, C Commonwealth Edison Co. 2pp. 18465.087 24X Fiche: 50-454.83/04/26. 8303170238.
- --8305170248 IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 \$ 31 No noncompliance noted Major areas inspected environ protection including preoperational radiological environ monitoring implementation & results & mgt controls. OESTMANN.M. J. 8CHUMACHER.M.C. Region J. Office of Director. 83/04/25 7pp. 18465.089. 24X Fiche: 50-454,83/04/26,8305170238
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Bteam Camerators at PWRs." Svc list encl JORDAN.E.L. Division of Emergency Preparadness & Engineering Rasponse (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp. 18382-047. 24X Fiche. 50-000, 83/04/28, 8303040026
- 8303040027 IE Info Notice 83-25. "Standby Cas Treatment Sys Hester High Temp Trip Setpoint Adjustment." Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83704/28 Consolidated Edison Co. of New York, Inc. 118pp 18382-145 24X Fiche: 50-000, 83/04/28, 8303040027
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl. URDANIE L. Division of Emergency Preparedness & Engineering Response (Fost 830102). 83/05/03. Consolidated Edison Co of New York, Inc 122pp 18441.170. 24X Fiche: 50-000,83/05/03,8303040028

- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York: Inc. 112pp 18382 282 24X Fichs 50-000.83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- B305190019 Forwards IE Insp Repts 50-454/83-15 & 50-455/83-13 on B30321 & 28-31 No noncompliance noted LITTLE, N. B. Region 3, Office of Director B3/05/04 REED, C Cammonwealth Edison Co 2pp 18502 004 24X Fiche 50-454,83/05/04,8305190019
- --8305190027 IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted Major areas inspected evaluation of NDE results for pool liner welds & review of quality records WARD,K 0, DANIELSON,D H Region 3, Office of Director 83/04/29, 11pp 18502 006 24X Fiche 50-454.83/05/06.8305190019
- 8305130127 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 30-455/82-04 SESSARD.R L Region 3, Diffice of Director 83/05/10 REED.C Commonwealth Edison Co. ip 18437 280 24X Fiche 50-454,83/05/10,8305170129
- --8305130135 Responds to NRC 820424 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Welding procedures & instructions need not be at each location where actual welding performed, per ABME Code BTIEDE, W.L. Commonwealth Edison Co 83/01/03 KEPPLER, J O Region 3, Office of Director 3pp 18437 281 24X Fiche: 50-454, 83/05/10, 8305130129
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp. 18524 003. 24X Fiche 50-000,83/05/11,8303040034
- 8305170458 Confirmatory action ltr re insp of pipe whip restraints in safety-related high energy piping sys on 830503-04 & 09-10. Restarting installation of whip restraints contingent upon transmittal of as-built drawings to Sargent & Lundy KEPPLER, J Q Region 3, Office of Director 83/05/13 REED, C Commonwealth Edison Co. 2pp 18469 319 24X Fiche 50-454, 83/05/13, 8305170458.
- 8305200508 Ack receipt of 830210 & 0504 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-434/82-17 & 50-435/82-12.

 8FESSARD, R L Region 3, Office of Director 83/05/17 REED, C Commonwealth Edison Co ip 18516:060 24X Fiche. 50-454, 83/05/17, 8305200508
- --8305200522 Responds to 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions contractor placed hold tags on 50 panels & notified electrical const dept per Procedure & FARRAR, D L Commonwealth Edison Co 83/05/04 KEPPLER, J, Q Region 3, Defice of Director App 18516, 061 24X Fichs 50-454, 83/05/17, 8305200508
- --8305200540 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 30-454/82-17 & 50-455/82-12 Corrective actions contractor instructed to identify panels which contained cable separation problems & hold tags placed on panels FARRAR, D. L. Commonwealth Edison Co. 83/02/10, KEPPLER, J G Region 3, Office of Director, 7pp 18516 067 24X Fiche: 50-454,83/05/17,8305200508
- B305240524 Confirms arrangements for B30513 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers NORELIUS, C E Division of Project & Resident Programs 83/05/18 REED, C, Commonwealth Edison Co. ip 18571 181 24X Fiche: 50-000, 83/05/18, 8305240524

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 83033040040
- 8305260278 Ack receipt of 830417 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-434/83-07 & 50-435/83-03 Finding only 10 rejectable welds out of 1.067 not proper indication of inspector performance NORELIUS.C E Division of Project & Resident Programs 83/05/20 REED.C Commonwealth Edison Co ip 18625 136 24X Fiche 50-454.83/05/20.8305260278
- --8305260282 Responds to NRC 830324 ltr re violations noted in IE Insp Repts 50-454/63-07 & 30-455/83-03 Corrective actions welds reinspected New onsite contractor GA/GC qualification procedures implemented FARRAR.D L Commonwealth Edison Co 83/04/19 KEPPLER, J G Region 3, Office of Director 3pp 18625 157 24X Fiche 30-454,83/05/20,8305260278
- 8305270476 Ack receipt of 830429 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing math tests

 SPESSARD.R L Division of Engineering 83/05/24 REED.C Commonwealth Edison Co ip 18644 087 24X Fiche 50-000,83/05/24,820570474
- --B3052704B9 Responds to NRC 830331 ltr re violations noted in IE Insp. Repts 50-454/B3-06 & 50-455/83-05 Corrective actions site design procedures compiled into manual by Westinghouse & issued to facility for site use on 830415 FARRAR, D. L. Commonwealth Edison Co. 83/04/29 KEPPLER, J. O. Region 3. Office of Director lipp 18644 OBS 24X Fiche 50-000, 63/05/24, 8305270476
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list entl JORDAN,E L Division of Energency Preparedness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices initially reported on 830420 Attachments will be replaced w/devices w/widened gradges to accommodate new retaining rings Mfg drawings revised RAME.E P Westinghouse Electric Corp 83/04/21 DEYQUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427
- B305030270 Final deficiency rept re reactor coolant pump & steam generator support columns not installed within tolerances specified on Bargent & Lundy Design Drawing S-1105 Initially reported on B3025 Revised tolerances will be verified BWARTZ,E D Commonwealth Edison Co B3/04/25 KEPPLER:J G. Region G. Office of Director 3pp 18300 027 24X Fiche 50-454,83/04/25,8305030270
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO,8 F Niagara Mohauk Power Corp 83/04/26 STAROSTECKI,R Region 1, OFFice of Director 2pp 18433-072, 24X Fiche 50-000,83/04/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOGA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83/03/11. CDLLINB, J T. Region 4. Office of Director 3pp 18433 074 24X Fiche 30-000,83/04/28,8305120392
- B305190233 PND-III-B3-035 on B30511, licensee stopped work on new installation of pipe-whip restraints on safety-related piping per B30513 confirmatory action ltr Restraints installed w/o adequate procedures or GC insp program DANIELSON,D. H. LITILE, W. 8. Region 3, Office af Director B3/05/13 p. 18501-318 24X Fiche 50-454, B3/05/13, B305190233.
- T. Hearing transcripts on non-antitrust matters
- B305040349 Transcript of B30415 hearing in Rockford, IL Pp 4.67 Supporting documentation encl * NRC - No Detailed Affiliation Given B3/04/15 163pc 18323.031 24X Fiche 50-454:B3/04/15:B305040349

- 8305020163 Transcript of 830426 hearing in Rockford.1L Pp 3.964-6.156 * NRC - No Detailed Affiliation Given 83/04/26 192pp 18277 301 24x Fiche 50-454.83/04/26.8305020163
- 8305170408 Forwards proprietary & nonproprietary versions of statements made by NRC witness re Hestinghouse Model D4/D5 steam generators Proprietary info withheld (ref 10CFR2 790) RAHE.E P Westinghouse Electric Corp 83/04/26 EISENMUT, D C Division of Licensing 1p 18469 326 24X Fiche 50-454,83/04/26,8305170408
- --8305170411 Forwards application for withholding proprietary version of statements made by NRC witness re Westinghouse Model D4/D5 steam generators per 10CFR2 790 WIESEMANN.R A Westinghouse Electric Corp 83/04/26 EISENNUT.D G Division of Licensing 9pp 18469 327 24X Fiche 50-454,83/04/26,8305170408
- --8305170413 Nongraprietary version of statements made by Rajan re Hestinghouse Model D4/D5 steam generators Pp 4.691-4.692 & 4.699 RAJAN NRC - No Detailed Affiliation Given 83/04/26 3pp 18469 336 24X Fiche 50-454,83/04/26,8305170408
- 8305030305 Transcript of 830427 hearing in Rockford. IL Pp 6.157-6.400 * NRC - No Detailed Affiliation Given 83/04/27 204pp 18296 200 24X Fiche 50-454.83/04/27.8305030305
- B305030508 Motion to permit J Hughes testimony re QA/QC at facility & to shorten time for responses by util & NRC Matters of testing documentation & welding constitute significant safety issues HHICHER.J M League of Homen Voters of Rockford, IL. HHICHER.J M DeKalb Area Alliance for Responsible Energy & HHICHER.J.M Safe Energy for New Haven B3/04/27 Atomic Safety and Licensing Board Panel 4pp 18295 091 24% Fiche 50-454,83/04/27,B30503008
- --8305030516 Handwritten testimony of J Hughes re GA/GC at facility HUGHES,J Leagus of Homen Voters of Rockford, IL HUGHES,J DaKalb Area Alliance for Responsible Energy HUGHES,J Safe Energy for New Haven 83/04/25 3pp 1829
- 8305030391 Transcript of 830428 hearing in Rockford, IL Pp 6.401-6.540 Supporting documentation encl • NRC - No Detailed Affiliation Given 83/04/28 221pp 18295 329 24X Fiche 50-454.83/04/28,8303030391
- 8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unerecuted stipulation
 BIELAMSKI/A P Commonwealth Edison Co B3/05/12 Atomic Bafety and Licensing Board Panel 2pp 18468-168 24X fiche 50-454,83/05/12.8305170565
- ---8305170369 Testimony of P Halmbeck re investigation into adequacy of emergency plans re emergency planning contentions Util made no attempt to study protective value of sheltering populations around plant HOLMBECK, P Dekalb Area Alliance for Responsible Energy HOLMBECK, P Sinnissippi Alliance for the Environment (SAFE) HOLMBECK, P League of Nomen Voters of Rockford, IL 83/05/12 73pp 18468 170 24X Fiche 50-454,83/05/12,8305170565
- --8305170572 Testimony of Q Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable MONTEL.Q Dekalb Area Alliance for Responsible Energy MONTEL.Q Sinnissippi Alliance for the Environment (SAFE). MONTEL.Q League of Women Voters of Rockford, IL 83/02/16 12pp 18468 245 24% Fiche 50-454,83/05/12,8305170565
- --B305170576 Testimony of JM Maloney on emergency preparedness contentions Util emergency plan cannot be implemented until questions on notification, transportation, communication & liability answered MALONEY, JM DeKalb Area Alliance for Responsible Energy MALONEY, JM Sinnissippi Alliance for the Environment (SAFE) MALONEY, JM League of Momen Voters of Rockford, IL B3/02/17. 12pp 18468 257 24% Fiche 50-454.83/05/12,8305170565
- --8305170381 Testimony of C Lamb rs emergency preparadness contentions LAMB.C DeXalb Area Alliance for Responsible Energy LAMB.C Sinnissippi Alliance for the Environment (SAFE) LAMB.C League of Women Voters of Rockbord, IL 83/02/16 11pp. 18468 271 24X Fiche 30-454.83/05/12,8305170365

- --8305170588 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications, transportation difficulties & school blability school blability TURNER, D Dekalb Area Alliance for Responsible Energy TURNER, D Sinnissippi Alliance for the Environment (SAFE) TURNER, D League of Women Voters of Rockford, IL 83/02/10 12pp 18468 282 24X Fiche 50-454,83/05/12,8305170555
- --8305170590 Testimony of D Miller re emergency preparedness contentions Concerns include procedures for & modes of emergency communications transportation difficulties & school liability MILLER, D DeKalb Area Alliance for Responsible Energy MILLER, D, Sinnissippi Alliance for the Environment (SAFE) MILLER, D League of Homen Voters of Rockford, IL 83/02/28 12pp 18468 275 24% Fiche 50-454,83/05/12,8305170555
- --8305170593 Testimony of JL Murphy on Contentions 3 & 13 Listed problems inherent in any radiological accident & should be resolved to provide reasonable degree of safety to citizens MURPHY. J L DeKalb Area Alliance for Responsible Energy MURPHY. J L Sinnissippi Alliance for the Environment (SAFE). HURPHY. J L League of Women Voters of Rockford, IL 83/02/28 16pp, 18468 307 24X Fiche 50-454,83/05/12,8305170565
- 8305310093 Transcript of 830523 hearing in Rockford, IL Pp 6,541-6,675 * Atomic Safety and Licensing Board Panel 83/05/23 167pp 18655 129 24X Fiche 50-454,83/05/23,8305310093
- 8305310116 Transcript of 830524 hearing in Rockford, IL Pp 6,676-6,951 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/24 359pp 18556 129 24X Fiche 50-454.83/05/24,8305310116
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

 A Application/construction stage documents & correspondence
- B305120552 Informs that ABME Code Case N-340. "Alternate Rules for Exam of Weld Edge Preparation Section III. Div 1. Classes 1.2.MC & CS." not acceptable for generic use & not listed in reg guide series.per B30302 submittel Y0UNOBLOOD, B J Licensing Branch 1 B3/05/03 FARRAR, D, L Commenwealth Edison Co 2pp 18443 120 24X Fiche 50-000.83/05/03. B305120552
- 8303100237 Forwards response to FBAR question re crushable pipe whip restraint matl.per 830330 request for addl info Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FBAR amend SWARTZ.E D Commonwealth Edison Co 83/05/04 DENTON.H.R Office of Nuclear Reactor Regulation, Director 2pp 18373 269, 24X Fiche 30-000,83/05/04,8305100237
- B305130001 Forwards add1 FBAR info, responding to Questions 241 1,241 2, 241 7 % rev to 241,6-3 in NRC 830114 % 0201 ltrs F8AR will be amended to include info SWARTZ,ED Commonwealth Edison Co 83/05/06 DENTON,H,R Office of Nuclear Reactor Regulation, Director 24pp 18436-344 24X Fiche 30-456,83/05/06,8305130001
- B30313005i Forwards revised response to Question 270 9, Part C re environ qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev SWARTZ,E D Commonwealth Edison Go 83/05/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18436-313 24X Fiche 50-000, 83/05/06, 8305130051
- 8305090439 Ceneric Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT, D 0 Division of Licensing 83/05/09 Convolidated Edison Co of New York, Inc. 14pp 19427 153 24X Fichs 50-000, 83/05/09, 8305090659
- 8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review, "Suppls 1 & II. BWARTZ.E D. Commonwealth Edison Co 83/05/09 DENTON.H.R. Office of Nuclear Reactor Regulation, Director ip 18487 001 24X Fiche 50-000,83/05/09,8305180385
- --8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review,"
 Suppls I & II
 * Commonwealth Edison Co 83/04/30 221pp 18487-002, 24X
 Fiche 50-000,83/05/09,8305180385

- B305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREO-0876) Supporting documentation encl REED.C Commonwealth Edison Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fichs 30-000,83/05/11,8305200621
- --8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed" CURRAN,R N Energy Incorporated 82/07/06 65pp 18521 095 24X Fiche 50-000,83/05/11,8305200621
- --8305200447 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects "
 a Commonwealth Edison Co 82/11/17 350pp 18521 140 24% Fiche 50-000,83/05/11,8305200621
- --8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment MARCUS, 0 F Commonwealth Edison Co 81/10/04 6pp 18522 150 24X Fiche 50-000,83/05/11,8305200621
- --8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy GA program implementation & adequacy of facility design BUMMERFIELD.T Commonwealth Edison Co 83/03/23 189p 18522 156 24X Ficher 50-000, 63/05/11,8305200621
- --8305200675 Rept of 820607-il audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info anci MARCUS, 0 F Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche 50-000,83/05/11,8305200621
- --8305200683 Rev C to Procedure 3 0 4, "Design Control New Design, Byran Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl WHITAKER,W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fithe 50-000,83/05/11,8305200621
- --83052006BB Rev O to "Auxiliary Feedwater Sys Design Review Rept "-Util GA statement re verification of adequacy of design & const of Byron Unit i encl HATTELET, P. L. Sargent & Lundy, inc. DRR-AF-001-88 ROO 80/07/16 26pp 18523 001 24X Fiche 50-000,83/05/11,8305200621
- --8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed." BIOREE, D Energy Incorporated 83/04/04 127pp 18523 027 24X Fiche 50-000,83/05/11,8305200621
- 8305260287 Forwards add1 FSAR info on Questions 241 3 & 330 1 re lean concrete & toxic mat1 shipments, respectively & revised response to Questions 241 5 & 241 7 per 83014 1tr Info will be included in FSAR amend SMARTZ.E D Commonwealth Edison Co 83/05/23 DENTON.H R. Office of Nuclear Reactor Regulation. Director lipp 18625 145 24X Ficher 30~456, 83/05/23, 8305260287
- 6305310086 Notification of 630614 meeting w/util in Bethesda: MD to discuss util DCRDR program plan GILBERT.R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD: D Operating Reactors Branch 5 2pp 18658 063 24X Fiche. 50-000: 83/05/26: 8305310086
- F Security, medical, emergency & fire protection plans
- 8305040062 Requests that response to NRC position re source range neutron flux manitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability YOUNGBLOOD, B. J. Licensing Branch 1 83/04/11 FARRAR, D. L. Commonwealth Edison Co. 3pp. 18336 217 24X Fiche 30-000,83/04/11,83350.40062
- 8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No moncompliance noted KNOP, R C. Region 3, Office of Director 83/05/04 REED, C Commonwealth Edison Co 2pp 18548 212 24X Fichs 50-456,83/05/04, 8305240264
- --8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins action on previously identified items & fire protection requirements HINDS.J.M. HAYES.D W Region 3, Office of Director 83/05/03 7pp. 18548 214 24X Fiche 50-456.83/05/04.8305240264

- B305110034 Generic Ltr B3-2: to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540-095 24X
 Fiche 30-000.83/05/11.8305110034
- B305240213 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983 DIRCKS,M J Office of the Executive Director for Operations B3/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X Fiche 50-000.83/05/13.8305240213
- B305270079 Forwards expanded resume for station health physicist & proposed training program FSAR will be amended to reflect changes
 BHARTZ.E D Commonwealth Edison Co B3/05/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 18638 293 24X Fiche 50~436,82/05/23,8305270079
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24x Fiche 50-000.83/03/21.2212040385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Cansolidated Edison Co of New
 York, Inc 126pp 18435-155 24X Fiche 50-000.83/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Reizef Valve Failures "
 Svc list encl
 JURDAN.C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 50-000,83/04/25,8303040025
- B305020110 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Request to withdraw Violation 3 denied Audit revealed 176 drawings missing NORELIUS: C E Division of Project & Resident Programs 83/04/25 REED. C Commonwealth Edison Co 2pp 18278 203 24X Fiche 50-456.83/04/25.8305020110
- --8305020115 Responds to NRC 830214 ltr re violations noted in 1E Insp. Repts 50-456/82-08 & 50-457/82-08 Corrective actions grounding connection removed floor drains cleaned & foreign math removed from cable pans FARRAR, D L. Commonwealth Edison Cu. 83/03/16 KEPPLER, J G Region J. Office of Director 9pp 18278 205 24X Fiche 50-454,83/04/25,8305020110
- 8305020224 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations & 830202 proposed imposition of civil penalties noted in IE Insp. Repts 50-456/82-05 & 50-457/82-05
 NORELIUS.C E Division of Project & Resident Programs REED.C Commonwealth Edison Co 1p 18278 144 24X Fiche 50-456,83/04/26,8305020224
- --8305020734 Responds to NRC 830225 ltr re violations noted in IE lnsp Repts 30-456/82-05 & 30-457/82-05 Corrective actions full-time project manager assigned to site & improvements in organization & procedures of site contractors made REED,C Commonwealth Edison Co 83/04/04 XEPPLER, J 9 Region 3. Office of Director 22pp 18278 145 24X Fiche 50-456,83/04/26,8305020224
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/20 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Svc List enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

- 8309060947 Ack receipt of 830308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/81-14 & 50-437/81-14 BFEBSARD.R L Division of Engineering 82/05/02 REED.C Commonwealth Edison Co 1p 18348 245 24X Fiche 50-456.83/05/02, 8309060347
- --830S0A0559 Responds to NRC 830105 ltr re violations noted in IE Insp Repts 30-436/81-14 & 50-457/81-14 Corrective actions restressing of eight dome tendons w/liftoff values below predicated level began 830307 SWARTZ.E D Commonwealth Edison Co 83/03/08 KEPPLER, J 0 Region 3, Office of Director ip 18348 246 24X Fiche 50-456,83/05/02,8305060547
- B303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc 1/2pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted KNOP, R C Region 3. Office of Director 83/05/04 REED, C Commonwealth Edison Co 2pp 18548 212 24X Fiche 50-456,83/05/04, 8305240264
- --8305240268 IE lnsp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins, action on previously identified items & fire protection requirements HINDS, J M. HAYES, D M. Region 3, Office of Director 83/05/03 7pp 18548, 214 24% Fiche 50-456, 83/05/04, 8305240264
- 8303040033 IÉ Info Notice 83-29, "Fuel Dinding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers NORELIUS.C E Division of Project & Resident Programs 83/05/18 REED.C Commonwealth Edison Co ip 18571 181 24% Fiche 50-000.83/03/18,8305240524
- 8303040040 IE Into Notice 83-31. "Error in ADLPIPE Computer Program "
 Bvc list encl.
 JURDAN.E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8305270191 Ack receipt of 830331 ltr in response to items of noncompliance noted in IE Insp Rept 50-456/82-06 ltems i a 3 & 4.a incomplate item 4 a re nonconforming cable reels deleted.per Region II 830510 meeting SPESSARD.R L Region 3, Office of Director 83/05/23 REED.C Commonwealth Edison Co 2pp 18637 344 24% Fiche 50-456,83/05/23,8305270191.
- --8305270193 Responds to notice of violation noted in IE Insp Rept 30-435/82-06 Corrective actions field walkdown of cable tray sys will be performed to identify pulled cables installed w/separation less than required FARRAR.D Commonwealth Edison Co 83/03/31 KEPPLER,J G Region 3. Office of Director 6pp 18637 346 24X Fichm 50-436,83/05/23,8305270191
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.

- S Reportable occurrences, LERs & related correspondence
- 8305110427 Part 21 & deficiency repts re misoperation of D8-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Hfg drawings revised RAHE.E F Westinghouse Electric Corp 83/04/21 DEYOUNG.R.C Director's Uffice, Office of Inspection and Enforcement 5pp 18405 075 24% Fiche 50-000.83/04/21.8305110427
- DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305120552 Informs that ASME Code Case N-340. "Alternate Rules for Exam of Wold Edge Preparation Section III, Div 1.Classes 1,2:MC & CB." not acceptable for generic use & not listed in reg guide series.per 830302 submittal YDUNGBLODD, B J Licensing Branch 1 83/05/03 FARRAR.D L Commonwealth Edison Co 2pp 18443 120 24X Fiche 50-000.83/05/03.
- 8305100237 Forwards response to FSAR question re crushable pipe whip restraint math.per 830330 request for addl info. Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FSAR amend SMARTZ.E D Commonwealth Edison Co 83/05/04, DENTON.H R Dffice of Nuclear Resctor Regulation, Director 2pp 18373 269 24X Fiche 50~000,83/05/04,8305100237
- B305130001 Forwards add1 FSAR info, responding to Questions 241 1.241.2. 241 7 & rev to 241 6-3 in NRC B30114 & 0201 Itrs FBAR will be amended to include info SMARTZ.E D Commonwealth Edison Co B3/05/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 24pp 18436-344, 24X Fiche 30-436,83/05/06,8305130001
- 8305130051 Forwards revised response to Question 270.7.Part C resolvino qualification program Representative sample of active mechanical equipment in harsh environ qualified FBAR will be amended to include rev. SWARTZ.E D Commonwealth Edison Co 83/05/06 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp 18436-313, 24X Fiche 50-000.83/05/06.8305130051
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENHUT, D G Division of Licensing 83/05/09, Consolidated Edison Co of New York, Inc 16pp 18627, 153 24% Fiche 50-000, 83/05/09, 8305090659
- B305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review." Suppls I & II.
 SHARTI.E D Commonwealth Edison Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director. 10 18487.001 24X
 Fiche 50-000,83/05/09,8305180385
- --8305180397 "Freliminary Design Assessment of Byron/Breidwood Generating Station Control Room Human Factors Engineering Review,"
 Suppls I & II
 * Commonwealth Edison Co 83/04/30 221pp. 19487 002 24X
 Fiche 50-000,83/05/09,8305180395
- 8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREO-0876) Supporting documentation encl. REED: Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Resctor Regulation, Director 10pp 18521 085 24X Fiche 50-000.83/05/11.8305200621
- --8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed" CURRAN, R N Energy Incorporated 82/07/06 65pp 18521 095 24% Fiche, 50-000, 83/05/11, 8305200621
- --8305200447 "Rept on INPO Self-Injtiated Evaluation for Syron & Statiowood Nuclear Station Conet Projects."

 + Commonwealth Edison Co. 82/11/17 350pp 18521.160 24X Fiche 50-000,83/05/11,8305200621
- --8305200655 Rept of 810929-30 audit to verify Bargent & Lundy conformance to NVREG-0588 re environ qualification of Class IE electrical equipment MARCUS, G F Commonwealth Edison Co 81/10/06 App 18522;130 24X Fiche, 50-000, 83/05/11, 8305200621

- --8305200665 Rept of B30307-15 audit to evaluate Sargent & Lundy GA program implementation & adequacy of facility design SUMMERFIELD.T Commonwealth Edison Co 83/03/29 18pp 18522 136 24X Fiche 50-000.B3/05/11.B305200621
- --8305200675 Rept of 820607-11 audit re Sargent & Lundy GA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
 encl
 MARCUS, 0 F Commonwealth Edison Ca 82/06/17 48pp 18522 174
 24X Fiche 50-000.83/05/11.8305200621
- --83052006B3 Rev C to Procadure 3 0 4. "Design Control New Design. Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood and! WHITAKER:W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fiche 50-000.83/05/11.8305200621
- --830520068B Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util GA statement re verification of adequacy of design & const of Byron Unit 1 encl WATTELET.P L Sargent & Lundy, Inc DRR-AF-001-88 R00 B0/07/16 26pp 18523 001 24% Fiche 50-000,83/05/11,8305200621,
- ---B305200491 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed " B108EE,D Energy Incorporated 83/04/04 127pp 18523 027 24X Ficha 50-000,83/05/11,8305200621
- B303260287 Forwards add1 FSAR info on Questions 241 3 & 330 1 re lean concrete & toxic math shipments, respectively & revised response to Questions 241 5 & 241 7 per 830114 ltr Info will be included in FBAR amend BHARTLE D Commonwealth Edison Co 83/05/23 DENION, H R Office of Nuclear Reactor Regulation, Director 11pp 18625 145 24X Fiche 30-436,83/05/23,8305260287
- B305310086 Natification of B30614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan OILBERT, A Operating Reactors Branch 5 B3/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000
- F Security, medical, emergency & fire protection plans
- B305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability YdUNGBLOOD.B.J Licensing Branch I B3/04/11 FARRAR.D L Commonwealth Edison Co 3pp 18336 221 24X Fichs 50-000.83/04/11.8305040062
- 8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted KNOP.R C Region 3: Office of Director 83/05/04 REED.C Commonwealth Edison Co 2pp 18548 212 24X Fiche 50-456,83/05/04,8305240264
- --8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licenses response file for IE circulars & bulletins, action on previously identified items & fire protection requirements HINDS, J M Region 3, Office of Director 83/05/03 7pp 18548 214 24% Fiche 50-456,83/05/04.8305240264
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Bvc list encl EIBENHUT, D 0 Division of Licensing 63/05/11 Consolidated Edison Co of New York, Inc 16pp 16540-075. 24X Fiche: 50-000, 83/05/11, 6305110034
- 8305270079 Forwards expanded resume for station health physicist & proposed training program FSAR will be amended to reflect changes SHARTZ/E D Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation. Director 5pp 18638 293 24x Fische: 50-456,83/05/23,8305270079
- Q. Inspection reports, IE Bulletine & correspondence
- 8212040385 IC Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212040385

- B303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator"
 Svc list encl
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/15 Consolidated Edison Co of New
 York, Inc 124pp 18435 155 24X Fiche 50-000, B3/04/15, B303040021
- B303040023 IE Info Notice 83-22. "BWR Safety/Ralief Valve Failures"
 Svc list encl
 JORDAN.C L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 244 Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 82/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24x Fische 50-000, 83/04/25, 8303040025
- B305020110 Ack receipt of B30316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-436/82-08 & 50-457/82-08 Request to withdraw Violation 3 denied Addit revealed 196 drawings missing NRELIUS.C E Division of Project & Resident Programs B3/04/25 REED.C Commonwealth Edison Co 2pp 18278 203 24X Fishe 50-436, 83/04/25, 8305020110
- --8305020115 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-455/82-08 & 50-457/82-08 Corrective actions grounding connection removed floor drains cleaned & foreign matl removed from cable pans FARRAR, D L Commonwealth Edison Co 83/03/16 XEPPLER, J G Region J. Office of Director 9pp 18278 205 24X Fiche 50-456,83/04/25,8305020110
- 8305020224 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations & 830202 proposed imposition of civil penalties noted in IE Insp Repts 50-456/82-05 & 50-457/82-05
 NORELIUS, C E Division of Project & Resident Programs 83/04/26 REED.C Commonwealth Cdison Ca ip 18278 144 24X Fiche 50-456,83/04/26,8305020224
- --8305020234 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-456/82-05 & 50-457/82-05 Corrective actions full-time project manager assigned to site & improvements in organization & procedures of site contractors made REED, C Commonwealth Edison Co 83/04/04 KEPPLER, J 0 Region 3, Office of Director 22pp 18278 145 24X Fiche 50-456, 83/04/26, 8305020224
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040024
- 8303040027 IE Info Notice 83-25, "Standby Bas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8305060547 Ack receipt of B3D308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-455/81-14 & 50-457/81-14 SPESBARD, R L Division of Engineering 82/05/02 REED, C Commonwealth Edison Co ip 18348 245 24X Fiche 50-456.83/05/02, 8305060547
- --8305060559 Responds to NRC 830105 ltr re violations noted in IE Insp Repts 50-456/81-14 & 50-457/81-14 Corrective actions restressing of sight dome tendons w/liftoff values below predicated level began 830307 SMARTZ.E D Commonwealth Edison Co 83/03/08 KEPPLER.J 9 Region 3. Office of Director ip 18348 246 24X Fiche 50-456,83/05/02,8303060547
- 8303040028 IE Info Notice 83-24. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Evolist encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc. \$12pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted KNOP, R C Region 3. Office of Director 83/05/04 REED, C Commonwealth Edison Co 2pp. 18548 212 24% Fiche 50-456, 83/05/04, 8305240264
- --8305240268 IE Insp Repts 50-456/B3-05 & 50-457/B3-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins.action on previously identified items & fire protection requirements HINDS, J M . HAYES, D W Region 3, Office of Director 83/05/03 7pp 18548 214 24% Fiche 50-456,83/05/04,8305240264
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers NGRELIUS.C E Division of Project & Resident Programs 83/05/18 REED.C Commonwealth Edison Co ip 18571 181 24X Fiche 50-000,83/05/18,8303240524
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil" Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York
- S Reportable occurrences, LERs & related correspondence
- B305i10427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Hfg drawings revised RAHE.E P Westinghouse Electric Carp B3/04/21 DEYOUNO, R C Director's Office, Dffice of Inspection and Enforcement 3pp 18405 075 24X Fiche 50-000.83/04/21,8305110427
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8305040289 Advises that effective 830418. JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues.

 NOVAK, T M Assistant Director for Licensing 83/04/26
 HGLT2SCHER. D L Illinois Power Co 2pp 18326-343 24X Fiche 50-000. 83/04/26. 8305040289
- 8305100198 Forwards containment issues cross ref & action plan to address addl containment issues.per util 821209 ltr W/four oversize drawings Aperture cards are available in PDR 800KER.J E Gulf States Utilities Co 83/04/29 8CHWENGER.A Licensing Branch 2 170pp 18380 104 24X Fiche, 30~458, 83/04/29, 8305100198
- B305040677 Responds to B30112 request to withhold from public disclosure info re seismic reflection lines depicted in FBAR Figure 2 5-18 Request acceptable SCHWENCER. A Licensing Branch 2 83/05/02 CAHILL, W J Gulf States Utilities Co 3pp 18336 253 24X Fiche 50-458,83/05/02,8305040677

- 8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT, D @ Division of Licensing 83/05/03 EDELMAN, M R Clevel
- --8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENMUT.D 0 Division of Licensing B3/05/03 HALE,D P, Illinois Power Co 2pp 18523 200 24X Fiche 50-000.83/05/03, 2205-2004.
- --8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EIBENHUT, D & Division of Licensing 83/05/03 FERGUSON, M R Hashington Public Power Supply System 2pp 18523 202 24X Fiche 50-000,83/05/03,8305190046
- --8305190068 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 CL applicants EISENHUT, D Ø Division of Licensing 83/05/03 MCGAUGHY, J P Mississippi Power & Light Co 2pp 18523 204 24X Fiche 30-000,63/05/03,8305190046
- ---B305190077 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BHR/6 OL applicants EISENHUT.D 9 Division of Licensing B3/05/03 CAHILL, J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03,
- 8305090602 Forwards NRC position re turbine maint Commitment to meet position classifying turbine missile issue as confirmatory required SCHWENCER, A Licensing Branch 2 83/05/04 CAHILL, N J Oulf States Utilities Co 3pp 18367 338 24X Fiche 50~458,83/05/04,8305090602
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees tholders of CPs re integrated scheduling for implementation of plant mode Svc list encl
 EISENHUT.D G Division of Licensing 83/05/09 Consolidated
 Edison Co of New York, Inc. 14pp 18427 153 24X
 Fiche 30-000,83/05/09,8305090659
- 8305270039 Forwards request for add1 info re personnel training as part of NRC review of application for OL SCHHERCER: A Licensing Branch 2 83/05/23 CAHILL, W J Gulf States Utilities Co 3pp 18662 097 24X Fiche, 50-458, 83/05/23, 820837032
- C Utility Environmental Report (ER), amends & correspondence
- 8305260305 Summary of 830428 meeting w/util in Bethesda.MD re various environ rept OL stage topics Topic 4 re summary cost-benefit analysis not discussed Meeting notice & agenda encl
 WEINKAM.E J Licensing Branch 2 83/05/18 Licensing Branch 2 5pp 18629 294 24% Fiche: 50-458.83/05/18.8305260305
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8303030106 Forwards draft SER on reactor sys open items. Add1 questions enci Meeting will be arranged & schedule established to resolve open items
 SCHWENCER. A Licensing Branch 2. 83/04/21 CAHILL, H J. Gulf
 States Utilities Co. 46pp 18310 031 24X Fiche. 50-458,83/04/21,8305030104.
- 8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND.J.J. Licensing Branch 1 83/05/02. HOLTZBCHER.D.L.,
 11linois Power Co. 2pp 18443-173 24X Fiche. 50-000.83/05/02,
 8305120460
- --8305120470 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental BERS Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO.J. J. Licensing Branch 1 83/05/02 POWELL.P Washington Public Power Supply System ip 18443 174. 24X
 Fiche 50-000.83/05/02.8305120460

- --B305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO.J J Licensing Branch 1 83/05/02 RICHARDSON.J D Mississippi Power & Light Co 1p 18443 176 24X Fiche 50-000.83/05/02.8305120440
- ---B305120491 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 BTEFANG.J J Licensing Brench i B3/05/02 BUZZELLI, E M Cleveland Electric Illuminating Co ip 18443 177 24X Ficha 50-000,83/05/02,8305120460
- 8305110616 Forwards structural engineering input for draft SER Encl provides summary of open items & scope of review BCHMENCER: A Licensing Branch 2 83/03/04 CAHILL.W J., BOOKER: J E Oulf States Utilities Co 28pp 18419 307. 24X Fiche 30-458,83/05/04,8305110616
- 8305260348 Forwards draft SER input re auxiliary sys Difficulty encountered in performing review due to illegibility of some drawings
 8CHMENGER, A Licensing Branch 2 83/05/18 CAHILL, W J Qulf
 8tates Utilities Co 211pp 18629,077 24X Fiche 50-458,83/05/18,8305260348
- 8305260306 Forwards revised safeguards SER & Tech Specs in response to 830502 request for review & comments on draft SER.
 MIRAGLIA,F J Assistant Director for Safety Assessment 83/05/20
 NOVAK,T M Assistant Director for Licensing 4pp 18627 272 24X
 Fiche 50-458,83/05/20,8305260306
- F Security, medical, emergency & fire protection plans
- 8303110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Bvc list encl
 EISENHUT,D 0 Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X
 Fiche 50-000,83/05/11,8305110034
- 8305170468 Forwards Amend 8 to FSAR, providing responses & text changes to Section 13 3 re emergency planning CAHILL, W J. Oulf States Utilities Co 83/05/13 EISENHUT, D 0 Division of Litensing 4pp 18470 167 24X Fiche 50-458,83/05/13,8305170468
- 8305190482 Notification of 830525 meeting w/util & 9&W in Batheada, MD to discuss fire protection/safe shutdown open items WEINKAM, E J Licensing Branch 2 83/05/13 8GHMENCER, A Licensing Branch 2 3pp 18523 163 24X Fiche 50-458, 83/05/13, 8305190482
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS, W. J. Office of the Executive Director for Operations 83/05/13 PALLADING, W. J. Cammissioners 5pp. 18593 322 24) Fiche: 50-000, 83/05/13, 8305240213
- B305230007 Releases public version of applicant responses to NRC questione re emergency plan FELTON, J M. Division of Rules and Records 83/05/20 Document Management Branch ip. 18535 190. 24X Fiche 50-458,83/05/20,8305230007,
- --8305230009 Forwards public version of responses to NRC 821214 questions re emergency plan Responses prepared per 830203 discussion w/NRC BOOKER, J E Gulf States Utilities Co 83/03/01 SCHWENCER, A Licensing Branch 2, 89pp 18535 191 24X Fiche 50-458,83/05/20,8305230007
- 8305260306 Forwards revised safeguards SER & Tech Specs in response to B30502 request for review & comments on draft SER.
 MIRAGUIA, F. J. Assistant Director for Bafety Assessment. B3/05/20
 NOVAK, T. M. Assistant Director for Licensing 4pp 18629-292 24X
 Fiche: 50-458, 83/05/20, 8305260306

Q Adjudicatory correspondence

- 8305030548 Order scheduling 830614 prehearing conference in Baton Rouge: LA COTTER: B P Atomic Safety and Licensing Board Panel 83/04/29 2pp 18303 319 24X Fiche 50-458:83/04/29.8305030548
- 8305100328 Response to NRC answer to State of LA Contentions 1-6
 Reasonable specificity requirements of 10CFR2 714(b)
 satisfied Contentions 2 & 5 premature & should be accepted
 conditionally Certificate of Svc encl
 LINDSAY, I D Louisiana, State of 83/05/03 Atomic Safety and
 Licensing Board Panel 11pp 18379 007 24X Fiche 50-458,83/05/03,870.5100328

I Financial information

- 8305310102 Annual Financial Rept 1982 W/830407 1tr LEE,N R . MURRILL,P W . BODKER,J E Gulf States Utilities Co 83/04/07 DENTON,H R Office of Nuclear Reactor Regulation. Director 46pp 18655 276 24X Fiche 50-458,B3/04/07,B305310102
- K Utility Final Safety Analysis Report (FSAR) & amends
- B30517046B Forwards Amend B to FSAR, providing responses & text changes to Section 13 3 re emergency planning CAHILL, M J Gulf States Utilities Co 83/05/13 EISENHUT, D G Division of Licensing 4pp 18470 167 24X Fiche 50-458,83/05/13,830517046B
- --8305170473 Amend B to FSAR * Quif States Utilities Co 83/05/31 370pp 18470-171 24X Fiche 50-458,83/05/13.8305170468
- Q Inspection reports, IE Bulletins & correspondence
- 82:2060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- B305100137 Forwards IE Insp Rept 50-45B/83-07 on B30307-11 No noncompliance noted MADBEN,G L. Region 4, Office of Director B3/04/11 CAHILL,W J Oulf States Utilities Co 2pp 18975 010 24X Fiche 50-45B,83/04/11,8305100137
- ---B305100142 IE Insp Rept 50-458/83-07 on B30307-ii No noncompliance noted Major areas inspected action on previous insp findings, review of GA program for safety-related pipe supports & observation of work activities JOHNSON, C E, CROSSMAN, W A, HUNNICUTT, D M Region 4, Office of Director. B3/04/07 App 18375 012 24X Fiche 50-458,83/04/11, B305100137
- B303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator"
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fiche 50-000, B3/04/15, B303040021
- 8305050157 Forwards IE Insp Rept 50-458/83-09 on 830305-0406 No noncompliance noted MADSEN,O L. Region 4, Office of Director 83/04/21 CAHILL.W J Gulf States Utilities Co 2pp 18342 001 24X Fiche 50-458,83/04/21,8305050157
- --8305050163 IE Insp Rept 50-458/83-09 on 830305-0406 No noncompliance noted Major areas inspected containment structural concrete, storage of safety-nelated pipe & valves, structural steel installation, reactor vessel & internals storage BROWN, R L , CROBSMAN, W A Region 4 Office of Director 83/04/20 Bpp 18342 003 24X Fiche 50-458/83/04/21/8305050157
- B303040023 IE Info Notice 83-22. "BWR Safety/Relisf Valve Failures "
 Svc list and
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383.089, 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 117pp 18381 291 24% Fiche 50-000-83/04/25,8303040025

- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fithe 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8305230305 Forwards IE Insp Rept 50-458/83-08 on 830328-31 No noncompliance noted MADSEN.G L. Region 4. Office of Director 83/04/29 CAHILL: W J Gulf States Utilities Co. 2pp 18539 135 24X Fiche 50-458.83/04/29.8305230305
- --8309230314 IE Insp Rept 50-458/83-08 on B30328-31 No noncompliance noted Major areas inspected site tour observation of work & review of records for welding & NDE of safety-related plping & raview of procedures for protective coatings OTLBERT, L D , JOHNSON, C E , DESS, J E Region 4, Office of Director B3/04/25 Bpg 18539 137 24X Fiche 50-458,83/04/29,8305230305
- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8305120343 Responds to IE Bulletin 80-16, "Potential Misapplication of Rusemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Pressure transmitters not amployed in safety-related applications
 BOOMER, JE Gulf States Utilities Co 83/03/03 COLLENS, J T
 Region 4. Office of Director ip 18432 319 24X
 Fiche 50-458,83/05/03,8305120343
- 8305120369 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NOVAK, T M Assistant Director for Licensing 83/03/03 HOLTZSCHER.D L Licensing Review Group II 6pp 18440 356 24X Fiche 30-000,83/05/03,8305120367
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Conterning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Quidelines " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/03/11 Consolidated Edison Co of New York, Inc 114pp. 18524 003 24X Fiche 50-000,83/05/11,8303040034
- B303040040 IE Info Notice B3-31. "Error in ADLPIPE Computer Program,"
 Svc list encl
 JURDAN:E L Division of Emergency Preparadness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co of New
 York: Inc 114pp 18697 009 24X Fiche 50-000, B3/05/19, B303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated 011." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 30-000.83/05/26,8303040046

- S Reportable occurrences, LERs & related correspondence
- 8305030422 Interim Deficiency Rept DR-72 re improper installation (torquing), testing & insp. of concrete drilled-in expansion-type anchors Evaluation in progress Interim or final rept will be sent by 830610 BOOKER. J E Gulf States Utilities Co. 83/04/25 COLLINS, J T Region 4, Office of Director ip 18306 248 24X Fiche 50-458,83/04/25,8305030422
- 8305110324 Part 21 rept re Type 8A-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Hestinghouse corrective action includes replacing SCR w/burn-in SCR DUVALL.D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.) 83/04/27 STELLO.V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000,83/04/27.8305110324
- 8305040435 Interim Deficiency Rept DR-105 re electrical separation of reactor protection sys wiring from NSSS shutoff wiring. Initially reported on 8303297 Investigation incomplete Next rept expected by 830701
 BOOKER, J. E. Gulf States Utilities Co. 83/04/28 COLLINS, J. T. Region 4. Office of Director 1p. 18343 148 24X
 Fiche 30-458.83/04/28.8305060435
- 8305060475 Interim Deficiency Rept DR-104 rs overturning of Transilift crans that was lifting reactor whield bldg dams Initially reported on 830328 Investigation incomplete Next rept expected by 830624

 BOUKER, J E Quif States Utilities Co 83/04/28 COLLINB, J T. Region 4. Office of Director ip 18349 166 24X

 Fiche 50-458,83/04/28,8305060475
- B305120367 Final Deficiency Rept DR-23 re HPCS diesel generator radiative heat loss value used in sizing of HPCS room cooling fans initially reported on B20212 QE committed to change heat load data in manuals for diesel engines BOOKER. J E Oulf States Utilities Co B3/04/27 COLLINS, J T Region 4, Office of Director 2pp 18433 118 24X Fiche 50-458,83/04/29,8305120367
- 8305120321 Interim Deficiency Rept DR-107 rs Category I air circuit breakers w/krip coils of higher range than shown on bill of matls Initially reported on 830404 Investigation incomplete Next rept will be submitted by 830614 BOOKER, J E Gulf States Utilities Co 83/05/04 COLLINB, J. T Region 4. Defice of Director ip 18431 080 24X Fiche 50-458,83/05/04,8305120321
- 8305120409 Interim Deficiency Rept DR-106 re Interstate Steel, Hub Inc. Regal & Welded Tube of America documentation for Class 1, A-500, Grade B tube steel Initially reported on 830404. Investigation ongoing Next rept by 830707 BOOKER. J E Gulf States Utilities Co 83/05/04 COLLINS, J. T. Region 4, Dffice of Director ip 18431-152, 24X Fiche 50-458, 83/05/04, 8305120409
- 8305120413 Interim Deficiency Rept DR-108 re Bergen-Paterson pipe support and components nonconformance w/design drawings initially reported on 830406 investigation ongoing Interim or final rept will be submitted by 830621 BODKER.J E Gulf States Utilities Co. 83/05/06 COLLINS.J T Region 4. Office of Director ip 18434-094 24X Fiche 50-458.83/05/06.8305120413
- 8305120424 Final Deficiency Rept DR-91 re misapplication of Bethlehem Steel load indicating washer in structural steel slip connection in reactor bldg, Initially reported on 83011 Condition determined not reportable per 10CFR50 55(a) BODKER, J E Gulf States Utilities Co 83/05/06 COLLING, J T Region 4, Dffice of Director 1p 18431 160 24X Fiche 50-458,83/05/06,8305120424
- 8305170281 Final Deficiency Rept DR-86 re 821213 notification of possible misinterpretation of electrical equipment hold down weld detail Detail adequate for design considerations Item not reportable under 100FR30 55(e) 800KER.J E Gulf States Utilities Co. 83/05/09. COLLING.J T. Region 4. Defice of Director ip. 18465.070. 24X Fiche 50-458,83/05/09.8305170291.
- B305170385 Interim Deficiency Rept DR-109 re Velan 3/4-inch,600 lb, socket-welded globe valves w/counterbores not concentric to valve ctr Initially reported on B30408 Nonconcentric counterbores may cause weld problems Next rept by B30613.
 BOCKER.J E Oulf States Utilities Go 83/05/09 COLLINS.J.T. Region 4, Office of Director ip 18471 201 24X Fichs 50-458.83/05/09.8305170385

- 8305170479 Interim Deficiency Rept DR-iiO re possible contamination of stainless steel w/ultrasonic couplant failing to meet chamical analysis requirements Initially reported on 830408 Next rept to be submitted by 830615 800KCR.J E Gulf States Utilities Co 83/05/09 COLLINS, J T Region 4. Defice of Director ip 18467 290 24X Fiche 50-458.83/05/09.8305170479
- B305200151 Interim Deficiency Rept DR-100 re Category I motor control ctr motor operated valve feed breaker settings supplied by Oould-Brown Boveri Initially reported on 830222 Util awaiting addl info from AE Next rept expected by B30620 BOOKER.J E Quif Btates Utilities Co 83/05/12 COLLINS.J T Region 4. Office of Director ip 18519 003 24X Fiche 50-45B.83/05/12.8305200151
- 8305200390 Interim Deficiency Rept DR-111 re dimensional discrepancy on two small bore pipe support design drawings Initially reported on 830412 Design drawings reflect longer dimension than justified Next rept expected by 830408 BOOKER, J E Quif States Utilities Co 83/05/12 COLLINS, J T. Region 4. Office of Director ip 18518 109 24X Fiche 50-458, 83/05/12, 8305200390
- 8305200264 Interim Deficiency Rept DR-92 re PYCO, Inc & subsupplier ABME III documentation for Category I stainless steel thermowells Initially reported on 830114 Add1 info from AE pending Next will be provided by 830627 BOOKER, J E. Quif States Utilities Co. 83/05/13 COLLING, J T Region 4. Defice of Director tp 18517 092 24X Fiche 50-458, 83/05/13, 8305200264
- 8305230462 Interim Deficiency Rept DR-85 re incorrect taper at welds between outside diameter of heavy wall pipe fittings & std wall pipe on 30-inch svc water piping sys Initially reported on 921208 AE will submit addl info Next rept by 830728 BOOKER.J E Oulf States Utilities Co 83/05/16 COLLING.J T Region 4, Office of Director. ip 18337 197 24X Fiche.50-458.83/05/16.8305230462
- B305230438 Final Deficiency Rept DR-87 re enlarged connection bolt holes in electrical tray supports & overtorqued connecting bolts Initially reported on B21217 Support sys structurally tested Condition not reportable per 10CFR50 55(e) B0CMER.J E Ouif States Utilities Co B3/05/17 COLLINS.J T Region 4, Office of Director. Ip 18538 204 24X Ficha 50-458,83/05/17,8305230438
- B30524046B Interim Deficiency Rept DR-30 re interpretation of radiographs performed by DF Shaw Co AE evaluation of defective welds will be completed by B30603 Next rept will be submitted by B30624.
 BOOKER, J. E. Quif Btates Utilities Co 83/05/18 CDLLING, J T Region 4. Office of Director ip 18549 295 24X Fiche 50-438, B3/05/18, B30524046B
- 8303250268 Interim Deficiency Rept DR-112 re oversized power cable lugs supplied by Power Conversion Products, Initially reported on 830419 Investigation continuing Interim or final status rept will be submitted by 830528 800MER.J E Oulf States Utilities Co 83/05/14 COLLING.J.T. Region 4, Office of Director. 1p 18625.043, 24X Fiche.50-458,83/05/19,8305260268
- B305260299 Interim Deficiency Rept DR-113 re misapplication of matis used for in-line cable splices on electrical connections for hydrogen igniter assemblies Initially reported on 830419. Investigation continuing Next rept by 830629. BOOKER.J.E. Gulf States Utilities Co. 93/05/19, COLLINS.J.T Region 4, Office of Director. Ip. 18625 018 24X Ficher 50-458, B3/05/19, 8305260299
- B305260318 Interim Deficiency Rept DR-ii4 re weld defects in radial rebar anchor ring for shield bldg roof Initially reported on 830419 Investigation continuing. Interim or final status rept will be submitted by 830630 BOOKER, J E. Gulf Btates Utilities Co 83/05/14 COLLINS, J T Region 4, Office of Director 1p. 18625, 177, 24% Fiche 50-458, 83/05/19, 8305260318.
- 8305310042 Interim Deficiency Rept DR-96 re linear indication in section of tube steel supplied by Bergen-Patterson. Initially reported on 830217. Investigation continuing Next rept will be submitted by 830701.

 800KER, J E Gulf States Utilities Co 83/05/20 COLLINS, J. T Region 4, Office of Director. ip 18653 306. 24X Fiche 50-458, 83/05/20, 8305310042

- DOCKET 50-459 RIVER BEND STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305040289 Advises that effective 830418. JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues NOVAK.T M Assistant Director for Licensing 83/04/26 HOLTZSCHER. D L Illinois Power Co 2pp 18326 343 24X Fiche 50-000.83/04/26.8305040289
- B305100198 Forwards containment issues cross ref & action plan to address addl containment issues, per util B21209 ltr H/four oversize drawings Aperture cands are available in PDR B00KER.J E Gulf States Utilities Co 83/04/29 SCHWENCER.A Licensing Branch 2 170pp 1B380 106 24% Fiche 50-458.83/04/29, B305100198
- B305040677 Responds to 830112 request to withhold from public disclosure into re seismit reflection lines depicted in FBAR Figure 2 5-18 Request acceptable BCHMENCER. A Licensing Branch 2 83/05/02 CAHILL. W J Gulf Btates Utilities Co 3pp 18336 233 24X Fiche 50-458, 83/05/02, 8305040677
- 8305i90046 Commands representatives of BWR/6 utils participating in Licensing Review Group II for afforts in resolving issues generic to BWR/6 OL applicants EISENNUT.D. 9 Division of Licensing 83/05/03 EDELMAN, M R Clevel
- --8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT,D G Division of Licensing 83/05/03 HALE,D P Illinois Power Co. 2pp 18523 200 24X Fiche: 50-000,83/05/03, 8305190046
- --B305190060 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BHR/6 OL applicants
 EISENHUT.D G Division of Licensing 83/05/03 FERGUSON, M R
 Washington Public Power Supply System 2pp 18523 202 24X
 Fiche 50-000,83/05/03,8305190046
- --8305190068 Commends representatives of BHR/6 utils participating in Licansing Review Group II for efforts in resolving issues generic to BHR/6 OL applicants EISENHUT.D 9 Division of Licensing 83/05/03 MCGAUOHY. J P Mississippi Power & Light Co 2pp 18523 204 24X Fiche 30-000.83/05/03,8305190046
- --8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT,D 0 Division of Licensing 83/05/03 CAHILL,J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03, 8305190046
- B305090602 Forwards NRC position re turbing maint Commitment to meet position classifying turbing missile issue as confirmatory required SCHWENCER. A Licensing Branch 2 83/05/04 CAHILL, W. J. Gulf States Utilities Co. 3pp 18367 338, 24X Fiche: 50-458, 83/05/04, 8305090602.
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D. O Division of Licensing 83/05/09 Consolidated Edison Co
- B305270039 Forwards request for add1 info re personnel training as part of NRC review of application for OL BCHMERCER.A Licensing Branch 2 83/05/23. CAHILL,W J Gulf States Utilities Co 5pp 18462 097 24X Fiche: 50-458,83/05/23,8305270039.
- C Utility Environmental Report (ER), amends & correspondence
- B305260305 Summary of B3042B meeting w/util in Bethesda.MD re various environ rept OL stage topics Topic 4 re summary cost-banefit analysis not discussed Meeting notice & agenda encl
 WEINKAM.E.J. Licensing Branch 2 83/05/18, Licensing Branch 2, 5pp 18627-296 24X Fiche: 50-458,83/05/18,8305260305

8305030106

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305030106 Forwards draft BER on reactor sys open items Add1 questions encl Meeting will be arranged & schedule established to resolve open items
 SCHWENCER:A Licensing Branch 2 83/04/21 CAHILL.W J Gulf States Utilities Co 46pp 18310 031 24X Fiche 50-458.83/04/21.
- 8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO, J J Licensing Branch 1 83/05/02 HDLTZSCHER, D L III nois Power Co 2pp 18443 173 24X Fiche 50-000,83/05/02,8305120460
- --B305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO, J J Licensing Branch i 83/05/02 PDMELL, P Washington Public Power Supply Bystem ip 18443 174. 24X Fiche 50-000,83/05/02,9305120460
- --8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERS Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO, J J Licensing Branch i 83/05/02. REED, W J Gulf States Utilities Co ip 18443 175 24X Fiche.50-000,83/05/02,8305120460
- --8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue STEFANO, J J Licensing Branch 1 83/05/02 RICHARDSON, J. D Mississippi Power & Light Co ip 18443 176 24X Fiche 30-000,83/05/02,8305120460
- --8303120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Oroup II generic issue
 STEFANO, J Licensing Branch 1 83/05/02 BUZIELLI, E M. Cleveland Electric Illuminating Co ip 18443 177 24X
 Fiche 50-000,83/03/02,8305120460
- 8305110616 Forwards structural angineering input for draft SER Encl provides summary of open items & scope of review SCHMENCER.A Licensing Branch 2 83/05/04 CAHILL.W.J. BOOKER.JE Guif States Utilities Co 28pp 18419 309 24X Fiche 50-458.83/05/04.8305110616
- 8305170604 Forwards site analysis sections for draft SER Open items re gopulation data & barge transportation of toxic gases highlighted SCHWENCER, A Licensing Branch 2 83/05/05 CAMILL, W. J Gulf States Utilities Co 17pp 18497 027. 24X Fiche 50-459,83/05/05, 02081704004
- 830524034B Forwards draft SER input re auxiliary sys Difficulty encountered in performing review due to illegibility of some drawings
 SCHWENCER.A Licensing Branch 2 83/05/18 CAHILL.H J. Qulf
 States Utilities Co. 211pp. 18629 077 24X Fiche 50-458,83/05/18,8302260348
- F Security, medical, emergency & fire protection plans
- 8305110034 Owneric Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISENHUT.D G Division of Licensing 83/05/11, Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000.83/05/11,8305110034
- 8305170468 Forwards Amend B to FSAR, providing responses & text changes to Section 13 3 re emergency planning CAHILL, W J Gulf Btates Utilities Co 83/05/13 EISENHUT, D. G Division of Licensing 4pp. 18470 167. 24X Fiche 50-458, 83/05/13, 8305170468
- 8305230007 Releases public version of applicant responses to NRC questions re-emergency plan FELTON-J M Division of Rolles and Records, 83/05/20 Document Management Branch ip 18535-190 24X Fiche 50-458,83/05/20,830523007

- --8305230009 Forwards public version of responses to NRC 821216 questions re emergency plan Responses prepared per 830203 discussion w/NRC BOOKER. J E Gulf States Utilities Co 83/03/01 SCHWENCER. A. Licensing Branch 2 89pp 18535 191 24K Fiche 50-458.83/05/20, 8303230007
- @ Adjudicatory correspondence
- 8305030548 Order scheduling B30614 prehearing conference in Beton Rouge:LA COTTER:BP Atomic Safety and Licensing Board Panel 83/04/29, 2pp 18303 319 24X Fiche 50-458,83/04/29,8305030548
- 8305/00328 Response to NRC answer to State of LA Contentions 1-6
 Reasonable specificity requirements of 10CFR2 714(b)
 satisfied Contentions 2 & 5 premature & should be accepted
 conditionally Centificate of Svc encl
 LINDSAY. I D Louisiana, State of 83/05/03 Atomic Sefety and
 Licensing Board Panel (1pp 18377 007 24X Fiche 50-458,83/05/03,
 8305100328
- I Financial information
- 8305310102 Annual Financial Rept 1982 W/830407 1tr LEE,N R , MURRILL,P W , BODKER J E Gulf States Utilities Co 83/04/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 44pp 18655 296 24X Fiche.50-458,83/04/07,8305310102
- K Utility Final Safety Analysis Report (FSAR) & amends
- B30517046B Forwards Amend 8 to FBAR, providing responses & text changes to Section 13 3 re emergency planning CAHFLL, MJ Gulf States Utilities Co B3/05/13 EISENHUT, D. O Division of Licensing 4pp 18470 167. 24X Fiche 50-458, 83/05/13, 830517046B
- --8305170473 Amend 8 to FBAR * Gulf States Utilities Co 83/05/31 390pp 18470 171. 24X Fiche 50-458,83/05/13,8305170468
- G. Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR.J M Division of Sefeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York; Inc. 112pp 18308 319 24% Fiche 50-000:83/03/21,8212040385.
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator"
 Eve list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435;155 24X Fichs 50-000,83/04/15,8303040021
- B303040023 IE Info Notice B3-22, "BWR Bafety/Relief Valve Failures "
 Svc list encl.
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383-089, 24X Fiche 50-000,83/04/22,8303040023.
- 8303040025 IE Info Notice 83-29, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25, Consolidated Edison Co. of New York, Inc. 119pp 18381-291 R4X Fiche 50-000, 83/04/25, 8303040025.
- 8303040026 IE Info Notice 83-24, "Loose Parts in Becondary Side of Steam Generators at PHRs " Bvc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/04/28 Consolidated Edison Co. of New York: Inc 115pp. 18382,047 24X Fiche 50-000.83/04/28,8303040026.
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Bys Heater High Temp Trip Setpoint Adjustment." Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co. of New York: Inc. 118pp 18382:165, 24X Fiche 50-000.83/04/28,8303040027.
- 8303040028 IE Info Notice 83-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441:170 24X Fiche 50-000,83/05/03,8303040028

- 8305120343 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Pressure transmitters not amployed in safety-related applications 800KER. J E Gulf States Utilities Co 83/05/03 COLLINS, J T Region 4, Office of Director ip 18432 319 24x Fiche 50-438,83/05/03,8305120343
- 8305120569 Discusses guidelines developed to aid in review of IE
 Bulletin 79-15 re long-term operability of deep draft pumps
 Afternate qualification method incorporating vibration
 monitoring & std plant test procedures proposed encl
 NOVAK,TM Assistant Director for Licensing 83/05/03
 HOLTZBCHER,D L Licensing Review Oroup II 6pp 18440 356 24X
 Fiche 30-000,83/05/03,8305120569
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidate Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- 9303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/03/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/03/19,8303040040
- B303040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26, Consolidated Edison Co of New York, Inc 114pp 18647:007 24X Fiche 50-000, B3/05/26, B303040046.
- S Reportable occurrences, LERs & related correspondence
- 8305110324 Part 21 rept re Type SA-1 Class IE relays Bilicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
 DUVALL.D D Brown Boveri Corp (subs Brown Boveri & Ca , Ltd)
 83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp. 18373 278 24X Fiche 50-000.83/04/27.8305110324

DOCKET 50-460 WPP89 NUCLEAR PROJECT, UNIT 1

- A. Application/construction stage documents & correspondence
- B305090659 Generic Ltr B3-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENHUT, D G. Division of Licensing. B3/05/09 Consolidated Edison Co of New York, Inc. 14pp 18627 153 24X Fiche 50-000, B3/05/09, B305090659
- 8305170721 Notifies that use of ASME Code Cases N-19 & N-19-2 for application in const of diesal exhaust sys components acceptable based on review of 830401 request NOVAK.T.M Assistant Director for Licensing 83/05/11. FERNOUSON.R.L. Mashington Public Fower Supply System 1p. 18496-195 24X Fiche 50-460,83/05/11,8305170721
- F. Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for GLs & holders of CPs re clarification of access to control procedures for law enforcement visits, 8vc list encl EIBENHUT.D 0 Division of Licensing 83/05/11. Consolidated Edison Co. of New York. Inc 16pp 18540 095 24X Fiche' 50-000,83/05/11,8305110034

G Adjudicatory correspondence

- 8305020473 Motion to strike Wall Street Journal 830404 article appended to petitioner response to applicant motion for reconsideration &/or certification Article of insufficient probative value Certificate of Svc encl
 REYNOLDS.N S Washington Public Power Supply System REYNOLDS.N S Debevoise & Liberman 83/04/28 Atomic Safety and Licensing Board Panel 6pp 18283 281 24x Fiche 50-460.83/04/28,8305020473
- 8305050009 Response to 830414 first set of interrogatories Certificate of Svc encl Related correspondence
 REYNOLDS: N S Washington Public Power Supply System REYNOLDS: N S Debevoise & Libernan 83/05/03 Coalition for Safe Power 10pp 18339 018 24x Fiche 50-460.83/05/03,8305050009
- 8305050019 First set of interrogatories & requests to produce Certificate of Svc encl Related correspondence REYNOLDS,N S Washington Public Power Supply System REYNOLDS,N S Debevoise & Liberman 83/05/03 Coalition for Safe Power 9pp 18338 355 24X Fiche 50-460,83/05/03,8305050019
- 8305050082 First set of interrogatories & document production requests Certificate of Svc encl MAQNER,M E Hearing Branch 4 83/05/04 Coalition for Safe Power 8pp 18342 044 24X Fichs 50-460,83/05/04,8305050082
- 8305100263 Advises that 830404 memb re PDRV environ & safety qualification not received Failure to receive notifications prejudices future involvement in case Assurance of future full notification requested

 BELL,N Coalition for Safe Power 83/05/04 GROSSMAN,H,

 HARBOUR, J. BRIGHT, 0 O Atomic Safety and Licensing Board Panel

 19 18372 295 24X Fiche 50-460.83/05/04.8305100263
- B305310076 Hotion to be admitted as interested state in proceedings Certificate of Svc encl LEMIS:N D Washington State of B3/05/07 Atomic Safety and Licensing Board Panel 3pp 18655 i19 24X Fiche 50-460.83/05/09. B305310076
- B305170516 Opposes petitioner B30504 request for ASLB action to ensure petitioner fully notified of issues re OL Petitioner should not be treated as party since intervention status not granted REYNOLDS.N B Debevoise & Liberman. REYNOLDS.N B Waskington Public Power Supply System B3/05/12 GROSSMAN,H , BRIGHT, 0 Q , HARBOUR, J Atomic Safety and Licensing Board Panel 18467 247 24% Fichs 50-460.83/05/12.8305170516
- 8305200576 Response opposing applicant 830428 motion to strike Wall Street Journal article appended to petitioner response to applicant motion for reconsideration Argument re probative value & admissibility misplaced W/Certificate of Svc HACNER, M E Hearing Branch 4 83/05/18 Atomic Safety and Licensing Board Panel App 18514 122 24X Fiche 50-460,83/05/18,8305200576
- B305200582 Advises that no communication received from Combition for Bafe Power in response to ASLB B30426 order to disclose names & addresses of individuals needed to meet standing requirements Deadline was B30506 WAONER, M E Hearing Branch 4 B3/05/18 BELL.N Combition for Bafe Power ip 18814 249 24X Fiche 50-460/83/05/18/8303200582
- 8305240347 Motion to compel responses to 830414 first set of interrogetories to applicant re const delay Licensee objected to request Claim w/o basis Util should be ordered to respond Certificate of Svc encl
 BELL,N Coalition for Safe Power 83/05/18 Atomic Safety and Licensing Board Panel 5pp 18573 001 24X Fiche 50-440,83/05/18.
- B305240465 Memorandum opposing petitioner intervention Petitioner failed to reapond to protective order, so standing can no longer be based on undisclosed individuals Certificate of Svc enci
 HARTMAN, S L. Washington Public Power Supply System HARTMAN, S L. Debevoise & Liberman 83/05/20 Atomic Safety and Licensing Board Panel 6pp 18573 175 24x Fiche 50-460,83/05/20,8305240465
- 8305310005 Response to Interrogatories 1 through 22 (first set) Certificate of 8vc encl Related correspondence BELL.N Coslition for 8afe Power 83/05/23 Washington Public Power Supply System. 7pp 18653 231 24X Fiche 50-460,83/05/23,

- 8303260172 Memorandum & order setting new time limits for responding to potitioner disclosure of individual members needed to establish standing Applicant, NRC & petitioner responses due 83060616 & 27, respectively QROSEMAN.H Atomic Safety and Licensing Board Panel 83/05/25 Hashington Public Power Supply System 3pp 18599 286 24X Fiche 50-440,83/03/25,8303260172
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8303030166 Forwards Amend 2 to FSAR BOUCHEY.6 D Washington Public Power Supply System 83. ADENSAM.E 0 Licensing Branch 4 2pp 18298 140 24X Fiche 50-460.83/04/18.8305030166 83/04/18
- --8305030172 Amend 2 to FSAR W/33 oversize figures Aperture cards are available in PDR * Washington Public Power Supply System 83/04/30 600pp 18278 12 24X Fiche 50-460.83/04/18.6305030166
- 8305100246 Forwards Certificate of Syc for FSAR Amend 2 Atty General ofc returned FSAR & Amend 1 Ofc will no longer be provided w/documents
 BOUCHEY. G D Hathington Public Power Supply System 83/
 ADENSAME 6 Licensing Branch 4 3pp 18374.105 24X
 Ficha 50-460,83/05/05,8305100246
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list
- TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24% F(che 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
- JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- Svc list encl
 JORANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22.8303040023
- 8303040025 IE info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc li5pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc JiBpp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000-83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030.
- 8303040031 IE Info Natice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New 117pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
 - Info Notice 83-29, "Fuel Binding Caused by Fuel Rack The Notice when it is the state of the state 83/05/06, Consolidated Edison Co of New 27 248 247 Siche 50-000,83/05/06,8303040033 .st #301031 115pp 18527 748

- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EDP) Ouldelinss "Svc list encl Operating Procedures (EDP) Ouldelinss "Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edition Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11,8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Bampling of Contaminated Oil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8303240346 Forwards responses to add1 concerns of J Humphrey n containment, consisting of Action Plans 15, 18, 19, 22, 25, 28, 31 & 32 & 32 WULLER,G E Illinois Power Co 83/03/17 SCHWENCER,A Licensin Branch 2 46pp 17681 310 24X Fiche 50-461,83/03/17,8303240346
- 8305040287 Advises that effective 830418.JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining Will neip expense recover to the state of th
- 8305190046 Commenda representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
 EISENHUT, D 0 Division of Licensing 83/05/03 EPELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 198 24X
 Fithe 50-000,83/05/03,8305190046
- --8305190054 Commends representatives of BWR/6 utils participating in 303190034 Commends representatives of BMR/6 utils participating i Licensing Review Group II for efforts in resolving issues generic to BMR/6 OL applicants EIBENHUT.D G Division of Licensing 83/03/03 HALE,D P Illinais Power Co 2pp 18323 200 24X Fiche, 30-000,83/05/03, 8305190046
- --B305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
 EIBENHUT: D 0 Division of Licensing 83/05/03, FEROUSON, M R
 Washington Public Power Supply System 2pp 18523 202, 24X
 Fiche BO-000, 83/05/03, 8305190046
- --8305190068 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 DL applicants
 EIBENHUT, D. G. Division of Licensing 83/05/03 MCGAUGHY, J.P.
 Mississippi Power & Light Co. 2pp 18523 204 24X Fiche 50-000, 83/05/03, 8305190046
- -8305190077 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BHR/6 DL applicants
 EISENHUT, D Q Division of Licensing B3/05/03 CAHILL, J. Qulf Btates Utilities Co 2pp 18523 206 24X Fiche 50-000, 83/05/03, 8305190046
- 8305170701 Requests applicant latest presentation & summary of Caseload Forecast Panel evaluation of facility BUDHANIR N Affiliation Unknown 83/05/06 NRC No Detailed Affiliation Given 2pp 18476-258 24X Fiche 50-461,83/05/06.
- --8305170705 Forwards most recent (B01112-14) Caseload Forcast Panel meeting summary re const status SCHMENGER, A Licensing Branch 2. 83/05/06 BUDWANI,R, Affiliation Unknown 1p 18496 260 24X Fichs 50-461.83/05/06.8303170701
- 8305200667 Submits updated info to 820924 response to 820326 request for addi info re fast scram loads on control rod drive sys.

 Test data revealed that 45-ms valve opening parameter more appropriately models valve hydraulic response WULLER.6 E lilinois Power Co 83/05/18 SCHWENCER.A Licensing Branch 2 ip 18519 094 24X Fiche 50-461,83/05/18.8305200667.

- 8305240406 Concurs in NRC recovery plan for procurement of spare & replacement parts & in lifting of stop work order KEPPLER, J C. Region 3, Office of Director 83/05/19 GERBINER, W C 111inois Power Co 1p 18571 044 24X Fiche 50-461,83/05/19,8305240406
- 8305240407 Ack receipt of 830408 & 0502 requests for concurrence in lifting Stop Work Orders 017.018 & 010 on electrical equipment, instrumentation installation & drywell refueling bellows, respectively Concurrence granted KEPPLER, J 9 Region 3, Office of Director 83/05/17 GERGINER, W C Illinois Power Co 2pp 18574 287 24% Fiche 50-461,83/05/19, 8305240407
- --8305240413 Requests concurrence in lifting 820623 Stop Work Orders 017 re electrical equipment installation & 018 re electrical instrumentation installation Recovery plan, correcting deficiencies in traveler control procedure, encl HALL.D P Illinois Power Co 83/04/09 KEPPLER, J Q Region 3, Office of Director 34pp 18574 287 24X Fiche 50-441,83/05/19,8305240407.
- ~-8305240421 Requests evaluation of completed refueling bellows recovery program to permit lifting of 820226 Stop Work Order 010 to continue bellows installation HALL.D P lilingis Power Co 83/05/02 KEPPLER.J G Region 3. Office of Director 2pp 18574 323 24X Fiche 50-461.83/05/19.8305240407
- 8305260246 Ack receipt of 830505 ltr requesting NRC review & concurrence w/HVAC recovery plan for Stop Work Orders 014, 015 & 020 Concurs w/plan intent KEPPLER, J G Region 3, Office of Director 83/05/19, GERSTNER, W C Illinois Power Co ip 18626 139 24x Fiche. 50-461, 83/05/19, 8305240246
- --8305260247 Forwards Rev 1 to "HVAC Recovery Plan" for review & concurrence Rev divides actions under Phases II & III resulting in add! Phases IV & V. HALL, D P Illinois Power Co 83/05/05 KEPPLER, J Q Region 3, Office of Director 2pp 18626 140 24X Fiche 50-461,83/05/17,8303260246
- --8305260253 Rev 1 to "HVAC Recovery Plan " W/one oversize encl Aperture card is available in PDR # Illinois Power Co 83/05/03 58pp 18626 142 24X Fiche 50-461,83/05/19,8305260246
- B305240142 Forwards response to Equipment Qualification Branch review comments on FBAR Section 3 11. "Environ Qualification of Electrical Equipment"

 WULLER, 0 E Illinois Power Co 83/05/20 BCHWENCER, A Licensing Branch 2 369pp 18547 001 24X Fiche 50-461,83/05/20,8305240142
- E305270017 Advises that fuel load date revised from Jan 1984 to Jan 1986. Const schedule updates will continue to be submitted quanterly Next update planned for Jul 1982 HALL, D.P. Illinois Power Co. 83/05/24 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 18638-317 24X Fiche 30-461, 63/05/24, 6308270017
- E. NRC Safety Evaluation Report (BER), supple & correspondence
- B305120460 Requests info re issue solutions accepted by NRC which have a have not been addressed in BER/supplemental BERs Info needed to document evaluation on each Licensing Review Group II generic issue.

 BTEFANO, J Licensing Branch 1. B3/05/02 HULTZSCHER, D L. Illingis Power Co 2pp 18443 173 24X Fiche 50-000, 83/05/02, 8305120460
- --8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue

 STEFANO. J Licensing Branch i 83/05/02 POHELL.P Washington Public Power Supply System ip 18443 174 24X
 Fiche 50-000, 83/05/02,8305120460

- --8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERS Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND. J Licensing Branch 1 83/05/02 RICHARDSON, J D Mississippi Power & Light Co ip 18443 176 24X
 Fiche 50-000,83/05/02,8305120460
- --B305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND. J Licensing Branch I 83/05/02 BUZZELLI, E M Cleveland Electric Illuminating Co 1p 18443 177 24X
 Fiche 50-000,83/05/02.8305120460
- 8305130146 Lists documentation to be provided re SER Dutstanding Issue 3 (NUREG-0853), "Seismic Analysis," per NRC request at 830428 meeting W/Sargent & Lundy in Bethesda, MD, satisfying site-specific spectrum concerns
 WULLER, G E 111inois Power Ca 83/05/10 SCHWENCER, A Licensing Branch 2 3pp 18438 124 24x Fiche 50-461,83/05/10,8305130146
- F Security, medical, emergency & fire protection plans
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS.W J Office of the Executive Director for Operations 83/05/13 PALLADINO.N J Commissioners 5pp 18393 322 24X Fiche 50-000.83/05/13.8305240213
- 9 Adjudicatory correspondence
- B305120336 Memorializes B30509 conversation w/Judge Paris ABLB will participate in B30602 site visit All parties may attend G0DBARD.R J Hearing Branch 3 B3/05/11 FDY.J Prairie Alliance NEUMAN.R Illinois, State of TABEL.5 A Schiff, Hardin & Waite 1p 18432 294 24X Fiche 50-461.83/05/11.8305120336
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8304050243 Forwards Amend 24 to FBAR, consisting of Tables 3 10-1 & -2 re dynamic qualifications of BOP & NSSS electrical equipment & revs to jet impingement evaluation & froth impingement loads
 HALL. D P Illinois Power Co 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation. Director ip 17831 252 24X
 Fiche 50-461,83/03/28,8304030243
- 8304050254 Amend 24 to FSAR # Illinois Power Co 83/03/31 773pp 17831 253 24X Fiche 50-461.83/03/28.8304060243
- 4 Inspection reports. 1E Bulletins & correspondence
- 8303190005 Final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B:C.D & E documents withheld (ref FDIA Exemption 7) FELTON;J M Division of Rules and Records 83/03/11 PRENDERGAST.R Prendergast, R J 17pp 18506 059 24X Fiche 50-000, 83/03/11; 8303190005
- ~~B305190030 Summarizes 820430 meeting w/president of Zack Co, HVAC contractor at facilities; re-potential allegations Zack Co-planning to terminate several employees in document control section
 HAYES, D. W. Region 3, Office of Director 82/05/12 Region 3, Office of Director, 1p. 18506-089 24X Fiche 50-000, 83/03/11, 8305/90005
- --B305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast * Radio TV Reports, Inc 82/07/24 NRC No Detailed Affiliation Given 2pp 18506-124 24X Fiche 50-000.83/03/11, 8305190005
- --8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co.HVAC contractor at facilities AT Howard & S Marelio allegations discussed DEVINE: T Covernment Accountability Project 82/07/26 PALLADINO: N. J. Commissioners iipp 18506 128 24% Fiche 50-000,83/03/11,8305190005
- --B305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co.HVAC contractor at facilities MARELLO.S L Affiliation Unknown B2/07/26 22pp 18506 139 24% Fiche 50-000.B3/03/11.B30519005

8305060576

- --8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co. KVAC contractor at facilities HQWARD.A T Affiliation Unknown 82/07/26 95pp 18506 160 24% Fiche 90-000.83/03/11.8305190005
- --8305190396 Discusses B20624 telcan w/8 Garde of Govt Accountability Project re allegations concerning Zack Co GA program at facilities Personally identifiable info deleted
 NORELIUS.C E Division of Engineering 82/07/12 Division of Engineering 19 18512 323 24X Fiche 50-000.83/03/11. 8305190005
- B303020336 Forwards IE Mgt Heeting Rept 50-461/83-06 on B30317 KEPPLER, J O Region G. Office of Director B3/04/08 GERSTNER Illinois Power Co 1p 18277 068 24X Fiche 50-461,83/04/08, B303020336 GERSTNER, H C
- ---8305020339 FE Mgt Meeting Rept 50-461/83-06 on 830317 Major areas discussed status of stop work recovery & overinsp &
- 8305060576 Forwards revised overinsp & record verification program Procedures BGA 185.BGA 190-BGA 194 & BGA 196.for review W/o encl HALL,D P Illinois Power Co 83/04/13 KEPPLER,J Ø Region 3. Dffice of Director 1p 18349 052 24X Fiche 50-461.83/04/13.8330506576
- B305020111 Informs of withdrawal of 830413 request for review & concurrence of revs to overinsp & record verification program procedures HALL, D.P. Illinois program procedures
 HALL, D.P. | Illinois Power Ca 83/04/20 | KEPPLER, J. Q. Region 3,
 Dffice of Director | p. 18278 216 | 24% Fichs 30-461, 83/04/20,
- 8305120345 Forwards IE Insp Rept 50-461/82-25 on 820914-830325 No Noncompliance noted
 LITTLE.W S Region 3, Office of Director 83/04/27 GERSYNER.W C
 Illinois Power Co 2pp 18432 271 24% Fiche 50-461,83/04/27,
- --8305120348 IE Insp Rept 50-461/82-25 on 820914-830325, No moncempliance noted Major areas inspected procedures & records for reinsp of structural steel bolting KEATING.D E . OANIELEON.D H Region 3. Office of Director 83/04/27 7pp 18432 273 24% Fiche 50-441,83/04/27,8305120345
- 8305170013 Forwards IE Insp Rept 50-461/83-04 on 830106-0317 No MOST/OUTS Formation of the control o GERSTNER, W C
- --8305170022 IE Insp Rept 50-461/83-04 on 830106-0317 No noncompliance noted Major areas inspected mat! laydown & storage areas, program control, general welding activities & stop work recovery activities
- 8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NOVAK, T M Assistant Director for Licensing, 83/05/03, HOLTSCHER, D L Licensing Review Group II 6pp 18440.356 Fiche, 50-000, 83/05/03, 8305120569
- 8305260244 Forwards IE Insp Rept 50-461/83-01 on 830420 & 21 Np noncompliant noted
 STRESTER, J F Region 3, Office of Director 83/05/12
 GERSTNER, W C 11linois Power Co 2pp 18599 324 2
 Fichs 30-461,83/05/12,8305260244
- --9305260250 IE Inse Rest 50-461/83-01 on B30420 & 21 No noscompliance noted Major areas inspected licensee action on space replacement part procurement sys inadequacies register. A . HANKINS.F C Region 3. Office of Director 4pp 18597 326 24X Fiche. 50-461.83/05/12,8305260244 83/03/12
- R Periodic operating reports & related correspondence
- 8305030559 Forwards "Preoperational Environ Radiological Munitoring Program Clinton Power Station 1982 " WULLER, 0 E Illinois Power Co 83/04/26 SCHWENCER, A Licansin Branch 2 ip 18305 150 24X Fiche 50-461,83/04/26,8305030559 Licensing

- --8305030592 "Preoperational Environ Radiological Monitoring Progress Clinton Power Station, 1982 " MARUCUT, C R , HUEBNER, L G Hazleton Laboratories America, Inc 83/04/07 78pp 18305 151 24X Fiche 50-461, 83/04/26, 830503 24X Fiche 50-461, 83/04/26, 8305030279
- 8 Reportable occurrences, LERs & related correspondence
- B305190005 Final response to FOIA request for documents re Zack Co & events performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7) FELTON,J M Division of Rules and Records 83/03/11 PRENDERGAST,R Prendergast, R J (7pp 18506 059 24% Fiche 50-000.83/03/11,80319/0005 Fich . 50-000, 83/03/11, 8305190005
- --8305190112 Deficiency rept me errors & discrepancies contained in MAC mat1 certifications Procurement documentation will be revalidated, document & records mgt program will be developed & GA/GC personnel will be added Also reportable per Part 21 CALKINS, D.E. Zack GO. 81/10/23 310pp 18506-215 24X Fiche 50-000, 83/03/11.8305190005
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Inti Initially reported on 830328 Matter under investigation final rept by 830808 Reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI.8 Region: 0.09fice of Director 2pp 18433 072 24X Fiche 50-000.83/04/26,8305120392 STAROSTECKI, #
- --8305120404 Part 21 rept re failure of post-LGCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4. Office of Director 5pp. 18433 074 24X Fiche 50-000,83/04/26,8305120392
- 8305040298 Interim Dficiency Rept B2-11 re incorrect identification of base math & weld procedures on piping hanger travelers Initially reported on B21020 Further traveler review necessary Investigation to be completed in 90 days HALL DP Illinois Fower Co B3/04/27 KEPPLER, J Q Region 3. Office of Director 5pp 18324 020 24X Fiche 50-461,83/04/27.
- 8305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attached hold tags to 13 HVAC control panels w/defect. Evaluation being conducted
 HALL, D P Illinois Power Co 83/05/04 KEPPLER, J Q Region 3,
 Office of Director 2pp. 18431 049 24X Fiche 30-000,83/05/04, P303120475
- --8305120484 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformance rept will be issued for applicable sites PAUCONNEAU, G Mark Controls Corp 83/04/18 Director's Office
 Office of Inspection and Enforcement 2pp 18431 051 24x
 Fiche 50-000, 83/05/04, 8305120475
- 8305310129 Interim Deficiency Rept 83-05 re failure of 1/4 inch 20 Res head cap screws Initially reported on 830412 Conduit straps will be installed w/higher strangth cap screws & torque instructions will be (save). HALL, D.P. Illinois Power Co. 83/05/23 KEPPLER, J. Q. Region 3. Office of Director 4pp 18655-035 24X Fiche: 50-461, 83/05/23. 8305310129
- 8305310183 Interim Deficienty Rept 81-04 re inconsistencies in certifications of HVAC matls Initially reported on 811002 Zack Co revised corporate & site 9A manuals to enhance controls & describe programs
 HALL-D P Illinois Power Co 83/05/23 KEPPLER, J Q Region 3, Office of Director 4pp 18658 129 24X Fiche 50-461,83/05/23,8305310183

DOCKET 50-462 CLINTON POWER STATION, UNIT 2 G Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FDIA request for documents re Zack Co &/or JUSIYUUUS Final response to Fula request for documents acats work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR. App B.C.D & E documents withheld (ref FUIA Exemption 7). FELTON.J.M Division of Rules and Records 83/03/11 PREMDERGAST, R Prendergast, R J 17pp 18506, 059 24X Fiche 50-000, 83/03/11, 8305190005

- --B305190050 Summarizes 820430 meeting w/president of Zack Co.HVAC contractor at facilities repotential allegations Zack Co.lanning to terminate several employees in document control action
 HAYES, D.W. Region 3. Office of Director 82/05/12 Region 3. Office of Director 1p 18506-089 24% Fiche 50-000.83/03/11, 8305190005
- --8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly Naws broadcast a Radio TV Reports, Inc. 82/07/24 NRC No Detailed Affiliation Given 2pp 18506-124 24X Fiche 50-000, 83/03/11, 8305190005
- --8305190097 Requests investigation of Region III inadequate investigative oversight re 8A breakdown & possible criminal falsification at Zack Co.HVAC contractor at facilities AT Howard & 8 Marello allegations discussed DEVINE.T Government Accountability Project 82/07/26 PALLADIND, N. J. Commissioners 11pp 18306 128 24X Fiche 50-000.83/03/11.8305190005
- --8305190102 Affidavit of SL Marello re GC breakdown & criminal falsification at Zack Co.HVAC contractor at facilities MARELLO.8 L Affiliation Unknown 82/07/26 22pp 18504 137 24% Fiche 50-000.83/03/1i.8305140005
- --8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co.HVAC contractor at facilities HOHARD. A T Affiliation Unknown 82/07/26 53pp 18506 160 24% Fiche 50-000.83/03/11.8305190005
- --8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability
 Project re allegations concerning Zack Co GA program at
 facilities Personally identifiable info deleted
 NORELIUS.C E Division of Engineering 82/07/12 Division of
 Engineering ip 18512 323 24X Fiche 50-000,83/03/11,
 8305190005
- 8 Reportable occurrences, LERs & related correspondence
- B305190005 Final response to FOIA request for documents re Zack Co &/pr work performed by Zack in const of facilities Forwards App A documents Documents denoted w/esterisk available in PDR App B.C.D & E documents withheld (ref FOIA Exemption 7) FELTON, J M Division of Rulea and Records 83/03/11 PRENDERGAST, R Prendergast, R J 17pp 18506 059 24X Fiche: 50-00G,83/03/11,8305190005
- ---8305190112 Deficiency rept re errors & discrepancies contained in HVAC mat1 certifications Procurement documentation will be revalidated document & records mgt program will be developed & GA/GC personnel will be added Also reportable per Part 21 CALKING.D E Zack Co 81/10/23 310pp 18506 215 24X Fiche 30-000,83/03/11,8305190005
- 8305120392 Interim deficiency rept re misapplication of ITE Oould circuit breakers in post-LDCA hydrogen recombiners supplied by Rockwell Intl Instituting reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO, B F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI.R Region i, Office of Director 2pp 18433 072 24X Fiche 50-000.83/04/26.8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEV, D.C. Rockwell International Corp. 83/03/ii COLLINS, J.T. Region 4, Office of Director. 3pp. 18433-074 24X Ficher 50-000,83/04/26,8305120392
- DOCKET 50-449 KUOBHENO POWER STATION, UNIT 1
- P. Operating license stage documents & correspondence
- 8305240474 Forwards "Safety Relief Valve Discharge Test," final rept for Kudsheng Nuclear Power Station.including Apps A-T Rept withheld (ref 10CFR2 770) Info submitted per DL Condition 2. C(45). DALE, L.F. Mississippi Power & Light Co 83/05/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp. 96187 286 24% Fiche: 50-000, 83/05/02, 8305240496

- DOCKET STN-50-470 CESSAR SYSTEM 80
- A Application/construction stage documents & correspondence
- BBQ05170326 Forwards revised CEBSAR-F Section 3 11 re environ design of mechanical & electrical equipment Rev will be incorporated into amend to CESSAR-F SCHERER.A E Combustion Engineering, Inc. 83/05/10 EISENHUT, D Q Division of Licensing 52pp 18465 173 24X Fiche 50-470,83/05/10,83005170326
- 8305230704 Responds to ACRS 811215 recommendation re C-E svaluation of interface requirements for applications ref CESSAR ACRS recommendations could have antitrust implications Dutlined response to be included in CESSAR SER EISENHUT.D G Division of Licensing 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp 18542 304 24% Fiche 30-470,83/05/16.8305230704
- --8302250480 Expresses concern that requiring C-E NSBS applicants to select C-E to make CESSAR interface requirements determination may have antitrust implications VOLLMER, R H Division of Engineering 83/07/17 EISENHUT, D 0 Division of Licensing 3pp 18542 313 24X Fiche 50-470, 83/05/16.8305230704
- O Utility Preliminary Safety Analysis Report, amends
- 8305120120 Forwards Amend 8 to CESSAR-F List of rev topics encl SCHERER.A E Combustion Engineering, Inc 83/05/10 THOMAS.C Standardization & Special Projects Branch 5pp 18428 260 24X Fiche 50-470,83/05/10,8305120120
- --8305120124 Amend 8 to CESSAR-F # Combustion Engineering, Inc 83/05/10 246pp 18428 265 24X Fiche 50-470.83/05/10.8305120120
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305020400 Forwards "Sys 80 CESSAR FSAR, Responses to Questions on Steam Line Break Method," per SER Confirmatory Item 14 Proprietary responses withheld (ref 10CFR 2790) SCHERER.A E Combustion Engineering, Inc 83/04/26 THOMAS, C O Standardization & Special Projects Branch 6pp 18284 034 24X Fiche 50-470, 83/04/26, 8305020400
- --8305020406 "Bys 80 CESSAR FSAR, Responses to Questions on Steam Line Break Method " * Combustion Engineering, Inc 83/04/30 16pp 18284 040 24X Fiche 50-470.83/04/26,8305020400
- 8305090338 Forwards proprietary & nonproprietary "Response to NRC Questions on CESSAR-F Statistical Combination of Uncertainties in Thermal Margin Analysis for Sys 80," (SER Item 7) Proprietary response withheld (ref 10CFR2 790) SCHERER, A E Combustion Engineering, Inc 83/05/03 EISENHUT, D 0 Division of Licensing 6pp 18363 074 24% Fiche 50-470,83/05/03,8305090338
- --8305090372 Nonproprietary "Response to NRC Questions on CESSAR-F Statistical Combination of Uncertainties in Thermal Hargin Analysis for Sys 80," (SER Item 7) « Combustion Engineering, Inc. 83/04/30 39pp 18363 080 24X Fiche 50-470,83/05/03.8305090338
- B305120185 Forwards nonproprietary & proprietary responses to Questions 440 5.10.11 & 12 on steam line break method, resolving 8ER Confirmatory Items 14 & 15 Proprietary responses withheld (ref 10CFR2.790) Affidavit encl SCHERER.A E Combustion Engineering, Inc B3/03/10 THOMAS, C O Standardization & Special Projects Branch 19pp 18424 208 24X Fiche 50-470.83/05/10.8305120185
- 8305130081 Notifies that steam generator tube rupture analysis addressed in 830426 ltr will be performed per SER Confirmatory Item 18 & will be submitted by 830715 SCHERER. A E Combustion Engineering, Inc. 83/05/10 EISENHUT, D O Division of Licensing 2pp 18437 088 24X Fiche 50-470,83/05/10,8305130081
- B305180017 Requests current schedule to respond to SER Suppl 1 open item re finalization of generic statistical combination of uncertainty analysis
 THOMAS.C O Standardization & Special Projects Branch 83/05/13
 BERLINGER.C Core Performance Branch 2pp 18497 178 24X
 Fiche 30-470.83/05/13.8305180017

E3052005AB Forwards emended Table 3-1 of Section II F 2.App B reflecting clarification of addressing TMI Action II em II F 2 re inadequate core couling detection instrumentation, Open Item 4 of CESSAR-F SER SCHERER, A E Combustion Engineering, Inc. 63/05/13 EISENHUT, D Q Division of Licensing App. 18514-279, 24X Fiche 30-470,83/05/13,83052005AB

M Antitrust correspondence

- 8305230704 Responds to ACRS 811215 recommendation re C-E evaluation of interface requirements for applications ref CESSAR ACRS recommendations could have antitrust implications Outlined response to be included in CESSAR SER EISENHUT, D G Division of Licensing 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 18542 304 24X Ficha 50-470,83/05/16,8305230704
- --8302250480 Expresses concern that requiring C-E NSSS applicants to select C-E to make CESSAR interface requirements determination may have antitrust implications VOLLMER, R H Division of Engineering 83/02/17 EISENHUT, D G Division of Licensing 3pp 18542 315 24X Fiche 50-470, 83/05/16,8305230704

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 83050400006 Forwards request for add1 info to complete evaluation of 830310 environ qualification plan Info should be provided within 30 days or NRC licensing project managers notified within 7 days of itr receipt if schedule cannot be met YOUNGBLOOD, B J Licensing Branch 1 83/04/20 SCHNELL, D F Union Electric Co 6pp 18331 248 24% Fiche 50-000,83/04/20,8305040006
- 8305020229 Discusses inacturacies in util 830121 response to NRC questions re SNM application No enforcement action planned Complete candor between NRC & licensee emphasized OAGLIARDD, J E Division of Resident, Reactor Project & Engineering Programs 83/04/28 KOESTER, G L Kansas Gas & Electric Co 2pp 18278 142 24X Fiche 50-482.83/04/28,8305020229
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & halders of CPs re integrated scheduling for implementation of plant mods Svr list encl
 EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Ficha 50-000.83/05/09,8305070659
- 8305110014 Forwards response to 820907 request for add1 info re pump & valve operability & purps valve operability.consisting of master listing of seismic & dynamic qualification for facilities Proposed audit schedule encl
 PETRICK:N A Standardized Nuclear Unit Power Plant System
 83/05/09 DENTON:N R Office of Nuclear Reactor Regulation.
 Director 233pp 18621 203 24X Fische 50-000.83/05/09.8305110014
- 8305130007 Requests permission to use Paragraph NX-4427 of Winter 1982 Addenda to ASME Builer & Pressure Vessel Code. Section III allowing undersizing of fillet welds PETRICK. N A Standardized Nuclear Unit Power Plant System 83/05/09 DENTON. R Defice of Nuclear Reactor Regulation, Director 19 18437 148 24X Fiche 50-000.83/05/09.8305130007
- 8305250193 Notification of 830615 public meeting w/util in Burlington, KS & Caseload Forecast Panel 830616 & 17 site visit to assess status of const & completion schedules HOLONICH, J J Licensing Branch 1 83/05/09 YOUNGBLOGD, B J Licensing Branch 1 6pp 18626 324 24X Fiche 30-482,83/05/09,8305250193
- B30527005B Advises that fuel load scheduled for 840815 & commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltr 82-33) requirements re emergency plans will be met CADMAN.W K Kansas Gas & Electric Co B3/05/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18638 250 24X Fiche 50-482.83/05/23,8305270058
- 8305310175 Forward Rev 1 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0588" PETRICK.N A Standardized Nuclear Unit Power Plant System 83/05/27 DENTON.H R. Office of Nuclear Reactor Regulation, Director 344pp 18659 144 24X Fiche 50-000.83/05/27,8305310175

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305110047 Forwards test summary rept demonstrating acceptability of using regulating-type transformer as isolation device in IE circuit per SER Confirmatory Issue 19 PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18409 017 24% Fiche 50-000,83/05/09,8305110047
- 8305250231 Summary of Power Sys Branch 830405-09 site audit re power supply for auxiliary feedwater sys per BER Confirmatory Issues 15,17 & 23 (Bection 1 7 of NUREO-0830)
 EDIBON, 6 E , HOLONICH, J J Licensing Branch 1 83/05/12
 YOUNDBLOOD, 8 J Licensing Branch 1 7pp 18427 100 24X
 Fiche 50-000,83/05/12,8305250231
- B303180393 Informs that results of tests on isolating regulating transformer in conjunction w/change in B30509 ltr re BER Confirmatory Issue 19. assure that faults postulated on secondary circuits will not adversely affect Class IE bus PETRICK, N A Standardized Nuclear Unit Power Plant Bystem B3/05/13 DENTON, H R Office of Nuclear Bactor Regulation, Director 1p 18486 346 24% Fiche 50-000.83/05/13.8305180393
- 8305270210 Forwards div input to emergency planning for suppl to BER Matl updates info contained in Section 13 3, "Emergency Planning of Wolf Creek Generating Station SER," (NUREG-OBBI, Apr 1982)
 PAGANO,F O Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/25 YOUNDBLOOD,B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482,83/05/25,8305270210
- F Security, medical, emergency & fire protection plans
- B305060338 Releases public version of addl info for review of emergency plan FELTON.J M Division of Rules and Records B3/04/25 Document Management Branch, 1p 18353 026 24X Fiche 50-482,83/04/25,8305060338
- --8305060346 Forwards public version of add1 info re review of emergency plan, consisting of revised response to NRC questions & of revised emergency plan pages KOESTER, O L. Kansas Oas & Electric Co. 93/04/15 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18353 027 24X Fiche 50-482,83/04/25,8305060338
- --8305060354 Public version of revised pages to emergency plan, including revised response to NRC questions & of revised emergency plan pages a Kansas Gao & Electric Co 83/04/30 App 18353 029, 24X Fiche 50-482,83/04/25,830506038
- 8305020421 Forwards add1 info re emergency plan per 821206 request Info addresses Question 8.4 concerning plant personnel response capability during emergency situation per staffing goals in Suppl 1 to NUMEG-0737 KOEBTER.0 L Kansas Cas & Electric Co. 83/04/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 10pp 18273.100 24X Fiche 50-482.83/04/29,8305020421
- B30512008B Requests review schedule for applicant response to Generic Ltr 82-33 re NUREG-0737. Suppl 1 concerning emergency response capability W/o encl YOUNOBLOOD. B J Licensing Branch 1 B3/04/29. MOORE, V Human Figure Fing Bection ROBA, F Instrumentation & Control Branch PAGANO, F Emergency Preparedness Licensing Br (after 801119 tee 18E) 2pp 18443 171 24X Fiche 50-000, 93/04/29, 8305120088
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Bvc list encl EISENHUT, D @ Division of Licensing, 83/05/il Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X Fiche 50-000,83/05/i1,8305i10034
- B305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKS,W J Office of the Executive Director for Operations B3/05/13 PALLADING,N J Complesioners 5pp 18593 322, 24X Fiche 50-000, 83/05/13, 8305240213
- 8305270058 Advises that fuel load scheduled for 840815 & commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltp 82-33) requirements re emergency plans will be met CADMAN. W K Mansas Gas & Electric Co 83/05/23 DENTON. H R Office of Nuclear Reactor Regulation, Director, 2pp 18638-250 24x Fiche 50-482,83/05/23,8305270058

8305270210 Forwards div input to emergency planning for suppl to SER Matl updates info contained in Section 13 3. "Emergency Planning of Wolf Creek Operating Station SER." (NUREO-0881, Apr 1982)
PAGANO,F O Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/25 YOUNGBLOOD, B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482,63/05/25,8305270210

Q Adjudicatory correspondence

- 8305040498 Objections to proposed issues & motion for adoption of interrogatory responses as statement of issues for litigation Proposed stipulation lacks specificity Certificate of Svc encl Related correspondence RIDOMAY. D A Kansas Gas & Electric Co 83/05/03 Atomic Safety and Licensing Board Panel 24p 18348 214 24X Fiche 50-482,83/05/03,8305060498
- 8305090496 Order denying objection to ASLB prehearing order re amend of contention/stipulation by intervenor & granting request to add Kenses Dept of Transportation & Highway Patrol employees to witness list
 LAURENSON, J A Atomic Safety and Licensing Board Panel 83/05/05
 Jpp 18361 148 24% Fiche 30-482.83/05/05.8303090496
- 8305090503 Order of expedited briefing schedule re applicant objection & motion for adoption of interrogatory responses as statement of issues for litigation Responses due by 830516 LAURENSON. J A Atomic Bafety and Licensing Board Panel 83/05/05 Kansas Gas & Electric Co 2pp 18362-010 24X Fiche 50-482,83/05/05,8305090503
- 8305120391 Attachment A, alternative evacuation plan contention, to response in opposition to intervenors W Christy & ME Salava 830330 objections to ASLB 830318 prehearing conference order Related correspondence RIDGWAY. D Kansas Gas & Electric Co RIDGWAY. D Shaw, Pittman, Potts & Troubridge 83/05/05 34pp 18433 081 24X Fiche 50-482, 83/05/05, 8305120391
- 3305180288 Response apposing util B30503 objections to issues & motion for adoption of interrogatory responses as statement of issues for litigation ABCB should adopt intervenor second stipulation of contentions H/Certificate of Svc BIMPBON.J M Christy, W, Intervenor BIMPBON.J M Christy, W, Intervenor BIMPBON.J M Balava, M E Intervenor 83/05/12 Atomic Safety and Licensing Board Panel 28pp 18490 305 24X Fiche 50-482,83/05/12,8305180288
- 8305170002 Response to util 830503 objections to intervenor proposed issues & motion for adoption Util correct in limiting scape of inquiry to plume emergency planning zone.per Commission regulations. Certificate of 8vc encl KARMAN.M Hearing Branch 1 83/05/13 App 18466 225 24X Fiche. 50-482.83/05/13,8305170002.
- 8305240313 Informs of agreement to develop acceptable statement of contentions & resolution of all but one objection to proposed issues for litigation, per applicant 830503 objections.

 SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge SILBERG, J. E. Kanses Cas & Electric Co. 83/05/19 LAURENSON, J. A. ANDERSON, G. C. PAXTON, H. C. Atomic Safety and Licensing Board Panel 3pp. 18548 188 24X Fichs. 50-482, 83/05/19, 8305240313

I. Financial information

- B305230567 Forwards Annual Financial Repts for 1982 for Kansas Qas & Electric Co, Kansas City Power & Light Co & audited financial statements for 1982 from Kansas Electric Power Cooperative, Inc.

 KOESTER. C L Kansas Qas & Electric Co 83/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 18535 280 24X Fiche. 50-482.83/05/18,8305230567.
- ---8305230570 Annual Financial Rept 1982. GADMAN, H K Kaneas Gas & Electric Co. 83/02/04 32pp. 18535 281. 24X Fiche 50-482,83/05/18,8305230567
- --8305230572 Annual Financial Rept 1982 Audited statements from Kansas Electric Power Cooperative. Inc for 1982 encl. DOVLE:A J Kansas City Power & Light 83/03/01 46pp 18535 313. 24X Fiche. 50-482, 83/05/18, 8305230567

Q. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Syc list enc! TAYLOR.J.M. Division of Safeguards & Inspection Programs (Post B30103) B3/03/21 Consolidated Edison Co of New York, Inc 112pp 18308.319 24X Fiche 50-000.83/03/21.8212060385.

- B305100303 Forwards B30315 IE investigation rept re activities under CPPR-147 No violations identified COLLINS, J T Region 4. Office of Director B3/04/05 KDEBTER, G L Kansas Oas & Electric Co 4pp 18370 081 24X Fiche 50-482
- --B305100307 Rept of investigation on 820802-830110 re allegations concerning activities authorized by CPPR-147 No violations observed GRIFFIN,H B , HERR,R K , WARD,W J Region 4, Office of Director 83/03/19 3pp 18370 082 24X Fiche 50-482,83/04/03,8305100303
- 8305100112 Forwards 1E Insp Rept 50-482/83-06 on 830221-0315 No noncompliance noted SEIDLE.W C Region 4. Dffice of Director 83/04/12 K0ESTER.O L Kansas Gas & Electric Co 2pp 18375 036 24X Fiche 50-482, 83704/12, 8305100112
- --8305100116 IE insp Rept 50-482/83-06 on 830221-0315 No noncompliance noted Major areas inspected action on previous insp findings; const deficiency repts; observations of safety-related pipe hangers & supports & general plant tours ROBERDS.H W. JOHNSON, W.D. Region 4. Office of Director 83/04/04 Spp 18375 038 24X Fiche 50-482,83/04/12.8305100112
- B303040021 1E Info Notice 83~21, "Defective Emergency Use Respirator" 8vc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 50-000.B3/04/15.8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8305100151 Forwards IE Inep Rept 50-482/83-07 on 830301-31 & notice of violation
 SEIDLE-W C Region 4, Office of Director, 83/04/22 KOESTER.0 L Kansas Gas & Electric Co 2pp 18374 223 24X
 Fiche 50-482,83/04/22,8305100151
- --8305100155 Natice of violation from insp on 830301-31 * Region 4, Office of Director B3/04/22 lp 18374 225 24X Fiche 50-482.83/04/22,8305100151
- --8305100160 IE Insp Rept 50-482/83-07 on 830301-31 Noncompliance noted failure to implement GA program requirements for constructor test program BCHUM, W 8 . JOHNSON, W D Region 4, Office of Director 83/04/21 9pp 18374 226 24X Fiche 50-482,83/04/22,8305100151
- 8303040025 IE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Bys " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305030617 Ack receipt of 830325 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/92-22 SEIDLE:W G Region 4. Office of Director 83/04/27 KOESTER:O L Kansas Oas & Electric Co 2pp 18303 321 24% Fiche 50-482.83/04/27.8305030617
- --8305030622 Responds to NRC 830223 ltr re violations noted in IE Insp Rept 50-482/82-22 Corrective actions maint forms revised. Vendor contact documented & maint records for Westinghouse supplied items will be reviewed KOESTER.0 L. Kansas Gas & Electric Co. 83/03/25 SEIDLE.W C Region 4. Defice of Director Spp. 18303 323 24X Fiche 50-482.83/04/27.8305030617
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- B303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment," Syc list enci, JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past B30103) B3/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-24, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441 170 24X Fiche 50-000,83/05/03.8303040028

- 8303040030 IE Info Notice 83-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment" Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83705/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 80303) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New Yort, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06.8303040033
- B305230473 Forwards IE Insp Rept 50-482/83-10 on B30316-0415 & notice of violation SEIDLE-H C Region 4. Office of Director 83/05/06 KOESTER, G L Kansas Gas & Electric Co 2pp 18537 186 24% Fiche 50-482,83/05/06,8305230473
- --8309230476 Notice of violation from insp on 830316-0419 4 Region 4, Office of Director 83/05/06 ip 18537 188 24X Fiche 50-482,83/05/06,8305230473
- ---8305230480 IE Insp Rept 50-482/83-10 on 830316-0415 Noncompliance noted failure to prescribe activities affecting quality by procedure for welding of electrical raceway supports ROBEROS.H W. JOHNSON,W D. Region 4. Office of Director 83/05/03 5pp 18537 189 24X Fiche 50-482,83/05/06,8305230473
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3705/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, B3/05/11, B303040034
- G305230485 Ack receipt of B30421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-482/83-04 Add1 info requested re measures to assure that all equipment opened prior to rev had necessary controls applied SEIDLE,W C Region 4, Office of Director 83/05/18 KDESTER, 0 L Kansas Oas & Electric Co 1p 18537 183 24% Fiche 50-482, 83/05/18,8305230485
- --8305230489 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-482/83-04 Corrective actions vol control tank cleaned & procedures for maintaining cleanliness revised KGESTER.0 L Kansas Qas & Electric Co 83/04/21 BEIDLE,W C Region 4. Office of Director 2pp 18537 184 24X Fiche 50-482.83/05/18,8305230485
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Ever list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/03/19,8303040040
- 8305310104 Ack receipt of 830511 ltr discussing educational qualification of util OC inspector Results of verification process for personnal educational level requested.

 SEIDLE: N C Region 4, Office of Director 83/05/25 KOESTER, Q L Kansas Qas & Electric Co 1p 18658 067 24X Fiche 50-482, 83/05/25 8305310104
- --8305310110 Advises that incident re educational qualification of QC inspector under investigation Completion of high school not verified if completion of higher level of educ verified. High school educ verification continuing KOESTER.0 L Kansas Qas & Electric Co 83/05/11 SEIDLE.W C Region 4, Diffice of Director 2pp 18458 049 24X Fiche 50-482.83/05/23.8305310104
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046
- S. Reportable occurrences, LERs & related correspondence
- 8304130354 Part 21 Rept U-48 & Interim deficiency rept re GE ARR-30 & AKR-30 circuit breaters. Initially reported on 830211, Assessment of safety implications & corrective actions requested of AE Final rept expected by 830429 SCHWELL, D.F. Union Electric Co. 83/04/07 SPESSARD, R. L. Division of Project & Resident Programs. ip 17982 128 24X Fiche 30-000, 83/04/07, 8304130334

- B305020073 Final Deficiency Rept SDR B3-06 re Anchor/Darling check valves failing to close Initially reported on B30323 Gaused by improper design Hinge pins replaced & Btellite 6 bushings to be installed SEIKEN,S J Btandardized Nuclear Unit Power Plant Bystem B3/04/20 KEPPLER. J O Region 3. Defice of Director COLLINB. J T Region 4. Defice of Director 2pp 18279 100 24X Fiche 50-000,83/04/20,830530073
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHG, E P Westinghouse Electric Corp 83/04/21 DEYOUNO, R C Director's Office. Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000.83/04/21.8305110427
- 8305030354 Interim deficiency rept re restricted movement of nonstationary pipe supports Initially reported on 821014, AE evaluation in progress Next rept will be sent by 830729 KDESTER: 0 L. Kansas Gas & Electric Co 83/04/25 BEIDLE: W C. Region 4. Office of Director ip 18300 022 24X Fiche 50-482,83/04/25,8305030354
- B305030378 Interim deficiency rept re compromised welding inspector exams Initially reported on B20712 Number of inspectors under investigation reduced to four & reinsp of welds accepted by four inspectors in progress Next rept by B30826, K0E8TER.0 L Kansas Oas & Electric Co B3/04/25 SEIDLE, W C, Region 4, Office of Director ip 18306/258 24X Fiche 50-482,83/04/25,8305030378
- 8305030492 Second interim deficiency rept re documentation & hardware discrepancies in borated refueling water sys Initially reported on 830121 Status rept of evaluation will be submitted by 830624 KDESTER.0 L Kansas Gas & Electric Co 83/04/25 SEIDLE,W.C Region 4. Office of Director 2pp 18306 181, 24X Fiche, 30-482, 83/04/25, 8305030492
- 8305040430 Final Significant Deficiency Rept 83-05 re QE AKR 30 & 50 electrically operated low voltage circuit breakers. Initially reported on 83021 Field rework plan will be issued to effect necessary breaker repairs
 SEIKEN.9 Standardized Nuclear Unit Power Plant System 83/04/28, KEPPLER, J G Region 3, Office of Director GOLLINB.T T, Region 4 Defice of Director 8pp 18319.319 24X Fiche 50-000.83/04/28, 83035040430
- 8305200335 Supplemental final deficiency rept re suspect modules mfg by Foxboro Co Eight addl suspect modules identified & will be replaced KOESTER.O L Kansas Oas & Electric Co 83/05/12, BEIDLE, W C. Region 4, Office of Director ip 18516 228 24X Fiche 50-482,83/05/12,8305200335
- B3053i014B Final deficiency rept re mat1 traceability of U-bolts & bulk bolting mat1s Initially reported on B30204 Marking requirements established to assure proper mat1 identification.

 KUESTER, Q. L. Kansas Gas & Electric Co. 83/05/23 BEIDLE, W. C. Region 4. Office of Director 5pp. 18653.055 24X Fiche 50-482.83/05/23,8305310148.
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8303240307 Forwards "Offsite Dose Calculation Manual "
 BCNNELL,D F Union Electric Co 83/03/21 DENTON,H R Office of
 Nuclear Reactor Regulation, Director 3pp. 17682:049 24X
 Fiche 50-483,83/03/21,8303240307
- --8303240311 "Offsite Dose Calculation Manual" * Union Electric Co. 83/03/21 66pp 17682 052. 24% Fiche 50-483,83/03/21,8303240307
- 8305040006 Forwards request for add1 info to complete evaluation of B30310 environ qualification plan Info should be provided within 30 days or NRC licensing project managers notified within 7 days of ltr receipt if 'schedule cannot be met. YOUNOBLODD, B J Licensing Branch 1 83/04/20 8CHNELL, D. F. Union Electric Co 6pp 18331 248 24X Fiche 50-000, 83/04/20, 8305040006
- 8305040323 Board Notification 83-057, forwards differing prof opinions re sys interaction & safety classification, Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17,
 EISENHUT, D @ Division of Licensing 83/05/04, PALLADINO, N Commissioners. 22pp 18337:139 24X Fiche 50-000,83/05/04,8305040323

- B305110014 Forwards response to B20907 request for add1 info re pump & valve operability & purge valve operability, consisting of master listing of seismic & dynamic qualification for facilities Proposed audit schedule enci
 PETRICK,N A Standardized Nuclear Unit Power Plant System
 B3/03/07 DENTON,H R Office of Nuclear Reactor Regulation,
 Director 233pp 18621 203 24% Fiche 50-000,83/03/09,8305110014
- 8305130007 Requests permission to use Paragraph NX-4427 of Winter 1982 Addenda to ASME Boiler & Pressure Vessel Code, Section III allowing undersizing of fillet welds PETRICK.N A Standardized Nuclear Unit Power Plant System 89/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18437 148 24X Fiche 30-000.83/05/09, 8305130007
- ### B305310175 Forward Rev 1 to "Rept of Independent Review of Environ Gualification Programs to NUREG-0588"

 PETRICK.N A Standardized Nuclear Unit Power Plant System ### B3/05/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 344pp 18659 144 24% Fiche 50-000, 83/05/27, 8305310175
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B303110047 Forwards test summary rept demonstrating acceptability of using regulating-type transformer as isolation device in IE circuit per BER Confirmatory Issue 19
 PERRICK, N A Standardized Nuclear Unit Power Plant System B3/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18409 017 24% Fichs 50-000.83/05/09/8305110047.
- 8305250231 Summary of Power Sys Branch 830405-07 site audit re power supply for auxiliary feedwater sys per 8ER Confirmatory Issues 15:17 & 23 (Section 1 7 of NUREO-0830)
 EDISON, G. E., HOLONICH, J. J. Licensing Branch 1 83/05/12, YGUNOBLOOD, B J. Licensing Branch 1 7pp 18627 100 24X Fiche: 50-000.83/05/12,8309280231
- B305180393 Informs that results of tests on isolating regulating transformer, in conjunction w/change in 830509 ltr re BER Confirmatory Issue 19.assure that faults postulated on secondary circuits will not adversely affect Class IE bus PETRICK,N A. Btandardized Nuclear Unit Power Plant Bystem B3/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p. 18486-346 24% Fiche 50-000,83/05/13,8305180393
- F Security, medical, emergency & fire protection plans
- 63031200BB Requests review schedule for applicant response to Generic Ltr 82-33 re NURGO-0737. Suppl 1 concerning emergency response capability W/o smc 1 concerning emergency YOUNDELOOD, 9 J. Licensing Branch 1 B3/04/29. MOORE, V. Human Engineering Section. ROSA: F. Instrumentation & Control Branch PAOANO.F. Emergency Preparedness Licensing Br (after 80119 see 1&E). 2pp 18443.171 24X Fiche 30-000.83/04/29.830512008B
- B3051702R2 Ack receipt of B30427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-14.

 BPESBARD.R L Division of Engineering B3/05/09 BCHNELL, D F Union Electric Co ip 18466 346 24X Fiche. 50-483,83/05/09, B305170222.
- --8305170227 Responds to NRC 830329 ltr re violations noted in 1E Insp Rept 50-483/82-14 Corrective actions complete walkdown performed on all outside area bldgs; fuel bldg & other firerated openings BCHNELL,D F Union Electric Co 83/04/27 LITTLE;W B Region 3, Office of Director 3pp 18466/347 24X Fiche 50-483,83/05/09, 8305170222.
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enc!
 EISENHUT.D 0 Division of Licensing 83/03/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095, 24X Fiche: 50-000, 83/05/11, 8305110034
- 83052402i3 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKB, W J. Diffice of the Executive Director for Operations, 83/05/13 PALLADINO, N J Commissioners 5pp. 18593-322 24X Fiche 50-000,83/05/13,8305240213.

G Adjudicatory correspondence

- 8305030447 Forwards Daniel Const Co summary of relevant events & corrective actions re potential reportable deficiency in testing of candidates for QC inspector certification Certificate of Svc encl BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Union Electric Co 83/04/28 ROSENTHAL.A B . EDLES.O J . OOTCHY.R L Atomic Safety and Licensing Appeal Panel Spp 18292 166 24X Fiche 30-483.83/04/28.8305030467
- 8305020394 Order scheduling 830614 oral argument in Bethesda,MD re Joint Intervenors appeal from ASLB partial initial decision TOMPKINS.B A Atomic Bafety and Licensing Appeal Panel 83/04/29 2pp 18276 327 24X Fichs 50-483.83/04/29,8305020394
- 8305100257 Requests rescheduling of 830614 oral argument on appeal of Joint Intervenors from partial initial decision Certificate of Svc encl
 CHACKES.K N Chackes & Hoare 83/05/06 YDMPKINS, B A Atomic Safety and Licensing Appeal Panel 2pp 18374 062 24X
 Fiche 50-483, 83/05/06, 8305100257
- 8305110266 Confirms svc of Callaway County/Fulton County radiological emergency response plan on 830506 Plans for Osage Gasconade & Montgomery Counties & state plan forthcoming Svc list encl
 BAXTER.T A Shaw, Pittman, Potts & Trowbridge 83/05/09 REED.J G Missouri, State of 2pp 18393 155 24X Fiche 50-483,83/05/09, 8305110266
- 8305120314 Order rescheduling oral argument for 830422 per Joint Intervenors request
 SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/05/10
 Joint Intervenors-Callaway 1p 18424 105 24X
 Fiche 50-483,83/05/10,8305120314
- 8305130083 Notice of rescheduling of 830614 oral argument for 830622 in Bethesda MD SHOEMAKER.C J Atomic Safety and Licensing Board Panel 83/05/11 p 18436 265 24X Fiche 50~483,83/05/11,8305130083
- 8305190249 Confirms util delivery of State of MO accident plan for plant & Osage County radiological emergency response plan Gyc list encl BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union Electric Co B3/05/17 REED, J Q Reed, J Q 2pp 18501 301 24X Fiche 50-483,83/05/17,8305190249
- 8305250205 Confirms delivery of Casconade & Montgomery County radiological amergency response plans on 830519 8vc list encl W/O encl I trs 8AXTER, T A Shaw, Pittmen, Potts & Trowbridge BAXTER, T A Union Electric Co 83/05/20 REED, J O Reed, J O 2pp 18392 356 24X Fiche 50-483,83/05/20,8303250205
- 8305250294 Memorandum of law supporting motions for summary disposition of amergency pianning issues Hearing time should not be spent on baseless allegations Notice of appearance encl BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 14pp 18585 001 24x Fiche 50-483,83/05/20,8305250294
- ---8305250297 Motion for summary disposition of Reed Contention i re staffing of Montgomery County sherief ofc No genuine issue of math fact exists & applicant entitled to favorable decision. BAXTER.T A Union Electric Co. BAXTER.T A Shaw, Pittman, Pott & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 25pp 18586 015 24X Fiche: 50-483,83/05/20,8305250294
- --8305250300 Statement of matl facts as to which there is no genuine issue re Reed Contention I staffing of Montgomery County sheriff ofc BAXTER:TA Union Electric Co BAXTER:TA Shaw, Pittman, Potts & Trowbridge. 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 040 24X Fiche 50-483,83/05/20,8305250294
- --8305250304 Affidavit of WM Clark re Reed Contention i on staffing of sheriff ofts Adequate personnel available w/law enforcement training to provide emergency law enforcement svcs for Callaway County & City of Fulton CLARK, W M. Union Electric Co CLARK, W M. Callaway County, MO CLARK, W M. Fulton, MO 83/05/16 16pp 18586 042 24X Fiche. 50-483, 83/05/20, 8305230274
- --8305250341 Affidavit of QW Stanfill re Reed Contention 1 on staffing of sheriffs ofc. Sufficient personnel available per shift to fulfill law enforcement functions assigned to Montgomery, Gasconade & Osage Counties

 STANFILL, Q W Union Electric Co STANFILL, Q W Missouri, State of. 83/05/12 12pp 18586 058 24X Fiche 50-483, 83/05/20, 8305250274

- --8305250346 Motion for summary disposition of Read Contention 2 restaffing of county clerk ofcs No genuine issue of math fact exists & applicant entitled to favorable decision BAXTER, TA Union Electric Co BAXTER, TA Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 18pg 18586 070 24X Fiche 50-483.83/05/20,8305250294
- --B30525035! Statement of matl facts as to which there is no genuine issue re Read Contention 2 on staffing of county clerk ofce BAXTER.T A Union Electric Co BAXTER.T A Shaw Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18386 098 24X Fiche 50-483,83/05/20,8305250274
- --8305250354 Affidavit of HM Clark re Reed Contention 2 on staffing of Callaway County & City of Fulton clerk ofcs No addicterical personnel needed to provide assistance during emergency shifts Prof qualifications encl
 CLARK.W M Union Electric Co CLARK.W M Callaway County, MO CLARK.W M Fulton.MO 83/05/16 9pp 18586 090 24X
 Fiche 50-483.83/05/20,8305250294
- --8305250356 Affidavit of GW Stanfill re Regd Contention 2 on staffing of clark ofcs Emergency-related clarical functions described in county plans will be properly incorporated in Mantgomery, Gasconade & Gaage Counties Prof qualifications encl BTANFILL.0 W Union Electric Co STANFILL.0 W Missauri, State of 83/05/12 4pp 18386 099 24% Fiche 50-483,83/05/20,8305250274
- --8305250358 Motion for summary disposition of Reed Contention 3 re emergency mgt director staffing No genuine issue of matl fact exists & applicant entitled to favorable decision BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman. Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 13pp 18586 103 24X Fiche 30-483,83/05/20,8305250274
- --8305250359 Statement of matl facts as to which there is no genuine issue re Reed Contention 3 on emergency mgt director staffing BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 118 24X Fiche 30-483.83/05/20.8305250294
- --8305250360 Affidavit of T Mitchell re Read Contention 3 on emergency mgt director staffing Full-time emergency mgt director in Montgomery County unnecessary VB Eldringhoff is alternate director MITCHELL. J Union Electric Co MITCHELL. J Affiliation Unknown 83/05/17 4pp 18586 120 24X Fiche 90-483:83/05/20.8305230294
- --8309250363 Affidavit of H Lalk re Reed Contention 3 on emergency mgt director staffing Full-time emergency mgt director for Gasconade County unnecessary LALK.H Union Electric Co LALK.H Gasconade County, MO 83/03/16 4pp 18586 124 24Y Fiche 50-483,83/03/20,8305250294
- --8305250372 Affidavit of J Crowe re Reed Contention 3 on emergency mgt director staffing Full-time emergency mgt director for Osage County unnecessary CROME. J Union Electric Co CROME. J Osage County. MO 83/05/09 4pp 18586
- --8305250383 Mution for summary disposition of Reed Contention 4 researcy action level scheme/worker notification No genuine issue of matl fact exists & applicant entitled to favorable decision

 BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18586 132 24X Fiche 50-483.83/05/20,8305250874
- ---8305250388 Statement of math facts as to which there is no genuine issue re Reed Contention 4 on emergency action level scheme/worker notification
 BAXTER: T A Union Electric Co BAXTER: T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 147 24X Fiche 50-483.83/05/20,8305250274
- --B305250374 Affidavit of JW Baer re Reed Contention 4 on emergency action level scheme/worker notification Emergency classification sys & worker notification provisions reflect sound operational concepts Prof qualifications encl BAER.J W Union Electric Co BAER.J W Energy Consultants, Inc B3/05/13 12pp 18586 149 24X Fiche 50-483,83/05/20,8305250294
- ---B305250401 Motion for summary disposition of Read Contention 5.Parts B & G re radio communications No genuine issue of matl fact exists & applicant entitled to favorable decision BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman. Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 5pp 18586 161 24X Fiche 50-483,83/05/20,8303250274

- ---B305250403 Statement of matl facts as to which there is no genuine issue re Read Contention 5, Parts B & C on radio communications

 BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Trowbridge B3/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 166 24X Fiche 50-483, 83/05/20, 8305250294
- --8305250408 Affidavit of MA Stiller re Reed Contention 5.Parts B & C on radio communications Commitment to supply add1 transceivers for designated patrol & rescue vehicles provides sufficient communication for patrol & rescue STILLER:M A Union Electric CO 83/05/18 4pp 18586 168 24X Fiche 50-483,83/05/20.8305250274
- --8305250412 Motion for summary disposition of Read Contentions 4 & 16 re protective actions against radiolodines & messages for long-term sheltering No genuine issue of matl fact exists & applicant entitled to favorable decision BAXTER.TA Union Electric Co BAXTER.TA Shaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 50pp 18586 172 24X Fiche 50-483,83/05/20,8305250294
- --8305250419 Statement of matl facts as to which there is no genuine issue re Reed Contentions & & 16 on protective actions against radioiodines & messages w/instructions for long-term sheltering

 BAXTER: TA Union Electric Co DAXTER: TA Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 3pp 18586 222 24X Fiche 50-483,83/05/20,8305250294
- --8303250424 Affidavit of KV Miller re Reed Contention 6 on protective actions against radioiodines State of MD will not administer potassium igdine to general public in avent of accident, but drug will be available to state emergency workers MILLER, K V Union Electric Co MILLER, K V Missouri, State of 83/05/11 7pp 18586 225 24X Fiche 50~483,83/05/20,8305250274
- --8305250428 Affidavit of RE Linnamen re Reed Contention 6 on protective actions against radiolodines Describes risks & benefits associated w/ingestion of potassium iodine & endorses State of MO policy re distribution of potassium iodine LINNEMANN,R E Union Electric Co LINNEMANN,R E Radiation Management Corp 83/04/28 14pp 18586 232 24X Fiche 50-483,83/05/20,8305250294
- --8303250432 Affidavit of NO Blaten re Reed Contentions & 16 on protective actions against radioiodines & messages w/ instructions for long-term sheltering Explains effectiveness of sheltering as protective action SLATEN,N O Union Electric Co. E3/05/16 Epp 18586,246 24X Fiche 50-483,83/05/20,8305250274
- --8305250436 Affidavit of S Harris re Reed Contentions 6 & 16 on protective actions against radiologines & messages w/ instructions for long-term sheltering Explains effectiveness of ad hoc respiratory protection HARRIS.8 Union Electric Co 83/05/16 14pp 18586:254 24X Fiche 50-489,83/05/20,8305250274
- --8305250440 Motion for summary disposition of Reed Contention 7 represented decontamination facilities No genuine issue of matl fact exists & applicant entitled to favorable decision BAXYER.T A Union Electric Co BAXYER.T.A Shaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 6pp 16386 268 24X Fiche 30-483,83/05/20,8303250274
- --B305250444 Statement of matl facts as to which there is no genuine issue re Reed Contention 7 on presited decontamination facilities

 BAYTER, T A Union Electric Co BAYTER, T A Shaw, Pittman, Potts & Troubridge B3/05/20 Atomic Safety and Licensing Board Panel 2pp 18366-274, 24X Fiche 30-483, B3/09/20, B305250274
- ---B30523044B Motion for summary disposition of Read Contention 8 re radiation detection equipment. No genuine issue of matl fact sxists & applicant entitled to favorable decision BAUSER, D B Union Electric Co BAUSER, D, B. Shau, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 11pp 18586-276 24X Fichs 50-480,83/05/20,8305250274
- --8305250451 Statement of matl facts as to which there is no genuine issue re Reed Contention 8 on radiation detection equipment BAUSER.D B Union Electric Co BAUSER.D, B. Shaw, Pittman, Potts & Trowbridge 83/05/20, Atomic Safety and Licensing Board Panel 2pp 18386 287 24X Fichs 50-483,83/05/20,8305250294
- --8305250458 Affidavit of RE Linnemann re Reed Contention 8 on radiation detection equipment State of MO & local govts have sufficient equipment, lab facilities & expertise to evaluate external & internal radiation exposures
 LINNEMANN.R E Union Electric Co LINNEMANN.R E. Radiation Management Corp. 83/04/28, 13pp 18586-289 24X
 Ficha 30-483,83/05/20,8305250294

- --8305250461 Motion for summary disposition of Reed Contention 9 on radiological exposures No genuine issue of matl fact exists & applicant entitled to favorable decision BAUSER.D B Union Electric Co BAUSER.D B Shaw Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18586 302 24X Fiche 30-483,83/05/20,8305250294
- --8305250463 Statement of matl fact as to which there is no genuine issue re Reed Contention 9 on radiological exposures
 BAUSER.D B Union Electric Co BAUSER.D B Shaw, Pittman, Potts
 & Trowbridge 83/05/20 Atomic Safety and Licensing Board
 Panel 2pp 18586 317 24X Fiche 50~483,83/05/20,8305250294
- --8305250469 Affidavit of RE Linnemann re Reed Contention 9 on radiological exposure Means for controlling radiological exposure of local emergency workers during accident established per 10CFR50 47(b)(11)
 LINNEMANN.R E Union Electric Co LINNEMANN.R E Radiation Management Corp 83/04/28 17pp 1898 319 24X Fiche 50-483,83/05/20.8305250294
- --8305250474 Motion for summary disposition of Reed Contention 10 re medical treatment No genuine issue of matl fact exists & applicant entitled to favorable decision BAUSER, D B Union Electric Co BAUSER, D B Shaw, Pittman, Potts & Trombridge 83/05/20 Atomic Safety and Licensing Board Panel 22pp 18586, 336. 24X Fiche 30-483, 83/05/20, 8305250274
- --8305250477 Statement of matl fact as to which there is no genuine issue re Reed Contention 10 on medical treatment BAUSER.D B Union Electric Co BAUSER.D B Shaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Fanel 2pp 18586 358 24X Fiche 50-483,83/05/20,8305250294
- --8305250492 Affidavit of RE Linnemann re Read Contention 10 on medical treatment Upon completion of training program, Callaway Memorial Hosp will provide adequate local medical resources to handle all types of radiation injuries LINNEMANN, R E Union Electric Co LINNEMANN, R E Radiation Management Corp 83/04/28 26pp 18586 360 24X Fiche 50-483,83/05/20.8305250294
- --8305250486 Motion for summary disposition of Reed Contention 11 re reentry/recovery radiation stds No genuine issue of matl fact exists & applicant entitled to favorable decision BAXTER.TA Union Electric Co BAXTER.TA Shaw, Pittman. Potts & Troubtridge 83/05/20 Abomic Safety and Licensing Board Panel 13pp 18587,024 24X Fiche 50-483,83/05/20,8305250294
- --8305250490 Statement of matl fact as to which there is no genuine issue re Read Contention 11 on recovery & reentry radiation stds

 BAXTER: TA Union Electric Co. BAXTER: TA Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel Rpp 18587 037 24% Fichs 50-483:83/05/20,83032502594
- --B305250476 Affidavit of JW Baer rs Reed Contention 11 on reentry/
 recovery radiation stds Offsite emergency plans reentry
 decision process description complies w/planning criteria
 Prof qualifications encl
 BAER, J W Union Electric Co BAER, J W. Energy Consultants, Inc
 B3/05/13 9pp 18587 039 24X Fiche 50-483,83/05/20,8305250294
- --8303230502 Motion for summary disposition of Reed Contention 13 re organizations requiring SDPs No genuine issue of math fact exists & applicant entitled to favorable decision BAXTER.T.A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18587-048, 24X Fichs 30-483,83/05/20,8305250294
- --8305250506 Statement of math fact as to which there is no genuine issue re Reed Contention 13 on organizations requiring SOPs BAXTER, T.A Union Electric Co BAXTER, T.A Shaw, Pittman, Potts & Trombridge 83/05/20, Atomic Safety and Licensing Board Panel 2pp. 18587 063 24X Fichs 50-483,83/05/20,8305250294
- --B305250511 Affidavit of JW Baer re Reed Contention 13 on organizations requiring BOPs Functional procedures will provide adequate instructions to organizations assigned emergency response role
 BAER.J W. Union Electric Co BAER.J W Energy Consultants, Inc B3/05/13, 13pp 18587 065 24X Fiche 50-483.83/05/20,8305250274
- --8305250515 Motion for summary disposition of Reed Contention 14 on incorporated cities, towns & villages No genuine issue of mat1 fact exists & applicant entitled to favorable decision BAXTER, TA Union Electric Co BAXTER, TA Bhaw, Pittman, Potts & Troubridge, 83/05/20. Atomic Safety and Licensing Board Panel 19pp, 18587 078 24X Fiche 50-483,83/05/20,8305250294

- ---B305250521 Statement of matl fact as to which there is no genuine issue re Contention 14 on incorporated cities, towns & villages
 BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 200 18587 097 248 Fiche 50-483,83/05/20,8305250294
- ---8305290524 Motion for summary disposition of Reed Contention 15 re ltrs of agreement No genuine issue of mati fact exists & applicant entitled to favorable decision BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 83/09/20 Atomic Safety and Licensing Board Panel 14pp 18387 099 24Y Fiche 50-483.83/05/20.8305250294
- --8305250531 Statement of matl fact as to which there is no genuine issue re Contention 15 on ltrs of agreement BAXTER.T A Union Electric Co 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 113 24% Fiche 50-483, 83/05/20.8305250294
- --8305250536 Affidavit of WM Clark re Reed Contention 15 on ltrs of agreement Sufficient ltrs of agreement exist or will exist prior to plant operation to ensure necessary emergency support & resources to implement util/Fulton plan CLARK.W M Union Electric Co CLARK.W M Callaway County, HD CLARK.W M Fulton,MO 83/05/16 17pp 18587 115 24X Fichs 50-483,83/05/20.8305250294
- --8303250540 Motion for summary disposition of Reed Contention 17 re radiological monitoring No genuine issue of math fact exists & applicant entitled to favorable decision BAXTER:TA Union Electric Co BAXTER:TA Shaw, Pittman, Potts & Troubridge 83/05/20. Atomic Safety and Licensing Board Panel 21pp 13587 132 24X Fiche 50-483:83/05/20.8303250224
- --8305250542 Statement of matl fact as to which there is no genuine issue re Reed Contention 17 on radiological monitoring BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 3pp 18587 133 24X Fiche 50~483,83/05/20,8305250294
- --8305250544 Affidevit of KV Miller to Reed Contention 17 on radiological monitoring State resources in trained personnel & radiation monitoring equipment adequate Prof qualifications encl MILLER.K V Union Electric Co MILLER.K V Missouri, State of 83/05/17 12pp 18387 136 24X Fiche 50-483,63/05/20,8305250294
- --8305250548 Affidavit of HK Johnson re Reed Contention 17 on radiological monitoring State resources in trained personnel & radiation monitoring equipment adequate Prof qualifications encl
 JCHNSCN.H K Union Electric Co JCHNSCN.H K Missouri, State of 83/05/13 6pp 18587 168 24% Fiche 50~483.83/05/20.8303250294
- --8305250552 Affidavit of NG Slaten re Reed Contention i7 on radiological monitoring Util radiological emergency organization includes extensive radiological monitoring capability & resources Prof qualifications encl
 SLATEN.N G Union Electric Co B3/05/16 23pp 18587 174 24X Fiche 50-483,83/05/20,8305250294
- --8305250553 Motion for summary disposition of Reed Contention 18 re
 human food & animal feeds No genusne issue of mati fact
 exists & applicant entitled to favorable decision
 BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts
 & Troubridge 83/05/20 Atomic 8afety and Licensing Board
 Panel 15pp 18587 197 24X Fiche 50-483.83/05/20,8305250294
- ---8305250957 Btatement of matl fact as to which there is no genuine issue is Reed Contention 18 on human food & animal feeds BAXTER:TA Union Electric Co BAXTER:TA Bhaw, Pittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 212 24% Fiche 50-483,83/05/20,8305250294
- --8305280559 Motion for summary disposition of Reed Contention 19 re impediments to use of evacuation routes No genuine issue of matl fact exists & util entitled to favorable decision BAXTER.T A Union Electric Co BAXTER.T A Shaw. Pittman. Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 82pp 18587 214 24% Fiche 50-483,83/05/20,8305250294
- --8305250562 Statement of matl fact as to which there is no genuine issue re Reed Contention 19 on impediments to use of evacuation routes

 GAXTER.TA Union Electric Co BAXTER.TA Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18387 236 24K Fiche 90-483,83/05/20,8309250274
- --8305250566 Affidavit of RO Wright re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments
 WRIGHT.R G Union Electric Co WRIGHT.R A Callaway County, MD 83/05/17 7pp 18587 238 24X Fiche 50-483,83/05/20,8305250294

- --8305250573 Affidavit of G Epple re Read Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments EPPLE.G Union Electric Co EPPLE.G Gasconade County, MD 83/05/16 4pp 18587 245 24X Fiche 50-483,83/05/20,8305250294
- --8305250574 Affidavit of VB Eldringhoff re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments ELDRINGHOFF, V Union Electric Co ELDRINGHOFF, V Montgamery County, MD 83/05/14 7pp 18387 249 24% Fiche 50-483, 83/05/20,8305250274
- --B3092505B0 Affidavit of H Matthews re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments MATTHEMS.H Union Electric Co MATTHEWS.H Affiliation Unknown 83/05/16 3pp 18587 256 24X Fiche 50-483.83/05/20.8305250294
- --8303250583 Motion for summary disposition of Reed Contention 20 re authorization of excess radiological worker exposures & spec of decontamination action levels No genuine issue of math fact exists & util entitled to favorable decision BAXTER:T A Union Electric Co DAXTER:T A Shaw, Pittman, Potts & Trowbridge 63/05/20 Atomic Safety and Licensing Board Panel 122p 18387 239 24X Fiche 50-483,83/05/20,8305250274
- ----8305250584 Statement of matl fact as to which there is no genuine issue re Reed Contention 20 on authorization of excess radiological worker exposures & spec of decontamination action levels

 BAXTER.T A Union Electric Co BAXTER.T A Shaw, Fittman, Potts & Troubridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 271 24X Fiche 50-483,83/05/20,8305250294
- --8305250587 Affidavit of WM Clark re Reed Contention 20 on authorization of excess exposures to workers & spec of decontentination action levels Planning need for authorization per NUREQ-0554. Section III E 3, met Prof qualifications encl CLARK-W M Union Electric Co CLARK-W M Callaway County. MD 83705718 7pp 18387 279 248 Fichs 50-483.83705720,8305250294
- ---8305250589 Affidavit of JW Baer re Reed Contention 20 on authorization of excess radiological worker exposures & spec of decontamination action levels Certificate of Svc & prof qualifications encl
 BAER.J W Union Electric Co
 B3/05/18 67pp 18587 280 24X Fiche 50-483, 83/05/20, 8305230294
- 8305260168 Forwards corrected Certificate of Svc certifying svc of documents on 830520 Original certificate date incorrect BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Union Electric Co 83/05/23 OLEASON.J P. BRIGHT, G O. KLINE, J R Atomic Safety and Licensing Board Panel ip 18599 273 24X Fiche 50-483,83/05/23,8305260168
- --8305260173 Corrected Certificate of Svc certifying svc of documents on 830520 BAXTER.T A Union Electric Co 83/05/20 9pp 18599 274 24X F(che 50-483,83/05/23,8305260168
- B305260164 Advises that TA Batter will represent util at B30622 oral argument in response to Joint Intervenors appeal BAXTER.T A Shaw, Pittman, Potts & Trowbridge. BAXTER.T A Union Electric Co. B3705/24 TUMPKINS.B A Atomic Safety and Licensing Appeal Panel 1p 18599 283 24X Fiche 50-483,83/05/24,8305260164
- 8305310170 Advises that table of contents & table of cross-refs to NUREQ-0654 planning stds/evaluation criteria adequate to locate portions relevant to contentions Referenced portions of plans listed BAXTER T A Shaw, Pittman, Potts & Trowbridge 83/05/26 REED, J. 6 Affiliation Unknown 7pp 18652 326 24X Fiche 30-483,83/05/26,8305310170
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Syr list ent!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 30-000,83/03/21,8212060385
- 8305030469 Forwards iE Integrated Designed Insp Rept 50-483/82-22 on 821110-19 & 29-1214
 DEYQUING: C Director's Office, Office of Enspection and Enforcement 83/04/04 SCHNELL, D.F. Union Electric Co. 5pp. 18295.183 24X Fiche 50-483, 83/04/04, 8305030469

- --8305030474 IE Integrated Design Insp Rept 50-483/82-22 on 821110-19 & 27-1214 Noncompliance noted no formal control over Bechtel plant design newsletters & ability of motor controllers to withsteand fault currents not considered ALLISON.D P . NORKIN.D P . FAIR.J R Director's Office of Inspection and Enforcement 83/03/31 114pp 18275 189 24X Fiche 50-483,83704/04.8305030469
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021,
- 8305020350 Forwards IE Insp Rept 50-483/83-02 on 830223-24 to 0314-17 & notice of violation SPESSARD.R L. Division of Engineering 83/04/18 SCHNELL, D F Union Electric Co 2pp 18274 107 24X Fiche 50-483, 83/04/18, 8305020350
- --8305020354 Natice of violation from insp on 830223-24 to 0314-17 8PESBARD,R L Division of Engineering 83/04/18 ip. 18274:109 24% Fiche 50-483,83/04/18.8305020350
- --8305020357 IE Insp Rept 50-483/83-02 on 830223-24 to 0314-17.
 Noncompliance noted failure to include design document
 limits & precautions in Safety Injection Accumulator
 Preoperational Test Procedure CS-03EP01
 WOHLD, P R . RING, M A . REYES, L A . Region 3, Office of Director
 83/04/18 Spp 18274 110 24X Fiche 50-483.83/04/18.8305020350.
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 8vc list encl
 JORDAN. E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fichs 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parte in Secondary Side of Steam Generators at PWRs." Byo list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047 24x Fiche 50-000,83704/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Bys Heater High Temp Trip Betpoint Adjustment " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28, Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- B305030258 Ack receipt of B3040B ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-21.
 SPEBSARD, R L Region 3. Office of Director 83/04/28 BCHNELL.D F Union Ejectric Co ip 18300 034 24% Fiche 50-483,83/04/28,8305030258
- --8303030263 Responds to NRC 830308 ltr re violations noted in IE Insp Rept 50-483/82-21 Corrective actions scaffolding immediately removed from load ctrs Visual insp of load ctrs after scaffolding removed revealed no damage SCHNELLID F. Union Electric Co 83/04/08 LITTLE W S Region 3, Office of Director 3pp 18300 035 24X Fiche 50-483.83/04/28, 83030303038
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Bvc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03, Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche. 50-000, 83/05/03, 8303040028.
- 8305060284 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-20 SPESSARD.R L Division of Engineering 83/05/03 SCHNELL.D F. Union Electric Co ip 18344 325 24X Fiche 50-483.83/05/03.8305040284
- --8305060293 Responds to NRC 830315 ltr re violations noted in IE Insp Rept 50-483/82-20 Corrective actions component support checklist revised, hanger insp underway, revised insp procedures implemented & training sessions will be held, BCHNECL, D F Union Electric Co 83/04/13. LITTLE, W S. Regian 3, Office of Director App 18344-326 24% Fiche 50-483,83/05/03, 8305060284

- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-27, "Fuel Rinding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B305170130 Ack receipt of B30504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-21 SPEBBARD, R L Division of Engineering 83/05/09 SCHNELL, D F Union Electric Co ip 18466 261 24X Fiche 50-483,83/05/09,8305170130
- --8305170136 Responds to NRC 830308 ltr re violations noted in 1E Insp. Rept 50-483/82-21 Corrective actions test program to confirm max sidewall pressure values & contact w/vendor to verify validity of max values in progress

 8CHNELL,D F Tunion Electric Co 83/05/04 LITTLE,W 8 Region 3, Office of Director 3pp 18466 262 24X Fiche 50-483,83/05/07,8305170130
- B305170182 Ack receipt of B30429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-09 Extension of compliance date to B30801 acceptable BPEBSARD. R L Division of Engineering B3/05/09 SCHNELL, D F Union Electric Co ip 18466 324 24% Fiche 50-483,83/05/09, B305170182
- --B30517018B Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-483/82-07 Extension to 830801 to complete rebar scanning activities requested SCHNELL.D F Union Electric Co 83/04/27 NORELIUS, C E Division of Engineering 1p 18466 325 24X Fiche 50-483,83/03/07,8305170182
- 8305170222 Ack receipt of 830427 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-14 SPESSARD.R L Division of Engineering 83/05/09 SCHNELL.D F Union Electric Co ip 18466 346 24X Fiche 50-483.83/05/09.
- --9305170227 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-483/82-14 Corrective actions complete walkdown performed on all outside area bldgs: fuel bldg & other firerated openings SCHNELL.D F Union Electric Co 83/04/27 LITTLE, W S Region 3, Office of Director 3pp 18466 347 24X Fiche 50-483,83/05/07, 8305170222
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8305200512 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 50-483/83-03 NRELIUS, C E Division of Project & Resident Programs 83/05/13 BCCNELL, D F Union Electric Co ip. 18516 088 24X Fiche 50-483,83/05/13,8305200512
- --8305200518 Responds to NRC 830331 itr re violations noted in IE Insp Rept 50-483/83-03 Corrective actions damaged & missing mat1 replaced & cable ISBV09CA pulled out & replaced w/new cable per approved Disposition 250-973-E SCHNELL, D F Union Electric Co 83/04/29 NORELIUS. C E Division of Project & Resident Programs 3pp. 18516.089 24X Fiche 50-483.83/05/13.8300200312
- B303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co. of New
 York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040.
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN, E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York. Inc 114pp 18647 007 24X Fiche 50-000.83/05/26,8303040046

- S Reportable occurrences. LERs 5 related correspondence
- 8304150354 Part 21 Rept U-48 % interim deficiency rept re GE ARR-30 & AKR-50 circuit breakers [nitially reported on B30211 Assessment of safety implications & corrective actions requested of AE Final rept expected by 830429 SCHNELL.D F Union Electric Co B3/04/07 SPESSARD.R L Division of Project & Resident Programs ip 17982 128 24% Fiche 30-000, 83/04/07, 8304150354
- B305020073 Final Deficiency Rept SDR 83-06 re Anchor/Darling check valves failing to close Initially reported on B30223 Caused by improper design Hinge pins replaced & Stellite 6 bushings to be installed SEIKEN.9 J Standardized Nuclear Unit Power Plant System 83/04/20 KEPPLER.J G Region 3, Office of Director CDLLING.J T Region 4, Office of Director 2pp 18279 100 24X Fiche 50-000.83/04/20, 830502073
- 8305020133 Supplemental Part 21 Rept 6 re possible thermostatic valve malfunction fail-safe to full cooling position Lower overrum assemblies in Robertshaw valves on diesel generator sets replaced w/assemblies using cotter pins MORIARTY. J M Colt Industries, Inc 63/04/21 KEPPLER, J 9 Region 3, Office of Director 1p 18278 219 24% Fiche 30-483,83/04/21,8305020133
- B305i10427 Part 21 & deficiency repts re misoperation of D8-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/uidened grooves to accommodate new retaining rings Mfg drawings revised RAME,EP Westinghouse Electric Corp B3/04/21 DEYOUNG,R C Director's Office. Dffice of Inspection and Enforcement Spp 18405 095 24X Fiche 50-000,83/04/21,8305110427
- B305030467 Forwards Daniel Const Co summary of relevant events & corrective actions re potential reportable deficiency in testing of candidates for GC inspector certification Certificate of Svc encl BAXTER.T A Shaw, Pittman. Potts & Trowbridge BAXTER.T A Union Electric Co B3/04/28 ROSENTHAL.A S. EDLES.G J. GOTCHY.R L Atomic Safety and Licensing Appeal Panel Bpp 18292 166 24X Fiche 50-483,83/04/28,8305030467
- 8305040430 Final Significant Deficiency Rept 83-05 re GE AKR 30 & 50 electrically operated low voltage circuit breakers Initially reported on 830211 Field rework plan will be issued to effect necessary breaker repairs
 BEIKEN.5 Standardized Nuclear Unit Power Plant System 83/04/28 KEPPLER.J G Region 3. Office of Director CCLLINS.T T Region 4. Office of Director Bpp 18319 319 24X Ficha 50-000.83/04/28.
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- B Reportable occurrences, LERs & related correspondence
- 8305030374 PNO-II-83-031 on 830427. Unit 1 cancellation announced Caused by lower than anticipated growth in customer demand for power 10NATONIS. A . DANCE. H C Region 2. Office of Director 83/04/2 2pp 18306 302 24X Fiche 50-491. 83/04/29. 8305030374
- DOCKET 30-496 MONTAQUE NUCLEAR POWER STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8303090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Syc list enci ETBENHYT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 133 24X Fiche 30-000,83/05/09,8305090639
- F Security, medical, emergency & fire protection plans
- 8305i10034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D Q Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 075 24X Fiche 50-000, 83/05/11, 8305110034

- G. Inspection reports, IE Bulletins & correspondence
- 8212060385 (E Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction' Svc list

TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212040385

830304002: IC Info Notice 83-21, 'Defective Emergency Use Respirator' list encl

OVE 1184 enc.) JORDAN.F L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000.83/04/15.8303040021

- 8303040023 IE info Notice 83-22, "NWR Safetu Relief Valve Failures " Svc list encl ORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
 JORDAN.E L Division of Energency Preparedness & Engineering
 Response (Post 830103) 83/04/25 Consolidated Edison Co of New
 York, Inc 119pp 18381 291 247 Fiche 50-000,83/04/25,8303040025
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list enc! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 110pp 18382 165 24X Fiche 50-000,83/04/28,8303040027
- 830304002B IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JURDAN/E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co 18441 170 24X Fiche 50-000,83/03/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events VOUNDUSS IN INFO NOTICE 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York. Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/04 Consolidated Edison Co of New York, Inc (19pp 1844) 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 lE Infa Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGF) Guidelines "Syc list encl JORDAN/E L Division of Emergency Preparedness & Engineering Response (Post 8330103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 lE Info Notice 83-31. "Error in ADLPIPE Computer Program " Svc list enc)

 JORDAN-E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) B3/05/19 Consolidated Edison Co of New

 York, Inc 114pp 18697 009 24% Fiche 30-000,83705/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 50-000,83/05/26,8303040046

- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305070659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enc!
 EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp. 18627 153 24X
 Fiche 50-000,83/05/09,8305070659 Consolidated
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 83/05/11 24X
- G Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent lon Exchange Resin Susceptibility to Exothermic Chamical Reaction " Svc list TAYLOR J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112ap 18308 319 24X Fiche 50-000,83/03/21,8212040385
- 8303040021 1E Info Notice 83-21, "Defective Emergency Use Resoirator " Svc list encl JORDAN,E L OVC 11st enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24% Fiche 30-000,83/04/15,830304002[
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Seve list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc. 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere 93349025 It Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 117pp 18381 291 24X Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Cenerators at PWRs " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fichs 50-000,83/04/28,8303040026.
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve pischange Line Vacuum Breakers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice B3-27, "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment "Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830(03) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for Owneral Emergencies" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/03/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
- 303040040 to the street of the
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8305180001 Addl response to FDIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
 FELTON, J M Division of Rules and Rocords 83/03/09 LINDEMAN, H N Lowenstein. Newman. Reis, Axelrad & Toll 6pp 18497 219 24X
 Fiche 50-000,83/03/09,8305180001
- --B005140276 Responds to 800418 memo re concrete voiding Discusses status of problems & repairs STELLO,V Office of Inspection & Enforcement, Office of the Director BO/04/25 BRADFORD,P A Commissioners 3pp 18497 139 24X Fiche 50-000,83/03/09,8305180001
- --BQ06090443 Forwards WA Post article re harassment of GC personnel Lack of enforcement action questioned BRADFORD,P A Commissioners 79/10/10 STELLO,V Office of Inspection & Enforcement. Office of the Director 2pp 18497 237 24X Fiche 50-000,83/03/09,8305180001
- -- 8008120773 Forwards outlines of JF Ahearne & V Stello proposed DUDIEUT/S FORWARDS OUTLINES OF UP AREATRE & V StellO proposed testimony refacility before House Subcommittee on Oversight & Investigation
 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/07/11 AMEARNE, J T. GILINEKY, V. HENDRIE, J Commissioners 6pp 18499 163 24X Fiche 50-000,83/03/09.
 R3D518000/
- --- 8010090450 Forwards draft Commission info paper re plan for resumption PLODY0430 Forwards draft Commission into paper re plan for resumpts of const Comments or concurrences needed by 800912 M/v encl
 THORNBURG, H D Division of Reactor Construction Inspection
 80/09/11 DENTON, H R Diffice of Nuclear Reactor Regulation,
 Director SHAPAR, H K Diffice of the Executive Legal Director
 STELLD. V Office of Inspection & Enforcement, Office of the
 Director 9pp 18499 222 24X Fiche 50-000, 83/03/09, 8305180001
- --8010280578 Responds to Guestion 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual inso & status summarized Licensee unii complete visual insplacemply w/corrective actions in enci AMS Code
 BTELLO.V Office of Inspection & Enforcement, Office of the
 Director 80/09/25 AHEARNE.J F Commissioners 5pp
 18997 228 24% Fiche 90-000.83/03/09/8309180001
- --8010280581 Assigns questions resulting from 800923 Eckhardt hearing AHEARNE.J F Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193 24X Fiche 50-000.83/03/09.8305180001
- --8305180121 Requests info re scope & significance of voids in concrete at site Response requested by 800423
 BRADFORD, P A Commissioners. 80/04/18 DIRCKS, W J Office of the Executive Director for Operations ip 18499 138 24X
 Fiche 50-000,83/03/09,8305180001
- --B303180148 Advises that staff should notify Commission in advance of proposed actions re facility investigation, per Commissioner Bradford B00418 memo CHILK, S J Office of the Secretary of the Commission B0/04/28 DTRCKB, W J Office of the Executive Director for Operations ip 18499 142, 24X Fiche 50-000.83/03/09,8305180001.
- --8305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility
 KAMMERRER C Office of Congressional Affairs 80/07/09
 AHEARNE, J.F. OILINSKY, V. HENDRIE, J. M. Commissioners 2pp
 18499 157 24X Fiche 50-000, 83/03/09, 8305180001

- --8305180236 Submits schedule of Congressional hearings re waste bill H R 7418, West Valley Bill H R 6865 & South Texas project Related info enc!
 REMM.T A Office of the Executive Director for Operations 80/07/07 STELLO, V Office of Inspection & Enforcement, Office of the Director DAVIS. J Office of Nuclear Material Safety & Safeguards, Director 4pp 18499 159 24X Fiche 50-000.83/03/07, 8305180001 8305180001
- --B305180250 Forwards Chairman Ahearne \hbar V Stello testimony prepared for House Subcommittee on Oversight b Investigation hearing re STELLO.V Office of Inspection b Enforcement, Office of the Director 80/07/25 AHEARNE, J F GILINSKY, V , HENDRIE, J M Commissioners 2pp 18499 169 24X Fiche 50-000, 83/03/09, 8305180001
- --9305180315 Forwards Part 2 of Commission regulations re practice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl BURNS, S G BURNS, S. G. Office of the Executive Legal Director 80/05/29 CORTEZ. B. Communities Organized for Public Service 1p 18499-218 24% Fiche 50-000, 83/03/09,8305180001
- --8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickuit, general counsel STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS, W J Office of the Executive Director for Operations (1pp 18499 231 24X Fiche 50-000, 83/03/09, 2008-18000) 8305180001
- --8305180337 Discusses importance of NASLAP decision re protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants THOMPSON, D Enforcemen allegers or informants
 THOMPSON, D. Enforcement & Investigation Staff (Pre 820201)
 81/05/14 GRIER, D. H. Region 1, Philadelphia, Office of the
 Director (81/03/01) D'(REILLY, J. P. Region 2, Atlanta, Office of
 the Director (81/03/01) KEPPLER, J. G. Region 3, Chicago, Office
 of the Director (81/03/01) ip 18499 244 24X
 Fiche 50-000,83/03/09,8305180001
- 8303090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode Svc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York. Inc 16pp 18627 133 24X Fiche S0-000.83/05/09.8305090659
- B3053i0177 Forwards licensing review schedule Submittal of first comprehensive update of FSAR scheduled for B30701 Review of updated issues requested GDLDBERGJ H Houston Lighting & Power Co B3/05/17 EISENHU requested
 Houston Lighting & Power Co 83/05/17 EISENHUT, D @
 icensing 6pp 18659 037 24X Fiche 50-498, 83/05/17, Division of Licensing Spp 8305310177

F Security, medical, emergency & Fire protection plans

- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits SVc list ench EISENHUT, D @ Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 30-000, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1783 DIRCKS.W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18973 322 Fiche 50-000, 83/05/13, 8305240213

6 Adjudicatory correspondence

- B305020434 Motion to compel Citizens Concerned About Nuclear Power answers to applicant B30328 seventh set of interrogatories & requests for production of documents No response received Certificate of Svc encl
 NEWMAN.J R Joint Apolicants-South Texas Project NEWMAN.J R
 Lowenstein, Newman, Reis, Azelrad & Toil B3/04/27 Atomic B. and Licensing Board Panel Spp 18281 213 24X
 Fiche 50-498.83/04/27.8305020434 Atomic Bafety
- 8305060479 Response to State of TX atty general 830421 request for extension of discovery schedule for 90 days Applicants do not object to extension for TX but object to extension for other parties Centificate of Svc encl
 NEWMAN.J R Joint Applicants—South Texas Project 83/05/03
 Atomic Safety and Licensing Board Panel 4pp 18348 108 24X
 Fiche 50-498,83/05/03,8305060499

- 8305060274 Order extending time until 830523 for Commission to act to review 630303 Director's decision CHILK-5 J Office of the Secretary of the Commission 83/05/05 Commissioners ip 18345 023 24X Fiche 50-496.83/05/05.83
- 8305110225 Response in opposition to Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension of deadlines until 830617 CCANP has failed to show good cause for requested deferrals W/Certrificate of Svc NEWHAN, J R Houston Lighting & Power Co NEWHAN, J R Lowenstein, Newman, Reis, Azeirad & Toll 83/05/05 Atomic Safety and Licensing Board Panel 8pp 18407 068 24X Fichs 50-498,83/05/05,8305110225
- 8305090143 Response opposing Atty General of TX 830421 motion for 90-day extension of discovery until 830725 State of TX failed to take full advantage of available discovery period Cartificate of 8vc encl PERLIB.R 0 Rearing Branch 3 83/05/06 Atomic Safety and Licensing Board Panel 3pp 18364 044 24X Fiche 50-498.83/05/06.8305090143
- B305110339 Response opposing Citizens Concerned About Nuclear Power (CCANP) B30420 motion for deferral of rulings & extension until B30617 Time to reply to applicant interrogatories may be extended until B30522 Certificate of Svc encl PERLIS.R 9 Hearing Branch 3 B3/05/10 Atomic Safety and Licensing Board Panel Opp 18406 148 24X Fiche 50-498.83/05/10.8305110339
- 8305200511 Memorandum & order granting Atty General of State of TX B30421 motion for extension of discovery deadline until 90 days from syc of order Effective participation by State in resolution of Guadrex Rept issues werents add time. BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/05/18 Texas, State of 5pp 18516 103 24X Fiche 50-478,83/05/18.8305200511
- 8305260176 Order extending time until 803530 for Commission to act to review 830303 Director's decision CHILK:8 J Office of the Secretary of the Commission. B3/05/23 Commissioners ip 18599 271 24X Fiche 50-498.83/05/23.
- 8305310015 Order extending time until 830606 for Commission to act to review 830303 Director's decision CHILK:6 J Office of the Secretary of the Commission 83/05/27 Commissioners 1p 18653 220 24X Fiche 50-498.83/05/27.8305310015
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8305250056 Forwards Amend 31 to FBAR Amend relects changes to HVAC design OOLDBERG.J H Houston Lighting & Power Co 83/05/20 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 18571 168 24X Flche 50-498,83/05/20
- --B305250058 Amend 31 to FSAR GOLDBERG, J H Houston Lighting & Pawer Co 83/05/20, 221pp 18591 171 24X Fiche 50-478,83/05/20,8305250056
- G Inspection reports, IE Bulletins & correspondence
- 8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Taxas project Forwards App B documents Documents also available in PDR Addl documents undergoing review FELTON. J M Division of Rules and Records 83/03/09 LINDEMAN, H N Lowenstein. Neuman, Reis, Azeirad & Toll 6pp 18497-219 24X Fiche: 50-000, 83/03/09, 8305180001
- --7908080036 Forwards matl re allegations of harassment & intimidation per 790524 request
 THOMPSON: D Executive Officer for Operations Support, 79/06/12
 FORTUNA: R A Office of Inspector & Auditor 8pp, 18499 196 24X
 Fiche 50-000:83/03/09:8305180001

- --8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is awaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing

 STELLO.V Office of Inspection & Enforcement, Diffice of the Director 80/04/11 AHEARNE, J. GILINBKY, V. KENNEDY, R. Commissioners 175pp 18498 304 24X Fiche 50-000,83/03/09,8305180001
- ---8006090238 Responds to 800421 request that IE interview former site GC inspectors Of 69 persons identified 23 contacted STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/13 BRADFORD, P A Commissioners 3pp 18499 149 24X fiche 50-000.83/03/09.8305180001
- --B006090440 Responds to 791010 memo re enforcement action against Brown & Root Enforcement peckage complete No enforcement action taken previously since earlier insps did not substantiate allegations

 STELLO,V. Office of Inspection & Enforcement, Office of the Director, B0/05/15 BRADFORD,P A Commissioners 2pp. 18499 150 24X Fiche 50-000 83/03/09.8305180001
- --B009120352 Advises that Region 4 should assume responsibility for review & verification of corrective actions by licensee as followup action associated w/Bouth Texas problems Headquarters will be responsible for monitoring reviews. THORNBURGH D Division of Reactor Construction Inspection 80/06/24 SEYFRIT.K V Region 4. Dallas. Office of the Director 3pp 18499 219. 24X Ficher 50-000.83/03/09.8305180001.
- --8103250385 Summarizes events re 810317 telcon w/L Sinkin concerning allegations at facility improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged WILBER.H A Reactor Projects Sections (Regions 2, 4 & 5), 81/03/17 SEYFRIT.K.V Region 4, Dallas, Office of the Director, 2pp 18497 242 24X Fiche 50-000,83/03/09,8305180001
- --B305180064 Responds to Cossick request to reply to inquiry re adequary of GA/GC program Licensee continuing to look for add1 voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners

 BTELLO,V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY.R T, Commissioners 3pp 18477:234 24X Fiche. 50-000. B3/03/09. B305180001
- --8305180075 Responds to Commissioner Bradford 791017 inquiry re newspaper article concerning facility insps "Burprise insp" announced IE insp of facility OA program Allegations re beating of GC inspector could not be substantiated HUBACEK.W G Region 4, Dallas, Office of the Director 79/10/26 REINWITH, G W Division of Reactor Construction Inspection, 2pp, 18497 239 24X Fiche 50-000,83/03/09,8305180001
- --83051800B3 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barber/Thompson REINMUTH. 2 M Division of Reactor Construction Inspection. 79/11/02 SEIDLE-M.C Region 4. Dallass Reactor Construction & Engineering Support Branch 2pp 18497 241. 24X Fichs 50-000,83/03/09.8305180001
- --B305180094 Discusses recommendations for further IE investigation & insp efforts at facilities Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established Related info encl HAYES, D W Region 3, Chicago, Office of the Director 80/03/11, THORNBURG, H D. Division of Reactor Construction Inspection 4219p 18497 243 24X Fiche 50-000/83/03/09,8305180001.
- --B305180157 Forwards enforcement package including enforcement notice, draft press release, forwarding ltr, notice of violation, proposed imposition of civil penalty & show cause order, W/o encis STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/04/28 AHEARNE, J. F., OILINSKY, V., KENNEDY, R. T. Commissioners ip 18499 143 24X Fiche. 30-000, 83/03/09, 8305180001.
- --8305180167 Informs that Commission concensus not in favor of recommendations contained in 800418 memo re facility investigation. Modified version of Suggestion i further modified by Commissioner Kennedy Responses encl. W/o encls. CHILK, B J Office of the Secretary of the Commission. 80/04/28. BRADFORD, P.A. Commissioners. Ip 18499 144, 24X Fiche 50-000,83/03/09,8305180001
- --B303180175 Recommends that IE address Ofc of General Counsel Questions 1-7 prior to enforcement action IE will take action on 800901 BRADFORD, P.A. Commissioners 80/04/30, AHEARNE, J. F. Commissioners 1p 18499; 145 24X Fiche: 50-000, 83/03/09, 8305180001.

- --8305180181 Discusses results of followup inquires by Region IV re terminated Brown & Root, Inc GC civil engineer inspectors SEYFRIT, K V Region 4, Dailas, Office of the Director 80/04/30 DEYQUNG, R C Office of Inspection & Enforcement, Office of the Director 2pp 18499 146 24X Fiche 50-000, 83/03/09, 8305180001
- --8305180189 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Guestions 1-7 prior to time of enforcement action CHILK:S J Office of the Secretary of the Commission B0/05/02 BRADFORD, P A Commissioners ip 18499 148 24X Fichs 50-000,83/03/09,8305180001
- --8305180202 Informs of new allegations concerning possible intimidation of GC inspectors received while preparing response to 791010 memo Investigation will be conducted to verify facts Appropriate enforcement action will be taken STELLO, V Office of Inspection & Enforcement, Office of the Director 83/03/09 RRADFORD, P A Commissioners ip 18499 132 24X Fichs 50-000,83/03/09,8305180001
- ---8305180211 Responds to 791010 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of elleged beating of Brown & Root GC inspector Allegation could not be substantiated STELLO.V Office of Inspection & Enforcement, Office of the Director 83/03/07 BRADFORD.P A Commissioners 2pp 18499 153 24% Fiche 50-000,83/03/09,83051800001
- --8305180276 Forwards draft Commission info paper intended for presentation during wk of 800414 re investigation & proposed enforcement action Comments needed by 800409 THORNBURG.H D Division of Reactor Construction Inspection 80/04/03 DENTON.H R Office of Nuclear Reactor Regulation. Director BHAPAR.H K Office of the Executive Legal Director STELLO.V Office of Inspection & Enforcement. Office of the Director 11pp 18479 204 24X Fiche 50-000.83/03/09.8305180001
- B212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post
- TAYLOR,J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308.319. 24X Fiche 50-000.83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JURJOAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 135 24X Fiche 50-000.83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BMR Bafety/Relief Valve Failures " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). B3/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, B3/04/22, B303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing Bys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/04/25 Consolidated Edison Co of New York
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Cenerators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83704/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Traetment Sys Heater High Tamp Trip Setpoint Adjustment" Syc list encl. JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidate Edison Co of New York, Inc 1882 165 24X Fiche 50-000.83/04/28,8303040027.
- B303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl URDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/03 Consolidated Edison Co of New York: Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Ficher 50-000, 83/05/04, 8303040030.
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

- 8309170212 Forwards IE Insp Repts 50-498/83-06 & 50-497/83-06 during Mar 1983 No noncompliance noted MADSEN/G L Region 4, Office of Director 83/05/04 OPREA, G W Houston Lighting & Power Co 2pp 18467 001 24X Fiche 50-498, 83/05/04, 8305170212
- --B305170224 IE Insp Repts 30-498/83-06 & 50-499/83-06 during Mar 1983
 No noncompliance noted Major areas inspected storage &
 maint of equipment. IE bulletins & notices.const deficiency
 repts.electrical sys.structural concrete & GA/GC procedures
 HILL.W H . CROBSMAN.W A Region 4, Office of Director 83/05/03
 18pp 18467 003 24% Fiche 50-498.83/05/04.8305170212
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 63/05/11 Consolidate Edison Co of New York, Inc 114pp 19524 003 24X Fiche 50-000.B3/05/11.B303040034
- 8303040040 IE Info Notice 83-3i, "Error in ADLPIPE Computer Program "
 Byc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 30-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24% Fiche 50-000.83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 83D5180001 Add] response to FOIA request for seven categories of documents re Brown & Root. Inc & South Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON.J M Division of Rules and Records 83/03/09 LINDEMAN.H N
 Lowenstein, Neuman, Reis, Axelrad & Toll App 18497 219 24X
 Fiche 50-000.83/03/09.8305180001
- --7909180214 Requests visus re adequacy of GA/GC program in light of PNO-79-179, "Voids in Reactor Containment Wall" (NENNEDY, R. T. Commissioners 79/06/25 GOBSICK, L. V. Office of the Executive Director for Operations of 18497 233 24X Fiche 50-000,83/03/09,8305180001
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHE.E P Westinghouse Electric Corp B3/04/21 DEYOUNG.R C Director's Dffice, Dffice of Inspection and Enforcement 5pp 18405 095 R4X Fiche 50-000.83/04/21.8305110427
- 8305060436 Final deficiency rept re incorrect motor operator weights used in stress analyses of valves supplied by Anchor Darling Valve Co.Initially reported on 820629 Stress analysis for valve MS-143 will be reperformed using actual weight OPREA: 0 W Houston Lighting & Power Co 83/04/27 COLLING.J T. Repion 4. OPFice of Director 4pp 18351:156 24X Fichs 50-498,83/04/27,8305060456
- 8305170510 Sixth interim deficiency rept re nonconforming welds in vendor fabricated Category I structural steel Initially reported on 81010B Review & evaluation program in progress Next rept will be submitted by Sept 1983 OPREA:0 W Houston Lighting & Power Co 83/05/10 COLLING, J T Region 4. Office of Director 3pp 18470 015 24X Fiche; 30-498. 83/05/10, 8305170310
- B305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on B30513 Bolting parts greater than 2-inch size not examined MOVI.t. NPB Industries, Inc. B3/05/16 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement ip 18574 001 24X Fiche 50-000,83/05/16,8305240356
- B305230416 Interim deficiency rept re voltage regulation problem for large motors on 480-volt Class IE load ctrs Initially reported on B30419. Bechtel evaluating corrective actions. Next rept will be submitted by 830530 OPREA: Q W Houston Lighting & Power Co 83/05/18 COLLING, J T Region 4. OPfice of Director 3pp 18538, 232 24X Fichs: 50-498, 83/05/18, 8305230416

- 8305230523 Final deficiency rept re Westinghouse reactor trip suitchgear undervoltage attachments w/design discrepancy Initially reported on 830422 Attachments replaced Mfg drawings & GC procedures modified Also reported per Part 21 OPREA. G W Houston Lighting & Power Co 83/05/18 COLLING, J T Region 4. Office of Director 4pp 18536 319 24X Fiche 50-498,83/05/18,8305230525
- T Hearing transcripts on non-antitrust matters
- B305180001 Add1 response to FOIA request for seven categories of dacuments of Brown & Root Inc & South Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON, J M Division of Rules and Records B3/03/09 LINDEMAN, H N
 Lowenstein. Newman, Reis. Axelrad & Toll 6pp 18497 219 24X
 Fiche 50-000,83/03/09,8303180001
- ---8305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5 AMEARNE: J F Commissioners 80/07/29 6pp 18499 171 24X Fiche 50-000,83/03/09.8305180001
- --8305180257 Statement of V Stello before House Subcommittee on Oversight & Investigations 800729 hearing Pp 1-15
 SIELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 18499 177 24X Fiche-50-000,83/03/09,8305180001

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

- A Application/construction stage documents & correspondence
- 8303180001 Addi response to FDIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards
 App B documents Documents also available in FDR Add1
 documents Undergoing review
 FELTON.J M Division of Rules and Records 83/03/09 LINDEMAN.H N
 Lowenstein, Newman, Reis, Axelrad & Toll App 18497; 219 24X
 Fiche 50-000,83/03/09.8305180001
- --B00514027& Responds to B00418 memo re concrete voiding Discusses status of problems & repairs

 BTELLO.V Dffice of Inspection & Enforcement, Office of the Director B0/04/25 BRADFORD, P.A. Commissioners 3pp 18497 139 24X Fiche 50-000.83/03/09.8305180001
- --8006090443 Forwards WA Post article re harassment of GC personnel Lack of enforcement action questioned BRADFGRD.P A Commissioners 79/10/10 STELLO.V Office of Inspection & Enforcement, Office of the Director 2pp 18497 237 24X Fiche 50-000.83/03/09.8303180001
- --BOOB120773 Forwards outlines of JF Ahearne & V Stallo proposed testimony re facility before House Subcommittee on Oversight & Investigation STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/11 AHEARNE, J F. OILINSKY, V , HENDRIE, J Commissioners 6pp 18497 163 24X Fiche 50-000, 83/03/09, 8305180001
- --8010090450 Forwards draft Commission info paper re plan for resumption of const Comments or concurrences needed by 800912 M/o encl THORNBURG, H D Division of Reactor Construction Inspection. 80/09711 DENION, H R Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director STELLD, V Office of Inspection & Enforcement, Office of the Director 9pp 18499 222 24X Fishe 50-000, 83/03/09, 8305180001
- --8010280578 Responds to Question 4 of 800923 mamo re Eckhardt hearing Kajor Brown & Root Copp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AMS Code STELLO.V Office of Inspection & Enforcement. Office of the Director 80/09/25 AHEARNE, J F Commissioners, 5pp. 18497.228 24X Fiche 50-000.83/03/09.8305180001
- --80102805B: Assigns questions resulting from 800923 Eckhardt hearing AMEARNE.JF Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193 24X Fiche 50-000:83/03/09:8305180001.
- --8305180121 Requests info re scope & significance of voids in concrete at site Response requested by 800423 BRADFORD, P A Commissioners. 80/04/18 DIRCKS, W J Office of the Executive Director for Operations ip 18499 138 24X Fiche 50-000,83/03/09.8305180001

- --8305180148 Advises that staff should notify Commission in advance of proposed actions are facility investigation.per Commissioner Bradford 800418 memo
 CHILK.S J Office of the Secretary of the Commission 80/04/28
 DIRCKS J Office of the Executive Director for Operations. 19
 18499 142 24X Fiche 50-000.83/03/09.8305180001
- --B305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility KAMMERIER. C. Office of Congressional Affairs B0/07/09 AMERINE, J F. O'LLINEKY, V. HENDRIE, J M. Commissioners 2pp 18499 157 24X Fiche 50-000, 83/03/09, 8305180001
- --B305180836 Submits schedule of Congressional hearings re waste bill H R 7418. West Valley Bill H R 6865 & South Texas project Related info ancl REHM.T A Office of the Executive Director for Operations 80/07/07 STELLO,V Office of Inspection & Enforcement Office of the Director DAVIS.J Office of Nuclear Material Safety & Safeguards, Director 4pp 18479 197 24X Fichs 50-000.83/03/09.
- ~-8305180250 Forwards Chairman Ahearne & V Stello testimony prepared for House Subcommittee on Oversight & Investigation hearing refacility STELLO.V Office of Inspection & Enforcement, Office of the Director 80/07/25 AHEARNE, J F , OILINSKY, V , HENDRIE, J M Commissioners 2pp 18499 169 24X Fiche 30-000, 83/03/09, 8305180001
- --8305180315 Forwards Part 2 of Commission regulations re practice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl BURNS,8 9 Office of the Executive Legal Director 80/05/29 CORTEZ,8 Communities Organized for Public Service 1p 18499 218 24X Fiche 50-000,83/03/09.8305180001
- --8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickwit, general counse).

 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS, W J. Office of the Executive Director for Operations 11pp. 18497 231 24X Fiche 50-000, 83/03/09, 8305180001
- --B305180337 Discusses importance of NASLAP decision re-protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants

 THOMPSON.D Enforcement & Investigation Staff (Pre 820201)

 S1/05/14 GRIER.B H. Region I, Philadelphia: Office of the Director (81/03/01) O'REILLY, J.P. Region 2, Atlanta. Office of the Director (01/03/01) KEPPLÉR, J.Q. Region 3, Chicago, Office of the Director (81/03/01) ip 18499-244 24X

 Fiche 50-000, B3/03/09, B3051800001
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT.D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627-153 24X Fiche 50-000.83/05/09.6305090659
- B305310177 Forwards licensing review schedule Submittal of first comprehensive update of FSAR scheduled for B30701. Review of updated issues requested.
 OULDBERG.J H Houston Lighting & Power Co B3/05/17. EISENHUT. D. 0
 Division of Licensing opp 18659 037. 24X Fiche 50-498.83/05/17.
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors: applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, Svc list encl
 EISENNUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095. 24X
 Fichs 50-000.83/05/11.8303110034
- Q Adjudicatory correspondence
- 8305020434 Motion to compel Citizens Concerned About Nuclear Power answers to applicant 830328 seventh set of interrogatories & requests for production of documents No response received. Certificate of 8vc encl.

 NEHMAN, J R Joint Applicants-South Texas Project NEHMAN, J.R Lowenstein, Newman, Reis, Axelrad & Toll, 83/04/27 Atomic Safety and Licensing Board Panel 5pp 18281:213 24x

 Fiche: 50-498,83/04/27,8305020434

- 8305060499 Response to State of TX atty general 830421 request for extension of discovery schedule for 70 days Applicants do not object to extension for TX but object to extension for not better parties Certificate of Svc encl NEWHAN, J R Joint Applicants-South Texas Project 83/05/03 Atomic Bafety and Licensing Board Panel 4pp 18348 108 24X Fiche 50-498,83/05/03.8305060499
- 8305060274 Order extending time until 830523 for Commission to act to review 830303 Director's decision CHILK.8 J Office of the Secretary of the Commission 83/05/05 Commissioners ip 18345 023 24X Fiche 50~498.83/05/05, 8305060274
- 8305:10225 Response in opposition to Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension of deadlines until 8306/17 CCANP has failed to show good cause for requested deferrals W/Certificate of Svc NEWMAN, JR Houston Lighting & Power Co NEWMAN, JR Lowenstein, Newman, Reis, Azelrad & Toll 83/05/05 Atomic Safety and Licansing Board Panel 8pp 18407 068 24X Fiche 50-498.83/05/05, 8305110225
- 8305090143 Response opposing Atty General of TX B30421 motion for 90-day extension of discovery until 830725 Stats of TX failed to take full advantage of available discovery period Certificate of Svc encl PERLIS, R G Hearing Branch 3 83/05/06 Atomic Safety and Licensing Board Panel 5pp 18364 044 24X Fiche 50-498,83/05/06,8308590143
- 830511033? Response opposing Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension until 830617 Time to reply to applicant interrogatories may be extended until 830522 Centificate of Svc enci PERLIB.R 9 Hearing Branch 3 83/05/10 Atomic Safety and Licensing Board Panel 6pp 18406 148 24% Fiche 50-498,83/05/10,8305110339.
- 8305130045 Memorandum & order ruling on Citizens Concerned About Nuclear Power 830420 motions Extensions granted until 830531 to respond to various filings BECHMOEFER.C Atomic Bafety and Licensing Board Panel 83/03/11 Citizens Concerned About Nuclear Power, Inc. 4pp 18436:335 24X Fiche 50-478.83/05/11.8305130045
- 8303200511 Memorandum & order granting Atty General of State of TX 830421 motion for extension of discovery deadline until 90 days from eve of order Effective participation by State in resolution of Guadres Rept issues warrants addl time BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/05/18 Texas, State of Spp 18316-103 24X Fiche 50-498,83/05/18,8305200511
- B305260176 Order extending time until B03930 for Commission to act to review B30903 Director's decision CHILK 8 J Office of the Secretary of the Commission B3/05/23 Commissioners. 1p. 18599-271 24X Fiche 50-498,83/05/23
- B305310015 Order extending time until B30606 for Commission to act to review B30303 Director's decision CHILK: 5 J Office of the Sacretary of the Commission B3/05/27 Commissioners ip 18653 220 24X Fiche. 50-498, 83/05/27, B305310015
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8305250056 Forwards Amend 31 to FSAR Amend relects changes to HVAC design OCLOBERG, J H Houston Lighting & Pawer Co 83/05/20 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 18591 168 24X Fiche 50-498,83/05/20,8305250056
- --8305250038 Amend 31 to FSAR
 GOLDBERG, J H Houston Lighting & Power Co 83/05/20. 221pp,
 18591 171 24X Fiche 50-498,83/05/20,8305250056
- G Inspection reports, IE Bulletins & correspondence
- B305180001 Add1 response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project, Forwards App B documents Documents also available in PDR Add1 documents undergoing review, FELTON.J M. Division of Rules and Records B3/03/09 LINDEMAN, H N Lowenstein. Newman, Reis, Axelrad & Toll 6pp 18497:219, 24X Fiche 30-000,83/03/09,8305180001

- --7908080036 Forwards matl re allegations of harassment & intimidation per 790824 request
 THOMPSON D Executive Officer for Operations Support 79/06/12
 FORTUNA: R A Defice of Inspector & Auditor Spp 18499 196 24X
 Fiche 50-000.83/03/09.8303180001
- --8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is awaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing STELLO.V Office of Inspection & Enforcement, Office of the Director 90/04/11 AHEARNEL J. (ILINSKY.V , KENNEDY.R Commissioners 175pp 18478 304 24X Fiche 30-000.83/03/09, 83053100001
- --8006090238 Responds to B00421 request that IE Interview former site QC inspectors Of 69 persons identified 23 contacted STELLO.V Defice of Inspection & Enforcement Office of the Director 80/05/13 BRADFORD, P A Commissioners 3pp 18499 149 24x Fiche 50-000.83/03/09.8305180001
- --8006090440 Responds to 771010 memo re enforcement action against Brown & Root Enforcement package complete No enforcement action taken previously since earlier inspection not substantiate allegations

 STELLO: V Office of Inspection & Enforcement, Office of the Director 80/05/15, URADFORD, P A Commissioners 200 18479 155 24X Fiche 50-000, 83/03/09, 83051800001
- --Bi032503B5 Bummarizes events re Bi0317 telcon w/t. Sinkin concerning allegations at facility Improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged WILBER.H A Reactor Projects Sections (Regions 2,4 & 5) Bi/03/17 SEYFRIT,K V Region 4, Dallas, Office of the Director 2pp 18499 242 24X Ficha 50-000,83/03/09,8305180001
- --8305180064 Responds to Gossick request to reply to inquiry re adequacy of GA/GC program Licensee continuing to look for addl voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners

 STELLO, V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY, R Y Commissioners 3pp 18497 234 24X Fiche 30-000,83/03/09,8305180001
- --8305180075 Responds to Commissioner Bradford 791019 inquiry re newspaper article concerning facility (nsps "Surprise Insp" announced IE insp of facility (Aprogram Allegations re beating of GC inspector could not be substantiated HUBACEK.W G Region 4. Dallas. Office of the Director 79/10/26 REINMUTH.G N Division of Reactor Construction Inspection 2pp 18497 239. 24x Fiche 50-000,82/03/09,8305180001
- --8303180083 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barber/Thompson REINKUTH-G W Division of Reactor Construction Inspection 79/11/02 SEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 2pp 18497 241 24X Fichs 50-000,83/03/09,8305180001
- ---8305180074 Discusses recommendations for further IE investigation & insp efforts at facilities. Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established Related info encl MAYES. D W Region 3. Chicago. Office of the Director BO/O3/1; THORNINGR, H D Division of Reactor Construction Inspection 421pp 18497 243 24% Fiche 30-000.83/03/09.8305180001
- ---B305180157 Forwards enforcement package including enforcement notice, draft press release, forwarding ltr.notice of violation, proposed imposition of civil penalty & show cause order W/o encls
 STELLO.V Office of Inspection & Enforcement, Office of the Director B0/04/28 AHEARNE,J.F., OILINSKY,V., KENNEDY,R.T. Commissioners ip 18499-143 24X Fiche 50-000, 83/03/09, 8305180001
- --8305180167 Informs that Commission concensus not in favor of recommendations contained in 800418 memo re facility investigation Modified version of Suggestion I further modified by Commissioner Kennedy Responses encl W/o encls CHILK.S J Office of the Secretary of the Commission 80/04/28 BRADFORD.P A Commissioners Ip 18499 144 24X Fiche 50-000,83/03/09,8305180001
- --B305180175 Recommends that IE address Dfc of General Counsel Guestions 1-7 prior to enforcement action IE will take action on 803501 BRADFORD.F.A Commissioners 80/04/30 AHEARNE, J F Commissioners ip 18499 143 24X Fiche 50-000.83/03/09, 8305180001

- --8305180181 Discusses results of followup inquires by Region 1V re terminated Brown & Root, Inc QC civil engineer inspectors SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/30 DEYOUNG, R C Office of Inspection & Enforcement, Office of the Director 2pp 18499 146 24X Fiche 50-000.83/03/09.8305180001
- --B305180187 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Questions 1-7 prior to time of enforcement action CHILK, S J Office of the Secretary of the Commission B0/05/02 BRADFORD, P A Commissioners ip 18499, 148 24X Fishe 50-000, 83/03/09, 8305180001
- --8305180202 Informs of new allegations concerning possible intimidation of GC inspectors received while preparing response to 791010 memo Investigation will be conducted to verify facts Appropriate enforcement action will be taken STELLO,V Office of Inspection & Enforcement, Office of the Director 83/03/09 RRADFORD,F A Commissioners ip 18499 152 24X Fiche 5Q-000.83/03/09.83051800001
- --8305i802i1 Responds to 7910i0 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of alleged beating of Brown & Root GC inspector Allegation could not be substantiated STELLO,V Office of Inspection & Enforcement, Office of the Director 83/03/09 RRADFORD.P A Commissioners 2pg 18499 153 24X Fiche, 50-000.83/03/09.8305180001
- --B305180275 Forwards draft Commission info paper intended for presentation during wk of B00414 re investigation & proposed enforcement action Comments needed by B00409 THORNOURG, H D Division of Reactor Construction Inspection B0/04/03 DENTON.H R Office of Nuclear Reactor Regulation, Director BHAPAR, H K Office of the Executive Legal Director STELLO, V Office of Inspection & Enforcement, Diffice of the Director 11pp 18497 204, 24X Fiche 50-000, E3/03/09, B305180001
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction." Svc list enci TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co. of New York, Inc. 112pp 18308 319 24% Ficher 50-000,83/03/21,8212040385
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155 24X Fiche 50-D00,83/04/15,8303040021.
- 8303040023 [E Info Notice 83-22, "BHR Safety/Relief Valve Failures "
 Svc list end)
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
 York, Inc 112pp 18383.089 24X Fiche 50-000, 83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list enci JORDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Go of New York: Inc. 119pp 18381 291 24X Fiche 30-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list enc: JORDAN/E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standay Cas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list enci JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Int 118pp 18382 165 24X Fiche 50-000, 83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Faiture of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.

 JORDAN/E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282, 24X Fiche.50-000,83/05/04,8303040030.
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

- 8305170212 Forwards IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1983 No noncompliance noted MADSEN,0 L. Region 4, Office of Director 83/05/04 OPREA,0,W Houston Lighting & Power Co 2pp 18467 001 24X Fichs 50-498,83/05/04.8305170212
- --8305170224 IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1783
 No noncompliance noted Major areas inspected storage &
 maint of equipment IE bullatins & notices, const deficiency
 repts, electrical sys. structural concrete & GA/GC procedures.
 HILL,W H . CROSSMAN,W A Region 4, Office of Director 83/05/03
 18pp 18467 003 24X Fiche 50-498,83/05/04.8305170212
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation" Svc list enc!

 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fichs 50-000.83/05/11,8303040034
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program" Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000, B3/05/19, B303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305110427 Pert 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Hfg drawings revised RAHE, E.P. Wastinghouse Electric Corp. 83/04/21 DEYOUNO, R.C., Director's Dffice, Uffice of Inspection and Enforcement 5pp 18405:095 24X Fichs. 50-000, 83/04/21, 8305110427
- 8305060436 Final deficiency rept re incorrect motor operator weights used in stress analyses of valves supplied by Anchor Darling Valve Co Initially reported on 820629 Stress analysis for valve MB-143 will be reperformed using actual weight OPREA.6 W Houston Lighting & Power Co. 83/04/27 COLLINS, J. T. Region 4. Dffice of Director App 18351 156 24X Fiche 30-498,83/04/27,8305060456
- 8303170510 Sixth interim deficiency rept re nonconforming welds in vendor fabricated Category I structural steel. Initially reported on Bi0108 Review & evaluation program in progress Next rept will be submitted by Sept 1983 OPREA.9 W Houston Lighting & Power Co B3/05/10 COLLINS.J T Region 4. Office of Director 3pp 18470 015 24X Fiche 50-498,83/05/10,8305170510.
- 8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513. Bolting parts greater than 2-inch size not examined.

 HOVI, L NPS Industries, Inc 83/05/16 DEYGUNG, R. C. Director's Office, Office of Inspaction and Enforcement 1p 18574:001, 24X Fichs 50-000,83/05/16.8305240356
- 8305230416 Interim deficiency rapt re voltage regulation problem for large motors on 480-volt Class IE load ctrs initially reported on 830419, Bechtel evaluating corrective actions Next rapt will be submitted by 830650 OPREA:0 W. Houston Lighting & Power Co 83/05/18 COLLINS, J. T. Region 4, Office of Director. 3pp 18538 232 24X Fiche 50-498,83/05/18,8305230416.
- 8305230525 Final deficiency rapt re Westinghouse reactor trip suitchgear Undervoltage attachments w/design discrepancy initially reported on B30422 Attachments replaced. Mfg drawings & GC procedures modified Also reported per Part 21. OPREALQ W Houston Lighting & Power Ca 83/05/18 COLLINB, J T Region 4. Office of Director 4pp. 18536 319 24% Fiche. 50-498, 83/05/18, 8305230525.

- T Hearing transcripts on non-antitrust matters
- B305180001 Add1 response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON.J M Division of Rules and Records B3/03/09 LINDEMAN, H N
 Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
 Fiche 50-000, B3/03/09, B305180001
- --8305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5 AHEARNEL J F Commissioners 80/07/29 App 18499 171 24X Fiche 50-000,83/03/09,8305180001
- --8305180257 Statement of V Stello before House Subcommittee on Oversight & Investigations 800729 hearing Pp 1-15
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 18499 177 24X Fiche 50-000, 83/03/09, 8305180001
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE. J Regulatory Reform Task Force B3/04/11 PALLADING.N J. Commissioners 2pp 18542 272 24X Fiche: 50-000, B3/04/11, B305230720
- DOCKET 30-301 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J. Regulatory Reform Task Force 83/04/11 PALLADIND, N. J. Commissioners 2pp 18542 272 24X Fiche: 50-000, B3/04/11, 8305230720
- DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on beckfitting
 TCMRTELLOTTE.J Regulatory Reform Task Force 83/04/1)
 PALLADING,N J Commissioners 2pp 18542 272 24X
 Fichs 50-000.83/04/11.8305230720
- DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B305230720 Forwards list of utils responding to requests for cost figures on backfitting YOURTELLOTTE. J Regulatory Reform Task Force B3/04/11 PALLADING. N J Commissioners 2pp 1B542 272 24X Ficha 50-000.B3/04/11.B305230720
- DOCKET STN-50-508 HPPSB NUCLEAR PROJECT, UNIT 3

 A Application/construction stage documents & correspondence
- B305100097 Forwards responses to NRC acceptance review questions for Mar 1983, Marked-up FBAR pages which show changes to be included in subsequent emend also encl W/two oversize figures Aperture cards are available in PDR BOUCHEVO D Washington Public Power Supply System 83/04/20 KNIGHTON, 0 W Licensing Brench 3 App 18371 339 24X Fiche. 50-508, 83/04/20, 8305100097
- B3051i0018 Bummary of 830419 meeting w/util in Bethesda, MD rediscussion on program plan for control room design review HHEELER, L. Licensing Branch 3 B3/04/20 Licensing Branch 3 Bp. 18415 059 24% Fiche 50-508,83/04/20,8305110018
- 8305230155 Forwards second set of requests for add1 info re safety review Responses should be forwarded no later than 830712 Draft BER will be prepared to provide basis for series of meetings designed to close out open items, NOVAK-T M Assistant Director for Licensing 83/05/03 FERGUSON,R L Washington Public Power Supply System 42pp 18577-207 24X Fiche 50-508,83/05/03,8305230155

- 8305100304 Discusses responses to NRC 820625 & 0730 questions re usage of ITT Grinnell pipe clamps Response to 820914 questions delayed pending minor clamp mods & retesting program Meeting suggested to insure closure of issue BOUCHEY, G D Washington Public Power Supply System 83/05/05 KNIGHTON, G W Licensing Branch 3 2pp 18371 251 24X Fiche \$0-508.83/05/05,8305100304
- 8303090639 Generic Ltr 83-20 to all operating reactor licensees to holders of CPs re integrated scheduling for implementation of plant mode Svc list encl
 EISENHUT.D O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 133 24x
 Fiche \$0-000.63/05/09.8305070639
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8305230155 Forwards second set of requests for add1 info re safety review Responses should be forwarded no later than 830712 Draft SER will be prepared to provide basis for series of meetings designed to close out open items NOVAK. T M Assistant Director for Licensing 83/05/03 PERGUSON.R L Hashington Public Power Supply System 42pp 18577 207 24X Fiche 50-508.83/03/03.8309230135
- B305260205 Forwards request for add1 info re safety review Response requested by B30712 Draft SER will be prepared to close out open items NOVAK.T M Assistant Director for Licensing 83/05/11 FERGUSON.R L Hashington Public Pawer Supply System 17pp 18448 048 24X Fiche 50-508.83/05/11,8305260205
- F Security, medical, emergency & fire protection plans
- B305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENNUT, D 0 Division of Licensing B3/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 30-000.83/05/11.8305110034
- 8303240213 Forwards monthly status rept on offsite emergancy preparedness for OL reviews for Apr 1983 DIRCKS,W J. Office of the Executive Director for Operations 83/05/13 PALLADINO,N J. Commissioners 5pp 18593-322 24X Fiche 50-000.83/05/13.R308240212
- Q Adjudicatory correspondence
- 8305060491 Joint util.NRC & Coalition for Safe Power recommended schedula for submission of proposed contentions & subsequent responsive filings & for time & place for holding prehearing conference Certificate of Svc encl
 REVNOLDS, N S Washington Public Power Supply System REYNOLDS,N S Debevoise & Liberman 83/05/05 5pp 18348 144 24X Fiche 30-508,83/05/05,8305060491
- B305130110 Notice of ASLD reconstitution MB Margulies, chairman & FJ Bhon & JH Carpenter members
 COTYER, B P Atomic Safety and Licensing Board Panel B3/05/11
 2pp 18437 358 24% Fiche 50-508,83/05/11,8305130110
- 8305170483 Memorandum & order scheduling 830803-04 special prehearing conference in Montesano, WA Addl schedule dates listed MARGULIES, M B Atomic Bafety and Licensing Board Panel 83/05/16 2pp 18470 073 24K Piche 50-508,83/05/16,8305170483
- G Inspection reports: IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Constit
- 8305130116 Notification of 830523 significant licensee meeting w/util in Walnut Creek.CA to discuss licensee efforts to increase owner involvement in quality issues, actions taken to improve design control & status of sys completion # Region 5, Office of Director 83/04/05 Region 5, Office of Director 1p 18438 008 24X Fiche 30-508,83/04/05,8305130116

- --B3051703B7 Notice of deviation from inso on 830314-17 DDDDSR 7 Region 5. Office of Director 83/04/08 1 18469 218 24X Fisch 50-508,83/04/08,83031703B4
- --8309170390 lE Insp Rept 50-508/83-03 on 830314-17 Noncompliance noted failure to qualify weld procedure in accordance w/ANS D 1 1 requirements
 HAIST D P , BURDOIN, J F , DUDDS R T Region 5, Office of Director 83/04/07 8pp 18469 219 24% Fiche 50-508,83/04/08,8305170384
- 830304002: IE Info Notice 83-21. "Defective Emergency Use Respirator"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15 Consolidated Edison Co of New

 Vork, Inc 126pp 18435 155 24X Fiche 50~000.83/04/15,8303040021
- 8303040023 IE Info Notice 83-22. "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 087 24X Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing 98s" Svc list encl JORDAN,E L Pivision of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PHRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Cas Treatment Sys Heater High Temp Trip Betpoint Adjustment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 30-000,83/04/28,8303040027
- 8303040020 IE Info Notice 83-24. "Failure of Safety/Relief Valve Discharge Line Vacuum Breaters " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 93/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment "Suc list end! JÜRDANIE L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/03/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- B305170494 Forwards IE Insp Rept 50-508/83-05 on 830328-0427 No noncompliance noted STERNBERG,D M Region 5. Office of Director 83/05/04 LEDDICK.R S Washington Public Power Supply System to 18470 02: 24X Fiche 50-508.83/05/04.8305170494
- --B30517049B IE insp Rept 50-508/83-05 on 930328-0427 No noncompliance noted Major areas inspected const activities, including exam of welding for safety-related pipe supports & restraints & installation of core internals
 ALBERTIN O. DDDDS, R. T. Region S. Office of Director 83/05/04
 9pp 18470 024 24X Fiche 50-508.83/05/04,8305170494
- 8303040033 IE Info Notice 83-27. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOF) Guidelines " Svc list encl. JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103). B3/05/ii Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/i1,8303040034
- 8303040040 IE Info Notice 83-31; "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009. 24X Fiche 30-000.83/05/19.8303040040

- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24% Fiche 50-000.83/05/26,8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305160049 Supplemental final deficiency rept re safety injection tank seferend indications (D/N 23) Saferend-to-nozzle-welds for injection tanks reradiographed approved & accepted per spec & ASME Code requirements
 LEDDICKLR S Washington Public Power Supply System 83/04/06
 STERNBERG, D M Region 5, Office of Director 2pp 18453 130, 24X Fiche 30-308,83/04/06,8305160049
- 8305030487 Final deficiency rept re Rockbestos insulated cable Type
 D60-1 Initially reported on 821203 Dented cable to be
 reworked to restore cable to original specified thickness
 Deficiency determined not reportable under 100FR50, 55(e)
 LEDDICK.R B Washington Public Power Supply System 83/04/20
 SIERNBERG, D M Region 5. Office of Director 3pp 18274:147 24x
 Fiche 50-308,83/04/20,8305030489
- DOCKET 50-513 WPP88 NUCLEAR PROJECT, UNIT 4
- S Reportable occurrences, LERs & related correspondence
- 8305100094 PNB-V-83-006 on 830504, articls in Tri-City Herald erroneously quoted util spokesman J Britton as saying 1.700 or 1.800 craft workers will be asked to take varations during 830705-15 or be laid off Util will clarify MORTENBEN, P P, NORDERHAUO, L R Region 5, Office of Director. 83705/05 ip 18377 261 24% Fiche 50-513,63705/05,8305100094
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & firs protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list enc!
 EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095, 24X Fiche 50-000,83/05/11,8305110034
- P Operating license stage documents & correspondence
- 8305090659 Generic Ltr B3-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D 9 Division of Licensing 83/05/09 Consolidated Edison Co af New York, Inc 16pp 19627 153, 24X Fichs 50-000-83/05/09.8305090659
- @ Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Svc list encl
 TAYLOR.J M Division of Bafeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc.
 112pp 18308 319 24X Fiche 30-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator." Bvc list and JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consulidated Edison Co of New York, Inc. 126pp 18435 155, 24X Fiche 50-000.83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures."

 Bvc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24% Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119p 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040024 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Syc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28.8303040026

- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 1189p 18382 165 24X Fiche 50-000.83/04/28.8303040027
- B303040028 IE Info Notice B3-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co of New Yerk, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events
 Concerning Deliberate Acts Directed Against Plant
 Equipment " Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/04 Consolidated Edison Co of New
 York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- B30304003i IE Info Notice 83-2B, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JGRDANLE L Division of Emergency Preparedness & Engineering Response (Post B30103) B3705/04 Cansolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.B3705/04.B303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York
- B303040034 IE Info Notice B3-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 30-000, B3/05/11, B303040034
- 8303040040 IE Info Natice 83-31, "Error in ADLPIPE Computer Program"

 Byc 11st encl

 JORDAN,E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/05/17 Consolidated Edison Co of New

 York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B305090659 Owneric Ltr 83-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT, D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 159 24X Fiche, 50-000, 83/05/09, 8305090659
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 3vc list encl EISENHUT,D © Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18340 095. 24X Fiche 50-000,83/05/11,8305110034
- O Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list enc! TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000.83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." SVc list encl JORDAN/E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Syc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383-089 24X Fiche 50-000,83/04/22,8303040023.

- B303040025 IE Info Notice B3-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDJAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, B3/04/25, B303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28,8303040026
- 8303040027 IC Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list entl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 11299 18382 282 24X Fiche 50-000.83/05/04.8303040030
- B303040031 IE Info Notice B3-28, "Criteria for Protective Action Recommendations for General Emergencies" Byc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 30-000.B3/05/04.B303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc! JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06,8303040033
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EDP) Quidelines " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24% Fiche 50-000.83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Evc list encl
 JORDAN,E L Division of Emergency Preperedness & Engineering
 Response (Post 830103) 83/05/17 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- B3D3040046 IE Info Notice B3-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647-007 24X Fiche 30-000, B3/05/26, B303040046
- DOCKET BIN-50-518 HARISVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8305100189 Forwards "Details of Deferral Plans for Hartsville Nuclear Plant A " Yellow Creek plan submittal delayed until 830513 MILLS.L M Tennessee Valley Authority 83/05/05. DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18374, 294. 24% Fiche 50-518, 83/05/05, 8305100189
- --8303100193 "Details of Deferral Plans for Hartsville Nuclear Plant A "
 * Tennesses Valley Authority 83/05/31 9pp 18374 295 24X
 Fiche 50-518.83/05/05.8305100189
- G. Inspection reports. IE Bulletins & correspondence
- 8305270468 Forwards IE Insp Repts 50-518/83-01:50-519/83-01: 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted VERRELLI-D M Division of Project & Resident Programs 83/03/25. PARTIS:H 9. Tennessee Vailey Authority 2pp 18644 147 24X Fiche 50-518:83/03/25:8305270468
- --8305270496 IE Insp Repts 50-518/83-01.50-519/83-01.50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units) independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) & SCHAPKER.JF, CANTRELL.FS Region 2, Office of Director 83/03/24 5pp 18644-149 24X Fiche 50-518.83/03/25.8305270468

S Reportable occurrences, LERs & related correspondence

- 8305120372 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Inti Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.S F Niagara Mohauk Power Corp 83/04/26 STAROSTECKI.R Region 1. Office of Director 2pp 18433 072 24X Fiche 30-000.83/04/26.8305120372
- --8305120404 Part 2) rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp. 83/03/11 COLLINB.J T Region 4. Office of Director Spp. 18433 074 24X Fiche 50-000.83/04/28.8305120392

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

- G Inspection reports, IE Bulletins & correspondence
- 8305270448 Forwards IE Insp Repts 50-518/83-01.50-519/83-01. 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted VERRELLI.0 M Division of Project & Resident Programs 83/03/25 PARRIS.N C Tennesser Valley Authority 2pp 18644 147 24X Fiche 50-518.83/03/25.8305870468
- --8305270496 IE Insp Repts 50-518/83-01.30-519/83-01.50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units). Independent Insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER, J F. CANTRELL.FS Region 2. Office of Director. 83/03/24 Spp 18644 149 24% Fiche 50-518.83/03/25.8305270468
- S Reportable occurrences, LERs & related correspondence
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Intitally reported on 830928 Hatter under investigation Final rept by 830808 Reported per Part 21 MANNO, 6 F Niagara Mohawk Power Corp 83704/26 STAROSTECKI, R Region i, Office of Director 2pp 18433 072 24X Ficher 50-000,83704/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application. Plant operators notified of deviation

 EMPEY, D C Rockwell International Corp 83/03/11 CDLLINS, J T Region 4, Office of Director 5pp 18433 074 24X

 Fiche 50-000, 83/04/26, 8305120392

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

- A Application/construction stage documents & correspondence
- 8305100189 Forwards "Petails of Deferral Plans for Hartsville Nuclear Plant A " Yellow Creek plan submittal delayed until 830513 MILLS,L M Tennessee Valley Authority 83/05/05 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 18374 294. 24X Fiche 50-518,83/05/05,8305100189
- --8305100193 "Details of Deferral Plans for Hartsvills Nuclear Plant A "
 + Yennessee Valley Authority 83/05/31 9pp (8374 295, 24X Fiche 50-518,83/05/03,8305100189
- Q Inspection reports, IE Bulletins & correspondence
- 830527046B Forwards IE Insp Repts 50-518/83-01, 50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-83021B No noncompliance noted VERRELLIO M Division of Project & Resident Programs 83/03/25. PARRISH 0 Tennessee Valley Authority 2pp 18644-147, 24X Fiche 50-518,83/03/25,830327046B
- ---8305270496 IE Insp Repts 50-518/83-01, 50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units), independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER, J f . CANTRELL, F S Region 2. Office of Director 83/03/24 Spp 18644 149 24X Fiche: 50-518, 83/03/25, 8305270468

- 8 Reportable occurrences, LERs & related correspondence
- 8305120392 Interim deficiency rept re misapplication of ITE Could circuit breakers in post-LDCA hydrogen recombiners supplied by Rockwell Intl Initially reported on B30328 Matter under investigation Final rept by B30808 Reported per Part 21 MANNO.9 F Niagara Mohawk Power Corp B3/04/26 STAROSTECKI, R Region I. Office of Director 2pp 18433 072 24X Fiche 30-000,83/04/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOGA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83/03/11 COLLING, J T, Region 4. Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

- Q Inspection reports, IE Bulletins & correspondence
- 8305270468 Forwards IE Insp Repts 50-518/83-01, 50-519/83-01, 30-320/83-01 & 50-521/83-01 on 821120-830218 No nuncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/03/25 PARRIS, H 9 Tennesses Valley Authority 2pp 18644 147 24% Fiche 50-518,83/03/25,8305270468
- --8305270496 IE Insp Repts 50-518/83-01,50-519/83-01,50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units),independent insp effort (A-1 & A-2),& site deferral preparation (A-1 & A-2), SCHAPKER, J F Region 2, Office of Director 83/03/24 5pp. 18644 147 24X Fiche 50-518.63/03/25,8305270468
- S Reportable occurrences. LERs & related correspondence
- 8305120392 Interim deficiency rept re misapplication of ITE Qould circuit breakers in post-LOGA hydrogen recombiners supplied by Rockwell Intl. Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.5 F Niagara Mohawk Power Corp 83/04/26 BTAROSTECKI,R. Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000.83/04/26.8305120392
- ---B3D5120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C. Rockwell International Corp. B3/03/ii COLLINS.J.T. Rejion 4. OPfice of Director Spp. 18433 074 24X fiche 50-000,83/04/26.8305120392

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mode 8vc list encl.
 EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24% Ficher 50-000, 83/05/09, 8305090659
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for GLs & holders of GPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT, D 9 Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc. 16pp 18540 095 24X Fiche 30-000,83/05/11,8305110034
- 6 Adjudicatory correspondence
- 8303170272 Motion for summary disposition of Contention 1 recalculation of demand for electrical energy negeting need for plant, No genuine issue of matl fact exists
 GAVANAGH, R Natural Resources Defense Council CAVANAGH, R.
 Coalition for Safe Power CAVANAGH, R Columbia River Inter-Tribal Fish Commission 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 061. 24X Fiche: 50-522, 83/05/12, 8303170272

- 8305170279 Statement of matl facts as to which there is no genuine issue re Contention 1
 CAVANAGH.R Natural Resources Defense Council 83/05/12 Atomic Bafaty and Licensing Board Panel 2pp 18465 327 24X
 Fiche 50-522.83/05/12.8305170279
- B305170347 Memorandum of points & authorities supporting intervenor motion for summary disposition since Contention i no longer controversial issue Certificate of Svc encl CAVANAGH.R Natural Resources Defense Council B3/05/12 Atomic Safety and Licensing Board Panel 14pp 18469 008 24X Fiche 50-522.83/05/12.8305170347
- 8305170557 Affidavit of DB Goldstein supporting NRDC motion for summary disposition of Contention I re need for power Four forecasts for energy needs refute need for power justification developed by util Prof qualifications encl GOLDSTEIN.D B Natural Resources Defense Council 83/05/12 81pp 18468 040 24X Fiche 50-522,83/05/12,8305170557
- 6303310029 Requests current suspension of federal & state licensing proceedings continue until mid-Sept 1983 to consider licensing alternatives THOMSEN,F T Perkins, Coie, Stone, Olsen & Williams THOMSEN,F T Puget Sound Power & Light Co 83/05/25 WOLF, J.F., LEWIS, N.D. Atomic Safety and Licensing Board Panel 3pp 18653 127 24X Fiche 50-522,83/05/25,8303310029
- 8305310082 Request for extension until 830930 to answer NRDC motion for summary disposition of Contention i Time needed to consider implications of final northwest conservation electric power, plan & licensing alternatives Certificates of Syc encl THOMSEN.F T. Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie, Stone, Olsen & Williams 83/05/25 Atomic Safety and Licensing Board Panel Spp 18658 040 24% Fiche 50-522,83/05/25,8305310082

Q Inspection reports, IE Bulletins & correspondence

- 8212060385 IE Info Notice 83-14. "Dewatered Spent Ion Exchange Resin 8Usceptibility to Exothermic Chemical Reaction " Syc list enci TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Svc 11st encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc 126pp 18435 155 24X Fichs 50-000.83/04/15.8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 Svc list encl
 JDRDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8303040026 IE Info Notice 83-24. "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche. 50-000, 83/04/28, 8303040027,
- B303040028 IE Info Notice 83-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000.83/05/03.8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382,282 24X Fiche 50-000,83/05/04,8303040030

- 8303040031 IE Info Notice 83-28, "Critoria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl UDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York
- 8303040034 IE Info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl URDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- B303040040 IE Info Notice B3-3i, "Error in ADLPIPE Computer Program "
 Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50~000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040046

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

- 8305070659 Generic Ltr 83-20 to all operating reactor licensess & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D 9 Division of Licensing 83/05/09 Consolidate Edison Co of New York. Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305070659
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 30-000,83/05/11,8305110034

O Adjudicatory correspondence

- B305170272 Motion for summary disposition of Contention 1 recalculation of demand for electrical energy negating need for plant No genutne issue of matl fact erists
 CAVANAOH.R Natural Resources Defense Council CAVANAOH.R
 Caclition for Safe Power CAVANAOH.R Columbia River Inter-Tribal
 Fish Commission B3/05/12 Atomic Safety and Licensing Board
 Panel 2pp 18465 061 24X Fiche 30-522.B3/05/12.B305170272
- S305170279 Statement of matl facts as to which there is no genuine issue re Contention 1
 CAVANAGH, R Natural Resources Defense Council B3/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 327 24X
 Fiche 50-522,83/05/12,8305170279
- B305170347 Memorandum of points & authorities supporting intervenor motion for summary disposition since Contention i no longer controversial issue Certificate of Bvc encl CAVANAOH.R Natural Resources Defense Council B3/05/12 Atomic Bafety and Licensing Board Panel 14pp 18449 008 24X Fiche 50-522.83/05/12.8305170347
- B305170557 Affidavit of DB Goldstein supporting NRDC mation for summary disposition of Contention 1 re need for power Four foracasts for energy needs refute need for power gustification developed by util Prof qualifications encl GOLDSTEIN, D. B. Natural Resources Defense Council B3/05/12 Bipp 18469 040 244 Fichs 30-522:80705/12.B305170557
- 8305310029 Requests current suspension of federal & state licensing proceedings continue until mid-Sept 1983 to consider licensing alternatives THOMSEN,F T Ferkins, Cole, Stone, Olsen & Williams, THOMSEN,F T Puget Sound Power & Light Co 83/05/25 WOLF,J F, LEWIS,N D Atomic Safety and Licensing Board Panel 3pp 18653 127 24X Fiche 50-522,83/05/25,8303310029

- 8305310082 Request for extension until 830930 to answer NRDC motion for JOS310082 Request for extension until 830930 to answer NRDC motion fo summary disposition of Contention 1 Time needed to consider implications of final northwest conservation electric power plan & licensing alternatives Certificates of Svc enci THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie. Stone, Olsen & Williams 83/03/23 Atomic Safety and Licensing Board Panel Bpp 18658 040 24% Fiche 50-322,83/05/25,8305310082
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptability to Exothermic Chemical Reaction " Svc list
 - TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24Y Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Natice 83-21, "Defective Emergency Use Respirator"
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Cp of New
 York, Inc 112pp 18383 089 24% Fiche 50-000.83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inocerable Containment Atmosphere Solution Sys "Svc list end System Sensing Sys "Svc list end System Syste
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Cenerators at PMRs "Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) E3/04/28 Consolidated Edison Co of New
 York, Inc. 115pp 18382-047 24X Fiche 50-000/83/04/28.8303040026
- B303040027 IE Info Notice B3-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list enci JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/28 Consolidated Edison Co of New York. Inc 118pp 18382 165 24X Fichs 50-000.83/04/28.8303040027
- 8303040028 [E Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 30-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000:83/05/04,8303040031
- 8303040033 [E Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Natice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040040 LE Info Notice 83-31. "Error in ADLPIPE Computer Program " 303040040 to into mosts - Sec list entl
 SVc list entl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24x Piche 50~000,83/05/19,8303040040
- 8303040046 [E Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Dil " Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/03/26.8303040046

- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8305030013 Forwards NRC comments on C-E Owners Group study re depressurization & DMR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision NOVAK.T M Assistant Director for Licensing 83/04/20 BRUNT,E E Arizona Public Service Co 4pp 18310 349 Fiche 50-528,83/04/20,8305030013
- B305110022 Summary of B30406-07 meetings w/util & Bechtel at site re NRC power sys site audit findings Agenda encl LICITRA-E A Licensing Branch 3 B3/05/03 Licensing Branch 3 7pp 18415 066 24X Fiche 50-528, B3/05/03, B305110022
- B305230003 Forwards request for add1 info re B30322 proposed rev to Table 3 2-1 of FSAR Rev deleting commitment to apply GA program to certain items during operations phase ω/ο Justification
 KNIGHTON, 0 W Licensing Branch 3 83/05/03 VAN
 Arizona Public Service Co 4pp 18541 352 24X
 Fiche 50-528.83/05/03.8305230003 VAN BRUNT, E E
- --8309230004 Suggests that encl request for add1 info be transmitted to applicant Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 QA program during operations phase
 HAASS.W P QA Branch 83/04/26 KNIGHTON, Q W Licensing Branch
 G 6pp 18541 356 24X Fiche 50-528,83/05/03,8305230003
- 8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue EISENHUT, D G Division of Licensing 83/05/04 PALLADIND, N., GILINSKY, V., ROBERTS, T M. Commissioners 22pp 18337 139. 24x Fiche 50-000,83/05/04,8305040323
- 8305170219 Forwards summary of 830407 meeting w/util in Bethesda, MD redraft procedures generation package for emergency orocedures RALE A Licensing Branch 3 83/05/06 Licens 18476 343 24% Fiche 50-528,83/05/06,8305170219 Licensing Branch 3
- --8305170225 Summary of 830428 meeting w/util in Bethesda, MD re draft procedures generation package for emergency procedures GODDMAN M J Procedures & Systems Review Branch 83/04 CLAYTON, H B Procedures & Systems Review Branch 4pp 24X Fiche 50-528,83/03/06,8305170219 83/04/28 18476 345
- 8305090659 Generic Ltr B3-20 to all operating reactor licenses & holders of CPs re integrated scheduling for implementation of plant mods 8vc list encl EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24x Fiche 50-000,83/05/09,830509659 Consolidated
- 8305240038 Requests schedule for submittal of addl info needed in order to resolve remaining FSAR items prior to decision on OL issuance Response requested within 2 wks of receipt of NICHTON.O W Licensing Branch 3 83/05/09 VAN Arizona Public Service Co 7pp 18594 294 24X Fiche 50-528,83/05/09,8305240038 VAN BRUNT, E E
- 8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda, MD to present results of independent da evaluation & discuss status of corrective actions LICITRA:E A Licensing Branch 3 83/05/10 KNIGHTON:0 W Licensing Branch 3 3pp 18593 300 24X Fichs 50-528,83/05/10. 8305240253
- 8305140071 Forwards application for amend to CPPR-141, requesting extension of const completion date from 830831 to 1231 Class II fee encl VAN BRUNT, E E Arizona Public Service Co 83/03/12 Office Nuclear Reactor Regulation, Director 2pp 18433 027 24X Fiche 30-328,83/09/12,8303140071 Office of
- ~-8305160072 Application for amend to CPPR~141, requesting extension of const completion date from 830831 to 1231
 VAN BRUNTLE E Arizona Public Service Co 83/05/12 4pp
 18453 031 24X Fiche 50~528.83/05/12,8305160071
- 8305200417 Justifies rev to FBAR Section I B re exception to Reg Quide I 3B storage requirements for fission chamber detectors & sealed sources; in response to Jan 1983 request VAN BRUNT, E E Arizona Public Service Co B3/05/18 KNIOHTON, Q Licensing Branch 3 2pp 18517 162 24X Fiche 50-528, 83/05/18, 8305200417

- B305310161 Nutifies that util will provide plant-specific info re depressurization & DHR capabilities by B30731 instead of previous schedule date of B30930 VAN BRUNTLE E Artions Public Service Co B3/05/24 KNIGHTON, G Licensing Branch 3 2pp 18652 345 24X Fiche 50-528,83/05/24, B305310161
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305230273 Confirms requests for info identified in discussions w/util re analysis of Sys 80 fuel design under combined seismic & LOCA loads & protection against low temp overpressure event per SER open item KNIOHTON: 0 W Licensing Branch 3 83/05/04 VAN BRUNT, E Antiona Public Service Co 3pp 18543 265 24X Fiche 50-528.83/05/04.8305230273
- 8305120385 Forwards RCS pressure temp (P-T) curves requested in Bection 5 3 2 of SER (NUREQ-0857) P-T curves will be submitted as part of final Tech Spec submission Submittal resolves issue VAN BRUNTLE Artiona Public Service Co 83/05/09 KNIGHTON, G Licensing Branch 3 4pp 18433 120 24X Fiche 50-528,83/05/09,8305120385
- F. Becurity, medical, emergency & fire protection plans
- 8305110034 Qeneric Ltr 83-21 to all licenses of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits 8vc list encl EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11.8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983 DIRCKB,W J Office of the Executive Director for Operations 83/03/13 PALLADIND,N J Commissioners 5pp 18593 322 24X Fiche 50-000.83/05/13,8305240213
- B305200322 Advises that installation of source range neutron flux monitor, per 10CFR50, App R. Section III L. will be accomplished by end of first refueling outage VAN BRUNT, E E Arizona Public Bervice Co B3/05/17 KNIGHTON, C Licensing Branch 3 App 18516 294 24X Fiche 50-528.89/05/17.8305200322

G Adjudicatory correspondence

- B305200488 Advises that time for Commission to review ALAB-713 expired Commission declined review Decision became final agency action on B30427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners CHILK, B. J. Dffice of the Secretary of the Commission 63/05/19. Office of the Executive Legal Director 1p 18514 039 24X Fiche 50-528,83/05/19,8305200488
- B305310215 Requests apportunity to respond to West Valley Agricultural Protection Council B30506 supplemental motion re FES OL stage & to argue relevancy if ABLB determines that consideration should be given OEHR.A C Snell & Wilmer GEHR.A C Arizona Public Bervice Co B3/05/23 LAZO,R M., CALLIHAN,D., COLE,R F Atomic Safety and Licensing Board Panel Spp 18658 137 24X Fiche 50-528,83/05/23,8305310215
- K Utility Final Bafety Analysis Report (FBAR) & amends
- E305020089 Forwards Amend ii to FSAR
 VAN BRUNT.E E Arizona Public Service Co 63/04/28, Office of
 Nuclear Reactor Regulation, Diractor 2pp 18274 123 24X
 Fiche 50-528.83/04/28,8305020089
- --8305020092 Amend 11 to FSAR W/47 oversize figures Aperture cards are available in PDR * Artitona Public Service Co. 83/04/30 804pp. 18274 125 24X Fiche 50-528,83/04/28,8305020089
- @ Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptability to Exothermic Chamical Reaction," Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 19435 155 24X Fiche 50-000.83/04/15,8303040021
- 8305030302 Notification of 830302 enforcement conference w/util in Walnut Creek.CA * Region 5. Office of Director 83/04/20 Region 5. Office of Director 29 18304/20 80305030302
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000.83/04/22,8303040023
- 8305170531 Forwards IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance noted CREWS, J L Division of Resident, Reactor Project & Engineering Programs 83/04/22 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 001 24x Fichs 50-528, 83/04/22, 8305170531
- --B305170537 IE Insp Repts 50-528/83-10,50-529/83-07 & 50-530/83-05 on 820601-830311 Nuncompliance noted improper documentation of cable termination records ECKHARDT.J H , VORDERBRUEGGEN, ELIN,J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-328,83/04/22,8305170531
- 8303040025 lE Info Notice 83-23. "Inoperable Containment Atmosphere Sensing Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/25 Consolidated Edison Co of New York, Inc ii9pp i8381 291 24X Fiche 50-000.83/04/25.8303040025
- 8305170560 Forwards IE Insp Repts 50-528/83-09, 30-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted STERNBERG, D M Region 5. Office of Director 83/04/25 VAN BRUNT, E E Artiona Public Service Co 2pp 18468 128 24X Fiche 50-528.83/04/25,8305170560
- --8305170544 IE Insp Repts 50-928/83-09, 90-929/83-04 & 50-530/83-04 on 830404-07 No noncompliance noted Major areas inspected allegations made by R Gunderson & W Royce in affidavits before ASLD on 830108 \$ 0229 VORDERBRUEGGEN, FICHELLI, G , BURDDIN, J Region 5, Office of Director 83/04/22 14pp 18468 130 24x Fiche 50-528,83/04/25,8309170940
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PMRs" Svc list encl
 JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3704/2B Consolidated Edison Co of New York, Inc 115pp 18302 047 24X Fiche 30-000.83/04/2B.8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000.83/04/28.8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers" Svc list ench JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24% Fiche 50-000,83/05/03,8303040028
- 8305260319 Ack receipt of 830404 & 22 ltrs informing ARC of steps taken to correct violations noted in IE insp on 830104-07 & 17-21 STERNBERG.D M Region 5. Office of Director 83/03/03 VAN BRUNT, E E Arisone Public Service Co ip 18625 007 24X Fiche 50-528,83/05/03,8305260319
- --8305260321 Responds to NRC B30302 itr re violations noted in 1E inspon B30104-07 & 17-21. Corrective actions 6-inches of pipe & weld replaced Listed supports installed on B30323 per Design Change Package 1-98-RD-013

 VAN BRUNT.E E Arizona Public Service Co B3/04/04

 STERNBERG.P M Region 5. Office of Director App 18625 008
 24X Fiche 50-528, B3/05/03, B302520319
- --8305260326 Revises B30404 response to IE inspire unauthorized undocumented weld Alleger did not claim to have knowledge of any other incidents VAN BRUNT, E. E. Arizona Public Service Co. B3/04/22 STERNBERG, D. M. Region 5, Office of Director 4pp. 18625-014 24X Fichs 30-328-83/05/03,8305260319

- B303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list april URBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York. Inc 112pp 18382 282 24X Fiche 50-000.83/05/04.8303040030
- B303040031 IE Info Notice B3-28. "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York. Inc. 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031
- 8305170377 Forwards IE Insp Rept 50-528/83-13 on 830321-0429 No noncompliance noted STERNBERG.D M Region 5, Office of Director 83/05/04 ANDGONINI.6 C Arizona Public Service Co 2pp 18470 128 24x Fiche 50-528/83/05/04,8305170377
- --B3051703B2 IE Insp Rept 50-528/83-13 on 830321-0429 No noncompliance noted Major areas inspected startup testing,maint, fuel receipt & reactor coolant pump repairs FIGRELLI.0 , JOHNSTON.6 , YOUNG, T. Region 5, Office of Director 83/05/04 6pp 18470 130 24X Fiche 50-528,83/05/04,8305170377
- 8303040033 IE Info Notice 83-27, "Fuel Binding Caused by Fuel Rack Deformation" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06.8303040033
- B305160008 Notification of B30525 meeting w/wtil & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1981 -Feb 1983 * Region 5, Office of Director B3/05/10 Region 5, Office of Director 2pp 18456 079 24X Fiche 5D-528, 83/05/10, 8305160008
- 8303160087 Confirms 830525 meeting w/applicant at Deer Valley Project oft to discuss SALP for Jul 1981 Feb 1983 CREWS, J L Division of Resident.Reactor Project & Engineering Programs 83/05/10 VAN BRUNT.E E Arisona Public Service Co 3pp. 18448 146 24X Fishe 50-528,83/05/10,8305160087
- --8305160179 SALP rept for Jul 1981 Feb 1983 * Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528.83/05/10.8305160089
- 8303040034 IE Info Notice 83-30, "Misapplication of Ceneric Emergency Operating Procedures (EOP) Quidelines " Svc list encl.
 JDRDAN,E,L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Bvc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Ficher 50-000, 83/05/19, 8303040040.
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647-007 24X Piche, 50-000, 83/05/26, 8303040046
- S Reportable occurrences, LERs & related correspondence
- 8305030626 Interim Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power. Initially reported on 830318 Final rept by 830519 VAN BRUNT. E E Aritona Public Service Co 83/04/15 STERNBERG, D M Region 5, Office of Director 3pp 18303 339 24X Fiche: 50-526,83/04/15,8305030626
- 8305030285 Final Deficiency Rept DER 82-84 re internal damage to Class IE load ctrs by space heaters Initially reported on 830127 Deficiency not reportable under 10CFR50 55(e) Space heaters being supplied w/correct voltage VAN BRUNT, E E Aritona Public Servica Co 83/04/19. STERNBERG, D M Region 5, Office of Director 4pp 18300 080 24X Fichs 50-528,83/04/19,8305030285
- 8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection switches failure to meet requirements of TMI Task 18A Initially reported on 830304 Info will not be finalized until 830517 due to extensive investigation. VAN 8RUNT, E. E. Arizona Public Service Co. 83/04/21, 8TERNBERG, D.M. Region 5, Office of Director ip 18440,093 24X Fiche 50-528,83/04/21,8305130229

- 8305120392 Interim deficiency rept re misapplication of ITE Qould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO, 6 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region 1. Dffice of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY. D C Rockwell International Corp 83/03/11. CDLLING, J 7 Region 4. Office of Director 5pp 18433 074 24X Fiche 50-000, 83/04/26, 8305120392
- 8305130183 Interim Deficiency Rept DER 82-51 rs Pullman-Kelloge pips
 line failure in essential cooling water sys Initially
 reported on 820910 Submittal of final rept delayed until
 830531 due to extensive evaluation required
 VAN BRUNTIE E Arizona Public Service Co 83/04/26 STERNBERG,D M.
 Region 5. Office of Director 2pp 18439:345 24X
 Ficha 30-528,83/04/26,8305130183
- 8305i30i27 Final Deficiency Rapt DER 83-4 re failure of Waldinger test procedures for air handling units to meet ANSI N510 requirements Initially reported on 830i26 Condition datermined not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 83/04/27 STERNBERG, D M Region 5, Office of Director 6pp 18437 271 24X Fiche 50-528,83/04/27,8305i30i27
- 8305/30169 Interim Deficiency Rept DER 82-53 re failure of Joy fan blade causing 2-inch penetration of containment liner plate. Initially reported on 820924 Submittal of final rept delayed until 830628 due to extensive investigation required VAN BRUNT.E E Arizona Public Service Co 83/04/27 STERNBERO, D N Region 5, Office of Director 2pp. 18438-111 24X Fiche 50-528,83/04/27.8305130169
- 8305130124 Deficiency Evaluation Rept 83-18 re installation of pips supports which do not meet Beismic IX requirements Initially reported on 830329 Deficiency determined not reportable per 10CFR30 55(e) Documentation will be maintained in files VAN BRUNTLE E Arizona Public Service Co 83/04/28. STERNBERG, D M. Region 5. Office of Director 2pp 18438, 057 24X Fiche 50-528, 83/04/28, 8305130124
- 8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 830406. Deficiency determined not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizone Public Service Co 83/04/29. BIERNBERG,D M Region 5. Office of Director 2pp. 18437 185 24X Fiche 50-528.83/04/29,8305130159
- 8305130210 Advises that Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co. 83/04/29 STERNBERG.D K Region 5. Office of Director ip 18440 070 24X Fichs 50-528,83/04/29,8305130210
- 8305130082 Final Deficiency Rept DER 82-62 re ESF actuation sys dc power supply ground detectors failing preoperational tests Initially reported on 821021. Item determined not reportable under 10CFR30 35(e)
 VAN SRUNT, E E Arizona Public Service Co 83/05/03 STERNBERG, D K Region 9, Dffice of Director 6pp 18436, 273, 24X Fiche: 50-528,83/05/03,8305130082
- B305130107 Final Deficiency Rept DER 83-2 re valve operators accidentally interchanged by Posi-Seal on inside & outside containment valves, Initially reported on B30125 Operators to be replaced Also reported per Part 21 by Posi-Seal VAN BRUNT.E E Anizona Public Service Co 83/03/03 BTERNBERG, D M. Region 5, Office of Director 4pp. 18437 219. 24X Fichs 50-528.83/03/03.8305130107
- 8305130148 Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tach Spec requirements. Initially reported on 821124 Revised test plan reviewed by Bechtel Final rept expected by 830823, Also reported per Part 21.

 VAN BRUNT. E E Arizona Public Service Co 83/05/03, 8TERNBERG, D H Region 5, Office of Director App 18438, 117 24% Fichs 30-528, 83/05/03, 8305130148
- 8305130168 Interim Deficiency Rept DER 83-19 re Pacific Scientific safety injection sys snubber failure to function properly. Info will be finalized by 830801 Delay due to extensive investigation & evaluation.

 VAN BRUNT, E E Arizona Public Service Co. 83/05/03 STERNBERG, D. H Region 5, Office of Director. 3pp 18436 101. 24X Fiche 50-528,83/05/03.8305130168.

- B305130189 Final Deficiency Rept DER 83-12 re malfunction of GE add-on electric interlocks used w/Class IE. Size 2. starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21 VAN BRUNT.E E Arizona Public Service CO B3/05/03 STERNBERG.D M Region 5. Dffice of Director 5pp 18439 340 24X Fiche 50-528,83/05/03.8305130189
- 8305130226 Rev i to Interim Deficiency Rept DER 82-80 re failure of Conex electrical penetration low level insulation resistance to meet qualification tests Initially reported on 821217 Testing in progress Next rept by 830914 VAN BRUNT, E E Arisona Public Service Co 83/05/03 STERNBERG, D M Region 5. Office of Director 3pp 18439 188 24X Fiche 50-528,83/05/03.8305130226
- 83D513O264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 83O318 Also reportable per 10CFR21 VAN BRUNT, E E Arizona Public Service Co. 83/05/03 STERNBERG. D M Region 5, Office of Director 4pp 18439 238 24X Fiche. 50-528, 83/05/03, 8305130264
- 8305230517 Final Deficiency Rept DER 83-21 re operation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)

 VAN BRUNT, E. E. Arizona Public Service Co. 83/05/06 STERNBERG, D. M. Region 3, Office of Director 2pp. 18536-313 24X

 Fiche 50-528,83/05/06,8305230517

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION. UNIT 2

- A Application/construction stage documents & correspondence
- 8305030013 Forwards NRC comments on C-E dwners Group study redepressurization & DHR capability of C-E plants w/o PORVs info re need for PORVs in plants required by 830630 in order to be considered in final decision NDVAK, T M Assistant Director for Licensing 83/04/20 VAN BRUNTLE Afizona Public Service Co 4pp 18310 349 24X Fiche: 50-528, 83/04/20, 8305030013
- 8305110022 Summary of 830406-07 meetings w/util & Bechtel at ..te re NRC power sys site audit findings Agenda encl LICITHA.E A Licensing Branch 3 83/05/03 Licensing Branch 3 7pp 18415.066 24% Fiche 50-528.83/05/03.8305110022
- 8305230003 Forwards request for add1 info re 830322 proposed rev to Table 3.2-1 of FSAR Rev deleting commitment to apply GA program to certain items during operations phase w/o justification KNIOHTON: 0 W. Licensing Branch 3 83/05/03 VAN BRUNT, E. E. APIJONA Public Service Co 4pp 18541 352 24X Fiche 50-528, 83/05/03, 8305230003
- ---8305230004 Suggests that encl request for addl info be transmitted to applicant Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 QA program during operations phase HAABS, W P QA Branch 83/04/24 KNIGHTON, O W Licensing Branch 3 App 18541-335 24X Fiche: 50-328-83/05/03.8305230003
- B305040323 Board Notification B3-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications B3-17 & B3-44 re Unresolved Safety Issue A-17.

 EISENHUT, D 9 Division of Licensing 83/05/04 FALLADINO, N .
 OILINSKY, V , ROBERTS, T, M Commissioners 22pp 18337 139 24X Fiche 50-000, B3/05/04, B305040323
- 8305170219 Forwards summary of 830407 meeting w/util in Bethesda, MD redraft procedures generation package for emergency procedures
 LICITRA, E. A. Licensing Branch 3 83/05/06, Licensing Branch 3 2pp. 18476:343 24X Fiche: 50-528, 83/05/06, 8305170219
- --8305170225 Summary of 830428 meeting w/util in Bethssda, HD rs draft procedures generation package for emergency procedures.

 2000DMAN: M J Procedures & Systems Review Branch 83/04/28.

 CLAYTON: H B Procedures & Systems Review Branch 4pp 18476; 34: 24X Fiche 50-528; 83/05/06, 8305170219
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods, Svc list encl EISENHUT, D. G. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659

- 8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda.MD to present results of independent GA evaluation & discuss status of corrective actions LICITRA.E A Licensing Branch 3 83/05/10 KNIGHTON.O W Licensing Branch 3 3pp 18593 300 24X Fiche 50-528,83/05/10. 8305240253
- 8305200417 Justifies rev to FSAR Section 1 B re exception to Reg Quide 1 38 storage requirements for fission chamber detectors & sealed sources, in response to Jan 1983 request VAN BRUNT.E E Arizona Public Service Co 83/05/18 KNIGHTON.G Licensing Branch 3 2pp 18917 162 24X Fiche 50-528,83/05/18,8305200417
- 8305250209 Board Notification B3-063 transmits mamos re status of DHR studies for C-E plants. W/emphasis on need for PDRVs in current C-E designs
 NOVAK.T M Assistant Director for Licensing B3/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X Fiche 50-000. B3/05/18, 8305250209
- --BJ03250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ASLAB MATTBON, R J Division of Systems Integration (post 811005) BJ704/2B EISENHUT, D O Division of Licensing 19 18627 ii3 24X Fiche 50-000, 83/05/18, 8305230209
- --8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACR8 views be solicited on issue prior to reporting back to Commission Study to be concluded 830630 DIRCKS.W J Office of the Executive Director for Operations 83/04/25 CHILK.S J Office of the Secretary of the Commission ip 16627 115 24X Fiche 50-000,83/05/18,8305250209
- B3053i016i Notifies that util will provide plant-specific info re depressurization & DHR capabilities by B30731.instead of previous schedule date of B30930 VAN BRUNTLE E Arizona Public Service Co 83/05/24 KNIGHTQN.O Licensing Branch 3 2pp 18652 345 24X Fiche 50-528.83/05/24. 830531016i
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8305230273 Confirms requests for info identified in discussions w/util re analysis of Sys 80 fuel design under combined seismic & LOCA loads & protection against low temp overpressure event per SER open item KNIGHTON:0 W Licensing Brench 3 83/05/04 VAN BRUNT.E E Arizona Public Service Co 3pp 18543 265 24X Fiche 50-528.83/05/04.8305230273
- F Security, medical, emergency & fire protection plans
- 83051i0034 Owneric Ltr B3-2i to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enci
 EISENHUT, D O Division of Licensing 83/05/ii Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
 Fiche 50-000, 83/05/ii, 8305110034
- B305200322 Advises that installation of source range neutron flux monitor, per iOCFR50, App R. Section ISI L. will be accomplished by end of first refueling outage VAN BRUNT.E E Arizona Public Service Co B3/05/17 KNIGHTON.0 Licensing Branch 3 App 18316 294 24X Fiche 30-328,83/05/17,8305209322
- O Adjudicatory correspondence
- B305030594 Second set of nanuniform interrogatories Certificate of Svc encl Related correspondence CRAWFORD, V A. Joint Applicants-Palo Verde CRAWFORD, V A Snell & Wilmer B3/04/27 West Valley Agricultural Protection Council, Inc. 36pp i8303 215 24X Fiche 50-529,83/04/27,8305030594
- B305030498 Second set of interrogatories Certificate of Svc encl DEMEY.L 5 Hearing Branch 3 B3/04/29 West Valley Agricultural Protection Council, Inc 9pp 18295 109 24X Fiche 50-529, B3/04/27.B305030498
- 8305160080 Memorandum supporting West Valley Agricultural Protection Council, Inc supplemental motion for declaration that NEFA amalysis inadequate & for continuance No attempt made to identify/analyse salt drifts W/Cetificate of Svc BERLIN, K. West Valley Agricultural Protection Council, Inc BERLIN, K. Berlin, Roisman, Kassler & Cashdan 83/05/06 Atomic Safety and Licensing Board Panel 6pp 18450 120 24X Fiche 50-529,83/05/06,8305160080

- B305110268 Comments on format of Univ of Arizona agricultural productivity study methodology Methodology adequate for evaluating impacts of salt drift on representative agricultural crops

 DEMEY.L S Hearing Branch 3 83/05/10 PLATT.W E Snell & Wilmer 3pp 18393 23 24% Fiche 50-529, 83/05/10, 8305110268
- 8305140032 Supplemental motion to 830202 motion for declaration that NEPA analysis inadequate & for continuence of proceedings Joint applicant responses to interrogatories lacked meaningful data on salt deposition BERLINIK Hest Valley Agricultural Protection Council, Inc 83/05/13 Atomic Safety and Licensing Board Panel 13pp 18453 149 24% Fiche 30-329, 83/05/13, 8305160032
- 8305160034 Motion for mod of ASLB 830323 discovery schedule, per 830309 stipulation on discovery Depositions scheduled for 830718 should be rescheduled for 830827 Discovery on Univ of Arizona crop study should begin on 831220

 BERLIN,K West Valley Agricultural Protection Council Inc 83705373 Atomic Safety and Licensing Doard Panel 5pp 18454 089 24X Fiche 50-529,83705713,83051640034
- 8303140085 Memorandum supporting West Vailey Agricultural Protection Council Inc motion for discovery schedule Projected date for crop study completion 6 wks later than original date BERLINK West Vailey Agricultural Protection Council, Inc BERLINK Berlin, Roisman, Kessler & Cashdan 83/05/16 Atomic Safety and Licensing Board Panel 3pp 18451 024 24X Fiche 30-529,83/05/16,8305160086
- 8305240482 Joint Applicants response to Wost Valley Agricultural Protection Council second set of interrogatories OEHR.A C. PLATT.W E. BISCHOFF.C A Snell & Wilmer 83/05/18 Atomic Safety and Licensing Board Panel 61pp 18572 252 24X Fiche 50-529,83/05/18,8305240482
- 8305200488 Advises that time for Commission to review ALAB-713 expired Commission declined review Decision became final agency action on 830427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners CHLK.S & Defice of the Secretary of the Commission 83/05/19 Defice of the Executive Legal Director ip 18514 039 24X Fiche 50-528.83/05/19,8303200488
- 8305310215 Requests apportunity to respond to West Valley Agricultural Protection Council 830506 supplemental motion re FES OL stage & to argue relevancy if ASLB determines that consideration should be given GEHR. A C Arizona Public Service Co 83/05/23 LAZO,R M. CALLIHAN. D. CQLE.R F Atomic Safety and Licensing Board Panel 5pp 18658 137 24X Fiche 50-528.83/05/23, 22035/05/25
- 8305270024 Response to West Valley Agricultural Protection Council
 830306 motion for mod of discovery schedule Requests (0-day
 extension to answer motion since Joint Applicants & Council
 stipulation not received Certificate of Svc encl
 DEWEY.L S Hearing Branch 1 83/05/26 Atomic Safety and
 Licensing Board Panel App 18640 057 24X Fiche 50-529.83/05/26.
 8305270024
- B305310074 Response to West Valley Agricultural Protection Council, Inc supplemental motion for declaration that NEPA analysis inadequate for continuance of proceedings Request for new EIS & continuance should be denied W/Certificate of Svc DEWEY.L S Hearing Branch 3 83/05/26 Atomic Safety and Licensing Board Panel 14pp 18659 105 24% Fiche 50-529,83/05/26,8305310074
- X Utility Final Safety Analysis Report (FEAR) & amends
- 9305020089 Forwards Amend 11 to FSAR
 VAN BRUNT, E E Arisona Public Service Co 83/04/28 Office of
 Nuclear Resctor Regulation, Director 2pp 18274 123 24X
 Fiche 50-528,83/04/28,8305020089
- --8305020092 Amend 11 to FSAR W/47 oversize figures Aperture cards are available in PDR # Arizona Public Bervice Co 83/04/30 806pp 18274 125 24x Fiche 50-528,83/04/28,8305020089
- @ Inspection reports, IE Bullstins & correspondence
- 8212060395 IE info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

- 8303040021 [E Info Notice 83-21, "Defective Emergency Use Respirator." Svc 11st encl
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co of R4w
 York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8393040021.
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
 Svc list encl
 JORDAN, E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,830304023
- 8305170531 Forwards IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance noted CREWS, J. Division of Resident, Reactor Project & Engineering Programs 83/04/22 VAN GRUNT, E E Arizona Public Service Co 2pp 18468 001 24% Fiche 50-528, 83/04/22, 8305170531
- --8305170337 IE Insp Repts 50-528/83-10:50-529/83-07 % 50-530/83-05 on 820501-830311 Noncompliance noted improper documentation of cable termination records ECKHARDT.J H , VORDERBRUEOGEN, ELIN.J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-528:83/04/22:8305170531
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305170560 Forwards IE Insp Repts 50-528/83-09,50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted STERNBERG, D M Region 5, Office of Director 83/04/25 VAN BRUNT, E E Ariona Public Service Co 2pp 18468 128 24X Fichs 50-528,83/04/25,8305170560
- --8305170564 IE Insp Repts 50-528/83-09.50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted Hajor areas inspected allegations made by R Ounderson & W Royce in affidavits before ABLB on 830108 & 0225 VORDERBRUEGOEN, FIGRELLI, 0 . BURDOIN, J Region 5, Office of Director 83/04/22 14pp 18468 130 24X Fiche 50-528,83/04/25,8305170560
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PURs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Tamp Trip Setpoint Adjustment " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Conspildated Edison Co of Naw York, Inc 118pp 18382 145 24X Fiche 50-000,83/04/28,8303040027
- 8305020466 Informs that insp of facility not warranted unless significant safety deficiency identified re elongated roof truss bolts VITS item closed & matl placed in vendor reactive file CONNAY, J T Region 4, Office of Director 83/04/28 BARNES, I. Region 4. Office of Director 19 18283 307 24X Ficha 30-529,83/04/28,6305020466
- B303040028 IE Info Notice B3-26, "Failure of Bafety/Relief Valve Discharge Line Vacuum Breakers " Svc list enc! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/03/03,8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Syc list encl.
 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York

- B30516000B Notification of 830525 meeting w/util & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1781 -Fab 1783
 - * Region 5, Office of Director 83/05/10 Region 5, Office of Director 2pp 18456 079 24X Fiche 50-528,83/05/10,8305160008
- 8305160087 Cunfirms 830525 meeting w/applicant at Deer Valley Project ofc to discuss SALP for Jul 1981 - Feb 1983 CREMS. J L Division of Resident.Reactor Project & Engineering Programs 83/05/10 VAN BRUNT.E E Arizona Public Service Co 3pp 18448 146 24X Fiche 50-528,83/05/10.8305160089
- --8305160179 SALP rept for Jul 1981 Feb 1983 * Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528,83/05/10,8305160089
- 8303040034 IE Info Notice 83~30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp 18697 009 24X Fiche 50-000, B3/05/19, B303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Ficho 50-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- B305030346 Interim Deficiency Rept DER B3-15 re Marathon A354 anchor bolt breaking after overtorquing during test acceptance Initially reported on B30318 Due to extensive investigation & evaluation. Final rept expected by B30517
 VAN BRUNT. E Arizona Public Service Co 83/04/15 STERNBERG, D M Region 5. Office of Director 3pp 18277 134 24X
 Fiche 50-529,83/04/15,8305030346
- 8305030626 Interlm Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power initially reported an 830318 Final rept by 830519 VAN BRUNT. E E Arizona Public Service Co 83/04/15 STERNBERG, D M Region 5, Office of Director 3pp 18303 339 24X Fiche 50-528,83/04/15,8305030626
- 8305130161 Interim Deficiency Rept DER 82-72 re concrete void in containment exterior wall Initially reported on 821124 Grouting procedure implemented Apr 1983 per Bechtel investigation final rept will be submitted by 830629 VAN IRUNT, E E Arisona Public Service Co 83/04/21 STERNBERG, D M Region 5, Office of Director 3pp 18437 296 24X Fiche 50-529.83/04/21.8305130161
- 8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection sultches failure to meet requirements of TMI Task 18A Initially reported on 830304 Info mill not be finalized until 830519 due to extensive investigation VAN BRUNTLE E Arizona Public Service Co 83/04/21 STERNBERG, D M Region 5. Office of Director ip 18440 073 24X Fiche 50-528,83/04/21,8305130229
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation final rept by 830808 Reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region I. Office of Director 2pp 18433 072 24X Fiche. 30-000,83/04/26,8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application. Plant operators notified of deviation EMPEY, D C Rockwell International Corp 83/03/11 COLLING, J T Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392
- 8305130124 Deficiency Evaluation Rept 83-18 re installation of pipe supports which do not meet Seismic IX requirements Initially reported on 830329 Deficiency determined not reportable per 10GFRSO 55(e) Documentation will be maintained in files. VAN BRUNT, E E Arizona Public Service Co 83/04/28 STERNBERG, D M Region 5, Office of Director 2pp 18438 059 24X Fiche 30-528,83/04/28,8305130124

- 8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 83040A Deficiency determined not reportable per (OCFRSO 55(e) VAN BRUNT, E E Arijona Public Service Co 83/04/29 STERNBERG, D M Region 5, Office of Director 2pp 18437 185 24X Fiche 50-526,83/04/29,8305130159
- 8305130210 Advises that Deficiency Evaluation Rept DER B3-20 re startup test personnel qualifications not reportable per 10CFR50 53(e) VAN BRUNT.E E Artiona Public Service Co 83/04/27 Region 5. Deffice of Director 1p 18440 090 24X Fiche 50-528.83/04/27.8305130210
- B30513014B Revised interim Deficiency Rept DER 82~76 re Target Rock valves not meeting Tech Spec requirements Initially reported on B21124 Revised test plan reviewed by Bechtol Final rept expected by B30623 Also reported per Part 21 VAN BRUNT.E E Arijona Public Service Co 83/05/03 STERNBERG.D M Region 5. Office of Director 4pp 18438 117 24X Fiche 50-528,83/05/03,8305130148
- 8309130226 Rev 1 to Interim Deficiency Rept DER 82-80 rm failure of Conax electrical penetration low level insulation resistance to meet qualification tests Initially imported on 821217 Testing in pragress Next rept by 830914

 VAN DRUNTLE E Arizona Public Service Co 83/05/03 STERNBERG, D M Region 5, Office of Director 3pp 18439 188 24X Fiche 50-328,83/05/03,8305130226
- 8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Also reportable per IOCFR21 VAN BRUNT.E E Arizona Public Service Co 83/05/03 STERNBERO, D M Region 5, Office of Director 4pp 18439 238 24X Fiche 50-528,83/05/03,8305130264
- 8303230517 Final Deficiency Rept DER 83-21 re operation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)
 VAN BRUNT.E E Arizona Public Service Co 83/05/06 STERNBERG, DM Region 5. Office of Director 2pp 18536 313 24X
 Fiche 50-528,83/05/06,8305230517
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents % correspondence
- 8305030013 Forwards NRC comments on C-E Owners Group study redepressurization & DNR capability of C-E plants w/o PGRVs Info re need for PGRVs in plants required by 830430 in order to be considered in final decision NDVAK.T M Assistant Director for Licensing 83/04/20 VAN BRUNT.E E Arizona Public Service Co App 18310 349 243 Fiche 50-528.83/04/20.8305030013
- B305110022 Summary of B30406-07 meetings w/util & Bechtel at site re NRC power sys site audit findings Agenda encl LICITRA.E A Licensing Branch 3 83/05/03 Licensing Branch 3 7pp 18415 066 24% Fiche 50-528.83/05/03.8305110022
- 8305230003 Forwards request for add1 info re 830322 proposed rev to Table 3 2-1 of FSAR Rev deleting commitment to apply 9A program to certain Items during operations phase w/o justification MIGHTON.G W Licensing Branch 3 83/05/03 VAN BRUNT,E E Arizona Public Service Co 4pp 18541 352 24X Fiche 50-529,83/05/03,8305230003
- --8305230004 Suggests that encl request for add1 info be transmitted to applicant Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 GA program during operations phase HAASS, W P GA Branch 83/04/26 KNIGHTON, G W Licensing Branch 3 App 18541 356 24X Fiche 50-528.83/08/03.8305230003
- 8305040323 Board Notification 83-097 forwards differing prof opinions re sys Interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 rp Unresolved Safety Issue A-17 EISENHUT.D & Division of Licensing 83/05/04 PALLADIND, N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323
- B305170219 Forwards summary of B30407 meeting w/util ln Bothesda.MD redraft procedures generation package for emergency procedures
 LICITRA.E A Licensing Branch 3 83/05/06 Licensing Branch 3 2pp 18476 343 24% Fiche 50-528,83/05/06.8305170219

- ~-B305170225 Summary of 830428 meeting w/util in Bethesda, MD re draft procedures generation package for emergency procedures GODDMAN M J Procedures & Systems Review Branch B3/04/28 CLAYTON, H B Procedures & Systems Review Branch 4pp 18474 345 24% Fiche 50-528, 83/05/04, 8305170219
- 0305090659 Otheric Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT,D 0 Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659
- 8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda, MD to present results of independent GA evaluation & discuss status of corrective actions LICITRALE A Licensing Branch 3 63/05/10 KNIGHTON, 0 W Licensing Branch 3 3pp 18593 300 24X Fiche 50-528,83/05/10, 8305240253
- 8305200417 Justifies rev to FSAR Section 1 8 re exception to Reg Quide 1 38 storage requirements for fission chamber detectors & sealed sources, in response to Jan 1983 request VAN BRUNT,E E Arizona Public Service Co 83/05/18 KN19HTON, O Licensing Branch 3 2pp 18917 162 24X Fiche 50-528.83/05/18, 8305200417
- 8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants; w/emphasis on need for PORVs in current C-E designs
 NOVAK, T M Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X
 Fiche 50-000,83/05/18,8305230209
- --8305250221 Requests that encl documents on status of DHR studies for C-E plants: w/emphasis on need for PORVs in current C-E designs.be provided to ASLB & ASLAB MATTSON.R J Division of Systems Integration (post 811005) 83/04/28 EISENHUT.D & Division of Licensing ip. 18427-113 24X Fiche 30-000.83/05/18.8309250209
- --8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630 DIRCKS.W J Office of the Executive Director for Operations 83/04/25 CHILK.S J Office of the Servetary of the Commission ip 18627 115 24X Fiche 30-000.83/05/18.8305250209
- 8305310161 Notifies that util will provide plant-specific info re depressuriration & DHR capabilities by 830731.instead of previous schedule date of 830930 VAN BRUNT, E E Arizona Public Service Co 83/05/24 KNIOHTON, O Licensing Branch 3 2pp 18652 345 24X Fiche 50-528,83/05/24,8300310161
- E NRC Safety Evaluation Report (SER). supple & correspondence
- 8305230273 Confirms requests for info identified in discussions w/etil re analysis of Bys 80 fuel design under combined seismic & LOCA loads & protection against law temp overpressure event per SER open item KNIOHTON.O W Licensing Branch 3 83/05/04 VAN BRUNT.E E. Ariiona Public Service Co 3pp 18543 265 24X Fiche 50-528.83/05/04.8305230273
- F Security, medical, emergency & fire protection plans
- B305110034 Generic Ltr B3-21 to all licensees of operating reactors, applicants for DLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D G Division of Licensing B3/05/11 Consolidated Edison Co of New York inc 16pp 18540 075 24X
 Fiche 50-000, 83/05/11, 8305110034
- 8305200322 Advises that installation of source range neutron flux monitor per 10CFR30. App R. Section III L. will be accomplished by end of first refueling outage VAN BRUNT.E E Arizone Public Bervice Co. 83/05/17 KNIOHTON.G Licensing Branch 3 6pp 18516 274. 24X Fiche 50-528.83/05/17,8305200322
- G Adjudicatory correspondence
- 8305030594 Second set of nonuniform interrogatories Certificate of Evc encl.Related correspondence CRAMFORD,V A Joint Applicants-Palo Verde, CRAMFORD,V.A Snell & Wilmer 83/04/27 West Valley Agricultural Protection Council, Inc. 54pp 18303 215 24X Fiche.50-529,83/04/27,8305030594

- B305030498 Second set of interrogetories Certificate of 8vc encl DEMEY.L S Hearing Branch 3 83/04/29 Hest Valley Agricultural Protection Council, Inc 9pp 18275 109 24X Fiche 50-529, B3/04/29, B305030498
- B305160080 Memorandum supporting West Valley Agricultural Protection Council, Inc supplemental motion for declaration that NEPA analysis inadequate & for continuance No attempt made to identify/ənalyse sait of rifts W/Cetificate of Svc BERLIN.K West Valley Agricultural Protection Council, Inc. BERLIN.K Berlin, Roisman, Kessler & Cashdan B3/05/06 Atomic Safety and Licensing Board Panel 6pp 18450 120 24X Fiche 50-529,83/05/06.8305160080
- B305110268 Comments on format of Univ of Arizona agricultural productivity study methodology Methodology adequate for evaluating impacts of ealt drift on representative agricultural crops
 DEMEY, L. B. Hearing Branch 3 B3/05/10 PLATT, W.E. Snell & Wilmat God 18393 293 24X Fiche 50-527, 83/05/10, 8305110268
- B305160032 Supplemental motion to B30202 motion for declaration that NPPA analysis inadequate & for continuance of proceedings Jaint applicant responses to interrogatories lacked meaningful data on salt deposition BERLIN.K West Valley Agricultural Protection Council, Inc. B3/05/19 Atomic Bafety and Licensing Board Panel 13pp 18453 147 24% Ficher 50-529, 83/05/13, 8305160032
- 8305160034 Motion for mod of ASLE 830323 discovery schedule, per 830309 stipulation on discovery Depositions scheduled for 830718 should be rescheduled for 830829 Discovery on Univ of Arizona crop study should begin on 831220 HERLIN,K West Valley Agricultural Protection Council, Inc 83/05/13 Acomic 84ety and Licensing Board Panel 5pp 18456 089 24X Fiche 50-529,83/05/13,8305160034
- 8303160086 Memorandum supporting West Valley Agricultural Protection Council. Inc motion for discovery schedule Projected date for crop study completion 6 wks later than original date BERLIN.K West Valley Agricultural Protection Council, Inc. BERLIN.K Berlin. Roisman. Kessler & Cashdan 83/05/16. Atomic Bafety and Licensing Board Panel 3pp 18451 024 24X Fiche 50-329,83/05/16.8305160086
- 8305240482 Joint Applicants response to West Valley Agricultural Protection Council second set of interrogatories GENR.A C., PLATT.H E., BISCHOFF.C A. Shell & Wilmer B3/05/18. Atomic Safety and Licensing Board Panel 61pp 18572;292. 24X Fiche 50-529.83/05/18.8305240482
- 8305200488 Advises that time for Commission to review ALAB-713 expired Commission declined raview Dacision became final agency action on 830427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners CHILK/8 J Office of the Secretary of the Commission, 83/05/19, 0ffice of the Executive Legal Director Ip 18514 039, 24X Fiche 50-528,83/05/19,8305200488
- 8305310215 Requests opportunity to respond to West Vallay Agricultural Protection Council 830506 supplemental motion re FES QL stage & to argue relevancy if ASLB determines that consideration should be given OEHR.A C Bnell & Wilmer. OEHR.A C Arizona Public Service Co. 83/05/23. LAZO,R.M., CALLIHAN,D., CQLER F., Atomic Safety and Licensing Board Panel Spp 18658-137 24X Fiche.50-328,83/05/23,8305310215
- 8303270024 Response to West Valley Agricultural Protection Council 830306 motion for mod of discovery schedule Requests 10-day extension to answer motion since Joint Applicants & Council stipulation not received, Certificate of Svc encl DEWEY.L S Hearing Branch 1 83/05/26 Atomic Safety and Licensing Board Panel 4pp. 18640 059 24X Fiche. 50-529.83/05/26, 8305270024
- 9305310074 Response to West Valley Agricultural Protection Council. Inc supplemental motion for declaration that NEPA analysis inadequate for continuance of proceedings Request for new EIB & continuance should be denied W/Certificats of Syc. DENEY.L S Hearing Branch 3 83/05/26 Atomic Safety and Licensing Board Panel. 14pp 18655 105 24X Fiche 50-529.83/05/26. B305310074
- K Utility Final Safety Analysis Report (FBAR) & amends
- B305020089 Forwards Amend 11 to FBAR
 VAN BRUNT.E E Arizona Public Service Co B3/04/28. Office of
 Nuclear Reactor Regulation. Director 2pp 18274,123. 24X
 Fiche 30-328.83/04/28.8305020089

- --- 8305020092 Amend 11 to FBAR W/47 oversize figures Aperture cards are available in PDR
 - Arizona Public Bervice Co 83/04/30 806pp 18274 123 24X Fiche 50-528,83/04/28,8305020089
- @ Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list
 - M Division of Gafeguards & Inspection Programs (Post 83/03/21 Consolidated Edison Co of New York, Inc 8308 319 24X Fiche 50-000,83/03/21,8212060385 TAYLOR, J M TAYLUNI 2 83(103) 83(03/2 11200 18300 319
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
- SUC list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Service (Post 830103) 83/04/15 Consolidated Edison Co of New
 York, Inc. 126pp 18435 155 24X Fiche 30-000,83/04/15,8303040021
- 9303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- SUC list enc:
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc. 112pp 18383 087 24X Fiche 30-000,83/04/22.8303040023
- 8305170531 Forwards IE Insp Repts 50-528/83-10,50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance
 - onted CREMB, J. L. Division of Resident, Reactor Project & Engineering Programs. B3/04/22 VAN BRUNT, E. Arizona Public Service Co. 2pp. 18468 001 24X Fiche 50-528, 83/04/22, 8305170531
- --8305170537 IE Insp Repts 50-528/83-10.50-529/83-07 & 50-530/83-05 on B20601-830311 Noncompliance noted improper documentation of cable termination records ECKHARDT.J H, VORDERBRUEGGEN: ELIN, J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-528,83/04/22,8305170531.
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere
- Bensing Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305170560 Forwards IE Insp Repts 50-528/83-09,50-529/83-06 & 50-530/83-04 on 830404-07. No noncompliance noted STERNSERG, D M Region 5. Office of Director 83/04/25 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 128 24X Fiche: 50-528,83/04/25,8305170560
- --B305170564 IE Insp Repts 50-528/83-07:50-529/83-06 % 50-530/83-04 on 305170564 IE Insp Repts 30-528/83-07.50-529/83-06 & 30-530/83-04 on 830404-07 No noncompliance noted Major areas inspected allegations made by R Ounderson & W Royce in affidavits bafore ASLB on 830108 & 0225 VGRDERBRUEGGEN, FIGRELLI, G, BURDOIN, J Region 5, Office of Director 83/04/22 14pp 18468 130 24X Fiche 50-528,83/04/25,8305170560.
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs," Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 1155p 18382 047 24X Fichs 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Sys Heater High Temp Trip Setpoint Adjustment," Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co. of New 18382 145 24X Fich# 50-000, 83/04/28, 8303040027 118pp
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/03 Consolidated Edison Co York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303 24X Fiche 50-000, 83/05/03, 8303040028
- 830-3040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc. i12pp, 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Byo list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co York, Inc. 119pp 18441.001, 24X Fichs 30-000;83/05/04,8303 18441.001, 24X Fichs 50-000,83/05/04,8303040031

- B303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co of New Response (Post 830103) B3/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033
- 8305160009 Notification of 830525 meeting w/vtil & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1981 -Feb 1983 Region 5, Office of Director 83/05/10 Region 5, Office or rector 2pp 18456 079 24X Fiche 50-528,83/05/10,8305160008 Director
- 8305160089 Confirms 830525 meeting w/applicant at Deer Valley Project oft to discuss SALP for Jul 1981 Feb 1983
 CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs 807/05/10 VAN JRUNT, E. E. Artiona Public Service Co. 3pp. 18448 146 24x Fiche 50-528,83/05/10,8305160089
- --8305160179 SALP rept for Jul 1981 Feb 1983 * Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528, 63/05/10, 6305150089
- B303040034 IE Info Notice 83-30; "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/ii Consolidated Edison Co of Net 18524 003 24x Fich. 50-000.83/05/11.8303040034 114pp
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " 303040040 it into notice to the Sec list enct Sec list enct Sec list enct CARDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24X Fiche 30-000.83/05/19.8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 OO7 24% Fiche 50-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- B305030426 Interim Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Final rept by 830517 VAN BRUNTIE E Arizona Public Service Co 83/04/15, STERNBERG, D M Region 5. Office of Director 3pp 18303 339 24X Fiche 50-528,83/04/15,8305030626
- 8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection switches failure to meet requirements of TMI
 Task 18A Initially reported on 830304 Info will not be
 finalized until 830519, due to extensive investigation
 VAN RRUNT, E E Arizona Public Service Co 83/04/21 STERNBERG, D M
 Region 5, Office of Director 1p 18440 093 24X
 Fiche 30-528,83/04/21,8305130229
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 83/04/26. STAROSTECKI.R Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392
- ---8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation

 EMPEY.D C Rockwell International Corp 83/03/11 CDLLINS, J T 11 COLLING, J T operators notified of deviation EMPEY,D C Rockwell International Corp 83/03/ii Region 4, Office of Director 5pp 18433 074 24 Fiche 50-000,83/04/24,8305120392
- 8305130124 Deficiency Evaluation Rept 83-18 re installation of pipe supports which do not meet Seisnic IX requirements Initially reports which do not meet Seisnic IX requirements Initially reported on 830327 Deficiency determined not reportable per 10CFR50 55(e) Documentation will be maintained in files VAN BRUNT.E E Arisona Public Service Co 83/04/28 STERNBERG.D M Region 5, Office of Director 2pp 18438 059 24X Fiche 50-528,83/04/28,8305130124
- 8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 830404 Deficiency determined not reportable per 10CFR5Q 55(e) VAN BRUNT:E E Arizona Public Service Co 83/04/29 STERNBE Region 5, Office of Director 2pp 18437 185 24X Fiche 50-528,83/04/29,8305130159. 727 STERNBERGID M

- 8305130210 Advises that Deficiency Evaluation Rept DER 83-20 restartup test personnel qualifications not reportable per 10CR90 55(e)
 - TOURSO 35(e)
 VAN BRUNT, E E Arizona Public Service Co 83/04/27 STERNBERG, D M
 Region 5. Office of Director 1p 18440 090 24X
 Fiche 50-528,83/04/29,8305130210
- 8305130148 Revised Interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements Initially reported on 82124 Revised test plan reviewed by Bechtel Final rept expected by 830823 Also reported per Part 21 VAN GRUNT.E E Ariiona Public Service Co 83/05/03 SYERNBERG, D M Region 5, Office of Director 4pp 18438 117 24X Fiche 50-528,83/05/03.8305130148
- 8305130189 Final Deficiency Rept DER 83-12 re malfunction of GE add-on electric interlocks used w/Class IF,Size 2, starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21 VAN BRUNT.E E Apriona Public Service Co 83/05/03 STERNBERO, D M Regton 5, Office of Director 5pp 18439 340 24X Fiche 50-528,83/05/03,8305130189
- 8305130226 Rev 1 to Interim Deficiency Rept DER B2-80 re failure of Conax electrical penetration low level insulation resistance to meet qualification tests Initially reported on 821217 Testing in progress Next rept by 830714

 VAN BRUNT.E E Arizona Public Service Co 83/05/03 STERNBERG, D M Region 5. Office of Director 3pp 18437 188 24X Fiche 50-528,83/05/03.8305130226
- 8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test made ugon loss of power Initially regarted on 830318 Also reportable per iOCFR21 VAN BRUIN,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5. Office of Director 4pp 18439 238 24X Fiche 30-528.83/05/03.8305130264
- 8305230517 Final Deficiency Rept DER 83-21 re aperation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)
 VAN BRUNT, E E Arizona Public Service Co 83/05/06 STERNBERG, D M Ragion 5, Office of Director 2pp 18536 313 24X
 Fiche 50-528,83/05/06,8305230517
- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR
- A Application/construction stage documents & correspondence
- 8305170086 COMPARISON OF CRBR DESIGN BASIS EVENTS WITH THOSE OF FOREIGN LIMBER PLANTS

 AGRAMAL A K Brookhaven National Laboratory FIN A-3364

 NUREG/CR-3240 83/04/30 Clinch River Breeder Reactor Program

 Office BSpp Available at NRC \$5.00 18493 193 24X

 Fithe 50-337, 83/04/30, 8305170086
- B305110590 Notification of B30524 meeting w/DDE, Project Mgt Corp & TVA in Bethesda, MD to review status of applicant PRA GTARK/R M Clinch River Breeder Reactor Program Office 83/05/04 GRACE/J N Clinch River Breeder Reactor Program Office 3pp 18417 341 24X Fiche 50-537.83/05/04,8305110590
- 8305090659 Generic Ltr 83-20 to all operating reactor licensess tholders of CPs re integrated scheduling for implementation of plant mods Svc list encl
 EISENHUT,D,Q Division of Licensing 83/05/09 Consolidated Edison Co of New York: Inc 16pp 18627 153 24X Ficher 30-000,83/05/09,8305090659
- B305170449 Submits supplemental info to B30401 ltr re cable separation by confirming that approx 75 ft of DHR svc & steam generator auxiliary heat removal sys cable will be run in separate conduits or encl raceways

 LONGENECKER.J Energy, Dept of, Clinch River Breeder Reactor Flant
 B3/05/16 ORACE.J,N Clinch River Breeder Reactor Program Diffice
 Ip 18471 220 24X Fiche 50-537,83/05/16,8305170449
- B305230113 Forwards Rev 5 to Vol 2 to "Thermal Margin Beyond Design Base." Rev incorporates isotopic inventory for heterogeneous core.current meteorology, add1 organ doses & more realistic fu sparging calculations LONGENECKER.J Energy. Dept of, Clinch River Breeder Reactor Plant B3/05/17 ORACE.JN Clinch River Breeder Reactor Program Office ip 18696 200 24X Fiche 50-537, B3/05/17, B305230113
- --8305310003 Rev 5 to "Hypothetical Core Disruptive Accident Considerations in CRBRP." Vol 2, "Assessment of Thermal Margin Beyond Design Base" " & Emergy, Dept. of CRBRP-3 VO2 RO5 83/03/31 52pp 18696 201 24X Fiche 50-537

- 8305230285 Forwards Rev i to "CRBR Project Heat Transport Sys
 In-Containment Piping Reserve Seismic Margins" & rept re
 consequences of leeks from small diameter primary heat
 transport sys piping
 LUNOENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
 83/05/19 GRACE, J N Clinch River Breeder Reactor Program Office
 2pp 18539 043 24X Fiche 50-537,83/05/19,8305230285
- --8305230292 Rev 1 to "CRBR Project Heat Transport Bys In-Containment Piping Reserve Seismic Margins " MELLO.R M. CHANDRA.U., MALLETT.R H. Energy, Dept of, Clinch River Breeder Reactor Plant ES-LPD-B3-001 R01, 83/05/31 75pp 18539 045 24X Fiche 50-537, 83/05/19, 8305230285
- B Utility Preliminary Safety Analysis Report, emends
- B305200459 Forwards Amend 77 to PBAR LDNGENGECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B3/05/20 ORACE, J N Clinch River Breeder Reactor Program Office 4pp 18513 201 24X Fiche 50-537,83/05/20,8305200459
- --8305200463 Amend 77 to PBAR

 * Energy, Dept of, Clinch River Breeder Reactor Plant 63/05/31,
 166pp 18513-209 24X Fiche 50-537,83/05/20,8305200459,
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8305090013 Forwards SER (NUREG-094B, Suppl 1) including addl info received from applicant & ACRS comments GRACE.J N Clinch River Breader Reactor Program Office B3/05/02, LONDENECKER.J Energy, Dept of, Clinch River Breader Reactor Plant 32pp 18369 322 24X Fiche 50-537,83/05/02,8305090013.
- 8305060524 Forwards revised responses to SER Item & re QA, including info to complete identification of safety-related structures, sys & components controlled by CRBR QA program for PSAR Marked-up Tech Specs encl LONGENECKER, J Energy, Dept of 83/05/05 GRACE, JN Clinch River Breeder Reactor Program Office 18pp 1835; 095 24X Fiche 50-537,83/05/05,8305060324
- 8305230166 Forwards Suppl 1 to SER (NUREG-0968) re evaluation of addition on previously identified as outstanding review items since preparation of SER Response to comments for ACRS 830419 rept to Commission also encl M/o encls GRACE.J N Clinch River Breeder Reactor Program Office 83/05/19 LONGENECKER.J Energy, Dept of, Clinch River Breeder Reactor Plant 2pp 18596 140 24X Fiche 50-537,83/05/19.8305250166
- 8305240022 Forwards Suppl 2 to SER (NUREG-0968) re evaluation of addlenge on previously identified outstanding review items ORAGE.J N Clinch River Breeder Reactor Program Office. 83/05/20 LONGENECKER.J Energy Dept of Clinch River Breeder Reactor Plant 16pp 18577 314 24X Fiche 50-537.83/05/20.8305240022
- 8305170057 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No 50-537 (U 8 Department of Energy, Tennessee Valley Authority And Project Management Corporation)

 w Clinch River Breeder Reactor Program Office NUREG-0768 801 83/05/31 36p 18493 159 24% Fiche 50-537, 83/05/31, 8305170057
- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enc!

 EISENHUT, D 0 Division of Licensing 83/05/11, Consolidated Edison Co of New York, Inc 16pp 18340 095 24X

 Fiche 50-000,83/05/11,8305110034
- O Adjudicatory correspondence
- 8303240390 Suppl to 830307 schedule motion Parties need definite milestones to work toward commencement of hearings EDDAR, G L Project Management Corp. LUCK, N.D Energy, Dept of. 83/03/23 Atomic 88-ety and Licensing Board Panel 4pp 17479 117 24X Fichs 50-537,83/03/23,8303240390.
- --8303240394 Forwards draft statement of scope & schedule for forthcoming CP hearings & requests teleon to discuss schedule Certificate of Svc encl EDOAR, C L. Horgan, Lewis & Bockius, 83/03/02 TURK, B E. Hearing Branch i FinAMDRE, B.A. Natural Resources Defense Council. 6pp 17679 121 24% Fiche 30-537, 83/03/23, 83/03/240390

- B305030572 Requests to make limited appearance statement at B30718 CP hearings re regional socioeconomic impacts PATE.D S Affiliation Unknown B3/04/27 CHILK.S J Office of the Secretary of the Commission 1p 18306 117 24X Fiche 50-537,83704/27,8305030572
- 8305030490 Advises that NRC will not file separate response to util 830427 motion to dismiss intervenor Contention 10 NRC position agreeing contention is no longer in issue was accurately represented in util motion MIZUNG. 0 S Hearing Branch 1 83/04/29 MILLER.M. LINENBERGER.O HAND.C H Atomic 84fety and Licensing Board Panel ip 18292 175 24X Fichs 50-537.83/04/29.8305030490
- 8305030502 Motion for extension of time for discovery permitted by 830327 CP scheduling order to provide apportunity to prepare questions & responses to documentation supporting CP contentions WiCertificate of Svc FINAMORE, B A. WEISS, E R. Natural Resources Defense Council WEISS, E R. Sierra Club 83/04/27 MILLER, M E., LINEMBERGER, G., HAND, C H. Atomic Safety and Licensing Board Panel 9pp 18306-183-24X Fiche 50-537,83/04/27,8305030502
- B305030483 Notice of T Cochran B30509 deposition in Washington, DC re Contentions la-b.3a-c.9c & 9f-g Certificate of Svc encl MIZUND.0 B Hearing Branch 1 83/05/02 3pp 18308 247. 24X Fiche 50-537.83/05/02.8305030483
- 8305030542 Suppl to updated response to intervenor interrogatories transmitting A Schwallie.RE Hottel.EK Sliger & HP Planchon statements of prof qualifications Centificate of Svc encl busint Applicants-Clinch River Breeder Reactor 83/05/02 Natural Resources Defense Council 12pp 18305 266 24X Fiche 50-537.63/05/02.8305030042
- B305060317 Advises that NRC will not file formal response to applicant B30427 motion to dismiss intervenor Contentions 2(#), (g) & (h) NRC position agreeing that contentions no longer in issue is correct TURK. B E Hearing Branch 1 83/05/05 MILLER, M. LINENBERGER, 9, HAND. C H Atomic Befsty and Licensing Board Panel 1p 18344 151 24X Fiche 50-337,83/05/03,8303060317
- B305090499 Order concurring w/ALAB-721 denying stay of effectiveness of partial initial decision authorizing issuance of LWA
 Btatements of Commissioners Palladino, Ahearne & Gilinsky encl
 HOYLE, J C Commissioners 83/05/05 Energy, Dept of 7pp 18341 141 24X Fiche 50-537,83/05/05,8305090499
- B305100022 Confirms that B30509 Cochran deposition re Contentions 1(a)-(b) 3(a)-(c) & 9(c), (f) & (g) rescheduled for B30512 in Hashington, DC TURK, S E Hearing Branch 1 83/05/04 FINAMORE, B A Natural Resources Defense Council FINAMORE, B A Finamore, B A 1p 18377 151 24X Fiche 30-537,83/05/06,8305100022
- 8305100210 Response to applicant 830421 tenth set of interrogatories Related correspondence FINAHORE, B A Natural Resources Defense Council B3/05/06 10pp 18374 037 24X Fiche 50-537,83/05/06,8305100210
- 8305100276 Affidavit of TB Cochran re answers to interrogatories Related correspondence COCHRANT B Natural Resources Defense Council 83/05/06 Atomic Bafety and Licensing Board Panel 1p 18371 242 24X Fiche 50-537,83/05/06
- 8305100350 Supplementary response to eighth & ninth set of interrogatories dtd 830401 & OB Review of SER & related documentation incomplete, hindering response to certain interrogatories Related correspondence FINAHORE, B. A. Natural Resources Defense Council FINAHORE, B. A. Bierra Club 83/05/06 MILLER, M. E., LINENBERGER, G., HAND, C. H. Atomic Safety and Licensing Board Panel 15pp 18410 321. 24x Fiche. 50-537. 83/05/06, 8305100350
- 8305120291 Certifies svc on 830506 of intervenor supplementary response to applicant eighth & ninth set of interrogetories dtd 830401 & 08 & intervenor response to applicant tenth set of interrogetories dtd 830421 FINAMORE, B A Natural Resources Defense Council FINAMORE, B A. 81erra Club 83/05/06 3pp. 18424 122 24X Fiche 50-537,83/05/06,83051220291
- 8305110220 Response opposing intervenor 830427 motion for extension of time. Good cause not demonstrated EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/09 Atomic Safety and Licensing Board Panel 11pp 18407 052 24X Fiche 50-537,83/03/09,8305110220

- 8305110337 Notice of 830513 conference w/parties in proceeding & respective counsel in Bethesda-MD to discuss pending motions & requests
 MILLER.M E Atomic Safety and Licensing Board Panel 83/05/07 1918406 177 24X Fiche 50-337.83/05/09.8305110337
- B30511043B Response to first set of CP interrogatories & request to produce Requested documents will be made available for insp & copying Related correspondence
 * Energy, Dept of * Project Management Corp * Tennessee Valley Authority B3/09/07 Natural Resources Defense Council 2pp 18405 008 24X Fiche 50-537,83/05/09,830511043B
- Valley Authority B3/05/09 Natural Resources Defense Counci 2pp 18405 008 24X Fiche 50-537, 83/05/09, 8305110438 B305110448 Responds to second set of CP interrogatories Aerosol
- plateout & fallout calculations discussed Affidavit encl
 Related correspondence
 * Energy, Dept of * Project Management Corp * Tennessee
 Valley Authority 83/05/07 Natural Resources Defense Council
 7pp 18403 010 24X Fiche 50-537,83/05/09,8305110448
- 8305120313 Certifies svc on 830507 ED0AR, G L Project Management Corp 83/05/09 3pp 18424 102 24X Fiche 50-537,83/05/09,8305120313
- 8305110445 Forwards corrected 830509 response to NRDC & Sierra Club first set of interrogatories & request to produce directed to applicant Driginal document not identified as response SCHMUTZ.TA Morgan Lewis & Bockius 83/05/10 Dacieting & Services Branch ip 18405 048 24X Fiche 50-537,83/03/10,8305100445
- --B305110449 Corrected response to first set of interrogatories & request to produce Requested documents will be made available for insp & copying * Energy, Dept of * Project Management Corp * Tennessee Valley Authority B3/05/07 Natural Resources Defense Council 2pp 18405 047 24X Fiche 50-537, B3/05/10, B305110445
- B305110450 Amended response to NRDC & Sierra Club 830407 first set of CP interrogatories & request to produce Discusses NRC best estimate of containment failure pressure Affidavit and TURK. S E Hearing Branch 1 83/05/10 Natural Resources Defense Council 3pp 18405 058 24X Fiche 50-537.83/05/10.8305110450
- --8305i10455 Response to NRDC & Sierra Club 830426 second set of CP interrogatories & request to produce Affidavits & Certificate of Svc encil TURK.S E Hearing Branch 1 83/05/10 Natural Resources Defense Council 12pp 18405 061 24X Fiche 50-537,83/05/10.8303110450
- B305130063 Submission of encl to NRC B30510 response to second set of CP interrogatories Certificate of Svc encl TURK, S E Hearing Branch i B3/05/11 Natural Resources Defense Gouncil 9p 18436-304 24K Fiche 50-537,83/05/11
- 8305160128 Response opposing NRDC & Sierra Club 830429 motion for extension until 830708 to complete discovery Delay in hearing schedule to permit further discovery unreasonable Two Certificates of Svc encl
 TURK.8 E Hearing Branch I 83/05/13 Atomic Safety and Licensing Board Panel 7pp 18446 105 24X Fiche 50-537,83/05/13,8305160128
- 8305160149 Response to 830427 second set of CP interrogatories & request for admissions Related correspondence FINAMORE, BA, WEISS, ER Natural Resources Defense Council WEISS, ER Sierra Club 83/05/13 Office of the Executive Legal Director 13pp 18445 088 24X Fiche 50-537,83/05/13,8305160149
- B305160191 Response to B30429 eleventh set of interrogatories & request for admissions Certificate of Svc encl Related correspondence FINAMORE.B A, WEISS.E R Natural Resources Defense Council WEISS.E R Sierra Club B3/05/13 Joint Applicants-Clinch River Breeder Reactor 36pp 18445 092 24X Fiche 50-537, B3/05/13, B305160181
- 8305190204 Order following B30513 conference w/parties Remaining contentions are Contentions 1 re envelope of DBA not including core disruptive accidents. 3 re core disruptive accidents & P(c). (f) & (g) re emergency planning MILLER.M E Atomic Safety and Licensing Board Panel B3/05/17 10pp 18502 195 24X Fiche 50-537.83/05/17.8303190204
- 8305190221 Third set of CP interrogatories & request to produce Certificate of Svc encl Related correspondence FINAMORE D A., WEISB,E R. Natural Resources Defense Council WEISB,E R. Sierra Club. 53/05/17 Office of the Executive Legal Director 7pp 18501 323 24x Fiche 50-537,83/05/17,8305190221

- 8305190337 Notification re PRA status rept Encl Phase I PRA rept not submitted to NRC for review Results of rept insignificant to proceeding W/o Phase I rept Certificate of Svc encl EDGAR.G L Project Hanagement Corp LUCK.W D Energy, Dept of 83/05/18 6pp 18500-212 24X Fiche 50-537.83/05/18,8305190339
- B305240553 Brief supporting exceptions to ASLB B30228 partial initial decision re LWA FINAMORE.B A . WEISS,E R Natural Resources Defense Council, WEISS,E R Bierra Club B3/05/1B Atomic Bafety and Licensing Board Panel B9pp 18575 294 24X Fiche 50-537,83/05/18, 8305240553
- 8303200636 Motion for summary disposition of Contention 9(g) re emergency plans No genuine issue of mat1 fact exists EDGAR.O L Project Management Corp LUCK.W D Energy, Dept of 83/05/19 Atomic Safety and Licensing Board Panel 4pp 18519 327 24X Fiche 50~537.83/05/19.8305200636
- --8305200648 Statement of matl facts as to which there is no genuine issue re Contention 9(q) on emergency planning Certificate of Svc encl EDGAR, O.L. Project Management Corp. LUCK, W.D. Energy, Dept. of 83/05/19. Atomic Sefety and Licensing Board Panel. 5pp. 18519-333. 24X Ficher 50-537, 83/05/19, 8305200636
- 8305240070 Response to 830517 third set of CP interrogatories & request to produce Certificate of Syc and TURK, S.E. Hearing Branch i 83/05/20 Natural Resources Defense Council 15pp 18549 078 24X Fiche 50-537, 83/05/20, 8305240070
- B305240475 Motion for summary disposition of intervenor Contentions 9(c) k 9(f) re adequary of evacuation time analysis in PSAR. No genuine issue of matl fact exists k applicant entitled to favorable decision Certificate of 8vc encl EDDAR, 0 L Project Management Corp LUCK, W D Energy, Dept of. 83/05/23 Atomic Safety and Licensing Board Panel 10pp 18949 345 R4X Fiche 50-537, 83/05/23, 8309240475
- 8305240480 Statement of mati facts as to which there is no genuine issue re Contentions 9(c) & (f) on emergency plans EDGAR, 0 L Project Management Corp. LUCK, N D Energy, Dept of 83705723 Atomic Safety and Licensing Board Panel 3pp 18571 266 24X Fichs 50-537,83/05/23,8305240480
- 8305240503 Motion for extension until 830722 to file response to intervenors 830518 brief in support of exceptions Ceptificate of Svc encl EDDAR.0 L Project Management Corp &UCK:W D Energy, Dept of 83/05/23 Atomic Safety and Licensing Appeal Panel 6pp 18571 238 24X Fiche 50-537,83705/23,8305240503
- 83053(0189 Notification of pending litigation re NRDC 82100) motion to expedite consideration of emergency motion to amend US District Court of Appeals remand & to review EPA regulations. Certificate of Svc encl EDGAR. G L. Project Menagement Corp LUCK, W D. Energy, Dept of 83/05/27 11ep 18652,271 24X Fiche 50-537.89/05/27.8305310188
- L. Limited work authorization & related correspondence
- 8305260001 Forwards notice of issuance of LWA-1 constituting authorization to conduct activities described in 770401 request & revised site preparation activities rept dtd June 1982 GRACE. J N Clinch River Breeder Reactor Program Office. 83/05/19 LONGENECKER. J Energy. Dept of, Clinch River Breeder Reactor Plant. App 18649 105 24X Fiche 50-537.83/05/19.8305260001
- --8305260002 Notice of issuance of LWA-1, authorizing util, DDE & Project Mgt Corp to conduct certain site activities prior to decision on issuance of CP GRACE, J N Clinch River Breeder Reactor Program Office B3/05/19, 3pp 18649, 109 24X Fiche 50-537, 83/05/19, 8305260001
- D Advisory Committee on Reactor Safeguards reports & correspondence
- B30414015B Summary of ACRS CRBR Bubcommittee meeting on 821027 in Mashington, DC re plant design criteria, rationals of selection of DBA spectrum & associated prevention/ mitigation syst & plant sefeguards & security.

 a ACRS Advisory Committee on Reactor Bafeguards 82/10/29.
 ACRS Advisory Committee on Reactor Safeguards 82/10/29.
 24X Fiche 50-537, 82/10/29, 8304140158

- B305160299 Forwards rept summarizing review of TMBDB presentation at ACRS 830310-11 meetings Review confined to thermomechanics, engineering design & finite element analysis Review will be summarized at 830414 meeting ANDERSON.C A Los Alamos Scientific Laboratory ANDERSON.C A ACRE Advisory Committee on Reactor Safeguards 83/03/29. CARBON.K, ACRS Advisory Committee on Reactor Safeguards 6pp 18472 069, 24X Fiche 50-537,83/03/29,8305160299
- B305130359 Telecopy of comments on CRBR re pressure boundary Design of reactor pressure vessel meets & usually exceeds requirements of ABME 111 & relevant code cases BUSH-S H Battelle Hemorial Institute, Pacific Northwest Laboratory BUSH-S H ACRS Advisory Committee on Reactor Safguerds, B3703/30 CARBON, M ACRS Advisory Committee on Reactor Bafeguerds 2pp 18443 324 24X Fiche 50-537.83/03/30.8305130359.
- 8305130349 Submits comments on core disruptive accidents & seismic margins per request made at ACRB B30315-17 meetings Applicant energetic source term acceptable Seismic margin calculations not acceptable LIPINSKI, W. C. ACRB Advisory Committee on Reactor Safeguards 83/03/31. CARBON'N W. ACRB Advisory Committee on Reactor Safeguards 3pp. 18457-340. 24X Fiche 50-537.83/03/31.8305130349
- 8305130350 Comments on seismic design safety margin for facility Additionments to be made at ACRS 830414 mesting SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS Advisory Committee on Reactor Safeguards 83/03/31, BDEFANERT,P, ACRS Advisory Committee on Reactor Safeguards, 3pp 18443:357 24X Fiche 50-537,83/03/31,8305130350,
- 8303130335 Provides input re-seismic sefety margins for CRBR, based on ongoing seismic safety margins research program at lab BDRH.H.P. ACRB Advisory BDHH.H.P. ACRB Advisory Committee on Reactor Safeguards 83/04/08 CARBON.H ACRB Advisory Committee on Reactor Safeguards App 18443 326. 24X Fiche 30-537,83/04/08,8305130355.
- 8305180637 Expresses appreciation for opportunity to participate in CRBR project review Seismic safety margin estimates probably conservative Failure of small diameter pipes will be discussed

 BEIDENSTICKER Argonne National Laboratory BEIDENSTICKER ACRS Advisory Committee on Reactor Safeguards 83/04/15, CARBON:M ACRS Advisory Committee on Reactor Safeguards 1p. 18505.327, 24X Fiche 50-537.83/04/15,8305180637.
- 8305120556 "Consultant Rept for ACRS Review of CRBR Thermal Margin Beyond Design Basis " POMERS,D A. Sandia Laboratories POMERS,D A ACRS - Advisory Committee on Reactor Safeguards B3/05/10. 30pp 18443:070. 24X Fiche.50-537,83/05/10.8305120556
- O Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Expthermic Chemical Reaction " Byc list and!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319, 24X Fichs 50-000,83/03/21,8212060385.
- 8305270472 Forwards IE Insp Rept 50-537/83-01 on B30315.No noncompliance noted DANCE: H.C. Division of Project & Resident Programs 83/04/06, BREMINGTON, P. Energy, Dept. of, Clinch River Breeder Reactor Plant 2pp 18644-081, 24x Fiche-50-537, B3/04/06, 8305270472.
- --8305270482 IE Insp Rept 50-537/83-01 on 830315 No noncompliance noted Project mpt meeting, warehouse tours & site tour conducted. IGNATONIS, A J Region 2. Office of Director BROWNLEE, V. L. Division of Project & Resident Programs. 83/04/06, 4pp 18644.083 24X Fichs 50-537,83/04/06.8305270472
- 8305270314 Forwards IE Insp Rept 50-537/83-02 on 830328-0401 No noncompliance noted.

 DANCE/H C Division of Project & Resident Programs. 83/04/14.

 BREWINGTON: P Energy, Dept of, Clinch River Breeder Reactor Plant 2pp. 18642 204 24X Fiche: 50-537, 83/04/14, 8305270314.
- --B305270319 IE Insp Rept 50-537/83-02 on B30328-0401, No noncompliance noted Major areas inspected pre-CP GA activities MCFARLAND,C, R Region 2. Office of Director. UPRIOHT.C. M. Division of Engineering & Radiological Safety Programs. B3/04/13. 4pp. 18642 206 24X Fiche 30-537.83/04/14.8305270314
- 8303040021 IE Info Notice 83-21. "Defective Emergency Use Respirator" Svc list enc!

 JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15. Consolidated Edison Co. of New York: Inc 126pp. 18435 155 24X Fiche 50-000;83/04/15,8303040021

- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bansing Bys " Svc list encl JORDAN: EL Division of Emergency Praparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000.83/04/25,8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Bide of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026
- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York: Inc 118pp 18382 165 24X Fiche 50-000:83/04/28:8303040027
- 8305270197 Forwards IE Insp Rept 50-537/83-03 on 830404-06 No
- --8305270200 IE Insp Rept 50-537/83-03 on 830404-06 No noncompliance ### 1952/0200 IE Insp Rept 30-33/03-03 in B35-04 33 in B3
- B303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Syc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382.282 24X Fiche, 30-000, 83/05/04, 8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04. Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Gaussd by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523-248 24X Fichs 50-000,83/05/06,8303040033
- 8305270273 Forwards IE Insp Rept 50-537/83-04 on 830411-15 No noncompliance noted noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/05/06
 BREWINGTON, P Energy, Dept of, Clinch River Breeder Reactor Plant
 2pp 18644 268, 24% Fiche 50-537,83/05/06,8305270273
- -8305270278 IE Insp Rept 50-537/83-04 on 830411-15 No noncompliance noted Major areas inspected preconst GA activities JACKBON, L., UPRIGHT, C.M. Region 2. Office of Director 83/05/06 4pp. 18644, 270 24x Fiche 50-537, 83/05/06, 8305270273 83/05/02
- B303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines." Svc list enct.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/11. Consolidated Edison Co. of New York, Inc 114pp. 18524.003 24X Fiche 50-000, 83/05/11, 8303040034
- 8303040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program " Bvc list encl.

 JORDAN, E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp. 18697.009. 24X Fiche 50-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103), 83/05/26. Consolidated Edison Co of New
 York, Inc. 114pp, 18647 007 24X Fiche 50-000,83/05/26,8303040046

- T Hearing transcripts on non-antitrust matters
- 8305170293 Transcript of 830513 conference in Bethesda, MD Po 7, 106-7, 279 * Atomic Safety and Licensing Board Panel 83/0 18464 149 24x Fiche 50~537,83/09/13,8305170293 83/05/13 184pp
- U Congressional/Executive Correspondence
- B305240019 Responds to B30418 ltr recommending retention of technical cadre of experts to review CRBR & overall DDE breeder program Maint of CRBR Program Dfc at adequate level planned Decision on issuance of CP expected by June 1984 DIRCKS,W J Office of the Executive Director for Operations B3/05/10 LLOYD,M House of Rep. Science & Technology 3pp 18977 308 24X Fiche 30-537.83/05/10.8305240019
- --B305240023 Recommends that Commission retain technical cadre of experts to review CRBR & overall DDE breeder program LLQVD.H House of Rep. Science & Technology B3/04/18 PALLADINO.N J Commissioners ip 18577-310 24X Fiche 50~537,83/05/10,8305240019
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8305230634 Ack receipt of ltr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron 83/03/10
- THICKNAYS W Public Service Co of Indiana. Inc. 83
 YOURTELLOTTE.J Regulatory Reform Task Force 2pp
 Fiche 50-546.83/03/10.8305230654 18542 352
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting
 TOURTELLDITE, J Regulatory Reform Task Force 83/04/11
 PALLADIND, N J Commissioners 2pp 18542 272 24X
 Fiche 50-000.83/04/11,8305230720
- 8305120457 Confirms 830414 commitment re electrical cable tray hanger installation under conditions outlined in 830203 confirmatory action ltr Request to restart installation of hancers renewed BHIGLDS,S W Public Service Co of Indiana, Inc KEPPLER,J G Region 3, Office of Director 3pp Fiche.50-546,83/04/15,8305120457 18434 036 24X
- 8304250167 Application for amend of CPPR-170 & CPPR-171 (filed in PDR Category A).consisting of Amend 24 to FBAR (filed in PDR Category K) & Suppl I to environ rept OL stage (filed in PDR Category C)

 SHIELDS.8 W Public Service Co of Indiana, Inc 83/04/21
 DENTON.H R Office of Nuclear Reactor Regulation, Director 16pp
 18212 083 24X Fiche 50-546,83/04/21,8304250167
- 8305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984 YOUNOBLOOD, B J Licensing Branch I 83/04/28 YOST, F E Utility Data Institute 1p 18434 279 24X Fiche 50-546,83/04/28. 8305110185.
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list enci EISENMUT.D. O Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000.83/05/09.8305090659 Consolidated
- B305130119 Forwards response to Generic Ltr B3-10C re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps "Response to Items I le. I 3a & I 3c will be addressed in FBAR.App E.scheduled for submittal by B40331
 BHIELDS.S W Public Service Co of Indiana. Inc 83/05/07
 EIBENHUID Q Division of Licensing 5pp 18437 353 24X
 Fiche 50-546,83/05/09.830513019
- B305230635 Forwards request for add1 info re environ qualification of electrical & mechanical equipment Schedular commitment for submittal of program should be provided within 30 days YOUNOBLODD, B J Licensing Branch 1 B3/05/10 SHIELDS, S W Publ: Bervice Co. of Indiana, Inc. 4pp 18543 021 24X Fiche 50-546. B3/05/10. B305230635 SHIELDS, S W Public

- B305170306 Application to amend GPPR-170 & CPPR-171 w/submittal of revised Suppl I to environ rept - OL stage Affidavit of Distribution enc] SHIELDS.S W Public Service Co of Indiana, Inc SHIELDS.S W
 - Distribution encl
 SHIELDS.5 W Public Service Co of Indiana, Inc SHIELDS.5 W
 Wabash Valley Power Association, Inc 83/03/13 DENTON.4 R Diffice
 of Nuclear Reactor Regulation, Director 6pp 18466 024 24X
 Fiche 30-346,83/03/13.8305170306
- --8305170312 Revised Suppl 1 to environ mept QL stage * Public Service Co of Indiana, Inc 83/05/31 1p 18466 030 24X Fiche 50-546,83/05/13,8305170306
- 8305200289 Forwards Amend 25 to CP & OL applications, including revs to security plan Amend withheld (ref 10CFR2 790)
 SHIELDS.E W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18516 319 24X
 Fiche 50-546, 83/05/16,8305200289
- C Utility Environmental Report (ER), amends & correspondence
- 8304250167 Forwards Suppl 1 to environ rept OL stage (filed in PDR Category C) Supporting repts oncl
 SHIELDS.5 W Public Service Co of Indiana. Inc 83/04/21
 BENTON.H R Office of Nuclear Reactor Regulation. Director 16pp
 18212 083 24X Fiche 50-546.83/04/21.8304250167
- B305110185 Responds to B30413 ltr re B30325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984 YOUNGBLOOD, B J Licensing Branch I B3/04/28 YOST, F E Utility Data Institute 1p 18434 279 24X Fiche 50-546, B3/04/28, B305110185
- B305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ tept GL stage Affidavit of Distribution encl SHIELDS:S W Public Service Co of Indiana, Inc SHIELDS:S W Wabash Valley Power Association, Inc B3/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18466-024 24X Fiche 50-546/83/05/13,8305170306
- --8305170312 Hevised Suppl 1 to environ rept OL stage # Public Service Co of Indiana, Inc 03/05/31 1p 18466 030 24X Fiche 50-546,83/05/13,8305170306
- F Security, medical, emergency & fire protection plans
- 8305:10034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enc!
 EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 160p 18540 095 24X
 Fich & 50-000.83/05/11.8305110034
- B305240213 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983 DIRCKG,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13,8305240213
- 8305200289 Forwards Amend 25 to CP & OL applications, including revs to security plan Amend withheld (ref 10CFR2 790)
 8H[ELDS,8 W Public Service Co of Indiana, Inc SHIELDS,8 W Wabash Valley Power Association, Inc 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18516 319 24X
 Fiche 50-546,83/05/16.8305200289
- B305260233 Advises of B30527 prompt notification sys development meeting in Clarksville, IN to discuss objectives & design of emergency planning ione KNIGHT, N.R. Public Service Co of Indiana, Inc. B3/05/18 AXELSON, H.L. Region 3, Office of Director ip 18599 338 24X Fiche 50-546,83/05/18,8305260233
- G Adjudicatory correspondence
- 8305130073 Answer to Indiana Sassafras Audubon Society (ISAS) petition for leave to intervene ISAS fails to establish right to intervene Certificate of Svc encl

 Public Service Co of Indiana. Inc * Wabash Valley Power Association. Inc * LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 11pp 18436 251 24% Fiche 50-546.83/05/12.83305/30073

- 8305130098 Response w/o objection to Save the Valley petition for leave to intervene, provided applicant may object to contentions & right to hearing after petition suppl filed Certificate of Svc encl VOIOT, H Public Service Co of Indiana, Inc VOIOT, H Wabash Valley Power Association, Inc VOIOT, H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 4pp 18438 097 24X Fiche 30-946, 63/05/12, 8305130078
- 8305130244 Response opposing Valley Watch, Inc 820427 petition for leave to intervene in proceeding Petitioner fails to establish sufficient interest in proceeding to establish standing as matter of right or discretion WiCentificate of Svc VOIGT.H H Public Service Co of Indiana, Inc VOIGT.H H. Wabsah Valley Power Association, Inc VOIGT.H H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners lipp 18439 174 24% Fiche 30-346,83/05/12,8305130244
- 8305160146 Response in opposition to Valley Watch. Inc 830419 patition for intervention & request for public hearing re CL application Petition has not established requisite standing to intervene Certificate of Svc encl CHANLE I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 078 24X Fiche 50-546:83/05/12.
- B305160158 Response to Bave the Valley petition to intervene Requisite standing to intervene established Aspects of proceeding to be addressed by intervenor identified Certificate of Bvc encl CHAN, E I Hearing Branch 2 B3/05/12 Atomic Bafety and Licensing Board Panel Tipp 18445 141 24X Fiche 30-546.83/05/12.8305160159
- 8305170003 Response to Sassafras Audubon Soc of South Central Indiana B30416 petition to intervene Requisite standing to intervene not established Specific aspects appropriate for consideration identified by Soc Centificate of Svc encl CHAN, E. I. Hearing Branch 2 B3/05/13 Atomic Safety and Licensing Board Panel 11pp 18466 231 24X Fiche 50-546, B3/05/13, B305170003
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8304250167 Forwards Amend 24 to FSAR (filed in PDR Category K) W/277 oversize drawings Aperture cards are available in PDR SHIELDS.8 W Public Service Co of Indiana. Inc. 83/04/21 DENTON.H R Office of Nuclear Reactor Regulation. Director 16212 083 24X Fiche. 50-546.83/04/21.8304250167
- --8304250190 Amend 24 to FSAR W/277 oversize drawings Aperture cards are available in PDR = Public Service Co of Indiana, Inc. 83/04/30 139pp 18212 099 24X Fiche 50-546,83/04/21,8304250167
- G Inspection reports, IE Bulletins & correspondence
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Progrem "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/03/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040.
- B212060395 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chamical Reaction " Svc list enc!

 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York. Inc 112pp 18308 319 24% Fiche 50-000,83/03/21.8212060385
- 8303040021 IE Info Notice B3-21, "Defective Emergency Use Respirator solve list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Cansolidated Edison Co of New York, Inc. 126pp 18435 155 24X Fiche 50-000,83/04/15,830304002
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list encl JORRANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383 089 24X Fiche: 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list enc! JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271, 24X Fiche 50-000.83/04/25,8303040025

- 8305120419 Forwards IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 & notice of violation BPESSARD: R L. Division of Engineering 83/04/25 SHIELDS, 6 W Public Service Co of Indiana, Inc. 2pp 18434-051 24X Fiche 50-546,83/04/25,8305120419
- --8305120423 Notice of violation from insp on 830124-28 & 0224-25 SPESSARD, R L Division of Engineering 83/04/25 App 18434 053 24X Fiche 50-546, 83/04/25, 8305120419
- --B305120428 IE Insp Repts 50-346/83-01 % 50-347/83-01 on 830124-28 & 0224-28 Noncompliance noted failure to assure that applicable requirements translated into instructions, procedures or drawings Nonconforming Items not tagged LdVE, R S . MENDEZ, R, WILLIAMS, C Region 3, Office of Director 83/04/20 23pp 18434 037 24X Fiche 50-346.83/04/28,8303120419
- 8305170148 Forwards IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance moted STREETER.J F Region 3, Office of Director 83/04/27 SHIELDS,8 W Public Service Co of Indiana, Inc 2pp 18466 285 24X Fiche 50-546,83/04/27,8305170148
- --8305170153 IE Insp Repts 50-544/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted Major areas inspected electrical contractors GA program.implementing procedures & training VANDEL.TE, KISH.JN, HAKKINS,FC Region 3, Dffice of Director 83/04/27 App 18466 287 24X Fichs 50-546,83/04/27,8305170148
- EL 33040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" Svc list encl JORDAN, L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000.83/04/28.8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDÁN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidate
- 830304002B IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Syt list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Contolidated Edison Co of New York, Int 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Byc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Ine 112pp 18382 282 24X Fiche 30-000.83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list enc!
 JURDAN, E. L. Division of Emergency Preparadness & Engineering Response (Past 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034
- 8303040046 IE Info Notice 83-33. "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046
- 8 Reportable occurrences, LERs & related correspondence
- 8305020291 Final deficiency rept re-potential for inaccurate indication of Westinghouse mfg gate valve position Initially reported on 821222 Westinghouse issued field change notice documenting corrective actions SHIELDS.5 W Public Service Co of Indiana, Inc. 83/04/21 KEPPLER.J G Region 3. Office of Director 2pp. 18281 296—24X Fiche 50-546.83/04/21.8305020291

- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAHE/E P Westinghouse Electric Corp 83/04/21 DEYCUNG, R C Director s Office, Office of Inspection and Enforcement 5pp 18405 095 244 Fiche 50-000.83/04/21,830510427
- B305020i18 Final deficiency rept re interference between rear attachment brackets & mechanical snubber pivot mount brackets initially reported on B30325 Rear brackets will be returned to ITT Orinnel for reworking SHIELDS: S W Public Service Co of Indiana, Inc. B3/04/22 KEPPLER: J G. Region 3. Office of Director 1p 18278 217 24X Fiche 30-546,83/04/22,8305020118
- B305110324 Part 2: rept re Type SA-1 Class iE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
 DUVALL.D D Brown Bover: Corp (subs Brown Bover: & Co., Ltd.)
 B3/04/27 STFLLO.V Director's Office. Office of Inspection and Enforcement 5pp 18373 278 24X Fiche 50-000, B3/04/27, B305110324
- 8305040494 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on 800509 Hestinghouse 2 util working to refine equipment mod to mutual satisfaction Next rept by 831028 SHIELDS, S W Public Service Co of Indiana, Inc. 83/04/28 KEPPLER, J G Region 3, Office of Director 2pp. 18319-264 24X Fiche 50-546,83/04/28.8305040494
- 8305130207 Interim deficiency rept re problem involving embedded plates in primary shield wall w/deformed wire anchors missing or welds between plate % anchor being cracked Initially reported on 820818 Caused by axial tensile stresses SHIELDS.S W Public Service Co of Indiana. Inc 83/05/07 KEPPLER.J & Region 3. Office of Director 2pp 18439 395 24X Fiche 50-544,83/05/09.8305130207
- 8305240408 Final deficiency rept re potential for improper operation of DS-416 reactor trip switchgear undervoltage attachments Initially reported on 830421 Attachments to be replaced w/ attachments having modified grooves
 8HIELDS.S W Public Service Co of Indiana, Inc 83/05/16
 KEPPLER.J O Region 3, Office of Director 2pp 18574 277 24X
 Fiche 50-544.83/05/16.8305240408
- B305260332 Interim deficiency rept re Commonwealth-Lord Joint Venture failure to adequately implement GA program Initially reported on 830211 Nonconformance repts for items not previously audited written Next rept by B30803 SMIELDS.8 W Public Service Co of Indiana. Inc 83/05/18 KEPPLER.J G Region 3. Office of Director 2pp 18625 005 24% Fiche 50-546.83/05/18.8305260332
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8305230654 Ack receipt of ltr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron increases
 EMIELDS: 8 W Public Service Co of Indiana, Inc 83/03/10 TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18542 352 24X Fiche 50-546,83/03/10,8305230654
- 8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLAPIND.N J Commissioners 2pp 18542 272 24X Fiche 30-900.83/04/11.8305230720
- 8305120457 Confirms 030414 commitment re electrical cable tray hanger installation under conditions outlined in 830203 confirmatory action ltr Request to restart installation of hangers renewed SHIELDS. B W Public Service Co of Indiana, Inc 83/04/15 KEPPLER.J 9 Region 3; Office of Director 3pp 18434 036 24X. Fiche 50-546,83/04/15,8305120457
- 83D4250167 Application for amend of CPPR-170 & CPPR-171 (filed in PDR Category A).consisting of Amend 24 to FBAR (filed in PDR Category K) & Suppl 1 to environ rept OL stage (filed in PDR Category C)

 BHIELDB.S W Public Service Co of Indiana. Inc 83/04/21

 DENION.H R Office of Nuclear Reactor Regulation, Director 16pp 18212 083 24X Fiche 50-546.83/04/21,8304250167.

- E305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984 YOUNGBLOOD. B J Licensing Branch i 83/04/28 YOST, F E Utility Data Institute ip 18434 279 24X Fiche 50~546,83/04/28, 8305110183
- 8305070657 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mode Sive list encl EISENHUT.D G Division of Licensing 83/05/07 Consolidated Edison Co of New York. Inc. 16pp 18627-153 24X Fiche 50-000-83/05/07,8305070659
- 8305130119 Forwards response to Generic Ltr 83-10C re resolution of TMI Action Jtem II K 3 5. "Automatic Trip of Reactor Coolant Pumps "Response to Items I leil 30 % I 3c will be addressed in FSAR-App E.scheduled for submittal by 840331 SHIELDS.S W Public Service Co of Indiana, Inc 83/05/07 EISENNUT.D G Division of Licensing 5pp 18437 353 24% Fiche 50-546,83/05/09,8305130119
- 8303230635 Forwards request for add1 info re environ qualification of electrical & mechanical equipment Schedular commitment for submittal of program should be provided within 30 days YOUKOBLOOD, B J Licensing Branch 1 83/05/10 SHIELDS, S W Public Service Co of Indiana, Inc. 4pp 18543 021 24X Fiche 50-546,83/05/10,8303230635
- B305170305 Application to amend CPPR-170 > CPPR-171 w/submittal of revised Suppl 1 to environ rept DL stage Affidavit of Distribution encl
 SHIELDS.S & Public Service Co of Indiana, Inc SHIELDS.S & Wabbash Valley Power Association, Inc 83/05/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 6pp 18465 024 24X Fiche 30-546.83/05/13,8305170306
- 8305200287 Forwards Amend 25 to CP & OL applications, including revs to security plan Amend withheld (ref 10CFR2 790)
 SHIELDS:SW Public Service Co of Indiana. Inc 83/05/16
 DENTON:HR Office of Nuclear Regulation. Director 4pp
 18514-317 24X Fiche 50~544.83/05/16.8305200289
- C Utility Environmental Report (ER), amends & correspondence
- 8304250167 Forwards Suppl 1 to environ rept OL stage (filed in PDR Category C) Supporting repts encl
 SHIELDS, SH Public Service Co of Indiana, Inc. 83/04/21
 DENTON, HR Office of Nuclear Reactor Regulation. Director 16pp
 18212 083 24X Fiche 50-546,83/04/21.8304250167
- B305110185 Responds to B30413 ltr re B30325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984 YOUNOBLODD. B J Licensing Branch 1 B3/04/28 YOST, F E Utility Data Institute 1p 18434 279 24X Fiche 50-546.83/04/28, 830510185
- 8305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ rept - OL stage Affidavit of Distribution encl SHIELDS.5 W Public Service Co of Indiana. Inc 83/05/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 6pp 18466 024 24% Fiche 50-546.83/05/13.8309170306
- --B305170312 Revised Suppl 1 to environ rept QL stage * Public Service Co of Indiana, Inc 83/05/31 ip 18466 030 24X Fiche 50-546, 83/05/13, 8303170306
- F Security, medical, emergancy & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for DLs & hulders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
 EISENHUT, D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
 Fiche 30-000, 83/05/11, 8305110034
- 8305240213 Forwards monthly status rept on offsite emergency preparedness for DL reviews for Apr 1983 DIRCKS,W J Diffice of the Executive Director for Operations 83/05/13 PALLADING,W J Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13.8305240213
- 8305200289 Forwards Amend 25 to CP & GL applications, including revs to security plan Amend withheld (ref 10CFR2 790)
 SHIELDS:S W Public Service Co. of Indiana, Inc. SHIELDS, S.W. Wabash Valley Power Association, Inc. 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18516-319 24X
 Fiche 50-346,83/05/16,8305200289

- 8305260233 Advises of 830527 prompt notification sys development meeting in Clarksville. In to discuss objectives & design of emergency planning zone MNIGHT.MR Public Service Co of Indiana. Inc 83/05/16 AXELSON.W L Region 3. Office of Pirector ip 18599 338 24X Fiche 30-546/83/05/18.8303260233
- G Adjudicatory correspondence
- 8305130073 Answer to Indiana Sassafras Audubon Society (ISAS) petition for leave to intervene ISAS fails to establish right to intervene Certificate of Svc encl

 * Public Service Co of Indiana, Inc * Wabash Valley Pawer
 Association, Inc * LeBosuf, Lemb, Leiby & MacRae 83/05/12,
 Commissioners 11pp 18436 251 24X Fichs 50-546,83/05/12,
 B305130073
- 8303130098 Response w/o objection to Save the Valley petition for leave to intervene provided applicant may object to contentions & right to hearing after petition suppl filed. Certificate of Sec encl VOIOT.H H Public Bervice Co of Indians, Inc VOIOT.H H Habash Valley Power Association, Inc VOIOT.H H LeBoeuf, Lamb, Leiby & MacRae B3/05/12 Commissioners App 18438 097 24X Fiche 50-546,83/05/12,8305130098
- 8305130244 Response opposing Valley Watch. Inc 820427 petition for Isava to intervene in proceeding. Petitioner fails to establish sufficient interest in proceeding to establish standing as matter of right or discretion W/Certificate of Svc VOI0T. H H Public Service Co of Indiana. Inc VOI0T. H H Wabsh Valley Power Association. Inc VOI0T. H LeBosuf, Lamb. Leiby & MacRae 83/05/12 Commissioners lipp 18439 174 24X Fiche 30-546.83/05/12.8305130244
- 8305160146 Response in opposition to Valley Hatch, Inc 830419 petition for intervention & request for public hearing re OL application Petition has not established requisite standing to intervene Certificate of Buc encl CHAN, E I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 078 24X Fiche 50-546, B3/05/12, B305160146
- 8305160158 Response to Save the Valley patition to intervene Requisite standing to intervene established Aspects of proceeding to be addressed by intervenor identified Certificate of Svc encl
 CHAN.E I Hearing Branch 2 83/05/12 Atomic Safety and
 Licensing Board Panel 11pp 18445 141 24X Fiche 50-546/83/05/12:
- 8305170003 Response to Bassafras Audubon Soc of South Central Indiana BJ0416 petition to intervene Requisite standing to intervene not established Specific aspects appropriate for consideration identified by Soc Certificate of Byc enci CHAN.E J Hearing Branch 2 83/05/13 Atomic Safety and Licensing Board Panel 11pp 18466 231 24X Fiche 50-546.83/05/13,8305170003
- K Utility Final Safety Analysis Report (FSAR) & smends
- 8304250167 Forwards Amend 24 to FSAR (filed in PDR Category K) W/277 oversize drawings Aperture cards are available in PDR SHIELDS.5 W Public Service Co of Indiana, Inc 83/04/21 DENTON.H R Office of Nuclear Regulation, Director. 16pp 18212 083 24X Fiche 50-546,83/04/21.8304250167
- --8304250190 Amend 24 to FBAR W/277 oversize drawings Aperture cards are available in PDR * Public Service Co of Indiana, Inc. 83/04/30 138pp 18212 099 24X Fiche 50-546,83/04/21,8304250167
- Q Inspection reports, IE Bulletins & correspondence
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list and TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319, 24X Fiche 50-000,83/03/21,8212060385
- B30304002: IE Info Notice 83-21, "Defective Emergency Use Respirator Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New
 York, Inc. 126pp 18435 155 24X Fiche, 50-000, 83/04/15, 8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures."

 8vc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/22 Consolidated Edison Co of New

 York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,830304023

- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- 8305120419 Forwards IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 & notice of violation 8PESSARD, R L Division of Engineering 83/04/25 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18434 051 24X Fiche, 50-546, 83/04/25, 8305120419
- --8305120423 Notice of violation from insp on 830124-28 & 0224-25 SPESSARD,R t. Division of Engineering 83/04/25 4pp 19434 053 24x Fiche 50-546,83/04/25,8305120419
- --8305120428 IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 Noncompliance noted failure to assure that applicable requirements translated into instructions, procedures or drawings Nonconforming items not tagged LOVE, R S · MENDEZ, R · HILLIAMS, C C Region 3, Office of Director 83/04/20 23pp 18434 037 24X Fiche 50-546,83/04/25,8303120419
- 830317014B Forwards IE Insp Repts 50-946/83-04 & 50-547/83-04 on B30309-18 No noncompliance noted STREETER: J F Region 3, Office of Director B3/04/27 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18466 285 24X Fichs 50-546, 83/04/27, 830517014B
- --8305170153 IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted Major areas inspected electrical contractors OA program implementing procedures & training VANDEL.T E , KIEH.J N , HAWKINS.F C Region J, Office of Director 83/04/27 4pp 18466 287 24X Fiche 50-546.83/04/27.8305170148
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/28 Consolidated Edison Co of New York, Inc 119pp 18382 047 24% Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Qas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000.83/05/03,8303040028
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York: Inc. 112pp 18382 282 24X Fichs 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for Owneral Emergencies " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidate Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04.8303040031.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp 18523 248 24% Fichs 50-000,83/05/06,8303040033
- 8303040034 IE info Notice 83-30. "Misapplication of Generic Emergency Operating Procedures (EOP) Quidelines," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of Naw York, Inc 114pp 18524 003 24X Fiche 30-000,83/05/11,8303040034
- B303040040 IE Info Notice B3-31, "Error in ADLPIPE Computer Program"

 Svc list encl

 JORDAN/E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) B3/05/19 Consolidated Edison Co of New

 York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

- S Reportable occurrences, LERs > related correspondence
- 8305020291 Final deficiency rept to potential for inaccurate indication of Westinghouse mfg gate valve position Initially reported on 821222 Westinghouse issued field change notice documenting corrective actions SHIELDS.S W Public Bervice Co of Indiana, Inc 83/04/21 MEPPLER.J G Region 3, Office of Director 2pp 18281 296 24X Fiche 50-546, 83/04/21,8305020291
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on B30420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised RAME.E P Westinghouse Electric Corp B3/04/21 DEVOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 075 24% Fiche 50-000 B3/04/21.8303110427
- 830502011B Final deficiency rept re interference between rear attachment brackets & mechanical snubber pivot mount brackets Initially reported on 830325 Rear brackets will be returned to ITT Grinnel for isworking SHIELDS.5 H Public Service Co of Indiana, Inc 83/04/22 KEPPLER.J Q Region 3, Office of Director 1p 18278 217 24X Fiche 30-546,83/04/22,8305020118
- 8305110324 Part 21 rept re Type SA-1 Class II relays Silicon controlled rectifier (SCR) in trip output circuit may cause randam trip output Westinghouse corrective action includes replacing SCR W/burn-in SCR
 DUVALL, D.D. Brown Bover; Corp. (subs. Brown Bover; & Co., Ltd.)
 B3/04/27 STELLO, V.Director's Office. Office of Inspection and Enforcement. Spp. 18393-278 24X Fiche 30-000,83/04/27,8305110324
- 8305040494 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on 800509 Westinghouse & util warking to refine equipment mod to mutual satisfaction Next rept by 831028 SHIELDS-8 W Public Service Co of Indiana, Inc. 83/04/28 KEPPLER-J O Region 3. Office of Director 2pp 18319 264 24X Fiche 30-546.83/04/28,8305040474
- 8305130207 Interim deficiency rept re problem involving embedded plates in primary shield wall w/deformed wire anchors missing or welds between plate & anchor being cracked initially reported on 820818 Caused by axial tensile stresses SHIELDS.5 W Public Service Co of Indiana, Inc 83/05/07 KEPPLER.J G Region 3, Office of Director 2pp 18439 355 24X Fiche 50-546.63/05/09,8305130207
- 8305240408 Final deficiency rept re potential for improper operation of D5-416 reactor trip switchgear undervoltage attachments Initially reported on 830421 Attachments to be replaced w/ attachments having modified grooves 8HIELDS.S W Public Service Co of Indiana, Inc 83/05/16 KEPPLER, J G Region 3, Office of Director 2pp 18574 277 24X Fichs 50-546.83/05/16,8305240408
- 8305260332 Interim deficiency rept re Commonwealth-Lord Joint Venture failure to adequately implement QA program Initially reported on 830211 Nonconformance repts for items not previously audited written Next rept by 830805 SHIELDS.S W Public Service Co of Indiana, Inc. 83/05/18 KEPPLER.J G Region 3, Offfice of Director 2pp. 18625 Q05 24X Fiche 50-546,83/05/18,8305260332
- DOCKET 8TN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1
- S Reportable occurrences. LERs & related correspondence
- B305120392 Interim deficiency rept re misapplication of ITE Qould circuit breakers in gost-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported an B30328 Matter under investigation Final rept by B30808 Reported per Part 21 MANNOLS F Niagara Mohawk Power Corp B3/04/26 STAROSTECKI.R Region 1. Office of Director 2pp 18433 072 24X Fiche 50-000.B3/04/26.B305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators natified of deviation
 EMPEY.D C Rockwell International Corp 83/03/ii COLLINS.J T Region 4, Office of Director 5pp 18433 074 24X
 Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION. UNIT 2

S. Reportable occurrences, LERs & related correspondence

- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LDCA hydrogen recombiners supplied by Rockwell Inti Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO.5 F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI.R Region 1. Office of Director 2pp 18433 072 24% Fiche 50-000,83/04/26,8305120392
- ---R305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation

 EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T Region 4, Office of Director 3pp 18433 074 24X

 Fiche 50-000.83/04/26.8305120392

DOCKET SIN-50-556 BLACK FOX STATION, UNIT I

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mads Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fithe 50-000.83/05/09/B305090659

- F Security, medical, emergency & fire protection plans
- 8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list enci EISENHUT.D 0 Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034
- G Adjudicatory correspondence
- 630526017G Advises that time for Commission to review ALAB-723 expired Commission declined review Decision became final agency action on 930524 CHILK, S.J. Office of the Secretary of the Commission 83/05/25 Atomic Safety and Licensing Board Panel ip 18579 270 24X Fiche 30-556,83/05/25,8305260178
- G Inspection reports. IE Bulletins & correspondence
- 8212050385 IE Info Natice 83-14, "Dewstered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction" Svc list encl
 TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000.83/03/21.8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 8vc tist encl

 JORDAN-E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15 Consolidated Edison Co. of New

 York, Inc 126pp 18435 155 24X Fichs 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp 18383 087 24Y Fiche 50-000,83/04/22,8303040023
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York Inc 119pp 18381 291 24X Fiche 50-000,83/04/28,8303040025
- 8303040036 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25. "Standby Gas Treatment Sys Heater High Famp Trip Setpoint Adjustment " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/04/28 Consolidated Edison Co of New York, Inc 11899 18382 163 24X Fiche 50-000,83/04/28,8303040027

- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24% Fiche 30-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04.8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/06 Consolidated Edison Co of Hew York
- 8303040034 IE info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EQP) Guidelines "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Progres" Svc 1ist encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24% Fiche 50-000.83/05/19,8303040040
- 830304004å IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000.83/05/26.8303040045

DOCKET SYN-50-557 BLACK FOX STATION, UNIT 2

Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EISENHUT.D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

- F Security, medical, emergency & fire protection plans
- 8305110034 Ceneric Ltr 83-21 to all licensess of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl EISENHUT.D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 1App 18540 095 24X Fiche 30-000.83/05/11.8305110034
- O Adjudicatory correspondence
- 8305260178 Advises that time for Commission to review ALAB-723 expired Commission declined review Decision became final agency action on 830524
 CHILK, 8 J Office of the Secretary of the Commission 83/05/25 Atomic Safety and Licensing Board Panel 1p 18579 270 24X Fiche 50-556:83/05/25.8305260178
- O Inspection reports, IE Bulletins & correspondence
- 8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Sve Jist enc!
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112p 18308 319 24X Fiche 50-000,83/03/21,8212060385
- 8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator' Svc 1ist encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc. 126pp 18435 155 24X Fiche 30-000, 83/04/15, 830304002(
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Cansolidated Edison Co of New York Inc 112pp 18383 089, 24X Fiche; 50-000, 89/04/22, 80303040023.

- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list oncl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fishe 50-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment "Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/28 Consolidated Edison Co of New York, Inc 18982 165 24X Fiche 50-000.83/04/28,8303040027
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83703703 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000 83705703,8303040028.
- 8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/03/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." 8vc list encl JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Quidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24% Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
 Svc list encl
 JORDAN,E, L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc 114pp. 18697 009 24X Fiche 30-000,83/05/19,8303040040
- 8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/03/26,8303040046
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8305090285 FDIA request for all documents re decision to terminate const of facility.

 DEVIENCE: A Devience & O'Meara. Ltd 83/02/24 Office of Administration ip 18381 225 24% Fiche: 50-546, 83/02/24, 83/0590285
- 8305090292 Responds to FOIA request for all documents re decision to terminate const of facility Forwards documents listed in App A
 FELTON, J M Division of Rules and Records 83/03/21 DEVIENCE, A
 Devience & O'Meare, Ltd. 2pp 18381 226 24X Fiche 30-366,
 83/03/21,8303090292.
- B305170237 Forwards "Details of Deferral Plans for Yellow Creek Nuclear Plant " MILLS.L M Tennessee Valley Authority B3/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18465 079 24X Fiche 30-566,83/05/12,8305170237
- --8305170240 "Details of Deferral Plans for Yellow Creek Nuclear Plant." # Tennessee Valley Authority 83/05/31 7pp 18465 080 24X Fiche 30-566,83/05/12,8305170237

- G Inspection reports, IE Bulletins & correspondence
- 8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacoum Breakers " Svc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents $oldsymbol{b}$ correspondence
- 8305090285 FDIA request for all documents re decision to terminate const of facility
 DEVIENCE A Devience & O'Meara, Ltd 83/02/24 Office of Administration in 18381 225 24X Fichs 50-566,83/02/24, 8305090285
- 8305090292 Responds to FUIA request for all documents re decision to terminate const of facility Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 83/03/21 DEVIENCE.A
 Devience & D'Meara, Ltd 2pp 18381 226 24X Fiche 50-566.
 83/03/21.8305090292
- 8305170237 Forwards "Details of Deferral Plans for Yellow Creek Nuclear Plant " MILLS.L M Tennessee Valley Authority B3/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18465 079 24X Fiche 50-566-83/05/12-8305170237
- ---8305170240 "Details of Deferral Plans for Yellow Creek Nuclear Plant " * Tennessee Valley Authority 83/05/31 7pp 18465 080 24X Fiche 50-566,83/05/12,8305170237
- DOCKET STN-50-599 CARROLL FACILITY I
- 9 Adjudicatory correspondence
- 8303040461 Provides quarterly status rept on developments Projected inservice dates revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001

 BIELAWSKI,AP Isham, Lincoln & Deale BIELAWSKI,AP Consolidated Edison Co of New York, Inc 83/05/02 MOLF,JF, HOLTON,R L, BRIGHT,G O Atomic Safety and Licensing Board Panel 2pp 18348 070 24X Fiche 50-599,83/03/02.8305060461
- DOCKET STN~50-600 CARROLL FACILITY II

 O Adjudicatory correspondence
- 8305060461 Provides quarterly status rept on developments Projected inservice dates revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001 BIELAMSKI.A P Isham, Lincoln & Beale BIELAMSKI.A P Consolidated Edison Co of New York, Inc. 83/05/02 WOLF.J.F., HOLTON.R.L., BRIGHT.O O Atomic Bafety and Licensing Board Panel 2pp 18348 070 24X Fiche 50-599.83/05/02.8305060461

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0008 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH
- 830917096B Forwards renewed License SNM-7, consolidating activities authorized by License SNM-7 & Byproduct Matls License 34-6854-05 tepproduct Matls License 34-6854-05 tepproduct Matls License 34-6854-05 terminated ROUSE, L C Advanced Fuel & Spant Fuel Licensing Dranch 83/04/29 TOV-N L Battelle Memorial Institute. Columbus Laboratories 2pp 18496
- ---B305170570 Renewed License SNM-7.consolidating activities authorized by License SNM-7 & Byproduct Habis License 24-6854-05 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 89/04/29 12pp 18496 128
- --830517057! Forwards question & answer fact sheet & 821227 FR notice re final rulemaking on land disposal of low level radwaste (10CFR61) New provisions include waste classification, manifest preparation & missing shipment investigation HANKINS,EF Low Level Waste Licensing Branch 83/02/11 Affiliation Unknown 43pp 18494 338
- 8305040623 Forwards IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401 No moncompliance noted PAPERIELLO.C J Region 3, Office of Director 83/05/03 UNDAR,E W Battelle Memorial Institute, Columbus Laboratories 2pp 18348 251

- --B305060634 IE Insp Repts 70-000B/B3-01 % 40-B202/B3-01 on B30330-0401 No noncompliance noted Major areas inspected radiation protection, raduaste mgt, facility changes & safety committees PECK.C.C., GREGER, L. R. Region 3, Office of Director 83/04/29
- B305190141 PND-111-B3-036 bioassays & in vivo count of licenses worker indicated potential thorium uptake Cause unknown No potential exposure sources identified Addl medical tests scheduled for B30514 GREGER.L. R. MILLER.D E. PAPERIELLO.C J Region 3, Office of Director B3/05/13 1p 18902 238
- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP . CANOGA PARK, CA
- 8305200338 Recommends that item of noncompliance re License SNM-21 be classified as Severity Level IV violation & handled per guidance in Item 2 of encl 820719 telcon memo W/o encl AXELRAD. J A Director's Office. Office of Inspection and Enforcement 82/10/18 JOHNSON, A Region 5, Office of Director 10 18516 229
- 8303240906 Forwards IE Safeguards Insp Rept 70-0025/83-02 on 830307-11 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUG.L R Region 5. Office of Director 83/03/21 FEILER.F W Rockwell International Corp 2pp 17678 106
- 8305310219 Forwards "Radiation Survey for Phase I Release for Unrestricted Use of E80 Headquarters.Bldg 001 " Document describes efforts to assure elimination of any residual contamination, scope of survey & procedures followed REMLEY.M E Rockwell International Corp 83/05/05 THOMAS.R D Region 5, Office of Director 2pp 18662 269
- --8305310220 "Radiation Survey for Phase I Release for Unrestricted Use of ESG Headquarters.Bldg 001 "
 REMLEY.M E Rockwell International Corp 83/05/06 GBpp 18462-271
- DUCKET 70-0027 BABCOCK & WILCOX CD . LYNCHBURG, VA
- 8305270548 Forwards IE Insp Rept 70-0027/83-04 on 830314-18 No noncompliance noted STONR, JP Division of Emergency Preparedness & Materials Safety 83/04/20 ECKERT, JP Babcock & Wilcox Co 2pp 18647.165
- --8305270554 IE Insp Rept 70-0027/83-04 on 830314-18 No noncompliance noted Major areas inspected operations, IOCFR21 implementation, internal reviews & audit, safety committees, training & nonroutine events
 CORYELL.G P Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/04/20 Soc. 18447 147
- 8305030368 Forwards IE Safeguards Insp Rept 70-0027/83-06 on 830404-08 No noncompliance noted. 8TCHR.J P Division of Emergency Preparedness & Materials Safety 83/04/28 ECKERT.J P Babcock & Wilcox Co 2pp 18292 176
- --B305030371 IE Safeguards Insp Rept 70-0027/83-04 on B30404-08 No noncompliance noted Major areas inspected site organization, review of security organization-mpt & security organization-personnel Datails withheld (ref 10CFR73 21)

 TILLMANA , URYC. B Region 2, Office of Director KCGUIRE, D R Division of Emergency Preparedness & Katerials Safety B3/04/28 ip 18292 178
- B305140178 Issues Amend 19 to License SNM-42 incorporating radiological contingency pian Amend supersedes Amend 15 dtd B20328 PAGE,R G Uranium Fuel Licensing Branch B3/05/03 REGAN,N Babcock & Wilcox Co 2p 18462:357
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORD, MA
- 8305190001 Advises that official files for License SNM-23 transferred to Region I due to regionalization, effective 830401, PAGE.R G Uranium Fuel Licensing Branch 83/05/05 8HERMAN,F L Teras Instruments, Inc. ip 18523 244
- 8305190008 Advises of 830418 transfer of official docket file & outstanding licensing action from NMSS to Region I PAGE.R G Uranium Fuel Licensing Branch B3/05/05 STARDSTECKI, R Division of Project & Resident Programs 1p 18323, 220

- 8305250601 Requests change of iddress for transmitting future correspondence as result of further implementation of regional licensing program.per 830505 ltr PAGE.R G Uranium Fuel Licensing Branch 83/05/18 SHERMAN, F L. Texas Instruments, Inc 1p 18594 322
- DOCKET 70-0082 NUCLEAR METALS: INC : WEST CONCORD: MA
- B305120224 Addl response to FOIA request for litense epplications, litense & insp repts ro Nuclear Matals, Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/03/01 MODNEY, B C Lowell Sun, Lowell, MA 9pp 18460 050
- --8305120246 Notifies that Nuclear Metals Div of Textron.Inc acquired by Whittaker Corp Approval for transfer of licenses requested. THOMPSON P Nuclear Metals, Inc 66/08/11 Atomic Energy Commission Ip 18460-063
- --8305120260 IE Insp Findings & Licensee Ack dtd 691202-03 of License SMB-177 Insp findings no noncompliance noted SMITH.R H Atomic Energy Commission 69/12/03 ip 18460:066
- ---8305120264 Advises that response to 670822 application for Lirense SMB-177 has not been received Info re issuance of license requested LEE, M R Whittaker Corp 69/10/22 NUSSBAUMER, D, A Atomic Energy Commission ip 18460
- --8305120268 Submits list of replacement pages to application for License SNM-65-in response to 670923 comments ISSEROH,S Whittaker Corp 69/10/22 NUSBBAUMER,D A Atomic Energy Commission 2pp 18460 068
- --8305120269 Forwards application for rensual of License SNM-65
 Application refiled in loose leaf format incorporating 17
 items from 680806 itr W/O encl
 KNEPPEL.D S Whittaker Corp 69/02/26, NUSSBAUMER, D. A. Atomic
 Energy Commission ip 18460 070
- --8305120274 IE Insp Findings & Licensee Ack dtd 690903 & 04 of Licenses SNM-65 & SMB-179 Insp findings proper evaluations not made of certain aspects of health physics program per Sections II b 4 through II b 6(b) of License Condition 8
 BROWNE,W G Atomic Energy Commission 69/09/18 ip 18460 071.
- --8305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & SM8-179 Insp findings no noncompliance noted SMITH,R H Atomic Energy Commission 70/07/16, ip 18460 076
- --8305120289 Notifies that no items of noncompliance observed during insport Licenses SNM-65 & SMB-179 Corrective measures implemented re item of noncompliance during 690903 & 04 insp 8 Isserow replaced DS Kneppel as criticality officer SMITH: R H Atomic Energy Commission 70/01/06 Atomic Energy Commission ip 18460 077
- --8305120294 IE Insp Findings & Licensee Ack dtd 710513 & 14 of Licenses SNM-65 & SNM-179 Insp findings no nancompliance noted Related info encl SMITH-R H Atomic Energy Commission 71/05/14 22pp 18460:078
- --8305120316 Ack receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr O'REILLY.J P Region 1, Philadelphia, Office of the Director. 74/04/26 TUFFIN,W B Nuclear Metals, Inc. ip. 18460 140.
- --8305120352 Suppls 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler. In response to 740404 telcon. Releted info encl. TUFFIN.W B. Nuclear Netals, inc. 74/04/16 O'REILLY, J.P., Region 1. Philadelphia. Office of the Director 5pp 18460.141.
- --8305120356 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-28 & 740108-09 & notice of violation W/o insp repts. O'REILLY, J. P. Region i, Philadelphia, Office of the Director. 74/02/13 TUFFIN.W B. Nuclear Metals, Inc. 2pp. 18460.146

- --8305120372 Insp Repts 40-0672/73-02 & 70-0082/73-05 on 721227-28 & 740108-09 Noncompliance noted failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products

 JERMAN, P. C., KNAPP, P. J. Region i. Philadelphia. Office of the Director 74/02/01 20pp 18460 164
- --B3051203B1 Responds to IE Bulletin 75-07 re emission of corrosive gases into ventilation sys filtered by HEPA filters No HEPA or other cellulosic filters used in ventilation sys exhausting nitrogen oxides Plastic overwrap used in disposal GILMAN, A R Nuclear Metals, Inc 75/12/22 Region 1, Philadelphia, Office of the Director 1p 18460 187
- DOCKET 70-0124 TELEDYNE ISOTOPES, INC , WESTWOOD, NJ
- B305180759 Lists official docket files & outstanding licensing actions transferred to Region I.effective B30401 PAGE.R G Uranium Fuel Licensing Branch B3/05/05 MARTIN,T T Division of Engineering & Technical Programs 1p 18504 053
- 8305180858 Advises that official files for License SNM-107 transferred to Region I due to regionalization.effective 830401 PAGE.R Q Uranium Fuel Licensing Branch 83/05/05 BLACK.S A Teledyne Isotopes ip 18506 039
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- B305050099 Forwards Rev 51 to Section 2 O of Fundamental nuclear matl control plan.Rev 40 Rev withheld (ref 10CFR2 790) No 10CFR170 fees applicable HENSLEY.K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) B3/02/16. BMITH, C N Fuel Facility Safeguards Licensing Branch 1p 18342 Oil
- 8305030699 Provides status of progress in const phase of ventilation upgrade project & correction to schedule contained in 821203 ltr Ventilation sys expected to be fully operational by 830430 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 83/03/29. PAGE.R O Division of Fuel Cycle & Material Safety 2p; 18309 lii
- B305030694 Requests procedures forwarded in encl Biii09 ltr to recent request re new ventilation sys be treated as proprietary info IDEKER.R L. Nuclear Fuel Services, Inc. (subs. of Gotty Oil Co.) S3/04/07. B00NG, A.L. Uranium Fuel Licensing Branch ip 18309 113
- 8305190003 "Daily Summary of Stack Monitoring for Mar 1983 "
 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 83/04/14. D'REILLY, J.P. Region 2, Office of Director 5pp
 18523 238
- B3051B0B52 Responds to alleged violation noted in IE Insp Rept 70-0143/B3-14 Corrective actions personnel performing calibr & testing sample counting (Procedure NFB-HB-A-4) reinstructed in procedure requirements MANSER.W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) B3/04/22 BTOHR.J P Region 2, Office of Director 2pp 18506.027
- 8305190033 Amends 821209 application for amend to License SNM-124, revising Page 79 to apply specifically to proposed unsafe geometry pits in floor beneath processing furnaces W/three oversize drawings. Aperture cards are available in PDR. IDEKER, R L Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 83/04/25 PAGE, R G. Uranium Fuel Licensing Branch. 3pp. 18523-169
- 8305270640 Forwards IE Insp Rept 70-0143/83-15 on 830405-08 No noncompliance noted. BTOHR, J.P Division of Emergency Preparedness & Materials Safety 83/04/25. MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Ca). 2pp 18646 201
- --8305270648 IE Insp Rept 70-0143/83-15 on 830405-08 No noncompliance noted Major areas inspected organization: IOCFR21 implementation: facility mods, safety committees, operations, nuclear criticality safety & previous insp findings CORVELL-0 P Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/04/25 4pp 18646 203.

- 8305200658 Forwards Rev 53 to Feb 1983 fundamental nuclear matl control plan Section B 0.per 10CFR70 32 Changes upgrade mods & do not decrease effectiveness of plan No fees required Rev withheld (ref 10CFR2 770)
 HENSLEY.K D Nuclear Fuel Services. Inc (subs of Getty Dil Co) 83/095/04 MCALPINE.E J NRC No Detailed Affiliation Given 1p 18519 319
- B305270135 Ack receipt of B30422 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/B3-14 STOHR.J P Division of Emergency Preparedness & Materials Safety B3/05/04 MANSER.H C Nuclear Fuel Services. Inc (subs of Getty Oil Co) 1p 18638 070
- B305i30i73 PND-II-B3-037 on B305i0, unusual event declared per emergency plan after ventilation sys stopped operating in bldg where high emriched U recovered from scrap Caused by electric motor & backup blower CGRYELL, GP, GIBSON, AF Region 2. Office of Director B3/05/10 1p 18437 205
- 8305i30055 Order CLI-83-12 approving 830406 joint motion to suspend proceeding Proceeding held in abeyance NRC directed to implement agreement Dissenting views of Commissioners Ahearne & Roberts encl.

 CHILK, S. J. Office of the Secretary of the Commission 83/05/11 Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 3pp. 18436-212
- B305200310 Forwards IE Safeguards Insp Rept 70-0143/B3-20 on B30404-29 No noncompliance noted STGHR,J P Division of Emergency Preparedness & Materials Bafety B3/05/17 GUINN,F K Nuclear Fuel Services, Inc (subs of Getty Gil Co) 2pp 18516 290
- --8305200318 IE Safeguards Insp Rept 70-0143/83-20 on 830404-27 No noncompliance noted Major areas inspected facility operation, facility changes & mods, criticality safety & environ protection Details withheld (ref 10CFR2 770)
 LEE, T D . MCALPINE, E J Region 2, Office of Director 83/05/13 ip 18316 272
- 930527016J Forwards IE Safeguards Insp Rept 70-0143/83-19 on 930418-22 No noncompliance noted STOHR, J P Division of Project & Resident Programs 83/05/18 GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18638 134
- --8305270167 IE Safeguards Insp Rept 70-0143/83-19 on 830418-22 No moncompliance noted Major areas inspected storage & internal control, records & repts 2 shipping & receiving Details withheld (ref 10CFR2 790)

 JQNES, D W. RICHARDS, B L. LANKFORD, J B. Region 2, Office of Director 83/05/17 ip 1863B 136
- 8305250537 PND-II-83-041 on 830520, unusual event declared 1 h after process ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by failure of electric motor Employees evacuated No contamination noted KAHLE, J D . 01050N, A F Region 2, Office of Director 83/05/20 tp 18588 226
- 8305270600 Forwards IE Bafeguards Insp Rept 70~0143/83-12 on 830807-0304 No noncompliance noted 8TOHR, J P Division of Emergency Preparedness & Materials Safety 83/00/25 MANER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18646-324
- --8305270613 IE Safeguards Insp Rept 70-0143/83-12 on 830207-0304 No noncompliance noted Major areas Inspected licensee action on previous insp findings, facility operation, facility changes & mods & criticality safety

 LEE, T D . MCALPINE, E J Region 2, Office of Director 83/03/23
 7pp 18646 326
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT
- 8305200177 Forwards revised fundamental nuclear matl control plan, Page 3-4 & request to revise Mass Measurement 8 used to overcheck gross weight of clad matl W/o encl WOLVENDYK, A United Nuclear Corp 83/03/10 HAYNES, R C Region 1, Office of Director 2pp 18540 230
- B305170390 Forwards IE Safeguards Insp Rept 70-0371/83-02 on 830317-23 & notice of violation Encls withheld (ref 10CFR2 790) MARTIN.T T Division of Engineering & Technical Programs 83/05/06 AMY.G G United Nuclear Corp 2pp 18301 023

- B305290543 Ack receipt of B30228.0310 & 0406 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/82-14 & forwards revised notice of violation STAR05TECKI. R Division of Project & Resident Programs 83/05/13 AMY/G O United Nuclear Corp 2pp 18588 187
- --8305250568 Revised notice of violation from insp on 821110-12
 Noncompliance noted raw fuel storage vault & three trailers
 containing U-bearing waste not posted w/authorized
 criticality safety limits
 * Region 1, Office of Director 83/05/02 2pp 18588 189
- --8305250378 Supple 830228 & 0310 ltrs re violations noted in IE Insp Rept 70-0371/82-14 Corrective actions air flow restored to license requirements between metallography eram area & sample preparation room & between lab & sectioning AMY.Q O United Nuclear Corp 83/04/06 MARTIN.T 7 Division of Engineering & Technical Programs Spp 18588 191
- --8305250582 Notifies that response to B30228 ltr re Item A of App A & Paragraph 3 of details re air balance, addressed in 820224 renewal application for License SNM-368 Pending disposition of moding disposition of moding disposition of MRK.W F United Nuclear Curp B3/03/10 MARTINIT T Division of Engineering & Technical Programs ip 18388 196
- --8305250586 Responds to NRC 830121 ltr re violation noted in IE Insp Rept 70-0371/82-14 Corrective actions raw fuel storage vault modified during Bept & Oct 1982 Conservative posting of "cans on their side," remains until shelves modified AMY.0 O United Nuclear Corp 83/02/28 MARTIN.T T Division of Engineering & Technical Programs 20p 18388 202
- 8305250605 Issues Amend 20 to License SNM-368, authorizing fabrication of new fuel parts SER enc)
 PAGE.R © Uranium Fuel Licensing Branch 83/05/18 KIRK, W.F.
 United Nuclear Corp. 2pp. 18594 309
- --8305250607 SER supporting Amend 20 to License SNM-368, authorizing fabrication of new fuel elements using new individual unit & spacing requirements BIDINGER OH Uranium Fuel Licensing Branch 83/05/18 Spp 18594 311

DOCKET 70-0378 ARMY, DEPT OF, ADELPHI, MD

- G305020007 Partial response to FOIA request for documents re Harry Diamond Labs located at 2800 Powder Mill Road, Adelphi, MD from 1985 to present Forwards documents responsive to request Documents also available in PDR FELTON, J M Division of Rules and Records 83/01/11 SIMPSON, C Affiliation Unknown 1p 18356 003
- --8305020081 Forwards Harry Diamond Labs application to amend Licenses 19-17250-01.19-17250-03.19-17250-04.19-17250-05 & SNM-0348 Amend removes JE Stafford as radiation protection officer & substitutes CA Rowe GUEFN.W G Army Dept of 78/07/06 Radioisotopes Licensing Branch (Pre 790501) 3pp 18335-047
- --8305020095 Application to amend Licenses 19-17250-01,19-17250-03, 19-17250-04,19-17250-05 & BNN-0348, removing JE Stafford as radiation protection officer & substituting CA Rowe GOODWIN,C R Army, Dept of 78/08/11 2pp 18355 048
- --8305020539 Application for amend to Licenses 19-17250-04, 19-17250-03, 19-17250-01: 19-17250-05 & SNM-034B, removing JE Stafford as radiation protection officer & replacing CA Ruwe QUEEN.W G Army, Dept of 78/08/11 Radioisotopes Licensing Branch (Pre 770301) 2pp 18355 117
- --8305030189 Amend 3 to License SNM-348 revising Subitems 9 A-9 F & Conditions 10.12 & 18 re dosimetry studies & calibr studies MALKER, W J Division of Fuel Cycle & Material Bafety 62/12/21 ip 18335 259
- --8305030195 Amend 2 to License SNM-348, revising Condition 18 represented to the second of the seco
- --8305030201 Amend I to License SNM-348, revising possession amounts for Pu-237, Np-237, depleted U,U-235 & U-238 encapsulated fission foils & sources COMBS.F C Division of Fuel Cycle & Material Safety 78/10/30 3pp 18355

- --8305030207 Renewed License 8NM-348 for Harry Diamond Labs.authorizing possession & use of Pu-239.U-235.natural & depleted U & Np-237 encapsulated fission foils LAYFIELD.R L Atomic Energy Commission, Directorate of Licensing 72/12/19 2pp 18353 264
- --8303030212 License SNM-348 for Harry Diamond Labs, authorizing possession & use of Pu-239, U-235, natural & depleted U & Np-237 encapsulated fission foils
 LAYFIELD, R L Atomic Energy Commission 68/07/15 3pp 18335 266
- --8305030213 License 8NM-348 for Harry Diamond Labs, authorizing possession & use of Pu & U enriched in U-235 fission foil JOHNSON, L Atomic Energy Commission 65/07/16 3pp 18355 269
- --8305030218 Application to amend License SNM-348, requesting storage of matls prior to transfer, substituting CA Rows as alternate radiation officer & listing MJ Borisky as radiation protection officer
 MOTHERSBAUGH, L. Army, Dept of 82/11/22 Radioisotopes
 Licensing Branch (Pre 790501) 12pp 18355 272
- --B305030225 Forwards resume of MD Funkhouser, designated new radiation protection officer at Harry Diamond Labs replacing G Rowe W/o entl
 TARAS D N Army, Dept of 80/05/22 Radioisotopes Licensing Branch (Pre 790501) 4pp 18353 284
- --8305030233 Forwards Harry Diamond Labs response to 780706 ltr re License SNM-348 Headquarters concurs w/response Ack of receipt of correspondence requested W/o encl TARAS.D N Army. Dept of 78/07/24 COMBS.F. Radioisotopes Licensing Branch (Pre 790501) lp 18355 289
- --8305030239 Submits add1 info re security requirements, radiation safety facilities & procedures for storage & use of Np-237 foil matl listed on Harry Diamond Labs application for renewal of License SNM-348
 GOODWIN, C R Army, Dept of 78/07/19 COMBS, F Radioisotopes Licensing Branch (Pre 790501) 2pp 18355 290
- --8305030249 Requests addl info re security requirements, radiation safety facilities & procedures for use & storage of Np-237 & description of leak testing procedures for fission folls COMBS, R Radioisotopes Licensing Branch (Pre 790501) 78/07/06 TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command ip 18395 292
- --8305030251 Application for renewal of License SNM-348, reflecting changes in location of lab headquarters, amount of Pu-239 in Pu-De neutron source & radiation protection officers & users
 TARAS, D N Army, Dept of 77/11/18 Radioisotopes Licensing Branch (Pre 790501). 17pp 18355 293
- --B305030255 Ack receipt of application to renew License BNM-34B License will not expire until final action taken BROMN-J M Radiolsotopes Licensing Branch (Pre 790501). 77/12/05 TARAS-D N Army. Dept of Ip 18355-310
- --8305030260 Application for amend & renewal of License BNM-348, authorizing possession & use of 9 76 mg Pu-239, 0 24 g U-235, 1 72 g U-235 & 5 0 g Np-237 REHRIG.A W Army, Dept of 72/12/04 Atomic Energy Commission 21pp 18355 311
- --8305030264 Amend 4 to License ENM-348, revising expiration date to 650731. TB Grucci qualifications added to license record, LAYFIELD, R L Atomic Energy Commission 65/01/12 FLYNN, R, M Army, Dept of 1p 18355-332
- ---8305030268 Amend 3 to License BNM-348, revising Items 7 & 8 & adding Item 14 re licenses compliance w/attached leak test conditions for Pu alpha sources DOULOSIN , NVSBBAUMER, D Atomic Energy Commission 64/01/21 GOLDSTEIN.B L. Army, Dept of 1p 18355 333.
- --8303030278 Forwards Amend 2 to License SNM-34B License does not authorize insertion of matls into nuclear reactor Insertions must be authorized W/o encl JOHNSON, L. Atomic Energy Commission 63/09/26 GOLDSTEIN, B L. Army
- --8305030281 Amended License SNM-348 for Harry Diamond Labs.authorizing enriched U-235 as Pu-Be neutron source & 64.6 g as fission foils

 * Atomic Energy Commission. 63/09/26 4pp. 18355 335

DOCKETED ITEMS

- --8305030286 License GNM-348 for Harry Diamond Labs, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source, 12 micrograms encapsulated in fast neutron detectors & 10 g encapsulated as neutron activation detectors

 JOHNSON, L Atomic Energy Commission 62/02/27 Ip 18355 339
- --B305030289 License SNM-348 for Diamond Ordnance Fure Lab.authorizing use of 16 g Pu encapsulated as Pu-Be neutron source 12 micrograms encapsulated in fast neutron detectors * Atomic Energy Commission 61/11/14 2pp 18355
- --8305030296 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu encapsulated as Pu-Be neutron source & 12 micrograms encapsulated in fast neutron detectors

 NUSSBAUMER, D Atomic Energy Commission 61/05/18 1p
- --8309030301 License SNM-348 for Diamond Ordnance Fuze Lab.authorizing possession & use of 16 g Pu as encapsulated Pu-Be neutron source
 DELANEY, J C Atomic Energy Commission 60/02/03 2pp 18335 343
- --B305030304 Amend to License SNM-348, correcting docket number error in Item 5 Correct number should be 70-0378 LAYFIELD, R L Atomic Energy Commission 68/07/24 HAAS, C F Army, Dept of 1p 18355 345
- --B305030309 Forwards renewed License BNM-348, reflecting leak test condition for Pu as sealed source W/o encl LAYFIELD, R L Atomic Energy Commission 48/07/15 HAAS, C F Army, Dept of ip 18335.346
- --8305030312 Application for renewal & amend of License SNM-348, authorizing possession & use of 54, 7 g Pu & 16 g Pu-239. Np-237. depleted U,U-235 & U-238 neutron source in encapsulated calibr sources & fission foils HAAS,C F Army, Dept of 68/06/25 lipp 18355 347
- --8305030320 Notifies that License SNM-348 expires on 680731
 Application for renewal of license should be filled within 30 days Notification should be given at decision not to renew by completing encl form W/o encl NVSSBAUMER.D A Atomic Energy Commission 68/05/26 SEIDLER.G Army. Dept of Ip 18355 358
- --8305030323 Forwards renewed License SNM-348 W/o encl
 JDHN80N, L Atomic Energy Commission 65/07/16 SEIDLER, C Army,
 Dept of 1p 18355/359
- --8305030326 Forwards add1 info re use & storage of Pu neutron source, per AEC 650604 request Includes description of Pu neutron source & dimensions of tantalum & stainless steel source container

 SEIDLER.O Army, Dept of 65/07/06 Atomic Energy Commission 2pp 18355 360
- --8305030332 Requests add1 info re use & storage of Pu neutron source & personnel monitoring program, in response to 650505 application to renew License SNM-348 LAYFIELD, R. L. Atomic Energy Commission 65/06/04 FLYNN, R. M. Army, Dept of 1p 18355 362
- ---8305030335 Application for renewal & amend to License SNM-348, authorizing 13 4 g Np-237.54 5 g Pu-239.54 5 g U-235 & 143 g U-228 in form of fission folls for calibr studies FLYNN,R M Army, Dept of 65/05/05 Atomic Energy Commission 12pp 18356 001
- --8305040060 Application to amend License 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-348, removing JE Stafford as radiation protection officer & substituting CA Rowe GODDWIN, CR., QUEEN, WO Army, Dept of Headquarters Materiel Development & Readiness Command 78/08/11 Radioisotopes Licensing Dranch (Pre 790501) 3pp 18356 023
- --8305040468 Forwards Harry Diamond Labs application to amend Matl/ Byproduct Licenses 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-348. GUEEN,W G Army, Dept of, Headquarters Materiel Development & Readiness Command 78/09/06 Radioisotopes Licensing Branch (Pre 790501) 1p 18356-326
- --8305040478 Application for amend to Matl/Byproduct Licenses 19-17250-01,19-17250-03,19-17250-03 & SNM-348 Amend requests removal of JE Stafford as radiation protection officer & substitutes CA Rows. GOODWIN.C R Army, Dept of 78/08/11 2pp 18356 327

- ~-8305040583 Application for renewal & amend to License SNM-348, including TB Grucci as authorized user FLYHAN,R M Army, Dept of 64/12/30 4pp 18397 036
- --8305040586 Notifies that License SNM-348 expires on 650131 Application for renewal should be submitted 30 days prior to expiration of Iticense Notification of nonrenewal should be given by completing encl form W/o encl
 NUSSBAUMER, D. A. Atomic Energy Commission 64/12/19
 GOLDSTEIN. B. L. Army, Dept of 1p 18357 040
- --B305040587 Notifies that no action will be taken on Harry Diamond Labs 640417 application to amend License SNM-348, per 640605 telcon LAYFIELD.R L Atomic Energy Commission 64/06/24 SEIDLER, 0 Army, Dept of 1p 18357 041
- ---8305040593 Application for amend to License SNM-348 re periodic leak tests SIEDLER, 0 Army, Dept of 64/05/22 Atomic Energy Commission 2pp 18357 042
- --8305040579 Application for amend of License SNM-348 to include 5 mCi Pu-239 for Marry Diamond Labs GOLDSTEIN B L Army. Dept of 63/12/17 Atomic Energy Commission 3pp 18357 044
- --8309040603 Discusses Condition 13 of License 9NM-348 in response to 631011 ltr & 631003 teleon Condition 13 does not authorize actual insertion of mati held under license into any reactor Insertions should be authorized NUSSBAUMER. D A Atomic Energy Commission 63/10/23 DERMAN.P 9 Army. Dept of ip 18357 047
- --8305040674 Requests cancellation ltr requesting allocation of 99 8% U-235 for use as threshold detector for fast neutron dosimetry BERMAN.P 9 Army, Dept of 63/10/11 LAYFIELD.R Atomic Energy Commission Ip 18397 048
- --8305040678 Forwards addl info re Harry Diamond Labs application for amend to License SNM-348 per request OOLDSTEIN B L Army, Dept of 63/09/13 Atomic Energy Commission 7pp 18357 049
- --8305040687 Requests addl info re procedures for use & storage of Np-237.Pu-239 & U-238 fission foils, in response to 630531 request for amend to License SNM-348 for Harry Diamond Labs NUSSBAUMER. D Atomic Energy Commission 63/07/17 DANIELS,R Q Army, Dept of 6pp 18357 056
- --8305040696 Requests allocation of 31 g U-235 as metal of 99 8% purity for fission foil fast neutron dosimetry sys for DDRF-Triga reactor BERMAN.P G Army, Dept of 63/08/21 NUSSBAUMER.D A Atomic Energy Commission ip 18357
- --8305050292 Requests addl info re procedures for use 5 storage & description of folis in response to 650531 application to amend License SIMM-348 NUSSDAUMER, D A Atomic Energy Commission 63/07/15 DANIELS, R Q Army, Dept of [p 18357 063]
- --8305090297 Application for amend to License SNM-348, authorizing possession & use of 13 4 g Np-237, 54 5 g Pu-239, 54 5 g U-235 & 143 g U-238 DANTELG, R 0 Army, Dept of 63/05/31 Atomic Energy Commission 9pp 18357 064
- --8305030301 Notifies that RW McEvoy 621115 itr made part of records under Docket 70-378 Changes in technical & supervisory personnel having health-safety responsibilities should be provided on continual basis NUSSBAUMER.D A Atomic Energy Commission 63/01/29 DANIELS.R G Army, Dept of 1p 18357 073
- --8305050306 Application for amend to License SNM-348, substituting WL Gieseler for W Hunker as supervisor of instruments incorporating Pu calibr sources
 DANIELS,R O Army, Dept of 63/01/22 Atomic Energy
 Commission 3pp 18357 074
- ---B303050310 Requests nuclear matl draft re receipt of 5 g Pu foils contained in nuclear accident dosimetry sys HANSDN,O F Army, Dept of 62/11/26 LANE,J Atomic Energy Commission ip 18357 07/
- ---8305050312 Amend to License SNM-348, revising Item 8 re authorized use of licensed mati NUSSBAUMER: D A Atomic Energy Commission 62/08/15 DANIELG:R G Army, Dept of 1p 18357 078

- ~~B305050316 Application for amend to License SNM-348, revising Item 8 recalibr of neutron survey meters & designating GP Hanson as authorized mat1 user
 DANIELS.R G Army, Dept of 62/08/07 Atomic Energy
 Commission 3pp 18357 079
- --8305050319 Forwards amended License SNM-348 W/o enc1 NUSSDAUMER.D A Atomic Energy Commission 62/02/27 DANIELS,R Q Army, Dept of 1p 18357 082
- --8305050322 Application for renewal of License SNM-348 for possession & use of 26 g Pv.12 mg Pv.1 g Np-237 & 50 g depleted U DANELS.R G Army, Dept of 62/01/15 Atomic Energy Commission ip 18357 083
- --B309050326 Notifies that License SNM-348 expires on 620131 Renewal application should be filed within 30 days NUSSBAUMER, D A Atomic Energy Commission 61/12/01 DANIELS, R G Army, Dept of 1p 18337-085
- --8305050328 Forwards diagram of cannister used in nuclear accident dosimetry sys.per telcon request MCCOSKEY.R E Army, Dept of 61/10/24 NUSSBAUMER.D Atomic Energy Commission 2pp 18357 086
- --8305050330 Forwards application to amend License SNM-348, authorizing possession & use of 50 g depleted U.10 g Pu-237 & 1 g Np-237 DANIELS,R G Army, Dept of 61/10/09 Atomic Energy Commission 3pp 18357 088
- --8305050333 Application to amend License SNM-348, authorizing possession b use of add1 12 micrograms Pu in form of callbr devices

 KRAUL-C W Army, Dept of 61/05/01 Atomic Energy Commission 2pp 18357 091
- --8308050235 Forwards License SNM-348 H/o encl
 DELANEY, J C Atomic Energy Commission 60/02/03 HIRMAN, W B
 Army, Dept of 1p 18357 093
- --8305050337 Forwards Diamond Ordnance Fuse Lab 591113 application for SNM license Classification review requested W/o encl FLEURY.E R Atomic Energy Commission 60/01/28 STRAUSER.W A Atomic Energy Commission 1p 18337 094
- --8305050339 Application for amend to License SNM-348, authorizing possession & use of Pu KRAUL, C W Army, Dept of S9/12/21 Atomic Energy Commission Spp 18337 095
- DOCKET 70-0466 MAINE MARITIME ACADEMY, CASTINE, ME
- 8305050132 Discusses IE Insp Rept 70-0466/83-01 conducted on B30322 No noncompliance noted Major areas inspected activities re Pu/Be sealed sources MARTIN.T T Division of Engineering & Technical Programs. 83/05/02 CUKIERSKI.M W Maine Maritime Academy 2pp 18341 351.
- DUCKET 70-0498 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8305020075 Forwards "Rept on Results of Guarterly Ground Hater Monitoring Samples at Walt: Mill Site " GALM.D T Hestinghouse Electric Corp 83/03/30 HAYNES.R C. Region I. Office of Director 2pp 18308 265
- --8305020074 "Rept on Results of Quarterly Ground Water Monitoring Samples at Waltz Mill Site " * Westinghouse Electric Corp 83/02/28 18pp 18308-247.
- DOCKET 70-0712 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK
 - al response to FOIA request for insp repts of safety t Kerr-Ntoge Pu plant at Cressant OK from Aug-JF Donahus 73:102 memo transmitting IE . 70-1193/73-01 w/portions deleted iion of Rules and Records 83/03/22 WIDMER, R R. In 19 18543 154
 - usses closeout insp of Licenses SMB-664 & SNM-695 on ends that licensee be authorized to transfer itles to unlicensed recipient mic Energy Commission 66/07/29 DUBINSKI, Lamission. 4pp 18943 223

- --8305230233 Requests authorization to release vacated facilities at Cushing OK to refining div for unrestricted use Bidgs used by nuclear products dept cleaned & decontaminated Health physics survey indicates contamination below limits MULLER, O B Kerr-McGes Nuclear Corp 64/06/09 NUSSBAUMER, D A Atomic Energy Commission 4pp 18543 227
- DOCKET 70-0734 OA TECHNOLOGIES, INC , SAN DIEGO, CA
- 8305100127 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE physical security insp rept NRRDERHAUG, L R Region 5. Office of Director 83/05/04 PARKER, J W GA Technologies, Inc /General Atomic Co ip
- DOCKET 70-0754 GENERAL ELECTRIC CO , PLEABANTON, CA
- B305020520 Forwards Annual Financial Rept 1982 CUNNINGHAM, G E General Electric Co 83/04/04 CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety 1p 18284 337
- 8305160067 Forwards IE Insp Rept 70-0754/83-01 on 830314-16,18,21 & 22 No noncompliance noted BOOK.H E Region 5, Office of Director 83/04/29 DARMITZEL, R. W General Electric Co Spp 18453 089
- --8305160078 IE Insp Rept 70-0754/83-01 on 830314-16,18,21 & 22 No noncompliance noted Major areas inspected organization, facility changes & mods, internal review & audit, radwaste mgt.criticality safety & radiation protection BROCK, B L. THOMAS, R D. BODK, H E Region 5, Office of Director 83/04/29 13pp 18453 092.
- B305130035 Memorandum & order extending GE time to respond to ASLB B3040B inquiry into license renewal application until 15 days following svc of Commission decision whether to review ALAB-720 FRYE.J H Atomic Safety and Licensing Board Panel 83/05/12 Ceneral Electric Co 2pp 18436 315 24X Fiche 50-070:83/05/12, 8305130035
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JCT . RI
- B305260371 Forwards drawings w/marked locations of concrete core samples taken during site characterization survey & drawings showing location of underground piping W/o encl HELOEBON.K A United Nuclear Corp B3/05/06 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 1p 18647, 286
- DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA
- B303020523 Forwards decommissioning plan for facility GLSEN, A F. Babcock & Wilcox Co 83/03/28 CROW, W T Uranium Fuel Licensing Branch ip 18284 294
- ---B305020526 Decommissioning plan for facility * Babcock & Wilcox Co B3/03/30 27pp 18284 295
- DOCKET 70-0846 TEXAS NUCLEAR CORP , AUSTIN, TX
- 8305030297 Forwards IE Insp Rept 70-0846/83-01 on 830301 No noncompliance noted BRGMN,0 D Region 4, Office of Director 83/04/28 Remsey Engineering Company 2pp. 18298 133
- --8305030308 IE Insp Rept 70-0846/83-01 on 830301 No noncompliance noted, Major areas inspected nuclear matl control & accountability, including facility organization & operation.measurement & controls & shipping & receiving CALDWELL,R A , EVERETT.R J , KELLY,J,A Region 4, Office of Director 83/04/20, 3pp 18298 135
- DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8305120224 Add1 response to FOIA request for license applications, license & insp repts re Nuclear Metals, Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6), FELTON, J M Division of Rules and Records 83/03/01 MOONEY, B C Lowell Sun, Lowell, MA 9pp 18460,050

- --Bi12290557 Ack agreement w/proposed enforcement action per Bi1016 memo, since revised hased on NRC consultant conclusion that evaluation of U uptake could not establish that regulatory limit was exceeded THOMPSON,D Enforcement & Investigation Staff (Pre 820201) 81/12/01 KEPPLER,J Region 3, Chicago, Office of the Director (B1/03/01) 2pp 18462 107
- --8305120656 Forwards Enforcement Guidance Memorandum 81-31 re proposed enforcement action for facility CARLBON.R T Enforcement & Investigation Staff 81/12/15 STAROSTECKI.R Division of Resident & Project Inspection MARTIN.T Division of Engineering & Technical Inspection BMITH.G H Division of Emergency Preparedness & Operational Support ip 18462 106
- 8305180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses, from U Fuel Licensing Branch to Region III PAGE.R G Urantum Fuel Licensing Branch 83/05/05 HIND, J A Region 3. Office of Director 1p 18505 075
- 8305180850 Notifies that official files for License SNM-928 transferred to Region III as of 830401.as part of regional licensing program W/o stated FR notice PAGE.R 0 Uranium Fuel Licensing Branch 83/05/05 SHELLEY,W J K
- 8305200472 Forwards IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted MILLER, JR Region 3, Office of Director 83/05/17 SHELLEY, W J Kerr-HcQee Corp 2pp 18516 112
- ---8305200482 IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted Major areas inspected facility organization & operations, records & repts & mgt of matl control sys Details withheld (ref 10CFR2 790) MADEDA:T J. KNICELEY, J.R. CREED, J.R. Region 3, Office of Director 83/05/16 2pp 18516 114

DOCKET 70-0992 DAVID WITHERSPOON, INC , KNOXVILLE, TN

- 8305180765 Lists official docket file & outstanding licensing action transferred to Region II, effective 830401 PAGE.R G Uranium Fuel Licensing Branch 83/05/05 QLSHINEKI, J A Division of Engineering & Radiological Safety Programs ip 18506 054
- B305180859 Advises that official files for License SNM-952 transferred to Region II due to regionalization effective B30401 PAGE.R G Uranium Fuel Licensing Branch B3/05/05 WITHERBPOON, D David Witherspoon, Inc. 1p 18506 040
- DOCKET 70-1007 GENERAL ELECTRIC CO . SAN JOSE. CA
- 8305020050 Forwards Annual Financial Rept 1982 CUNNINGHAM, G E General Electric Co 83/04/04 CUNNINGHAM, R E Division of Fuel Cycle & Material Bafety 1p 18285 304
- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON, NC
- 8305310109 Ack receipt of 830317 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-1113/83-03 STOHR, JP Division of Emergency Preparedness & Materials Safety 83/04/06 LDNGJ A General Electric Co 1p 18653 117
- --8305310115 Responds to NRC 830216 ltr re violation noted in IE 8afeguards Insp Rept 70-1113/83-03 Corrective actions withheld (ref 10CFR2.770), VAUCHAN, C M General Electric Co 83/03/17 STOHR, J P Division of Emergency Preparedness & Materials Safety ip 18653 II8
- 8305310132 Forwards IE Bafeguards Insp Rept 70-1113/83-09 on 830314-18 No noncompliance noted 8TOHR, J P Division of Emergency Preparedness & Materials Safety. 83/04/04 LONG, J A General Electric Co 2pp 18453 119
- --B305310134 IE Sefeguards Insp Rept 70-Li13/03-09 on B30314-18 No noncompliance noted Major areas inspected records & repts & internal controls, Details withheld (ref 100FR2 790) LANKFORD, J. B. Region 2, Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Bafety B3/04/04 1p 18653 121

- 8305270113 Forwards IE Insp Rept 70-1113/83-08 on 830307-11 No noncompliance noted STORR, J P Division of Emergency Preparedness & Materials Safety 83/04/11 LDNG, J A General Electric Co 2pp 18638 225
- --8305270116 IE Insp Rept 70-1113/83-08 on 830307-11 No noncompliance noted Major area inspected emergency preparedness MARSTON, R R Region 2, Office of Director JENKINS, C R Division of Emergency Preparedness & Materials Safety 83/04/08 7pp 18638 227
- B30505016B Forwards revised pages to fundamental nuclear mati control plan Pages withheld (ref 10CFR2 790)
 VAUDHAN.C M General Electric Co 83/04/22 O'REILLY, J P Region 2, Office of Director ip 18341 092
- 8305270156 Forwards IE Safeguards Insp Rept 70-1113/83-10 on 830404-08 No noncompliance noted STOHR, J.P. Division of Emergency Preparedness & Materials Safety 83/04/27 LONG, J. A. General Electric Co. 2pp. 18638 131
- --8305270159 IE Safeguards Insp Rept 70-1113/83-10 on 830404-08 No noncompliance noted Major areas inspected MG-83206B measurements & statistical controls Details withhold (ref IGCFR2 790)
 CLAY,E L. Region 2, Office of Director MGALPINE.E J. Division of Emergency Preparedness & Materials Safety 83/04/27 1p 1843B 133
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B304180541 Forwards IE Safeguards Insp Rept 70~1143/83-02 on B30316 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B3/04/05 JACOBI.W M Westinghouse Electric Corp 2pp 17996 159
- --B304i80554 IE Safeguards Insp Rept 70-1i43/B3-02 on B303i6 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate, strategic significance BMITH, G C , GODY, A T Region 1, Office of Director B3/04/01 2pp 17976 161
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B305270450 Ack receipt of B30317 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1131/83-03
 BTOHR.JP Division of Emergency Preparedness & Materials Safety B3/04/06 D'AMBRE.M Hestinghouse Electric Corp ip 18644 176
- --8305270459 Responds to NRC 830215 ltr re viutation noted in IE Insp Rept 70-1151/83-03 Corrective actions signs identifying nuclear criticality control parameters replaced on 830120 D'AMORE, M. Westinghouse Electric Corp. 83/03/17 O'REJLLY, J. P. Region 2, Office of Director. 2pp. 18644-177
- --8305270467 Forwards 1E Insp Rept 70-1151/83-05 on 830117-21 & notice of violation
 STDHR.J P Division of Emergency Preparedness & Materials Safety
 83/02/15 D'AMORE,M Westinghouse Electric Corp 2pp
 18444 179
- --8305270471 Notice of violation from insp on 830117-21 * Region 2, Office of Director 83/02/15 1p 18644 181
- --8305270480 IE Insp Rept 70-1151/83-03 on 830117-21 Noncompliance noted failure to post critical control parameters on equipment in SNM areas CORYELL, Q P Region 2, Office of Director MCALPINE, E. J Division of Emergency Preparedness & Materials Safety 83/02/15 5pp 18644 182
- B305310120 Ack receipt of B30327 & 10 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/83-01
 BTOHR.JP Division of Emergency Preparedness & Materials Safety.
 B3/04/12 D'AMORE.M Westinghouse Electric Corp 1p 18656 128
- 8303270142 Forwards IE Safeguards Insp Rept 70-1151/83-06 on 830411-15 No noncompliance noted STOHR, J P Division of Project & Resident Programs 83/05/18 BRITTON, W. H Westinghouse Electric Corp 2pp 18638 137

- --8305270145 IE Safeguards Insp Rept 70-1151/83-06 on 830411-15 No noncompliance noted Major areas inspected export % import verification & followup on previous insp findings Details withheld (ref 10CFR2 770)

 BATES: J W Region 2: Office of Director MCALPINE: E J Division of Project & Resident Programs 83/05/16 ip 18638 139
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- B305230112 Final response to FOIA request for insp repts of safety violations at Kerr-McGee Pu plant at Cresant CK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted FELTON JM Division of Rules and Records B3/03/22 WIDMER, R Affiliation Unknown ip 18543 154
- --8305230134 Forwards Regulatory Investigation Rept 70-1193/73-01 on 730917-21 No significant health & safety problems associated w/occurrences reported in allegations DONAHUE, J. F. Atomic Energy Commission 73/11/02 FIORELLE, G. Atomic Energy Commission 4pp 18543 155
- --8305230137 Regulatory Investigation Rept 70-1193/73-01 on 730917-21 Major area investigated anonymous allegations re leaks in Porwarts drums & unsafe practices Info re personnel interviews deleted DONAHUE. J F., FINN. J A., RIDGHAY, K.R. Atomic Energy Commission 73/11/01 18pp 18543 159
- --8305230179 Discusses licensee employee allegations re spills of Pu & leaking tanks Facility insp w/emphasis on incidents, spills, decontamination & personnel exposures scheduled for 730917

 DONAHUE, J F Atomic Energy Commission 73/09/04 Atomic Energy Commission 4pp 18543 177
- --8305230186 Updates 730904 memo re licensee employee allegations concerning unsafe working conditions due to possible contamination of work sites Related news articles & press release encl
 DDNAHUE, J. F. Atomic Energy Commission 73/09/13 Atomic Energy Commission 10pp 18543 181
- --8305230196 Rev 1 to Pu Plant Std Operating Procedure KM-NP-37-2, "Liquid Waste Solidification " Related info encl KULKIN:R Kerr-McGee Nuclear Corp 72/05/02 Sipp 18543 191
- 8305200472 Forwards IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No nencompliance noted MILLER,J R Region 3, Office of Director 83/05/17 SHELLEY,W J Kerr-McGee Corp 2pp 18516 112
- --8305200482 IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted Major areas inspected facility organization & operations, records & repts & mgt of matl control sys Details withheld (ref 10CFR2 790) MADEDA,T J, KNICELEY, JR, CREED, JR Region 3, Office of Director 83/05/16 2pp. 18516 114

DOCKET 70-1201 BABCOCK & WILCOX CO . LYNCHBURG, VA

- 9305050100 Forwards revised pages to fundamental nuclear matls control plan Revs incorporate reorgalization of matls mgt group change from nuclear power to util power generation group & provide new facility layout Pages withheld (ref IOCFR2 770) FORD.JT Babcock & Wilcox Co 83/02/28 Region 2, Office of Director ip IB341 361
- 8305050205 Forwards revised Pages II.111 & 1 & revised Figures 2 & 5 to security plan Encl withheld (ref 10CFR2 790) FORD.J T Babcock & Wilcox Co 83/03/03 Region 2, Office of Director 1p 18338 146
- 8305270174 Forwards IE Safeguards Insp Rept 70-1201/83-04 on 830321-24 No noncompliance noted STOHRJ P Division of Emergency Preparedness & Materials Safety 83/04/22 ALTO.R A Babcock & Wilcox Co 2pp 18638 128
- --8305270254 IE Safeguards Insp Rept 70-1201/83-04 on 830321-24 No noncompliance noted Major areas inspected measurement & independent insp effort Details withheld (ref 100FR2 790) BATES.J W Region 2: Office of Director MCALPINE.E J Division of Emergency Preparedness & Materials Safety 83/04/20 ip
- 8305310016 Forwards IE Bafeguards Insp Rept 70-1201/83-05 on 830409-08 No noncompliance noted BTOHR.J P Division of Emergency Preparadness & Materials Safety 83/04/28 ALTO.R A Babcock & Wilcox Co. 2pp 19653-122

- --8303310022 IE Safeguards Insp Rept 70-1201/83-05 on 830405-08 No noncompliance noted Major areas inspected inventory difference & associated limit of error & records & repts Details withheld (ref 10CFR2 790)
 JONES D W . RICHARDS, B L . LANKFORD, J B Region 2, Office of Director 83/04/27 1p 18653 124
- 8305260376 Application for amend to License SNM-1168 changing health physics & conditions sections re reactor insp sys FORD.J T Babcock & Wilcox Co 82/05/04 PAGE.R.Q Uranium Fuel Licensing Branch 20pp 18647 258
- DOCKET 70-1224 TELEFLEX, INC , NORTH WALES, PA
- 8305050176 Discusses IE Insp Rept 70-1224/83-01 on 830331 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/04/21 ALBOM, I Teleflex, Inc 2pp 18341 118
- --B305050182 Notice of violation from insp on B30331 Noncompliance noted required inventory of BNM not conducted & records not maintained * Region 1, Office of Director 83/04/21 ip 18341:120
- DOCKET 70-1257 EXXON NUCLEAR CO . INC . RICHLAND, HA
- 8305100184 RD on 820403, routine sampling of solutions between top & bettom liners of Lagoon 2 revealed top liner leaking Lagoon emptied, solids removed & liner cleaned Slit & blisters in lining repaired HALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp.) 82/05/05 ENSELKEN, R H Region 5, Office of Director, 2pp 18374 314.
- 8305100178 RD on 830113, large quantity of air or gas existed between liners causing large bulge Caused by rotten upper lagoon liner Upper liner patched at deteriorated area MALODY.C W Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 83/04/04 ENSELKEN,R H Region 5, Office of Director 2pp. 18374 288
- 8305180642 Advises that state-approved sys for monitoring fluoride emissions in stack gases operational, satisfying License Condition 20 requirements Determination of line loss as part of std sampling procedure not required MALODY.C W Exxon Nuclear Co , Inc (subs of Exxon Corp), 83/04/19 CROW,W T Uranium Recovery Licensing Branch 2pp 18504 020
- --B305180648 "Control & Monitoring of Fluoride Emissions for Erxon Nuclear Fuel Fabricat(on Facility " Draft Procedure P69261, Rev 1 to XN-NF-103, "Determination of Fluoride as HF in Environ Filters or Liquid Samples," encl # Exxon Nuclear Co., Inc (subs of Exxon Corp) 83/01/31, 22pp 18504 050
- 8305030074 Notifies of issuance of Amend 9 to License SNM-1227, authorizing const & operation of liquid waste treatment facilities Condition 9 date for insp of feed tank changed to 830103 PAGE.R G. CROM.W T Uranium Fuel Licensing Branch 83/04/20 MALODY.C W Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 1(18326-110
- --8305030077 SER supporting Amend 9 to License BNM-1227 BIDINOER, 9 H Uranium Fuel Licensing Branch 83/04/20 3pp. 18326 111
- DOCKET 70-1301 FLORIDA POWER CORP : ST PETERBBURG: FL
- 8305240034 Bubmits annual rept re changes, tests & experiments at Morris Operations facility during period 820504-830430, per IOCFR72 35(b)2 EGER.K.J General Electric Co 83/05/02 Region 3, Office of Director 1p 18577 359
- DOCKET 70-1308 GENERAL ELECTRIC GO . BAN JOSE, CA
- 8305170548 Forwards addendum consisting of confirmatory measurements program data sheet of analysis of waste lagoon sample completed after onsite inspitransmitted by 830215 ltr PAPERIELLO.C J Region 3, Office of Director 83/05/09. VAN HOOMISSEN General Electric Co 2pp 18468-031

- B305130227 Forwards IE Bafeguards Insp Repts 70-1308/B3-02 4 72-0001/B3-02 on B30419-21 No noncompliance noted MILLER, J R Region 3, Office of Director. 83/05/10 VAN HODMISSEN General Electric Co 2pp 18439 171
- --8305130834 IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-01 on 830419-21 No noncompliance noted Major areas inspected mati control & accountability, measurement & statistical control Details withheld (ref 10CFR2 790) MADEDA,T J , STAPLETUN,B W , CREED,J R Region 3, Office of Director 83/05/10 lp 18437 173

DOCKET 70-1959 IRT CORP , BAN DIEGO, CA

- B305230026 Application for amend to License SNM-1405 deleting provision for licensee use of bldg located at 7070 Convoy Court CROBBIE.K L IRT Corp 83/01/25 PAGE.R 0 Uranium Fuel Licensing Branch 3pp 18543 126
- --8305230033 Requests payment of fee for review of 830125 application for amend to License BNM-1405 WEISB, D License Fee Management Branch 83/03/07 CROSBIE, K L IRT Corp ip 18543 130
- --8305230035 Forwards fee for amend requested in 830125 ltr CROS91E,K L IRT Corp 83/03/14 WE185,D License Fee Management Branch ip 18543 131

DOCKET 70-1402 ABINGTON MEMORIAL HOSP : ABINGTON: PA

- 8305050134 Discusses IE Insp Repts 70-1402/83-01.30-02948/83-01 & 30-00453/83-01 on 830315 & forwards notice of violation MARTINIT Division of Engineering & Technical Programs 83/04/21 CANDIA.0 Abington Radiology Services, Ltd 2pp 18341 348
- --8305030140 Notice of violation from insp on 830315 Noncompliance noted one patient implanted w/pacemaker did not have required 6-month followup examper Condition 16 (10CFR2, App C) Reply expected within 30 days # Region 1, Office of Director 83/04/21 ip 18341 350

DOCKET 70-1621 DUQUESNE LIGHT CO., PITTEBURGH, PA

8305120011 Forwards Endorsement 63 to NELIA Policy NF-226 & Endorsement 54 to MAELU Policy MF-87. BARNETT, J E Conover & Associates, Inc Insurance 83/05/05 DINITI, J Office of Nuclear Reactor Regulation, Director 3pp 18423

DOCKET 70-2926 DETROIT EDISON CO , DETROIT, MI

- B305030706 Discusses items of interest, including DQE 830419 visit to NMBS to examine docket files of Kern-McGee West Chicago Rare Earths Facility & Datroit Edison Co 830419 visit to discuss proposed license conditions for BNM-1915 for fuel storage PAOE, R C Uranium Fuel Licensing Branch 83/04/20 DAVIS, J O Division of Fuel Cycle & Material Bafety 3pp 18309 105
- B305170662 Advises that proposed statutory merger of Wolverine Electric Cooperative Inc & Northern Michigan Electric Cooperative Inc completed on 821231 Wolverine Power Supply Cooperative Inc is new company name TAUBER.H Detroit Edison Co. B3/04/20 SERINI.B L Uranium Fuel Licensing Branch. 1p. 18476-346.

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO , DALLAS, TX

- 8305170027 Application for amend to License SNM-1912 adding other matls requiring NRC license specifically & seeking authorization to receive, own & use certain byproduct matl in connection w/preoperation & startup activities GARY,R J. Texas Utilities Generating Co 83/04/11 Office of Nuclear Material Safety & Safeguards, Director 138pp 18474:017,
- 8305190002 Forwards executed Indemnity Agreement 8-96, per 830214 request COSS.B W Texas Utilities Generating Co 83/04/18, PAGE.R G Uranium Fuel Licensing Branch 14pp 18502.021

DOCKET 70-2959 CONNECTICUT, UNIV DF. STORRS, CT

- 8304230152 Discusses IE insp of Licenses SNM-1889.04-01450-47 & O4-01450-48 on 830303-04 & forwards nutice of violation MARTIN.T T Division of Engineering & Technical Programs 83/04/11 VAN GELDER.A Connecticut. Univ of 2pp 18179 275
- --B304250163 Notice of violation from insp on 830303-04 Noncompliance noted Rooms 302R & 32d containing licensed math not posted, current copies of Form NRC-3 not posted & Room 472 not secured

 * Region 1, Office of Director 83/04/11 ip 18179 277
- DOCKET 70-2973 COMMONWEALTH EDISON CD . CHICAGO: IL
- 8305180787 Executed Indomnity Agreement B-97
 SALTZMAN.J Assistant Director for State & Licensee Relations *
 Commonwealth Edison Co. 83/05/06 13pp 18805 332
- 8305190004 Forwards Hatls License SNM-1917 & safety evaluation License SNM-1917 authorizes receipt possession insp & storage of U enriched in U-235 isotope contained in fuel assemblies PAGE.R O Uranium Fuel Licensing Branch 83/05/06 TRAMM, T R Commonwealth Edison Co 2pp 18523 221
- --8305190006 Matls License SNM-1917.authorizing receipt.possession.insp & storage of U enriched in U-235 isotope contained in fuel assemblies * Division of Fuel Cycle & Material Safety 83/05/06 3pp
- --8305190007 Safety evaluation supporting License BNM-1917 authorizing receipt possession insp & storage of fuel assemblies containing U enriched to 355% SERINI.B L Uranium Fuel Licensing Branch 83/05/06 12pp 18929 226
- 8305240339 Forwards executed copy of Indemnity Agreement 8-97 OSTER, J Commonwealth Edison Co 83/05/19 SALTZMAN, J Assistant Director for State & Licensee Relations 13pp 18572 342

DUCKET 70-2982 ROCHESTER, UNIV OF, ROCHESTER, NY

- 8305200139 Forwards License BNM-1918 for Univ of Rochester, authorizing possession of 456 g enriched U. in form of U hexafluride PAGE.R G Uranium Fuel Licensing Branch 83/05/13 QREGORY, W D Rochester. Univ of. 1p 18540 239
- --8305200165 License SNM-1918 for Univ of Rochester authorizing possession of 456 g enriched U as U hexafivoride PAGE.R G Division of Fuel Cycle & Material Safety 83/05/13 4pp 18340 240

DOCKET 70-2983 PENNSYLVANIA POWER & LIGHT ALLENTOWN, PA

- 8305180646 Application for license to receive, possess, store, inspect & package for transport nuclear fuel bundle/assemblies
 Supporting documentation encl
 CURTIS,N W Pennsylvania Power & Light Co 83/04/12 Office of
 Nuclear Material Safety & Safeguards, Director 25pp 18505 204
- 8305240939 Forwards 930412 application for receipt & storage of new fuel W/o encl KETZLACH N Uranium Fuel Licensing Branch B3/05/17 CUTCHIN, J H Office of the Executive Legal Director ip 18393 337
- 8305240543 Forwards 830412 application for receipt & storage of new fuel W/o encl KETZLACH.N Uranium Fuel Licensing Branch 83/05/17 PERCH.R L Licensing Branch 2 ip 18593 327

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0001 ANEFCO, INC

8305040700 Requests add1 info re 830315 application for review & approval of Rav 7 to GA program concerning requirements for Anefco shipping packages MACDDNALD,C E Transportation Branch 83/04/29 MURPHY,D J Anefco,Inc 3pp 18336-250

DOCKET 71-0143 RANCHERS EXPLORATION & DEV CO

8305240051 Advises that final testing balancing adjustment & acceptance of new ventilation sys scheduled for completion by 830630 Entire sys must be rebalanced each time add1 process component added to sys MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/05/03 PAGE.R Q Uranium Fuel Licensing Branch 2pp 18594 302

DOCKET 71-0166 NEW YORK TESTING LABS, INC

B305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source, Model IR-30 source changer & Model 7 encapsulated source ROCKETT, D R Babcock & Wilcox Co 83/04/19 MACDONALD, C E Transportation Branch 1p 18594 301

DOCKET 71-0494 MONTANA X-RAY, INC

B304130034 Forwards Montana X-Ray, Inc GA program, implemented for License 25-21134-01 per 10CFR71 12(b)(1)(i)(i) STRINGHAM, S D Montana X-Ray, Inc 83/03/05 Office of Nuclear Material Safety & Safeguards, Director 1p 17938 290

--5304130042 OA program for QA procedures, engineering procedures & specific package design approval provisions
5TRINGHAM.5 D Montana X-Ray, Inc. 83/03/05 2pp 17958 291

DUCKET 71-0495 SOUTHWEST X-RAY CORP

B305040671 Forwards 0A program for License 42-19788-01 TILLEY,R Southwest X-Ray B3/04/13 MACDONALD, C E Transportation Branch 1p 18336 258

--8305040479 GA program for compliance w/10CFR71.App E TILLEY.R Southwest X-Ray 83/04/13 3pp 18336 259

8305130256 Forwards GA program approval for Radioactive Matl Package 0495.Rev O MACDDNALD.C E Transportation Branch 83/05/03 TILLEY,R Southwest X-Ray ip 18457 172

--B305i30261 GA program approval for Radioactive Matl Package 0475.Rev 0 MACDONALD.C E Transportation Branch 83/05/03 1p 18457 173

DOCKET 71-0496 NUS CORP

8305230165 Forwards Revs A & B to GA program manual for packaging used in transport of radioactive mati MOTL-0 P NUS Corp B3/05/02 MACDUNALD-C E Transportation Branch ip 18546-141

--B305230176 Revs A & B to GA program manual for packaging used in transport of radioactive matis CASELLI, A E , MOTL, O P NUS Corp B3/05/02 Pipp 18546: 143

DOCKET 71-4986 MODEL RA-2, RA-3, RA-J, GENERAL ELECTRIC CO

B305110015 Notification of registration as user of Model RA-3 in response to B30217 request MACDONALD, C E Transportation Branch B3/05/03 COUNSIL.W @ Northeast Utilities ip 18421 242

9303170097 Forwards Rev 14 to Certificate of Compliance 4986 for Models RA-2 & RA-3 MACDONALD.C E Transportation Branch 83/05/11 VAUGHAN.C M General Electric Co 2pp 18493 331.

--8305170102 Certificate of Compliance 4786 Rev 14 for Models RA-2 & RA-3 MACDONALD C E Transportation Branch 83/05/11. 5pp. 18495 333. DOCKET 71-5026 MODEL CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC

B305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct metl providing lOCFRI70 limits are not exceeded POPPE.L K Chem-Nuclear Systems. Inc B3/04/14 MACDONALD.C E Transportation Branch 2pp 18476 183

DOCKET 71-5332 MODEL 2030-1, ENERGY, DEPT OF

8305040782 Informs that Certificate of Compliance 5332 for Model 2030-1 shipping package expired on 830131 MACDDNALD.C E Transportation Branch 83/04/19 BARRACLAUGH,E Energy, Dept of 1p 18327 245

DUCKET 71-5552 MODEL GAS CYLINDER FIRE IMPACT SHIELD, ENERGY, DEPT

B305260003 Forwards Rev 1 to DRNL/ENG/TM-5, "BAR for Packaging ORNL, Gas Cylinder Fire & Impact Shield," final draft TRAVIS,W H Energy, Dept of B3/04/18 MACDONALD,C E Transportation Branch 2pp 1864B 123

--8305260004 Rev 1 to "8AR for Packaging DRNL Gas Cylinder Fire & Impact Shield," final draft W/six oversize drawings Aperture cards are available in PDR EVANS.J H. LEVINE.D L., EVERBOLE.R E Dak Ridge National Laboratory DRNL/ENG/TM-5 DRF 01 83/04/30 129pp 18648*125

DOCKET 71-5607 MODEL T-2, ENERGY, DEPT OF

B305230080 Forwards revised pages to ANL "T-2 Shipping Package SAR." MOSER,R M Energy, Dept of 83/04/12 MACDONALD,C E Transportation Branch 3pp 18546 001

--8305230086 "T-2 Shipping Package SAR," revised pages FRANKLIN.E.M Argonne National Laboratory 83/03/31 137pp

8305180626 Documents 830414 telcon re registration for GE T-2 package. No ltr of registration located in files Current validity of NRC 770428 notice of registration questioned DEIGLH J Texas A&M Unity , College Station, TX 83/04/18. MACDONALD, C E Transportation Branch 1p 18305 325

--8305180630 Notification of registration as user of Model QE T-2 in response to 770404 request MACDONALD, C E. Transportation Branch 77/04/28 RANDALL, J D Texes A&M Univ , College Station, TX 1p. 18505-326

8305230697 Requests clarification as to whether licensee may continue to use GA procedure already approved or whether request for registration should be amended based on mod to inner basket on GE T-2 package
DEIGC.H J Texas A&M Univ , College Station, TX. 83/05/02
MACDONALD.C E. Transportation Branch ip 18542 325

DOCKET 71-5814 MODEL NRBK-41, -42 & -43, ENERGY, DEPT. OF

8305090048 Forwards Rev 1 to Certificate of Compliance 5914 for Modela NRBK-41: NRBK-42 & NRBK-43 MACDUNALD, C.E. Transportation Branch 83/04/28 ENGEL, W.P. Energy, Dept of 4pp 18381 176.

--8305090056 Certificate of Compliance 5814, Rev 1, for Models NRBK-41, NRBK-42 & NRBK-43 MACDONALD, C E Transportation Branch 89/04/28 4pp 18381-180

DOCKET 71-5874 MODEL, WAPD-40, ENERGY, DEPT. OF

8305090145 Forwards Rev 1 to Certificate of Compliance 5874 for Model WAPD-40. MACDONALD: C.E. Transportation Branch. 83/04/28 ENGEL, W.P. Energy, Dept. of. App. 18381 113

--8305090150 Certificate of Compliance 3874/Rev 1.for Model WAPD-40 MACDONALD.C E Transportation Branch 83/04/28 3pp 18381 117

- DOCKET 71-5875 MODEL WAPD-39 & NRBK-44, ENERGY, DEPT OF
- B305090133 Forwards Rev 1 to Certificate of Compliance 5875 for Models WAPD-39 & NRBK-44 MACDDNALD, C E Transportation Branch 83/04/28 ENGEL, W P Energy, Dept of 4pp 18381 120
- --8303090140 Certificate of Compliance 5875, Rev 1, for Models WAPD-39 & NRBK-44 MACDUNALD.C E Transportation Branch 83/04/28 4pp 18381 124
- DOCKET 71-5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY
- 8305230016 Requests registration as user of Model BMI-1 WETHY.C M Florida Power & Light Co 83/04/20 MCDDNALD.C E Transportation Branch 1p 18542 256
- DOCKET 71-5979 MODEL 5979, ALPHA-DMEGA SERVICES, INC
- 830506020B Forwards Rev 4 to Certificate of Compliance 5979 for Model 5979
 MACDONALD.C E Transportation Branch 83/04/21 BRADLEY.W. Alpha-Omega Services.Inc ip 18359 357
- --8305060212 Certificate of Compliance 5979.Rev 4, for Model 5979 MACDONALD,C E Transportation Branch 83/04/21 3pp 18359 358
- DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO
- B305090113 Forwards Rev 7 to Certificate of Compliance 5980 for Model 0E-600 MACDIANALD, C E Transportation Branch B3/04/28 CUNNINGHAM, O E General Electric Co 2pp 18381:132
- --9305090121 Certificate of Compliance 5980, Rev 7 for Model GE-600 MACDONALD, C E Transportation Branch 83/04/28 6pp 18381 134
- DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR BYSTEMS, INC
- 8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded PDPPE, L K Chem-Nuclear Bystems, Inc 83/04/14 MACDONALD, C E Transportation Branch 2pp 18476 183
- DOCKET 71-6272 MODEL 6272, U S ECOLOGY
- 830518D670 Forwards revised application for amend to Cartificates of Compilance 6400 & 6272 MOBER,R M Energy, Dept of 83/04/15 MACDONALD,C E Transportation Branch 250 18305 154
- --8305180676 Revised application for amend to Certificates of Compliance 6400 & 6272 Approval for special packaged solidified waste as authorized contents in shipping containers requested # Energy, Dept of 83/04/30 24pp 18505 136
- DOCKET 71-6294 MODEL: UNC-2901, COMBUSTION ENGINEERING CO. INC
- 8305030001 Forwards changes to 821217 request for amend of Certificate of Compliance 6294 W/three oversize drawings Aperture cards are available in PDR FORDJ T Babcock & Wilcox Co 83/04/15 MACDONALD, C E Transportation Branch 85pp 18309, 243
- B305060187 Forwards Rev 6 to Certificate of Compliance 6294 for Model UNC-2901 MACDUNALD.C E Transportation Branch 93/04/25 ESKRIDGE,H K Combustion Engineering, Inc. 2pp 18364 302,
- --8305060190 Certificate of Compliance 6294, Rev 6, for Model UNC-2901 MACDONALD, G E Transportation Branch 83/04/25 5pp 18364, 304

- DOCKET 71-4344 MODEL FSV-1. GENERAL ATOMIC CO
- 8305090231 Requests registration as user of Model FSV-1 KALIVIANAKIS.N Commonwealth Edison Co 83/04/15 MACDONALD.C E Transportation Branch ip 18381 101
- 83D5170584 Natification of registration as user of Model FSV-1 in response to B30415 request MACDQNALD.C E Transportation Branch 83/05/09 KALIVIANAKIS,N Commonwealth Edison Co 1p 18496 107
- DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP
- 8305180670 Forwards revised application for amend to Certificates of Compliance 6400 & 6272 MOSER.R M Energy, Dept of 83/04/15 MACDUNALD.C E Transportation Branch 2pp 18505 154
- --8305180676 Revised application for amend to Certificates of Compliance 6400 & 6272 Approval for special packaged solidified waste as authorized contents in shipping containers requested # Energy, Dept of 83/04/30 24pp 18505 156
- DOCKET 71-6495 MODEL PADUCAH DEMONSTRATION CASK, ENERGY
- 8305160278 Forwards request for add1 info re 821117 application requesting approval of model Paducah demonstration cask packaging Response must be received within 30 days of ltr receipt MACDUNALD, C E Transportation Branch 83/05/06 PRICHARD, R P Energy, Dept of 3pp 18475 038
- DOCKET 71-6550 MODEL 6-06-1, ENERGY, DEPT OF
- 8305240552 Forwards Certificate of Compliance 6550.Rev O.for Model 6-08-1 HARVEY, R V Lawrence Berkeley Laboratory 83/05/03 MACDDNALD, C E Transportation Branch 1p 18594 220
- --8305240556 Certificate of Compliance 6590.Rev O.for Hodel 6-08-1 MACDONALD.C E Transportation Branch 83/05/03 2pp 18594 221
- DOCKET 71~6553 MODEL PADUCAH TIGER, ENERGY, DEPT OF
- 8305040791 Informs that Certificate of Compliance 6553 for Paducah Tiger shipping package expired on 830331 MACDUNALD.C.E Transportation Branch 83/04/19 BLALOCK.L Energy, Dept of 2pp 18327 194
- 8305240064 Requests extension of Certificate of Compliance 6553 for use in moving U hexefluoride between gaseous diffusion plants Leak test data forthcoming PRICHARD, R P Energy, Dept of 83/04/29 MAGDONALD, C E Transportation Branch ip 18577 361
- DOCKET 71-6601 MODEL CNS B-120, CHEM-NUCLEAR SYSTEMS, INC
- 8305020535 Requests mailing address change for BD Withers * Portland General Electric Co 83/04/09 NRC - No Detailed Affiliation Given ip 18284 258
- B305170733 Requests amend to Certificates of Compliance 4244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing IOCFRI70 limits are not exceeded POPPE,L K Chem-Nuclear Systems, Inc. 83/04/14 MACDONALD,C E Transportation Branch 2pp 18496 183
- 8305170589 Notification of registration as user of Model CNS 8-120 in response to 830304 request MACDQNALD, C.E. Transportation Branch 83/05/09 COUNEY, M J Philadelphia Electric Co ip 18496 105
- DOCKET 71-6639 MODEL MH-1A, ENERGY, DEPT OF
- 8305180210 Responds to 830224 ltr requesting addl info re approval of Model MH-iA Estimates that 4 months will be required to respond to questions Packaging angineers will arrange meeting to discuss request PRICHARD, R P Energy, Dept. of 83/04/20 MACDONALD, C E Transportation Branch ip 18503 331

B305170573 Summary of B30502 meeting w/DQE & Sandia in Silver Spring.MD re review of SAR for 820907 MH-1A application DDEGARDEN,R H Transportation Branch 83/05/06 Transportation Branch 2pp 18496 124

DOCKET 71-6708 MODEL C-6, ENERGY, DEPT OF

8305090214 Informs that Certificate of Compliance 6708 for Model C-6 shipping package expired on B21031

MACDONALD,C Transportation Branch B3/04/19 PETERSON.J M
Energy. Dept of 1p 18381 110

DOCKET 71-6717 MODEL 6717-8. GAMMA INDUSTRIES

83030200&1 Requests registration as user of Gulf Nuclear 10x,20v,U-110A & Gamma Industries Models C-10 & Century & Pipeliner 1 FILLEY,R Southwest X-Ray 83/04/13 MACDONALD,C E Transportation Branch 1p 18308 286

B305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source, Model IR-90 source changer & Model 7 encapsulated source ROCKETT.D R Babcock & Wilcox Co 83/04/19 MACDONALD.C E Transportation Branch 1p 18574 301

8305110023 Notification of registration as user of Model 6717-8 in response to 830413 request
MACDONALD.C E Transportation Branch 83/05/03 TILLEY.R Sooner
X-Ray & Mag , Inc 1p 18411 357

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

8305170108 Forwards Rev 9 to Certificate of Compliance 7010 for Model MACDONALD, C E Transportation Branch 83/05/10 JOHNSON, C R Nuclear Assurance Corp 3pp 18495 348

-8305170113 Certificate of Compliance 9010.Rev 9. for Model NLI-1/2 MACDONALD.C E Transportation Branch 83/03/10 8pp 18495 351

DOCKET 71-9015 MODEL TN-8, -9L, NO USERS

0305230107 Forwards Rev 1 to second addendum to TN-8/9 SAR GOLDMANN,K Transnyclear, Inc 93/05/03 MACDONALD.C E Transportation Branch ip 18546 303

--8305230118 Forwards Rev 1 to second addendum of TN-8 & TN-9 SAR Issuance of Rev 3 to Certificate of Compliance 9015 for Models TN-8 & TN-8L packaging requested COLDMANN,K Transpuclear, Inc 83/04/26 MACDDNALD.C E Transportation Branch 2pp 18546 304

--8305230125 Rev 1 to "TN-8 & TN-9 SAR Second Addendum for TN-8 & TN-8L Packagings " # Transnuclear, Inc E-3508 R01 83/04/26 33pp 18346 307

8305170245 Forwards Rev 4 to Certificate of Compliance 9015 for Models TN-8 & TN-8L MACDONALD,C E Transportation Branch 83/05/12 GOLDMANN.K Transpuclear, Inc.

--8305170251 Certificate of Compliance 9015.Rev 4, for Models TN-8 & MACDONALD, C E Transportation Branch 83/05/12 7pp 18493 344

DOCKET 71-9033 MODEL 460 & 660E, TECHNICAL OPERATIONS, INC

8305170738 Application for registration as user of Tech/OPs Model 660 KAWACHI,M Navy,Dept of,Pearl Harbor Naval Shipyard 83/02/11 MACDONALD,C E Transportation Branch 1p 18496 182

DUCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8305110143 Notification of registration as user of Model QE-1600 in response to 830331 request MACDONALD, C E Transporta Transportation Branch 83/05/06 JONES-W C Omaha Public Power District 1p 18421 349

DOCKET 71-9049 MODEL GE-500, GENERAL ELECTRIC CO

B305110021 Notification of registration as user of Model 9E-500 in response to B30412 request MACDONALD, C E Transportation Branch B3/05/03 STEIN, 8 B Advanced Medical Systems, Inc 1 p 18411 358

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8305180019 Application for exemption from requirement of Certificate of Compliance 9070 for Model N-55 Requests one time shipment of Pu fluoride neutron source containing 35 Ci Pu-238 in encapsulated form encepsotates form
NARDIA J Hestinghouse Electric Corp 83/04/27 MACDON
Division of Fuel Cycle & Material Safety 3pp 18497 200 MACDONALD, C E

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

8305040147 Advises that encl Hittman Nuclear & Development Corp 830406 proprietary application & associated repts & drawings re Model HN-100, Series 2 package design should be placed in PDR, per 830216 ltr MACDONALD, C E Transportation Branch 83/04/25 SCOTT, 8 Document Management Branch 18336 231

--8309040159 Forwards addi info to support 830216 request that HN-100, Beries 2 casks be included in renewal of Certificate of Compliance 9079 Rev 6 to "Cask Handling Procedure for HN-100, Series 2 & Series 3 " encl MALLORY,C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/06 MACDONALD,C Transportation Branch, Spp. 19324 232 18336 232

---8305040176 Rev & to "Cask Handling Procedure for HN-100, Series 2 & Series 3 Shielded Transport Casks " W/three oversize drawings Aperture cards are available in PDR # Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/06 15pp 18336 235

8305110211 Notification of registration as user of Model HN-100 Beries 2 in response to 830401 request MACDONALD.C E Transportation Branch 83/05/06 MINECK.D L Iowa Electric Light & Power Co 1p 1841 352

DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8305180816 Requests registration as user of Model 9080 radioactive matls shipping cask HIS.F J Rochester Oas & Electric Corp 83/04/21 MACDONALD.C E Transportation Branch ip 18303 336

B305110019 Notification of registration as user of Model 9080 in response to 830218 request MACDONALD, C E Transportat MACDONALD, C E Transportation Branch Wisconsin Electric Power Co 1p 184 83/03/03 FAY, C H. 18411 357

DOCKET 71-9081 MODEL CNBI 1-13C, CHEM-NUCLEAR SYSTEMS, INC

8305170587 Notification of registration as user of Model CNS 1-13C in response to 830228 request MACDONALD.C E Transportation Branch 83/05/09 90R8T.F J Public Service Co of Colorado ip 18496 106

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC

8305160280 Forwards request for add1 info supporting 830228 application for amend to Model CNS 21-300 Response should include drawings, shielding & operating procedures & acceptance tests Response requested within 30 days MACDONALD, CE Transportation Branch 83/05/03 POPPE, L K Chem-Nuclear Systems, Inc. 3pp 18475 008

DOCKET 71-9100 MODEL KKP-20-4950, KERR-MCGEE NUCLEAR CORP

8305030181 Requests registration as user of Model KKP-20-4950. O'HEA.P B. Rhone-Poulens, Inc 83/04/14. MACDONALD.C.E Transportation Branch 1p 18310 030

- B305110130 Forwards Rev 2 to Certificate of Compliance 9100 for Model KKP-20-4950 MACDONALD, C.E. Transportation Branch 83/05/06 SHELLEY, W.J. Kerr-McGee Nuclear Corp 2pp 18434 105
- --8305110151 Certificate of Compliance 9100.Rev 2.for Model KKP-20-4950 MACDONALD, C E Transportation Branch 83/05/06 4pp 18434 107
- DOCKET 71-9103 MODEL NUT-A502, NO USERS
- 8305110011 Forwards Rev 3 to Certificate of Compliance 9103 for 30511001: rorus, ... Model NLI-6502 MACDONALD,C E Transportation Branch n Branch 83/05/03 JOHN8ON, C R 18421 R43
- --8305110013 Certificate of Compliance 9103, Rev 3 for Model NLI-6502 MACDONALD, C E Transportation Branch 83/05/03 5pp 18421 251
- DOCKET 71-9105 MODEL RAD-WASTE CR I, CHEM-NUCLEAR SYSTEMS, INC.
- 8305030716 Forwards Rev 2 to Certificate of Compliance 9105 for Model RAD-WASTE CARRIER I MACDONALD.C E Trensportation Branch 83/04/25 DEAL.R Chem-Nuclear Systems. Inc 4pp 18309 075
- --8305030720 Certificate of Compliance 9105.Rev 2.for Model RAD-WASTE MACDONALD, C E Transportation Branch 83/04/25 2pp 18309 079
- DOCKET 71-9106 MODEL BW-20MC-3, BABCOCK & WILCOX CO
- 8305040772 Informs that Certificate of Compliance 9106 for Model BW-20WC-3 shipping package expired on 830228 MACDONALD.C E Transportation Branch 83/0 A RINAGROS PILAGNER Babcock & Wilcox Co 18327 299 10
- DUCKET 71-9111 MODEL CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC
- 8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 3026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded POPPEL K Chem-Nuclear Systems. Inc 83/04/14 MACDONALD, C E Transportation Branch 2pp 18496 183
- 8305110017 Notification of registration as user of Model CNS 6-80-2 in response to 830314 request MACDONALD, C E Transportation Branch 83/05/03 MUSQLF, D MACDCHALD, C.E. Transportation Branch S: Northern States Power Co 1p 18411'360
- DOCKET 71-9135 MODEL CENTURY B & SA, CEN UNIV B & SA, GAMMMA IND
- 8304270399 Ack receipt of response to error natice for Model C-10 Identical typographical error observed on Page 5 of 820430 safety evaluation
 RIDDLE,D H Nuclear System 83/04/08 MACDONALD,C E
 Transportation Branch ip 18244/311
- 8305230104 Requests registration as user of Model Century S & 5A ENGBLOM, M R Hardy Associates, Inc 83/04/18 MACPONALD, C E Transportation Branch 1p 18546 342
- 8305050436 Forwards revised Page 5 to SER on Model Century series packaging.per 830408 ltr MACDDNALD.C E Transportation Branch 83/04/26 RICHARDSON.H D Nuclear System 2pp 18352 049
- DOCKET 71-9148 MODEL 770, TECHNICAL OPERATIONS, INC.
- B305170592 Notification of registration as user of Model 770 in response to B30323 request MACDONALD, CE Transportation Branch, B3/05/09 CUNNINGHAM, O E General Electric Co 1p 18496 103

- DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT OF
- B305180684 Forwards application for amend to Certificate of Compliance 9150 revising operational controls for shipping Pu safeguards samples UDLE.RE Energy, Dept of 83/04/19 CUNNIN Fuel Cycle & Material Safety 2pp 18504 073 CUNNINGHAM, R F Division
- ---8305180688 Application for amend to Certificate of Compliance 9150, revising operational controls for shipping Pu safeguards Sandia Laboratories 83/04/30 53pp 18504 076
- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP
- 8305230730 Submits rev to Paragraph 5(b)(2) of revised Certificate of Compliance 7151 for Model HN-100 Series 3 re max quantity of masi MALLORY,C W Hittman Corp B3/04/29 MACDONALD,C Transportation Branch 3pp 18576 175
- 8305170591 Notification of registration as user of Model CNS 14-170 in response to 830228 request MACDDMALD.C E Transportation Branch 83/05/09 MUSOLF.D Northern States Power Co ip 18496 104
- B305170255 Forwards Rev 2 to Certificate of Compliance 9151 for Models INN-100 Series 3 & CNS 14-170 Series 3 MACDUNALD. C E Transportation Branch B3/05/12 SILLYMAN. D Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 18493 351
- --B305170260 Certificate of Compliance 9151.Rev 2.for Model HN-100 Series 3 & CNS-14-170 Series 3 MACDONALD, C E Transportation Branch 53/05/12 5pp 18493 353
- 8305260350 Advises that encl Hittman Nuclear & Development Corp 830427 Itr re 830200 application for amend to Certificate of Compliance 9151 & associated proprietary SARs & drawings Compilance 733 a massacration should be placed in PDR MACDONALD,C E Transportation Branch 83/05/13 SCOTT,8 Document Management Branch ip 18648 025
- --8305260355 Forwards add1 info supporting 830203 application for amend to Certificate of Compliance 9151 to permit use of stainless steel shielding insert, in response to NRC request W/four oversize drawings Aperture cards are available in PDR MALLDRY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/27 MACDONALD, C Transportation Branch Opp Corp) 18648 026
- --8305260373 Rev 7 to "Cask Handling Procedure for HN-100 Series 2 & Series 3 Shielded Transport Casks "
 Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/26 16pp 1848 032
- DOCKET 71-9156 MODEL, IR-50, INDUSTRIAL NUCLEAR CO
- 8305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source, Model 1R-50 source changer & Model 7 encapsulated source agreement of Model 7 encapsulated source ROCKETT.D R Babcock & Wilcox Co B3/04/17 MACDUNALD, C & Transportation Branch 1p 18594 301
- DOCKET 71-9163 MODEL GNG-20, GULF NUCLEAR, INC.
- 8305240031 Forwards revised info re Model GNG-20 source container HOPCRAFT,C P Gulf Nuclear, Inc 83/04/28 MACDONALD.C.E Transportation Branch 35pg 18594 224
- DOCKET 71-9175 MODEL CNS6-80B, NUCLEAR PACKAGING, INC
- 8305060133 Releases Nuclear Packaging, Inc 830304 application for certificate of compliance, SAR & drawings to public W/o drawings MACDONALD, C E Transportation Branch 83/04/25 SCOTT, 8 Document Management Branch ip 18384 029
- --B309060142 Responds to B30318 request for add1 application fee for certificate of compliance Intent is to limit payload so Model CNS 6-808 can be licensed under Category IIC so no add1 fee required.

 STREUTKER, S. R. Nuclear Packaging, Inc. B3/03/24 JACKBON, G STREUTKER, S.R. Nuclear Packaging, Inc License Fee Management Branch 2pp i 18354 030

- --8305060148 Application for certificate of compliance for Model CNS6-808 bulk resin shipping flask BTREUTIFERS R Nuclear Packaging. Inc 83/03/04 MACDONALD, C E Transportation Branch 8pp 18354 032
- --8305060152 "SAR for CNS 6-80B Shielded Cask to IOCFR71 Type B Packaging Requirements" Nuclear Packaging, Inc. 83/03/04 225pp IB354 040
- --8305060154 Requests add1 fee re 830304 application for certificate of compliance for Model CNS5-808 bulk resin shipping flast JACKSON, 9 License Fee Management Branch 83/03/18 STREUTHER, 8 Nuclear Packaging, Inc 2pp 18354 266
- DOCKET 71-9177 MODEL NUPAC 10/140, NUCLEAR PACKAGING, INC
- B305020002 Forwards Rev O to Certificate of Compliance 9177 for Model NUPAC IO/140
 MACDUNALD.C E Transportation Branch B3/04/18 SIMCHUK, J D Nuclear Packaging, Inc. 1p iB308 289
- --8305020004 Certificate of Compliance 9177.Rev D.for Model NUPAC 10/140 MACDONALD,C E Transportation Branch 83/04/18 12pg
- --830502000B Safety evaluation approving use of Model Series A waste shipping packages for shipment of low-specific activity radioactive matl
 MACDENALD, C E Transportation Branch 83/03/28 9pp 18308 273
- DOCKET 71-9180 MODEL 500-SU: AUTOMATION INDUSTRIES: INC
- 8305180194 Forwards add1 info on operating instructions, acceptance criteria & general maint for Model 5008U-OP, per 830411 request SANTORO. M P Automation Industries, Inc B3/04/21 MACDONALD. C E Transportation Branch App 18503 324
- DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC
- B305040096 Releases Nuclear Packaging Inc B30331 application for certificate of compliance & SAR for placement in PDR MACDDNALD C E Transportation Branch 83/04/25 SCOTT.S Document Management Branch 16 18331 267
- --8305040105 Application for certificate of compliance for NUPAC Post-Accident Sampling Cask PAS-2 STREUTKER.5 R Nuclear Packaging, Inc 83/03/31 Transportation Branch 4pp 18331 268
- --8305040i10 "BAR for NUPAC PAS-2 Packaging to 10CFR71 Type B Packaging Requirements"

 Notlear Packaging, Inc. 83/03/31 91pp 18331 272
- DOCKET 71-9510 MODEL GPHS, ENERGY, DEPT OF
- B303020036 Forwards info on shipping cylinder for GPHS module & welding & insp procedures, in response to NRC 820930 request W/three oversize drawings Aperture cards are available in PDR MILLER, R L Energy. Dept of 83/04/18 MACDONALD, C E Transportation Branch 10pp 18308-251

- DOCKET 71-9788 MODEL 55W REACTOR COMPARTMENT, ENERGY, DEPT OF
- B305110612 Forwards Rev O to Certificate of Compliance 9788 for Model SSM reactor compartment MACDONALD, C E Transportation Branch 83/05/06 ENGEL, W P Energy, Dept of 1p 18415 354
- --8305110614 Certificate of Compliance 9788.Rev O.for Model 85W reactor compartment MACDONALD.C E Transportation Branch 83/05/04 4pp 18415 355,
- DECKET 71-9901 MODEL 120, ENERGY, DEPT OF
- B305040786 Notifies that Certificate of Compliance 9901 for Model 120 shipping package expired on B30228 MACDONALD: C E Transportation Branch 83/04/19 PETERSON, J M. Energy. Dept of 1p 18327 196
- 8305110033 Forwards Rev I to Certificate of Compliance 9901 for Model 120 MACDUNALD,C E Transportation Branch 83/05/06 PETERSON,J M Energy, Dept of 1p 18421 304
- --8305110035 Certificate of Compliance 9901, Rev 1, for Model 120 MACDONALD, C.E. Transportation Branch 83/05/06 6pp 18421:305

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

- DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- 8305240034 Submits annual rept re changes, tests & experiments at Morris Operations facility during period 820304-830430, per 100FR72 336(b)2 EOER, K. J. General Electric Co. 83/05/02 Region 3, Office of Director ip 18377
- 8305170549 Forwards addendum consisting of confirmatory measurements program data sheet of analysis of waste lagoon sample completed after onsite inspitransmitted by 830215 ltr PAPERIELLO, C J Region 3, Office of Director 83/05/09 VAN HOOMISSEN General Electric Co Zpp 18468-031
- 8305130227 Forwards IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-02 on 830419-21 No noncompliance noted MILLER, J R Region 3, Office of Director 83/05/10 VAN HOOMISSEN General Electric Co 2pp 18439 171
- --8305130234 IE Safeguards Insp Repts 70-1308/63-02 & 72-0001/83-01 on 830419-21 No noncompliance noted Major areas inspected matl control & accountability, measurement & statistical control. Details withheld (ref 10CFR2 790) MADEDA: T J . STAPLETON: B W . CREED, J R Region 3, Office of Director 83/05/10 ip 18439 173

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

- 8305020529 Unofficial transcript of Commission 830424 public meeting re-possible vote on restart in Washington. DC Pp 1-107 * Commissioners. 83/04/26 127pp 18284 075 24x Fiche 50-272, 83/04/26. 8305020529
- B305040054 Discusses status of B&W-OPU lawsuit document review Next rept expected within 2 wks DIRCKS,W J Office of the Executive Director for Operations 83/04/20 PALLADINO,N, QILINSKY,V., AMERNE, J Commissioners 2pp 18336.325 24X Fiche 50-289,83/04/20,8305040054
- --8305040068 Staff requirements memo re 830330 briefing on investigation & possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wks.

 CHILK, B. J. Office of the Secretary of the Commission M830330B 83/04/08 DIRCKS, H. J. Office of the Executive Director for Operations HAYES, B. B. NRC No Detailed Affiliation Given CUMINOS, J. J. Office of Inspector & Auditor 2pp 18336 327 24X Fiche: 50-289, 83/04/20, 8305040054
- 8305040086 Transcript of 830422 briefing in Washington, DC re THI-2 cleanup Pp 1-98
 # Commissioners 83/04/22 124pp. 18328 242 24x
 Ficha: 50-320, 83/04/22, 8303040086
- 8305040755 Transcript of Commission 830427 public meeting in Washington, DC re midyr program review, Pp 1-90 # Commissioners 83/04/27 50pp 18351 260.
- 8305060696 Staff requirements memo re Nuclear Haste Policy Act of 1982 (ref SECY-83-107)
 CHILK:8 J Office of the Secretary of the Commission M830318
 83/03/26. DIRCKS:W J Office of the Executive Director for Operations. 2pp. 18358.128.
- --B905060700 Discusses co-location of test & evaluation facility & geologic repository.per B30318 Commission briefing on Nuclear Weste Policy Act of 1982 Related info encl DIRCKB.W J Diffice of the Executive Director for Operations. B3/04/05 CHILK.S J Office of the Becretary of the Commission 15pp. 18398-130
- 8305090512 Responds to 830406 staff requirements memo re briefing on DHR studies on C-E plants. Investigation will be completed by 830630 & results of study, conclusions & recommendations will be presented to Commission by Aug-Bept. DIRCKS.H.J. Office of the Executive Director for Operations. 83704/25. CHILK.B.J. Office of the Sacratary of the Commission, ip. 18381-846.
- --8305090516 Staff requirements memo re 830404 briefing on DHR studies on C-E plants. Commission requested NRC accelerate study & solicit & address ACR8 views on issue CHILK, 8. J Office of the Secretary of the Commission M830404 83/04/04. DIRCKS, W J Office of the Executive Director for Operations. ip. 18381 249
- B305090645 Transcript of Commission 830504 brisfing on state of nuclear industry in Washington.DC Pp 1~47. Supporting documentation encl
 # Commissioners 83/05/04 BBpp 18366:017
- B305110604 Transcript of Commission B30429 briefing in Washington DC ra U mill tailings stds.Pp 1-61 Viewgraphs encl # Commissioners. B3/04/29. 62pp. 18421:001.

- B305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at 830419 meeting w/PO&E in Ban Francisco.CA EISENHUT, D 0 Division of Licensing 83/05/04 PALLADING, N J , GILINGKY, V , AHEARNE, J Commissioners 3pp 18440 228 24x Fiche 30-275,83/05/04,830512061i.
- ---8305120621 Transcript of 830419 public meeting in 8an Franciso,CA re review of component coaling water sys Pp 1-121 * Commissioners 83/04/19 123pp 18440 231 24X Fiche 50-279,83/05/04,8305120611
- 8305130327 Transcript of Commission 830505 meeting discussion & possible vota in Washington DC re status of emergency planning at facilities Pp 1-22
 * Commissioners 83/05/05 27pp 18457 277 24X
 Fichs. 50-247, 83/05/05, 8305130327
- 8303170089 Transcript of Commission 830312 meeting in Washington, DC to discuss evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation ent1 * Commissioners 83/03/12 81pp 18495 226 24X Fiche 30-272.83/03/12,8303170089
- 8305170192 Transcript of Commission 830512 meeting in Washington, DC to discuss Regulatory Task Force administrative proposals re backfit rule Pp 1-78 Bupporting documentation encl & Commissioners 83/05/12 87pp 18492 213
- B305180076 Transcript of Commission B30513 affirmation/discussion & vote in Hashington, DC re proposed rule on storage & disposal of high level waste Pp 1-5.

 ** Gommissioners B3/05/13 6pp 18499, 350
- B305180082 Transcript of Commission B30512 affirmation/discussion & vots on BECY-83-157 concerning facility OL in Washington, DC Pp 1-4

 * Commissioners 83/05/12 7pp 18503 279 24X
 Fichs 50-322,83/05/12,8305180082
- B305180391 Transcript of Commission B30513 public meeting w/ACR8 in Weshington: DC to discuss severe accident research program & accident source term program Pp 1-66 * Commissioners. B3/05/13 66pp 18482-041
- 8305230130 Transcript of Commission 830518 public meeting in Hashington. DC re evaluation of implications of facility event 'art 1) Pp 1-82. Supporting documentation encl # Commissioners, 83/05/18 97pp 18577 110 24X Fiche 50-272,83/05/18,8305230130
- B305240566 Releases transcript of Commission B21222 discussion & possible vote on emergency planning actions for placement in PDR, per 10CFR7 Commission determination statement enti CHILK.B J Office of the Secretary of the Commission B3/03/18 PUBlic Document Branch 2pp 18393 063 24X Fiche 50-003,83/05/18-8305240566
- --8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington.DC e Commissioners 82/12/22. 15pp 18573-065. 24X Fiche 30-003.83/05/18,8305240566
- --8305240574 Transcript of 821222 discussion & possible vote on amergancy plenning actions in Mashington.DC
 * Commissioners, 82/12/22, 39pp 18593-082, 24X
 Fichs. 50-003,83/05/18,8305240566
- 9305250256 Staff requirements memo re 830504 briefing on state of nuclear industry in Washington, DC GHILK, 8 J Office of the Secretary of the Commission M830504A, 83/05/05 Office of the Secretary of the Commission. Ip 18595 343.

- 8305250303 Requests info on why resolution of Unresolved Issue A-17 will precede Unresolved Issue A-47 since both items are closely related Response requested by 830517 using std question & answer format FUNCHES, J. L. Plenning & Program Analysis Staff 83/05/11 SPEIS, T.P. Division of Safety Technology 2pp 18594 356
- --B305250308 Staff requirements memo re B30427 midyr program review on info requested on number of people & dollars necessary to handle Waste Mgt Act as well as questions Chairman Palledino will be addressing by separate memo CHILK.S. J Office of the Secretery of the Commission MB30427 B3703/06 DIRCKS,W J Office of the Executiva Director for Operations. 3pp 18594 358
- 8305230588 Responds to 830415 steff requirements memo ra schedule for decision on license amend request to permit operation of steam generators, Schedule for decision contingent upon outcome of significant hezards determination DIRCKS.W J Office of the Executive Director for Operations 83/05/19 CHLK,B.J Office of the Secretary of the Commission 9pp 18594:337 24X Fiche 50-289,83/05/19,8305250588
- --8305250590 Staff requirements mamo re 830415 brisfing on status of TMI-1 steam generator repairs Commission requested info on differing dates for decision on license amend request depending on significant hazards determination CMILK, B J. Office of the Secretary of the Commission. M8304158 83/04/25 DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 18594-346 24X Fiche 50-289, 83/05/19, 8305250588,
- 8305240195 Transcript of Commission 830523 affirmation/discussion & vote in Washington,DC re SECY 83-117,83-059 & 83-0598 * Commissioners 83/05/23 14pp 18648,074
- 8305270041 Transcript of Commission 830523 briefing on NRC comments on EPA proposed Title II 864s (U mill tailings) in Washington, DC. Pp 1-90 Visugraphs enct # Commissioners, 83/05/23 94pp 18661 363
- 8305310055 Transcript of Commission 830523 discussion of Indian Point order in Washington, DC Pp 1-19.

 * Commissioners 83/05/23 23pp 18663 128 24X
 Fichs 50-247,83/05/23,8305310055.
- 8305310071 Transcript of Commission B30524 briefing in Hashington, DC re NRC revalidation of mgt competence for restart Pp 1-57 Viewgraphs enci # Commissioners 83/05/24 73pp 18669 025 24X Fiche 50-289,83/05/24,830531007i

ACRE ADVISORY COMMITTEE ON REACTOR SAFEOUARDS

- 8304140158 Summary of ACRS CRBR Subcommittee meeting on 821027 in Washington, DC re plant design criterial retionale of selection of DBA spectrum & associated pravention/mitigation sys & plant safeguards & security a ACRS Advisory Committee on Reactor Safeguards 82/10/29 ACRS Advisory Committee on Reactor Safeguards 21pp 18541-04 24X Fichs 50-537.62/10/29,8304140158
- 8305020087 Transcript of ACRS Subcommittee on Reactor Radiological Effects 830428 mesting in Washington DC Pp 1-278 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/04/28, 512pp 18279 279.
- 8305020174 Transcript of ACRS Bubcommittee on QE Hater Reactors, DESSAR-II B30422 meeting in Santa Monica.CA Pp 361-609. Bupporting documentation encl # ACRS Advisory Committee on Reactor Safeguerds. B3/04/22 357pp 18281 299 24X Fiche 50-447.83/04/22.8305020174
- 8305030327 Transcript of ACRS Subcommittee on Reactor Radiological Effects 830429 hearing in Heshington, DC Pp 299-567 Supporting documentation encl a ACRS Advisory Committee on Reactor Safeguerds. 83/04/29 310pp 18297, 183.
- 8305040552 Notification of contract execution "Extreme External Phenomena Subcommittee," awarded to George Mashington Univ. HOYLE, A Administrative Contracts Branch FIN B-1557 NRC-11-83-703, 83/04/25, FRALEY, R.F., ACRS Advisory Committee on Reactor Bafeguards BAVIG, R. NRC No Detailed Affiliation Given ip. 18351 234.
- --8305040553 Contract "Extrama External Phenomena Subcommittee," ewarded to George Washington Univ FOX.R.R George Washington Univ. REBELLO, J.E. Division of Contracts. FIN 8-1557. NRC-11-83-703 83/04/25 4pp 18351: 235

- B305090366 Comments on proposed plan for regionalization of certain NRC operations reviewed during ACRS 274th.275th & 276th meetings on B30210-12, 0310-12 & 0414-16 respectively Potential negative impact on reactor safety discussed, EBERSOLE.J.C. ACRB Advisory Committee on Reactor Bafeguards B3/04/19 PALLADING.N J Commissioners 3pp 18367.216
- 8305100164 Trenscript of ACRS LACBWR SEP Subcommittee 830506 hearing in Washington. DC Pp 1-166 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/05/06 227pp 18370 265 24% Fiche 50-409, 83/05/06, 8305100164
- 8305120001 Transcript of ACRS Subcommittee on Electrical Sys 830510 hearing in Washington, DC Pp 1-155. Supporting documentation encl.

 * ACRS Advisory Committee on Reactor Safeguards. B3/05/10 231pp 18428 001
- 8305120002 Transcript of ACRB Subcommittee on ECCS 830510 hearing in Weshington, DC, Pp 1-294 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/05/10. 379pp 18423 077
- 8305120127 Transcript of ACRS Subcommittee on AC/DC Power Sys 830510 meeting in Washington, DC. Pp 1-173 Supporting documentation encl.

 * ACRS Advisory Committee on Reactor Safeguards. 83/05/10 232ss. 18422:004.
- 8305120556 "Consultant Rept for ACRS Revisw of CRBR Thermal Hargin Beyond Design Basis," POWERS, D. A. Sandia Laboratories POWERS, D. A. ACRS - Advisory Committee on Resctor Bafeguards. 83/05/10 30pp. 18443:090 24) Fiche: 50-537,83/05/10,8305120556.
- 8305120562 Summary of 269th ACRS meeting on 820909-11 re safety goals for nuclear power plants.

 * ACRS Advisory Committee on Reactor Safaguards 83/05/05.

 ACRS Advisory Committee on Reactor Safaguards, 239pp 18442;211.
- 8305130005 Transcript of ACRS Subcommittee on Safety Research Program 830511 meeting in Washington, DC Pp 1-322. Supporting documentation and a ACRS Advisory Committee on Reactor Safeguerds, 83/05/11, 399pp 18438 132.
- 8305130015 Transcript of ACRS Combined Bubcommittees on Reliability & Probabilistic Assessment & Extrame External Phenomena 830511 meeting in Mashington DC. Pp 1-136 Supporting documentation encl.

 # ACRS Advisory Committee on Reactor Safeguards. 83/05/11 188pp. 18436, 020.
- 8305130270 Summary of 268th ACRS meetings on 820512-14 in Washington.DC * ACRS - Advisory Committee on Reactor Sefeguards. 83/05/05 ACRS - Advisory Committee on Reactor Sefeguards. 327pp. 18458:225 24X Fiche: 50-000.83/05/05.8305130270.
- 8305130321 Gomments on ACRS Equipment Qualification Subcommittee 830315 meeting. Mild environs need attention; equipment vibration qualification incomplete & plant aging research required. CATTON, I. ACRS Advisory Committee on Reactor Safeguards. 83/04/04. CAPPUCCI.A.J. ACRS Advisory Committee on Reactor Safeguards. ip 18457 307
- 8305130326 Comments on NUREO/CR-3324 itams Unprotected transient overpower accident & unprotected loss-of-flow accident should be reviewed at ACRS full committee meeting. RASTENBERG, N.E. ACRS Advisory Committee on Reactor Bafeguards. 83/03/28. CARBON, M. ACRS Advisory Committee on Reactor Bafeguards 4pp. 18457-303.
- 8305130340 Responds to ACRS 830315 meeting request for comments on qualification program for safety-related squipment Analysis of equipment in mild & extreme environs; comparative seismic stresses & electrical distribution sys recommended.
 LIPINGKI,W.C. Argonne Netional Laboratory LIPINGKI,W.C. ACRS Advisory Committee on Reactor Safeguards 83/03/28. ESERBOLE,J.C. ACRS Advisory Committee on Reactor Safeguards 2pp. 18457.338.
- B305130344 Comments on qualification program for ACRS Subcommittae on Safety-Related Equipment 830315 meeting.
 PICKEL,T.H. Union Carbide Corp. PICKEL,T.H. ACRS Advisory Committee on Reactor Bafeguards. B3/03/23. CAPPUCCI.A J. ACRS Advisory Committee on Reactor Safeguards. 2pp 18443:340.

- B305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities Supporting documentation encl.

 MAXWELL, J C Maxwell, J C MAXWELL, J C ACRS Advisory Committee on Reactor Safeguerds B3/05/05 KERR, W ACRS Advisory Committee on Reactor Safeguerds Spp 18443:335 24X Fiche 50-443:83/05/05, 22034:20347
- 8303130349 Submits comments on core disruptive eccidents & seismic margins per request made at ACRS 830316-17 meetings Applicant energetic source term acceptable Seismic margin calculations not eccaptable LIPINSKI.W C Argonne National Laboratory LIPINSKI.W C ACRS Advisory Committee on Reactor Safeguards 83/03/31 CARBON, N W ACRS Advisory Committee on Reactor Safeguards. 5pp 18457 340 24% Fichs 50-537,83/03/31.8305130349.
- 8305130350 Comments on seismic design safety margin for facility Additionments to be made at ACRS 830414 meeting SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS Advisory Committee on Reactor Safeguards 83/03/31 BOEHNERT, PACRS Advisory Committee on Reactor Safeguards, 3pp. 18443 357 24X Fiche 30-537,83/03/31,8305130350.
- 8305130332 Informs of unessiness on selection of 1735 Cape Ann earthquake as facility std for design response spectra. Critical safety-related components should be designed to withstand larger Chapleston event. POMEROY, P. W. Rondout Associates, POMEROY, P. W. ACRS Advisory Committee on Reactor Sereguards B3/04/05 KERR, W. ACRS Advisory Committee on Reactor Sereguards 2pp. 18443'333 24X Fiche. 30-443, 83/04/05, 8305130332,
- 8305130355 Provides input re seismic safety margins for CRBR, based on ongoing seismic safety margins research program at lab.

 BOHM.H.P. Lawrence Livermore Laboratory. BOHM.H.P. ACRB Advisory Committee on Reactor Sefeguards. SB-83-76/0911U. 83/04/08

 CARBON,H ACRS Advisory Committee on Reactor Safeguards. 6pp 18443-326 24X Fiche 50-537,83/04/08,8305130355
- 8305130359 Telecopy of comments on CRBR re pressure boundary Design of reactor pressure vessel mests & usually exceeds requirements of ABME III & relevant code cases.

 BUSH:8 H Bettelle Hemorial Institute, Pacific Northwest Laboratory BUSH:8 H ACRB Advisory Committee on Reactor Bafeguards 82/03/30. CARBON, M. ACRB Advisory Committee on Reactor Bafeguards.

 Bafeguards, 2pp 18443-324 24X Fiche:50-537,83/03/30,8305130359
- B303160030 Transcript of ACRS 277th general meeting on B30512 in Washington,DC.Pp 1-241. Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/05/12 315pp. 18452 023
- 8305160246 Commants on BBHRP risk analysis. Risks from seismic events should be analyzed separately from internal events w/results treated independently. Only upper limits need be estimated to determine if risks acceptable.

 DAVIS, P. R. Affiliation Unknown DAVIS, P. R. ACRS Advisory Committee on Reactor Bafeguards. B3/04/16. CKRENT. D. ACRS Advisory Committee on Reactor Bafeguards ip. 18472, 001 24X Fiche. 50-295, 83/04/16.8305160246.
- 8305160299 Forwards rapt summerizing review of TMBDB presentation at ACRB 830310-11 meetings Review confined to thermomechanics, engineering design & finite element analysis. Review will be summerized at 830414 meeting.

 ANDERSON.C.A. Los Alamos Scientific Laboratory ANDERSON.C.A. ACRS Advisory Committee on Reactor Safeguards G-13-83 163. 83/03/29 CARBON.M ACRS Advisory Committee on Reactor Safeguards. 6pp. 18472:069 24X Fiche: 50-537.83/03/29,8305160299.
- 8305170301 Transcript of ACRS 277th general meeting on B30513 in Weshington, DC Pp 242-438 Supporting documentation encl * ACRS - Advisory Committee on Reector Safeguards. B3/05/13 321pp. 18463-188
- B305180391 Transcript of Commission B30513 public meeting w/ACRS in Washington,DC to discuss savere accident research program & accident source term program. Pp 1-66 ** Commissioners 83/05/13. 66pp. 18482;041
- B305180620 Summary of ACRS Subcommittees on Metal Components & TMI-1
 B30128 meeting in Washington: DC re review of potential steam
 generator generic requirements & current steam generator
 repair program
 # ACRS Advisory Committee on Reactor Safeguards, 83/04/12,
 ACRS Advisory Committee on Reactor Safeguards, 19pp, 18504:001.
 24X Fiche: 50-289, 83/04/12, 8305180620

- 8305180637 Expresses appreciation for opportunity to participate in CRER project review Seismic safety margin estimates probably conservative Failure of small diameter pipes will be discussed SEIDENSTICKER Argonne Netional Laboratory SEIDENSTICKER ACRS Advisory Committee on Reactor Sefeguards 83/04/15 CARBON, M ACRS Advisory Committee on Reactor Sefeguards 1p 18505 329 24K Fiche 50-537.83/04/15,8305180637
- 8305180664 Burmary of ACRS 830223 meeting u/Subcommittee on SEP in Mashington, DC to review facility integrated safety assessment w ACRS Advisory Committee on Reactor Safeguards ACRS-2078 83/04/07. ACRS Advisory Committee on Reactor Safeguards 18pp 18502 327 24X Fiche 30-027,83/04/07.8305180664
- S305180668 Summary of ACRS Subcommittee on Regulatory Policy & Procedures S30207 & OB meetings in Mashingon;DC re-briefing by Regulatory Reform Task Force:Ofc of General Counsel & Ad Hoc Committee on Regulatory Reform # ACRS Advisory Committee on Reactor Safeguards 83/04/14 ACRS Advisory Committee on Reactor Safeguards 12pp 18505 062
- --8305180674 Summary of ACRS 830208 meeting c/Subcommittee on Regulatory Policy & Procedures in Washington.DC re Ofc of Executiva Director briefing on concept of regionalization * ACRS - Advisory Committee on Reactor Safeguards. 83/04/14 ACRS - Advisory Committee on Reactor Safeguards 3pp 18505 071
- --B305180678 Certifies minutes of ACRS Subcommittee on Regulatory Policy & Procedures 830207-08 maetings Issued on 830331 LEMIS,H ACRS - Advisory Committee on Reactor Safeguards 83/03/31 OASKE,M C Deputy Executive Legal Director. 1p 18505-074
- 8303230002 Transcript of ACRS Subcommittee on Human Factors 830519 meeting in Washington, DC Pp 1-290 Supporting documentation and ACRS Advisory Committee on Reactor Safeguards 83/05/19 369pp. 18533 273
- 8305240033 Forwards comments on ACRS Subcommittee on Reactor Radiological Effects 830428 meeting re use of potassium indine as thyroid blocking agent. NRC risk/benefit analyses not compatible w/comparable approaches. EBERSCH.E.J C ACRS - Advisory Committee on Reactor Safeguards 83/05/17 DIRCKS.H J. Office of the Executive Director for Operations 26pp 18577 333
- 8305250074 Comments on Task IC 126-5, "Reg Quide on Instrument Sensing Lines," dtd 821108 Provisions of guide & referenced std not to be backfitted to nuclear plants now operating or under comst EBERBOLE.J C. ACR8 Advisory Committee on Reactor Bafaguards. 83/05/23. DIRCKS, W J. Office of the Executive Director for Operations ip 18394,304
- 8305230078 Clarifies major concerns w/plan for regionalization of certain NRC operations, per 830210-12, 0310-12, 0414-16 & 0512-14 ACRB 274-277th meetings EBEREOLE, J. C. ACRB - Advisory Committee on Reactor Bafeguards 83/05/16 PALLADING, N. J. Commissioners 2pp. 18596; 309
- 8305260008 Comments on recent work & proposed programs re accident sequence precursor atudy & use of operational experience, at 274th & 277th ACRB meetings on 830414-16 & 0512-14 respectively.
 EBERSCHE, J. C. ACRS Advisory Committee on Reactor Bafeguards 83/05/18. DIRCKB: W J. Office of the Executive Director for Operations. 7pp 18449:098
- B305260104 Forwards summary of ACRB Subcommittee on Reactor Radiological Effects B30428 meeting re-control room hebitability. Evaluation of potential need for monitoring oxygen concentrations recommended EBERSOLE, J C. ACRB Advisory Committee on Reactor Safeguards B3/05/17. DIRCKB, W J. Office of the Executive Director for Operations Spp. 18649-068
- 8305310162 Trenscript of ACRS Subcommittee on Joint Metal Components/ Reactor Fuel 830526 mueting in Mashington, Dc. Pp 1-217. Supporting documentation encl. • ACRS - Advisory Committee on Reactor Safeguerds 83/05/26 325pp 18651:306.

ADVCM NRC ADVISORY COMMITTEE

8305230006 Forwards draft ltrs to individuals willing to appear at next advisory committee meeting in order to expedite preparation for 830526 meeting. LEVI.R P. NRC - No Deteiled Affiliation Given 83/04/29. SILBERT.E.J Schwalb, Donmenfeld, Bray & Bilbert 3pp. 18542 215

- --8305230010 Forwards transcript of Advisory Committee on Rights of Licensee Employees Under Investigation B30413 meeting.copy of committee charter & questions for committee in response to E Silbert request LEVI.R P. Office of the General Counsel 83/04/29 DEVINE, T Institute for Policy Studies ip 18542 217
- --8305230012 Discusses possibility of having investigators from other agencies testify at Advisory Committee on Rights of Employees Under Investigation 830526 meeting re-procedures & practices
 8[LBERT, E S Schwalb, Donnenfeld, Bray & Silbert 83/05/03
 FITIGERALD, A Office of Investigation REUBHAUSEN, D Debevoise & Plington SCOTT, J B Kator, Scott & Heller 2pp 18542 220
- --8305230017 Confirms appearance at Advisory Committee on Rights of Licenses Employees Under Investigation 830526 meeting. Transcript of last meeting.list of questions for committee & committee charter encl LEVI-R P NRC - No Detailed Affiliation Given 83/05/04 SHOOP-P. Affiliation Unknown ip 18542 222
- --8305230025 Forwards draft FR notice announcing Advisory Committee on Rights of Licenses Employees Under Investigation 830526 meeting LEVI.R P. NRC - No Detailed Affiliation Given 83/05/03. REUBHAUSEN.O Debevoise & Plimpton ip 18542:223
- --8305230032 Forwards draft FR notice announcing Advisory Committee on Rights of Licenses Employees Under Investigation 830526 meeting LEVI,R P NRC - No Detailed Affiliation Given. 83/05/05. SILBERT.E J Schwalb, Donnenfeld, Bray & Silbert. ip 18542 224.
- --B305230040 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting LEVI:R P NRC - No Detailed Affiliation Given. B3/05/05 BCOTT.J B. Kator, Scott & Heller. ip. 18542 225.
- --8305230048 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting LEVI:R P. NRC - No Detailed Affiliation Given. E3/05/05 BPRITIER:R S Pennsylvania, Univ. of. 5pg 18542,226
- 8305230384 Submits questions Advisory Committee on Rights of Employees Under Investigation should address to aid in deliberations, PALLADING.N J Commissioners 83/04/11 SILBERT.E J Schwelb, Donnenfeld, Bray & Silbert 2pp. 18543-360.

COMMISSION NRC COMMISSIONERS

- B30504013B Forwards proposed Chairman testimony before Udall Subcommittee B30406 hearing re developments since Apr 1982 at TMI, responding to items in Congressman Udall B30413 ltr. W/o proposed testimony DENTON, H R. Office of Nuclear Rescutor Regulation, Director-B3704/20 DIRCKS, W J. Office of the Executive Director for Operations 2pp 18327:011 24X Fiche. 50-289.83/04/20,8305040138.
- --8303040145 Enumerates items to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982 UDALL.M K House of Rep , Interior & Insular Affairs. 83/04/13 PALLADINO, N Commissioners 2pp. 18327.013 24% Fiche 50-289,83/04/20,8305040138
- 8305040777 Heekly info rept for wk ending 830422. REHM:T A Office of the Executive Director for Operations 83/04/29 42pp 18327:257
- 8905110105 Heatly info rept for wk ending 830429. REHM:T A Office of the Executive Director for Operations. 83/05/06 47pp 18421-257.
- 8305170717 Washly info rept for wk ending 830306, REHM.T.A Office of the Executive Director for Operations. 83/05/12. 42pp. 18496.202
- 8305230121 Heetly info rept for wk ending 830513. REHM:T. A Office of the Executive Director for Operations. 83/05/20. 44pp. 18577:066
- 8305230354 Forwards rept on nondisclosure of safeguards info for quarter ending Mar 1983, PALLADINO, N J. Commissioners 83/05/06, BUSH, 9 H. Benate. O'NEILL, T. P. House of Rep. 5pp 18542-001,

- 8305230360 Responds to 830406 ltr re basis for not implementing or enforcing codified U mill licensing regulations contained in App A to 100FR40, Prior approval from Committee on Appropriations sought appropriating spending funds PALLADINO, N J Commissioners 83/05/05 UDALL, M.K House of Rap., Interior & Insular Affairs. 2pp 18542 007
- --B305230369 Expresses concern re status of implementation & enforcement of U mill licensing regulations to have been effective beginning B30101 UDALL-M K. House of Rep., Interior & Insular Affairs. B3/04/06 PALLADINO,N J Commissioners 2pp 18542:009
- B305230377 Responds to questions in B30323 ltr re steem generator tube rupture scenario at TMI-1 & Subcommittee on Oversight & Investigation B21213 hearing Updated status of TMI action plan items provided on B30325 PALLADINO, N J Commissioners B3/05/05 MARKEY, E J House of Rep.: Interior & Insular Affairs Bpp 18683'307 24X Fiche 50-289,83/05/05,8305230377
- --8305230388 Requests further response to issues in 830121 ltr re steam generator tube degradation at TMI-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items also requested.

 MARKEY.E. J. House of Rep., Interior & Insular Affairs. 83/03/23, PALLADINO,N J. Commissioners. 2pp 18542:019, 24x Fiche: 50-289,83/05/05,8305230377
- B305230384 Submits questions Advisory Committee on Rights of Employees Under Investigation should address to aid in deliberations. PALLADING, N. J. Commissioners 83/04/11. BILBERT, E. J. Bchwelb, Donnenfeld, Bray & Silbert, 2pp 18543:340
- 8305230397 Responds to 830330 request for views on B.B. 389, creating offense for aggravated property destruction at energy facility. Position not taken as legislation not applicable to facilities under NRC jurisdiction.

 PALLADING, N. J. Commissioners 83/05/05, THURMOND, B. Benete, Judiciary Committee. 1p. 18542-021
- ---B305230406 Requests views on encl 8,8 388 to create offense for aggravated property destruction at energy facility. Response requested within 20 days.
 THURMOND: B Benate: Judiciary Committee 83/03/30.
 PALLADINO, N. J. Commissioners 4pp. 18542*022.
- B305230413 Advises of Commission decision not to make any changes in present structure for provision of legal sycs within Commission, in response to request in House Rept 77-880, Commissioners Gilinsky & Roberts advocate further study. PALLADING, N J. Commissioners 83/05/05, BEVILL, T. House of Rep., Appropriations, 1p 18342-026
- B305230420 Responds to B30314 ltr urging implementation of spent fuel provisions of Nuclear Haste Policy Act (P.L. 97-425). Proposed rule 10CFRS3, "Criteria for Determining Adequacy of Available Beent Nuclear Fuel Storage Capacity" encl PALLADIND,N.J. Commissioners. B3704/27, RILEY,R.W. South Carolina, State of. 2pp. 18542:027.
- --B305230425 Proposed rule iOCFR53, "Criteria & Procedures for Determining Adequacy of Available Spent Nuclear Fuel Btorage Capacity." CHILK: B J Office of the Secretary of the Commission. B3/04/26, 20pp 18542,029.
- 8305230435 Forwards response to Question 20 in 830223 ltr re NRC review of BEW/GPU trial record.
 PALLADING,N J. Commissioners 83/04/28. UDALL,M K. House of Rep., Interior & Insular Affairs 2pp 18542:051 24X Fiche: 50-289,83/04/28.8305230435.
- --8305230440 Informs of dissenting opinion re Commission majority decision blocking General Counsel review of BMM/GPU trial record in TMI-1 restart proceeding. Decision will hamper ability of individual Commissioners to obtain needed info. QILINBKY.V. Commissioners. 83/04/07 SIMPBON.A.K. Benate, Environment & Public Works. 2pp. 18542:033. 24X Fiche: 50-289, 83/04/28, 8305230435.

- --8305230443 Responds to Chairman Palladino 830307 request for views on legality of Commission decision directing Executive Director for Derections, rather then Dfc of General Counsal, to review B&W/OPU trial record Actions supported PLAINE.H H E Office of the General Counsal 83/03/25 PALLADINO.N J. GILINERY.V. A MEARNE.J Commissioners 5pp 18542 055 24% Fiche 50-289,83/04/28.8305230435
- --8305230446 Provides Commission response to Commissioner Gilinsky 830407 Itr disagreeing w/Commission majority decision to block General Counsel review of 84k/6PU trial record in TMI-1 restart proceeding Commission actions justified PALLADING,N J Commissioners 83/04/19 UDALL,M K House of Rep., Interior & Insular Affairs 4pp 18542 060 24X Fiche 50-289,83/04/28,8305230435
- --8305230453 Disagrees w/Commission mejority views in Chairman Palladino 830419 ltr justifuing Commission decision to block General Counsel review of B&H/GPU trial record in TMI-1 restart proceeding

 ABSELSTINE, J K Commissioners 83/04/25 UDALL, M K House of Rep , Interior & Insular Affairs 3pp 18342 064 24X Fiche 50-289,83/04/26,8305230435
- B305230457 Forwards NRC "Rept to Congress on Study of Financial Impacts on Resident Inspectors "
 PALLADINO,N. U Commissioners B3/04/29 OTTINGER,R L House of Rep., Energy & Commerce SIMPSON.A Senate, Environment & Public Horks UDALL,M K House of Rep., Interior & Insular Affairs Spp. 18842-067.
- 8305230465 Responds to 830322 1tr discussing activities of ANS Special Committee on Source Terms Info meeting to present work of committee welcomed PALLADING, N. J. Commissioners 83/05/02 STRATTON, H.R. American Nuclear Society. 1p. 18542:151
- --9305230469 Discusses activities of ANB Special Committee on Source Terms Meeting to discuss source term issue & present work of committee proposed STRATTON.W.R. American Nuclear Society 83/03/22 PALLADINO.N J Commissioners. 2pp 18542-152
- 8305230474 Forwards "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness. Jan-Mar 1983 "
 PALLADING, N J. Commissioners, GIUFFRIDA, L G Federal Emergency Hanagement Agency 83/05/03 BIMPBON, A K. Benate, Environment & Public Works. 2pp. 18542-154
- --B205230479 "NRC/FEMA Joint Guarterly Rept to Congress on Emergency Preparedness, Jan-Mar 1983." * NRC - No Detailed Affiliation Given * Federal Emergency Managsment Agency 83/03/31, 59pp 19542, 156
- B303230660 Forwards current long-range research plan, in response to B30325 request for info on ongoing & anticipated research activities using existing source terms PALLADINO,N J Commissioners B3/04/21 BQUGARD,M House of Rep., Science & Technology, 3pp 18542 333
- --8305230664 Ack receipt of 830104 response to request for Commission views on implementing recommendations in committee rept on NRC research program (H R 97-793) List of ongoing & anticipated research activities requested 80000ARD; M. L. House of Rep., Science & Technology 83/03/25, FALLADINO, N. Commissioners. 3pp. 18542.336
- 8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level amergency plan per cited conditions. NMRG-0654-FEMA-REP-1, Rev 1 stds would place heavy resource burden on state.

 GIUFFRIDA.L.O Federal Emergency Management Agency 83/04/18, PALLADINO.N.J Commissioners. 1p 18342-329, 24X Fiche 50-003,83/04/18,6305230670.
- --B305230676 Beeks clarification of issue re FEMA review of offsite amergency planning around facilities Questions whether state can substitute for county w/o own emergency plan. PALLADINO, N. J. Commissioners. B3/03/30. OIUFFRIDA, L. D. Federal Emergency Management Agency 2pp. 18542:330. 24X Fiche: 50-003, 83/04/18, 8305230470.
- B305230692 Comments on H R.600 re federal monitoring, analysis, reporting & policy on foreign acquisition of US businesses & assets in vital & sensitive net! interest sectors of economy, in response to B30218 ltr.NRC cannot support bill as drafted, PALLADINO, N. J. Commissioners, B3/04/20 BROOKS, J. House of Rep. Government Operations, 2pp. 18543:063.

- --B305230675 Forwards H R 600 for comment Transmittal of reply in triplicate requested BROURG J House of Rep , Government Operations B3/02/18 PALLADINO,N J Commissioners 61pp 18543 065
- 9305230703 Urges resolution of remaining questions re facility restart Delay in resolving restart issue unacceptable when jobs at stake Restart issue should receive high priority this Opring BROYHILL, J T , MOORHEAD, C J , RITTER, D House of Rep , Energy & Commerce 93/03/16 PALLADINO, N Commissioners 3pp 18342 317 24X Fiche 50-289,83/03/16,8305230703
- B305230732 Concurs w/B30307 ltr re informal resolution of NRC response to Congressional correspondence Senior Commission staff may sign responses involving submittal of factual info,per B30218 ltr
 PALLADINO, N J Commissioners 93/04/13 MARKEY, E J House of Rep. Interior & Insular Affairs 1p 18942 260
- --8305230735 Objects to Congressional response procedure outlined in 830218 ltm. Commission should be accounteble to members of Congress for accuracy & completeness of info Commissioners requested to review issues MARKEY.E J House of Rep , Interior & Insular Affairs 83/03/07 PALLADINO.N J Commissioners 2pp. 18542 261
- B305240019 Responds to B30418 ltr recommending retention of technical cadre of experts to review CRBR & overell DDE breeder program Maint of CRBR Program Dfc at adequate level planned. Decision on issuance of CP expected by June 1984 DIRCKS,H J Office of the Executive Director for Operations B3/05/10 LLOVP,H House of Rep. Bcience & Technology 3pp 18577 308 24X Fiche 50-537.83/05/10.8305240019
- ---8305240023 Recommends that Commission retein technical cadre of experts to review CRBR & overall DDE breeder program LLOYD, M House of Rep. Science & Technology 83/04/18 PALLADINO, N J Commissioners ip. 18577-310 24X Fiche 50-537,83/05/10.8305240019
- 8305240075 Discusses study of significant hazards consideration posed by reracking of spent fuel pools in response to 830414 memo. Science Applications, Inc will provide independent assessment. Final rept will be submitted by 830801 DIRCKS,W J. Office of the Executive Director for Operations 83/05/06 PALLADING,N, GILINSKY,V., AHEARNE, J.F. Commissioners 3pp 18594-305
- --8305240084 Requests description of plans for completing study on potential significant hazards of spent fuel pool reracking amends Description should include study approach & schedules for assuring submittal of final study by 830801 PALLADINGSN U Commissioners 83/04/14 DIRCKS, W U Office of the Executive Director for Operations ip 18594 308
- B305240155 Ack receipt of B30315 ltr expressing concern re Commission treatment of license amend request concerning retacking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis PALLADINO, N J Commissioners B3/04/22 SIMPBON, A K House of Rep., Environment & Public Works 2pp 18594 001
- --B305240167 Ack receipt of B30315 ltr expressing concern re Commission treatment of license amend request concerning remarking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis PALLADINO.N Commissioners B3/04/22. HART.O. House of Rep . Environment & Public Horks. 2pp. 18574 003
- --8305240179 Ack receipt of 830315 & 24 ltrs expressing concern re Commission treatment of license amend requests concerning remacking of spent fuel storage pools in interim final rule Amend requests examined on cese-bu-case basis. PALLADINO,N J. Commissioners 83/04/22 MITCHELL,O J House of Rep., Environment & Public Works 2pp. 18394:005
- --B305240190 "Btds for Determining Whether Licanse Amends Involve No Bignificent Hazands Considerations," 10CFR30 interim final rule, Amends regulation to specify stds for determining if requested amend to DL involves significant hazerds CHILK.B J Office of the Secretary of the Commission 83/04/04 44pp 18594,007.
- --8305110584 Discusses Sholly provision in FY82-83 NRC Authorization Act re treatment of emends to rerack spent fuel storage pools Treatment unecceptable BIMPBON. A K., HART. C., MITCHELL, C J Senate, Environment & Public Horks 83/03/15 PALLADINO, N J Commissioners 3pp. 18594 051

- --8305110401 Confirms 830323 telcon re proposed regulations for Sholly provision on amends to rerack spent fuel storage pools Proposed case-by-case exam for reracking unacceptable MITCHELL.0 J Senate 83/03/24 PALLADING, N J Commissioners 2pp 18574 054
- B305240216 Advises that B30323 ltr requesting immediate halt to all work at TMI-1 & 2. W/exception of maint necessary for safety, will receive consideration as request for action under 100FM2.206 FR notice end.

 DENTON, HR Defice of Nuclear Reactor Regulation, Director B3/05/17 kNO.R. Three Mile Island Public Interest Resource Center 2pp 18593 306, 24% Fiche 50-289,83/05/17,8305240216
- --8305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at THI-1 & 2

 DENTON.H R Office of Nuclear Reactor Regulation, Director.

 83/05/17 1p 18593 308 24X Fiche 30-289, 83/05/17, 8305240216.
- 8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All NRC ofcs will comply w/FOIA request. Request Requests will be coordinated w/Ofc of General Counsel PALLADING, N J Commissioners. 83/04/14 UDALL, M K. House of Rep , Interior & Insular Affairs 7pp. 18574 131 24X Fiche 50-358,83/04/14,8305240252
- --8305240256 Responds to 830302 ltr re processing of T Applegate FDIA request for documents on investigation into alleged const deficiencies All FDIA requests will be coordinated w/Ofc of General Counsel Commissioners views encl PALLADINO, N J Commissioners. 83/04/14 BEIBERLINO, J, F House of Rep . Interior & Insular Affairs 12pp 18594-138 24x Fiche 30-359,83/04/14,8305240252
- --B108250739 Bubmits minor organizational change & reaffirms previously established administrative procedures.

 CUMMINOS.J., Office of Inspector & Auditor 80/06/20, Office of Inspector & Auditor 80/06/20,
- --8305240263 Discusses investigation of Applegate allegations: "Adequacy of IE investigation 50-338/80-09 at WH Zimmer Nuclear Power Station," per Udall 821207 Itr IE investigation found unsatisfactory in Aug 1981 T Hampster interview enci CUMMINO8.J J Office of Inspector & Auditor 83/01/05 BICKWIT,L Diffice of the General Counsal. 8pg. 18394,153 24X Fiche 50-358,83/04/14.8305240252
- --8305240267 Forwards add1 info re NRC withholding of T Harpster interview w/Govt Accountability Project 811123 FOIA request, per Commission 830207 instructions CUMMINOS, J Office of Inspector & Auditor. 83/02/16 MALSCH, H G Office of the General Counsel 6pp 18574 163 24X Fiche 50-358,63/04/14,8305240252
- --8305240272 Requests into re Ofc of Inspector & Auditor (OIA) inquiry into Zimmer matter Reasons for removal of documents from OIA ofcs questioned Mithholding of documents contributed to delay in public recognition of true status of project.

 UDALLIM K. House of Rep. Interior & Insular Affeirs 82/12/07 PALLADINOIN J. Commissioners. ip 18594 169 24X Fiche 50-358,83/04/14,8305240252
- --8305240275 Requests add1 info re 821207 ltr seeking explanation of circumstances surrounding compliance w/FGJA request for documents pertaining to facility Adequacy of Cummings reply questioned UDALLM, SIESERLING, J. House of Rep., Interior & Insular Affairs 83/03/02, PALLADING, N Commissioners. 2pp 18594.170 24X Fiche 30-358,83/04/14,8305240252
- 8305250311 Responds to 830414 request for info re frequency of reactor scrams for US plants & explanation why comparable Japaness plants experience fewer reactor scrams. Table providing number of trips experienced for 1980.81 & 82 encl DIRCKS,W J Office of the Executive Director for Operations. 83/05/04. AHEARNE, J Commissioners. 9pp 18595:317
- --8305250313 Requests info re trips per yr per plant for US plants for last 3 yrs of operation & explanation why Japanese plants experience fewer trips. AMEARNE, J. Commissioners 83/04/14, Office of the Executive Director for Operations. 1p 18395, 327

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- B305030707 Corrected notification of contract execution. Mod 3 to "Earthquake Recurrence Intervals at Nuclear Power Plant Sites "Contractor: Ertes Western. Inc QUBTAVE.R P Technical Assistance Contracts Branch FIN B-7226. NRC-04-Bi-167 B3704/14 BATSON.W Office of Nuclear Regulatory Research. Director. MURPHY.A NRC No Detailed Affiliation Given in 18309 104
- 8305040280 Notification of contract execution, Mod & to "Electrostatic Copying Sycs " Contractor Literature Research Co BMITH, P.A. Division of Contracts NRC-10-79-361 83/04/25. BESAN, H.J. Division of Technical Information & Document Control. BAGGETT, M. NRC - No Detailed Affiliation Given 1p 18326.345
- --B305040284 Mod 6, deobligating balance of funds for closeout, to
 "Electrostatic Copying Svcs "
 BULLINOTON, R L Literature Research Corp. SMITH.P A Division of
 Contracts NRC-10-79-361, 83/04/25 ip 18326.346.
- 8305040341 Notification of contract execution. Mod 10 to "Gareer Counseling." Contractor. Binder, Elster, Mendelson & Wheeler, Inc.

 SMITM, P. A. Division of Contracts. NRC-10-79-387 83/04/28.

 BPRINGER, M. Office of Administration. TAYLOR, K. Management Development & Training Staff. ip 18324, 333
- --8305040345 Mod 10, deabligating balance of funds remaining unfor contract for official closeout, to "Career Counseling."
 MENDELBON, I N. Binder, Elster, Mendelson & Wheeler, Inc. SMITH, A. Division of Contracts NRC-10-79-387. 83/04/28 ip. 18326:334.
- 8305040552 Notification of contract execution: "Extreme External Phenomena Subcommittee:" awarded to George Washington Univ MOYLE, A. Administrative Contracts Branch FIN B-1357, NRG-11-83-703 83/04/25, FRALEY, R. F. ACR8 Advisory Committee on Reactor Safeguards SAVIO, R. NRG No Detailed Affiliation Given. 1p. 18351, 234.
- ---8305040553 Contract "Extreme External Phenomena Bubcommittee," awarded to George Washington Univ FOX.R R George Washington Univ. RESELLO, J. E. Division of Contracts FIN B-1557 NRC--11-B3-703, 83/04/25. 4pp 18351 235.
- B305040635 Notification of contract execution "Evaluation of Hatl Accounting Performence at Nuclear Fuel Cycle Facilities," awarded to NUSAG. Inc.
 HI001NB:E Technical Assistance Contracts Branch, FIN B-7379, NRC-02-93-027 B3/04/2l DAVIB:J Office of Nuclear Haterial Bafety & Bafeguards, Director, HILLER, M. NRC No Detailed Affiliation Given ip 18336:283
- --8305040643 Contract. "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities," awarded to NUSAC: Inc. PERENSTEIN.J.E NUSAC: Inc. MORTON,K.V. Division of Contracts. FIN 8-7379 NRC-02-83-027, 83/04/21 22pp. 18936:284
- 8305040650 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ. .." Contractor State of MI.

 8ILVIB.R M Technical Assistance Contracts Branch. NRC-05-73-014, 83/04/29. Director's Office, Office of Inspection and Enforcement. 1p. 18336, 269
- --B305040660 Mod i, deobligating funds, to "Establish Collaborative Program Retween State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ Around Selected Commission Licensed Activities," REIVITZ.L Misconsin, State of, OUSTAVE.R P. Division of Contracts, NRC-05-73-014. B3/04/27. ip. 18336-270.
- 8305050385 Notification of contract execution, Mod 3 to "Lease of Vehicles." Contractor: We Try Harder, Inc.

 BROMBERG: 8 Administrative Contracts Brench. FIN 8-8153,

 NRC-10-82-377. B3/04/26. CORLEY, J., GRANT, L., NRC No Detailed Affiliation Given 1p 18352.063.
- --8305050389 Mod 3, extending period of performance to 840512, to "Lease of Vehicles,"

 * He Try Harder, Inc. SMITH.P.A. Division of Contracts. FIN 8-8153 NRC-10-82-377. 83/04/26 ip. 18352:064.

- B305050400 Notification of contract execution, Mod 5 to "Performance of Engineered Barriers in Geologic Repository " Contractor Oolder Assoc. Inc.
 FIELDS, J A Division of Contracts FIN B-6986-3 NRC-02-81-027
 B3703/28 DAVIS, J Office of Nuclear Material Safety & Bafeguards, Director PITTIGLIG, L NRC No Detailed Affiliation Oiven ip 18352 060
- --B305050404 Mod 5, establishing provisional overhead rate for labor costs & increasing funding to "Performance of Engineered Barriers in Geologic Repository" PENTZ.D L Golder Associates GUSTAVE, R P Division of Contracts FIN 8-6986-3, NRC-02-81-027 83/03/28 2pp 18392 061
- B305060174 Notification of contract execution, Mod 7 to "Energetic Thermal Interactions & Coolant Flow Phenomena Associated M/Nuclear Reactor Goncepts, "Contractor Purdue Research Foundation FLEENOR, C Division of Contracts NRC-03-80-102 B3/02/25 MATTSON, R J Division of Bystems Integration (post B11005) MEYER, J NRC - No Detailed Affiliation Given ip 18359.354
- --8305060183 Mod 7. extending period of performance through 830322 & revising billing instructions to "Energetic Thermal Interactions & Coolant Flow Phenomena Associated W/Nuclear Reactor Concepts."

 OREENKORN, R A Purdue Research Foundation GUSTAVE, R P. Division of Contracts NRC-03-80-102 83/02/25 2pp 18359.355
- 8305060235 Notification of contract execution, Mod 5 to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for Ban Onofre Nuclear Generating Station Unit 1 Final Rept, '" Contractor Univ of California at Ban Diego BHITH P A Division of Contracts FIN B-6531, NRC-03-78-186 83/04/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. REITER, L. NRC No Detailed Affiliation Given 1p. 18359 352, 24% Fiche 30-206,83/04/25,B305060235.
- --8305060237 Mod 5, deobligating funds for closeout, to "Review of Rept Entitled 'Simulation of Earthquake Oround Motions for San Onefre Nuclear Generating Station Unit 1 - Final Rept.'" * California, Univ of, Ban Diego SMITH,P A Division of Contracts FIN 8-6531, NRC-03-76-186 83/04/25 ip 18359, 353 24% Fiche, 50-206, 83/04/25, 8305060235.
- 8305040246 Notification of contract execution. "Perform Studies Re-Data & Analysis of Nuclear Fuel Cycle," awarded to Nuclear Assurance Corp HOYLE: A Administrative Contracts Branch FIN 8-7386-3 NRC-02-83-037 83/04/26 BROWN.R 8 Program Support Branch. LOWENBERG.H. NRC - No Detailed Affiliation diven 1p. 18359-346
- --8303060251 Contract: "Perform Studies Re Data & Analysis of Nuclear Fuel Cycle:" awarded to Nuclear Assurance Corp DOIRON.D.9 Nuclear Assurance Corp REBELLO, J. E. Division of Contracts FIN 8-7386-3 NRC-02-83-037. 83/04/26 5pp. 1938 347
- 8305060320 Notification of contract execution. "Development of Reg Ouide & Regulatory Analyses," awarded to Analysis & Technology MI2001N8,E. Division of Contracts. FIN 8-8645 NRC-03-83-107, 83/04/01. THOMPBON.H.L. Division of Human Factors Bafety BENDER,L NRC - No Detailed Affiliation Given. ip. 18353-035
- ---B305060326 Contract "Development of Reg Quide & Regulatory Analyses."

 awarded to Analysis & Technology
 NOLF.D M Analysis & Technology, Inc. MORTON, K V Division of
 Contracts. FIN 8-8645. NRC-03-83-107, B3/04/01 28pp.
 18353-036.
- 8:305040341 Notification of contract execution, Mod 1 to "Geotechnical On-Call Assistance for Case Reviews." Contractor.US Army Corps of Engineers.
 FIELDS, J.A. Division of Contracts. NRC-03-82-107. 83/02/23.
 VOLLMER, R.H. Division of Engineering, HELLER, L. NRC No Detailed Affiliation Given, 1p. 18353:024.
- --B305060351 Mod i, changing address for submission of invoices to:
 "Geotechnical On-Cail Assistance for Case Reviews"
 KAVANAUGH, P.F. Army, Dept. of, Corps of Engineers HAGAN, T.F.
 Division of Contracts, NRC-03-82-107, B3/02/23 ip. 18353:025.
- 8305040379 Notification of contract execution Mod 4 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2, " Contractor Deotechnical Engineers Inc. FIELDB.J.A. Division of Contracts. NRC-03-82-092 83/04/12 VOLLMER.R.H. Division of Engineering. KANE, J. NRC No Detailed Affiliation Given. 1p 18353:086. 24X Fiche: 50-329,83/04/12.8305060379.

- --B305060384 Mod & modifying monthly business ltr reporting requirements, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 "
 POULDS, 3 J Geotechnical Engineers, Inc OUSTAVE, R P Division of Contracts NRC-03-82-092 83/04/12 3pp 18353 087 24X
 Fiche 50-329,83/04/12,8305060379
- 8305090009 Natification of contract execution, Mod 9 to "Site Suitability Assessments Based on Sepage & Groundwater Conditions Associated H/U Recovery Operations " Contractor Williams-Robinette & Assoc DELOATCH: V Technical Assistance Contracts Branch FIN B-7383-3 NRC-02-81-0239 83/04/29 DAVIS, J Office of Nuclear Material Sefety & Safeguards, Director 1p 18369 360
- --8305070012 Mod 9.extending period of performance to 830520, to "Bita Suitability Assassments Based on Beepage & Groundwater Conditions Associated H/U Recovery Operations "HILLIAMS, R. E. Williams-Robinette & Associates, Inc. QUBTAVE, R. P. Division of Contracts FIN B-7383-3 NRC-02-81-039 83/04/29 ip 18369 361
- B305090050 Notification of contract execution. Mod 7 to "Fire Protection Research Program " Contractor Underwriter Labs, Inc MOLLETT.8 Technical Assistance Contracts Branch FIN B-6197 NRC-04-77-122, 83/04/29 BATSON, W Office of Nuclear Regulatory Research, Director NOTLEY, D NRC No Detailed Affiliation Given. is 18361 174
- --8305090058 Mod 7, providing no cost extension until 830930, to "Fire Protection Research Program"

 4 Underwriters Laboratory OUBTAVE.R.P Division of Contracts FIN 8-6197 NRC-04-77-122 83/04/29 ip. 18381 i75
- 9305090068 Notification of contract execution, Mod 3 to "Goordination of Cooperative Organizations Participating in Geological, Geophysical & Seismological Studies "Contractor Bt Louis Univ. WOLLETT, 8 Technical Assistance Contracts Branch. FIN 8-7242. NRC-04-80-229 83/04/27 8AT80N.N Office of Nuclear Regulatory Research, Director WASTLER, S NRC No Detailed Affiliation Given ip 18381.136
- ---B305090ii7 Mod 3.extending performance to B31i0B at no add1 cost, to "Coordination of Cooperative Organizations Participating in Geological Geophyscial & Beismological Studies "

 * St Louis Univ , St Louis, MO GUSTAVE, R P Division of Contracts FIN B-7242 NRC-04-80-229 B3/04/29, 1p iB381:157
- 8303090122 Notification of contract execution, Mod 2 to "Manual to Define Lower Limits of Detection in Radiological Effluent & Environ Measurements " Contractor NBS.

 DELOATCH.V. Technical Assistance Contracts Branch FIN B-8615 NRC-03-B2-126 83/04/28 MATTSON:R Office of Nuclear Reactor Regulation, Director MEINKE.W NRC No Detailed Affiliation Given 1p 18381.128.
- --8305090131 Mod 2, changing period of performance to 840501 & increasing funds, to "Manual to Define Lower Limits of Detection in Radiological Effluent & Environ Measurements" SHREVE, D B Commerce: Dept of National Bureau of Standards. QUSTAVE, R. P. Division of Contracts FIN 8-8615 NRC-03-82-126 83/04/28 2pp 18381, 129
- B305090291 Notification of contract execution, Mod 2 to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys." Contractor, WBI Corp.
 COLEMAN. R Administrative Contracts Branch. NRC-33-83-456,
 B3/03/03 BASSETT, H Division of Data Automation & Management Information JOHNSON, C. NRC No Detailed Affiliation Olven Ip
- --8305090300 Mod 2, correctly stating amount certified under Mod 1, to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys " * HBI Corp MATTIA: M. J. Division of Contracts NRC-33-89-456 83/05/03 ip 18381 236
- B305110005 Notification of contract execution, Mod 4 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals." Contractor, O Charnoff TOWNSEND, B Administrative Contracts Branch, FIN B-8179, NRC-18-82-481 83/05/03 ROYHSCHILD, T Office of the General Counsel 1p. 18421 249.
- --8305110008 Hod 4.extending period of performance to 831231.to "Ad Hoc Committee for Review & Licensing Reform Proposals." ** Charnoff, Q. REBELLO, J. E. Division of Contracts FIN 8-8179. NRC-18-82-481. 83/05/03 Ip 18421 250.

- 8305110031 Notification of contract execution Mod 7 to "Technical Assistance on Site Characterization & Monitoring "
 Contractor US Army Corps of Engineers
 FLEENOR.C Technical Assistance Contracts Branch NRC-02-81-056
 83704/29 DAVIS.J Office of Nuclear Material Safety &
 Safeguards. Director. PENNIFILL.R NRC No Detailed Affiliation
 given ip 18421 311
- --8305110041 Mod 7, revising delivery schedule for task repts to extend period of performance to 830228, to "Technical Assistance on Bite Characterization & Monitoring " MARCUSON, W.F. Army, Dept of, Corps of Engineers GUSTAVE, R. P. Technical Assistance Contracts Branch NRC-02-81-036. 83/04/29 ip 18421 312
- 8305110146 Notification of contract execution "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Debevoise & Plimpton TOWNBEND.B Administrative Contracts Branch FIN 8-8182 NRC-18-83-407 83/05/03 ROTHSCHILD.T Office of the General Counsel LEVI.R NRC No Detailed Affiliation Given ip 18421 341
- --8305110152 Contract "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Debevoise & Plimpton RUEBHAUSEN, D M Pickard, Lowe & Garrick, Inc. REBELLO, J E. Division of Contracts. FIN 8-8182 NRC-18-83-407 83/05/03 App. 18421 342
- 8305110159 Notification of contract execution. Hod 3 to "Computer Based Spftware, Installation, Testing Documentation, Training & Sys Integration for Implementation of NRC YLD Direct Radiation Monitoring Network " Contractor Applied Physical Technology OLDENHORN, A J Administrative Contracts Branch NRC-10-80-671 B3/04/26 DORIEM Direct Administrative Contracts Contractor Costello, F NRC No Detailed Affiliation Oliven 19, 18434:241
- --8303ii0i63 Mod 3 reducing total amount of contract, to "Computer Based Software, Installation, Testing Dacumentation, Training & Sys Integration for Implementation of NRC TLD Direct Rediation Monitoring Network Program"

 * Applied Physical Technology, Inc HAGAN, T. F. Division of Contracts NRC-10-80-691, 83/04/26 2pg 18434 242.
- 8305110190 Notification of contract execution, Mod 3 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals "Contractor Dio Blate Univ HOYLE, A. Administrative Contracts Branch. FIN B-8179 NRC-18-82-481 83/04/25 ROTHSCHILD, T Office of the General Counsel. ip 18434 280.
- --8305i10i92 Mod 3.extending period of performance to 831231 & increasing total funding to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals "
 REDMOND.R F Ohio State Univ REBELLO.J & Division of Contracts FIN 8-8179 NRC-18-82-481 83/04/25 ip 18434 281.
- 8305i10194 Notification of contract execution.Mod 23 to "Security Burvey Ouides & Appraisal Ouide " Contractor: D Wright. HOYLE:A Administrative Contracts Branch. NRC-10-82-385 83/05/03. BRADY, R. J. Division of Security KIDD: D NRC No Detailed Affiliation Given ip 18434 277.
- ~~8305110198 Mod 3, reflecting new delivery schedule & payment, to "Security Survey Guides & Appraisel Guide" HRIGHT, D. Hright, D. REBELLO, J. E. Division of Contracts. NRC-10-82-395 83/03/03. jp 18434 278
- 8305110229 Notification of contract execution: "Automated Library Sys," awarded to On-Line Computer Sys,Inc.
 COLEMAN, R Administrative Contracts Branch NRC-33-83-454.
 83/05/05 BASSETT, H Office of Resource Management, Director.
 ZUNOOLI, 8 NRC No Detailed Affiliation Given. 1p. 18434 285.
- ---8305110232 Contract "Automated Library Sys," awarded to On-Line Computer Sys, Inc. LYNN, D.L. On-Line Computer Systems, Inc. MATTIA, M J. Division of Contracts NRC-33-83-454 83/05/05. 12pp. 18434 286.
- 8305i10233 Notification of contract execution, Mod 3 to "Investigation Into State of Stress in Crust Under Northeastern US."
 Contractor Columbia Univ.
 FIELDS.J.A Technical Assistance Contracts Branch. NRC-04-B1-180
 B3/04/29 BATSON.W.F. Office of Nuclear Reactor Regulation,
 Director. ZURFLUEH, E NRC No Detailed Affiliation Given 1p.
 18434 283
- --8305110236 Mod 23, extending expiration date to 831014, to "Investigation Into State of Stress in Crust Under Mortheastern US."

 STAMBAUCH, P. Columbia Univ QUSTAVE, R. P. Division of Contracts,
 NRC-04-81-180 83/04/29 [p. 18434-284.

- 8305110504 Notification of contract execution, Mod 4 to "Radiological Evaluation of Burjal Grounds" Contractor Radiation Mgt Corp FLEENOR, C Technical Assistance Contracts Branch, NRC-02-80-034 83/04/15 DAVIB, J Defice of Nuclear Material Bafety & Safeguards, Diractor CROW, B, NRC No Detailed Affiliation Given. 19 18415 359
- --8305110509 Mod 4.extending period of performance to 830501.to
 "Radiological Eyaluation of Burial Grounds."
 BOOTH.L F Radiation Management Corp QUSTAVE.R P Division of Contracts NRC-02-80-034 83/04/15 1p 18415 360
- B30510539 Notification of contract execution, Mod 10 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 " Contractor Franklin Inst FLYNN, M Technical Assistance Contracts Branch NRC-03-81-130 B3/04/14 EISENHUT, D 0 Division of Licensing CARRINOTON, M. NRC No Detailed Affiliation Given ip 18415 112
- --8305i10345 Mod 10, replacing project officer & certain members of performance evaluation board & incorporating revised Manual Chapter 3202, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2"
 ABHTON-A.M. Franklin Institute/Franklin Research Center OUSTAVE.R P Division of Contracts NRC-03-81-130 83/04/14
 20p 18415.113
- 8303120142 Notification of contract execution. "Listing of High Technology 8(a) Firms," awarded to Miranda Assoc. Inc BAZIN.J Administrative Contracts Branch NRC-13-B3-446, 83/05/03, KERR,W Ofc of Small & Disadvantaged Bus, Utilization & Civil Rights. COLEMAN, H NRC - No Detailed Affiliation Givan ip. 18433-289
- --B305120150 Contract: "Listing of High Technology B(a) Firms," awarded to Miranda Assoc.Inc BER0DOLL-T.E Miranda Associates, Inc MATTIA,M J Division of Contracts NRC-13-83-446 83/05/03 2ipp, 18435:270.
- 8305120513 Notification of contract execution "Fire Protection Program Review Casework Plants 6," awarded to Rolf Jensen & Assoc. Inc EDGENORTH.P., FLEENOR.C. Technical Assistance Contracts Branch FIN B-8642, NRC-03-83-104 83/05/03 VOLLMER.R H Division of Engineering NOLAN,F. NRC No Detailed Affiliation Given. 1p. 18443:125.
- ~-8305120517 Contract. "Fire Protection Program Review Casework Plants 6: " awarded to Rolf Jensen & Assoc Inc WEB.H.A. Rolf Jensen & Associates, Inc. MORTON, K.V. Division of Contracts. FIN B-8642, NRC-03-83-104 83/05/03 15pp
- 8305120555 Notification of contract execution. "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Schwelb. Donnenfeld. Bray & Silbert TOWNSEND. B. Administrative Contracts Branch FIN 8-8182. NRC-18-83-406 83/05/06. ROTHSCHILD.T. Office of the General Coursel LEVI.R. NRC No Detailed Affiliation Given. 1p. 18441.338.
- --8305120560 Contract: "Advisory Committee for Review of Dfc of Investigation Policy Rights of Licensee Employees Under Investigation: "awarded to Bichwalb, Donnenfeld, Bray & Silbert SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert, RESELLD, J. E Division of Contracts FIN 8-8182, NRC-18-83-406, 83/03/06, 4pp 18441-359.
- 8305130297 Notification of contract execution Mod 1 to "Career Counseling for NRC Participants, Region II." Contractor'R Nawyn HOPPER, A. Division of Contracts NRC-10-82-370. 83/05/09. GOLDMAN, P.J. Hanagament Development & Training Staff VAN BANTEN, L. NRC ND Detailed Affiliation Given. 19, 18460:042.
- --8305130300 Mod 1, increasing funding, to "Career Counseling for NRC Participants, Region II."

 * Nawyn: R. REBELLO.J.E. Division of Contracts. NRC-10-82-370, 83/00/09. ip 18460:043.
- 8305130356 Notification of contract execution: "Grievance Review Examiner," awarded to JE Kaufmann.
 HOYLE: A Administrative Contracts Branch. NRC-10-83-359. 83/05/10.
 BIRD: P.E. Division of Organization and Personnel JACKSON, J NRC-No Detailed Affiliation Given Ip. 18460:044.
- ----B305130361 Contract: *Orievance Review Examiner, " awarded to JE Kaufmann. KAUFMANN,J E Kaufmann,J.E. REBELLO,J E. Administrative Contracts Branch NRC-10-B3-359. B3/05/10. 5pp. 18460:045.

- 8305160304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc MILES, E B Administrative Contracts Branch FIN 8-8855 NRC-33-83-440 83/05/02 BASBETT, H S Office of Resource Management, Director FITTI, C Atomic Safety and Licensing Board Panel 1p 18471 247 24X Fiche 50-247, 83/05/02.8305160304
- --9305i603i2 Contract "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc & Central Data Processing, Inc MATTIA,M J Division of Contracts FIN 8-8855 NRC-33-83-460 83/05/02 2pp 18471 248 24X Fiche 50-247,83/05/02,8305i60304
- --B305160316 Bolicitation, offer & award to "Conversion of Prefiled Testimony for Indian Point Hearings," to Central Data Processing, Inc. COUCH.M J Central Data Processing, Inc. MATTIA.M J Administrative Contracts Branch FIN 8-8855 NRC-33-83-460 B3/04/26 Sepp 18471 230 24% Fiche 30-247, 83/05/02, 8305160304
- 8305160318 Notification of contract execution.Mod 1 to "Div of Engineering Review Support on Sailly Nuclear Plant I "Contractor MT Davisson FIELDS, J. A. Technical Assistance Contracts Branch FIN B-7505 NRC-03-81-092 83/05/06 VOLLMER.R H Division of Engineering LEAR, O. NRC No Detailed Affiliation Given 1p 18472 051 24X Fiche.50-367,83/05/06,8305160318.
- ---8305i60332 Mod 1, terminating contract & deopligating funds, to "Div of Engineering Review Support on Bailly Nuclear Plant I "
 DAVISBON.M T Darisson, M T QUSTAVE, R P Division of Contracts
 FIN B-7505 NRC-03-81-092 83/05/06 2pp 18472-052. 24X
 Fiche 50-367, 83/05/06.8305i60318
- B305170065 Notification of contract execution. "Development of Reg Quide & Regulatory Analyses," awarded to Analysis & Technology. HIGGINS,E Division of Contracts FIN B-8645 NRC-03-83-107 B3/04/01 THOMAB,H L Division of Human Factors Safety BENDER,L NRC - No Detailed Affiliation Given Ip 18495 030
- ---B3C5170070 Forwards two fully executed copies of NRC-03-B3-107, "Development of Reg Ouids & Regulatory Analyses "
 KRAVITS: D. L. Analysis & Technology, Inc. FIN B-8645
 NRC-03-B3-107, 83/04/06, MORTON, K, V. Division of Contracts 1p
 18495-031
- --B305170077 Contract: "Development of Reg Quide & Regulatory Analyses," awarded to Analysis & Technology NOLF,D M Analysis & Technology, Inc FIN B-8645 NRC-03-83-107 83/04/01 134pp 18495 032
- B305170&03 Notification of contract execution. Mod 1 to "Reviewing Hydrogeologic Investigations of NV Test Site-Project C" Contractor Hilliams-Robinette BILVIB.R Technical Assistance Contracts Branch. NRC-02-82-046 B3/05/03, DAVIB.J. Office of Nuclear Material Bafety & Bafeguards. Director. JEFFREY.P NRC No Detailed Affiliation Given 1p 18497:044
- 8305170606 Notification of contract execution, Mod 5 to "GA for Geotechnical GC." Contractor, US Army Corps of Engineers FLEENGR.C. Technical Assistance Contracts Branch NRC-02-82-035 83/04/28 DAVIS, J. Office of Nuclear Material Safety & Bafsguards, Director. PENNIFILL, R NRC No Detailed Affiliation Given. ip. 18497-024
- --8305170407 Mod 5, modifying reporting requirement, revising schedule for submission of task & updating billing instructions, to "dA for Geotechnical GC"

 MARCUSON, W.F. Army, Dept. of, Corps of Engineers QUSTAVE, R.P. Technical Assistance Contracts Branch. NRG-02-82-035, 83/04/28, 2pp. 18497, 025
- B305170648 Notification of contract execution, Mod i to "Installation, Deinstallation & Maint Support Sycs for High Frequency. Very High Frequency & Ultra High Frequency Radio Equipment Owned & Operated by NRC." Contractor.Matrocom. Inc MCLEAREN, T. Division of Contracts NRC-10-83-331 83/05/19 CORLEY, J. Division of Facilities & Operations COHEN, 8 NRC No Datailed Affiliation Given 1p. 18496.347

- --8305170664 Mod 1. raising contract ceiling & adding project officer, to "Installation, Deinstallation & Maint of Support Svcs for High Frequency, Very High Frequency & Ultra High Frequency Radio Equipment Owned & Operated by NRC "

 # Metrocom, Inc SMITH, P A Division of Contracts NRC-10-83-331 83/05/13 1p 18496 348
- 8305170698 Notification of contract execution, Mod 5 to "Presentation of GE BWR/6 Design & Operation Courses " Contractor GE MOLLETY.8 Technical Assistance Contracts Branch FIN B-1224 NRC-03-80-2892 83/05/13 ELAMA.J Program Support Branch HAVENS.D NRC No Detailed Affiliation Oiven 1p 18496 318
- --8305170493 Mod 5, reducing rates for three courses & canceling one course, to "Presentation of GE BMR/6 Design & Operation Courses "
 PIERCE, R L General Electric Co GUSTAVE, R P Division of Contracts FIN B-1224 NRC-05-80-282 83/05/13 2pp 18496 319
- 8305180038 Notification of contract execution, Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ HOYLE, A Administrative Contracts Branch FIN B-8644 NRC-03-83-106 83/05/10 DENTON, H Office of Nuclear Reactor Regulation, Director CODELL, R NRC No Datalled Affiliation Given 1p 18499-289 24% Fiche 50-247,83/05/10.8305180038
- --8305180047 Mod i.extending period of performance to 830630 & changing payment & general provisions, to "Consulting Svc on Indian Point Probabilistic Safety Study "
 LEHIB.J P Columbia Univ REBELLO.J E Division of Contracts NRC-03-83-106 83/05/10 1p 18499 290 24X Fiche 50-247,83/05/10,8305180038
- B305180412 Notification of contract execution Mod 3 to "On Call Maint for NRC Computer Peripheral Equipment" Contractor Computer Bys Bupport Corp PERLMAN, J Division of Contracts FIN B-8174 NRC-33-83-451 B3/05/12 BASBETT: H B Division of Data Automation & Management Information JOHNSON, C NRC No Detailed Affiliation Given 19 185003 359
- --83D5180421 Mod 3, increasing funds, to "On Call Maint for NRC Computer Peripheral Equipment " * Computer Systems Support Corp SMITH, P A Division of Contracts FIN D-8174 NRC-33-83-451 83/05/12 ip 18503-360
- B305180557 Notification of contract execution "Purchase & Installation of Multichannel Analyzer Sys," awarded to Nuclear Data. Inc MILES,E B Administrative Contracts Branch FIN B-8855 NRC-31-83-662 B3/05/13 ENDELKEN,R Region 5. Office of Director COLLING. J. T. WISE,R Region 4. Office of Director ip.
- ---B305180560 Contract "Purchase & Installation of Multichannel Analyzer Sys," awarded to Nuclear Data. Inc * Nuclear Data. Inc MATTIA.M J Division of Contracts FIN B-B855 NRC-31-B3-662 B3/05/13 3pp 1B505-122
- --8305180362 Solicitation.offer & award to "Purchase & Installation of Multichannel Analyzer Sys." to Nuclear Data, Inc RISSO, R P Nuclear Data, Inc MATTIA, J Division of Contracts. FIN B-8855 NRC-31-83-662 B3/03/01 29pp 18505 125
- B305180785 Notification of contract execution Mod 4 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals." Contractor Trial Lawyers for Public Justice HOPPER.A Division of Contracts FIN 8-8179 NRC-18-82-418 83/05/13 RDTHSCHILD, T Office of the General Counsel ip 18-805 330
- --B305180792 Mod 4, extending period of performance to 831231, to "As Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " ROISMAN,A Z Frial Lawyers for Public Justice RESELLO, J E. Division of Contracts FIN B-B179 NRC-18-82-418 83/05/13 1p 18505 331
- B305190506 Notification of contract execution, Mod 8 to "Review & Evaluation of Geologic & Baismic Features of Nuclear Power Bites "Contractor USG8 FIELDS, J A Technical Assistance Contracts Brench. NRC-03-80-113. B3/04/12 VOLLMER, R H Division of Engineering JACKSDN, R NRC-No Datailed Affiliation Given 1p 18523 154
- - * Interior, Dept of, Geological Survey. GUSTAVE, R P Division of Contracts NRC-03-80-113, 83/04/12 ip 18523; 155

- 8305200002 Notification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations Contractor Barr Engineering Co FIELD, J A Administrative Contracts Branch NRC-02-80-033-03 83/05/13 DAVIS, J Office of Nuclear Material Bafety & Safeguards, Director GARCIA, P NRC No Detailed Affiliation Given in 18328 338
- --8305200004 Hod 4, extending period of performance to 830930, to "Licensing Assistance/Deotechnical & Hydrological Evaluations"

 Barr Engineering Co GUSTAVE, R P Division of Contracts NRC-02-80-033-03 83/05/13 ip 18528-359
- 8303200062 Notification of contract execution Mod 1 to "ABC Stenoscript Shorthand " Contractor Montgomery County MD Public Schools DDRSEY:M Administrative Contracts Branch MRC-10-79-385. 83/03/11 DDRIE:H M Office of Administration OALLAGRER.J M NRC - No Detailed Affiliation Given ip 18540-126
- --8305200071 Mod 1,deobligating remaining balance, to "ABC Stenoscript Bhorthand" PASCOE.S Montgomery County, MD SMITH,P A Division of Contracts NRC-10-79-385 83/05/11 1p 18540 127
- 830320013! Notification of contract execution, Nod 4 to "Microfiche Verification & Retrofit " Contractor SBA Subcontractor Labat-Anderson. Inc OILDENHORM. A J. Administrative Contracts Branch. NRC-10-82-425 83/04/29 BESAM.W J Division of Technical Information & Document Control STGCZLAS.J., SCOTT.S NRC No Detailed Affiliation Given in 18388 340
- --8305200134 Mod 4, extending pariod of performance to 830405, to "Microfiche Verification & Retrofit" BERODOLL, T E Small Business Administration LABAT, V Labat-Anderson, Inc. HAGAN, T F Division of Contracts NRC-10-82-425 83/04/29 2pp 18528 341
- 8305200145 Notification of execution: Mod 2 to "Const & Calibr of Er-90 Irradiator Multiple Dosimeter Irradiations" Contractor Univ of MI FLYNN: M Technical Assistance Contracts Branch. FIN B-8285 NRC-04-82-024 83/05/13 FOREMAND. M Office of Nuclear Regulatory Research Director DENNIS.N NRC No Detailed Affiliation Given
- --8309200149 Mod 2, extending completion date for 3 months, to "Const & Calibr of 8r-90 Irradiator for Multiple Dosineter Irradiations "
 STEMPLE: P J Michigan, Univ of GUBTAVE. R P Division of Contracts. FIN 8-8265 NRC-04-82-024 E3/05/13 1p. 18540: 246
- 8303230024 Notification of contract execution, Mod 1 to "Interagency Agreement to Provide NRC Power Plant Location Mapping Svcs "Contractor USGS DORBEY, M Administrative Contracts Branch FIN 8-1279 NRC-03-81-868 83/05/09 C088, L I Training & Administration Staff MEINGTEIN, E NRC No Detailed Affiliation Given 1p. 18542 258
- --8305230031 Mod 1.deobligating funds.to "Interagency Agreement to Provide NRC Power Plant Location Mapping Svcs " SOUTHARD.R B Interior, Dept of, Geological Survey SMITH, P. A Division of Contracts FIN 8-1299 NRC-03-81-268 83/05/09 16 18542 259
- 8305230139 Notification of contract execution, Mod 4 to "Transient Prototypical Steam Generator (MB-2) Research Testing Program "Contractor Hestinghouse & EPRI BAISDENL Technical Assistance Contracts Branch FIN 8-8252 NRC-04-82-020. 83/05/13 BATSON, W Office of Nuclear Regulatory Research Director HOPENFELD.J. NRC No Detailed Affiliation Given ip 18543 345
- --B305230169 Ltr contract NRC-04-B2-020, Mod 4. extending period of performance to B30531, to "Transient Prototypicel Steam Generator (NB-2) Research Testing Program "
 MORTON.K.V NRC No Deteiled Affiliation Given. FIN B-8252.
 NRC-04-B2-020 B3/05/13 SPENCE.L W Westinghouse Electric Corp. RYTKONEN.B.B Electric Power Research Institute 2pp. 18543 246
- 8303230245 Notification of contract execution. "Executive Development Program:" awarded to UBDA Oraduate School BAIN-U Administrative Contracts Branch. STEMART.S D. Division of Contracts NRC-10-83-299. 83/05/17 OULDMAN-P J Management Development & Training Staff ALLEN.R A. NRC No Detailed Affiliation Given ip 18543 237.

- --8305230249 Contract "Executive Development Program," awarded to USDA Graduate School A Agriculture Dept of Graduate School MATTIA, M J Division of Contracts NRC-10-83-299 83/05/17. App 18543 238
- 8305230254 Notification of contract execution "Managerial Competencies," awarded to USDA Graduate Bchool STEMART.S.D. BAZIN.J Administrative Contracts Branch NRC-10-83-300 83/05/17 COLDMAN.P.J Management Development & Training Steff ALLEN.R.A. NRC No Detailed Affiliation Given. 1p 18543:251
- --8305230274 Ltr contract "Managerial Competencies," detailing terms of Task 3.providing & developing training programs for selected NRC personnel in eccordance w/statement of work & listed terms & conditions

 MATTIA.M J Division of Contracts NRC-10-83-300 83/04/13, VARNER, S Agriculture, Dept of, Graduate School 6pp. 18343 252
- 8305230281 Notification of contract execution, Mod 6 to "Cenadian Beismic Agreement" Contractor Canadian Commercial Corp. MOLLETT.8 Technical Assistance Contracts Branch. FIN 8-6275. NRC-04-79-180 83/05/13 BAT80N.W. Office of Nuclear Regulatory Research. Director MURPHY NRC No Datailed Affiliation Given. In. 1873/3-292
- --8305230289 Mod 6. providing add1 funding & extending period of performance to 840331 to "Canadian Commercial Corp " SHAWL Cenadian Commercial Corp QUSTAVE.R.P Division of Contracts FIN 8-6275. NRC-04-79-180 83/05/13 2pp.
- 8305230287 Notification of contract execution, Mod 17 to "On-Call Maint for NRC Computer Peripheral Equipment"
 DORSEY: M Administrative Contracts Branch FIN 8-8162,
 NRC-10-79-395, 83/05/02. DORTE: M Office of Administration
 JOHNSON: C NRC No Detailed Affiliation Given Ip 18543:290
- --8305230293 Mod 17, deobligating balance of funds for contract clossout, to "On-Call Haint for NRC Computer Peripheral Equipment "ROOT.L E Computer Systems Support Corp BMITH.P. Division of Contracts. FIN 8-8162 NRC-10-79-393 83/05/02 ip 18943:291
- B303230278 Notification of grant execution, Mod 3 to "Natural Convection Heat Transfer in Spent Breeder Fuel Shipping Configurations " Orantee. Howard Univ MCDERNOTT, D. Technical Assistance Contracts Branch. FIN 9-1013. NRC-9-04-81-007 83/05/11 BATSON, H Office of Nuclear Regulatory Research, Director. MURPHY, J NRC No Detailed Affiliation Given. ip 18574-327
- --8305230311 Mod 3 providing addl funds extending period of performance to 840901 & incorporating renewal proposal, to "Natural Convection Heat Transfer in Spent Breeder Fuel Shipping Configurations."

 HARRIB.C L. Howard Univ MORTON, K V Division of Contracts. FIN G-1015 NRC-Q-04-81-007. 83/05/11 ip. 18576, 328.
- 8305230326 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of PA, MCDERHOTT.D Technical Assistance Contracts Branch FIN 8-8356. NRC-28-83-607. 83705712 MCDBCAR.J. Region i
- --8305230332 Contract. "Radiation Monitoring Program Requirements," awarded to State of PA Cooperative agreement encl * Pennsylvania. Commonwealth of. MORTON.K.V Division of Contracts FIN 8-8356 NRC-28-83-607 B3/05/12. 16pp. 18577-292
- 9305260081 Notification of contract execution, Mod 1 to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Bys." Contractor: WBI Corp OILDENHORN, A J. COLEMAN. R C. Administrative Contracts Branch. NRC-93-83-456 93/04/08 BASSETT. H. Division of Data Automation & Management Information. JOHNSON, C. NRC No Detailed Affiliation Oiven ip. 18649 076
- --B305260087 Mod 1, adjusting language of statement of work, travel ceilings, overhead rate ceiling, adding special provisions & increasing contract amounts to "Comprehensive Current (Real" Time) Geophysical Data Storag & Retrieval Bys " # MSI Corp. MATTIA.M. J Division of Contracts, NRC-33-83-436. B3/04/08. Spp 18649:077
- 8305260206 Notification of contract execution, Nod 1 to "Computer Output Microfilm Production " Contractor Anacomp. Inc.

 MCLEARRN, T Administrative Contracts Branch NRC-10-83-297
 83/05/23, BESAN, N J. Division of Technical Information & Document Control. SKOCZLAS, J. NRC No Datailed Affiliation Given. 1p. 18647:184.

- --8305260222 Mod 1, changing location for pickup & delivery, to "Computer Output Microfilm Production"

 8EYMOURL A Anacomp Inc HAGAN, T Division of Contracts

 NRC-10-83-297 83/05/23 ip 18647 183
- 8305260340 Notification of grant execution. Hod i to "Condensation & Evaporation Rates for Nuclear Aerosols Fission Product Release & Hydrogen Mitigation " Grantee Univ of MD -MCDERMOTT, D Technical Assistance Contracts Branch FIN 0-1024 NRCO-04-81-26 83/05/13 8ATEDN, W Office of Nuclear Regulatory Research, Director LARKINS, J NRC - No Detailed Affiliation Given.

1p. 18629 288.

- --8305260341 Mod 1,increasing funds & extending period of performance to 840930, to "Condensation & Evaporation Rates for Nuclear Aerosols Fission Product Release & Hydrogen Mitigation "BLQUNT.D H Missouri, Univ of, Columbia MORTON.K V Technical Assistance Contracts Branch FIN G-1024 NRCG-04-81-026 83/05/13, 1p. 18627 289,
- B305260377 Notification of contract execution, Mod 3 to "Exam of Agreement State Program " Contractor, Natl Governors Assoc MCLEAREN, T Administrative Contracts Branch NRC-06-B1-293, B3/05/16 KERR, G W Office of State Programs, Director LUBENAU, J NRG No Detailed Affiliation Given 1p 18647, 236
- --8305260380 Mod 3, providing consideration to govt for late delivery of contract deliverables, to "Exam of Agreement State Program"

 SCHEPPACH.R C National Governors' Association SHITH,P A.
 Division of Contracts NRC-06-18-293 83/05/16 ip 18647 257
- 8303270090 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor State of NE, MCDERMOIT, D. Technical Assistance Contracts Branch FIN B-8303, NRC-31-89-670 83/03/16 MEYERS, D M. Region 4, Office of Director NICHOLAS, J D NRC No Detailed Affiliation Given 1p 18661 352
- --8305270093 Mod 1.correcting B&R numbers.to "Radiation Monitoring Program Requirements" "Nebraska, State of. MORTON,K.V Division of Contracts FIN 8-8503 NRC-31-83-670 83/05/16 ip 18661.353.
- 8305270097 Notification of contract execution, Mod 5 to "Source Term Characterization Resulting From Explosively-Caused Excondary Violations of Spent Fuel Shipping Casks " Contractor. BMI WOLLETT, B. Technical Assistance Contracts Branch. FIN 8-6710 NRC-04-80-180 83/04/28 FOREHAND, W Office of Nuclear Regulatory Research, Director LAHS, B. NRC - No Datailed Affiliation Given 18661: 350
- --8305270100 Mod 5, decbligating funds, to "Bource Term Characterization Resulting From Explosively-Caused Secondary Violations of Spent Fuel Bhipping Caeks."

 LUKZ,F J Battelle Memorial Institute, Columbus Laboratories GUBTAVE,R P. Division of Contracts, FIN B-6710, NRC-04-80-180 83/04/28 ip 18661-351.
- 8305270103 Notification of contract execution, Mod 28 to "Downcomer Effects Experimental Program " Contractor Crears, Inc MOLLETT, 8. Technical Assistance Contracts Branch FIN A-4070 NRC-04-75-162, 83/05/06. BATSON, W Office of Nuclear Regulatory Research, Director REYES, J. NRC No Detailed Affiliation Given ip. 18661 342
- --- 8305270105 Mod 28. increasing funding, to "Downcomer Effects Experimental .A. Creare, Inc. MORTON, R. V. Division of Contracts FIN NRC-04-75-162. 83/05/06, 7pp 18661,343. HICKIN, R. A.
- BG0527010B Notification of contract execution; Mod 3 to "Technical Assistance in Nuclear Reactor Core Physics," Contractor, Pickard, Lowe & Carrick Assoc, Inc.
 BILVIB.R.M Technical Assistance Contracts Branch, FIN B-5547
 NRC-04-75-213, B3/05/18, SATBON, M. Office of Nuclear Regulatory Research, Director, 1p. 18661;340
- --B305270110 Mod 3, deobligating funds, to "Technical Assistance in Nuclear Reactor Core Physics."
 PICKARD, J K Pickard, Lowe & Garrick, Inc. GUSTAVE, R P. Division of Contracts FIN B-5547. NRC-04-75-213. 83/05/18 1p. 18661;741.
- FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES FOIA
- B305020006 FOIA request for documents to Harry Diamond Labs located at 2800 Powder Hill Road, Adelphi, MD from 1965 to present. BIMPSON, C Affiliation Unknown. 82/12/15. Office of Administration 2pp. 18355, OOI.

- 8305020007 Partial response to FOIA request for documents re Harry Diamond Labs located at 2800 Powder Mill Road, Adelphi, MD from 1965 to present. Forwards documents responsive to request Documents also available in PDR FELTON. J M Division of Rules and Records 83/01/11 SIMPSDN, C Affiliation Unknown 1p 18354 003
- --8006180578 Requests amend of Mati/Byproduct Licenses 19-17250-01. 19-17250-04,19-17250-05 & BNM-348 Amend replaces C Rowe w/MD Funkhouser as rediation protection officer Resume for MD Funkhouser encl. MD Funkhouser encl. TARAS.D N Army. Dept of. Headquarters Materiel Development & Readiness Command 03752 80/05/22 Licensing Management Branch 5pp 18355 109
- --8009250310 Matl/Byproduct License 19-17250-05 for Dept of Army, Harry Diamond Labs is amended per 800505 ltr Amend 4 adds conditions of use of licensed matl GUINN, P.R. Licensing Management Branch 80/07/15 2pp 18335 090
- --B008250337 Mat1/Byproduct License 19-17250-04 for Dept of Army, Harry Diamond Labs is amended per 800505 ltr Amend 3 authorizes use of licensed mat1 per 780118 & 0811 applications & 800505 GUINN.P R Licensing Management Branch 80/07/09 ip 18354 015
- --8008250463 Matl/Byproduct License 19-17250-01 for Dept of Army, Harry Diamond Lebs is amended per 800805 ltr Amend 3 adds conditions of use of licensed metl.

 GUINN P R Licensing Management Branch 80/07/02. 1p 18356 211
- --8103130267 Requests amend of Mati/Byproduct License 19-17250-01 to delete PA Caldwell, HE Biesieler & JE Stafford, add KO Kerris, CC Caseer & P Barigianis & remove radiation detection instruments BENDIT.W R Army, Dept of 06402 B1/01/22 Detailed Affiliation Olven 3pp 18354 314 NRC - No
- --8104030770 Matl/Buproduct License 19-17230-01 for Dept of Army, Harry Diamond Labs is amended per 810122 ltr Amend 4 changes reading of Conditions 12 & 16 re names of users of licensed mati OUINN,P R Licensing Management Branch 81/02/25 ip. 18356 210
- --B104060899 Requests amend of Matl/Byproduct License 19-17250-05 to add P Serigianis as alternate operator of Co-60 facility & delete obsolete radiation detection instruments TARAS.D. Army. Dept of Headquarters Materiel Development & Readiness Command 26974 81/02/09 Licensing Management Branch 1p 18355 104
- ---8305020010 Amend 1 to Matl/Syproduct License 19-17250-04 for Dept of Army-Harry Diamond Labs, authorizing use of irradiated electronic equipment & threshold detectors. GUINN-P.R. Licensing Management Branch 78/06/07 2pp. 19355 004
- ~-8305020015 Application to renew & amend Matl/Byproduct License 08-02434-01 for Harry Diamond Labs, authorizing listed individuals as Users of Co-60 & Cs-137 sealed sources for calibr of radiation detection instruments CAMPAGNA, J H. Army, Dept of 93820 67/04/03 10pp. 18355 006.
- ---8305020016 Forwards application to renew Matl/Byproduct License 08-024034-01 for Harry Diamond Labs. Approval recommended. HCGRAH, T.L. Army, Dept. of 93820 67/04/10, Atomic Enercommission. ip 18355-016 Atomic Energy
- --8305020019 Application to renew Matl/Byproduct License 08-02534-01.for Harry Diamond Labs, authorizing listed individuals as users of Co-60 & Cs-137 sources for calibr of radiation detection 818CO, H W. Army, Dept of 69029 65/05/17 2pp 18355-017
- ---8305020022 Recommends that encl application for renewal of Matl/ Byproduct License OB-02534-01 for Harry Diamond Labs be approved M/o encl FLYNN R. M. Army, Dept. of. 69029, 65/06/17 Atomic Energy Commission 3pp. 18355 Atomic Energy
- --8305020027 Ack receipt of 620417 notification designating QP Hanson as radiation protection officer & chairman of radioactive matte control board Application to amend license raquested, CUNNINOHAMR A Atomic Energy Commission ORDTL-032 62/06/15 Army, Dept. of ip. 18355-020

- ~-8305020031 Recommends approval of encl request for changes in Diamond Ordnance Fuse Lab radiation protection program Radioisotope facilities adequate DANIELS.R O Army. Dept of MEDPB-PO 62/04/25 Atomic Energy Commission 3pp 16355 021
- --8305020035 Subnits results of leakage tests on Co-60 sealed sources per Condition 15 of Metl/Syproduct License 08-02534-01 Smear test recoved contamination of 0.5 mCi from one sealed source MCCOSKEY.R E Army, Dept of ORDTL-230 62/02/08 Atomic Energy Commission ip 1835-024
- --8305020039 Hati/Byproduct License 08-02534-01 for Diamond Ordnance Fuze Labs, authorizing possession & use of Co-60 tracerlab silver soldered sealed sources

 * Atomic Energy Commission 57/05/01 2pp 18355 025
- --8305020042 Recommends approval of encl application for renewal of Matl/ Byproduct Licenses 08-02534-01 & 08-02534-02 for Diamond Ordnance Fuse Lebs, requesting use & possession of 246 2 mCi Co-60 & 15 mCi Cs-137 DANIELS.R 0 Army, Dept of MEDP8-PD 61/08/01 Atomic Energy Commission 19 18355 027
- --8305020047 Application for renewal of Matl/Byproduct License OB-02534-01, authorizing RE McCoskey as radiation protection officer & possession & use of 245 mCi Co-60 & 15 mCi Ca-137 stored in lead pigs 4 Army, Dept of 36370 61/07/12 6pp 18355 028
- ~-8305020049 Trip rept of 390414 visit to Diamond Ordnance Fuze Lab, Washington, DC re radioisotope program at facility Program is limited & does not require svcs of full-time health physicist

 BASSIN.N Atomic Energy Commission 59/04/14 Atomic Energy Commission 3pp 18355 036
- ---B305020057 Application for renewal of Matl/Byproduct License 08-02534-01.authorizing R RcCoskey as development supervisor & EE Conrad as radiological safety officer as users of Co-60 & Ca-137 sealed sources * Aray
- --B305020063 Forwards Diamond Ordnance Fuze Lab application for matl/ byproduct license, authorizing use of 225 mCi cobalt Expedited handling requested License needed by 370315 Related mati encl BARKER: RF Atomic Energy Commission 57/04/15 BUCHANAN, C R Atomic Energy Commission 3pp 18355 043
- --B305020070 Recommends approval of encl application for matl/byproduct license for Diamond Ordnance Fuze lab, authorizing use of 245 mCi Co-60 k 15 mCi Co-137 in sealed sources CALLIBON, R L Army, Dept of MEDCE-0H 57/04/17 BUCHANAN, C R Atomic Energy Commission 19 18355 046
- --8305020081 Forwards Harry Diamond Labs application to amend Licenses 19-17230-01:19-17230-03:19-17230-04:19-17230-05 & SAM-0348 Amend removes JE Stafford as radiation protection officer & substitutes CA Rowe GUEEN.H @ Army. Dept of 96381 78/09/06 Radioisotopes Licensing Branch (Pre 790501) 3pp 18355 047
- ---B305020095 Application to amend Licenses 19-17250-01,19-17250-03, 19-17250-04,19-17250-05 k SNM-024B, removing JE Stafford as radiation protection officer & substituting CA Rowe GOODMIN.C R Army, Dept of 96381 78/08/11 2pp 18355 048
- --B305020132 Ack receipt of application for renewal of Hat1/Byproduct License 19-17250-04 Current license will not expire until final action taken b Division of Fuel Cycle & Haterial Safety 88400 77/07/15 TARAS.D N Army, Dept of 1p 18355:051
- --8303020158 Submits add1 info to be added to application for mat1/byproduct license re handling & storage of sources HINMAN M.S. Army. Dept of. 37/04/30 BABSIN,N Atomic Energy Commission. Zpp 18355.052.
- --8305020169 Recommends approval of Diamond Ordnance Furs Lab application for Licenses 08-0234-05: 08-0234-04: 08-0234-04: 08-0234-02: authorizing possession of listed radioactive matts KRAUL, C W Army, Dept of. 17455 59/03/24. Atomic Energy Commission ip 18355 054
- --8305020178 Application for mati/byproduct license, authorizing possession & use of 245 mCi Co-60 & 15 mCi Cs-137 in tracerlab & sealed sources.

 e Army, Dept of 57/04/12 5pp 18355.055.

- --8305020187 Amend 3 to Matl/Byproduct License 19-17250-03, authorizing Sr-90 for use as check source GUINN.P Division of Fuel Cycle & Material Bafety 82/08/30 3pp 18355 060
- --B305020191 Amend 2 to Matl/Byproduct License 19-17250-08, revising Condition 16 re possession & use of licensed matls COMBS, F Radioisotopes Licensing Branch (Pre 790501) 78/09/29 ip 18355 043
- ---B305020196 Amend 1 to Matl/Byproduct License 19-17250-03, authorizing storage of Am-241, Sr-90 as check source in Victoreen Models AGB-10KG-BR survey instrument & 716A remote area monitors BABBIN, N Radioisotopes Licensing Branch (Pre 790501) 77/08/29 3pp 18355 064
- --8305020200 Metl/Byproduct License 19-17250-03 for Harry Diamond Labs, authorizing use of Am-241.8r-90 sealed sources for startup of Triga Mark F Reactor & check sources in Victoresn Hodels AOB-10X0-BR & 716A remote area monitors BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 76/11/23. 3pp 18355-067
- --8305020201 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-03 License will not expire until final action taken MICKEY.J. W Division of Fuel Cycle & Meterial Bafety 12134 82/08/05 TARAS.D Army, Dept. of 1p 18355 070.
- --B303020204 Forwards application to renew Hatl/Byproduct License 19-17250-03, authorizing possession & use of Br-90 Victoreen BB-1010A sealed source as calibr source TARAB: D N Army, Dept of DRCBF-P/82-0075 B2/07/27 Rad
- --8305020207 Application for matl/byproduct license, authorizing MJ Borisky as radiation protection officer & JM McGarrity as alternate, for use of Br-90 Victoreen BB-1010A sealed source as calibr source

 > Army, Dept of, 12134 82/06/02 17pp 18355 072.
- ---8305020212 Notifies that Matl/Byproduct License 19-17250-03 expires on 820831 Renswal application must be filed w/updated info re radioisotope program * Licensing Management Branch 12134, 82/05/20 Army, Dept. of ip 18355-089
- --B305020220 Mati/Byproduct License 19-17250-05 for Harry Diamond Labe, authorizing possession & use of Co-60 OUINN,P R Licensing Management Branch 79/05/10 3pp. 18355 092.
- --8305020306 Amend 1 to Matl/Byproduct License 19-17250-05, adding Co-60 sealed source to Items 6,7 & 8,per 780112 application COMBS, C Radioisotopes Licensing Branch (Pre 790501). 78/05/15. ip 18355,095
- --8305020318 Amend 2 to Matl/Byproduct License 19-17250-05, revising Condition 17 re possession & use of licensed matl, per 780Bi1 application, COMBS, F C Radioisotopes Licensing Branch (Pre 790501) 78/09/29, 1p 18355 096
- --8305020323 Hati/Buproduct License 19-17250-05 for Harry Diamond Laba, authorizing possession of 37,276 Ci Co-60 sealed source for use in water pool irradiator for irradiation of matls excluding explosives & flammable matts.

 BASBIN.N Radioisotopes Licensing Branch (Pre 790501) 77/11/14.

 Spp 18355,097
- --8303020505 Mati/Byproduct License 19-17250-05 for Harry Diamond Lebs, authorizing use 37,296 Ci Co-60 sealed sources in water pool irradiator for irradiation of matis exluding explosive & flammable matis.

 BABBIN.N. Radioisotopes Licensing Branch (Pre 790501), 77/11/03. 3pp 18355;100
- --8305020525 Amend 4 to Matl/Byproduct License 19-17250-05 for Harry Diamond Lab. Histing P Barigianis as alternate operator of Co-60 facility & removing listed radiation detection instruments from Item 10.

 BENAIT.W.R Army, Dept. of 06974. 81/01/03. 4pp. 18355:105.
- --8305020539 Application for amend to Licenses 19-17250-04, 19-17250-03, 19-17250-01, 19-17250-05 & BNM-0348, removing JE Stafford as radiation protection officer & replacing CA Rowe GUERN, N O Army, Dept, of 79/08/11. Radioisotopes Licensing Branch (Prs 790501), 2pp. 18355-117.

- --8305020545 Forwards Harry Diamond Labs application for renewal & amend of Matl/Byproduct License 19-17250-03 Amend deletes 16 g Pu/Be neutron source from list of sources available for calibr & inclusion of storage for Am-241 source TARAS,D N Army, Dept of 88400 77/04/30 Division of Fuel Cycle & Matarial Safety ip 18355 120
- ---B305020550 Application for renewal of Matl/Byproduct License 19-17250-03, authorizing JE Stafford as radiation protection officer & JM McGarrity & CA Rowe as alternates & listed users of Am-241 & ST-90 sealed sources LOWREY, A Army, Dept of 88400 77/05/23, 14_{PP} 18355 121
- --8305020554 Application for amend to Matl/Byproduct License O8-02534-10, authorizing TB Grucci, radiation protection officer, as user of Am-241 beryllium neutron source as startup source for Triga reactor # Army, Dept of 71783 76/10/06 3pp 18355 135
- --8305020558 Application for amend of Matl/Byproduct License 08-02534-09. authorizing JE Stafford as radiation protection officer MCOREGOR, T. Army, Dept. of 84025 76/10/04 App 18355 138
- ---E305020560 Forwards Harry Diamond Labs application to rensw & amend Matl/Byproduct Licenses OB-02534-01 & OB-02534-09 Licenses will expire on 720831 Approval requested REHRIO.A W Army, Dept. of 28995 72/06/29 Atomic Energy Commission 2pp 18355 144
- ---8305020564 Application for renewal of Matl/Byproduct License OB-02534-09, authorizing KA Camann as radiation protection officer & JM McGarrity & GA Roue as alternate users of Am-241 & Sr-90 sources for Triga Mark F reactor MOONEY, T Army, Dept of 29041 72/06/12. 17pp 18355 146
- --8305020567 Application for renewal of Mati/Byproduct License OB-02534-09, authorizing TB Grucci as radiation protection officer & HL Qieseler, UM McGarrity, ED McGarry & RB Oswald as users of Am-241, Br-90 & HP-198 CAMPAONA, U, H Army, Dept of 95702 67/06/12 12pp 18355 162
- ---B305020571 Forwards Harry Diamond Labs application for renewal of Matl/Byproduct License 08-02534-09. Approval recommended, M/o ancl.

 MCMEEN.C M. Army. Dept of LOO/PE-ISB 67/07/17 Atomic Energy Commission ip 18355 174
- --B305030008 Recommends that encl application for amend to License OB-02534-10 be approved FLYNN:R M Army, Dept of L00/E2 65/09/29 Atomic Energy Commission. Ip 18355.175.
- --8305030020 Application for renewal of Mati/Byproduct License 08-02934-10, authorizing possession & use of 50 uCi Am-241 & 10 Ci beryllium neutron source BISCO.H W Army, Dept of 74495. 66/01/11 9pp 18355 176.
- --B305030023 Notifies that amend to License OB-02534-09 requesting possession of 5 mCi Au-198 in liquid form canceled Au-198 sealed sources consist of solid metallic fails ORUCGIT.B Army, Dept. of 65/06/25, BASSIN, N Atomic Energy Commission ip, 18355-185
- --B305030027 Recommends that Au-198 in liquid form be deleted from 650416 application to renew License OB-02534-09 Approval also requested FLYNN:R.M. Army, Dept of 65/07/19. Atomic Energy Commission ip 18355,186
- --8305030035 Application for renewal of Matl/Syproduct License OS-02539-09, authorizing TB Grucci as radiation protection officer k possession k use of Sr-90, Au-198 & Po-210 SISCO, H. W. Army, Dept. of 45/06/01 11pp. 18355:187.
- --8305030047 Requests add1 info re use & handling of Au-178 & drawings or specs for sealed sources containing Au-178, in response to 650416 application to amend License OB-02534-09 BABBIN, N. Atomic Energy Commission. 68231. 65/06/21 Army, Dept of. ip. 18355.197
- --B305030055 Application for matl/byproduct license, authorizing TB Grucci as radiation protection officer & listed individuals as users of 5 mci Au-198 auric chloride liquid for use w/Triga dosimetry studies
 BISCO,H,W Army, Dept of 89291, 65/04/16 9pp 18355 200.

- --8305030063 Application to amend Matl/Byproduct License 08-02534-09, substituting TD Grucci in place of GP Hanson as radiation protection officer FLYNN,R M Army, Dept of 65/05/18 Atomic Energy Commission 3pp 1835 209
- --B305030073 Application to amend Mat1/Byproduct License 08-02534-09, substituting TB Grucci in place of GP Hanson as radiation protection officer H/o encl resume FLYNN.R H Army, Dept of 66549 65/03/09 ip 18355 212
- --8305030080 Forwards Harry Diamond Labs application for renewal of Matl/Byproduct License OB-02534-10 Approval recommended SEIDLER, O Army, Dept of 65/01/27 Atomic Energy Commission ip 18355 213
- --8305030087 Forwards drawings for encapsulation of 10 Ci Am/De neutron source for use as startup source in HDL-DDRF Triga Mark F reactor Both vendors should be approved as possible sources for item Related info onc!

 BERMAN, P G Army, Dept of 64/02/01 DASSIN, N Atomic Energy Commission 4pp 18355 214
- --8305030092 Submits add1 info in response to 651101 request re 650819 application for possession & use of Am-241 beryllium neutron source US Nuclear Corp has two sources of 6 48 % 10 Ci designated as Models AM-200 & Am-309 GRUCCI.T B Army, Dept of 65/11/30 BASSIN,N Atomic Energy Commission ip 18398 066
- --8305030098 Requests add1 info re model numbers of Monsanto Research Corp & Numec Instrument & Contols Corp sources, in response to 650819 application for Am-241 beryllium neutron source BASBIN.N Atomic Energy Commission 65/11/01 Army. Dept of 7pp 18355 219
- --8305030i05 Application for renewal of Matl/Byproduct License 08-02534-07, authorizing GP Hanson as radiation protection officer & WL Ofesler & PO Berman as users of Po-210 & Sr-90 SISCO.H W Army, Dept of 53145. 63/08/05 lipp 18355:226
- --8305030125 Recommends that amends & renewals of Matl/Hyproduct Licenses OB-02534-01 & OB-02534-09 for Herry Diamond Labs be approved & disposition of isotopes on License 08-02534-02 be shown as stated on encl certificate W/o encl DANIELS:R,O Army, Dept of, 63/08/01. Atomic Energy Commission ip 18355 207
- --8305030142 Forwards Diamond Ordnance Fuse Labs application for amend to Matl/Byproduct License OB-02334-09 for 2:430 mCi Br-90.
 Approval recommended Radiation protection program adequate for proposed use
 DANIELS, R O Army, Dept of 49063 63/01/22 Atomic Energy Commission ip 18355 238
- --8305030147 Application for amend to Metl/Byproduct License 08-02534-09 for possession & use of Po-210 DANIELS.R.O Army, Dept of 62/08/28 Atomic Energy Commission 2pp 18355.241
- --B305030154 Forwards Diamond Ordnance Fuze Labs application to amend Matl/Byproduct License O8-02534-09 to include one add1 Sr-90 sealed source Approval recommended DANTELB,R. 9 Army, Dept of. 41312 62/02/28 Atomic Energy Commission 5pp 18399 007.
- --8305030163 Application for amend to Matl/Byproduct License 08-02534-07, authorizing OP Hanson to perform tests for leakage & contamination, replacing A Schwebel HCEVOY, R. M. Army, Dapt of, 62/07/11 2pp 18355 244.
- --8305030169 Application for metl/byproduct license, authorizing possession & use of Br-90 sealed sources included in listed monitoring instruments.

 FLYNN,R M. Army. Dept of 68281 61/10/30 5pp 18355-247.
- --8305030174 Forwards Diamond Ordnance Fuze Lab application for mat1/byproduct license for 1820 mCi Sr-90. Approval recommended Radioisotope facilities adequate DANIELS,R. 9. Army, Dept. of. 61/11/01 Atomic Energy Commission 1p. 18355:252
- --8305030179 Forwards Diamond Ordnance Fuze Lab application for mati/byproduct license for possession & use of 20 Ci Po-210
 DANIELS,R @ Army, Dept. of 38700 61/08/17 Atomic Energy Commission. ip 18355.253
- --8305030185 Application for matl/byproduct license, authorizing possession & use of 20 Ci Po-210 sealed neutron sources SISCO, H. W. Army, Dept of 61/08/16 5pp 18355-254,

- --8305030187 Amend 3 to License SNM-348, revising Subitems ? A-9 F & Canditions 10.12 & 18 re dosimetry studies & calibr studies WALKER, W.J. Division of Fuel Cycle & Material Bafety 82/12/21 ip 1835 259
- --8305030195 Amend 2 to License SNM-348, revising Condition 18 repassession & use of licensed mati described in Items 6.7 & 8
 GUINN.P R Division of Fuel Cycle & Material Safety 80/07/09
 1p 18355 260
- --8303030201 Amend I to License BNM-348, revising possession amounts for Pu-239, Np-237, depleted U.U-235 & U-238 encapsulated fission foils & sources COMBS:F C Division of Fuel Cycle & Material Safety 78/10/30 3pp 18355 261
- --8305030207 Renewed License SNM-348 for Harry Diamond Labs, authorizing possession & use of Pu-239, U-235, natural & depleted U & Np-237 encapsulated fission foils LAYFIELD, R. L. Atomic Energy Commission. Directorate of Licensing 72/12/19 2pp 18355 264
- --8303030212 License ENM-348 for Harry Diamond Labs, authorizing possession & use of Pu-237.U-235.natural & depleted U & Np-237 encapsulated fission foils
 LAYFIELD.R L Atomic Energy Commission 68/07/15 3pp
- --8305030213 License SNM-348 for Harry Diamond Labs.authorizing possession & use of Pv & V enriched in U-235 fission foil JOHNSON:L Atomic Energy Commission 65/07/16 3pp 18355 269
- --8305030218 Application to amend License SNM-348, requesting storage of matls prior to transfer, substituting CA Rowe as alternate radiation officer & listing MJ Borisky as radiation protection officer
 MOTHERSBAUGH, L. Army, Dept. of 21639 82/11/22
 Radioisotopes Licensing Branch (Pre 790501) 12pp 18355-272
- ——8305030225 Forwards resume of MD Funkhouser, designated new radiation protection officer at Harry Diamond Labs replacing C Rowe H/o encl TARAS, D N Army, Dept of 16469 80/05/22 Redicisotopes Licensing Branch (Pre 790501) 6pp 18355 284
- --8305030233 Forwards Harry Diamond Labs response to 780706 ltr re License SMM-348 Headquarters concurs w/response Act of receipt of correspondence requested W/o encl TARAS, D N Army, Dept of 70667. 78/07/24 COMBS,F Radioisotopes Licensing Branch (Pre 790501) ip 18355 289
- --8305030239 Submits addl info re security requirements radiation safety facilities & procedures for storage & use of Np-237 foil matl listed on Harry Diamond Labs application for renewal of License SNM-348 GOODWIN.C R Army, Dept of 78/07/19 COMBS,F Radioisotopes Licensing Branch (Fre 790501) 2pp 18335:290
- --8308030247 Requests additinfor resecurity requirements, radiation safety facilities & procedures for use & storage of Np-237 & description of leak testing procedures for fission foils (CUMBs, F. Radioisotopes Licensing Branch (Pre 790301) 78/07/06 TARAS, D.N. Army, Dept of Headquarters Materiel Development & Readiness Command ip 18355 272
- --8305030251 Application for renewal of License SNM-348, reflecting changes in location of lab headquarters, amount of Pu-239 in Pu-8e neutron source & radiation protection officers & users
 TARAB, D N Army, Dept of 77/11/18 Radioisotopes Licensing Branch (Pre 790501) 17pp 18355 293
- --8305030255 Ack receipt of application to renew License SNM-348 License expire until final action taken
 Radioisotopes Licensing Branch (Pre 790501) 08143
 TARAS,D N Army, Dept of ip 18355 310

amend & renewal of License SNM-348, use of 9 76 mg Pu-239,0 24 g U-235,

/04 Atomic Energy

evising expiration date to to license record on 65/01/12 FLYNN,R M

- --8305030268 Amend 3 to License SNM-348, revising Items 7 & 8 & adding Item 14 re licensee compliance w/attached leak test conditions for Pu alpha sources
 DDULOS, N, NUSSBAUMER, D Atomic Energy Commission 64/01/21
 ODLOSTEIN-B L. Army, Dept of 1p 19355 333
- --8305030278 Forwards Amend 2 to License 8NM-348 License does not authorize insertion of matls into nuclear reactor Insertions must be authorized W/o encl JOHN89N.L Atomic Energy Commission 63/09/26 QQLDSTEIN, B L Army, Dept of 1p 18355 334
- --8305030281 Amended License SNM-348 for Harry Diamond Labs, authorizing enriched U-235 as Pu-Be neutron source & 64 6 g as fission foils

 * Atomic Energy Commission 63/09/26 4pp 18355 335
- --8305030286 License BNM-348 for Harry Diamond Labs, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source, 12 micrograms encapsulated in fast neutron detectors & 10 g encapsulated as neutron activation detectors

 JOHNSON L Atomic Energy Commission 62/02/27 ip 18355 339.
- --8305030289 License BNM-348 for Diamond Ordnance Fuze Lab.authorizing use of 16 g Pu encapsulated as Pu-Be neutron source 12 micrograms encapsulated in fast heutron detectors e Atomic Energy Commission 61/11/14 2pp 18355
- --8305030296 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu encapsulated as Pu-Be nautron source & 12 micrograms encapsulated in fast neutron detectors

 NUSBBAUMER, D Atomic Energy Commission 61/05/18 ip
- --B305030301 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu as encapsulated Pu-Be neutron source DELANEY, J C Atomic Energy Commission 60/02/03 2pp 18355 343
- --8305030304 Amend to License SNM-348, correcting docket number error in Item 5 Correct number should be 70-0378 LAYFIELD, R L Atomic Energy Commission 68/07/24 HAAB, C F Army, Dept of 1p 18355-345
- --B305030309 Forwards renewed License BNM-348, reflecting leak test condition for Pu as sealed source W/o encl LAYFIELD, R L Atomic Energy Commission 68/07/15 HAAB, C F Army, Dept of 1p 18355 346
- --8305030312 Application for renewal & amend of License 8NM-348, authorizing possession & use of 54 7 g Pů & 16 g Pů-239, Np-207-depleted U, U-235 & U-235 neutron source in encapsulated callbr sources & fission foils HAAS, C F Army, Dept of 68/06/25 lipp 18355-347.
- --8305030320 Notifies that License SNM-348 expires on 680731.
 Application for renewal of license should be filed within
 30 days Notification should be given at decision not to
 renew by completing encl form W/o encl
 NVSSBAUMER.D A Atomic Energy Commission 68/05/26 8EIDLER.O.
 Army. Dept of 1p 18355, 338
- --8305030323 Forwards renewed License SNM-348, W/o encl JOHNSBN.L Atomic Energy Commission 65/07/16 SEIDLER.Q Army, Dept of 1p 1835:359
- --8305030326 Forwards add1 info re use & etorage of Pu neutron source, per AEC 650604 request Includes description of Pu neutron source & dimensions of tantalum & stainless steel source container.

 SEIDLER(O Army, Dept of 65/07/06 Atomic Energy Commission 2pp 18355 360
- ---8305030332 Requests add1 info re use & storage of Pu neutron source & percennel monitoring program, in response to 650505 application to renew License SMM-348.

 LAYFIELD.R L. Atomic Energy Commission 65/06/04 FLYNN, R M Armg. Dept of 1p 18355 362
- --8305030335 Application for renewal & amend to License SNM-348, authorizing 13.4 g Np-237.54 5 g Pu-239.54 5 g U-235 & 143 g U-238 in form of fission foils for calibr studies FLYNN,R M. Army, Dept of 65/05/05 Atomic Energy Commission. 12pp 18356 OOI

- --8305030339 Math/Byproduct License 19-17250-04 for Dept of Army, Harry Diamond Labs, authorizing use of 250 mC1 irradiated electronic equipment & threshold detectors for experimental development of laser devices

 BABSIN, N Radioisotopes Licensing Branch (Pre 790501) 76/11/24
 20p 18356 013
- --8305030684 Amend 2 to Matl/Byproduct Litense 19-17250-04 making editorial changes to Condition 14 COMBB.F Radioisotopes Litensing Branch (Pre 790501) 78/09/29 ip 18356 016
- --8305040060 Application to amend License 19-17250-01.19-17250-03, 19-17250-04.19-17250-05 & SNM-348, removing JE Stafford as radiation protection officer & substituting CA Rowe OCODMIN, CR, GUEEN, WO Army. Dept of, Headquarters Material Development & Readiness Command 78/08/11 Radioisotopes Licensing Branch (Pre 790501) 3pp 18356 023
- --8305040081 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-04 License will not expire until final action taken QUINN:P R Radioisotopes Licensing Branch (Pre 790501) 92389 78/01/27 TARABID.N Army, Dept of, Headquarters Materiel Development & Readiness Command ip 18356 026
- --8305040089 Application for renewal & amend of Matl/Byproduct License 19-17230-04, removing ED McCarry, FN Balicki & MS Rothstein from list of authorized users of licensed matl & adding CR Heimbach, TL Pruitt & S Share as authorized users TARAS, D N Army, Dept of Headquarters Material Development & Readiness Command 92389, 78/01/16, Redicisotopes Licensing Branch (Pre 790301) 2pp 18356 027
- --8305040093 Application for renswal & amend of Matl/Byproduct License 19-17250-04, authorizing listed individuals to use any byproduct matl w/Atomic Numbers 3-93 inclusive, w/activated electronic & threshold detectors RAMSDEN, J J Army, Dept of 92389 83/01/11 15pp 18356 029
- --8305040103 Forwards Harry Diamond Labs application for renewal of Matl/ Byproduct License 19-17250-04. TARAB,D N Army, Dept of Headquarters Materiel Development & Readiness Command 94530 78/05/12 Radioisotopes Licensing Branch (Pre 790501) 1p 18356-044
- --8305040114 Application for renewal & amend of Matl/Byproduct License 19-17250-04, authorizing listed individuals as users of any byproduct matl w/Atomic Numbers 3-8 & electronic squipment RAMSDEN, J Army, Dept of 94530 78/01/16 16pp. 18356 047
- --8305040120 "Procedures for Maintaining Radiological Bafety," Administrative Circular 6. * Army, Dept. of 23772. 57/10/31, 48pp 18356-063
- ---8305040127 Forwards application to amend Matl/Byproduct License OB-02534-06 for Herry Diamond Labs Amend reflects new location of headquarters & removes Semiconductor & Radiation Effects Physics Branch.

 TARAS: D N Army, Dept. of: Headquarters Materiel Development & Readiness Command DRCBF-P176-0090 76/10/06 Office of Nuclear Meterial Bafety & Bafeguards, Director. 1p. 18336-112
- --8305040158 Application for amend of Matl/Byproduct License 08-02534-08 for Harry Diamond Labs No changes indicated MCGREGOR, T. Army, Dept of 89035 76/10/04, 2pp. 18356 113
- --8305040165 Forwards application for amend to Matl/Byproduct License OB-02534-06 for Harry Diamond Labs.authorizing listed individuals as users of any byproduct matl w/Atomic Numbers 3-83 in activated electronic equipment RATCLIFF, R.H. Army, Dept of DALO-MAB-I 74/04/08. Atomic Energy Commission 1p. 18356.115
- ~-8305040175 Application to amend Matl/Byproduct License 08-02534-06 for Harry Diemond Labs, authorizing listed individuals as users of any byproduct mati wAtomic Numbers 3-83 in activated electronic equipment & threshold detectors EINSEL.D.W. Army: Dept. of 47101 74/04/18 16pp 18356'116
- ~-8305040183 Forwards application for renewal of Natl/Byproduct License O8-02534-06 for Harry Diamond Labs, deleting & adding listed names for users of activated electronic equipment & threshold detectors for experimental lasar development REHRIO.A W Army, Dept of DALO-MAI 73/01/11. Atomic Energy Commission. 1p. 18356-132

- --8305040189 Application for renewal & amend of Matl/Byproduct License OB-02834-06 for Harry Diamond Labs deleting & adding listed names for users of activated electronic equipment & threshold detectors for experimental laser development EINSEL.D W Army, Dept of 73/01/04 14pp 18356 133
- --8305040200 Forwards application to amend Matl/Byproduct License 08-02534-06 for Harry Diamond Labs Amend allows for max possession of 100 Ci of isotopes resulting from activation of crystals (laser matls)

 KELLEY.W D Army, Dept of DALO-MAE-I 71/11/10 Atomic Energy Commission 1p i8356 146
- --8305040211 Application for amend of Matl/Byproduct License 08-02534-06, authorizing listed individuals as users of activated electronic squipment & threshold detectors for experimental development of laser devices CAMPAGNAJ H Army, Dept of 25059 71/09/24 11pp 1835-147
- --8305040217 Application to amend Matl/Byproduct License 08-02534-06, including Connecticut Avenue & Van Ness Street location as place of usage for irradiated electronic equipment HAAB; C.F. Army, Dept of LOG/PE-ISB 69/09/05 Atomic Energy Commission 2pp 18356-158
- --8305040224 Application for renewal of Matl/Byproduct License 08-02534-05 for Harry Diamond Labs, authorizing listed individuals as users of any matl byproduct w/Atomic Numbers 3-8 w/activated electronic equipment CAMPAGNA, J H Army, Dept of 99831 67/11/30 10pp 18336 160
- --8305040234 Application for renewal of Matl/Byproduct License OB-02534-06, authorizing listed individuals as users of any matl product w/Atomic Numbers 3-83 for activated electronic equipment BISCO, H W Army. Dept of 74456 66/01/05 10pp 18356 171.
- --8305040237 Application for amend to Licenses 08-02534-06 & 08-02534-08, listing TB Grucci as radiation protection officer FLYNN,R M Army, Dept of 65/02/24 Atomic Energy Commission ip 1835. i81.
- ---8305040244 Application to amend Licenses 08-02534-06 & 08-02534-08, substituting TB Grucci as radiation protection officer GRUCCI,T B. Army, Dept of LOG/62 65/01/28 2pp 18356 182
- ~-8303040250 Application for renewal of Matl/Byproduct License 08-02334-06, authorizing listed individuals as users of activated electronic equipment subj to post-irradiation easien BIBGO,H W Army, Dept of. 57098 63/12/31 8pp 18356 184
- --B305040256 Recommends approval of encl request for renewal of Matl/ Byproduct License OB-02534-06 for Harry Diamond Labs H/o encl CHEATHAM, J R Army, Dept of 57098 64/01/30 Atomic Energy Commission ip 18356-192
- ~-8305040266 Notifies that no amend to Hatl/Byproduct Licenses 08-02534-01.08-02534-06 & 08-02534-10 needed re designation of OP Hanson as radiation protection officer BASSIN.N A Atomic Energy Commission 62/11/05 Army, Dept of 1p 18356 193
- --8305040272 Application to amend Hatl/Byproduct License 08-02534-05, for Diamond Ordmance Fure Labs, designating OP Hanson as radiation protection officer, replacing RE McCoskey MCEVOY, R. W Army, Dept of 62/10/02 Atomic Energy Commission 2pp 18354 194
- --8305040279 Recommends approval of Matl/Byproduct License 08-02534-06 for Diamond Ordnance Fuze Labs for 250 mCl of all isotopes W/Atomic Numbers 3-83
 DANIELB,R O. Army, Dept. of. 90341 62/02/08 Atomic Energy Commission, 1p. 18356 196
- --8305040287 Application for renewal of Matl/Byproduct License 08-02534-06.authorizing listed persons as users of activated electronic equipment subj to post-irradiation exam HORTON.S.M Army, Dept. of 40841 62/01/11 2pp 18356 197
- ---6305040290 Application for metl/byproduct license for Diamond Ordnance Fuze Labs.requesting listed individuals as users of all Isotopes 3-83 activated electronic equipment subj to post-irradiation exam MCCDSKEY, R E Army, Dept. of 23772 60/01/26 7pp 18356.199

- --8305040294 Recommends approval of encl application for Matl/Byproduct License 08-02534-04 for Diamond Ordnance Fuze Labs, authorizing use of 250 mCi of all Isotopes 3-83 KRAULC.W Army, Dept of 23772 60/01/20 Atomic Energy Commission 1p 18356 206
- --B305040297 Amend 5 to Matl/Byproduct License 19-17250-01, authorizing use of listed matl at Harry Diamond Labs
 HICKEY.J W Office of Nuclear Material Safety & Safeguards.Director B3/01/11 3pp 18356 207
- --8305040310 Amend 2 to Matl/Byproduct License 19-17250-01.adding editorial change to Condition 16
 CQH89,F Radioisotopes Licensing Branch (Pre 790501) 78/09/29 ip 18356 212
- --8309040366 Amend 1 to Matl/Byproduct License 08-02534-01, authorizing use of tracer lab sealed sources & Nuclear Chicago Model 850233 containing Co-60 & Cs-137 at Harry Diamond Labs # Radiolisotopes Licensing Branch (Pre 790301). B3/01/11 Spp 18345 213
- --B305040376 Met1/Bygroduct License 19-17250-01 for Harry Diamond Labs, authorizing use of tracerlab sealed sources & Nuclear Chicago Model 850213 sealed sources, containing Co-60 & Cs-137
 BASSIN.N Radioisotopes Licensing Branch (Pre 770501), 76/11/23, 4pp 18356 216
- --8305040380 Notifies that Matl/Byproduct License 19-17250-01 expires on 820831 W/o encl renewal forms

 * Licensing Management Branch 82/05/20 Agriculture, Dept of. ip 18354 219
- --B305040387 Forwards Harry Diamond Labs response to 821007 request for add1 info in support of application to renew Mat1/Byproduct License 19-17250-01.

 TARASJO N. Agriculture: Dept of DRCSF-P/82-0035 82/11/04. PATTERSONJ M. Radioisotopes Licensing Branch (Pre 790501) 1p 18356 220
- --8305040392 Forwards instrument calibr procedures, radiation survey program & personnel exposura repts HILLIAMSIR Agriculture, Dept of 82/10/28 NRC No Detailed Affiliation Given 68pp 18356 221
- --8305040403 Requests add1 info re instrument calibr procedure & radiation survey program for renewal of License 19-17250-01 for Harry Diamond Labs Response should be provided per Reg Guide 10 7
 PATTERSON, J W Assistant Director for Material Bafety & Licensing 12247 82/09/30 Army, Dept of 2pp 18356 292.
- --8305040408 Ack receipt of application for renewal of Mati/Byproduct License 19-17250-01 HICKEY.J W Assistant Director for Material Safety & Licensing 12247 82/08/19 Army, Dept of 2pp 18336 294
- --8305040414 Forwards Harry Diamond Labs application for renewal of Matl/ Byproduct License 19-17230-01 H/o enci MOTHERSDAUGH,L Army: Dept of DRCSF-P/82-0035. 82/08/09, Radioisotopes Licensing Branch (Fra 790301) 2pp 18336
- --8305040425 Application for renewal of Matl/Byproduct License 19-17250-01, authorizing KQ Kerris as physicist, CC Casaer & P Sarigianis as Co-60 irradiator operator & MJ Borisky as radiation protection officer BURKE, A R Army, Dept. of 12247 82/03/12 16pp. 18354 297.
- --8305040450 Forwards Harry Diamond Labs application to amend Matl/ Byproduct License 19-17250-01 Amend lists new personnel & deletes other personnel from list of individual vsers, deletes instruments & adds replacement instrumentation TARASID N Army, Dept of, 81/01/27 Radjoisotopes Licensing Branch (Pre 70501). jp 18356 313
- --B305040468 Forwards Harry Diamond Labs application to amend Matl/ Byproduct Licenses 19-17250-01,19-17250-03,19-17250-04, 19-17250-05 & SNM-348 GUEEN,W G Army, Dept of, Headquarters Materiel Development & Readiness Command. 96382 78/09/06 Radioisotopes Licensing Branch (Pre 790501). 1p 18356 324
- --8305040478 Application for amend to Matl/Byproduct Licenses 19-17250-01,19-17250-03,19-17250-05 & SNM-348 Amend requests removal of JE Stafford as radiation protection officer & substitutes CA Rowe GOODHIN.C R Army, Dept of. 76382, 78/08/11 2pp 18356.327.

14 X

- --8305040484 Ack receipt of application to renew Mati/Byproduct License 19-17230-01 License will not expire until final action taken
 COMBS:F C Radioisotopes Licensing Branch (Pre 790501) 88401
 77/07/15 TARAS,D N Army, Dept of, Headquarters Materiel
 Development & Readiness Command 1p 18336 329
- --B305040489 Forwards Harry Diamond Labs application to rensw Metl/ Byproduct License 19-17250-01 Ack of correspondence requested TARAS-D N Army, Dept of Headquarters Materiel Development & Readiness Command DRCSF-P/77-0048 77/06/30 Office of Nuclear Material Safety & Bafeguards, Director ip 18366 330
- --8305040501 Application for renewal of Matl/Byproduct License 17-17230-01, authorizing listed individuals as users of Co-60 & Cs-137 sealed sources for calibr of radiation detection instruments LOWREY.A Army, Dept of 88401 77/05/26 14pp 18356 331,
- ---B305040502 Forwards Harry Diamond Labs application to amend Matl/ Byproduct License OB-02534-01 TARAS,D N Army, Dept of, Headquarters Material Davelopment & Readiness Command DRCSF-P/76-0093 76/10/06 Dffice of Nuclear Material Safety & Safeguards, Director. 2pp 18356 345.
- --8303040510 Application to amend Matl/Byproduct License 08-02534-01, authorizing JE Stafford as radiation protection officer & JH McGarrity & CA Rowe as alternate radiation protection officer, MCOREGOR, T Army, Dept of 84012 76/10/04 12pp 18356-347.
- --8305040519 Application to rensw & amend Matl/Byproduct License O8-02534-01, authorizing listed individuals as users of Co-60 & Cs-137 sealed source, for calibr of radiation detection instruments
 MODNEY.TR Army, Dept of 28995 72/06/13, 14pp 18356-361.
- --8305040523 Notifies that sources will be used for calibr of scintillation detectors & TLDs in response to 670626 ltr calibr procedure discussed ORUCCI.T B Army, Dept of AMXDD-RBB 67/06/29 BABBIN, N Atomic Energy Commission 2pp. 18357 013.
- --8305040554 Recommends application to amend Mat1/Byproduct Licenses 08-02534-01,08-02534-06 & 08-02534-10 for Diamond Ordnance Fure Labs be approved Amend revises name of radiation protection officer
 DANIELS,R 0 Army, Dept. of MEDRE-PO. 62/10/27 Atomic Energy Commission 1p. 18357 015
- --8305040536 Application to amend Matl/Byproduct Licenses 08-02534-01. 08-02534-06 & 08-02534-10, revising name of radiation protection officer. HGEVOY,R W. Army, Dept. of 45482 82/07/14 3pp 18357:016
- --8305040559 Application for renewal & amend to Mati/Byproduct Licenses 08-02534-01 & 08-02534-09, designating OP Hanson as radiation protection officer, replacing RE McCoskey MCEVOY,R.W. Army, Dept of 47842, 62/10/02, 2pp, 18357:020
- --8303040562 Recommends approval of encl application for amend of Matl/ Byproduct Licenses OB-02534-01 & OB-02534-09 for Diamond Ordinance Furs Labs, W/o encl DANIELS:R 9. Army, Dept. of, 45482 62/08/08 Atomic Energy Commission 1p. 18357 022
- ---B305040569 Application to renew Mati/Byproduct License 08-02334-01 for Harry Dimond Labs, authorizing GP Hanson as radiation protection officer & listed individuals as users of Co-60 & Cs-137 sources
 818CO:H W Army, Dept of 53144 63/07/16. 9pp. 18357:023.
- ----8305040573 Requests that Harry Diamond Labs Matl/Byproduct License OB-02534-01 be annotated to list TB Grucci as radiation protection officer Resume encl. FLYNNR M. Army, Dept. of 66554 65/03/09. Atomic Energy Commission, 3pp. 18357-032.
- --8305040578 Application for Amend 4 to Metl/Byproduct License 08-02534-01, substituting TB Grucci as radiation protection officer oRUCCI.T.B. Army, Dept. of. 66554 65/02/19. 2pp 18357, 033
- --B305040579 Ack receipt of application for renewal of Matl/Byproduct License 08-02534-01.License will remain in effect until final action taken AddI info re use & handling of sources requested BASSIN.N. Atomic Energy Commission 67/06/26 Army, Dept. of, 19 18357:035

- --B305040383 Application for renewal & emend to License SNM-348, including TB Grucci as authorized user FLYNN.R M Army, Dapt. of 64/12/30 4pp 18357 036
- --8305040586 Notifies that License SNM-348 expires on 650131 Application for renewal should be submitted 30 days prior to expiration of license Notification of nonrenewal should be given by completing encl form W/o encl NUBSBAUMER, D. A. Atomic Energy Commission 64/12/19 OOLDSTEIN.8 L. Army, Dept of ip 18357 040
- --B305040587 Notifies that no action will be taken on Harry Diamond Labs 640417 application to amend Licensa BNM-348.per 640605 telcon LAYFIELD.R L Atomic Energy Commission 64/06/24 SEIDLER.G Army: Dept of ip 18357 041
- --B305040593 Application for amend to License SNM-348 re periodic leak tests BIEDLER: 0 Army, Dept of 64/05/22 Atomic Energy Commission 2pp. 18357:042
- --B305040597 Application for amend of License ENM-348 to include 5 mGi Pu-239 for Harry Diamond Labs GOLDSTEIN.B L Army, Dept of 63/12/17 Atomic Energy Commission 3pp 18357 044
- --8305040603 Discusses Condition 13 of License 8NM-348, in response to 631011 ltr & 631003 teleon Condition 13 does not authorize actual insertion of math held under license into any reactor Insertions should be authorized NUSSBAUMER, D. A. Atomic Energy Commission 63/10/23 RERMAN, P. G. Army, Dept. of, ip 18357-047
- --8305040674 Requests cancellation ltr requesting allocation of 99 8% U-235 for use as threshold detector for fast neutron dosimetry.

 BERNAN.P.O. Army, Dept. of. 63/10/11 LAYFIELD,R Atomic Energy Commission. 1p. 18357 048
- ---8305040478 Forwards addl info re Harry Diamond Labs application for amend to License SNM-348 per request ODLDSTEIN.B L Army, Dapt of 63/09/13 Atomic Energy Commission. 7pp 18357-049
- --8303040687 Requests add1 info re procedures for use & storage of Np-237.Pu-239 & U-238 fission foils in response to 630531 request for smend to License SNM-348 for Harry Diamond Labs NUSBBAUMER.D. Atomic Energy Commission 63/07/17 DANIELS,R, Army, Dept. of 6pp. 18357:036
- ---8303040696 Requests allocation of 31 g U-235 as metal of 99 8% purity for fission foil fast neutron dosimetry sys for DORF-Triga reactor
 BERMAN, P. O Army, Dept. of 63/08/21 NUSBBAUMER, D. A. Atomic Energy Commission. ip 18357.062.
- --8305050292 Requests add1 info re procedures for use & storage & description of fails, in response to 650531 application to amend License SRM-348 NUSSBAUMER, D. A. Atomic Energy Commission 63/07/15. DANIELS, R. Q. Army, Dept. of. 1p. 18357-063.
- --8305050297 Application for amend to License SNM-348, authorizing possession & use of 13.4 g Np-237,54 5 g Pu-239,54 5 g U-235 & 143 g U-238.
 DANIELBIR 9. Army, Dept. of. 4020. 63/05/31 Atomic Energy Commission. 9pp. 18357.064,
- --8305050301 Notifies that RW McEvoy 521115 ltr made part of records under Docket 70-378. Changes in technical & supervisory personnel having health-safety responsibilities should be provided on continual basis.

 NUBBRAUMER.D. A. Atomic Energy Commission. 63/01/29 DANIELS, R Q. Army, Dept. of 1p 18357 073
- --8305050304 Application for amend to License SNM-348, substituting WL Oleseler for W Hunker as supervisor of instruments incorporating Pu calibr sources DANIELES.R.O. Army, Dept of 63/01/22. Atomic Energy Commission. 3pp, 18357:074
- ---B305050310 Requests nuclear math draft re receipt of 5 g Pu foils contained in nuclear accident dosimetry eys.
 HANSON.9 P. Army, Dept of. 10769 62/11/26 LANE, J Atomic Energy Commission ip. 18357-077
- --8305050312 Amend to License SNM-348, revising Item 8 re authorized use of licensed meth, NUSSSAUMER, D. A. Atomic Energy Commission. 62/08/15, DANIELS, R. GARNY, Dept. of. 1p 18357:078

- --8305050316 Application for smend to License SNM-348 revising Item 8 re calibr of neutron survey meters & designating GP Hanson as authorized matl user DANIELB,R 9 Army, Dept of 62/08/07 Atomic Energy Commission 3pp 18357 079
- ---9305050319 Forwards amended License 8NM-348 W/o encl NUSSBAUMER, D A Atomic Energy Commission 62/02/27 DANIELS,R Q Army, Dept of 1p 18357 082
- --8305050322 Application for renewal of License SNM-348 for possession & use of 26 g Pu,12 mg Pu,1 g Np-237 & 50 g depleted U DANIELB,R O Army, Dept of 62/01/15 Atomic Energy Commission ip 18357 083
- --8305050324 Notifies that License SNM-348 expires on 620131 Renewal application should be filed within 30 days NUSBBAUMER, D. A. Atomic Energy Commission 61/12/01 DANIELS, R. G. Army. Dept. of 1p 18357-085
- --8305050328 Forwards diagram of cannister used in nuclear accident dosimetry system telcon request MCCOBKEY, R E Army. Dept of 61/10/24 NUSSBAUMER, D Atomic Energy Commission 2pp 18357 086
- --8305050330 Forwards application to amend License SNM-348; authorizing possession & use of 50 g depleted U.10 g Pu-239 & 1 g Np-237 DANIELB, R P Army, Dept of 61/10/09 Atomic Energy Commission 3pp 18357.088
- --8305050333 Application to amend License SNM-349, authorizing possession & use of addl 12 micrograms Pu in form of calibr devices KRAUL.C W Army, Dapt of 61/05/01 Atomic Energy Commission 2pp 18357:071
- --8305050335 Forwards License 8NM-348 W/o encl DELANEY, J C Atomic Energy Commission 60/02/03 HIRMAN, W 8 Army, Dept of. 1p 18357 093
- --8305050337 Forwards Diamond Ordnance Fuze Lab 591113 application for SNM license Classification review requested W/o encl FLEURY.E.R Atomic Energy Commission 60/01/28 STRAUSER,W A Atomic Energy Commission ip 18337 094
- --8305050339 Application for amend to License BNM-349, authorizing possession & use of PU KRAUL.C W Army, Dept of 59/12/21 Atomic Energy Commission 3pp 18357: 095
- --B30505030242 Submits detailed results of radiation survey conducted on 771213-15, per License Condition 16 & NRC requirements RAMSDEN, J J Army, Dept of 93972 78/01/12 COMBS.F Radioisotopes Licensing Branch (Pre 790501) 8pp. 18357-100
- --8305050346 Concurs w/enc! Herry Diamond Labs radiation survey conducted on 771213-15 W/o enc!.
 TARAB.D.N. Army. Dept of. 93972 78/03/28 COHBS.F.
 Radioisotopes Licensing Branch (Pre 790501) ip. 18357 108
- --8305050349 Forwards Harry Diamond Labs 770922 response to 770823 inquiry re procedures for obtaining authority to possess, use & transfer radioactive matl, per License 08-02534-12 TARABJD N Army, Dept of, 77/09/26 COMBS.F. Radioisotopes Licensing Branch (Pre 790501) 2pp 18357 109
- --B3050503B: Forwards add1 info re Harry Diamond Labs application for amend of License 08-02534-12. Training procedures for individuals using Co-60 discussed W/o encl.
 RAMSDEN,J J Army, Dept of 90132 77/09/22 CDMB8,F
 Radioisotopes Licensing Branch (Pre 790501) ip. 18357:111
- --B305050355 Requests addl info in response to application for license to use radioactive matl in custom-designed water well irradiator Description of operators training program-mods to facility & procedures to conduct daily checks requested COMBS.F. Radioisotopes Licensing Branch (Pre 790501). 84795 77/08/23. STAFFORD.J Army, Dept of 15pp 18357:114
- --B305050359 Application for amend to Matl/Byproduct License
 OB-02534-12, allowing for establishing Co-60 water-well/freeair irradiation facility.
 GUEEN.W.9 Army. Dept. of 86795 77/04/07. Radioisotopes
 Licensing Branch (Pre 790501) 3pp iB357, 130
- --8305050361 Application for amend to Matl/Byproduct License
 08-02534-12.authorizing possession & use of 267 Ci Co-60 in
 encapsulated heteron sources.
 MCGREGOR.T. Army, Dept. of, 86795 83/01/11, 50pp 18357 133.

- --8305050363 "Co-60 Irradiator Sys for Harry Diamond Labs "
 a Nautron Products, Inc 86795 93/01/11 123pp 18357 184
- B305060073 Addi response to FDIA request for documents re efforts to make facility more earthquake resistant Documents 1 through 7 listed on app encl Documents 8 through 10 withheld (ref FDIA Exemption 5) FELTON,J M Division of Rules and Records B3/03/14 WHARTON,R San Diego State College 3pp 18365 023 24% Fiche 50-206: B3/03/14.B305060073
- --B2031B0052 Discusses facility capability to shut down safely for postulated steam line breaks regardless of whether failure seismically induced Unit to remain shut down until issues resolved DENTON, HR Office of Nuclear Reactor Regulation, Director B2/03/02 REMICK.F J Office of Policy Evaluations 3pp 18365 121 24% Fiche 50-206.83/03/14,8305040073
- --8204190027 Updates status of resolution of steam line break & seismic upgrade issues for facility, identified in 820302 memo DENTON, H R Office of Nuclear Reactor Regulation, Director 82/04/08 REMICK.F J Office of Policy Evaluations App. 18365 126 24% Fiche 50-206.83/03/14,8305060073
- B305060096 FDIA request for current salary scales &/or QO schedules as applied to NRC staff positions MILLIAMS,0 0 NUTECH Engineers, Inc. CGW-83-029 83/02/24 FELTON,J M Division of Rules and Records 1p 18354-277.
- 8305060112 Responds to FDIA request for current salary scales &/or GO schedules as applied to NRC staff positions Forwards App A documents FELTON, J M Division of Rules and Records 83/03/14 WILLIAMS, D G NUTECK Engineers, Inc. 2pp 18354 278
- --8305060117 App 4130-C re current pay administration salary schedules for NRC staff positions * NRC - No Detailed Affiliation Given 82/12/19 12pp 18334 280
- 8305060123 Add1 response to FOIA request for three categories of documents Forwards 29 slides used at 820916 meeting between NRC.0E & BNR licensees. Remaining 33 slides withheld (ref FOIA Exemption 4) FELTON.J M Division of Rules and Records 83/03/15 VAN ALLEN.S Northern Sun Alliance 1p 18399 233
- 8305060135 Addi response to FOIA request for info re Nuclear Metals.
 Inc.including incidents of employee overexposures Forwards
 App A documents Info partially withheld names of overexposed
 individuals (ref FOIA Exemption 6)
 FELTON.U H Division of Rules and Records 83/03/03 MOONEY, B C
 Lowell Sun, Lowell, MA 3pp 18353 165
- --B201070110 Confirms BI1215 telcon agreement re consulting svcs for probable U overexposure incident described in encl Work involves analysis of health significance of uptake & most likely initial update of depleted U Guidance & forms encl MAYNES,R C Region i, Philadelphia, Office of the Director (BI/O3/O1) BI/12/O0 HURBH, J B Hursh, J B 12pp. 18333 190
- --B208060242 Forwards rept on last quarter 1981 skin dose to Nuclear Matals, Inc employee ALLARD, D J Nuclear Metals, Inc 82/03/01. KINNEMAN, J D Division of Engineering & Technical Programs Ip 18359 223
- ---B208060244 Rept on last quarter 1981 skin dose to Nuclear Metals, Inc smployee ALLARD.D J Nuclear Metals, Inc 82/03/01 15pp. 18353 224
- ---B305060141 Submits final rept re 740913 smoke & vapor emission at 5 gallon can of depleted U Analysis of container & surrounding area revealed no spread of contamination Control procedures improved Info partially deleted
 OILMAN.A R Nuclear Netals, Inc 74/10/24 ALLEN.W Region 1, Philadelphia. Office of the Director 5pp 18353 169
- --8305060145 Forwards 771020 complaint re alleged radiation exposure at Nuclear Metals, Inc. in response to 771031 telcon RILEY.E J Labor, Dept of 77/11/03 MCCLINTOCK.R. Office of Inspection & Enforcement, Office of the Director 3pp 18353 174
- --B305060136 Ack receipt of 780630 transmittal of final overexposure rept.per 10CFR20 405(a)
 MCCLINTOCK,R.D. Region i, Philadelphia, Fuel Facility & Materials Safety Branch 78/07/13 OILMAN, A.R. Nuclear Metals, Inc. 2pp

. . .

- --B305060181 Submits rept re amployee whole body overexposure to beta plus gamma radiation.per iOCFR20 405(a)(i) Film badge reevaluation & overexposure of U confirmed 780530 Reassignment of personnel & early alert procedure initiated QLLMAN.A R Nuclear Metals. Inc 78/06/20 Region 1. Philadelphia, Office of the Director 3pp 18353 180
- --8305060189 Forwards JE 91mm 810106 memo re allegations of unsafa conditions & improper firing of amployee by Nuclear Metals, Inc No further action planned unless written complaint filed KINNEMAN, J D Nuclear Metals, Inc 81/01/13 SMITH. 9 H Regisn 1. Philadelphia, Office of the Director 1p 18353 187
- --B305D60193 Discusses allegations by former Nuclear Metals.Inc employee re unsafe conditions & improper firing. Info partially deleted GLENNI J E Region i, Philadelphia, Office of the Director. B1/01/06 KINNEMAN, J D Region i, Philadelphia, Office of the Director 2pp 18383 188
- --8305060200 Forwards "Analysis of Exposure Involving Depleted U at Nuclear Metals.Apr 1981: " consultant rept HURSH.J B Rochester, Univ of. 82/02/18 HAYNEB.R C Region 1. Office of Director. 1p 18353 202
- --8305060207 Discusses allegations made by Nuclear Metals, Inc employee re unsafe conditions involving risk of employee contamination Related info encl. Info partially deleted ROME. C. Region i. Office of Director 82/04/22 KINNEMAN, J. D Region 1. Office of Director ip 18353 241
- --8305060214 Notifies of results of inquiries re allegations made by Nuclear Metals, Inc employee No items of concern represented noncompliance w/NRC regulations or safety hazards KINNEMAN.J D Region 1. Office of Director 82/04/02 FIATARONE, J V Labor, Dept of 1p. 18953 242
- --8305060220 Forwards complaint from Nuclear Metals, Inc amployee reunsafe conditions & health hazards at facility Related info encl Info partially deleted FIATARONE, J V Labor, Dept of 82/02/02 KINNEMAN, J Region i, Office of Director. 20pp 18353 243
- 8305060144 Responds to FOIA Requests 82-455,82-471 & 82-479 re suppression pool dynamic loads, Encls to Documents 3 & 4 & rept encl w/Document 7 withheld (ref FOIA Exemption 4) FELTON-J M Division of Rules and Records 83/03/17 HAFMER,8 Affiliation Unknown 2pp 18364 261.
- --8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vent clearing & steam quenching phenomena Schedule coordinated w/OE & other utils WOFFORD, A W Long Island Lighting Co BNRC-50 75/06/03. STOLZ, J F Light Water Reactors Branch 1 4pp 18364 266
- --8305060155 Requests add1 info re suppression pool temp limit Responses to Questions 1.2.4 % 5 will be provided by OE Question 3 must be answered by util.

 KNIEL.K Light Water Reactors Branch 2 77/08/31. WOFFORD A W. Long Island Lighting Co 2pp 18364.283
- --B305060160 Forwards rept "170 F Pool Temp Limit for Safety Relief Valva Ramshead Condensation Stability," in response to NRC questions Applicable subscale test results & field data survey appropriate during low probability events FULLER, E.D. Oeneral Electric Co., MFN 343-77, 77/09/06 PARR, D.D. Light Water Reactors Branch 3 2pp 18344 285.
- --8305060164 Responds to 770831 ltr ref QE rept "170 F Pool Temp Limit for Bafety Relief Valve Ramshead Condensation Stability," in response to Questions 1.2.4 & 5 Submittal date for response to Question 3 will be provided BURKE, T. J. Long Island Lighting Co 77/09/26 KNIEL, K Light Water Reactors Branch 2 ip. 18364-287
- --8305060171 Forwards proprietary "Buppression Pool Temp Response to Safety/Relief Valve Discharge Through Ramshead in Mark I & II Containments." for review as part of Mark I Task 7 5 & Mark II Task 8 6 Withheld (ref 100FR2 790) SUBON.L J General Electric Co. MFN-138-78, 78/03/31 STOLZ.JF Light Water Reactors Branch 1, 2pp. 18364,300
- ~-8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vent clearing & steam quenching phenomena, Schedule coordinated w/GE & other utils, WOFFORD.A W Long Island Lighting Co SNRC-50 75/06/03. STOLZ.J F Light Water Reactors Branch 1 4pp 18364 286.

- --8303060135 Requests add1 info re suppression pool temp limit Responses to Questions 1,2.4 & 5 will be provided by GE Question 3 must be answered by util

 KNIEL.K Light Water Reactors Branch 2 77/08/31 WOFFORD, A W Long Island Lighting Co 2pp 18364 283
- --8305060160 Forwards rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to NRC questions Applicable subscale test results & field data survey appropriate during low probability events FULLER.E D General Electric Co MFN 343-77 77/09/06 PARR.O D Light Water Reactors Branch 3 2pp 18364 285
- --8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to Guestions 1,2,4 & 5 Submittal date for response to Guestion 3 will be provided BURKE.T J. Long Island Lighting Co 77/09/26 KNIEL,K Light Water Reactors Branch 2 ip 18364 287
- --83050&0171 Forwards proprietary "Suppression Pool Temp Response to Bafsty/Relief Valve Discharge Through Ramshead in Mark I & II Containments," for review as part of Mark I Task 7 5 & Mark II Task 8, 5, Withheld (ref 10GFRZ 790)
 SOBON,L J General Electric Co MFN-138-78 78/03/31
 STOLZ,J F Light Water Reactors Branch 1 2pp 18364-300
- --8305040153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vant clearing & steam quenching phenomena Schedule coordinated w/GE & other utils HOFFORD, A H Long Island Lighting Co. SNRC-50 75/06/03 STOLZ, J. F Light Water Reactors Branch 1 4pp 18364 266
- --8305060135 Requests add1 info re suppression pool temp limit Responses to Questions 1,2,4 & 5 will be provided by QE Question 3 must be answered by util.

 KNIEL, K Light Water Reactors Brench 2, 77/09/31 WOFFORD, A W Long Island Lighting Co 2pp 18364,283
- --B303060160 Forwards rept "170 F Pool Temp Limit for Safaty Relief Valva Ramshead Condensation Stability," in response to NRC questions, Applicable subscale test results & field data survey appropriate during low probability events FULLER.E.D. General Electric Co MFN 343-77 77/09/06 PARR.D.D. Light Water Reactors Branch 3 2pp. 18364 285
- --8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Sefety Relief Valve Remshead Condensation Stability," in response to Guestions 1,2,4 k 5 Submittal date for response to Guestion 3 will be provided.

 BURKET J. Long Island Lighting Co 77/09/26 KNIEL,K Light Water Reactors Branch 2 ip 18364,287
- --8305060171 Forwards proprietary "Suppression Pool Temp Response to Safety/Relief Valve Discharge Through Ramshead in Mark I & II Containments: "for review as part of Mark I Task 7 5 & Mark II Task 8.6. Hithheld (ref 10CFR2 790)
 80BONL J General Electric Co MFN-138-78 78/03/31
 8TGLZ, J. F. Light Water Reactors Branch 1 2pp 18364 300
- 8303090024 Add1 response to FOIA request for documents re 821130 special insp rept. Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6) Documents 3 & 4 withheld (ref FOIA Exemption 7) FELTON.J M. Division of Rules and Records 83/03/21, QARDE, 8 Qovernment Accountability Project, 4pp 18381 158 24X Fiche: 50-206, 83/03/21, 8305090024,
- --B305070038 Discusses telcon w/8 Kohn (Qovt Accountability Project (QAP)) on B21101 re tape cassettes & transcript of interview W/EE Kent on 821015 Transcript unsatisfactory & replete W/errors.

 SHACKLETON.O.C. Region 5, Office of Director 82/11/04 Region 5, Office of Director. 2pp. 18381-164
- --8305070043 Discusses telcon w/unidentified male on 821014 re 8 Kohn 821015 request for tape cassettes of interview w/EE Kent on 821015. Original tapes sent to headquarters for reproduction 8MACKLETON.O C Region 5. Office of Director 82/11/04 Region 5. Office of Director 1p. 18381:166
- --8305090047 Forwards tape cassettes of EE Kent 821015 interview.per request M/o encl.
 SHACKLETON.O.C. Region 5, Office of Director 82/11/02
 FAULKENBERRY, B. Region 5, Office of Director 1p. 18381:147,
- ---B305090055 Requests reproductions of tape caseatts of EE Kent 821015 interview, mailed to 8 Faulkenberry, SHACKLETON, O. C. Region 5, Office of Director, 82/11/03, WARD, WJ Director's Office, Office of Inspection and Enforcement ip 18381.168

- --8305090057 Notifies that seven tape cassettes of EE Kent 821015 interview will be sent for reproduction Tapes will be returned for use at disposition SHACKLETON. O C Region 5. Office of Director 82/11/03 FAULKENBERRY. 8 Region 5. Defice of Director ip 18381 169
- 8305090234 FOIA request for Ohio Citizens for Responsible Energy sixth & seventh set of interrogatories. Sunflower Alliance third set of interrogatories & draft responses to five ASLB questions re hydrogen issue HIATT.S L. Ohio Citizens for Responsible Energy 83/02/14 FELTON.J M. Division of Rules and Records 1p 18381 212
- 8308090241 Responds to FOIA request for Ohio Citizens for Responsible Energy & Sunflower Alliance interrogatories & draft responses to ASLE questions Forwards App A documents Infopartially withheld (ref FOIA Exemption 5) H/o encls FELTON, J M Division of Rules and Records 83/03/21 HIATT, 8 & Ohio Citizens for Responsible Energy 3pp 18381 213
- 8305070285 FOIA request for all documents re decision to terminate const of facility
 DEVIENCE, A Devience & O'Meara, Ltd 83/02/24 Office of Administration ip 18381 225 24X Fiche 50-566,83/02/24, 8305070285
- B305070292 Responds to FDIA request for all documents re decision to terminate const of facility Forwards documents listed in App A FELTON.J M Division of Rules and Records 83/03/21 DEVIENCE.A Deviance & O'Meara, Ltd 2pp 18381 226 24x Fiche 50-566. 83/03/21.8305070272
- B305090306 Add1 response to FOIA request for all records prepared at Region III.ell investigators involved in investigation of T Howard & S Morella allegations & all internal records reproblems discovered at facility Forwards App B documents FELTON.O.M Division of Rules and Records B3/03/22 OARDE, B Oovernment Accountability Project 2pp 18391 216 24X Fiche.50-373:83/03/22,8305090306
- ---B305090313 IE Investigation Repts 50-373/B2-51 & 50-374/B2-15 on B20721-1001 No noncompliance noted Major areas investigated followup on allegations re mat! proceurement & GA deficiencies of HVAC sys installed by Zach Co LANKEBURY.R D. WESTCOTT.H M Region 3, Office of Director 50-374/B2-15 B2/08/16 4pp 183B1 219 24X Fiche 30-373,83/03/22,8305090306
- 8305090523 FDIA request for add1 info re earlier request on Pilgrim dtd 821105 concerning similar documentation for Smabrook facilities BHOTWELL_J A Massachusetts. Commonwealth of, 83/01/05 FELTON.J M Division of Rules and Records 2pp 19369 001 24X Fiche 50-443.83/01/05.8305090523
- 8305090529 Partial response to FOIA request for add1 info re 821105 request pertaining to facility Forwards App A documents Documents also available in PDR App B documents completely withheld (ref FOIA Exemption 5)
 FELTON-J M Division of Rules and Records 83/03/10 SHOTHELL.J A Massachusetts, Commonwealth of, 5pp 18368 003 24X
 Fiche 50-443.83/03/10,8305090529
- --Biii030553 Forwards revised draft discussing paper re safety goals for nuclear power plants; for review NRC Bi0723-24 second workshop in Hargers Ferry comments & new ideas incorporated Comments requested by Bii0i5 REMICK; F. J. Office of Policy Evaluations 81/10/01 PALLADINO, N. J. Commissioners. ip 18368 213
- --8111030655 Revised draft discussion paper re safety goals for nuclear power plants, incorporating 810723-24 second workshop in Harpers Ferry comments & other new ideas * Office of Policy Evaluations 81/10/01 78pp 18368 214
- --BR03150093 Forwards branch review comments of facility emergency plan, performed against NUREO-0654 criteria Addl info & commitments required prior to acceptance PAGANO, F. Q. EP Licensing Branch 82/03/03 MIRAGLIA, F J. Licensing Branch 3 20pp 18368 014 24X Fiche 30-443,83/03/10,8305090529.
- ---8208190078 Requests findings on prompt protective action decisionmaking in States of VT.NH & MA Bignificant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 enci GRIMES, B. K. Division of Emergency Preparedness (Pre 830103), 82/04/27 KRIMN, R. M. Federal Emergency Management Agency 6pp 18368 034 24X Fiche 50-443,83/03/10,8305090529

- --8305070614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station" Station 8TACION ... * HRM Associates, Inc 83/03/10 54pp 18348 155 24X Fichs 50-443, 83/03/10, 8305090529
- --Bii1030653 Forwards revised draft discussing paper re safety goals for nuclear power plants for review NRC Bi0723-24 second workshop in Harpers Ferry comments & new ideas incorporated Comments requested by Bii015 REMICK.F J Office of Policy Evaluations Bi/10/01 PALLADING,N J Commissioners ip 18368 213
- --8111030455 Revised dreft discussion paper re safety goals for nuclear power plants.incorporating 810723-24 second workshop in Harpers Ferry comments & other new ideas * Office of Policy Evaluations 81/10/01 78pp 18368 214
- --B20B190078 Requests findings on prompt protective action decisionmaking in States of VT.NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 mcl oRIMES, B K Division of Emergency Preparedness (Fre 830103) 82/04/27 KRIML, R M Federal Emergency Management Agency App 18368 034 24X Fiche 50-443,83/03/10,8305090529
- --8303090614 "Estimates of Evacuation Time for Beabrook Nuclear Power Station " Station 4 HPM Associates, Inc 83/03/10 56pp 18368 155 24X Fiche 50-443,83/03/10,8305090529
- 8305090537 FOIA request for transcript of Commission meetings discussing 821112 order CLI-82-33 & documents supporting NRC recommendation to Commission relissuance of order. SAMP, R.A. Shaw, Pittman, Fotts & Trombridge 83/02/09 ORIMBLEV, D.H. Division of Rules and Records 29p 18365 : Fichs. 50-358, 83/02/09, 8305090537 18365 134. 24X
- 8305090542 Partial response to FGIA request for transcript of Commission meetings discussing B21i12 order & documents supporting NRC recommandations to Commission re issuance of order Forwards App B documents App A documents in PDR FELTON.J M Division of Rules and Records 83/03/17 SAMP,R A Shaw, Pithman, Potts & Troubridge, 4pp 18365:136 24X Fiche:50-358,83/03/17,8305090542
- ---B305090545 Submits interim rept of Natl Board Notification ASME Code related const at facility, per State of OH, Div of Boiler Insp MCDDNALD.D O Ohio, State of 82/05/12 MILAN.D M Ghio, of 76pp 18365 140 24% Fiche 50-358,83/03/17,8305090542. Ohio, State
- --8305090549 Testimony of JO Keppler before US House of Representatives.
 Committee on Interior & Insular Affairs, Bubcommittee on
 Energy & Environ on 820610 re GA problems & related
 activities at facility Pp 1-12.
 KEPPLER: JO NRC No Detailed Affiliation Given 82/06/10
 12pp 18365 216 24X Fiche 30-338,83/03/17.8305090342
- --8303090561 Submits Natl Board Audit Interim Rept 3 re ASME Code related const at facility,per State of OH Div of Boiler Insp Rept covers activities from 820807-0930 MCDONALD.D J. ALLISON.C W., SULLIVAN.M F. Ohio, State of 82/09/30 MILAN.D M Ohio, State of 18pp 18365-361 24X Fiche 50-358,83/03/17,8305090342
- 8305120005 FOIA request for Sandia Lab electromagnetic gulse study MARSHALL,W H Mapleton Intervenors 83/02/27, FALLADING.N.J. Commissioners Ep 18435-361
- 8305120007 Responds to FGIA request for Sandia Lab electromagnetic pulse study NUREG/CR-3069, "Interaction of Electromagnetic Pulse H/Commerical Power Reactor Sys," sent to S Galder, per 830325 telcon. FELTON.J M Division of Rules and Records 83/03/31. MARSHALL.W H Mapleton Intervenors. Ip 18435-360
- 8305120010 Add1 response to FDIA request for documents re exploration, mining or milling of U in specific areas of NE Forwards documents listed on app Review of remaining documents subject to request in progress.

 FELTON, J M Division of Rules and Records 83/03/21, REID, A B Broken Plow Law Office ip 18443 282
- --8305i200i4 Comments on Proposed Draft LB 550.per 8ii2i0 request. Use of word "mining" may cause some problems NRC does not have jurisdiction over conventional mining of source matt or other mat! MONTGOMERY, J L MONTCOMERY, J.L. Region 4, Dallas, Office of the Director (81/03/01). 82/01/19 DRAIN.D.T. Nebraska, State of 18443 284,

- --8305120019 Discusses 820202 telcon w/J Lange re proposed U in situ project in NE by Wyoming Fuels Co State has licensing & insp jurisdiction over project until 821108 MONTGOMERY. J. Region 4, Office of Director 82/02/08 COLLINS, J.T. Region 4, Office of Director 2pp 18443:286
- --B303120023 Forwards info re 810313 meeting w/NE State officials concerning state & UMTRCA topics State will seek amended agreement after 811108 Agency other than E Simmons div assigned to handle U mills MENTOMERY J Region 4, Dallas, Office of the Director (81/03/01) 81/03/18 YOUNG,F Office of State Programs, Director 4pp.
- ---8305120035 Concurs w/D Drain request for assistance in developing MOU to define respective roles in connection w/U or solution mining in northwest NE June 1982 meeting suggested to begin formulating MOU

 CQLLINS, J T Region 4, Office of Director 82/05/03 DAVIS, J. Q.

 Office of Nuclear Material Safety & Safeguards, Director KERR, Q. H

 Office of State Programs, Director 1p 18443 292 KERR, O. H.
- --8305120041 Requests assistance in arrenging meeting in Lincoln, NE to discuss requirements & develop MOU defining roles re U or solution mining in northwest NE DRAIN.D T Nebrasks. State of 82/04/27 COLLING, T Region 4, Office of Director 2pp 18443 293
- --8305120045 Informs that draft MOU ready for signature panding review & concurrence by OELD Due to changes in location & organization of U Recovery Licensing Branch: MOU should be signed by regional administrator COLLINS, J T Region 4, Office of Director 82/07/28 DAVIS, J 9 Office of Nuclear Material Safety & Bafeguards, Director ip. 18443 275
- --8305120052 Forwards draft MOU re site U mining in NE Draft considers all previous NRC ofc comments & is acceptable to State of NE Comments should be provided by 821015 COLLINS. J T Region 4. Office of Director, 82/10/01. DIRCKS, H J. Office of the Executive Director for Operations. STELLO, V Regional Operations & Generic Requirements KERR, G W Office of State Programs, Director 3pp 18443 296
- --8305120056 Forwards notice of issuance & availability of MOU between NE Dept of Environ Control & NRC for in situ U mining for filing & publication in FR COLLINS, J T Region 4: Office of Director. 82/12/01. COMBS.T.R Correspondence & Records Branch ip 18443 299
- --8305120062 Notice of issuance & availability of MOU between NRC & NE Dept of Environ Control re in situ U mining COLLINS.J T. Region 4. Office of Director 82/11/30 ip. 18443 300
- -- 8305120045 MOU between NRC & NE Dept of Environ Control re in situ U mining COLLING, J T. Region 4, Office of Director DRAIN, D T Nebraska, State of, 82/11/02 2pp. 18443 301.
- 8305120070 Add1 response to FOIA request for IE Insp Rept 50-358/81-13 Portions of documents listed on app withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records. 83/03/21 DEVINE, T., ROBENTHAL Government Accountability Project 3pp 18443 193 24% Fiche 50-358,83/03/21,8305120070
- --8305120074 Forwards Electrical Drafting 8td ED88-126 revised on 791005, Pages 2-43 through 2-48 of Electrical Installation Spec H-2173 & Pages 8 3-27, 8 3-30 & 8 3-65 of FSAR.per request re tray loading criteria, Related info encl COTTA:R E Sargent & Lundy. Inc 81/02/18, BARRETT.P. Region 3, Chicago. Office of the Director 36pp 18443:196 24% Fiche 50-358,83/03/21,8305120070
- 8305120095 Responds to FDIA request by WH Marshall that 8 Galder receive "Interaction of Electromagnetic Fulse W/Commercial Power Reactor Sys " Documents forwarded. FELTON, J M Division of Rules and Records 83/03/31 GADLER, S. Affiliation Unknown 1p. 18435 358.
- 8305120224 Add1 response to FOIA request for license applications.
 license & insp repts re Nuclear Metals, Inc & correspondence
 on employee overexposures to 1980 Forwards documents listed
 in App A Info partially withheld (ref FOIA Exemption 6)
 PELTON, J. M. Division of Rules and Records
 Lowell Sun, Lowell, MA. 9pp 18460-050,

- --Bii2160237 Forwards urinalysis history form for review by Docupational Health Stds Branch Info requested as result of recent insp at Nuclear Metal in Concord.MA where employees urins showed concentration of U in excess of licenses guide KINNEMAN.J D. Materials Radiological Protection Section Bi/12/07 GRELLA.A W Fuel Cycle & Materials Safety Section 4pp 18462 186
- --B112290557 Ack agreement w/proposed enforcement action per B1i016 memosince revised, based on NRC consultant conclusion that evaluation of U uptake could not establish that regulatory limit was exceeded THOMPSON,D Enforcement & Investigation Staff (Pre B20201) EA-B2-009 B1/12/01 KEPPLER,J Region 3. Chicago, Office of the Director (B1/03/01) 2pp 18462 107
- --B305120234 Insp Findings & Licensee Ack dtd 620424 of License SMB-179
 Insp findings no noncompliance nated
 KLEVIN,P B Atomic Energy Commission 62/04/24 2pp 18460 060
- --8305120240 Insp Findings & Licensee Ack dtd 651207 & 08 of License 8MB-179 Insp findings no noncompliance noted # Atomic Energy Commission 65/12/08 1p 18460 062
- --B305120244 Notifies that Nuclear Metals Div of Textron, Inc acquired by Whittaker Corp Approval for transfer of licenses requested THOMPSON, P. Nuclear Metals, Inc 66/08/11 Atomic Energy Commission ip 18460 063
- --8305120251 IE Insp Findings & License Ack dtd 671227 & 28 of License SMB-179. Insp findings no nancompliance noted QRELLA:A W , BROWNE:W Q Atomic Energy Commission 67/12/28 ip 18460 064
- --B305120257 Forwards IE lnsp Findings & Licensee Act 6td 671227 & 28 No noncompliance noted W/o encl KIRMMAN,R. M Atomic Energy Commission CD I AWO, 68/01/03 ABREAU,M.A. Whittaker Corp Ip 18460,065
- --8305120260 IE Insp Findings & Licensee Ack dtd 491202-03 of License SMB-179, Insp findings no noncompliance noted. SMITH.R H. Atomic Energy Commission 69/12/03 ip 18460 046
- --8305120264 Advises that response to 690822 application for License BMB-179 has not been received Info re issuance of license requested LEE,M R Whittaker Corp 69/10/22 NUSSBAUMER.D A Atomic Energy Commission 1p 18460-067
- --8305120268 Submits list of replacement pages to application for License BNM-65, in response to 690923 comments IBBERQW, B. Whittaker Corp. 69/10/22 NUBBBAUMER, D.A. Atomic Energy Commission, 2pp. 18460,068.
- --8305120267 Forwards application for renewal of License 8NM-65.
 Application refiled in loose leaf format incorporating 17
 items from 680806 ltm W/O encl
 KNEPPEL, D B Whittaker Corp 69/02/26 NUSSBAUMER, D A Atomic
 Energy Commission. 1p 18460 070
- ~~8305120274 IE Insp Findings & Licensee Ack dtd 690903 & 04 of Licenses SNM-65 & EMB-179 Insp findings, proper evaluations not made of certain aspects of health physics program per Sections II b 4 through II b 6(b) of License Condition B BROWNE, W 9. Atomic Energy Commission 69/09/18 ip 18460 071
- ~-B305120279 Application for renewal of License SMB-179, authorizing possession & use of U-235 solid metal & alloy for fabrication & experimentation OUMNESON, P. U Whittaker Corp 2696 69/08/22 3pp 18460 072
- --8305120283 Notifies that License 8MB-179 expires on 690930 Renewal application should be filed within 30 days Enci certification of status of source mati activities form should be completed for nonrenewal of license NUSBBAUMER, D. A. Atomic Energy Commission 69/07/25. HANNA, W. J. Whittaker Corp. 1p. 18460:075.
- --8305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & SMB-179, Insp findings, no noncompliance noted, BMITH.R H Atomic Energy Commission, 70/07/16, 1p. 18460-076
- ---B3051202B9 Notifies that no items of noncompliance observed during insp of Licenses BNM-65 & SMB-179 Corrective measures implemented re item of noncompliance during 690903 & 04 insp 8 Isserow replaced DB Kneppel as criticality officer SMITH:R H. Atomic Energy Commission 70/01/06 Atomic Energy Commission. ip 18460-077.

- --B305120294 IE Insp Findings & Licensee Ack and 710513 & 14 of Licensee BNM-65 & SMB-179 Insp findings no noncompliance noted Related info encl SMITH.R H Atomic Energy Commission 71/05/14 22pp 18460 078
- --830512029B Discusses 740913 smoke & paper emission from 5-gallon pail of U Fire dept removed pail Smoke & vapor emission ceased No personnel contamination resulted or radiation released Caused by reaction between metal & oil OILMAN.A R Nuclear Metals. Inc 74/09/13 Region 1. Philadelphia, Office of the Director 3pp 18460 125
- --B305120303 Discusses insp of License SMB-179 radiation control program License classification should be changed from E-3 to B-1 Next insp scheduled during Nov 1974

 JERMAN-P C Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22 Atomic Energy Commission, Directorate of Regulatory Operations. Ip 18460 128
- ---B305120307 Forwards Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance noted MELSON.P R Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22. TUFFIN.W B Nuclear Metals, Inc. 2pp 18460 129
- --8305120310 Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance on noted Major areas inspected radiation control program JERMAN.P C , KNAPP P J Region 1, Philadelphia, Office of the Director. 74/08/20 9pp 18460 131
- --8305120316 Act receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr O'REILLV.J P Region 1. Philodelphia. Office of the Director 74/04/26 TUFFIN.W B Nuclear Metals, Inc. ip 18460 140
- ---8305120352 Suppls 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler in response to 740404 telcon Related info encl TUFFIN.W B Nuclear Metals, Inc 7404/16 O'REILLY,J P Region i, Philadelphia. Office of the Director 5pp 18460 141
- --8305120354 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-26 & 740108-09 & notice of violation W/o insp repts O'REILLY, J P Region is Philadelphia, Office of the Director 74/02/13 TUFFIN W B Nuclear Metals, Inc 2pp 18460 144
- ---8305120359 Notice of violation from insp of 731227-28 & 740108-09 Noncompliances noted failure to conduct adequate evaluations of hand exposures, to survay for airborne U-238 & to analyze environ water & soil samples * Region 1. Philadelphia. Office of the Director 74/02/15 3pp. 18460 148.
- --B30512036† Responds to NRC 740215 ltr re violations noted in Insp Repts 70-0082/73-05 & 40-0672/73-02. Corrective actions finger dosimeters placed on individual employees monthly on rotating basis U handling employees surveyed TUFFIN-W Nuclear Metals, Inc. 74/03/27 O'REILLY, J P Region 1, Philadelphia, Office of the Director 1ipp 18460:153
- ---B305120372 Insp Repts 40-0672/73-02 & 70-0082/73-05 on 721227-28 & 740108-09. Noncompliance noted failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products
 JERMAN.P C , KNAPP.P J Region 1, Philadelphia, Office of the Director, 70-0082/73-05 74/02/01 20pp 18460 164
- ---8305120374 Confirms 740104 & O7 telcons relactions taken to correct violations noted in insp on 731227 & 28 Representatives will visit plant on 740107 to evaluate corrective actions O'REILLY, J.P. Region i. Philadelphia. Office of the Director 74/01/07 TUFFIN.W B. Nuclear Metals, Inc. 3pp 18460 184
- ---8305120381 Responds to IE Bulletin 75-07 re emission of corrosive gases into ventilation sys filtered by HEPA filters No HEPA or other cellulosic filters used in ventilation sys exhausting nitrogen oxides Plastic overwrap used in disposal, OILMAN A R Nuclear Metals, Inc. IEB-75-07 75/12/22 Region 1, Philadelphie, Office of the Director ip 18460-187
- --8305120450 Forwards Insp Rept 40-0672/75-01 on 750527 & 30 No noncompliance noted Major areas inspected selective exam of procedures & representative records interviews w/gersonnel, measurements made by inspector & observations H/a encl NELSON.P.R Region 1, Philadelphia, Office of the Director 75/06/25 TUPFIN.W 8 Nuclear Metals, Inc 2pp 18460 191
- --8305120454 "Nuclear Reactor Fuel Bycs Semiannual Insp II Plan & Field Notes." EPSTEIN, E., MCCLINTOCK, R Office of Inspection & Enforcement, Office of the Director 75/06/23 16pp 18460:195

- --8305120462 IE Insp Rept 40-0672/75-01 on 750529-30. No noncompliance noted Major areas inspected mpt interview re scope of program & operations, external & internal exposures, stack air monitoring, liquid waste & controls LPSTEIN,E, MCLINTOCK,R U Region i, Philadelphia, Office of the Director 75/06/23 4pp 18460 21t
- --8305120466 IE Insp Findings & Licensee Ack dtd 760410 of License SMB-179 Insp findings no noncompliance noted Radiation data sheet encl EPSTRIN.E Region 1, Philadelphia. Office of the Director 76/06/10 9pp 18460 217
- --8305120472 Forwards results of analyses of samples taken at Nuclear Metals, in response to 771118 ltr & 771208 telcon W/o stated guidelines for decontamination of Pscilities MCCLINTOCK,R O Office of Inspection & Enforcement, Office of the Director 77/12/27 CROWTHER,T Labor, Dept of, Occupational Safety & Health Admin 2pp 18460 234
- --B305120474 Forwards samples of lathe turning of depleted U collected on 771116 in machine shop at Nuclear Metals per T Crouther telcon FIATARONE, J V Labor, Dept of Occupational Safety & Health Admin 77/11/18 MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 12pp 18460 237
- --8305120478 Ack receipt of 770510 ltr re violations noted in IE Insp Rept 40-0672/77-01 Records of evaluations denoting true exposure of individual exposed to contemination should be maintained for review during next insp NELSON.P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/05/31 TUFFIN.W B Nuclear Metals, Inc 1p 18460 231
- --83051204BO Responds to NRC 77041B ltr re violations noted in IE Insp Rept 40-0672/77-01 Corrective actions amployee will present badge to guard at exit Badge sealed within cleanable mylar envelope TUFFIN.H B Nuclear Metals, Inc 77/03/10 NELSON,P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 3pp 18460 232
- --8305120483 Discusses IE Insp Rept 40-0672/77~01 on 770329 & forwards notice of violation NELSON,P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/04/18 TUFFIN,W B Nuclear Metals, Inc 2pp 18460 255
- --8305120489 Notice of violation from insp on 770329 Noncompliance noted failure to perform surveys to assure compliance w/ 100FR20 101 is 100FR20 405 re radiation exposure to personnel monitoring (film) badge for Third Quarter 1976 * Region i. Philadelphia, Office of the Director 77/04/18 ip 18460 237
- --8305120493 Ack receipt of 780919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-02 CROCKER.H H Region 1. Philadelphia: Fuel Facility & Materials 8afety Branch 78/09/27 TUFFIN,H B Nuclear Metals, Inc. ip 18460.258
- --8305120494 Responds to NRC 780821 ltr re violations noted in IE Insp Rept 40-0672/78-02 Corrective actions radiation levels along guéside rear waif of Butier Bidg i reduced to 1 m/h Fencing placed between ends of bidgs TUFFIN.H B Nuclear Metals, Inc 78/07/19 Region 1, Philadelphia, Office of the Director ip 18460 259
- --8305120500 Forwards notice of violation from insp on 780727-28 Results of smear samples within license guidelines
 CROCKER,H W Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch 78/08/21 TUFFIN,H B Nuclear Metals, Inc. 3pp
 18460 260
- --8305120503 Notice of violation from insp on 780727-28 Two individuals working in restricted area received exposures to skin of 8.54 & 8.19 rems, respectively, during First Quarter CY78 Braft insp Rept 78-02 encl

B Noncompliance noted rems during , extended

tia: Office of the

- --8305120509 Ack receipt of 780418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-01 Request to amend license must accompany changes to procedures noted in 780448 ltr NELSON.P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 78/05/ii TUFFIN.W B Nuclear Metals, Inc 2pp 19460 275
- --B305i205ii Responds to NRC 780324 itr re violations noted in IE insp on 780228-030i Corrective actions personnel instructed to collect floor sweeping in containers color coded to identify scrap containing licensed metl
 TUFFIN.W B Nuclear Metals, Inc 78/04/18 Region 1, Philadelphia, Office of the Director 2pp 18460 277
- --B305120514 Forwards notice of violation from insp on 780228 & 0301 Methods for detecting radioactive contamination should be reviewed Comments on smoking in restricted area requested NELSON.P R Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 78/03/24 TUFFIN.W B Nuclear Metals. Inc 3pp 18460 279
- --8305120518 Notice of violation from insp on 780228 & 0301 Noncompliance noted failurs to perform surveys re disposal of licensed mati in waste & radiation exposure to extremities

 # Region i, Philadelphia, Office of the Director 78/03/24 ip 1840 282
- --8305120518 IE Insp Rept 40-0672/78-01 on 780228 & 0301 Noncompliance noted failure to evaluate exposure to extremity & to wear ring dosimeter in restricted area Radwaste found in trash dumpster
 GLENN.J., MCCLINTOCK.R Region 1. Philadelphia. Office of the Director 78/03/13 8pp 18460-283
- --8305120519 Forwards proposed ack ltr to Nuclear Metals 801003 response to notice of violation & 800729 notice of proposed inposition of civil penalty ORIER, B H Region I, Philadelphia, Office of the Director, 80/11/19 THOMPSON, D Executive Officer for Operations Support, 2pp 18461 026
- --8305120523 Forwards draft suforcement action ltr & notice of violation & proposed imposition of civil penalty re failure to meet NRC & DOT requirements for shipment of radwaste to Barnwell burial site

 ORIER B H Region i Philadelphia. Office of the Director 80/08/26 THOMPSON,D Executive Officer for Operations Support 5pp 18461 107
- ~-B305120527 Amend 2 to License BMB-179, revising Items 6 & 7 re source mat1 & max possession & Use, per 751003 telegram DRACOMETTE: K S Division of Fuel Cycle & Material Safety 73/10/08 ip 18461: 185.
- ~8305120530 Confirms discussions re-possible overexposure of employee to airborne concentration of depleted U JB Hursh & KM Strable engaged as consultants for NRC Assistance requested KINNEMAN, J D. Region 1, Philadelphia, Office of the Director 81/01/15 TUFFIN.W B Nuclear Metals, Inc. 3pp. 18461 199,
- --8305120540 Discusses IE Insp Rept 40-0672/80-04 on 801120 Proposed transmittal ltr & notice of violation & proposed imposition of civil penalties encl GRIER.B H. Region i, Philadelphia, Office of the Director 81/02/03 THOMPSON.D Office of Inspection & Enforcement, Office of the Director.
- --8305120602 Discusses IE insp on 801120 & forwards notice of violation & proposed imposition of civil penalty STELLO,V Director's Office, Office of Inspection and Enforcement. EA-81-23 B1/02/24 TUFFIN,W B Nuclear Metals, Inc 2pp. 18461 229
- --8305120609 Notice of violation & proposed imposition of civil penalty in amount of \$5,000 Noncompliance noted low specific activity radioactive mat! found leaking from Drum 58 STELLO.V. Director's Office. Office of Inspection and Enforcement, 81/02/26 2pp 18461 231
- --8305120614 Forwards into from State of WA Dept of Social & Health Svcs re transportation discrepancy by licensee Pollowup action requested.

 ORELLA, A W Office of Inspection & Enforcement, Office of the Director 81/03/31 KNAPP,P Region 1, Philadelphia, Office of the Director 2pp 18461, 293.

- --8305120617 Responds to 810226 ltr re violations noted in 1E insp rept Corrective actions staging area completely encl by chain link fencing to clearly delineate region from rest of complex Payment of civil penalty encl TUFFIN.W B Nuclear Metals, Inc EA-81-23 81/03/16 STELLO, V Director's Office, Office of Inspection and Enforcement 21pp 18461 237
- --8305120620 Ack receipt of 810316 ltr & payment of civil penalty proposed in 810226 ltr THOMPSON.D Director's Office (Pre 820201) 81/03/27 TUFFIN.W B Nuclear Metals, Inc. ip 18461 258
- --B305120623 Discusses licensee 810312 fire Approx 10 lb U chips in drum in waste handling area ignited by spontaneous combustion Fire spread to flammable math Wipes in area revealed gross beta contamination.

 CUBTELLD.F.M NRC No Detailed Affiliation Given B1/04/03 KINNEMAN.J.D NRC No Detailed Affiliation Given 2pp. 18461 259
- --8305120627 Discusses 810312 fire caused by auto-ignition of 10 lb of encapsulated U turnings.
 QILMAN.A R. Nuclear Metals, Inc 81/04/10. COSTELLO.F Region 1. Philadelphia, Office of the Director (81/03/01) 3pp 19841 261
- --B305120630 Forwards IE Insp Rept 40-0672/81-01 on 810219 No noncompliance noted Major areas inspected selective exams of procedures & representative records; interviews w/personnel, measurements & observations by inspector W/o enc! KINNEMAN.J.D. Region i, Philadelphia, Office of the Director (B1/03/01). B1/04/14, TUFFIN.M.B. Nuclear Hetals, Inc. 2pp.
- --8905120633 Responds to 810724 application to amend source matl License Addl infd re incineration of U chips & turnings requested HANO,J C. Division of Fuel Cycle & Materiel Safety 19716 81/09/29. OILMAN,A R Nuclear Metals, Inc. 1p 18461 297
- --B305120642 Requests add1 info re B10527 application to amend License BMB-179; proposing dilution factor of 143 be applied to air affluent releases from vantilation stacks per 10CFR20 106(d) WANG; J C Division of Fuel Cycle & Material Safety B1/11/12, OILMANA R Nuclear Metals, Inc 2pp 18461 326
- --8305120656 Forwards Enforcement Quidance Memorandum 81-31 re proposed enforcement action for facility CARLSON, R T Enforcement & Investigation Staff EGM-81-31 81/12/15 STAROSTECKI, R Division of Resident & Project Inspection MARTIN, T Division of Engineering & Technical Inspection SMITH, OH Division of Emergency Preparedness & Operational Support ip. 19462 106
- --8305130006 Ack receipt of application for renewal of License SMB-179 License will not expire until final action taken by NRC HICKEY.J W Division of Fuel Cycle & Material Safety. 20002 81/12/28 GILMANA R Nuclear Metals, Inc. ip 18462 109
- --8305130011 Confirms 820216 conversation w/G Rows re possible quarterly skin overexposure to employee Detailed rept forthcoming Info deleted.

 VVMBACD:F J Nuclear Metals: Inc 82/02/16 KINNEMAN: J D Region 1: Office of Director 1p 18462:110
- --8305130016 Confirms telcon re application for renewal of License 8HB-179 Site visit scheduled for 820304 HICKEY,J H Division of Fuel Cycle & Meterial Safety. 20002 82/02/18 OILMAN,A.R Nuclear Metals, Inc. ip 18462:111.
- --B305130031 Discusses 820126 telcon re small crack in dike during discharge of U neutralized acid waste to lagoon Possibly caused by freeze-thaw cycle. Dike reinforced KINNEMANU D Region 1. Office of Director 82/03/24 Region 1. Office of Director, ip 18462-130.
- --B305130037 Comments on application for renewal of License SMB-179
 Application should provide more specific procedures for
 frisking personnel & clothing at exits from controlled area
 KINNEMAN.J D Region 1, Office of Director. B2/04/01
 MILLER.V L. Office of Nuclear Material Safety &
 Bafeguards, Director. 2pp 18462:131
- --8305130042 Forwards Rev 2 to "NM1 Scrap Packaging Procedures," for disposal of depleted U wastes, in support of Dec 1981 license renewal submittal. VUMBACO, F. J. Nuclear Hetals, Inc. 82/05/10. HICKEY, J. Division of Fuel Cycle & Material Safety ip. 18462:154

- --8305130053 Forwards 820513 request for add1 info re licensed application for renewal application HICKEY, J W Division of Fuel Cycle & Material Safety 82/05/13 KINNEMAN, J D Region 1, Office of Director 2pp 18462 174
- --8305130062 Ack receipt of Billi6 application for renewal of License SMB-179 Addl info re temporary job sites at which source matls will be possessed or used radiation survey program & waste disposal requested W/o stated encl WANO, J C Division of Fuel Cycle & Material Safety 82/05/13 GILMAN, A R Nuclear Metals, Inc 4pp 18462-176
- B305120488 Addl response to FQIA request for six categories of documents Forwards App A documents FELTON.J M Division of Rules and Records B3/03/25 HIATT.S L Ohio Citizens for Responsible Energy 2pp 18457 211 24X Fiche 50-271.83/03/25.8305120488
- --820730Di78 Details of IE Investigation Rept 50-271/82-12 on 820606-10 No noncompliance noted Major areas investigated licensee actions in withholding info re 820424 loss of feedwater transient Proprietary details deleted (ref 10CFR2 790) * Region 1, Office of Director 82/07/20 38pp 18457 217 24X Ficha 50-271,83/03/25.8305120488
- --8305130223 Forwards chronology of Region I actions re 820424 loss of feedwater event, insp investigation documentations, meetings w/state & licensee officials, evaluations of appropriate enforcement action & processing civil penalty HOLODY, D J Region 1. Office of Director 82/10/13 AXELRAD, J Director's Office of Inspection and Enforcement 3pp 18457 262 24X Fiche 50-271.83/03/25,8305120488
- B305i20573 FOIA request for list of all export licenses for Cf-252 since beginning of 1980 including to whom license issued, quantity for which license issued & ultimate consignee KRONZEK.A L FOI Services B3/03/02 FELTON, J M Division of Rules and Records 1p 18440 203
- 8305120576 Responds to FDIA request for list of all export licenses for Cf-252 since beginning of 1980, including to whom license issued, quantity for which license issued & ultimate consignee Forwards requested info FELTON.J M Division of Rules and Records 83/03/24 KRONZEK.A L FOI Services 7pp 18440 204
- 8305160192 FOIA request for all documents dtd 820101 or after detailing or referring to BALP for facility CLARKIR Sen Francisco Examiner B3/02/22 FELTON, J M Division of Rules and Records 1p 18462 190 24% Fiche 50-312,83/02/22,8305160192
- B305160175 Add1 response to FGIA request for all documents dtd B20101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress FELTON, J M Division of Rules and Records B3/03/31 CLARK, R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312,83/03/31,8305160195
- --B21103019: Provides results of reactor operator & senior reactor operator exams administered Jul 1981-Sept 1982, as input to SALP rept All operators passed exams BECKHAILD H Operator Licensing Branch B2/10/19 MINER, B Sacramento Municipal Utility District 15pp 18462 211 24X Fichs 30-312.83/03/31.8305160195
- --8211180501 Forwards NRR input for util SALP.per 821014 memo MINER.S Operating Reactors Branch 4 82/11/16 STERNBERG.D M Region 5. Oppice of Director 7pp 18462 226 24X Fichs 50-312,83/03/31,8305160195
- --8305i60200 Notifies that SALP board schedulad to meet 821123
 Evaluation period remains Jul 1981 Sept 1982
 ENGELKEN,R H Region 5, Office of Director 82/10/04
 DENTON,H R Office of Nuclear Reactor Regulation, Director DAVIS,J G Office of Nuclear Material Safety & Bafaguards, Director MICHELSON,C Director's Office ip 18462 193 24X Fiche 50-312,83/03/31.8309160175
- --8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility QIBBBN. Btandardization & Special Projects Branch 82/10/18 MINER, S. Operating Reactors Branch 4. 2pp. 18462-194, 24X Fiche 50-312,83/03/31,8305160195
- --8305140213 Forwards draft NRR BALP input re licensing activities for Jul 1981 Sept 1982 Comments received by 821115 will be considered in final rapt MINER, 5 Operating Reactors Branch 4 82/11/10 EISENHUT, D G Division of Licensing MATTSON, R Division of Systems Integration (post 811005) VOLLMEN, R Division of Engineering 15pp 18462 196 24X Fiche 50-312,83/03/31.8305160195

- --8305160218 Forwards SALP for Jul 1981 Sept 1982 Overall performance of licensed activities acceptable Prof & responsive attitude in dealings w/NRC & in day-to-day conduct of safety-related activities notewarthy STERNBERG, D M Region 5, Office of Director 82/12/15 ENGELKEN, R M. Region 5, Office of Director 2pp 18462 233 24X Fiche 50-312,83/03/31.8305160195
- --8305160222 Forwards SALP evaluation input, per Sternberg 821014 memo Info consists of safeguards licensing portion MCCORKLE.0 W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG.L Region 5. Office of Director 3pp 18462 235 24X Fiche 50-312.83/03/31.8305160195
- 8303160255 Partial response to FOIA request for all documents old 820101 or after detailing or referring to SALP for facility FELTON, J M Division of Rules and Records 83/03/24 CLARK, R 8at Francisco Examiner 2pp 18472-241 24X Fiche 50-312,83/03/24, 8305160255
- --8211100028 Provides engineering evaluation of 810807 turbine/reactor trip Event review agrees w/licensee Event had little effect on plant safety Automatic functions occurred substantially as expected given concurrent operator actions PELLET. J L Reactor Operations Analysis Branch AEDD/E247 82/10/26 SEYPRIT.K V. Reactor Operations Analysis Branch App 18472 290 24X Fiche 50-312.83/03/24,8305160255
- --B211110445 Discusses licenses reporting of 810807 turbine/reactor trip Proposed LER rule would require more detailed & complete event rept W/o encl ORNSTEIN.H L. Reactor Operations Analysis Branch AEOD/E249 82/11/04 BEYFRIT,K V. Reactor Operations Analysis Branch 3pp 18473 006 24% Fiche: 50-312, 83/03/24, 8305160255
- --82111500AB Discusses performance evaluation of SALP for facility LERs contained adequate info enabling knowledgeable readers to understand events; however, LER 81-39 failed to adequately inform reader of event.

 SEYFRIT.K V Reactor Operations Analysis Branch 82/11/05
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs ip 18473 005 24% Fiche 50-312-83/03/24; 8303160255
- --8305160271 Notification of 830105 meeting w/util in Secramento.CA to discuss BALP for Jul 1981 - Sept 1982 Meeting agenda encl & Region 5, Diffice of Director. 82/12/02 Region 5, Office of Director 3pp 18473 018 24X Fiche 50-312.83/03/24.8305160255
- B3D5180001 Add1 response to FOIA request for seven categories of documents re Brown & Root. Inc & South Texas project Forwards
 App B documents Documents also available in PDR Add1
 documents undergoing review
 FELTON.J M Division of Rules and Records B3/03/09 LINDEMAN.H N
 Lowenstein, Nawman: Reis. Axelrad & Toll 6pp 18497 219 24X
 Fithe 30-000.83/03/09.8305180001
- --7908080036 Forwards matt re allegations of harassment & intimidation per 790324 request THOMPSON.D Executive Officer for Operations Support 79/06/12 FORTUNA:R A Office of Inspector & Auditor Bpp 18499 196 24X Fiche 50-000.83/03/09.8305180001
- --7909180214 Requests views re adequacy of QA/QC program in light of PND-79-179, "Voids in Reactor Containment Wall "
 KENNEDY.R T Commissioners 79/06/25 QOBBICK.L.V Office of the Executive Director for Operations ip 18497-233 24X Fichs 50-000,83/03/09,8305180001
- --8005140294 Responds to 800418 memo re concrete valding Discusses status of problems & repairs
 STELLO,V Diffice of Inspection & Enforcement, Office of the Director 80/04/25 BRADFORD,P A Commissioners 3pp. 18499 139 24X Fiche 30-000,83/03/09:8305180001
- --8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is ewaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/11 AMEARNE, J., GILINSKY, V , KENNEDY, R Commissioners 175pp 18498 304, 24X Fiche. 50-000, 83/03/09, 830-3180001
- --8006090238 Responds to 800421 request that IE interview former site GC inspectors Of 69 persons identified, 23 contacted. STELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/13 BRADFCRD, P. A Commissioners 3pp. 18499 149. 24X Fiche: 50-000, 83/03/09, 8305180001

- ---8006090440 Responds to 791010 memo re enforcement action against Brown & Root Enforcement package complete No enforcement action taken previously since earlier inspection to substantiate allegations

 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/15 BRADFORD,P A Commissioners 2pp 18499 135 24X Fiche 30-000,83/03/09.8305180001
- --B006090443 Forwards WA Post article re harassment of GC personnel Lack of enforcement action questioned. BRADFORD.P.A Commissioners 79/10/10 BTELLD,V. Office of Inspection & Enforcement, Dffice of the Director 2pp. 18497 237 24X Ficha 50-000.83/03/09.8305180001
- --8008120773 Forwards outlines of JF Ahearne & V Stello proposed testimony re facility before House Subcommittee on Oversight & Investigation
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/11 AHEARNE, J F, OILINSKY, V, HENDRIE, J Commissioners 6pp 18497 163 24X Fiche 50-000, 83/03/09, 8305180001
- --8009120352 Advises that Region 4 should assume responsibility for review & verification of corrective actions by licensee as followup action associated w/South Texas problems Headquarters will be responsible for monitoring reviews. THORNBURG, H D Division of Reactor Construction Inspection 80/06/24 SEYRIT, K, V. Region 4, Dallas, Office of the Director 3pp 18479 217 24X Fiche 50-000, 83/03/09, 8305180001
- --8010070450 Forwards draft Commission info paper re plan for resumption of const. Comments or concurrences needed by 800912, W/o encl.
 THORNBURO, H D Division of Reactor Construction Inspection, 80/09/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director STELD, V Office of Inspection & Enforcement, Diffice of the Director 7pp, 18499 222 24X Fiche 50-000,83/03/09.8305180001
- --B010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corprective actions in encl AWS Code.

 STELLO, V Office of Inspection & Enforcement, Office of the Director B0/09/25 AHEARNE, J F. Commissioners 5pp. 18497 228 24X Fiche. 50-000, 83/03/09. 8305180001
- --8010280381 Assigns questions resulting from 800923 Eckhardt hearing AHEARNE.J F Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193. 24X Fiche 50-000,83/03/09.8305180001
- --Bi03250385 Summarizes events re Bi0317 telcon w/L Sinkin concerning allegations at facility Improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged.

 WILBER.H A. Reactor Projects Sections (Regions 2,4 & 5)
 Bi/03/17 SEYFRIT,K V Region 4, Dallas, Office of the Director 2pp. 18499,242 24X Fichs 50-000,83/03/09,8305180001
- --B305180064 Responds to Gossick request to reply to inquiry re adequacy of QA/GC program. Licensee continuing to look for add1 voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners
 STELLO.V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY.R.T. Commissioners. 3pp. 18497 234 24X Fiche 50-000. B3/03/09. B305180001.
- --8305180075 Responds to Commissioner Bradford 791019 inquiry renewspaper article concerning facility insps "Burprise insp" announced IE insp of facility QA program Allegations rebeating of QC inspactor could not be substantiated.

 HUBACEK.N Q Region 4. Dallas. Office of the Director 79/10/26.

 REINMUTH.Q.N Division of Reactor Construction Inspection. 2pp. 18497 239 24X Fiche 50-000,83/03/09,8305180001
- --8305180083 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barbar/Thompson.

 REINNUTH, 9. W Division of Reactor Construction Inspection. 79/11/02. SEIDLE W.C. Region 4. Dellas, Reactor Construction & Engineering Support Branch 2pp 18497-241 24X

 Fiche 50-000,83/03/07,8305180001
- --8305180094 Discusses recommendations for further IE investigation & insp efforts at facilities Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established. Related info encl.

 HAYER,D W Region 3, Chicago, Office of the Director 80/03/11 THORNBURG,H D. Division of Reactor Construction Inspection.

 421pp. 18497 243 24X Fiche. 50-000, 83/03/09, 8305180001.

- --8305180121 Requests info re acops & significance of voids in concrete at site Response requested by 800423

 BRADFORD, P. A. Commissioners 80/04/18 DIRCKS, W.J. Office of the Executive Director for Operations ip 18499 138 24X

 Fishe 50-000, 83/03/09,8305180001
- --8305180148 Advises that staff should notify Commission in advance of proposed actions re facility investigation, per Commissioner Bradford 800418 memo CHILK.8 J Office of the Secretary of the Commission COMPS-80-16 80/04/28 DIRCKS.W J Office of the Executive Director for Operations ip 18499 142 24X Fichs 50-000, 83/03/09,8305180001
- --B305180157 Forwards enforcement package including enforcement notice, draft press ralease, forwarding ltr, notice of violation, proposed imposition of civil penalty & show cause order H/o encis
 STELLO, V Office of Inspection & Enforcement, Office of the Director B0/04/28 AHEARNE, J F, GILINSKY, V, KENNEDY, R T Commissioners ip 18499:143 24X Fiche 50-000, 83/03/09.
- --B305180167 Informs that Commission concensus not in favor of recommendations contained in B00418 memo re facility investigation Modified varsion of Buggestion I further modified by Commissioner Kennedy. Responses enci Wo encis CHILK.B J Office of the Secretary of the Commission COMPS-B0-016 B0/04/28. BRADFORD, P A Commissions in 18499, 144 24X Fiche 50-000, 83/03/09, 8305180001
- --8305180175 Recommends that IE address Ofc of General Counsel Questions 1-7 prior to enforcement action IE will take action on 800501 BRADFORD, P. A Commissioners COMPB-80-19 80/04/30 AHEARNEL J F. Commissioners 1p 18499 145 24X Fiche 50-000.83/03/09,8305180001
- --8305180181 Discusses results of followup inquires by Region IV reterminated Brown & Root, Inc GC civil engineer inspectors BEYFRIT.K V Region 4, Dalles, Office of the Director 80/04/30 DEYCOUNG,R C Office of Inspection & Enforcement, Office of the Director 2pp 18499:146 24X Fiche 50-000,83/03/09.8305180001
- --8305180189 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Guestions 1-7 prior to time of enforcement action CHILK.9 J Office of the Secretary of the Commission COMP8-80-19, 80/05/02 BRADFORD, P A Commissioners ip 18499 148. 24X Fiche.50-000;83/03/09,83051800001
- --B305180202 Informs of new allegations concerning possible intimidation of QC inspectors received while preparing response to 771010 memo. Investigation will be conducted to verify facts.

 Appropriate enforcement action will be taken
 STELLO: V. Office of Inspection & Enforcement Office of the Director 83/03/09 BRADFORD: P.A. Commissioners ip 18499 152 24X Fiche, 50-000, 83/03/09, 8305180001
- ---B305180211 Responds to 791010 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of alleged beating of Brown & Root GC inspector Allegation could not be substantiated.

 STELLO, V Office of Inspection & Enforcement. Office of the Director. B3/03/09 PRADFORD.P.A Commissioners 2pp 18479,133. 24X Fiche 30-000,83/03/09,8305180001
- ---B305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility.

 KAMMERER.C. Office of Congressional Affairs 80/07/09

 AHEARNE.J.F., OILINSKY.V., HENDRIE, J.M. Commissioners 2pp 18499 137 24X Fiche: 50-000, 83/03/09, 83051800001
- --B305180236 Bubmits schedule of Congressional hearings re wests bill H.R.7418, West Valley Bill H.R.6885 & South Texas project Related info enci.
 REHM.T.A Diffice of the Executive Director for Operatjons.
 B0/07/07. BTELLO.V. Office of Inspection & Enforcement, Diffice of the Director DAVIS.J. Office of Nuclear Material Safety & Bafaguards.Director 4pp 18479;139. 24X Fiche 50-000,83/03/09,830480001
- --8305180250 Forwards Chairman Ahearns & V Stello testimony prepared for House Subcommittee on Oversight & Investigation hearing refacility STELLO.V. Office of Inspection & Enforcement. Office of the Director. 80/07/25. AHEARNE.J.F., GILINSKY.V., HENDRIE.J.M. Commissioners 2pp. 18499:169 24X Fichs: 50-000, 83/03/09. 8303180001.

- --9305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5
 AHEARNEL J F Commissioners 80/07/29 App 18499 171 24X
 Fiche 50-000,83/03/09,8305180001
- --B305180257 Statement of V Stello before House Subcommittee on Gyersight & Investigations B00727 hearing Pp i-15
 STELLO, V Office of Inspection & Enforcement, Office of the Director B0/07/27 18pp 18499 177 24X Fiche 50-000.83/03/09, 8305180001
- --G305180276 Forwards draft Commission info paper intended for presentation during wk of 800414 re investigation k proposed enforcement action Comments needed by 800409 THORNBURGH D DIVISION of Reactor Construction Inspection 80/04/03 DENIGN, H R Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director STELLO, V Office of Inspection & Enforcement, Office of the Director 11pp 18499 204 24X Fiche 50-000,83/03/09,8305180001
- --8305180315 Forwards Part 2 of Commission regulations reprectice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl
 BURNIS 9 Office of the Executive Legal Director 80/05/29 CORTEZ.B Communities Organized for Public Service 1p 18497 218 24X Fiche 50-000,83/03/09.8305180001
- --8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickwitigeneral counsel STELLO.Y Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS.W J Office of the Executive Director for Operations 11pp 18497 231 24X Fiche 50-000,83/03/09,8303180001
- --8305180337 Discusses importance of NASLAP decision re-protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants

 THOMPSON.D Enforcement & Investigation Staff (Pre 820201)

 Bi/05/14 GRIER.B H Region i. Philadelphia, Office of the Director (Bi/03/01) D'REILLY,J P Region 2, Atlanta, Office of the Director (Bi/03/01) KEPPLER,J Q Region 3, Chicago, Office of the Director (Bi/03/01) ip 18499 244 24x

 Fiche 30-000,83/03/09,8305180001
- B305180003 FDIA request for documents associated w/investigation of Nuclear Pharmacy. Inc by NRC Ofcs of Inspector & Auditor & IE EMSHWILLER, J. R. Hall Street Journal B2/10/26 NRC No Detailed Affiliation Given 1p 18503
- 8303180005 Add1 response to FOIA request for documents associated w/ investigation of Nuclear Pharmacu, Inc by Ofcs of Inspector & Auditor & IE Forwards documents listed in Apps A & B Info partially withheld (ref FDIA Exemptions 5 & 7) FELTON, J M Division of Rules and Records 83/04/12 EMSHHILLER, J R Wall Street Journal 7pp 18503 052
- --7911150333 Informs that Nuclear Pharmacy, Inc shipped Xe-133 Unit doses not fit for human use List of shipments date distributed, activity & prescription number encl KEPPLER.J.9 Region 3. Chicago. Office of the Director 79/11/02 COMISKEY, J Bt Michael Hosp. Milwaukee, WI 2pp 18503 080
- --B305180010 Documents basis for certain statements contained in IE Insp. Rept 79-01 for Nuclear Pharmacy, Inc Personally identifiable info deleted
 DICEY, B. B. Region 3. Chicago, Office of the Director 79/09/21
 PAPERIELLO, C. → Region 3. Chicago, Office of the Director 3pp. 18503 039
- --8305180013 Discusses BOD129 interview w/JH Shierek re BOD121 meeting w/Nucleer Pharmacy, Inc concerning notice of violation OAMBLE, D.H. Office of Inspector & Auditor BO/01/31 STRICKLER, L.J. Office of Inspector & Auditor 4pp 18503,063
- --8305180021 Forwards Region III 79:102 ltr sent to certain customers (hosps) of Nuclear Pharmacy, Inc (NPI) notifying that NPI sold Xe-133 prepared from chemical-grade bulk matl rather than from pharm-grade bulk matl STRICKLER, L J Office of Inspector & Auditor 79/11/04 Office of Inspector & Auditor. 19 18503 079.

- --8305180031 Discusses 791108 meeting w/DOJ re potential for developing prosecutable case against Nuclear Pharmacy. Inc DOJ has no interest in proceeding w/criminal action if violation not of sufficient significance to warrant civil penalty STRICKLER. J Office of Inspector & Auditor 79/11/13 Office of Inspector & Auditor 2pp 18503 082
- ---B305180037 Discusses 771108 briefing w/DDJ re deficiencies in case against Nuclear Pharmacy, Inc concerning purchase of Xe-133 from Union Carbide STRICKLER, L. J. Office of Inspector & Auditor 79/11/14 Office of Inspector & Auditor 79/11/14 Office
- --8305180044 Urges NRC not to mitigate fine for Nuclear Pharmacy, Inc.re
 Unauthorized acquisition & breakdown of packaging & delivery
 of Xe-133 unfit for human use Other vendor violations cited
 Personally identifiable info deleted
 # Affiliation Unknown 79/12/01 SNIEZEK, J H Division of Fuel
 Facility & Materials Safety 3pp 19503 085
- --8305180052 Documents recollections of statements made during 790323 mgt enforcement conference re procurement & distribution of Union Carbon Xe-133 contrary to FDA & NRC requirements DICEY, B B Region 3. Chicago, Office of the Director 79/12/05 STRICKLER, J Office of Inspector & Auditor 2pp 18503 089
- --B3051B0056 Submits amended response to 750410 questions re license application Hanufacturers package insert for all radiopharms dispensed by use will be forwarded to each user. SANCHEZ, R.L. NuPharm, Inc. 75/04/23 BOYER, J.E. Division of Fuel Cycle & Material Safety 3pp 18503 091
- --8305180043 Application to amend License 24-14519-01.reflecting corporate name change to Nuclear Phermacy, Inc & change of address REAVIS.J H NuPharm, Inc 86499 77/03/18 DDYER.J E Office of Nuclear Material Safety & Safeguards, Director ip 18503 094
- ~~8305180070 Discusses 791207 telcon re postponement of meeting w/Nuclear Pharmaty, Inc (NPI) Allegations in notice of violation w/o foundation Prompt action to resolve matter requested VAMERICS, T V O'Connor & Hannan 79/12/07 STELLO, V Director's Office, Office of Inspection and Enforcement 3pp 18503 095
- --8305180074 Confirms 791205 telcon re withdrawal of Nuclear Pharmacy, Inc matter from consideration by DDJ Investigation of source of unauthorized disclosures of confidential info requested VAMERICS: TV D'Connor & Hannan 79/12/07 CUMMINGS, J J Office of Inspector & Auditor ip 18503 098
- --8305180080 Documents recollection of 790323 enforcement mgt meeting re Nuclear Pharmacy, Inc reason for distributing Union Carbide Xe-133 PAPER/ELLO, C. Regian 3, Chicago, Office of the Director 79/12/10 STRICKLER, J. Office of Inspector & Auditor 1p 18503 100
- --8305180092 Discusses status of other NRC ofc actions from 790614-1127 re NRC criminal referral to DOJ re allegations of improper activities by Nuclear Pharmacy, Inc STRICKLER.L J Office of Inspector & Auditor 79/12/13 CUMMINGS.J J Office of Inspector & Auditor 5pp 18503 101
- --8305180076 Forwards 771201 ltr re allegations of improper activities by Nuclear Pharmacy.Inc Ltr includes number of issues which appear to warrant further investigation Personally identifiable info deleted GOMER.G C Executive Officer for Operations Support 77/12/19 FORTUNA:R Office of Inspector & Auditor Jpp 18303 106
- ---8305180100 Discusses 800128 interview w/J Murray re 800121 meeting w/ Nuclear Pharmacy.Inc on proposed hotice of violation SINCLAIR.J.R Office of Inspector & Auditor 81/02/04 SYRICKLER.L J Office of Inspector & Auditor 3pp 18503 107
- --8305180106 Discusses 800205 interview w/V Stello re 800121 meeting w/ Nuclear Pharmacy. Inc concerning sales of Xe-133 not approved for human use Affidavit encl Personally identifiable info deleted GAMBLE.D H. Office of Inspector & Auditor 81/02/08 STRICKLER, L. J. Office of Inspector & Auditor 6pp 18503 112
- --8305180111 Discusses Senator H Schmitt 800102 itr re Nuclear Pharmacy, Inc (NPI) & T Brockett responses concerning possible criminal violations by NPI STRICKLER.L NRC No Detailed Affiliation Given 80/02/19 NRC No Detailed Affiliation Given 1p 18503-118
- --8305180116 Requests expeditious resolution of notice of violation issued to Nuclear Pharmacy, Inc SCHNITT, H Benate 80/01/02 AHEARNE, J Commissioners ip 18503-119

- --8305(80123 Urges final action to resolve notice of violation issued to Nuclear Pharmacy. Inc in Aug 1979 Review by another agency not sufficient justification to forestall prompt action DOMENICI.P V Senate 80/01/09 AHEARNE, J F Commissioners 2pp 18503 120
- --B305iB0153 Discusses 800109 ltr re pending administration action against Nuclear Pharmacy, Inc (NPI) DDJ currently reviewing matter No operating restrictions placed on licensee DIRCKS W J Office of the Executive Director for Operations 80/02/ii DDMENICI,P V Senate ip 18503 122
- --8305180159 Confirms 800227 telcon re Jan 1979 insp at Nuclear Pharmacy, Inc (NPI) No indication that NPI reused New England Nuclear dose vials for packaging & distributing Xe-133 observed Interview rept enci Personally identifiable info deleted DICEV, B B Michigan, Univ of 80/02/27 STRICKLER, J Office of Inspector & Auditor 9pp 18503 123
- --8305180164 Notifies that D Leggett & J Fischer provided w/listed statements during 800310 visit.per DOJ instructions re Nuclear Pharmacy.Inc investigation Personally identifiable info deleted STRICKLER.L J Office of Inspector & Auditor 80/03/13 Office of Inspector & Auditor 10 19503 132
- --8305180174 Advises that listed original statements placed in Nuclear Pharmacy. Inc investigation file on 800313. Personally identifiable info deleted STRICKLER, L. J. Office of Inspector & Auditor 80/03/13. Office of Inspector & Auditor 19 18503 133
- ~-8305180178 Forwards DOJ 800307 ltr describing frustrations in dealing w/NRC during consideration of possible criminal aspects of Nuclear Pharmacy.Inc case CUMMINOS.J J Office of Inspector & Auditor 80/03/13. AHEARNE.J F Commissioners ip 18503.134
- --8305180186 Disagrees w/800313 memo to Chairmen re civil penalties resulting from notice of violation issued to Nuclear Pharmacy. Inc.
 STELLO.V Director's Office. Office of Inspection and Enforcement 80/03/18 CUMMINOS.J J Office of Inspector & Auditor 2pp 18303 143
- --9305180196 Discusses 800321 telcon w/former employee of Nuclear Pharmacy. Inc. re Unsafe & Unethical practices Interview encl. Personally identifiable info deleted WARD. U Executive Officer for Operations Support 80/03/31, Executive Officer for Operations Support 7pp 18503 145
- --8305180207 Notifies that final rept of 900401 interview placed in Nuclear Pharmacy, Inc. statement file on 800404 Personally identifiable info deleted STRICKLER, L. J. Defice of Inspector & Auditor 80/04/04 Office of Inspector & Auditor 11pp 18503 132
- --8305180223 Notifies that original 800319 statement placed in Nuclear Pharmacy, Inc file on 800404. Personally identifiable info deleted STRICKLER, L J Office of Inspector & Auditor 80/04/04 Office of Inspector & Auditor 80/04/04 Office
- --P305180233 Discusses conflict of interest on part of former Region I employee re civil penalty action against Elfreth Alley Apothecary, part of Nuclear Pharmacy, Inc. Personally identifiable info deleted FORTUNALR A Office of Inspector & Auditor, 80/05/29 BISCUIT, L Office of the General Counsel ip 18503 199
- --8305180241 Discusses corrective actions per 800310 ltr.in response to NRC 800407 & 0219 ltrs re radiation safety for personnel Mar film badge results indicate significant improvement Personally identifiable info deleted NUPharm.Inc EA-80-005 80/05/05 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 18503,200.
- --8305180247 Notifies that 800516 statements placed in Nuclear Pharmacy, Inc file on 800603 Personally identifiable info deleted STRICKLER.L J Office of Inspector & Auditor 80/06/03 Office of Inspector & Auditor 13pp. 18503 202
- --B3031B0258 Forwards Amend & to Matl Byproduct License 4B-17466-01MD.
 License may be suby to subsequent action by NRC or DOJ
 resulting from exam of past activities involving Xe-133
 Personally identifiable info deleted
 DELMEDICO, J Division of Fuel Cycle & Material Safety 80/05/03,
 REAVIS, J M NuPharm, Inc 32pp 18503 215

- --8305180263 Forwards Nuclear Pharmacy, Inc 800626 ltr discussing actions initiated to provide max mafety for employees FORTUNA, R A Office of Inspector & Auditor 80/07/07 GREENSPUN, J Justice, Dapt of 1p 18503 247
- --8305180249 Discusses 800624 meeting re development of corporate radiation safety program Personally identifiable info deleted

 * NuPharm, Inc 80/06/26 DAVIS, B Region 3, Chicago, Fuel Facility & Materials Safety Branch 4pp 18503 248
- --B305180285 Forwards documents on investigation of Nuclear Phermacy, Inc (NPI) per 800827 commitment re NPI-Milwaukee distribution of non-NDA Xenon in willful violation of license condition Personally identifiable info deleted M/o encis FORTUNA.R A Office of Inspector & Auditor 80/09/19 GREENSPUN, J Justice, Dept of 3pp 18303 252
- --8305180291 Forwards six interview summaries prepared by Region III re apparent conflict of interest by former Region I employee concerning Nuclear Pharmacy, Inc investigation Personally identifiable info deleted FORTUNA: R A Office of Inspector & Auditor 80/11/25 GREENSPUN, J Justice, Dept of 10pp 18503 255
- 8305180308 FOIA request for SECY-83-17 & SECY-83-17 BREADY, J C MMC, Inc 83/02/08 CHILK, 8, J Dffice of the Secretary of the Commission, 1p 18305 227.
- B305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records B3/03/29. BREADY, J C KMG. Inc ip 18505 230 24x Fiche 50-237,83/03/29,8305180316
- --8305180322 SECY-83-019
 Informs of proposed plan to convert seven remaining provisional OLs to full-term OLs after completion of SEP Phase II
 DIRCKS W J Office of the Executive Director for Operations 83/01/17 15pp 18505 231
- --8305180328 9ECY-83-017 Notifies of results of SEP review of facility DIRKKGH J D Office of the Executive Director for Operations 83/01/12 47pp 18505 246 24X Fichs 50-237,83/03/29,8305180316
- 8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of Pacilities Forwards App A documents Documents denoted w/asterisk available in PDR App B.C.D & E documents withheld (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDERGAST, R Prendergast, R.J 17pp 18506 057 24X Fiche.50-000,83/03/11.8305190005
- --8208250506 Trip rept of 820802 audit, reviewing seismic & qualification file for Zack Co equipment, at Sargent & Lundy Engineers of in Chicago, IL ROBITOCIY, Z.R. Equipment Qualification Branch 82/08/06 SCHMENCER, A. Licensing Branch 2 8pp 18507 201 24X Fiche 50-000,83/03/11,8305190005
- --8305190045 Requests vendor insp of facilities having contracts ω/Zack Co due to GA/GC problems at Midland re HVAC activities Zack Co correspondence re LaBalle & related info encl FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 PDTOPQUS, U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000.83/03/11, 2203180007
- --8305190050 Summarizes 820430 meeting w/president of Zack Co, HVAC contractor at facilities, repotential allegations Zack Coplanning to terminate several employees in document control section
 HAYES, D. W. Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 087 24X Fiche. 50-000, 83/03/11, 8305190005
- --8305190061 Summarizes 820510 telcon w/T Howard, former employee of Zack Co.re allegations concerning Zack Co.HVAC contractor at various nuclear power const sites Matter will be pursued upon return of C Heil on or about 820517 PHILLIP.G A Region 3. Office of Director EIS 82-25 82/05/21 Region 3. Office of Director ip 18306 090
- --9305190084 RD fire dampers supplied by American Marming & Ventilation,
 Inc declared inoperative Caused by discrepancy in fuse link
 assembly size Fuse assembles will be replaced. JV Winkle ltr
 re news telecast & J Dierbeck note encl,
 HOLYDAK,R. H. Commonwealth Edison Co. 92/07/01 KEPPLER,J Q
 Region 3, Optice of Director. 33pp. 18506 091 24X
 Fiche 30-000,83/03/11,8305190005

- -~8305190098 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast * Radio TV Reports, Inc 82/07/24 NRC No Detailed Affiliation Given 2pp 18506 124 24x Fiche 50-000.83/03/11, 8305190065
- --8305190097 Requests investigation of Region III inadequate investigative oversight re GA breakdown & possible criminal falsification at Zack Co. HVAC contractor at facilities AT Howard & B Marello allegations discussed DEVINE. T. GARDE. B Government Accountability Project 82/07/26 PALLADING. N. J. Commissioners lipp 18506 128 24% Fiche 50-000.83/03/11.8305190005
- --B305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co.HVAC contractor at facilities MARELLO,S L Affiliation Unknown B2/07/26 22pp 18506 139 24% Fiche 30-000,83/03/11.8305190005
- --8305170108 Affidavit of AT Howard re QC breakdown & criminal faisification at Zack Co.HVAC contractor at facilities HOWARD.A T Affiliation Uninown 82/07/26 55pp 18506 160 24X Fiche 30-000.83/03/11.8305170005
- --8305190112 Deficiency rept re errors & discrepancies contained in HVAC mat1 certifications Procurement ducumentation will be revalidated document & records mpt program will be developed & 94/9C personnei will be added Also reportable per Part 21 CALKINS, D E , EICHSTAEDT, C L , DEZUTEL, C Z Zack Co 10CFR 050 55E 81/10/23 310pp 18506 215 24X Fiche 50-000,83/03/11,8305190005
- --8305190li7 Repts investigation re possible flawed equipment at facilities, per Eyewitness News broadcast * Radio TV Reports, Inc 82/07/26 NRC No Detailed Affiliation Given 2pp 18507 165 24X Fiche 50-000, 83/03/11, 8205180005
- --8305190124 Offers assistance & cooperation in investigating Zack Co Suggestions discussed DEVING, T. GARDE. B. P. Government Accountability Project. B2/07/27 PALLADINO. N. J. Commissioners 2pp 18507 167 24X Fiche 50-000, 83/03/11.8305190005
- --8305190128 Forwards outline of investigation ropt re Zack documentation concerning HVAC activities Discussion of mat1 spec & mechanical properties for galvanized sheet steel & stiffener hanger & support steel & L DelGeorge handwritten notes encl NORELIUS.C E Region 3. Office of Director 82/07/28 KEPPLER, J O. DAVIS.A B. FOSTER, J Region 3. Office of Director 25pp 18507 169 24X Fiche 50-000.83/03/11.8305190005
- ~-8305190132 Forwards results of analyses of carbon steels received from Region LIT on 820726 NBS stds used to quality assure phosphorus manganese & copper results performed on same sample solution GREEN,D W Argonne National Laboratory 82/08/02 LANKSDURY,R Region 3. Office of Director 6pp 18307 194
- ~~B305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removal welds Certain welds on Unit 2.Div II switchgear heat removal sys may not meet applicable code requirements
 HOLVOAK, R H Commonwealth Edison Co 82/OB/O6 Region 3, Office of Director 1p 18507 200 24X Fiche 50-000, 83/03/11, 8305190005
- --8305190151 Informs of atty general of State of IL intention to attend NRC 820811 meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations
 VAN VRANKEN.J Illinois, State of 82/08/07 KEPPLER, J G Region J. Office of Director ip 18507 209 24X Fiche 50-000,83/03/1i,8305190005
- --8305190153 Forwards results of reanalyses of carbon steels received on 820736 Analysis results of NBS carbon & sulfur std data submitted OREEN, D. H. Argonne National Laboratory 82/08/10 LANKSBURY, R. Region 3. Office of Director 2pp 18507 210
- --8305190162 Introduction of 820811 public meeting to discuss util plans re employment of third party contractor to conduct independent review of HVAC sys at facilities ** NRC No Detailed Affiliation Given 82/08/11 2pp 18507-214 24X Fiche 50-000/83/03/11.8305190005

- --B305190167 Requests that all interested parties be furnished proposed contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized VAN VRANKEN.J Illinois. State of B2/08/12 KEPPLER.J O Region G. Office of Director 2pp 18507 215 24% Fiche 50-000.83/03/ii.8305170005
- --8305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & S Marello experience & knowledge be utilized in review process Util 820813 ltr to CF Braun & Co enc!
 HOWARD,A T Affilation Unknown 82/08/13 KEPPLER, J G Region 3, Office of Director lipp 18507 216 24X
 Fichs 50-000,63/03/11.8305190005
- --8305190184 Confirms 820812 talcon re telephone call from M Cherry concerning Zack investigation & circumstances surrounding termination of Zack employees.

 DAVIS, A B Region 3. Office of Director 82/08/16 FIYZGERALD, J Office of Investigation 2pp 18507 230 24K fiche 50-000, 83/03/11, 8305190005
- ---930519D189 Notification of 820824 meeting w/util in Olen Ellyn. IL to discuss status of licensee independent HVAC review # Region 3, Office of Director 82/08/18 Region 3, Office of Director 1p 18507 231 24% Fishe 50-000.83/03/11.8305190005
- ---E305190207 Verifies AT Howard receipt of four cassette tapes of 820730 discussions between NRC & AT Howard SL Marello & T Devine at Region III ofc in Olen Ellyn IL 4 Region 3, Office of Director HOHARD, A T Affiliation Uninown 82/08/20 Region 3, Office of Director. ip 16507 258
- --9305190232 Requests investigation re discharge of AT Howard & S Marello from Zack Co.per 820819 discussion w/ J Fitzgerald DAVIS, A B Region 3, Office of Director 82/08/23 FOSTER, J E Region 3, Deflice of Director 19 18507 259
- --8305190276 Confirms oral direction given to RD Lanksbury requesting that Zack investigation determine adequacy of qualifications of Zack personnel involved in Zack GA/GC program Work may be performed by Region IV DAVIS
- --B305190283 Introduction of B20824 public meeting to discuss util preliminary plans re independent review of HVAC sys at facilities Heeting will focus on CF Braun technical proposals
 # NRC No Datailed Affiliation Given 83/08/24 1p 18507 266 24% Fiche 50-000,83/03/1i,8305190005
- --8305190289 Forwards T Devine 820813 ltr.AT Howard 820813 ltr & 88
 Marello 820816 ltr for NRR consideration in assessment of
 util proposal on third party review of HVAC sys at
 facilities

 SPESSARD.R L Division of Project & Resident Programs. 82/08/25.
 ETSENHUT) D 0 Division of Licensing. 1p 18507 293 24X
 Fiche 50-000.83/03/11.8305190005
- --8305190292 Advises that AT Howard & 89 Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co, subj to listed conditions Related info enci
 DEVINE, T Government Accountability Project 82/08/13
 KEPLER, J Region 3, Office of Director 18pp 18507 294 24X
 Fiche 50-000,83/03/11,8305190005
- --8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities. CF Braun should rept directly to NRC & should audit all critical areas at facilities

 MARELLO; L Affiliation Unknown 82/08/16 KEPPLER: J Region
 9, Office of Director 3pp 18507 313 24X Fiche 50-000,
 83/03/11,8305190905
- --8305190279 Advises that HVAC review consists of independent review & review of allegations & that NRR & Region III responsibilities delineated per 820824 meeting, in response to HR Denton question (draft memo) BOURNIAA Licensing Branch 2 82/08/26. NOVAK, T. M. Assistant Director for Licensing. 1p 18507 316
- --B305190302 Forwards Rev O to "Assessment of Stitch Weld Strength in HVAC Ductwork Const, LeSalle County Station Units 1 & 2, " QC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired POLLOCK, R. H. Sergent & Lundy, Inc. 82/08/27, SHELTON, B R Commonwealth Edison Co ip 18507 317 24X Fiche: 30-000, 83/03/11, 8303/9005.

- --8305170303 CGD-003490 R00
 Rev O to "Assessment of Stitch Held Strength in HVAC
 Ductwork Const.LaSalls County Station Units 1 % 2"
 CHO.F. L. KISISEL. IT, MELIOI.A V Sargent & Lundy, Inc
 82/08/27 27pp 18507 318. 24X Fiche 50~000, 83/03/11, 8305170005
- --8305190304 Discusses concerns on behalf of AT Howard & S Marello, for NRC consideration in review of GF Braun final proposal to conduct independent review of HVAC sys at facilities, per 820824 meeting
 DEVINE.T Government Accountability Project 82/09/04
 KEPPLER.J G Region 3, Office of Director 6pp 18507, 345 24X
 Fiche 50-000,83/03/11,8305190005
- --B305190304 Clarifies initial actions taken re A Howard ellegations concerning Zack Co Agrees w/RF Harnick handling of case w/ relative priority FOSYER.J E Region 3. Office of Director B2/09/07 KEPPLER.J 9. Region 3. Office of Director 2pp 18507 351
- --8305190307 Discusses A Howard 820503 allegations re Zack Co tampering w/documents concerning HVAC activities at facilities. Further investigation will be implamented if deemed appropriate by mgt SHAFER.W.D. Region 3, Office of Director. 82/05/11 HARNICK.R F Region 3, Office of Director. 3pp. 18507-354 24X Fiche 30-000.83/03/11.8303190005
- --8305190329 Responds to 820704 ltr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taten into consideration in NRR review of proposal KEPPLER.J G Region 3, Office of Director 82/09/13 DEVINE,T Government Accountability Project. 1p 18507.357 24X Fiche.50-000.83/03/11.8305190005
- --8305190332 Forwards "LaSalle County Station Independent HVAC Revise," interim rept. Rept also sent to JO Keppler KEMPIAK.A J C F Braun & Co BL-6 82/09/15. SHELTON, B R. Commonwealth Edison Co 1p 18507 359 24X Fiche 50-000, 83/03/11,8305190005
- ---8305190337 Forwards results of analysis of steel received on 820715, GREEN: D W Argonne National Laboratory 82/07/29 LANKBBURY: R Region 3: Office of Director 3pp 18508:085
- --8305190341 Forwards results of analysis of steels received on 820924 GREEN.D W. Argonne National Laboratory, 82/10/11 LANK8BURY, R. Region 3, Office of Director 2pp 18508-088,
- --8305190353 Forwards TE Watts 821017 & 25 memos to CH Schroeder responding to R Lanksbury questions re HVAC ductwork design & transmitting Rev O to Project Instruction PI-LS-42.
 "Review of QC Documentation for LaBalis County Station "
 SCHROEDER.O W. Commonwealth Edison Co 5332N, 82/10/27
 KEPPLER.J G Region 3, Office of Director, 9pp. 18508-093 243
 Fiche 50-000.83/03/11,8305190005
- --8305190357 Rev O to Project Instruction PI-L8-42, "Review of GC Documentation for LaBalls County Station Units 1 & 2 " # Eargent & Lundy, Inc. 82/10/21 9pp. 18508:102 24X Fichs 50-000.83/03/11.8303190005
- --8305190365 Forwards Vols 1-4 to "Independent HVAC Review, LaBalle County Nuclear Plent," final rept.

 KEMPIAK, A. J. C. F. Braun & Co., BL-25 82/10/27 SHELYON, B.R. Commonwealth Edison Co., ip 18508.iii, 24X Fiche 50-000, B3/03/ii,8305190005.
- --B305190367 Ack receipt of CF Braun final rept of independent HVAC review at facilities
 PHILLIPS,R.W. Region 3, Office of Director. 82/10/27 Region
 3, Office of Director ip 18508.112 24X Fiche.50-000,83/03/11,8305190005
- --B305190374 Forwards itr from Chicago-based law firm representing Zack Co. requesting withholding of documents re NRC investigation of Zack Co. per 10CFR2 790 Conference call will be held on 821i10 to discuss subj W/o snel.

 COLLINS.J. T. Region 4, Office of Director. 82/11/08 KEPPLER.J. Region 3, Office of pirector. CUNNINGHAM.Q. Office of the Executive Legal Director ip. 18508-113
- --8305190379 Requests list of results of detailed calculations on rebar damage for 647 concrete elements effecting Unit 1 operation & approved CF Braun proposal for independent HVAC review. Zack Co chronology encl 90001E, J S Illinois, State of 82/09/07. KEPPLER, J Q, Region 3, Diffice of Director. Spp. 18511:278 24X Fichs:50-000, 83/03/11,8305190005.

- --8305190384 Advises that field insp of HVAC sys at facility completed, including review of Govt Accountability Project allegations against Zack Co No technical basis swists for further restriction of facility power level W/related info KEPPLER. J G Region 3. Office of Director 82/12/03 DENTON. H R Office of Nuclear Reactor Regulation. Director 11pp 18512 038 24X Fiche 50-000.83/03/11.8305190005
- --B305190387 Rev 1 to "LaBalle County Station Technical Proposal," including scope of work work plan to accomplish independent HVAC review, organization chart & resumes of personnel assigned to project List of matl specs for HVAC const encl # C.F Braun & Co 82/08/25 34pp 18512 155 24X Fiche 50-000, 83/03/11, 8305190005
- --9305190390 P Donahue show Transcript 08302 re nuclear power safety Info re facilities & Zack Co encl * Multimedia Program Production, Inc 83/03/11 128pp 18512 187 24X Fiche 50-000.83/03/11,8305190005
- --8305190393 Discusses Zack Co Part 21 rept re dual traveler record sys for fabrication of duct work & hangers at facility.per 620729 telcon w/L DelGeorge & C Read AT Howard resume encl HILLIAMS.C C NRC - No Detailed Affiliation Given 83/03/11 LANKSBURY.R.D. NRC -- No Detailed Affiliation Given. Spp 18512 317. 24X Fiche 50~000.B3/03/11.8305170005
- --B305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co GA program at facilities Personally identifiable info deleted MORELIUS, C. E. Division of Engineering 82/07/12 Division of Engineering ip. 18512 323 24X Ficha 50-000,83/03/11,8305190005
- --8305190399 Handwrittan notes re mesting w/util on allegations concerning Zack Co activities at facilities
 DAVIS.A.B NRC No Detailed Affiliation Given. 82/07/16 9pp
 18512.335 24X Fiche 50-000-83/03/11.8305190005
- B3052000B7 Responds to FDIA request for name of manufacturer of fuel rods used at facility Fuel rods mfg by B&H.
 FELTON.J M. Division of Rules and Records B3/03/3i WHITED.P.J Affiliation Unknown ip. 18541.004 R4X Fiche 50-320.83/03/31, B3052000B7
- B305200101 FDIA request for name of manufacturer of fuel rods used at facility HHITED, P.J. Affiliation Unknown B3/03/23 FELTON, J.M. Division of Rules and Records. ip 18541-005 24X Fiche 50-320, B3/03/23, B3/03200101.
- B305230005 F0IA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Safety Quals: "between NRC Ofc of Policy Evaluation & NUS Corp BHOLLY, B.C Union of Concerned Scientists FIN B-8178 NRC-19-82-493 B3/03/11 FELTON, J. M Division of Rules and Records 1p. 18546.262
- 8305230028 Responds to FOIA request for all correspondence & repts re NRC Contract NRC-17-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp. Forwards App A documents FELTON, J M Division of Rules and Records FIN B-8178. NRC-19-82-493 83/03/01 SHOLLY, 8 C. Union of Concerned Scientists. 2pp. 18545-263
- --8305230039 Comments on NUREQ-OBBO, "Bafety Goals for Nuclear Power Plants. Discussion Paper," Feb 1982 Proposed policy does not contain independent numerical guideline for early fatality societal risk.

 LEVINE: 8 NUB Corp CQ-BL-28-82 82/05/26, REMICK, F. J. Office of Policy Evaluations. 7pp. 18546:265.
- ~-8305230047 Advises that 8 Levine directed to provide followup discussion & advice on safety goals re 820526 written rept & 820715 meeting w/F Remick providing advice on use of PRA, per Article I of Contract NRC-19-82-493 HONTGOMERY, J M. Office of Policy Evaluations NRC-19-82-493 82/07/19. Office of Policy Evaluations, ip. 18546:274.
- ~-8303230037 Forwards matl from O Keiser re calculation of individual & societal risks for comparison w/safety goals Requests meeting w/O Kaiser & R Bland to discuss differences in predictions of weighted individual risk requested LEVING.8 NUS Corp. CO-SL-98-62 82/11/18. ZERBE, J. E. Office of Policy Evaluations. 28pp. 18546.275.
- 8305230059 FOIA request for SECY-82-13D. PEDRO, J MUS Corp. CD-LIB-8992, 83/02/28 Division of Rules and Records, 1p 18543 136.

- B30523006) Responds to FOIA request for SECY-82-13D Forwards requested document Document also available in PDR FELTON.J M Division of Rules and Records 83/03/31 PEDRO,J MUS Corp lp 18543 137
- --8305230070 SECY-82-013D
 Informs Commission of status of implementation of IOCFR50 48 & App R to IOCFR50 re fire protection rule for Third Quarter 1982.per SJ Chilk B01103 request DIRCKS.W J Office of the Executive Director for Operations 82/12/10 9pp 18543 138
- 8305230112 Final response to FOIA request for insp repts of safety violations at Kern-McGee Pu plant at Cresant. OK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted FELTON.J M Division of Rules and Records 83/03/22 WIDMER.R R Affiliation Unknown ip 18043 154
- --8305230134 Forwards Regulatory Investigation Rept 70-1193/73-01 on 730917-21 No significant health & safety problems associated Wioccurrences reported in allegations DONAHUE, J. F. Atomic Energy Commission 73/11/02 FIDRELLI.0 Atomic Energy Commission 4pp 18543 155
- --8305230137 Regulatory Investigation Rept 70-1193/73-01 on 730917-21 Major area investigated anonymous allegations re leaks in Pu waste arums & unsafe practices Info re personnel interviews delated DONAHUE. J F., FINN, J A., RIDGWAY, K.R. Atomic Energy Commission 73/11/01 18pp 18343 139
- --8305230179 Discusses licensee employee allegations re-spills of Pu & leaking tanks Facility insp w/emphasis on incidents, spills, decontemination & personnel exposures scheduled for 730917
 DONAHUE, J. F. Atomic Energy Commission 73/09/04 Atomic Energy Commission 4pp 18543 177
- --9305230186 Updates 730904 memo re licenses employee allegations concerning unsafe working conditions due to possible contamination of work sites Related news articles & press release enci
 DONAHUE, J. F. Atomic Energy Commission 73/09/13 Atomic Energy Commission 10pp 18543 181
- --8305230194 Rev 1 to Pu Plant Std Operating Procedure KM-NP-37-2,
 "Liquid Waste Solidification " Related info encl
 MULKIN.R Kerr-McGee Nuclear Corp 72/05/02 31pp 18543 191
- --8305230207 Forwards Region IV 660729 memo re facility closeout survey results Licensee measurements in 660609 ltr substantiated by Region IV findings ROY-0 W. Atomic Energy Commission 66/08/08 NUBGBAUMER, D A Atomic Energy Commission ip 18543 222
- --B305230222 Discusses closeout inap of Licenses SMB-644 & SNM-695 on 660706 Recommends that licensee be authorized to transfer control of facilities to unlicensed recipient, HALKER, D. L. Atomic Energy Commission 66/07/29 DUBINSKI, L Atomic Energy Commission 4pp 18543, 223
- --8305230233 Requests authorization to release vacated facilities at Cushing, OK to refining div for unrestricted use Bldgs used by nuclear products dept cleaned & decontaminated Health physics survey indicates contamination below limits WULLER, O B Kerr-McGee Nuclear Corp 66/06/09 NUSBBAUMER, D A Atomic Energy Commission 4pp 18543 227
- 8305230203 FDIA request for NRC Investigation Rept 1-83-003 QDRELICK,M S Steinberg, Greenstein, Gorelick, Price & Laveson 83/03/25 CHRISTOPHER,K Office of Investigation ip 18543 307
- B305230215 Responds to FOIA request for NRC Investigation Rept 1-83-003 Rept withheld (ref FOIA Exemptions 5 & 7) FELTON.J M Division of Rules and Records 83/05/02 GDRELICK.M B Steinberg, Greenstein, Gonelick, Price & Laveson 1p 18543:308
- 8305230220 FDIA request for names & addresses of outside law firms which have performed legal svc for NRC during past 3 yrs involving Title VII or similar employment discrimation matters, I e age or handicap SIMPSON, O H Simpson, O.H. 83/03/29 Office of Administration ip 18543 343
- 8305230223 Responds to FOIA request for hames & addresses of putside law firms which have performed legal syes for NRC during past 3 yrs involving Title VII or similar employment discrimation matters No records subj to request available FELTON, J M Division of Rules and Records 83/04/25 BIMPEON. C H Binpson. C H. ip 18543-344.

- B305230229 FOIA request for three categories of documents PUNTENNEY, J Safe Energy Coalition 83/02/14 Division of Rules and Records 1p 18543 307
- 8305230232 Partial response to FDIA request for three categories of documents Forwards App A documents Document 3 sent to NRC by State of YT & approved for release by DDT Review of add1 documents in progress FELTON, J M Division of Rules and Records 83/03/21 PUNTENNEY, J Bafe Energy Coalition 3pp 18543 310
- --9305230234 FR Natice, Vol 47. Number 78 from Research & Special Programs Administration Related news articles & ltr from State of VT to DOT secretary encl * Transportation. Dept of 82/04/22 30pp 18543 313
- B305230243 FOIA request for documents re meeting between representatives of ABEA-ATOM (Sweden) & NRC concerning Process Inherent Ultimate Safety Reactor SHOLLY.S C Union of Concerned Scientists B3/04/13 FELTON, J M Division of Rules and Records ip 18545 263
- 8305230246 Partial response to FOIA request for documents re-matering between representatives of ASEA-ATOM (Sweden) & NRC concerning Process Inherent Ultimate Safety Reactor Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/04/28 SHOLLY, S C Union of Concerned Scientists 2pp 18545-264
- --830523025; Notifies that K Hanner; of ASEA-ATOM (Sweden) has offered to present wem(ner on 830528 to interested staff re proposed super safe LWR concept called Process Inherent Uttimate Safety (PIUS) reactor List of participants encl LAFLEUR, J D Director's Office, Office of Inspection and Enforcement 83/03/02 GARNER, D, ABBOTT, E, CORNELL, K NRC No Detailed Affiliation Oiven 2pp 18545 266
- --8305230254 Draft of "Toward Intrinsically Safe LWRs "
 HANNER7.K Oak Ridge Associated Univ 82/06/04 82pp
 18545 268
- 8305240087 Add1 response to FDIA request for draft insp evaluation repts & comments on J Reppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
 FELTON.J M Division of Rules and Records 83/03/31. QARDE, B Government Accountability Project 2pp 18593 015 24X
 Fiche: 50-373.83/03/31.8305240087
- --8305240098 Five draft summaries of affidavits & statements, draft comments on followup of allegations: minutes of Region III 820329.0419.0503 & 0706 staff meetings & draft investigation schedule. Personally identifiable info deleted NRC No Detailed Affiliation Given 83/03/25 36pp 18593 018 24% Fichs 50-373,83/03/31,8305240097.
- --8305240125 Discusses actions planned during add1 insp to resolve concerns re adequacy of workmanship during const of masonry walls R Lipinski assistance requested to resolve issues starting wk of 820015

 SPESSARD.R L Division of Project & Resident Programs. 82/09/17
 EISENIUT, D 0 Division of Licensing 2pp 18593 034 24X
 Fiche 50-973,83/03/31,8305240087
- --8305250144 Recommends unesorted access to protected areas for R Lipinski & 8 Chan Rapifac sheet transmitting evaluation of technical rept. "Assessment of Effects of Nicked Reinforcing Steel," encl KEPPLER, J Q Region 3, Office of Pirector 82/06/14 REED, C Commonwealth Edison Co 7pp 18993 056 24X Fiche 50-373,83/03/31,8303240887
- 9305240249 FDIA request for three categories of documents re Reactor Eafety Study Methodology Application Program (NUREO/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515, 2787 & 2802)
 SHOLLY, S C Union of Concerned Scientists 83/03/11 FELYON, J M Division of Rules and Records 1p 18593 178 24X
 Fiche 50-000, 83/03/11, 8305240249
- 8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress FELTON, J M Division of Rules and Records. 83/03/31 SHOLLY.S C Union of Concerned Scientists. 2pp. 18593-177 24X Fiche 50-000.83/03/31.8305240254

- --Bio3300276 Comments on draft "Reactor Safety Study Methodology Applications Program Results for Grand Gulf 1 BMR Power Plant " Dmissions & simplifications overstate risk of facility operation HODGES-M Reactor Systems Branch 81/03/24 CURRY, J Office of Nuclear Regulatory Research, Director 3pp 18593 252 24X Fiche 50-000,83/03/31,8305240224
- --B305240237 Forwards comments on draft rept re Reactor Safety Study
 Methodology Applications Program for facility Changes
 indicated in areas of validity of sys criteria & correctness
 & appropriateness of assumptions in sys analysis
 PARKER.W O Duke Power Co 004022 B0/09/22 BERNERO.R
 Probabilistic Analysis Staff (Pre B01ii9) 11pp 18373 181 24X
 Fiche 50-000, 883/03/31,8303240254
- --B305240260 Forwards util comments on Reactor Safety Study Methodology Applications Program results Risks associated w/BWR/6 plant design misrepresented CESARE.G NRC No Detailed Affiliation Given B1/02/17 CURRY.J NRC No Detailed Affiliation Given 5pp 18593 195 24X Fiche 50-000.89/03/31,8305240254
- ---8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RSSMAP) evaluation conducted by Sandia Natl Labs Excessively conservative calculations used Related correspondance and DALE, L.F. Mississippi Power & Light Co. AECM-81/184, 81/01/20 BERNERO, R.M. Office of Nuclear Regulatory Research, Director 47pp 18593 200 24X Fiche 50-000-83/03/31,8305240254
- --8303240267 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RBSMAP) analysis If rept is to be published clear statement of program assumptions & limitations should be included TIERNAN.J A Baltimore Oas & Electric Co 82/03/05 BURDICK, C. R. Office of Nuclear Regulatory Research, Director. 35pp 18593 253 24X Fiche 50-000,83/03/31.8305240254
- 8305240355 FDIA request for RFP EDD-83-436, "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements " NEWHANK A Debevoise & Liberman 83/03/24 FELTUN, J M. Division of Rules and Records ip 18627 031
- 8305240345 Responds to FDIA request for RFP EDD-83-434, "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements "Forwards document Document also available in PDR PDR DIVISION OF Rules and Records 83/03/31. NEWMAN.K.A. Debevoise & Liberman ip 18427-032.
- --8303240367 RFP R8-EDD-83-436, "Devaloping Decisionmaking Rational for Establishing New Regulatory Requirements," RFP summary proposal submission instructions no-offer response form & solicitation package encl MATTIAN J Administrative Contracts Branch, 83/01/17 67pp 18627 033
- B305230025 FOIA request for RFP-R8-80-102 & technical & business sections of winning proposal for NRC Contract NRC-03-80-102 BURKE, S Affiliation Unknown NRC-03-80-102, B3/03/08 Division of Rules and Records 1p 18596, 207
- 8305250029 Responds to FOIA request for RFP & winning proposal under Contract NRC-03-80-102 Forwards requested document RFP also available in PDR FELTON, J M. Division of Rules and Records. NRC-03-80-102 83/03/29 BURKE, S. Affiliation Unknown ip 18596, 208
- --8305250034 R9-NRR-80-102
 RFP RS-NRR-80-102 for "Energetic Thermal Interactions,
 Recriticality & Coolant Flow Phenomena Associated w/
 Advanced Nuclear Reactor Concepts"
 DOUGHERTY, D. J. Division of Contracts 79/08/02 48pp
- ---8305250038 NRC Manual Chapter 3202, "Publication of Unclassified Regulatory & Technical Documents Prepared by NRC Contractors Including Repts Prepared Under or Per Interagency Agraements" # Office of Administration 78/01/25 7pp 18574:257
- --8305250043 "Publication of Regulatory & Technical Documents Prepared by NRC Contractors, Including Repts Preparad Under or Per Interagency Agreements " # Division of Technical Information & Document Control, 78/01/25, 42pp 18596 264

- 8303260397 Add1 response to FOIA request for transcripts of Commission 821028.1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/03/28 SAMP.R A Shaw, Pittman, Potts & Troubridge 4pp 18647 294 24X Fiche 30-358.83/03/28,8305260397
- --BJ05260401 Forwards press release, withers list & J Keppler final testimony for 820914 hearing on status of NRC review of const activities at facility KAMMERER, C Dffice of Congressional Affairs 82/09/13 PALLADINO, N, GILINGKY, V, AHEARNE, J Commissioners 1p 18447 248 24X Fiche 30-338,83/03/28,8305260397
- --8305260405 Testimony of J9 Keppler (Region III) before Subcommittee on Energy & Environ of Committee on Interior & Insular Affairs on 830914 re quality confirmation program in Washington, DC KEPPLER, J 9 Region 2. Dffice of Director 82/09/14 62pp 18647 302 24X Fiche 50-358,83/03/28,8305260397

GEN TEC IS GENERIC TECHNICAL ISSUES

- 8305020345 Summarises 830425 meeting w/NRC re reactor vessel internals & thermal shield plant recovery program concerning pressurized thermal shock Plant may safely operate w/o restriction from pressurized thermal shock considerations UHRIO.R E Florida Power & Light Co L-83-263 83/04/27 CLARK.R A Operating Reactors Branch 3 15pp 18274 079 24X Fiche 50-335,83/04/27,8305020345
- 8305040323 Board Notification 83-057 forwards differing prof opinions re-sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17 EIBENHUT.D C Division of Licensing 83/05/04 PALLADING.N Commissioners 22pp 18337 139 24x Fiche 50-000.83/05/04.8305040323
- B305040405 Memorandum & order denying intervenor 830428 oral motion to teep record open on steam tube integrity subissues Record contains sufficient info to make decision re Unresolved Bafety Issue A-3
 BMITH, I W Atomic Safety and Licensing Board Panel IBSVANCES OL 83/05/03 League of Women Voters of Rockford, IL 2pp 18323 208 24X Fiche 50~454,83/05/03,8305040405
- 8305040730 Discusses AEOD/8307, "Potential for Water Hammer Damage During Restart of RHR Pumps at BWR Nuclear Power Plants "Recommendations provided do not extend beyond procedurel development & operator awareness HELTEMES.C J Director's Office AEOD/8307 83/04/22 EISENHU Division of Licensing, SPEIS.T Division of Safety Technology 1p. 18328 047 24X Fiche 50-257.83/04/22.8305040730
- --8305040737 Forwards AEOD/E309, "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Planta" RUBIN:8 Reactor Operations Analysis Branch AEOD/E309 B3/04/21 BEYFRII.K V Reactor Operations Analysis Dranch is 18683 319 24X Fiche 50-259,83/04/22,8305040730
- --8305040745 "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Plants," AEOD engineering evaluation rept RUBIN:8, LANIK:0 Director's Office AEOD/E309 83/04/30 27pp 18328 069 24X Fiche 50-259.83/04/22.8305040730
- 9305060395 Forwards response to B20923 ltr re open items in NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants " Dynamic load effects inservice insp & exam frequency reviewed Phase II results expected by 830601 CROUSE.R P Toleda Edison Co 743 B3/05/02 BTOLZ.J F. Operating Peactors Branch 4 7pp 18343 167 24X Fiche 30-346.83/05/02.8303060395
- B303060397 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point, Unit 3 Nuclear Generating Station, Steam Generator Girth Held Cracke Under Pressurized Thermal Shock Conditions, "Rept withheld (ref 100FR2 790)
 BAYNE, J P Power Authority of the State of New York IPN-83-32
 B3705709 VARQA: S A Operating Reactors Branch 1 2pp 18348 203
 24% Fiche 50-286,83/05/03,8305060397
- --8305060407 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point.Unit 3 Nuclear Generating Station. Steam Generator Oirth Weld Cracks Under Pressurized Thermal Shock Conditions " Rept withheld (ref 10CFR2 790) COTTER.K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation. Director 1p. 18348 205 24% Fiche 50-286,83/05/03,8305060397

- --8305040417 Submits application for withholding from public disclose.
 "Fracture Mechanics Analysis of Indian Point Unit 3 Nuclear
 Generating Station, Steam Generator Cirth Weld Cracks Under
 Pressurized Thermal Shock Conditions"
 COTTER.K H Fracture Proof Design Corp 83/04/29 Office of
 Nuclear Reactor Regulation, Director 4pp 18348 204 24X
 Fiche 50-286,83/05/03.8305060397
- 8305090244 Responds to 830329 memo re mgt & technical issues of ATHS events Issues to be addressed in NUREG-1000. "Generic Implications of ATHS Events at Salem Nuclear Power Plant "RHR capability addressed in Unresolved Safety Issue A-45 DENTON.H R Office of Nuclear Reactor Regulation. Director 83/04/29 EPLERIE P Epler. E P Bpp 18381 084 24X Fiche 50-272.83/04/29, 8305090244
- 8303090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon FREBY. S A Hearing Branch i 83/05/05 BLOCH.PB Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 30-445.83/05/05,8303090368
- ~~B305090607 Affidavit of FD Coffman on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants," per ASLB 830407 telcon request Prof qualifications encl COFFMAN, FD Reliability & Risk Assessment Branch 83/05/05 9pp 18360 058 24% Fiche 50-445.83/05/05,8305090368
- --B305090640 Affidavit of CE Rossi re ABLB 830407 telcon questions concerning status of NRC position on Unresolved Safety Issue A-9, "ATMS " Prof qualifications encl ROSSI.C E Instrumentation & Control Systems Branch B3/05/05 5pp 18380 083 24X Fiche 50-445.83/05/05.8305090568
- --8305090446 Affidavit of AJ Szukiewicz & TO Dunning re ASL8 830407 questions on Unresolved Safety Issue A-47. "Safety Implications of Control Bys " Prof qualifications encl SZUKIEWICZ. A J Generic Issues Branch DUNNING.T G Instrumentation & Control Systems Branch 83/05/05 9pp 18360 093 24% Fiche 50-445,83/05/05,8305090568
- B305100240 Forwards response to Unresolved Safety Issues A-1.A-5.A-11.A-12.A-17.A-40.A-43.A-44.A-45.A-46.A-47.A-48 & A-49 Responses support position that plant can be operated safely until resolution of open items MILLS.L M Tennessee Valley Authority B3/05/05 ADENSAM.E Licensing Branch 4 26pp 18372 278 24% Fiche 50-43B.83/05/05, B305100240
- 830511Q154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07, NUREG-0612, "Control of Heavy Loads." to confirm & clarify items discussed in 820804 telcon LIDEN,E A Public Service Electric & Qas Co of New Jersey GL-81-07 83/04/27 VARGA:S A Operating Reactors Branch 1 Bpp 24X Fichs 50-272,83/04/27,8305110154
- --8305110156 PSE-0108, "Maint Procedures "

 # Public Bervice Electric & Gas Co of New Jersey GL-81-07
 83/04/27 1.057pp 18400 001 24X Fiths 50-272,83/04/27,
 8305110154
- B305110385 Forwards response to open item on safe load paths contained in NRC B20923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREO-0612) CROUBE,R F Toledo Edison Go 946 B3/05/06 STOLZ,J F Operating Reactore Branch 4 11pp 18406 201 24X Fiche 50-346.83/05/06.8305110385
- 8303110415 Notification of CROR Meeting 38 on 830318 in Bethesda.MD to discuss proposed rule. "Analysis of Potential Pressurized Thermal Shock Events," prioritization of generic safety issues & operator requalification program Review mat1 encl STELLG.V Regional Operations & Generic Requirements 83/05/10 E18ENHUT.D G. Office of Nuclear Reactor Regulation, Director JRDAN.E L. Director's Diffice. Office of Inspection and Enforcement CUNNINGHAM.R E. Office of Nuclear Material Safety & Safeguards, Director 2pp 18394 221
- --8305110423 Forwards draft FR notice & supporting regulatory assessment on proposed tule re pressurized thermal shock CROR review requested within 2 wks
 DENTON.H R. Office of Nuclear Reactor Regulation, Director 83/05/03 STELLO.V Regional Operations & Generic Requirements 36pp 18374 222
- 8305120325 Forwards response to NUREG-0612, "Control of Heavy Loads" Ack of receipt of matl requested CRANE,P A Pacific Oas & Electric Co 83/05/09 KNIGHTON,O W Licensing Dranch 3 282pp 18432 042 24X Fiche 50-275,83/05/09, 8305120325

- 8305120520 Summary of 830425 meeting w/util & C-E in Bethesda. MD re thermal shock to reactor pressure vessel w/removal of thermal shield from facility Viewgraphs enci SELLS, D E Operating Reactors Branch 3 83/05/03 Operating Reactors Branch 3 17pe 18441 341 24X Fiche 50-335,83/05/03,830512020
- B305130054 Act receipt of B21103 ltr re intention to complete Phase II of control of heavy loads issue (NUREG-0412) Final technical evaluation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested QARRITY. J H Maine Yankee Atomic Power Co MN-B3-94 B3/05/10 CLARK, R A Operating Reactors Branch 3 2pp 18437 031 24X Fiche, 50-309, 83/05/10, 8305130054
- 8305130294 Forwards safety evaluation & Frantlin Research Ctr technical evaluation rept. "Control of Heavy Loads (C-10). Oconee Nuclear Power Station. Units 1.2 & 3 " Phase 1 actions acceptable per NURGG-0612 STOLT.J. F. Operating Reactors Branch 4 83/04/20 TUCKER, H. B. Duke Power Co. 3pp 18457 179 24X Fiche 30-269, 83/04/20, 02084-03084
- --8305130276 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612) * Office of Nuclear Reactor Regulation, Director 03/04/20 1p 18457 182 24X Fiche 50-269,83/04/20,8305130294
- --8304070286 TER-C5506-374/375/37
 "Control of Heavy Loads (C-10), Ocones Nuclear Power Station
 Unite 1.2 & 3," technical evaluation rept
 ROBERTS.8 Franklin Institute/Franklin Research Center
 NRC-03-Bj-130 TAC 08065 83/03/31 CLEMENSON,F NRC No
 Detailed Affiliation Given 28pp 18457 183 24X
 Fichs 50-249,83/04/20,8305130294
- 8305170118 NUREO-0897 FC
 CONTAINMENT EMERGENCY SUMP PERFORMANCE Technical Findings
 Related To Unresolved Safety Issue A-43
 BERKIT, A W Division of Bafety Technology 83/04/30 129pp
 18493 007
- B305170123 NUREG-0869 FC
 USI A-43 RESOLUTION POSITIONS
 SERVIZ: A W Division of Safety Technology B3/04/30 74pp
 18496 023
- 8305170594 Requests attendance at 830519 public meeting in Betheada.MD to exchange info on two aspects of possible ATMS requirements for final ATMS rule. (Generic Issue A-09) ERNST.M L Division of Risk Analysis 83/04/28 KNUTH.D F KMC, Inc. 4pp 18495 024
- 8305230255 Summarizes info supporting position that postulated pipe breaks in RCB primary loop piping should be eliminated from structural design basis of all Westinghouse plants Testing program per Generic Issue A-Z documented RAHELE P Westinghouse Electric Corp NS-EPR-2768 83/05/11 VDLLMER.R H Division of Engineering 2pp 18537 139
- 8305230276 Forwards "Control of Heavy Loads (C-10) Heddam Neck Plant," draft technical evaluation rept Response within 60 days af receipt of itr requested CRUTCHFIELD.D Operating Reactors Branch 5 LS05-83-05-044 B3/05/19 COUNSIL.H 0 Connecticut Yankee Atomic Power Co 2pp 18539 006 24X Fichs 50-213.83/05/19.8305230276
- --83052302E4 TER-C5506-358 DRFT

 "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept

 BUMBERGER C, AHMED:N Franklin Institute/Franklin Research Center NEC-03-81-130 83/02/15 CLEMENSON:F NRC No Detailed Affiliation Olven 35pp 18539 000 24X Fiche 50-213.83/05/19.8305230276
- B305240516 First set of interrogatories on pressurized thermal shock contention Certificate of Svc ent] Related correspondence LEWIS.M I Lewis, M B3/05/19 Office of the Executive Legal Director ip 18571.175 24% Fichs 30-352.83/05/19.8305240516
- 8305250305 Requests info on why resolution of Unresolved Issue A-17 will precede Unresolved Issue A-47 since both items are closely related Response requested by 830517 using std question & answer format FUNCHES.J L. Planning & Program Analysis Staff 83/05/11 SPEIS.T P. Division of Safety Technology 2pp 18594-356

- --8305250308 Staff requirements memo re 830427 midyr program review on info requested on number of people & dollars necessary to handle Waste Mgt Act as well as questions Chairman Pailadino will be addressing by separate memo CHILK.S J Office of the Secretary of the Commission M830427. 83705/06 DIRCKS, W J Office of the Executive Director for Operations 3pp 18574 358
- B305260270 Commits to resolution of three open items re NUREO-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable RMBAK.B Commonwealth Edison Co 6611N B3/05/19 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 1p 18625 354 24X Fiche 50-227, B3/05/19, B305260290
- 8305260294 Forwards response to 830403 draft technical evaluation rept re-control of heavy loads Phase I review complete Util position accepted per 830318 telcon ASN.R E Baltimore 0as & Electric Co 83/05/24 EISENHUT, D. Q Division of Licensing 2pp 18625 161 24X Fiche 50-317,83/05/24, 8308280294
- 8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Westinghouse rept STEWART. W L Virginia Ejectric & Power Co 322 83/05/20 DENTON. H R Office of Nuclear Reactor Regulation, Director 1p 18637 325 24X Fiche 30-338,83/05/20,8305270220
- 8305310240 Requests add1 info for control of heavy loads review. including info open items for updated "Control of Heavy Loads"

 CLARK. R A Operating Reactors Branch 3 83/05/17 JONES, W. C Omaha Public Power District 2pp 18662 180 24X

 Fiche 50-285,83/05/17,8305310240
- --8309310241 TER-C5506-356 DRFT
 "Control of Heavy Loads (C-10), Gmaha Public Power District,
 Fort Calhoun Station," updated draft technical evaluation
 rept
 VDSBURY,F, BDMBERGER,C, SARGENT,I H Franklin Institute/Franklin
 Research Center NRC-03-81-130, TAC 07991 82/11/29
 CLEMENSUN,F NRC No Detailed Affiliation Given 52pp
 18662 182 24X Fiche 50-285,83/05/17,8309310240

14E INSPECTION AND ENFORCEMENT

- 8109040024 PND-II-Bi-032A on Bi0715, while performing reactor vessel insp w/remote video cameras, loose parts discovered in bottom of vessel farts identified as missing from internal vessel structures Caused by corrosion fatigue BRYANT, J C Region 2, Atlanta, Office of the Director (81/03/01) BI/08/07 1p 18326 300 24X Fiche 30-269, 81/08/07, 8109040024
- 8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " SVc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp, 18308 319 24x Fiche 50-000.83/03/21,8212040385
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/04/15 Consolidated Edison Co. of New
 York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021
- B303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl.
 JGRDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383-089 24X Ficher 50-000,83/04/22,8303040023.
- 8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025
- B303040026 IE Info Notice B3-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/04/28 Cansolidated Edison Co of New York, Inc 115pp 18382 047. R4X Fiche 30-000,83/04/28,8303040026
- 8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp, 18382 165 24X Fiche. 50-000,83/04/28,8303040027.

- 8303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breaters " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028
- 8303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering UQRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidate Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.
- 8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24% Fiche 50-000.83/05/06.8303040033
- 8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines "Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24% Fiche 50-000,83/05/11,8303040034
- 8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " 303040040 IE INFO NOVICE OF U.S.

 BVc list encl

 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/19 Consolidated Edison Co of New
 York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040
- 8393040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil" Svc list encl
 JORDAN,EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24x Fichs 50-000,83/05/26,8303040046
- B304110196 PNO-I-B3-025 on B30330 only four of five packages containing radioactive matl received by group carrier Missing package contains 330 mCi Xe-133 encased in two lead pipes Search DENNIS, N , GODY, A. T Region 1, Office of Director 83/04/04 ip 17918 011
- 8304120582 PNO-IV-83-014A on 830325, worker received apparent 30-40 rem whóle body exposure Addl blood studies being conducted but no apparent symptoms observed from exposure Investigation continuing.

 EVERETY: R. J Region 4, Office of Director B3/04/07 1p 17929 237
- 8304280139 PNA-II-81-042 re mailgram sent on or about 810501 by union at Tennesses Nuclear Specialties, Inc to State of TN alleging unsafe working conditions at Jonesboro, TN plant Licenses cited for inadequate controls over airborne U.
 WOODRUFF,R.L., QIBSON,A Region 2. Atlanta, Office of the Director
 (81/03/01). 81/06/11 ip 18621 190
- 8304280299 PNS-II-80-030 on 801104, bomb threat received from unknown famale caller Const site not evacuated State of NC & local law enforcement agencies notified HALL. B. L. HCOURED Region 2. Atlanta, Office of the Director 80/11/04 p 18255 330 24X Fiche 50-400.80/11/04.8304280299
- 8305020183 PNO-V-83-018 on 830421, util received ltr from C-E informing of error in equivalent voltages corresponding to subpoints associated Wisteam generator high delta pressure trip function Corrective action being developed SISHOP, T W Region 5. Office of Director 83/04/25 ip 18277, 275 24X Fiche 50-361, 83/04/25, 8305020183
- 8305020252 EN-83-028 on 830503 notice of violation & proposed 305020252 EN-83-028.on 830503.notice of violation & proposed imposition of civil penalty in amount of \$10,000 to be issued. Action based on failure to control access into protected & vital areas & unauthorized entry ROBAND.R. Director's Office. Office of Inspection and Enforcement. 83/04/28. 1p 18277 277 24X Fiche 50-295.83/04/28.8305020252
- 8305020271 PNO-III-83-031A on 830421 piece of solid radioactive math appearing to be U metal found in unsecured shed behind residence in Waterford.MI.Matl placed in shipping container & sent to Univ of MI for interim storage SRENIAMBKI.D. MILLER, J. Region 3. Office of Director 83/04/25 19 18277.250

- B305020337 PNO-1-83-038A on B30427.rectrculation loop A riser exam completed One weld in each of two risers had crack indications Data forwarded to GE for more detailed analysis Licensee addressing repair method & impact on outage BLOUGH, MCCABE.E Region 1. Office of Director 83/04/27 ip 18277 134 24x Fiche 50-278.83/04/27.8305020337
- 8305020457 PNS-1-83-009 on 830427, bomb threat phoned in by unidentified male caller Evacuation initiated Search conducted w/negative findings Normal operations resumed Authorities notified MADDEN.W. OODY, A T. JUYNER, J H. Region 1, Office of Director 83/04/27 1p 18283 310 24% Fiche 50-219,88/04/27,8305020459
- 8305020511 PNO-III-83-032 on 830426, scram circuitry failed to operate properly when made switch moved from refuel position to shutdown position Caused by three loase wires in rectifier bridgs JORDAN,M , SHAFER,W Region 3. Dffice of Director 83/04/27 ip 18281 253 24x Fiche 50-331.83/04/27.8305020511
- 8305030094 PNO-I-83-040 on 830428, protesters arrived at north gate Gate closed & access established through south gate No press release planned CONTE.R., KEIMIG.R. Region 1. Office of Director 83, 18300 179 24% Fiche 50-289.83/04/28,8305030094 B3/04/28 24X Fiche 50-287, 83/04/28, 8305030074
- 8305030118 PNO-I-83-038 on 830425, three 1-inch long stial indications & one circumferential indication in heat affected zone of recirculation pump riser discovered Caused by intergranular stress corrosion cracking BLOUGH, MCCABE Region 1. Office of Director 83/04/26 ip 18308 187 24% Fiche 50-278,83/04/26,8305030118
- 8305030256 PND-11-83-030 on 830428 controlled shutdown begun due to steam generator tube leak which increased from 0 i to 0 308
 gpm Licensee plans to keep plant out of eve for 3 wts to
 repair leak & conduct eddy current testing
 HARDIN.A K , VERRELLI.D M Region 2, Office of Director 83/04/28
 1p 18300 038 24X Fiche 50-261.83/04/28.8305030256
- B305030294 PNS-I-83-008 on B30424, security officer overheard voices from storage trailer in protocted area Officers apprehended four contractor employees exiting trailer rear window Search revealed marijuana cigarette Employees suspended MCKEONN, L. GODY, A.T. JOYNER, J.H. Region 1. Office of Director B3/04/25 1p 18297 144 24% Fichs 50-286, 83/04/25, 8305030294
- 8305030313 PNS-V-83-005 on 830426, region dispatched reactive insp team to review findings & status to date of licensee investigation of safety significance of recent vandalism event on 830419 involving gauges in coolant pipe MCOUEEN.A D. NORDERHAUG.L R Region 5. Office of Director 83/04/27. 1p. 18297 069 24Y Fiche 50-275.83/04/27.8305030313
- 8305030374 PND-II-83-031 on 830429.Unit 1 cancellation announced Caused by lower than anticipated growth in customer demand FOR DOMER for power IONATONIS.A , DANCE,H C Region 2, Office of Director 2pp 18305 302 24x Fiche 30-491,83/04/29,8305030374
- 9305030405 EN-93-027 on 830503, notice of violation & proposed imposition of civil penalty in amount \$40,000 to be issued for licensee failure to perform evaluations to ensure dose atds for workers exposed to radiation not exceeded FALACK, E. AXELRAD. J Director's Office of Inspection and Enforcement 83/04/28 ip 18304 312 24X Fiche 50-250,83/04/28. 8305030405
- 9305030450 PND-1-83-041 on B30425, while closing reactor trip breaker 18 to test newly installed reactor manual trip switches, breaker would not latch in closed position Caused by unattached coil spring at latch mechanism end LAZARUSH W. KEINIG.R Region i. Office of Director 8: 18306.249 24% Fiche 50-272.83/04/28.8305030450
- 9305030459 PN9-1-83-010 on 830427. Bechtel safety representative AUSUSU439 PAM-1-83-010 on 830427. Bechtel safety representative received telephone call that bomb located in reactor.

 Search of reactor bldg conducted w/negative results Police notified No press release planned MCKEOHNLL , KUSHNER, W , JOYNER, J Region 1, Office of Director 83/04/28 ip 18294 190 24X Fiche 50-354.83/04/28,8305030459
- 8305030469 EN-83-027 on 830505, notice of violation & groposed imposition of civil penalty in amount of \$4,000 will be issued Action based on violation re licenses failure to conduct adequate survey, causing employee overexposure FLACK.E. AXELRAD, J. Region 3, Office of Director 83/05/018308 245 83/05/02 1p

- 8305030534 PND-I-83-039 small fire occurred beneath auxiliary boiler A located in turbine bldg Caused by small amount of oil on concrete pad Fire extinguished using hand eitinguisher CONTER, KEIMIG, R Region 1, 0ffice of Director 83/04/26 1p 18308 190 24X Fiche 50-289,83/04/26,8305030534
- 8305040192 PNA-83-007 on 830303,100 uCi I-125,3 mC1 T1-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town, NY Packages not found Press release may be issued CAMPBELL, M Region 1. Office of Director 83/04/04 ip 18326 353
- 8305040201 PNA-83-007A on 830303,100 uci 1-123,3mCi T1-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town:NY Package of I-125 found on 830315 in home of suspect CAMPBELL-M Region 1, Office of Director 83/03/15 ip
- 8305040445 PND-III-83-033 on 830428, contract health physics technician observed w/small vial containing white powdery substance Preliminary test identified substance as cocaine Individual denied access to site CHRISTOFFER. G., CREED. J., MILLER. J. Region 3, Office of Director 83/04/27 ip 18321 277 24X Fiche 50-331.83/04/27.8305040445
- 8305050189 PND-1-83-042 on 830428, during packaging of waste, employee ruptured plastic bag & spread Pu-238 contamination in lab Employee clothes & shoes discarded Employee decontaminated Cleanup will start 830502 OLENN.J. KINNEMAN.J. Region i, Office of Director 83/04/29 ip 18342-258
- B305050193 PND-I-83-043 on B30430.Troxler gauge 34-11-B, containing approx 40 mCi Am-241 damaged at const site Caused by accidentally cracking gauge case u/backhoe bucket Hipes taken & analyzed Cauge shipped to manufacturer for repair LADUN, R. XINNEMAN, J. Region 1, Office of Director B3/05/02 ip 18337 135
- 8305060387 PNO-I-83-045 on 830503, shutdown initiated due to containment pressure increase to 0 6 ps; & unidentified containment leakage of 5 4 gpm Recirculation pump cooling water leakage noted MCCABE.E. KEIMIG.R Region 1. Office of Director 83/05/03 ip 18343 145 24X Fiche 50-277,83/05/03,8305060387
- 8303040530 FND-I-83-044 on 830303, effect of continued feedwater flow due to failed open feedwater regulating valve incorporated per add1 questions re lifenses response to IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break "ARCHITZEL, MCCABE Region 1. Office of Director IEB-80-04 83/03/03 1p 18347 292 24X Fiche \$0-317,83/05/03,8305040530
- B305060558 PND-I-B3-045A on B30503, drywell entry identified packing leak on recirculation pump discharge header cross connect motor operated valve MD-65A Cause not stated Region I will respond to media inquiries

 MCCABE
- 8305060580 PND-V-83-019 on 830502.6 5 Richter scale earthquake occurred approx 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected KIRSCH, D F Region 3. Office of Director 83/05/03 [p 18349 057 24X Fiche 50-275,83/05/03,8305060880
- 8305090184 EN-83-031 on 830510, notice of violation & proposed imposition of civil penalties in amount of \$40,000 will be issued to util Action based on Tech Spec limiting condition for operation violation re secondary containment integrity BARBER.C., AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/05 ip 18364 001 24X Fiche 30-271,83/05/05,8305090184
- B305090224 EN-B3-030 on B30509, notice of violation & proposed imposition of civil penalty in amount of \$40,000 issued to literase Action based on serious weaknesses in internal & external dose monitoring & procedural compliance FLACK, E. AXELRAD, J. Director's Office. Office of Inspection and Enforcement B3/03/04 ip 18363 349 24X Fiche 50-280,83/05/04,83/0390224
- 8305070397 EN-83-032 on 830505, notice of violation & proposed imposition of civil penalties in amount of \$850,000 to be issued Action based on violation of Tach Spec requirements re reactor trip breaker failure KLINGLER.G., AXELRAD.J Director's Office, Office of Inspection and Enforcement 83/05/05 ip. 18363 339 24% Fiche 50-272,83/05/09,8305090397

- 8305100004 PNS-I-83-011 on 830504, security officer received bomb threat on inside plant telephone line from male caller Search initiated No bomb found Call considered hoax MCKECNN, GODY, JOYNER Region 1. Office of Director 83/05/04 ip 18377 251 24X Fiche 50-272,83/05/04.8305100004
- 8305100094 PNS-V-B3-006 on B30504, article in Tri-City Herald erroneously quoted util spokesman J Britton as saying 1,700 or 1,800 craft workers will be asked to take vacations during 830705-15 or be laid off Util will clarify MORTENSEN.H P, NORDERHAUG,L R Region 5, Office of Director B3/05/05 lp 18377 261 24X Fiche 50-513,83/05/05,B305100094
- 8305100098 PND-II-83-034 on 830504 licensee issued news release re inoperability of two auxiliary feedwater pumps on 830419 Caused by valves inadvertently closed on 830414 UULIAN.C A , LEWIS.R C Region 2, Office of Director 83/05/05 2pp 18377 255 24X Fichs 50-250,83/05/05.8305100098
- 8305100258 PNO-I-83-046 on 830428, diesel generator iC tripped off bus during i h test Caused by biofouling in avc water sys Licensee plans comprehensive program of svc water sys chlorination & insp to evaluate extent of biofouling NORRHOLM, J. TRIPP.L., KEIMIG.R. Region 1. Office of Director 83/05/04 2pp 18373 317 24X Fiche 50-272,83/05/04,8305100258
- 8305110258 PND-I-83-047 on 830504, contractor employee entered roped-off area for radiographic exams of pipe welds & received approx 40 mrem dose No overexposure identified Industrial radiography suspended pending completion of evaluation HCCANN, MCCABE Region I. Office of Director 83/05/05 ip 18378 270 24x Fiche 50-388,887/05/05.8305110258
- 8305110262 PNO-II-83-036 on 830508 unit achieved initial criticality w/o incident Actual parameters in close agreement w/ predicted conditions NEUFELT.O M . IONATONIB, A Region 2. Office of Director 83/05/07 1p 8393 158 24X Fiche 50-370,83/05/09,8305110262
- 8305110297 PND-I-83-04B on 830429, potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds, involving procedural violations during magnetic particle exam CERNE, A, CALLO, R. Region i, Office of Director 83/05/06 ip 18393 333 24% Fiche 30-443,83/05/06.8305110299
- 8305110399 PNO-II-83-035 on 830507, fire detected in circuitry of one of three component cooling water pumps Licenses declared alert Caused by faulty relay Relay replaced & pump restored to operability
 BUTCHER,R C , CANTRELL,F B Region 2, Office of Director 83/05/09 ip 18406 189 24X Fichs 50-395,83/05/09,8305110399
- B305110437 PN9-I-83-012 on B30305, licensee informed Region 1 that contract health physics employee of Inst for Resource Mgt arrested on suspected multiple federal drug-related charges Individual access to site voided as of B30505 MCKEONN, BAILEY, GODY Region 1, Office of Director B3/05/05 ip. 18405 087 24X Fiche 50-286,83/05/05,8305110439
- 8305120412 PND-I-83-0458 on 830503, Ultrasonic testing conducted on Sample 2 recirculation riser welds & one RHR wald on Unit 2 to determine if Unit 3 crack indications exist on Unit 2 RHR shawed cracks on both pipe & elbow side 8LOWOH, MCCABE Region 1. Office of Director 83/05/09 1p 18431 IS3 24X Fiche 50-277, 83/05/09, 8305120412
- B305120434 PN9-1-83-013 on 830502, Lower Alloways Creek, NJ, police dept informed licensee of planned, peaceful demonstration to protest facility restart scheduled for 830508 No press release planned MCKEDWNL 1, 00DY, A T , JUYNER, J Region 1, Office of Director 83705706 ip 18431 i31 24X Fiche 50-272, 83705706, 8305120434.
- 8305130139 PND-II-83-032 on 830501, contractor employee suffered broken arm, fractured pelvis & possible skull fracture in machine shop accident Caused by cotton glove caught by valve stem pulling person into lathe w/conteminated valve ROGGE, J F , DANGE-H C Region 2, Office of Director 83/05/02 2pp 18437 277 24X Fiche 50-321,83/05/02,8305130138
- 8305130142 PNO-II-83-038 on 830510, safety injection pumps inadvertently actuated during heatup in preparation for restart Caused by loss of vital dc electrical bus Damaged batteries replaced JENISDN.K M. JULIAN.C.A. Region 2, Office of Director, 83/05/10 ip 18438 131 24X Fiche 50-280,83/05/10,8305130142
- B305130165 PND-III-B3-034A on B30507, insp performed at refinery facility due to damage caused by fire on B30507 Radiation survey performed on nuclear gauge involved in fire datermined gauge intact w/shutter remaining open MIEDEMAN, D. MILLER, J. Region 3, Office of Director B3/05/10 ip 18438 ii5

- 8305130173 PNO-II-83-037 on B30510 unusual event declared per mmergency plan after ventilation sys stopped operating in bidg where high enriched U recovered from scrap Caused by electric motor & backup blower CORYELL 9 P. GIBSON: A F. Region 2. Office of Director B3/05/10 ip 18437 205
- 8305130186 PND-II-83-033 on B3050; inadvertent safety injection occurred Caused by spurious signal during tests of steam generator D.Lou power OL received on B30303 & initial criticality planned during wk NEJFELT.6, IGNATONIS.A Region 2. Office of Director B3/05/02 ip 18440 049 24% Fiche 50-370.83/05/02.8305130186
- 8305130187 PNO-V-83-022 on 830509, while performing add1 ultrasonic exams. RCB piping in eras of one weld determined less than min wall thickness specified by code Caused by welds being ground smooth during original preservice exam KTRBCH.D F Region 5. Office of Director 83/05/11 ip 18439 347 24X Fiche 50-275.83/05/11.8305130187
- 8305160009 PNU-V-83-021 on 830429, lask discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity

 KIRSCH, D F Region 5. Defice of Director 83/05/10 ip
 18456-081 24x Fiche 50-275.83/05/10.8305160009
- 8305170557 PNO-III-83-034 two nuclear gauges, containing 150 mCi Cs-137 to 300 mCi Cs-137, involved in facility fire, Cause of fire not stated No evidence of contamination found WIEDEMAN,D, MILLER,J Region 3, Office of Director 83/05/09 ip
- B305190072 PNO-I-83-051 on B30516, vehicle ran stop sign & struck licensee-ouped van carrying radioactive mati Package not damaged & no contemination found Package returned to site for repackaging.
 THOMAS, CONNER Region 1, Office of Director B3/05/16 1p 18502 068 24x Fiche 50-217,83/05/16,6303190072
- B303190079 EN-B3-034 on B30520, notice of violation & proposed imposition of civil penalty in amount of \$40,000 to be issued Action based on violation re operating reactor w/one train of HPSI incapable of automatically starting BARBER, G. AXECRAD, J. Director's Office. Office of Inspection and Enforcement B3/05/17 ip 18502 069 24X Fiche 50-309,83/05/17,870.519072
- B305190161 PNO-III-83-036 bicassays & in vivo count of licensee worker indicated potential thorium uptake Cause unknown No potential exposure sources identified Addl medical tests scheduled for B30516 OREGER, L. R., MILLER, D. E., PAPERIELLO, C. J. Region 3, Office of Director B3/05/13 ip 18502 238
- 8305190233 PNO-III-83-035, on 830511. licensee stopped work on new installation of pipe-whip restraints on safety-related piping per 830513 confirmatory action itr Restraints installed w/o adequate procedures or GC insp program DANIELBON, D. W. LITTLE, W. B. Region 3. Office of Director 83/05/13 ip. 18501 318 24X Fiche 50-454, 83/05/13, 8305190233
- 8305190336 PNO-I-83-050 on 830513, 100 gallons of contaminated water discharged from auxiliary bldg sump onto ground between auxiliary & fuel handling bldgs Cause under investigation No offsite release occurred Contaminated soil removed.

 8UNMERS.R., TRIPP.L. Region 1, Office of Director 83/05/13 ip. 18500 233 24X Fiche 50-272,83/05/13,8305190336
- B305200344 PND-IV-83-019 on 830517, indications of intergranular stress corrosion cracking in heat-affected zone of welds in RGS identified Data forwarded to GE for detailed analysis.RCS loops inspected DUBOIRD. D. WESTER
- B305200430 PNO-II-83-040 on 830515, two util employees & one former employee arrested for cocaine & martjuana possession Arrest occurred offsite Employees not involved in licensed operator activities.

 LANDIS, K D , DANCE, H. C Region 2, Office of Director 83/05/17, 1p 18517-150 24X Fiche 50-335,83/05/17,8305200430
- B305200497 PNO-I-B3-049 all licensee commitments required for restart completed Actions to essess & mitigate svc water biofouling in support of plant heatup anticipated to occur on 830518 completed NORRHOLM, L. COLLING, 8 Region 1, Office of Director B3/05/17 ip 18514 032 24X Fiche 50-272, B2/05/17, B305200497

- 8305200588 PNO-II-83-039 two intergranular stress corrosion cracks found on recirculation line end cap weld Cracks found during ultratonic insp per IE Bulletin 83-02 Further weld insps planned BLAKE, J J. BUTCHER, R C. Region 2, Office of Director IEB-83-02 83/05/16 1p 18514 247 24X Fiche 50-259, 83/05/16, 8305200588
- 8305240002 PNO-III-83-037 on 830509. Region III radiation specialist learned that main steam line noble gas monitors not yet installed per 830314 commitment date Ofc of investigation investigating failure Monitors to be installed by mid June LOVENDALE, P. PAPERIELLO, C. Region 3, Office of Director 83/05/18 p 18549 138 24X Fiche 50-266.83/05/18.8303240002
- 8305240439 EN-83-035 on B30520 notice of violation & proposed imposition of civil penalties in amount of \$4.000 issued to licensee Action based on one violation involving falsification of radiation survey records KLINGLER, G. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/20 ip 18572 337
- 830525023B PNO-I-83-052 on 830520, plant went critical for first time since 830225 Reactor startup & required reactor trip breaker testing completed within 24 h Power ascension to 100% expected over next several days NORRHOUML . JACOBS.R. GREENMAN.E Region 1, Office of Director 83/03/23 ip 18592 358 24% Fiche 50-272,83/05/23,8305250238
- 8305250537 PNO-II-83-04i on 830520 unusual event declared 1 h after process ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by failure of electric motor Employees evacuated No contamination noted KANLE, J B. (JUBON, A F. Region 2. Office of Director 83/05/20 1p 18588 224
- 8305260314 PNO-III-83-038 on 830519, reactor placed in hot shutdown to investigate & repair steam leak in drain line between moisture separator & preheater in nonsafety-related turbing sys Addl steam leak found in turbine control valve flange. WALKER,R D . SHAFER,W D Region 3, Office of Director 83/05/20 ip 18625 198 24% Fichs 50-263,83/05/20,8305260314
- 8305270115 PNS-V-83-007 on 830520, while performing security duties, upon approaching truck being offloaded, security officer observed individual throwing article into cab Investigation revealed cocaine in small glass container Police notified SCHAEFER, D. H. NORDERHAUG, L. R. Region 5. Office of Director 83/05/23 ip 18638 165 24% Fiche 50-312,83/05/23,8305270115
- 8305270152 PNG-III-83-039 on 830323.util employee entered protected area through open & unmonitored entrance to receive whole body count individual escorted out of area Region III will investigate.

 GREED, J. HIND, J. Region 3. Office of Director 83/05/23 ip 18638 i59 24X Fiche 50-255, 83/05/23, 8305270152
- B3053i0174 PND-II-83-042 on B3052i, employee injured while pressurizing inflatable. bladder-like pipe plug Rupture of bladder caused employee left hand to hit adjacent piping resulting in cuts & broken bones Hand decontaminated IGNATUNISA, a GIBBON.A F Region 2. Office of Director B3/05/23 2pp 18652 247 24X Fiche 30-357.83/05/23.8305310174

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- B305020342 Submits requested info re generic QA problems in equipment qualification industry Problems include failure of grantizations to include 10CFR50, App B & Part 21 requirements in purchase orders or contracts.

 BANQART, R L Division of Vendor & Technical Programs B3/04/22 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) Spp 18277 073
- B305030704 Forwards comments on NRC reliability program plan repts per B30210 request Foreign experience in reliability programs should be considered IPPOLITO T A Operating Reactors Assessment Branch B3/04/IB THADANI, A C Reliability & Risk Assessment Branch. 2pp 18309 10
- #305040596 "Performance Tests of Commercial Personnel Monitoring Svcs."
 740723-750123
 NICHOLS,L L., NEWTON.C E. Commerce, Dept of, National Bureau of
 Standards NICHOLS,L L Battelle Memorial Institute, Pacific
 Northwest Laboratory. 75/01/23 18pp i8336 080
- ---8011180782 BNML-2159
 "Test of Performance of Personnel Dosimeters"
 NICHOLS: L. Battella Memorial Institute, Pacific Northwest
 Laboratory, NRC-1 77/04/30 37pp 18336 099

- 8305070204 Responds to 830324 memo requesting assistance in updating safeguards program plan for FYB3-87 Standardization & Special Projects Branch responsible for interface w/NM99 on reactor safeguards matters EISENHUT.D O Division of Licensing 83/04/21 BURNETT.R F Division of Bafeguards 2pp 18381 iil
- 8305090279 Responds to 830304 invitation to attend Natl Organization of Test Research & Training Reactors 831020-21 meetings WJ Direks & V Stello unable to attend due to prior commitments, however. H Denton, Director of NRR, will attend DIRCKS.W J Diffice of the Executive Director for Operations 83/03/02 CLARK.L Massachusetts Institute of Technology 3pp 18381 071
- --8305070270 Requests designation of appropriate NRR personnel to attend & prepare response to L Clark invitation to attend Natl Organization of Test Research & Training Reactors annual meeting on 831020-21 in Cambridge MA DIRCKS,W Office of the Esecutive Director for Operations 83/04/11 DENTON,H Office of Nuclear Reactor Regulation, Director ip 18381 073
- --8305090315 Extends invitation to attend Natl Organization of Test
 Research & Training Reactors 831020-21 annual meeting at
 MIT Agends for Oct 1982 meeting & list of attendees encl as
 indication of program format & content
 CLARK, L. Massachusetts Institute of Technology 83/03/04
 DIRCKS, W. Office of the Executive Director for Operations 10p;
 18381-074
- 8305090295 Concurs in 830329 statement of work re development of data base for 10CFR30 55(e) & Part 21 defictioncy reporting DENTON.H R Office of Nuclear Reactor Regulation, Director 83/04/22 HELTEMES,C J Director's Office 2pp 18381 241
- --8304i40328 Requests comments on development of data base for managing & analyzing info reported under 10CFR21 & 10CFR50 55(e) Data could provide info re capability to determine similarities or trends in reported deficiencies
 HELTEMES, C. J. Director's Office 83/03/29 NRC No Detailed Affiliation Given 3pp 1838i 243
- 8305120607 Forwards documentation re LERs on reactor trip breaker failures between 800101 & 830222.per 830329 request Many trip breaker failures unreported when occurring during modes when operability not required by Tech Specs DENTON.H Office of Nuclear Reactor Regulation, Director. 83/04/28 HELTEMES.C J Director's Office 2pp 18440 127
- --8212070092 Discusses review of LER failure data for reactor protection sys electrical & mechanical components No basis found to support industry intuitive guess that ratio of electrical to mechanical failures is 10 to 1

 KENDALL,R Instrumentation & Control Systems Branch 82/11/17

 PYATT,D W Reactor Risk Branch 53pp 18440 129
- --8305120613 Summary of 820908 operating reactor events meeting MIRAGLIA.F J Assistant Director for Safety Assessment 82/09/16 EISENHUT.D C Division of Licensing 11pp 18440 185
- --8304040591 Requests documentation or other info re reviews or analyses of reactor trip breaker failure repts performed 800101-830222 by 830411 HELTEMEB, C. J. Director's Office 83/03/27 HAYNES, R. C. Region 1, Office of Director O'REILLY, J. P. Region 2, Office of Director KEPPLER, J. G. Region 3, Office of Director Zpp 18440 196
- --8304010159 Discusses study of two issues re implications of reactor trip failure on NRC program for collection & analysis of operational experience Preliminary outline for study encl Preliminary draft of study will be sent by 830401
 HELTEMESIC J Director's Office 83/03/28 MATTEON, R J Salem Oeneric Implications Task Force 5pp 18440 198
- B305190356 Notifies that JE Olenn will be available for meeting on B30516 to discuss recent application for Co-60 facility.per B3040B request ALLAN,J M Region 1, Office of Director B3/05/04 CAMPBELL,E Andover Township, NJ 2pp 18500 025
- --8305190361 Requests NRC representative attend meeting of planning board & other municipal agencies to discuss proposed Co-60 facility CAMPBELL, E Affiliation Unknown B3/04/08. HAYNES, R C Region is Office of Director. ip 18500-026

- 8305230511 Forwards "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand" Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls HELTEMES,C J Director's Office 83/04/29 DEMION,H.R Office of Nuclear Reactor Regulation, Director 2pp 18541 277
- --B305230519 Forwards "Failures of Class IE Bafety-Related Bwitchgear Circuit Breakers to Close on Demand " Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls HELTEMES.C J Director's Office 83/04/29 WILKINSON.E P Institute of Nuclear Power Operations 2pp 18541 279
- --8305230524 Forwards "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand." Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls HELIEMES.C J Director's Office 83/04/29 ROSSIN,D Nuclear Safety Analysis Center ip 18541 281
- --B305230531 "Failures of Class IE Bafety-Related Switchgear Circuit Breakers to Close on Damand " CHIRAMAL.M Reactor Operations Analysis Branch, AEGD/C301, B3/04/30 30pp 18576-356
- B30525029B Notification of B30517 meeting w/HAFA Intl Corp.American Nuclear Insurance & TECo in Bethesda.MD to discuss application of acoustic emission testing as alternative to volumetric insp method of inservice insp of components VISBING.O Operating Reactors Branch 4 B3/05/09 BTOLZ.J Operating Reactors Branch 4 2pp 18594.361
- 8305260149 Responds to 830413 ltr re deletion of nonradiological water quality-related requirements from OLs NRC Mar 1983 actions consisted of issuance of license amends to delete requirements from OLs for facilities w/NPDE8 permit EISENHUT.D G Division of Licensing 83/05/10 DREY,L A Affiliation Unknown 1p 18648 121
- --8304180420 Requests description of NRC actions taken in Mar 1983 re deletion of nonradiological water-quality-related requirements from OLs Also requests info re changes made in requirements on radiological releases DREY.K Affiliation Unknown 83/04/13 Office of Nuclear Reactor Regulation, Director, ip 18648 122
- 8305260151 Forwards DOE responses re review of SIC reactor prototype, Windsor Site, for review & comment Reply requested by 830523 since DOE const mods have already begun at site W/o encis
 THOMAS.C O Standardization & Special Projects Branch 83/05/11
 LEAR.G. Structural & Geotechnical Engineering Branch, ip. 18648 120
- 8305260378 Speech entitled "NRC Views on Svc Suppliers Roles, Qualifications & Acceptability," presented at 830519 conference on nuclear svcs business in 1980s in Washington, DC BTELLO,V Regional Operations & Generic Requirements 83/05/19 5pp 18647.251
- NUREO NUREO REPORTS AND RELATED CORRESPONDENCE
- B303280319 Forwards order confirming licensee commitments on post-TMI-related issues Order based on commitments contained in util responses to NRC Generic Ltrs B2-05 & B2-10 STOLZ, JF Operating Reactors Branch 4. GL-B2-05 83/03/14 HANCOCK, JA Florida Power Corp 3pp 17713 234 24X Fichs 50-302, B3/03/14, B303280319
- --B303280325 Order confirming licensee commitments on post-TMI-related issues
 PURPLE,R.A Assistant Director for Licensing 83/03/14,
 Florida Power Corp. 10pp. 17713 237 24X Fiche 50-302,83/03/14,
 B303280319
- 8304120027 Forwards revised order confirming licenses commitments on post-TMI-related issues, correcting info re implementation schedule for Item II B 3, "Post-Accident Bempling."

 STOLZ, J F Operating Reactors Branch 4 B3/03/30 BECKHAH, J T Georgia Power Co. 4pp 17957 320 24X Ficher 50-321, 83/03/30, 8304120027
- --8304120042 Order revising schedule for submittal of info re Item II 8.3. "Post-Accident Sampling." from 830401 to 830701 PURPLE.R A. Division of Licensing OL-82-05 83/03/30. Georgia Power Co 10pp 17957 324 24X Fiche 50-321,83/03/30. B304120027

- 8304180548 Forwards proprietary MCAP-8200, Rev 1, MCAP-8301, MCAP-8302, MCAP-8821, draft responses to questions on MCAP-10079 & related info re new small break evaluation model per NUREG-0737, Item II K 3 30 Encls withheld (ref 100FR2 790) RAME, E P Westinghouse Electric Corp NS-EPR-2746 83/04/12 THOMAS, C O Standardization & Special Projects Branch 2pp 17997 049
- 8305020066 Forwards BER based on review of NURE9-0737, Item III D 3 4, "Control Room Habitability," submitted in 801219 & 821017 ltrs Control room habitability sys acceptable CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-04-074 83/04/27 VANDEWALLE, D J Consumers Power Co App 18276 236 24X Fiche 50-255,83/04/29,8305020066
- --8207080528 Notifies that control room meets requirements of SRP 2 2 1 2,2,2 2 3 & 6 4 & General Design Criteria 4 & 19 Conclusions based on present plant sys & presumes implementation of effective HVAC mods by licensee HURPHY,D W Battelle Hemorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/24 HULMAN,L Q Accident Evaluation Branch 2pp 18276 242 24X Fiche 50-255.83/04/29, 8305020064
- B305020209 Forwards response to NRC 830316 ltr re NUREQ-0737, Item II. K. 3 13, "RCIC Automatic Restart" RCIC sys modified to relocate signal for high reactor vessel water level trip from RCIC turbine trip valve to steam supply valve.

 BAYNE, J. P Power Authority of the State of New York JPN-83-36
 83/04/28 V8SALLO. D B Operating Reactors Branch 2 2pp
 18278 133 24X Fiche. 50-333, 83/04/28, 8305020209
- 8305020359 Forwards supplemental response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys" & NUREG-0737, Item II F 2. M/one oversize drawing. Aperture card is available in PDR GAREY, J. J Duquesne Light Co QL-82-28, 83/04/21 VARGA, B A Operating Reactors Branch i 22pp 18273 198 24X Fiche 50-334 83/04/21,8305020359
- 8305020362 Forwards plant-specific responses to six NRC questions re safety/relief valve testing (NUREO-0737 Item II.D 1).per 821217 request 8afety/relief valve discharge piping utilizes Y quencher w/sparger at discharge pipe exit FIEDLER:P B General Public Utilities - GPU Service Corp 83/04/27 CRUTGHFIELD D Operating Resctors Branch 5 2ipp 18274 058 24 Fiche. 50-219, 83/04/27. 8305020362
- 8305020383 Confirms 830502 submittal date for proposed solution to three remaining open items on NRC review of upgraded auxiliary feedwater sys per NUREO-0737. Item II E I Contractor requested to provide cost estimate for study, RODRIGUEZR J Sacramento Municipal Utility District 83/04/27 BTGLZ.J.F Departing Reactors Brench 4 ip. 18276 313 24% Fiche: 50-312, 83/04/27, 8308020383
- 8303020384 Forwards response to 821115 request for add1 info re NUREQ-0737. Items II E i 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/ii oversize drawings Aperture cards are available in PDR. RODRIGUEZ.R J. Sacramento Municipal Utility District 83/04/28 BTML7.J F Operating Reactors Branch 4 3pp 18283 329 24X Fiche. 50-312.83/04/28.8305020384
- --8305020392 BHNP-20004 (4-76) R3
 Rev 3 to "Auxiliary Feedwater Bys Bys Description"
 * Behoock & Wilcox Co 15-1120580-03 83/04/04 54pg
 18283 332 24X Fiche 50-312,83/04/28,8305020384
- 8305020387 Responds to NRC 830203 & 0330 questions re proposed SRP Amend 19. No need exists to arbitrarily increase initial power to account for uncertainty in power level Errata sheet & transient summary of feedwater controller failure encl. CURTIS:N W. Pennsylvania Power & Light Co PLA-1640 83/04/28 BCHMENGER.A. Licensing Branch 2, 4pp 18276 314 24X Fiche 50-387,83/04/28,8305020387
- B303020388 Responds to B30322 request for add1 info on instrumentation sys for detection of inadequate core cooling (Generic Ltr B2-28) Installation completed & sys currently being tested.

 Btatus of conformance w/NUREO-0737:Item II F 2 encl
 BCHUYLER, J D Facific Gas & Electric Co GL-82-28 83/04/27
 EIBENHUT, D. 9 Division of Licensing. 7pp 18276-329 24X
 Fiche 50-275.83/04/27,8305020388
- 830502042i Forwards add1 info re emergency plan per 821204 request Info addresses Guestion B 4 concerning plant personnel response capability during emergency situation per staffing goals in Suppl 1 to NUREG-0737.

 KOESTER.O L Kansas Gas & Electric Co KMLNRC 83-051, 83/04/29.
 DENTON:H R Office of Nuclear Reactor Regulation, Director 10pp. 18273:100 24X Fiche:50-482,83/04/29,8305020421

- B303020449 Application to amend License DPR-46, changing Tech Specs to incorporate NUREG-0737 items per B30110 Generic Ltr B3-02 PILANT, J M Nebraske Public Power District GL-83-02 B3/04/27 VASBALLO. D B Operating Reactors Branch 2 3pp 18283 173 24X Fiche 50-298,83/04/27,8305020449
- --8305020464 Proposed Tech Specs changes re Generic Ltr 83-02 concerning NUREO-0737 Items

 * Nebraska Public Power District OL-83-02 83/04/27 3pp 18283 176 24X Fiche 50-298.83/04/27,8305020449
- 8305020453 Forwards add1 info per NRC 821210 request re Generic Ltr 82-28 concerning inadequate core cooling sys Procurement of reactor vessel level instrumentation sys completed Sys installation 30% complete EURY-L W Carolina Power & Light Co LAP-83-83 83/04/26 EISENUT.D G Division of Licensing 2pp 18281 222 24X Fiche 50-261,83/04/26,8305020453
- 830502045B Forwards info re NUREO-0737, Item II D i, "Performance Testing of BHR Safety/Relief Valves." per NRC 830104 request Applicability of load combination info to BHR Owners Group generic test rept acceptable RYBAK.B Commonwealth Edison Co 6226N 83/04/27 DENTDN,H R Office of Nuclear Reactor Regulation. Director 18pp 18283 311 24X Fiche:50-254,83/04/27,830502045B
- 8305020538 NUREC/CR-2000 VO2 N3 LICENSEE EVENT REPORT (LER) COMPILATION For Month Of March 1983 # Oak Ridge National Laboratory FIN A-9135 ORNL/N8IC-200 83/04/30 Director's Office 122pp 18285 182
- 8305020547 NUREG/CR-3071
 REVIEW OF WASTE PACKAGE VERIFICATION TESTS Semiannual
 Report Covering The Period April-September 1982
 81DA.0 T. FASTWODD.D. JAIN.H. Brookhaven National Laboratory FIN
 A-3167 BNL-NUREG-51630 83/04/30 Division of Waste Management
 147pp Available at NRC \$6 00 18285 035
- B305030010 Advises that position concerning nonestablishment of backup emergency operations facility (EOF) unacceptable Plans to astablish EOF by B30601 must be submitted & must meet NUREO-0737.8uppl i (Generic Ltr B2-33) criteria EIBENHUT.D 0 Division of Licensing. GL-82-23 83/04/25 DIXON.D W South Carolina Electric & Gas Co 3pp 18310 353 24X Fiche 50-395,83/04/25,8305030010
- 8305030135 Forwards safety evaluation based on review of util submittals re TMI Action Item II B 1, "RCS Vents " Licensee venting capability acceptable.
 VASSALLO,D B Operating Reactors Branch 2 89/04/18 BAYNE,J P Power Authority of the 8tate of New York 4pp 18309 235 24X Fichs 50-333,83/04/18,8305030135
- --B303310020 B14/TER-B-7

 "Beletted Operating Reactor Issues Program II,RCS Vents
 (NURSEG-0737, Item II B 1)," finel technical evaluation rept
 HELD.J T Energy Incorporated HELD.J T Lawrence Livermore
 Laboratory FIN A-0250 TAC 44373 B3/03/02 ALBERTHAL,C NRC
 No Detailed Affiliation Diven 4pp 18309 239 24X
 Fiche 50-333.83/04/18.8305030135
- 8303030144 Forwards application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(1) to extend completion data for safety parameter display sys to 831230, as part of NUREG-0737, item III A 1 2 (Generic Ltr 82-33) CURTIGN W Pennsylvania Power & Light Co PLA-1634 83/04/29, BCHMEACER; A Licensing Brench 2, ip 18306 328 24% Fiche 50-387, 83/04/29, B305030144
- ---8303030153 Application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREO-0737, Item III A 1 2 CURTIS, N W. Pennsylvania Power & Light Co. CL-82-33, 83/04/27 2pp 18306 327 24X Fiche: 50-387, 83/04/27, 8305030144
- 8305030463 Application for amend to Licenses DPR-62 & DPR-71, supplementing 820416 request for miscellaneous Tech Spec reve originally scheduled for completion during 820901 refueling outage. Outage & mods to be completed by 830624 HOME.P.W Carolina Power & Light Co LAP-83-100 83/04/28, VASBALUO.D B. Operating Reactors Branch 2 2pp 18308 222 24X Fiche. 50-324, 83/04/28, 8305030463

- --8305030481 Proposed Yech Spacs re safety-related hydraulic snubbers; post-accident monitoring instrumentation gas analyzer sys, reactor coolant leakage detection sys & remote shutdown monitoring instrumentation

 Carolina Power & Light Co 83/04/28 19pp 18308 224 24X Fiche 50-324.83/04/28.8305030463
- 8305030491 Forwards response to 821210 Generic Ltr 82-28 re inadequate core cooling instrumentation sys.including reactor coolant inventory sys description.comformance summary to NUREQ-0737. Item II F 2 b proposed implementation schedule RANDAZIA.J B Maine Yankee Atomic Power Co GL-82-28 83/04/29 EISENHUT.D Q Division of Licensing 34pp 18275 118 24X Fiche: 50-309.83/04/29.8305030491
- 8305030519 Advises that separate todine particulate sampling systems tailed & temporary mods performed on vent monitoring system NRC 830314 order re NUREO-0737, Item II F 1. Attachment 2 Unit i systoperational Unit 2 system II be completed shortly ALEXICH.M P. American Electric Power Service Corp. AEP NRC 0678E 83704/27 DENTON, HR Defice of Nuclear Reactor Regulation. Director 2pp 18293 326 24% Fiche 50-315,83/04/29,8305030319
- 0305030558 Advises that applicable recommendations contained in B&W Topical Rept BAW-1544, "Integrated Control Sys Reliability Analysis." will be implemented prior to fuel loading to fulfil requirements of NUREG-0737, Item II K 2 9 MILLS, L M Yennessee Valley Authority 83/04/26 ADENSAM. E Licensing Branch 4 Ip 18303 299 24X Fiche 50-438,83/04/26,83050558
- 8305030588 Forwards response to 830215 request for add1 info re
 NUREO-0737. Item 11 B 3 re pott-accident sampling sys Areas
 discussed include radiological & chemical analysis capacity
 & reactor coolant gas analysis
 FILANTIM Nebraska Public Power District LGAB300026 83/04/22
 VASSALD. D B Operating Reactors Branch 2 4pp 18305-354. 24X
 Fiche-50-298.83/04/22.8305030588
- 8303030606 Forwards response to Generic Ltr 83~10C re program for resolution of NUREG-0737, Item II. K 3 5. "Automatic Trip of Reactor Coollant Pumps " Pump trip can be achieved safely & reliably by operator when required MILLS.L M Tennessee Valley Authority GL-83-10C 83/04/22 ADEMSAME Licensing Branch 4 8pp 18303 172 24X Fiche 50-390,03/04/22,8305030606
- 8303030634 Application to amend Licenses DPR-97 & NPF-5, revising Tech Specs re TMI Action Plan Items I A 1 1 3.1 A 1 3.11 E 4 1, II E 4 2 5-7.11 K 3 3.11 K 3 13.11 K 3 22.11 K 3 15. II K 3 19.11 K 3 27.11 K 3 45 & 11 F 1-4

 BECKHAHAU T Georgia Power Co NED-83-267 83/04/22 STOLZ, J F. Operating Reactors Branch 4 Bpp 18305 285 24X Fiche 50-321, 83/04/22, 8305030634
- --8305030665 Revised Tech Specs to TMI Action Plan Items I A 1 1 3, I.A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 16, II K 3 19, II K 3 27, II K 3 45 & II F I-4 corogia Power Co 83704/22 31pp 18305 293 24X Fiche 50-321, 83/04/22, 83050306/34,
- B305040311 Forwards response to B30202 request for add1 info re NUREO-0737, I tem II F 1 6, "Containment Hydrogen Monitor " Info re water level monitors to be provided by B30615 BAYNE, J P Power Authority of the State of New York JPN-83-38 B3/05/02 VASSALLO, D B Operating Reactors Branch 2 3pp 18323:300 24X Fiche 50-333,83/05/02,8305040311
- 9305040317 Responds to NRC request for add1 info re TMI action plan items Mati supports util position that nonsafety-related equipment falls outside scope of Franklin Research Ctr review Justification not necessary LENTINE:F 9 Commonwealth Edison Co 4491N 83/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 18323 289 24X Fiche 50-295.83/03/02.8305040317.
- 8305040362 Responds to 830217 & 0407 requests for additinfo re NUREG-0737. Item II. K 3 17. "ECCS Outages " Info compiled from equipment inoperability record which is completed each shift during cold shutdown HURFORD. W J Carolina Power & Light Co LAP-B3-144 B3/04/27 VARCA. S A Operating Reactors Branch I 4pg 18323 194 24X Fiche. 50-261. 83/04/29, 8305040362
- 8305040474 Informs that analysis of aircraft traffic for facility per integrated assessment rept (NUREG-0822) followup acceptable. CRUTCHFIELD.D Operating Reactors Branch 5 LS05-83-05-005 83/05/03 FIEDLER: P 8 Ceneral Public Utilities GPU Service Corp 2pp. 18319 315 R4X Fiche 50-219.83/05/03.8305040474

- 8305040546 Requests remittance of Class III fee for 821110 application re nonconformance w/NUREO-0737, Item II E 4 2 on containment isolation dependability ploos. R M License Fee Management Branch 83/04/27 CURTIS, N W Pennsylvania Power & Light Co ip 18351 230 24x Fiche 50-387, 83/04/27, 8305040546
- 8303040664 Forwards Buppl 3 to BER (NUREO-OBB7) W/o encl YOUNOBLOOD B J Licensing Branch 1 83/04/27 EDELMAN M R Cleveland Electric Illuminating Co 2pp 18336 266 24X Fiche 50-440:83/04/27.8305040664
- B305040669 Forwards BER on BWR Owners Group generic response to NUREO-0737. Item II K 3 18. "Mod of Automatic Depressurization Sys (ADS) Logic "Response acceptable w/ stipulated conditions Response requested expediently SCHMENGER.A Licensing Branch 2 B3/04/25 CURTIG.N W Pennsylvania Power & Light Co 10pp 18336 338 24X Fiche 50-387.83/04/25,8305040669
- B3D50406B2 NUREO-0827
 INTEGRATED PLANT SAFETY ABBESSMENT REPORT, SYSTEMATIC
 EVALUATION PROGRAM LACROSSE SDILING MATER REACTOR, Docket
 No 50-409 (Dairyland Power Cooperative)
 * Division of Licensing B3/04/30 494pp 18334 142 24x
 Fich* 50-409, 83/04/30, 8305040682
- 8305040686 Requests responses re relief from surveillance requirements of equipment which would result in excessive exposure Tech Spec change requests, scheduling for recovering affected system to recovery plan requested BARRETT.L H TMI Program Offics NRC-TMI-83-024 83/04/27 KANGA.B K General Public Utilities GPU Service Corp 3pp 18336-329 24X Fiche 50-320.83/04/27.8303040686
- 8303040689 NUREO-0040 VO7 NO1 LICENBEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT Data As Of March 31, 1983 (White Book) * Region 4, Office of Director 83/04/30 284pp 18332 00
- B305040693 NUREQ-0540 V04 N01
 TITLE LIBT OF DOCUMENTS MADE PUBLICLY AVAILABLE January 131,1983
 4 Division of Technical Information & Document Control B3/04/30,
 577pp 18332 285
- 8305040740 NUREO/BR-0051 VQ4 N6
 POWER REACTOR EVENTS September-October 1982.
 MASSARO 8 A , TRENERY 8 E Director's Office 83/04/30 35pp 18327 143
- 8303040769 Forwards safety evaluation & technical evaluation rept re TMI Items I A 2 i 4 "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4 "Training for Mitigating Core Damage " Programs satisfy NUREO-0737 requirements STOLZ.U F Operating Reactors Branch 4 83/04/20 BECKHAM.J T. Georgia Power Co 3pp 18327 300 24% Fiche 50-321.83/04/20, 8303040769
- B303050022 Forwards status, description & schedule for meeting requirements re emergency response capabilities, per Generic Ltr 82-33 (Buppl 1 to NUREG-0737); FIEDLER, P. B. General Public Utilities GPU Bervice Corp. GL-82-33 B3/04/15 EISENHUT, D. Q. Division of Licensing. 17pp. 18342 118 24X Fiche 50-219, B3/04/15, B305050022
- 8305050026 Forwards NEDO-22209, "Analysis of Scram Discharge Vol Sys Piping Integrity "No further action planned re equipment qualification k sys dexign mods identified in generic SER (NURSO-0803)
 BAYNE, J P Power Authority of the State of New York JPN-83-39, 83705703 VASSALLO, D B. Operating Reactors Branch 2 2pp. 18339 313 24X Fiche 50-333,83705703,8305050026
- 8305050229 Submits progress rept re TMI Items II F. 1 1 & II F. 1.2 re efficient monitor mods Vendor schedular uncertainties resolved Remaining work consists of training operators, software changes & minor wiring change COUNSIL, H O Northeast Nuclear Energy Co (subs. of Northeast Utilities B10767. 83/04/29 CRUICHFIELD,D Operating Reactors Branch 5 2pp. 18338 062 24% Fiche 50-245,83/04/29,8305050229
- 8305050293 Forwards draft SER of NUREO-0737, Item II. B 3, "Post-Accident Bampling " Eight of 11 criteria met Criterion 2,10 & 11 incomplete Add1 info requested to complete review of PASB sys VAROA. B. A. Operating Reactors Branch 1 83/04/22. UHRIO, R. E. Florida Power & Light Co 31pp 18352 074. 24X Fiche: 50-250, 83/04/22, 8305050273

8305050426 NUREG/CR-2001 BMR REFILL-REFLOOD PROGRAM TASK 4 3-BINGLE HEATED BUNDLE FINAL REPT BUTHERLAND.W A , BARTON, J E , FINDLAY, J A General Electric Co FIX B-5877 EPRI NP-2372 83/04/30 Division of Accident Evaluation 83pp Aveilable at NRC 85 50 18352 279

8305050432 NUREO/CR-3140 CONTAINMENT BUMP TEST DATA SCHMIDT.W H Sandia Leboratories FIN A-1276 SAND82-2785 83/04/30 Division of Safety Technology 73pp Available at NRC 65 00 18352 227

B305060001 Forwards EQLQ summery of discussion re radiological effluent Tech Specs during B20602-03 plant visit Final draft of proposed radiological effluent Tech Specs & offsite dose calculation manual should be developed within 60 days CLARK.R A Operating Reactors Branch 3 B3/04/25 FAY.C W Wisconsin Electric Power Co 45pp 18353:263 24X Fiche 50-266,83/04/25,8305060001

--8305060007 NUREQ-0472 D07 R03
STANDARD RADIOLOGICAL EFFLUENT TECHNICAL SPECIFICATIONS
FOR PRESSURIZED WATER REACTORS SEPTEMBER 1982
* NRC - No Detailed Affiliation Given PWR-ST8-I 82/09/03
83pp. 18353 308. 24% Fiche 50-266,83/04/25,8305060001

B305060017 Forwards SER re util responses to NUREO-0737. Items II F i 4. "Containment Pressure Monitor," II F i 5, "Containment Water Level Monitor" & II F i 6, "Containment Hydrogen Monitor." Items resolved CLARK, R A. Operating Reactors Brench 3 B3/04/21 STEWART, W L Virginia Electric & Power Co Bpp 18354: 314 24X Fiche 30-338, 83/04/21. 8305060017

B305060045 Forwards BER supporting util responses to NUREG-0737, Items II, F.1.4. "Containment Pressure Monitor." II F 1 5. "Containment Hater Level Monitor" & II F 1 6. "Containment Hydrogen Monitor" I Items resolved CLARK.R.A. Operating Reactors Branch 3 83/04/21 LUNDVALL.A E Baltimore Oas & Electric Co 9pp 18354 279 24X Fiche 50-317,83/04/21,8305060045

8303060108 Advises that requirements of NUREO-0737, TMI Action Plan Items II.F 1.4, II F 1.5 & II F. 1.6 met & items resolved Criteria requiring equipment to be environmentally qualified will be reviseed under environ qualification program CLARK, R.A. Operating Reactors Branch 3 83/04/21 MUSOLF, D. M Northern States Power C 9pp 18334 268 24% Fiche: 50-282, 83/04/21, 8305060108

B303060233 NUREO/CR-3136
AQUIFER REBTORATION AT IN-SITU LEACH URANIUM MINES EVIDENCE
FOR NATURAL RESTORATION PROCESSES
DEUTSCH N J., SERNE, R J. BELL, N E Battells Memorial Institute,
Pacific Northwest Laboratory FIN B-2379, PNL-4604 83/04/30
Division of Health, Siting & Waste Management. 96pp Available at
NRC \$5.50, 18359-001.

8305060306 Requests that portion of 830422 response to Generic Ltr 83-02 be withdrawn. Portion re Item II.F.1, "Add1 Accident Monitoring Instrumentation," will be reevaluated upon receipt of NRC guidance
QUCWALL T Georgia Fower Co. NED 83-278 83/05/02 8TOLZ, J.F. Operating Reactors Branch 4 1p 18344 323 24X
Fishe: 50-321, 83/05/02, 8305060306

B303060327 Responds to New England Coelition on Nuclear Pollution & State of NH submittals subsequent to B30407-08 prehearing conference. Objects to word "omission" in reworded Coelition Contention I D.2 LESSY.R.P. Hearing Branch 3 IBBUANCES UL. 83/05/04. HOYT.H., LUEBKE.E.A., HARBOUR.J. Atomic Safety and Licensing Board Panel. 4pp. 18344'081. 24X Fichs'50-443.83/05/04.8305060329

B305060347 NUREO/CR-3229

EXPLORATORY ASSESSMENT OF POSTIRRADIATION HEAT TREATMENT
VARIABLES IN NOTCH DUCTILITY RECOVERY OF A533-B STEEL
HAMTHORNE, J. R. Haterials Engineering Testing Services, Inc. #
EMSA, Inc. FIN B-8133 83/04/30 Office of Nuclear Regulatory
Research, Director 20pp Available at NRC, \$3 25 18359.097.

8305060395 Forwards response to 820923 ltr re open items in NURE9-0612, "Control of Heevy Loads at Nuclear Power Plants " Dynamic load effects, inservice insp & exam frequency reviewed Phase II results expected by 830601 CROUSE,R.P Toledo Edison Co 943 83/05/02 STOLZ, J.F Operating Reactors Branch 4 7pp. 18343 167. 24X Fiche. 50-346,83/05/02,8305060395.

8305060399 Comments on proposed rule re-safety goals evaluation plan Milano Natl Nuclear Regulatory Agency presently involved in similar but more restrictive task Requests to be kept informed of proceedings
GARRIBBA.S Institute of Ingegneria Nuclears, Milan, Italy
48FR10772 83/04/26 Docketing & Services Branch 1p

8305060415 Forwards resolution of open items re NUREG-0737. Item II B 3, "Post-Accident Sampling Sys." per 830215 evaluation & 830314 telcon No significant radiation effects anticipated. LATHAM.W K Sacramento Municipal Utility District 83/05/02 870L7.J F Operating Reactors Branch 4 2pp 18343 279 24X Fiche 50-312.83/05/02,8305060415

8305060431 Forwards application for amend to License DPR-64, changing Tach Specs 6 9 1.6 9 1 4.6 9 1 7.6 9 1 8.6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment isolation valve mods & NRC & util organizational changes BAYNE, J P Power Authority of the State of New York IPN-83-34 83/05/03 VARGAS A Operating Reactors Branch 1 3pp 18351 199 24X Fiche 50-286,83/05/03 8300060431

---8305060432 Application for amend to License DPR-64, changing Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8.6 9 2 % Tables 3 6-1 % 4 4-1 to reflect containment isolation valve mods & NRC & util organizational changes

BAYNE, J. P. Power Authority of the State of New York 83/05/03 ip 18351 202 24% Fiche 50-286,83/05/03,8305060431

--8305060433 Proposed changes to Tech Specs 6 9 1.6 9 1 4.6.9 1 7.6 9 1 8.6 9 2 % Tables 3 6-1 % 4 4-1 to reflect containment isolation valve mods % organizational changes W/one oversize drawing Aperture card is available in PDR # Power Authority of the State of New York 83/05/03 13pp 18351 203 24X Fiche 50-286,83/05/03,8305060431

B305040457 Forwards draft responses to NUREG-0737, Items I C i, I C 6, I, D i, I D 2. I Q i & III A i 2 Responses will be incorporated into FBAR by June 1983
BRADLEY, E J Philadelphis Electric Co 83/05/04 SCHHENCER, A Licensing Branch 2 9pp 18351 160 24X Fichs 50-352,83/05/04,8305060457

B305060562 Forwards BER (NUREQ-0979) re application for final design approval for OEBSAR II & FR notice W/o NUREQ THOMAS.C O Btandardization & Special Projects Branch B3/04/28 BHERNOOD.G Q General Electric Co 2pp 18359 210 24X Fiche 30-447.83/04/28.8305060562

--830306056B Notice of availability of SER (NUREG-0777) on proposed final design approval for GEBSAR II
BRINKMAN,D S Standardization & Special Projects Branch.
B3/04/2B, ip 18359:212 24X Fiche 50-447,83/04/2B,8303060562

B303060645 Advises that Class III fee appropriate for each listed application filed w/NRR for review Request of 830331 for exemption from order, confirming commitment to implement NUREO-0737; not exempt from fees
MILLER; W D License Fee Management Branch B3/05/02
RODRIOUEZ, R. J Sacramento Municipal Utility District 2pp 18358, 362. 24% Fiche: 50-312; B3/05/02, B305060645

8305060658 Forwards safety evaluation re NUREO-0737. Items II F 1 4, II F 1 5 & II F 1.6 on containment pressure; water level & hydrogen monitors Util 801210 submittal & 830218 rev acceptable Environ qualification to be reviewed separately VAROA: S A Departing Reactors Branch 1 83/04/22 STEWART, W L Virginia Electric & Power Co 2pp 18357 357 24X Fiche 50-280.83/04/22,8305060658

--8305060663 Safety evaluation re TMI Action Plan Items (NUREG-0737)
II.F I 4, "Containment Pressure Monitor." II F I 5,
"Containment Hater Level Monitor" & II.F I 5, "Containment
Hydrogen Monitor " Designs acceptable,
" Office of Nuclear Reactor Regulation, Director 83/04/22 5p;
18357:359. 24X Fiche 50-280, 83/04/22,8305060658

8305060674 NUREO/CR-2924
RADDN DIFFUSION IN CANDIDATE SOILS FOR COVERING URANIUM
MILL TAILINGS
SILKER.W B . KALKWARF, D.R Battelle Memorial Institute, Facific
Northwest Laboratory. FIN B-2269 PNL-4434 83/04/30 Division
of Health. Siting & Weste Management 52pp Available at NRC
45 00 18338 200.

8305060675 NUREG/CR-2005 RO1
CHECKLIST FOR EVALUATING EMERGENCY OPERATING PROCEDURES USED
IN NUCLEAR POWER PLANTS
BRUNER L , MEINSTEIN, M HPT, Inc * Sandia Laboratories FIN
8-3098 SANDB1-7074 83/04/30 Division of Safeguards &
Inspection Programs (Post 830103) 35pp Available at NRC. \$4.50
18358_262

- 8305060680 NUREG-0485 V05 ND3

 SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPT Data As OF March 31.1983 (Buff Book)

 * Office of Resource Management, Director 83/03/31 63pp 18358 295
- 8305090013 Forwards SER (NUREG-0968, Suppl 1) including addl info received from applicant & ACRS comments GRACE.JN Clinch River Breeder Reactor Program Office 83/05/02 LONGENECKER,J Energy Dept af, Clinch River Breeder Reactor Plant 32pp 18367 322 24x Fiche 50-537,83/05/02,8305090013
- 8305090035 NUREG/BR-0004 ROI ER
 INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION
 REPORTS Forms DDE/NRC-741.7414 And 740M
 # Office of Nuclear Material Safety & Safeguards, Director
 83/03/04 | p | 18381 199
- B305090040 NUREG/BR-0006 R01 INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION REPORTS Forms DOE/NRC-741:741A And 740M * Office of Nuclear Material Safety & Bafeguards, Director. B3/04/30 102pp 18380 276
- 8305090046 NUREG-0728 R01 NRC INCIDENT RESPONSE PLAN # Director's Office, Office of Inspection and Enforcement 83/04/30 27pp Available at NRC \$3 75 18381 042
- B305090144 Summarises review of completed Generic Item B-24 re containment purps & vent & TMI Action Pian Item II E 4 2 BER & "Override & Reset of Control Circuitry in Ventilation/Purgs Isolation & Other ESF Sys (B-24)." encl CLARK.R A Operating Reactors Branch 3 83/04/20 STEWART.W L Vinginia Electric & Power Co 3pp 18347 072 24X Fiche 30-338.83/04/20.8305090144
- --8305090149 Safety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purga isolation & other ESF sys # Office of Nuclear Reactor Regulation, Director 83/04/20 App 18367 075 24X Fiche 50-338,83/04/20.8305090144
- B305090162 NUREO/CR-3117

 BEISHTCITY AND TECTONIC RELATIONSHIPS OF THE NEMAHA UPLIFT
 AND MIDCONTINENT GEOPHYSICAL ANOMALY Final Project Bummary
 BURCHETT,R R Netwaska, State of LUZA; K V Otlahoma; State of
 VAN ECK,O J Towa Geological Survey FIN A-5774 B3/02/28

 Division of Health, Siting & Waste Management 42pp Available at
 NRC. \$12 00 18367 175
- 8303090200 Forwards response to NUREG-0737 Item II K 3 13, "RCIC Automatic Restart " RCIC eys modified such that reactor high water level signal will adutomatically close RCIC turbine steam supply valve, should valve be open.

 HARRINOTON, W D Boston Edison Co 83-108 83/04/29 VASSALLO, D, B Operating Reactors Branch 2 1p 18363 361 24X Ficher 50-293, 83/04/29, 8305090200
- 8303090380 Ack receipt of 830131 ltr requesting additinfo re
 NVREG-0737. Item II K 3 28. "Gwalification of ADS Accumulator
 Bys." Info requested from GE Response will be submitted by
 830630.
 ZIMMERMAN, B R Carolina Power & Light Co LAP-83-119 83/05/03
 VASSALLO.D B. Operating Reactors Branch 2 ip 18363 340 24X
 Fiche: 50-324, 83/05/03.8305090380
- 8305090462 Forwards B&W "Bounding Analytical Assessment of NUREO-0630 on LOCA & Operating kW/Ft Limits." per 830321 commitment WESTAFER, O.R. Florida Power Corp. 3F-0483-32 83/04/29 8TOL7, J.F. Operating Reactors Branch 4 1p 18362 153 24x Fiche 50-302,83/04/29,8305090462
- ---8303090464 77-1140899-01
 **Bounding Analytical Assessment of NUREO-0630 on LOCA & Operating BW/Ft Limits."
 ** Babcork & Hilcox Co 83/04/27 29pp 18362 154 24X Fiche 30-302,83/04/29,8305090462
- 8305070484 Forwards response to Buppl 3 of BER (NUREO-0528), Section 3 iO. "Seismic & Dynamic Qualification of Seismic Category I Mechanical & Electrical Equipment" FLYNN.J D Cincinnati Gas & Electric Co 83/05/05, DENTON,H Office of Nuclear Reactor Regulation, Director 4pp 18360:22 24X Fiche 50-358,83/05/05,8305070486
- B305090553 Requests remittance of fee due for review of B30217 amend application re implementation of NUREO-0737 items:providing justification for imposition of fees in response to B30401 itr contesting fee fittLER.W O License Fee Management Branch 83/05/02, R00R109E7.R J. Sacramento Municipal Utility District ip 18367 360 24X Fichs.50-312,83/05/02,8305090553

- 830510010B Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREQ-0472 "Defeite Dose Calculation Hanual" also encl STEMART, M L Virginia Electric & Power Co 179 83/05/04 DENTON, H R Defice of Nuclear Reactor Regulation, Director VARQA, B A Operating Reactors Branch 1 3pp 18371 346 24X Fiche 50-280, 83/05/04, 8305100108
- --8305100111 Proposed revs to radiological effluent Tech Specs,in accordance w/Rev 3 to NUREO-0472
 * Virginia Electric & Power Co 83/05/04 87pp 18371 349, 24X
 Fichs 50-280,83/05/04,8305100108
- 8305100110 Responds to 830413 ltr re TM1 Action Item 11 K 3 18, "Mods to ADS Sys Logic " One of two options (2 or 4) will be implemented Choice based on benefit to design impact on schedule.availability of hardware & analysis & total cost BDUCHEY.0 D Washington Public Power Supply System 002-83-408 63/05/04 SCHWENCER, A Licensing Branch 2 ip 18375-032 24X Fiche 50-397,83/05/04,8305100110
- 8305100114 Forwards review of existing specs re containment cooling sysoperability No mods required Revised Section 3 3, "ESF & Auxiliary Sys," will be consistent w/NUREG-0452 & will be submitted as part of Amend 55 oIESLER.C W Hisconsin Public Service Corp. NRC-83-102 83/05/06. VARGAB A Operating Reactors Branch 1 6pp 18375 020 24X Fiche 50-305,83/05/06,8305100114
- ### 8305100168 Forwards SER, Suppl 3 (NUREO-0887) W/o encl.
 CUTCHIN.J M Hearing Branch 4 ISSUANCES OL 83/05/08
 SLOCH.P B. BRIGHT.O D. KLINE.J R. Atomic Safety and Licensing
 Board Panel 1p 18374 273 24% Fichs 50-440.83/05/09.8305100168
- 8303100175 Forwards add1 info re instrument accuracy & related data for containment pressure monitors, containment water level monitors & containment hydrogen monitors (NUREO-0737, Items II F 1 4. II F 1 5 & II F 1 6), per 821118 request.

 0. TDOLE, J D Consolidated Edison Co. of New York, Inc. 83/04/29 VARGA: 8 Operating Reactors Branch 1 14pp 18374 274. 24x Fiche 50-247, 83/04/29, 8305100175
- 8305100197 Forwards comments re proposed NUREG-0737 Yech Spece, per 830321 ltr request Comments should not be interpreted as formal position or commitment to specific course of action. DENTE.T J BHR Gumers Group BHRGO-8313 83/05/06 EISENHUT, D G. Division of Licensing 4pp. 18374 311
- 8305100229 Forwards response to questions raised during 830422 telcon ra util plans concerning NUREO-0737. Item II F i, "Containment Instrumentation Upgrades" Dedicated recorder for hydrogen concentration will be provided RDDRIGUEZ/R U Sacramento Municipal Utility District. 83/09/06. 870LZ/J F Operating Reactors Branch 4 3pp 18374:128 24X Fiche: 50-312, 83/05/06, 8305100229.
- G305100344 Submits info re NUREO-0737. Item II E 1.1, "Auxiliary Feedwater Bys Upgrade Review," per G30407 request Info resolves protection of sys from internal missiles & addl protection required for condensate storage tank RODRIQUEZ.R J Sacramento Municipal Utility District. G3/05/02. STOLZ.J F. Operating Reactors Branch 4 2pp 18378-231 24X Fiche 50-312.63/05/02.8305100344
- 8305100347 Forwards addl Justification supporting adequacy of test of electrical load to satisfy License Condition 2.C & HCAP-B92; "Betpoint Study. Duke Power, William B McQuire Nuclear Plant, Units 1 & 2 " Rept withheld (ref 100FR2 790). TUCKER: H B. Duke Power Co 83/05/05 DENTON, H R. Qffice of Nuclear Reactor Regulation, Director ADENBAME. E., Licensing Branch 4 2pp 18378 325 24X Fiche 50-369,83/05/05,8305100347.
- 8305100356 Forwards responses to New England Coalition on Nuclear Pollution fourth, sixth, eighth, twelfth, fourteenth & fifteenth motions for summary disposition LESBY, R.P. Hearing Branch 3 ISBUANCES OL 83/03/21. HOYT, H., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 18411,001 24X Ficher 50-449,83/03/21,8305100356.
- --8305100419 Affidavit of RD LaGrange on util commitment to qualify wide-range pressure transmitters per NUREO-0088 requirements. Commitment acceptable LAGRANGE.R. G. Equipment Qualification Branch IBBUANCES QL. 83/03/18. 3pp 18411.047 24X Fiche 50-443,89/03/21,8305100356.
- --8305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREO-0737, Item I.A i 1 requirements re shift technical advisor position Proposal acceptable.
 HIGOINS.U.T Division of Project & Resident Programs, ISBUANCES OL. 83/03/17. 2pp iB411.057. 24X Fiche.50-443,83/03/21.

- --B305100424 Affidavit of RO LaGrange on qualification of Class IE electric valve operators installed inside containment Util committed to qualification per NUREO-O588 LAGRANGE, R. C. Equipment Qualification Branch ISSUANCES OL B3/03/18 3pp 18411.064 24X Fiche 50-443.83/03/21.8305100356
- 8305100348 Advises that w/exception of Item II K 3 31 on compliance w/100FR30 36,830324 comments applicable to 830321 draft generic 1tr Review of 830324 submittal re comments on draft NUREO-0737 BWR Tech 8pecs requested COUNBIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.H 0 Northeast Utilities B10783 83/05/05 E18ENHUT.D 0 Division of Licensing 2pp 19378 212 24X Fiche 30-245.83/05/05,8305100348
- 8303110003 Forwards evaluation of loss of discharge back pressure on pump operability re NUREO-0737, Item II E 1 1 & 830131 SER, par IE Bulletin 80-04. Operability of auxiliary feedwater pumps after extended operation at runout flow addressed OIEBLER, C W. Misconsin Public Service Corp NRC-83-103 B3/05/04 VARQA, S A Operating Reactors Branch 1. 9pp 18408:280 24X Fiche, 50-305, 83/05/06, 8305110003
- 9305110009 Comments on adequacy of implementation of NUREO-0737. Item III. A 2 i. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." Offsite & onsite emergency preparedness adequate.

 CRUTCHFIELD D Operating Reactors Branch 5 LS05-83-05-023 RS705/09. FIEDLER.P B General Public Utilities OPU Service Corp 3pp 18409-023 24% Fiche 50-219. BS/05/09.8303110009
- 8305110026 Revised statement of P Vacca on 830419 re SECY 83-62 concerning rev to 10CFR35. "Human Use of Syproduct Matl "VACCA,P C Assistant Director for Material Safety & Licensing 83/04/19. 7pp. 18412 338
- --8305110029 Supports J Deimedico 830228 statement of differing prof opinion re SECY 83-62 (proposed rev to 100FR35) VACCA:P C. Assistant Director for Material Bafety & Licensing 83/03/02. PALLADINO,N , OILINSKY,V., AHEARNE,J Commissioners 10pp. 18412 345.
- ---8305110030 Testimony of J Delmedico on 830419 in opposition to SECY 83-62 (proposed rev to 10CFR35).

 DELMEDICO, J Assistant Director for Material Bafaty & Licensing 83/04/19 4pp 18412/355.
- 8305110027 NUREO/CR-3119 VOI NUCLEAR POWER SAFETY REPORTING SYSTEM FEASIBILITY ANALYSIS FINLAYSON,F., IMB.J APPOSPACE COPP FIN B-8255. 83/04/30 Division of Facility Operations. 35pp Available at NRC. \$4 50
- 8303110049 Comments on implementation of NUREG-0737. Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10GFR30." Onsite & offsite emergency preparedness adequate. CRUTCHFIELD. D. Operating Reactors Branch 5. L805-83-05-024 83/05/10. KAY, J. A. Yankee Atomic Electric Co 3pp. 18409.014. 24X Fichs. 50-029, 83/03/10, 8305110049
- B305110059 Advises that onsite & offsite emergency preparedness adequate. Emergency plans upgraded per NUREO-0737. Item III A. 2. 1. "Emergency Preparedness, Upgrade Emergency Plans to App E. 100FR50." Item complete GRUTCHFIELD. D. Operating Reactors Branch 5 LS05-83-05-022 B3/03/09. DIETCH, R. Bouthern California Edison Co. 3pp. 18408. 106. 24X Fiche: 50-206.83/03/09.8305i10059.
- 8305110114 NUREG-0871 VO2 NO2 EUMMARY INFORMATION REPORT. Data As Of April 30, 1983, (Brown Book) # Management Information Branch 83/04/30, 55pp 18419:195
- B30511011B NUREG-0949
 REPORT OF THE EVALUATION TEAM ON THE QUALITY OF CONSTRUCTION AT THE ZIMMER NUCLEAR POWER STATION.
 ** NRC No Detailed Affiliation Given 83/04/30, 391pp 18418.001. 24% Fiche 30-358,83/04/30,8305110118
- B305110119 NUREQ/CP-0035
 THE MAN-MACHINE INTERFACE AND HUMAN RELIABILITY AN
 ASSESSMENT AND PROJECTION.
 HALL, R. E. FRAODLA, J. R., LUCKAS, W. J. Institute of Electrical &
 Electronic Engineers. FIN A-3217 BNL-NUREG-51579, 83/04/30
 Office of Nuclear Regulatory Research, Director 265pp. 18416,001.
- B305110120 NUREO/CR-2069 R01 SUMMARY REPORT ON A BURVEY OF LIGHT-WATER-REACTOR BAFETY BYSTEMB, HEDDLEBON:F. A. Dak Ridge National Laboratory, FIN B-0431, ORNL/NBIC-181/R, B3/05/31 Division of Risk Analysis 356pp. 18417:001.

- 8305110126 NUREO/CR-3013
 REVIEW OF THE RANCHO SECO NUCLEAR GENERATING STATION UNIT
 NO 1 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYSIS Docket
 No 50-312 (Sacramento Municipal Utility District)
 ILBERG, D. YDUNGBLODD, R. PAPAZOGLOU, I A Brookhaven National
 Laboratory FIN A-3393 BNL-NUREO-51620 83/04/30 Division of
 Safety Technology 49pp Available at NRC 64 75 18416 266 24.
 Fichs. 50-312, 83/04/30, 8305110126
- B305110127 NUREG/CR-3187
 CREVICE CORROSION OF TITANIUM ALLOY TICODE-12 IN SIMULATED
 ROCK SALT BRINE AT 130 CENTIGRADE Topical Report
 AHN,T,M, LEE,B 8, BOOLP Brookhaven National Laboratory FIN
 A-3237 BNL-NUREG-51653 83/04/30 Division of Health, Siting &
 Waste Management 28pp 18416 317
- 8305110131 NUREO/CR-3073
 CONSTITUTIVE RELATIONS IN TRAC-PD2
 ROHATOI,U 8 , JO,J , NEYMOTIN,L Brookhaven National Laboratory
 FIN A-3215 BNL-NUREG-51616 83/04/30 Division of Accident
 Evaluation 43pp 18412 294
- 8303110148 NUREG/CR-2774 VO4
 PHYSICS OF REACTOR SAFETY Guarterly Report.October December 1982
 # Argonne National Laboratory FIN A-2015 ANL-82-24 83/04/30
 Division of Accident Evaluation 31pp 18412 195
- 8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07, NUREG-0512, "Control of Heavy Loads," to confirm & clarify items discussed in 820804 telcon LIDEN, E.A. Public Service Electric & Oas Co. of New Jersey GL-81-07 83704/27 VAROA, 8 A. Operating Reactors Branch i Bpp 18399 007 24X Fiche 50-272,83/04/27,8305110154
- --8305110156 PSE-0108, "Maint Procedures "

 * Public Service Electric & Gas Co of New Jersey GL-81-07
 83/04/27 1,317pp. 18399 101 24X Fiche 50-272:83/04/27,
 8305110154
- B305110162 NUREO/CR-3220

 MECHANISTIC ASPECTS OF STRESS-CORROSION CRACKING OF TYPE 304

 BTAINLESS STEEL IN LWR SYSTEMS

 NICHOLS: F A Argonne National Laboratory FIN A-2212 ANL-83-15

 B3/04/30 Division of Engineering Yachnology 67pp 18412 227
- B305110174 NUREG-0940 VO2 NOI ENFORCEMENT ACTIONS BIGNIFICANT ACTIONS RESOLVED Quarterly Progress Report. January-March 1983 # Director's Office. Office of Inspection and Enforcement 83/04/30 286pp 18411.066
- 8303110176 NUREG/CR-2368

 IMR REFILL-REFLOOD PROGRAM TASK 4 4 CCFL/REFILL SYSTEM
 EFFECTS TESTS (30 F SECTOR) SSTF SYSTEM RESPONSE TEST
 RESULTS

 8CHUMACHER, D. Ø., ECKERT, T., FINDLAY, J.A. General Electric Co. FIN
 B-3877 GEAP-22046 B3/04/30 Division of Accident Evaluation
 130pp. Available at NRC \$6.00 18412 065
- 8305110208 NUREO/CR-2716 VO4
 REACTOR SAFETY RESEARCH PROGRAMS Guarterly Report,October —
 December 1982.
 EDLER,8 K Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN 8-2101 PNL-4275-4. 83/04/30 Division of
 Accident Evaluation 49pp. Available at NRC #5.00 18412 001
- 8305110223 Responds to 811031, 820702 & 830104 requests for exception from Table 1 of NUREO-0737, Suppl 1 requirements relocation of emergency operations facility Exception granted, EISENNUTD Q Division of Licensing 83/04/29 UHR10, R E Florida Power & Light Ca 2pp. 18434:334 24% Fiche 50-250, 83/04/29, 8305110223
- 8305110227 NUREG/CR-3074
 APPLICATION OF REDUCTION METHODS TO NUCLEAR POWER PLANT
 STRUCTURES.
 MILLER.C A , PHILIPPACOPOULD Brookheven National Laboratory FIN
 A-3216 BNL-NUREG-31629 83/04/30. Division of Engineering
 Technology. 98pp 18413 008
- 8305110237 NUREO/CR-2331 VO2 N3
 BAFETY RESEARCH PROGRAMS SPONSORED BY DFFICE OF NUCLEAR
 REGULATORY RESEARCH. Quarterly Progress Report, July I —
 September 30, 1982
 KOUTS, H J. BARI, R A, CERBONE, R J. Brookhaven National Laboratory
 FIN A-3011. BNI-NUREO-51454 83/04/30. Division of Accident
 Evaluation. 163pp 18419-032.
- 8305110240 NUREQ-0748 VO3 NO3

 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of April 30,1783 (Orange Book)

 * Management Information Branch. 83/04/30, 317pp 18420 001.

8305110308 Application for amend to OLs revising Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions CLAYSDN.F L Alabama Power Co 83/05/03 VAROA,S A Office of Nuclear Reactor Regulation. Director 5pp 18393 178 24X Fiche 50-348,83/05/03,8305110308

8305ii0374 Forwards addl info re NUREG-0737, Items IJ F 1 4, II F 1 5 & II F 1 6 concerning containment pressure, water level & hydrogen monitors, respectively, per 830106 request No obstructions would prevent hydrogen from escaping from core FIEDLER.P B General Public Utilities - GPU Service Corp 83/05/06 CRUTCHFIELD. D Operating Reactors Branch 5 8pp 18406 279 24X Ficha 30-219,83/05/06,8305110374

8305110385 Forwards response to open item on safe load paths contained in NRC 820923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREG-0612) CROUSE,R P Toledo Edison Co 946 83/05/06 STOLZ, J F Openating Reactors Branch 4 lipp 18406 201 24X Fiche 50-346,83/05/06,8305110385

B305110415 Notification of CROR Meeting 3B on B3051B in Bethesda, MD to discuss proposed rule. "Analysis of Potential Pressurized Thermal Shock Events," prioritization of generic sefety issues & operator requalification program Review matl encl STELLO, V. Regional Operations & Generic Requirements 83/05/10 EISENHUT. D. Office of Nuclear Reactor Regulation, Director JORDAN, E. L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R. E. Office of Nuclear Material Safety & Bafeguards, Director 2pp 18394 221

--930511042B Forwards proposed Commission paper discussing prioritization of generic safety issues & transmitting draft NUREO-0933.

"Prioritization of Generic Safety Issues" Procedures for identifying & managing issues encl
DENTON.H R Office of Nuclear Reactor Regulation, Director 89/09/02 DIRCKB.W J Office of the Executive Director for Operations 771pp 18394 259

8305110437 Forwards "Bounding Analytical Assessment of NUREQ-0630 on LOCA & Operating kW/FT Limits." per 830405 ltr CROUSE,R P Toledo Edison Co 945 83/05/06 870LZ.J F. Operating Reactors Branch 4 lp 18404 320 24X Fiche 50-346,83/05/06,8305110437

--B303110443 77-1142162-00

"Bounding Analytical Assessment of NUREG-0630 on LOGA & Operating kM/FT Limits"

* Babcock & Wilcox Co B3/05/06 28pp 18404 321 24X Fiche 30-346, 83/05/10437

8305110457 NUREO/CR-2749
COMPARISON OF FIELD-MASURED RADON DIFFUSION COEFFICIENTS
WITH LABORATORY-MEASURED COEFFICIENTS
LEPEL,E A , SILKER,W B , THOMAS,W V Battella Memorial Institute,
Pacific Northwest Laboratory FIN B-2249 PNL-4414 B3/04/30
Division of Health, Siting & Waste Management 36pp Available at
NRC 44 50 18413 214

8305110467 NUREO/CR-3216
HEISSDAMPFREAKTOR (HDR) STEEL CONTAINMENT VESSEL AND FLOOD
WATER STORAGE TANK STRUCTURAL DYNAMICS TEST
OGRMAN.V W , ARENDTS, J O , THINNES, O L EG&O, Inc FIN A-6306
EG0-2249 83/04/30 Division of Engineering Technology 108p,
18413 106

B305110476 NUREG/CR-3255

ANALYSIS OF REINFORCED CONCRETE CONTAINMENT VESSELS HITH

NONLINEAR SHEARING STIFFNESS

CONCEY, C H, WHITE: R N, GERGELY, P Cornell Univ FIN B-3688

B3/04/30 Division of Engineering Technology 11ipp. Available

at NRC \$5 50 18413 232

8305110482 NUREO/CR-0169 VOI LOFT EXPERIMENTAL MEASUREMENTS UNCERTAINTY ANALYSES METHODOLOGY AND SUMMARY LASSANN, 0 D EO&O, Inc FIN A-6043 EGO-2037 83/04/30 Division of Accident Evaluation 4fpp 18415 020

BJ05110491 NUREO/CR-2744 VO2
HUMAN RELIABILITY DATA BANK FOR NUCLEAR POHER PLANT
OPERATIONS Volume 2 A Data Bank Concept And System
Description
COMER, H K . KOSINSKY, E J . ECKEL, J. S General Physics Corp FIN
A-1188 SAND82-7057. 83/04/30 Division of Facility Operations
177pp 18414 001

8305110501 Forwards IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted STAROSTECKI, R. Division of Project & Resident Programs. B3/04/26 MCNEILL-C A Power Authority of the State of New York 2pp. 18393 350 R4X Fiche 50-333.83/04/26.8305110501

--8205110508 IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREO-0737, Itam II B 2, "Design Review of Plant Shielding "
BRICOS.L. HAVERKAMP.D. EAPEN.P. Region 1. Office of Director. 83/04/22 Bpp 18393 352 24X Fiche 50-333,83/04/26.8305110501

8305110512 NUREO/CR-3261 COOPERATIVE TEST PROGRAM ON CRACK ARREST TOUGHNESS MEASURENENT Final Report FOURNEY, W. L., HARN, O. T., HOAQLAND, R. Q. Maryland, Univ. of FIN B-0119 B3/04/30 Division of Engineering Technology 202pp Available at NRC 87 00 18414 178

B305110518 NUREO/CR-3195 ANALYSIS OF SEMISCALE MDD-2A SYSTEM UHI/SBLOCA EXPERIMENTS BHIMECK.D J EQ&Q, Inc FIN A-6038 E90-2246 B3/04/30 Division of Accident Evaluation 42pp 18415 184

B305110523 NUREG/CR-3184
PBF LOCA TEST LOC-6 FUEL BEHAVIOR REPORT
BROUGHTON, M , VINJAMURI, K , HAGRMAN, D L EG&G, Inc FIN A-6041
EGG-2244 83/04/30 Division of Accident Evaluation 68pp
18415 115

8305110529 NUREG/CR-2743
PROCEDURES FOR USING EXPERT JUDOMENT TO ESTIMATE HUMAN
ERROR PROBABILITIES IN NUCLEAR POWER PLANT OPERATIONS
SEAVER D A , STILLWELL W G Decision Science Consortium, Inc *
Sandia Laboratories FIN A-1188 SAND92-7054 83/04/30
Division of Facility Operations 127pp 18415-227

B305120003 Responds to B30316 ltr requesting review of RCIC sysautomatic restart per TMI Action Item II K 3 13 Acceptance criteria [dentified in ltr satisfied IIMERMAN, S R Carolina Power & Light Co LAP-83-124 B3/05/09. VABBALLO, D B Operating Reactors Branch 2 ip 18423-076 24% Fiche 50-324, B3/05/09, B305120003

8305120088 Requests review schedule for applicant response to Generic Ltr 82-33 re NNREG-0737. Suppl i concerning emergency response capability M/o enci / YOUNOBLOOD. B J Licensing Branch i GL-82-33 83/04/27 MODRE, V Human Engineering Section ROSA.F Instrumentation & Control Branch PAGANO, F Emergency Preparadness Licensing Br (after 801119 see I&E) 2pp 18445.191 24% Fiche 50-000.83/04/29.8305120088

8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR30, App E Emergency plans upgraded per NUREO-0737. Item III A 2 1 Item complete CRUTCHFIELD.D Deperating Reactors Branch 5 LSQ5-83-05-026, 83/05/11 FARRAR.D L Commonwealth Edison Co 3pp 18423.040 24% Fiche 50-010, 83/05/11, 8305120116

8305120189 Informs that post-implementation review info on NUREQ-0737. Items II F 1 4.II F 1 5 & 11 F 1 6 will not be provided until 930701 due to higher priority post-TMI work KRIEOER.R W Southern California Edison Co 83/05/10 CRUTCHFIELD.D Operating Reactors Branch 5. 1p 18427-152. 24X Fiche 50-206.83/05/10,8305120189

B305120325 Forwards response to NUREO-0612: "Control of Heavy Loads "
Ack of receipt of matl requested
CRANK,P A Pacific Osa & Electric Co 83/05/09 KNIGHTON G.W
Licensing Branch 3 222pp 18432 042 24% Fiche 50-275,83/05/09,

8305120370 Forwards Accident Evaluation Branch SER input re NUREO-0737. Item III D 3 4. "Control Room Habitability " Sys acceptable CRUTCHFIELD: D Operating Reactors Branch 5 LS05-83-05-027 83/05/11 FARRID, L Commonwealth Edison Co 6pp 18432 295 24X Fichs: 50-237,83/05/11.8305120370

--B305120374 Advises that licenses proposed program re NUREQ-0737, Itaa III D 3 4, "Control Room Habitability," acceptable MURPHY, D b Battella Memorial Inteltute, Pacific Northwest Laboratory FIN B-2323 82/03/23 MULMAN, L Q Accident Evaluation Branch 2pp 18432 301 24X Fiche, 50-237, 83/05/11, 8305120370

8305120385 Forwards RCS pressure temp (P-T) curves requested in Section 5 3 2 of BER (NUREG-0857) P-T curves will be submitted as part of final Tech Spec submission Submittal resolves issue VAN BRUNT, E E Arizona Public Service Co ANPP-23714-WFG/ 83/03/09 KNIGHTON, 0 Licensing Branch 3 4pp. 18433:120 24X Fiche, 50-528, 83/05/09, 8305120385

8305120440 Forwards IE Insp Rept 50-237/83-03 on B30111-0324 & notice of violation
LITTLE: M.S. Region 3, Office of Director. 83/04/25 REED.C Commonwealth Edison Co. 2pp 18431.091 24X Fiche.50-237,83/04/25.8305120440

- --8305120449 IE Insp Rept 50-237/83-03 on 830111-0324 Noncompliance noted failure to control recirculation riser gips wold rod studs.unused rod & unused rolls of E308L-16 stainless steel wire

 KEY, H J DANIEL80N, D H Region 3, Office of Director IE8-82-0: 83/04/21 11pp 18431 094 24X Fiche 30-237, 83/04/25, 8305120440
- 8305120562 Summary of 269th ACRS meeting on 820909-ii re safety goals for nuclear power plants # ACRS - Advisory Committee on Reactor Bafeguards 83/05/05. ACRS - Advisory Committee on Reactor Safeguards 239pp 18442 211
- 830513000B Informs that emergency offsite facility (EOF) operational w/erception of issuance of Procedure 1212 & installation of dedicated phone lines at near-site support ctr & EOF, per Oeneric Ltr 82-33
 UHRIG,R E Florida Power & Light Co QL-82-33 83/05/07
 E18ENHUT,D 0 Division of Licensing 1p 18436-326 24X
 Fiche-50-250,83/05/09,8305130008
- B305130009 Updates progress in meeting schedular commitments per NRC B30314 order re implementation of post-TMI Action Item II F 1, "Add1 Accident Monitoring Instrumentation " FAY, C H Hisconsin Electric Power Co B3/05/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 18436-341 24X Fiche 50-266,83/05/06,8305130009
- 8305130020 Forwards add1 justification required by SER (NUREG-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities MILLS, L M Tennessee Valley Authority 83/03/10 ADENSAM.E. Licensing Branch 4 App 18437 127 24X Fiche 50-390.83/05/10.83035/3020
- 8305130038 Responds to 830316 request for add1 info re NUREG-0737. Item II.K. 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Bys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-018 RYBAK, 9 Commonwealth Edison Co IEB-79-018 R3/05/10 DENTON, HR Office of Nuclear Reactor Regulation. Director 2pp 18436-339 24X Fiche 50-000,83/05/10,8305130038
- 8305130039 Forwards supplemental info to 821012 response to NUREO-0737. Item II 8 3. "Post-Accident Sampling Sys " Response to NRC Question 9(b) not presently available Info will be submitted by 830615

 BAYNE, J P Power Authority of the State of New York IPN-83-38
 B3/05/10 EISENHUT, D 9. Division of Licensing 16pp 18437 010
 24X Fiche 50-286,83/05/10,8305130039
- B305130054 Ack receipt of B21103 ltr re intention to complete Phase II of control of heavy loads issue (NUREG-0612) Final technical evaluation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested GARRITY.J.H. Maine Yankee Atomic Power Co MN-B3-94 B3/05/10. CLARK.R A Operating Reactors Branch 3 2pp 18437 031 24X Fiche. 50-309, B3/05/10, B303130054
- 83051300A7 Advises that util endorses Rev 3 to BAM-10072P & BAM-10154P as response to NUREO-0737. Item II K 3 30. "Revised Small Break LOCA Methods to Show Compliance W/10CFR50.App K " Work on item will not commence until repts approved by NRC MESTAFER.OR Florida Power Corp 3F-0583-07 83/05/07 STOLZ.JF Operating Reactors Branch 4 1p 18436 245 24X Fiche 50-302.83/05/09.8305130067
- 8305130099 Forwards licensee 830428 ltr re emergency feedwater instrumentation & control (EFIC) sys & upgraded auxiliary feedwater sys, NUREO-0737, Items II E 1.2 & II K.2 10 Ltr provides new info on mod completion schedule W/svc list BAXTER, T.A. Bhaw, Pittman, Potts & Troubridge BAXTER, T.A. Sacramento Municipal Utility District B3/05/11 ROSENTHAL.A.B., BUCK.J.H. KDHL.C.N. Atomic Safety and Licensing Appeal Panel 39:18437:223 24X Fiche.50-312,83/05/11,8305130099
- B305130i18 Advises that mods to purge sys not required Sufficient margin exists to allow check valve to perform intended safety function. Item closes out 5% of rated thermal power sportion of License Condition 2 C.8

 URBIG.R E Florida Power & Light Co. L-83-286, 83/05/10

 EIBENHUT,D 0. Division of Licensing 2pp 18438,057 24X

 Fiche: 50-389,83/05/10,8305130118
- 8305130146 Lists documentation to be provided re SER Outstanding Issue 3 (NUREG-0853), "Beismic Analysis," per NRC request at 830428 meeting M/Bargent & Lundy in Bethesdam MD. satisfying site-specific spectrum concerns MULLER, 0 E Illinois Power Co. U-0636 83/05/10 BCHWENCER, A Licensing Branch 2. 3pp 18438:124 24X Fiche 50-461.83/05/10, 8305130146.

- 8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept. "Control of Heavy Loads (C-10).Oconee Nuclear Power Station, Units 1.2 & 3 " Phase I actions acceptable per NUREG-0612 STOLZ.J F Operating Reactors Branch 4 83/04/20 TUCKER.H B Oute Power Co 3pp 18457 179 24X Fiche 50-269.83/04/20, 8305130294
- --8305130296 Safety evaluation supporting Phase 1 actions re control of heavy loads (NUREG-0612) * Office of Nuclear Reactor Regulation, Director 83/04/20 ip 18457 182 24X Fiche 50-269.83/04/20.8303130294
- --8304070286 TER-C5506-374/375/37

 "Control of Heavy Loads (C-10). Deonee Nuclear Power Station Units 1.2 & 3." technical evaluation rept RDSERTS. S Franklin Institute/Franklin Research Center NRC-03-81-120 TAC 08065 83/03/31 CLEMENSON.F NRC No Detailed Affiliation Given 28pp 18437 183 24X Fiche 50-269,83/04/20,8305130294
- 8305130326 Comments on NUREG/CR-3324 items Unprotected transient overpower accident & unprotected loss-of-flow accident should be reviewed at ACRS full committee meeting KASTENBERG, W E ACRS Advisory Committee on Reactor Safeguards 83/03/28 CARBON, M ACRS Advisory Committee on Reactor Safeguards 4pp 18457 303
- B305130341 NUREO/CR-3114 ERR
 PROCEEDINGS OF MORKSHOP ON COGNITIVE MODELING OF NUCLEAR
 PLANT CONTROL ROOM OPERATORS August 15-18,1982, Dedham,
 Massachusetts
 Oak Ridge National Laboratory ORNL/TM-8614 83/03/10 Office
 of Nuclear Regulatory Research, Director 1p 18443 332
- 8305160015 Submits schedule for providing info re NUREO-0737. Item II 8 3, "Post-Accident Sampling Capability "Formal procedure for relating radionuclide contentrations to core damage expected by startup from 1984 refueling outage MANOAN.C V Niagara Mohawk Power Corp 83/05/11 EISENHUT.D 0 Division of Licensing ip 18453 162 24X Fiche 50-220.89/05/11, 8305160015
- 8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737. Item III A 2 litem complete CRUTCHFIELD, D Operating Reactors Branch 5 & 505-83-05-03 83/05/13 CDUNSIL'N G Connecticut Yankee Atomic Power Co 4p 18452 347 24X Fiche 50-000, 83/05/13, B305160028
- 8305160041 Forwards marked-up FSAR pages describing equipment for sampling & monitoring process & effluent streams during postulated accidents Submittal closes out commitment in Section 11 5 2 (Page 11-14) of SER NUREO-0872

 BOUCHEY. Q D Washington Public Power Supply System GO2-83-417

 B3/05/10 BCHWENCER. A Licensing Branch 2 20pp 18444'009 24X

 Fiche 50-397.83/05/10.8305160041
- 8305160059 Clarifies commitments re timing for completion of preoperational testing of auxiliary bldg ventilation sys Review of SER.NUREG-OB76, indicates misunderstanding may exist
 TRAMM.TR Commonwealth Edison Co 6554N 83/05/11 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 18453 118 24X Fiche 50-454.83/05/11.8305160059
- 8305160195 Add1 response to FOIA request for all documents dtd 820101 datailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress FELTON, J M Division of Rules and Records 83/03/31 CLARK, R A 8am Francisco Examiner 2pp, 18462 171 24X Fiche 50-312.83/03/31, 8305160195
- --8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility GIBSON.J Standardization & Special Projects Branch 82/10/18 MINER, S Operating Reactors Branch 4 2pp 18462 194 24% Fichs. 50-312, 83/03/31, 8305160195
- 8305170048 Advises that NUREO-0737. Item III A 2 1. "Amend 10CFR50 & App E," considered complete following comprehensive 2-wk onsite emergency preparedness appraisal VARQA; S A Operating Reactors Branch 1 83/05/11 UTLEY, E Carolina Power & Light Co 3pp 18494 IB1 24X Fiche 30-261, 83/05/11, 8305170048
- 8305170037 NUREQ-0748 S01
 8AFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Ducket No 50-537. (U S Department of Energy, Tennessee Valley Authority And Project Management Corporation)

 * Clinch River Breeder Reactor Program Office 83/05/31 36pp 18473.159 24X Fiche: 50-537, 83/05/31; 8305170057

B305170064 Responds to B30412 petition & O418 amend, requesting that NRC order PSE&O to show cause why facility restart should not be restrained Petition denied based on encl Director's Decision DENTON.H R Office of Nuclear Reactor Regulation, Director B3/04/27 RODRIGUEZ.J H New Jersey, State of 3pp 18494 184 24X Fiche 50-272,83/04/29,8305170064

--B305170095 Bafety evaluation re restart of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue # Office of Nuclear Reactor Regulation, Director DD-83-06 B3/04/28 45pp 18494 195 24X Fiche 50-272,83/04/29,8305170064

8305170096 NUREG/CR-3240
COMPARISON OF CRBR DESIGN BASIS EVENTS WITH THOSE OF
FOREIGN LMFBR PLANTS
AORAHAL.A K Brookhaven National Laboratory FIN A-3364
BNL-NUREG-31669 83/04/30 Clinch River Breeder Reactor Program
Office 85pp Available at NRC \$5 00 18493'193 24X
Fiche 50-537,83/04/30.8305170086

8305170088 NUREG-0580 V12 NO4
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of April
30,1983 (Blue Boot)
* Maragement Information Branch 83/05/31 68pp 18493 277

8305170092 NUREG-0800 R04
BTANDARD REVIEW PLAN Proposed Revision 4 To 6 2 2.
Containment Heat Removal Systems
Office of Nuclear Reactor Regulation. Director PSRP-6 2 2 R4
83/05/16 10pp 18475 308

8305170093 Board Notification 83-62 forwards NRC evaluation team independent assessment of installed safety-related equipment H/o rept NOVAK, T M Division of Licensing 83/05/10 Atomic Bafety and Licensing Appeal Panel 7pp 18495 317 24X Fiche 50-358:83/09/10.

--8305170098 Forwards NRC evaluation team rept (NUREC-0969) re onsite hardware evaluation conducted 830124-0304 M/o encl DIRCKS! W J Office of the Executive Director for Operations 83/05/04 PALLADINO! OF JINSKY! V A HEARNEL J Commissioners ip. 18495 323 RAX Fiche 50-358.83/05/10.8305170093

8305170096 NUREG-0887 803
84FETY EVALUATION REPORT RELATED TO OPERATION OF THE PERRY
NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And
50-441 (Cleveland Electric Illuminating Company)
9 Office of Nuclear Reactor Regulation, Director 83/04/30 75pp
18492 303 24X Fiche 50-440.83/04/30,8305170096

B305170101 NUREG/CR-2482 VO2
REVIEW OF DEE WASTE PACKAGE PROGRAM Subtask I 1 — National
Waste Package Program Parts 1 And 2
SISKIND, B. HSIEH, D. BHAD, J. Brootheven National Laboratory FIN
A-3164 BNL-NUREG-51494 83/04/30 Division of Waste Management
129pp Available at NRC \$6.00 18477.087

8305170118 NUREG-0897 FC
CONTAINMENT EMERGENCY SUMP PERFORMANCE Technical Findings
Related To Unresolved Safety Issue A-43
SERKIZ,A W Division of Safety Technology 83/04/30 127pp
18493 007

8305170121 NUREG/CR-3173 NEW MADRID SEISMOTECTONIC STUDY Summary Of Activities 1977-1981 BUSCHBACH.T C. St Løvis Univ , St Louis, MD 83/03/31, Division of Health, Siting & Weste Management 214pp Available at NRC \$7 00 18480 209

B305170122 NUREO/CR-3235 VOI
TECHNICAL ABSISTANCE FOR REGULATORY DEVELOPMENT REVIEW AND
EVALUATION OF THE DRAFT EPA STANDARD 40CFR191 FOR DISPOSAL
OF HION-LEVEL WASTE
ORTIZ:N R Sandia Laboratories WAHI,K K Science Applications,
Inc FIN A-1145 BAND82-1557 B3704/30 Division of Waste
Management 22pp Available at NRC #3 25 18493 136

8305170123 NUREG-0869 FC
USI A-43 RESOLUTION POSITIONS
SERKIZ, A W Division of Safety Technology 83/04/30 74pp
18494 029

B30517012B NUREQ-0020 V07 NO1 LICEMBED OPERATINO REACTORS BYATUS SUMMARY REPORT Data As Of December 31.1952 (Oray Book) * Management Information Branch. 83/01/31 391pp 18478 074. B305170132 NUREO/CR-3235 VO2-04
TECHNICAL ASSIBTANCE FOR REGULATORY DEVELOPMENT REVIEW AND EVALUATION OF THE DRAFT EPA BTANDARD 40CFR191 FOR DIBPOBAL OF HIGH-LEVEL WABTE

* Sandia Laboratories FIN A-1165 SANDB2-1557 83/04/30
Division of Waste Management 316pp Available at NRC \$9 00, 18479 253

8305170135 NUREQ/CR-3235 VO5-06
TECHNICAL ABSISTANCE FOR REQULATORY DEVELOPMENT REVIEW AND
EVALUATION OF THE DRAFT EPA STANDARD 40CFR191 FOR DISPOSAL
OF HIGH-LEVEL WASTE
* Sandia Laboratories FIN A-1165 SANDB2-1557 83/04/30
Division of Waste Management 146pp Available at NRC 66.50,
18479 107

8305170137 NUREG/BR-0025 V09 N4 INFORMATION REPORT ON STATE LEGISLATION KERR, Q W Office of State Programs, Director 83/05/31 14pp, 18494,001

B305170149 NUREO-0972

DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARDN HARRIS NUCLEAR POMER PLANT UNITS 1 AND 2 Docket Nos STN 50-400 And STN 50-401 (Carolina Power And Light Company) Office of Nuclear Reactor Regulation, Director. B3/04/30 220pp. 18477:216 24X Fiche 50-400.83/04/30,8305170149

830370150 Forwards add1 info requested in 830302 ltr re PDRV/8V failures & challenges Further ref should be made to 820625 response to NUREO-0737. Item II D 1 OIEBLER: C W Hisconsin Public Bervice Corp NRC-83-108 83/05/13 VAROA, B A Operating Reactors Branch 1 3pp 18466-291, 24X Fiche 50-305,83/05/13,8305170150

8305170218 Forwards response to 830208 & 0317 requests for add1 info re NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Mater Level Monitor" & II F 1.6, "Containment Hydrogen Monitor" LENTINE: F G Commonwealth Edison Co 6366N 83/03/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director Spp 18466 332, 24% Fiche 50-275,83/05/13,83/05/10218

B305/70232 SECY-B3-15B
Informs Commission of findings of Salem ATWS generic
implications task force we overall mpt capability &
performance & reactor trip sys reliability
DIRCKS, M J. Office of the Executive Director for Operations.
B3/05/02 159pp 18476 184 24X Fiche 50-272, B3/05/02, B305170232

8305170346 Forwards IE Insp Rept 50-397/83-13 on 830404-08 No noncompliance noted STERNBERO, D M Region 5, Office of Director. 83/04/19 CARLISLE: C 8 Washington Public Power Supply System 2pp 18465 268 24X Fiche 50-397,83/04/19,830517034

--8305170349 IE Insp Rept 50-397/83-13 on 830404-08 No noncompliance noted Major areas inspected preoperational test program open items. IE builetin/circular response: TMI (NUREO-0737) activities & independent insp WILLETT, D J , DODDS, R T Region 5: Office of Director IEB-82-04 83/04/19 3pp 18465, 270 24X Fiche 50-397, 83/04/19, 8305170346

8305170369 Comments on NUREO-0737. Item III A 2.1: "Emergency Preparedness. Upgrade Emergency Plans to App E, 10CFR50 " Onsite & offsite emergency preparedness adequate. Item completa CRUTCHFIELD. D Operating Reactors Branch 5 LB05-83-05-036. 83/05/16 VANDEWALLE, D J. Consumers Power Co. 5pp 18466-077. 24X Fiche 50-155.83/05/16.8305170367

8303170416 Notifies that onsite & offsite emergency preparedness adequats. NUREQ-0737, Item III. A 2. i, "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR50," complete CRUTCHFIELD. B Operating Reactors Branch 5, L805-83-05-037 83/05/16 LINDER,F Dairyland Power Cooperative 3pp 18469:250. 24X Fiche. 30-409. 83/05/16, 8305170416

8305170439 forwards proposed schedule for resolution of 8EF integrated assessment open items identified in NUREG-0825, "Integrated Plant Bafety Assessment" NRC will be informed immediately of any schedular difficulties
KAY, J. A. Yankse Atomic Electric Co. FYR83-48 83/05/02
CRUTCHFIELD, D. Operating Reactors Branch 5. 5pp. 18469, 321 24%
Fichs 50-029,83/05/02,8305170459

8305170471 Responds to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re
smergency response capability requirements, Progress in areas
of safety parameter displey sys, detailed control room design
reviews & emergency response facilities summarized
BASKIN.X P Southern California Edison Co GL-82-33. 83/05/13.
EISENNUT; D Q. Office of Nuclear Reactor Regulation, Director Bpp
18470 077 24X Fiche 50-361,83/05/13,8305170471

ł

- B305170496 Forwards IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted
 B00K:H E Region 5, Office of Director 83/04/22 CRANE,P A
 Pacific Gas & Electric Co 2pp 18470 045 24X
 Fiche 50-275,83/04/22,8305170496
- --8305170501 IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted Mejor areas inspected implementation of NUREG-0737, Item II F I, "Addi Accident Monitoring
 - Instrumentation "
 QARCIA.E H. MENBLAWSKI,F A., BOOK, H E Region 5, Office of Director 83/04/22 7pp 18470 Q47 24X Fiche 50-275,83/04/22,8305170496
- B305170515 Forwards IE Inep Repts 50-361/B3-14 & 50-362/B3-14 on 830321-30 & notice of violation BCARANO, R A. Division of Radiological Safety & Safeguards Program 83/04/18, PAPAY, L T Southern California Edison Co 2pp 18467 260 24X Fiche 50-361,83/04/18,8305170515
- --8305170330 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 Noncompliance noted failure to perform surveys, inform workers & properly monitor liquid radioactive effluent release
 YUHAS, Q F, WENSLAWSKI, F A, BODK, H E Region 5, Office of Director 50-362/83-14 83/04/14 iOpp 18467 R64 24X Fiche 50-361, 83/04/18, 8305170515
- B305170556 Forwards SER Suppl 1 (NUREG-0954) W/o enc1 JOHNSON.0 E Hearing Branch 4 B3/05/16 KELLEY,J L , FOSTER,R F , CALLIHAN,D. Atomic Safety and Licensing Board Panel ip 18468,160 24% Fiche: 50-413,83/05/16,8305170556
- 8305170579 NUREO-0837 VO2 NOSER
 NRC TLD DIRECT RADIATION MONITORING NETHORK Progress Report,
 July September 1982,

 Division of Technical Information & Document Control. 83/04/28
 1p. 18496.115
- 8305170668 NUREQ-0896 S01

 8AFETY EVALUATION REPORT RELATED TO THE OPERATION OF

 8EABROOK STATION, UNITS 1 AND 2 Docket Nos 50-443 And

 50-444. (Public Service Company of New Hampshireset al)

 * Division of Licensing, 83/04/30 32pp Available at NRC

 84.50 18481 332, 24% Fichs 50-443,83/04/30.8305170668
- B305170674 NUREQ-1000 VOI

 QENERIC IMPLICATIONS OF ATHS EVENTS AT THE BALEM NUCLEAR
 PUMER PLANT Generic Implications

 * Office of Nuclear Reactor Regulation, Director B3/04/30 149pp.
 Available at NRC, \$6.50 18481.183 24X Fiche:50-272,83/04/30,
 B305170674
- B305170712 NUREG-0954 S01

 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAMBA
 NUCLEAR STATION, UNITE 1 AND 2 Docket Nos 50-419 And 50-414
 (Duke Fower Company. et al)

 B Division of Licensing. 83/04/30 56pp Available at NRC
 64.75, 18481.126 24X Fiche 50-419.83/04/30,8305170712
- B305180081 Forwards Amend 90 to License DPR-49 & notice of issuance & availability Amend deletes requirements for shift technical advisor to be on duty during refueling per TMI Action Item I. A i 1 VASBALLO.D B. Operating Reactors Branch 2 83/05/03. ARNOLD.D lows Electric Light & Power Co. 3pp. 18503;270 24% Fiche: 50-331,83/05/03,8305180081
- ---8305180091 Amend 90 to License DPR-49, deleting requirement for thift technical advisor to be on duty during refueling per TMI Action Item I.A i.i VABBALLO, D B. Operating Reactors Branch 2, 83/05/03, 4pp 18503:273 24X Fiche 50-331,83/05/03,8305180081.
- 8305180161 Informs that NUREO-0737. Item III.A 2 1, "Emergency Preparedness. Upgrade Emergency Plans to App E.10CFR50." complete.

 BTOLZ.JF Operating Reactors Branch 4, CLARK.R A. Operating Reactors Branch 3 83/05/11 GRIFFIN.J M. Arkansas Power & Light Co. 3pp 18502 348 24X Fiche 50-313.83/05/11.8305180161
- 8305180169 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREQ-0737, Item III A 2 1 requirements complete.
 VAROA: 8 A. Operating Reactors Branch 1, 83/05/13 BTEMART, W. L. Virginia Electric & Power Co 3pp 18502:351 24X Fiche: 50-280, 83/05/13,8305180169
- 8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review," Supple I & II
 BHARTZ.E.D Commonwealth Edison Co. 6546N 83/05/09 DENTON, N R
 Office of Nuclear Reactor Regulation, Director 1p 18487:001 24X
 Fiche 50-000,83/05/09,8305180385.

- --8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review."
 Supply I & II

 * Commonwealth Edison Co 83/04/30 22ipp 18487 002 24X
 Fishe 50-000,83/05/09,8305180385
- B305180433 Forwards safety evaluation re BHR Owners Group B01230 response to NUREO-0737, Item II K 3 45. "Depressurization H/Other Than Automatic Depressurization Bys " No mods required CRUICHFIELD, D. Operating Reactors Branch 5 LS05-B3-05-041 B3/05/17 FIEDLER.P.B General Public Utilities GPU Service Corp 2pp 18486 195 24X Fichs 50-217, B3/05/17, B3051B0433
- --B305180440 Bafety evaluation of BMR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys" No mods required a Operating Reactors Branch 5 83/05/17 4pp 18486 197 24X Fiche 50-219,83/05/17,8305180433.
- 8305180468 Forwards responses to NRC conterns raised at 830218 meeting w/util to close out open items re emergency feedwater control sys, per NUREO-0787. Suppl 1 W/23 oversize drawings Aperture cards are available in FDR MAURIN.L V Louisians Power & Light Co W3P83-1484 83/05/13 KNISHTON.O W Licensing Branch 3 31pp 18482 131 24% Fiche 50-382,83/05/13.8305180468
- 8305180547 Forwards order extending completion date for installation of plant mods needed to comply w/NUREQ-0641 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
 VABSALLO, D B Operating Reactors Branch 2 83/05/05 PILANT, J M Nebraska Public Power District 2pp 18505 084 24X Fiche 50-298, 83/05/05, 8305180547
- --B305180548 Order modifying 810113 & 820915 orders, extending completion date for installation of plant mods needed to comply W/NUREG-0661 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
 PURPLE:R A Division of Licensing. 83/05/05 Nebraska Public Power District 4pp 18505 086 24X Fiche 50-298.83/05/05.
- 8305180563 Forwards revised order establishing 830930 completion date for implementing NUREQ-0737, Items II 8 3 re post-accident sampling & II F i 1 & II F i 5 re accident monitoring VASSALLO, D B Operating Reactors Branch 2 83/05/05 UTLEY, E E Capolina Power & Light Co. 2pp 18504 354 24X Fiche 50-324, 83/05/05, 8305180563
- --8305180546 Revised order confirming licenses commitments to implement NUREO-0737. Items II B.3 re-post-accident sampling & II F.1 i & II F i 5 re-accident monitoring.by 8309300 PURPLE.R A Division of Licensing. 83/05/05 Carolina Power & Light Co 5pp 18504 356 24X Fiche.50-324,83/05/05,8305180563
- 8305180568 Informs that emergency plan upgrade to meet IOCfR50 App E, NUREG-0737, Item III. A 2 1, complete Item closed VAROA.S. A Depreting Reactors Branch 1 83/05/13. UHRIG.R E Florida Power & Light Co 3pp 18505 275 24X Fichs 50~250, 83/05/13, 8305180368
- 8305180573 Forwards SER supporting licensee responses to NUREO-0737, Items II F i 4, "Containment Pressure Monitor," II F i 5, "Containment Water Level Monitor," & II F i 6, "Containment Hydrogen Monitor "
 VAROA: 8 A Operating Reactors Branch 1 83/05/02 GIESLER, C W Wisconsin Public Services Corp 2pp 18505 308 24X Fiche 50-305, 83/05/02, 83/05180573,
- ---8305180580 Safety evaluation supporting licensee responses to NUREO-0737. Items II, F: 4, "Containment Pressure Monitor:"
 II F: 15, "Containment Hater Level Monitor:" & II F: 1, 6, "Containment Hydrogen Monitor."
 * Office of Nuclear Reactor Regulation, Director. 83/05/02 4pp 18505:310 24% Fiche 50-305;83/05/02.8305180573
- 8303180491 Forwards revised order modifying completion dates for NUREG-0737. Items II B 2, "Plant Bhielding," II B 3, "Post Accident Sampling" & II F i 2, "Accident Monitoring Instrumentation" VARGA. S.A. Operating Reactors Branch i B3/04/28 FARRAR. D.L. Commonwealth Edison Co. 2pp. 18305-181 24X Fiche: 50-275,83/04/28,8303180691.
- ---B305180702 Revised order modifying campletion dates for NUREQ-0737, Items II B.2. "Plent Shielding," II B 3. "Post-Accident Sampling" & II F 12. "Accident Monitoring Instrumentation," per Generic Ltrs B2-05 & 82-10
 EIBENHUT, D 0 Division of Licensing CL-82-05 83/04/28. Commonwealth Edison Cp 9pp 18505.183 24X
 Fiche 50-295,83/04/28.8305180491

- 8305180745 Informs that NUREG-0737. Item III A 2 1, "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR30." completed Item closed # Operating Reactors Branch 1 83/05/13 DDLAN. J Indiana & Nichigan Electric Co 2pp 18506 045 24X Fiche 30-315.83/05/13. 8305180745
- B305180782 NUREG/CR-3016
 EVALUATION OF THE SPLIT-H APPROACH TO MODELING NON-BUOYANT
 RELEASES FROM VENT STACKS
 RAMSDELL, J V Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN B-2514 PNL-4516 B3/04/30 Division of Systems
 Integration (post B11005). 49pp Available at NRC \$4.75
- B3051B0796 NUREO-0741
 THE NRC'S LIMIT ON INTAKE OF URANIUM DRE DUST
 MCOUIRE,S A Division of Facility Operations B3/04/30 30pp
 Available at NRC \$3 50 1B504 327
- 8305180854 Forwards safety evaluation of util submittals re NUREQ-0737. Items II F 1 4. II F 1 5 & II F 1 4 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately VARGA: A Operating Reactors Branch 1 83/05/02 UHRIO.R E Florida Power & Light Co 2pp 18506 031 24% Fiche 50-250.83/05/02.8305180854
- --8305:80856 Safety evaluation of util submittals re NUREG-0737, Items II F 1 4 re containment pressure monitor, II F 1 5 on containment water level monitor & II F 1 6 re containment hydrogen monitor Licensee design acceptable # Office of Nuclear Reactor Regulation, Director 83/05/02 5pp. 18506 033 24x Fiche 50-250, 83/03/02, 8305180854
- B305190031 Forwards JE Insp Rept 50-322/83-09 on B30412-15 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 83/05/05 POLLOCK, M S Long Island Lighting Co 2pp 18502 043 24X Fiche 50-322,83/05/05
- ---8305190038 IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted Major areas inspected NUREG-0737 items.followup on previous insp findings & review of licensee controls over portable radio transmissions in plant areas HIGGINS, J T , GALLD.R M Region 1, Office of Director 83/05/03 13pp 18502 045 24X Fiche 50-322.83/05/05.8305190031
- 8305190032 Forwards response to outstanding environ qualification items identified in Section 78 of Suppl & to SER & technical evaluation rept Info supports full power licensing TUCKER: H B Dute Power Co 83705/12 DENTON H R Diffice of Nuclear Reactor Regulation, Director ADENBAM, E. O. Licensing Branch 4 pp 18502 058 24x Fiche 50-370, 83705/12,8305190032
- 8305170076 Advises of NRC evaluation findings of automatic depressurization sys logic mod options in response to TMI Action Item II K 3 18 Util should advise NRC of which action will be implemented & furnish necessary design & info YOUNGRLOOD, B J Licensing Branch 1 83/04/27. EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 174 24X Fiche 50-440,83/04/27,8305190096
- 830517009? Forwards safety evaluation for TMI Action Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage "Training & requalification programs acceptable VABSALLO.D B Operating Reactors Branch 2 83/04/29 UTLEY.E E Carolina Power & Light Co 3pp 18523 175. 24X Fich= 30-324.83/04/29,8305190099.
- B305190147 Discusses issuance of revised policy statement result position on NUREG-0737. Item I.C 6. "Verify Performance of Operating Experience" Policy Will be integrated into existing operations procedure by B30812
 HARRINGION.H D Boston Edison Co B3-126 B3/05/13 VASSALLO.D B Operating Reactors Branch 2 ip 18502 970 24X
 Fiche 50-293.83/05/13.8303190147
- 8305190199 Motion to amend petition to intervene by adding Contention SAPL Suppl 7, "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate of Svc encl
 BACKUS, R A Seaccest Anti-Pollution League BACKUS, R A Backus, Shea & Meyer ISSUANCES DL 83/03/16 Atomic Safety and Licensing Board Panel 5pp 18502 205 24X Fiche 50-443,83/05/16,8303190199

- 8305190253 Informs of status of NUREG-0737, Itam II F 1 3 recontainment high-range radiation monitors Qualified in-containment electrical terminations will be made par IE Bulletin 79-01B NUREG-058B schedule STEMART.W L Vinginia Electric & Power Co IEB-79-01B 83/05/12 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 1p 18501 283 24% Fiche 50-337,83/05/12,8305170253
- B305190343 Forwards Rev i to NUREG-0728, "NRC Incident Response Plan," in response to B30429 itr requesting updated itr of agreement W/o enci
 HIND.J A Division of Radiological & Materials Bafety Programs,
 B3/05/13 LARSON.C E Northern States Power Co 2pp 18500-225,
 24% Fichs 50-000, 83/05/13, 8305190343
- 8305200021 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparadness, Upgrade Emergency Plans to App E. 10CFR30, " completed Item closed CLARK.R A Operating Reactors Branch 3 83/05/12 FAY.C H Misconsin Electric Power Co 3pp 18540 114 24X Fiche 50-266.83/05/12,8305200021
- 8305200023 Notifies that NUREO-0737. Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR30, " completed Item closed CLARK.R A Operating Reactors Branch 3 83/05/13, MUSOLF, D. M Northern States Power Co 3pp 18540 117 24% Fichs 50-282,83/03/13,8305200023
- 8305200030 Notifies that NUREO-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." completed Item closed CLARK.R A Operating Reactors Branch 3 83/05/12 WITHERB.B D. Portland General Electric Co 3pp 18540 120. 24X Fiche 50-344.83/05/12.8305200030
- B305200040 Informs that oneite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, item III A 2 | Item closed CLARK,R A Operating Reactors Branch 3 B3/05/II JONES,N, C Omaba Public Power District Spp 18540 123 24X Fiche 50-285,83/05/II.8305200040
- 830520006B Informs that 830405 methodology submittal re radiation environ for equipment qualification inside containment acceptable, per NUREG-0588 Submittal also provides ref for radiation levels outside containment CLARK, R A Decrating Reactors Branch 3 83/05/13, GARRITY, J H Maine Vankee Atomic Power Ca 2pp 18540 128 24X Fiche 50-307,83/05/13,830520006B
- 8305200090 Notifies that NUREO-0737, Itam III A 2 1, "Emergency Preparedness: Upgrade Emergency Plans to App E.10CFR50," completed Item closed CLARK, R A Operating Reactors Branch 3 83/05/11 UHRIQ, R E Florids Power & Light Co 3pp 18541 001 24X Fiche 50-335,83/05/11,8305200090
- B305200094 Notifies that NUREO-0737, Item III A 2 1, "Emergency Preparedness Upgrade Emergency Plants to App E,10CFR50," completed Item closed CLARK, R A Operating Reactors Branch 3 83/05/10 SYEHART, H L Virginia Electric & Power Co 3pp, 18540 355 24X Fiche 30-338, 83/05/10, 8305200094
- 8305200122 Forwards DES & FR notice H/o DES KNIOHTON/O H Licensing Branch 3 83/05/12 UYLEY/E.E Carolina Power & Light Co. 2pp 18528 346 24X Fiche. 30-400/83/05/12/ 8305200122
- --8305200125 Notice of availability of DES
 KNIGHTON G W Licensing Branch 3 83/05/12 2pp 18528 348
 24% Fiche 50-400,83/05/12,8305200122
- 8305200195 Supports util onsite emergency preparedness & upgraded plan per NUREO-0737. Item III A 2 1, "Emergency Preparedness," Upgrade Emergency Plans to App E, 10CFR50 " Item complete VAROA.S A Operating Reactors Branch 1 83/05/11 CAREY.J J. Duquesne Light Co 3pp 18540 222 24X Fiche 50-334.83/05/11, 8305200175
- B305200198 Draft Commission paper re NRC intention to publish NUREG-0906, "Guidance for Implementation of 10CFR50 34(g)," rule requiring applicants to evaluate differences from BRP. DIRCKS, W J Office of the Executive Director for Operations B3/05/02 2ipp 18540 247

- --0305200204 Forwards draft Commission paper advising of NRC intent to publish NUREO-0906, "Guidance for Implementation of 10CFR30 34(g)"

 DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/21 DIRCKS.W J Office of the Executive Director for Operations 3pp 18540 266
- 8305200244 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREO-0737. Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved VASSALLO, D B Operating Reactors Branch 2 83/05/05 BAYNE, J P Power Authority of the State of New York 5pp 18540 206 24X Fiche 50-333.83/05/05.8305200244
- 8305200435 Forwards revised & reformatted comprehensive list of NUREO-0737 licensing issues containing status & priority assigned for open items IMMERMAN.5 R Carolina Power & Light Co LAP-83-180 83/05/17 VAROA.8 A Operating Reactors Branch 1 lipp 18517 134 24X Fiche 30-261.83/05/17.8303200435
- 8305200502 Forwards master lists & sys component evaluation worksheets for NUREG-0737 environ qualification of electrical equipment mods installed in harsh area HUKILL, H D General Public Utilities GPU Service Corp 5211-83-076 83/05/16 870LZ, J F Operating Reactors Branch 4 83pp 18513.082 24X Fiche 50-289,83/05/16.8305200502
- 8305200316 Forwards order confirming util commitments on post-TMIrelated issues Order based on commitments in util 820317 & 0505 Itrs responding to Generic Ltrs 82-05 & 82-10 MADSEN.O L Region 4. Office of Director GL-82-05 83/04/27 LEE.O R Public Service Co of Colorado 4pp 18516 045 24X Fiche 30-267.83/04/27.8305200516
- --8305200528 Order confirming licensee commitments on post-TMI-related issues Schedule changes acceptable for TMI Items 1 A 3 i, II.8, 2, II B 3, II.8, A II.F i OAGLIARDD, J.E. Division of Resident, Reactor Project & Engineering Programs 83/04/27 Public Service Co of Colorado Ilsp 18816 049 24X Fiche: 50-267, 83/04/27, 8305200516
- B305200517 Forwards list of additions & deletions of safety-related shock suppressors installed to conform w/acceptance criteria in NUREQ-0661, Proposed change to Tech Specs will be submitted by B30601
 SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. FVY B3-37 B3/05/17, V4854LLD, D. B. Operating Reactors Branch 2. 3pp 18516:080 24X Fiche 50-271.83/05/17,8305200517
- 8305200568 Forwards amended Table 3-1 of Section II F. 2. App B reflecting clarification of addressing TMI Action Item II F 2 re inadequate core cooling detection instrumentation. Open Item 4 of CEBBAR-F SER SCHERER. A E Combustion Engineering. Inc. LD-83-046 83/05/13 EIBENHMIT, D Q. Division of Licensing 4pp 18514 279 24X Fiche: 50-470, 83/05/13, 8305200568
- 8303200621 Documents review of procedures & practices used in control of design & conet of Byron Station & highlights important findings Conet of Byron mests requirements of FSAR & BER (NUREO-0876). Supporting documentation encl REED. C. Commonwealth Edison Co 6434N 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche 50-000,83/05/11,8305200621
- --8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREO-0588 re environ qualification of Class IE electrical equipment.
 MARCUS, 0.F Commonwealth Edison Co 81/10/06 App. 18522 150 24X Fichs 50-000.83/05/11,8305200621
- 8305200707 Forwards request for add1 info on NUREO-0737, Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days VABSALLO, D 8 Deprating Reactors Branch 2 83/05/11, FARRAR, D L Commonwealth Edison Co. 3pp 18308 350 24X Fiche: 50-000, 83/05/07/11, 8305200707.
- 8305230005 FDIA request for all correspondence & repts re NRC Contract NRC-17-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp SHOLLY, S C Union of Concerned Scientists FIN 8-8178 NRC-17-82-493, 83/03/11 FELTON, J.M Division of Rules and Records, 1p. 18546.262
- B305230028 Responds to FOIA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Bafety Goals," between NRC Ofc of Policy Evaluation & NUS Corp. Forwards App A documente FELTON.J M Division of Rules and Records FIN 8-8178. NRC-19-82-493 83/03/31, BHOLLY, S.C Union of Concerned Bcientists 2pp. 18546 263

- --8305230037 Comments on NUREO-0880, "Safety Goals for Nuclear Power Plants Discussion Paper," Feb 1982 Proposed policy does not contain independent numerical guideline for early fatality societal risk

 LEVINE, NUS Corp CO-SL-28-82 82/05/26 REMICK, FJ Office of Policy Evaluations 9pp 18346 265
- --8305230047 Advises that S Levine directed to provide followup discussion & advice on safety goals re 820526 written rept & 820715 meeting w/F Remick providing advice on use of PRA, per Article I of Contract NRC-19-82-493 MONTGOMERY, J M Dffice of Policy Evaluations NRC-19-82-493 82/07/19 Office of Policy Evaluations ip 18546-274
- --8305230057 Forwards met1 from 0 Kaiser re calculation of individual & societal risks for comparison w/safety goals Requests meeting w/0 Kaiser & R Dland to discuss differences in predictions of weighted individual risk requested LEVING. S NOS Corp. CO-SL-78-82 82/11/18 ZERBE.J E Office of Policy Evaluations 28pp 18546 275
- 8305230115 Forwards safety evaluation of util submittal re procedure verification & design mod per NURED-0737, Item II K 3 22, "Automatic Switchover of RCIC Suction" I tem resolved VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp 18546 344 24X Fiche 50-271, 63/05/05, 6305230115
- 8305230127 Forwards emergency operating procedures generation package, per NUREG-0737. Suppl I (Generic Ltr 82-33) "Requirements for Emergency Response Capability "
 OARRITY.J H Maine Yankae Atomic Power Co GL-82-33 83/05/17 CLARK,R A Operating Reactors Branch 3 3pp 18531 263 24X Fiche 50-307, 83/05/17, 8305230127
- 8305230128 Forwards BER supporting licensee compliance w/NUREG-0737, Item II B 2 2, "Required Plant Mods." & design review of plant shielding requirements for access to vital areas CLARKR A Operating Reactors Branch 3 8TOLZ, JF Operating Reactors Branch 4 83/05/11 GRIFFIN, J M Arkansas Power & Light Co 2pp 18546 347 24X Fiche 50-313,83/05/11.8305230128
- ~-8305230145 Safety evaluation supporting licensee compliance w/NUREG-0737. Item II 8 2, "Design Review of Plant Shielding Access to Vital Areas "

 * Office of Nuclear Reactor Regulation, Director 83/05/11 2pp 18546 351 24X Fiche: 50-313,83/05/11,8305230128
- 8305230230 Advises that Tech Specs from Amends 47 & 36 rs auxiliary feedwater sys surveillance satisfy open item noted in 820702 SER on NUREO-0737. Item II E I 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication " VAR9A:S A Operating Reactors Branch I GL-82-16 83/05/16 CARFY, J Duquesne Light Co 2pp i8543 i52 24X Fichs 50-334,83/05/16,8305230230.
- 8305230242 Forwards safety evaluation of util 820831 submittal reprocedure verification & design mod per NUREQ-0737, Item II, K 3 22, "Automatic Switchover of RCIC Suction" Requirements met VA88ALLO.D B Operating Reactors Branch 2 83/05/05 PILANT, J M Nebraska Public Pawer District 5pp 18543 232 24X Fiche 50-298,83/05/05,8305230242
- 8303230248 Forwards safety evaluation supporting resolution of NUREG-0737. Item II K 3 22. "Automatic Switchover of RCIC Suction," based on review of util 811231 & 820708 submittals re-procedure verification & design mod VASSALLO, D D Operating Reactors Branch 2 83/05/05 MUSOLF, D M Northern States Power Co. 5pp 18543 244 24X Fiche 50-263, 83/05/05, 8305230248
- 8305230276 Forwards "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept Response within 60 days of racelpt of ltr requested CRUTCHFIELD D Operating Reactors Branch 5 LSO5-83-05-044 83/05/19. COUNSILW 0 Connecticut Yankee Atomic Power Co 2pp 18539 006. 24X Fiche 50-213,83/05/19.8305230276
- --8305230284 TER-C5506-358 DRFT
 "Control of Heavy Loads (C-10) Haddam Neck Plant," draft
 technical evaluation rept
 BOMBERGER, C., AHMED, N. Franklin Institute/Franklin Research
 Center NRC-03-81-130 93/02/15 CLEMENSON, F. NRC No Detailed
 Affiliation Given 35pp 18539 008 24X Ficha 50-213,83/05/19,
 8308320276
- 8305230279 Forwards safety evaluation of plant mods & design review of shielding for vital areas per NUREG-0737, Item II B 2 2 Required mods completed & acceptable.

 VASBALLO, D B Operating Reactors Branch 2 83/05/05 BINCLAIR, J B Vermont Yankes Nuclear Power Corp 5pp 18543 268 24% Fiche 50-271, 89/05/05, 8305230879

- 8305230312 Forwards request for add1 info needed to complete review of util 810515 response to NUREO-0737. Item II K 3 28, "Qualification of ADS Accumulators " Response requested within 45 days of receipt of ltr VASSALLO.D B Operating Reactors Branch 2 83/05/11 SINCLAIR.J B Vermont Yankee Nuclear Power Corp 3pp 18543 301 24X Fiche 30-271.83/05/11.8305230312
- B305R30323 Forwards emergency procedures generation package containing procedure guidelines, writers guide & training program in response to NUREO-0737. Suppl 1 (Generic Ltr B2-33).

 "Requirements for Emergency Response Capability "
 COUNSIL N O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL N O Northeast Utilities A02757 B3/05/13 CRUTCHFIELD. D Operating Reactors Branch 5 19 18538 264 24X Fiche 30-245.03/05/13.8303230323
- 8305230503 Summary of CRGR Meeting 35 on 830425 re Balem Generic Implications Task Force findings.per NUREG-1000 STELLD, V Committee to Review Generic Requirements 83/05/13 DIRCKS, W J Office of the Executive Director for Operations App 18537 164
- B305230541 Advises that util endorses BWR Quners Group rept NEDO-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity "Proposed amend to License NPF-14 will be submitted to reflect position CURTIS:N W Pennsylvania Power & Light Ca PLA-1669 B3/05/19 SCHHENCER, A Licensing Branch 2 2pp 18537 335 24X Fiche 50-387.83/05/19, B305230541
- 8305230583 Forwards backfit cost info in response to 830208 ltr Two
 3,500 kW standby diesel generators, diesel generator bldg,
 auxiliary bldg addition, associated electrical equipment &
 new computer sys added per NUREG-0737
 MATTIMDE, J J Sacramento Municipal Utility District 83/03/16
 TQURIELLOTTE, J Regulatory Reform Task Force 4pp 18541 318 24X
 Fiche 50-312,83/03/16,8305230583
- 8305220639 Advises that NRC has considered & reviewed constituent HD Turner comments on 830228 New Yorker magazine article on sefety goal program Histarding impressions corrected DIRCKS-W J Office of the Executive Director for Operations 83/05/05 JACKSON:H M Senate 22pp 18576-336
- 8305230645 Forwards NUREG-0887, Suppl 3 to SER N/o and YOUNGBLOOD, B J Licensing Branch 1 83/03/09 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18542 360 24X Ficha 50-440,83/05/09,8305230645
- 8305240015 NUREC/CR-3230
 EFFECTS OF TEMPERATURE ON FATIOUE CRACK GROWTH OF A508-2
 STEEL IN LHR ENVIRONMENT
 CULLEN,W H Materials Engineering Testing Services. Inc
 TORRONEN,K, DEMPPAINEN,M Finland FIN 8-8133 MEA-2013
 83/04/30 Division of Engineering Technology 38pp Available at
 NRC #4 50 18594 172
- 8305240022 Forwards Suppl 2 to SER (NUREG-096B) re evaluation of addinfo on previously identified outstanding review items GRACE, J N Clinch River Breeder Reactor Program Office 83/05/20, LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 16pp 18577 314 24X Fiche 50-537,83/05/20,8305240022.
- 8305240036 Forwards request for OMB review & supporting statement re NUREG-0737/TMI action plan NURRY.P G. Diffice of Administration 83/05/19 SCURRY.N Diffice of Management & Budget tp 18394 260
- 8305240195 Forwards summary of NUREQ-0737 Tech Spec review to determine consistency w/guidance criteria provided in 830110 Generic Ltr 83-02 SINCLAIR, J B Vermont Yankee Nuclear Power Corp GL-83-02. 837057/7 VASSALLO,D B Operating Reactors Branch 2 5pp 18548 032 24X Fiche 50-271,83705/17,8305240195

- B305240198 Provides info re emergency operations facility in response to NRC request When control room HVAC is upgraded as result of NUREO-0737. Item III D 3 4. technical support ctr HVAC will be reviewed to ensure uniformity of design BASKIN, K P Southern California Edison Co 83/05/20 CRUTCHFIELD. D Operating Reactors Branch 5 2pp 18548 010 24x Fiche 50-206,83/05/20,8305240198
- B305240246 Advises that requirements of NUREQ-0737. Item III A. 2 i.
 "Emergency Preparedness, Upgrade Emergency Plans to Meet
 App E to 10CFR30." satisfied
 VARGA.B A Operating Reactors Branch 1 B3/05/16 FARRAR.D L
 Commonwealth Edison Co 3pp 18393 303 24X Fiche 50-293.83/05/16.
 B305240246
- B305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREO/CR-1659, Vois 1-4) & Interim Reliability Evaluation Program (NUREO/CR-2515, 2787 & 2802) SHOLLY, 8 C Union of Concerned Scientists B3/03/11 FELTON, J. H. Division of Rules and Records ip 18593 178 24X Fiche 50-000, 83/03/11, 8305240249
- 8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress. FELTON.J M. Division of Rules and Records. 83/03/31 SHOLLY.B.C Union of Concerned Scientists 2pp 18593 179 24X Fiche 50-000.83/03/31.8305240254
- B305240284 Forwards IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted PAPERIELLO:C J Region 3. Office of Director 83/05/18, LIU.L Iowa Electric Light & Power Co 2pp 18548 088 24X Fichs 50-331.83/05/18.8305240284
- --B305240292 IE Insp Rept 50-331/B3-05 on B30321-25 No noncompliance noted Major areas inspected radiation protection program for operation & refueling, including organization & staffing, staff qualifications, training & outage planning.
 HUSTER.L J. PAUL.R A. GREGER,L R. Region 3, Office of Director, B3/05/17 17pp 18548 090 24X Fiche 50-331,83/05/18,8305240284
- B30524032B Forwards, "Identification & Listing of Electrical Equipment Important to Safety per 10CFR50, 49 " Nonsafety-related electric equipment w/failure that would prohibit accomplishment of safety functions not identified BAYNE, J P Power Authority of the State of New York IPN-B3-45 B3/05/20 VARQA, S A Operating Reactors Branch 1 36pp. 18549 239 24% Fiche 50-286, B3/05/20, B30524032B
- B305240343 Withdraws commitment re NUREO-0737, Item I A I 3, "Licensing Exam Criteria " Recommendations to delete requirement for use of simulator exam as part of operator license exam program approved per 821012 Generic Ltr 82-18 & 8ECY 82-232 HEIDER, L H Vermont Yenkee Nuclear Power Corp 2 C 2 1. 83/05/19 VASSALLO, D B Operating Reactors Branch 2 2pp 18572:359 24X Fiche 50-271,83/05/19,8305240343
- 8305240360 Informs that response to NUREQ-0737, Item II. E.1 2, "Emergency Fredwater Bys Automatic Initiation & Flow Indication" per 830411 request, will be provided by 830614, Change discussed w/E Tourigny MARSMALL. J R Arkansas Power & Light Co 2CAN058306 83/05/17 CLARK, R A Operating Reactors Brench 3 1p. 18574'002 24X Fiche 50-368,83/05/17,8305240360
- B305240372 Forwards responses to NRC B30118 request for info reaccident monitoring, to aid in post-implementation review of NUREO-0737. Items II F 1 4, II F 1 5 & II F 1.6.

 UHRIO,R E Florida Power & Light Co L-83-10 83/05/19.

 CLARK,R.A Operating Reactors Branch 3 17pp 18575 078 24)
 Fiche 50-335,83/05/19,8305240372
- B305240399 Discusses B30315 commitment to provide results of B&W supplemental ECCS calculations addressing impact of cladding models presented in NUREG-0630. "Results of Bounding Analysis" Revised NUREO-0630 being prepared by B&W MARSHALL.J R Arkansas Power & Light Co. ICANO36904 83/05/18 ST0LZ.J F Operating Reactors Branch 4. 2pp 18571.042, 24X Fichs: 50-313,83/05/18,8305240399
- B305240447 Provides status of implementation of SER recommendations re NUREG-0737, Item II.K 3 16: "Feasability Study -- Challenges & Valve Failures" Preventive maint program will be available for site review in 2 months.

 SHITH, J L Long Island Lighting Co SNRC-893 83/05/20 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 3pp. 18572 338 24% Fiche 50-322,83/05/20,8305740447

- 8305240458 Forwards status of environ qualification of electrical aquipment per 10CFR50 49(g) All equipment except auxiliary feedwater pump motors, meets NUREG-0588 guidelines for Category II plant

 BABKIN, K P Southern California Edison Co 83/05/20 KNIGHTON, G W Licensing Branch 3 5pp 18549 286 24X Fiche 50-361,83/05/20,8305240458
- 8305240557 Informs that NUREO-0737, Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation enc! VASSALLO,D B Operating Reactors Branch 2 83/05/18 MUSOLF,D M Northern States Power Co 7pp 18593 290 24X Fiche 50-263,83/05/18,8305240557
- 9305240560 Informs that NUREO-0737. Item II F 1, "Containment High Range Radiation Monitor," completed Item closed Safety evaluation encl VASSALLO, D B Operating Reactors Branch 2 83/05/13 MORISI, A V Boston Edison Co 4pp 18593 356 24X Fiche 50-293,83/05/13,8305240560
- 8305240564 Informs that NUREQ-0737, Item III A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR30," completed Item closed VA88ALLO, D B Operating Reactors Branch 2 83/05/18 LIU, L Iowa Electric Light & Power Co 3pp 18593 348 24X Fiche 30-331,83/05/18,8305240564
- 9305240571 Notifies that NUREO-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." completed Item closed VASSALLD. D B Operating Reactors Branch 2, 83/03/18 HARRINGTON.H D Boston Edison Co 3pp 19594 217 24K Piche 50-293.83/03/18.8305240571
- B305240572 Informs that NUREQ-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." completed Item closed VABBALLO. D B Operating Reactors Branch 2 83/05/18 MUSDLF. D M Northern States Power Co 3pp 18593 345 24X Fiche. 50-263. 83/05/18. 8305240572
- B305240573 Notifies that NUREO-0737, item II K 3 45, "Depressurization w/Other than Automatic Depressurization Bys," completed Item closed Safety evaluation encl VASSALLOD B Operating Reactors Branch 2 93/05/18 FARRAR, D L Commonwealth Edison Co. 7pp 18573 338 24X Fiche 50-254,83/05/18,8305240573
- B305240574 Informs that NUREO-0737. Item III A 2 1. "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." compileted Item closed VABBALLO.D B Operating Reactors Branch 2 83/05/18 RHODE.O K Niagara Mohawk Power Corp 3pp 18594 214 24X Fiche 50-220.83/05/18.8305240576
- B305240591 Informs that NUREO-0737, Item III.A 2 1, "Emangency Preparedness, Upgrade Energency Plans to App E. 10CFR50," completed Item closed VABBALLO, D B Operating Reactors Branch 2 83/05/18 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp 18594 211 24X Fiche. 30-271, 83/05/18, 8305240591
- 8305230082 Forwards Suppl 3 to SER (NUREQ-0892) W/o encl BCHMENCER: A Licensing Branch 2 B3/05/19 FERQUEON R L. Washington Public Power Bupply Bystem 2pp 18596 307 24X Fiche: 50-397: 83/05/19, 8305250082
- B305250136 Forwards request for add1 info re NUREO-0737, Item 11 K 3 28, "Qualification of ADB Accumulators " Info requested within 45 days.

 VABBALLO, D B Operating Reactors Branch 2 83/05/11 PARRIS, H 0 Tennessee Valley Authority 3pp 18596 204 24X Fiche: 50-259, 83/05/11, 8305280136
- 8305250137 Informs that NUREG-0737 Item III A 2.1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility. Item closed VABSALLO, D B Operating Reactors Branch 2 83/05/18 BAYNE, J. P Power Authority of the State of New York 3pp 18576 201. 24X Fiche: 50-333, 83/05/18, 8305250137
- B305250141 Informs that NUREO-0737, Item III A 2 1 re emergency plan upgrade to meet 100FRBO App E requirements complete for facility Item closed.

 VASBALLO, D B Operating Reactors Branch 2 B3/05/19 FARRAR, D L Commonwealth Edison Co 3pp 18594 198 24X Fiche 50-254,83/05/18,8303250141.

- 8305250145 Informs that NUREG-0737. Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M Nebraska Public Power District 3pp 18396 195 24X Fichs 50-278, 83/05/18, 8305250145
- 8305250166 Forwards Suppl 1 to SER (NUREO-0968) re evaluation of additinfo on previously identified as outstanding review items since preparation of SER Response to comments for ACRS B3D419 rept to Commission also encl W/o encis GRACE.J N Clinch River Breeder Reactor Program Office B3/05/19 LONGENECKER.J Energy, Dept of, Clinch River Breeder Reactor Plant 2pp 18596 140 24X Fichs 50-537.83/05/19.8305250166
- B305250183 Forwards IE Insp Rept 50-289/83-10 on B30420-22 & 25-28 Joint headquarters/Region I insp initiated to evaluate effectiveness of GPU actions to ensure adherence to procedures since issuance of NUREG-0080. Suppl J REHM.T A Office of the Executive Director for Operations B3/05/18 PALLADING, N J , GILINSKY, V , AHEANEJ Commissioners Ip 18596 001 24X Ficho 50-289,83/05/18,8305250183
- 8305250226 Forwards IE Insp Rept 30-286/83-05 on 830328-31 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 83/05/13 BRONS, J C Power Authority of the State of New York 2pp 18627 017 24X Fiche 30-286,83/05/13.8305250226
- --8305250230 IE Insp Rept 50-286/83-05 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements of NUREG-0737. Item II 8 2. "Design Review of Plant Shielding"

 HAVERKAMP.D R , KENNY, T J , EAPEN, P K Region I, Office of Director 83/05/12 12pp 18627 019 24X Fiche 50-286, 83/05/13. 8305230226
- 8305250231 Summary of Power Sys Branch 830405-09 site audit re power supply for auxiliary feedwater sys per SER Confirmatory Issues 15.17 & 23 (Section 1 7 of NUREO-0830) EDISON. Q E , HOLONICH. J J Licensing Branch 1 83/05/12 YOUNOBLOOD. B J Licensing Branch 1 7pp 18627 100 24X Fiche 50-000, 83/05/12, 8305250231
- 8305250266 Forwards Draft 7 of Rev 3 to NUREO-0742. "Std Radiological Effluent Tech Specs for PWRs." as guidance in developing final submission of radiological effluent Tech Specs Tech Specs requested within 60 days M/o encl VASSALLO.D D Operating Reactors Branch 2 83/05/18 PILANT.J M Nebreska Public Power District 2pp 18575 336 24X Fiche 50-278:83/05/18.8305250266
- 8305250285 Forwards response to B30204 SERs & NRC B304(2 ltr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included CLAYTON.F L Alabama Power Co B3/05/20 VARGA.8 A Office of Nuclear Reactor Regulation, Director 118 p 18696 251 24X Fiche 30-348, B3/05/20, B305250285
- 8305250294 Memorandum of law supporting motions for summary disposition of emergency planning issues Hearing time should not be spent on baseless allegations Notice of appearance encl BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Troubridge ISSUANCES OL B3/05/20 Atomic Bafety and Licensing Board Panel 14pp 18585 OOI 24X Fiche 50-483,83/05/20,8309250294
- ---B3052505B7 Affidavit of HM Clark re Reed Contention 20 on authorization of excess exposures to workers & spec of decontamination action levels Planning need for authorization per NUREO-0636 Section IIJ E 3.met Prof qualifications encl CLARK, W M Union Electric Co CLARK, W Callaway County, MD ISSUANCEB DL 83/05/18 7pp 18597 273 24X Fiche 50-483,83/05/20,8305230294
- 8305250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Btation Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B "RYBAK, B Commonwealth Edison Co IEB-79-01B 83/03/17 DENTON, HR Office of Nuclear Reactor Regulation Director. 2.118pp 18378 001 24X Fiche 30-000,83/03/17,8305250377
- 8309250437 Forwards IE Insp Rest 50-245/83-07 on 830411-14 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/05/11 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588 075 24% Fiche 50-245,83/05/11,8305230437

- --B3D5250443 IE insp Rept 50-249/83-07 on 830411-14 No noncompliance noted Major areas inspected actions taken to comply w/NUREQ-0737. Item II B 2, "Design Review of Plant Shielding"

 BRIGGS,L , EAPEN,P , PLISCO,L Region 1, Office of Director 83/05/09 App 18388 077 24% Fiche 50-245,83/05/11,8305250437
- 8308250459 Forwards IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 83/05/11 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588-096 24% Fiche 50-336,83/05/11,8305250459
- --8305250465 IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements discussed in NURG-0737. Item II B 2 re design review of plant shielding LAZARUS.N J. MAVERKAMP.D R. EAPEN.P K. Region i. Office of Director 83/05/09 App 18588 098 24X Fiche 50-336.83/05/11.8305230459
- 8303250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4
 Detailed Control Room Design Reviews Program Plan." per
 830415 commitment re Suppl 1 to NUREO-0737
 UHRIG.R E Florida Power & Light Co L-83-313 83/05/20
 EISENHUT.D G Division of Licensing ip #8588 333 24X
 Fiche 30-000.83/05/20,8305230472
- 8305250479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation.per NUREG-0737.TMI Action Item II B 4 provided Response to IE Bullatin 79-018 will be revised TUCKER.H B Duke Power Co IEB-79-018 83/05/19 DENTGN.H R Office of Nuclear Reactor Regulation. Director 27pp 18589 005 24X Fiche 50-269.83/05/19.8305250479
- 8305250477 Forwards IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted STARDSTECKLIR Division of Project & Resident Programs 83/05/11 COUNSIL W G Connecticut Yankee Atomic Power Co 2pp 18588 255 24X Fiche 50-213
- --8309250504 IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737. Item II 8 2. "Design Review of Plant Shielding"

 BAUNACK, W # , EAPEN, P K , PLISCO, L R Region 1, Office of Director 83/05/10 9pp 18588 257 24X Fiche 50-213,83/05/11,8305250497
- B305250514 Forwards safety evaluation re BWR Owners Group response to NUREG-0737. Item II K 3 45. "Depressurization W/Other Than Automatic Depressurization Sys "Attion on sizem complete VABBALLO.D D Operating Reactors Branch 2 83/05/18 RHODE.G K Niagara Mohawk Power Corp 2pp 18595 310 24X Fiche 50-220.83/05/18.8305250514
- --8305250523 Safety evaluation supporting BMR Duners Group generic response to Item II K 3 45 of NUREG-0737. "Depressuritation W/Other Than Automatic Depressuritation Sys."

 * NRC No Detailed Affillation Given 83/05/18 5pp 18595 312 24X Fiche 50-220.83/05/18.8305250314
- 8305250556 Notifies that noble gas monitor-stack high-renge radiation monitor (NUREO-0737. Item II F 1(1)) reported as being operable in 830318 orders, became imperable on 830426 Caused by molsture contamination New monitors ordered TUCKER.H B Duke Pawer Co 83/05/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18388 185 24X Fiche 30-269.83/05/19.8305250556
- 8305260008 Comments on recent work & proposed programs re accident sequence precursor study & use of operational experience, at 276th & 277th ACRS meetings on 830414-16 & 0312-14 respectively EBERSOLE, J C ACRS Advisory Committee on Reactor Safeguards 83705718 DIRCKS,W J Office of the Executive Director for Operations 7pp 18647 098
- 8305260037 Forwards supplemental responses to Power Sys Branch questions re GESSAR-II ac/dc power sys/balance-of-plant interfaces Responses will be included w/Amend 15 to SER SHERWDDD, G 0 Openeral Electric Co MFN 091-83 83/05/24 EISENHUT. D 0. Division of Licensing 10pp 18622 310 24X Fiche. 50-447. 83/05/24, 8305260037
- --8305260048 Forwards draft Amend 15 to GEGSAR-II Amend resolves selected outstanding & confirmatory issues identified in SER (NUREG-0979) & completes Subsection 1 9 1 on GESSAR-II/FGAR interfaces
 SHERMODD, G G General Electric Co MFN 090-83 83/05/24
 EISENHUT, D G Division of Licensing 446pp 18622 320 24X
 Fiche 50-447.83/05/24.8305260037

- B305260094 Provides info identifying electrical equipment important to safety within scope of 10CFR50 49(g) already qualified BChadules for qualification of post-accident instrumentation enci
 HUKILL.H D General Public Utilities GPU Service Corp
 3211-83-157 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp. 18597 314 24X Fiche 50-289,83/05/20.
- 8305260114 Informs that response to NUREG-0737. Item II K 3 13 re RCIC restart complete for facility, based on B30415 commitment to follow GE Guners Group conceptual design VASBALLO, D B Operating Reactors Branch 2 83/05/20 SINCLAIR, J B Vermont Vankee Nuclear Power Corp 2pp 18649 065 24X Fiche 50-271.83/05/20.8305260114
- 8305240130 Informs that NUREO-0737, Item II K 3 45 re depressurization w/other than automatic depressurization sys would not contribute to plant safety & no plant design or operation mod required Safety evaluation encl VASBALLO, D B Operating Reactors Branch 2 83/05/18 HARRINGTON, W D Boston Edison Co 2pp 18647 052 24X Fiche 50-273,83/05/18,8305260130
- 8305260134 Informs that NUREG-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFR50, App E requirements complete for facility Item closed VASSALLO, D B Operating Reactors Branch 2 83/05/18 UTLEY, E E Carolina Power & Light Co 3pp 18649 049 24X Fiche 30-324,83/05/18,8305260134
- 8305260167 Forwards request for add1 info re NUREO-0737. Item II k 3.28 on qualification of automatic depressurization sys accumulators Response within 45 days requested VASBALLO, D B Operating Reactors Branch 2 83/05/11 LIV.L Iowa Electric Light & Power Co 3pp 18648 117 24X Fiche 30-331.83/05/11,8305260167
- 8305260170 Forwards request for add1 info re NUREG-0737, Item 11 K.2 28 on qualification of automatic depressurization sys accumulators Response requested within 45 days VASSALLO, D B Operating Reactors Brench 2 83/05/11 PILANT, J. M Nebraska Public Power District 4pp 18648 113 24X Fiche 30-298, 83/05/11, 8305260170
- 8305260175 Forwards request for add1 info re NUREO-0737, Item II K, 3 2B on qualification of automatic depressurization sysaccumulators Response within 45 days requested VASSALLO, D B Operating Reactors Branch 2 83/05/11 MORIBI, A V. Boston Edison Co 3pp 18648 110 24X Fiche 50-293,83/05/11,8305260175
- 8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1.

 VASSALLO, D B Deterating Reactors Branch 2 83/05/18 PARRIS, H 0. Tennessee Valley Authority 3pp 1848 107 24X Fichs 30-259, 83/05/18, 8305260177
- 8305240187 Forwards safety evaluation re BHR Dwners Group response to NUREG-0737. Item II K 3 45. "Depressurization H/Other Than Automatic Depressurization 8ys " Action complete VASGALLO,D B Operating Reactors Branch 2 83/05/18. PARRIS.H 9 Tennessee Valley Authority 2pp 18648 097 24X Fiche 50-259.83/05/18.8305260187
- 8303260192 Forwards safety evaluation re BWR Owners Group response to NUREO-0737. Item II K 3 45, "Depressurization W/Other Then Automatic Depressurization 8ys " Action complete VASSALLO, D B Operating Reactors Branch 2 83/05/18 LIU. L IDWA Electric Light & Power Co. 2pp 18648 089 24X Fiche 30-331.83/05/18,8305260192
- 8305260201 Forwards request for add1 info re 811231 response to NUREO-0737. Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of itr receipt VASSALLO.D.B Depressing Reactors Branch 2 83/05/11 MUSOLF, D M Northern States Power Co 3pp 1848 067 24X Fiche 50-263.83/05/11,8305260201
- 9305260207 Forwards revised order confirming licensee commitments on NUREO-0737. Item II F. 1: "Post-Accident Monitoring:" per 83031 & 0411 ltrs.Extended completion schedule to 840515 acceptable, VAROA:8 A Operating Reactors Branch 1 QL-82-05 83/05/11. UHRIO:R E Florida Power & Light Co 3pp. 18629 340. 24% Fiche 50-250;63/05/11.8305260207
- ~-8305240211 Revised order confirming licensee commitments on post-TMI related issues
 EISEMHUT, D G Division of Licensing GL-82-05, 83/05/11.
 Florida Power & Light Co 9pp 18629 343 24X
 Fichs 50~250,83/05/11,8305260207

- 8305260209 Forwards request for add1 info re 820401 response to NUREQ-0737, Item II K 3 28. "Gualification of Accumulators on Automatic Depressuritation Sys " Reply requested within 45 days of ltr receipt VASSALLO, D B Operating Reactors Branch 2 83/05/11 BAYNE, J P Power Authority of the State of New York 3pp 18629 354 24X Fiche 50-333, 83/05/11, 8305260209
- 8305260285 Forwards request for addl info re 810123 response to NUREG-0737. Item II K 3 28. "Gualification of Accumulators on Automatic Depressurization 89s " Reply requested within 30 days of itr receipt VABBALLO, D B Operating Reactors Branch 2 83/05/11 UTLEY, E E Carolina Power & Light Cd 3pp 18627 337 24x Fiche 50-324, 83/05/11, 8305260285
- 8303260270 Commits to resolution of three open items re NUREO-0612, "Control of Heavy Loads," using Guad Cities guidelines Guad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable RVBAK.B Commonwealth Edison Co &611N 83/05/17 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 18625-354 24) Fiche 50-237,83/05/17,8305260270
- 8305260294 Forwards response to 830405 draft technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per 830518 teleon ABH.R E. Baltimore Gas & Electric Co 83/05/24 EISENHUT.D G Division of Licensing 2pp 18625 161 24X Fiche 50-317,83/05/24, 8305260294
- 8305260276 Forwards safety evaluation of BWR Owners Group generic response to NUREO-0737. Item II K 3 45. "Depressurization M/Other Then Automatic Depressurization Sys" No mod to plant design or operations required Action complete VABBALLO.D B Operating Reactors Branch 2 83/05/18 SINCLAIR.J B Owner Theory 1 18627 330 24X Fichs 30-271,83/05/18,8305260276
- 8305260297 Forwards safety evaluation of BHR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys "No mod to plant design or operations required Action complete VASBALLO,D B Operating Reactors Branch 2 83/05/18 BAYNE,J P Power Authority of the State of New York 2pp 18629 323 24X Fichs 50-333,83/05/18,8305260297
- B305260300 Forwards safety evaluation of BHR Owners Oroup generic response to NUREO-0737, Item II K 3 45, "Depressurfication W/Other Than Automatic Depressurfication Bys" Alternative modes would not contribute to plant safety No modes required VABSALLO, D 8 Operating Reactors Branch 2 B3/05/18 PILANT, J M Nebraska Public Power District 2pp 18629 316 24X Fiche 50-298,83/05/18.8305260300
- B305260322 Response to ASLB B30516 scheduling order Add1 statement re NRC use of PRA & rept on NUREO-0737; Item II K 3 18 enc! Schedules for NRC issuance of documents discussed at second special problem conference valid W/Certificate of Svc HDD9DDN.A P Hearing Branch 2 83/05/24 9pp 18625 017 24X Fiche 50-352,83/05/24,8305260322
- --8305260327 Forwards evaluation of BMR Chiners Group generic response to NVREQ-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic Feasibility for Increased Diversity of Some Event Sequences "Response requested SCHMENCER: A Licensing Branch 2 83/05/23 BAUER: E 9 Philadelphia Electric Co 9pp 18625 028 24X Fiche 50-352,83/05/24,8305260322
- --B304140161 Forwards safety evaluation of mods proposed by BHR Owners
 Oroup re NUREQ-0737. Item II K 3 18, "Mod of ADS Logic "
 Two options proposed acceptable W/o encl
 HOUSTON,R W Assistant Director for Reactor Safety 83/04/01
 LAIMAS.Q C Assistant Director for Safety Assessment 2pp
 18625 037 24X Fiche 50-352,83/05/24,8305260322
- 8305270003 Forwards proposed Tech Specs in form of marked-up Rev 4 to NUREQ-0452, "8TB for Westinghouse PMRs."
 TUCKER.H.B Duke Power Co 83/05/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADEN9AM.E G Licensing Branch 4 741pp 18630-001 24X Fiche 50-413.83/05/20.8305270005
- 8305270026 Provides clarification of util position on NUREG-0737, Items 1 A 1.3, "Min Shift Crew" & III A 1.2, "Staffing Level for Emergency Situations "MANGAN,C V Niagara Mohawk Power Corp 83/05/24 VASSALLO,D B Operating Reactors Branch 2 2pp 18638 304. 24X Fiche 50-220,83/05/24,8305270026

- B305270030 Forwards response to B30316 request to document compliance w/acceptance criteria & schedule for NUREG-0737. Item I1 K 3 13. "Separate HPCI & RCIC Initiation Levels "Criteria will be met MILLS.L M Tennessee Valley Authoraty B3/05/24 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 1863B 306 24X Fiche 50-259,83/05/24,8305270030
- B305270039 Forwards request for addl xnfo re personnel training as part of NRC review of application for OL SCHMENCER. A Licensing Branch 2 83/05/23 CAHILL, H J Gulf States Utilities Co 5pp 18662 097 24X Fiche 50-458.83/05/23, 8305270039
- 8305270058 Advises that fuel load scheduled for 840815 £ commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltr 82-33) requirements re emergency plans will be met CADMAN, W K Kansas Gas & Electric Co GL-82-33 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18638 250 24X Fiche 50-482, 83/05/23, 8305270058
- B305270060 Forwards safety evaluation of util response to SER, NUREO-0916. Item 3 re affiluent radioactivity monitoring sys alarm setpoints & surveillance requirements Monitoring sys acceptable CRUTCHFIELD. D Operating Reactors Branch 3 LS05-83-05-058 B3/05/26 MAIER, JE Rochester Oas & Electric Corp 4pp 18638 333 24X Fichs 50-244.83/05/26.8305270060
- ### B305270077 Advises that NUREO-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E. JOCFH50." complete CRUTCHFIELD, D. Operating Reactors Branch 5 LS05-83-05-054 83/05/25 MAIER, J E Rochester Gas & Electric Corp 3pp 18698 153 24X Fiche 50-244.83/05/25.8305270077
- 8305270080 Requests extension to 831015 to provide schedule for accomplishing proposed actions to close outstanding issue re IE Bulletin 77-01B items Exemptions from 10CFR50 49 & Rev 2 to Reg Guide 1 97.
 RODRIGUEZ.R J Sacramento Municipal Utility District IEB-79-01B 83/05/20 STOLZ.J F Operating Reactors Branch 4 2pp 18638 291 24X Fichs 50-312-83/05/20.8305270080
- 8305270082 Updates 830415 ltr re installation & operability of postaccident sampling sys per NUREC-0737, Item II B 3 Items agreed upon at 830512 meeting listed Installation work will be completed during current refueling outage FIEDLER:P B General Public Utilities - GPU Service Corp 83/05/20 EISENUT, D 0 Division of Licensing 2pp 18638 287 24X Fiche 30-219,83/05/20,8305270082
- B305270109 NUREO/CP-0043
 JOINT NRC/ANS MEETING ON BABIC THERMAL HYDRAULIC MECHANISMS
 IN LUR ANALYSIS
 HSU,YY, LEE,R American Nuclear Society B3/04/30 Office of
 Nuclear Regulatory Research, Director 612pp 18649 112
- 8303270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program OUCHALL T Georgia Power Co NED-83-256 83/05/19 STOLZ.JF Operating Reactors Branch 4 19 18638 217 24% Fiche 50-321.83/05/19,8305270128
- 8305270144 Advises that QA program described in NEDO-11207-04A being implemented satisfactorily Results of insp published quarterly in NUREG-0040 COLLING.J T Division of Vendor & Technical Programs 83/05/24 BRUGGEMAN, W W General Electric Co 2pp 18638 203
- B305270170 Forwards "Bt Lucie 1 & 2 & Turkey Point 3 & 4 Detailed Control Room Design Reviews Program Plan," fulfilling 830415 commitment per NUREO-0737, Suppl 1 UHR10,R E Florida Power & Light Co L-83-323 B3/05/14 EIBENNUT.D Q Division of Licensing tp 18638 072 24X Fiche 50-335,83/05/14,8305270170
- 8305270210 Forwards div input to emergency planning for suppl to SER Matl updates info contained in Section 13 3, "Emergency Planning of Wolf Creek Generating Station SER," (NUREG-0881, Apr 1982)
 PAGANO, FO Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/23 YOUNGBLOOD B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482,83/05/25,8305270210
- 8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted DANCE:H C. Division of Project & Resident Programs 83/05/06 UHRIG:R E Florida Power & Light Co 2pp 18637 329. 24X Fiche: 50-250, 83/05/06, 8305270215

- --8305270217 IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted Major areas inspected followup on previous insp findings. IE bulletins, post-TMI implementation, surveillance testing & maint activities VOOT-LOHELL.R, AGLES.J A Region 2, Office of Director JULIAN.C Division of Project & Resident Programs 50-251/83-05 83/05/05 8pp 18637 331 24X Fiche 50-250,83/05/06,8305270215
- B305270220 Requests extension until B30620 for completion of special lifting rig analysis per NUREO-0612 Extension required dua to late receipt of Westinghouse rept BTEWARTH L Virginia Electric & Power Co 322 83/05/20 DENTON:H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 ip 18637 325 24x Fiche 50-338.83/05/20,8305270220
- 8305270274 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-24 Regusted actions to improve QA program listed MARTIN.T T Division of Engineering & Technical Programs 83/05/23 MCNEILL.C A Power Authority of the State of New York 2pp 18643 131 24X Fiche 50-333/83/05/R3/8305270274
- --8305270284 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-333/82-24 Corrective actions design verification by supervisors in Design & Analysis Procedure 3 11 & 3 18 revised per insprept Rev to be completed by Apr 1983 BAYNEJ P Power Authority of the State of New York JPN-83-28 B3/04/01 HAYNES, R C Region I. Office of Director 15pp 18643 133 24X Fiche 50-333,83/05/23,8305270274
- B303270432 Discusses B&W Owners Oroup emergency procedure guidelines (abnormal transient operating guidelines ATGG), per B30305 ltr Detailed schedule for expansion of technical bases for procedure will be submitted by and of June HHITNEY.D D Babcock & Wilcox Operating Plants Duners Group HHITNEY.D D Sacramento Municipal Utility District GL-82-33 83/05/21 EISENHUT.D G Division of Licensing 2pp 18642 289
- B305270479 Ack receipt of B30325 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-02 LEWIS.R C Division of Project & Resident Programs B3/04/07 UTLEY.R E Carolina Power & Light Co 2pp 18644 03R 24X Fiche 50-261.83/04/07.8305270479
- --8303270506 IE Insp Rept 50-261/83-02 on 830110-0210 Noncompliance noted failure to implement equipment control procedures, to initiate prompt corrective action & to maintain annunciator procedures

 MRISE: S Region 2. Office of Director BEMIS, P Division of Project & Resident Programs 83/02/22 12pp 18644.042 24X Fiche 50-261,83/04/07.8305270479
- 8305270497 Forwards IE Insp Repts 50-269/83-09.50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted. DANCE, HC Division of Project & Resident Programs 50-287/83-09 83/04/05 TUCKER, H B Duke Power Co 2pp 18646 192 24X Fiche 50-269.83/04/05.8303270497
- --8305270518 IE Insp Repts 50-249/83-09.50-270/83-09 & 50-287/83-09 on 830308-11 No nancompliance noted Hajor areas inspected NUREG-0737.Items II B 2. "Plant Shielding Mods" & II B 3. "Fost-Accident Sampling Sys"

 COLLINS.T R Region 2. Office of Director 50-270/83-09 83/04/01 7pp I8646 194 24X Fiche 50-269.83/04/05.8305270497
- 8305270361 Forwards IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/04/06 UHRIG, R E Florida Pawer & Light Co 2pp 18645 321 24X Fiche 50-325,83/04/06,8303270261
- --8305270576 IE Insp Repts 50-339/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted Major areas inspected Unit [plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items WRAY.J R . BARR.K P Region 2. Office of Director 50-389/83-25 83/04/05 8pp 18645 323 24X Fiche 50-335.83/04/06.8305270561
- B30531002B Advises that requirements of NUREC-0737, Item II F 1 4, "Containment Pressure Monitor," II F 1.5, "Containment Mater Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved.per B21220 & B01215 submittals CRUTCHFIELD.D Operating Reactors Branch 5 LS05-83-05-060 B3/05/27 FARAR.D L Commonwealth Edison Co 7pp 18659 213 24X Fiche 50-000, B3/05/27, B305310028
- 8305310039 Forwards info re schedule for steam generator mods, per SER (NUREQ-0847) design changes HILLS-L M Tennessee Valley Authority 03/05/27 ADENSAM, E Licensing Branch 4 2pp 18653 307. 24X Fiche 50-390,83/05/27,8305310039

- B305310046 Informs of NRC determination that onsite & offsite amergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 i Item complete CRUTCHFIELD, D Operating Reactors Branch 5 L805-83-05-065, B3/05/27 VANDEWALLE, D J Consumers Power Co 3pp 18453:149, 24X Fiche 50-255, B3/05/27, B305310046
- 8305310073 Submits info re analyses & repairs of large-diameter stainless steel piping welds per inservice insp conducted during 1983 maint/refueling outage identifying unacceptable ultrasonic indications in recirculation & RHR sys BECKHAH.J T Georgia Power Co IEB-83-02 83/05/26 BTDLZ.J F Operating Reactors Branch 4 9pp 18655 345 24X Fiche 30-366.83/05/26,8305310073
- --B305310084 Provides response to IE Bulletin 83-02 re stress corresson cracking in large-diameter stainless steel recirculation syspiping at BHR plants
 BECKHAM, J T Georgia Power Co ICB-83-02 83/05/26
 0'REILLY, J P Region 2, Office of Director 37pp 18655 334
 24X Fichs 50-366,83/05/26,8305310073
- --8305310072 Discusses possible imposition of augmented leak detection requirements for RCS due to discovery of unacceptable pipe flaw indications in recirculation & RHR sys Util commitments to incorporate NUREG-0313, Rev 1. Section IV B 1 a 2 BECKHAM. J T Georgia Power Co NED-83-322 83/05/25 870LZ; J F Operating Reactors Branch 4 2pp 18656 032 24X Fichs 50-366,83/05/26,8305310073
- 8305310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Teledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits.

 MUNIER, R 8 Indiana & Michigan Electric Co AEP NRC 0585F 83/05/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18638 065 24% Fiche 50-315,83/05/27,8305310088
- B305310074 Forwards revised description of NUREG-0737. Item II.F 2.
 "Inadequate Core Cooling Instrumentation:" providing sufficient info to close item & corresponding requirement in BER DRUMHOND, F J Louisiane Power & Light Co. W3P83-1542 B3/05/23. KNIGHTON, G W Licensing Branch 3 34pp 18655 039 24X Fichs:50-382,83/05/23,8305310074
- 8305310147 Response to SAPL motion to amend petition to intervane re-SER open items Motion should be denied on grounds of timeliness. Certificate of Syc encl. DIGNAN, T.O. Public Service Co. of New Hampshire, DIGNAN, T.O. Repes 4 Oray ISSUANCES OL. 83/05/24 Atomic Safety and Licensing Board Panel. Bpp. 18651 209 24X Fiche 50~443,83/05/24,8305310147
- 8305310170 Advises that table of contents & table of cross-refs to NUREO-0654 planning stds/evaluation criteria adequate to locate portions relevant to contentions Referenced portions of plans listed BAXTER T A Shaw, Pittman, Potts & Trowbridge, ISBUANCES OL 83/03/26 REED, J Q. Affiliation Unknown 7pp 18652 326 24X Fichs 50-483,83/05/26,8305310170
- 8305310175 Forward Rev 1 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0388" PETRICK, N A Standardized Nuclear Unit Power Plant Bystem 83-0030 83/05/27 DENTON H R Office of Nuclear Reactor Regulation, Director 344pp. 18659 144 24X Fich 50-000,83/05/27,8305310175
- 8305310200 Informs of plans to perform mods to Hestinghouse Model D2/D3 steam generators per SER (NURE-0766) issued on 830316 Plant-specific mod details encl TUCKER, H B Duke Power Co 83/05/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 7pp, 18651:014 24X Fiche: 50-413, 83/05/18, 8305310200.
- 8305310205 Advises that installation of two Controlatron sonic flow devices on each flow path to once-through steam generators satisfies requirements of restart SER (NUREG-0680),811214 partial initial decision & NUREO-0737.1tem II E.I HUKILL,H D General Public Utilities GPU Service Corp 5211-83-154 83/05/24 830LZJJ,F Operating Reactors Branch 4. 1p 18658 157 24X Fiche, 50-289,83/05/24,8305310205.
- 8305310208 Fowards check in payment of review re nonconformance W/ NUREO-0737, Item II. E 4, 2, per 830427 request CURTIS:N W Pennsylvania Power & Light Co. PLA-1683 83/05/25 8CHMENCER:A Licensing Branch 2 1p 18658.133 24X Fichs 50-387,83/05/25,8305310208
- 8305310209 NUREO/CR-3100
 RELAPS ASSESSMENT PKL NATURAL CIRCULATION TESTS
 THOMPSON.S.L., KMETYK, L.N. Sandia Laboratories FIN A-1205
 SAND82-2902 83/04/30. Division of Accident Evaluation 60pp.
 18663:132

- 8305310210 NUREG/CR-2326
 CALCULATIONS OF REACTOR ACCIDENT CONSEQUENCES VERSION 2
 CRACZ COMPUTER CODE Users Guide
 RITCHIE, L T., JOHNSON, J D., BLOND, R M. Bandia Laboratories FIN
 A-1042 SANDB1-1974 83/04/30 Division of Risk Analysis
 146pp 18663 211
- 8305310213 Forwards safety evaluation of util 830328 response to NUREQ-0737. Item II K 3 21. "Core Spray & LPCI Sys Low Level Initiation " Proposed mod designs acceptable CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-062 83/05/27 FIEDLER:P B General Public Utilities ~ GPU Service Corp 4pp. 18658 142 24X Fiche 50-219.83/05/27.8305310213
- 8305310231 Advises that responses to NUREO-0737. Item III D 3 4, "Control Room Habitability," acceptable, completing action on item Bafety svaluation encl VASBALLO, D B Licensing Branch 2 83/05/17 FARRAR, D L Commonwealth Edison Co 4pp 18462 255 24X Fiche 50-254, 83/05/17. 8305310231.
- 8305310234 Bummary of 830411 meeting w/util in Bethesda,MD re schedule for completing items in Generic Ltr 82-33. Suppl I to NUREG-0737 requirements for emergency response capability LAZO,L Licensing Branch 3 0.-82-33 83/05/11 Licensing Branch 3 12pp 18662 234 24X Fiche 50-412.83/05/11.8305310234
- B305310237 NUREG/CR-2000 VO2 N4 LICENSEE EVENT REPORT (LER) COMPILATION For Month of April 1983 * Dak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200 B3/05/31 Director's Office. 114pp 18683 118
- B305310240 Requests addl info for control of heavy loads review. including info open items for updated "Control of Heavy Loads "
 CLARK.R A Operating Reactors Branch 3 B3/05/17 JONES,W C Dmaha Public Power District 2pp 18662.180 24X Fiche 50-285.83/05/17.8305310240
- --8305310241 TER-C5506-356 DRFT

 "Control of Heavy Loads (C-10), Omaha Public Power District,
 Fort Celhoun Station." updated draft technical evaluation
 rept
 VUBBURY, F. BOMBERGER.C., SARGENT, I H Franklin Institute/Franklin
 Rasearch Center NRC-03-81-130 TAC 07791 82/11/29
 CLEMENSON, F NRC No Detailed Affiliation Given 52pp
 18662 182 24X Fiche 50-285, 83/05/17,8305310240

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- 8212060395 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Busceptibility to Exothermic Chemical Reaction " Svc list and TAYLOR. J H Division of Bafeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fichs 50-000.83/03/21.8212060385
- B303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator"

 8vc list encl

 JORDAN, EL Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/04/15 Consolidated Edison Co of New

 York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021
- 8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures"
 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/22 Consolidated Edison Co of New
 York, Inc 112pp. 18383:089. 24% Fiche 50-000.83/04/22.8303040023
- B303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Bensing 8ys " Svc list enc!

 JDRDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/25 Consolidated Edison Co of New York, Inc. 119pp, 18381 271 24X Fiche 50-000,83/04/25,8303040025.
- 8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs" Svc list encl UORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp 18382 047. 24X Fiche 50-000,83/04/28,8303040026.
- 8303040027 IE Info Notice 83-25, "Standby Oas Treatment Bys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382.165 24X Fiche 50-000.83/04/28.8303040027

- 6303040028 IE Info Notice 83-26. "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 63/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24x Fiche 50-000.83/05/03.8303040028
- B303040030 IE Info Notice 83-27. "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030
- 8303040031 IE Info Notice 83-28. "Criteria for Protective Action Recommendations for General Emergencies" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000.83/05/04,8303040031
- B303040033 IE Info Notice 83-29. "Fuel Binding Caused by Fuel Rack Deformation " Bvc list enc!

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033
- 8303040034 IE Info Notice 83-30. "Misopplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co of New York. Inc 114pp 18524 003 24X Fiche 50-000.83/05/11.8303040034
- 83D3040040 IE Info Notice 83-31. "Error in ADLPIPE Computer Program" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 83D103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000.83/05/19.8303040040
- 8303040046 IR Info Notice 83-33, "Nunrepresentative Sampling of Contaminated Dil " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18447 007 24X Fiche 50-000,83/05/26,8303040046
- 8305020403 Discusses DOE agreement re Region IV equipment qualification insp program & consultant svc provided from 821001-830328 Areas needing greater supplasts or improvement listed PHILLIPS H B Region 4. Office of Director FIN 3-3101 83/04/28 BANGART R L Division of Vendor & Technical Programs 2pp 18273 023
- 8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning, for info Certificate of Svc encl Related correspondence GLASS, 8 M Federal Emergency Management Agency ISSUANCES SP 83/04/25 QLEASON, J P Atomic Safety and Licensing Board Panel 62pp 18273-128 24X Fiche 50-247, 83/04/25, 8305020419
- B305040001 Responds to approval request for info collection re 10CFR73 concerning physical protection of plants & matts Request approved through 651031 under OMB Number 3150-0002, per Paperwork Reduction Act BCURRY.N Office of Management & Budget DMB 3150-0002 83/04/25 SCOTT.8 Document Management Branch 2pp 18336-319
- B305040003 Responds to approval request for info collection re
 10CFR70 32(E) concerning changes in physical security plans
 Request approved through 831231 under DMB Number 3150-0007,
 per Paperwork Reduction Act
 SCURKY,N Diffice of Management & Budget DMB 3150-0007 83/04/26
 SCOTT,B Document Management Branch 2pp 18336-321
- 8303060306 Responds to 830426 itr re Westchester County, NY bus driver issue, Rockland County, NY plan issue & questions raised re FEMA briefing & status rept on offsite emergency preparedness KRIMMR W Federal Emergency Hanagement Agency 83/05/04 CHILK, 8 J Office of the Secretary of the Commission 16pp 18348 331 24X Fiche 50-247, 83/05/04, 8305060506
- --8305060629 Responds to request for clarification of issue on whether state emergency plan can substitute for county which does not have emergency plan State can substitute plan but NUREO-0654 places heavy resource burden on state OIUFFRIDA, L.O. Federal Emergency Management Agency 83/04/15 PALLADIND, N.D. Commissioners 2pp 18348-347 24X Fiche 50~247,83/05/04,8305060506
- B305090006 Responds to approval request for info collection re NRC Form 5, "Current Occupational External Radiation Exposure" Request approved through 850430 under OMB Number 3150-0006, per Paperwbrx Refuction Act
 SCURRY,N Office of Management & Budget OMB 3150-0006 89/04/25
 SCOTT,8 Document Management Branch 2pp 18369 354

- 8305090209 Forwards survey of GA procedures applied by INEL to computer code activities for NRC-funded programs
 BANGART,R L Division of Vendor & Technical Programs B3/05/04
 MATTEON,R J Division of Systems Integration (post 811005) 3pp 18364 041
- 8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl EIBENHUT, D O Division of Licensing GL-83-20 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09.8305090659
- 8305100122 Forwards post-exercise evaluation for 810729 exercise, final rept of reexercise on 81007 % final exercise rept of 830118 exercise No significant deficiencies cited KRIMMR W Federal Emergency Management Agency 83/04/08 URBJANJE L Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp 18375 048 24% Fiche 50-295,83/04/08,8305100122
- --8305100126 "Zion Nuclear Generating Station Small-Scale Joint Emergency Exercise.830118," final rept Federal Emergency Management Agency 83/03/0 375 050 24% Fiche 50-295,83/04/08,8305100122 83/03/04
- --8305100131 "Zinn Nuclear Power Station Reexercise, WI/Kenosha County (Small-Scale) BildO7," Final Fept February B2/04/30 32pp 18375 121 24X Fiche 50-295, 83/04/08, 8305100122
- --8305100136 "Post-Exercise Evaluation Exercise of State & Local Radiological Emergency Response Plans for IL & WI (Near Zien Nuclear Power Station) " Federal Emergency Management Agency 81/07/29 373 153 24X Fiche 50-295,83/04/08,8305100122 18375 153
- B305100143 Submits status of offsite emergency preparedness issues re FEMA regional verifications through B30304 & data received through B30331 concerning schedule for completion of issues at facilities

 KRIMM.R W Federal Emergency Management Agency 83/04/26

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 9pp 18375 ODI 24X Fiche 50-289, 83/04/26,

 8305100143
- 8305120421 Ack receipt of PEMA 830421 ltm & "Final Exercise Rept Joint State & Local Radiological Emergency Response Exercise "Emergency preparedness does not provide reasonable assurance that protective measures will be taken ALLANJ M Region 1. Office of Director 83/05/04 RANDAZZA, J. Maine Yankse Atomic Power Co 2pp. 18433 153 24% Fiche 50-309,83/05/04.8305120421 7/04 RANDAZZA, J. B 24X
- --8305120426 Forwards "Final Exercise Regt Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant, " conducted on 821211 MCLOUGHLIN.D Federal Emergency Management Agency 83/04/21 DIRKRS W J Office of the Executive Director for Operations 1p 18433 155 24X Fiche 30-309,83/03/04.8303120421
- --8305120427 "Final Exercise Rept Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant "
- * Federal Emergency Management Agency 83/03/31 83pp 18433 156 24X Fiche: 50-309, 83/05/04, 8305120421
- 6303200458 Forwards FEMA avaluation of prompt notification sys proposed for Herren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be eramined by NRC during next amergency preparedness insp HIND. J A Division of Radiological & Materials Safety Programs. 83/05/20 SOUTHHOOD. R J Michigan. State of Ip 18513:001 24% Fiche 30-315.63/05/20,8303200458
- --8305200465 Responds to 821213 ltr re potential inadequaties of public notification sys at Warren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding population ANDERSON.J T Federal Emergency Management Agency 83/04/01 KEPPLER.J.O Region 3. Diffice of Director 3pp 18513 002 24X Fiche 50-315,83/05/20,8305200458
- 8305230465 Responds to 830322 ltr discussing activities of ANS Special Committee on Source Terms Info meeting to present work of committee welcomed PALLADINO, N J Commissioners 83/05/02 STRATTON, N R American Nuclear Society 1p 18542 151.

- --8305230469 Discusses activities of ANB Special Committee on Source Terms Heeting to discuss source term issue & present work of committee proposed STRATTON. W.R. Amer STRATTON.W R American Nuclear Society 83/03/22 PALLADING.N J Commissioners 2pp 18542 152
- 8305230474 Forwards "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness: Jan-Mar 1983 " FALLADIND: N J Commissioners GIUFFRIDA: L O Federal Emergency Management Agency 83/05/03 GIMPSON: A K Senate: Environment & Public Works 2pp 18542 154
- --9305230479 "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness.Jan-Har 1983 " * NRC No Detailed Affiliation Given * Federal Emergency Management Agency 83/03/31 59pp 18542 156
- 8305240036 Forwards request for OMB review & supporting statement re NUREO-0737. TMI action plan NCRRV, P G Office of Administration 83/05/19 SCURRY, N Office of Management & Dudget ip 18594 260
- B305240488 Forwards INPO "Evaluation of Dyster Creek Nuclear Generating Station: 1982 " Evaluation conducted 821025-1101 DRUNNER: E J Division of Project & Resident Programs 83/05/06 TAYLOR, J M Division of Resident Programs (Pre 830103), 19 18571 315 24% Fiche 50-219,83/05/06,8305240488
- --8305240476 "Evaluation of Oyster Creek Nuclear Generating Station, Prostitute of Nuclear Power Operations 83/03. 18571 316 24X Fiche: 50-219.83/05/06.8305240488 83/03/31 44pp
- 8305240510 Forwards "RE Ginna Nuclear Power Plant, 1982 Evaluation " BRUNNER, E.J. Division of Engineering & Tochnical Programs 83/03/04 TAYLOR, J.M. Division of Bakeguards & Inspection Programs (Post 830103) CAEE, E. O. Office of Nuclear Reactor Regulation, Director Ip 18371 274 24X Fichs 50-244, 83/03/04, 8303240510,
- --8305240519 "RE Ginna Nuclear Power Plant 1982 Evaluation." conducted during wks of 820531 & 0407

 In Institute of Nuclear Power Operations 83/05/06 41pp
 16571 275 24X Fiche 50-244.83/05/06.8305240510
- B3052A0375 Speech entitled "NRC Looks Ahead." presented at B30523 INPO meeting of plant managers in Atlanta.GA BTELLO.V Regional Operations & Generic Requirements B3/05/23 6pg 18647 278
- 8305270109 NURE9/CP-0043 JOINT NRC/ANM MEETING ON BABIC THERMAL HYDRAULIC MECHANISMB HSU, Y Y., LEE, R American Nuclear Society 83/04/30 Nuclear Regulatory Research, Director 612pp 18649 112. Office of
- 8305310049 Responds to 830523 ltr outlining specific proposals for ameliorating facility offsite preparedness situation & views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness of STEPRIDAL O Federal Emergency Management Agency 83/05/25 CUOMO.N N New York. Bate of 4pp 18633 284 24X Fiche 50-247,83/05/25,8305310049

PR PROPOSED RULE

- 8304270179 Advises of rev in due date for submittal of proposed final rule on Yech Specs to CRGR & AEOD, Final package will be due at CRGR on 830731 & at AEOD on 830831

 THOMAS: C 0 Standardization & Special Projects Branch 83/04/19
 EISENHUT, D 0 Division of Licensing 2pp 15244 169
- 8304280121 Package of two comments opposing proposed rule re NRC policy statement on regionalization
 MAY,D C , TREXLER,R C Affiliation Unknown 48FR12617 83/04/22
 Diffice of the Secretary of the Commission 2pp 18251:293
- 8305020422 Motion to allow Citizens Assoc for Sound Energy to file written argument on issue in lieu of presenting oral argument at 830119 hearing Citizens do not have finances to come to Bethesde. MD for 40-minute argument.
 ELLIB-J Citizens Association for Bound Energy 83/01/11 A: Safety and Licensing Appeal Panel 2pp 18283 001 24% Fiche 50-445,83/01/11,8305020422 Atomic
- --B305020430 Written argument on issues to be argued orally on 830119 in Rethesda.MD Citizens Assoc for Sound Energy Unable to attend or find representative Whistleblower protection discussed ELLIS.J Citizens Association for Sound Energy Atomic Safety and Licensing Appeal Panel 45pp Fiche 50-445,83/01/11,8305020422 18283 003. 24X

- --8305020437 Forwards Citizens Assoc for Bound Energy witness J Doyle affidavit re blacklisting due to testimony at hearings ELLIB.J Citizens Association for Sound Energy 83/01/18 ROSENTHAL.A 8 Atomic Safety and Licensing Appeal Panel 1p 18283 068 24X Fiche 50-445.83/01/11,8305020422
- --B305020444 Affidavit of J Doyle re blacklisting due to testimony at hearings NRC should take immediate & stringent measures to stop instituous practice NRC current protection for whistleblowers is farce & charade Certificate of Evc encl DOYLE. J Affiliation Unknown 8370//17 4pp 1B283 069 24X Fiche 50-445, B3701/11, B305020422
- 8303030069 Commants on 830415 final 10CFR90 73 rulemaking package re LERS Concerns listed MARTIN, J B Region 5, Office of Director 83/04/27 HELTEMES, C J Director's Office 2pp 18300 358
- 8303030416 Package of two comments supporting proposed rule 10CFR35 re group licensing for certain Oroup IV medical devices ROBINSON,R O American College of Nuclear Physicians STRAUBS,R J Affiliation Unknown 4BFR13189 83/04/29 Docketing & Services Branch 4pp 18306 316
- 8305030418 Comments on proposed rules 10CFR2 & 50 re granting temporary OLS Opposes rule LEWIS.M I Lewis, M 48FR14926 002 83/04/22 Office of the Secretary of the Commission to 18306 247
- B305030430 Comments on proposed rule re alternative programs for improving GA & GC in const of nuclear power plants NRC considerations should be to assure that regulatory framework combines activities of licensee & NRC OPREA: O H Houston Lighting & Power Co 48FR9106 013 B3/04/22 CHILK: BJ Défice of the Secretary of the Commission 9pp 18292 154
- 8305030437 Comments on proposed rule re QA programs for const of nuclear power plants Supports improvement of GA program COMPTGN,N Affiliation Unknown 48FR9106 014 83/04/25 Office of the Secretary of the Commission 4pp 18306 320
- 8305030441 Package of three comments on proposed rule re planned studies of GA programs for const of nuclear power plants KELLY,R B Stone & Webster Engineering Corp UHRIG,R E Florida Power & Light Co ALLEN,R E Power Engineering 48FR9106 83/04/29 Docketing & Services Branch 13pp 18304 280
- 8305030472 Comments on proposed rule re NRC policy statement on regionalization Supports rule Special attention should be given to areas of staffing, regional ofcs & mechanisms to assure uniformity in program administration QIESE.D J Minnesota, State of 48FR12617 028 83/04/26 CHILK.S J Office of the Secretary of the Commission 1p 18306 214.
- B305030480 Comments on proposed rule 10CFR35 adding Group IV medical device for instantaneous imaging w/I-125 sealed source (lixiscope) Supports rule
 TANSEY;W J Downers Grove Orthopedic Associates, Downers Grove, IL
 48FR13189 007 83/04/22 Docketing & Services Branch ip
- 8305030487 Comments on proposed rule re policy statement on regionalization Opposes rule MURTHEN, M Affiliation Unknown 48FR12617 026 83/04/20 Office of the Secretary of the Commission ip 18308 250
- 8305030598 Comments on proposed rule re-policy statement on regionalization Supports rule TEDFORD.C F Arizona, State of 48FR12619-027-83/04/22 Docketing & Bervices Branch 2pp 18306-089
- 8305060236 Comments on proposed rule re decentralization of NRC headquarter functions Opposes rule FREY.D 0 Sessefres Audubon Society 48FR12619 031 83/05/02 NRC No Detailed Affiliation Given 2pp 18345 191
- B305060244 Comments on proposed rule 10CFR50 re changes to regulations on Tech Specs for nuclear power reactors Endorses concepts embodied in rule Urges Commission to implement rule on schedule reflecting priority COUNBIL, W Q Northeast Utilities Bervice Co COUNBIL, W Q Northeast Utilities 47FR13369 032 B3/04/25 CHILK, B J Office of the Secretary of the Commission 3pp 18345 193
- 8305060234 Comments on proposed rule 10CFR140 re removal of Apps A through H from financial protection requirements & indemnity agreements Opposes rule OUCWAL T. Georgia Power Co 4BFR9284 018 83/04/28 Docketing & Bervices Branch 2pp 18345 222

- 8305060289 Comments on proposed rule re draft NRC policy statement on regionalization Supports rule EICHBAUM.W M Maryland. State of 48FR12619 029 83/04/20 DIRCKS.W J Office of the Executive Director for Operations 1p 18344 324
- 830-9060294 Comments on proposed rule re decentralization of NRC licensing functions Requests maintaining centralized licensing function for radiopharm business to enhance safety of employees.customers & public MHITE.L M Syncor International 48FR12619 030 83/04/29 Docketing & Services Branch 2pp 18344 320
- 8303060382 Package of three comments on proposed rule re planned studies of GA programs for const of nuclear power plants GUSTAFSON.L D. Affiliation Unknown HENRY.W O Duke Power Co WEISS.E R. Union of Concerned Scientists 48FR9106 83/05/02 Docksting & Services Branch 29pp 18344 108
- B305060436 Comments on proposed rule 10CFR35 re group licensing for certain Group IV medical devices Supports rule GARCIA:N J. Affiliation Unknown 48FR13189 010 83/05/02 Docksting & Services Branch 2pp 18343 149
- 8305040437 Comments on proposed rule re GA/GC for const of nuclear power plants prepared by D Hubbard on behalf of NRDC Bupports rule
 O'NETLL: J Affiliation Unknown 48FR9106 022 83/05/03 Commissioners ip 18343 145
- 8305060438 Comments on proposed rule replanned studies of QA programs for const of nuclear power plants
 TIERNAN, J.A. Baltimore Gas & Electric Co. 48FR9106 02; 83/04/29
 Docketing & Services Branch 3pp 18343 151
- 8305060973 Comments on proposed rule 10CFR50 re environ qualification Many operating plants operating w/unqualified equipment & w/o justification NRC made finding that justifications adequate NRC should be obligated to enforce requirements WEISS, E.R. Harmon & Weiss 47FR2076 087 83/04/19 PALLADIND, N.J., ASSELSTINE, J., AHEARNE, J.F. Commissioners 2pp 18348 349
- B3051i0012 Comments on methods for improving quality of nuclear power plant const.per B3032B request Focus of NRC GA/GC programs should be shifted away from program content & more towards actual program performance
 MARIANIL P , CARNEY, J American Nuclear Insurers 48FR9106 O31
 B3/05/03 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 18409 020
- B305180266 Comments on proposed rule re NRC policy statement on regionalization Supports rule WITHERS,B D Portland General Electric Co 48FR12619 035 B3/05/02 Docketing & Services Branch 2pp 18490 060
- B305180272 Comments on proposed rule re-NRC policy statement on regionalization Opposes rule ELLIG, J Citizens Association for Sound Energy 48FR12619 033 83/05/02 STELLO, V Regional Operations & Generic Requirements 7pp 18490 062
- 8305180306 Comments on proposed rule re planned studies of GA programs for const of nuclear power plants Opposes rulo Present OA programs adequate Implementation & timeliness of programs require more active participation

 ECKERT,R M Atomic Industrial Forum 48FR9106 023 83/05/06

 Docketing & Bervices Branch 3pp 18486 014
- --8305180313 "Positive Experience in Designing & Constructing Nuclear Power Plants" * Atomic Industrial Forum 83/01/31 38pp 18486-017
- 8305180330 Comments on proposed rule re planned studies of GA/GC programs for const of nuclear gower plants Extension of deadline for public comments requested so public input will be considered in studies
 FREY, D.O. Sassafras Audubon Society 48FR910A 024 83/05/05
 HARPBYER, T.L. ON Branch 2pp 1848A 055
- 9305180334 Package of three comments opposing NRC policy statement on regionalization
 PENNER,P S Illinois, State of RUZICKA,H Q Union Carbide Corp
 RUBLING,D H Interior, Dept of, Geological Survey 48FR12619
 93/05/12 Docketing & Services Branch 3pp 18486 289
- 8305180341 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OL & significant hazards consideration DOUGHERTY. J B Daugherty. J B LANPHER.L C Kirkpetrick, Lackhart, Hill. Christopher & Phillips 48FR14926 83/05/06 Office of the Secretary of the Commission 17pp 18486 267

- 8305180342 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations Supparts rule Changes to current Commission practices can be achieved w/o compromising public safety HELFRICH.R E Yankee Atomic Electric Co. 4EFR14864 016 83/05/06 Docketing & Services Branch. App. 18482 001
- B305180347 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OL & significant hazards considerations
 HIATT.S L Obio Citizens for Responsible Energy TIEDKE, J H
 League of Homen Voters of Suffolk Co , NY 48FR14726 83/05/05
 Docketing & Services Branch 3pp 18485 291
- 8305180351 Comments on proposed rule ra NRC policy statement on regionalization Policy has potential to improve quality of nuclear regulation if definitive policies & proper mgt controls are developed in advance of implementation DWEN.W H Atomic Industrial Forum 46FR(2617-032 83/05/04 Docketing & Services Branch 4pp 18485-278
- B3051B0353 Package of three comments opposing NRC policy statement re regionalization LEVINE,S H Pennsylvania State Univ RICHARDS,W J American Nuclear Society BUDNITZ.R J Future Resources Associates. Inc 4BFR12619 83/05/09 Docksting & Services Branch App
- B305180356 Comments on proposed rule 10CFR30 re stds for determining whether license amend involves no significant hazards considerations Rule does not meet Congressional mandate WEISS.ER. BISMOP.LL Union of Concerned Scientists 48FR14864 003 83/05/06 Commissioners 17pp 18485 245
- 8305180358 Package of five comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations MEARNEY.J J Edison Electric Institute TIERNAN.J A Baltimore Gas & Electric Co * LeBoeuf. Lamb. Leiby & MacRae 48FR14864 83/05/09 Docketing & Services Branch 19pp 18485 226
- 8305180363 Comments on proposed rule 10CFR50 re environ qualification NRC shirking responsibility to enforce environ qualification rule promulgated on 830105 CURRANLD WEISSLE R Harmon & Weissl 47FR2876 OBB 83/05/04 PALLADINON J , ASSELSTINE, J , AMEARNE, J F Commissioners 3pp 18488 214
- B305180344 Comments on proposed rule 10CFR30 re stds for determining whether license amends involve no significant hazards considerations Rule vague & unsatisfactory DOUOHYY, J Seacoast Anti-Pollution League 48FR14864 011 83/05/06 Docketing & Services Branch 1p 18490 354
- 8305180369 Package of two comments opposing 10CFR50 re-stds for determining whether license amends involve no significant safety halards consideration FREY.D G Bassafras Audubon Society DDROSHOW, J Three Mile Island Alert 48FR14864 83/05/09 Docketing & Services Branch 4pp
- 8305180378 Comments on proposed rules 10CFR2 & 50 re significant hazards consideration & issuance of temporary OL Supports rules CONNAY.B Atomic Industrial Forum 48FR14926 83/03/06 Docketing & Services Branch 4pp 18482 039
- B3051803B3 Comments on proposed rule 10CFR50 re notification & consultation w/state in emergency situation Situation should exist when plant already in shutdown could be prevented from startup because NRC failed to act in timely manner BRADBUHY.R B Stone & Mebster Engineering Corp 48FR14864 004 B3/05/04 Docketing & Services Branch ip 18470 345
- 8305180404 Package of two comments opposing proposed rule 10CFR50 restde for determining whether license amend involves no significant hazards considerations & notification of & consultation w/states

 AXELRAD.M Lowenstein. Newman. Reis. Axelrad & Toll HIATT.S L

 Ohio Cititens for Responsible Energy 48FR14864 83/05/05

 CHILK,S J Office of the Secretary of the Commission Spp. 18486 001
- 8305180425 Comments on proposed rule 10CFR35 re adding device to Schedule A. Group VI used for instantaneous imaging w/I-125 sealed source Supports rule DEYELJA American Association of Physicists in Medicine 48FR13189 012 83/05/05 PALLADINO,N J Commissioners 2pp [8485 300

- 8305180436 Comments on proposed rule 10CFR35 re adding device to Schedule A. Group VI used for instantaneous imaging, w/I-125 sealed source (Lixiscope) Supports rule SUNDAG, T J Good Samaritan Hosp Downers Grove, IL 48FR13189 011 83/05/05 Docketing & Bervicas Branch 1p 18486 194
- 8305180449 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OLs LATHAM,S B Twomey, Latham & Shea REYNOLDS,N B , HORIN,W A Dabevoise & Liberman 48FR14926 B3/05/09 CHILK,S J Office of the Secretary of the Commission 10pp 18486 184
- 8305180454 Comments on proposed rules 10CFR2 & 50 re issuance of temporary OLs BRADBURY.R B Stone & Webster Engineering Corp 48FR14926 00: 83/05/04 Docketing & Services Branch 1p 18486 183
- 8305180460 Package of two comments opposing proposed rule 10CFR50 re significant hazards considerations TIERNEY,J E., ARRENS.P., STERN.P. Minnesota, State of 48FR14864 83/05/10 Docketing & Services Branch 13pp 18483 101
- 8305200218 Package of two comments opposing proposed rule re NRC policy statement on regionalization DEWITT.R B Consumers Power Co GAGE.K Nuclear Information & Resources Services 48FR12619 83/05/16 Docketing & Services Branch 5pp 18517 095
- B305200222 Comments on proposed rule re-studies of GA/GC programs at nuclear power plants Supports rule
 CAMPBELL.9 E Simmissippi Alliance for the Environment (SAFE)
 4BFR9106-025 B3/05/12 Office of the Secretary of the
 Commission 2pp 18317-100
- 8305200276 Comments on proposed rule re NRC policy statement on regionalization Supports regionalization concept ROBINSON,R 0 American College of Nuclear Physicians 48FR12617 044 83/05/16 Docketing & Services Branch ip. 18516 272
- 8305200304 Comments on proposed rule re NRC policy statement on regionalization Opposes rule Potential problem re handling generic issues as result of occurrences in plants under const foreseen RAHE,E P Westinghouse Electric Corp 48FR12619 043 83/05/12 CHILKIBJ Office of the Secretary of the Commission 2pp
- B305200441 Package of two comments opposing proposed rule 10CFR50 renotice & state consultation stds for determining whether license amends involve no significant hazards considerations

 COUNSILH Ø Northeast Utilities LEWIB, M I Lewis, M 48FR14864.

 B3/05/16 CHILK, D Office of the Secretary of the Commission 13pp 18518 128
- 8305200454 Requests comment period for proposed rule on GA programs be extended until full impact of GA breakdown leading to ATM8 at Salem fully assessed & reported LEMIS.N I Leuis. M 48FR9106.024 83/05/12 Docketing & Services Branch 2pp 18512 360
- 8305200461 Comments on proposed rules 10CFR2 & 50 re issuance of temporary OL Supports rule PATTERSON.J D Middle South Utilities, Inc - Middle South Energy, Inc 48FR14926 010 83/05/06 Docketing & Services Branch 2pp 1851
- 8305200470 Submits UCB comments on proposed rule re NRC policy statement on regionalization Opposes rule WEISS.E R Harmon & Weiss 48FR12619 046 83/05/17 Commissioners App 18513 015
- 8305230324 Revised procedures for processing license amends for power reactor testing facilities (Sholly legislation). Interim final rules for notice & state consideration & stds for determining whether amends involve no hazards encl EISENHUT, D 9. Division of Licensing 83/05/06 17pp 18576:179.
- --8305230333 Interim final rule for 10CFR2 & 10CFR50 re revised procedures for processing license amends & notice & state consultation CHILK:S Office of the Secretary of the Commission DLOP-228, 83/04/04 34pp 18576-196
- --8305i105Bi "Btds for Determining Whether License Amende Involve No Significant Hazards Considerations " Interim final rule Dissenting views of Commissioners Asselstine & Gilinsky re use of Sholly amend encl CHILK.S J. Office of the Secretary of the Commission DLOP-228. 83/04/04 45pp 18576-230

- 8305230420 Responds to 830314 ltr urging implementation of spent fuel provisions of Nuclear Waste Policy Act (P.L. 97-425)
 Proposed rule 10CFR53, "Criteria for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity" encl
 PALLADINON J Commissioners 83/04/27 RILEY.R W South Carolina, State of 2pp 18542 027
- --8305230425 Proposed rule iOCFR53, "Criteria & Procedures for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity "CHILK, S.J. Office of the Secretary of the Commission 83/04/26 20pp 18542 029
- 8305240155 Ack receipt of 830315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spant fuel storage pools in interim final rule License amend requests examined on case-by-case basis PALLADIND, N J Commissioners 83/04/22 SIMPSON, A K House of Rep , Environment & Public Works 2pp 18374 001
- --B305240167 Ack receipt of B30315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis PALLADINO,N Commissioners B3/04/22 HART, G House of Rep . Environment & Public Works Rpp 18594 003
- --8305240179 Ack receipt of 830315 & 24 ltrs expressing concern re Commission treatment of license amend requests concerning reracking of spent fuel storage pools in interim final rule Amend requests examined on case-by-case basis PALLADINO.N J Commissioners 83/04/22 MITCHELL.Q J House of Rep . Environment & Public Works 2pp 18594 005
- --8305240190 "Btds for Determining Whether License Amends Involve No Significant Hazards Considerations," 10CFR30 interim final rule. Amends regulation to specify stds for determining if requested amend to OL involves significant hazards CHILK.B. J Office of the Secretary of the Commission 83/04/04 44pp. 18594 007
- B305250378 Comments on proposed rule re planned studies of GA programs for const of nuclear power plants. Supports program # Affiliation Unknown 48FR9106 028 B3/05/14 Docketing & Bervices Branch ip 18372 100
- 8305250381 Comments on proposed rule re-planned studies of GA programs for const of nuclear power plants. Supports INPO const & evaluation program. Further use of third-party svcs may result in reduction of util responsibility EDELMAN, M R Cleveland Electric Illuminating Co 48FR9106-027-83705714 Docksting & Services Branch ip 18592-101
- 8305250406 Package of two comments supporting proposed rule re NRC policy statement on regionalization REYNOLDS,N S. Debevoise & Liberman BRADBURY,R B Stone & Webster Engineering Corp. 46FR12617 83/05/19 CHILK,S J Office of the Becretary of the Commission 7pp. 18572 084
- B305230409 Comments on proposed rule re NRC policy statement on regionalization Supports rule MUSQLF.D. Northern States Power Co 48FR12619 050 83/05/16 Docteting & Services Branch 2pp 18585 330
- B305250415 Package of two comments opposing proposed rule re NRC policy statement on regionalization UHRIGAR E Florida Power & Light Co * Affiliation Unknown 49FR122619. 83/05/20 Docketing & Bervices Branch 7pp
- 8305250420 Comments on proposed rule re NRC policy statement on regionalization Supports rule KEARNEY, J Edison Electric Institute 48FR12619 047 83/05/16 CHILK, B J Defice of the Secretary of the Commission 2pp 18585:281.
- 8305250422 Comments on proposed rule iOCFR30 re license amends involving no significant hexards consideration NRC proposal vague & open to interpretation a Affiliation Unknown ABFR14864 019 83/05/14 Dockwiing & Services Branch ip 18583 358
- 8305250489 Forwards comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations.
 FLYNN:8 F. Carolina Power & Light Co 48FR14864 018 83/05/16 CHILK:8 J Office of the Secretary of the Commission 19 128881-200

- --8305250493 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations
 HURFORD.W J Carolina Power & Light Co 48FR14864 018 83/05/16
 CHILK,S J Office of the Secretary of the Commission App
- 8305250517 Package of two comments on proposed rule re GA program for const of nuclear power plants
 WILKINSON,E P Institute of Nuclear Power Operations MARIANI,L P.
 CARNEY,J American Nuclear Society 48FR9106 83/03/23
 DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 5pp 18588 268
- 8305250529 Forwards J Jackson comments on proposed rule re GA programs for const of nuclear power plants
 STINSON.R C Management Analysis Co 48FR9106 D29 83/04/25
 DIRCKS.W J Diffice of the Executive Director for Operations ip
 183588 230
- --8305250535 Comments on proposed rule re GA programs for const of nuclear power plants Recommends strong emphasis on GA mgt experience JACKEDN.J Management Analysis Co. 48FR9106 029 83/04/22 TAYLOR.J M. Division of Bafeguards & Inspection Programs (Post 830103) 3pp 18588 231
- 8305270003 Comments on proposed rule re NRC policy statement on regionalization Major technical activities re plant licensing should remain within NRR jurisdication BRADBURY: R B Stone & Webster Engineering Corp 48FR12619 049 83/05/16 Docketing & Services Branch 1p 18638 325

PROJECTS - PREDOCKET LICENSING

- B305030688 Clarifies definitions of plant & project low level radwastes to be used in developing West Vailey Demonstration Project mgt plan & subsequent environ assessment documentation HANNUM.W H Energy, Dept of 22157 B3/04/01 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 2pp 18309 138 24X Fiche 50-201,83/04/01,8305030688
- 8305040092 Forwards comments on 830224 topical rept, "Topical SAR for Castor Cask Type JSFS1 (Dry Storage) " Revised rept still lacks adequate definition re design requirements & objectives ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 83/04/22 ROLLINS, J.D. Geselischaft fuer Nuklear Service, mbH 33pp 18328 187
- B305060261 Forwards Vol 2 to "Annual Environ Rept.Radiological, 1982" SIEBER, J D Duquesne Light Co NDIMSL 2463 63/04/25 HIGGINTON. D Operating Reactors Branch 1 1p 18344 193 24X Fiche 50-334.83/04/25, 8305060261
- --8305060269 Vol 2 to "Annual Environ Rept.Radiological.1982" * Duquesne Light Co 83/04/25 126pp 18344 194 24X Fiche 50-334,83/04/25,8305060261
- B305090212 Forwards proprietory "Hestinghouse Advanced PWR Pretendering Module 5 Chemical & Vol Control Bys " Application for withholding & affidavit enci Rept withheld (ref 10CFR2 790) RAHE, E P Westinghouse Electric Corp NS-EPR-2759 B3/04/29 EISENHUT-D Q Division of Licensing 2pp 18362 342
- --8305070202 Application for withholding proprietary "Westinghouse Advanced PHR Pretendering Module 5 - Chemical & Vol Control Bys " Affidavit enc! HIESEMANN.R A Westinghouse Electric Corp AW-83-36 83/04/29 EIBENHUT.D 0 Division of Licensing 9pp 18362 344
- 8305100339 Notifies of applicant request for leave to withdraw appeal in instant matter
 ADRAGNA, J M Spiegel & McDiarmid ADRAGNA, J M Pacific Oas & Electric Co ISSUANCES A 83/05/09 ROSENTHAL, A S , MOGRET S , EDLES, O J Atomic Safety and Licensing Appeal Panel 1p 18378 339.
- B305100345 Advises that author will present B30518 oral argument on behalf of util re intervenor Northern California Power Agency appeal from B30i19 memorandum & order FALLIN.JF Pacific Oas & Electric Co ISSUANCES A B3/05/04 SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel 1p 18379 018
- 8305110345 Order granting Northern California Power Agency motion for leave to withdraw appeal from 830119 memorandum & order in antitrust proceeding Order scheduling appeal from 830518 oral argument vacated SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel ISBUANCES A 83/03/07 Pacific Gas & Electric Co ip 18406-186

- 8305130276 Requests add1 info re 830201 affidavit requesting Apps 1,3, 5,6 & 10 of Rev 1 to "forcal SAR for Castor Cask Type ISFSI (Dry Storage)," he withheld (ref IOCFR9 5 & 2 790) ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 83/05/03 ROULINS, J. D. Cesellschaft fuer Nuklear Service, mbH 1p 18458 226
- 8305160363 Forwards nonproprietary & proprietary varsions of "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," per 10CFR72 Affidavit to withhold proprietary info enct W/o proprietary version PARKER,P E Ridihalgh, Eggers & Associates 22161 83/04/14 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch App 18473 021
- --8305160365 "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel " * Riddhaigh, Eggers & Associates 22161 83/04/06 574pp
- E305180805 Responds to 830329 ltr requesting records of former NRClicensed burial area Arrangement should be made w/DDE for site access WHITE, I L. New York, State of, Energy Research & Development Afministration 22213 B3/04/12 CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety ip 18505 350
- 8305180810 Responds to 830307 Jtr advising of continued monitoring of Series 1780 & t782 wells by DOE Ultimate disposition of ualls will be determined by DOE & ERDA prior to completion of project DEBOER, T K New York, State of, Energy Research & Development Administration 2214 83/04/15 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety ip 18505 352
- 8305230015 Forwards Rev 1 to "Functional & Operational Requirements for Component Test Stand," for comments by 830515 HUNNUM,W H Energy, Degt of, Idaho Operations Ofc 83/04/18 CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch Ip 18542 232 24x Fiche 50-201.83/04/18.8305230015
- --8305230020 Rev 1 to "Functional & Operational Requirement» for Component Test Stand "

 * West Valley Nuclear Services Co , Inc 83/03/23 22pp 18342 233 24x Fiche 50~201.83/04/18.8305230015
- 830523004f Forwards "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel: " for review PARKER,P E Ridihalgh, Eggers & Associates 1098/83/57 83/04/14 RDUSE,L C Advanced Fuel & Spent Fuel Licensing Branch ip
- --B309230056 Forwards affidavit requesting withholding of proprietary info included in "Topical Rept for REA 2023 Dry Storage Cask for BUR Spent Fuel," (ref 10CFR2 790) PARKER:P E Ridihalgh. Eggers & Associates 1098/83/38 B3/04/14 ROUSE:L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18943 133
- 8305240614 Requests comments on "Geological Recommendations for Investigation of NRC Disposal Area," by 830527 MANNUM.N H Energy, Dept of, Idaho Operations Ofc 22219 83/04/21 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch Ip 18573 142 24X Fiche 50-201.83/04/21.8305240614
- --8303240618 "Genlogical Recommendations for Investigation of NRC Disposal Area "

 West Valley Nuclear Services Co . Inc 22219 83/03/16 21pp 18593 143 24X Fichs 30-201.83/04/21,8305240614
- 8305260393 Responds to itrs requesting comment re disposal of low level radweste DDE plan for disposal acceptable Detailed waste packaging info.per 10CFR61.requested Comments enci CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 83/05/16 HANNUM, W H Energy. Dept of 14pp 18647 193
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- B304150354 Part 21 Rept U-48 % interim deficiency rept re GE ARR-30 & AKR-50 circuit breakers Initially reported on B30211 Assessment of safety implications & corrective actions requested of AE Final rept expected by B30429 SCHNELL, D.F. Union Electric Co. 10CFR 030 55E B3/04/07 SPESSARD, R.L. Division of Project & Resident Programs ip 17982 128 24X Fiche. 50-000, B3/04/07, B304150354,

- 8305020133 Supplemental Part 21 Rept 6 re possible thermostatic valve malfunction fail-safe to full cooling position Lower overrun assemblies in Robertshaw valves on diesel generator sets replaced w/assemblies using cotter pins MORIARTY, J M Colt Industries, Inc. 83/04/21 KEPPLER, J Q. Region 3, Office of Director ip 18278 219 24X Fiche 50-483,83/04/21,8305020133
- B303030271 Supplemental response to Part 21 rept re postulated pipe crack in HPCI.RCIC.reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program DIET7.C R Carolina Power & Light Co BBEP/83-1260 B3/04/26 O'REILLY, J P Region 2, Office of Director 1p 18300 061 24% Fiche 50-324.83/04/26.8305030291
- 8305030300 Part 21 rept re linear indications identified in BA 106 grade pipe Initially reported on 830413 Caused by mfg process error & ultrasonic exam inadequecies All seamless pipe put on hold & magnetic particle examined CARLISLE.C S Washington Public Power Supply System 002-83-349 83/04/15 MARTIN.J B Region 5, Office of Director 18pp 18297 070 24X Fiche 50-397,83/04/15,8305030300
- B305030370 Søventh interim deficiency rapt re failure of balts & nuts to meet ASTM space Initially reported on B10924 Results of analysis of bolting matl will be evaluated Next rept will be submitted by B30707 Also reported per 10CFR21 MILLS,L M Tennessee Valley Authority 10CFR 050 55E B3/04/25 0'REILLY,J P Region 2, Office of Director 2pp 18306:217 24X Fiche 50~43B,83/04/25,8305030370
- 8305030387 Part 21 rept re pipe clamps for snubber/struts oriented in off-axis direction initially reported on 830224 & by IE Info Notice 83-13 Clamps will be replaced by end of Fall 1983 refueling outage
 DIETZ-C R Carolina Power & Light Co BSEP/83-1220 83/04/22
 O'REILLY, J P Region 2, Office of Director 2pp 18292 316 24X Fiche 50-324,83/04/22,8305030387
- 8305040486 Interim deficiency rept re nonconforming condition on Class IE low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222 Welding fix planned for cubicle EF2C05 Final rept will be submitted by 831130 EDELMANN R Cleveland Electric Illuminating Co 100FR 050 55E 83/04/27 KEPPLER. J G Region 3. Office of Director 2pp 18319 393 24X Fiche 50-440.83/04/27,8305040486
- 8305040496 Final deficiency rept re patential breach of seal integrity of hydrogen igniter Model 6043 glow plug component supplied by Power Sys Initially reported on 830207 Igniters repaired Also reportable per Part 21
 EDELMAN.H R Cleveland Electric Illuminating Co 10CFR 050 55E 83/04/27 KEPPLER.J Q Region 3, Office of Director 2pp 18319 336 24X Fiche 30-440.83/04/27.8305040496
- 8305050122 Second interim deficiency rept re unqualified flex-hose connections initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21 MILLS.L.M. Tennosses Valley Authority 10CFR 050 55E 83/04/28 0'REILLY.J.P. Region 2. Office of Director 2pp 18342 178 24X Fiche 50-438.83/04/28.8305050122
- 8303050124 Final deficiency & Part 21 repts re pressure boundary mati supplied by Tube Line Corp failing to meet Tech Specs, Item 123 Initially reported on 830330 Items returned to vendar New fittings purchased PARBONS, R M Carolina Power & Light Co 10cFR 050 55E 83/04/28 0'REILLY, J F Region 2, Office of Director 4pp 18341-343 24% Fiche 50-400.83/04/28,8305050124
- 8303050185 Interim deficiency & Part 21 repts re base metal defect in spool piece supplied by Southwest Fabricating & Welding Co. Initially reported on 830125 Vendor directed to show preventive measures Final rept by 830801 PARSONS:R M Carolina Power & Light Co 100FR 050 55E 83/04/29 0'REILLY.J P Region 2, Office of Director 4pp 18342'240 24X Fiche 50-400.83/04/29,8305050185
- 8305050299 Final deficiency & Part 21 repts re 480-volt switchgear design defect in secondary disconnects Initially reported on 82:102 Brown-Boveri completed change-out of all old style stationary secondary disconnects
 PARSONS:R M Carolina Power & Light Co 10CFR 050 55E. 83/04/29 O'REILLY.J P. Region 2, Office of Director 4pp 18338 016. 24% Fiche 50-400.83/04/29,8305050259
- 8305110292 Third interim deficiency rept re linear indications in Natl Valve & MFg Co spool pieces Initially reported on 820924. Vendor requested to supply list of spool pieces w/Heat Code L63687 Util awalting reply Also respontable per Part 21 HILLB, L M Tennessee Valley Authority 10CFR 050 55E 83/05/02 0'REILLY.J P Region 2, Office of Director 2pp 18373.234 24X Fiche 50-439.83/05/02.8305110292

- 8305110313 Part 21 rept re blow-out panel in east & west penetration areas Initially reported on 830506 Structural framing sys designed to protect flow transmitter & related instrument tubing BARKER, N R Gilbert/Commonwealth Cos 83/05/09 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 18393 196 24% Fiche 50-395,83/05/09,8305110313
- B305110322 Part 21 rept re ring duct stiffener failure Initially reported on 830506 Design change to eliminate airflow-induced vibration & redesign of ring stiffener submitted to util

 BARKER, N R Gilbert/Commonwealth Cos 83/05/07 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 18393 177 24X Fiche 50-395,83/05/07,8305110322
- 8305110324 Part 21 rept re Type SA-1 Class IE relays Bilicon controlled rectifier (BCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR W/burn-in SCR DUVALL,D. D. Brown Boveri Corp (subs. Brown Boveri & Co., Ltd.) PT21 83-807-000 B3/04/27 STELLO,V Director's Office Of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000.85/04/27.8305110224
- 8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened graces to accommodate new retaining rings Mfg drawings revised RAHG.E.P Westinghouse Electric Corp NS-EPR-2753 83/04/21 DEYQUNGR C Director's Office of Inspection and Enforcement 5pp. 18405 095 24% Fiche 50-000,83/04/21.8305110427
- 8305110441 Final deficiency rept re faulty relays mfg by Brown Boveri Electric in auxiliary power distribution sys Initially reported on 820528 Four relays returned to vendor for repair & reinstalled at facility Also reported per 10CFR21 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/05/02 0'REILLY.J P Region 2. Office of Director 2pp 18393 348 24X Fiche 50-439,83/05/02,8305110441
- 8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOGA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21 MANNO,8 F Niagara Mohawk Power Corp 6489 83/04/26 81AROSTECKI.R Region I. Office of Director 2pp 18433 072 24X Fiche: 50-000,83/04/26.8305120392
- --8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation EMPEY.D C Rockwell International Corp 83ES9-14B3 83/03/11 GQLLINS.J T Region 4. Office of Director 5pp 18433 074 24) Fiche 50-000,83/04/26,8305120392
- E305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attached hold tags to 13 HVAC control panels w/defect Evaluation being conducted HALL:D P Illinois Power Co 1404-L B3/05/04 KEPPLER.J G Region 3. Office of Director 2pp 18431 049 24X Fiche. 50-000. 83/05/04.8305120475
- --B305120484 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformence rept will be issued for applicable sites
 FAUCONNEAU.0 Mark Controls Corp 83/04/18 Director's Office, Office of Inspection and Enforcement 2pp 1843i 051 24X Fiche, 50-000, 83/05/04, 8305120475
- 8305130027 Part 21 & final deficiency repts (Item 104) re incorrect design of 480-volt suitchgear on secondary disconnects Disconnects installed in breaker cradle will be replaced PARBONS: R M Carolina Power & Light Co 10CFR 050 55E 83/04/27 O'REILLY, J P Region 2, Office of Director 4pp 18437 125 24% Fiche: 50-400, 83/04/27, 8305130027
- B305i30080 Deficiency rept re Class IE motor control ctrs from ITT Gould containing weld defects Initially reported on 830408 Vendor evaluation to be completed by Jul 1783 Extension until 8307i3 requested Also reported per Part 21. PARBONS, R M. Carolina Power & Light Co 100FR 050 55E 83/05/06 0'REILLY, J P Region 2, Dffice of Director 1p 18436: 264. 24X Fiche: 50-400, 83/05/06, 8305130080
- 8305130107 Final Deficiency Rept DER 83-2 re valve operators accidentally interchanged by Posi-Seal on inside & outside containment valves Initially reported on 830125 Operators to be replaced Also reported per Part 21 by Posi-Seal VAN BRUNTLE E. Arizona Public Bervice Co 10CFR 050 55E, 83/05/03 STERNBERGO.DM. Region 5. Office of Director 4pp 18437 219 24% Fichar 50-528,83/05/03,8305130107

- 8305130113 Part 21 rept re low natural frequency of counterbalance assembly, resulting in unacceptable stresses on backdraft damper counterbalance arm Seismic qualification criteria not fully met investigation & testing underway HILL/T D Ruskin Manufacturing Co 83/05/10 Director's Office, Office of Inspection and Enforcement 7pp 18438 001 24X Fiche 50-400, 83/05/10, 8305130113
- 830513014B Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements Initially reported on 821124 Revised test plan reviewed by Bechtei Final rept expected by 830823 Also reported per Part 21

 VAN BRUNT, E E Arizona Public Service Co DER 82-76 83/05/03

 STERNBERO D M Region 5, Defice of Director 4pp 18438 117 24X

 Fiche 50-528,83/05/03,8309130148
- 8305130154 First interim deficiency rept re defects in pipe clamps mfg by ITY Orinnell Initially reported on 830406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/05/06 0'REILLY.J P Region 2. Office of Director 3pp 18437 182 24X Fiche 50~438.83/05/06.8305130154
- 8305130189 Final Deficiency Rept DER 83-12 re maifunction of GE add-on electric interlocks used w/Class IE. Size 2, starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21 VAN BRUNT, E E Arizona Public Service Co 100FR 050 55E 83/05/03 STERNBERG, D M Region 5, Defice of Director 5pp 18439 340 24X Fiche 50-528.83/05/03.8305130189
- G305130222 Part 21 rept re potential ASME Section III & V violation Initially reported on G30412 Scope & condition of nonconformance under (nvestigation WHEATON, W R Dorg-Warner Corp G-B3-007/WRW G3/04/15 MARTIN, J B Region 5, Office of Director 4pp 16439 336 24X Fiche 50-440, 63/04/15, G305130222
- 8305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LOCA Initially reported on 830407 Final rept expected by 830815 Also reported per Part 21 EDELMAN.MR Cleveland Electric Illuminating Co 10CFR 050 55E 83705706 KEPPLER.J G Region 3. Office of Director 2pp 18439 212 24X Fiche 50-440.83/05/06.8305130248
- 8305130264 Interim Deficiency Rept DER 83-16 re failure of dieset generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on B30318 Also reportable per 105FR21 VAN BRUNT, E E Arizona Public Service Co DER 83-16 55E 83/05/03 STERNDERGO, DM Region 5, Defice of Director 4pp 18439.238 24X Fiche 50-528,83/05/03,8305130264
- 8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in FDR App B.C.D & E documents withheld (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/03/11 PRENDEROAST.R Prendergast. R J 17pp 18504 059 24X Fiche 50-000.83/03/11.8305190005
- --8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & GA/GC personnel will be added Also reportable per Part 21 CALKINS,D & Zact Co 100FR 050 55E 81/1023 310pp 18306 215 24X Fiche 50-000,83/03/11,8305190005
- 8305200429 Final Significant Deficiency Rept 82-06 re failed sheared pinion keys in Limitorque motor operators supplied by Usstinghouse All deficient keys replaced Also reportable per Part 21 WOOLEVER.E J Duquesne Light Co 100FR 050 55E 83/05/10. ALLANJ Region I. Office of Director 5pp 18517 145 24X Fiche 50-412.83/05/10.8305200427
- 8305200495 Supplementary Part 21 rept re adequacy of svc water cooling towar structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630
 SARSTEN-0 E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/04/29 Region I, Office of Director 3pp 18514 033 24X Fiche 50-443, 83/04/29, 8305200495
- 8305230525 Final deficiency rept re Westinghouse reactor trip switchgear undervoltage attachments w/design discrepancy initially reported on 830422 Attachments replaced Mfg drawings & GC procedures modified Also reported per Part 21 OPREA:0 W Houston Lighting & Power Co 10CFR 050 55E 83/05/18 CCLLINS.J T Region 4. Defice of Director 4pp 18336 319 24X Fichs 50-498.83/05/18.8305230525

- 8305230545 Second interim rept re generic deficiencies at Consolidated Controls Carp Initially reported on 820916 Evaluation indicates QC problems corrected & equipment failures random Also reported per Part 21 Next rept by 831117 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/05/18 0'REILLV.J P Region 2, Office of Director 2pp 18537 085 24X Fiche 50-438,83/05/18,8305230545
- 8305240356 Part 21 rept re boiting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers initially reported on B30513 Bolting parts greater than 2-inch size not examined HOVI.L NPS Industries, Inc. PT21 B3-876-000 B3/05/16 DEYGUNOR C Director's Office. Office of Inspection and Enforcement ip 18374 001 24% Fiche 30-000,83/05/16.8305240356
- B305240405 Recommends consideration by afforded to contacting listed utils to determine review & mod status of deficient vertical lift metal-clad suitchgeal mag by GE POTAPOVS, U Division of Vendor & Technical Programs 83/05/19 BAER,R L Engineering & Generic Communications Branch 2pp 18374-279
- B305250435 Final rept re deficiencies in Ameron cement mortar lining Initially reported on B20521 Corrections to each deviation listed Also reportable per 100FR21 MILLS, L. M. Tennessee Valley Authority 100FR 050 55E B3/03/20 O'REILLY, J. P. Region 2. Defice of Director 6pp 18585 293 24X Fiche 30-390, 83/05/20, 8305250435
- 8305270625 Part 21 rept re-potential problem w/3-phase rectifier assembly in exciter not connected in perallel which could cause premature failure initially reported on 830520 Utils will measure vibration HAISLER, R K Litton Industries. Inc. 83/05/20 KEPPLER, J 9 Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20,8305270625
- B30531013B Seventh interim deficiency rept re inconsistency between assumptions for pipe break in LOCA & structural analyses for connecting pipes in affected loop Initially reported on B01121 Next rept by B3111B Also reported per Part 21 MILLS,L M Tennessee Valley Authority LOCFR 050 55E B3/05/23 O'REILLY,J P Region 2, Office of Director 2pp 18656 125 24% Fiche 50-438,83/05/23,830531013B
- 8305310214 Eighth interim deficiency rept re 8&H nonconservative analysis of heutron flux Initially reported on 801105 Also reportable per Part 21 Util auaiting results of 8&H analysis Next rept will be submitted by 831024 MILLS.L M Tennessee Valley Authority 100FR 030 55E 83/05/23 0'REILUV.J P. Region 2, Office of Director 2pp 18658 146 24% Fiche 50-438.83/05/23.8305310214

GA999 GUALITY ASSURANCE INSPECTIONS

- 8305020254 Confirms QA program insp on 830524-27 at Radiation Technology.Rockaway.NJ plane, per 830425 telcon FOTAPOVS,U Region 4. Office of Director 83/04/28 WELT,M A Radiation Technology ip 18281 298
- 8305020261 Ack receipt of 830308 ltr informing NRC of steps taken to correct nonconformance noted in GA Program [nsp Rept 97900913/92-02 POTAPOVS.U Region 4. Office of Director 83/04/28 DIETZ.O R Isomedia. Inc. (subs of Masefield Enterprises, Inc.) ip 18272 251
- --B30502026B Responds to NRC B30207 ltr re nonconformance noted in GA Program Insp. Rept 99900913/82-02 Corrective actions operators given formal instructions re calculation of dose rate & GC manuals revised

 TYMPANICK, Isomedix, Inc (subs of Masefield Enterprises, Inc.) B3/03/08 POTAPOVS, U Region 4, Office of Director 12pp 18277 252
- 8305020289 Forwards GA Program Insp Rept 99900403/82-03 on 820628-0701 & D713-15 & notice of nonconformance PDTAP009.U Division of Vendor & Technical Programs 83/02/02 BRUGGEMAN, H M General Electric Co 2pp 18277 176
- ---8305020295 Notice of nonconformance from insp on 820628-0701 & 0713-15 * Region 4. Office of Director 83/02/02 ip 18277 178
- --8305020307 GA Program Insp Rept 97900403/82-03 on 820628-0701 & 0713-15 Noncompliance noted documented instructions or procedures not utilized to communicate quality requirements re dispositioning of potential design action items CHAMBERLAIN. D. HALERC J. Region 4, Office of Director 82/08/19 17pp 18277 179.

- B305020316 Forwards GA Program Insp Rept 99700403/82-04 on 820628-0719, No noncompliance nated POTAPOVS, U Region 4. Office of Director B3/02/02 BRUQOEMAN, H H General Electric Co 2pp 18277 140
- --8305020319 GA Program Insp Rept 99900403/82-04 on 920628-0719 No noncompliance noted Major areas inspected interview of former employee re number of Mark III containment unresolved issues per Part 21 requirements HILLIAMSON,E L, BURCH,R H, ALDERBON,C E Region 4. Office of Director 82/08/20 App 18277 142
- 8305020344 Confirms OA program insp at Tustin, CA plant on 830502-04, par 830415 tolcon POTAPOVS, U Region 4. Office of Director 83/04/28 CHIN, A Radiation Sterilizers, Inc. ip 18277 064
- 8303020364 Ack receipt of 830228 & 0407 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900403/82-03 PGTAPDVS.U Region 4. Office of Director 83/04/28 BRUQQEMAN.H H General Electric Co ip 18284 025
- --8305020365 Responds to NRC 830317 ltr requesting add1 info re nonconformance noted in GA Program Insp Rept 99700403/82-03 Requirements for design actions formally documented in engineering operation procedures 80HL,L S General Electric Co. 83/04/07 PDTAPOVS.U. Region 4, Office of Director 2pp 18284 026
- --8305020366 Ack receipt of 830228 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9990403/82-03 Add1 info needed re actions on design action item 11st PDTAPOVS.U Region 4. Office of Director 83/03/17 BRUGGEMAN.W H Conseral Electric Co ip 18284.028
- --8305020349 Forwards response to NRC 830202 ltr re nonconformance notes in QA Program Insp Rept 97900403/82-03 Corrective actions: Engineering Operating Procedure 55-4 00, "Change Control Board," revised on 820714
 BOHLLL S General Electric Co 83/02/28 PQTAPOVS, U Region 4, Office of Director 2pp 18284 029
- 8305020420 Summary of 830422 meeting w/Hestinghouse in East Pittsburgh. PA re reactor trip breaker problems Changes in mfg controls & 9A program planned Attendance list encl PTOTAPDYSU Division of Vendor & Technical Programs 83/04/28 Division of Vendor & Technical Programs 4pp 18273 124
- 8305020448 Confirms QA program insp at Cherry Hill, NJ ofc on 830502-Côper 830420 telcon POTAPOVS.U Region 4, Office of Director. 83/04/28 KELLY, R B Stone & Webster Engineering Corp 1p 18283 179.
- 8305030349 Forwards GA Program Insp Rept 99900759/83-01 on 821127-1203 POTAPOVS: U Region 4. Office of Director 83/04/15. BUNDSTEDT: J E Woodward Governor Co 2pp 18297 118
- --8305030351 GA Program Insp Rept 99900759/83-01 on 821129-1203. No noncompliance noted Major areas inspected defective governor furnished to Palisades & deficient EOB-13P actuator furnished to Stewart & Stevenson Sycs, Inc.
 FUSTER, W E., BARNES, I Region 4, Office of Director 83/03/31, 13p 18297, 120
- 8305030358 Forwards QA Program Insp Rept 99900769/83-01 on 830207-10 & notice of nonconformance.
 POTAPOVS, U Region 4. Office of Director 83/04/15 HE88/L. R. Pacific Air Products Co 2pp 18291 342
- --8305030362 Notice of nonconformance from insp on 830207-10.

 * Region 4, Office of Director 83/04/15. 1p. 18291.344.
- --8305030366 GA Program Insp Rept 99900769/83-01 on 830207-10
 Noncompliance noted:records not maintained to indicate
 evaluation made for reportability of defectively-mounted
 blade locks in safety-related fire dampers.
 OLLER, R E , BARNES, I. Region 4, Office of Director, 83/04/15,
 16pp 18291 345

- 9305030363 Forwards QA Program Insp Rept 97900053/83-01 on 930125-28 Followup on failure to perform verification of torque adequacy requested W/o encl POTAPOVS,U Division of Vendor & Technical Programs 83/04/28 NORELIUS
- B305030377 Forwards GA Program Insp Rept 99900769/B3-01 on 830207-10 identifying potential loose locks on fire dampers at McGuire station W/o encl POTAFOVS:U Division of Vendor & Technical Programs B3/04/29 LEWIS:R L Division of Project & Resident Programs Ip 18306-293
- 8305030413 Recommends actions be taken to verify whether welding in place has been accomplished & impact of mounting on seismic qualification re vendor insp at En-Tronic Controls of dissel generator high voltage cubicles & foundations POTAPOVB.U Division of Vandor & Technical Programs 83/04/27 CREWB.J L Division of Resident, Reactor Project & Engineering Programs ip 18306-315
- B305030427 Informs that AITS F03034682 re defective diesel generator governor at Palisades closed following insplat Engine & Turbine Controls Div of Woodward Governor Co W/o QA Program Insplay 19900739/82-01 POTAF0VS.U Division of Vendor & Technical Programs. VITS 82-254 83/04/27 BPES9ARD.R L Division of Project & Resident Programs ip 18306 276
- 8305030466 Forwards QA Program Insp Rept 99900053/83-01 on 830125-28 & notice of monconformance FOTAPDV81 W Region 4, Office of Director. 83/04/12 CAROD.A E Anchor/Darling Valve (subs Anchor/Darling Industries) 2pp 18294:152
- ---8305030471 Notice of nonconformance from insp on 830125-28 * Region 4, Office of Director 83/04/12. 2pp 18274 154
- --8305030475 0A Program Insp Rept 97900053/83-01 on 830125-28
 Noncompliance noted design rept for 900-16 feedwater
 isolation valves furnished to Haterford Unit 3 did not
 address validity of valve closing design
 KELLEY, W D., BARNES, I Region 4: Office of Director 83/04/07
 10ps 1824 156
- 8305030509 Forwards GA Program Insp Rept 99900373/83-01 on 830214-18 & notices of nonconformance & violation POTAPOVS.U Region 4, Office of Director 83/04/12 DEKKER.H A Entronic Co 3pp 18295 305
- --8305030511 Notice of violation from insp on 830214-18 * Region 4, Office of Director 83/04/12. 2pp 18295.308
- --8305030518 Notice of nonconformance from insp on 830214-18 * Region 4, Office of Director. 83/04/12 2pp 18295 310
- --8305030525 GA Program Insp Rept 99900373/83-01 on 830214-18
 Noncompliance noted current copies of Section 206 of Energy
 Reorganization Act not posted & procedures not adopted to
 provide for deviation evaluations & informing director
 FGSTER.W E , BARNES I Region 4. Office of Director 83/04/04
 Ppp 18295-312.
- 8305030320 Requests guidance for insp of vendors not committed to App B of 10CFR30 or 10CFR31. Insp of Woodward Governor Go discussed GA Program Insp Rapt 97900759/82-01 not encl.

 8ANGART.R L. Division of Vendor & Technical Programs 83/04/20
 TAYLOR.J. Division of Engineering & Guality Assurance (Fre 830103)
 2pp. 18295-321
- 8305030544 Forwards QA Program Insp Rept 99900769/83-01 on 830207-10 re potential loose locks on fire dampers W/o encl POTAPDV8/U Division of Vendor & Technical Programs 83/04/29 BTARGSTECKI,R Division of Project & Resident Programs ip. 18305-265
- B305050068 Forwards GA Program Insp Rept 99900303/83-01 on 830308-10 No noncompliance noted PDTAPOV6.U Region 4, Office of Director B3/04/21 METTA,8 Applied Engineering Co 2pp 18339.094
- --8305050071 GA Program Insp Rept 99900303/83-01 on 830308-10 No noncompliance noted Major areas inspected mgt meeting status of previous insp findings.10CFR21 insp. GA program, mfg process control.corrective action & audits SUTTON.J W. BARKEB, I Region 4, Office of Director 83/04/20 7pp 18339 096
- 8305050088 Forwards QA Program Insp Rept 99900017/83-01 on 830228-0304 & notices of nonconformance & violation POTAPOVS,U Region 4, Office of Director, 83/04/21 ANDERSON,K Drave Corp 3pp, 18342:028

- --8305050090 Notice of violation from insp on 830228-0304 * Ragion 4. Office of Director 83/04/21 ip 18342-031
- --8305050091 Notice of nonconformance from insp on 830228-0304 * Region 4. Office of Director 83/04/21 3pp 18342-032
- --8305050093 GA Program Insp Rept 99700017/83-01 on 830228-0304 Noncompliance noted failure to post regulations/procedures in either of two fabrication shop bldgs & failure to generate nonconformance repts for five rejected fittings CONHAY.J T. BARNES.I Region 4. Office of Director 83/04/20 9pp 18342-035
- 8305050094 Ferwards OA Program Insp Rept 99900401/83-01 on 830308-10 No noncompliance noted POTAPOVS.U Region 4. Office of Director 83/04/19 ETHERIDGE.M R Combustion Engineering, Inc. 2pp 18342 012
- --8305030097 GA Program Insp Rept 99900401/83-01 on 830308-10 No noncompliance noted Major areas inspected status of previous insp findings re shoulder gap problems at five facilities MCNEILL.H M. PARNES. I Region 4. Office of Director 83/04/15 App 18342 014
- 8305050102 Forwards GA Program Insp Rept 97900002/83-01 on 830308-10 & notice of nonconformance PDTAPDV8.U Region 4. Office of Director 83/04/21 LICHEMBERGER.H Combustion Engineering, Inc. 3pp 18341 319
- --8305050104 Notice of nonconformance from insp on 830308-10 * Region 4. Office of Director 83/04/21 ip 18341 322
- --8305050110 GA Program Insp Rept 99700002/83-01 on 830308-10
 Noncompliance noted failure to enter release number for
 poison pallets & compression sleeve used for Lot 115-1 &
 traveler for Lot 128-1 missing release number
 MCNEILL: H M, BARNES: I Region 4: Office of Director. 83/04/19
 App 18341 323
- 8305050107 Forwards QA Program Insp Rept 99900348/83-01 on 830222-25 No moncompliance hoted POTAPOVS.U Region 4. Office of Director 83/04/13 O'CONNELL.T J NP8 Industries, Inc. 2pp 18342 147
- --8305050111 GA Program Insp Rept 97900348/B3-01 on 830222-25 No noncompliance noted Major areas inspected status of previous insp findings.mPg process control equipment calibr & procurement document control

 GLLER.R E , BARNES, I Region 4, Office of Director 83/04/04
 1100 18342 169
- 8305050114 Forwards QA Program Insp Rept 99700911/83-01 on 830207-11 & notice of nonconformance POYAPOVS,U Region 4: Office of Director 83/04/13 BRUGGEMAN.W H General Electric Co 2pp 18342 180
- --8305050115 Notice of nonconformance from insp on 830207-11
 * Region 4: Office of Director 83/04/13 2pp 18342 182
- --8305050117 QA Program Insp Rept 99900911/03-01 on 830207-11
 Noncompliance noted environ qualification testing initiated
 before review approval & issuance of product performance
 qualification Spec PPQS 22A5760
 AGEG.J R , PHILLIPS.H S Region 4, Office of Director 83/04/08
 14pp. 18342:184
- 8305050145 Forwards QA Program Insp Rept 99900264/83-01 on 830214-18 No noncompliance noted POTAPOVS,U Division of Ventor & Technical Programs 83/04/19 HAGGARD,K D Dragon Valves, Inc 2pp 18341 093
- --B305050149 GA Program Insp Rept 99900264/83-01 on 830214-18 No noncompliance noted Major areas inspected GA program (organization), nonconformance/corrective action, process control, final insp. mesembly & test & audits 8UTTON.J W. BARNES, I Region 4, Office of Director 83/04/15 9pp 18341:095
- 8305050160 Discusses GA Program Insp Rept 97900224/83-01 on 830214-18
 Appropriate corrective action taken & problem re ECCS
 cabinets incorrectly wired determined not generic
 POTAPOVB.U Division of Vendor & Technical Programs
 8PE8BARD.R.L. Division of Project & Resident Programs
 19341 360
- 8305050162 Forwards GA Program Insp Rept 99900795/83-01 on 830314-17 & notices of nonconformance & violation POTAPOVS.U Region 4. Office of Director 83/04/21 LOTT.J E E L Manufacturing Peebles, Inc 3pp 18339 352

- --8303050169 Notice of violation from insp on 830314-17 * Region 4. Office of Director 83/04/21 lp 18339 355
- --8305050171 Notice of nonconformance from insp on 830314-17 * Region 4. Office of Director 83/04/21 ip 18339 356
- --8305050179 GA Program Insp Rept 99900795/83-01 on 830314-17 Noncompliance noted all unidentified electrodes were not discarded & current copy of 100FR21 not posted MCNEILL,W M , BARNES,I Region 4, Office of Director 83/04/20 7pp 18339 357
- B305050177 Forwards QA Program Insp Rept 99900323/B3-01 on 830222-25 & natices of nonconformance & violation PDTAPDVS.V Region 4, Office of Director B3/04/I3 ADAMS.J Conax Corp 2pp 18341 039
- --8305050181 Natice of violation from insp on 830222-25
 * Region 4, Office of Director. 83/04/13 ip 18341 041
- ---8305050184 Notice of nonconformance from insp on 930222-25 4 Region 4, Office of Director 83/04/13 2pp 18341 042
- --8305050192 GA Program Insp Rept 99900323/83-01 on 830222-25
 Noncompliance noted records for all lead auditors not
 updated annually, IOCFR21 & procedures not posted & testing
 for Grand-Rer control cables not performed
 SMITH.A L , FMILLIPS, H S Region 4, Office of Director 83/04/07
 18pp 18341 044
- 8305050219 Forwards GA Program lasp Rept 99900525/83-01 on 830228-0304 No noncompliance noted PDTAPDVS.U Region 4. Office of Director 83/04/15 LORENZ.H Gilbert/Commonwealth Cas 2pp. 18336 076
- --8305050226 CA Program Insp Rapt 99900525/83-01 on 830228-0304 No noncompliance noted Major areas inspected status of previous insp findings, internal audit program & review of design activities associated w/clamp-induced local pipe stresses HARRELL.P H. HALE.C J Region 4. Office of Director 83/04/13 14pg 18338 078
- 8305050237 Forwards GA Program Insp Rept 99900224/83-01 on 830214-18 No noncompliance noted PDTAPDVS, U Region 4, Office of Director 83/04/13 KEYES, H A Bailey Controls Co (subs of Babcock & Wilcox Co) 3pp 18337 302
- --8305050241 QA Program Insp Rept 99900224/83-01 on 830214-18 No noncompliance noted Major areas inspected 10CFR50 55e rept re wiring errors in emergency core cooling actuation sys at Midland Units 1 & 2 PARKER, L B., BARNES, I Region 4, Office of Director 83/04/14 24pp 18337 303
- 830503025! Forwards OA Program Insp Rept 99900705/83-01 on 830117-20 & notices of nanconformance & violation POTAPOVS.U Region 4. Office of Director 83/04/21 SADLIER.R C Wile Laboratories 3pp 18337 342
- --8303050255 Notice of violation from insp on 830117-20 * Region 4, Office of Director 83/04/21 ip 18337 345
- --9305050259 Notice of nonconformance from insp on 930117-20 + Region 4, Office of Director 93/04/21 2pp 19337 346
- --8305050262 GA Program Insp Rept 99900905/83-01 on 830117-20
 Noncompliance noted failure to post current regulations,
 insufficient info in GA manual & failure to conduct mgt
 audit of GA program
 AGEE.J R Region 4. Office of Director PHILLIPS.H S Division
 of Vandor & Technical Programs 83/04/14 J5pp 18337 348
- 8305090001 Ack receipt of 830331 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900761/83-01 POTAPOVS, U. Region 4, Office of Director 83/04/21. MORROW, Reliance Electric Co. ip 18364-052
- --8305090003 Responds to NRC 830225 itr re nonconformances noted in GA Program Insp Rept 99900761/83-01 Corrective actions last phase of retraining program completed 821130 Evaluation of suppliers of calibr svc will be completed 930520 MORROW, R Reliance Electric Co 83/03/31, PDTAPOVS, U Region 4, Office of Director 2pp 18364 053

- 8305090371 Ack receipt of 830418 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900512/83-01 PUTAPUVS, U Region 4, Office of Director 83/05/04 BUPP, L. P Quafrex Corp ip 18363
- --B305090388 Responds to NRC B30325 ltr re nonconformance noted in QA Program Insp Rept 99900512/83-01 Corrective actions audit completed on B21006 QA procedure revised to require advisement should any response to external insp not be met BUPP.L P Quadrex Corp LPB-B3-O22 83/04/18 POTAPOV8,U Region 4. Office of Director 2pp 18363 357
- 8305070386 Forwards GA Program Insp Rept 99700283/83-01 on 830228-0304, notice of violation & notice of nonconformance POTAPOVS, U Region 4. Office of Director 83/04/20 MANCHESTER, E BIW Cable Systems. Inc. 2pp 18363 038
- --8305090393 Notice of violation from insp on 830228-0304 * Region 4, Office of Director 83/04/20 ip 18363 040
- --8305090404 Notice of nonconformance from insp on 830228-0304 * Region 4, Office of Director 83/04/20 3pp 18363:041
- --83050904i3 OA Program Insp Rept 99900283/83-01 on 830228-0304
 Nancompliance noted safety-related testing svcs procured
 from Associated Testing Labs & Isomedix, Inc w/o specifying
 applicability of 10CFR21 provisions
 SMITH,A L. PHILLIPS,H 8 Region 4, Office of Director 83/04/15
 18pp 18363 044
- B3D5090392 Forwards QA Program Insp Rept 99900370/B3-01 on B30131-0204 & notice of nonconformance POTAPUS, U Region 4. Office of Director B3/04/20 KULB.B. garrett Corp 2pp 18363 026
- --8305070398 Natice of nanconformance from in*p on 830131-0204
 * Region 4, Office of Director, 83/04/20 1p 18363 028
- ---8305090403 GA Program Insp Rept 99900370/83-01 on 830131-0204
 Noncompliance noted NRC not formally notified per Part 21
 that shipped solenoid valves contained defect & GA program
 did not include identification & control sys
 SUTTON.J W. HAMILTON.J Region 4. Office of Director 83/04/14.
 9pp 18363 029
- 8305090450 Confirms QA program insp at Process Technology on 830607-10, per 820425 telcon POTAPOVS,U Region 4, Office of Director 83/05/04 WELT,M A Process Technology, Inc. 1p. 18362-264
- 8305090479 Forwards OA Program Insp Rept 99900387/83-01 on 830207-10 & notice of nonconformance COLLING, J T Region 4. Office of Director 83/04/20 UISSUNETTE, P QA Technologies, Inc /Qeneral Atomic Co 3pp 18362 325
- --8305090482 Notice of nonconformence from insp on 830207-10. * Region 4, Office of Director 83/04/20 3pp 18362 328.
- --8305090485 GA Program Insp Rept 99900387/83-01 on 830207-10
 Noncompliance noted 820323 itr to NRC failed to assure
 adherence to stipulated test methods & series of training
 sessions did not provide clear direction
 MCNETLL.W M , BARNER, I Region 4, Office of Director 83/04/15,
 7pp 18362 331
- 8305100336 Ack receipt of 830125 & 0329 ltre informing NRC of steps taken to correct nonconformance noted in QA Program Insp. Rept 99900902/82-08 POTAPDVS, U Region 4, Office of Director 83/05/04 HOLBROOK, W Wyle Laboratories ip 18378 337
- ---8305100343 Requests addl info re responses to Nonconformances A 3,A 2 i C noted in GA Program Insp Rept 99900902/82-08 Info requested within 25 days PDTAPDVS-U Region 4, Office of Director 83/03/14 HOLBROCK-W W Hyle Laboratories 2pp 18378 338
- --8305100349 Responds to 830314 request for add1 info re Nonconformance:
 A 3,A 2 & C GA personnel instructed in responsibilities to
 keep approved procedure list current
 HOLBROOK,H W Myle Laboratories 83/03/29 POTAPOVS,U. Region
 4, Office of Director 3pp 18378-340

- --8305100355 Responds to NRC 830104 ltr re nonconformance noted in GA Program Insp Rept 99900902/82-08 Corrective actions GA program changed to eliminate requirement for GA/safety job requirements review HOLBROOK, W W Wije Laboratories 83/01/25 PDTAPOVS, U Region 4. Office of Director 16pp 18378 343
- 9305120305 Confirms QA program insp on 830509-13 at Chicago pfc per 830504 telcon POTAPUSJU Region 4. Office of Director 83/05/06 PATTERSON,R W 8argent & Lundy, Inc. 1p 18424 207
- 8305120394 Forwards QA Program Insp Rept 99900768/82-02 on 820128-0310 No noncompliance noted POTAPOVS.U Region 4. Office of Director 83/02/09 KDH.B Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp
- 18432 320

 --8305120397 QA Program Insp Rept 99900768/82-02 on 820128-0310 No noncompilance noted Major areas inspected allegations by
- --B3012C397 (A Program Insp Rept 79900768/82-02 on 820128-0310 Ni noncompliance noted Major areas inspected allegations by former employee re quality of HN-100 Series 1,HN-1008 & HN-200 shipping casks. SHEPHERD.R E , CARLSON.R T Region 1, Office of Director 82/07/19 65pp 18432 322
- 8305120482 Confirms GA program insp at New Haven,CT plant on 830606-10 per 830502 telcon PDTAFDV8.U Region 4. Office of Director 83/05/10 REED,E S Rockbestos Co ip 18431 054
- 8305170541 Confirms QA program insp at Culver City.CA plant on B30523-27.per 830504 telcon Insp will cover equipment qualification testing of safety-related equipment PCTAPOVS.U Region 4. Office of Director 83/05/13 RNDLER.O J ANCO Engineers, Inc. ip 18468 027
- 8305170549 Confirms QA program insp at Whippany, NJ plant on B30531-0602.per 830509 telcon POTAPOVB, U Region 4, Office of Director 83/05/13 DIETZ, OR Isomedix, Inc (subs of Masefield Enterprises, Inc) ip 18469 022
- 8305200308 Ack receipt of 830217 & 0414 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 97900005/82-02 POTAPBUSI U Region 4, Office of Director 83/05/10 JACOBI, W M Westinghouse Electric Corp ip 18516 280
- --8305200315 Responds to NRC 830322 ltr requesting add1 info re nonconformances noted in GA Program Insp Rept 97900005/82-02 Corrective actions meetings held w/quality & customer svcs engineers to review customer needs RUSSO, H L Westinghouse Electric Corp PA-83-012. 83/04/14 FOTAPOVS, U Region 4. Office of Director 2pp. 18516-281
- --8305200323 Ack receipt of 820217 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 99900005/82-02 Add1 info needed confirming that actions implemented re documentation of reviews POTAPOVS.U Region 4. Office of Director 83/03/22 JACOBI.H M Westinghouse Electric Corp ip 18316-283
- --8305200332 Responds to NRC 830118 itr re nonconformances noted in GA Program Insp Rept 9990005/82-02 Corrective actions procedures for order & spec review evaluated w/quality & customer svc engineers RUBSO,H L Hestinghouse Electric Corp PA-83-008 83/02/17 POTAPOVS,U Region 4, Office of Director 3pp 18516 285
- B305200333 Forwards QA Program Insp Rept 99900503/B3-01 on B30318 No noncompilance noted PGTAPOUS,U Region 4, Office of Director B3/05/04 HENDRICKSON,T Burns & Roe Co 2pp. 18516 220
- --B305200340 QA Program Insp Rept 97900503/B3-01 on B30318 No noncompliance noted Hajor areas inspected piping stress analysis in area of pipe clamps mfg by E-Bys & status of previous nonconformances

 BEARB, P. HALE, C. J. Region 4, Office of Director 83/05/04. App 18516 222
- 8305200370 Forwards GA Program Insp Rept 99700056/83-01 on 830214-18 & notice of nonconformance Response requested within 30 days.

 POTAPOVS.U Region 4. Office of Director 83/04/28. WILSDN, A K Henry Pratt Co 3pp 18517 349
- ---8305200376 Notice of nonconformance from insp on 830214-18 * Region 4, Office of Director 83/04/28 5pp 18517 352

- --8305200379 OA Program Insp Rept 99700056/83-01 on 830214-18
 Noncompliance noted failure to implement fully GA program to
 meet training & indoctrination requirements
 CCNMAV.J T. BARNES.I Region 4. Office of Director 83/04/21
 18pp 18517 357
- 8305200395 Responds to nonconformances noted in GA Program Insp Rept 99900743/82-01 on 821006 & 07 Revs to procedures & data sheets for TVA units returned for mod or rework will be completed by 830130 DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co, Ltd.) 83/01/04 POTAPOVS.U Region 4, Office of Director 2pp 18318 175
- 8305200411 Ack receipt of 830104.11 & 0309 itrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900743/82-01 POIAPOUS,U Region 4, Office of Director 83/05/10 DUVALL.D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.) 1p 18517 164
- --B305200415 Responds to NRC B30215 ltr re nonconformance noted in QA Program Insp Rept 97700743/82-01 Corrective actions QA procedure written to define steps necessary to implement mod of relays returned from field DUVALL.D D Drown Bover! Corp (subs Brown Bover! & Ca , Ltd) B3/03/09 POTAPQVS.U Region 4, Office of Director 3pp 18517 165
- --8305200418 Ack receipt of B30104 & 11 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900743/82-01 Understands procedures will be generated to prevent recurrence Add1 info needed re ftem C POTAPBVS,U Region 4, Office of Director 83/02/15 DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 2pp 18517 168
- --B3D5200422 Responds to NRC 821202 ltr re nonconformance noted in GA Program Insp Rept 9790743/82-01. Corrective actions test procedures & data sheets will be revised by B30130 DWALL: D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.) B3/01/1; PDTAPOVS, U Region 4, Office of Director 3pp 18517 172
- 8305200443 Confirms QA program inap on 830613-16 at Milford.OH plant, per 830427 telcon POTAPOVS.U Region 4, Office of Director 83/05/17 FARWELL,C R Farwell & Hendrix, Inc. 1p. 18517 118
- 8305200444 Ack receipt of 821122 & 830314 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99700782/82-01 PGTAPOVS.U Region 4. Office of Director 83/05/10 FLANNERY.E J Brunswick Co
- ~-8309200457 Responds to NRC 830131 ltr re monconformance noted in GA Program Insp Rept 99700782/82-01 All procedures will be fully operational by 830630 Rev to GA manual defining procedure for handling latent defects added FLANNERY,E J Brunswick Co 83/03/14 POYAPOVS.U Region 4, Office of Director 2pp 18513 046
- --B305200462 Ack receipt of B21122 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900782/82-01 Requests addl info per F Vollmer 830107 telcon re audits.tool insp card initiation & labeling POTAPDVS.U Region 4. Office of Director 83/01/31 FLANNERY, E J Brunswick Co 2pp 18513 048
- --8305200449 Responds to NRC 821105 ltr rs nonconformance noted in GA Program Insp Rept 97900782/82-01 Corrective actions GA procedural changes will be implemented & fully operational by 830630 FLANNERY, E. J. Brunswick Co. 82/11/22 POTAPOVS, U. Region 4, Office of Director. 27pp. 18513-050
- 8305200589 Ack receipt of 830428 itr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 95900519/83-01 PDTAPDVS.U Region 4. Office of Director 83/05/13 KOMES.J M Bechtel Corp 1p 18514 041
- --83D3200593 Responds to NRC 830331 ltr re monconformance noted in GA Program Insp Rept 79900519/83-01 Corrective actions Procedure EDPI 4.62-12 revised to allow review through approval process of field change motice & request KOMES, J M Bechtel Corp 0A5-83/115 83/04/28 PDTAPGVS, U Region 4, Office of Director 3pp 18514 042

- 8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FBAR & SER (NUREG-0876) Supporting documentation encl REED. C Commonwealth Edison Co 6434N 83/05/11 DENTON. H R Office of Nuclear Reactor Regulation. Director 10pp 18521 085 24X Fiche 30-000,83/05/11,8305200621
- --8305200664 Advises that Westinghouse GA program implementation described in WCAP-8370. Rev 9A. satisfactory SEYFRIT. K V Region 4. Dallas. Office of the Director (81/03/01) 81/04/30 SLEMBER, J Westinghouse Electric Corp 2pp 18522 259 24X Fiche 50-373.83/05/11.8305200621
- B30520046B Forwards GA Program Insp Rept 99900794/83-01 on 830317 & notice of nonconformance POTAPDVS.U Division of Vendor & Technical Programs 83/05/04 EGGERS.P E Ridihalph, Eggers & Associates 2pp 88519 099
- --8303200673 Natice of nonconformance from insp on 830317 * Region 4. Office of Director 83/05/04 ip 18519 102
- --8305200678 GA Program Insp Rept 99900794/83-01 on 830317 Noncompliance noted design change failed to eliminate formation of void in siphon tube MCNEILL.W M . BARNES, I Region 4, Office of Director 83/05/03 3pp 18519 103
- B305230497 Forwards QA Program Insp Rept 99900056/83-01 on 830214-18
 AITS Items F02700230.F02700301.302 & 303 re failed pneumatic
 actuators closed M/o encl
 PDTAPDVS.U Division of Vendor & Technical Programs B3/05/19
 LEWIS.R C Division of Project & Resident Programs Ip 18537 141
- 8305230514 Forwards GA Program Insp Rept 99900056/83-01 on 830214-18
 Insp uncovered leakage & closure problems w/Manry Pract
 butterfly valves W/o enc!
 POTAPGVS, U Division of Vendor & Technical Programs 83/05/19
 8PESSARD, R L Division of Project & Resident Programs 2pp
 18537 168
- B305240333 Confirms GA program insp at Huntsville,AL test facility on 830627-0701,per 830511 telcon Insp will address electrical equipment qualification process for safety-related Class IE equipment POTAPDVS.U Region 4. Office of Director 83/05/20 SHITH.E N Wyle Laboratories ip 18572 341
- 8305240336 Ack receipt of 830415 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900273/83-01 Vendor not excused from compliance Extension for response granted until 830601 POTAPDV8.U Region 4. Office of Director 83/05/20 BCHMIDT.W J Wastinghouse Electric Corp 2pp 18349 361.
- 8305240344 Ack receipt of 830413 ltr informing NRC of steps taten to correct nonconformance noted in QA Program Insp Rept 99700900/83-01 POTAPOVS.U Region 4: Office of Director 83/05/20 SLEMBER.R J Hestinghouse Electric Corp ip 18574:079
- --8305240346 Responds to NRC 830317 ltr re nonconformance noted in GA Program Insp Rept 99900900/83-01 Corrective actions test & execution & test data control procedure manual revised to include description & use of route card4 SLEMBER.R J Hestinghouse Electric Corp PI&DA-83-719 83/04/13 PUTAPOVS.U Region 4. Office of Director 2pp 18574 080
- B305240352 Ack receipt of B30302 & 0422 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900289/82-03
 PDTAPUVS.U Region 4. Office of Director B3/05/20 TESTHUIDE.R R Borg-Harner Corp. ip 18575-073
- --8305240337 Responds to NRC 830325 ltr re nonconformance noted in GA Program Insp Rept 99900289/82-03 Corrective actions: personnel instructed not to utilize vendors not appearing on approved vendor list MILINAZO.P.L Borg-Harner Corp G-83-083/PLM 83/04/22 POTAPDVS-U Region 4, Defice of Director. Ip 18375-074
- ---8305240341 Ack recept of 830302 ltr informing NRC of steps taken to correct nonconformances hoted in QA Program Insp Rept 97900289782-03 Requests description methods to prevent recurrence & use of vendor not on approved list POTAPOVS.U Region 4. Office of Director 83/05/25 TESTHUIDE.R R Borg-Warner Corp 1p 18575-075

- --8305240363 Responds to NRC 830118 ltr re nonconformance noted in QA Program Insp Rept 99900289/82-03 Corrective actions list of vendors used for calibr svcs reviewed, updated & added to nuclear products approved vendor list MILINAZZD.P L Borg-Warner Corp G-83-049/NMS 83/03/02. POTAPQUS, U Division of Vendor & Technical Programs 2pp 19374 0724.
- B305240400 Ack receipt of B30504 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9990905/83-01 POTAPOVS.U Region 4. Office of Director B3/05/20 HOUBTEAU.L Wyle Laboratories 1p 18574
- --8305240403 Responds to NRC 830421 ltr re nonconformance noted in GA Program Insp Rept 99900905/83-01 Corrective actions procedures revisedingt audits & purchase orders reviewed & audits supervised by lead auditor HUDSTEAU, L. Wyle Laboratories 83/05/04 POTAPOVS, U. Region 4, Office of Director App 18574 193
- 83052404ii Ack receipt of 830429 itr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97905001/83-01 Extension of 30 days for response granted PDTAPOVS.U Region 4. Office of Director 83/05/20 WAHL.H.W Bechtel Corp ip 18573 354
- --8305240415 Responds to NRC 830330 ltr re honconformance noted in QA Program Insp Rept 99900501/63-01 Corrective actions 30-day extension requested to prepare rept re supplier surveillance program improvements Drawings will be revised WAHL,H W Bechtel Corp 83/04/29 PDTAPOVS,U Region 4, Office of Director 2pp 18573 355
- 8305240419 Confirms GA program insp at Richland, WA site on 830606-10, per 830224 telcon insp will address GA program implementation POTAPOVS, U Region 4, Office of Director 83/05/20 VOLMER, C. J Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 1p 18574 281
- B305240424 Confirms GA program insp at Columbia, BC site on B30520-24, per B30224 telcon Insp will address GA program implementation PDTAPOVS.U Region 4, Office of Director, B3/05/20 JACOBI, H. M. Hestinghouse Electric Corp ip 18573 035
- 8305240426 Forwards QA Program Insp Rept 99900311/83-01 on 830228-0304, notices of violation & nonconformance POTAPOVS.U Region 4: Office of Director 83/04/25. GREENE.R Owners Electric Co 3pp 18574.128
- --8305240433 Forwards corrected natice of violation for GA Program Insp Rept 9790031/83-01 POTAPOVS.U Region 4. Defice of Director 83/05/03 GREENE.R General Electric Co 1p 18574-131
- --8305240437 Corrected notice of violation from insp on 830228-0304 * Region 4, Office of Director. 83/05/03 ip. 18574.132
- --8305240445 Notice of violation from insp on 830228-0304 * Region 4, Office of Director, 83/05/03 ip 18574/133
- --8305240452 Notice of nonconformance from insp on 830228-0304. # Region 4. Office of Director 83/04/25 2pp 18574 134.
- ---8305240462 GA Program Insp Rept 99900311/83-01 on 830228-0304.

 Noncompliance noted failure to notify NRC of 4 16-kV
 vertical lift metal-clad switchgear failure to comply w/
 momentary current tests per ANSI Std C37 20-1974
 FOSTER,W E , BARNEB, I Region 4, Office of Director 83/04/21
 10pp 18574 136
- 8305240431 Informs that QA program.per SWBQAP 1-74A.Rev C. satisfactorily implemented.Continuing QA program acceptability contingent upon satisfactory implementation varified through Vendor Programs Branch insps. CDLLINS.J T Region 4. Office of Director. B3/05/20 KELLY.R B Stone & Webster Engineering Corp 2pp 18374.124.
- --8305240435 Advises that S&W satisfactorily implements GA program per SHSGAP 1-74A, Rev C Confirmation recommended. CHAMBERLAIN, D Region 4, Office of Director 83/05/18. COLLING. J T Region 4, Office of Director 2pp 18574, 126
- 8305260291 Forwards 830513 second interim deficiency rept re cable testing partially responding to enforcement actions from insp of mfg & testing activities Final rept scheduled for 830630 M/o encl PDTAPGVS.U Region 4. Office of Director 83/05/20 BAER,R.L. Engineering & Generic Communications Branch. 1p 18625 160.

NONDOCKETED ITEMS

- 8305270144 Advises that GA program described in NEDO-11209-04A being implemented satisfactorily Results of insp published quarterly in NUREO-0040 CDLLINS.J T Division of Vendor & Technical Programs 83/05/24 BRUOGEMAN,W H General Electric Co 2pp 18638 203
- --B305270149 Discusses corrective actions on nonconformances noted in IE insps since Jan 1980 GE satisfactorily implemented GA program per NEDD-11209-04A Confirmation of implementation recommended CHAMMERLAIN.D Division of Vendor & Technical Programs B3/05/20 COLLINS; J T Region 4. Office of Director ip 18638 205
- B305270267 Forwards GA Program Insp Rept 99900722/B3-01 on 830228-0304 & notices of violation & nonconformance POTAPDVS.U Region 4. Office of Director 83/05/13 JOHNSON.I O Robert Shaw Controls Co 3pp 18644 274
- --B305270272 Natice of violation from insp on 830228-0304 + Region 4, Office of Director 83/05/13 ip 18444 277
- --8305270277 Notice of nonconformance from insp on 830228-0304 * Region 4, Office of Director 83/05/13 ip 18644 278
- ---8305270286 GA Program Inep Rept 99900722/83-01 on 830228-0304
 Noncompliance noted copies of Part 21 of Energy
 Reorganization Act of 1974 posted & procedures adopted per
 regulations not readily available to personnel
 PARKER.L B . BARNES.I Region 4. Office of Director. 83/05/12
 88pp. 18644 279
- 8305270291 Forwards QA Program Insp Rept 99900031/83-01 on 830228-0303 & notice of nonconformance PDTAPOVS.U Region 4, Office of Director 83/03/13 PATTY, D F. Bingham-Willamette Co Spp. 18644 305
- --8305270298 Notice of nonconformance from insp on 830228-0303 4 Region 4, Office of Director 83/05/13 2pp 18644 309
- ---B905270307 QA Program Insp Rept 99900031/83-01 on 830228-0303 Noncompliance noted no documented evidence that committed training of pump engineering personnel re HX design accomplished KELLEY, W D , BARNES, I Region 4. Office of Director 83/05/12 12pp 18644 311
- 8305270302 Forwards OA Program Insp Rept 99900404/83-01 on 830314-16 No noncompliance noted POTAPUS.U Region 4. Office of Director 83/05/10 SLEMBER.R J Wastinghouse Electric Corp 2pp 18642 048
- --B305270311 QA Program Insp Rept 99900404/83-01 on 830314-16 No noncompliance noted, Major areas inspected difference between post-weld heat treatment on Indian Point Unit 3 steam generators & generators in other plants CONNAY, J. T., BARNES, I Region 4. Office of Director 83/05/04 6pp 18442 050

REGOD REGULATORY GUIDEB

- B305160302 Reg Quide 8 31 Task OH 941-4, "Info re Ensuring That Occupational Rediation Exposures at U Mills Will be ALARA" * Office of Nuclear Regulatory Research, Director 83/05/31 12pp 18462 336
- B30520D619 Notification of CRGR Meeting 40 on B30601 in Bethesda, MD to discuss proposed amend to 10CRR50 re hydrogen control requirements, proposed insider rulemaking package & operator requalification program
 BTELLO, V Committee to Review Generic Requirements B3/05/18
 EIBENHUT.D Q. Office of Nuclear Reactor Regulation, Director JORDAN, E. L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R. E. Office of Nuclear Material Safety & Safeguards, Director. 2pp 18520 158
- --8305200654 Dreft Reg Guide 5 XXX, "Std Format & Content Guide for Nuclear Reactor Access Authorization Plan" * NRC - No Detailed Affiliation Given 83/05/03 37pp 18320 289
- --8305200661 Draft value/impact statement of power reactor access authorization rule Amend to 10CFR73 proposed to establish uniform min criteria for granting individuals unescorted access to protected areas

 a NRC No Detailed Affiliation Given. 83/05/03 47pp 18520 326.

- --8305200671 Draft Reg Guide 5 XXX, "Guidance for Miscellaneous Amends to 10CFR73 55" * NRC - No Detailed Affiliation Given 83/05/04 26pp 18521 040
- --8305200677 Draft value/impact accessment of miscellaneous amends re physical protection of nuclear power plants + NRC - No Detailed Affiliation Given 83/05/03 19pp 18321 066

RES RESEARCH AND TECHNICAL ABSISTANCE REPORTS

- B206100204 Forwards SAI~i-186-03-043-i. "Design Review of Fox-Mowlett Reinforcing Bar Splice Sys," technical evaluation rept JOHNSON,B W Science Applications, Inc NRC-096 B2/06/0B NRC - No Detailed Affiliation Given Ip 18683 243
- --B204100210 "Design Review of For-Howlett Reinforcing Bar Splice Sys," technical evaluation rept "
 + Brience Applications, Inc NRC-03-82-074 SAI-1-184-03-04 B2/06/08 62pp 18483 244
- 8303080182 "Design Review of Dayton Bar-Grip Reinforcing Bar Splice
 Bys." technical evaluation rept
 ** Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
 B3702/28 NRC-No Detailed Affiliation Given 60pp 18926 044
- --8303080187 "Design Review of Dayton Bar-Grip Reinforcing Bar Splice Sys." technical evaluation rept refs * Science Applications, Inc. NRC-03-82-076 SAI-1-186-03-61 83/02/88 NRC - No Detailed Affiliation Given 47599 18826
- 8303080194 "Design Review of Dywidag Threadbar Reinforcing Sys," technical evaluation rept * Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61 83/02/28 NRC - No Detailed Affiliation Oiven 57pp 18527 219
- --B303080202 "Design Review of Dywidag Threadbar Reinforcing Sqs," technical evaluation rept refs * Science Applications, Inc. NRC-03-82-096 SAI-1-186-03-61 B3/02/28 NRC - No Detailed Affiliation Given 396pp 18527 279
- 8303080209 "Design Review of Cadweld Reinforcing Bar Splice Sys."
 technical evaluation rept
 # Science Applications. Inc NRC-03-82-096 SAI-1-186-03-61
 83/02/28 NRC No Detailed Affiliation Given 80pp 18524 178
- --8300080213 "Design Review of Cadweld Reinforcing Bar Splice Bys," technical evaluation rept refs * Science Applications, Inc NRC-03-82-076 SAI-1-186-03-61 83/02/28 488pp 18524 258
- 8305030025 "Guarterly Hgt Rept ORNL Projects for NRC Ofc of NRR " LOTTS,A L Oak Ridge National Laboratory 63/04/01 Office of Nuclear Regulatory Research, Director 176pp 18326 124
- B305060349 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC Licensed Furl Cycle Facilities," monthly progress rept for Mar 1983 BIMAN-TOV, M Union Carbide Corp FIN B-0495 B3/04/29 BERNSTEIN, B Transportation & Materials Risk Branch 3pp 18933 081
- 8305ii0062 "Investigation of Ventilation Component Response to Large-Pressure Pulses," monthly progress rept for Feb 1983 GRECORY,N S Los Alamos Scientific Laboratory FIN A-7028 83/04/08 BOLDERG,D E Transportation & Materials Risk Branch 6pp 18420 318
- B3051100B3 "Investigation of Ventilation Component Response to Large-Pressure Pulse," monthly progress rept for Mar 1983 QREGORY, W B Los Alamos Brientific Laboratory FIN A-702B B3/04/21 SDLBERG, D E Transportation & Materials Risk Branch 6pp 18419 354
- B305130292 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities." monthly progress rept for Mar 1983 MARTIN,R A . GREGORY,W S. Los Alamos Scientific Laboratory FIN A-7029 B3/05/10 BERNSTEIN,S Transportation & Materials Risk Branch 7pp 18458 003
- 8305250155 "Grneric Study of Recycle of Contaminated Matls," monthly progress rept for Apr 1783
 TRAVIS,C C Dak Ridge National Laboratory FIN B-0824
 NRC-60-10-01-05 83/05/10 BICEHOUSE,H J Transportation & Materials Risk Branch 3pp. 18574 188

- 8305230168 "Accident Aerosol Characterization," informal monthly progress rept for Apr 1983 OWCIARSKI,P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 83/05/11 BERNSTEINS Division of Risk Analysis 3pp 18596 142
- 8305250174 "Accident Aerosol Characterization," informal monthly progress rept for Mar 1983 OMCIARSKI,P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2287 83/05/11 BERNSTEIN,S Division of Risk Analysis 5pp 18596 348

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- B303180429 Forwards response to B30208 ltr re backfitting costs of two nuclear power plants Atl three units have combined capability of 1,539 MME (summer) net HADLEY.C D Northern States Power Co B3/03/15 TOURTELLOTTE, J Regulatory Reform Task Force App 18541 041 24X Fiche 50-000.83/03/15.8303180429
- 8305040630 Notifies of CRGR Meeting 36 on 830429 to discuss findings of Salem Generic Implications Task Force
 STELLO,V Committee to Review Generic Requirements 83/04/27
 EISENHUT,D Q Office of Nuclear Reactor Regulation, Director JORDAN,F L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E. Office of Nuclear Material Safety & Safeguards,Director 2pp 18336 306 24X Fiche 50-272,83/04/27,8305040630
- B305050354 Summary of B30301 meeting w/Nuclear Util Fire Protection Group, EPM Debevoise & Liberman. CPC. Bechtel & GPU re clarification of fire protection rule, App R to 10CFR50 MAMBACH.T V Deprating Reactors Branch 5 LS05-83-04-019 B3/04/11 Operating Reactors Branch 5 4pp 18352-022
- 8305050399 Comments on proposed rule re safety goals evaluation plan Milano Nati Nuclear Regulatory Agency presently involved in similar but more restrictive task Requests to be kept informed of proceedings OARRIBBAS Instituto di Ingegneria Nucleare. Milan. Italy 48FR10772 83/04/26 Docketing & Services Branch ip 18343 159
- 8305110415 Notification of CRGR Meeting 38 on 830518 in Bethesda, MD to discuss proposed rule. "Analysis of Potential Pressurized Thermal Shock Events." prioritization of generic safety issues & operator requalification program Review matl encl STELLO.V Regional Operations & Concric Requirements 83/05/10 EISEMHUT.D G Office of Nuclear Reactor Regulation. Director JORDAN, E.L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, E. Office of Nuclear Haterial Safety & Safeguards, Director 2pp 18394 221
- --8305i10423 Forwards draft FR notice & supporting regulatory assessment on proposed rule re pressurized thormal shock CROR review requested within 2 wks
 DENTON-H R Office of Nuclear Reactor Regulation, Director 83/05/03 STELLO, V Regional Operations & Generic Requirements 34pp 18374 222
- --B305110428 Forwards proposed Commission paper discussing prioritization of generic safety issues & transmitting draft NUREG-0933, "Prioritization of Generic Safety Issues "Procedures for identifying & managing issues encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director
 B3/03/02 DIRCKS.H J Office of the Executive Director for Operations 771pp 18394 259
- --8305110432 Forwards options for operator requalification exams
 Administered requalifications option recommended
 DENTON:H R Office of Nuclear Reactor Regulation, Director
 83/03/07 DIRCKS.W J Office of the Executive Director for
 Operations 8pp 18396 310
- --8305110485 Notification of CRGR Meeting 37 on 830525 in Bethesda,MD to discuss proposed amend to 10CFR71 re transportation regulations & to review proposed ATMS rule 10CFR50 &0 STELLG.V Regional Deprections & Generic Requirements 83/05/10 EISENHUT.D G Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E. Office of Nuclear Material Basety & Safeguards,Director 2pp 18396 314
- -~8305110493 Forwards proposed FR notice & regulatory analysis on ATHS rule 10CFR50 &0 Add requirements discussed at CRGR 830420 briefing added Expeditious response requested MINOGUE:R B Office of Nuclear Regulatory Research. Director 83/05/06 STELLO,V Regional Operations & Generic Requirements 58pp. 18396 320

James 1

- --8309030722 Requests CROR review of encl Commission paper to amend 10CFR71 re transportation regulations, per 830120 memo MINOGUE, R D Office of Nuclear Regulatory Research, Director. 83/04/25 STELLO, V Regional Operations & Ceneric Requirements, 225pp 66766 146
- B305120460 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFAND, J Licensing Branch i B3/05/02 HOLTZBCHER, D L
 III inois Power Co 2pp 18443 173 24X Fiche 50-000, B3/05/02,
 B305120460
- --B305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licansing Review Group II generic issue
 STEFAND. J Licensing Branch 1 83/05/02 POHELL, P Washington Public Power Supply System 1p 18443 174 24X
 Fiche 50-000, B3/05/02, 8305120460
- --8305120477 Requests info re issue solutions accepted by NRC which have a have not been addressed in SER/supplemental BERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO, J. J. Licensing Branch 1 83/05/02 REED, W.J. Qulf States Utilities Co. 1p. 18443 175 24X Fiche 50-000, 83/05/02, 8305120460
- --8305;20485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANG.J J Licensing Branch 1 83/05/02 RICHARDSON, J D.
 Hississippi Power & Light Co 1p 18443 176 24X
 Fishe 50-000.83/05/02,8305;20460
- --8305120491 Requests info re issue solutions accepted by NRC which have a have not been addressed in BER/supplemental BERs Info needed to document evaluation on each Licensing Review Group II generic issue
 STEFANO. J J Licensing Branch 1 83/05/02 BUZZELLI.E M Cleveland Electric Illuminating Co ip 18443 177 24X Fiche 50-000.83/05/02.8305120460
- 8305120569 Discusses guidelines developed to aid in review of IE Bullstin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl NOVAK.T M Assistant Director for Licensing IEB-79-15 B3/05/03, HQLTISCHER.D L Licensing Review Group II 6pp 18440.356 24X Fiche 50-000.83/05/03,8305120569
- B305170275 Notification of CRGR Meeting 37 on B30511 in Bethesda,MD to discuss methodology used to prioritize generic safety issues & operator requalification program STELLO,V Committee to Review Generic Requirements B3704/27 EISENHUT,D G Division of Licensing JORDAN,E L Director's Office Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Bafeguards, Director 2pp 19403 288
- 8305170715 Lists agenda items from CROR Meeting 37 postponed until 830518 Meeting 38 Items re methodology used by NRR to prioritize generic safety issues & briefing on operator requalification program among items postponed STELLO, V Regional Operations & Generic Requirements 83/05/06 EISENHUT.D.C Office of Nuclear Reactor Regulation, Director JORDAN, E.L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R Office of Nuclear Material Safety & Safeguards, Director 3pp 18476 233
- B30517071B Summary of B30503 meeting w/NRR & CROR to clarify scope & intent of proposed licensee actions stemming from Salem Generic Implications Task Force Rept (NUREO-1000,Vol 2) Meeting suggested to discuss recommendations on Item 3 TAYLOR,M , SCHRINK,W Regional Operations & Generic Requirements B3/05/06 STELLO.V , MURLEY.T Regional Operations & Generic Requirements 3pp 18496 199
- 8305190010 Summary of CROR Meeting 34 on 830420 ra technical positions concerning waste classification & form, status of proposed ATMS & proposed IE bulletin on Hayward Tyler Pump Copumps & spars parts
 STELLO, V Regional Operations & Generic Requirements 83/05/04.
 DIRCKS.W J Office of the Executive Director for Operations, 7pp 18523 213
- 8303190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants EISENHUT, D @ Division of Licensing 83/05/03 EDELMAN.M R Clevel

- --8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 CL applicants EISENHUT, D 0 Division of Licensing 83/05/03 HALE, D P Illinois Power Co 2pp 18523 200 24X Fiche 50-000,83/05/03, 8305190046
- --8305190060 Commends representatives of BMR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BMR/6 OL applicants EISENHUT,D G Division of Licensing 83/05/03 FERGUSDN,M R Hashington Public Power Supply System 2pp 18523 202 24X Fiche 50-000,83/05/03,8305190046
- --8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 QL applicants EISENHUT,D 0 Division of Licensing 83/05/03 MC0AUGHY,J P Mississippi Power & Light Co 2pp 18523 204 24X Fiche 50-000, 83/05/03, 8305190046
- --8305190077 Commends representatives of BHR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BHR/6 DL applicants EIGENHUT.D G Division of Licensing 83/05/03 CAHILL, J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03. 8305190046
- B305200535 Forwards "Bummary of CRGR Activities for Apr 1983 " SCHHINK.W Committee to Review Generic Requirements 83/05/17 Committee to Review Generic Requirements 4pp 18516 021
- 8305200619 Notification of CROR Meeting 40 on 830601 in Bethesda.MD to discuss proposed amend to 100FR30 re hydrogen control requirements, proposed insider rulemaking package & operator requalification program
 BTELLD.V Committee to Review Generic Requirements. 83/05/18
 EISENHUT.D Q Défice of Nuclear Reactor Regulation. Director JORBAN.E L Director's Office. Office of Inspection and Enforcement CUNNINOHAM.R E Défice of Nuclear Material Bafety & Bafeguards.Director 2pp 18520 158
- --8305200623 Forwards draft Commission paper on amends to 10CFR50 re hydrogen control for review & comment HINOQUE,R B Office of Nuclear Regulatory Research, Director 83-083 83/05/12 STELLO,V Committee to Review Generic Requirements ip 18520 160
- --B305200627 Draft Commission paper requesting approval for FR publication of amends to iOCFR50 re hydrogen control Recommends affirmation at open meeting DIRCKS.W J Office of the Executive Director for Operations 83/03/10 94pp 18520 161
- --B305200634 Forwards draft Commission paper re insider safeguards rulemaking package for concurrence List of safety/safeguards review committee recommendations w/appropriate cross-reference to areas changed by CRGR also encl.

 DAVIB.J G Diffice of Nuclear Material Bafety & Bafeguards.Director B3/05/13 STELLO, V Committee to Review Generic Requirements 34pp 18520-295
- --8305200654 Draft Reg Ouide 5 XXX, "Std Format & Content Ouide for Nuclear Reactor Access Authorization Plan" ** NRC - No Detailed Affiliation Given 83/05/03 37pp 18520 289
- --8305200661 Draft value/impact statement of power reactor access authorization rule Amend to 10CFR73 proposed to establish uniform min criteria for granting individuals unescorted access to protected areas
 .* NRC No Detailed Affiliation Given 83/05/03 47pp, 18520 326
- --8305200664 Draft value/impact accessment of nuclear power reactor search procedures rule Amend to 10CFR73 55(d)(i) proposed to clarify requirements for searches

 NRC No Detailed Affiliation Given 83/05/03 29pp 18321 011
- --8305200671 Draft Reg Guide 5 XXX. "Guidance for Miscellaneous Amends to EOCFR73 55."

 * NRC No Detailed Affiliation Given 83/05/04 24pp 18521 040
- ---B305200677 Draft value/impact accessment of miscellaneous amends re physical protection of nuclear power plants 4 NRC - No Detailed Affiliation Given B3/05/03 17pp 18521 066

- 8305230270 "Active Mod Projects.Operating PWR,1982" # Consumers Power Co 82/12/3! 4pp 18976-332 24x Fiche 80-000.82/12/31.8305230270
- B305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
 SMITH-5 H Carolina Power & Light Co 83/03/22 TOURTELLOTTE, J Regulatory Reform Task Force 13pp 18543 277 24X
 Fiche 50-000.83/03/22.8305230283
- 8309230364 Forwards cost info associated w/bac/fitting nuclear units, per JL Mauiden 830224 commitment MARSHALL,J R Arkansas Power & Light Co 83/03/11 TOURTELLDTTE,J Regulatory Reform Task Force 11pp 18546 234 24X Fiche 50-313,83/03/11.8305230364
- B30523036B Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs." providing cost analysis per 83020B request
 WHITE.W S American Electric Power Co . Inc 83/03/30
 TOURIELLOTTE.J Regulatory Reform Task Force 7pp 18544 336 24X
 Fiche 50-315.823/03/30.830523036B
- B305230387 Responds to B3020B request for backfit info Total of \$281 million spent on backfitting through Jul 1982 Addl \$50 million required to complete work on NRC imposed backfits ARTHUR.J M Duquesne Light Co B3/03/09 TOURTELOTTE.J Regulatory Reform Task Force 17pp 18546 245 21X Fiche 50-334.83/03/09.8305230387
- 8305230393 Forwards analysis of estimated backfitting costs per 830208 ltr Estimated \$174 milition spent for backfitting Backfitting expenditures will average 40% of annual expenditures from 1977 through 1985 HANCOCK JA Florida Fower Corp NGA93-0145 83/03/25 TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18943 358 24) Fiche 50-302.83/03/25,8305230393
- 8305230402 Forwards info on tosts incurred from backfitting & upgrading facilities, per 830210 request Mods categorized NRC-required, TMI-lessons learned or util-initiated DIECKAMP, H. General Public Utilities GPU Service Corp. 83/03/08 TOURTELLOTTE, J. Regulatory Reform Task Force. 9pp. 18576-318. 24x Fiche 30-000.83/03/08.8305230402
- 8305230407 Informs that backfitting mat1 wiil be forwarded as soon as available, in response to 830208 ltr
 FURDUSH, M.H. Pacific Gas & Electric Co. 83/02/23 TOURTELLOTTE, J. Regulatory Reform Task Force. 1p. 18543 357 24X
 Fiche 50-000.83/02/23.8309230407
- 8305230303 Summary of CROR Meeting 35 on 830425 re Salem Generic Implications Task Force findings.per NUREG-1000 STELLO,V Committee to Review Generic Requirements 83/05/13 DIRCKS,W J Office of the Executive Director for Operations 4pp 18537 164
- 8305230507 Summary of CRGR Meeting 36 on 830427 relactions derived from Salem generic implications rept List of attendees encl BTELLO.V Committee to Review Generic Requirements 63/05/13 DIRCKS.H J Office of the Executive Director for Operations 4pp 18537 320
- 8305230581 Forwards lists of NRC initiated & TM1-related backfit items, in response to 830208 ltr Backfitting costs resulting from utils own needs also provided HITHERS, B D Portland General Electric Co 83/03/24 TOURTELLOTTE, J Regulatory Reform Task Force 4pp 18541 314 24X Fiche 30-344,83/03/24,8305230581
- 8305230583 Forwards backfit cost info in response to 830208 ltr Two 3,500 kH standby diesel generators, diesel generator blog, auxiliary blog addition, associated electrical equipment & new computer sys added per NUREO-0737 MATTIMOE, J J Sacramento Municipal Utility District 83/03/16 TOURTELLOTTE, J Regulatory Reform Task Force 4pp 18341 318 24X Fiche 50-312,83/03/16,8305230583
- 8305230589 Forwards backfitting & regulatory impact cost data for hardware & ronhardware-related backfits Requirement for adding one addl senior reactor operator to each operating shift will cost \$600,000 per yr
 REZNICEK.B H Omaha Public Power District 83/03/04
 TOURTELLOTIE.J Regulatory Reform Task Force 16pp 18541 322
 24X Fiche 50-285,83/03/04,8305230559
- 8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Force effort.per 821221 ltr
 DYSON.J S. Power Authority of the State of New York 83/03/02 TOURTELLOTTE.J Regulatory Reform Task Force 2pp 18541 398 24X Fiche 30-000:83/03/02.8305230597

8305230608 Provides lump sum number representing direct cost impact of regulatory proliferation during approx period from NRC CP to low-power OL.in response to 830208 request re backfitting costs

LUTKEN.D C Hississippi Power & Light Co 83/03/04

TOURIELLOTTE.J Regulatory Reform Task Force 2pp 18541 340 24X
Fiche 30-416.83/03/04.8305230608

8305230616 Forwards info in response to B30208 ltr requesting backfit cost data for operating nuclear units Cost categorised according to NRC imposed. THI & non-THI backfits. util-initiated & hybrid backfits
CDUNSIL, W G Connecticut Yanise Atomic Power Co B10721 B3/03/21
TOURISELLOTES, J Regulatory Reform Tast Force 25pp 18543 038
24X Fiche 30-000,83/03/21,8305230616

8305230634 Ack receipt of itr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron increases
SHIELDS, S W Public Service Co of Indiana. Inc SVP-0080-83
83/03/10 TOURTELLOTTE, J Regulatory Reform Task Force 2pp
18542 352 24% Fiche 50-546,83/03/10.8305230654

8305230669 Notifies that operator requalification program postponed until CRGR Meeting 40, tentatively scheduled for 830501 CRGR Meeting 38 scheduled for 830518 in Bethesda MD STELLD, V Regional Operations & Generic Requirements 83/05/17 EISENHUT.D Q Office of Nuclear Reactor Regulation. Director URDAN, EL Director's Office, Office of inspection and Enforcement CUNNINGMAM, R & Office of Nuclear Material Safety & Safeguards Director ip 19542 332

8305230716 Responds to 830208 request for backfitting expenditures Actual cost at OL date was \$583 million Projected addituture cost for NRC imposed mode conservatively estimated at \$26,500.000 CROUSE.R P Toledo Edison Co 83/02/18 TOURTELLOTTE.J Regulatory Reform Task Force 10pp 18542 294 24X Fiche 50-346,83/02/18.8305230716

8305230720 Forwards list of utils responding to requests for cost figures on backfitting TOURTELLOTTELJ Regulatory Reform Task Force 83/04/11 PALLADINO.N J, OILINSKY,V AHEARNE.JF Commissioners 299 19542 272 24X Fiche 50-000.83/04/11.8305230720

8305230724 Forwards estimated annual regulatory & nonregulatory expenditures in 830208 ltrs re cost of backfitting Combined capacity of facilities is 994 MMe 8URSTEIN-S Wisconsin Electric Power Co 83/02/25 TOURTECLOTTE. J Regulatory Reform Task Force 30p 18542 269 24X Fiche 50-266/83/02/23.8305230724

8303230728 Forwards listing of regulatory-induced major plant mods & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 79-01.79-02 & 79-14 mods provided GIESLER.C W Hisconsin Public Service Corp IEB-79-01 B3/03/25 TOURTCLLOTTE.J Regulatory Reform Task Force 6pp 18542 263 2 Fiche 50-305.83/03/28.8305230728

SECY POSITION PAPERS DEFORE THE COMMISSION

0302280090 SECY-83-059
Requests approval to publish encl technical criteria for regulating geologic disposal of high level radwaste as final amends to 100FR60 W/draft final rule on 100FR60 DIRCKS.W J Office of the Executive Director for Operations 83/02/09 450pp 18629 001

8304220083 SECY-83-0598

Bubmits proposed responses to comments of Commissioners Gillnesy & Abearne re BECY-83-59 concerning technical criteria & conforming amends to disposal of high level raduastes in geologic repositories

DIRCKS-W J Office of the Executive Director for Operations 83/04/11 26pp 18627 190

8305020530 BECY-83-140
Presents NRC review of & recommendations on util 830131
revised schedule & cost info re recovery
BIRCKS, W J Office of the Executive Director for Operations
83/04/15 33pp 18284 261 24% Fiche 50-320,83/04/15,8305020530

8305170232 SECY-83-158
Informs Commission of findings of Salem ATMS generic implications task force re overall mgt capability & performance & reactor trip sys reliability
BIRCKSN J Office of the Executive Director for Operations
83/05/02 139pp 18476 184 24X Fiche 50-272,83/05/02.8305170232

B305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in FDR FELTON, J M Division of Rules and Records B3/03/29 BREADY, J C KMC, Inc ip 18303 230 24x Fiche 50-237, 83/03/27, 8305180316

--8309180328 SECY-83-017
Notifies of results of SEP review of facility
DIRKNS, W J Office of the Executive Director for Operations
83/01/12 47pp 18505 246 24X Fiche 50-237,83/03/29,8305180314

--8305180322 SECY-83-019
Informs of proposed plan to convert seven remaining provisional DLs to full-term OLs after completion of SEP Phase II
DIRCKS.W J Office of the Executive Director for Operations 83/01/17 15pg 18505

8305230065 Responds to FOIA request for SECY-82-13D Forwards requested document Document also available in PDR FELTON, J M Division of Rules and Records 83/03/31 PEDRO, J Myg Corp ip 18543 137

--8305230070 SECY-82-013D

Informs Commission of status of implementation of iOCFR5D 48 & App R to iOCFR5D re fire protection rule for Third Guarter 1982, per SJ Chilk B01103 request DIRCKB, W J Office of the Executive Director for Operations 82/12/10 9pp 18543 138

8305250250 SECY-83-067
Provides Commission w/info rept explaining status of activities re fraudulent practices of Ray Miller, Inc DIRCKS, W J Office of the Executive Director for Operations 83/02/16 30pp 18627 123

B305270118 SECY-83-195
Requests Commission approval to transmit comments to EPA on proposed stds for U & thorium mill tailings at licensed commercial processing sites Comments re groundwater protection & radon stds not supportive of EPA proposed rule DIRCKS, U Office of the Executive Director for Operations 83/05/20 BBpp 18461 251

STATE PROG STATE PROGRAMS

B305040192 PNA-B3-007 on B30303,100 uCi I-125,3 mCi Ti-201 & B mCi Qa-67 stolen from US Priority Transport vehicle near Colonie Town,NY Packages not found Press release may be issued CAMPBELL,M Region 1, Office of Director 83/04/04 1p 18326 353

B305040201 PNA-83-007A on B30303,100 uci I-125,3mCi Tl-201 & B mCi Qs-67 stolen from US Priority Transport vehicle near Colonie Town,NY Package of I-125 found on B30315 in home of suspect. CAMPBELLM Region i, Office of Director B3/03/15 ip 18326.354

8305040650 Notification of contract execution. Mod i to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ "Contractor State of WI BILVIB,R M Technical Assistance Contracts Branch NRC-05-73-014 83/04/29 Director's Office, Office of Inspection and Enforcement in 18336 269

--8305040660 Mod i, deobligating funds, to "Establish Collaborative Prefita Between Btate & Commission to Provide Independent Heasurements of Radioactivity in Effluents & in Environ Around Selected Commission Licensed Activities "REIVITZ,L Hisconsin, State of OUSTAVE,R,P Division of Contracts NRC-05-73-014 83/04/29 ip 18336-270

8305040466 Provides technical comments & recommendations on State of M& radiation control program Program for regulation of agreement matis adequate; however, outdated radiation control regulations prevent compatibility determination COLLINS, J T Region 4, Office of Director 83/05/02 SABOL: B J Kansas, State of Spp. 18331 169

8305100086 Confirms discussion of NRC review & evaluation of State of LA radiation control program Program adequate, State should focus efforts on reducing backlog of insps Technical comments & recommendations encl COLLINB.J T Region 4, Office of Director 83/05/05 BIMONEAUX,F P Louisiana, State of App 18377-226

- 8305120010 Add1 response to FOIA request for documents re exploration, mining or milling of U in specific areas of NE Forwards documents listed on app Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 83/03/21 REID, A B Broken Plow Law Office ip 18443 282
- --8305120041 Requests assistance in arranging meeting in Lincoln.NE to discuss requirements & develop MOU defining roles te U or solution mining in northwest NE BRAIN.D T Nebraske, State of 82/04/27 COLLINS.T Region 4. Office of Director 2pp 18443 273
- --8305120045 Informs that draft MOU ready for signature pending review & concurrence by OELD Due to changes in location & organization of U Recovery Licensing Branch, MOU should be signed by regional administrator
 COLLINS.J T Region 4. Office of Director 82/07/28 DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director ip
- --B305120052 Forwards draft MOU re site U mining in NE Draft considers all previous NRC ofc comments & is acceptable to State of NE Comments should be provided by B21015 COLLINS, J T Region 4, Office of Director B2/10/01 DIRCKS, W J Office of the Executive Director for Operations STELLO, V Regional Operations & Generic Requirements KERR. D W Office of State Programs, Director 3pp 18443 296
- --8305120056 Forwards notice of issuance & availability of MOU between NE Dept of Environ Control & NRC for in situ U mining for filing & publication in FR COLLING, J T Region 4, Office of Director 82/12/01 COMBS, T R Correspondence & Records Branch 1p 18443 299
- --8305120062 Notice of issuance & availability of MOU between NRC & NE Dept of Environ Control re in situ U mining. COLLING, U T Region 4, Office of Director 82/11/30 ip 18483 300
- --8305120065 MOU between NRC & NE Dept of Environ Control re in situ U mining CCLLING, J T Region 4, Office of Director DRAIN.D T Nebraska, State of 82/11/02 2pp 18443 301
- --8305120014 Comments on Proposed Draft LB 350, per 811210 request Use of word "mining" may cause some problems NRC does not have jurisdiction over conventional mining of source matl or other matl HONTGOMERY, J. L. Region 4, Dallas, Office of the Director (81/03/01) 82/01/19 DRAIN.D T Nebraska, State of, 2pp 19443 284
- --8305120019 Discusses 820202 telcon w/J Lange re proposed U in situ project in NE by Hyaming Fuels Co State has licensing & insp jurisdiction over project until 821109 MONTOOMERY, J L Region 4. Office of Director 82/02/08 COLLINS.J T Region 4. Office of Director 2pp 18443 286
- --8305120023 Forwards info re 810313 meeting w/NE State officials concerning state & UMTRCA topics, State will seek amended agreement after 811108 Agency other than E Simmons div assigned to handle U mills
 MONTODMERY, J. Region 4, Dallas, Office of the Director (81/03/01)
 81/03/18 YOUNG, F Office of State Programs, Director 4pp 18443 288.
- --B305120035 Concurs w/D Drain request for assistance in developing MDU to define respective roles in connection w/U or solution mining in northwest NE, June 1982 meeting suggested to begin formulating MOU CDLLINS,J. T. Region 4, Office of Director 82/05/03 DAVIS,J @ Office of Nuclear Material Safety & Safeguards, Director KERR, W Office of State Programs, Director ip 18443 272
- 8305170137 NUREG/BR-0025 VO9 N4
 INFORMATION REPORT ON STATE LEGISLATION
 KERR, Q. W. Office of State Programs, Director, 83/05/G1 14pp
 18474:001
- B305190014 Ack receipt of B30411 ltr re NRC review of Dept of Environ Conservation radiation control progrem on B30509 or 10 Schedule permitting, author will meet w/representatives on B30510
 WILLIAMB.H & New York, State of B3/04/28, ALLAN, J M Region 1, Office of Director 1p, 18501 339
- B305190264 Forwards responses to specific technical comments & recommendation per B30225 ltr re evaluation of NY City radiation control program.
 BENCER:D J New York, NY. 83/04/22 HAYNES:R C Region 1, Office of Director 5pp 18501 242

- 8305200320 Confirms administrative & technical review & evaluation findings re State of 1D radiation control program Program adequate Technical comments & recommendations encl COLLING. J T Region 4, Office of Director 83/05/13 PURCE.T L Idaho, State of 5pp 18517-038
- 8305230326 Notification of contract execution "Radiation Monitoring Program Requirements." awarded to State of PA MCDERMOTT.D Technical Assistance Contracts Branch FIN B-8356 NRC-28-83-607 83/05/12 MCDGCARLJ Region 1, Office of Director COSTELLD.F NRC - No Detailed Affiliation Given 1, 18577 291
- --B305230332 Contract "Radiation Monitoring Program Requirements."
 awarded to State of PA Cooperative agreement encl
 # Pennsylvania, Commonwealth of, MCRTCN.K V Division of
 Contracts FIN B-8356 NRC-28-83-607 83/05/12 iApp
 18577 292
- B305240377 Notification of contract execution.Mod 3 to "Exam of Agreement State Program " Contractor Natl Governors Assoc MCLEAREN.T Administrative Contracts Branch NRC-06-81-293 B3/05/16 KERR,O W Office of State Programs, Director LUBENAU, JNRC No Detailed Affiliation Given ip 18647 256
- --8305260380 Mod 3.providing consideration to govt for late delivery of contract deliverables to "Exam of Agreement State Program" SCHEPPACH.R C National Governors' Association SMITH.P A Division of Contracts NRC-06-18-293 83/05/16 ip 18447 257
- 8305270090 Notification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NE MCDERMOTTJD. Technical Assistance Contracts Branch FIN B-8503 NRC-31-83-670 83705716 MEYERS,D M Region 4. Office of Director NICHOLAS,J B NRC No Detailed Affiliation Given 1p 18661 352
- --B305270093 Mad 1.correcting B&R numbers, to "Radiation Monitoring Program Requirements" * Nebraska, State of MORTON, K V Division of Contracts FIN B-8503 NRC-31-83-670 B3/05/16 ip 18661 353
- 8305270130 Ack receipt of 830407 1tr accepting results of NRC review of MD Dept of Realth & Mental Hygiene radiation control program

 BUCK,C R Maryland, State of 83/05/11 ALLAN,J M Region i.

 Office of Director ip 18638 214
- 8305270165 Responds to B30502 ltr re RJ Doda evaluation of agreement matis portion of state of LA radiation control program & concern re overdue insps Staff relatively new & several more months of on-the-job training necessary
 PDRTER; BJ Louisiana, State of B3/05/10 CDLLINS, JT Region 4, Office of Director 2pp 18638 062
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8210190253 Suggests implementation of emergency response guideline program in three steps, including preparation of plant-specific procedures List of questions & concerns encl EISENHUT.D O Division of Licensing 82/09/17 KINGSLEY, D D Hestinghouse Operating Plants Owners Group 10pp 18308 309
- 8303240026 Discusses review of B20408.0601.1103 & 930216 submittals on YAEC-1296P. "DNBR Limit Methodology & Application to ME Vantee Plant" Critical heat flux correlation acceptable for application to facility reload w/14x14 fuel assemblies CLARK.R A Operating Reactors Branch 3 83/03/09 OARRITY, J H Mains Yankee Atomic Power Co 2pp 17690 299 24X Fiche 30-309.83/03/09.8303240026
- --8301060137 FATE-82-114

 "Review of YAEC-1276P DNBR Limit Methodology & Application to Maine Yankes Plant "

 HESSON.0 M Battelle Hemorial Institute, Pacific Northwest Laboratory 82/12/31 NRC No Detailed Affiliation Given. 7pp 17670 308 24X Fiche 50-307,83/03/07.8303240026
- B304180548 Forwards proprietary WCAP-B200, Rev 1, WCAP-B301, WCAP-B302, WCAP-8921, draft responses to questions on WCAP-10079 & related info re new small break evaluation model per NUREG-0737, Item II & 3, 30 Encls withheld (ref 10CFR2 770) RAHE, E P Westinghouse Electric Corp NS-EPR-2746 B3/04/12 THOMAS, C O Standardization & Special Projects Branch 2pp. 17997 049
- --B30418055B Requests that draft answers to NRC questions on WCAP-10079, "NOTRUMP, Nodal Transient Small Break & General Network Code," be withheld per 10CFR2 790
 WIESEMANN,R A Westinghouse Electric Corp AW-83-27
 THOMAS.C O Standardization & Special Projects Branch ip

- 8304200001 Forwards Endorsements 106 & 105 to NELIA Policies NF-111 & NF-83, respectively BOTHMAN, J McDermott, Inc 83/04/11 DINITZ, I Division of Engineering 3pp 18066-092
- 8305020272 Forwards Affidavit AW-80-27 in support of request to withhold proprietary info re affect of radiation on insulating matts in Westinghouse medium motor per 10CFR2 790 re encl util draft 830413 ltr KIESEMANN,R A Westinghouse Electric Corp CAW-83-28 83 THOMAS.C O Division of Licensing 9pp 18277 196 24X Fiche 50-266.83/04/13.8305020272 83/04/13
- --8305020292 71-102-RADMC-R1 auguara: 71-122-RADNG-R1 Nonproprietary version of "Effect of Radiation on Insulating Matis Used in Westinghouse Hedium Notors " BARTKO, J Westinghouse Electric Corp 71/04/10 39/ 18277 205 24% Fiche 50-266.83/04/13.8305020272
- 8305020281 Forwards results of survey of GA procedures applied by BNML to computer code activities for NRC-funded programs
 BANGARTIR L Division of Vendor & Technical Programs 83/04/28
 MATTSON R J Division of Systems Integration (post 811005) 2pp
- 8303020384 Forwards response to 821115 request for addl info re NUREO-0737. Items II E 1 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/II oversize drawings Aperture cards are available in PDR ROBRIOUEZ. R J Sacramento Hunicipal Utility District 83/04/870LISJF Operating Reactors Branch 4 3pp 18293-329 24 Fiche 50-312,83/04/28,8305020384 83/04/28
- ---8305020392 BWNP-20004 (6-76) R3
 Rev 3 to "Auxiliary Feedwater Sys Sys Description"
 * Babcock & Wilcox Co 15-1120580-03 83/04/04 54pp
 18283 332 24X Fiche 50-312.83/04/28.8305020384
- 8305020398 Forwards "B&W 177 Fuel Assembly Owners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozile Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup norries COOK, J W Consumers Power Co 22343 83/04/13 DENTON H R Office of Nuclear Reactor Regulation, Director 3pp 18273 (24X Fiche 50-329, 83/04/13, 8305020398
- --8305020404 77-1141514-00

 "B&H 177 Fuel Assembly Owners Group Stafe End Task Force Rept on Generic Investigation of HPI/Makeup Nozzie Component Cracking "

 + Babcuck & Wilcox Co 83/04/13 61pp 18273 005 24X Fiche 50-029
- 6305020502 Forwards comments on C-E Owners Group calculations re depressurization & DHR capability of C-E plants w/o ospressurvation & DMR capability of C-E plants w/o
 pressurizer PORVs, discussed at 830112 meeting w/C-E Dwners
 Group in Bethesda, MD
 NGVAK, T M Assistant Director for Licensing 83/04/19 MAURIN, L V
 Louisiana Power & Light Co 4pp 18284 333 24X
 Fiche 50-382,83/04/19,8305020502
- 8305020524 Notification of 830505 meeting w/QE in Bethesda.MD to discuss improvements in physics methods & submittal of topical repts FIENC D Core Performance Branch 83/04/20 BERLINGER.C H Performance Branch 2pp 18284 202 83/04/20 BERLINGER, CH Care
- 8305030013 Forwards NRC comments on C-E Dwners Group study re depressurization & DMR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision NOVAK-T M Assistant Director for Licensing 83/04/20 VAI BRUNT-E E Arizona Public Service Co 4pp. 18310 347 24: Fiche 50-528.83/04/20 ROSSOS0015 Fiche 50-528,83/04/20,8305030013
- 8305030272 Forwards propristary versions of XN-NF-CC-38 & Suppl 1, "Users Manual for PTSPMR2.FORTRAN Program for Simulation of PHR Plant Transients " Repts withheld (ref 10CFR2 790) AB Bloot affidayit encl. CHANDLER, J. C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 JCC:061-83 B3/04/20 THOMAS.C.O. Standardization & Special
 Projects Branch 4pp. 18300-023
- G305030337 Forwards proprietary & nonproprietary versions of "Radwaste Solidification Sys " Affidavit for withholding document encl Proprietary version withheld (ref 10crg2 790) POWELL, R H J NVS Corp F5-35-0387 S3/04/27 THOMAS, C O Standardization & Special Projects Branch 4pp 18272 318,

- 8303030410 Provides further specific info re ATMS Salem incident implications on B&W plants B&W control rod drive trip sys contains higher degree of diversity than any other trip sys in industry

 ROY, D H Babcock & Wilcox Co 83/04/28 DENTON, H Office of
 Nuclear Reactor Regulation, Director 2pp 18306 313
- 830503D426 Forwards proprietery version of WCAP-10241, "Westinghouse BWR ECCS Evaluation Model " Computer Codes GOBLIN, DRAGON & CHACHA for GE BWR N888 designs comply w/requirements of App K to 10CFR50 46 Rept withheld (ref 10CFR2 790) R to locking 45 kept withheld (fer locking N9-07) RAME, E P Westinghouse Electric Corp N9-07-07 THOMAS, C D Standardization & Special Projects Branch 2pp
- --B305030438 Requests withholding of proprietary version of WCAP-10241, "Mestinghouse BWR ECCS Evaluation Model," per 10CFR2 790 &
 - 10CFRY 5(4) WIESEMANN:R A Hestinghouse Electric Corp 83/04/20 THOMAS,C O Standardization & Special Projects Branch ip 18294 172
- 8305040302 Summary of 830422 meeting w/Chem-Nuclear & FCTC in Silver Spring.ND re IE Info Notice 83-10, "Clarification of Several Aspects Re Use of NRC-Certified Transport Packages" DDEOAARDEN.R H Transportation Branch 83/04/26 Transportation Transportation 2pp 18324 341
- 8305040433 Forwards proprietary viewgraphs antitled "Probability of Turbine Overspeed," from 930408 meeting w/NRC in Bethesda, MD Affidavit for withholding encl Viewgraphs withheld (ref TOGFR2 790)
 TIMO, P P Deneral Electric Co 83/04/28 IPPOLITO, T A Operating Reactors Branch 2 10pp 18319 135
- 8305040458 Forwards "Core Spray Design Methodology Confirmation Tests," per established procedures PFEFFERLEN.M C General Electric Co MFN-067-B3 B3/04/11 MIRAGLIA.F J Assistant Director for Bafety Assessment 1p 18320 251
- --8305040466 NEDO-24712-A "Core Spray Design Nathodology Confirmation Tests " SANDOZ, B A , MYERS, L L , WOOD, J E General Electric Co 74NED122R1 83/03/31 217pp 18320 252
- 8305040565 Forwards Rev 7 to WPPSS-QA-004, "Operational QA Program Description BOUCHEY.G D Washington Public Power Supply System 83/04/26 GRIMES,D K GA Branch ip 18320 159
- --B305040598 Supports Rev 7 to WPPSS-GA-004, "Operational GA Program Description," reflecting organizational changes Revised rept meets criteria of App B to 10CRS50 HARPSTER,T L GA Branch B3/03/23 BOUCHEY,G D Washington Public Power Supply System 2pp 18320 160
- ---8305040613 WPSS-QA-004 R07
 Rev 7 to WPPSS-QA-004, "Operational GA Program Description"

 * Washington Public Power Supply System 83/03/16 89pp,
- 8305050026 Forwards NEDD-22209, "Analysis of Scram Discharge Vol Sys Piping Integrity " No further action planned re equipment qualification & sys design mods identified in generic SER (NUREG-0803) MAYNE, J P Power Authority of the State of New York JPN-83-39. 83/05/03 VASSALLO, D B Operating Reactors Branch 2 2pp 18339 313 24X Fiche 50-333,83/05/03,8305050026
- 8305050034 Forwards correction to Item 5 of 830329 ltr clarifying emergency procedure guidelines in C-E Owners Group 821122 submittal Discrepancies in termination criteria for once-through cooling clarified WELLS,R W C-E Operating Plants Owners Group WELLS,R W Northeast Utilities RWH-83-23 83/04/22 EISENHUT,D 0 Division of Licensing 2pp 18339 108
- 8305050200 Forwards proprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept " Rept withheld Offereator tope Expansion neps (1997)

 RAHE, E P Westinghouse Electric Corp NS-EPR-2751

 EISENHUT, D G Division of Licensing 1p 18338 153 83/04/20
- --8305050208 Application for withholding "Counterflow Preheat Bteam Generator Tube Ex, ansion Rept," from public disclosure per 10CFR2 770 WIEBEMANN, R A Westinghouse Electric Corp AW-83-32 EISENHUT, D Q Division of Licensing ip 18338 154 AW-83-32 83/04/20

- 8305050347 Informs of fees due for review of Amend 6 to Topical Rept DUME-1-A re GA program MILLER:N D License Fee Management Branch 83/04/25 GRIER.G W Duke Power Co ip 18352 021
- 8305040040 Application to amend License DPR-49, revising App A Tech Specs re max critical power ratio operating limits for 8x8 & 8x8R/P8x8R fuel types to allow implementation of turbine control valve mod ROOT.L D Iowa Electric Light & Power Co NO-83-1152 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18345 052 24x Fiche 50-331.83/05/04.8303060060
- --8305060076 Y1003J01A46 R01
 Rev 1 to "Supplemental Reload Licensing Submittal for Duane Arneld Atomic Energy Ctr.Reload 6 "
 WAONER.R L , ZARBIS, M A . CHARNLEY, J S General Electric Co
 83/03/31 20pp 18345 055 24X Fiche 50-331.83/05/04.8305060060
- 8305060204 Summary of 830320 meeting w/GE in Silver Spring.MD re design criteria for nodular cast iron casts No objections to basic concept expressed.

 ODEQAARDEN.R M Transportation Branch 83/04/21 Transportation Branch 1p 18339 361
- 8305060358 Forwards topical rept evaluation of BAW 10141(P). "TACO-2 Fuel Pin Performance Analysis," Rept acceptable Publication of proprietary & nonproprietary versions of rept requested within 3 months of 1tr receipt THOMAS,C D. Standardization & Special Projects Branch 83/04/13 TAYLOR,J H Babcock & Wilcox Co 2pp 18353 112
- --8304080009 Nonproprietary topical rept evaluation of BAN-10141, "TACO-2 Fuel Pin Performance Analysis " Rept acceptable * NRC - No Detailed Affiliation Given 83/03/31 Sipp
- 8305090212 Forwards proprietary "Mestinghouss Advanced PMR Pretendering Module 5 Chemical & Voi Control Sys " Application for withholding & affidavit encl Rept withhold (ref 100FR2 790) RAME.E P Westinghouse Electric Corp NS-EPR-2759 83/04/29 EIGENHUT.D.O. Division of Licensing 2pp 18362 342
- --8305090202 Application for withholding proprietary "Westinghouse Advanced PHR Pretendering Module 5 Chemical & Vol Control Bys " Affidavit encl WIESEMANN,R A Westinghouse Electric Corp AW-83-36 B3/04/29 EISENHUT.D Q Division of Licensing 9pp 18362 344.
- B305090217 Forwards topical rept evaluation of XN-NF-79-6(P&NP). "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PHRs." defining basis for acceptance of rept THOMAS.C D Standardization & Special Projects Branck TAC 12026-B3/04/28 CHANDLER.J C Affiliation Unknown 2pp 18381 103
- --8305090228 Topical rept evaluation of XN-NF-79-6 (P&NP), "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs " Rept acceptable & Core Performance Branch TAG 12026 83/02/23 5pp 18381 105
- B305090467 Forwards Rev 6 to "GA Program." per NRC B30414 request TAYLOR: H B Bargent & Lundy: Inc 0037-00 B3/04/29 HAABS: W P Division of Engineering & Guality Assurance (Pre B30103). Ip 18360.154
- --8305090469 BL-TR-1A R06
 "QA Program"
 TAYLOR:H 8 , ACKMANN,L E Sargent & Lundy: Inc 83/04/22 48pp
 18360 155
- B305090483 Forwards errata & addenda to NEDD-24011-A-US, "Licensing Topical Rept. GE Std Application for Reactor Fuel (Suppl for US)" & to NEDD-24011-A: "Licensing Topical Rept GE Btd Application for Reactor Fuel"

 CHARNLEY, J B General Electric Co MFN-078-83 83/05/04 TROMAB, C D Division of Licensing ip 18360 263
- ---B303090495 NEDO-24011-A011-A-US
 Errata & addenda to "Licensing Topical Rept GE Std
 Application for Reactor Fuel (Suppl for US) "
 SHERHODD, 0 Q General Electric Co B2NED058, 82/08/31 72pp
 18360:254
- --8305090497 NEDO-24011-A-5 ERR
 Errata & addenda to "Licensing Topical Rept GE Std
 Application for Reactor Fuel "
 * General Electric Co. 82NEDO57 82/08/31 15ipp 18360-336

- 8305070512 Responds to 830405 staff requirements memo re briefing on DHR studies on C-E plants Investigation will be campleted by 830630 & results of study.canclusions & recommendations will be presented to Commission by Aug-Sept DIRCKS.W J Office of the Executive Director for Operations 83/04/25 CHILK, S J Office of the Secretary of the Commission ip 18381 246
- --8305090516 Staff requirements memo ro 830404 briefing on DHR studies on C-E plants Commission requested NRC accelerate study & solicit & address ACRS views on issue CHILK: S J Defice of the Secretary of the Commission M830404 83/04/06 DIRCKS.W J Defice of the Executive Director for Operations ip 18381 249
- 8305090532 Notification of canceled 830505 meeting w/GE in Bethesda, MD to discuss improvements in GE physics methods & submittal of topical repts
 FIEND D Core Performance Branch 83/04/28 BERLINGER, C H Core
 Performance Branch 2pp 18367 336
- B305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Inpical Rept CPC-1A. "GA Manual for Midland Nuclear Plant, vol 1 "
 MILLER, W O License Fee Management Branch B3/04/25 BYRD, W
 Consumers Power Co ip 18367 361 24X Fiche 50-329,83/04/25,
 B305090551
- B305090554 Forwards topical rept evaluation of NEDE-24011-P-A-4,
 "Barrier Fuel Amend to GE Std Application for Reactor Fuel "
 Rept acceptable
 THOMAS.C O Standardization & Special Projects Branch B3/04/13
 CHARNLEY, J S General Electric Co 2pp 18381 254
- --8303090557 Topical rept evaluation of NEDE-24011-P-A-4. "Barrier Fuel Amend to OE Std Application for Reactor Fuel " Rept acceptable Core Performance Branch 83/04/13 12pp 18381 256
- 8305090597 Forwards request for add1 info re review of Addendum 3 to WCAP-8720, "Improved Analytical Models Used in Mestinghouse Fuel Rod Design Computations/Application for BWR Fuel Analysis " Response by 830625 requested THOMAS.CO Standardization & Special Projects Dranch 83/05/02 RAME.E P Westinghouse Electric Corp 3pp 18367 341
- 8305100197 Forwards comments re proposed NUREO-0737 Tech Specs, per 830321 ltr request Comments should not be interpreted as formal position or commitment to specific course of action DENTE.T.J. BWR Owners Oraup. BWR09-8313 83/05/06 EISENHUT.D G Division of Licensing App. 18374-311
- 830510026B Forwards Westinghouse Nev 1 to Procedure 181-154, "Preservice & Inservice Insp of Reactor Vessels " Procedure meets intent of Reg Guide 1,150, Rev 1 as referenced in Generic Ltr 83-15
 CAREY, J J Duquesne Light Co 83/05/06 VARGA, 8 A Operating Reactors Branch 1 ip 18371 160 24X Fichs 50-334,83/05/06,8305100268
- --B305100273 Rev 1 to Procedure ISI-154, "Preservice & Inservice Inservice Inservice Reactor Vessels"

 ADAMONIS.D C . LE FEBVRE. B J , VANO, J A Westinghouse Electric Corp 83/03/16 75pp 18371 161 24X Fiche 50-334,83/05/06,830510024B
- 8305100316 Forwards response to 820830 request for add1 info & revised pages to BAH-10025(P). Rev 1. "Reactor Vessel Model Flow Tests for 203 Fuel Assembly Core " Encl withheld (ref 10CFR2 790)
 TAYLOR, J H Dabcock & Wilcax Co 83/05/02 THOMAS, C G Standardization & Special Projects Branch 2p 18370 098
- 8305100362 Forwards Y1003J01A53, "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant, Unit 1, Reload 3(M/o Recirculation Pump Trip)." inadvertently omitted from 830502 Tech Spec rev request ZIMMERMAN, S R Carolina Power & Light Co LAP-83-167 83/05/06 VASSALLO, D B Operating Reactors Branch 2 ip 18379 059 24X Fiche 50-325,83/05/06,8305100362
- --8305100370 Y1003J01A53

 "BUpplemental Reload Licensing Submittal for Brunswick Steam Electric Plant.Unit 1.Reload 3 (W/o Recirculation Pump Trip) "

 XANARDI, 0 , HILL.R T , CHARNLEY, J S General Electric Co 83/01/31 28pp 18379 060 24X Fiche 50-325.83/05/06,8305100362

- 8305110360 Forwards WCAP-10252, nonproprietary version of WCAP-10196, "Second Cycle Performance of Beaver Valley Unit I Fuel" Application for withholding WCAP-10196, submitted on 830202 encl
 CAREY, J J Duquesne Light Co 83/05/02 VAR9A, S A Operating Reactors Branch i 1p 18392 146 24X Fiche 50-334,83/05/02,8305110360
- --8305110377 Application for withholding proprietary MCAP-10194. "Second Cycle Performance of Beaver Valley Unit 1 Fuel." per 10cFR2 790 Affidavit encl WIEGEMANN.R A Westinghouse Electric Corp CAW-83-13 83/04/20 VARCA.8 A Operating Reactors Branch 1 8pp 18392 147 24X Fiche 50-334.83/05/02.8305110360
- --8305110398 WCAP-10252

 Nonproprietary version of, "Second Cycle Performance of Beaver Valley Unit 1 Fuel"
 PRITCHETT.P A, KUNISHI.H, ROBERTS.E Westinghouse Electric Corp 83/05/02 66pp 18392 156 24X Fiche 30-334.83/05/02, 8305110360
- 8305110437 Forwards "Bounding Analytical Assessment of NUREO-0430 on LOCA & Operating kW/FT Limits," per 830405 ltr CROUSE,R P Toledo Edison Co 945 83/05/06 STOLZ,J F Operating Reactors Branch 4 1p 18404 320 24X Fiche: 50-346,83/05/06,8305110437
- --8305110443 77-1142162-00
 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating HM/FT Limits"
 8 Babcott & Wilcox Co 83/05/06 28pp 18404 321 24X Fiche 50-346,83/05/06,8305110437
- B305120018 Submits organizational charges within util power generation div Effective B30401, nuclear fuel svc dissolved as business segment & integrated into field technical svc.Organization chart encl.

 TAYLORJ H Babcock & Wilcor Co B3/04/22 MAAS, W P Quality Assurance Branch 3pp 18423.045
- 8305120029 Forwards request for add1 info re WCAP-8720.Addendum 2, "Westinghouse Revised PAD Code Thermal Safety Model" Responses should be received by 830525 THOMMAG. C Standardisation & Special Projects Branch 83/05/03 RAME.E P Westinghouse Electric Corp 21pp 18443 257
- 8305120073 Apprises of B&W Owners Oroup plans re plant emergency procedure technical guidelines Abnormal transfent operating guidelines program will be enhanced w/higher level generic ducument expanding emergency operating technical bases HHITNEY.D D. Babcock & Hiltors Operating Plants Owners Group HHITNEY.D D. Sacramento Municipal Utility District 83/05/04 EISENHUT.D G. Division of Licensing 2pp 18427 361
- 930512024f Forwards proprietary & nonproprietary responses to NRC B20819 request for add1 info re measurement uncertainties & "Shape Annealing Factor Component of Axial Shape Index "Proprietary response & rept withheld (ref 10CR2 790) COUNSIL, H G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H, O Northeast Utilities A02724 B3/05/03 CLARK, R A Operating Reactors Branch 3 16pp 18429 151 24X Fiche 50-306.83/05/03,8305120241
- --8305120252 CEN-247(N)-NP
 "Shape Annealing Factor Component of Axial Shape Index
 Uncertainty "
 * Combustion Engineering, Inc. 83/03/31 48pp 18429 167 24X
 Fiche 50-336.83/05/03.8305120241
- B305130126 Forwards response to questions included in B30203 ltr re
 Hydrogen Control Owners Group program Questions 8 & 9 must
 be addressed on plant-specific basis Tentative arrangements
 made for meeting w/Containment Bys Branch on B30602
 RICHARDSON.J D Hydrogen Control Owners Group, BHR-6 Mark III
 RICHARDSON.J D Hississippi Power & Light Co H0N-011
 B3/05/11,
 HOUSTON.R M Division of Systems Integration (post 811005) 25pp
 18437 231 24X Fiche 50-416,83/05/11,8305130126
- 8305160063 Forwards Endorsement 124 to NELIA Policy NF-1 ROBBINS, J G Marsh & McLennan, Inc. 83/03/29 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp. 18451-034
- 8305160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAGLU Policy NF-39 Mc McLennan, Inc 83/05/06 SALTZMAN, J Assistant Director for State & Licensee Relations 3pg 18450 353 24X Fiche 50-089,83/05/06,8305160084

- B305160363 Forwards nonproprietary & proprietary versions of "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," per 10CFR72 Affidavit to withhold proprietary info encl W/o proprietary version PARKER, P E Ridihalgh, Eggers & Associates 22161 B3/04/14 RDUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 4pp 18473 021
- 8305170302 Requests withholding proprietary varsion of "Corrections to Critical Crack Size." per 10CFR2.790 Affidavit encl COLLIER.A R Nestinghouse Electric Corp 8E-83-01 83/04/15 8CHIFFOENS.J O Materials Engineering Branch 9pp 18463 001
- --8305170307 Forwards proprietary & nonproprietary versions of "Gorrections to Critical Crack Size" Proprietary version withheld (ref 1006782 790)
 DICKINSON, J D Westinghouse Electric Corp. SE-83-02 83/05/13 SCHIFFGENS, J O Materials Engineering Branch ip 18463-010
- --8305170311 CT-25086A Nonproprietary version of "Corrections to Critical Crack Size " # Hestinghouse Electric Corp 83/04/15 6pp 18463 011
- 8305170554 Clarifies commitment to apply 100% insp to selected components of DB-50 & DB-416 undervoltage trip attachments, in response to NRC requests New GC procedure will be applied to DB-50 attachments RAHEJE P Westinghouse Electric Corp NB-EPR-2762, 83/05/06 DENTON,H Office of Nuclear Reactor Regulation, Director 29 18467 021
- 8305180262 Forwards response to 830407 & 28 telcon requests for add1 info re Rev 1 to proprietary WCAP-10021 "Westinghouse Wet Annular Burnable Absorber Evaluation Rept " Response withheid (ref 10CFR2 790), RAHELE P Westinghouse Electric Corp 83/04/29 THOMAS.C D Standardization & Special Projects Branch 1p 18487, 223.
- --8305180273 Application for withholding response to request for additing reflection for Rev I to proprietary WCAP-10021 "Hestinghouse Net Annular Burnable Absorber Evaluation Rept," from public disclosure WIESEMANN, R A Westinghouse Electric Corp AM-83-39, 83/04/29, THOMAS.C D Standardization & Special Projects Branch. Ip 18487 224
- 8305190298 Forwards changes in MPGP-1, Rev 5 re GA engineering, providing insp plan to GC & removing requirement for reviewing design documents NRC approval of activity requested MILLER, D B consumers Power Co CSC-6694 83/05/06 HARRISON, J J Region 3, Office of Director 1p. 18501.083 24X Fiche 50-329,83/05/06,8305190298
- --8303190300 MPGP-1 R06 DRFT
 Draft quality plan for underpinning activities.

 * Consumers Pawer Co. MPGP-1 83/05/03, 23pp 18501:084. 24X
 Fiche 50-329,83/05/06,8305190298
- B305200072 Forwards revised pages to fundamental nuclear mati control plan deleting refs to NRC documents & repts no longer applicable. Revs include description of new fuel rod item control sys W/o encl.
 LICHTENBERGER Combustion Engineering, Inc 83-04 83/05/04 JACKSON: R NRC No Detailed Affiliation Oiven 1p 18540.130.
- 8305200552 Deficiency rept re-potential defect in steel spring bands of 60 ampere fuseholders. Initially reported on 830504 Metallurgical testing of broken bands continuing Next rept will be submitted within 30 days DHYER.P W General Electric Co. 83/05/10. DEYQUNG.R Director's Office. Office of Inspection and Enforcement 5pp 18516-007.
- 8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREO-0876) Supporting documentation encl REED, C Commonwealth Edison Co 6434N 83/05/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 10pp 18521 085. 24X Fiche 50-000,83/05/11,8305200621.
- ~~B3052006B4 Advises that Westinghouse QA program implementation described in MCAP-8370, Rev 9A: satisfactory SEYFRIT: K V Region 4. Dallas: Office of the Director (81/03/01). 81/04/30 SLCMBER, R J Westinghouse Electric Corp. 2pp. 18522 259 24X Fiche 30-373,83/05/11,8305200621

- 8305230235 Summarizes info supporting position that postulated pipe breaks in RCS primary loop piping should be eliminated from structural design basis of all Westinghouse plants Testing program per Generic Issue A-2 documented RAMELE P Westinghouse Electric Corp NS-EPR-2768 83/05/11 VOLUMER.R H Division of Engineering 2pp 18537 139
- 8305230505 Requests add1 info to complete review of Rev 12 to GA program topical rept Specific questions will be provided 1 wt prior to 830526 meeting in Framingham MA.per 830512 telcon HARTIN T T JOHNSON, W.P. Yankee Atomic Electric Co. 200 18537 172
- 8305240144 Forwards draft proprietary Amend 2 to Rev 3 to EDR-1(P)-A, "Ederers Nuclear Bafety-Related Extra-Bafety & Monitoring (X-8AM) Cranes " Affidavit dtd 831008 encl Rept withheld (ref 10CFR2 790)
 HOLLDRAN,R W Holloran & Associates 83/05/16 HORAN,D Standardization & Special Projects Branch 3pp 18373 126

- --8305240154 Forwards draft proprietary Amend 2 to Rev 3 to EDR-1(P)-A. "Elevers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes "Rept withheld (ref 100FR2 790) HORAN, D HOLLORAN, R W Holloran & Associates 83/05/13 MORAN, D Standardization & Special Projects Branch 2pp 18573 [
- 8305240310 Forwards Endorsement 59 to NELIA Policy NF-193 & Endorsement 29 to MAELU Policy MF-94
 NILSON, R. Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/17
 SALTIMAN J Office of Nuclear Reactor Regulation, Director Spp
- 8305240431 Informs that GA program.per SWSGAP 1-74A, Rev C. 10324431 informs that OA program.per SWEIGHT 1-74A:REV C, satisfactorily implemented Continuing GA program acceptability contingent upon satisfactory implementation verified through Vendor Programs Brench insps COLLING, J T Region 4, Office of Director 83/05/20 KELLY,R B Stone & Webster Engineering Corp 2pp 18574 124
- ---B305240435 Advises that 8&W satisfactorily implements GA program per BMBGAF 1-74A.Rev C Confirmation recommended CHAMBERLAIN,D Region 4. Office of Director 83/05/18 COLLINS,J T Region 4. Office of Director 2pp 18574 126
- 8305240505 Forwards Rev 1 to CPC-2A "QA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112, Bubmittal serves as VANDEWALLE, D J Consumers Power Co 83/05/11 KEPPLER, J @ Regio 3, Office of Director 2pp 18575 116 24X Fiche 50-000,83/05/11, 8305240305,
- ---8305240565 CPC-2A RO1
 Rev i to "GA Program Description for Operational Nuclear Power Plants" REYNOLDS, J. W., DEWITT, R. B., COOK, J. W. Consumers Power Co. 83/01/10 90pp 18575 118 24X Fiche 50-000, 83/05/11, 8305240505. 70pp
- B305250150 Notification of B30603 meeting w/BWR-Hydrogen Control Owners Group in Bethesda.MD to discuss hydrogen control program & amergancy procedure guidelines HOUBTON:D Licensing Branch 2 83/05/17 SCHWENCER.A Licensing Branch 2 4pp 18596/191 24X Ficha 50-416,83/03/17,8305250150
- 8305250514 Forwards safety evaluation re BHR Owners Group response to NUREQ-0737, Item II K 3 45. "Depressurization W/Other Than Automatic Depressurization Bys " Action on item complete. VASSALLO, D. B. Operating Reactors Granch 2 83/05/18 RHODE, 9 K Niagara Mohawk Power Corp. 2pp 18595 310 24X Fiche 30-220, 83/05/18, 8305250514
- --8305250523 Safety evaluation supporting BMR Owners Group generic response to Item II K. 3.45 of NUREQ-0737, "Depressurization W/Other Than Automatic Depressurization Sys " * NRC No Detailed Affiliation Olven 83/05/18 3pp. 18395 312 24X Fiche: 50-220, 83/05/18, 8305250514
- B305260309 Interim deficiency rept re core support structure bolting Initially reported on B30419 Evaluation of corrective action in progress. Next rept will be sent by B31101. COOK, J W Consumers Power Co 83-05 #1 83/05/19 KEPPLER, J Q. Region 3, Office of Director, 3pp. 18625.200 24X Fiche: 50-000, 83/05/19, 8305260309
- ---8305260311 Deficiency rept re ultrasonic test abnormal indications in upper barrel bolting of reactor internals. Initially reported on 830328. Results of internal bolt insp discussed Add1 info will be forwarded, TAYLOR, J.H. Babcock & Wilcox Co. 83/04/ii. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement Spp. 18625 205 24X Fiche, 50-000, 83/05/19, 8305260309

- --8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
 TAYLOR.JH Babcock & Hilcox Co 83/04/22 DEYOUNG.R C
 Director's Defice. Office of Inspection and Enforcement 3pp
 18625 210 24X Fichs 50-000, 83/05/19, 8305260309
- 8305260320 Forwards NEDO-24582. "Mark I Containment Program Plant-Unique Load Definition. Brunswick Steam Electric Plant Units 1 & 2 " Attachment detailing pressure/temp calculations also enc. ZIMMERHAN, 9 R Caroline Power & Light Co LAP-83-170 83/05/24 VABBALLO.D B Operating Reactors Branch 2 1p (8625 058 24X Fiche 50-324,83/05/24,8305260320
- --8305260325 NEDO-24582 ROI "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 " • General Electric Co «SINEDDO78 81/10/31 61pp 18625 059 * General Electric Co 81NEDD078 24% Fiche 50-324,83/05/24,8305260320
- 8305260376 Requests board notification be issued to boards associated w/c-E plants currently w/o PORVs NRC briefed Commission on 830404 re status of DHR studies w/emphasis on need for PORVs in current C-E designs MATTSON.R J Division of Systems Integration (post 81005) 83/04/28 EISENHUT, D Q Division of Licensing ip 18627 360
- B305270006 Forwards proprietary & nonproprietary versions of viewgraphs presented at B3033 meeting re counter flow preheat steam generator program Proprietary version withheld (ref 10CFR2 790) RAHE, E P Westinghouse Electric Corp NS-EPR-2747 83/04/11 EISENHUT, D G Division of Licensing HQPKINS, B NRC - No Detailed Affiliation Given ip 18638 140
- --8305270012 Submits application for withholding vieugraphs presented at B30331 meeting re-counterflow preheat steam generator program from public disclosure (ref 10CFR2 790)
 Nonproprietary vieugraphs enc1
 HIESEMANN.R A Westinghouse Electric Corp AW-83-24
 EISENHUT.D @ Division of Licensing 12pp 18638 141
- 8305270144 Advises that GA program described in NEDB-11209-04A being implemented satisfactorily Results of insp published quarterly in NUREO-0040 COLLINS J T. Division of Vendor & Technical Programs 83/05/24 BRUGGEMAN, W H General Electric Co 2pp 18638 203
- --8305270149 Discusses corrective actions on nonconformances hoted in IE insps since Jan 1980 QE satisfactorily implemented QA program per NEDD-11209-04A Confirmation of implementation nacommended CHAMBERLAIN, D Division of Vendor & Technical Programs B3 COLLING J T Region 4. Office of Director ip 18638 205 B3/05/20
- 8305270259 Application to amend License DPR-38, changing core protection safety limits, protective sys max allowable setpoints b rod position limits
 TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 App 18641 224 24X Fiche 30-269,83/05/19,8305270259 4pp
- --- 8305270309 BAW-1774 ***Connex Unit 1 Cycle 8 Reload Rept "

 ** Babcock & Wilcox Co 83/02/28 46pp 18641 267 24X

 Fiche 50-269,83/05/19,8305270259
- 8305270340 Forwards application to amend License DPR-59 & "Supplemental Reload Licensing Submittel for JA Fitzpatrick Nuclear Power Plant, Reload 5 "Amend changes std reload licensing submittel for forthcoming Reload 5/Cycle & core HAYNE, J P Power Authority of the State of New York 82/05/25 VASBALLO, D B Operating Reactors Branch 2 2pp 18643 071 24X Fiche 50-333,83/05/25,8305270340
- --8305270378 Y1003J01A56 ROI
 Rev O to "Supplemental Reload Licensing Submittal for JA
 Fitzpatrick Nuclear Power Plant, Reload 5 "
 ZARBISH A , WANNER, R.L. CHARNLEY, J S General Electric Co
 83/03/31. 25pp 18643 103 24% Fiche 50-333,83/05/25,8305270340
- B305270361 Submits topics to be discussed during B30526 meeting reneed for add1 info to complete NRC review of Rev 12 to operational QA program topical rept MARTIN,T.T Division of Engineering & Technical Programs B3/05/20 JOHNSON.W.P Yankee Atomic Electric Co 2pp 18638 361.

- 8305270432 Distusses B&W Owners Group emergency procedure guidelines (abnormal transient operating guidelines ~ ATGG), per 830505 itr Detailed schedule for expansion of technical bases for procedure will be submitted by end of June HHITNEY, D D Babcock & Wilcox Operating Plants Owners Group HHITNEY, D D Sacramento Municipal Utility District GL-82-33 83/05/21 EISENHUT, D O Division of Licensing 2pp 18642 289
- 8305270481 Forwards proprietary "Vantage 5 Fuel Sys, Westinghouse Presentation to NRC Staff," presented at 830510 meeting & application for withholding info from public disclosure RAHELS P Westinghouse Electric Corp NS-EPR-8760 83/03/18 RUBENSTEIN.L S Assistant Director for Core & Plant Systems 2p;
- --8305270488 Submits application for withholding proprietary info re Westinghouse Vantage 5 fuel sys design meeting presentation from public disclosure (ref 10CFR2 790) WIESEMANN.R A Westinghouse Electric Corp AW-83-37 83/05/18 RUBENSTEINL S Assistant Director for Core & Plant Systems 1p 18440 054

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8303290556 Forwards proposed schedule for Basalt Waste Isolation Project 810922 visit WRIGHT.R J High Level Waste Technical Development Branch 0019 81/08/21 GORANSON.R Energy, Dept of 5pp 17743 235
- B303270813 Discusses progress made since Jul 1980 site visit re regulations for high level radwaste repository MRIGHT.R J High Level Waste Technical Development Branch 00266 B1/10/07 LIVINGSTON.V E Washington, State of 2pp 17748 073
- 8305060319 Forwards "Breathing Zone for Airborne Particulates. Cotter Employees for Month of Mar 1983" & "Breathing Zone Summary for CY83" CAIN. J. Cotter Corp. 00232 83/04/13 HAZLE: A. J. Colorado, State of 200 18338 064
- --8305060325 "Breathing Zone for Airborne Particulates, Cotter Employees for Month of Har 1983" & "Breathing Zone Summary for CY83 " * Cotter Corp 0232 83/04/13 2pp 18353 066
- 8305090567 Responds to topical rept on RADMAN computer code to classify & document packaged low level wasts per 10CFR61 Program shows promise as valid tool for wasts generators to use as part of compliance w/Part 61 requirements RULES, OW Low Lavel Waste Licensing Branch 83/03/28. TUITE, P T Waste Nanagement Group, Inc. 1p. 18367-359
- 8305090572 Forwards listed publications per code evaluation
 "Documentation of Computer Codes for High Level Waste Hgt"
 also encl No significant changes expected prior to final
 promotigation H/o encls.
 KNAPP.M R High Level Waste Licensing Management Branch 83/04/12
 BERMANIS.H L Roy F Weston, Inc. 19 18367-358
- 8305090576 Forwards first ii radiological assessment repts for detected areas of residual radioactive maths in Edgemont, SD Add1 repts will be submitted as available W/o encis MARTIN, D E Low Level Haste Licensing Branch 83/04/08. BRICH, R South Dakota, State of ip 18367-357
- 8305090582 Comments on review of Atlantic Research Corp request to allow onsite disposal of soil contaminated w/Sr-90 Patential dose commitment limited to less than 2 mrem to bone provided drinking water not within 250 ft of Sr-90 HIGGINBOTHAN, L. Low Level Waste Licensing Branch 83/04/21 PAGE, R. G. Uranium Fuel Licensing Branch 3pp 18367-354
- B30509058B Submits current & projected activities in fuel cycle program area Resource estimates & level of effort may change after evaluating 1983 budget
 BROWNING R E Division of Waste Management B3/04/15.
 CUNNINGHAM R E. Division of Fuel Cycle & Material Safety 2pp 18367 34B
- B305090606 Trip rept of 830924 visit to Rio Algom mill in Grand Junction.CO PENNIFILL, R A Low Level Waste Licensing Branch 83/04/11 HIGGINBOTHAM.L Low Level Waste Licensing Branch 3pp. 18381:237
- B305090617 Comments on Rev I to "Selection of West Valley Demonstration Project Low Level & Transuranic Waste Form " Insufficient technical data in document to judge adequacy of either cament or asphalt for solidification HIGDINBOTHAM. Low Level Waste Licensing Branch B3/04/15 ROUSE.L C. Advanced Fuel & Spent Fuel Licensing Branch App 18367-372.

- B305090620 Summary of B30316 meeting w/DDE in Bilver Spring,MD re UMTRAP vicinity properties FLORV.C A Low Level Waste Licensing Branch B3/04/28 HIGGINBOTHAM,L Low Level Waste Licensing Branch 2pp 18367 330
- 8305090626 Forwards list of docoments within Div of Waste Mgt re K Dunn FOIA 83-153 request STILLN Division of Waste Management 83/04/06 BEVERIDGE. O Program Support Branch 4pp 18367 325
- B305070643 Forwards NRC comments to DDE on proposed high level waste repository siting guidelines W/o encl BROWNING.R E Division of Waste Management 83/04/18 LEWIS.N D Washington, State of 1p 18367-306
- B305090647 Trip rept of 830419-21 U808 low level waste research meetings in Urbana, IL & at Sheffield site SIEFKEN, D L Low Level Waste Licensing Branch 83/04/27. HAHKINS, E F Low Level Waste Licensing Branch 4pp 18381 208.
- 8303070653 Trip rept of low level waste compact negotiators 830315-16 meetings in Atlanta.GA JACKSON.K Low Level Waste Licensing Branch 83/04/27 HIGGINBOTHAM.L Low Level Waste Licensing Branch 5pp 18381-279
- 8305090656 Forwards for concurrence review. Commission paper recommending publication of proposed suspension of portions of App A to 10CFR40 re U mill tailings regulations Telephone response by 830429 requested H/o encl
 BROWNING, R E Division of Waste Management 83/04/28 KERR, G W Office of State Programs: Director CUNNINOHAM, G, H Office of the Executive Legal Director CUNNINOHAM, R E Division of Fuel Cycle & Material Safety 2pp 18381 277
- 8305070561 Ack receipt of 830308 ltr inviting participation in 2-day meeting on "MIPP Site Suitability for Radwaste Disposal:" on 830512-13 in Carlsbad, NM NRC cannot participate in meeting or evaluation MILLER:H J High Level Maste Technical Development Branch, 83703/31 NEILL.R H New Mexico: State of 2pp 18381 040.
- B305090670 Forward comments on topical rept "Results of Test Program for Soldification of Contaminated Waste Lubricating Dils." State of WA comments should be addressed separately W/o encl UNINSON.T C Low Level Waste Licensing Branch B3/04/27 IRVING.B A Vikem Industries, Inc ip 18369 362
- B305090675 Reviews marked-up handout on high level waste reflecting enactment of Nuclear Waste Policy Act in Jan 1983 W/o encl BROWNING.R E Division of Waste Management B3/03/29 COOK, J Office of Public Affairs 2pp 18381 289
- 8305090679 Forwards 24 radiological assessment repts for properties in Edgemont.8D re presence of residual radioactive metl Repts submitted to DOE for remedial action W/o encis MARTIND E Low Level Waste Licensing Branch 83/04/28 OEIDT.J R Environmental Protection Agency ip 18381.288
- B305090696 Forwards NRC "Technical Criteria for Disposal of High Level Radwaste in Geologic Repositories," 10CFR60. Subpart E.par B30412 ltr Final version to be released on NRC approval H/o encl BALL,H J High Level Maste Licensing Management Branch B3/04/25 BMITH.0 R Michigan, State of 10 18391.287
- 8305090705 Forwards response to 830312 request for comment on remedial action concept paper for U mill tailings site at Green River.UT MARTIN.D E Low Level Haste Licensing Branch 83/04/22 MARLEY.J A Energy, Dept of 3pp 18381*284
- 8305110024 Forwards comments to DDE on 830207 proposed siting guidelines (10CFR960), established in response to Nuclear Waste Policy Act of 1982 requirements NRC comments on DDE FR notice also provided M/o encl DIRCKS:W J Office of Nuclear Reactor Regulation, Director 83/04/25 MATHESON, S M Utah, State of, 1p 18411,356.
- 830511006B Informs that 830406 ltr & attachments sent to M Bell. Copy of Reg Guide 4 17 encl. W/o encl WRIGHT.R J High Level Waste Technical Development Branch 83/04/26 HOVIS, J. B Hovis, Cockrill, Weaver & Bjur 1p, 18421
- 830511013B Forwards info on 20 contaminated properties in vicinity of Grand Junction site Remedial action being prepared, W/o encl.
 BAUBLITZ, J E Energy, Dept of 83/04/15, HAWKINS, E P Low Level Waste Licensing Branch ip 18421 338

- 8305110142 Forwards final draft remodual action concept paper for Qunnison inactive U mill tailings sits Comments requested 6y 830506 W/a encl o enc: Energy, Dept of 83/04/18 ing Branch 1p 18421 350 83/04/18 HAWKINS, E Low Level ORLEY, J. A
- Waste Licensing Branch
- 8305110147 Forwards J Hayes comments on draft ANS 16 1 std W/o enci JOHNSON.J C Low Lavel Waste Licensing Branch 83/04/07 GODBEE.H Cak Ridge National Laboratory 1p 18434 111
- 8305i10i38 Forwards separate responses to RADMAN code topical comments provided by States of SC.WA & NV Code will reinforce GA program & survey acceptabilities
 TUITE,P T Waste Management Group, Inc 83/04/13 JOHNSON,T NRC
 No Detailed Affiliation Given 6pp 18434 097
- B305ii017B Summarizes B304iB meeting w/DDE & Battelle in Gaithersburg.

 MD re siting guidelines (proposed 10CFR96)

 PFLUM.C.G High Level Waste Licensing Management Branch
 BDYLE.R.R High Level Waste Licensing Management Branch
 2pp
- 8305110183 Forwards 24 radiological assessment repts for properties in Edgement, SD w/detected presence of residual radioactive matts Add1 repts will be submitted W/o encl
 MARTIN, D. E Low Level Maste Licensing Branch 83/04/28 BRITCH, R
 South Datota, State of ip 18434 282
- 8305i102iB Forwards comments on proposal for transuranic waste sorting at West Valley per 830405 request Concept acceptable H1001NB0THAN.L Low Level Waste Licensing Branch 83/04/15 ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 4pp 18434 350
- 8305260356 "RADON-222 Repts for Feb & Mar 1983," based on TLD chips for probes placed on 830211 & removed 830405 Replacement probes not available during Mar due to procurement of new lab to perform svcs. Jobbs Cotter Corp 3pp 18647 271 00287 83/04/25 HAZLE, A J Colorado, State CAINCU
- 8305260360 "Breathing Zone Rept for Apr 1983" & "Cumulative Breathing Zone Bummary for CY83" CAIN, J Cotter Corp 00277 83/05/13 HAZLE, A J Colorado, State of, 2pp 18648 021
- 8305310211 C05/8116R028 "Qeology & Hydrology of Yucca Mountain & Vicinity,NV Test Bite," final rept W/three oversize figures Aperture cards are available in PDR
 READE, M T , MCKAY, E D CGS, Inc 83/03/31 71pp 18651 230
- B305310217 Confirms B30601 meeting W/J Baublitz (DDE) in Bathesda,MD to discuss implementation of UMTRCA for Cannonsburg site.

 PAGE.R.O Uranium Fuel Licensing Branch B3/05/23 H100INBOTHAM,L

 High Level Waste Licensing Management Branch FONNER.R Office of the Executive Legal Director CROW.W T NRC No Detailed Affiliation Oliven 1p 18662 268

XPORTLIC EXPORT AND IMPORT LICENSES

- 8305020001 License for QE to export 500 pieces of zircomium tubing to West Germany
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Bafeguards BDW-044-83 B3/04/25 1p 1830B:30B
- 8305020003 Requests Executive Dranch position re QA Technologies, Inc epplication to amend license to export decreasing quantity from 1.1 kg U-235 to 250 g U-235 ZIMMEMAN, B V. Assistant Director for Export/Import & International Safeguards 18308:307 83/04/26 STOIBER, C.R. State, Dept of
- 8305020005 Application to amend license to export, adding addl 120 g U-235 & add1 utilimate consignee
 MARCHAL, J European Communities, Commission of AQ/1543 83/04/14
 GRIFFIN, J A. Energy, Dept. of 1p 18308,306
- B305020021 Application to amend licenses for export & import, extending expiration date by 1 yr BALALIS,C 0. Union Carbide Corp 83/04/18 WRIGHT, 8 NRC No Detailed Affiliation Given 1p 18308 305.
- 8305020096 Ltr of assurance re Westinghouse application to export 200 g U-235 contained in 5.600 g total U to United Kingdom MARCHAL, J European Communities, Commission of. 83/04/14 GRIFFIN: J A Energy, Dept. of ip 18308 264.

- 8305020098 License for Mitsubishi Intl Corp to export 500 mCi Cf~252 to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 64-7739-83 83/04/26 ip 18308 263
- 8305020288 Forwards application to export six depleted U blanks to United Kingdom GDMER, D Nuclear Metals, Inc 83/04/14 WRIGHT, B Office of International Programs, Director 1p 18308 261
- --8305020296 Application to export 30 4 kg depleted U. in six depleted blanks, to United Kingdom
 * Nuclear Metals, Inc. 83/04/14 ip 18308 262
- B305020353 Forwards application for license to export slightly enriched U hexafluoride to Japan
 OSHIMA:S Mitsubishi International Corp (subs of Mitsubishi Corp) HBA-3483-01 B3/04/14 Assistant Director for Export/Import & International Safeguards 3pp 18284 071
- --8305020557 Application for license to export 80,420 kg slightly enriched U hexafluoride to Japan enricated of nexamination of Corp. (Subs. of Mitsubishi Corp.) HSA-5483-01 B3/04/14 1p. 19284-074
- 8305030018 Forwards application for license to export one fission counter, Model RS-P6-0805-134, to West Germany BAER, O Disc Corp C-4422 B3/04/11 HEMBY, E Assistant Director for Export/Import & International Safeguards 2pp 18310 286
- --8305030056 Application for license to export one fission counter, Model RB-P6-0803-134, to West Germany BAER.D Disc Corp C-4422 83/04/11 2pp 18310 288
- 8305030097 Requests Executive Branch position re Transnuclear.Inc application for license to export highly enriched U to Denmark M/o encl ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 00290 82/10/06 STOIBER.C R State. Dept of 1p
- 8305030250 Application to export 500 liters deuterium to Korea HWANG, T Pacific International 455 83/04/18 1p 1830 18309 339
- 8305040395 Add1 info re 830225 application to export 1 kg U-235 to Indonesia Quantity reduced to 250 g.contained in reactor irradiation targets, to allay concerns raised re export MOMRY, W R OA Technologies. Inc /General Atomic Co IEL-4069 B3/04/13 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 9pp 18326 301
- B305040558 Forwards applications for licenses to export 500 pieces scrap zirconium tubing to West Germany & 10 pieces zirconium tube shell to Japan HILSON, B D General Electric Co DDM-046-B3 83/04/14 HEMBY, E D NRC - No Detailed Affiliation Given ip 18351 239
- --8305040561 Application for license to export 500 pieces scrap zirconium tubing to West Germany * General Electric Co. 80W-044-83 63/04/14 1p 18351 240
- --8305040567 Application for license to export 10 pieces zirconium tube sheil to Japan WILSON, D.D. General Electric Co. UDW-045-83 83/04/14 1g 18351 241
- B305040637 Application to import zirc clad U/Zircaloy & U/Zircaloy & metal components & scrap waste from Canada REGAN.NA Babcock & Hilcox Co B3/04/15 Assistant Director for Export/Import & International Safeguards 2pp 18336 281
- 8305040639 informs that Disc Corp 830411 application for license to export proportional counter to Hest Germany meets requirements of Atomic Energy Act License issued w/o normal 15 day waiting period
 ZIMMERMAN, J V Assistant Director For Export/Import & International Bafeguards 83/04/22 Assistant Director for Export/Import & International Bafeguards ip 18336 280
- 8305040644 Notifies that GE 830414 application for license to export irronium tube shells to Japan meets requirements of Atomic Energy Act License issued w/o normal 15 day waiting period ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/04/25 Assistant Director for Export/Import & International Safeguards 1p 18336-279

- B305040658 Amend 2 to Ediow Intl Co as agent for Microtec, Inc export license, changing name of ultimate consigned & extending expiration date to 900501 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards M&B-1 B3/04/26 ip 18334 268
- 8305040665 Requests Executive Branch position re Mitsubishi Intl Corpapplication for license to export enriched U to Japan ZIMMERMANJ V Assistant Director for Export/Import & International Safeguards 83/04/26 87018ER.C R State, Dept of 1p 18336 265
- 8305050440 Amend 3 to QA Technologies. Inc export license, adding vitimate consigned & increasing quantity of math to 3 167 kg U-235.contained in 15 989 kg U.for export to Italy ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards IEL-2013 83/04/28 1p 18352 228
- 8305060006 Application to export two fission counters, Model RS-PG-2403-114, to Argentina SKARUPA, J D Reuter-Stokes, Inc. A-9705 83/04/19 2pp
- 8305060014 Notifies that QE 830414 application for license to export zinconium tubing to West Germany meets requirements of Atomic Energy Act.License issued W/O normal 15 day waiting period ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 83/04/25 Assistant Director for Export/Import & International Safeguards 1p 18354 313
- 8305060052 Ltr of assurance re amend to license to export 33,750 kg U, contained in 1,135 kg U-235,to Sweden MAGNUSON:L Sweden, Ocyt of, 83/04/19 GRIFFIN.J A Energy. Dept of 1p 16354 361
- 8305060687 Executive Branch position re SNUCO. Inc application to export 5 kg U-235. contained in 70 kg U, to Taiwan License should be granted DEVINE. J B State. Dept. of Bureau of Oceans & Intl Environ & Scientific Affairs 83/04/25 SHEA, J R Office of International Programs. Director 3pp 18357-308
- 8305060690 Application for amend to export license, increasing SNM by 312 39 g U-235, contained in 1.573 74 g U, to Japan MOWRY. H R OA Technologies, Inc / General Atomic Co IEL-4072 83/04/25 IMMERMAN, J Assistant Director for Export/Import & International Safeguards. ip 18357 307
- 8305090010 Application to import 26,000 kg U.enriched to 3 30% U-235, from France MARCHALJ Exxon Nuclear Co , Inc (subs of Exxon Corp) 11003189 83/04/25 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 2pp 18369 358
- 8305090014 Application for license to export 2.205 lb Zircaloy trex, w/pure lirconium liner.to West Germany AERNI.B L Teledyne Wah Chang Albany 2625(2) (JFM) 83/04/27 lp 18369 336
- 8305070015 Application for license to export one in-core detector containing 0 001 g U-235 to West Germany FOCHAL Westinghouse Electric Corp ZE10534 83/04/21. ip 18369 357
- 8305090042 Amend 2 to Union Carbide Corp license to import 10,8 kg U. containing up to 10 tg U-235 in 55 MTR plate-type fuel elements. From France.

 ZIMMENANIJ V Assistant Director for Export/import & International Bafeg
- 8305090114 Application for license to export 97,000 lb Zircaloy tres to West Germany. AERNIJE L Teledyne Wah Chang Albany 2907(JFM) 83/04/21 ip (\$1381:131
- 8303090498 License for OA Co to export miscellaneous specially design or pregared replacement parts & components for use in Triga II research reactor to Zaine ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards IEL-3096. 83/04/29 ip 18381 240
- B305090500 License for Westinghouse to export one compensated ionization chamber, Model WL-6377, to Zaire.
 ZIMMERMAN, J. V Assistant Director for Export/Import & International Safeguards IE 20594. 83/05/02 ip. 1838I 251

- 8305090723 Requests renewal of Export Licenses XU-8499 & XU-8499 which expire on 830601 No change in quantity & matts expected GOMER, D A. Nuclear Metals, Inc. 83/04/25 HEMSY, E. Office of International Programs, Director Ip. 18381 276
 - International Programs, Director 1p 18381 276
- 8305070730 Forwards FR notice re applications for licenses to import/export nuclear facilities or matls ZIMMERKAN, J V Assistant Director for Export/Import & International Safeguards 82/05/03 COMBS.T R Correspondence & Records Branch ip 18381 273
- --830509073: Notice of receipt of applications for licenses to import/ export nuclear facilities or matls ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/03 2pp 18381 274
- 8305090733 License for Wastinghouse to export 200 g U-235.contained in 5.600 g U.to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards MNH-353 83/04/29 2pp 18381 271
- B305090736 Amend 2 to Union Carbide Corp export license, extending expiration date to B40701
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 281 83/04/29 1p 18381 270.
- B305090779 Amend i to Exxon export license, increasing quantity to 1,135 kg U-235, contained in 33.750 kg U.to Sweden ZIMKERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/29 lp 18381 269
- 8303090782 Informs that Amend i to Export License X8NM-1903 may be issued No met) changed circumstances since issuence of License X8NM-1974
 MODREJR N Assistant Director for Export/Import & International Bafeguards 83/04/28 Assistant Director for Export/Import & International Sefeguards 1p 18381 269
- 8305130254 Application for license to export one component case studfor specially prepared coolant pumps for nuclear svc.to Spain PEARBON.A Borg-Warner Corp 834V3070 83/05/02 ip 18457:174
- B305130265 Amend I to Nuclear Metals, Inc export license, extending expiration date until B60601 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards B3/05/05 ip 18457 171
- 8305130267 Amend 1 to Nuclear Metals, Inc export license, extending expiration date until 860601
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/05 1p 18457 170
- 8305/30273 Executive Branch position re Edlow Intl Co application for license to export 40 mg Cf-252. In form of cermet wire, to United Kingdom License should be amended DEVINE.JB State, Dept of B3/05/03 SHEA.JR Diffice of International Programs, Director Ip 18457'169
- B305i3030i Application for license to export 2,002 mCi Cf-252.in form of cermet wire, to France.

 HANNETT.B Transpuclear, Inc. TNP-426 83/05/02 2pp 18457.167.
- B305:30303 Application for license to export two WX-33356 BF3 counter tubes & eight WX-33358 Uncompensated ionization chambers to West Germany POCHAL-W F Westinghouse Electric Corp ZE 10149 83/05/03 1p. 18457 166
- 8303130305 Application for license to export primary recirculation pusp accessories to Spain PEARSON.A Borg-Warner Corp. 823-V-2207 81 83/05/02 ip. 18457 145
- 8305160294 Forwards application for export license for minor nuclear export Ltr of assurance required. H/o encl ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards 83/05/11 RAYMOND, J F Energy, Dept of 1p, 18472 078
- 8305160296 Forwards Exxon Nuclear Co. Inc application for amend to export license increasing quantity of U-235 Ltr of assurance required M/o encl ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/05/11 RAYMOND, J.F. Energy, Dapt. of 1p 18472-077

- 8305160298 Application for license to export 200 guide thimble tubes to Japan.
 YUMOTO, H C 1toh & Co (America). Inc MQI-144 83/05/10 2pp
- 8305160300 Amend 1 to 0A Co export license changing name of licensee to 0A Technologies. Inc.
 ZIMMERHAN, J V Assistant Director for Export/Import & International Saféguards IEL-3094 83/05/12 ip 18472 048
- B305160301 Forwards application for license to export cerium fluoride to Canada, United Kingdom, Australia, West Oermany, Japan, France & The Netherlands
 - MENNER, R G M & T Chemicals, Inc 83/03/03 HENLEY, E NRC ~ No Detailed Affiliation Oiven 2pp 18472 063
- --B305160303 Application for license to export cerium fluoride to Canada, United Kingdom, Australia, West Germany, Japan, France & The Netherlands BENNER, R O M & T Chemicals, Inc B3/05/03 ip 18472 065
- --8305160305 Requests info whether new license required to export cerium fluoride to Canada, United Kingdom, Australia, West Germany, Japan, France & The Netherlands BENNER, R G M & T Chemicals, Inc 83/04/07. NRC No Detailed Affiliation Given 2pp 18472 066
- B305160306 Informs that License XSNM-2030 may be issued No matl changed circumstances since issuance of License XSNM-2005 MODRE, R. N. Assistant Director for Export/Import & International Bafaguards 83/05/10 Assistant Director for Export/Import & International Safeguards 1p 18472 062.
- 8305160307 License for Mitsubishi Intl Corp to export 365 kg U-235, contained in 10,554 kg U-to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards HSA-5482-09 83/05/11 2pp 18472-060
- B305160309 Litense for Mitsubishi Intl Corp to export 682 kg U-235, contained in 19.754 kg U. to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards H8A-5482-08 83/05/11 2pp 18472-038
- 8305160310 License for Edlow Intl Co to export 382 kg U-235, contained in 14, 410 kg U. to Japan 21MHERNAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/05/11 Rpp. 18472-056
- 8305160313 License for Teledyne Wah Chang Albany to export 2,205 lb Zircaloy to West Germany ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 2625(2)(JFM) 83/05/01 lp 18472.055
- B3051&0315 License for Nuclear Metals, Inc to export 30 4 kg depleted U.contained in 6 U blanks, to United Kingdom ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafeguards 1-201-7 B3/05/11 ip 18472 054
- 8305170120 Requests Executive Branch position re Nissho Iwai American Corp application for amend to licenses; increasing quantity of highly enriched U for export to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International 8afsguards. 83/05/11 STOIBER, C R State, Dept of ip 1849-1021
- --8303170125 Application to amend licenses, changing quantity to 12,270 tg.contained in 27 026 kg & 25,047 kg.contained in 35 174 kg.for export to Japan YAMANA:K Nissho-Iwai American Corp MPD-0763 B3/05/04 MOCRE:N Assistant Director for Export/Import & International Bafeguards ip, 18496 022
- 8305170575 Ltr of assurance re export of 382 kg U-235, contained in 14,410 kg U,to Japan SHIRAKAWA: T Japan, Govt of. 83/05/03 GRIFFIN, J. A Energy, Dept. of ip 18494.120
- B305170578 Application for amend to export license, extending expiration date to 850630 MILBON, 8 D General Electric Co BDW-050-B3 B3/05/02, MRIGHT, B.L. Office of International Programs, Director, Ip 18496, (iii
- 8305170580 Ltr of assurance re export of 365 kg U-235, contained in 10,854 kg U, to Japan.

 BHIRAKAHA, T. Japan, Govt of, 83/05/03 GRIFFIN, J.A. Energy, Dept. of, ip. 18496-114.

- 8305170582 Ltr of assurance re export of 403 kg U-235, contained in 13,418 kg U-to Japan SHIRAKANA, T Japan, Govt of, 83/05/03 GRIFFIN, J A Energy, Dept of 19 18496 113
- 9305170584 Application for license to import 28,600 kg U.containing i.000 kg U-235, from France KIEL, G R Exxon Nuclear Co , Int (subs of Exxon Corp) 83/04/29 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 2pp 18496 109
- 8305170594 License for Westinghouse to export 5 kg U-235, contained in 150 kg U.to Sweden
 IIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-241 83/05/10 2pg 18495 028
- 8305170609 Informs that License XSNM-2023 may be issued no math changed circumstances since issuance of License XSNM-2005 MORE,R N Assistant Director for Export/Import & International Safeguards 83/05/10 Assistant Director for Export/Import & International Safeguards ip 18497 023
- 8305170611 Informs that License X9NM-2017 may be issued No math changed circumstances since issuance of License XSNM-2005 MODRE:R N Assistant Director for Export/Import & International Safeguards 83/05/10 Assistant Director for Export/Import & International Bafeguards ip (8497 022
- 8305170616 Forwards applications to export 32.000 kg U.enriched to 3 85% U-235 & nuclear fuel hardware, to France W/o application to export hardware KIEL, O R Exxon Nuclear Co , Inc (subs of Exxon Corp.) 83/05/05 ZIMMERMANJ V Assistant Director for Export/Import & International Safeguards 1p 18497-015
- --8303170621 Application for license to export 52,000 kg U,enriched to 3 85% U-235, to France
 KIEL.9 R Exxon Nuclear Co , Inc (aubs of Exxon Corp)
 83/05/05 lp 18477 016
- 8305180067 Forwards applications for licenses to export 52,000 kg U, enriched to 3 85% U-235 & nuclear fuel hardware to France H/O X8NM-2043 application
 KIEL, O R Exxon Nuclear Co . Inc (subs of Exxon Corp) 83/05/05
 ZIMBERMAN, J V Assistant Director for Export/Import & International Safeguards ip 18479 349
- --8305180073 Application for license to export nuclear fuel rod hardware & cage assemblies to France
 KIEL,O R Exxon Nuclear Co , Inc. (subs. of Exxon Corp.)
 83/05/05 1p 18499 348
- 830518007B Forwards application for export license for minor huclear export Ltr of assurance required W/o encl ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards B3/05/11 RAYMOND, J F Energy, Dapt of ip 18499 359
- 8305180086 Amend 3 to 0E & GE Technical Sycs Co.Inc export license. extanding expiration date to 830630 ZIMMERHAN.J V Assistant Director for Export/Import & International Bafeguards BDW-050-83 83/05/12 1p 18499 360
- 8305180090 Amend 5 to 0E export license extending expiration date to 860630 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards BDW-053-B3 63/05/12 ip 18499 361
- B3051B0551 License for GM Corp to export stainless steel spare parts to Canada Timber 1 to Canada Timber 1 to Canada Timber 1 to Canada Timber 1 to Canada Safeguards B4068 B3/05/09 ip. 18504 353
- B305180617 Application to amend export license extending expiration date to 860630 MILBON B.D General Electric Co. BDW-053-83 83/05/02 MRROHT, B.L. Office of International Programs, Director 1p 18805-814
- 8305180629 Ltm of assurance me export of 297 kg U-235, contained in 8:601 kg U. to Japan SHIRAKAHA:T Japan Covt of 83/05/03 GRIFFIN:J A Energy, Dept of 1p. 18505.328
- B305:80703 License for Cerac.Inc to export 11 31 kg thorium.contained in 15 0 kg thorium fluoride.to Suftrerland. ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/05/01 2pp 18506 041

- 8305180709 Application to amend Export Licenses XSNM-1778 & XSNM-1779, changing quantities to 12 270 kg & 25 049 kg.respectively YAMANA.K Nissho-Twai American Corp MPD-0763 83/05/04 MOORE,N Assistant Director for Export/Import & International Safeguards in 18506 045
- 8305180713 Application for license to export 77 kg U oxide powder to Japan HILSON.B D General Electric Co BDH-051-83 83/05/02 ip 18305 044
- 8305180818 Ltr of assurance re export of 65,000 kg U,containing 2.652 kg U-235 & 150 kg U.containing 5 kg U-235.to Sweden MAGNUSON.L Sweden Bovt of, 83/05/09 RAYMOND,J F Energy. Dept of 1p 18505 358
- 0305180819 Ltr of assurance re export of 682 kg U-235,contained in 19,754 kg U-to Japan SHIRAKAHA,T Japan, Govt of, 83/05/03 GRIFFIN.J A Energy, Dapt of up 18505-359
- 9305180826 Ltr of assurance re export of 341 kg U-235, contained in 11,439 kg U, to Japan BHRAKANA, T Japan Govt of, 83/05/03 GRIFFIN, J A Energy, Dept of 1p. 18505-362
- 8305180831 Application to amend export license, increasing quantity to 901 325 kg U-233 contained in 27,509 kg U HANNETF.B A Transnuclear, Inc TNP-398 83/05/03 MDGRE,N Office of International Programs, Director Ip 18506 008
- 8305180833 Application to amend export license, increasing quantity to 2,330 kg U-235
 KIEL & R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/05
 ZIMERMAN, J V Assistant Director for Export/Import & International Safeguards ip 18306 009
- 8303180835 Ferwards application to amend licens# to export 625 62 g U-235, to japan ZIMHERMÁN.J V Assistant Director for Export/Import & International Safeguards 83/05/10. GRIFFIN.J A Energy, Dept of ip 18506 011
- --8305180839 Application to amend license to export 625 62 g U-235.to Japan MOHRY,H R. GA Technologies, Inc /General Atomic Co IEL-4072 B3/04/25 ZIMMERMAN,J Assistant Director for Export/Import & International Safeguards 1p 18306 012
- B305190053 Requests Executive Branch position re Safety Light Corpapplication for license to export dispersed tritium, contained in self-luminous devices, gas chromatograph detector foils & accelerator target devices ZIMMERMAN.J V. Assistant Director for Export/Import & International Safeguards 83/05/09 STOIBER.C R State. Dept of Bureau of Oceans & Intl Environ. & Scientific Affairs ip 18323 196.
- --8305190057 Application for license to export 120,000 Gl tritium to various countries

 MILLER J Safety Light Curp 83/04/22 HEMBRY, E Assistant Director for Export/Import & International Safeguards. 1p 18523 197
- 9305190452 Withdraws 930503 request for amend to export license HANNETT.B A Transpuctear, Inc TNP-398 83/05/10 MOGRE, N Office of International Programs, Director p 18323-167
- 8305200127 Forwards notice of receipt of applications for licenses to export/import nuclear matl Request for hearing or petition for leave to intervene may be filed within 30 days of FR notice publication
 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 83/05/ii COMBS.T R Correspondence & Records Branch ip. 18528 343
- ---B305200137 Notice of receipt of applications for licenses to export/ import nuclear mati ZIMMERNAN.J V Assistant Director for Export/Import & International Sufeguards 83/03/11. 2pp 18528 344
- 8305250165 Forwards updated rept of export licensing actions & summary of pending export applications as of 830430 ZIMMERMAN.J V Assistant Director for Export/Import & International 8afeguards 83/05/13 Assistant Director for Export/Import & International Safeguards. 40pp 18596-147
- 8305240016 Requests Executive Branch position re Exxon Nuclear application for license to export U to Taiwan ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards 83/05/17 STOIBER.C R State, Dept of Ip 18447 097

100

- 8305260018 Application to amend license increasing dollar amount of export to West Germany KIEL, G.R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 83/05/10 ZIMMERMAN, J.V. Assistant Director for Export/Import & International Bafaguards. 1p. 18449-096
- 8305260027 License for C Itoh & Co (America) Inc to export 200 guide thimble tubes to Japan ZIMMERNAN,J V Assistant Director for Export/Import & International Bafeguards MOI-144 83/05/13 ip 19649 095
- 8305260029 License for Byron Jackson Pump Div to export case stud for use in coolant pump to Spain
 ZIMMERNAN.J V Assistant Director for Export/Import & International Bafeguards 836/3070 83/05/20 ip 18649 094
- 8305260034 License for Reactor Experiments, Inc to export il 5 mg Pu-239, as metal disc.encapsulated on nickel, to Japan ZIMMERHAN, J V Assistant Director for Export/Import & International Bafeguards i046 83/05/20 2pp 18649 092
- 8305260055 Requests Executive Branch position re Hestinghouse application for amend to license increasing quantity of U-235 for export to Yugoslavia ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards #83/05/18 STOIBER.C R Btate, Dept of Bureau of Oceans & Intl Environ & Scientific Affairs ip 18647 OE6
- --8305260057 Application to amend license increasing quantity of U-235 for export to Yugoelavia HERBCH,M H Westinghouse Electric Corp MMH-373 B3/05/11. ZIMMERHANJ, U V Assistant Director for Export/Import & International Safeguards 1p 18649 087
- 8305260060 Ltr of assurance re Ediow Intl Co export of 75,000 kg U, containing 3,037 5 kg U-235 & Transnuclear, Inc export of 19 735 kg U-containing 993 2 kg U-235 to Swaden.
 MACNUSCON,L Swaden, Govt of,. 83/05/12 RAYMOND, J F Energy, Dept of 1p 18649 085
- B305260064 Application to amend license to import 23,000 kg U, containing 782 kg U-235,from France
 KIEL,O R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) B3/05/13
 ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 2pp 18647-083
- 8303260067 License for Pacific Intl to export 90 g deuterium to South Korea ZIMHERMAN, J V Assistant Director for Export/Import & International Safeguards 455 83/05/13 ip 18449 082
- 8305260070 Application to amend license to export addl 5,210 kg U, contained in 90,420 kg U-235,to Yugoslavia
 HERSCH: M M Westinghouse Electric Corp MMH-373 83/05/ii,
 ZIMHERMAN,J V Assistant Director for Export/Import & International
 Safeguards ip 18649 081
- 8305260075 Application for Amend 1 to license increasing dollar amount of export
 MILSON.B D General Electric Co BDH-058-83 83/05/10. HEMBY, E D
 NRC No Detailed Affiliation Given 1p 18649.080
- 8305260090 Forwards application for export license for minor nuclear export Ltr of assurance required H/o and ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/19 HART. T Energy, Dept of, 1p. 18649 075
- 8305260097 Responds to 830503 request for confirmation of end use of matl for export license application End use statment encl HANNETT.B A Transnuclear, Inc TNP-426 83/05/16 HEMBY, E. Office of International Programs, Director 2pp. 18649.073
- 8305260113 Forwards application for export license for minor nuclear export Ltr of assurance required H/o encl
 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/05/17 RAYMOND.J J Energy, Dept of 1p 18649 067
- 8305260185 Amend 7 to Ediow Intl Co export license, authorizing retransfer of Cf-252 microgram source from United Kingdom to Iraq ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafeguards TRC-4 83/05/12, ip 18648 106
- 8305260189 License for GE to export 0,125 kg U-235.contained in 12 fully-clad, irrediated fuel segments & 0 070 kg Pu to Denmark & 0 250 kg U-235.contained in 22 fully-clad irrediated fuel segments & 0 110 kg Pu to Norway ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 80H-005-83 83/05/17 2pp 18648-097

- 83052&0191 Amend i to QE export licensurrevising total value of items to be exported to Japan
 ZIMNEMAN, JV Assistant Director for Export/Import & International Safeguards BDH-058-83 83/05/16 ip 18648 096
- 8305250194 License for Teledyne Wah Chang Albany to export 2,205 lb XIrtaloy trex.w/pure Zirconium liner.to Hest Oermany ZIMMERKAN, J V Assistant Director for Export/Import & International Bafeguards. JFM-2625 83/05/10 ip 18448-088
- 8305260197 License for Separative Work Unit Corp. Inc to export 5 kg U-235.contained in 70 kg U. to Taiwan III9MERMAN, J V Assistant Director for Export/Import & International Bafeguards 83/05/13 2pp 18448 072
- 8305260198 Amend 1 to Mitsubishi Intl Corp export license, reflecting change in end use to Genkai Unit 1
 ZIPMERMAN, J V Assistant Director for Export/Import & International Bafaguards MSA-5482-09 83/05/19 1p 18648 071
- 83052&0199 License for Westinghouse to export one unit in-core detector Model ML2379B, to West Germany ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards. ZE1053H 83/05/19 ip 1848 070
- 8305260203 License for Westinghouse to export two BF 3 counter tubes & might uncompensated ionization chambers to West Germany ZITMERMAN.JV Assistant Director for Export/Import & International Bafeguards ZE 10149 83/05/20 1p 18648 066

- B305260204 License for Teledyne Wah Chang Albany to export 97,000 lb Zircalgy trex to West Germany ZIMMERMAN.J V Assistant Director for Export/Import & International Bafegyards JFM-2907 B3/05/18 lp 18648 065
- B309260317 Application for license to export 26,865 kg U-235, as smricked U diaxids, to Japan OKADA. S Mitsui & Co (U S A), Inc (subs of Mitsui & Co , Ltd) MBM-F3-R8 83/05/11 1p 18627 291
- B305260330 Application for license to export 3 modules (75-M0D-287) including support math for penetration to Switzerland POCHALW, SCHNAUTICE Westinghouse Electric Corp. ZE-10503 B3/03/11 1p 18629 290
- 8305270032 Forwards FR notice of applications for licenses to import/export nuclear facilities or matis ZIMMERMANJ V Assistant Director for Export/Import & International Safeguards 83/05/16 COMBS.TR Public Document Branch ip 18662 102
- --6305270034 Notice of applications for licenses to import/export nuclear facilities or matis
 ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards 63/05/16 2pp 18662 103

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT
		50-269 0	ALLAN, J M	8305120421	50-309	F	AUGER.J C	8305120317+	50-320 T
AAHGDT, K. H.	B305100205	50-287 G	ALLAN, J H	8305190356	HISC	•	AULUCK, R	B305250261	50-397 A
AAHGDT, K. H	8305100404		ALLAN, J. H	8305230137*	FOIA		AUSTIN, O	8305120016*	50-295 R
ACKMANN, L E	8305090449*	TOPREP	ALLAN, J. M.	8305250274	50-29	F	AUTIO, H A	Ø305030590	50-29 S
ADAMONIS, D C	8305100273*	50-334 G	ALLANI J M	8305250426	50-334	F	AUTIO, H A	8305050263	50-29 8
ADENBAM, E. Q.	8305020556	50-413 A	WELLING II	6300230426	50 554	•			
ADENSAM, E Q.	8305040021*	50-395 P	ALLAN, J M.	8305250572	50-271	G .	AXELRAD, J AXELRAD, J	8305030405 8305030468	50-250 B
ADENBAH, E. Q	8305040130	50-375 P	ALLAN, J M	8305250577*	50-271	Q	AXELRADI J	8305090184	50~271 G
ADENSAM, E Q.	#\$8\$040282#	50-395 P	ALLANI J H	8305270434	50-309	G.	AXELRAD, J	8305070224	50-280 Q
ADENSAM, E G.	8305060275*	50-395 P	ALLAN, J H	8305270445*	50-309	G	AXELRAD, J	8305070224	50-272 0
ADENSAM, E. O.	8305110136	50-395 P	ALLARD.D J	B208060242*	40-472		AXELKADI O	8303070377	30-2/2 0
ADENSAN, E O.	8305110246	50-327 P	ALLARD, D J	8208060244*	40-672		AXELRAD, J	8305190079	50-309 0
ADENBAH, E. Q.	8305110249*	50-327 P	ALLEN, R E	B305030461	PR		AXELRAD, J	8305240439	1&E
ADENSAM, E Q	8305110253*	50-327 P	ALLENSPACH F R	B305170D47*	50~289	O	AXELRAD, J A	8305200271	50-263 G
ADENSAM, E. O	B305160196	50-413 E	ALLENSPACH: F R	8305230460*	50-289	a	AXELRAD, J A	8305200294	50-315 G
ADENSAM, E. Q	8305160362	50-327 P	ALLISON, C W	8305090561*	50-358	A	AXELRAD, J A	8305200303	50-269 G
AMERICAN P. A.	8305140366*	50-327 P	ALLISON, D. P	8305030474×	50-4B3	G	AXELRAD, J A	830520033B	70-25
ADENSAM, E O		50-327 P	AMICO P J	8305180146*	50-247	Ğ	AXELRAD, J A	9305270164	50-272 0
ADENSAM, E Q	8305160369* 8305170730*	50-347 P	ANICO P J	8305180146*	50-247	Ö	AXELRAD, J A	8305270216	50-254 0
ADENBAN, E G.		50-395 P	AMIN, M.	8305270501#	50~454	à	AXELRAD, M	8305180404	PR
ADENSAH, E. Q. ADENSAH, E. Q	8305180012 8305180023*	50-395 P	ANY, Q D	830525057B*	70-371	•	AXELBON: W L	8305100090*	50-346 G
			*****	######################################	70-671		AXELSON, W L	8305270614*	50~346 G
ADENBAM, E Q	8305180053	50-369 P	ANY, O D	8305250586*	70-371 50-443	•	AXELSON, W L	8305310181*	50-331 0
ADENBAM, E Q	8305180072*	50-369 P	ANAND, R K	8305100400*	50-249	Q	BACHMANNI R O	B305100314	30-266 0
ADENBAM, E. Q.	8305180234*	50-327 P	ANANDAPPA, A	8305020256*		8	BACHMANN, R O	8305240513	50-155 0
ADENSAM, E. O	8305200113	50-395 P	ANANDAPPA, A	8305060422*	50-237	8	BACHMANN R Q	8305270020	50-135 Q
ADENBAM, E. O	8305310187	50-390 F	ANANDAPPA, A	8305060599*	50-237	8	DECEMBER 9	BUODETOOLO	30-100 4
ADRAGNA, J. M.	B305100339	PROJ	ANDERSON, C A	8305140299	50-537	0	BACKUS, R A	8305190199	50-443 Q
ADRAGNA, J. H	8305100339	PROJ	ANDERBON, C A	B305140277	50-537	a	BACKUS, R A	9305190199	50-443 G
AERNIIB L.	8305090014	XPORTLIC	ANDERBON, J. T	8305200465#	50-315	F	BAERI J W	8305250394*	50-483 0
AERNI, B L	8305090114	XPORTLIC	ANDERSON, R D	B305100144*	20-563	R	BAER, J W	8305250374*	50-483 G
AGEE, J R	8305050117*	QA999	ANO. W P	B305270094*	50-395	G.	BAER, J W	B305250474*	50-483 G
AGEE, J R	8305050262*	GA999	ANG, W.P	8305270315*	50-389	Q	BAER, J W	B305250494*	50-483 0
AGLES, J. A.	8305270219*	50-250 G	ANG, W P	6305270389*	50-261	Q	BAER, J W	B305250511*	50~483 0
AGRAHAL, A. K	8305170086	50-537 A	APICELLA, F L	8305110100	50-331	P	BAER, J W	8305250511*	50-483 Q
AREARNE, J.	9305250313*	COMMISSION	APICELLA, F L	8305110549	50-331	p	BAER, J W	8305250589*	50-483 G
AHEARNE, J. F	8010280581*	50-498 A	APPEL, R R	8305130281	40-8728		BAER, J W	8305250589*	50-483 G
		an -	ARAND, J.	8305060401*	50-373	8	BAER, D	9305030018	XPORTL1C
AHEARNEI J. F.	8305180254*	50-498 T	ARAND, J J	8305020353*	50-373	ទ	BAER, D	8305030056*	XPORTL1C
AHEARNE, J. F.	8305230207*	50-320 T	ARAND, J J	8305240354	50-373	š	BAER R E	B305240003*	50-445 Q
Almen, I	B305030474*	50-483 G	ARCHITZEL	B305060530	50-317	8	BAILEY	B305110439	50-284 8
AHMED, I.	B305120368*	50-374 G 50-213 P	ARCHITZEL, R E	8305030208*	50-317	ũ	BAILEY, R. J	8305050190*	50-247 G
AFMED, N.	8305230284*	50-213 P	, media 1 2 cor ()			•			
AHN, T. H	8305110127	NUREO	ARENDTS, J 0	8305110447	NUREO		BAIR. G G	9305130152*	50-344 8
AMRENS, P.	8305030547*	50-309 Q	ARMSTRONG. A B	B305090510*	50-445	Т	BAISDEN, L	8305230159	CONTRACT
AHRENS, P.	8305180460	PR	ARNOLD, R C	8305090351	50-287	P	DALALIS C 0	8305020021	XPORTLIC
AHRENS, P.	B305240386	50-309 0	ARTHUR, J M	8305230387	50-334	P	BALL M J	B305090696	WASTE HOT
ALBERT, W. O	8305170498*	50-508 G	ASH, R E	8305260294	50-317	₽	BALLARD, T A	8303240487*	50-313 P
ALBRECHT, V S.	8305200659	50-338 Q	ASHBURN, D. J	8305160084	50-89	J	BALLARD, T A	B303240495*	50-313 P
ALBRECHT, V. 8.	8305200657	50-338 Q	ASHE, F.	8305230430	50-213	S	BANGART-R L	8305020281	TOPREP
ALBRIGHT, R H.	8305270231*	50-261 G	ASHE, F	8305230441*	50-213	8	BANGART, R L	8305020342	MIBC
ALBRIGHT, R H.	8305270428*	50-369 Q	ASHE, F	8305230531*	MISC		BANDART, R L	8305030520	QA999
ALDERSON, C E	8305020319#	QA999	ASHE, F B	8305050341	50-269	8	BANGART, R L	8303040504	ORG
				000 - 000 MF4	=0.045		BARAN, R	8305230437*	50-219 R
ALEXICH, M. P	8305030519	50-315 P	ABHE, F S.	8305050353*	50-269	S	BARBER, C	8305090184	50-214 N
ALEXICH: M. P.	8305120108	50-315 F	ASHTON, A M	8305110545*	CONTRACT 50-289		BARBER, G	B305190079	50-309 Q
ALLAN: J. M	830427027B	50-244 F	ABSELSTINE, J K	B305230453*	50-352	U G	BARHAM, C D	8305140045	50-241 J
ALLAN, J. M.	8305040785*	50-322 0	AU, T. Y	8305120278 8305120278	50-352	o o	BARHAM, C D	8305160135	50-324 J
ALLANIJ M.	8305040790*	50-322 0	AU, T Y	8305120280*	20-352	•	emaining b	220010000	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
BARI,R A BARKER,N R BARKER,N R DARKER,R F BARNER,I	8305110237 8305110313 8305110322 8305020063* 8305090485*	NUREG 8	BAUNACK, W H BAUNACK, W H BAUSER, D B BAUSER, D B BAUSER, D B	8305250453* 8305250504* 8305100310 8305100310 8305250448*	50-244 G 50-213 G 50-287 G 50-287 G 50-483 G	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305250553* 8305250557* 8305250557* 8305250559* 8305250559*	50-483 Q 50-483 Q 50-483 Q 50-483 Q
BARNES, I BARNES, I BARNES, I DARNES, I BARNES, I	8305030351* 8305030364* 8305030475* 8305030525* 8305050071*	GA999 GA999 GA999 GA999 GA999	BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B	B305250448* B305250451* B305250451* B305250461* B305250461*	50-483	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305250562* 8305250562* 8305250583* 8305250583* 8305250584*	50-483 Q 50-483 Q 50-483 Q 50-483 Q 50-483 Q
BARNES, I BARNES, I BARNES, I BARNES, I BARNES, I	8305050093* 8305050097* 8305050110* 8305050111* 8305050149*	CPPAP PPPAP PPPAP PPPAP PPPAP	BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B	8305250463* 8305250463* 8305250474* 8305250474* 8305250477*	50-483	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305250584# 8305260164 8305260164 8305260168 8305260168	50-483 0 50-483 0 50-483 0 50-483 0
BARNES, I BARNES, I BARNES, I BARNES, I DARNES, I	8305050179* 8305050241* 8305200379* 8305200678* 8305240462*	QA999 QA999 QA979 QA979 QA999	BAUSER, D B BAXTER, T A BAXTER, T A BAXTER, T A BAXTER, T A	8305250477* 8305030467 8305030467 8305030591 8305030591	50-483 0 50-483 0 50-483 0 50-289 0 50-289 0	BAXTER,T A BAXTER T A BAY,J H BAYNARD,P Y BAYNARD,P Y	8305240173* 8305310170 8305050041 8305240357 8305270092	50-483 0 50-483 0 50-142 H 50-302 P 50-302 P
BARNES, I BARNES, I BARNES, I BARNETT, J E BARR, K	8305270286* 8305270307* 8305270311* 8305120011 8305030164*	QA999 QA999 QA999 70-1621 50-320 Q	BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8305100283 8305100283 8305100357 8305100357 8305110266	50-289 0 50-289 0 50-289 G 50-289 G 50-483 G	BAYNARD, PY BAYNE, JD BAYNE, JP BAYNE, JP	8305270275 8305240527 8305020207 8305020381 8305030408	50-302 Q 50-286 P 50-333 P 50-286 P 50-286 P
BARR.X DARR.X P DARR.X P BARR.X P DARR.K P	8305140199* 8305270121* 8305270231* 8305270245* 8305270322*	50-269 G 50-302 G 50-261 G 50-260 G 50-327 G	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305130079 8305130079 8305170450 8305170450 8305170497	50-312 0 50-312 0 50-400 0 50-400 0 50-400 0	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8305040311 8305040424 8305040434* 8305050026 8305050037	50-333 P 50-333 P 50-333 P 50-333 P 50-247 9
BARR,K P BARR,K P CARR,K P BARR,K P DARR,K P	8305270325* 8305270357* 8305270384* 8305270428* 8305270458*	50-62 Q 50-321 Q 50-250 Q 50-369 Q 50-395 Q	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305170497 8305190249 8305190249 8305250205 8305250205	50-400 Q 50-483 Q 50-483 Q 50-483 Q 50-483 Q	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8305040397 8305060427 8305060431 8305060432* 8305060439	50-284 P 50-284 P 50-284 P 50-284 P
BARR, K P BARR, K P BARR, K P BARR, K P BARR, K P	8305270469* 8305270518* 8305270534* 8305270576* 8305270666*	50-111 G 50-269 G 50-338 G 50-335 G 50-259 G	BAXTER.T A BAXTER.T A DAXTER.T A BAXTER.T A BAXTER.T A	8305250274 8305250274 8305250277* 8305250277* 8305250300*	50-483 0 50-483 0 50-483 0 50-483 0 50-483 0	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8305040446* 8305040476 8305040500 8305100340 8305110053	50-286 P 50-247 0 50-286 0 50-333 S 50-286 P
BARRIK P BARRETT, L H BARRETT, L H GARRETT, L H BARRETT, L H	8305270668* 8305040163 8305040170 8305040686 8305060668	50-259	BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8305250300* 8305250346* 8305250346* 8305250351* 8305250351*	50-483	BAYNE, JP, BAYNE, JP BAYNE, JP BAYNE, JP BAYNE, JP	830511005B* 8305110167 8305130039 8305130117 8305160106	50-286 P 50-286 Q 50-286 P 50-286 P 50-333 P
BARRETT, L H BARRETT, L H BARRETT, P A BARTH, C A BARTH, C A	8305240561 8305240603 8305260231* 8305260231 8305240077	50-320 R 50-320 R 50-358 Q 50-400 G 50-400 T	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305250358* 8305250358* 8305250359* 8305250359* 8305250383*	50-483	PAYAB PAYAB PAYAB PAYAB PAYAB PAYAB PAYAB	8305200265 8305200268* 8305200405 8305230375 8305240070	50-333 P 50-333 P 50-296 P 50-333 F 50-296 P
BARTKO.J BARTON.J E BARTON.J J BASKIN.K P BASKIN.K P	8305020292* 8305050424 8305040580* 8305020427 8305170278	30-266 P NUREG 50-320 F 50-206 P 50-361 S	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305250383* 8305250388* 8305250388* 8305250401* 8305250401*	50-483 0 50-483 0 50-483 0 50-483 0 50-483 0	BAYNE, J. P BAYNE, J. P BAYNE, J. P BAYNE, J. P BAYNE, J. P	8305240099 8305240234 8305240328 8305240338 8305240349	50-286 F 50-286 F 50-286 P 50-286 F 50-286 F
BASKIN, K P BASKIN, K P BASKIN, K P BASKIN, K P BASKIN, K P	8305170471 8305170028 8305240178 8305240458 8305240501	50-361 F 50-361 P 50-206 F 50-361 P 50-206 P	DAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8305250403* 8305250403* 8305250412* 8305250412* 8305250417*	50-483 Q 50-483 Q 50-483 Q 50-483 Q 50-483 Q	BAYNE, J. P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8305240442 8305240463 8305240492 8305270284# 8305270340	50-333 P 50-333 P 50-333 P 50-333 9 50-333 P
Baskin, k p Baskin, k p Bass, c w Bass, c w Bass, c w	B305240509 B305250512 B305100036* B305100272* B305250508	50-206 P 50-206 P 50-260 8 50-260 5 50-276 S	BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8305250419# 8305250440# 8305250440# 8305250444# 8305250444#	50-483	BAYNE.J P BAZIN.J BAZIN.J BAZIN.J BEACH.A B	8305270352# 8305120142 8305230245 8305230254 8305070660#	50-333 F CONTRACT CONTRACT CONTRACT 50-445 9
Basin, N Bassin, N Bassin, N Bassin, N	8305020047* 8305020196* 8305020200* 8305020323* 8305020505*	FDIA FDIA FDIA FDIA FDIA	BAXTER,T A DAXTER,T A BAXTER,T,A BAXTER,T A BAXTER,T A	8305250486* 8305250486* 8305250490* 8305250490* 8305250502*	50-483 0 50-483 0 50-483 0 50-483 0 50-483 0	BEACH, A. B BEACH, A. B BEACH, O. BEACH, O. BEACH, O.	8305120155* 8305130021* 8305060826 8305160211 8305160274	50-445 9 50-445 9 40-8380 40-8384 40-8380
Basein, n Basein, n Basein, n Basein, n, Basein, n	8305030047* 8305030078* 8305030339* 8305040264* 8305040376*	FOIA FOIA FOIA FOIA FOIA	BAXTER,T A BAXTER,T A BAXTER,T, A BAXTER,T A BAXTER,T A	8305250502* 8305250506* 8305250505* 8305250515* 8305250515*	50-483 Q 50-483 Q 50-483 Q 50-483 Q 50-483 Q	BEAVER, J.R. BECHHOEFER, C. BECHHOEFER, C. BECHHOEFER, C. BECHHOEFER, C.	8305040580* 8305130045 8305200511 8305240472 8305270606	50-320 F 50-498 9 50-498 9 50-329 9 50-329 9
Bassin, n Basso, l f Basso, l f Bateman, w h Bates, j w	8305040579* 8305190352* 8305230528* 8305140091* 8305270145*	FOIA 50-318 8 50-318 8 50-354 9 70-1151	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8305290521* 8305250521* 8305250524* 8305250524* 8305250531*	50-483	BECK, J. W. BECKER, B. D. BECKER, B. D. DECKHAM, D. H. BECKHAM, J. T.	8305200575* 8305110215 8305110215 8211030191* 8305030634	50-329 A 50-454 9 50-454 9 50-312 0 50-321 P
BATES, J H BAUBLITZ, J E BAUER, E G BAUER, T L. BAUM, A	8305270254* 8305110138 9305030307* 8305100005 8305270035*	70-1201 WABTE MGT 50-352 A 50-172 P 50-320 P	BAXTER, T. A	8305250540* 8305250540* 8305250542* 8305250542* 8305250553*	50-483	BECKHAM, J. T BECKHAM, J. T. BECKHAM, J. T BECKHAM, J. T BEHAN, J. L	B305270336* B305310073 B305310084* B305310092* B305180260*	50-321

AUTROR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
BELANGER, J. L. BELANGER, J. L. BELIBLE, O. A. BELIBLE, O. A. BELIBLE, O. A.	8305020397* 8305040418* 8305270354* 8305270442* 8305270442*	50-255 G 50-275 G 50-321 G 50-338 G 50-335 G	BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8305180277 8305200588 8305270094* 8305270244* 8305270249*	50-289 G 50-259 B 50-395 G 50-33B G 50-302 G	BDRDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8305100223 8305100224 8305100238 8305100237* 8305100255	50-322
BELL.N BELL.N SELL.N SELL.N E BELLAMY.R R	8305100263 8305240347 8305310005 8305060233 8305020340	50-460 G 50-460 G 50-460 G NUREG 50-317 G	BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8305270276* 8305270315* 8305270339* 8305270342* 8305270387*	50-324 Q 50-389 Q 50-335 Q 50-324 Q 50-224 Q	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDINE, T C	8305100380 8305100398 8305200570 8305250373 8305020294	50-322 Q 50-322 Q 50-322 Q 50-322 G 50-155 P
BELLAMY, R. R BELTZ, I L. BEMIB, P BEMIS, P BEMIS, P.	8305250560 8305100369* 8305270308* 8305270401* 8305270506*	50-213 G 50-438 A 50-400 G 50-261 G	BLAKE'A A BLAKE'A A BLAKE'A A BLAKE'A A	8305270402* 8305270406* 8305270478* 8305270492* 8305270537*	50-367 G 50-400 G 50-395 G 50-400 G 50-438 G	BORDINE, T C BORDINE, T C BORDINE, T. C BORGMANN, E A BORGMANN, E A	8305130215 8305190317 8305230044 8305030528 8305170454*	50-155 G 50-155 G 50-155 G 50-358 K 50-358 G
BEMIS, P BEMIS, P. BENAIT, W. R BENNER, R O BENNER, R O	8305270431* 8305270435* 8305020525* 8305140301 8305140303*	SO-400 G SO-324 G FOIA XPORTLIC XPORTLIC	BLAKE.J J. BLOCK.J.D BLOCK.J.D BLOND,R.M	8305270574* 8305270657* 8305070560 8305240527 8305310210	50~280 G 50-370 G 50-445 G 50-247 G NUREG	Borgmann, E. A Borgmann, E. A Borgmann, E. A Borgmann, E. A Borgmann, E. A	8305170553* 8305190168 8305190278 8305190314* 8305240012*	50-358 A 50-358 A 50-358 A 50-358 A 50-358 Q
BENNER, R. 9 BENOIT, W R BENTON, J BERGOOLL, T. E. BERGOOLL, T. E	8305160305* 8103130267* 8305090572* 8305120150* 8305200134*	XPORTLIC FOIA 50-445 G CONTRACT CONTRACT	BLOSSOM, J N BLOUGH BLOUGH BLOUNT, D H	8305020363 8305020337 8305030118 8305120412 8305260341*	40-8452 50-278 S 50-278 S 50-277 S CONTRACT	Borgmann, e a Born, c L Boenax, r J Bothman, J Bouchey, g D	8305240016* 8305090510* 8305130040* 8304200001 8305030166	50-358 G 50-445 T 50-445 G TOPREP 50-460 K
BERDIN, J. H BERLIN, K. BERLIN, K. BERLIN, K BERLIN, K	8305270239 8305140032 8305140034 8305140080 8305140080	50-334 8 50-529 0 50-529 0 50-529 0 50-529 0	BLUBAUGH, R E BODGEN, G BOERGERS, M BOGARDUS, R H. BOGART, D	8305130362 8305250175 8305180439* 8305240530 8305130047*	40-3453 40-1162 50-170 U 50-247 G 50-302 R	BOUCHEY, O D BOUCHEY, O, D BOUCHEY, O, D BOUCHEY, O, D BOUCHEY, O, D	8305040565 8305050159 8305100097 8305100110 8305100246	TOPREP 50-397 G 50-508 A 50-397 A 50-460 K
BERLIN: K BERLIN: K BERMAN: P O BERMAN: P. O BERMAN: P. O	8305160086 8305160086 8305030087* 8305040674* 8305040676*	50-529 G 50-529 G F0IA 70-378 70-378	BOODEN, O BOOER, B. A BOHL, L. S BOHL, L. S BOHN, M. P	8305020407 8305170054 * 8305020365 * 8305020367 * 8305130355	40-1162 50-289	BOUCHEY, G. D BOUCHEY, G. D BOUCHEY, G. D BOUCHEY, G. D BOUKHEY, G. D	8305100304 8305120233 8305160041 8305170156 8305200633*	50-50B A 50-397 K 50-397 E 50-397 A 50-395 S
Bernabei, L Bernabei, L Bernabei, L Bernabei, L Bernard, H	8305190216 8305190216 8305260166 8305260166 8305170100	50-327	BOHM, M P BOLIN, R BOLON, A E BOMBERGER, C	8305130355 8305270048* 8305030375 8305310006 8305230284*	50-537 D 50-320 P 50-123 R 50-123 P 50-213 P	BOUKNIGHT,R J BOUGUARD,M L BOURNIA,A BOWDEN,T J BOWMAN,M E	8305250347 8305230664* 8305170277* 8305240481 8305030388*	50-395 8 COMMISSION FOIA 50-348 I 50-318 S
BERNARD, H BERNHOFT, S, L BERNY, Z, E BERRY, Z, E BERRY, Z, E	8305170114 8305100397* 8305270198 8305100253* 8305110496*	50-112 P 50-305 8 50-305 8 50-251 8 50-250 8	BOMBERGER, C BOOK, H E BOOK, H E BOOK, H E BOOK, H E	8305310241* 8305100416* 8305140029 8305140067 8305140078*	50-285 P 50-237 G 50-142 Q 70-754 70-754	BOYD.D C BOYD.D C BOYD.D C BOYD.D C	8305020348* 8305100271* 8305170174* 8305200247* 8305240037*	50-315 0 50-275 0 50-155 0 50-255 0 50-255 0
BESS, J. E. BEVERLY, K BEVERLY, K P BEYER, B R BIDA: O. T	8305230314* 8305310149 8305310158 8305040702* 8305020547	50~458 G 50~237 8 50~237 8 50~346 F NUREG	800%, H E. 800%, H E 800%, H E 800%, H E	8305170335 8305170343* 8305170494 8305170501* 8305170530*	50-397 Q 50-397 Q 50-275 Q 50-275 Q 50-361 Q	BOYD, D C BOYER, V S BOYER, V S BRADBURY, R B BRADBURY, R B	8305240307* 8305040513 8305100359 8305180383 8305180454	50-315 Q 50-277 Q 50-277 F PR PR
BIDINGER, OH BIDINGER, O.H. BIELAWSKI, AP BIELAWSKI, AP BIELAWSKI, AP	8305030077* 8305250607* 8305060461 8305060461 8305170297	70~1257 70~371 50~599	BOOK, H E BOOK, H E BOOK, H E BOOKER, J. E	9305170562 9305170567* 9305260269 9305260273* 9305030422	50~344 Q 50~344 Q 40~8137 40~8137 50~458 8	BRADBURY.R B BRADBURY.R B BRADFORD,L BRADFORD,P A BRADFORD,P A	6305250406 6305270003 6305100212 8006070443* 8305180121*	PR PR 30-289 G 50-498 A 50-498 A
BIELANSKI, A P BIELANSKI, A P BIELANSKI, A P BIER, J BIER, J	8305170297 8305170565 8305170565 8305040542* 8305040543*	50-454	BODKER, J.E BOOKER, J.E BOOKER, J.E. BOOKER, J.E. BOOKER, J.E	8305040435 8305040475 8305100198 8305120321 8305120343	50-458 S 50-458 S 50-458 A 50-458 S 50-458 @	BRADFORD.P A BRADHAM.A S BRADLEY.E J BRADLEY.E J	8305180175* 8305270370* 8305050321* 8301310240 8305020255	50-498 G 50-348 G 50-395 F 50-352 K 50-352 E
BIQBEE, D BILANIN, A. J BIMBER, R. H BIRCH, M. L. BIRKEL, R. A	8305200491* 8305130104* 8305170464 8305200440* 8303300370	50-373 P 50-271 P 50-440 0 50-369 P 50-369 P	BODKER, J E BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	9305120367 9305120409 9305120413 9305120424 9305170281	50-45B S 50-45B S 50-458 S 50-458 S 50-458 S	BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J GRADLEY, E J	8305020454 8305030299 8305030307* 8305050021 8305050027*	50-352 E 50-352 A 50-352 A 50-277 P 50-277 P
BIRKEL,R A BIBCHOFF, C A BISHOP, L L BISHOP, L L BISHOP, L, L	8305030675 8305240482 8305030541 8305030541 8305040449	50-367 B 50-527 G 50-443 G 50-443 G 50-327 G	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8305170385 8305170479 8305200151 8305200264 8305200390	50~438 \$ 50~458 8 50~458 \$ 50~458 8 50~458 \$	BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J	8305060457 8305120320 8305130096 8305170187 8305170228	50-352 A 50-352 A 50-353 A 50-352 A 50-352 E
BISHOP, L. L BISHOP, L. L BISHOP, R. W BISHOP, T. W	8305040449 8305040382 8305180354 8305020073 8305020183	50-327	BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. E	8305230007* 8305230438 8305230462 8305240468 8305240268	50-45B F 50-458 S 50-45B S 50-45B S 50-45B S	BRADLEY.E J BRADLEY.E J BRADLEY.E J BRADLEY.E J BRADLEY.E J	8305180343 8305180389 8305180402 8305180414 8305180419	50-352 A 50-352 E 50-352 A 50-352 E 50-352 A
BISHOP, T. W BISHOP, T. W BISHOP, T. W. BISHOP, T. W.	8305170332 8305170359 8305170363 8305170417 8305170474	50-275	BOOKER: J E, BOOKER: J E BOOKER: J. E BOOKER: J. E BOOTH: L. F	8305260279 8305260318 8305310042 8305310102 8305110507*	50-458 8 50-458 8 50-458 8 50-458 I CONTRACT	BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J	8305180432 8305180451 8305190359 8305200615 8305230476	50-352 A 50-352 E 50-352 C 50-352 E 50-352 A
BISHOP, T H BISHOP, T H BISSETT, P, BLACKMON, T Q BLAKE, E L	8305240393* 8305260257 8305250305* 8305130155* 8305180277	50-275 G 50-275 G 50-287 G 50-373 F 50-289 G	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8305030488 8305090129 8305090136* 8305100196 8305100222	50-322	BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J	8305240307 8305250133 8305270375 8305310009 8305310045	50-277 J 50-352 A 50-352 A 50-352 E 50-352 E

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUB-JECT CATEGORY
Braeger, C B	8305200488*	50-373 P	BROYMILL, J T	8305230703	50-287 U	CANTRELL, F 8 CANTRELL, F 8 CANTRELL, F 8 CANTRELL, F 8 CANTWELL, P F	8305270381*	50-259 0
Brandenburg, B	8305020428	50-247 G	BRUNE, R L	8305040475	NUREG		8305270438*	50-416 0
Brandenburg, B	8305030583	50-247 G	BRUNNER, E J	8305240488	50-219 R		8305270476*	50-518 0
Brandenburg, B	8305040505	50-247 G	BRUNNER, E J	8305240510	50-244 R		8305270532*	50-395 0
Brandenburg, B	8305100208	50-247 G	BRUNNER, J E	8305240322	50-329 G		8305040572*	50-295 6
Brandenburg, B	8305130064	50-247 0	BRUTECH,W A	8305100309	50-213 F	CANTWELL, P F	8305310160	50-304 B
Brandenburg, B	8305130071	50-247 0	BRYANT,D	8305200656	50-440 G	CAPHTON, D L	8305230460*	50-289 Q
Brandenburg, B	8305240527	50-247 G	BRYANT,J	8305270338*	50-249 G	CAPHTON, D L	8305250306*	50-277 Q
Brandi, V A	8305200549	50-322 S	BRYANT,J	8305270411*	50-249 G	CAREY, J J	8305020359	50-334 P
Brannen, J	8305180459*	50-322 H	BRYANT,J C	8109040024	50-269 8	CAREY, J J	8305060604	50-334 P
BRANNEN, J BRANNIN, J P BRANBCOME, J M BREADY, J C BREAKEY, T	8305180461* 8305170250* 8305170601 8305180308 8305260180	50-322 H 50-335 8 40-3453 FDIA 50-155 G	BUCK.C R BUCKLES.J BUCKLEY.B BUDNITZ.R J BUDWANI.R N	8305270130 8305140024 8305040312* 8305180353 8305170701	State Prog 50-315 J 50-387 P PR 50-461 A	CAREY, J J CAREY, J J CAREY, J J CAREY, J, J CAREY, J J	8305040409# 8305100268 8305100337 8305110340 8305110424	50-334 P 50-334 Q 50-334 P 50-334 P
BRENIZER, J S	8305230548	50-396 P	BUDZIK, D M	8305240137	50-329 K	CAREY, J. J	8305200439*	50-334 Q
BRENIZER, J S	8305270226*	50-62 G	BUFE, J L	8305050025*	50-302 8	CAREY, J J	8305240401	50-334 P
GRENNAN, P J	8305240517	50-247 H	BUFE, J L	8305170402*	50-302 8	CAREY, J J	8305240404	50-334 Q
BRENNER, L	8305020390	50-322 G	BULLINGTON, R L	8305040284*	CONTRACT	CAREY, J J	8305250516	50-334 P
BRENNER, L	8305040429	50-322 G	BUPP, L P	8305090388*	GA999	CAREY, J J.	8305270187	50-334 P
Brenner, L Brenner, L Brenner, L Brenner, L Brenner, C	8305060459 8305090505 8305170538 8305180136 8305240432	50-322	BURCH, R H BURCHETT, R R BURDOIN, J BURDOIN, J F BURDOIN, J F	8305020319* 8305090142 8305170564* 8305170390* 8305170537*	QA979 NUREO 50-528 Q 50-508 Q 50-528 Q	CARFAONO, P CARLIBLE, C. B CARLIBLE, C B CARLIBLE, C B CARLIBLE, C B	8209210332* 8305030300 8305030324 8305030500 8305030507	50-336 P 50-397 B 50-397 A 50-397 B 50-397 B
BRENNER, L BRENNER, L BRENNER, L BRENNER, L BRENSTER, A	8305240460 8305250334 8305270563 8305270395 8305190201*	50-322	BURGE, C A BURGER, F J BURKE, A R BURKE, D J BURKE, D J	8305130309* 8305170007* 8305040425* 8305270439* 8305270490*	50-272 F 50-271 R F01A 50-280 G	CARLIBLE.C 8 CARLIBLE.C 8 CARLIBLE.R W CARLBON.J CARLBON.J D	8305130104 8305130245 8305310002 8305240393* 8305170339*	50-397 8 50-397 R 50-247 T 50-275 Q 50-275 Q
BREY, H L BREY, H L BREY, H L BREY, H L	8305020462 8305160048 8305160053 8305170380 8305240477	50-267 P 50-267 P 50-267 P 50-267 P 50-267 P	BURKE, S BURKE, T J. BURNETT, P. T BURNETT, P. T BURNS, S O	8305250025 8305040144* 8305270470* 8305270521* 8305180315*	FOIA FOIA 50-416 G 50-369 G 50-498 A	CARLBON, J. D CARLBON, R T CARNEY, J CARNEY, J	8305260262* 8305120397* 8305120656* 8305110012 8305250517	50-275 Q QA999 70-925 PR PR
BRICKS, O	83051300B6*	50-244 P	BURSTE IN: 8	8305060408	50-266 P	CARR: A V	8305090448	50-413 0
BRIDEN, D	8305060702*	50-344 F	BURSTE IN: 6.	8305110075	50-266 P	CARR: A V	8305100282	50-413 0
BRIGOS, L	8305110508*	50-333 Q	BURSTE IN: 9	8305110181	50-266 P	CARR: A V	8305100342	50-413 0
BRIGOS, L	8305250443*	50-245 Q	BURSTE IN: 9	8305110201	50-266 P	CARR: A V.	8305100415	50-413 0
BRIGHT, O	8305030582	50-142 9	BURSTE IN: 8	8305120408	50-266 G	CARR: A V	8305310025	50-413 0
BRIGHT, 0 O BRIGHT, 0 O BRIGHT, 0 O BRIGHT, 0 O	8305060520 8305100330 8305130076 8305130079 8305130150	50-142	BURSTE IN, S BURSTE IN, B BURTON, J W BURWELL, S. BURWELL, S. B	8305170144* 8305230724 8305310054 8305090578* 8305090600*	50-266 G 50-266 P 50-276 B 50-445 G 50-445 G	CARROW, H. CARROW, H CARROW, H. CARROW, H CARROW, H	8305040479 8305040485* 8305040492* 8305040498* 8305060471	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
BRIGHT, O O	8305160163	50-142 0	BURWELL, S. B	8305120107	50-445 A	CARROW, H	8305130075	50-400 0
BRINKMAN, D S	8305060568*	50-447 E	BURWELL, S. B	8305160244*	50-445 G	CARROW, H	8305130089	50-400 0
BRIXEY, P	8305190181*	50-293 8	BUSCHBACH, T C	8305170121	NUREO	CARROW, H,	8305240446	50-400 0
BROBST, O E	8305190290*	50-317 9	BUSH, M W	8305160174	50-352 G	CARROW, H	8305240551	50-400 0
BROCK, B L	8305160078*	70-754	BUSH, M. W	8305240316	50-352 H	CARTEAUX, P,	8305120397*	50-315 8
BROMBERO, B.	8305050385	CONTRACT	BUSH, S H BUSH, S. H BUSHNELL, T E BUTCHER, R C BUTCHER, R C	8305130357	50-537 0	CARTEAUX, P	8305170444*	50-315 8
BROMET, E J.	8305270022	50-320 P		8305130357	50-537 0	CARTEAUX, P	8305170451*	50-316 8
BROMET, E J.	8305270027*	50-320 P		8305130232*	50-344 8	CARUBO, R,	8305020561	50-322 R
BROOKS, E H	8305270306*	50-416 G		8305110397	50-395 8	CARUBO, R	8305170491	50-322 A
BROOKS, J	8305230675*	COMMISSION		8305200588	50-259 8	CARVER, A M	8305030579*	50-327 8
BROWN, E. J	8305190349	50-407 P	BYRD, R.	8305050178*	30-416 E	CARVER, A. M	8305050128*	50-327 8
BROWN, E. J	8305110523	KURE0	BYRD, R.	8305130200*	30-416 E	CARVER, A. M.	8305050217*	50-328 8
BROWN, E. J	8305200411*	50-263 G	BYRD, R.	8305170431*	50-416 E	CABE, E. Q	8305170110*	50-272 8
BROWN, E. J	8305050341	50-269 B	BYRD, R.	8305170433*	50-416 E	CABELLI, A. E.	8305230176*	71-496
BROWN, E. J	8305050353*	50-269 B	BYRD, R.	8305200286*	50-416 E	CABBELLI, A.	8305200720*	50-338 P
BROWN, E. J. BROWN, E. J BROWN, O. D BROWN, O. D BROWN, O. D	8305230573 8305230619* 8305030297 8305030499 8305120479	50-237 S 50-237 B 70-846 40-279 40-8027	BYRD, R BYRD, R BYRON, P CADMAN, W CADMAN, W K	8305250579 8305310204 8305020285* 8305230570* 8305270058	50-416 8 50-416 8 50-341 G 50-482 I 50-482 A	CATTON, I CAUDLE, R. E CAVANAOH, R. CAVANAOH, R CAVANAOH, R	8305130321 8305180684 8305170272 8305170272 8305170272	ACRB 71-9150 50-522 0 50-522 0 50-522 0
BROWN, H H BROWN, H H BROWN, H H BROWN, H H BROWN, J. M	8305040518 8305040518 8305120300* 8305030255*	50-322 0 50-322 0 50-322 0 50-322 0 70-378	CAHILL,W J Cain,J Cain,J. Cain,J. Caldhell,R a	8305170448 8305060319 8305260356 8305260360 8305030308*	50-458 K Haste Mot Haste Mot Haste Mot 70-846	CAVANAOH, R, CAVANAOH, R CAVANAOH, R CAVANAOH, R CAVANAOH, H	8305170272 8305170272 8305170279 8305170347 8305170290	50-522 0 50-522 0 50-522 0 50-522 0 50-382 H
BROWN: R. L.	8305050163*	50-458 G	CALKINS, D E	8305190112*	50-329 8	CAVANAUGH, W	8305200451*	50-313 8
BROWN: B. D.	8305250271*	50-287 P	CALLAN, L J	8304150154*	50-313 G	CERBONE, R	8305110237	NUREO
BROWNE: W. O.	8305120251*	40-672	CALLISON, R L	8305020070*	FOIA	CERNE, A	8305110299	50-443 8
BROWNE: W. G.	8305120274*	40-672	CAMP, M J	8305240370*	50-315 8	CERNE, A. C	8305050119*	50-443 0
BROWNING: R. E.	8305090588	Waste Mot	CAMPAONA, J H	8305020015*	FOIA	CEBARE, Q,	8305240260*	50-414 P
BROWNING, RE BROWNING, RE BROWNING, RE BROWNLEE, V L BROWNLEE, V L,	8305090643 8305090656 8305090675 8305270328* 8305270337*	WASTE MOT WASTE MOT WASTE MOT 50-424 G 50-424 G	CAMPAONA, J H CAMPAONA, J H CAMPAONA, J, H, CAMPBELL, E CAMPBELL, M	8305020 567* 8305040 211* 8305040 224* 8305170361* 8305040 172	FOIA FOIA FOIA MISC 14E	CHACKEB, K M CHAFFEE, A E. CHAMBERLAIN, D CHAMBERLAIN, D CHAMBERLAIN, D	8305100257 8305170421* 8305020307* 8305030474* 8305240435*	50~483 0 50~361 0 9A999 50~483 0 9A999
BROWNLEE, V L	8305270338*	50-269 Q	CAMPBELL, M	8305040201	1&E	CHAMBERLAIN, D.	8305270147*	9A999
BROWNLEE, V L	8305270462*	50-395 Q	CAMPBELL, S E	8305200222	PR	CHAN, E. I	8305140146	50-546 0
BROWNLEE, V L	8305270482*	50-537 Q	CANTER, H L	8305170421*	50-361 Q	CHAN, E. I.	8305140158	50-546 0
BROWNLEE, V L	8305270525*	50-302 Q	CANTRELL, F S	8305110399	50-395 S	CHAN, E. I.	8305170003	50-546 0
BROWNLEE, V L	8305270530*	50-366 Q	CANTRELL, F S	8305270370>	50-348 Q	CHANDLER, J. C.	8305030292	TOPREP

	ACCESSION	SUBJEC T		ACCESSION	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR	NUMBER	CATEGORY	AUTHOR	NUNBER	CATEGORY	Y 	CLARK.R A	8305200021	50-266
CHANDLER, L J	8305100199	50-361 G	CHILK, 8 J	8305310017 8305310018	50-277 50-358	G G	CLARKAR A CLARKAR A	8305200023 8305200030	50-282 ·
CHANDLER, L J CHANDLER, L J	8305100220 8305160127	50-361	CHILK'S 1	8305310021	50-155 MISC	G	CLARKIR A CLARKIR A	8305200060 8305200068	50-285 . 50-309 @
CHANDRA, U CHANQ, Q	9305230272* 8305200598	50-537 A 50-440 G	CHIRAMAL, M CHO, F L	8305230531* 8305170303*	50-373	P			50-317
CHAPLIN, S D	8305030535*	50-320 8	CHOULES, N C	8305260334*	50~373	œ	CLARKIR A CLARKIR A	930520007B 8305200081	50-336 (
CHAPLIN, 8 D	8305110378*	50-320 S	CHRIBSOTIMOS, N CHRIBTA-MARIA	8305310112* 8305040542*	50-254 50-155	Q G	CLARKIR A CLARKIR A	8305200090 8305200094	50-335 r 50-338 r
CHAPLIN.8 D CHAPLIN.8 D	8305310004* 8305310007*	50-320 8 50-320 8	CHRISTEL, B	8305310165	50-237	s	CLARK, R A	8305200710*	50-338 ,
CHAPLIN, S D	8305310010*	50-320 8	CHRISTIANSON, W	8305240231*	50-358		CLARK, R A	8305230128	50-313 · 50-285 ·
CHAPLIN, 8 D	9305310014* 9305310017*	50-320 S 50-320 S	CHRISTMAN, J N CHRISTMAN, J N	8305040461 8305040461	50~322 50~322	G G	CLARKIR A CLARKIR J	8305310240 8303300387	50-260 .
CHAPLIN, 8 D	8305310024*	50-320 8	CHRISTMAN, J N CHRISTMAN, J N	8305130077 8305130077	50-322 50-322	G G	CLARKIN M CLARKIN H	8305250304* 8305250304*	50-483 G 50-483 G
CHAPLIN, B D	9305310030* *AE00310058	50-320 S 50-320 S	CHRISTMAN, J N	B30516006	50-322	Q	CLARK, W M	B305250304*	50-483 €
CHAPLINAS D	9305310041*	50-320 B	CHRISTMAN, J N	8305160006	50-382	G G	CLARK, W M CLARK, W M	8305250354# 8305250354#	50-483 (50-483 (
CHAPLIN, B D CHAPLIN, B D	8305310047* 8305310056*	50-320 S 50-320 S	CHRISTOFFER, G CHRISTOFFER, G	8305020397* 8305040445	50-231	8	CLARK, W M	8305250354*	50-483 C 50-483 C
CHAPLIN, B D CHAPLIN, B D	8305310066* 8305310072*	50-320 8 50-320 8	CHURCHILL, B W	830502043B 830502043B	50-266 50-266	0 0	CLARK, W M	8305250536#	
			CHURCHILL, B W	8305170291	50-266	G	CLARK, H M CLARK, W M	8305250536* 8305250536*	50-483 (50-483 (
CHAPLIN, B D CHAPLIN, B D	8305310087* 8305310091*	50-320 8 50-320 8	CHURCHILL, B W	8305170271 8305120323*	50-246	G T	CLARK W M	8305250587* 8305250587*	50-483 (50-483 (
CHAPLIN, B D CHAPLIN, B D	8305310076* 8305310101*	50-320 8 50-320 8	CHWASTYK, J J CILIMBERG, R L	8304150364*	50-440	G	CLAY, E L	8305270159*	70-1113
CHAPLIN.8 D	8305310107*	50-320 8	CILIMBERO, R L	8305120420*	50-373	G .	CLAYTON, F L	8305020456	50-348 , 50-364
CHAPLIN, 8 D CHARNLEY, J. E	8305310114* 8305040055*	50-320 8 50-321 P	CILLIB.M CINGUEMANI.D	8305170567* 8305240537	50-344 50-247	G H	CLAYTON: F L CLAYTON: F L	8305030580 8305050148	50-348
CHARNLEY, J 8	8305060076*	50-331 P	CINTULA, T C CINTULA, T C	8305040146 8305040150*	50-318 50-318	6 8	CLAYTON: F L CLAYTON: F L	8305050195 8305100132	50-348 50-344
CHARNLEY, J 8. CHARNLEY, J 8	8305090483 8305100370*	TOPREP 50-325 P	CLARDY, L B	8305100218*	50-331	Q	CLAYTON, F L	8305110257	50-364
CHARNLEY, J. S	8305270378*	50-333 P	CLARK, A T	8305260393	PROJ	_	CLAYTON, F L	8305110308 8305160074	50~348 ; 50~348 (
CHEATHAM, J. R CHEN, C	8305040256* 8305060277*	FOIA 50-244 P	CLARK, D O CLARK, L	8305030333* 8305070315*	50-254 MISC	8	CLAYTON F L	8305200304	50~348 .
CHEN, S	8305200720* 8305090578*	50~338 P 50~445 G	CLARK, L CLARK, R.	8305140043 8305140192	50-20 50-312	8 Q	CLAYTON F L	8305200357	50-364 r
CHEN, W. P			CLARK, R. A	8303240026	50-309	P	CLAYTON, F L CLAYTON, F L	8305200579 8305230540	50-348 ·
CHEN, W P CHIANGI, N J	8305230449* 8305030401	50-445 G 50-400 B	CLARK, R. A.	6305020600	50-309 50-335	P	CLAYTON.F L CLAYTON.F L	8305240171 8305240440	50-348 ·
CHIANGI, N. J CHICK, D E	8305110252 8305020482	50-400 8 50-443 Q	CLARKIR A CLARKIR A	8305020402 8305040789*	50-317	p P	CLAYTON, F L	8305250285	50-348
CHICK, D E	8305020484	50-443 0	CLARK, R A	B305040795*	50-317	•	CLAYTON F L	8305250353	50-348
CHILK, S	8305230333* 8304040470	PR 50-277 Q	CLARKIR A CLARKIR.A	100040001 E1004000EB	50-266 50-282	P P	CLAYTON, F. L CLAYTON, F. L	8305250391 8305250581	50-348 50-348
CHILK, B. J. CHILK, B. J.	8305030522	50-445 G	CLARK, R A	8305060017 8305060023	50~338 50~282	P P	CLAYTON; F. L CLEMONS; P	8305310201 8305110320*	50-34B 50-309
CHILK, B. J. Chilk, B. J	8305030532 8305040068#	50-70 G 50-289 G	CLARK, R A.	8305060037	50-335	P	CLEHONS, P	8305190191*	50-271 (
CHILK, S. J.	8305040436	50-35B 0	CLARK R A	8305040042	50-309	p P	CLINE, W. E CLINE, W E	8305270427# 8305270446#	50-416 (50-375 (
CHILK, S. J. Chilk, S. J	8305050015 8305060274	50-445 0 50-498 0	CLARKIR A CLARKIR.A	8305040045 8305040058	50-317 50-336	P	COCHRAN, T B	B305100276	50-537 4 50-249
CHILK, B J CHILK, B. J.	8305040696 8305090516*	10CFR 10CFR	CLARKIR A CLARKIR A	8305060065 8305060077	50-338 50-317	P F	COEN, R.	8305240366	
	8305100299	50-289 G	CLARK, R. A	8305040108	50~282	P	COFFEY.J A.	8305030501 8305250402	50-259 50-259
CHILK.8.J	8305110581*	PR	CLARKIR A. CLARKIR, A	#051040120# #04104060E8	50-338 50-338	P P	COFFMAN, F. D COGAN, N	8305090407* 8305250505*	50-445 (50-289 (
CHILK: 8. J. CHILK: 8. J.	8305120309 8305130055	50-247 Q 70-143	CLARK, R. A	8303040466	50-344 50-344	P P	COGAN, N J	8305230460*	20-289 (
CHILK, B. J.	19005120061	50-277 Q	CLARK, R A	8305040647*	50-344	P	COHEN, L A	B305090425 B305310239*	50-247 50-309 }
CHILK: B. J. Chilk: B. J.	8305130068 8305160130	50-322 9 50-289 9	CLARK, R. A CLARK, R. A	9305060670* 8305090144	50-338	P	COLBURN, T Q	8305120495	50-266 . CONTRACT
CHILK, 8 J.	8305160167 8305170488	50-247 Q 40-2061	CLARKIR A CLARKIR.A	8303070440* 8305070546	50-245 50-266	P P	COLEMAN, R COLEMAN, R	8305090291 8305110229	CONTRACT
CHILK, B. J. Chilk, B. J.	8305170493	50-272 Q	CLARK, R A	8305110128	50~335	P	COLEMAN, R C	8305260081	CONTRACT
CHILK, B J	8305180148*	50-498 A	CLARK, R A	8305110169* 8305110173	50~368 50~313	P	COLEY, J L COLEY, J L	8305270179* 8305270276*	50-389 t
CHILK: 8. J. Chilk: 8. J	8305180167* 8305180189*	50-498 Q 50-498 Q	CLARKIR A CLARKIR A	8305110199#	50-313 50-313	P P	COLEY, J. L COLEY, J. L	8305270342* 8305270457*	50-324 c 50-390 c
CHILK, B. J CHILK, B. J.	8305200481, 8305200488	50-373 0 50-528 0	CLARK, R. A. CLARK, R. A.	8305110205* 8305110224*	50-334	P	COLLIER, A R	0305170302	TOPREP
CHILK, B. J.	8305200525	50-358 0	CLARK, R A.	8305110540	50-266	F	COLLING, D. J	8305110267*	50-277 4
CHILK, S. J.	8305200548 8305200554	50-155 9	CLARK, R. A. CLARK, R. A.	8305110625 8305120153*	50-313 50-335	P P	COLLINS, D. L COLLINS, J T	8305270035# 8305030435#	50-320 . 50-285
CHILK, B. J. CHILK, B. J.	8305200560	50-277 Q	CLARKIR A CLARKIR A	8305120498* 8305120504	50-246 50-313	P P	COLLINS, J T.	8305060466	State Pro
CHILK, B. J	8305200570	40-2061		8305120506*	50-313	P	COLLINS, J. T COLLINS, J. T.	8305090479 8305100086	QA999 State Pro
CHILK: 8. J. CHILK: 8. J.	8305230425# 8305240190#	COMMISSION COMMISSION	CLARK, R. A CLARK, R. A	8305130010	50-338	P P	COLLINB, J. T COLLINB, J T	8305100303 8305120035*	30-482 FOIA
CHILK, 8 J. CHILK, 8 J.	9305240522 9305240523	50-361 0 50-247 0	CLARK, R. A CLARK, R. A.	8305130017* 8305160188	50-338 50-213	P	COLLINS, J T	8305120045*	FOIA
CHILK, B. J.	9305240566	50-3 T	CLARK, R. A.	8305140201	50~309	P 	COLLINS, J T	B305120052*	FOIA
CHILK, B. J.	8305230256	10CFR	CLARK, R. A. CLARK, R. A.	9305170259* 8305170612	50-317 50-309	P P	COLLINS, J. T COLLINS, J. T	8305120054*	FOIA
CHILK, B, J. Chilk, B, J.	8305250308* 8305250324	GEN TEC IS 50-287 0	CLARK, R. A.	8305170619 8305170622	50-301 50-313	P P	COLLINS, J. T COLLINS, J. T	8305120065* 8305170374*	FOIA (
CHILK, B. J. Chilk, B J.	8305250570* 8305260174	50-289 P 50-397 0	CLARK, R. A CLARK, R. A	8305170657	50-282	F	COLLINS, J. T	8305200285	50-382
CHILK, B. J.	8305240176	50-498 0	CLARK, R. A.	8305180036*	84E-08	P F	COLLING, J. T COLLING, J. T.	8305200320 8305240431	State Pro
CHILK, B. J. CHILK, B. J.	8305240178 8305310008	50-556 9 50-272 9	CLARK, R. A. CLARK, R. A.	8305180161 8305180567	50-313 50-335	P	COLLINS, J. T	8305270144	QA999
CHILK, 8, J.	8305310011	50-445 Q	CLARK, R. A. CLARK, R. A.	9305190579* 9305190949	50-317 50-313	P P	COLLINS, B.	9305200497	50-272
CHILK, B. J.	8305310015	50~498 Q	***************************************						į

	ACCESS I DN	SUBJECT			ACCESSION	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	′
AUTHOR COLLINGS J COLLINGS T R COLLINGS T R COLLINGS T R	NUMBER 	50-27 @ 50-327 @ 50-327 @ 50-369 @ 50-269 @		AUTHOR COOPER, W E COPELAND, V G CORMIER, W CORMIER, H H	NUMBER 8305270317 8305110141 8305170067* 8305030524	50-275 50-155 50-142 50-142		COUNBIL, H 0 COUNBIL, H 0 COUNBIL, H 0 COUNBIL, H 0 COUNBIL, W 0	8305250565* 8305270036 8305270036 8305270037* 8305270037*	50-423	9 8 9 0
COLLINS, T R COLLINS, H E COLOMBO.R H COLOMBO.R H COLOMBO.R H	830526030B 8305240326 8305030270* 8305030561* 8305130231*	50-129 W 50-312 R 50-312 S 50-312 S 50-312 S		CORMIER, W H CORMIER, D	6305030548 6305030574 6305090473 6305240479 6305240499 6305250223	50-142 50-142 50-142 50-142 50-142 50-247	00000	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8305270074 8305270074 8305270114 8305270114 8305050321*	50~336 50~336 50~245 50~245 50~395	Q P P
COMBS: F COMBS: F COMBS: F COMBS: F COMBS: F	8305020171* 8305030247* 8305030464* 8305040310* 83050503355*	FOIA 70-378 FOIA FOIA FOIA	1	CORYELL, O P CORYELL, O P CORYELL, O P CORYELL, O P CORYELL, O P	8305130173 8305270304* 8305270480* 8305270556* 8305270648*	70-143 50-332 70-1151 70-27 70-143	G:	CONCELL M	8305170266* 8305110256* 8305250423 8305060574* 8305060611*	50-219 50-241 50-241 50-249 50-237	6 8 8 8
COMBS.F C COMBS.F C COMBS.F C COMBS.F C	8305020306* 8305020318* 8305030201* 8305040484* 8305110491	FOIA FOIA 70-378 FOIA NUREG		COSS. B H COSTELLO.F M COTTAR E COTTER. B P COTTER. B P	8305190002 8305120423* 8305120074* 8305030548 8305130050	70-2932 40-672 50-358 50-458 50-322	0 0	CRAGIN, J G CRANE, P A CRANE, P A CRANE, P A CRANE, P. A.	8305270317 8305020108 8305030188* 8305030510 8305040320	50-275 50-133 50-275 50-275 50-275	P F F P P
COMPTON, N CONLEY. C H CONLON, T E. CONLON, T E CONLON, T E	8305030437 8305110476 8305260243* 8305270101* 8305270200*	50-389		COTTER, B P COTTER, K H COTTER, K, H COTTER, K, H	8305130110 8305030412* 8305060407* 8305060417* 8305200412*	50~50B 50~284 50~286 50~286 50~286	G P P P	CRANE, P A. CRANE, P A. CRANE, P. A. CRANE, P A.	8305040328# 8305050178 8305060299 8305120042 8305120325	50-275 50-275 50-323 50-275 50-275	P P G P P
CONLON, T E, CONLON, T E CONLON, T E CONLON, T E CONLON, T E	8305270236* 8305270293* 830527034B* 8305270379* 8305270404*	50-389 50-400 50-389	G G G G	COUCH.M J COUNSIL.W O COUNSIL.W O COUNSIL.W O	8305160316* 8304110686 8305020379* 8305030404 8305030404	50-247 50-213 50-213 50-245 50-245	0 0 0 P	CRANE, P A CRANE, P A CRANE, P A CRANE, P A CRANE, P A.	9305120333 9305160172 9305190157 9305240238 9305240375	50-275 50-275 50-275 50-275 50-275	P = = = =
CONLON, T E	8305270415* 8305270420* 8305270542* 8305270551* 8305270618*	50-390 50-369 50-400	Q Q Q Q	COUNBIL, W O	8303030620 8305030620 8305040034* 8305040447	50-245 50-245 50-245 50-336 50-336	P P F P	CRANE, P A CRANE, P A CRANE, P A CRANE, P A CRANFORD, V A	8305260274# 8305270622 8305310130 8305310135# 8305030594	50-275 50-275 50-275 50-275 50-275	90 0
CONLON: T E CONNAUGHTON: K CONNER CONNER: E. L CONRAN: J	8305270432* 8305100176* 8305190072 8305090078 8305050295*	50-454 50-219 50-269	G 0 8 P P	COUNSIL, H G COUNSIL, H G COUNSIL, H G COUNSIL, H G	8303030054 8303030034 8303030054 8303030112 8303030229	50-213 50-213 50-213 50-213 50-245	# P P P	CRAWFORD, V. A CREED, J CREED, J R CREED, J R CREED, J R	8305030594 8305040445 8305270132 8305020397* 8305030521*	50-529 50-331 50-255 50-255 50-264	0 0 0
CONTE, R. CONTE, R. CONTE, R. CONTE, R. CONTE, R. CONMAY, B.	8305030074 8305030534 8305160177* 8305230460* 8305180378	50-289 50-289	6 8 9 9	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8305050229 8305060213 8305060213 8305060244 8305060244	50-245 50-213 50-213 PR PR	P F F	CREED: J. R CREED: J. R CREED: J. R CREED: J. R CREED: J. R	8305060418* 8305100365* 8305100371* 8305130234* 8305200482*	50-295 50-156 50-156 70-1308 70-925	Q: Q:
CONHAY, J T CONHAY, J T CONHAY, J T CONHAY, J. T COOK, Q S.	8305020466 8305050093* 8305200379* 8305270311* 8305160122	0A999 0A999 0A999	G G	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8305060424 8305060424 8305060455 8305060435 8305070404	50-336 50-334 50-423 50-423 50-213	0 9 9	CREWS, J L CREWS, J L CREWS, J L CREWS, J L CRLENJAK, R V	8305030075 8305030200* 8305160089 8305170531 8305270550*	50~361 50~275 50~528 50~528 50~366	9 9 9 9
CBOK' 1 M CDOK' 1 M CDOK' 1 M CDOK' 1 M	8305130134* 8305020378 8305030111 8305060483 8305090052	50-333 50-327 50-327 50-327 50-327	R E R A R	CBUNBIL.W G CGUNBIL.W G CGUNBIL.W G CGUNBIL.W G CGUNBIL.W G	9303090465 9303090465 9303090465 9303090471 9303090471	50-213 50-213 50-213 50-245 50-245	6 6 6 6	CROCKER, H W. CROCKER, H W CROCKER, H W. CROCKER, H W. CROCKER, L P	8305050151# 8305120493# 8305120500# 8305240232# 8305170044#	50-293 40-672 40-672 50-29 50-289	9
COOK' 1 M COOK' 1 M COOK' 1 M COOK' 1 M	8305110305 8305130182* 8305170283 8305170391 8305170409	50-329 50-329 50-329 50-329 50-329	8 9 8	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8305100331 8305100348 8305100348 8305100385 8305110049	50-213 50-245 50-245 50-213 50-213	P P P F	CROCKER, L. P CROSBIE, K. L CROSBIE, K. L CROSBAN, W. A.	8305230460# 8305230026 8305230035# 8305120250# 8305050163#	50-287 70-1359 70-1359 50-281 50-458	a P a
COOK'N M COOK'N M COOK'N M COOK'N M	8305170440 8305170489 8305170539 8305200349 8305200680	50-329 50-329 50-329 50-329 50-329	5 6 8 8	COUNSIL, W O COUNSIL, W, O	8305110574* 8305110574* 8305110574* 8305110574* 8305120241	50-213 50-213 50-213 50-336 50-336	F F F P	CROBBMAN, W. A CROBBMAN, W. A CROBBMAN, W. A CROBBMAN, W. A CROUBE, R. P.	8305100142* 8305170009* 8305170224* 8305230314* 8305040305	50-458 50-382 50-478 50-456 50-344	0 0 0 0
COCK' A M COCK' A M COCK' A M COCK' A M	8305240008* 8305240010 8305240365* 8305260218 8305260235	50-327	0 8 P 8	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	6305160183 8305170213 8305180268 8305180268 8305180304	50-213 50-213 50-245 50-245 50-245	다 다 다	CROUSE: R P. CROUSE: R. P. CROUSE: R. P. CROUSE: R. P. CROUSE: R P.	8303040472 8305040491 8305040497# 8305060395 8305060519	50~346 50~346 50~346 50~346 50~346	P P D
COOK, J H COOK, J H COOK, J H COOK, J H COOK, J H	8305240309 8305240324 8305270057 8305270043* 8305100217	50~330 50~329 50~329 50~329 50~329	8 8 K K T	COUNSIL, H C COUNSIL, H C COUNSIL, H C COUNSIL, H C	8305180304 8305190305 8305200441 8305200533 8305200533	50-245 50-213 PR 50-423 50-423	P Q 8 8	CROUBE, R P. CROUBE, R P CROUBE, R. P. CROUBE, R. P CROUBE, R P	8305110385 8305110437 8305130032 8305170462 8305180411	50-346 50-346 50-346 50-346 50-346	ь ь ь
C M YANGOO L M YANGOO L M YANGOO L M YANGOO L M YANGOO	8305110316 8305110340 8305110347* 8305120358 8305120473	50-277 50-278 50-278 50-277 50-277	S S S S	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8305200587 8305230323 8305230323 8305230508 8305230508	50-423 50-245 50-245 50-336 50-336	A F F P	CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P.	8305200337* 8305200514* 8305200520* 8305200527* 8305200592	50-346 50-346 50-346 50-346 50-346	0 0 0 P
COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8305050279 8305180395 8305200358 8305270296 8305270305	50-275 50-275 50-275 50-275 50-275	R R R P	COUNSIL, H O COUNSIL, H O COUNSIL, H O COUNSIL, H O	8305230616 8305230616 8305230616 8305250510 8305250510	50-213 50-213 50-213 50-213 50-213	P P P P	CROUSE.R.P. CROUSE.R.P. CROUSE.R.P. CROUSE.R.P. CROUSE.R.P.	8305230716 8305240072* 8305240251 8305240351 8305240423	50-346 50-346 50-346 50-346 50-346	POFF

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	BUBJECT CATEGOR'
GROUSE, R P GROUSE, R P GROUSE, R P GROW, W T GROW, W T	8305260241 8305260245# 8305260303 8305030074 8305110117	50-346 P 50-346 P 50-346 G 70-1257 40-8035	CURTIS.N W CURTIS.N W CURTIS.N W CURTIS.N W CURTIS.N W	8305030153* 8305060543 8305100308 8305110097 8305130114	50~397 50-397 50-397	- P G P K P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8305270561 8305270565 8305270566 8305270570 8305270570	50~335 50~280 50~251 50~321 50~413
CROWDER, J D CROWE, J CROWE, J CROWLEY, B, R CRUTCHFIELD, D	8305190029# 8305250372# 8305250372# 8305270339# 8305020060	50-293 S 50-493 Q 50-493 Q 50-335 Q 50-244 P	CURTIS,N W CURTIS,N W CURTIS,N W CURTIS,N W CURTIS,N W	8305180646 8305190285 8305190295 8305190319 8305230541	50-387 50-387	P P S P	DANIELS,R C DANIELS,R C DANIELS,R C DANIELS,R C DANIELS,R C	8305020031* 8305020042* 8305030125* 8305030142* 8305030147*	FOIA FOIA FOIA FOIA
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305020044 8305020121 8305020497 8305040144 8305040312	50-255 P 50-245 P 50-244 P 50-155 P 50-255 P	L'INTERPO H L'INTE	8305270064 8305310208 8305020477 8305030526 8305090487	50-387 50-440 50-440	P G T G	DANIELS, R. G DANIELS, R. G DANIELS, R. G DANIELS, R. G DANIELS, R. G	0305030154* 9305030174* 9305030179* 0303040279* 8305040554*	FOIA FOIA FOIA FOIA
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305040474 8305040488 8305040526 8305040537* 8305040540*	50-219 P 50-237 P 50-29 P 50-155 0 50-155 0	CUTCHIN, J H D'AMORE, M D'AMOURS, N E DALE, L F DALE, L F,	8305100168 8305270459* 8305130087 8304190378 8305110275	70-1151 50-443 50-416	9 9 9	DANIELS,R G DANIELS,R G DANIELS,R G DANIELS,R G DANIELS,R G	B305040562* B305050297* 8305050306* 8305050316* 8305050322*	FOIA 70-378 70-378 70-378 70-378
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305040228* 8305040234* 8305040372 8305040381* 8305040385*	50-206 P 50-206 P 50-206 P 50-206 P 50-206 P	DALE, L. F.	8305110418 8305170015 8305240143 8305240265* 8305240496	50-416 50-416 50-416 50-416 50-416	8 J P P	Daniels, R. G Danielson, D H Danielson, D H Danielson, D H Danielson, D H	8305050330* 8304150364* 8305020360* 8305120348* 8305120420*	70-378 50-440 50-331 50-461 50-373
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305090424 8305090436* 8305090463* 8305090488 8305090491*	50-245 P 50-245 P 50-245 P 50-213 P 50-213 P	DALTROFF, S L DALTROFF, S L DALTROFF, S L DALTROFF, S L DALZELL, G W	8303020077 8303030027# 8305170401 8305240428 8303240517	50-277 50-277 50-277 50-277 50-247	P P P H	DANIELSON, D H DANIELSON, D H DANIELSON, D H DAVIS, A B	8305120449* 8305190027* 8305190183* 8305190233 8305190184*	50-237 50-454 50-255 50-454 50-373
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305090492* 8305110009 8305110049 8305110059 8305110067	50-213 P 50-219 F 50-29 F 50-204 F 50-155 F	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8305030374 8305130138 8305200430 8305200556 8305270078	50-491 50-321 50-335 50-369 50-389	8 8 9 9	DAVIS, A B DAVIS, A B DAVIS, A B DAVIS, F X. DAVIS, F X	8305170232* 8305170276* 8305170377* 8305170314 8305170317	FOIA FOIA 50-373 50-454 50-454
CRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305110074 8305120114 8305120370 8305140022 83051400250	50-255 F 50-10 F 50-297 P 50-213 F 50-155 G	DANCE: H C DANCE: H C DANCE: H, C DANCE: H, C DANCE: H C	8305270112 8305270146 8305270154 8305270176 8305270177	50-302 50-369 50-349 50-389 50-537	9 9 0	DAVIS.F X DAVIS.F X DAVIS.J Q DAVIS.M J DAVIS.M J	8305170334 8305170522 8305200634* 8305270437* 8305270470*	50-454 50-454 REVIEW G 50-280 50-280
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305170367 8305170416 8305180292 8305180433 8305190016	50-155 F 50-409 F 50-155 P 50-219 P 50-409 F	DANCE, H. C.	8305270207 8305270215 8305270232 8305270238 8305270240	50-302 50-250 50-387 50-338 50-387	Q Q Q Q	DAVIB,PR DAVIS,PR DAVISEON,MT. DE AGAZIO,AW DEANDA,L	8305160246 8305160246 8305160332* 8305170667 8305200656	50-295 50-295 50-367 50-346 50-440
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305200200 8305200452 8305230276 8305240490 8305260082	50-255 Q 50-407 9 50-213 P 50-27 P 50-407 P	DANCE, H C	8305270242 8305270247 8305270252* 8305270260* 8305270273	50~280 50~302 50~280 50~302 50~537	G O O	DEB, A K DEBBAGE, A G DEBGER, T K DEBS, B. T. DEBS, B T	8305170116 8305270356* 8305180810 8305270384* 8305270668*	40-6500 50-321 PROJ 50-250 50-259
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D,	8305270002 8305270007 8305270040 8305270077 8305310028	50-407 P 50-255 F 50-244 P 50-244 F 50-297 P	DANCE, H. C.	8305270287 8305270289 8305270310 8305270314 8305270320	50-335 50-389 50-389 50-337 50-424	a a a a	DEIGL:H J DEIGL:H J DELANEY:J C DELANEY:J C DELGAIZD:T J	8305180626 8305230697 8305030301* 8305050335* 8206300177*	71-5407 71-5407 70-378 70-378 50-309
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8305310046 8305310108 8305310150 8305310213	50-235 F 50-217 P 50-206 8 50-219 P NUREO	DANCE, H C DANGE, H C DANGE, H C, DANGE, H, C,	8305270324 8305270326 8305270327 8305270329 8305270330	50-413 50-267 50-369 50-335 50-424	0 0 0 0	DELMEDICO, J. DELMEDICO, J DELOATCH, V DELOATCH, V DEMPPAINEN, M	8305110030* 8305180258* 8305090009 8305090122 8305240015	NUREG FDIA CONTRACT CONTRACT NUREG
Cullen, W. H. Culver, M. H. Cuminos, E. Cuminos, J. Cuminos, J. Cuminos, J. J.	8305240015 8305130047* 8305200578 8305240247* 8108250739* 8305180178*	50-302 R 50-440 9 50-358 9 COMMISSION FOIA	DANCE, H. C.	9305270332 8305270343# 8305270347 8305270350 8305270359	50-321 50-321 50-302 50-321 50-335	G G G	DENISON, E DENISON, E DENISON, E DENNIS, N	8305030573 8305030581* 8305180417 8305230224* 8304110176	50-275 50-275 50-275 50-275 1&E
CUMMINOS.J.J. CUMMINOS.J.J. CUMMINOS.J.E. CUMMINOMAM.A L. CUMMINOMAM.A L.	8305180178* 8305240263* 8305270354* 8305270528* 8305020050	50-358 Q 50-313 Q 50-302 Q 50-259 Q 70-1007	DANCE, H. C.	8305270374 8305270374 8305270382* 8305270385 8305270393	50-269 50-250	0 0 0 0	DENTE, T. J DENTON, H DENTON, H R. DENTON, H R DENTON, H R	8305100197 8305120407 8203180052* 8204190027* 8305020573	TDPREP MISC 50-206 50-206 50-447
CUNNINGHAM, G E. CUNNINGHAM, G E. CUNNINGHAM, G H. CUNNINGHAM, R. CUDMO, M. M. CUDMO, M. M.	8305020050 8305100214 8305100207* 8305130204* 8305310070*	70-754 50-409 G FOTA 50-322 G 50-247 U	DANCE, H. C.	8305270403 8305270414 8305270423 8305270435* 8305270447	50-269 50-338 50-280	G G G	DENTON, H R DENTON, H R DENTON, H R DENTON, H- R DENTON, H R	8305030019* 8305040056 8305040138 8305040534 8305040536*	50~3B9 50-144 50~2B9 50-155 50-155
CURRAN, D. CURRAN, D. CURRAN, D. CURRAN, D. CURRAN, D.	83053310070# 8305330070# 8305340002 8305340002 8305340019	50-443 Q 50-443 Q 50-443 Q 50-443 Q 50-443 Q	DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, M. C. DANCE, M. C.	8305270449* 8305270456 8305270472 8305270483 8305270491	50-395 50-302 50-537 50-280 50-346	0 0 0 0	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8305040625 8305040727 8305090244 8305090295 8305110423*	50-155 50-317 50-272 MISC REVIEW GR
CURRAN: D CURRAN: R. N CURRAN: R. N CURTIB: N. W CURTIB: N. W.	8305180343 8305200437# 8305200491# 8305020387 8305030144	PR 50-373 P 50-373 P 50-387 P 50-387 P	Dance, H C Dance, H C. Dance, H C. Dance, H C.	8305270497 830527051 1 8305270517 8305270523* 8305270530	50-269 50-369 50-338 50-366 50-338	0 0 0 0	DENTON, H R.	8305110428* 8305110432* 8305170064 8305170085* 8305200204*	REVIEW GRI 50-272 50-272 NUREG

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
DENTON, H R DENTON, H R DENTON, H R DEUTSCH, H J DEVIENCE, A	8305230189 8305240216 8305240220* 8305060233 8305070285	50-320 T 50-289 G 50-289 O NUREG 50-366 A	DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R	8305030612 8305050143 8305050201 8305050242 8305050265	50-324 8 50-325 8 50-325 8 50-324 8 50-324 8	DIXON, O W DOBEL, H F DODDS, R T DODDS, R T DODDS, R T	8305270441 * 8305270537 8305170349 * 8305170381 * 8305170387 *	50-395 Q 50-356 J 50-397 Q 50-397 Q 50-508 Q
DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J	8305050006 8305050006 8305160037 8305190164 8305190164	50-443 F 50-443 F 50-443 8 50-443 8 50-443 8	DIETZ.C R. DIETZ.C R. DIETZ.C R. DIETZ.C R. DIETZ.C R.	8305100412 6305110282 8305130108 9305130167 8305130170	50-324 R 50-325 8 50-325 8 50-324 8 50-324 8	DODDS,R T DODDS,R T DODDS,R T DOERFLEIN,L T DOIRON,D Q	8305170390* 8305170439* 8305170498* 8305110391* 8305060251*	50-508 Q 50-397 Q 50-508 Q 50-333 Q CONTRACT
DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J	8305200353 8305200353 8305200402 8305200402 8305250244	50-443 8 50-443 8 50-443 5 50-443 8 50-443 8	DIETZ.C R DIETZ.C R DIETZ.C R. DIETZ.C R. DIETZ.C R.	8305130177 8305200538 8305270256* 8305270531 8305270588*	50-324 8 50-324 8 50-324 0 50-324 0 50-324 0	DOMENICI, P V DONAHUE, J F DONAHUE, J F DONAHUE, J F DONAHUE, J F	8305180123* 8305230134* 8305230139* 8305230179* 8305230186*	FOIA 70-1193 70-1193 70-1193 70-1193
DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J DEVINE. A DEVINE. H F	8305250244 8305270017 8305270017 8305200598 8305230029	50-443 8 50-443 A 50-443 A 50-440 0 50-407 J	DIEYZ.C R DIETZ.C R DIETZ.C R DIGOS.R M DIGOS.R M	8305270579* 8305270610* 8305270617* 8305030014 8305040084	50-324 0 50-324 0 50-324 0 50-395 P 50-328 P	DONNELLY, P M DONNELLY, P M DOOLITTLE, E L DORDSHOW, J DORDSHOW, J	8305270451* 8305270460* 8305250185 8305180369 8305200469	50-331 B 50-331 B 50-423 A PR 50-289 0
DEVINE. J B DEVINE. J B DEVINE. T DEVINE. T DEVINE. T	8305060687 8305130273 8305190097* 8305190124* 8305190292*	XPORTLIC XPORTLIC 50-327 G 50-373 G 50-373 G	Diggs.R M Diggs.R M Diggs.R M Diggs.R M Diggs.R M	8305040545 8305040547 8305060638 8305090359 8305180791	50-387 P 50-244 Q 50-312 P 50-315 P 50-369 P	DOROBHOW, J DOROBHOW, J DORBEY, M DORBEY, M DORBEY, M	8305240444 8305240449 8305200042 8305230287	50-289 Q 50-289 Q CONTRACT CONTRACT CONTRACT
DEVINE, T DEWEY, L S DEWEY, L S DEWEY, L S DEWEY, L S	8305190304* 8305030498 8305110248 8305270024 8305310074	50-373	DIGOS,R M DIGOS,R M DIGOS,R M DIGON,T G	8305200185 8305260379 8305260381 8305310224 8305040300	50-237 P 50-273 P 50-387 P 50-375 P 50-443 Q	DOUGHERTY, D J DOUGHERTY, J B DOUGHERTY, J B DOUGHERTY, J B DOUGHERTY, J	8305250034* 8305130072 8305130072 8305180341 8305180344	FDIA 50-322 0 50-322 0 PR PR
DEWITT, R B DEWITT, R B DEWITT, R B DEWITT, R B DEWITT, R A	8305020079 8305100287* 8305200218 8305240565* 8305180425	50-255 F 50-255 P PR 50-155 P PR	DIGNAN, T O DIGNAN, T O DIGNAN, T O DIGNAN, T O DIGNAN, T O	8305040300 8305040316 8305040533 8305040533 8305310147	50-443	DOULOS, N DOYLE, J DOYLE, J DOYLE, J DOYLE, J.	8305030268# 8305230572# 8305020444# 8305040515# 8305040535	70-378 50-482 I 50-445 Q 50-445 T 50-445 T
DEYOUNG, R C DEYOUNG, R C DEZUTEL, C Z DI GIACOMO, C G DIAB, S	8305030449 8305120145 8305190112* 8305240554 8305090618*	50-483 0 50-445 0 50-329 S 50-247 T 50-445 0	Dignan, T. G Dimeglio, A F Dimeglio, A F Dircks, H Dircks, H, J	8305310147 8305240384 8305250445 8305090290* 8302280090	50-443	DOYLE, J. DOYLE, J DRAGUNETTE, K B DRAIN, D. T DRAIN, D. T.	8305110354 8305130157 8305120527* 8305120041* 8305120065*	50-445 T 50-445 T 40-672 FOIA FOIA
DICEY, B B DICEY, B B DICEY, B B DICK, G F DICK, G F	8305180010* 8305180052* 8305180159* 8305110424 8305180340	FDIA FDIA FDIA 50-244 P 50-244 P	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J.	8304220083 8305020530 8305040054 8305060700* 8305090279	BECY 50-320 P 50-289 G 10CFR MISC	DREY, K DRISKILL, D, D DRUGA, R J DRUGA, R, J DRUGA, R, J,	8304180420* 8305200254* 8305030316* 8305110353* 8305120411*	MISC 50-392 6 50-334 8 50-334 8
DICK, G F DICK, G F DICKEY, F DICKHONER, H H DICKINSON, A C	8305180361 8305260237 8304180513* 8305170170 8305030447*	50~244 F 50~244 P 50~311 S 50~358 A 50~219 S	DIRCKS.W J. DIRCKS.W J. DIRCKS.W J. DIRCKS.W.J.	8305070504 8305070512 8305110024 8305170078* 8305170232	50-289 Q 10CFR Waste Mot 50-958 A 50-272 S	DRUGA, R. J DRUGA, R. J DRUMHOND, F. J DRUMHOND, F. J DRUMHOND, F. J	8305140064* 8305190309* 8305200542 8305270138 8305270147	50-334 8 50-334 8 50-382 8 50-382 8 50-382 8
DICKINSON, J D DIECKAMP, H DIECKAMP, H DIEDERICH, & J DIEDERICH, & J	8305170307* 8305020465* 8305230402 8305240318 8305020086	TGPREP 50-217 I 50-217 P 50-373 B 50-373 8	Dircke, H J. Dircke, H J. Dircke, H J. Dircke, H J.	8305180153* 8305180322* 8305180328* 8305200198 8305200427*	FOIA FDIA 50-237 P NUREG REVIEW GRP	DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DUBOIB, D, DUBRY, N	8905270194 8905270373 8905310094 8905200344 8905020348*	50-382 8 50-382 8 50-382 £ 50-298 8 50-315 q
Diederich, G J Diederich, G J Diederich, G J Diederich, G J Diederich, G J	8305020109 8305020205 8305020241 8305020351 8305040365	50-373 8 50-373 8 50-373 8 50-373 8 50-373 R	DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J.	8305230070* 8305230639 8305240019 8305240075 8305240213	FOIA NUREG 50-537 U COMMISSION 50-275 F	DUBRY, N. E DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R.	8305240309* 8305030379 8305040180 8305040186 8305040202	50-315 0 50-389 J 50-348 J 50-335 J 50-321 J
DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8305060398 8305060493 8305110447 8305170374 8305170383	50-373 8 50-373 8 50-373 R 50-373 B 50-373 B	DIRCKS,W J. DIRCKS,W J. DIRCKS,W J. DIRCKS,W J. DIRCKS,W J.	8305240457* 8305250162 8305250228* 8305250230 8305250311	50-289 Q 50-358 R 50-361 P 8ECY COMMISSION	DUCK, J. R. DUCK, J. R. DUCK, J. R DUCK, J. R DUCK, J. R	8305040204 8305040208 8305040243 8305160005 8305190022	50-302 J 50-327 J 50-259 J 50-302 J
DIEDERICH, O J DIEDERICH, O J DIEDERICH, G J DIEDERICH, O J DIEDERICH, O J	8305240007 8305240025 8305240073 8305240229 8305240334	50-373 8 50-373 8 50-373 8 50-373 8 50-373 8	M.O.NOXIO DIRCKS, W.J DIRCKS, W.J DIXON:O. W DIXON:O. W	8305250588 8305270118 8305310238 8305030627 8305050057	50-287 P 8ECY 50-307 H 50-395 8 50-395 8	Duck, J. R Duck, J. R Duggan, J. Q. Duggan, J. Q Duggan, J. Q	B305200270 B305230027 B305160004 B305160258 B305160261*	50-321 J 50-321 J 40-7580 40-7580 40-7580
DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	B305240354 B305240381 B305240425 B305270195 B305270237	50-373 6 50-373 8 50-373 8 50-373 8 50-373 8	DIXON, O. W DIXON, O. W DIXON, O. W DIXON, O. W	8305050233 8305050317* 8305060619 8305100089 8305100301	50-395 8 50-395 F 50-395 P 50-395 B 50-395 P	DUGSTAD, D DUNAWAY, F R DUNCAN, P, S, DUNLAP, J M, DUNN, W L	8305160076* 8305100271* 8305060536* 8305170313* 8305310157*	50-282 R 50-295 G 50-352 A 50-271 G 50-244 P
DIETZ.CR DIETZ.CR DIETZ.CR DIETZ.CR DIETZ.CR DIETZ.CR	8305030291 8305030355 8305030387 8305030411 8305030445	50-324 8 50-324 8 50-324 8 50-324 8 50-325 8	DIXON, D W DIXON, D W DIXON, O, W DIXON, O, W DIXON, O, W	8305180373 8305180442 8305180445 8305200311 8305200510	50-395 F 50-395 P 50-395 G 50-395 G 50-395 8	DUNNING, T, G. DUNNING, T G DUPONT, B G DUPREE, D. DURDEL, R	8305090625* 8305090646* 8305170403* 8305240323 8305060608*	50-445 0 50-445 0 50-373 0 50-327 R 50-346 F
DIETZ,CR DIETZ,CR DIETZ,CR DIETZ,CR DIETZ,CR	8305030497 8305030505 8305030512 8305030530 8305030540	50-324 8 50-325 8 50-324 8 50-324 6 50-324 8	DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8305200513 8305200626 8305250349 8305250492 8305270422*	50-395 E 50-395 8 50-395 8 50-395 P 50-395 Q	DURR, J. DURR, J. DURR, J. P. DURR, J. P DURR, J. P	8305050147* 8305250507* 8305110338* 8305250275* 8305250575*	50-277 q 50-286 q 50-289 q 50-219 q 50-387 q

AUTHOR	ACCESSION NUMBER	CATEGOR	<u>′</u>	AUTHOR	ACCESSION REMUN	CATEGORY	<u>′</u>	AUTHOR	NUMBER	50-528
DUTTON, D E DUVALL, D D DUVALL, D D DUVALL, D D DUVALL, D D	8305050086 8305110324 8305200395 8305200415+ 8305200422*	50-424 50-269 GA979 GA999 GA999	A 8	EDGAR, Q L EDGAR, G L EDGAR, G L EDGAR, G L EDGAR, G L	8303240374 • 8305110220 8305120313 8305190339 8305200636	50-537 50-537 50-537 50-537 50-537	6 6 6 6	ELIN, J O ELLIOTT, C W ELLIOTT, N R ELLIOTT, N R	8305170537* 8305070478 8305240541 8305240546 8305270583	50-352 50-247 50-247 50-247
DWYER, P W DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8305200552 8305050005* 8305050005* 8305070136* 8305240548	TBPREP 50-322 50-322 50-322	G G G	EDOAR, G L EDOAR, G. L EDOAR, G L EDOAR, G L EDOAR, G L	8305200648* 8305240475 8305240480 8305240503 8305210188	50-537 50-537 50-537 50-537 50-537	0 0 0 G	ELLIS, J ELLIS, J ELLIS, J ELLIS, J	821230009 8305020422 8305020430* 8305020437* 8305040296	50-445 50-445 50-445 50-445 50-445
DYNNER, A R DYNNER, A R DYNNER, A R DYBON, J B EAPEN, P	8305240548 8305310063 8305310063 8305230597 8305110508*	50-322 50-322 50-322 50-266 50-333	0 0 0 P	EDGEWORTH, P EDISON, G E EDLER, S K EGER, K J EGLE, D M	8305120513 8305250231 8305110208 8305240034 8305250478	CONTRACT 50-4B2 NUREG 70-1301 50-112	Е	ELLIB, J ELLIB, J ELLIS, J ELLIS, J	8305040499 8305040507 8305040513 8305090443 8305110137	50-445 50-445 50-445 50-445 50-445
EAPEN, P EAPEN, P K EAPEN, P K EAPEN, P K EAPEN, P K	8305250443* 8305250230* 8305250314* 8305250465* 8305250504*	50-245 50-286 50-309 50-336 50-213	Q Q Q Q	EICHBAUM,W M EICHBHAEDT,C L EINBEL,D W EINBEL,D W	8305060289 8305160142* 8305190112* 8305040175* 8305040189*	PR 50~227 50~327 FO1A FO1A	g S	ELLIS, J ELLIS, J ELLIS, J	8305110332 8305110347 8305110357 8305110348 8305110397	50-445 50-445 50-445 50-445 50-445
EARLEY, A. F EARLEY, A. F EARLEY, A. F EARLEY, A. F EARLEY, A. F	8305030557 8305050024 8305050024 8305050029* 8305050029*	50-322 50-322 50-322 50-322 50-322	G T T T	EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G	8210190253 8303040044 8305020455 8305030010 8305030016	10PREP 50~275 50~3 50~3P5 50~3B9	P P F P	ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8305130046 8305130175 8305170287 8305170513 8305180272	50-445 50-445 50-445 50-445 PR
EARLEY, A. F. EARLEY, A F EARLEY, A F EARLEY, A F EARLEY, A F	8305070134* 8305100239* 8305190378 8305190378 8305190382*	50-322 50-322 50-322 50-322	G G G	EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q	8305030191 8305030577 8305040323 8305040549 8305040550	50-275 50-312 50-247 50-329 50-329	Р Р Н Н	ELLIB, J ELSASSER, T ELSASSER, T ELSASSER, T ELSASSER, T C	8305290504 8305140142* 8305250443* 8305020332* 8305050234*	50-445 50-293 50-245 50-57 50-97
EARLEY, A. F EARLEY, A F EARLEY, A F EARLEY, A F EASON, T. D	8305170382* 8305200651 8305310051 8305310051 8305180466*	50-322 50-322 50-322 50-322 50-375	G G G	EIBENHUT.D O EIBENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8305040084* 8305040553* 8305040460 8305060494* 8305070197*	50-317 80-333 50-407 50-361 50-331	F F P F	ELBASSER, T C ELGABSER, T C ELSASSER, T C ELSASSER, T C ELBASSER, T C	8305040027 8305110395* 8305250307* 8305250454* 8305250445*	50-273 50-225 50-213 50-184 50-334
EASTHOOD, D EBERSOLE, J C EBERSOLE, J C EBERSOLE, J C EBERSOLE, J C	8305020547 8305090364 8305130339* 8305240033 8305250074	NUREG ACRS 50-443 ACRS ACRS	A	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	83050 70204 83050 70282 83050 70457 83051 10034 83051 10037	MISC 50-275 50-3 50-331	P P F	ELBASBER: T C ELBABBER: T C ELBEN: M J EMCH: R L EMCH: R L	B305250504* B305270200* B305100414* B305040194 B305070484	50-213 50-184 50-237 50-155 50-155
EBERBOLE, J C EBERBOLE, J C EBERBOLE, J C EBNETER, 8 ECCLESTON, K T	8305250078 8305260008 8305260104 8305250505* 8305040275	ACRS ACRS ACRS 50-289 50-293	Q P	EISENHUT.D.G EISENHUT.D.G EISENHUT.D.G EISENHUT.D.G EISENHUT.D.G	8305110223 8305110513 8305110542* 8305120085 8305120524	50-250 50-289 50-266 50-275 50-128	ь ь ь	EMCH,R L EMCH,R L EMERSON,W EMPEY,D C EMSHWILLER,J R	8305140031 8305310145 8305050069 8305120404* 8305180003	50-155 50-155 50-423 50-410 FOIA
ECCLESTON, K, T ECCLESTON, K T ECCLESTON, K T ECKART, D E ECKEL, J, S	8305040264 8305120163 8305180197 8305170457 8305110491	50-293 50-293 50-293 50-440 NUREG	P P Q	EIBENHUT, D G EIBENHUT, D G EIBENHUT, D, G, EIBENHUT, D, G, EIBENHUT, D G	8305120532* 8305120544* 8305120585* 8305120611 8305130343	50-128 50-128 50-373 50-275 50-382	P P P A	ENOBLOM, M. R ENOELKEN, R H ENOELMANN, R ENOLE, L B ENOLE, L B	8305230104 8305160200* 8305040002 8305060107 8305200707	71-9135 50-312 40-8584 50-338 50-338
ECKERT, R M. ECKERT, T. ECKHARDT, J H ECKHARDT, J H ECONOMOS, N	8305180304 8305110176 8305170361* 8305170537* 8305270244*	PR NUREO 50-361 50-528 50-338	G G	EISENHUT, D Q, EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D, Q,	8305160185 8305160331 8305170233# 8305170649 8305170666#	50-275 50-331 50-361 50-369 50-282	R P P 8 F	EPLER, E P EPPLE, O EPPLE, O EPSTEIN, E EPSTEIN, E	8305090255* 8305250573* 8305250573* 8305120454* 8305120462*	50-272 50-483 50-483 40-672 40-672
ECONOMOB, N EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8305270267* 8305060485 8305110145 8305110222 8305110361	50-302 50-400 50-400 50-400 50-400	G O O O	EIBENHUT, D G EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D G EIBENHUT, D G	8305170685* 8305180015* 8305180034 8305180058* 8305180097	50-313 50-393 50-267 50-367 50-146	F P P P	EPSTEIN, E EPSTEIN, R ERICKSON, K T ERICKSON, K T	8305120466* 8305270366 8305030646* 8305030646* 8305030646*	40-472 50-247 50-247 50-247 50-247
EDDLEMAN, W. EDDLEMAN, W. EDDLEMAN, W EDELMAN, M. R. EDELMAN, M. R.	8305110366 8305120288 8305170528 8303280057 8305020308	50-400 50-400 50-400 50-440 50-440	0 0 0 A 8	EIBENHUT, D 0 EIBENHUT, D. G EIBENHUT, D, G EIBENHUT, D, G EIBENHUT, D Q	8305180224* 8305180577* 8305180622 8305180702* 8305180790	50-327 50-333 50-275 50-295 50-361	Р Г Н Р	ERNST, M L ESTEY, H P. EURY, L W EURY, L W EURY, L W	8305170596 8305030719 8305020453 8305200009 8305250249	QEN TEC 40-8064 50-261 50-261 50-261
EDELMAN, M. R EDELMAN, M. R EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	8305020500 8305040465 8305040486 8305040496 8305040516*	50-440 50-440 50-440 50-440 50-440	8 8 9 8 T	EISENHUT, D Q EISENHUT, D G EISENHUT, D, G EISENHUT, D, G EISENHUT, D Q	8305180830 8305180836* 8305190046 8305190054* 8305190060*	50-272 50-272 50-397 50-397 50-397	8 8 A A	EVANS, C. A EVANS, J H EVERETT, R J EVERETT, R. J	8305260304* 8305270086* 8305260004* 8304120582 8305030308*	50-298 50-395 71-5552 I&E 70-846
EDELMAN, M, R EDELMAN, M, R EDELMAN, M, R EDELMAN, M, R, EDELMAN, M, R,	8305070490* 8305100013 8305100333 8305100394 8305110300	50-440 50-440 50-440 50-440 50-440	0 8 8 8	EIGENHUT, D. Q EIGENHUT, D. Q EIGENHUT, D. Q. EIGENHUT, D. Q EIGENHUT, D. Q	8305170068* 8305170077* 8305200170 8305200266 8305230206	50-397 50-397 50-382 50-275 50-275	A A G P R	EVERETT, R. J EVERBOLE, R E FAIR, J R. FALCONER, D FALCONER, D	8305060462 8305260004* 8305030474* 8305270338* 8305270411*	40-8084 71-5552 50-483 50-269 50-269
EDELMAN, M. R EDELMAN, M. R EDELMAN, M. R. EDELMAN, M. R EDELMAN, M. R.	8305130236 8305130248 8305170203 8305230106 8305230143	50-440 50-440 50-440 50-440 50-440	9 9 0 E A	EIBENHUT, D Q EIBENHUT, D, Q, EIBENHUT, D, Q EIBENHUT, D Q EIBENHUT, D Q,	8305230216 8305230324 8305230381 8305230704 8305230066	50-275 PR 50-309 50-470 50-275	R A R	FALCONER, J C FALCONER, J C FALLIN, J F FARIS, J. A. FARLEY, J M	9305020425 9305020429* 9305100346 9305060608* 9305240484*	50-443 50-443 PROJ 50-346 50-348
EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R	8305230270 8305250381 8305260267 8305110328*	50-440 PR 50-440 50-244	A E S	EIBENHUT, D Q. EIBENHUT, D Q EL-ABHRY, M. T ELDRINGHOFF, V	8305260149 8305260211* 8305260307 8305250576*	MISC 50-250 50-327 50-483	р В О	FARMAN,R.F FARRAR,D.L FARRAR,D.L FARRAR,D.L FARRAR,D.L	8305200691* 8305020104* 8305020115* 8305040184 8305130144*	50-373 50-10 50-454 50-454 50-373

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY
FARRAR, D L	8305170331 * 8305170425 * 8305200522 * 8305200540 * 8305240308 *	50-374	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8305120007 8305120010 8305120070 8305120095 8305120224	FOIA FOIA 50-358 G FOIA 40-672	FIREBAUGH.L FIBCHER.D FIBCHER.D FIBCHER.D FITZOERALD.J A	8305040260* 8305170015 8305170079 8305170117 8304040391	50-369 8 50-311 P 50-272 P 50-272 P 50-322 U
FARRAR, D L FARRAR, D L FARRAR, D L FARRAR, D L FARRAR, D L	8305240315 * 8305260282 * 8305270193 * 8305270489 * 8305310095	50-373 Q 50-454 Q 50-456 Q 50-454 Q 50-295 Q	FELTON, J M	8305120488 8305120566 8305120576 8305120574 8305130307	50-271 G 50-267 F F01A 50-285 F 50-272 F	FITZGERALD, J A	8305180252 8305180366 8305180430 8305180437 8305180445	50-322 U 50-322 H 50-170 U 50-322 H
FARRAR, D.L. FARRELL, R.E. FARRELLY, T.J. FASANO, A. FAUCONNEAU, G.	8305310117* 8305260334* 8305030531 8305030164* 8305120484*	50-237	FELTON: J M	8305130310 8305160195 8305160255 8305160279 8305160283	50-387 F 50-312 Q 50-312 B 50-387 F 50-367 F	fitzpatrick, b flack, e flack, e flack, e flagg, d. m	8305120468* 8305030405 8305030468 8305090224 8305240544	50-266 0 50-250 8 14E 50-280 0 50-440 0
FAULKENBERRY, B FAULKENBERRY, B FAY, C W FAY, C W FAY, C W	8305240370 8305240373* 8305030275 8305030280* 8305030374	50-275 0 50-275 0 50-301 8 50-301 9 50-266 5	FELTON, J M FELTON, J M FELTON, J, M FELTON, J M FELTON, J M	8305160288 8305160001 8305180005 8305180005 8305180316	50-313 F 50-413 F 50-498 A FOIA 50-237 P	FLANAGAN, D D FLANAGAN, D D FLANNERY, E J FLANNERY, E J FLEENOR, C	8305170208 8305170208 8305200457* 8305200468* 8305060174	50-322 0 50-322 0 GA999 GA999 CONTRACT
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8305030382* 8305030523 8305130009 8305130034 8305140169	50-266	FELTON, J M	8305190005 8305200087 8305230007 8305230028 8305230045	50-329 0 50-320 P 50-458 F FOIA FOIA	FLEENDR.C FLEENDR.C FLEENDR.C FLEENDR.C. FLEIBCHAKER.D.	8305110031 8305110304 8305120513 8305170606 8305060451	CONTRACT CONTRACT CONTRACT CONTRACT 50-275 Q
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8305160171* 8305170252* 8305170263* 8305170226 8305200229	50-266 R 50-266 Q 50-266 Q 50-266 S 50-266 Q	FELTON, J H FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8305230112 8305230215 8305230223 8305230232 8305230246	40-1478 FOIA FOIA FOIA FOIA	FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHMANN, R	8305070438 8305070438 8305200273* 8305200273* 8305270117	50-275 Q 50-275 Q 50-275 P 50-275 P 50-278 B
FAY.C W FAY.C W FAY.C W FAY.C W	8305240131 8305240331 8305240350 8305240379 8305240412	50-266 P 50-301 S 50-301 S 50-266 S 50-301 S	FELTON, J M	8305240087 8305240254 8305240365 8305250027 8305260397	50-373 Q 50-245 P FOIA FOIA 50-358 A	FLEISCHMANN, R FLEISCHMANN, R FLEISHER, I S FLEISHER, I S FLEURY, E R.	8305270184 8305270235 8305050035 8305200405 8305050337*	50-277 8 50-277 8 50-247 9 50-247 9 70-378
FAY.C W FAY.C W FAY.C W FEIERABEND.C D FEIL.R A	8305240497 8305270241 8305270558 8305240061# 8305170439#	50-266 P 50-266 Q 50-266 0 50-282 Q 50-397 Q	FELTZ, D E FERG, D A FERG, D A FERGUSON, R N	8305050252 8305030171 8305030178* 8305050004 8305200637*	50-328 P 50-341 A 50-341 A 50-341 A 50-373 P	FLORY, C A FLYNN, J, D, FLYNN, M, FLYNN, M FLYNN, R M	8305070620 8305070486 8305110537 8305200145 8305020022*	HASTE MOT 50-358 E CONTRACT CONTRACT FOIA
FEITHNECHT.C FELCH.F B FELCH.F B FELTON.J M FELTON.J M	0305030593 0305020425 0305020429* 0304270424 0305020007	50-334 R 50-443 Q 50-443 G 50-313 F 70-378	FERNANDEZ, C FIATARONE, J V FIATARONE, J V, FIEDLER, P B FIEDLER, P B	8209210332* 8305040220* 8305120474* 8305020362 9305030365	50-336 P 40-672 FOIA 50-219 P 50-219 F	FLYNN, R M FLYNN, R M FLYNN, R. M FLYNN, R. M FLYNN, R M	8305030008* 8305030027* 8305030053* 8305030073* 8305030169*	FOIA FOIA FOIA FOIA
FELTON, J M	8305030074 8305030104 8305030180 8305030214 8305030231	50-275 F 50-275 F 50-275 F 50-282 F 50-387 F	FIEDLER, P B	#305030441 #305050022 #305110374 #305160023* #305170558	50-217 S 50-217 F 50-217 P 50-217 Q 50-217 P	FLYNN, R M FLYNN, R. M FLYNN, R. M FLYNN, R. M. FLYNN, S. F.	8305030335* 8305040237* 8305040573* 8305040583* 8305240446	70-378 F01A F01A 70-378 50-400 ©
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8305030685 8305030693 8305040007 8305040022 8305040069	50-321 F 50-287 F 50-305 F 50-245 F 50-454 F	FIEDLER, P B FIEDLER, P B FIEDLER, P B FIELD, J A FIELDS, H C	8305200500 8305230436 8305270082 8305200002 8305030637*	50-219 G 50-219 R 50-219 P CONTRACT 50-295 B	FLYNN.8, F. FLYNN.8, F FOLEY, T FORD, J 1. FORD, J. T	8303240551 8305250489 8305100433* 8305030001 8305050100	50-400 @ PR 50-247 @ 71-6294 70-1201
FELTON, J M	8305040235 8305040259 8305040575 8305040584 8305040614	50-3 F 50-315 F 50-320 F 50-369 F 50-285 F	FIELDS, H C FIELDS, J A FIELDS, J A FIELDS, J A FIELDS, J A	8305050061* 8305050400 8305060341 8305060377 8305110233	50-395 B CONTRACT CONTRACT 50-329 A CDNTRACT	FORD, J T FORD, J T FOREMAN, H FORTUNA, R. A FORTUNA, R. A	8305050205 8305240376 8305270434 8305180233* 8305180263*	70-1201 70-1201 50-382 0 FOIA
FELTON, J M	8305040628 8305040648 8305050285 8305050300 8305050311	50-257 F 50-321 F 50-387 F 50-289 F 50-395 F	FIELDS, J A FIELDS, J A FIEND, D FIEND, D FINAMORC, B A	8305140318 8305170504 8305020524 8305070532 8305030502	50-347 A CONTRACT TOPREP TOPREP 50-537 Q	FORTUNA, R A, FORTUNA, R A FORTER, D O FORTER, D O FORTER, E R,	8305180285* 8305180291* 8305100161 8305230452 8305270089	FOIA FOIA 50-424 8 50-424 B 50-336 8
FELTON, J M FELTON, J. M FELTON, J M FELTON, J M FELTON, J M	8305050377 8305060073 8305060112 8305060123 8305060135	50-320 F 50-206 P FOIA FOIA 40-672	FINAMORE, B A	8305100210 8305100350 8305100350 8305120291 8305120291	50-537	FOSTER, J. E FOSTER, W. E. FOSTER, W. E. FOSTER, W. E FOURNEY, W. L.	8305170306* 8305030351* 8305030525* 8305240462* 8305110512	FDIA GA999 GA999 GA999 NUREG
FELTON, J M	8305060144 8305060338 8305060575 8305060575 8305060616	FOIA 50-482 F 50-313 F 50-346 F 50-348 F	FINAMORE B A FINDLAY, J A	8305160149 8305160181 8305190221 8305240353 8305050426	50-537 Q 50-537 Q 50-537 Q 50-537 Q NUREQ	FDX: R: R FRAGULA: J: R FRAHM: R FRAHM: R: FRAHM: R:	8905040553* 8905110119 8905060482* 8905060489* 8905110274*	CONTRACT NUREQ 50-272 8 50-311 8 50-311 8
FELTON.J M FELTON.J M FELTON.J M FELTON.J M FELTON.J M	8305040427 8305040473 8305040492 8305090024 8305090241	50-317 F 50-295 F 50-346 F 50-206 H FOIA	FINDLAY, J A FINK, J FINLAYBON, F FINN, J A FINNERAN, J C	8305110176 8305240544 8305110027 8305230137* 8305070525*	NUREQ 50-440 G NUREQ 70-1193 50-445 T	Frahm, r Frahm, r. Frahm, r Frahm, r Frahm, r	8305160057* 8305160102* 8305160123* 8305170370* 8305200397*	50-311 8 50-311 8 50-311 8 50-311 8 50-272 8
FELTON, J M FELTON, J M FELTON, J. M FELTON, J M FELTON, J M	8305090292 8305090306 8305090529 8305090542 8305110549	50-566 A 50-373 0 50-443 F 50-358 T 50-213 F	FIDRELLI, O FIORELLI, O FIORELLI, O, FIORELLI, O FIREBAUGH, L	83051703B2* 8305170564* 8305170045* 8305230139* 8305040246*	50-528 G 50-528 G 50-329 G FOIA 50-369 B	Frahm, R Frahm, R. Francib, E. Francib, E. Frank, L.	8305200546# 8305250501 8305030253 8305030262# 8305190440	50~311 8 50~311 8 40~8728 40~8728 50~244 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
FRANK, L FRANKLIN, E M FREDRICKSON, P FREEMAN, M D FRENCH, J F	8305170462 8305230086* 8305270629* 8305260404 8305240517	50-369 G 71-5607 50-438 G 40-8768 50-247 H	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8305160065 8305170308 8305200341 8305200360 8305200467	50-309 S 50-309 P 50-309 F 50-309 S	GINSBERG.T GIRARD.E H GIVFFRIDA.L D GIVFFRIDA.L D GIVFFRIDA.L D	8305110237 8305270574* 8305060627* 8305230474 8305230470	NUREG 50-280 G 50-247 G COMMISSION 50-3 F
FRENCH, L D FREUDENTHAL, N FREUDENTHAL, N FREUDENTHAL, N FREUDENTHAL, N	8305030597* 8305030273* 8305130363 8305170242 8305250195	50-29 8 40-8728 40-8064 40-8064 40-8102	H L,YTIRRAD H L,YTIRRAD H L,YTIRRAD H L,YTIRRAD H L,YTIRRAD	8305200469 8305200529 8305200578 8305230127 8305230383	50-309 P 50-309 S 50-309 I 50-309 F 50-309 P	GIUFFRIDA,L O GLASS,S M GLASSPIEGEL,H GLEASON,J P GLEASON,J P	8305310047 8305020417 8305040506 8305040464 8305160133	50-247 F 50-247 Q 50-440 T 50-247 Q 50-247 Q
FREUDENTHAL,N FREY,D G FREY,D G FREY,D G FRIZZLE,C D	8305260389 8305060236 8305180330 8305180369 8305130128	40-279 PR PR PR 50-309 P	QARRITY,J H GARRITY,J H GARRITY,J H GARRITY,J H GARRITY,J H	8305230472 8305240264 8305240270 8305250429 8305310047	50-309 8 50-309 P 50-309 P 50-309 G 50-309 G	9 L. Kidbajo C. Kinajo G. Kinajo B.	8305180143 8305160153 8305050189 8305120518* 8305120518*	50-247 G 50-440 G I&E 40-672 40-672
FROUNFELKER: R FROUNFELKER: R FRYE: J H FRYE: J H FRYE: J H	8305240280 8305240290 8305030582 8305060520 8305100330	50-155 J 50-255 J 50-142 G 50-142 G 50-142 G	GARY, R J GARY, R J GARY, R. J GARY, R. J GARY, R. J	8305160138 8305170029 8305200298 8305200419* 8305200674*	50-445 K 70~2932 50-445 S 50-445 Q 50-445 Q	GLENN, J E GLORESEN, H B GLOVER, H S GODDARD, R J GODDARD, R J	8305120507* 8305270614* 8305040606* 8305100404 8305120336	40-672 50-346 G 50-369 F 50-155 G 50-461 G
FRYE, J H FRYE, J, H FRYE, J, H FRYE, J H FRYE, J H	8305130035 8305130074 8305130079 8305130150 8305160143	50-70	Odanek I, 8 Gears, Q Gears, Q. Gears, Q Gears, Q e	8305180424 8305060684 8305170522 8305230318 8305040704	50-247 Q 50-278 P 50-277 F 50-277 P 50-277 P	GODDARD, R. J GODY GODY, A T GODY, A T	8305170552 8305100004 8305110437 8304110176 8304180554*	50-309 G 50-272 B 50-286 S I&E 70-1143
FRYE, J H. FRYLING, R FUHRMAN, G R FUHB, A FULLER, C H	8305260171 8305200067 8305020509 8305260286 8305230427*	50-358 0 50-272 I 50-317 B 50-265 B 50-267 R	GEARS, O. E GEARS, O. E GEHR, A. C GEHR, A. C GEHR, A. C	8305040716 8305180007 8305240482 8305310215 8305310215	50-277 F 50-278 P 50-327 G 50-528 G	ODDY: A T ODDY: A T ODDY: A T ODDY: A T ODDY: A T	8305020457 8305030274 8305050170* 8305120434 8305170313*	50-219 8 50-286 S 50-247 Q 50-272 S 50-271 Q
FULLER.E D FULTON.J F FUNCHES.J L FURBUSH.M H QAD.R.K	8305060160* 8305060277* 8305250305 8305230407 8305040300	FDIA 50-244 P GEN TEG IS 50-133 P 50-443 G	GELMAN, M R GELMAN, M R GELMAN, M R GERDEMAN, F W GERDEMAN, F W	B305030355 B305030355 B305170219 B305040047 B305260418	30-338 Q 30-338 Q 40-7849 40-8698	COLDBERG, J H COLDBERG, J H COLDBERG, J H COLDBERG, J R COLDBERG, J R	8305250056 8305250058* 8305310177 8305050053 8305090481	50-478 K 50-478 A 50-287 G 50-287 G
GADIR K GADIR K GADIR. K GADIR. K GAGE, J	8305040300 8305040314 8305040533 8305040533 8305170207	50-443 Q 50-443 G 50-309 Q 50-309 G 50-440 Q	GERETY, H. F GERGELY, P GETTY, B. C. GIBBONS, T D GIBBONS, T D	8305230037 8305110476 8305170342* 8305270420* 8305270542*	50-219 J NUREO 50-133 S 50-370 Q 50-389 Q	ODLDBERG, J R ODLDBERG, J R OOLDBERG, J R OOLDBERG, J R OOLDBERG, M L	8305100231 8305170039 8305200632 8305240525 8305250337	50-289 G 50-289 G 50-289 G 50-289 G 50-247 G
QAQE,K. QAQLIARDO,JE QAQLIARDO,JE QAQLIARDO,JE QALEF,B.R.	8305200218 8305020229 8305100093 8305200528* 8305170342	PR 50-482 A 50-445 Q 50-267 Q 50-247 Q	OIBEON, A OIBEON, A F OIBEON, A F OIBEON, A F OIBEON, J	8304280139 8305130173 8305250537 8305310174 8305160204*	I&E 70-143 70-143 50-369 8 50-312 0	GOLDEN, D W GOLDEN, M P GOLDEN, M P GOLDEN, M P GOLDENNIN K	8305120209 8305160105 8305160157 8305230107	50-286 J 50-346 J 50-272 J 71-9015
OALLAGHER, P J OALLO, J OALLO, J, OALLO, J QALLO, J	8305240454 8305060495 8305060495 8305120297 8305120299	50~247	OIBSON, J OIBSON, R L OIBSON, R L. OIESE, D. J OIESLER, C. W	8305170014* 8305040455 8305310035 8305030472 8305030314	50-336 R 50-413 H 50-413 O PR 50-305 G	ODLEMANN.K OOLDBTEIN.B L ODLDBTEIN.B L ODLDBTEIN.D B OOMER.D	8305040597* 8305040678* 8305170557 8305020288	70-378 70-378 70-378 50-522 G XPORTLIG
QALLO: J. QALLO: J QALLO: J QALLO: J QALLO: J	8305130185 8305130185 8305200410 8305200410 8305240438	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	OIEBLER, C W OIEBLER, C W OIEBLER, C W OIEBLER, C W	8305030400 8305040009* 8305050104 8305100102 8305100114	50-305 P 50-305 F 50-305 R 50-305 P 50-305 P	ODMER. DA ODODEE, JB ODODMAN, LB ODODMAN, LB ODODMAN, LB ODODMAN, MJ	8305190379* 8305020170* 8305020182* 8305170225*	50-373 P 50-407 S 50-409 S 50-528 A
OALLO, J. OALLO, R OALLO, R OALLO, R OALLO, R. M	8305240438 8305030253* 8305110297 8305050119* 8305190038*	50-155	OIEBLER, C W OIEBLER, C W OIEBLER, C W OIEBLER, C W OIEBLER, C W	8305100389 8305110003 8305130250 8305170150 8305170267	50-305 8 50-305 P 50-305 R 50-305 P 50-305 S	GOODWIN.C R GOODWIN.C R GOODWIN.C R GORELICK.M S	83050200397* 8305040060* 8305040478* 8305230203	70-378 70-378 FOIA FOIA NUREO
QALLO,R M QALLO,R M QALM,D T QAMBLE,D H QAMBLE,D H	8305250431* 8305250450* 8305250475 8305180013* 8305180016*	50-29 Q 50-271 Q 70-698 FOIA FOIA	OIEBLER.C.W OIEBLER.C.W OIEBLER.C.W OIEBLER.C.W OIEBLER.C.W	8305170323 8305230300 8305230728 8305270009 8305270198	50-305 B 50-305 P 50-305 P 50-305 P 50-305 S	COMER, C. C COMER, C. C CRACE, J. N CRACE, J. N	8305120155* 830518009&* 8305090013 8305240022	50-445 G FOIA 50-537 E 50-537 E
QAMBLE, D. H. QAMMIE, Q. B QARCIA, E M QARCIA, M J QARCIA, P. J.	8305180104* 8305240302 8305170501* 8305060434 8305120494	FOIA 50-317 J 50-275 Q PR 40-3453	GIGGEY.C A GILBERT.L D. GILBERT.R A GILDENHORN.A J. GILDENHORN.A J	8305200473* 8305230314* 8305310084 8305110157 8305200131	30-309 P 50-458 G 50-237 P CONTRACT CONTRACT	GRACE, J N GRAEBSER, K L GRAEBSER, K L	8305250146 8305260001 8305260002* 8305030440 8305060443	50-537 L 50-537 L 50-304 S 50-295 B
GARCIA, P. J. GARDE, B. GARDE, B. P. GARDNER, R. N. GARLAND, H. L.	8305130297 8305190097# 8305190124# 8305100217 8305260363	40-3453 50-327 G 50-373 G 50-327 T 40-279	OILDENHORN, A. J OILDNER, H. L OILIMBKY, V OILIMBKY, V OILLEN, D M	8305250081 8305030537# 8305230209# 8305230440# 8305130325#	CONTRACT 50-440 T 50-320 T 50-289 U 40-8752	GRAESSER, K L GRAESSER, K L	8305060528 8305060567 8305120013 8305130196 8305240214	50-295
GARLAND, W L GARNER, L. W. GARRIBBA; S. GARRITY, J, H GARRITY, J H	8305240368 8305270635# 8305040399 8305020393# 8305050220	40~299 50~324	OILLEN, D. M. OILLEN, D. M. OILLEN, J. OILLMAN, D. OILLMAN, A. R.	8305130337 8305160259* 8305130123* 8305110290 8305060141*	50-286 P 50-358 G	ORAMHI R. A	9305240311 9305310140 9305140145 9305230538* 8305050119*	50-304 B 50-293 B 50-293 B 50-443 G
OARRITY, J. H. GARRITY, J. H. GARRITY, J H. GARRITY, J H GARRITY, J H	8305040474 8305040438 8305110423 8305130054 8305130078	50-309 8 50-309 8 50-309 8 50-309 P 50-309 P	gilman, A. R. Gilman, A. R. Gilman, A. R. Gilman, A. R. Gilmay, J. W.	8305040181* 8305120298* 8305120381* 8305120627* 8305100261	40-672 70-82	ORANNIS.A B ORAVES,R H ORAVES,R H ORAY,E OREEN,D.W	8305240541 8305200408 8305270224 8305110338* 8305190132*	50-247 H 50-213 B 50-213 G 50-289 G FOIA

AUTHOR	ACCESSION NUMBER	SUBJ CATE:		AUTUGE	ACCESSION	SUBJECT		ACCESSION	BUBJECT	
GREEN, D W GREEN, D W GREEN, D W GREEN, H J GREEN, H J	8305190153 8305190337 8305190341 8304190499 8305030176	* FOIA * FOIA * FOIA 50-32	7 8	AUTHOR GUGNA, L T	NUMBER 8305250530 8305260278 8305260377 8305060377	50-23B (F HALL, D P	NUMBER 8305240413# 8305240421# 8305240247# 8305270017 8305310129	50-461 A 50-461 A 50-461 A 50-461 A 50-461 A	
GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8305030264 8305030369 8305050123 8305050183 8305050211	50-294 50-32: 50-32: 50-32: 50-32:	7 S 7 S 7 S 8 S	QUILD, R QUILD, R QUINN, P QUINN, P R QUINN, P R	8305060252 8305310155 8305020187* 8008250310* 8008250337*	50-413 (50-413 (FOIA FOIA FOIA		8305310183 8305110119 8305110237 8305090403* 8305100099	50-441 B NUREG NUREG 0A979 50-312 F	
OREEN, H J OREEN, H J OREEN, H J OREEN, H J OREEN, H J	8305050218 8305050238 8305050266 8305100012 8305100031	50-328 50-260 50-259 50-259 50-260	9 5 9 5 9 6	QUINN.PR QUINN.PR QUINN.PR QUINN.PR QUINN.PR	8008250463* 8104030770* 8305020010* 8305020220* 8305030195*	FOIA FOIA FOIA FOIA 70~378	HANCOCK, J A HANDBOY, L HANNETZ, K HANNETT, B HANNETT, B	8305230393 8305200656 8305230254* 8305130301 8305180831	50-302 P 50-440 Q FOIA XPORTLIC XPORTLIC	
GREEN, H J GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8305100081 8305100107 8305100285 8305110325 8305110355	50-255 50-296 50-260 50-327 50-259	S	QUINN, PR QULDEMOND, WG QUMMEBON, PU QUMMO, R QUPPY, JG	8305040081* 8305240247* 8305120279* 8305120326* 8305110237	FDIA 50-373 G 40-672 50-320 T NUREG	HANNUM, W H	8305190452 8305260097 8305030688 8305240614 8305050310*	XPORTLIC XPORTLIC 50-201 P 50-201 P 70-378	
GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8305110373 8305110409 8305130085 8305130131 8305170030	50-327 50-326 50-259 50-260 50-296	S S S	QUSTAFSON.L D QUSTAVE.R P QUSTAVE.R P QUSTAVE.R.P QUSTAVE.R.P	8305060382 8305030707 8305040660# 8305050404# 8305060183*	PR CONTRACT CONTRACT CONTRACT CONTRACT	HANBON, W A HARDIN, A K HARDIN, A K HARDING, M R HARDING, M R	8305120135* 8305030256 8305270401* 8304190537* 8305030183*	50-445 q 50-261 8 50-261 q 50-327 8 50-327 8	
GREEN.H J GREEN.H J GREEN.H J GREEN.H J GREEN.H J	8305170330 8305200288 8305200420 8305200427 8305200577	50-260 50-260 50-260 50-327 50-327	8 8 8 9	GUBTAVE,R P GUSTAVE,R. P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8305040384* 8305070012* 8305070058* 8305070117* 8305070131*	50-329 A CONTRACT CONTRACT CONTRACT	HARDING, M. R HARDING, M. R HARDING, M. R HARDING, M. R, HARDING, M. R.	8305030577# 8305050128# 8305050204* 8305050217# 8305050224*	50-327 8 50-327 8 50-327 8 50-328 8 50-328 8	
GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8305230530 8305250342 8305250357 8305250380 8305250400	50-327 50-328 50-260 50-328 50-328	5 8 8 S 6	GUSTAVE,R.P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8305110041* 8305110236* 8305110509* 8305110545* 8305160332*	CONTRACT CONTRACT CONTRACT CONTRACT 50-367 A	Harding, m. r Harding, m. r Harding, m. r Harding, m. r Harding, m. r	8305110329* 8305110382* 8305110419* 8305200432* 8305200581*	50-327 8 50-327 8 50-328 8 50-327 8 50-327 8	
GREEN, H J GREEN, H J GREEN, H J GREENBAUM, R	8305250433 8305250526 8305250532 8305310054 8305180448*	50-328 50-327 50~327 50~296 50-322	8 8 8 #	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	B305170607* 8305170614* 8305170693* 8305190514* 8305200004*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HARDING, M R HARDING, M R HARDING, M R HARDING, M R, HARDING, M R	8305230534* 8305250342 8305250380 8305250400 8305250433	50-327 8 50-328 8 50-328 8 50-328 8	
GREENBAUM, R L GREENE, G A GREENE, H J GREENKORN, R A GREENMAN, E	8305170207 8305110237 8305250508 8305060183* 8305250238	50-440 NUREG 50-296 CONTRAC 50-272	Q S T SI	QUETAVE, R P QUETAVE, R P QUETAVE, R P QUETAVE, R P QUETIN, H L	8305200147* 8305230289* 8305270100* 8305270110* 8305310097*	CONTRACT CONTRACT CONTRACT CONTRACT 50-366 G	HARDING, M R HARDING, M R HARPSTER, T L HARRELL, E W HARRELL, E W	8305250526 8305250532 8305040588* 8305030158 8305030165*	50-327 8 50-327 8 TOPREP 50-338 8 50-338 8	
GREGER.L R GREGER.L R GREGER.L R GREGER.L R GREGER.L R	8305040434* 8305100402* 8305120353* 8305170353* 8305170161	40-8202 50-237 50-374 50-295 70-8	G G G	Gutman, D, Gutman, D Gutman, D Ghynn, T P, Haas, C F	8305030619* 8305030619* 8305030619* 8305260231* 8305030312*	50-247 0 50-247 0 50-247 0 50-358 0 70-378	HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W	9305030357	50-339 8 50-339 8 50-339 8 50-339 8	
OREGER, L. R OREGER, L. R OREGER, H OREGORY, E	8305240026* 8305240292* 8305240340* 8305250505* 8305180459*	50-255 50-331 40-3392 50-289 50-322	о н	HAAS,C F HAASS,W P. HAASS,W P HADLEY,C D HAQAN,T F	8305040217* 8305090432* 8305230004* 8303180429 8305040351*	F01A 50-445 Q 50-528 A 50-263 P CONTRACT	HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W	8305030635 8305030640# 8305050186	50-338 8 50-339 8 50-339 8 50-338 8 50-338 8	
OREGORY, W S GREGORY, W S OREGORY, W S ORELLA, A W ORELLA, A W	8305110062 8305110083 8305130292 8305120251* 8305120614*	REB RES RES 40-672 FOIA		HAGAN, T F. HAGAN, T F HAGAN, T F HAGRMAN, D L HAGUE, R L	8305110163* 8305200134* 8305260222* 8305110523 8305120468*	CONTRACT CONTRACT CONTRACT NUREQ 30-266 Q	HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W	8305050210 8305050215± 8305050271 8305050276*	50-337 8 50-337 8 50-337 8 50-337 8	
ORIER, B H ORIER, B H ORIER, B H ORIFFIN, H B ORIFFIN, J	9305120519* 9305120523* 9305120540* 9305100307* 9305260260	40-672 40-672 40-672 50-482 50-313	G S	HAHN, C.T. HAIRSTON, H. C. HAIRSTON, W. C. HAIRSTON, W. C. HAIRSTON, W. C.	8305110512 8305030589* 8305050154* 8305050158* 8305050203*	NUREO 50-364 8 50-348 8 50-348 8	HARRELL, E. W HARRELL, E W HARRELL, E W HARRELL, E W HARRELL, E W	9305100259 9305100265# 9305110285	50-339 8 50-339 8 50-339 8 50-338 8	
GRIMES.B K GRIMES.B K GRIMES.B K GROSCUP.O W GROSSMAN,H	9208190078* 8305030474* 8305100414* 8305030454 8305260172	50-443 50-483 50-155 50-247 50-460	F Q Q P O	Hairston, W o Hairston, W o Hairston, W o Hairston, W o Hairston, W o	8305100139* 8305110260* 8305200327* 8305200362* 8305230544*	50-364 8 50-364 8 50-348 R 50-364 R 50-348 8	HARRELL, E W HARRELL, E W HARRELL, E W HARRELL, E W HARRELL, E W	8305110336* 5 8305110453 5 8305110465* 5	50-337 8 50-337 8 50-337 8 50-337 8	
GROTENHUIS, M GRUCCI, T. B GRUCCI, T. B GRUCCI, T. B GRUCCI, T. B	8305110050 8305030023* 8305030072* 8305040244* 8305040523*	50-305 FOIA FOIA FOIA FOIA	Р	HAIRBTON, H G HAIRBTON, H G HAIRBTON, H, G. HAIBLER, R K HAIBT, D P.	8305230550* 8305250353 8305250781 8305270425 8305270425	50-348 8 50-348 8 50-348 8 50-321 8 50-508 Q	HARRELL, E W HARRELL, E, W HARRELL, E W HARRELL, E W HARRELL, E W	B305170412* 5 B305200146 5 B305200279 5 B305200284* 5	00-338 8 10-338 8 50-339 8 10-339 8	
ORUCCI,T B OUCHA,L T OUCHA,L T OUCHA,L T	8305040578* 8305030261 8305040051 8305040254 8305040304	FDIA 50-321 50-321 PR 50-321	H P	HALE,C J HALE,C J HALE,C J HALL,B. HALL,B.	8305020307* 8305050226* 8305200340* 8305100109* 8304280279	GA999 GA999 GA999 50-324 G 50-400	HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W HARRELL, E. W	8305200583* 5 8305250288 5 8305250384 5 8305250417 5	0-338 8 0-338 8 0-337 8 0-336 8	
QUCHA, L. T QUCHA, L. T QUCHA, L. T QUCHA, L. T. QUCHA, L. T.	8305040469 8305160144 8305160159 8305200453 8305240250	50-321 50-321 50-366 50-321 50-366	F G P P	HALL, D. P HALL, D. P. HALL, D. P. HALL, D. P. HALL, D. P.	8304050243 8305020111 8305040298 8305060576 8305120475	50-461 K 50-461 G 50-461 B 50-461 G 50-461 8	HARRELL, E, W HARRELL, P, H HARRINGTON, W. D. HARRINGTON, W. D HARRINGTON, W. D	8305270335 5 8305050226* 0 8304180590 5 8305020134 5	0-337 S A979 0-273 P 0-273 R 0-273 G	

AUTHOR	ACCESSION NUMBER	SUBJECT		ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HARRINOTON, H D HARRINOTON, H D HARRINOTON, H D HARRINOTON, H D HARRINOTON, H D	8305090200 8305100138 8305110334 8305110336 8305110384	CATEGORY 50-293 P 50-293 R 50-293 B 50-293 B 50-293 B	AUTHOR HELTEMES, C J HELTEMES, C J HELTEMES, C J HELTEMEY, L O HENRY, L, O	NUMBER 8305230511 8305230519* 8305230524* 8305100252 8305110380	CATEGORY	HOLMBECK, P HOLMBECK, P HOLMBECK, P HOLMES-RAY, P HOLDDY, D J	8305170549* 8305170549* 8305170549* 8305270550* 8305130223*	50-454 50-454 50-454 50-366 50-271
HARRINGTON, W D	8305130153 8305160044 8305160061 8305160134 8305170173	50-293 H 50-293 P 50-293 P 50-293 R 50-293 F	HENRY, W. O HENBLEY, K D HENBLEY, K D HERDT, A R HERING, R F	8305060382 8305050099 8305200658 8305270179* 8305030257	PR 70-143 70-143 50-389 G 50-315 P	HOLTIR R HOLTIR R HOLTIR R HOLTIR R	8305250193 8305250231 8305030629* 8305030629* 8305030629*	50-482 50-482 50-247 50-247 50-247
HARRINGTON, W D HARRINGTON, W D HARRINGTON, H D HARRINGTON, H D HARRINGTON, W D	8305170345 8305170418 8305170529 8305190024 8305190147	50-273 P 50-273 P 50-273 R 50-273 B 50-273 P	HERING.R F HERING.R F HERING.R F HERING.R F HERMANN.R	8305090363 8305160054 8305160121 8305260281 8305170027	50-315 R 50-315 R 50-315 P 50-315 P 50-220 P	HOLHAY,F I HOLYDAK,R H HOLYDAK,R H HOLIMER,M HOPCRAFT,C P	8305250331 8305190084* 8305190145* 8305020348* 8305240031	50-443 50-373 50-373 50-315 71-9163
HARRINOTON, H D	8305170176 8305170326 8305200259 8303200447 8305230434*	50-273 8 50-273 8 50-273 P 50-273 P 50-273 Q	HERNAN, R W HERNANDEZ, G H HERR, J C HERR, R K HERRINGTON, F A	8305040336 8305260262* 8305060277* 8305100307* 8305060383*	50-327 E 50-275 G 50-244 P 50-482 G 50-278 I	HOPPER, A HOPPER, A HORIN, W A HORIN, W A	8305130299 8305180785 8305050018 8305050018 8305100267	CONTRACT CONTRACT 50-445 50-445
HARRINGTON:W D HARRINGTON:W D HARRINGTON:W D HARRINGTON:W D HARRINGTON:W D	8305230450 8305230507 8305230516 8305230533 8305270073	50-293 F 50-293 8 50-293 8 50-293 8 50-293 9	HERBCH, M M HERBCH, M M HEBSON, G M. HIATT, S L HIATT, S L	8305260057* 8305260070 8301060137* 8305040528 8305040541	XPORTLIC XPORTLIC 50-307 P 50-440 Q 50-440 O	HORIN, W A	8305100267 8305130260 8305130260 8305180449 8305040287*	50-445 50-445 PR FOIA
HARRIS,C L HARRIS,D. HARRIS,J.R HARRIS,J.R HARRIS,J.R	8305230311* 8305170466 8305270200* 8305270415* 8305270551*	CONTRACT 30-225 F 30-337 G 50-438 G 50-400 G	HIATT, S L HIATT, S L HIATT, S L HIATT, S L HIATT, S L	8305040544 8305070234 8305170305 8305170341 8305180347	50-440 G FDIA 50-440 G 50-440 G PR	HOSEY, C M HOUSTEAU, L HOUSTON, D HOUSTON, R W	8305270265* 8305270384* 8305240403* 8305250150 8304140161*	50-280 50-250 GA999 50-416 50-352
MARRIBIR J. HARRIBIR HARRIBONIF. HARTIO, HARTMANIB L	8305200637* 8305250436* 8305100417* 8305110584* 8305240465	50-373 P 50-483 Q 50-324 R COMMISSION 50-460 Q	HIATTIS L HICKEYIJ W HICKEYIJ W. HICKEYIJ W. HICKEYIJ W	8305180404 8305020201* 8305040297* 8305040408* 8305130006*	PR FOIA FOIA FOIA 40-672	HOUSTON, R. W HOUSTON, R. W HOUSTON, R. W HOUTS, P. S HOUTS, P. S	8303020090* 8303170378* 8303170388* 8303270040* 8303270046*	50-373 50-373 50-373 50-320 50-320
HARTMAN, B. L. HARTMANN, P. L. HARTZMAN, R. M. HARTZMAN, R. M. HARVEY, R. V.	8305240465 8305100271* 8305160024 8305160024 8305240552	50-460 G 50-275 G 50-247 G 50-247 G 71-6550	HICKEY, J W. HICKEY, J W HICKEN, R A HICKE, M M HICOINBOTHAM, L	8305130016* 8305130053* 8305270105* 8305240454 8305090582	40-672 40-672 CONTRACT 50-247 0 WASTE MGT	HOVI,L HOWARD,A T HOWARD,A T HOWARD,A T HOWARD,T R	8305240356 8305190108* 8305190179* 8305190207* 8305030705	50-445 50-327 50-373 FOIA 40-8584
HABBE, R. HABBE, R. A. HABBE, R. A. HAUGHEY, M. F. HAVERKAMP, D	8305120447* 8305260250* 8305260334* 8305180054 8305110508*	50-373 @ 50-441 @ 50-373 @ 50-410 A 50-333 @	HIGGINBOTHAM, L. HIGGINBOTHAM, L HILL, D W HILL, R T HILL, T, D,	8305090617 8305110218 8305060383* 8305100370* 8305130113	WASTE MOT WASTE MOT 50-278 I 50-325 P 50-400 S	HOME.PW HOME.PW HOME.PW HOME.PW	8305030288 8305030463 8305060176 8305200597 8305200625	50-324 50-325 50-325 50-324 50-324
HAVERKAMP, D. R. HAVERKAMP, D. R. HAMKINB, E. F. HAMKINB, F. C. HAMKINB, F. C.	8305250230# 8305250465# 8305170571# 8305170153# 8305170315#	50-286 G 50-336 G 70-8 50-346 G 50-346 G	HILL,T K HILL,T K HILL,W H HIND,J HIND,J A.	8305200598 8305200656 8305170224* 8305270152 8303280177	50-440 Q 30-440 Q 50-498 Q 50-255 8 40-2061	HOHE, P W HOWE, R. 8 HOYLE, A HOYLE, A.	8305240434 8305200314 8305040552 8305060246 8305110170	50-324 50-309 CONTRACT CONTRACT
Hanking, F. C. Hanking, F. C. Hanking, F. C Hanking, F. C Hanthorne, J. R	8305190256# 8305260250# 8305260256# 8305260334# 8305060347	50-331 G 50-461 G 50-407 G 50-373 G NUREG	HIND, J.A. HIND, J.A. HIND, J.A. HIND, J.A	8305100379 8305100387# 8305100409# 8305170138 8305170343	50-237	HOYLE, A HOYLE, A HOYLE, J HOYLE, J C	8305110194 8305130354 8305180038 8305060468 8305060250	CONTRACT CONTRACT 50-247 50-247 50-277
MAYES, D. W. HAYES, D. W HAYES, D. W. HAYES, D. W HAYES, D. W.	8305020337* 8305100174* 8305170022* 8305180074* 8305190050*	50-461 Q 50-454 C 50-461 Q 50-498 Q 50-329 Q	A L'ADNIH B L'ADNIH A L'ADNIH HIND, J M HIND, J M HIND, J A	8305200458 8305270486 8305270493* 8305240268* 8305020158*	50-315 F 50-305 G 50-305 G 50-456 G FOIA	HOYLE, J C HOYLE, J C HOYT, H F HOYT, H, F HOYT, H F	8303060258 8305090499 8304250241 8305030570 8305060463	50-287 50-537 50-443 50-443
HAYEB, D. W. HAYNEB, R. C. HAZELTINE, J. HEAD, O. F. HEALEY, J. A.	8305240268* 8201070110* 8305110087* 8305270508* 8305240517	30-436 Q 40-672 50-373 P 50-366 Q 50-247 H	Hinrichs, o Hinrichs, o Hinrichs, o Hipsher, w Hipsher, w M	8305030380* 8305030407* 8305140025* 8305110134 8305110155	30-247 8 30-247 8 30-247 8 27-48 27-48	HDYT.H F HOYT.H F HOYT.H F HOYT.H F.	8305090508 8305100200 8305130181 8305170478 8305240451	50~443 50~443 50~443 50~443
HEATHERLY, T. L. HEBEL, C HEDDLESON, F. A HEIDER, L. H. HEIDER, L. H.	8305270303* 8305130220* 8305110120 8305240343 8305240358	50-390 G 50-254 B NUREG 50-271 V 50-27 P	Hirech, D Hirech, D Hirech, D, Hoagland, R G, Hodgdon, A P	8305170325 8305200496 8305200652 8305110512 8305060337	50-142 G 50-142 G 50-142 G NUREG 50-352 G	HOYT, H F HSIEH, D HSU, Y Y HU, C. K HUANG, A Y	8305270598 8305170101 8305270109 8305100281* 8305100281*	50-443 NUREQ NUREQ 50-352 50-352
HEIDER, L. H. HEIMBACH, L. HEISHMAN, R. F. HEISHMAN, R. F. HELD, J, T.	8305250569 8305240312 8305120155* 8305260255* 8303310020*	50-271 P 50-247 F 50-445 Q 50-397 Q 50-333 P	Hododon: A P Hodoes: W. Hogan: C. F. Hogan: J. J Holbrock: W W	8305260322 8103300276* 8305170207 8305240517 8305100349*	50-352 G 50-416 A 50-440 G 50-247 H GA999	HUBACEK, W O HUBBARD, K. S HUBBARD, M J HUBBARD, R B HUDSON, S. D	8305180075* 8305190209 8305200656 8305260183* 8305200392*	50-498 \ 50-440 \ 50-440 \ 50-275 \ 50-220
HELD, J T HELFRICH, R. E HELGEBON, K. A. HELLER, J HELLER, J K	8303310020* 8305180342 8305240371 8305020348* 8305200247*	50-333 P PR 70-820 50-315 Q 50-255 Q	HOLEROOK, W. W. HOLCOMBE, J. C HOLDEN, C. F HOLDER, E. T HOLDER, E. T.	8305100355* 8305120178 8305250450* 8305050245* 8305050272*	QA999 50-204 H 50-271 G 50-260 B 50-259 S	HUOSPETH, J B HUEBNER, L Q HUETER, L, J HUFFMAN, O N HUFFMAN, O N	8305060621 * 8305030592 * 8305240292 * 8305270297 * 8305270387 *	50-34B 50-441 50-331 50-335 50-269
HELLER, J. K. HELTEMES, C. J. HELTEMES, C. J. HELTEMES, C. J HELTEMES, C. J.	8305240037* 8304010159* 8304040591* 8304140328* 8305040730	30-255 @ MISC MISC 50-257 P	HOLDER, E.T. HOLDER, E.T. HOLLAND, B.A HOLLORAN, R.H. HOLLORAN, R.H.	8305100014* 8305170034* 8305250271* 8305240144 8305240154*	50-257 8 50-276 8 50-287 P TOPREP TOPREP	HUGHES: J HUGHES: J HUGHES: J HUGHES: J	8305270466* 8305030516* 8305030516* 8305030516* 8305030516*	50-302 50-454 50-454 50-454

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGOR	
HUGHES, P G HUGHES, P G HUKILL, H D HUKILL, H D HUKILL, H D	9305110370* 9305130188* 9305020232* 9305030075 9305030102	50-302 S 50-302 S 50-289 Q 50-289 S	JAFFE, D H JAFFE, D H JAFFE, D H JAFFE, H JAIN, H	8305170246 8305180556 8305180768 8305240441 8305020547	50-317 P 50-317 P 50-317 P 50-247 H NUREO	JOHNSON, W D JOHNSON, W K JOHNSON, W K JOHNSTON, Q JONES, D W	8305230480* 8305250548* 8305250548* 8305170382* 8305270167*	50-482 50-483 50-483 50-528 70-143	9 9
HUKILL, H D HUKILL, H D HUKILL, H D	8305030436 8305040374 8305040458 8305040449 8305040449 8305070453	50-287 S 50-287 P 50-287 R 50-287 R 50-287 P	JAKUBAITIB.T C JAKUBAITIS.T C JANO.J C JAPE.F JAPE.F	8305060544* 8305240214 8305110277* 8305270151* 8305270245*	50-295 8 50-304 8 50-317 0 50-369 0 50-389 0	JONES, D W JONES, W C JONES, W C JONES, W C	8305310022* 8305030154 8305030427* 8305040619* 8305060069	70-1201 50-285 50-285 50-285 50-285	P F F
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8305110286 8305110333 8305110346 8305120055 8305130065	50~287 S 50~287 S 50~287 F 50~287 P 50~287 P	JAPE, F JAPE, F JAPE, F JAPE, F JAPE, F	8305270304* 8305270367* 8305270453* 8305270470* 8305270521*	50-416	JONEB: W C JONEB: W C JONEB: W C JONEB: W C	8305040184 8305120403* 8305140027 8305140111 8305170445	50-285 50-285 50-285 50-285 50-285	P P R R
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H. D	8305130070* 8305130180 8305190158 8305190240 8305200173	50-289 P 50-289 F 50-289 P 50-289 R 50-289 P	JAPE, F JAPE, F JAPE, F JARBOE, E D JAUDON, J P	8305270526= 8305270562* 8305270587* 8305180183 8305100361*	50-259	JONES, W. C. JONESON, B. J. JONESON, B. J. JORDAN, E. L. JORDAN, E. L.	8305240474 8305120471* 8305120476* 8303040021 8303040023	50-285 40-215 40-215 50-3 50-3	P G G
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8305200502 8305200547 8305250249 8305240085 8305240094	50-287 P 50-287 8 50-287 P 50-287 Q 50-287 P	JAUDON, J P JENIBON, K M JENKINS, G R JENKINS, G R JENKINS, G R	8305230348* 8305130142 8305270116* 8305270297* 8305270387*	50-313 G 50-280 8 70-1113 50-335 G 50-267 G	JORDAN, E, L JORDAN, E L JORDAN, E L JORDAN, E L, JORDAN, E L	8303040025 8303040026 8303040027 8303040028 8303040030	50-3 50-3 50-3 50-3	9 9 9
HUKILL, H D HUKILL, H D HULMAN, L G HUNNICUTT, D M HUNNICUTT, D M	8305270203 8305310205 8303100248* 8305100007* 8305100142*	50-287 R 50-287 P 50-329 T 50-192 G 50-458 Q	JENKINB. G R JENKINB. G R JENKINB. G R JERMAN. P C	8305270427* 8305270446* 8305270466* 8305050257* 8305120303*	50-416 G 50-395 G 50-302 G 50-128 P 40-672	JORDAN, E.L. JORDAN, E.L. JORDAN, E.L. JORDAN, E.L. JORDAN, E.L. JORDAN, E.L.	8303040031 8303040033 8303040034 8303040040 8303040046	50-3 50-3 50-3 50-3	99999
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNUM, W H HUNSTAD, A A	8305230314* 8305230447* 830523045 8305230015	50-445 Q 50-458 Q 50-445 Q 50-201 P 50-306 S	JERMAN, P. C. JERMAN, P. C. JO, J. JOHNBON, A. JOHNBON, B. D.	8305120310* 8305120372* 8305110131 8305170564* 8305020138	40-472 40-472 NUREG 50-528 Q 50-255 S	JORDAN, H JORDAN, M, JORDAN, M J JORDAN, M J JORDAN, W, H	8305270011* 8305020511 8305020480* 8305100218* 8305270634	50-261 50-331 50-10 50-331 50-382	P 8 0 0 0
HUNSTADIA A HUNTIM D HUNTERID R HUNTERIR S HUNTERIR S	8305240166 8305270101* 8305260231* 8305160104 8305240086*	50-282 \$ 50-389 Q 50-358 Q 50-315 P 50-315 Q	0 104N80N 8 D D D D D D D D D D D D D D D D D D	8305020173 8305040475 8305040388 8305100076 8305100170	50-255 8 50-255 Q 50-255 B 50-255 R 50-255 P	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JOROENSEN, B L	8305160002 8305160002 8305160019 8305160019 8305200247*		00000
HUNTER, R S HURFORD, W J HURFORD, W J HURFORD, W J HURSH, J B	8305310088 8305040342 8305240004 8305250473* 8305060200*	50-315 P 50-261 P 50-324 P PR 40-672	NOUNDON: B D JOHNBON: B D JOHNBON: B D JOHNBON: B D	8305100378 8305100374 8305130140 8305130208 8305130225	50-255 8 50-255 8 50-255 8 50-255 8 50-255 8	JÖRÐENSEN, B. L. JOSHUA, G. JOY, J. JOYNER JOYNER, J.	8305240037* 8305240517 8305240454 8305100004 8305030459	50-247 50-247 50-272	0 H 0 B B
HWANG,T HYLKA.R IAVENDITTI,A IBEN,C A IDEKER,R L	8305030250 8305060517* 8305270075 8305020154* 8305030694	XFORTLIC 50-237 8 50-220 8 50-254 8 70-143	0 8 NOSNHOC D 8 NOSNHOC D 1005NHOC D 1005NHOC D 1005NHOC D 1005NHOC	8305240011 8305240043 8305240371* 8305240410 8305310168	50-255 S 50-255 G 50-255 G 50-255 R 50-255 S	JOYNER, J JOYNER, J H JOYNER, J, H, JULIAN, C JULIAN, C	8305120434 8305020459 8305030294 8305270219* 8305270439*	50-219 50-286	88866
ideker.r l Ignatonis.a Ignatonis.a Ignatonis.a Ignatonis.a	8305190033 8305030374 8305110262 8305130186 8305270160*	70-143 50-491 S 50-370 S 50-370 S 50-369 Q	10HUBON'C E 10HUBON'C E 10HUBON'B M 10HUBON'B D	8305310197 8305310202 8206100204 8305100142* 8305230314*	50-255 8 50-255 8 REB 50-458 Q 50-458 Q	JULIAN, C JULIAN, C. A. JULIAN, C. A. JULIAN, C. A. JULIAN, C. A	8305270544* 8305100078 8305130142 8305270455* 8305270470*	50-250 50-260 50-338	0 8 9 9
A.SINGTANDI L A.SINGTANDI L A.SINGTANDI L A.SINGTANDI L A.SINGTANDI	8305310174 8305270334* 8305270411* 8305270492* 8305270602*	50-369 8 50-413 Q 50-269 Q 50-537 Q 50-413 Q	JOHNSON, 6 E JOHNSON, 6 E JOHNSON, 6 E JOHNSON, 6 E	8305200256* 8305110089* 8305030504 8305030576 8305050080	50-382 Q 50-373 P 50-413 0 50-413 0 50-413 0	JUNGE, MA JUNGE, MA JUNGE, M.A. KAHLE, JB. KAHLE, JB	0305110363* 8305190352* 8305230560* 8305250537 8305270121*	50-318 50-317 70-143	8 8 0
ILBERG, D IMS, J IPPOLITO, T, A IRBY, B J IRWIN, G R	8305110126 8305110027 8305030704 8305030272* 8305110512	50-312 P NUREG MISC 50-296 S NUREG	70HN80N; 0 E 70HN80N; 0 E 70HN80N; 0 E 70HN80N; 0 E	8305100232 8305110462 8305130036 8305170556 8305230055	50-413	KAHLE, J B KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N	8305270469* 8305020142 8305030321 8305060390 8305090231	50-254 50-254	8 8 8
IRWIN.R B IGLEY.T IGBEROW.G JABBOUR.K N	8305240517 8305130205* 8305240341 8305120248* 8305020028	50-247 H 50-346 8 50-346 S 40-672 50-413 E	JOHNSON, J. C JOHNSON, J. C JOHNSON, L JOHNSON, L JOHNSON, L	8305160142* 8305110147 8305310210 8305030213* 8305030278*	50-293 G HABTE MOT NUREO 70-378 70-378	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8305130212 8305170372 8305240317 8305240321 8305240326	50-254 50-254 50-254	8 8 8 8
JABBOUR, K N JABBOUR, K N JACKIM, I N, JACKIM, I N JACKIM, I N	8305240021 8305250211 8305020356* 8305120468* 8305240061*	50-413 E 50-413 Q 50-305 Q 50-264 Q 50-282 Q	JOHNSON, L JOHNSON, L JOHNSON, P H JOHNSON, T C JOHNSON, T L	8305030286* 8305030323* 8305170437* 8305090670 8305030086	70-378 70-378 50-89 G WASTE MOT 40-1341	KALIVIANAKIS,N KALIVIANAKIS,N, KALKWARF,D.R KALKWARF,D.R KALMAN,K	8305310142 8305310152 8305060674 8305110457 8305250283		8
JACKBON'F JACKBON'F JACKBON'A JACKBON'A	8305040154* 8305250535* 8305090453 8305270278* 8305270442*	71-9175 PR WASTE MOT 50-537 Q 50-338 Q	JOHNSON, T. L. JOHNSON, T. L. JOHNSON, T. L. JOHNSON, H. JOHNSON, H. D.	8305250199 8305250270 8305250593 8305230475* 8304150154*	40~7869 40~8786 40~8786 50~285 @ 50~213 @	KALNINS, A KAMMER, D B KAMMER, D, B KAMMER, D B KAMMER, D B	8305250271* 8305030543 8305040433* 8305130029 8305130041	50-390 50-259 50-327	P E F P
JACOBB, R JACQUES, P JACQUES, P JACQUES, P H JAFFE, D H	8305250238 8305020078* 8305020151* 8305130101* 8305040783	50-272 S 50-316 B 50-315 S 50-315 S 50-317 P	JOHNSON, W D JOHNSON, W D JOHNSON, W D JOHNSON, W D JOHNSON, W D	8305100116* 8305100140* 8305100244* 8305100361* 8305230348*	50-482 G 50-482 G 50-285 G 50-313 G 50-313 G	KAMMER, D. 8 KAMMER, D. S. KAMMER, D. S. KAMMER, D. S. KAMMERER, C	8305240394 8305250473 8305270233* 8305270592* 8305180221*	50-259 50-390 50-438	P 9 9 4

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KAMMERER, C KAMMERER, C KANGA, B KANGA, B KANGA, B KANGA, B	8305230197* 8305260401* 8305030462 8305030527 8305060082	50-320 T 50-358 A 50-320 R 50-320 B 50-320 F	KELLY, W J KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8305270247 8305020335 8305050202 8305060507 8305100275	50~275 S 50~352 A 50~352 G 50~352 A 50~352 A	KIRSCH, D F KIRSCH, D F KIRSCH, D F KIRSCH, D F KIRSCH, D F	8305170337* 8305170361* 8305170365* 8305170420* 8305170421*	50~275 Q 50~361 Q 50~206 Q 50~361 Q 50~361 Q
KANOA, B K	8305110321	50-320 B	KEMPIAK.A J	8305170332*	50-373 P	KIRBCH, D F	B305170432*	50-89 Q
KANOA, B K	8305110370	50-320 B	KEMPIAK.A J	8305170365*	50-373 P		B305170437*	50-89 Q
KANOA, B K	8305120015	50-320 H	KENDALL.R	8212070092*	MISC		B305170480*	50-361 Q
KANOA, B K	8305120312	50-320 T	KENNEDY.D M	8305110396	50-255 R		B305260262*	50-275 Q
KANOA, B K	8305170435	50-320 P	KENNEDY.R P	8305170544*	50-329 A		B305260272*	50-275 Q
Kanga, B K	8305170448	50-320 P	KENYON, B D KENYON, B D KENYON, B D	7909180214*	50-498 8	KIRSLIS,S B	8305100166*	50-443 Q
Kanga, B K	8305200563	50-320 F		8305100410*	50-286 0	KISH,J N	8305170153*	50-546 Q
Kanga, B K	8305240348	50-320 R		8305250230*	50-286 0	KISISEL,I T	8305170303*	50-373 P
Kanga, B, K	8305250255	50-320 P		8305100014	50-387 P	KISTER,H	8305100410*	50-286 Q
Kanga, B K	8305250385	50-320 R		8305100019*	50-387 P	KISTER,H B	8305100433*	50-247 Q
KANGA, B K	8305310001	50-320 S	KENYON: B D	8305270255	50-387 Q	KISTER, H B	8305110391*	50-333 Q
KANGA, B K	8305310058	50-320 P	KENYON: T J	8305240440	50-390 A	KISTER, H B	8305110508*	50-333 Q
KANGA, B K	8305310118	50-320 P	KEPPLER: J O	7711150353*	FOIA	KISTER, H B	8305190334*	50-410 Q
KANGA, B K	8305310154	50-320 P	KEPPLER: J O	8305020334	50-461 Q	KISTER, H B	8305200392*	50-220 Q
KANTOR, F.	8305170058*	50-287 G	KEPPLER: J O	8305020337*	50-461 Q	KISTER, H B	8305250230*	50-286 Q
KAPLAN, C	8305030608	50-247 G	KEPPLER, J O	8305040410	30-275 Q	KISTER.H B	8305250453*	50-244 Q
KAPLAN, G	8305240532	50-247 G	KEPPLER, J O	8305090549*	30-358 T	KISTER.H B	8305250538	50-286 Q
KAPLAN, G	8305240532	50-247 G	KEPPLER, J O	8305100124	50-327 T	KITLER.E J	8305120330*	50-320 T
KARMAN, M	8305170002	50-482 G	KEPPLER, J O	8305130258	50-407 Q	KLEIN.D	8305100005	50-192 P
KARMAN, M	8305170555	50-261 G	KEPPLER, J O	8305170392	50-327 H	KLEINSORGE.W P	8305270402*	50-369 Q
KARSCH,R.D	8305030474*	50-483 G	KEPPLER.J O	8305170458	50-454 Q	KLEINBORGE,W P	8305270406*	50-400 q
KASTENBERG,WE,	8305130326	ACR8	KEPPLER.J O	8305190269	50-358 Q	KLEINBORGE,W P	8305270476*	50-395 q
KAUFHAN,PH	8305260182	50-275 G	KEPPLER.J O	8305190329*	50-373 Q	KLEYIN,P B	8305120234*	40-672
KAUFHANN,J,E	8305130361*	CONTRACT	KEPPLER.J O	8305190384*	50-373 Q	KLIMA,D L	8305110276	50-410 p
KAVANAUOH,PF	8305060351*	CONTRACT	KEPPLER.J O	8305200454	50-358 A	KLIMA,D C	8305070397	50-272 q
KAHACHI, M. KAY, J. A KAY, J. A KAY, J. A. KAY, J. A	8305170738 8305060172 8305060215 8305100228 8305110010	71-9033 50-29 F 50-29 F 50-29 P 50-29 F	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8305200558 8305240080 8305240380 8305240406 8305240407	50-358 A 40-2061 30-266 G 50-461 A 50-461 A	KLINOLER. G KMETYK.L N KNAPP.M R KNAPP.P J KNAPP.P J	8305240439 8305310209 8305090572 8305120310* 8305120372*	I&E NUREG Waste Mot 40-672 40-672
KAY, J. A.	8305170457	50-29 P	KEPPLER, J. Q	8305250144*	50-373 F	KNIEL'K'	8305120269*	70-82
KAY, J. A	8305240364	50-27 P	KEPPLER, J. Q	8305260246	50-461 A	KNICELEA'' A B	8305030521*	50-264 Q
KEARNEY, B	8305030711	40-2259	KEPPLER, J. Q	8305260310	50-329 Q	KNICELEA'' A B	8305100365*	50-156 Q
KEARNEY, B.	8305060222	40-8348	KEPPLER, J. Q	8305260405*	50-358 T	KNEELEA'' B B	8305200482*	70-925
KEARNEY, B	8305160276	40-299	KERCH, H	8305230575*	50-387 Q	KNEELE'' B B	83052004153*	FOIA
KEARNEY, J. J KEARNEY, J. J KEARNY, B. KEATING, D. E KEATING, D. E	8305180358 8305250420 8305130312 8305120348* 8305120420*	PR PR 40-2259 50-461 G 50-373 Q	KERN,P KERNS,M KERR,G W KESHISHIAN,P I KESBLER,P J	8305180459* 8305130120* 8305170137 8305120155* 8305240517	50-322 H 50-286 P NUREG 50-445 G 50-247 H	KNIGHT.H R KNIGHTON.G W KNIGHTON.G W KNIGHTON.G W KNIGHTON.G W	6305260233 6305020506 6305020570 6305030022* 6305060278	50-546 F 50-400 A 50-389 E 50-389 P
KEATING, DE. KEATING, DE KEATING, LA KEIMIG KEIMIG, R	B305170183* B305260231* B305100225* B305060558 B305030074	50-255 Q 50-358 Q 50-322 Q 50-277 S 50-289 S	KETZLACH, N KETZLACH, N KEUPER, J S KEY, W J KEY, W J	8305240559 8305240543 8305250135* 8305020360* 8305120449*	70-2983 70-2983 50-392 A 50-331 G 50-237 G	KNIGHTON, G W KNIGHTON, G W KNIGHTON, G W KNIGHTON, G W KNIGHTON, G W	8305040303* 8305040483 8305110177 8305110182* 8305110188*	50-389 P 50-361 P 50-361 P 50-361 P
KEIMIO, R KEIMIO, R KEIMIO, R KEIMIO, R KEIMIO, R	8305030450 8305030534 8305060387 8305160179*	50-272 8 50-289 9 50-277 8 50-272 9 50-289 0	KHLAFALLAH,M Z KIBLER,D R KIBLER,D R. KIEL,O R. KIEL,O R.	8305100281* 8305240221 8305270429 8305170584 8305170616	50-352 A 50-331 B 50-331 B XPORTLIC XPORTLIC	Knighton, C W Knighton, C W Knighton, C W Knighton, G W Knighton, G W.	8305130332 8305130335 8305170229 8305170236+ 8305170577	50-443 A 50-443 A 50-361 P 50-361 P 50-400 A
Keimig, R. R	8305170051*	50-289 0	Kiel, o r	8305170621*	XPORTLIC	KNIGHTON, G H	8305180024	50-275 P
Keimig, R. R	8305170266*	50-219 0	Kiel, o r	8305180067	XPORTLIC	KNIGHTON, G H	8305180025*	50-275 P
Keiser, H. W	8305030334	50-387 8	Kiel, o r	8305180073*	XPORTLIC	KNIGHTON, G H	8305180032*	50-275 P
Keiser, H. W	8305060442	50-387 8	Kiel, o r	8305180833	XPORTLIC	KNIGHTON, G H	8305200122	50-400 D
Keiser, H. W	8305060572	50-387 8	Kiel, o, r	8305260018	XPORTLIC	KNIGHTON, G H	8305200125*	50-400 D
KEIBER, H W,	8305110241	50-387 8	KIEL, OR KIMBRELL, M KINCAID, RH KINO, JP, KINNEMAN, J.	8305260064	XPORTLIC	Knighton, 0 h	8305200197	50-400 D
KEIBER, H. W	8305110348	50-387 8		8305270011*	50-26! P	Knighton, 0 h	8305200205	50-400 D
KEIBER, H W	8305110421	50-387 8		8305170544*	50-329 A	Knighton, 0 h	8305200209	50-400 D
KEIBER, H W	8305120422	50-387 8		8305240342	50-322 A	Knighton, 0 h	8305230003	50-528 A
KEIBER, H W	8305160124	50-387 8		8305050189	1&E	Knighton, 0 h	8305230263	50-412 A
KEIBER,H W.	8305160132	50-387 8	Kinneman, J.	8305050193	1 ME	KNIGHTON, O W	8305230273	50-528 E
KEIBER,H W	8305160140	50-387 8	Kinneman, J. D	8112160259*	40-672	KNIGHTON, O, W	8305230276	50-400 E
KEIBER,H W.	8305200555	50-387 8	Kinneman, J. D	8305050166*	40-3079	KNIGHTON, O, W	8305240038	50-528 A
KEIBER,H W.	8305200640	50-387 8	Kinneman, J. D	8305060189*	40-672	KNIGHTON, O W	8305260038	50-443 E
KEIBER,H W.	8305230471	50-387 8	Kinneman, J. D	8305060214*	40-672	KNOP, R C	8305020339#	50-441 Q
KEITH, H. N. KEITH, H. N. KELLEY, D. L. KELLEY, J. L.	8305110264* 8305110408* 8305110416* 8305170318* 8305040412	50-333 8 50-333 8 50-333 6 50-445 Q 50-400 Q	Kinneman, J. D Kinneman, J. D Kinneman, J. D Kinneman, J. D Kinney, W W	8305120530* 8305120630* 8305130031* 8305130037* 8305020332*	40-672 40-672 40-672 40-672 50-57 G	KNOP,R C KNOP,R C. KDESTER.O L KDESTER.O L KDESTER.O L	8305170013 8305240264 8305020421 8305030354 8305030378	50-461 Q 50-456 Q 50-482 F 50-482 S 50-482 S
KELLEY, J. L	8305170472	50-413 0	KINNEY, W W.	8303050236*	50-97 G	KOESTER.O L	8305030492	50-482 8
KELLEY, W. D.	8305030475#	GA999	KINNEY, W, W	8305110395*	50-223 G	KOESTER.O L	8305030622*	50-482 0
KELLEY, W. D.	8305040200#	FDIA	KINNEY, W, W.	8305250456*	50-184 G	KOESTER.O L	8305060346*	50-482 F
KELLEY, M. D	8305270307#	GA999	KINNEY, W W	8305270208*	50-184 G	KOESTER.O L	8305200335	50-482 8
KELLY, E. M.	8305030353#	50-309 Q	KINTNER, L L	8305120022	50-358 A	KOESTER.O L	8305230489*	50-482 0
KELLY, J A	8305020436	50-313 Q	KIRK,W F.	8305250582*	70-371	KGESTER, O. L	8305230567	50-482 G
KELLY, J. A	8305030308#	70-846	KIRKMAN,R W	8305120257*	40-672	KGESTER, O. L	8305310110*	50-482 G
KELLY, J. A	8305260304#	50-298 Q	KIRSCH,D F	8305060580	50-275 8	KGESTER, O. L	8305310148	50-482 G
KELLY, R. B.	8305030461	PR	KIRSCH,D F	8305130187	50-275 5	KOLTAY, P	8305100433*	50-247 G
KELLY, W J	8305240397	50-275 8	KIRSCH,D F.	8305160009	50-275 8	KOMES, J. M	8305200593*	GA777
								:

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEQURY
KOSLA: B KOSLA: B KONKLIN: J. E KONKLIN: J. E	B305020285* B305030537* B305110491 B305120129 B305170724	50-34! G 50-440 T NUREG 40-3392 40-3392	LANKBBURY,R D LANPHER,L C LANPHER,L C LANPHER,L C LANPHER,L C	8305260224# 8305050001 8305050001 8305100157 8305100157	50-440	LEVI.R P LEVI.R P LEVI.R P. LEVI.R P LEVI.R P	8305230006 8305230010* 8305230017* 8305230025* 8305230032*	ADVCM ADVCM ADVCM ADVCM ADVCM
KGSMAN.H D	8305040383*	50-278 I	LANPHER, L C	8305180341	PR	LEVI,R P	8305230040*	ADVCM
KQUTS:H J	8305110237	NUREG	Larizza, O F	8305230564*	50-244 8	LEVI,R P	8305230048*	ADVCM
KRAFT:D C.	8305200194*	50-148 G	Larson, C E	8305180352	50-263 9	LEVIN,H	8305200553	50-329 A
KRAUL:C W	8305020169*	FOIA	Lassahn, O D	8305110482	NUREC	LEVIN,H A	8304220515	50-329 A
KRAUL:C W	8305040294*	FOIA	Latham, B B	8305100201	50-322 0	LEVIN,H A	8305200575*	50-329 A
KRAUL,C W KRAUL,C W KRAUSE,D F KRAUSE,D F KRAUSE,R W	B305050333* B305050339* B305060414* B305240374* B305120439*	70-378 70-378 50-315 8 50-315 8 50-298 8	Latham, 8 8 Latham, 4 k Latham, 4 k Latham, 4 k Laurenson, 3 a	8305180449 8305060415 8305060429 8305130160 8305090496	PR 50-312 P 50-312 P 50-312 S 50-482 0	LEVIN.H A LEVINE.D L LEVINE.J M LEVINE,J M	B305310198 B305310203* B305260004* B305060591* B305260249	50-327 R 50-327 R 71-5552 50-313 F 50-368 8
KRAVITS: D L KRECHTING: J E KRECHTING: J E KRECHTING: J E	8305170070*	CONTRACT	LAURENBON, J A	8305090503	50-482 0	LEVINE, S	8305230039*	FOIA
	8305030271	50-275 R	LAURENBON, J A	8305160131	50-322 0	LEVINE, S	8305230057*	FOIA
	8305030538	50-275 R	LAWBON, L T	8305260261	50-269 J	LEVINE, S H	8305180353	PR
	8305100173	50-275 R	LAYFIELD, R L	8305030207*	70-378	LEWIS, H	8305180678*	ACRB
	8305120203	50-275 R	LAYFIELD, R L	8305030212*	70-378	LEWIS, J P	8305180047*	50-247 P
KRECHTINO, J E	8305170511 8305180377 8305230213 8305230556 8305250466	50-275 R 50-275 R 50-275 R 50-275 R 50-275 R	LAYFIELD, R L LAYFIELD, R L LAYFIELD, R L LAYFIELD, R L LAYFIELD, R L	8305030264* 8305030304* 8305030309* 8305030332* 8305040587*	70-378 70-378 70-378 70-378 70-378	LEWIS, K. B LEWIS, M I LEWIS, M I LEWIS, M I	8305160177 8305030418 8305200441 8305200456 8305240516	50-352 Q PR PR PR 50-352 Q
KRECHTING, JE KRICH, RM. KRICH, RM. KRICH, RM. KRICH, RM. KRIEGER, RW	8305310186	50-275 R	LAZARUS, H	8305030450	50-272 B	LEWIS, N. D	8305310074	50-460 Q
	8305030155	50-255 S	LAZARUS, W J	8305250465*	50-334 G	Lewis, R. C	8305100078	50-250 8
	8305030642	50-255 S	LAZO, L	8305170186	50-412 F	Lewis, R. C.	8305270202	50-259 Q
	8305100306	50-255 S	LAZO, L	8305170197	50-412 C	Lewis, R. C	8305270280	50-302 Q
	8305100377	50-206 P	LAZO, L	8305310234	50-412 F	Lewis, R. C	8305270345	50-259 Q
KRIEGER, R W	8305120166	50-206 P	LE FEBVRE, B J	8305100273*	50-334 Q	Lewib, R C	8305270349	50-387 q
KRIEGER, R W	8305120187	50-204 P	LE.N B	8305120155*	50-445 Q	Lewib, R C	8305270362*	50-257 q
KRIMM, R W	8305060506	50-247 G	LEAVERTON, H	8305240317	50-254 8	Lewib, R, C,	8305270365*	50-387 q
KRIMM, R W	8305100122	50-295 F	LEDDICK, R S	8305030489	50-50B 8	Lewib, R C	8305270394	50-338 q
KRIMM, R W	8305100143	50-289 F	LEDDICK, R S	8305160049	50-50B 8	Lewib, R C	8305270412	50-375 q
KRONZEK, A L KRUC, H E KUCZYNSKI.L A KUCZYNSKI.L A KUCZYNSKI.L A	8305120573 8305270587* 8305030338* 8305040598* 8305110247*	FOIA 50-251 G 50-387 S 50-387 S 50-387 S	LEE, B S LEE, M R LEE, D R LEE, D R	8305110127 8305120264* 8305310102 8305050214 8305050222*	NUREG 40-672 50-458 I 50-267 P 50-267 P	Lehib, R C Lewib, R C Lewib, R C Lewib, R C Lewib, R C	8305270421* 8305270433* 8305270437* 8305270474* 8305270479	50-338 Q 50-395 Q 50-338 Q 50-261 Q
KUCZYNSKI.L A	8305110358*	50-387 8	LEE, R	8305270109	NUREQ	LEWIB, R C	8305270494	50-261 Q
KUCZYNSKI.L A	8305140151*	50-387 8	LEE, T D	8305200318*	70-143	LEWIB, R C	8305270499	50-302 Q
KUCZYNSKI.L A	8305200446*	50-387 8	LEE, T D	8305270613*	70-143	LEWIB, R C	8305270507	50-387 Q
KUHNS.W O	8305020445*	50-219 I	LEECH, P H	8305110219	50-334 P	LEWIB, R C	8305270509*	50-302 Q
KUNDER.Q A	8305120335*	50-320 Y	LEFAVE, W T	8305100166*	50-443 Q	LEWIB, R C	8305270512	50-395 Q
KUNISHI,H	8305110398*	50-334 P	LEIDICH, G R.	8305040516*	50-440 T	LEWIS, R. C	8305270519*	50-375 Q
KUNKEL,T C	8305270575	50-247 H	LEMON, G E	8305200575*	50-329 A	Lewis, R. C	8305270527*	50-280 Q
KUSHNER,W	8305030459	50-354 8	LEMPOES, T E	8304110516	50-220 R	Lewis, R. C	8305270529*	50-389 Q
KUZO,G B	8305270354*	50-302 Q	LEMPOES, T E	8305060426	50-220 B	Lewis, R. C	8305270559	50-335 Q
KUOK,K	8305160043	50-20 S	LEMPOES, T E	8305060533	50-220 S	Lewis, R. C	8305270579*	50-335 Q
LABAT,V LACEY,W S LACEY,W S LACEY,W S	8305200134* 8305030311 8305110343 8305120402 8305160058	CONTRACT 50-334 8 50-334 8 50-334 8 50-334 8	LEMPOES.T E LEMPOES.T E LEMPOES.T.E LEMPOES.T E LEMAKAN.J J	8305160097 8305170393 8305200283 8305200383* 8305270236*	50-220 R 50-220 R 50-220 B 50-220 G 50-389 G	Lewie, R C Lewie, R. C Lewie, R C Liang, C Y Lichtenberger	8305270580 8305270596* 8305270621* 8305270626* 8305200072	50-324 Q 50-416 Q 50-324 Q 50-443 Q TOPREP
LACEY, W, 8	8305190185	50-334 S	LENAHAN, J J	8305270348*	50-400 G	LICITRA, E A	8305110022	50-528 A
LACEY, W 8	8305230520	50-334 8	LENAHAN, J J	8305270379*	50-389 G	LICITRA, E A	8305170219	50-528 A
LADUN, R	8305050193	14E	LENAHAN, J J	8305270632*	50-400 G	LICITRA, E. A	8305240253	50-528 A
LAFLAMME, 8 J	8305230483*	50-309 S	LENTINE, F O	8305040317	50-295 P	LIDEN, E A	8305050013	50-272 P
LAFLEUR, J D	8305230251*	FOIA	LENTINE, F O	8305170218	50-295 P	LIDEN, E. A	8305090457	50-272 P
LAGRANGE,R G	8305100419*	50-443	LENTINE, F O	8305200351	50-295 Q	Liden, E. A	8305110007	50-311 P
LAGRANGE,R G	8305100424*		LENTINE, F O	8305240473	50-295 P	Liden, E. A	6305110154	50-272 P
LAINASIG C	8305060355		LENTINE, F O	8305240506	50-295 P	Liden, E. A.	8305170328	50-272 P
LALK,H	8305250363*		LENTINE, F O	8305250077	50-295 P	Liden, E. A.	8305230094	50-311 P
LALK,H	8305250363*		LEONARD, J R	8305160286*	50-369 F	Liden, E. A	8305230504	50-272 P
LAMB,C	8305170581*	50-454 0	LEPEL, E A	8305110457	NUREG	Lieberman, J.	8305040545*	50-135 0
LAMB,C	8305170581*	50-454 0	LESSY, R P	8305030517	27-39	Liebler, G. H	8305040247*	50-3 F
LAMB,C	8305170581*	50-454 0	LESSY, R P	8305040329	50-443 G	Lin, D. L	8305110452*	50-373 R
LAMBERT,N E	8305160129	50-262 P	LESSY, R P	8305100158	50-443 G	Lindell, M	8305270046*	50-320 P
LANDERS,D F	8305270001	50-322 A	LESSY, R P	8305100219	50-443 G	Linder, F	8305020146	50-409 B
LANDGRAF, L.C	8305090480	50-341 F	Lessy, r p	8305100221*	50-443	LINDER, F	8305100025	50-409 P
LANDGRAF, L.C	8305090480	50-341 F	Lessy, r. p	8305100334		LINDER, F.	8305120066	50-409 P
LANDIS, K.D	8305200430	50-335 8	Lessy, r p	8305100356		LINDER, F	8305130112*	50-409 G
LANDRIEU, P.R.H	8305250387	50-354 R	Lessy, r p	8305100375*		LINDER, F	8305160050	50-409 F
LANDBMAN, R.B	8305100217	50-329 T	Lessy, r. p	8305100372*		LINDER, F.	8305230378	50-409 P
LANDRHAN,R B LANE,V M LANKFORD,J LANKFORD,J B	8305100261 8305270553 8305040745* 8305090461* 8305270167*	50-329 T 50-322 G 50-259 P 50-395 G 70-143	LESSY, R P. LESSY, R, P LESSY, R, P LESSY, R, P LETSCHE, K J	8305100411* 8305100425* 8305100430* 8305100432* 8305120297	50-443	LINDER, F. LINDER, F. LINDSAY, F J LINDSAY, I D LINEHAN, J J	8305240327 8305310169 8305130211* 8305100328 8305030086	50-409 G 50-409 F 50-304 B 50-458 G 40-1341
LANKFORD, J B LANKFORD, J, B LANKBBURY, R D LANKBBURY, R D LANKBBURY, R D	8305310022* 8305310134* 8305090313* 8305170403* 8305240247*	70-1201 70-1113 50-373 G 50-373 G 50-373 G	LETBCHE, K. J LETBCHE, K. J LEYI, I LEVI, I LEVI, I	8305120297 8305120329 8305120329 8305160028* 8305160028*	50-322 G 50-322 G 50-322 O 50-247 G	Linehan, J J Linehan, J. J Linehan, J J Linehan, J J Linehan, J, J,	8305060369* 8305130317 8305130333* 8305130336 8305170585	40-8783 40-4492 40-8783 40-8663 40-8084

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8305170595 8305250199 8305250270 8305250275 8305250279	40-8064 40-7869 40-8786 40-8786 40-8786	LUEBKE, E A LUKZ, F J LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8305160163 8305270100* 8305020344* 8305060402 8305060412	50-142 0 CONTRACT 50-317 G 50-317 P 50-317 G	MACDONALD, C E MACDONALD, C E MACDONALD, P E MACKAY, S D MADDEN, H	8305240556* 8305240350 8305110523 8305180040 8305020459	71-6550 71-9151 NUREO 50-324 50-219
Linehan, J J Linehan, J J Linnemann, R E Linnemann, R E Linnemann, R E	8305250283 8305250593 8305250428* 8305250428* 8305250458*	40~8697 40~8786 50~493	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUTKEN, D. C	8305170273 8305200620 8305200628* 8305200631 8305230608	50-317 P 50-317 Q 50-317 Q 50-317 R 50-416 P	MADEDA,T J MADEDA,T J MADEDA,T J MADEDA,T J MADBEN,O L	8305030521* 8305060418* 8305130834* 8305200482* 8305030157	50-264 50-275 70-1300 70-925 50-450
LINNEMANN, R E LINNEMANN, R E LINNEMANN, R E LINNEMANN, R E LINNEMANN, R E	8305250458* 8305250468* 8305250468* 8305250482* 8305250482*	50-483 G 50-483 G 50-483 D 50-483 Q 50-483 G	LUTKIN, M H LUZA, K V LYNCH, M D LYNCH, M D LYNCH, M D	8305260388 8305070162 8305110620 8305120231 8305230207	40-229 NUREG 50-341 F 50-341 A 50-341 A	MADBEN, G L MADBEN, G L MADBEN, G L MADBEN, G L MADBEN, G L	8305090066 8305100137 8305100247 8305120373 8305170004	50-128 50-458 50-445 50-445 50-382
Linville, J C Lipinski, H C Lipinski, H C Lipinski, H C	8305110391* 8305130340 8305130340 8305130349 8305130349	50-333 G ACRS ACRS 50-337 D 50-537 D	LYNCH, M D LYNCH, D D LYNN, D L LYNN, D L	8305250219 8305180030 8305180041* 8305110232* 8305110214	50-341 F 50-368 P 50-368 P CONTRACT 50-29 P	MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L	8305170212 8305170309 8305170329 8305200192 8305200251	50-498 50-445 50-278 50-148 50-382
LIBEND, R T LITTLE, B H LITTLE, W. S, LITTLE, W. B	8305110514* 8305020285* 8305130141* 8304120407 8304150362	50-333 8 50-341 G 50-240 6 50-373 G 50-440 Q	LYONB, P. J LYONB, P. J LYONB, P. J MA, J. S. MA, J. S.	8305240384 8305240395 8305240399* 8305030474* 8305270501*	40-299 40-299 40-299 50-483 @ 50-454 @	MADSEN, G L MADBEEN, G L MADBEEN, G L MADBEN, G L MADBEN, G L	8305200328 8305200416 8305200516 8305200666 8305230305	50-278 50-445 50-267 50-445 50-450
LITTLE, W. 8 LITTLE, W 8 LITTLE, W 8 LITTLE, W, 8 LITTLE, W, 8	8305020358 8305040518 8305120345 8305120361 8305120364*	50-331	MACDONALD.C MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE	8305090214 8305020002 8305020004* 8305020008* 8305030716	71-6708 71-9177 71-9177 71-9177 71-9105	MADBEN, G. L MADBEN, G. L MADBEN, G. L MADBEN, G. L MADBEN, G. L	8305230445 8305230566 8305240003 8305260301 8305310090	50-445 50-267 50-445 50-278 50-267
LITTLE, W. 8 LITTLE, W. 8 LITTLE, W. 8 LITTLE, W. 8 LITTLE, W. 8	8305120415 8305120440 8305120444* 8305170017 8305170178	50~373	MACDONALD, C. E.	8305030720* 8305040076 8305040147 8305040700 8305040772	71-9105 71-9181 71-9079 71-1 71-9106	MADBEN, O L MACHUSON, L MACHUSON, L MACHUSON, L MAIER, J E	83053 0227 8305040052 8305180818 8305240040 8305030021	50-267 XPORTLIQ XPORTLIQ XPORTLIQ 50-244
LITYLE, H 8 LITYLE, H 8 LITYLE, H 8 LITYLE, H 8 LIV, H C	6305190233 6305260236 6305260239* 6305310113 6305270492*	50~454 8 50~440 9 50~440 9 50~237 9 50~400 9	MACDONALD.C.E MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE	B305040782 B305040786 B305040791 B305050436 B305040133	71-5332 71-9901 71-6553 71-9135 71-9175	MAIER, J E MAIER, J E MAIER, J E MAIER, J E MAIER, J E	8305030352 8305050248* 8305040271 8305040404 8305110065	50-244 50-244 50-244 50-244 50-244
LIU, W. C LIVERMORE, H H LLOYD, M LOCHBAUM, D A. LOCHBAUM, D. A	8305270537* 8305170022* 8305240023* 8305240083* 8305250357	50~438 G 50~461 G 50~537 U 50~259 8 50~260 B	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8305040187 8305040190* 8305040208 8305040212* 8305090048	71-6294 71-6294 71-5979 71-5979 71-5814	MAIER, J E MAIER, J E MAIER, J E MAIER, J E MAIER, J E	8305110318 8305130084 8305160114 8305190170 8305190234	50-244 50-244 50-244 50-244 50-244
LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8305060524 8305170449 8305200459 8305230113 8305230285	50~537 E 50~537 A 50~537 B 50~537 A 50~537 A	MACDONALD, C E. MACDONALD, C E. MACDONALD, C E. MACDONALD, C E MACDONALD, C E	8305090054* 8305090113 8305090121* 8305090133 8305090140*	71-5814 71-5780 71-5980 71-5875 71-5875	MAIER, J.E. HAIER, J.E. HAIER, J.E HAIER, J.E HAIER, J.E	8305230452 8305230561 8305270578* 8305310020 8305310085	50-244 50-244 50-244 50-244, 50-244
LOCKABAUCH: A LOTITO; E. LOTITO; E. M LOTTO: A. L LOUDERBACK: T E.	8305090592* 8305200584* 8305200564 8305200525 8305160232	50~445 Q 50~317 R 50~317 R RES 40~8714	MACDONALD, C E	8305090145 8305090150# 8305110011 8305110013# 8305110015	71~5874 71~5874 71~9103 71~9103 71~4986	MAIER, J. E MAIER, J. E MAIER, J. E MALLETT, R H MALLETY, C H	8305310125 8305310218 8305310232 8305230292* 830523040159*	50~244 50~244 50~244 50~507 71~9079
LOUDERBACK, T E LOVE, R, B, LOVENDALE, P, LOVENDALE, P C LOVENDALE, P C,	8305240383 8305120428* 8305240002 8305100402* 8305170353*	40-8714 50-546 G 50-266 B 50-237 G 50-295 G	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E.	8305110017 8305110019 8305110021 8305110023 8305110033	71-9111 71-9080 71-9049 71-6717 71-9901	MALLORY,C W MALLORY,C W MALLOY,E A MALODY,C W MALODY,C W	8305230730 8305240355* 8305240517 8305100178 8305100184	71-9181 71-9181 50-247 70-1257 70-1257
LOVENDALE, P.C. LOWREY, A. LOWREY, A. LUCK, W.D. LUCK, W.D.	8305240026* 8305020550* 8305040501* 8305240370 8305110220	50-255 Q FOIA FOIA 50-537 Q 50-537 Q	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8305110035* 8305110143 8305110150 8305110151* 8305110211	71~9901 71~9044 71~9100 71~9100 71~9079	MALODY, C W MALONEY, J M MALONEY, J M MALONEY, J M MANGAN, C V	8305180642 8305170576# 8305170576# 8305170576# 8304210238	70-1257 50-454 50-454 50-454 50-410
LUCK, W. D. LUCK, W. D. LUCK, W. D. LUCK, W. D. LUCK, W. D.	8305190339 8305200636 8305200648* 8305240475 8305240480	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	MACDONALD, C. E. MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8305110412 8305110414* 8305130254 8305130241* 8305140278	71-9789 71-9789 71-493 71-493 71-6495	MANDAN, C V MANDAN, C V MANDAN, C V, MANDAN, C V MANDAN, C V	8305030515 8305040483 8305040493* 8305050030 8305050031*	50-410 50-220 50-220 50-220 50-220
LUCK, W. D. LUCK, W. D. LUCKAS, H. J. LUDHIG, W. C. LUDHIG, W. C	8305240503 8305310188 8305110119 8305110329* 8305110382*	50-537 Q 50-537 Q NUREQ 50-327 S 50-327 S	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	8305160280 8305170097 8305170102* 8305170108 8305170113*	71-9096 71-4986 71-4986 71-9010 71-9010	Mandani C. V. Mandani C. V Mandani C. V Mandani C. V Mandani C. V	8305100272 8305110315 8305130028 8305140015 8305200345	50-220 50-410 50-410 50-220 50-220
LUDWIO, W. C. LUDWIO, W. C. LUDWIO, W. C LUDWIO, W. C LUCEKE, E. A	8305200432* 8305230536* 8305250380 8305250532 8305030582	50-327 8 50-327 8 50-328 8 50-327 8 50-142 9	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E,	8305170245 8305170251* 8305170255 8305170240* 8305170584	71-9015 71-9015 71-9151 71-9151 71-6346	Mangan, C. V Mangan, C. V Mangan, C. V Mangan, C. V Mangan, C. V.	8305230574 8305240402 8305240498 8305240086 8305270026	50-410 50-220 50-410 50-410 50-220
LUEBKE, E. A LUEBKE, E. A LUEBKE, E. A, LUEBKE, E. A. LUEBKE, E. A.	8305060520 8305100330 8305130074 8305130079 8305130150	50-142 Q 50-142 Q 50-142 Q 50-142 Q 50-142 Q	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	8305170587 8305170589 8305170591 8305170592 8305180830*	71-9081 71-6601 71-9151 71-9148 71-5607	Mandan, C, V Marley, J Manno, B, F Manno, B, F Manno, B, F,	8305270075 83051300868 8305120334 8305120392 8305143073	50-220 50-244 50-410 50-410 50-410

AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	8UBJECT CATEODRY
MANNO, S F MANNO, S F MANSER, W C MANSER, W C MANSER, W C	8305250430 8305270645+ 8305030699 8305180852 8305190003	50-410 S 50-410 G 70-143 70-143 70-143	MARTIN.T T MARTIN,T T MARTIN.T T MARTIN.T T MARTIN.T T	8304250152 8305020258 8305020386 8305020395 8305050132	70-2953 50-272 G 50-309 G 50-213 G 70-466	MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V	8305050017 8305060347 8305060425 8305060566 8305060587	50-382 R 50-382 B 50-382 B 50-382 B
MANSER, W C MARCHAL, J MARCHAL, J MARCHAL, J MARCONNET, J	8305240051 8305020005 8305020076 8305070010 8305270011+	71-143 XPORTLIC XPORTLIC XPORTLIC 30-261 P	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305050134 8305050141 8305050144 8305050161 8305050176	70-1402 50-277 G 50-293 Q 40-3079 70-1224	MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8305130019 8305170223 8305170265 8305170327 8305170351	50-382 8 50-382 8 50-382 8 50-382 8
MARCUS. 0 F MARCUS. 0 F MARCUS. 0 F MARCUSON. W F MARCUSON. W F	8305200655* 8205200665* 8305200675* 8305110041* 8305170607*	50-373 P 50-373 P 50-373 P CONTRACT CONTRACT	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305050187 8305050246 8305110261 8305110276 8305110314	50-247	MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAXWELL, Q F	8305170484 8305170472 8305170500 8305180468 8305030537#	50-382 8 50-382 8 50-382 8 50-382 A 50-440 T
MARELLO,S L MARGULIES,M B MARGULIES,M B MARGULIES,M B	8305190102* 8305190296* 8305190413 8305170483 8305270014	50-327	MARTIN, T F MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305110331 8305120378 8305160018 8305170163 8305170187	50-289 Q 50-322 Q 50-219 Q 50-272 Q 50-271 Q	MAXHELL, 0 F MAXHELL, 0 F MAXHELL, J C MAXHELL, J C MAY, D C	8305270308* 8305270631* 8305130347 8305130347 8304280121	50-400 Q 50-400 Q 50-443 D 50-443 D PR
MARIANIL P MARIANIL P MARKEY.E J MARSHALL, J R	8305110012 8305250517 8305230388* 8305230735* 8303240480	PR PR 50-289 U COMMISSION 50-313 P	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305170310 8305170350 8305200382 8305200436 8305230455	50-271	MAYWEATHER.L MCALPINE.E J MCALPINE.E J MCALPINE.E J MCALPINE.E J	8304150372* 83052003(8* 8305270145* 8305270159* 8305270167*	50-341 Pt 70-143 70-1151 70-1113 70-143
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8304270426* 8305020373 8305020416 8305030331* 8305030385	50-313 F 50-348 S 50-348 P 50-313 G 50-313 S	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305230505 8305230571 8305240227 8305240285 8305250291	TOPREP 50-309 P 50-29 G 50-272 G 50-219 G	MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J	8305270254* 9305270304* 8305270480* 8305270554* 8305270613*	70-1201 50-332 G 70-1151 70-27 70-143
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8305040433 8305050125 8305050214 8305060452 8305070333	50-313 R 50-313 P 50-313 P 50-313 B 50-313 P	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305250277 8305250310 8305250314+ 8305250480 8305250488	50-277 G 50-309 G 50-309 G 50-271 G 50-412 G	MCALPINE,E J MCALPINE,E J MCALPINE,E J MCBREARTY,R A MCBRIDE,L M	8305270648* 8305310022* 8305310134* 8305250275* 8305050146	70-143 70-1201 70-1113 50-219 Q 50-267 F
MARSHALL, J R	8305090421 8305090440 8305100351 8305120414 8305120451*	50-313 J 50-313 P 50-313 P 50-313 B 50-313 Q	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305250495 8305250503 8305250571 8305270033 8305270274	50-287	MCCABE MCCABE MCCABE MCCABE	8305030118 8305060530 8305060558 8305110258 8305120412	50-278 5 50-317 6 50-277 8 50-277 8 50-277 9
MARSHALL, J R	8305160290* 8305170551 8305190363 8305200319* 8305200326	50-313 F 50-313 G 50-313 J 50-313 G 50-313 F	MARTIN, T T MARTIN, T T MARTIN, W J MARTINOVICH, M MARUCUT, C R	8305270361 8305270392 8305060233 8305020114* 8305030592*	TOPREP 50-333 G NUREG 50-373 & 50-461 R	MCCABE, E MCCABE, E. MCCABE, E. C MCCABE, E. C, MCCANN	8305020337 8305060387 8305030208* 8305110149 8305110258	50-278 19 50-277 19 50-317 0 50-387 0 50-388 8
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8305200445 8305200470 8305200541 8305200573 8305200580	50-313 S 50-313 B 50-313 P 70-348 R 50-368 P	MASON, C C MASSARD, S A MAST, L MASTERSON, V MASTERSON, V	B305240323 B305040740 B30520059B B305240381 B305270195	50-327 R NUREO 50-440 Q 50-373 S 50-373 S	MCCARTY, C.L. MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R.D	8305030707 8305120454* 8305120507* 8305120518* 8305060136*	40-9728 40-472 40-472 40-472 40-672
MARSHALL.JR MARSHALL.JR MARSHALL.JR MARSHALL.JR	8305230364 8305230723 8305240054* 8305240139 8305240360	50-313 P 50-368 P 50-313 Q 50-313 H 50-368 P	MASTERSON, V V MATHENY, D C MATHEWS, T, P MATHIS, C J, MATHIS, C J	8305060509* 8305130195* 8305170470* 8304110696 8305230535	50-379 8 50-344 8 50-285 R 50-279 8 50-279 R	MCCLINTOCK, R O MCCLINTOCK, R, O MCCOLLUM, W MCCOLLUM, W	8305120462* 8305120472* 8305140154 8305030428* 8305030428*	40-672 FOIA 50-440 Q 50-245 P 50-245 P
MARSHALL.JR MARSHALL.JR MARSHALL.JR MARSHALL.JS	8305240379 8305260260 8305270065 8305310179* 8305070517*	50-313 P 50-313 S 50-313 P 50-313 Q 50-445 T	MATHIB.C J MATHIB.J MATHIB.J L MATTHEWS.B A MATTHEWS.B A	8305230537* 8305270367* 8305270562* 8305030477 8305030486	50-293 R 50-335 G 50-370 G 50-261 H 50-261 G	MCCONNELL, T MCCORKLE, O W MCCOBKEY, R, E MCCOBKEY, R E MCCOBKEY, R E	8305160286* 8305160222* 8305020035* 8305040290* 8305050328*	50-349 F 50-312 Q FOIA FOIA 70-378
MARSHALL, W J MARSTON, R R HARTIN MARTIN, D E MARTIN, D E	8305120005 8305120338* 8305270116* 8305120384 8305090576	FOIA 50-320 T 70-1113 50-334 S WASTE MOT	MATTHEWS, B A MATTHEWS, B A MATTHEWS, H MATTHEWS, H	8305030493 8305180299 8305180452 8305250580* 8305250580*	50-261 0 50-261 0 50-261 0 50-483 0 50-483 0	MCCRORY, B L. MCCRORY, B L. MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D	8305170318# 8305230475# 8305230278 8305230324 8305230340	90-449 0 90-299 0 CONTRACT CONTRACT CONTRACT
MARTIN, D. E MARTIN, D. E MARTIN, D. E MARTIN, D. E MARTIN, J.	8305070679 8305070705 8305110183 8305170579 8305250597	WASTE MOT WASTE MGT WASTE MGT 40-299	MATTIA.H J HATTIA.H J MATTIA.H J MATTIA.H J HATTIA.H J	8305070300* 8305110232* 8305120150* 8305160312* 8305160316*	CONTRACT CONTRACT CONTRACT 50-247 O 50-247 O	MCDERMOTT, D MCDDNALD, D G MCDDNALD, D G MCDDNALD, D G, MCDDNALD, D, J	8305270070 8305070545* 8305170104 8305180541 8305070561*	CONTRACT 50-358 A 50-250 F 50-250 P 50-358 A
HARTIN, J B HARTIN, J B HARTIN, J B MARTIN, J B	8305030069 8305100011 8305260264 8305260270	50-397 Q PR 50-346 F 50-361 Q 50-275 Q	HATITAM J HATITAM J HATITAM J L HATITAM L HATITAM	8305180560* 8305180562* 8305230249* 8305230274* 8305240369*	CONTRACT CONTRACT CONTRACT CONTRACT FOIA	MCDONNELL, L J MCDUFFIE, M A MCDUFFIE, M A, MCDUFFIE, M A MCDUFFIE, M, A	8305310154 8305020124 8305060555 8305110248 8305110274	50-305 R 50-400 E 50-400 E 50-400 E
MARTIN, R E MARTIN, R E MARTIN, R E MARTIN, R E MARTIN, R E.	8305130292 8305110072 8305110079 8305130026 8305170012	RES 50-352 F 50-352 A 50-352 A	MATTIA.M J MATTIMOE,J J MATTEON.R J MATTEON,R J MATTEON,R J	8305260087* 8305230583 8305030587* 8305250221* 8305260396	CONTRACT 50-312 P 50-312 P 50-361 P TOPREP	MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A. MCDUFFIE, M. A	8305160017 8305160021 8305160107	50-400 A 50-400 E 50-400 E 50-400 E 50-400 A
MARTIN, T J. HARTIN, T, J. MARTIN, T J	8305260170 8305060470 8305110255 8305170470* 8304180541	50-352 A 50-354 S 50-354 S 50-354 Q 70-1143	MAURA:F A MAURIN,L V MAURIN,L V MAURIN,L V MAURIN,L V	8304120412* 8305020341 8305020411 8305020450 8305020479	50-373 Q 50-382 A 50-382 S 50-382 S 50-382 S	MCDUFFIE,M A MCDUFFIE,M A MCDUFFIE,M A MCDUFFIE,M A MCDUFFIE,M A	8305200329 8305200384 8305200442	50-400 E 50-400 E 50-400 E 50-400 E

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGOR
MCDUFFIE,M A MCDUFFIE,M A MCEVOY,R W MCEVOY,R W MCEVOY,R W	8305250494 8305260234 8305030163* 8305040272* 8305040556*	50-400 E 50-400 E FOIA FOIA	MCLOUGHLIN,D MGNEILL,C A MCNEILL,C A MGNEILL,C A MGNEILL,C A	B305120426* B305110259 B305110400 B305110405 B305110510	50-307 F 50-333 S 50-333 S 50-333 S 50-333 S	MILLER.J R MILLER.J R MILLER.J R MILLER.K V MILLER.K V	8305130227 8305170423 8305200472 8305250424* 8305250424*	70-1308 50-373 70-925 50-483 50-483
MCEVDY,R W	8305040557*	FOIA	MCNEILL,C A	8305130132	50-333 R	MILLER,K V	8305250544*	50-483
MCFARLAND,C R	8305270317*	50-537 G	MCNEILL,C A	8305230454	50-333 B	MILLER,K V	8305250544*	50-483
MCQARRY,J M	8305040538	50-413 Q	MCNEILL,C A	8305270189	50-333 R	MILLER,L F	8305170421*	50-361
MCQARRY,J M	8305040538	50-413 Q	MCNEILL,C A	8305270399*	50-333 G	MILLER,L K	8305170021*	50-272
MCQARRY,J M	8305070511	50-413 Q	MCNEILL,W M	8305050097*	QA777	MILLER,L K	8305170147*	50-311
MCGARRY, J M MCGARRY, J M MCGARRY, J, M MCGARRY, J M MCGARRY, J M	8305100289* 8305100289* 8305100297* 8305100297* 8305100305*	50-413	MCNEILL, W M MCNEILL, W M MCNEILL, W M MCPHERSON, D M	8305050110* 8305050177* 8305070485* 8305200478* 8305170207	GA777 GA777 GA777 GA777 GA777 50—440 G	MILLER, M A MILLER, M E MILLER, M E MILLER, M I MILLER, M, I	8305110122 8305110337 8305190204 8305120273 8305120273	50-329 50-537 50-537 50-329 50-329
MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGAUGHY, J	8305100305* 8305180358 8305240485 8305240485 83052110271	50-413 Q PR 50-413 Q 50-413 Q 50-416 S	MCGUEEN, A D MCGUEEN, A D MCGPEDON, T G MEISENHEIMER, J	8305030313 8305240393* 8305200565* 8305240517 8305190201*	50-275 S 50-275 G 50-369 G 50-247 H 50-155 P	MILLER, M S MILLER, M S MILLER, M S MILLER, M S MILLER, M T	8305050007 8305050007 8305130069 8305130069 8305050151*	50-322 50-322 50-322 50-322
MCOAUGHY, J. P.	B304110321	50-416 P	MEISENHEIMER, J	8305190284*	50-329 A	MILLER, M. T	8305240232*	50-27
MCOAUGHY, J. P.	B30411032B*	50-416 P	MEISTER, J R	8305200688*	50-373 P	MILLER, R. L	8305020036	71-9510
MCOAUGHY, J. P.	B304280037	50-416 P	MELIGI. A V	8305190303*	50-373 P	MILLER, R. W	8305270046*	50-320
MCOAUGHY, J. P.	B303030553	50-416 5	MELLO, R M	8305230292*	50-537 A	MILLER, W	8305180347*	50-331
MCOAUGHY, J. P.	B305030562	90-416 6	MENCZER, W B	8305160202	50-358 H	MILLER, W. M	8305270293*	50-389
HCQAUGHY, J P HCQAUGHY, J P HCQAUGHY, J. P HCQAUGHY, J P HCQAUGHY, J P	8305050075 8305050077 8305050131 8305050167 8305050227	50-416 F 50-416 F 50-416 B 50-416 B	MENDELSON, I N MENDEZ, R MENDONCA, M M MENDONCA, M M MENDONCA, M M	8305040345* 8305120428* 830517039* 8305170480* 8305260262*	CONTRACT 50-546 G 50-275 G 50-361 G 50-275 G	MILLER, W H MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8305270404* 8305020513 8305030679 8305050347 8305060645	50-413 50-219 50-259 TDPREP 50-312
MCOAUOHY, J. P	8305130194	50-416 S	MERRITT, S	8305060571*	50-249 S	MILLER, W O	8305070551	50-329
MCGAUGHY, J. P	9305170424	50-416 S	MERRITT, S	8305170140*	50-237 S	MILLER, W O	8305070553	50-312
MCGAUGHY, J. P.	8305170427	50-416 S	MERRITT, B	8305240335	50-237 S	MILLER, W O	8305110028	50-266
MCGAUGHY, J. P	8305170430	50-416 S	MERRITT, S	8305240494	50-237 S	MILLER, W, O	8305110144	50-295
MCGAUGHY, J. P	8305200280	50-416 S	MERRIWEATHER, N	8305260243*	50-440 G	MILLER, W O	8305180853	50-213
MCQAUQHY, J. P	8305200484	50-416 B	MERRIWEATHER, N	8305270542*	50-387 G	MILLER, W O	8305200073	50-320
MCQAUQHY, J. P	8305200523	50-416 B	MEYER, Q	8305250314*	50-309 G	MILLER, W O	8305200172	50-331
MCQAUQHY, J. P	8305200604	50-416 B	MEYER, Q N	8305230460*	50-289 G	MILLER, W O	8305200178	50-267
MCQAUQHY, J. P.	8305250072	50-416 R	MEYER, Q N	8305250306*	50-277 G	MILLER, W O	8305260372	50-259
MCQAUQHY, J. P.	8305250365	50-416 S	MEYER, T A	8305160119*	50-244 S	MILLER, W O	8305310227	50-204
MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J. P MCGAUGHY, J P MCGAUGHY, J P	8305250405 8305250434 8305250487 8305250513 8305250579	50-416 8 50-416 8 50-416 8 50-416 8	MIDDENDORF,W B MIDURA,H J MIDURA,H J MILES,E B. MILES,E B.	8305060536* 8304180491 8305130307* 8305160304 8305180557	50~352 A 50~311 S 50~272 F 50~247 G CONTRACT	MILLIGAN,M H MILLIGAN,M H MILLS,L M MILLS,L.M MILLS,L M	8305030274 8305200594* 8305030041 8305030072 8305030082	50-322 50-322 50-390 50-390 50-390
MCOAUOHY, J P. MCOAUOHY, J P MCOAUOHY, J P MCOAUOHY, J. P. MCOAUOHY, J. P.	8305270400* 8305270410* 8305270473 8305270515 8305270593*	50-416 Q 50-416 Q 50-416 B 50-416 B	MILINAZZO,P L MILINAZZO,P L MILLER,C A MILLER,D MILLER,D	B305240357* B305240363* B305110227 B305170590* B305170590*	GA797 GA797 Nureg 50-454 g 50-454 g	MILLB, L M MILLB, L M MILLB, L M MILLB, L. M. MILLS, L. M	8905030121 8905030252 8305030370 8305030434 8305030558	50-390 50-438 50-438 50-390 50-438
MCQAUQHY, J. P.	8305310065	50-416 B	HILLER, D	8305170590*	50-454 G	HILLB, L M	8305030578	50-370
MCQAUQHY, J. P.	8305310069	50-416 B	HILLER, D B.	8305170131	50-327 A	MILLB, L. M	8305030404	50-370
MCQAUQHY, J. P.	8305310146	50-416 B	MILLER, D B	8305170373	50-327 R	MILLB, L M	8305030425	50-259
MCQAUQHY, J. P.	8305310196	50-416 B	HILLER, D, B	8305170397	50-327 A	MILLB, L M	8305040253	50-390
MCQAUQHY, J. P.	8305310204	50-416 B	HILLER, D B	8305170422	50-327 A	MILLB, L M	8305040511	50-259
MCQAUQHY, J. P	8305310207	50-416 8	MILLER, D. B	8305170467	50-327 A	MILLS, L. M	8305050047	50-390
MCQRATH, R.	8305200374*	50-309 8	MILLER, D. B	8305190065	50-327 A	MILLS, L. M	8305050047	50-390
MCQRAW, T. L	8305020016*	FOIA	MILLER, D. B	8305190280	50-327 A	MILLS, L. M	8305050078	50-390
MCQREGOR, T.	8305020558*	FOIA	MILLER, D. B.	8305190298	50-327 G	MILLS, L. M	8305050120	50-438
MCQREGOR, T.	8305040158*	FOIA	MILLER, D. B.	8305200389	50-327 A	MILLS, L. M	8305050122	50-438
MCOREGOR, T. MCOREGOR, T. MCQUIRE, D. MCQUIRE, D. R. MCQUIRE, D. R.	8305040510*	FDIA	MILLER.D B	8305240353	50-329 A	MILLS, L M	8305030152	50~328
	8305050341*	FDIA	MILLER.D B.	8305240427	50-329 A	MILLS, L M	8305050188	50~390
	8304280299	50-400 8	MILLER.D.B	8305310190	50-329 A	MILLS, L. M	8305050232	50~390
	8305030371*	70-27	MILLER.D E	8305120353*	50-374 Q	MILLS, L. M	8305050243	50~390
	8305090418*	50-370 Q	MILLER.D E	8305170353*	50-295 Q	MILLS, L. M	8305100101	50~327
MCQUIRE, D.R.	8305070461*	50-395 Q	MILLER, D. E	8305190161	70-8	MILLS,L M	8305100189	50-518
MCQUIRE, D.R.	8305100109*	50-324 Q	MILLER, D. E	8305240340*	40-3392	MILLS,L M	8305100234	50-259
MCQUIRE, D.R	8305270212*	50-302 Q	MILLER, D. F	8305110491	NUREO	MILLS,L M	8305100240	50-438
MCQUIRE, B.A	8305180776	NUREQ	MILLER, D. S.	8305160099	50-309 O	MILLS,L M	8305100358	50-439
MCQURREN, H.J	8305170223	50-338 Q	MILLER, D. S.	8305160099	50-309 G	MILLS,L M	8305110292	50-439
MCINTOSH, M. D. MCKAY, E. D. MCKEEN, C. M MCKEGHN MCKEGHN	8305200440* 8305310211 8305020571* 8305100004 8305110439	50-369 F Habte Mgt Foia 50-272 B 50-286 B	MILLER, D & MILLER, D & MILLER, D & MILLER, D, S, MILLER, D &	8305170255 8305170255 8305240483 8305240493 8305240473	50~309 G 50~309 G 50~309 G 50~309 G	MILLE, L M MILLS, L M MILLS, L M MILLS, L M	8305110304 8305110317 8305110319 8305110404 8305110441	50-438 50-390 50-390 50-438 50-439
MCKEOHN, L MCKEOHN, L, MCKINNEY, C, J MCKINNEY, C J.	8305030294 8305030459 8305120434 8305050239* 8305100091*	50-286 8 50-354 8 50-272 8 50-395 8 50-395 8	MILLER, H J HILLER, J. MILLER, J MILLER, J MILLER, J	8305070461 8305020271 8305040445 8305130145 8305170557	Mabte Mot I&E 50-331 & I&E I&E	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305110505 8305130003 8305130009 8305130009 8305130133	50-391 50-259 50-390 50-439 50-390
MCKINNEY,C J	8305200515*	50-395 8	MILLER, J.	8305170037*	XPORTLIC	MILLS,L,M	8305130147	50-438
MCLAUGHLIN,L	8305250302	50-335 8	MILLER, J. R	8305020389	50-255 G	MILLS,L M	8305130154	50-438
MCLEAREN,T.	8305170648	CONTRACT	MILLER, J. R	8305030513	50-264 G	MILLS,L M	8305130217	50-390
MCLEAREN,T.	8305260206	CONTRACT	MILLER, J. R	8305100323	50-156 G	MILLS,L M	8305170145	50-327
MCLEAREN,T.	8305260377	CONTRACT	MILLER, J. R	8305100363	50-156 G	MILLS,L M	8305170237	50-566

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
MANNO.S F MANNO.S F MANSER.H C MANSER.H C MANSER.H C	8305250430 8305270645* 8305030679 8305180852 8305170003	50-410 8 50-410 0 70-143 70-143 70-143	MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T	8304250152 8305020258 8305020386 8305020395 8305050132	70-2953 50-272	MAURIN, L V	8305050017 8305060367 8305060425 8305060566 8305060587	50-382 R 50-382 S 50-382 S 50-382 S
MANSER, W C MARCHAL, J MARCHAL, J MARCHAL, J MARCONNET, J	8305240051 8305020005 8305020096 8305070010 8305270011*	71-143 XPORTLIC XPORTLIC XPORTLIC 50-261 P	MARTIN,T T HARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305050134 8305050141 8305050144 8305050161 8305050176	70-1402 50-277 G 50-293 G 40-3079 70-1224	MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8305130019 8305170223 8305170265 8305170327 8305170351	50-382 B 50-382 B 50-382 B 50-382 B
MARCUS, 0 F MARCUS, 0 F MARCUSON, W F MARCUSON, W F MARCUSON, W F	8305200659* 8305200665* 8305200675* 8305110041* 8305170607*	50-373 P 50-373 P 50-373 P CONTRACT CONTRACT	MARTIN,T T MARTIN,T T MARTIN,T Y MARTIN,T T MARTIN,T T	8305050187 8305050244 8305110241 8305110276 8305110314	50-247 Q 50-244 Q 50-277 Q 50-317 Q 50-309 Q	MAURIN,L V MAURIN,L V MAURIN,L V MAURIN,L V MAXWELL,G F	8305170484 8305170492 8305170500 8305180468 8305030537*	50-382 8 50-382 8 50-382 8 50-382 A 50-440 T
MARELLO,8 L MARELLO,8 L MARGULIES,M B MARGULIES,M B MARGULIES,M B	8305170102* 8305170276* 8305100413 8305170483 8305270014	50-329 Q 50-373 Q 50-261 G 50-308 Q 50-261 G	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305110331 8305120378 8305160018 8305190163 8305190187	50-289 Q 50-322 Q 50-219 Q 50-272 Q 50-271 Q	MAXHELL, G F MAXHELL, G F MAXHELL, J C MAXHELL, J C MAY, D C	8305270308* 8305270631* 8305130347 8305130347 8304280121	50-400 Q 50-400 Q 50-443 Q 50-443 Q
MARIANI,L P MARIANI,L P MARKEY,E J MARKEY,E J MARSHALL,J R	8305110012 8305250517 8305230388* 8305230735* 8303240480	PR PR 50-289 U COMMISSION 50-313 P	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305190310 8305190350 8305200382 8305200434 8305230455	50-271 G 70-371 50-220 G 50-334 G 50-289 G	Mayneather, L McAlpine, E J McAlpine, E J McAlpine, E. J McAlpine, E J	8304150372* 8305200318* 8305270145* 8305270157* 8305270167*	50-361 R 70-143 70-1151 70-1113 70-143
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8304270426* 8305020373 8305020416 8305030331* 8305030385	50-313 F 50-368 S 50-368 P 50-313 Q 50-313 S	MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8305230505 8305230571 8305240227 8305240285 8305250291	TOPREP 50-309 P 50-29 G 50-272 G 50-219 G	MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J	8305270254* 8305270304* 8305270480* 8305270556* 8305270613*	70-1201 50-332 q 70-1151 70-27 70-143
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8305040453 8305050125 8305050214 8305060452 8305070333	50-313 R 50-313 P 50-313 P 50-313 S 50-313 P	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305250299 8305250310 8305250314* 8305250480 8305250488	50-277 Q 50-309 Q 50-309 Q 50-271 Q 50-412 Q	MCALPINE, E J MCALPINE, E J MCALPINE, E J MCBREARTY, R A MCBRIDE, L M	8305270648+ 8305310022+ 8305310134+ 8305250275+ 8305050146	70-143 70-1201 70-1113 50-219 Q 50-267 F
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8305090421 8305090440 8305100351 8305120414 8305120451*	50-313 J 50-313 P 50-313 P 50-313 S 50-313 G	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8305250495 8305250503 8305250571 8305270033 8305270274	50-289 Q 50-286 Q 50-387 Q 50-423 Q 50-333 Q	MCCABE MCCABE MCCABE MCCABE MCCABE	8305030118 8305060530 8305060558 8305110258 8305120412	50~278 8 50~317 8 50~277 8 50~388 6 50~277 8
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8305160290* 8305170551 8305170363 8305200319* 8305200326	50-313 F 50-313 Q 50-313 J 50-313 Q 50-313 F	MARTIN, T T MARTIN, T T MARTIN, W J MARTINOVICH, M MARUCUT, C R	8305270361 8305270392 8305060233 8305020114* 8305030592*	TOPREP 50-333 G NUREQ 50-373 B 90-461 R	McCabe, e McCabe, e McCabe, e c McCabe, e, c McCann	8305020337 8305060387 8305030208* 8305110149 8305110238	50-278 B 50-277 B 50-317 G 50-367 G 50-388 B
MARSHALL.JR MARSHALL.JR MARSHALL.JR MARSHALL.JR	8305200445 8305200490 8305200541 8305200573 8305200580	50-313 8 50-313 8 50-313 P 50-368 R 50-368 P	MASON, C C MASSARO, S A MAST, L MASTERSON, V MASTERSON, V	8305240323 8305040740 8305200598 8305240381 8305270195	50-327 R NUREO 50-440 G 50-373 8 50-373 8	MCCARTY, C L MCCLINTOCK, R, MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R	8305030709 8305120454# 8305120507# 8305120518# 8305060136#	40-8728 40-672 40-672 40-672 40-672
MARSHALL.JR MARSHALL.JR MARSHALL.JR MARSHALL.JR	8305230364 8305230723 8305240054* 8305240139 8305240360	50-313 P 50-368 P 50-313 G 50-313 H 50-368 P	MASTERSON, V V MATHENY, D C MATHEWS, T P MATHIB, C J MATHIB, C J	B305050507# B305130195# B305170470# B304110494 B305230535	50-373 8 50-344 8 50-285 R 50-293 8 50-293 R	MCCLINTOCK,R D MCCLINTOCK,R D MCCLUBKEY,O MCCDLLUM,W MCCDLLUM,W	8305120462* 8305120472* 8305160136 8305030628* 8305030628*	40-672 F01A 50-440 G 50-245 P 50-245 P
MARSHALL, JR MARSHALL, JR MARSHALL, JR MARSHALL, JR MARSHALL, JS	8305240399 8305260260 8305270065 8305310199* 8305090517*	50-313 P 50-313 S 50-313 P 50-313 Q 50-445 T	MATHIB,C J MATHIB,J MATHIB,J L MATTHEMB,B A MATTHEMB,B A	8305230537* 8305270367* 8305270562* 8305030477 8305030486	50-273 R 50-335 Q 50-370 Q 50-261 H 50-261 G	MCCONNELL, T MCCORKLE, O W MCCOSKEY, R E MCCOSKEY, R E MCCOSKEY, R E	8305160286# 8305160222# 8305020035# 8305040290# 8305040290#	50-369 F 50-312 Q FOIA FOIA 70-378
MARSHALL,W H MARSTON,R R MARTIN MARTIN	8305120005 8305120338* 8305270116* 8305120384 8305070576	FOIA 50-320 T 70-1113 50-354 B WASTE MOT	MATTHEWS, B A MATTHEWS, B A MATTHEWS, H MATTHEWS, H MATTHEWS, H	8305030493 8305180299 8305180452 8305250580* 8305250580*	50-261	MCCRORY, S.L. MCCRORY, S.L. MCDERMOTT, D. MCDERMOTT, D. MCDERMOTT, D.	8305170318* 8305230475* 8305230298 8305230326 8305230340	50-445 Q 50-285 Q CONTRACT CONTRACT CONTRACT
MARTIN, D E MARTIN, D E MARTIN, D E MARTIN, D E MARTIN, D E	8305090679 8305090705 8305110183 8305170599 8305250597	WASTE MOT WASTE MOT WASTE MOT 40-299 40-299	MATTIA,M J MATTIA,M J MATTIA,M J MATTIA,M J MATTIA,M J	8305090300* 8305110232* 8305120150* 8305160312* 8305160316*	CONTRACT CONTRACT CONTRACT 50-247 G 50-247 G	MCDERMOTT, D MCDONALD, D G MCDONALD, D, G, MCDONALD, D G, MCDONALD, D J	8305270090 8305090545* 8305170104 8305180541 8305090561*	CDNTRACT 50-358 A 50-250 F 50-250 P 50-358 A
MARTIN, J MARTIN, J B MARTIN, J B MARTIN, J B MARTIN, J R	8305050164* 8305030069 8305100011 8305260264 8305260270	50-397 Q PR 50-346 F 50-361 Q 50-275 Q	MATTIA,M J HATTIA:M J HATTIA:M J HATTIA:M J HATTIA:H J	8305180560* 8305180562* 8305230249* 8305230274* 8305240369*	CONTRACT CONTRACT CONTRACT CONTRACT FOIA	MCDONNELL, L, J. MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A	8305310154 8305020124 8305040555 8305110248 8305110274	50-305 R 50-400 E 50-400 E 50-400 E 50-400 E
	8305130292 8305110072 8305110079 8305130026 8305190012	RES 50-352 F 50-352 A 50-352 A	MATTIA,M J MATTIMOE,J J MATTEON,R J MATTEON,R J MATTEON,R J	8305260087* 8305230583 8305030587* 8305250221* 8305260396	CONTRACT 50-312 P 50-312 P 50-361 P TOPREP	MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A	8305120467 8305160017 8305160021 8305160109 8305170282	50-400 A 50-400 E 50-400 E 50-400 E
	8305200170 8305060470 8305110255 8303170490* 8304180541	50-352 A 50-354 S 50-354 S 50-354 Q 70-1143	MAURA,F A. MAURIN,L V MAURIN,L V MAURIN,L V MAURIN,L V	8304120412* 8305020341 8305020411 8305020450 8305020479	50-373 G 50-382 A 50-382 E 50-382 B 50-382 B	MCDUFFIE, M A MCDUFFIE, M. A MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A	8305180400 8305200329 8305200384 8305200442 8305200676	50-400 E 50-400 E 50-400 E 50-400 E

	ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR HCDUFFIE, M A HCDUFFIE, M A HCEVOY, R W HCEVOY, R W	NUMBER 8305250494 8305260234 8305040272*	CATEGORY 50-400 E 50-400 E FOIA FOIA FOIA	MCLOUGHLIN.D MCNEILL.C A MCNEILL.C A MCNEILL.C A MCNEILL.C A	8305120426* 8305110257 8305110400 8305110405 8305110510	50-307 F 50-333 S 50-333 S 50-333 S 50-333 S	MILLER, J R MILLER, J R MILLER, J R MILLER, K V MILLER, K V	8305130227 8305170423 8305200472 8305250424* 8305250424*	70-1308 50-373 G 70-925 50-483 G 50-483 G
HCEVOY,R W MCEVOY,R W MCFARLAND,G R HCGARRY,J M MCGARRY,J M	8305040556* 8305040559* 8305270319* 8305040538 8305040538	FOIA 50-537 G 50-413 G 50-413 G 50-413 G	MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, W M	8305130132 8305230454 8305270189 8305270399* 8305050097*	50-333 R 50-333 S 50-333 R 50-333 G GA999	MILLER, K V MILLER, K V MILLER, L F MILLER, L K MILLER, L K	8305250544* 8305250544* 8305170421* 8305170021* 8305170147*	50-483 0 50-483 0 50-361 0 50-272 R 50-311 R
MCGARRY, J M MCGARRY, J, M MCGARRY, J M MCGARRY, J M	8305100289* 8305100289* 8305100297* 8305100297* 8305100297*	50-413	MCNEILL.W M MCNEILL.W M MCNEILL.W M MCNEILL.W M MCPHERSON.D M	8305050110* 8305050179* 8305070485* 8305200678* 8305190209	GA777 GA777 GA777 GA777 50-440 G	MILLER,M A MILLER,M E MILLER,M E MILLER,M I MILLER,M I	8305110122 8305110337 8305190204 8305120273 8305120273	50-329 Q 50-537 Q 50-537 Q 50-329 Q 50-329 Q
HCGARRY, J M	8305100305* 8305180358 8305240485 8305240485 8305110271	50-413 Q PR 50-413 Q 50-413 G 50-416 S	MCQUEEN, A. D MCQUEEN, A. D MCQUIRE, D. R MCSPEDON, T. G MEISENHEIMER, J	8305030313 8305240373* 8305200565* 8305240517 8305170201*	50-275 S 50-275 Q 50-369 Q 50-247 H 50-155 P	MILLER,M 8 MILLER,M 8 MILLER,M 8 MILLER,M 8 MILLER,M 8	8305050007 8305050007 8305130069 8305130069 8305050151*	50-322 G 50-322 G 50-322 G 50-322 G
MCGAUGHY, J P	8304110321 8304110328* 830428037 8305030553 8305030562	50-416 P 50-416 P 50-416 P 50-416 S 50-416 B	MEISENHEIMER. J MEISTER, J R MELIGI, A V MELLO, R M. MENCZER, W. B	6305170264* 6305200668* 6305170303* 6305230272* 8305160202	50-329 A 50-373 P 50-373 P 50-537 A 50-358 H	MILLER.M T MILLER.R L MILLER.R W MILLER.W MILLER.W H	8305240232* 8305020036 8305270046* 8305180349* 8305270293*	50-29 Q 71-9510 50-320 P 50-331 R 50-389 Q
HCQAUQHY, J P HCQAUQHY, J P HCQAUQHY, J P HCQAUQHY, J P HCQAUQHY, J P	8305050075 8305050077 8305050131 8305050147 8305050227	50-416 F 50-416 F 50-416 8 50-416 8	MENDELBON, I N MENDEZ, R MENDONCA, M M MENDONCA, M M MENDONCA, M M	8305040345* 8305120428*, 8305170339**\ 8305170480* 8305260262*	CONTRACT 50-546 G 50-275 G 50-361 G 50-275 G	MILLER.W H MILLER.W O MILLER.W.O MILLER.W O MILLER.W O	8305270404* 8305020513 8305030679 8305050347 8305060645	50-413 Q 50-219 P 50-259 X TOPREP 50-312 P
HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P	8305130194 8305170424 8305170427 8305170430 8305200280	30-416 8 50-416 8 50-416 8 50-416 8	MERRITT, B MERRITT, B MERRITT, B MERRITT, B MERRIWEATHER, N	8305040571* 8305170140* 8305240335 8305240474 8305260243*	50-249 S 50-237 S 50-237 S 50-237 S 50-237 G	MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,W O	8305090551 8305090553 8305110028 8305110144 8305180853	50-327 A 50-312 P 50-266 P 50-295 P 50-213 F
HCOAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P	8305200484 8305200523 8305200504 8305250072 8305250365	50-416 8 50-416 8 50-416 8 50-416 8	MERRIWEATHER, N MEYER, G MEYER, G W MEYER, G W MEYER, T A	8305270542* 8305250314* 8305230440* 8305250304* 8305140117*	50-389 Q 50-309 Q 50-289 Q 50-277 Q 50-244 S	MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,W O	8305200073 8305200172 8305200178 8305260372 8305310227	50-320 P 50-331 F 50-267 P 50-259 P 50-206 P
HCQAUQHY, J. P HCQAUQHY, J. P HCQAUQHY, J. P HCQAUQHY, J. F HCQAUQHY, J. P	8305250405 8305250434 8305250487 8305250513 8305250579	50-416 8 50-416 8 50-416 8 50-416 8	MIDDENDORF,W B MIDURA,H J MIDURA,H J MILEG,E.S MILEG,E.S.	8305040536* 8304180491 8305130309* 8305160304 8305180557	50-352 A 50-311 B 50-272 F 50-247 G CONTRACT	MILLIGAN, M H MILLIGAN, M H MILLB, L M MILLB, L M MILLB, L M	8305030274 8305200594* 8305030041 8305030072 8305030082	50-322 S 50-322 Q 50-370 A 50-370 B 50-370 B
HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P HCGAUGHY, J. P.	8305270400* 8305270410* 8305270473 8305270515 8305270593*	50-416 Q 50-416 Q 50-416 B 50-416 B 50-416 Q	MILINAZZO:P Ł MILINAZZO:P Ł MILLER:C A. MILLER:D MILLER:D.	8305240357* 8305240363* 8305110227 8305170590* 8305170590*	GA999 GA999 Nureq 50-454 g 50-454 g	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305030121 8305030252 8305030370 8305030434 8305030558	50-370 A 50-438 S 50-438 S 50-390 A 50-438 A
HCGAUGHY, J P HCGAUGHY, J P HCGAUGHY, J P HCGAUGHY, J P.	8305310065 8305310069 8305310146 8305310176 8305310204	50-416 8 50-416 8 50-416 8 50-416 8	MILLER, D. MILLER, D. B. MILLER, D. B. MILLER, D. B. MILLER, D. B.	8305170590* 8305170131 8305170373 8305170397 8305170422	50-434	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305030578 8305030606 8305030625 8305040253 8305040511	50-390 B 50-390 A 50-259 G 50-390 A 50-259 P
MCGAUGHY, J. P MCGRATH, R MCGRAW, T L MCGREGOR, T MCGREGOR, T	8305310207 8305200374* 8305020016* 8305020558* 8305040158*	50-416	MILLER, D B MILLER, D B MILLER, D B MILLER, D B MILLER, D B	8305170447 8305170065 8305170280 8305170278 8305200387	50-327 A 50-327 A 50-327 A 50-327 G 50-327 A	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305050047 8305050067 8305050078 8305050120 8305050122	50-390 8 50-390 8 50-390 8 50-438 8 50-438 8
MCOREGOR, T. MCOREGOR, T. MCGUIRE, D MCGUIRE, D R MCGUIRE, D R.	8305040510* 8305050361* 8304280277 8305030371* 8305070418*	F01A F01A 50-400 8 70-27 50-390 @	MILLER, D. B MILLER, D. B MILLER, D. B MILLER, D. E MILLER, D. E	8305240353 8305240427 8305310190 8305120353* 8305170353*	50-295 G	MILLB.L M MILLB.L M MILLB.L.M MILLB.L.M	8305050152 8305050188 8305050232 8305050243 8305100101	50-328 8 50-390 8 50-390 8 50-390 8 50-327 F
MCOUIRE, D. R MCOUIRE, D. R. MCOUIRE, D. R. MCOUIRE, B. A MCOUREN, H. J	8305090461* 8305100109* 8305270212* 8305180796 8305190223	50-395 Q 50-324 Q 50-302 Q NUREQ 50-338 Q	MILLER, D. E MILLER, D. E MILLER, D. P MILLER, D. S MILLER, D. S	8305190161 8305240340* 8305110491 8305160099 8305160099	NUREG 50-309 G 50-309 G	MILLB, L M MILLB, L M MILLB, L M MILLB, L M	8305100189 8305100234 8305100240 8305100358 8305110292	50-518 A 50-259 F 50-438 A 50-438 A 50-439 8
HCINTOBH, M D HCKAYE, D, HCKEEN, C M HCKEOHN HCKEOHN	8305200440* 8305310211 8305020571* 8305100004 8305110439	50-369 P HASTE MOT FOIA 50-272 B 50-286 B	MILLER.D S. MILLER.D S MILLER.D S MILLER.D,S MILLER.D S	8305170255 8305170255 8305240483 8305240473 8305240473	50-309 9 50-309 0 50-309 0 50-309 0	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8305110304 8305110317 8305110319 8305110406 8305110441	50-438 8 50-390 8 50-370 8 50-438 8 50-439 8
MCKEOHN, L. HCKEOHN, L HCKEOHN, L HCKINNEY, C. J HCKINNEY, C J	8305030294 8305030459 8305120434 8305050239* 8305100091*	50-286 8 50-354 8 50-272 8 50-375 8 50-375 8	MILLER, H. J MILLER, J MILLER, J MILLER, J MILLER, J	8305090661 8305020271 8305040445 8305130165 8305170557	WASTE MOT I&E 50-331 S I&E I&E	MILLS, L M MILLS, L M MILLS, L M	8305110505 8305130003 8305130020 8305130089 8305130133	50-391 8 50-239 P 50-390 E 50-439 S 50-390 B
HCKINNEY; C J. HCLAUGHLIN; L. HCLEAREN; T. HCLEAREN; T. HCLEAREN; T.	8305200515* 8305250302 8305170648 8305260206 8305260377	50-395 B 50-335 B CONTRACT CONTRACT CONTRACT	Hiller, J. Miller, J. R. Miller, J. R. Miller, J. R. Miller, J. R	8305170057: 8305020387 8305030513 8305100323 8305100363	* XPDRTLIC 50-255 Q 50-264 Q 50-156 Q 50-156 Q	MILLS.L.M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8305130154 8305130154 8305130217 8305170145 8305170237	50-438 8 50-390 8 50-327 P 50-566 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	5UBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEOURY
MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305170288 8305170299 8305200187 8305200274 8305200275	50-370 8 50-370 8 50-438 8 50-370 8 50-370 8	MODNEY, O MODNEY, G MODNEY, G MODNEY, G MONTGOMERY, J M	8305230047 * 8305030713 8305160209 8305250241 8305110403 *	FDIA 40-8697 40-8502 40-8697 50-247 S	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRILL, P W	8305240219 8305240341 8305260293 8305310038 8305310102	50-346 8 50-346 8 50-346 8 50-346 8 50-458 I
MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8305200325 8305200343 8305200387 8305200519 8305200569	50-390 A 50-390 S 50-390 S 50-438 S 50-438 S	MOONEY, J MOONEY, J MOONEY, T MOONEY, T R MOONE, D E	8305160079* 8305250483 8305020564* 8305040519* 8305090418*	50-247 8 50-247 5 FOIA FOIA 50-390 0	MUBELER, W J MUBELER, W J MUBOLF, D MUBOLF, D MUBOLF, D	8305180244 8305180324* 8305020320 8305020488 8305030403	50-322 Q 50-322 Q 50-282 Q 50-263 8 50-263 K
MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8305230433 8305230447 8305230482 8305230545 8305230551	50-370 8 50-370 8 50-370 8 50-438 5 50-438 5	MOCRE, D E. MOCRE, J E MOCRE, R N MOCRE, R N MOCRE, R N	8305270212* 8305020451 8305090782 8305160306 8305170609	50-302 G 50-247 G XPORTLIC XPORTLIC XPORTLIC	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8305120387 8305140054 8305140072 8305230523 8305240153	50-282 P 50-282 R 50-263 R 50-282 F 50-306 8
MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8305230565 8305230569 8305230575 8305250421 8305250425	50-438	MDDRE, R N MDDRHEAD, C J MDRGAN, C MDRGAN, C MDRGAN, C	8305170611 8305230703 8305030549 8305030549 8305100208	XPORTLIC 50-289 U 50-247 0 50-247 0 50-247 0	MUSOLF, D MUSOLF, D MYERS, D MYERS, L MYRASO, A L	8305240166 8305250409 8305270635* 8305040466* 8305160098*	50-282 8 PR 50-324 Q TOPREP 50-263 R
MILLS:L M MILLS:L M MILLS:L M MILLS:L M MILLS:L M	8305250435 8305270021 8305270030 8305270133 8305270171	50-370 8 50-257 P 50-257 P 50-370 0 50-257 0	MORGAN, C MORGAN, C MORGAN, C MORGAN, C MORGAN, C	8305100208 8305130064 8305130064 8305130071 8305130071	50-247 G 50-247 G 50-247 G 50-247 G 50-247 G	NADEAU, J P NAIDU, K R NAPUDA, G NAPUDA, G NARDACCI, G A	8305250331 8305120368* 8305230460* 8305250314* 8305020215*	50-443 H 50-374 Q 50-289 Q 50-309 Q 50-289 R
MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8305270177 8305270206* 8305270355* 8305270386* 8305270547*	50-259 Q 50-259 Q 50-259 Q 50-438 Q 50-390 Q	MORGAN, C MORGAN, C MORIARTY, J M MORLEY, J A MORRILL, P J	8305240466 8305240466 8305020133 8305110142 8305260272*	50-247	NARDACCI, G A NARDI, A J NARDDCI, P B NARDDCI, P, B NARDDCI, P, B	8305040465* 8305180019 8305190003* 8305110283* 8305170249*	50-289 R 71-9070 50-369 8 50-369 8 50-370 8
MILLB:L M MILLB:L M MILLS:L M MILLS:L M MILLS:L M	8305270597* 8305270408* 8305270452* 8305270440* 8305310037	50-438 Q 50-438 Q 50-259 Q 50-259 Q 50-390 E	MORRIBON, & M MORROW, R MORTENSEN, W P MORTON, D K MORTON, K V	8305110433* 8305070003* 8305100074 8305030474* 8305040643*	50-309 8 0A979 50-513 5 50-483 0 CONTRACT	NARDUCI,P.B NARDUCI,P.B NARDUCI,P.B NARDUCI,P.B NARDUCI,P.B	8305170358* 8305250404 8305250439 8305250459 8305310052	50-349 B 50-349 B 50-370 B 50-370 B 50-349 B
MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	6305310053 8305310077 8305310138 8305310147 8305310172	50-327 P 50-327 0 50-438 8 50-327 F 50-390 S	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8305060326* 8305120517* 8305170077* 8305230169* 8305230311*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	NARROW, L M NASH, B NEIGHBORB, J D NEIGHBORB, J D NEJFELT, G	8305050119* 8305050304* 8305090045 8305090321 8305130186	50-443
MILLS.L M MILLS.L M MILLS,L M MINECK.D L MINECK.D L	8305310187 8305310193 8305310214 8305030394 8305060472	50-327 P 50-438 S 50-438 9 50-331 S 50-331 S	MORTON, K V	8305230332* 8305260341* 8305270093* 8305270105* 8305180670	CONTRACT CONTRACT CONTRACT CONTRACT 71-6272	NEJFELT.O M NELBON.P R NELBON.P R NELBON.P R NELBON.P R	8305110262 8305120307* 8305120450* 8305120478* 8305120483*	50-370 8 40-672 40-672 40-672 40-672
MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L.	8305130094 8305180346 8305240221 8305240236 8305270429	50-331 S 50-331 R 50-331 S 50-331 S	MOBER, R M MOSLAK, T MOTHERSBAUGH, L MOTHERSBAUGH, L MOTL, O. P	8305230080 8305030164* 8305030218* 8305040414* 8305230165	70-378	NELSON, PR NELSON, PR NELSON, RH NELSON, RL NERSES, V	B305120509* B305120514* B305060545* B305020356* B305170141	40-672 40-672 50-309 8 50-305 9 50-335 F
MINECK,D L MINER,S MINER,S MINER,8 MINOGUE,R B	B305270440 B211180501* B305040365 B305140213* B305030722*	50-331 8 50-312 0 50-269 P 50-312 0 REVIEW GRP	MOTILIO P MOWRY: W R MOWRY: W R MOWRY: W R MROCZKA: E J	8305230176* 8305040395 8305060490 8305180839* 8305060501	XPORTLIC XPORTLIC	NEVEL, M NEWMAN, J H NEWMAN, J R NEWMAN, J R, NEWMAN, J, R,	8305180367* 8305240517 8305020434 8305020434 8305060499	50-322 H 50-247 H 50-498 Q 50-498 Q
MINDQUE,R B MINDGUE,R B MINDR.G C MIRAGLIA,F J MIRAGLIA,F J	8305110493* 8305200623* 8305160068 8305120613* 8305260306	REVIEW ORP REVIEW GRP 50-443 G Misc 50-458 E	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8305170010 8305170010 8305230549 8305270089 8305270089	50-336 R 50-336 R 50-245 S 50-336 S 50-336 S	NEWMAN, J. R. NEWMAN, J. R. NEWMAN, K. A. NEWMAN, P. T. NEWTON, C. E.	8305110225 8305110225 8305240355 8305040421* 8305040596	50-498 9 50-498 9 FDIA 50-400 9 MISC
MIB, F J MIBAK, A MIBAK, A MITCHELL, O J MITCHELL, G J	8305180814 8305040391* 8305170374* 8305110584* 8305110401*	71-7080 50-234 S 50-254 R COMMISSION COMMISSION	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MUDUFFIE, M A	8305270239 8305270239 8305270454 8305270454 8305270023	50-336 8 50-336 8 50-336 8 50-336 9 50-400 £	NEYLAN, A, J NEYLAN, A, J, NEYMOTIN, L NICHOLS, F	8305020367 8305020432 8305020435 8305110131 8305110162	50-358 A 50-358 A 50-358 A NUREO NUREO
MITCHELL.J MITCHELL.J MITCHELL.J A MITTL.R L MIZUNO,G S	8305250340* 8305250340* 8305100248* 8305310185 8305030464	50-483 Q 50-483 G 90-329 T 50-354 V 50-445 Q	MULKIKIN,R P MULKIN,R MUMA,F E MURPHY,D. MURPHY,D W	8305100249* 8305230176* 8305260180 8305110367* 8207080528*	70-1193 50-155 Q 50-259 B	NICHOLS, L L NICHOLS, L L NICHOLSON, N A NICHOLSON, N A	8011180782* 8305040596 8305040596 8303280182* 8305270502*	MISC MISC 40-2061 50-305 Q
MIZUNO, O S MIZUNO, O S MIZUNO, O S MIZUNO, O S	8305030483 8305030490 8305040540* 8305090548 8305130033	50-537	MURPHY, D K MURPHY, J L MURPHY, J L MURPHY, J L MURPHY, M E	8305120374; 8305170593; 8305170593; 8305170593; 8305100361	* 50-454	NIGHTINGALE,E NILSON,R NIMITZ,R L NIX,H NIX,H,C	8305260231* 8305240310 8305170174* 8305030690* 8305030687*	50-35B Q TOPREF 50-272 Q 50-321 F 50-321 F
MOLCHANY, W J MONTEL, O MONTEL, G MONTGOMERY, D	8305110160 8305170572* 8305170572* 8305170572* 8305270086*	50-387 P 50-454 Q 50-454 Q 50-454 Q 50-375 Q	MURPHY, M E MURPHY, W P MURRAY, B MURRAY, T, D MURRAY, T D	8305230475 8305170006 8305240005 8305060608 8305060702	50-271 R * 50-445 Q * 50-346 F	NIX,H C NIX,H C NIX,H C NIX,H C NIX,H C.	8305050030 8305050083 8305110269 8305110289	50-321 8 50-321 8 50-321 8 50-321 8 50-321 8
MONTGOMERY, D M MONTGOMERY, D M MONTGOMERY, J MONTGOMERY, J L MONTGOMERY, J L	8305270354* 8305270528* 8305120023* 8305120014* 8305120019*	50-902	MURRAY, T D	8305130093 8305130190 8305170162 8305170201 8305190149	50-346 8 50-346 8 50-346 8	NIX,H C NIX,H C NIX,H.C. NIX,H.C	8305110364 8305110375 8305110404 8305110410 8305110429	50-321 8 50-366 8 50-321 8 50-366 8 50-366 8

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIX,H C NIX,H C NIX,H C NIX,H C NIX,H C	8305110431 8305130235 8305170178 8305170254 8305170276	50-321 8 50-321 8 50-321 8 50-321 8 50-326 8	NOVAK.T M NOVAK.T M NOVAK.T M NOVAK.T M NOVAK.T M	8305240097 8305250209 8305250267 8305260122 8305260205	50-369 P 50-361 P 50-369 P 50-361 P 50-508 E	ORTIZ.N R OBHIMA:B OBTER, J OSTER, J OUBDE:R P	8305170122 830502053 8305230500 8305240339 8305240326	NUREG XPORTLIC 50-10 J 70-2973 50-312 R
NIX, H. C NIX, H. C NIX, H. C NIX, H. C	8305170389 8305170434 8305170442 8305170481 8305170502	50-366 8 50-321 8 50-321 8 50-366 8 50-366 8	D JAPON D JANON D JANO	8305200300* 8305270573 8305240357 8305030268* 8305030296*	30-260 S 50-443 O 40-2259 70-378 70-378	OWCZARBKI,P C OWCZARBKI,P C OWEN,W H OWEN,W H PAGANO,F G	8305250148 8305250174 8305050008 8305180351 8203150093*	RES RES 50~413 A PR 50~443 F
NIX, H C NIX, H, C NIX, H C NIX, H C NIX, H C	8305180279 8305230463 8305230486 8305230495 8305230568	50-321 R 50-366 8 50-366 8 50-366 8 50-321 8	NUBBBAUMER, D NUBBBAUMER, D NUBBBAUMER, D NUBBBAUMER, D NUBBBAUMER, D A	B305040687* B305030320* B305040584* B305040603* B305050292*	70-378 70-378 70-378 70-378 70-378	PAGAND, F G PAGE, R G PAGE, R G PAGE, R G PAGE, R G	8305270210 8305030074 8305030237 8305030706 8305040707	50-482 E 70-1257 40-8027 40-2061 40-8035
NIX.H C NIX.H C NIX.H C NIX.H C	8305270123 8305270234 8305310124 8305310166 8305310180	50-366 8 50-321 8 50-366 8 50-321 8 50-321 8	NUSSBAUMER, D A	B305050301* B305050312* B305050319* B305050324* B305120283*	70-378 70-378 70-378 70-378 40-672	PAGE, R G PAGE, R O PAGE, R O PAGE, R O PAGE, R G	830516017B 8305180176 8305180317 8305180325 8305180759	70~27 40~6500 40~7708 40~86 40~8406
NIX:H C NOLF:D.M NOLF:D.M NORDERHAUG:L R NORDERHAUG:L R	8305310206 8305040326* 8305170077* 8303240506 8305030313	50-366 8 CONTRACT CONTRACT 70-25 50-275 8	NYKIRK, J W NYKIRK, J W NYKIRK, J W NYKIRK, J W	6305030091* 6305030117* 9305100382* 8305100395* 8305170480*	50-295 F 50-295 F 50-438 A 50-438 A 50-361 G	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8305180765 8305180820 8305180824 8305180834 8305180850	70-992 40-8406 40-7708 40-8763 70-925
NORDERHAUG, LR NORDERHAUG, LR NORDERHAUG, LR NORDERHAUG, LR NORDERHAUG, LR.	8305100074 8305100127 8305240314 8305260242 8305270115	50-513 8 70-734 50-312 G 50-206 G 50-312 8	O'HEA,P B O'NEIL,J H O'NEIL,J. H O'NEILL,B O'NEILL,B	8305030181 8305240550 8305240550 8305030164* 8305160199*	71-9100 50-400 0 50-400 0 50-320 0 50-289 0	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8305180858 8305180859 8305190001 8305190004 8305190008	70-124 70-792 70-33 70-2973 70-33
Norelius, C e Norelius, C e Norelius, C. e Norelius, C. e Norelius, C. e	8305020094 8305020110 8305020128 8305020224 8305020264	50-373 Q 50-456 Q 50-266 P 50-456 Q 50-341 Q	O'NEILL, J O'NEILL, J O'NEILL, J O'NEILL, J H	8305060437 8305120287 8305240528 8305170245 8305200630	PR 50-155	PACE.R G PACE.R.O PACE.R G PACE.R G PACE.R G	8305200154 8305200159 8305200165* 8305250601 8305250603	40-770B 70-2982 70-2982 70-33 40-8027
NORELIUB, C E NORELIUB, C E NORELIUB, C E. NORELIUB, C E. NORELIUB, C. E	8305020274* 8305020347 8305020349 8305060441 8305100087	50-341 Q 50-315 G 50-305 Q 50-237 Q 50-305 Q	O'NEILLY, J P O'REILLY, J P O'REILLY, J P O'REILL, J H	6305200630 8305240512 8305090191 8305090454 8305120316#	50~400 0 50~440 0 50~259 0 50~375 0 40~672	PAGE,R G PAGE,R.G PALLADIND,N PALLADIND,N PALLADIND,N J	8305250605 8305310217 8305230209* 8305240167* 8305100141*	70-371 WASTE MOT 50-320 T COMMISSION 50-329 T
NORELIUS, C E NORELIUS, C E NORELIUS, C E NORELIUS, C E NORELIUS, C, E	8305100076 8305170275 8305170477 8305170495 8305170128*	50-346 G 50-255 G 50-373 P 50-315 Q 50-373 G	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8305120356* 8305120376* 8305120598 8305120404* 8305250541	40~672 40~672 50~250 @ 50~250 @ 50~280 @	PALLADIND, N J	8305130060 8305130070 8305230354 8305230360 8305230377	50-277 0 50-322 0 COMMISSION COMMISSION 50-289 U
NORELIUB, C. E NORELIUB, C E. NORELIUB, C E NORELIUB, C. E NORELIUB, C E.	8305170376* 8305200512 8305240241 8305240244* 8305240301	50-327	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8305250546* 8305270275 8305270425 8305270461 8305270513	50-280 Q 50-414 Q 50-269 Q 50-261 Q 50-280 Q	PALLADIND, N J	8305230384 8305230377 8305230413 8305230420 8305230435	ADVCM COMMISSION COMMISSION COMMISSION 50-289 U
NORELIUG, C. E NORELIUS, C. E. NORELIUS, C. E. NORKIN, D. P. NORRHOLM, L.	8305240524 8305260278 8305260315 8305030474* 8305100258	50-454 G 50-454 G 50-331 G 50-483 G 50-272 B	O'REILLY, J P O'REILLY, J P O'ROURKE, A P O'ROURKE, A P, O'TOOLE, J	8305270585 8305270664* 8305240533 8305240539* 8305250483	50-416 Q 50-259 Q 50-247 T 50-247 T 50-247 B	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8305230446* 8305230457 8305230465 8305230474 8305230660	COMMISSION COMMISSION COMMISSION
NORRHOLM, L NORRHOLM, L NORRHOLM, L. J. NORRY, P. Q. NORTON, J. F.	8305200497 8305250238 8305250314* 8305240036 8305040522*	50-272 S 50-272 S 50-309 G GRO 50-305 G	0/T00LE, J, D 0/T00LE, J, D 0/T00LE, J D 0/T00LE, J D 0/T00LE, J D	8305030373 8305030400 8305040242* 8305100175 8305110302	50-247 8 50-247 8 50-3 F 50-247 P 50-3 R	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8305230676* 8305230692 8305230732 8305240084* 8305240155	50-3 F COMMISSION COMMISSION COMMISSION COMMISSION
NOTHELFER, T NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M	8305200307* 8305020502 8305030013 8305040010 8305040289	50-237 8 50-382 A 50-528 A 50-395 P 50-397 A	0.100Fe7 p 0.100Fe7 p 0.100Fe7 p 0.100Fe7 p 0.100Fe7 p	9305110373 9305130018 9305130022* 9305160020 9305160075	50-247 5 50-247 P 50-247 P 50-247 S 50-247 S	PALLADINO:N J PALLADINO:N J PALLADINO:N J PALLADINO:N J PALLADINO:N J	B305240179* B305240252 B305240256* B305310059 B303280136*	CDMM18810N 50-358 Q 50-358 Q 50-247 U 50-315 S
NOVAK, T. M. NOVAK, T. M. NOVAK, T. M NOVAK, T. M NOVAK, T. M.	8305040780 8305040008 8305090277 8305090594 8305090722	50-322 G 50-382 B 50-440 A 50-327 E 50-445 A	DBERG, C.R. DDEGAARDEN, R.H. DDEGAARDEN, R.H. DDEGAARDEN, R.H. DESTMANN, M.J.	8305170009* 8305040302 8305060204 8305170573 8305170248*	50~382 G TOPREP TOPREP 71~4639 50~454 G	PALMER,R A PALMER,R A. PALMER,R A. PALMER,R. A PALMER,R A	8305020177* 8305020178* 8305060406* 8305130174* 8305130171*	50-316 8 50-316 8 50-315 8 50-314 8 50-315 8
NOVAK: T. H. NOVAK: T. H. NOVAK: T. M NOVAK: T. M. NOVAK: T. M.	8305110140 8305120569 8305130344* 8305160240 8305170093	50-327 A 50-416 G 50-382 A 50-445 G 50-358 A	OEBTMANN, M. J DOLE, K. M. OKADA, S. OLLER, R. E. DLLER, R. E.	8305270270* 8305040357 8305240317 8305030344* 8305050111*	50-341 G 40-8714 XPURTLIC GA999 GA999	PALMER,R A PALMER,R A PALMER,R A PALMER,R A. PALMER,R.A.	8305240330 8305270107 8305270227* 8305270230* 8305270444	50-315 & 50-315 & 50-314 & 50-314 & 50-315 & \$
NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M NOVAK, T. M	8305170615 8305170721 8305170723 8305180213 8305200015	50-413 E 50-460 A 50-369 P 50-327 P 50-373 P	OLLINGER, W H OLSEN, A F OLSHAN, L N OPREA, G. W. OPREA, G W.	9305040654* 9305020523 9305110216 9305030430 9305060456	50-321 F 70-824 50-454 A PR 50-478 8	Palmer, R A. Pandey, B Pandey, B Pangburn, C. C Pangburn, C. C	8305310179 8207210332* 8305200720* 8305250245 8305250591	50-316 S 50-336 P 50-338 P 40-8452 40-8452
NOVAK; T. M. NOVAK; T. M NOVAK; T. M. NOVAK; T. M. NOVAK; T. M.	8305200179* 8305200723 8305230155 8305230624 8305230717	50-362 Q 50-275 R 50-508 A 50-390 A 50-369 8	OPREA, Q. W OPREA, Q. W OPREA, Q. W ORDERS, H. ORNBTEIN, H. L	8305170510 8305230416 8305230525 8305270160* 8211110645*	50-478 8 50-478 8 50-478 8 50-367 9 50-312 8	PAPAY,L T PAPAZOGLOU,I A PAPERIELLO,C PAPERIELLO,C PAPERIELLO,C J	8305090278 8305110126 8305180080* 8305240002 8305030336	50-361 Q 50-312 P FOIA : 50-266 \$ 50-10 Q

	•							
AUTHOR PAPERIELLO, C J	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8305040423 8305100080 8305120344 8305130149 8305170238	40-8202 50-346 Q 50-374 Q 50-373 F 50~454 Q	PEERY,W W PELIZZA,M S PELL,W R PELLET,J L PELLETIER,J P	8305270458* 8305160228 8305190059 8211100028* 8305050101	50-395 Q 40-8786 50-322 H 50-312 S 50-271 S	PLISCO, L. R PLISCO, L. R PLISCO, L. R PLOSKI, T. J PLOSKI, T. J	8305250230* 8305250445* 8305250504* 8305270614*	50-286 Q 50-336 Q 50-213 Q 50-346 Q
PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8305170337 8305170344* 8305170503 8305170548 8305170161	50-295 Q 50-295 Q 50-315 Q 70-1308 70-8	PELLETIER, J P PENNER, P S PENNIFILL, R A PENTZ, D L PERCH, R	8305050108* 8305180334 8305070606 8305050404* 8305100426	50-271 S PR TOM STEAH CONTRACT 50-388 A	PLUMMER,M C POCHAL, POCHAL,W POCHAL,W F POLK,P J	8305200307* 8305090015 8305240330 8305130303 830513030284	50-237 8 XPORTLIC XPORTLIC XPORTLIC
PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8303240020 8303240284 8305240337 8303240376 8305240389	50-255 Q 50-331 Q 40-3392 50-155 F 50-282 F	PERENSTEIN, J E PERLIS.R O PERLIS.R O PERLIS.R O PERLIS.R O	8305040643* 8305070143 8305100334 8305100375* 8305100425*	CONTRACT 50-498 0 50-443 0 50-443 0 50-443 0	POLLOCK, M S	8305050107 8305120306* 8305120310* 8305120380* 8305180331*	50-286 P 50-322 Q 50-322 Q 50-322 Q 50-322 Q
PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PARIS,O H PARIS,O H	8305270261 8305270605 8305310176 8305040464 8305090458	50-341 0 50-346 0 50-331 0 50-247 6 50-247 G	PERLIS,R G PERLMAN.J PERNY.C PERRY.J F PESCHEL.J	8305110339 8305180412 8305070461# 8305120341# 8305020348#	50-498	POLLOCK,R H POMEROY,P W POMEROY,P W POOLE,J W POPPE,L K	8305190302* 8305130352 8305130352 8305200352* 8305170733	50-322 Q 50-373 P 50-443 Q 50-443 Q 71-5026
PARIB, O H PARIB, P. C PARIB, P. C PARKER, L. B PARKER, L. B	8305130030 8305030412* 8305200412* 8305050241* 8305270286*	50-247 G 50-286 P 50-286 F GA779 GA799	PETERS,R PETERSEN,J C PETRICK,N A PETRICK,N A PETRICK,N A	B305230459* B305200624* B305110014 B305110047 B305130007	50-333 8 50-142 T 50-482 A 50-482 E 50-482 A	PORTER, B J. PORTER, D W PORTER, W A POSNER, P POSNER, P	8305270145 8305050164* 8305090073* 8305030633* 8305240543	State Prog 50-397 Q 50-128 Q 50-247 Q
PARKER.M E PARKER.P E PARKER.P E PARKER.W O	8305170174* 8305140363 8305230041 8305230056* 8305020326	50-155 Q PROJ PROJ PROJ 50-413 A	PETRICK,N A PETRICK,N A PETTENGILL,H J PETTENGILL,H J PEYTENGILL,H J	8305180393 8305310175 8305120490 8305120496 8305120501	50-482 E 50-482 A 40-8602 40-3453 40-299	POTAPOVS, U. POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305020254 8305020261 8305020289 8305020316	QA999 QA999 QA999 QA999
PARKER, W O PARSONS, R M PARSONS, R M PARSONS, R M PARGONS, R M	8305240259* 8305050124 8305050185 8305050259 8305130027	50-287 P 50-400 8 50-400 S 50-400 S 50-400 S	PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8305130297 8305130317 8305130328 8305160259* 8305250245	40-3453 40-8584 40-6622 40-8675 40-8452	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305020346 8305020364 8305020366* 8305020448	QA777 QA777 QA777 QA777 QA777
PARSONS, R M	8305130080 8305130216 8305230442 8305270281* 8305270383*	50-400 S 50-400 S 50-400 G 50-400 Q	PETYENGILL.H J PETYFJ C PETYY,J C PETYY,J C PETYY,J C	8305250591 8305250594 8305110335* 8305170338* 8305170544*	40-8452 40-8550 50-270 8 50-269 8	POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U	8305030330 8305030349 8305030358 8305030343 8305030377	9A797 9A797 9A797 9A777 9A777
PARSONS.R M PASCIAK.W J PASCUA.M J PASTVA.M J PASTVA.M J	8305270615* 8305110277* 8305200071* 8305030361* 8305030419*	50-400 Q 50-317 Q CONTRACT 50-324 S 50-324 S	PFAFF, S J PFEFFERLEN, M C PFLUM, C O PHILIPPACOPOULO PHILLIP, G A	8305020439 8305040458 8305110178 8305110227 8305190061*	40-6659 TOPREP WASTE MOT NUREG FOIA	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305030413 8305030427 8305030466 8305030509 8305030544	GA799 GA799 GA799 GA799 GA799
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J	8305030473* 8305030534* 8305030547* 8305030618* 8305050244*	50~325 8 50~324 8 50~324 8 50~324 8 50~324 8	PHILLIPS.D PHILLIPS.H S PHILLIPS.H S PHILLIPS.H S PHILLIPS.H S	9305200598 8305020403 8305050117* 8305050192* 8305050262*	50-440 G ORO GA999 GA999 GA999	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305050068 8305050088 8305050094 8305050102 8305050107	GA999 GA999 GA999 GA999
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PATE.D S	8305050267* 8305110284* 8305130172* 8305130184* 8305030972	50-324 S 50-325 S 50-324 S 50-324 S 50-537 G	PHILLIPS.H S PHILLIPS.H W PHILLIPS.M W PHILLIPS.R W PICKARD.J K	8305070413* 8305120155* 8305270614* 8305170367* 8305270110*	GA999 50-445 G 50-346 G 50-373 P CONTRACT	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305050177	GA777 GA777 GA777 GA777 GA777
PATE.R J PATERBON.D A PATTERBON.J D PATTERBON.J P PATTERBON.J W	8305170480* 8305110402* 8305200461 8305310181* 8305040403*	50-361 G 50-255 R PR 50-331 G FDIA	PICKEL.T W PICKEL.T W PIEHUL.R H PIEHONTESE.A P. PIEHONTESE.A P	8305130346 8305130346 8305240327 8305110430* 8305230477*	ACRS ACRS 50-315 8 50-387 S 50-387 S	POTAPDVB, U POTAPDVB, U, POTAPOVS, U, POTAPOVS, U	8305050237 8305050251 8305070001 8305070371	GA999 GA999 GA999 GA999 GA999
PATTERSON, W F PATTERSON, W F PATTERSON, W F PATTERSON, W F	8305270029 8305100158 8305100221* 8305100392* 8305100411*	50-317 P 50-443 G 50-443 G 50-443 G 50-443 G	PIERCE.F W PIERGE.R L PIERINGER.P A PIERINGER.P A PIGOTT.D R	8305240547 8305170693* 8305030388* 8305230528* 8305190175	50-247 Q CDNTRACT 50-318 S 50-361 S	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305090392 8305090450 8305100336 8305100343#	GA999 GA999 GA999 GA999 GA999
PATTERSON,W F PATTERSON,W F PAUL,R A PAUL,R A PAULK, G L	8305100430* 8305100432* 8305100402* 8305240292* 8305270381*	50-443 G 50-443 G 50-237 G 50-331 G 50-259 G	PIOOTT.D R PIOOTT.D R PIOOTT.D R PIOOTT.D R PILANT.J M	8305190195 8305190212 8305190212 8305190252 8305020449	50~361 Q 50~361 Q 50~361 Q 50~361 G 50~298 P	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305120394 8305120482 8305170541 8305170549	GA999 GA999 GA999 GA999 GA999
PAULSON, W A	8305030414 8305050038 8305040225 8305240243 8305230540*	50-206 P 50-206 P 50-206 P 50-206 P 50-317 B	PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8305030393 8305030554 8305050113 8305060380 8305270369	50-278 P 50-278 P 50-278 P 50-278 I 50-278 P	POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U	8305200323# 8305200333 8305200370 8305200411	0A779 0A779 0A779 0A779 0A777
PAYNE, M T PAYNE, M T PAYNE, M T PAYNE, M T PEARSON, A	8305240500 8305240500 8305240507 8305240507 8305240507	50-400 G 50-400 G 50-400 G 50-400 G XPURTLIC	PILANT, M PLAINE, H H PLAINE, H H E PLAYT, W E PLIML, G	8305030588 8305230700 8305230443* 8305240482 8305030084*	50-278 P 50-289 G 50-289 U 50-529 G 50-295 F	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8305200443 (8305200446 (8305200462* (8305200589 (94777 94777 94777 94777
PEARSON, A PECK, C C. PECK, C C PEDRO, J PEERY, H W	8305130305 8305060634* 8305240340* 8305230059 8305230059	XPORTLIC 40-8202 40-3392 FOIA 50-62 Q	PLIML, G PLIML. G PLISCO, L PLISCO, L PLISCO, L	8305030114* 8305060679* 8305110508* 8305250443* 8305230460*	50-275 F 50-275 F 50-333 G 50-245 G 50-269 G	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305230497 (8305230514 (8305240333 (8305240336 (1477 1477 1477 1477 1477 1477

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	4.174.57	ACCESSION	SUBJECT		ACCESSION	SUBSECT
POTAPOVS, U	8305240352	GA999	AUTHOR RAY, H B	NUMBER 	CATEGORY 50-362 B	AUTHOR REYES, L A	NUMBER	CATEGOR
POTAPOVS, U POTAPOVS, U POTAPOVS, U	B305240361* B305240400 B305240405 B305240411	GA999 GA999 PT21 GA999	RAY, H B RAY, H B RAY, H B RAY, H B	8305040447 8305040505 8305040514* 8305140011	50-361 S 50-361 S 50-361 S 50-361 S	REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R	8305170403# 8305260224# 8305110212 8305110383 8305120285	50-373 50-440 50-275 50-275 50-275
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8305240419 8305240424 8305240426 8305240433* 8305260291	GA999 GA999 GA999 GA999 GA999	RAY, H. B RAY, H B RAY, H B RAY, H B RAY, H B	8305160014* 8305160047 8305160051* 8305160055 8305160069*	50~361 S 50~362 B 50~362 S 50~361 S	REYNOLDS.J R REYNOLDS.J W REYNOLDS.N S REYNOLDS.N S	8305120285 8305240565* 8303290382 8303290382	50-275 50-155 50-397 50-397
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTTERFIELD, A POTTERFIELD, A	9305270267 8305270291 8305270302 8305030408 8305030408	QA979 GA979 GA979 50~247 G 50~247 G	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	B305160101* B305160110 B305160115* B305160120 B305160125*	50-361 8 50-362 8 50-362 8 50-362 8 50-362 8	REYNOLDS.N S REYNOLDS.N S REYNOLDS.N S REYNOLDS.N S REYNOLDS.N S REYNOLDS.N S	8305020473 8305020473 8305050007 8305050007 8305050018	50~440 50~440 50~440 50~440
POTTERFIELD, A POTTERFIELD, A POTTERFIELD, A POTTERFIELD, A POULK, R M	8305030408 8305030641* 8305030641* 8305030652* 8305130176*	50-247 G 50-247 G 50-247 G 50-247 G 50-324 S	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8305270131 8305270157 8305270243 8305270321 8305270408	50-361 8 50-362 8 50-361 8 50-361 8	REYNOLDS: N S	8305050018 8305050019 8305060491 8305060491 8305060491	50-445 50-460 50-460 50-508 50-508
POULK.R M POULOS.8 J POWERE,D A POWERS,D A	8305200543* 8305060384* 8305030337 8305120556 8305120556	50-324 8 50-329 A TOPREP 50-537 0 50-537 0	READE.M T REAVIB.J A REAVIB.J A REAVIB.J H REBELLO.J E	8305310211 8305170460* 8305170540* 8305180063* 8305040553*	WASTE MOT 50-269 R 50-369 R FOIA CONTRACT	REYNOLDS, N S	8305070507 8305100270 8305100270 8305100275 8305100275	50-445 50-445 50-445 50-445 50-445
PRELL.J.A PRICHARD.R P PRICHARD.R P PRITCHETT.P A PROCTOR.S D	8305250306* 8305180210 8305240064 8305110398* 8305100264	50-277	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8305040251* 8305110008* 8305110152* 8305110172* 8305110178*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	REYNOLDS, N S	8305100321 8305100321 8305100260 8305130260 8305170516	50-445 50-445 50-445 50-445 50-460
PROCTOR, 8. D PROCTOR, 8 D PROCTOR, 8 D PROCTOR, 8 D PROCTOR, 8 D	8305100264 8305100418 8305240373 8305240491 8305240491	50-327 G 50-327 G 50-327 G 50-329 G 50-329 G	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	B305120560* B305130300* B305130361* B305180047* B305180792*	CONTRACT CONTRACT CONTRACT 50-247 P CONTRACT	REYNOLDS, N S REYNOLDS, N S REYNOLDS, S REYNOLDS, S REYNOLDS, S	8305170516 8305180447 8305250406 8305110338* 8305240321	50-460 PR PR 50-287 50-254
PROVENZANO, V P PROVENZANO, V P PUCEL, P PUNTENNEY, J PURPLE, R A	8305040441 8305040509 8305030709 8305230229 8303280325*	50-327 Q 50-329 Q 40-8728 FOIA 50-302 P	REBELGWEKI.T H REDANO.R T REDMOND.R F REDWANZ.F J REED.C	8305250309* 8305170333* 8305110192* 8305180284* 8305020234*	50-219	REYNOLDE.S D REYNOLDS.S D REZNICEK,B W RHEE.S RHODE,G K	8305050147* 8305250507* 8305230588 8305240207 8305040043	50-277 50-284 50-285 50-237 50-220
PURPLE, R A. PURPLE, R A PURPLE, R A PURPLE, R A QUEEN, W O	8304120042* 8305170645* 8305180548* 8305180566* 8305020081*	50-321 P 50-301 P 50-298 P 50-324 P 70-378	REED, C REED, C REED, C REED, C REED, J R	8305060554* 8305170167 8305170184* 8305200621 8305240544	50-373 Q 50-254 Q 50-254 Q 50-373 P 50-440 Q	RHODE, Q. K RHODE, Q. K RHODES, M RICCARDELLA, P RICE, D. A	8305040044* 8305230582* 8305030244* 8305040055* 8305050248*	50~220 50~410 40~8027 50~321 50~29
QUEEN, W O QUEEN, W O QUEEN, W O QUEEN, H O,	B305020537* B305040040* B305040468* B305030357* B305270303*	70-378 70-378 70-378 FOIA 50-390 @	REEDY, R F REESIDE, B, REESIDE, W O REEVES, E A REGAN, N A	8305180427 8305040260* 8305040246* 8305070016 8305040637	50-275 R 50-367 S 50-369 B 50-348 P XPORTLIC	RICHARDS, B L RICHARDS, B L RICHARDS, J RICHARDS, S RICHARDS, W J	8305270147* 8305310022* 8305050254 8305250505* 8305180353	70~143 70~1201 50~416 50~289 PR
RAHE, E, P RAHE, E, P RAHE, E P RAHE, E P RAHE, E P	8304180548 8305030424 8305050200 8305070212 8305110427	TOPREP TOPREP TOPREP PROJ 50-934 8	REHM, T REHM, T A REHM, T A REHM, T A REHM, T A	8305020545 8305040777 8305110135 8305170717 8305180236*	50-329 A COMMISSION COMMISSION COMMISSION 50-498 A	RICHARDSON, J D RICHARDSON, J D RICHARDSON, J D RICHMOND, J S RICHTER, L	9305130126 9305130126 9305250072 9305310164 9305130095*	50-416 50-416 50-416 50-305 50-346
RAHE; E, P RAHE; E, P RAHE; E P RAHE; E P RAHE; E P,	8305170408 8305170554 9305180262 8305200304 8305230255	50-454 T TOPREP TOPREP PR TOPREP	REHM, T A REMM, T A REHRIO, A W REHRIO, A W REHRIO, A W	8305230121 8305250183 8305020560* 8305030260* 8305040183*	COMMISSION 50-287 G FOIA 70-378 FOIA	RICHTER, L. RIDDLE, D H RIDGWAY, D RIDGWAY, D RIDGWAY, D	8305170171* 8304270399 8305120391 8305120391 8305060488	50-346 71-9135 50-482 50-482 50-482
RAHE, E. P RAHE, E. P RAJAN RAJAN, J. R RAJKI, 8	8305270006 8305270481 8305170413* 8305070578* 8305170452	TOPREP TOPREP 50-454 T 50-445 Q 50-440 Q	REIMANN, F W REIMANN, F W REIMERB, O A REIMERB, G A REINMUTH, O W	8305170304* 8305260224* 8305030396* 8305240236 8305180083*	50-341 Q 50-440 Q 50-331 B 50-331 B 50-498 Q	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D. A RIDGWAY, D. A RIDGWAY, K R	8305130137 8305130429 8305130429 8305240487 8305230139*	50-261 50-382 50-382 50-289 70-1193
RAMSDELL, J V RAMSDEN, J J RAMSDEN, J J RAMSDEN, J J RAMSDEN, J J	8305180782 8305040093* 8305040114* 8305050342* 8305050351*	NUREQ FOIA FOIA FOIA	REIS,M P REIVITZ.L REMICK.F J REMLEY.M E REMLEY.H E	B305160176* B305040660* B111030653* B305310219 B305310220*	50-275 P CONTRACT FOIA 70-25 70-25	RILEY, E J RILEY, J L RILEY, J L RILEY, R W RING, M A	8305060145* 8305060252 8305060252 8305230428* 8305020357*	FOIA 50-413 50-413 COMMISSIO 50-483
RAMSEY,C. RANDALL,R G RANDALL,R G RANDALL,R G RANDALL,W,I	8305120447* 8305060428* 8305060540* 8305200290* 8305020425	50-373 Q 50-220 8 50-220 8 50-220 8 50-220 8	RENNER, A E REPKA, D A REPKA, D, A REPKA, D A REPKA, D A	8305120304 8305100222 8305170563 8305200590 8305260271	50-440	RIPLING, E J RIBBO, R, P RITCHIE, L T RITTER, D RIVENBARK, G W	8305110512 8305180562* 8305180562* 8305210703 8305230703	NUREG CONTRACT NUREG 50~289 50~364
RANDALL, W I RANDAZZA, J, B RATCLIFF, R H RAMBON, R. J, RAMBON, R. J,	8305020429* 8305030491 8305040165* 8305170545 8305250367	50-443 Q 50-309 P FOIA 50-322 Q 50-322 Q	requa. O Requa. O Requa. O Regua. O Rebetar, J	8305060378 8305060678 8305110618 8305160346 8305270454	50-261 P 50-261 P 50-261 F 50-261 P 50-336 S	RIVENBARK, C W ROBBINS, J. O ROBERDS, H W ROBERDS, H W ROBERTS, E	8305040748 8305160063 8305100116* 8305230480* 8305110398*	50-321 TOPREP 50-482 50-482
RAY,H,B RAY,H,B RAY,H,B RAY,H,B RAY,H,B	8305030354 8305030359# 8305030340 8305030432 8305040448	50-361 8 50-361 8 50-361 8 50-361 8 50-362 8	REBBLER, W C. REVER, W T REYEB, L A. REYEB, L A REVEB, L A	8305020210 9305100391 9304120412* 9305020357* 9305170304*	50-289 R 50-322 G 50-373 Q 50-483 G 50-341 Q	ROBERTS: H R ROBERTS: S ROBERTS: W ROBINSON, D ROBINSON, D.	8305020481 8304070286* 8305110089* 8305020171* 8305020312*	40-8681 50-269 50-373 50-316 50-315

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY
ROBINSON, D	8305020321*	50-315 8	ROTHSCHILD, M U	8305030514	50-445	BAMICKI.J	8304040374*	50-322 U
ROBINSON, D	8305040411*	50-315 8	ROTHSCHILD, M U	8305040557		BCALETTI.D C	8305120078*	50-70 P
ROBINSON, D	8305120324*	50-316 8	ROTHSCHILD, M U	8305090568		BCARAND.R A	8305170515	50-361 Q
ROBINSON, D	8305240145	50-316 8	ROTHSCHILD, M U	8305130013		BCARAND.R A	8305240373*	50-275 G
ROBINSON, D	8305240345	50-315 8	ROTHSCHILD, M U	8305140147		BCHAEFER.D W	8305270115	50-312 B
ROBINSON, R G	8305030416	PR	ROTHSCHILD,M U	8305270015	50-445 G	BCHAEFFER, M A	8305270035*	50-320 P
ROBINSON, R G	8305200296	PR	ROUSE,L C	8305040072	PROJ	BCHAPKER, J F	8305270496*	50-518 Q
ROCKETT, D R	8305240046	71-146	ROUSE,L C	8305130276	PROJ	BCHEPPACH, R C	8305260380*	CONTRACT
RODGERS, H R	8305250526	50-327 B	ROUSE,L C	8305170568	70-8	BCHERER, A E	8305020400	50-470 E
RODRIGUEZ, P	8305190220	50-247 G	ROUSE,L C	8305170570*	70-8	BCHERER, A E	8305090338	50-470 E
RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J	8305020383 8305020384 8305020415 8305020483 8305030287	50-312 P 50-312 P 50-312 G 50-312 S	ROWE, C ROWE, C A ROWBOME, F ROY, D. H ROY, G W	8305060209* 8305050166* 8305100245* 8305030410 8305230207*	40-672 40-3079 50-329 T TOPREP 40-1478	SCHERER, A E SCHERER, A E SCHERER, A E SCHERER, A E SCHERER, A E	8305120120 8305120185 8305130081 8305170324 8305170527	50-470 B 50-470 E 50-470 E 50-470 A 50-335 B
RODRIGUEZ.R J	8305030551	50-312 B	ROJAK, S	8305270270*	50-341 Q	SCHERER, A E	8305200548	50-470 E
RODRIGUEZ.R J	8305040417	50-312 P	RUBENBTEIN, D	8301120436*	50-247 P	BCHMIDT, H C	8305100125	50-445 A
RODRIGUEZ.R J	8305100227	50-312 P	RUBENBTEIN, D	8305050287*	50-247 P	BCHMIDT, H C	8305100130	50-445 R
RODRIGUEZ.R J	8305100274	50-312 P	RUBENBTEIN, L	8304150458*	50-454 F	BCHMIDT, H C	8305310151	50-445 A
RODRIGUEZ.R J	8305100338	50-312 P	RUBIN, B	8305040737*	50-259 P	BCHMIDT, W H	8305050432	NUREG
RODRIGUEZ,R J	8305100344	50-312 P	RUBIN.S	8305040745*	50-259 P	SCHMITT, H	8305180116*	FOIA
RODRIGUEZ,R J	8305100381	50-312 G	RUDD.C C.	8305170214	50-440 0	SCHMITTDIEL, F	8305060651	40-8697
RODRIGUEZ,R J	8305130105	50-312 S	RUDIN.L	8305240517	50-247 H	SCHMUTZ, T. A	8305110445	50-537 Q
RODRIGUEZ,R J	8305130163	50-312 S	RUDY.C R	8305180117	40-6500	SCHNAUTZ, C E	8305260330	XPORTLIC
RODRIGUEZ,R J	8305130219	50-312 S	RUESHAUSEN.O M	8305110152*	Contract	SCHNELL, D F	8303240307	50-483 A
RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J ROGAN,R E ROGERS,H R	8305230454 8305270080 8305310171 8305240534 8304170537*	50-312 Q 50-312 Q 50-312 P 50-217 Q 50-327 B	RUFF, A B. RUITER, Q. H. RULAND, W. H RUNCO, F RUNCO, F	8305270618* 8305130251* 8305270370* 8305180459* 8305180461*	50-43B G 50-305 R 50-34B G 50-322 H 50-322 H	SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHNELL, D F	8304150354 8305030263* 8305060293* 8305170136* 8305170188*	50-482 8 50-483 9 50-483 9 50-483 9
RDGERS, H. R	8305030183*	50-327 8	RUNKLE, J	8305040532	50-400	SCHNELL, D F	8305170227*	50-483 0
RDGERS, H. R	8305050204*	50-327 9	RUNKLE, J	8305040532		SCHNELL, D F	8305200518*	50-483 0
RDGERS, H. R	8305050224*	50-328 8	RUNKLE, J.	8305090475		SCHROCK, C A	8305170271*	50-305 8
RDGERS, H. R	8305110417*	50-328 8	RUSLING, D H	8305180334		SCHROEDER, B A	8305130202*	50-237 R
RDGERS, H. R	8305200581*	50-327 9	RUSSELL, L B.	8305030383		SCHROEDER, C W	8304290034	50-373 P
ROGERS, H R	8305250342	50-328 8	RUSSELL.L B	8305060635*	50-317 F	BCHROEDER, C W	8305030161	50-373 P
ROGERS, H R	8305250400	50-328 8	RUSSELL.L B	8305110352	50-317 8	BCHROEDER, C W	8305060569*	50-373 G
ROGERS, L C	8305120347*	50-320 T	RUSSELL.L B	8305160081	50-318 8	BCHROEDER, C W	8305100352	50-374 S
ROGERS, P	8305020378*	50-368 8	RUSSELL.L B	8305190287	50-317 8	BCHROEDER, C W	8305110082	50-373 P
ROGERS, P.	8305030390*	50-313 8	RUSSELL.L B	8305190348	50-318 5	BCHROEDER, C W	8305190353*	50-373 P
ROGERS, P.	8305040454*	50-313 S	RUSSELL, L B	8305230510	50-317 8	SCHROEDER, C W	8305230584	50-373 P
ROGERS, P	8305120418*	50-313 S	RUSSELL, L B	8305230522	50-318 8	SCHROEDER, C W	8305240110	50-373 P
ROGERS, W H	8305030690*	50-321 F	RUSSELL, L B.	8305230555	50-317 8	SCHROEDER, C W	8305240111	50-374 A
ROGOE, J	8305270160*	50-369 G	RUSSELL, L B.	8305270072	50-317 8	SCHULER, R. T.	8305240517	50-247 H
ROGGE, J F	8305130138	50-321 S	RUSSELL, L B	8305270603	50-317 8	SCHULER, R. T	8305240517	50-247 H
ROHATOI.U S ROHRER.D M ROHRER.M V ROHRER.M V ROHRER.M V	8305110131 8305070584* 8305050261* 8305110279* 8305170426*	NUREG 50-445 G 50-416 S 50-416 S 50-416 S	RUSSO:H L RUSSO:H L RUTLEDGE:C RUTTENBERG:J I RUZICKA:W O.	8305200315* 8305200332* 8305260144 8305120296 8305170504*	GA799 GA799 40~8502 50~352	SCHULER, T. R SCHULER, T R SCHULLKE, D. A SCHULTZ, C SCHULZ, R. D.	8305190175* 9305190238* 8305030226* 9305060444* 8305190334*	50-244 B 50-244 B 50-282 F 50-295 B 50-410 Q
RDHRER, M V	8305200493*	50-416 B	HUZICKA, W O	8305170508*	50-34 G	BCHUMACHER, D G	8305100160*	50-482 0
ROHRER, M V	8305200532*	50-416 B	Ruzicka, W O	8305180334	PR	BCHUMACHER, M	8305110176	NUREQ
ROHRER, M V	8305250487	50-416 S	Ryan, R F	8305120344*	50-320 T	BCHUMACHER, M	8305270270*	50-341 0
ROHRER, M V	8305310065	50-416 S	Rybak, B	8304040268	50-237 G	BCHUMACHER, M C	8303280182*	40-2061
ROHRER, M V	8305310207	50-416 S	Rybak, B	8305020458	50-254 P	BCHUMACHER, M C	8305170248*	50-454 Q
RDIBMAN, A Z	8305180792*	CONTRACT	Rybak, B,	8305040446	50-237 P	BCHUMACHER, M C	8305270502*	50-305 G
ROLEG, Q W	8305090567	Waste mot	Rybak, B	8305040520	50-237 P	BCHUYLER, J D	8305020388	50-275 P
ROMAN, T W	8305170395*	50-220 R	Rybak, B	8305040551	50-237 P	BCHUYLER, J D	8305040328*	50-275 P
ROMANO, F R	8305040470	50-352 G	Rybak, B	8305050043	50-254 P	BCHUYLER, J D	8305310135*	50-275 P
ROMANO, F, R	8305260181	50-352 G	Rybak, B	8305100092	50-237 G	BCHWENCER, A.	8303300772	50-387 P
ROMO, L R ROONEY, V L ROONEY, V L ROONEY, V L ROONEY, V L	8305170376# 8305110045# 8305170069 8305180073# 8305180229#	50-329 H 50-331 P 50-271 P 50-331 P 50-293 P	RYBAK, B RYBAK, B RYBAK, B RYBAK, B	8305100190* 8305130038 8305130209 8305180376 8305200295	50-10 9 50-237 P 50-237 P 50-237 P 50-237 B	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A, SCHWENCER, A	8304290013 8305030106 8305040527 8305040616 8305040669	50-352 F 50-458 E 50-352 A 50-387 P 50-387 P
ROOT, L D	8305030131	50-331	Rybak, B	8305240245	50-237 F	BCHWENCER, A	8305040677	50-458 A
ROOT, L D	8305040389		Rybak, B	8305250377	50-237 G	BCHWENCER, A	8305050366	50-387 Q
ROOT, L D	8305060060		Rybak, B	8305260290	50-237 P	BCHWENCER, A	8305050402	50-373 F
ROOT, L D	8305100075		Rybak, B.	8305270395	50-237 G	BCHWENCER, A	8305090602	50-458 A
ROOT, L D	8305100320		Rybak, B	8305270419	50-237 P	BCHWENCER, A	8305090633	50-410 A
RDOT, L D	B305100372*	50-331 @	Rybak, B.	8305310037		SCHWENCER, A	8305090648#	50-410 A
ROOT, L D	B305230562	50-331 P	Saltzman, J	8305180787		SCHWENCER, A	8305110171	50-373 P
RDOT, L D	B305240120	50-331 P	Samp, R. A	8305070337		SCHWENCER, A	8305110616	50-458 E
RDOT, L D,	B305240511	50-331 @	Banchez, R. L	8305180056*		SCHWENCER, A,	8305120580	50-373 P
ROOT, L E,	B305230293*	CONTRACT	Banders, W. F	8305270328*		SCHWENCER, A	8305120593#	50-373 P
ROBAK, B	8305270502*	50-305 Q	SANDERS, W F	8305270337*	TOPREP	BCHHENCER, A	8305170604	50-459 E
ROBANO, R	8305020252	50-295 Q	SANDOZ, S A	8305040464		BCHHENCER, A	8305170705*	50-461 A
ROBE, J J	8305040514*	50-322 E	SANDOUIST, G M.	8305190380*		BCHHENCER, A	8305200071	50-387 F
ROBB, F W	8305060367*	40-8783	SANTORO, M P	8305180194		BCHHENCER, A	8305200176	50-387 P
ROSG, F. W	8305170595	40-8064	SARQENT, A, V	8305090501		BCHHENCER, A	8305250082	50-397 E
ROSS,W J	8305270574*	50-280 G	SAROENT, A V	8305070502*	50-338 P	BCHWENCER, A,	8305260327*	50-352 Q
ROSSBACH, L W	8305100410*	50-286 G	SAROENT, I	8208060247*		BCHWENCER, A	8305260348	50-458 E
ROSSIC E	8305090640*	50-443 G	SAROENT, I H	8305310241*		BCHWENCER, A	8305270028	50-416 F
ROSZIOCZY, Z R.	8208250506*	50-373 P	SARSTEN, O E	8305200495		BCHWENCER, A	8305270039	50-458 A
ROTE, A	8305200656	50-440 G	SAUBERMAN, A	8305240517		BCHWINK, W	8305170718	REVIEW ORP

AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SCHWINK, W	8305200535	REVIEW GRP	Selan, J C	8207020602*	50-335 P	SHERWOOD. 0 G	8305020355	50-447 E
SCOTT, D E	8305270438*	50-416 Q	Selan, J C	8304060471*	50-335 P		8305030403	50-447 A
SCOTT, D J	8305020246	50-249 S	Seljon, R	8305200656	50-440 G		8305090495*	TGPREP
SCOTT, D J	8305060416	50-237 S	Sells, D E	8305110105	50-335 P		8305100298	50-447 E
SCOTT, D J	8305060484	50-237 S	Sells, D E	8305120146	50-335 P		8305200157	50-447 A
U 0.11038 U 0.11038 U 0.11038 U 0.11038 U 0.11038	8305060511 8305060563 8305060581 8305060590 8305060603	50-237 8 50-247 8 50-249 8 50-237 6 50-237 8	SELLS.DE SELLS.DE SELLS.DE SEMMEL,H	8305120499 8305120520 8305170103 8305240599 8305100290	50-335 P 50-335 P 50-335 P 50-335 P 50-155 Q	SHERWOOD, G G SHERWOOD, G G SHEWMAKER, R E SHIELDS, S W SHIELDS, S W	8305260037 8305260048* 8305030474* 8304250147 8305020118	50-447 E 50-447 E 50-483 Q 50-546 A 50-546 B
0 0,11038 U 0,11038 U 0,11038 U 0,11038	8305130197 8305170134 8305170159 8305240202 8305240207	50-237 R 50-237 S 50-237 S 50-237 S 50-237 S	SEMMEL, H SEMMEL, H SEMMEL, H SEMMEL, H	8305100290 8305190366 8305190366 8305190371* 8305190371*	50-155 Q 50-155 Q 50-155 Q 50-155 Q 50-155 Q	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8305020291 8305040494 8305120457 8305130119 8305130207	50-546 S 50-546 S 50-546 A 50-546 A 50-546 S
8017.0 J 8017.0 J 8017.0 J 8017.0 J 8017.0 J	8305240335 8305240366 8305240474 8305310149 8305310158	50-237 8 50-249 8 50-237 8 50-237 8 50-237 8	BEMMEL,H BENCER,D J BERKIZ,A W BERKIZ,A W	8305170375* 8305170264 8305170007* 8305170118 8305170123	50-155 G State Prog 70-2973 NUREG NUREG	SHIELDS.S W SHIELDS.S W SHIELDS.S W SHIELDS.S W	8305170306 8305170306 8305200289 8305230289 8305230654	50-546 A 50-546 A 50-546 F 50-546 F 50-546 A
SCOTT, D J SCOTT, D J SCOTTON, L N SCURRY, N SCURRY, N	8305310165 8305310182 8305100144* 8305040001 8305040003	50-237 B 50-237 B 50-293 R 50-293 R ORG ORG	BERNE, R J BERRANG, W BESTAK, F BESTAK, F SESTAK, F	8305040233 8304220257* 8305030282* 8305030545* 8305100179*	NUREG 50-321 P 50-275 R 50-275 R 50-275 R	SHIELDS, S W SHIELDS, B W SHIFFER, J D SHIFFER, J D SHIFFER, J D	8305240408 8305240332 8305170334 8305240397 8305270249	50-546 S 50-546 S 50-133 S 50-275 S 50-275 S
BCURRÝ, N BEARB, C F BEARB, C F BEARB, C F BEARB, C, F	8305070006 8305030404 8305030404 8305060213 8305060213	ORG 50-245 P 50-245 P 50-213 F 50-213 F	Sestak, F Sestak, F Sestak, F Sestak, F. Sestak, F	8305100185* 8305120211* 8305120214* 8305170517* 8305230221*	50~275 R 50~275 R 50~275 R 50~275 R 50~275 R	SHIMA.S SHINE.C SHINE.C SHINE.C	8305020557* 8305110518 8305030624* 8305030624* 8305050261*	XPORTLIC NUREG 50-245 P 50-245 P 50-416 B
SEARS, C.F. SEARS, C.F SEARS, C.F SEARS, C.F. SEARS, C.F.	8305060455 8305060455 8305070404 8305070465 8305070465	50-423 8 50-423 8 50-213 P 50-213 P	SESTAK, F SESTAK, F SESTAK, F SEYFRIT, K V SEYFRIT, K V	8305230559* 8305250467* 8305310191* 8211150068* 8305180181*	50-275 R 50-275 R 50-275 R 50-312 G 50-498 G	SHINOLETON, E B SHINOLETON, E B SHINOLETON, E B SHINOLETON, E B SHIRAKAWA, T	8305110279* 8305170426* 8305310065 8305310207 8305170575	50-416 8 50-416 8 50-416 8 50-416 8 XPORTLIC
BEARB, C F	8305070465	50-213 P	SEYFRIT,K V	8305200684*	50-973 P	SHIRAKAWA: T	8305170580	XPORTLIC
BEARB, C F.	8305070471	50-245 P	SEYMOUR,L A	8305260222*	CONTRACT	SHIRAKAWA: T	8305170582	XPORTLIC
BEARB, C. F	8305070471	50-245 P	SHACKLETON,O C	8305090038*	FOIA	SHIRAKAWA: T	8305180627	XPORTLIC
SEARB, C. F.	8305100385	50-213 P	SHACKLETON,O C	8305090043*	FOIA	SHIRAKAWA: T	8305180817	XPORTLIC
SEARB, C F.	8305120241	50-336 P	SHACKLETON,O C	8305090047*	FOIA	SHIRAKAWA: T	8305180826	XPORTLIC
SEARB,C F	8305120241	50-336 P	SHACKLETON, O C	8305090055#	FOIA	SHIVELY, C	8305180447	50-36B P
SEARB,C F	8305140183	50-213 P	SHACKLETON, O C	8305090057#	FOIA	BHOEMAKER, C J	8305030550	50-352 Q
SEARB,C.F.	8305250510	50-213 P	SHAFER, W	8305020511	50-331 8	SHOEMAKER, C J	8305040504	50-358 Q
SEARB,C.F.	8305250510	50-213 P	SHAFER, W D	8305020100	50-10 0	SHOEMAKER, C J	8305110345	PROJ
SEARB,C F	8305270034	50-423 B	SHAFER, W D	8305100181	50-10 0	SHOEMAKER, C J	8305110350	50-358 Q
BEARB, C. F.	8305270036	50-423 8	SHAFER, W D.	8305100215	50-331	SHOEMAKER.C J	8305120314	50-483 G
BEARB, C. F	8305270037 *	50-423 0	SHAFER, W. D.	8305100216*		SHOEMAKER.C J	8305120317	50-289 G
BEARB, C. F.	8305270037 *	50-423 0	SHAFER, W D	8305100217		SHOEMAKER.C J	8305130083	50-483 G
BEARB, C. F	8305270074	50-336 9	SHAFER, W. D	8305100261		SHOEMAKER.C J	8305200657	50-275 G
BEARB, C. F	8305270074	50-336 0	SHAFER, W D	8305100262		SHOEMAKER.C J	8305240520	50-155 G
SEARS,C F. SEARS,C.F SEARS,F SEAVER,D A. SEIDENSTICKER	8305270114 8305270114 8305200340* 8305110528 8305130350	50-245 P 50-245 P GA999 NUREO 50-537 D	SHAFER, W D. SHAFER, W D SHAFER, W D SHAFER, W. D SHAFER, W. D	8305100266# 8305120456 8305120463# 8305130109 8305170166	50-275 G 50-266 G 50-266 G 50-407 G 50-155 G	SHOEMAKER, C J SHOLLY, S C SHOLLY, S C SHON, F J	8305270604 8305230005 8305230243 8305240249 8305040464	50-287 G FOIA FOIA 50-245 P 50-247 G
BEIDENSTICKER BEIDENSTICKER BEIDENBTICKER BEIDLE, W. C. BEIDLE, W. C	8305130350 8305180637 8305180637 8304150143 8305020445*	50-537 0 50-537 0 50-537 0 50-313 0 50-313 0	SHAFER, W. D. SHAFER, W. D. SHAFER, W. D. SHAFER, W. D.	8305170148* 8305190307* 8305200239 8305200244* 8305200591	50-155 G 50-329 G 50-255 G 50-255 G 50-263 G	SHON: F J SHOTWELL, J A SHREVE, D. B SHYMLOCK, M B SHYMLOCK, M B	8305130030 8305090523 8305090131* 8305270455* 8305270544*	50-247 0 50-443 F CONTRACT 50-33B Q 50-33B Q
SEIDLE, W. C.	8305030325	50-313 Q	SHAFER, W. D	8305240029	50-282	SIEBER, J D	8305040261	50-334 R
BEIDLE, W C	8305030425	50-285 F	SHAFER, W. D	8305240032		BIEBERL ING, J	8305240275*	50-358 G
SEIDLE, W C	8305030617	50-482 Q	SHAFER, W. D	8305240067		SIEDLER, G	8305040593*	70-378
SEIDLE, W C	8305100006	50-192 Q	SHAFER, W. D	8305240078		BIEFKEN, D L	8305090647	WASTE MGT
SEIDLE, W. C.	8305100007*	50-192 Q	SHAFER, W. D	8305240302		SIEGEL, B.	8305160337	50-278 P
SEIDLE, W. C.	8305100112	50-482 Q	SHAFER, W. D	8305240306*	50-315 G	BILBERG.J E	8305020470	50-440 G
SEIDLE, W. C.	8305100151	50-482 Q	SHAFER, W. D	8305240367	50-255 G	BILBERG.J E	8305020470	50-440 G
SEIDLE, W. C.	8305100241	50-285 Q	SHAFER, W. D.	8305260314	50-263 B	BILBERG.J E	8305040307	50-440 G
SEIDLE, W. C.	8305100348	50-313 Q	SHAFER, H. D.	8305310105	50-254 G	BILBERG.J E	8305040307	50-440 G
SEIDLE, W. C	8305120445	50-313 Q	SHAFFNER, J. A	8305110180	27-37	BILBERG.J E	8305040506	50-440 T
SEIDLE, W. C.	8305200313	50-313	SHANBAKY, M	8305110320*	50-309 Q	SILBERO, J E	8305240313	50-482 0
SEIDLE, W. C.	8305230337		SHANBAKY, M	8305190174*	50-272 Q	BILBERO, J E	8305240313	50-482 0
SEIDLE, W. C.	8305230464		SHANBAKY, M	8305190191*	50-271 Q	BILBERT, E J	8305120540*	CONTRACT
SEIDLE, W. C.	8305230473		SHANBAKY, M M.	8305110267*	50-277 Q	BILBERT, E, S	8305230012*	ADVCM
SEIDLE, W. C.	8305230485		SHANNON, J B.	8305260145	40-8064	BILKER, W S	830503042*	NUREG
BEIDLE, W. C. BEIDLE, W. C. BEIDLE, W. C. BEIDLE, W. C. BEIDLER, Q.	8305240047	50-313 Q	SHAD, J	8305170101	NUREO	SILKER, W B	8305110457	NUREG
	8305240173	50-285 Q	SHAPIRO, R,	8305100254	50-322 0	SILVER, H	8305170105	50-289 P
	8305310104	50-482 Q	SHAPIRO, R,	8305100274	50-322 0	SILVER, H	8305240028	50-289 P
	8305310174	50-313 Q	SHAUB, E T	8305230460*	50-269 0	SILVIS, R	8305170603	CONTRACT
	8305030080#	FOIA	SHAUB, E T,	8305250304*	50-277 0	SILVIS, R M	8305040650	CONTRACT
SEIDLER, Q.	8305030324*	70-378	BHAUB, E. T	8305250505*	50-289 Q	SILVIS.R M	8305270108	CONTRACT
SEIFFERT, S. Q.	8305140205	40-2257	BHAN, L.	8305230207*	CONTRACT	SIMAN-TOV.M	8305060347	RES
SEIFFERT, S. Q.	8305200031	40-4492	BHELLEY, N J	8305200052	40-8027	SIMPSON.A K	8305110584*	COMMISSION
SEIKEN, S.	8305040430	50-482 8	BHEPHERD, R. E	8305120397*	QA999	SIMPSON.C	8305020006	FOIA
SEIKEN, S. J.	8305020073	50-482 8	BHERHOOD, Q. Q	8303240338	50-447 A	SIMPBON.G H	8305230220	FOIA

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
M L MPSONI A	8305180268	50-482 G	SMITH, W G	8303280126	50-315 S	BPIELEB, P.R	8305250171	40-8697
M L MPSONI B	8305180268	50-482 G	SMITH, W G	8305020072	50-316 S	BPIELEB, P.R	8305260364	40-8380
B L MIALONIS	8305130103	50-271 P	SMITH, W G	8305020141	50-315 S	BPITZBERG, D.B	8305020476	40-8452
B L MIALONIS	8305200517	50-271 P	SMITH, W G	8305020161	50-316 S	BPRAGVE, R.L	8305030474*	50-483 @
B L MIALONIS	8305240195	50-271 P	SMITH, W G	8305020192	50-316 S	BRENIAWSKI, D	8305020271	14E
SINCLAIR, J B SINCLAIR, J B SINCLAIR, J R BINCLAIR, L W SINCLAIR, M	8305270141 8305310212 8305180100* 8305160088 8305250215	50-271 P 50-271 F FDIA 50-286 P 50-329 G	SWITH! W O SWITH! W O SMITH! W O SMITH! W O	8305020279 8305020317 8305020440 8305060400 8305120318	50-315 8 50-315 8 50-315 8 50-315 8 50-316 8	STACHNIAK,R STAMBAUGH,P STANFILL,O W STANFILL,O W STANFILL,O W	8305170163* 8305110236* 8305250341* 8305250341* 830525035*	50~237 B CONTRACT 50~483 Q 50~483 Q 50~483 Q
M C'ISINIS M C'ISINIS M C'ISINIS M'AISINIS	8305260167 8305120006 8305120059 8305120110 8305120156	50-329	emith, W o emith, W o emith, W o emith, W o	8305120396 8305130097 8305130166 8305130178 8305130206	50-315 8 50-315 8 50-316 8 50-315 8 50-315 8	STANFILL, 0 W STANOE, B J STANOE, B J STANOE, B J STANSSERRY, W W	8305250356# 8305030695# 8305050307# 8305050381# 8305270446#	50-483 ¢ 50-289 F 50-289 F 50-320 F 50-375 Q
818CO'H M 818CO'H M 818CO'H M 818ISI'A W	B305120200 B305020019* B305030020* B305030035* B305030055*	50-29 J FOIA FOIA FOIA	SMITH.W G SMITH.W G SMITH.W G SMITH.W G	8305170441 8305170446 8305240145 8305240329 8305240330	50-315 B 50-316 B 50-316 B 50-315 B 50-315 B	STAPLETON, B W STAPLETON, B W STARK, R M STARKEY, R B STARKEY, R B	8305100371* 8305130234* 8305110590 8305030599 8305050249	50-156 Q 70-1308 50-337 A 50-261 B 50-261 S
SISCO, H W SISCO, H W SISCO, H W SISCO, H W	8305030105* 8305030105* 8305040234* 8305040250* 8305010549*	FOIA FOIA FOIA FOIA	SMITH, W G SMITH, W G SMITH, W G SMITH, W G SMITH, W G	8305240345 8305240362 8305270087 8305270107 8305270223	50-315 8 50-315 8 50-315 8 50-315 8 50-316 8	BTARKEY,R B STARKEY,R B STARKEY,R B STAROSTECKI,R STAROSTECKI,R	8305110251 8305250423 8305270487* 8305020226 8305020322	50-261 8 50-261 8 50-261 0 50-289 0 50-57 0
SKINNER, PH	8305020547	NUREG	SMITH, W G	8305270444	50-315 8	STAROSTECKI, R	8305020343	30-277 q
	8305170101	NUREG	SMITH, W G	8305310179	50-316 8	STAROSTECKI, R	8305030139	50-277 q
	8305040004	XPORTLIC	SMYTH, C W	8305310247*	50-287 R	STAROSTECKI, R	8305030151	50-320 q
	8305070310*	50-445 T	SMELL, H G	8305310181*	50-331 G	STAROSTECKI, R	8305030178	50-317 q
	8305270442*	50-338 G	SMOW, B A	8305230526	50-244 8	STAROSTECKI, R	8305030350	50-309 q
SKINNER, PH SKOLDS, JL SKOLDS, JL SKOLDS, JL SKOLDS, JL	8305270594* 8305270462* 8305270532* 8305260273* 8305250432*	50~335	E BADYNE U BADYNE U BADYNE U BADYNE U BADYNE U BODNA U	8305180238 8305180245* 8305180253* 8305060389 8305060171*	50-320 P 50-320 P 50-320 P 40-8584 FDIA	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8305050114 8305050172 8305050223 8305100405 8305100427	50-443 Q 50-334 Q 50-97 Q 50-286 Q 50-247 Q
SLATEN, N G	8305250552*	50-483 G	SODERSTROM, J	8305270048*	50-320 P	STARDSTECKI, R	8305110349	50-333 0
SLEMBER, R J	8305240345*	GA999	SOLLENBERGER, D	8305170599	40-299	STARDSTECKI, R	8305110388	50-225 0
SMITH, A	8305040345*	CUNTRACT	SOLLENBERGER, D	8305250597	40-299	STARDSTECKI, R	8305110501	50-333 0
SMITH, A L	8305050172*	GA999	SOLNIT, A J	8305030646*	50-247 G	STARDSTECKI, R	8305120301	50-322 0
SMITH, A L	8305090413*	GA999	SOLNIT, A J	8305030646*	50-247 O	STARDSTECKI, R	8305140083	50-354 0
SMITH B G	8305120350*	50-320 T	SOLTIS, K S	8305170209	50-440 G	STAROSTECKI, R	8305140137	50-273 6
SMITH C F	8305310143	50-327 A	SONDAO, T J	8305180434	PR	STAROSTECKI, R	8305140194	50-287 9
SMITH G C	8304180554*	70-1143	SOO, P	8305020547	NUREG	STAROSTECKI, R	8305170487	50-354 9
SMITH G C	8305170313*	50-271 G	SOO, P	8305110127	NUREG	STAROSTECKI, R	8305170495	50-54 9
SMITH I W	8305040405	50-454 G	SOO, P	8305170101	NUREG	STAROSTECKI, R	8305190017	50-27 9
O C 'HIINS	8305160162	50-434 G	SGRENSEN, J	8305270048*	50-320 P	BTAROBTECKI, R	8305190031	50-322 q
O C 'HIINS	8305200521	50-434 G	SGUDER, J L	8305020563	50-146 H	BTAROBTECKI, R	8305190260	50-219 q
O C 'HIINS	8305120355*	50-320 T	SGUTHARD, R B	8305230031*	CONTRACT	BTAROBTECKI, R	8305190331	50-410 q
O C 'HIINS	8305020410	40-4622	SPECTOR, S M	8305230458*	50-244 8	BTAROBTECKI, R	8305200386	50-220 q
O C 'HIINS	8305030277	40-6622	SPENCE, G P	8305060091*	50-285 I	BTAROBTECKI, R	8305230429	50-223 q
EMITH.J L	8305040303	50-322 E	SPENCER, D	8305020236*	50-373 \$	STAROSTECKI, R	8305230527	50-410 0
SMITH.J L	8305040508	50-322 E	SPENCER, D	8305020251*	50-373 \$	STAROSTECKI, R	8305250226	50-286 0
SMITH.J L	8305120328	50-322 S	SPENCER, D A	8305240318	50-373 \$	STAROSTECKI, R	8305250307	50-213 0
SMITH.J L	8305160070	50-322 E	SPENCER, D A	8305240425	50-373 \$	STAROSTECKI, R	8305250427	50-29 0
SMITH.J L	8305160075	50-322 A	SPESSARD, R L	8305020350	50-483 Q	STAROSTECKI, R	8305250427	50-245 0
Smith J L	8305240447	50-322 A	SPESSARD, R L	8305020354*	50-483	Starostecki, r	8305250438	50-244 0
Smith J L	8305270013	50-322 E	SPESSARD, R L	8305030258		Starostecki, r	8305250447	50-271 0
Smith J L	8305310050	50-322 A	SPESSARD, R L	8305060284		Starostecki, r	8305250454	50-184 0
Smith M	8305170242	40-8064	SPESSARD, R L	8305060542		Starostecki, r	8305250457	50-336 0
Smith N A	8305120250#	50-281 P	SPESSARD, R L	8305060547		Starostecki, r	8305250497	50-213 0
SMITH.P	8305230273*	CONTRACT	SPESSARD.R L	8305100388	50-341 Q	STAROBYECKI, R	8305250543	70-371
SMITH.PA	8305040280	CONTRACT	SPESSARD.R L	8305120419	50-346 Q	STAROSYECKI, R	8305270043	50-272 Q
SMITH.PA	8305040284*	CONTRACT	SPESSARD.R L	8305120423	50-546 Q	STAROSYECKI, R	8305270204	50-184 Q
SMITH.PA	8305040341	CONTRACT	SPESSARD.R L	8305120438	50-373 Q	STAROSYECKI, R	8305270571	50-244 Q
SMITH.PA	8305050387*	CONTRACT	SPESSARD.R L	8305120443*	50-373 Q	STAROSYECKI, R	8305270638	50-410 Q
SMITH, P. A	8305040235	50-204 P	SPESSARD, R L	8305130129	50-454 Q	BTAROBTECKI, R	8305270696	50-412 0
SMITH, P. A	8305040239*	50-204 P	SPESSARD, R L	8305130139	50-373 Q	BTABEK, S.	8305020480*	50-10 0
SMITH, P. A	8305170441*	CONTRACT	SPESSARD, R L	8305170130	50-483 Q	STEFAND, J J	8305120130	50-440 0
SMITH, P. A	8305180421*	CONTRACT	SPESSARD, R L	8305170182	50-483 Q	BTEFAND, J J	8305120460	50-397 E
SMITH, P. A	8305200071*	CONTRACT	SPESSARD, R L	8305170222	50-483 Q	BTEFAND, J J	8305120470*	50-397 E
SHITH, P. A	8305230031*	CONTRACT	SPESSARD, R L	8305170241	50-266	STEFANO, J J	0305120477*	50-397 E
SHITH, P. A	8305260380*	CONTRACT	SPESSARD, R L	8305170294		STEFANO, J J	0305120405*	50-397 E
SHITH, R	8305050151*	50-293 Q	SPESSARD, R L	8305170298*		STEFANO, J J	0305120491*	50-397 E
SHITH, R. D	8305060363	40-8783	SPESSARD, R L	8305170322		STEFANO, J J,	0305250187	50-440 A
SHITH, R. D	8305130322	40-8752	SPESSARD, R L	8305170289*		STELLO, V	0005140294*	50-498 A
SMITH, R D	9305130330	40-8763	SPESSARDIR L	8305200330	50-346 G	STELLO, V.	8005280930*	50-498 G
SMITH, R D	9305160251	40-8693	SPESSARDIR L	8305200407	50-255 S	STELLO, V.	8006090238*	50-498 G
SMITH, R D	9305160253	40-8743	SPESSARDIR L	8305200421	50-237 G	STELLO, V.	8006090440*	50-498 A
SMITH, R D	9305160256	40-8675	SPESSARDIR L	8305200508	50-454 G	STELLO, V.	8008120773*	50-498 A
SMITH, R D	9305240396	40-8663	SPESSARDIR L	8305200509	50-346 G	STELLO, V.	8010280578*	50-324 P
SMITH, R, H SMITH, R, H SMITH, R, H SMITH, R, H SMITH, S, H	8305120260* 8305120284* 8305120284* 8305120294* 8305230283	40-672 40-672 40-672 40-672 50-261 P	SPEGBARD, R L SPEGBARD, R L SPEGBARD, R L GPEGBARD, R L SPEGSARD, R L	8305200586 8305240125* 8305260259 8305270191 8305270476	50-454 G 50-373 G 50-155 G 50-456 G 50-454 G	STELLO, V STELLO, V STELLO, V STELLO, V	8305040630 8305110415 8305110485* 8305120602* 8305120609*	90-272 8 REVIEW GRP REVIEW GRP 40-672 40-672

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STELLO. V STELLO. V STELLO. V STELLO. V	8305170275 8305170715 8305180064* 8305180157* 8305180184*	REVIEW GRP REVIEW GRP 50-498 G 50-498 G FOIA	STOHR.J P STOHR.J P STOHR.J P STOHR.J P STOHR.J P	8303270136 8303270161 8303270174 8303270288 8303270450	70-1113 70-143 70-1201 50-332 Q 70-1151	STRICKLER, L J STRICKLER, L J STRICKLER, L J STRICKLER, L J STRICKLER, L J	8305180031# 8305180037# 8305180092# 8305180166# 8305180174#	FOIA FOIA FOIA FOIA FOIA
STELLO, V STELLO, V STELLO, V STELLO, V	8305180202* 8305180211* 8305180250* 8305180257* 8305180326*	50-498 Q 50-498 Q 50-498 A 50-498 T 50-498 A	9 V.SHOTE 9 V.SHOTE 9 V.SHOTE 9 V.SHOTE 9 V.SHOTE	8305270467* 8305270548 8305270600 8305270640 8305310016	70~1151 70~27 70~143 70~143 70~1201	STRICKLER, L J STRICKLER, L J STRICKLER, L J STRINGHAM, S D STRINGHAM, S D	8305180207* 8305180223* 8305180247* 8304130034 8304130042*	FOIA FOIA FOIA 71-494 71-494
STELLO, V STELLO, V STELLO, V STELLO, V	8305190010 8305200619 8305230503 8305230507 8305230669	REVIEW ORP REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP	STOHR.JP STOHR.JP STOHR.JP STOLZ.JF STOLZ.JF	8305310109 8305310120 8305310132 8303280319 8304120027	70-1113 70-1151 70-1113 50-302 P 50-321 P	STRUMWASSER, M STRUMWASSER, M STRUMWASSER, M STUART, D L STUCKY, S W	8305110212 8305110217 8305110383 8305250327 8305200438	50-275 0 50-275 0 50-275 0 50-443 G 50-155 0
STELLO, V STEMPLE, P STEMPLE, P STEPHENSON, C STEPTOE, P	8305260375 8305260378 8305200149* 8305110342* 8305100341	dro Misc Contract 50-289 8 50-329 g	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8305020592 8305030389 8305040769 8305060671 8305090111*	50-312 P 50-344 F 50-321 P 50-321 P 50-247 P	STURKEY, J J STURKEY, J J SUERMANN, J F SUOARMAN, R J BUQARMAN, R J	8303240487* 8303240495* 8305230499 8305310013 8305310013	50-313 P 50-313 P 30-269 P 50-352 G 50-352 0
STEPTOE, P STEPTOE, P STEPTOE, P STERN, P STERN, P	8305100341 8305270547 8305270547 8305030565 8305030567*	50-327 G 50-327 G 50-327 G 50-307 G	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8305070138* 8305070147 8305070154* 8305070179* 8305070584	50-269 P 50-313 P 50-313 P 50-313 P 50-302 Q	SULLIVAN, M F SUMMERFIELD, T EUMMERS, R SUMNER, H L SUMNER, H L	8305090561* 8305200665* 8305170336 8305170445* 8305170477*	50-358 A 50-373 P 50-272 S 50-321 S 50-366 B
BTERN, P. BTERN, P STERNBERG, D M. STERNBERG, D M STERNBERG, D M	8305180460 8305240386 8305160218* 8305170346 8305170375	FR 50-309 G 50-312 G 50-397 G 50-397 G	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8305090589* 8305090608 8305110625 8305120037 8305120504	50-302 Q 50-269 P 50-313 P 50-302 P 50-313 P	SUNDIN, RE SUTHERLAND, HA SUTPHIN, RN SUTPHIN, RN SUTPHIN, RN	8305250195 8305050426 8305170315* 8305170256* 8305260258*	40-8102 NUREG 50-344 G 50-331 G 50-409 G
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8305170377 8305170384 8305170421* 8305170429 8305170436	50-528 d 50-508 d 50-361 d 50-89 d 50-397 d	BTOLZ, J F STOLZ, J F. STOLZ, J F. STOLZ, J F. STOLZ, J F	8305120306* 8305130294 8305170622 8305170673* 8305170677	50-313 P 50-267 P 50-313 P 50-346 P 50-313 F	SUTTON, J W SUTTON, J W SUTTON, J H SUWAL, G M SWAN, W	8305050071* 8305050149* 8305070403* 8305120250* 8305270303*	GA999 GA999 GA999 50-281 P 50-390 G
STERNBERO, D M STERNBERO, D M STERNBERO, D M STERNBERO, D M STERNBERO, D M	B305170494 8305170560 8305170564* 8305260252 8305260319	50-508 Q 50-528 Q 50-528 Q 50-397 Q 50-528 Q	8TOLZ, J F 8TOLZ, J F. 8TOLZ, J F. 8TOLZ, J F 8TOLZ, J F	8305170482* 8305180008* 8305180014* 8305180045* 8305180048*	50-346 P 50-278 P 50-278 P 50-267 P 50-269 P	SWANSON,E SWANSON,E R SWARTZ,E D SWARTZ,E D SWARTZ,E D	B3050Z0348* B305240309* B305030270 B305040559* B305100Z37	90-315 G 50-315 G 50-454 S 50-456 G 50-454 A
STETKA, T F STEWART, J. M STEWART, S D STEWART, S D STEWART, W L	8305270525* 8305200440* 8305230245 8305230256 8305040173	50-302 G 50-367 P CONTRACT CONTRACT 50-338 P	8TOLZ, J F 8TOLZ, J F 8TOLZ, J F 8TOLZ, J F. 8TOLZ, J F.	8305180099 8305180102 8305180104* 8305180114* 8305180128*	50~287 P 50~344 P 50~287 P 50~344 P 50~289 P	SWARTZ,E D SWARTZ,E D SWARTZ,E D SWARTZ,E D SWARTZ,E D	8305130001 8305130051 8305180385 8305260287 8305270079	50-456 A 50-454 A 50-456 A 50-456 F
STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8305040409 8305050126 8305060061 8305060100 8305060283	50-33B P 50-2B0 F 50-2B1 Q 50-2B1 F 50-337 P	8TOLZ, J F 8TOLZ, J F 8TOLZ, J F 8TOLZ, J, F 8TOLZ, J F	8305180151 8305180161 8305180187* 8305180494 8305180847	50-269 P 50-313 F 50-346 P 50-313 P 50-313 P	SWARTZWELDER, R SWARTZWELDER, R SWARTZWELDER, R SWETLAND, P SWEZEY, M	8305310061* 8305310078* 8305310080* 8305250314* 8305240517	50-320 8 50-320 8 50-320 8 50-309 G 50-247 H
STEWART, W L STEWART, W L STEWART, W, L STEWART, W, L	8305060556 8305090139 8305100108 8305100315 8305120047	50-280 P 50-280 Q 50-280 P 50-280 Q 50-337 Q	810LZ, J F 810LZ, J F 810LZ, J F 810LZ, J F,	8305200100 8305200103 8305200238* 8305230014 8305230128	50-277 0 50-249 P 50-277 Q 50-313 0 50-313 P	SHIGER, M A SHIGER, M A SYLVIA: B R SZCZECH, R A SZCZECH, R A	8305240515 8305240515 8305190273* 8305030112* 8305030127*	50-440 G 50-440 G 50-358 G 50-287 S 50-287 S
STEMART, W L STEMART, W L STEMART, W. L STEMART, W. L STEMART, W L	8305120244 8305120386 8305130058 8305180372 8305190253	50-281 P 50-337 P 50-280 F 50-280 P 50-337 P	STOLZ.J F. STONE.J STORR.J F. STOTZ.J, STOTZ.J	8305310083 8208060249* 8305230603* 8305130195* 8305310038	50-269 P 50-338 P 50-410 A 50-346 8 50-346 8	SZCZECH,RA SZCZECH,RA SZCZECH,RA SZUKIEWICZ,AJ TAM,PS	8305110287* 8305110351* 8305200551* 8305090646* 8305040621	50-289 & 50-289 & 50-289 & 50-445 & 50-334 P
STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L.	8305200163 8305200479 8305260232 8305260323 8305270143	50-280 P 50-280 P 50-280 P 50-336 P 50-336 Q	STRAKA, M STRATOULY, D C STRATOULY, D C STRATOULY, D C STRATON, W R	8305030375 8305030282* 8305030545* 8305170517* 8305230469*	50-123 R 50-275 R 50-275 R 50-275 R COMMISSION	TANGWEE,D. TANSEY,W J TAPIA,J I TAPIA,J I TAPIA,J I	8305030480 8305090578* 8305100009*	50-237 8 FR 50-445 G 50-192 G 50-445 G
STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L.	8305270150 8305270220 8305270248* 8305270407* 8305270416*	50-339 P 50-338 P 50-280 Q 50-338 Q 50-338 Q	STRAUSS: R. J STREETER: J F STREETER: J F STREETER: J F STREETER: J. F	8305030416 8305020352* 8305020467 8305100364 8305170148	PR 50-305 Q 50-10 Q 50-331 Q 50-546 G	TARAS, D. TARAS, D. N.	8006180578* 8305020204* 8305020545*	FOIA FOIA FOIA FOIA 70-378
STEWART, W. L. STEWART, W. L. STILES, H. STILES, H. A.	8303270426* 8305310079 8303130135* 8303200426* 8303100113*	50-338 G 50-339 P 50-454 G 50-260 B 50-296 B	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8305170303 8305170308* 8305170398 8305170400* 83051704251	50~346 Q 50~346 Q 50~373 Q 50~373 Q 50~331 Q	TARAS, D. N TARAS, D. N TARAS, D. N TARAS, D. N TARAS, D. N	8305030251* 8305040087* 8305040103*	70-378 70-378 FOIA FOIA
STILL, N. STILLER, M. A STILLHELL, W Q STINSON, R C STOETZEL, Q A	8305090626 8305250408* 8305110528 8305250529 8305030317	WASTE MOT 50-483 O NUREO PR 50-331 G	STREETER, JF. STREETER, JF STREETER, JF STREETER, JF STREETER, JF	8305260221 8305260244 8305260256 8305260329 8305260331*	50-440 G 50-461 G 50-469 G 50-373 G 50-373 G	TARAB, D. N TARAB, D. N. TARAB, D. N. TARAB, D. N. TARAB, D. N.	8305040450* ; 8305040469* ; 8305040502* ;	FOIA FOIA FOIA FOIA
BTOHR, J P. BTOHR, J P. BTOHR, J P. BTOHR, J P.	8305030348 8305200310 8305270113 8305270142 8305270155	70-27 70-143 70-1113 70-1151 70-143	STREUTKER, 8 R STREUTKER, 8 R STREUTKER, 8 R STRICKLER, L STRICKLER, L	8305040105# 8305060142# 8305060148# 8305180111# 8305180021#	71-9181 71-9175 71-9175 FOIA FOIA	TARAB,D N TAUBER,H TAUBER,H TAUBER,H TAUBER,H	8305020370 8305100119 8305170662	01A 0-341 A 0-341 A 0-2926 0-341 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEORY
TAYLOR.H S TAYLOR.H S TAYLOR.J H TAYLOR.J H TAYLOR.J H	8305070467 8305070467* 8305100316 8305120018 8305260311*	TOPREP TOPREP	TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B	930505067* 8305110272* 8305110273* 8305110273* 8305110389*	50-321 S 50-321 S 50-321 S 50-321 S 50-321 S	TROWBRIDGE, O F TUCKER, H B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8305240487 8305020020 8305020372 8305040229 8305040273	50-289 Q 50-413 E 50-249 P 50-349 8 50-349 8
TAYLOR, J H TAYLOR, J M TAYLOR, J H TAYLOR, J H TAYLOR, H	8305260313* 8212060385 8305160082* 8305130267* 8305170718	50-3 Q 50-309 S 50-409 Q REVIEW GRP	TIPPS, S. B. TIPPS, S. B. TIPPS, S. B TIPPS, S. B TIPPS, S. B	8305110412* 8305110417* 8305110434* 8305110436* 8305130242*	50-321 9 50-366 8 50-321 9 50-366 8 50-366 8	TUCKER, H. B.	8305040469 8305040564 8305040597* 8305050135 8305050133	50-370 P 50-249 P 50-349 F 50-349 F 50-370 B
TAYLOR,PA TAYLOR,PA TAYLOR,R TAYLOR,R G TAYLOR,R O	8305270245* 8305270453* 8305240227 8305070578* 8305070650*	50-389 G 50-373 S	TIPPS.8 B TIPPS.8 B. TIPPS.8 B. TIPPS.8 B TIPPS.6 B	8305170262* 8305170284* 8305170394* 8305170438* 8305170506*	50-321 8 50-366 8 50-366 8 50-321 8 50-366 8	TUCKER, H B TUCKER, H B TUCKER, H, B TUCKER, H B TUCKER, H B	8305050254 8305050283 8305060224 8305060403 8305060413	50-267 B 50-367 P 50-367 P 50-367 B 50-367 P
TEDFORD,C F TENNYSON,V H TERAD,D THIEB,A C THINNES,G L	8305030578 8305120077# 8305070454# 8305070435 8305110447	PR 50-275 P 50-445 Q 50-287 P NUREG	TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8 B	8305230468* 8305230478* 8305230478* 8305230577* 8305270123	50-366 8 50-366 8 50-366 8 50-321 8 50-366 8	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B.	8305090472 8305100002 8305100007 8305100148 8305100327	50-349 8 50-349 8 50-349 9 50-349 0
THOMAS: C O THOMAS: C O THOMAS: C O THOMAS: C O	8305170072 8304270179 8305050379 8305060358 8305060562	50-219 B PR 50-447 E TOPREP 50-447 E	TIPPS.8 B TIPPS.8 B TIPPS.5 B. TIPPS.8 B. TIPPS.8 B.	8305270234 8305310124 8305310166 8305310180 8305310206	50-321 8 50-366 8 50-321 8 50-321 8 50-366 8	TUCKER, H B TUCKER, H B. TUCKER, H B TUCKER, H B TUCKER, H B.	8305100347 8305100366 8305100383 8305110085 8305110281	50-349 P 50-349 B 50-349 P 50-349 B
THOMAS, CO THOMAS, CO THOMAS, CO THOMAS, CO THOMAS, CO	8305090217 8305090554 8305090597 8305120029 8305120057	TOPREP TOPREP TOPREP TOPREP 50-70 P	TOBIN.W J. TOBEN,W J. TODD:J T. TODD:J T. TODDROVICH,M H	8305090461* 8305100109* 8305120430* 8305200561* 8305240453	50-395 Q 50-324 G 50-387 8 50-387 8 50-247 H	TUCKER, H B TUCKER, H, B TUCKER, H B TUCKER, H B TUCKER, H B	8305110323 8305130025 8305130158 8305130192 8305160285*	50-270 B 50-269 P 50-369 B 50-369 F 50-369 F
THOMAS.C.O THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O	8305120047* 8305120089 8305120094* 8305180017 8305180060	50-70 P 50-73 P 50-73 P 50-470 E 50-447 A	TOMAN,O J TOMPKINS,B.A TOMPKINS,B.A. TONER,K.A TONER,K.A	8305170106* 8305020394 8305020405 8305020202 8305160090	50-272 8 50-483 0 50-352 0 50-155 P 50-255 P	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B,	8305160293* 8305170258 8305170277 8305170292 8305170294	50-413 F 50-370 B 50-369 P 50-413 B 50-413 F
THOMAS.C O THOMAS.J THOMAS.M THOMAS.M THOMAS.R D	8305240151 8305190266* 8305270151* 8305270562* 8305100416*	MISC 50-219 Q 50-347 Q 50-390 Q 50-237 G	TONER, K. A TONOUE, T. M TORRONEN, K TOSCANI, K TOTH, A. D.	8305170176 8305020480* 8305240015 8305200645 8305170381*	50-155 P 50-10 G NUREO 50-247 O 50-397 G	TUCKER, H B	8305170324 8305170355 8305170455 8305170455 8305170507	50-269 # 8 50-369 B 50-269 R 50-369 B 50-369 R
THOMAS,R D THOMAS,R D THOMAS,B THOMAS,H V THOMAS,W V	830516007B* 8305260273* 8305200598 8305100011 8305110457	70~754 40-8137 50~440 Q 50~346 F NUREO	TOTH, A D. TOURIONY, E O. TOURTELLOTTE, J TOWNSEND, B TOWNSEND, B	8305170437* 8305110145 8305230720 8305110005 8305110144	50-397 G 50-368 P 50-313 P CONTRACT CONTRACT	TUCKER, H. B. TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8305170561 8305170020 8305170032 8305200401 8305200438	50-269 B 50-370 F 50-370 E 50-413 E 50-369 P
THOMASON, P V THOMASON, P V THOMPSON, D THOMPSON, D, THOMPSON, D	8305060574 8305120433 7908080036* 8112270557* 8305120420*	50-298 8 50-298 8 50-498 G 70-925 40-672	TOWNSEND, B TRAMM, T. R TRAMM, T. R TRAMMELL, C M TRAMMELL, C M	8305120555 8305040074* 8305160059 8305110176* 8305110230*	CDNTRACT 50-454 F 50-454 E 50-368 P 50-336 P	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B, TUCKER, H B	8305200476 8305200544 8305250278 8305250281 8305250282	50-413 E 50-269 G 50-369 F 50-369 P 50-413 B
THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, H THOMPSON, P	8305170067* 8305180337* 8305200598 8305030587* 8305120246*	50-142 Q 50-498 A 50-440 Q 50-312 P 40-472	TRAMMELL,C M TRAMMELL,C M TRAMMELL,C M TRAMMELL,C M TRAMMELL,C M	8305120171* 8305120505* 8305120512* 8305130023* 8305170273*	50-335 P 50-266 P 50-313 P 50-338 P 50-317 P	TUCKER, H B TUCKER, H B TUCKER, H B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B	8305250287 8305250290 8305250404 8305250437 8305250442	50-369 P 50-370 P 50-369 B 50-370 B 50-369 P
THOMPSON:S L THOMSEN:F T THOMSEN:F T THOMSEN:F T THOMSEN:F T	8305310209 8305310029 8305310029 8305310082 8305310082	NUREQ 50-522 Q 50-522 Q 50-522 Q 50-522 Q	TRAMMELL,C M TRAMMELL,C M TRAMMELL,C,M TRAMMELL,C M TRAMMELL,C M	8305180049* 8305180614* 8305200087* 8305200724* 8305130201*	50-368 P 50-317 P 50-336 P 50-338 P 50-346 B	TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8305250449 8305250479 8305250499 8305250507 8305250525	50-414 8 50-269 P 50-370 8 50-370 8
THONUS, L THONUS, L THOROERSEN, J O THOROERSEN, J O THORNBURG, H D	8305030164* 8305160199* 8305100397* 8305270198 8009120352*	50-320 @ 50-287 @ 50-305 S 50-305 S 50-478 @	TRAVIB.C.C TRAVIB.W.H. TREBY.S A TREBY.S.A TRENERY.S E	B305250155 B305260003 B305040531 B30507056B B305040740	RES 71-5552 50-445 G 50-445 G NUREG	TUCKER, H B TUCKER, H B. TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B.	8305250549 8305250554 8305270005 8305270069 8305270259	50-369 8 50-269 8 50-413 A 50-413 B 50-269 P
THORNBURG: H D THORNBURG: H D THORSEN: E O THULL: T. S THULL: T. S	8010090450* 8305180276* 8305270586 8305060512* 8305230557*	50-498 A 50-498 Q 50-247 G 50-245 8 50-245 B	TREXLER, R C TRIMBLE, D C TRIPP, L. TRIPP, L. TRIPP, L	8304280121 8305030208* 8305100258 8305190336 8305040184	PR 50-317 0 50-272 8 50-272 8 50-219 0	TUCKER, H B TUCKER, H B, TUCKER, H. B TUCKER, H. B, TUETKEN, R. P	8305270366* 8305310052 8305310081 8305310200 8305160060	50-369 Q 50-369 B 50-269 Q 50-413 E 50-454 Q
THURMOND, S. TIEDKE, J. H. TIERMAN, J. A TIERNAN, J. A TIERNAN, J. A	8305230406* 8305180347 8305040394 8305040438 8305180358	COMMISSION PR 30-317 P PR PR	TRIPP, L.E. TRIPP, L.E TRIPP, L.E TROBKOSKI, W.M TROWBRIDGE, G F	8305050180* 8305060057 8305160091* 8305050180* 8305090431	50-334 Q 50-352 Q 50-354 Q 50-334 Q 50-289 Q	TUFFIN, W. TUFFIN, W. B. TUFFIN, W. B. TUFFIN, W. B. TUFFIN, W. B.	8305120369* 8305120352* 8305120480* 8305120494* 8305120511*	40-672 40-672 40-672 40-672 40-672
TIERNAN, J. A TIERNEY, J. E TIETZ, Q TILLEY, R TILLEY, R	8305240269* 8305180460 8305310142 8305020061 8305040671	50-317 P PR 50-254 8 71-6717 71-495	TROWBRIDGE, G F TROWBRIDGE, G F. TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F.	8305070431 8305070470 8305070470 8305120272 8305120272	50-289 Q 50-261 Q 50-261 Q 50-287 Q 50-289 Q	TUFFIN, W B TUITE, P. T. TULQDIESKI, D TURCOTTE, R. L TURK, S. E.	8305120617* 8305110158 8305310203* 8305310012 8305060317	FOIA WASTE MOT 50-329 R 50-131 P 50-537 Q
TILLEY,R TILLMAN.A TILLMAN.A. TIMO.P P. TIPPS,B B	8305040679* 8305030371* 8305200565* 8305040433 8305050040*	71-495 70-27 50-349 Q TOPREP 50-321 S	TROWBRIDGE, G F TROWBRIDGE, G F, TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F	8305130092 8305130162 8305130162 8305130162	50-261 0 50-261 0 50-261 0 50-261 0 50-289 0	TURK, B E TURK, S E TURK, B. E. TURK, B E. TURK, B. E.	8305100022 8305110450 8305110455* 8305130063 8305160128	50-537 9 50-537 9 50-537 9 50-537 9 50-537 9

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
TURK. B E TURK, B E TURNER. D TURNER. D TURNER. D	8305200642 8305240070 8305170588* 8305170588*	50-382 0 50-537 0 50-454 0 50-454 0 50-454 0	URYC. B UTLEY, E E UTLEY, E E VACCA, P C VACCA, P C	8305270212* 8305040420 8305270008 8305110024 8305110029*	50-302 G 50-324 G 50-324 P NUREG NUREG	VARGA, S A VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8305070335* 8305110052* 8305110056* 8305110538 8305160349*	50-200 P 50-305 P 50-305 P 50-286 F 50-261 P
TURNGUEST, L THISDALE, L A TYMPANICK, L UDALL, M UDALL, M, K	8305310182 8305310157* 8305020266* 8305240275* 8305040145*	50~237 8 50~244 P GA979 50~358 Q 50~269 U	VAKERICS, T V VAKERICS, T V VALDES, S A VAN BRUNT, E E VAN BRUNT, E E	B305180070* 8305180074* 8305170197* 8305020089 9305030285	FO1A FO1A 50-389 8 50-328 K 50-528 8	VARGA.S A VARGA.S A VARGA.S A VARGA.S A	8305160356# 8305170019# 830517002B# 830517004B 8305170080#	50-261 P 50-311 P 50-311 P 50-261 F 50-315 P
UDALL, M K UDALL, M K UDERITZ, R A UDERITZ, R, A UDERITZ, R, A	8305230349* 8305240272* 8305020150 8305020184 8305020267*	COMMISSION 50-358 Q 50-272 B 50-272 P 50-272 Q	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E, VAN BRUNT, E E VAN BRUNT, E E	8305030346 8305030626 8305120385 8305130082 8305130107	50-529 8 50-528 9 50-528 E 50-528 6 50-528 8	VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A VARGA.8 A	8305170084* 8305170090* 8305170112* 8305170119* 8305170129*	50-272 P 50-272 P 50-315 P 50-272 P 50-272 P
UDERITZ,R A UDERITZ,R A UDERITZ,R A UDERITZ,R A UHRIG,R E	8305040262 8305160085 8305240271* 8305270053* 8305020084	50-272 8 50-272 0 50-272 0 50-272 0 50-335 0	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8305130124 8305130127 8305130148 8305130159 8305130161	50-528 S 50-528 S 50-528 S 50-528 S 50-529 S	VARCA, S. A. VARCA, S. A. VARCA, S. A. VARCA, S. A. VARGA, S. A.	8305170597 8305170637 8305170644 8305170654 8305170659	50-261 P 50-286 P 50-247 P 50-261 Q 50-364 P
UHRIQIR E UHRIQIR.E. UHRIQIR.E UHRIQIR E UHRIQIR.E	8305020168 8305020345 8305020517 8305030168 8305030306	50-335 P 50-335 P 50-335 P 50-251 R 50-389 S	VAN BRUNT, E E	8305130148 8305130149 8305130183 8305130189 8305130210	50-52B 8 50-52B 8 50-52B 6 50-52B 5 50-52B 5	VARQA, B. A VARQA, S. A VARQA, S. A VARQA, S. A VARQA, S. A	8305170711 8305180147 8305180534 8305180548 8305180573	50-315 P 50-280 f 50-315 P 50-250 f 50-305 F
UHRIO, R. E. UHRIO, R. E. UHRIO, R. E UHRIO, R. E UHRIO, R. E	B305030340 B305030341 B305030392 B305030461 B305030604	50-335	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8305130226 8305130229 8305130264 8305160071 8305160072*	50-528 S 50-528 B 50-528 B 50-528 A 50-528 A	VARGA: S. A. VARGA: S. A. VARGA: S. A. VARGA: S. A. VARGA: S. A.	8305180586 8305180671 8305180712 8305180731* 8305180814	50-261 P 50-295 P 50-340 P 50-346 P
UHRIG, R E UHRIG, R. E UHRIG, R E UHRIG, R E UHRIG, R E	8305040563 8305070432 8305070476 8305100001 8305100088	50-335 F 50-250 P 50-335 P 50-350 G 50-387 B	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8305200322 8305200417 8305230517 8305240321* 8305260326*	50-528 F 50-528 A 50-528 B 50-528 G 50-528 G	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8305180838 8305180854 8305200079 8305200171 8305200175	50-315 P 50-250 P 50-250 F 50-247 0 50-334 F
UHRIG, R. E UHRIG, R. E UHRIG, R. E UHRIG, R. E UHRIG, R. E	8305100103 8305100165 8305100182 8305100227 8305100236	50-335 P 50-250 P 50-335 J 50-387 8 50-335 P	VAN BRUNT, E E VAN DE KAMP, J VAN ECK, D. J VAN KOVICB, J VAN KOVICB, J	8305310161 8305120073* 8305070162 8305180459* 8305180461*	50-528 A 50-275 P NUREO 50-322 H 50-322 H	VAROA, S. A. VAROA, S. A. VAROA, S. A. VAROA, S. A. VAROA, S. A.	8305230230 8305240104 8305240246 8305260207 8305310221	50-334 P 50-305 G 50-295 P 50-250 P 50-272 P
UHRIO, R. E UHRIO, R. E UHRIO, R. E UHRIO, R. E UHRIO, R. E	8305130008 8305130118 8305130121 8305160010 8305170356	30~250 F 50~387 P 50~335 P 50~251 P 50~389 F	VAN VRANKEN; J VAN VRANKEN; J VANDEL; T, E VANDEWALLE; D J VANDEWALLE; D J	8305170151 * 8305170167 * 8305170153 * 8305060477 8305100250	50-373	VASSALLO, D B	8303300396* 8303300408* 8304210030 8305020036 8305020532	50-260 P 50-260 P 50-220 P 50-273 P 50-271 P
UHRIG, R. E UHRIG, R. E UHRIG, R. E UHRIG, R. E. UHRIG, R. E.	8305170463 8305170520 8305170546 8305200181 8305200346	50-335 P 50-250 P 50-250 F 50-389 B 50-335 F	VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8305100279 8305120147 8305170300* 8305170404 8305170410	50-255 P 50-255 F 50-255 Q 50-155 F 50-155 P	VASSALLO, D B	8305020569 8305020597 8305030066 8305030135 8305040095	50-220 F 50-254 P 50-333 P 50-331 P
UHRIO,RE UHRIO,RE. UHRIO,RE UHRIO,RE UHRIO,RE	8305200489 8305230532 8305240372 8305250272 8305250395	50-335 F 50-335 P 50-335 P 50-335 P 50-335 P	VANDEWALLE, D. J. VANDEWALLE, D. J. VANDORN, P. K. VANDORN, P. K. VAND, J. A. VAND, J. VAND, J. VAND,	8305240505 8305260266* 8305270334* 8305270602* 8305100273*	50-155 P 50-155 Q 50-413 Q 50-413 Q 50-334 Q	VASSALLO, D B VASSALLO, D. B VASSALLO, D. B VASSALLO, D B VASSALLO, D B	8305040108* 8305040115* 8305060279* 8305060291* 8305060548	50-331 P 50-331 P 50-273 P 50-273 P 50-333 F
UHRIO, R. E. UHRIO, R. E UHRIO, R. E. UHRIO, R. E UHRIO, R. E	8305250397 8305250415 8305250416 8305250455 8305250462	50-335 P PR 50-387 S 50-389 P 50-335 P	VARELA: A VARGA: B A VARGA: B A VARGA: B A VARGA: B A	8305160197* 8303300001 8303300002* 8303300003* 8304270053	50-289 Q 50-295 P 50-295 P 50-295 P 50-295 P	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8305090186 8305110039* 8305110234* 8305110243* 8305110556*	50-331 P 50-331 P 50-331 P 50-331 P
UHRIO, R. E. UHRIO, R. E UHRIO, R. E. UHRIO, R. E. UHRIO, R. E.	8305250472 8305250481 8305250517 8305270104 8305270125	50-250 F 50-335 P 50-250 P 50-387 P	Varqa: 8 a Varqa: 8 a Varqa: 8 a. Varqa: 8. a Varqa: 8 a	8305020348 8305020375 8305040090 8305040117 8305040125#	50-3 F 50-3 F 50-305 P 50-305 Q 50-305 Q	VASBALLO, D B VASBALLO, D B, VASBALLO, D, D VASBALLO, D, D VASBALLO, D, B	8305110566* 8305120167* 8305120187* 8305140340* 8305140342*	50-331 P 50-293 P 50-293 P 50-298 P 50-298 P
UHRIO: R. E. UHRIO: R. E. UHRIO: R. E. UHRIO: R. E UHRIO: R. E.	8305270129 8305270153 8305270168 8305270170 8305270251	50-250	VARQA, B. A VARQA, B. A. VARQA, B. A VARQA, B. A VARQA, B. A	8305040363* 8305040382* 8305040512 8305040649 8305040667	50-315 P 50-315 P 50-334 P 50-315 P 50-305 P	VASBALLO, D. B VASBALLO, D. B VASBALLO, D. B VASBALLO, D. B VASBALLO, D. B	8305170052* 8305170060* 8305170071* 8305170075* 8305170716	50-220 P 50-220 P 50-271 P 50-271 P
UHRIG, RE UHRIG, R.E UHRIG, R.E, UHRIG, RE, UHRIG, RE,	8305270360* 8305270520* 8305270572* 8305310034 8305310184	50-387 Q 50-387 Q 50-335 Q 50-250 P 50-387 P	VARGA: S. A. VARGA: S. A. VARGA: S. A. VARGA: S. A. VARGA: S. A.	8305040672 8305050073 8305050280 8305050273 8305060653	50-250 P 50-286 F 50-286 G 50-250 P 50-250 P	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8305170719 830518002& 8305180039* 8305180048* 8305180061*	50-331 7 50-278 1 50-278 7 50-324 P 50-324 P
ULIE, J. UNKLE, T. J UPRIGHT, C. M UPRIGHT, C. M UPRIGHT, C. M	8305120447* 8305110363* 8305270278* 8305270319* 8305270356*	50-373	Varga. S. A Varga. S. A Varga. S. A Varga. S. A Varga. S. A.	8305060658 8305070019* 8305070029 8305070032* 8305070037*	50-280 P 50-348 F 50-280 G 50-348 P 50-280 G	VASSALLO, D. B VASSALLO, D. B VASSALLO, D. B VASSALLO, D. B, VASSALLO, D. B	8305180071* 8305180081 8305180091* 8305180204* 8305180547	50-548 50-531 50-531 50-548
UPRIGHT, C M UPRIGHT, C. M URBANIK, T. URYC, B. URYC, B,	8305270442* 8305270574* 8305070586* 8305030371* 8305200565*	50-338 Q 50-335 G 50-445 Q 70-27 50-367 Q	VARGA, B. A. VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A	8305090051 * 8305090070 * 8305090085 8305090104 * 8305090327 *		VASSALLO:D B VASSALLO:D.B. VASSALLO:D B VASSALLO:D B VASSALLO:D B	8305180563 8305180572 8305180752 8305180771 8305180801	50~324 50~333 50~331 50~240 50~331

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBUECT CATEODRY
VASSALLO, D B	8305180845 8305170079 8305200246 8305200707 8305200708	50~259 P 50~324 P 50~333 P 50~237 P 50~271 F	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8305270464 8305270465 8305270468 8305270484 8305270510	50-395 G 50-111 G 50-518 G 50-400 G 50-239 G	HAREMBOURG, D WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WARHOL, W N	8305310111 8305120570* 8305120578* 8305200494 8305180200	50-247 P 50-247 F 50-247 F 50-247 P 40-7097
VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8305230048 8305230115 8305230178 8305230242 8305230248	50-271 P 50-271 P 50-324 P 50-298 P 50-263 P	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8305270514 8305270524 8305270540 8305270546 8305270557	50-257 G 50-438 G 50-370 G 50-400 G 50-370 G	WARNICK,R F HARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8305130171 8305170321 8305170447 8305170550 8305170312	50-329 Q 50-329 A 50-358 Q 50-358 A
VASSALLO, D B	8305230253	50-271 Q	VERRELLI, D M	8305270582	50-438 G	WARNICK,R F	8305190316	50-358 8
VASSALLO, D B	8305230279	50-271 P		8305270589	50-438 G	WARNICK,R F	8305200557	50-329 0
VASSALLO, D B	8305230312	50-271 P		8305270601 *	50-438 G	WARNICK,R F	8305240001	50-358 0
VASSALLO, D B	8305240557	50-263 P		8305270609	50-400 G	WARNICK,R F	8305240006	50-329 0
VASSALLO, D B	8305240560	50-293 P		8305270616*	50-438 G	WARNICK,R F	8305260223	50-358 0
VASSALLO, D B	8305240562	50-263 P	VERRELLI, D M	8305270620*	50~400 0	WARNICK,R F	8305260223*	50-358 Q
	8305240564	50-331 F	VERRELLI, D M	8305270623	50~400 0	WARNICK,R F	8305260336	50-358 A
	8305240571	50-273 F	VERRELLI, D M	8305270642	50~259 0	WARNICK,R F	8305270076	50-329 Q
	8305240572	50-263 F	VERRELLI, D M	8305270651	50~390 0	WARNICK,R F	8305270297	50-329 A
	8305240573	50-284 P	VERRELLI, D M	8305270653	50~259 0	WARREN,R P	8305120357*	50-320 T
VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8305240576	50-220 F	VERRELLI, D M	8305270658*	50-259 Q	Wasserman, s P	8305020401	50-247 0
	8305240591	50-271 F	VIETTI, A	8305100422	50-275 P	Wasserman, s P	8305020401	50-247 0
	8305250136	50-259 P	VINJAMURI, K	8305110523	NUREQ	Wastler, s L	8305130298	40-8348
	8305250137	50-333 F	VISSING, O	8305250298	MISC	Wastler, s, L	8305170585	40-8084
	8305250141	50-254 F	VISSING, O S	8305230019	50-313 P	Wastler, s, L	8305170585	40-8084
VASSALLO.D B VASSALLO.D B VASSALLO.D B VASSALLO.D B VASSALLO.D B	8305250145 8305250266 8305250514 8305260114 8305260130	50-298 F 50-298 P 50-220 P 50-271 P 50-293 P	VOOLER, BH VOOT, HE VOOT-LOHELL, R VOIOT, HH VOIOT, HH	8305230239 8305240517 8305270219* 8305130098 8305130098	50-352	WATERS, J R WATERS, J R WATFORD, P 8 WATTELET, P L WEBD, W A	B305200701* B305100271* B305240025 B305200688* B305120517*	50-213 8 50-295 0 50-373 8 50-373 P CONTRACT
VASSALLO.D B VASSALLO.D B VASSALLO.D B VASSALLO.D B	8305240134	50-324 F	VOIOT.H H	8305130098	50-546 0	HEOBT, W F	8305160037*	50-142 0
	8305240147	50-331 P	VOIOT.H H	8305130244	50-546 0	WEIOANDT, J T	8305270575	50-247 H
	8305240170	50-278 P	VOIOT.H H	8305130244	50-546 0	WEINKAM, E J	8305170482	50-458 F
	8305240175	50-273 P	VOIOT.H H	8305130244	50-546 0	WEINKAM, E J	8305260305	50-458 C
	8305240177	50-259 F	VOLLMER.R H	8302250480*	50-470 A	WEINSTEIN, M	8305060675	NUREO
VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8305260187 8305260192 8305260201 8305260209 8305260285	50-259 P 50-331 P 50-263 P 50-333 P 50-324 P	VOLLMER: R H VORDERBRUEGGEN VORDERBRUEGGEN VOSBURY: F VUMBACO: F J	8303170135* 8305170537* 8305170564* 8305310241* 8305130011*	50-423 A 50-528 G 50-528 G 50-265 P 40-672	WEISE, S. WEISE, B WEISE, D. WEISE, D WEISE, E R	8305270401* 8305270504* 8305110278 8305230033* 8305030502	50-261 0 50-261 0 50-409 R 70-1359 50-537 0
VASSALLO, D B	8305260296	50-271 P	VUMBACD, F J	B305130042*	40-472	WEI88,E R	8305030502	50-537 0
	8305260297	50-333 P	HADE, D H	B305070521*	50-445 T	WEI88,E R.	8305030502	50-537 0
	8305260300	50-298 P	WAGNER, A G	B305270438*	50-416 G	WEI88,E R	8305060382	PR
	8305270045	50-271 Q	WAGNER, M E	B305050053	50-287 G	WEI88,E R	8305060573	PR
	8305270055*	50-271 Q	WAGNER, M E	B3050500B2	50-460 O	WEI88,E R	8305100204	50-247 0
VASBALLO, D D	8305310231	50-254 P	WAGNER, M E	8305090481	50-289 G	WEISB,E R	8305100204	50-247 0
VAUGHAN, C M	8305050148	70-1113		8305100231	50-289 G	WEISB,E R	8305160073	50-289 0
VAUGHAN, C M	8305310115*	70-1113		8305170039	50-289 G	WEISB,E R	8305160073	50-289 0
VEGA, A	8305070513*	50-445 T		8305200576	50-460 G	WEISB,E R	8305160149	50-537 0
VENDER, J	8305170330*	50-293 S		8305200582	50-460 G	WEISB,E R	8305160149	50-537 0
VERRELLI.D VERRELLI.D VERRELLI.D M VERRELLI.D M	8303070409 8305100100 8305030236 8305270083 8305270091	50-370	WAGNER, P C WAGNER, P C WAGNER, R L WAGNER, R L WAHI, K K	8305200167 8305310027 8305060076* 8305270378* 8305170122	30-267 P 30-267 P 50-331 P 30-333 P NUREG	WEI68:E R WEI68:E R WEI88:E R WEI88:E R WEI88:E R	8305160149 8305160181 8305160181 8305160181 8305180356	50-537 0 50-537 0 50-537 0 50-537 0 PR
VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8305270196 8305270228 8305270229 8305270250 8305270263*	50-62	WAHL, H W WALDORF, E J WALDRUP, U WALKER, D L WALKER, J R	8305240415* 8305170461 8305060613* 8305230222* 8305190346	GA999 50-440 G 50-238 R 40-1478 50-443 G	Weiss.e R Weiss.e R Weiss.e R Weiss.e R Weiss.e R	8305180363 8305170221 8305170221 8305170221 8305200470	PR 50-537 0 50-537 0 50-537 0 PR
VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D M	8303270266 8305270271 8305270283> 8305270290 8305270292*	50-259	WALKER, R D WALKER, R D WALKER, R D WALKER, R D WALKER, R D	8305200611* 8305240247* 8305240247* 8305260314 8305310112*	50-331	WEISS.E R WEISS.E.R WEISS.E R WEISS.E R WEISS.E R	8305240538 8305240538 8305240542* 8305240542* 8305240553	50-247 0 50-247 0 50-247 0 50-247 0 50-537 0
VERRELLI, D M	8305270300	50-416 Q	WALKER, W J	8305030189*	70-378	WEISBLE R.	8305240553	50-537 0
	8305270313	50-327 Q	WALLING, G E	8305130288	40-8829	WEISBLE R	8305240553	50-537 0
	8305270316	50-62 Q	WALLING, G E	8305050138*	50-335 8	WEISBLT	8305240555	50-247 T
	8305270333	50-324 Q	WALLING, G E	8305100278*	50-389 8	WEISBLT	8305240558*	50-247 T
	8305270341	50-400 Q	WALSH, M A	8305040529	50-445 9	WELLBLD A	8305020085	50-341 8
VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8305270358	50-348 Q	HALSH, M A	8305110157	50-445 T	WELLB: D. A.	8305030476	50-341 8
	8305270372	50-438 Q	HAMBACH, T V	8305050354	REVIEW GRP	WELLB: D. A	8305030585	50-341 8
	8305270377	50-400 G	HANG, J C	8305120633*	40-672	WELLB: D. A	8305030594	50-341 8
	8305270380	50-261 Q	HANG, J C	8305120642*	40-672	WELLB: D. A	8305100015	50-341 8
	8305270388	50-416 Q	HANG, J C	8305130062*	40-672	WELLB: D. A	8305100118	50-341 8
VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8305270390 8305270391* 8305270396* 8305270409 8305270413	50-261 Q 50-400 Q 50-438 Q 50-416 Q 50-390 Q	WARCLOUD, J WARD, E C WARD, K, D WARD, K D WARD, W J	8305200656 8305030221# 8304150364# 8305190027# 8305100307#	50-440 Q 50-282 F 50-440 Q 50-454 Q 50-482 Q	WELLB, D A WELLB, D A WELLB, D, A WELLB, D A	8305100154 8305100393* 8305100399* 8305170207 8305170535	50-341 8 50-341 0 50-341 0 50-341 8 50-341 8
VERRELLI.D N	8303270417*	50-416 Q	Ward, W. J.	8305180196*	FOIA	WELLS,R	8305110326#	50-320 8
VERRELLI.D M	8303270418*	50-416 Q	Warembourg, D.	8305060479	50-247 \$	WELLS,R.A	8305030349	50-341 8
VERRELLI.D M	8305270431	50-395 Q	Warembourg, D.	8305060546	50-247 R	WELLS,R.W	8305050034	TOPREP
VERRELLI.D M	8303270436	50-395 Q	Warembourg, D.	8305090489	50-247 R	WELLS,R.W	8305030034	TOPREP
VERRELLI.D M	8303270463	50-416 Q	Warembourg, D.	8305230426	50-247 R	WENDERLICH,R	8305230513#	50-317 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOUR'
HENBLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA HENSLAWSKI, FA HENSLAWSKI, FA	8305170343* 8305170501* 8305170521* 8305170530* 8305170530*	50-397 Q 50-275 Q 50-361 Q 50-361 Q 50-344 Q	WIEDEMAN, D WIEDEMAN, D WIEDEMAN, D G WIELAND, R H WIEGEMANN, R A	8305130165 8305170359 8305120465 8305170284* 8304180558*	1&E 1&E 40-215 90-329 A TOPREP	MICSON' 7 F MICSON' 7 F MICSON' 7 F MICSON' 7 F	B305130130* B305130136* B305130198 B305130203* B305130228	50-281 50-281 50-280 50-280 50-280
WERNER, R P WERSAN, D WESCOTT, H M WESLEY, D A WESTAFER, G R	8305110069 8305170533 8305020285* 8305170544* 8305030036	50-213 F 50-352 0 50-341 G 50-327 A 50-302 P	Wiesemann, R A Wiesemann, R A Wiesemann, R A Wiesemann, R A Wiesemann, R A	8305020272 8305030438* 8305050208* 8305050288* 8305090202*	50~266 P TOPREP TOPREP 50~369 P PROJ	Mireon'a F Mireon'a F Mireon'a F Mireon'a F	8305130243* 8305230424 8305230432* 8305230451* 8305170456	50-280 50-281 50-281 50-281 50-400
WESTAFER. Q R WESTAFER. Q R WESTAFER. Q R WESTAFER. Q R WESTAFER. Q R	8305030050 8305050014 8305090442 8305130002 8305130012	50-302 P 50-302 S 50-302 P 50-302 P	Wiesemann, R A Wiesemann, R A Wiesemann, R A Wiesemann, R A Wiesemann, R A	8305110377* 8305170411* 8305180273* 8305270012* 8305270488*	50-334 P 50-454 T TOPREP TOPREP YOPREP	WILSON, R WILSON, R WILT, D D WILT, D D WILT, D D	8305170486 8305170491 8305040325 8305040487 8305040487	50-400 50-400 50-440 50-440 50-440
HEBTAFER. O R HEBTAFER. O R HEBTAFER. O R HEBTAFER. O R HEBTAFER. O R	8305130043 8305130067 8305130179 8305170379 8305170344	50-302 R 50-302 P 50-302 S 50-302 S	3.841001H 3.841001H 5.841001H T C.841001H T C.841001H	8305040635 8305060320 8305170065 8305100429* 8305190038*	CONTRACT CONTRACT CONTRACT 50-443 G 50-322 G	WILT, D. D. WILT, D. D. WILT, D. D. WILT, D. D. WILT, D. D.	8305040548 8305040548 8305100294 8305100294 8305100367	50-440 50-440 50-440 50-440 50-440
HESTAFER, Q.R HESTAFER, Q.R HESTAFER, Q.R HESTAFER, Q.R HESTAFER, Q.R	8305270378 8305270258* 8305270258* 8305270312* 8305270318*	50-302 P 50-302 G 50-302 G 50-302 G 50-302 G	Higgine, J T Higginton, D L Higginton, D L Wilber, H A Hilcove, M N	8305250314* 8305040354 8305170074 8103250385* 8305100147	50-309 Q 50-315 P 50-315 P 50-498 Q 50-329 T	WILT, D D WILT, D D WINGO, M D WIRE, K, R WISENBURG, H R	B305100367 B305310031 B305170340* B305060594* B30518035B	50-440 50-440 50-240 50-298 PR
HESTAFER, Q R HESTSROOK, K S HESTCOTT, H M HESTCOTT, H M HESTERMAN, T	8305270503* 8305250275 8305250279 8305250279 8305090313* 8305230475*	50-302	MICCOVE, M N MICCOVE, M N MICCOVE, M N MICCOVE, M N	8305120295 8305190225 8305240059 8305250376 8305260276	50-329 G 50-329 G 50-329 G 50-320 G 50-329 G	WIGHNIE, R O WITHERS, B D WITHERS, B D WITHERS, B D WITHERS, B D	8305240508 8305040417 8305040600 8305060606* 8305130164	50-247 50-344 50-344 50-344 50-344
HEBTERMAN, T F HEBTERMAN, T, F, HEBTERMAN, T F HEBTERMAN, T F HEBTERMAN, T F	8305100249# 8305170318# 8305170333# 8305200344 8305230449#	50~445 G 50~445 G 50~278 G 50~278 S 50~445 G	WILCOX, J D WILKENBON WILKINBON, E P WILLETT, D J	8305270629* 8305240223 8304060126* 8305250517 8305170349*	50-438 G 50-329 A 50-440 E PR 50-397 G	WITHERS.B D WITHERS.B D WITHERS.B D WITHERS.B D WITHERS.B D	8305130224 8305130240 8305180266 8305200013 8305230581	50-344 50-344 FR 50-344 50-344
HEBTERMAN, T F HEBTERMAN, T F HEBTON, R. T HEBTON, R. T HETHY, C. M.	8305240005# 8305260304# 8305060529 8305060536# 8305030240#	50-445 G 50-298 G 50-352 A 50-352 A 50-389 F	WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C	8305030537* 8305040522* 8305120368* 8305120428* 8305120447*	50-440 T 50-305 Q 50-374 G 50-546 Q 50-373 Q	WITHERS, B D	8305260275 8305270182 8305270184* 8305270205 8305270211*	50-344 50-344 50-344 50-344 50-344
HETHY, C M HETHY, C M. HETHY, C. M. HETTERHAHN, M J HETTERHAHN, M J	8305160RB2# 8305170310 8305230016 8305020441 8305020441	50-387 F 50-389 S 71-5957 50-352 G 50-352 G	WILLIAMB.C C WILLIAMS.P L WILLIAMS.H G WILLIAMS.J WILLIAMS.J	8305190393# 8305240061# 8305190014 8305120342 8305120410	50-373	MOTEE'S 7 MOTEHONSKI'Y A MOLEDUD'Y M MIZNEE'D 6	8305270087 8305060153* 8305020357* 8305020492* 8305120322	50-315 FDIA 50-483 50-243 50-382
HETTERHAHN, M. J.	8305030517 8305030563 8305030563 8305060478 8305060478	27-39 50-352	Jilliams, J Hilliams, J Hilliams, J Hilliams, J	8305120429 8305120432 8305120446 8305120487 8305130111	50-358 \$ 50-358 \$ 50-358 \$ 50-358 \$ 50-358 K	WOLFE, S J. WOLLETT, S. WOLLETT, S. WOLLETT, S. WOLLETT, S.	8305270634 8305090050 8305090068* 8305170688 8305230281	50-392 CONTRACT CONTRACT CONTRACT CONTRACT
HETTERMAHN, M. J. HETTERHAHN, M. J. HHALEN, R. J. HHEATON, M. R. HHEELER, L.	8305240489 8305240489 8305060492* 8305130222 8305110018	50-352	Hilliams, J Williams, J Williams, J Williams, J Williams, J	8305170524 8305180458 8305190228 8305200536 8305260227	50-358 S 50-358 F 50-358 S 50-358 S 50-358 S	WOLLETT, 8 WOLLETT, 8 WOLVENDYK, A WOOD, E C WOOD, J. E	8305270097 8305270103 8305280177 8305110344 8305040466*	CONTRACT CONTRACT 70-371 50-309 TOPREP
WHEELER, L. L. WHICHER, J. M WHICHER, J. M WHICHER, J. M. WHICHER, J. M	8305110016 8305030508 8305030508 8305030508 8305100286	50-443 A 50-454 T 50-454 T 50-454 T 50-454 Q	Williams, J Williams, J W Williams, J W Williams, J W Williams, J. W	8305260337* 8305050127 8305100251 8305100269 8305110487	50-358 A 50-335 8 50-251 8 50-387 8 50-250 8	WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODHEAD, C, P HOODHEAD, C, P	8305030494 8305100312 8305160164 8305170001 8305170063	50-142 (50-142 (50-142 (50-142 (50-142 (
WHICHER, J, M WHICHER, J, M, WHITAKER, W A, WHITE, I. L WHITE, L. M	8305100286 8305100286 8305200683* 8305180805 8305060274	50-454 Q 50-454 Q 50-373 P PROJ PR	Williams, J. W Hilliams, J. W Williams, J. W Williams, D. G Williams, R	8305170191 8305170244 8305250302 8305060076 8305040392*	50-387 S 50-335 S 50-335 S FOIA FOIA	WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODLAN, D R WOODRUFF, R L	8305170067* 6305200613 6305240521 8305090530* 8304280139	50-142 50-142 50-142 50-145 1&E
WHITE, R N WHITE, W. 8 WHITED, P. J WHITENER, H L WHITENER, H, L	8305110476 8305230368 8305200101 8305270367* 8305270526*	NUREQ 50-315 P 50-320 P 50-335 Q 50-257 Q	WILLIAMS, RE WILLIAMS, RE WILLIAMS, VS WILLIAMS, VS, WILLIAMS, VS,	B305020491 B305070012* B305030446* B305240311 B305020319*	40-6622 CONTRACT 50-304 8 50-295 8 GA999	WDDLEVER, E J WDDLEVER, E J WDDLEVER, E J WDDLEVER, E, J	B305020426 B305100104 B305110275 B305180256 B305180283	50-412 50-412 50-412 50-412 50-412
MHITNEY, D.D. MHITNEY, D.D. MHITNEY, D.D. MHITNEY, D.D. MHITNEY, Q.Q.	8305120073 8305120073 8305270432 8305270432 8304110706*	TOPREP TOPREP TOPREP TOPREP 50-273 8	NILBON, B. D. WILBON, B. D. WILBON, B. D WILBON, B. D WILBON, B. D.	8305040558 8305040567* 8305170578 8305180617 8305180713	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	WDDLEVER, E. J WDDLEVER, E. J WDDLEVER, E. J WDDLEVER, E. J WDDLEVER, E. J	8305180559 8305200429 8305240248 8305250498* 8305270662*	50-412 50-412 50-412 50-412
HHITNEY, Q, Q HHITNEY, Q, Q, HHITNEY, Q, Q, HHITNEY, Q, Q HHITNEY, Q Q	8305110341* 8305110365* 8305110392* 8305170532* 8305230515*	50-273 8 50-273 8 50-273 8 50-273 8	HILBON, B. D. HILBON, F. H HILBON, J. H. HILBON, J. L HILBON, J. L	8305260075 8305070162 8305240258 8305050118 8305050121*	XPORTLIC NUREQ 50-382 A 50-281 S 50-281 S	WOOLSEY,R T WOOLSEY,R T WOOLSEY,R.T WOOLSEY,R.T WOOLSEY,R T	8305120490 8305120501 8305130295 8305170583 8305170583	40-8602 40-299 40-2259 40-299 40-299
HHITNEY, O Q HHITNEY, M. A HHITSON, D. R HICKS, F HIEBE, J	8305230521* 8305060503* 8305130091* 8305170466 8305030164*	50-293 B 50-309 B 50-259 B 50-225 F 50-320 Q	HILBON: J L HILBON: J L HILBON: J. L HILBON: J. L HILBON: J. L.	8305050130* 8305100115 8305100120* 8305100127* 8305130125	50-280 S 50-280 S	WORTHEN, M. WRAY, J. R WRAY, J. R WRAY, J. R WRIGHT, D	8305030487 8305270357* 8305270534* 8305270576* 8305110178*	PR 50-321 50-338 50-335 CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY
WRIGHT, O C	8305170174*	50~155 G		0705440404	50-312 P	ZIMMERMAN, J V	8305160313	XPORTLIC
WRIGHT, N A	8305100243	50-329 T	ADONG PLOOD'S	8305110126 8305190271	50-322 P	ZIMMERMAN, J V	8305140315	XPORTLIC
A NATHOLEN	8305240065	50-327 Q	YUHAB. Q P	B305170343*	50-397 Q	ZIMMERMAN, J V	8305170120	XPORTL (C
WRIGHT.R G	83052505 <i>6</i> 6=	50-483 G	YUHAS, G P	B305170530*	50-361 Q	ZIMMERMAN, J V	8305170594	XPORTL (C
WRIGHT, R G	8305250566*	50-483 G	YUMOTO, H	8305140298	XPDRTLIC	ZIMMERMAN, J V	8305180078	XPORTLIC
WRIGHT.R J	8303290554	WASTE MOT	YUNDT, C P	8305130143	50-344 8	ZIMMERMAN, J V	4800816058	XPORTLIC
WRIGHT, R J	8303290813	WASTE MOT	ZAHLER, R E	8305240287	50-289 0	ZIMMERMAN, J V	8305180090	XPORTLEC
WRIGHT.R J	8305110068	WASTE MOT	ZAHLER, R E	8305240287	50-289 G	ZIMMERMAN, J V	8305180551	XPORTLIC
HRIGHT, R W	8305270179=	50-389 G	ZAHLER, R E	8305240486	50-287 G	ZIMMERMAN, J V	8305180703	XPDRILIC
WULLER, C E	8303240344	50-461 A	ZAHLER, R E	B305240487	50-287 Q	ZIMMERMAN, J V	8305180835	XPORTLEC
HULLER, G E	8305030559	50-461 R	ZAHLER, R E	8305250202	50-289 G	ZIMMERMAN, J V	8305170053	XPORTLIC
WULLER. 0 E	B305 (301 44	30-461 E	ZAHLER, R E	8305250202	50-289 Q	ZIMMERMAN, J V	8305200127	XPORTLIC
WULLER, G E	8305200667	50~461 A	ZAHLER, R E	8305250208*	50-289 G	ZIMMERMAN, J V	8305200137*	XPORTLIC
HULLER, G E	8305240142	50-461 A	ZAHLER, R E	8305250208*	50-289 G	ZIMMERMAN, J V	8305250165	XPORTLIC
WULLER, O B	8305230233*	40-1478	ZAHLER, R E	8305250225*	50-289 G	ZIMMERMAN, J V	8305260016	XPORTLIC
HUNDERLICH, J	6305310152	50-265 8	ZAHLER, R E	8305250225*	50-289 G	ZIMHERMAN, J V	8305260027	XPDRTLIC
WYNGARDEN, S	8305030671	40-3392	ZANARDI, G	8305100370*	50-325 P	ZIMMERMAN, J V	8305240029	XPORTLIC
WYNGARDEN 6 D	8305250604=	40-8027	ZARBIS.W A	8305060076*	50-331 P	ZIMMERMAN, J V	8305260034	XPORTLIC
YAMANA, K	8305170125*	XPORTLIC	ZARBIS, W A	8305270378*	50-333 P	ZIMMERMAN, J V	8305260055	XPDRTL1C
YAMANA. K	8305180709	XPORTL1C	ZIEMER,P D	8305180261	50-305 G	ZIMMERMAN, J V	8305260067	XPORTLIC
YANDELL, L A	8305100244*	50-285 G	ZIMMERMAN, J V	8305020001	XPDRTLIC	ZIMMERMAN, J V	8305240090	XPORTLIC
YANG, M 8	B305270501*	50-454 G	ZIMMERMAN, J V	8305020098	XPDRTLIC	ZIMMERMAN, J V	8305260113	XPORTLIC
YARGER, K	B305170205*	50-346 8	ZIMMERMAN, J V	Ø305030097	XPORTLIC	ZIMMERMAN, J V	B305260185	XPORTLIC
YARGER, K	8305240293	50-346 8	ZIMMERMAN, J V	8305040639	XPDRTLIC	ZIMMERMAN, J V	8305260187	XPORTLIC
YARGER, K	8305310038	50-346 8	21MMERMAN, J V	8305040644	XPORTL IC	ZIMMERMAN, J V	8305260191	XPORTLIC
YORK, J W	830527049Z*	50-400 G	ZIMMERMAN, J V	830504065B	XPORTLIC	ZIMMERMAN, J V.	8305260194	KPORTLIC
YOUNG, F	8305140199*	50-289 G	ZIMHERMAN, J V	8305040665	XPORTLIC	ZIMMERMAN, J V	8305260197	XPDRTLIC
YOUNG. M A	8305100172	50-454 G	ZIMMERMAN, J V	8305050440	XPORTLIC	ZIMMERHAN, J V	8305260198	XPORTLIC
YOUNG, M A	8305230236	50-142 0	ZIMMERMAN, J V	8305060014	XPORTLIC	ZIMMERMAN, J V	8305260199	XPORTLIC
YOUNG: M L	8305250331	50-443 H	ZIMMERMAN, J V	8305070042	XPORTLIC	ZIMMERMAN, J V	8305240203	XPORTLIC
YOUNG: T	8305170392*	50-528 Q	ZIMMERMAN, J V	8305090498	XPORTLIC	ZIMMERMAN, J V	8305260204	XPORTLIC
YOUNG, T.	8305170537*	50-528 G	ZIMMERMAN, J V	8305070500	XPORTLIC	ZIMMERMAN, J V	8305270032	XPORTLEC
YOUNG: T	8305170564*	50-528 Q	ZIMMERHAN, J V	8305090730	XPORTLIC	ZIMMERHAN, J V	8305270034*	XPORTLIC
YOUNG Y. A	8305060369*	40-8783	ZIMMERMAN, J V	8305090731*	XPORTLIC	ZIMMERMAN, R P	8305250453*	50-244 G
YOUNG, Y. A	8305130333*	40-8783	ZIMMERMAN, J V	8305090733	XPORTLIC	ZIMMERMAN, S R	8305020003	XPORTL IC
YOUNGBLOOD, B J	8305040006	50-482 A				ZIMMERHAN, B R	8305020165	30-400 R
AONMOBFOOD'S 1	8305040062	50-454 F	ZIHMERMAN, J V	B305090736	XPORTLIC	ZIMMERMAN, B R	B305070380	50-324 P
ADONOBFOOD B 1	8305040664	50-440 E	ZIMMERMAN, J V	8305090779	XPORTLIC	ZIMMERMAN, S R	8305090456	50-324 P
ADONOBEOGD'B 1	8305060648	50-423 A	ZIMMERMAN, J V	8305130265	XPDRTL.IC	ZIMMERMAN, S R	8305100362	50-325 P
ADANGBEGGO'B 1	8305110185	90-546 A	ZIMMERMAN.J V ZIMMERMAN.J V	8305130269 8305160294	XPORTLIC XPORTLIC	ZIMMERMAN, 8 R	8305120003	50-324 P
YOUNGBLOOD, B J	8305120068	50-492 F				ZIMMERMAN, B R	8305200435	50-261 P
ADAMORFQUD' B 7	8305120552	50-454 A	ZIMMERMAN, J V	8305160296	XPORTLIC	ZIMMERMAN, S R	8305200433	50-261 H
YOUNGBLOOD, B J	8305120610	50-445 Q	ZIMMERMAN, J V	8305160300	XPORTLIC	ZIMMERHAN, S R	8305240417	20-400 K
YOUNGBLOOD, B J	8305190096	50~440 A	ZIHMERMAN, J V	8305140307	XPORTLIC	ZIMMERMAN, 8 R	8305260022	50-261 P
ADDNOBFOOD' B 1	8305230427	50-445 A	ZIMMERMAN, J V ZIMMERMAN, J V	#305160309 #305160310	XPORTLIC XPORTLIC	ZIMHERMAN, S R	8305240320	50-324 P
YOUNGBLOOD, B. J.	8305230630	50-35B A	4 TERRESHAN O V	B303160310	AFURILIG	ZIVKOVICH, E A	8305200456	50-440 0
YOUNGBLOOD, B J	8305230435	50~546 A				ZUPKO, J M	8305040476	50-272 B
YOUNGBLOOD, B ,J	8305230645	30-440 E				ZUPKO, J M	8305060480	50-311 8
AUMOBROOD' B 1	B305230649	50~440 E				ZUPKO, J M	8305110271	50-311 8
ACONGBEDOD'B ?	8305230658	50-358 A				ZUPKO: J M	8305110274#	50-311 8
						ZUPKD, J M	8305160052	50-311 8
						ZUPKO, J. M	8305140094	50-311 9
						ZUPKO.J M	8305160118	50-311 B
						ZUPKO, J M	8305170018	50-272 R
						ZUPKO, J M	8305170142	50-311 R
						ZUPKO, J M	8305170367	50-311 B
						ZUPKO, J. M	8305200394	50-272 B
						ZUPKD, J. M	9305200537	50-311 B
						ZUPKO, J M	8305250501	50-311 B

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	Y
Asmodts, The	8305100163 8305100205 8305100406	50-287 50-287 50-287	000
Advisory Council on Historic Preservation Aerospace Corp.		50-410 NURE9	Ď
Agriculture, Dept of	8305040397* 8305040392*	FOIA FOIA	
Agriculture, Dept of: Graduate School Air and Water Pollution Patrol	8305230249# 8305040470 8305260181	CONTRACT 50-352 50-352	0
Alabama Power Co	8305020456 8305030580 8305030589* 8305050148 8305050154*	50-348 50-364 50-364 50-348 50-348	P 8 8 8
	8305050158* 8305050175 8305050203* 8305040421* 8305060624*	50-348 50-348 50-348 50-348 50-348	8 8 F F
	8305100132 8305100137* 8305110257 8305110260* 8305110308	50-364 50-364 50-364 50-364 50-348	8 8 8 P
	8305110308 8305110311* 8305110311* 8305160094 8305160094	50-348 50-348 50-348 50-348 50-348	P P Q
	8305160100* 8305160107* 8305160107* 8305200306 8305200327*	50-348 50-348 50-348 50-348 50-348	Q Q Q R R
	#305200357 #305200342* #305200577 #305200579 #305230540	50-364 50-364 50-348 50-348 50-348	RRR
	8305230544# 8305230550# 8305240191 8305240191 8305240440	50-348 50-348 50-348 50-348 50-348	88 F F P
	8305240481 8305240481 8305240484* 8305250285 8305250285	50-348 50-348 50-348 50-348 50-348	I
	8305250353 8305250391 8305250391 8305250581	50-348 50-348 50-348 50-348 50-348	8 F F 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
American Association of Physicists in Medicine	8305180425	PR
American College of Nuclear Physicians	8305030414 8305200274	PR PR
American Electric Power Co . Inc	8305160062* 8305230368	50-315 R 50-315 P
American Electric Power Service Corp	8305030257 8305030519 8305120108	50-315 P 50-315 P 50-315 F
American Nuclear Insurers American Nuclear Spcietu	8305110012 8305180353	PR PR
•	8305230469# 8305250517 8305270109	COMMISSION PR NUREQ
Amesbury, MA Anacomp, Inc	8305250327 8305260222*	50-443 G CONTRACT
Analysis & Technology, Inc	8305040324* 8305170070* 8305170077*	CONTRACT CONTRACT CONTRACT
Antioch School of Law, Washington, DC	8305100290 8305190366	50-155 G 50-155 G
Applied Biology, Inc Applied Physical Technology, Inc. Applied Research Associates, Inc. Applied Risk Technology Corp	8305190371* 8305030347* 8305110163* 8305310157* 8305180146*	50-155 C 50-335 R CONTRACT 50-244 P 50-247 Q
Argonne National Laboratory	8305110148 8305110142	NUREQ NUREQ
	8305130340 8305130349 8305130350	ACRS 50-537 O 50-537 O
	8305180637 8305190132* 8305190153* 8305190337* 8305190341*	50-537 O FOIA FOIA FOIA FOIA
Arizona Public Bervice Co	8305020084 8305020087 8305020087 8305020087	71-5607 50-528 K 50-528 K 50-528 K 50-528 K
	8305030285 8305030346 8305030626 8305030626 8305120385	50-528 B 50-529 B 50-528 B 50-528 E
	8305130082 8305130107 8305130124 8305130124 8305130124	50-528 8 50-528 6 50-529 8 50-528 8 50-528 5
	8305130127 8305130148 8305130148 8305130148	50-528 8 50-528 8 50-529 8 50-528 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATIO	MUM MC	BBION BER	SUBJECT CATEOORY
	8305130159 8305130159 8305130159 8305130141 8305130148	50-528 50-528 50-528 50-529 50-528	\$ \$ \$ \$ \$ \$	Army, Dept of	83053 81031 83050 83050	310199* 130267* 020015* 020016* 020019*	POEA AIOA AIOA AIOA AIOA
	8305130210 8305130189 8305130189 8305130189	50-528 50-528 50-528 50-528 50-528	8 8 8 8 8		93050 93050 93050	020022* 020031* 020035* 020042* 020047*	FOIA FOIA FOIA FOIA
	8305130210 8305130210 8305130226 8305130226 8305130226	50-528 50-528 50-528 50-528 50-528	s s s s		93050 93050 93050	020057# 020070# 020091# 020095#	FOIA FOIA FOIA FOIA
	8305130229 8305130227 8305130264 8305130264 8305130264	50-528 50-528 50-528 50-528 50-528	9 9 8 \$ \$		93050 93050 93050	020095* 020095* 020095* 020158* 020149*	FOIA FOIA FOIA FOIA
	8305160071 8305160072* 8305200322 8305200417 8305230517	50-528 50-528 50-528 50-528 50-528	A A F A B		83050 83050 83050	20178* 220204* 020207* 020325* 020539*	FOIA FOIA FOIA FOIA 70-378
Arizona, State of	8305260321* 8305260326* 8305310161 8305310215 8305030578	50-528 50-528 50-528 50-528 PR	0 0 A 0		93050 93050 93050)20539#)20539#)20539#)20545#)20550#	70-378 FOIA 70-378 FOIA FOIA
Arkansas Power & Light Co	8303240480 8304270426# 8304270426# 8304270427# 8309020373	50-313 50-313 50-313 50-319 50-348	P F F S		83050 83050 83050	020354# 020358# 020360# 020364# 020367#	FOIA FOIA FOIA FOIA
	8305020378* 8305020416 8305030331* 8305030385 8305030370*	50-348 50-348 50-313 50-313 50-313	8 6 8 8		93050 93050 93050	020571 * 030008 * 030020 * 030023 * 030027 *	FOIA FOIA FOIA FOIA
	8305040453 8305040457* 8305050125 8305050125 8305050125	50-313 50-313 50-313 50-313 50-313	R R P P		83050 83050 83050	030035# 030055# 030063# 030073# 030080#	FOIA FOIA FOIA FOIA
	8305040452 8305040454* 8305040583* 8305040583* 8305040571*	50-313 50-313 50-313 50-313 50-313	8 8 F F F		83050 8305 <u>0</u> 840 <u>5</u> 0	030087 * 030092 * 030105 * 030125 * 030142 *	FOIA FOIA FOIA FOIA
	8305040591* 8305090333 8305090333 8305090421 8305090440	50-313 50-313 50-313 50-313 50-313	5 5 5 5		83050 83050 83050	030147# 030154# 030163# 030169# 030174#	FOIA FOIA FOIA FOIA
	8305100351 8305100351 8305120414 8305120418+ 8305120451*	50-313 50-313 50-313 50-313 50-313	P P S G		83050 83050 83050	030179* 030185* 030218* 030225* 030233*	FOIA FOIA 70-378 70-378 70-378
	8305160270+ 8305160270+ 8305170551 8305180467 8305190363	50-313 50-313 50-313 50-368 50-313	F G P J		83050 83050 83050	030239# 030251# 030260# 030312# 030326#	70-378 70-378 70-378 70-378 70-378
	8305200319* 8305200326 8305200455 8305200451* 8305200470	50-313 50-313 50-313 50-313 50-313	C F 8 8 8		83050 83050 83050	030335# 040073# 040114# 040120# 040158#	70-378 FOIA FOIA FOIA FOIA
	8305200541 8305200541 8305200573 8305200580 8305230364	50-313 50-313 50-368 50-368 50-313	ያ ያ የ የ		93050 93050 93050	040165# 040175# 040183# 040189#	FOIA FOIA FOIA FOIA
	8305230723 8305230725* 8305240054* 8305240139 8305240360	50-368 50-368 50-313 50-313 50-368	면 G H P		93050 93050 93050	040211# 040217# 040224# 040234# 040239#	FOIA FOIA FOIA FOIA
	8305240397 8305260249 8305260260 8305270065 8305310199*	50-313 50-348 50-313 50-313 50-313	P 8 9 P 0		83050 83050 83050	040244# 040250# 040256# 040272# 040279#	FOIA FOIA FOIA FOIA

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'	Υ	AUTTUA AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY
	8305040287* 8305040290*	FOIA FOIA		Babcock & Wilcox Operating Plants Owners	8305270309* 8305120073	30-269 TOPREP	P
	8305040274* 8305040414* 8305040425*	FOIA FOIA		Group Backus, Shea & Meyer Baltimore Gas & Electric Co	8305270432 8305190199 8305020344*	TOPREP 50-443 50-317	G G
	B305040450* B305040478* B305040478* B305040478* B305040501*	FOIA FOIA FOIA FOIA			8305020344* 8305020509 8305030383 8305030388* 8305040396	50-317 50-317 50-318 50-318 50-317	0 8 8 9
	8305040510# 8305040519# 8305040523# 8305040554# 8305040556#	FOIA FOIA FOIA FOIA			8305060376 8305060402 8305060405* 8305060405* 8305060412	50-317 50-317 50-317 50-317 50-317	P P Q
	8305040559* 8305040559* 8305040562* 8305040569* 8305040573*	FOIA FOIA FOIA FOIA			8305060412 8305060438 8305060631* 8305060635*	50-317 PR 50-317 50-317 50-317	0 F F
	8305040578* 8305040583* 8305040593* 8305040597* 8305040674*	FD1A 70-378 70-378 70-378 70-378			8305110352 8305110363* 8305160081 8305180358 8305170287	50-317 50-317 50-318 PR 50-317	9 9 9
	8305040678* 8305040696* 8305050297* 8305050306* 8305050310*	70-378 70-378 70-378 70-378 70-378			8305170270* 8305170273 830517034B 8305170352* 8305200564	50-317 50-317 50-318 50-318 50-317	8 P 8 S R
	8305050316# 8305050322# 8305050330# 8305050333#	70-378 70-378 70-379 70-378 70-378			8305200584* 8305200620 8305200620 8305200628*	50-317 50-317 50-317 50-317	R G G
	8305050339* 8305050342* 8305050346* 8305050349* 8305050351*	70-379 FOIA FOIA FOIA FOIA			8305200628* 8305200631 8305200631 8305200644* 8305200640*	50-317 50-317 50-317 50-317 50-317 50-317	Q R R R R
Army, Dept. of, Corps of Engineers	8305050357* 8305050361* 8305060351* 8305110041* 8305170407*	FOIA FOIA CONTRACT CONTRACT	T .		8305200450* 8305230513* 8305230522 8305230528* 8305230555	50-317 50-317 50-318 50-318 50-317	R 8 8 8
Army, Dept of, Headquarters Materiel Davelopment & Readiness Command	8006180578* 8104060897* 8305040060* 8305040089* 8305040103*	FOIA FOIA FOIA FOIA			B305230560* B305240269* B305260294 B305260294 B305260302	50-317 50-317 50-317 50-317 50-317	8 P P J
Atlas Minorals	8305040127* 8305040468* 8305040487* 8305040502* 8305130362	FOIA 70-378 FOIA FOIA 40-3453		Barr Engineering Co	B305270029 B305270029 B305270072 B305270403 B305200004*	50-317 50-317 50-317 50-317 CONTRACT	P 8 8
Atomic Industrial Forum	8305180304 8305180304	PR PR		Basic Energy Technology Associates Battelle Memorial Institute, Columbus	8305020160* 8305270100*	50-272 CONTRACT	8
	8305180351 8305180378	PR PR	•	Laboratories Battelle Memorial Institute, Pacific	9011180792*	MISC	
Audubon Bociety	8305160024 8305160024	50-247 50-247	9	Northwest Laboratory	8207080528* 8301040137*	50-255 50-309	P
Automation Industries, Inc. BHR Owners Group	8305160028* 8305160028* 8305180194 8305100197	50-247 50-247 71-9180 TOPREP	•		8305030317 8305040594 8305040233 8305060474	50-331 M180 NUREG NUREG	Ġ
Babcock & Wilcox Co.	8305020392* 8305020404* 8305020523 8305020524* 8305030001	50-312 50-327 70-824 70-824 71-6294	P E		8305100011 8305110208 8305110457 8305120374* 8305130359	50-346 NUREG NUREG 50-237 50-537	F P O
	8305030410 8305040637 8305050100 8305050205 8305070464*	TOPREP XFORTLI 70-1201 70-1201 50-302	C P	Bear Creek Uranium Co Bechtel Corp	8305180782 8305250168 8305250174 8305020363 8305100281*	NUREG RES RES 40-9452 50-352	Ą
	8305100316 8305110443* 8305120018 8305120344* 8305120347*	TOPREP 50-344 TOPREP 50-320 50-320	P T T		8305120330* 8305200593* 8305240415* 8305250393* 8305250399*	50-320 9A999 9A999 50-237 50-237	q q
	8305240046 8305260311* 8305260313* 8305260376	71-166 50-330 50-330 70-1201	8 8		8305250399* 8305250407* 8305250407*	50-237 50-237 50-237	a a

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO:		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Berlin, Roisman, Kessler & Cashdan	8305250413* 8305250413* 8305250520* 8305310143 8305160080	50-237 50-237 50-206 50-329 50-329	G G P A G		8305110212 8305110217 8305110217 8305110383 8305110383	50-275 g 50-275 g 50-275 g 50-275 g 50-275 g	
Beveridge, Fairbanks & Diamond Binder, Elster, Mendelson & Wheeler, Inc Borg-Warmer Corp	8305160084 8305200459 8305040345* 8305130222 8305130254	50-529 50-338 CONTRAC 50-440 XPORTL I	8	California, Univ of, Los Angeles	8305120093* 8305260182 8305260183* 8305260183* 8305030524	50-275 p 50-275 g 50-275 g 50-275 g 50-142 g	
Boston Edison Co	8305130305 8305240357# 8305240363# 8304110696 8304110706#	XPORTLIC GA999 GA999 50-293 50-293	c s s		6305030568 6305030574 6305090473 6305140037* 6305170067*	50-142 0 50-142 0 50-142 0 50-142 0 50-142 0	
	8304180590 8305020134 8305050250 8305070200 8305100138	50-293 50-293 50-293 50-293 50-293	P R G P R	California, Univ of, San Diego Callaway County, MD	B305240479 B305240499 B305060239# B305250304# B305250354#	50-142 0 50-142 0 50-206 P 50-483 0 50-483 0	
	8305100144* 8305110334 8305110341* 8305110356 8305110365*	50-293 50-293 50-293 50-293 50-293	R S S S	Commer & Bhapiro	8305250536* 8305250566* 8305250587* 8305100256 8305100274	\$0-483 0 50-483 0 50-483 0 50-322 0 50-322 0	
	8305110384 8305110392* 8305130153 8305140044 8305140041	50-293 50-293 50-293 50-293 50-293	8 8 H P P	Canadian Commercial Corp Carolina Environmental Study Group Carolina Power & Light Co.	8305230289* 8305060252 8305020124 8305020124 8305020165	CONTRACT 30-413 0 30-400 E 30-400 E 30-400 R	
	8305160134 8305160136* 8305160145 8305170173 8305170345	50-293 50-293 50-293 50-293 50-293	R B B F P		8305020165 8305020172* 8305020172* 8305020453 8305030288	30-400 R 50-400 R 50-400 R 50-261 P 50-324 P	
	8305170418 8305170529 8305170532* 8305190024 8305190029*	50-293 50-293 50-293 50-293 50-293	P R R S S		8305030291 8305030293* 8305030355 8305030361* 8305030387	50-324 B 50-324 P 50-324 B 50-324 B 50-324 B	
	8305190147 8305190174 8305190181* 8305190324 8305190330*	50-293 50-293 50-293 50-293 50-293	P 8 8 8 8		8305030387 8305030411 8305030419# 8305030463 8305030463	50-324 8 50-324 8 50-324 8 50-324 P 50-324 P	
	8305200259 8305200447 8305230434# 8305230450 8305230509	50-293 50-293 50-293 50-293 50-293	P G F 8		8305030465 8305030473* 8305030481* 8305030481* 8305030497	50-325 8 50-325 8 50-324 P 50-324 P 50-324 B	
	8305230515* 8305230516 8305230521* 8305230533 8305230535	50-293 50-293 50-293 50-293 50-293	9 9 9 8 R		8305030497 8305030505 8305030512 8305030530 8305030536*	50-324 9 50-325 9 50-324 8 50-324 8 50-324 B	
Botmin, Hays, Bilar & Herzberg Brigham Young Univ	8305230537* 8305230538* 8305270073 8305020401 8305140129	50-293 50-293 50-293 50-247 50-262	R 6 0 9		8305030540 8305030547* 8305030599 8305030601 8305030612	50-324 8 50-324 8 50-261 8 50-400 8 50-324 8	
Brookhaven National Laboratory	8305020547 8305110126 8305110127 8305110131 8305110227	NUREO 50-312 NUREO NUREO NUREO	Р		8305030&18# 83050403&2 8305040479 8305040479 8305040485#	50-324 8 50-261 P 50-400 9 50-400 0 50-400 0	
Brase & Poswistillo Brown Boyeri Corp (subs Brown Boyeri & Co , Ltd.)	8305110237 8305170086 8305170101 8305070478 8305110324	NUREO 50-537 NUREO 50-352 50-269	A 0 8		8305040485# 8305040492# 8305040492# 8305040498# 8305040498#	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	
Brunswick Co	8305120437* 8305200395 8305200415* 8305200422* 8305200457*	90-358 99999 99999 99990	B		8305050124 8305050143 8305050185 8305050201 8305050242	50-400 8 50-325 8 50-400 8 50-325 9 50-324 8	
·oup	6305200456* 6305240547 63050500034 6305160278 6305170332*	GA999 50-247 TOPREP XPORTLIC	Q :		8305050244# 8305050249 8305050259 8305050245 8305050247#	50-324 8 50-261 8 50-400 8 50-324 8 50-324 8	
	8305170365* 8305170387* 8305310211 8305110212	50-973 50-973 WASTE MG 50-275	P G		8305060176 8305060180# 8305060471 8305060555 8305060620	50-325 P 50-325 P 50-400 9 50-400 E 50-324 0	

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT	RY	AFFIL	THDR IATION	ACCESSION NUMBER	SUBJECT CATEODR	
	8305040420 8305090380 8305090380 8305090456 8305090456	50-324 50-324 50-324 50-324 50-324	д Р Р Р	_		8305240446 8305240446 8305240550 8305240550 8305240551	50-400 50-400 50-400 50-400 50-400	00000
	8305070470 8305100362 8305100412 8305100412 8305100417*	50-261 50-325 50-324 50-324 50-324	9 Р R R			8305240551 8305250247 8305250423 8305250489 8305250473*	50-400 50-261 50-261 FR PR	0 P 8
	8305110248 8305110248 8305110251 8305110252 8305110252	50-400 50-400 50-261 50-400 50-400	8 8 8			8305250494 8305260022 8305260234 8305260320 8305270008	50-400 50-261 50-400 50-324 50-261	6 8 8
	8305110256* 8305110282 8305110284* 8305110294 8305110294	50-261 50-325 50-325 50-400 50-400	8 8 8			8305270023 8305270256+ 8305270281+ 8305270281+ 8305270383+	50-400 50-324 50-400 50-400 50-400	E 0 0
	8305120003 8305120467 8305120467 8305130027 8305130075	50-324 50-400 50-400 50-400 50-400	P A B O			8305270487 * 8305270531 8305270588 * 8305270599 *	50-261 50-324 50-324 50-324 50-324	Q Q Q
	8305130075 8305130080 8305130080 8305130088 8305130088	50-400 50-400 50-400 50-400 50-400	9 8 9	Center for Law in t Central Data Proces		8305270615* 8305270617* 8305120285 8305160312* 8305160316*	50-400 50-324 50-275 50-247 50-247	0 0
	8305130092 8305130108 8305130162 8305130167 8305130170	50-261 50-325 50-261 50-324 50-324	8 8	Charkes & Hoare Charlevoix, MI Charnoff, Q Chem-Muclear System: Christa-Maria	s. Inc.	8305100257 8305260180 8305110008* 8305170733 8303040542*	50-483 50-155 CONTRACT 71-5026 50-155	0
	8305130172* 8305130176* 8305130177 8305130184* 8305130216	50-324 50-324 50-324 50-324 50-400	8 8 8	Christy, W , Interv	enor	8305100290 8305190366 8305190371* 8305190375* 8305180288	50-155 50-155 50-155 50-155 50-482	0000
	8305130216 8305160017 8305160017 8305160021 8305160021	50-400 50-400 50-400 50-400 50-400	E E E	Cincinnati Oas № Elo	ectric Co	8305030528 8305030533* 8305090484 8305120342 8305120410	50-358 50-358 50-358 50-358 50-358	K K E 8
	8305140045 8305140109 8305140109 8305140135 8305140135	50-261 50-400 50-400 50-324 50-324	J E J			8305120429 8305120432 8305120446 8305130111	50-358 50-358 50-358 50-358 50-358	8 8 8
	8305170282 8305170282 8305170285* 8305170285* 8305170450	50-400 50-400 50-400 50-400 50-400	A A A			8305170454* 8305170524 8305170553* 8305180458 8305190168	50-358 50-358 50-358 50-358 50-358	G S A F A
	8305170450 8305170497 8305180400 8305180400 8305200009	50-400 50-400 50-400 50-400 50-261	0 E E			8305190190 8305190228 8305190273* 8305190278 8305190281*	50-358 50-358 50-358 50-358 50-358	A G A A
	8305200329 8305200329 8305200384 8305200384 8305200435	50-400 50-400 50-400 50-400 50-261	E E E			8305190314* 8305200536 8305240012* 8305240016* 8305260227	50-358 50-358 50-358 50-358 50-358	A G G
	8305200442 8305200442 8305200538 8305200543* 8305200597	50-400 50-400 50-324 50-324 50-324	E 8 8 F	Citizans Against Nu Citizans Association		8305260337* 8305260338* 8305040421* 8212300007 8305020422	50-358 50-358 50-400 50-445 50-445	A
	8305200597 8305200400 8305200425 8305200425 8305200430	50-324 50-261 50-324 50-324 50-400	F H F O			8305020422 8305020430* 8305020430* 8305020437* 8305040274	50-445 50-445 50-445 50-445 50-445	00000
	8305200630 8305200676 8305200676 8305200679* 8305200679*	50-400 50-400 50-400 50-400 50-400	о К К К			8305040294 8305040499 8305040499 8305040507	50-445 50-445 50-445 50-445 50-445	e :
	8305230283 8305230442 8305240004 8305240417 8305240434	50-261 50-400 50-324 50-400 50-324	Р 8 Р К Р			8305040513 8305040513 8305040515* 8305040515* 8305040529	50-445 50-445 50-445 50-445 50-445	0 T T

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8305040529 8305040535 8305040535 8305090443 8305110137	50-445 50-445 50-445 50-445 50-445	G T T C G	Commerce, Dept of, National Bureau of Btandards	8305170326 8305170527 8305200072 8305200368 8305040596	50-470 50-335 TOPREP 50-470 HIBC	8
	8305110137 8305110157 8305110157 8305110332 8305110332	50-445 50-445 50-445 50-445 50-445	G T T G Q	Committee to Bridge the Gap	8305070131* 8305170067* 8305170325 8305200476 8305200652	CONTRACT 50-142 50-142 50-142 50-142	0000
	8305110347 8305110347 8305110354 8305110354 8305110357	50-445 50-445 50-445 50-445	0 0 1 T 0	Commonwealth Edison Co	8904040269 8904270034 8904270034 8905020086 8905020070*	50-237 50-373 50-373 50-373 50-373	Q P P B B
	8305110368 8305110368 8305110397 8305110397 8305130066	50-445 50-445 50-445 50-445 50-445	G G G		8305020106* 8305020107 8305020114* 8305020115* 8305020142	50-10 50-373 50-373 50-456 50-254	9 9
	8305130066 8305130157 8305130157 8305130175 8305130175	50-445 50-445 50-445 50-445 50-445	G T T O O		8305020154* 8305020205 8305020234* 8305020236* 8305020241	50-254 50-373 50-456 50-373 50-373	8 0 8
	8305170287 8305170287 8305170513 8305170513 8305180272	50-445 50-445 50-445 50-445 PR	0		8305020246 8305020251# 8305020256# 8305020351 8305020353#	50-249 50-373 50-249 50-373 50-373	8 8 8
Cleveland Electric Illuminating Co	8305200504 8303280059 8305020308 8305020300 8305040307	50-445 50-440 50-440 50-440	O A S S O O		8305020458 8305020458 8305020470 8305030084* 8305030084*	50-254 50-254 50-440 50-295 50-295	p 0 F
	8305040307 8305040465 8305040465 8305040486 8305040486	50-440 50-440 50-440 50-440	0 5 5 5		8305030091* 8305030091* 8305030114* 8305030114* 8305030117*	50-295 50-295 50-295 50-295 50-295	F F F
	8305040496 8305040496 8305040516* 8305040516* 8305090490*	50-440 50-440 50-440 50-440	9 9 1 7 0		8305030117* 8305030161 8305030270 8305030274 8305030321	50-295 50-373 50-454 50-322 50-254	F B B B
	8305070493# 8305100013 8305100013 8305100333 8305100333	50-440 50-440 50-440 50-440	0 9 9 9 9 9		8305030333# 8305030440 9305030446# 8305040074# 8305040080#	50-254 50-304 50-304 50-454 50-454	8 8 F
	8305100374 8305110300 8305130236 8305130236 8305130248	50-440 50-440 50-440 50-440	១៩០០១		8305040080# 8305040317 8305040345 8305040371# 8305040446	50-454 50-295 50-373 50-373 50-237	F P R A P
	8305130248 8305170203 8305230104 8305230143 8305230290	50-440 50-440 50-440 50-440 50-440	S G E A A		8305040446 8305040456* 8305040456* 8305040520 8305040520	50-237 50-237 50-237 50-237 50-237	P P P
	8305240515 8305240515 8305250381 8305260267 8305260267	50-440 50-440 PR 50-440 50-440	Q Q E E		8305040524* 8305040524* 8305040551 8305040551 8305040551	50-237 50-237 50-237 50-237 50-237	P P P
Cleveland-Cliffs Iron Co Coalition for Bafe Power	8305160232 8305260383 8305100263 8305170272 8305240347	40-8714 40-8714 50-460 50-522 50-460	0 0 0		8305040351 8305040351 8305040355* 8305040555* 8305040555*	50-237 50-237 50-237 50-237 50-237	P P P
Colt Industries, Inc. Columbia River Inter-Tribel Fish Commission Columbia Univ	8305310005 8305020133 8305170272 8305110236* 8305180047*	50-460 50-483 50-522 CONTRACT	G S O T		8305040555* 8305040555* 8305050043 8305050043 8305060184	50+237 50-237 50-254 50-254 50-454	ዞ የ የ የ
Combustion Engineering, Inc	8305020400 8305020406# 8305070338 8305070372# 8305120120	50-470 50-470 50-470 50-470 50-470	E E E B		8305060184 8305060390 8305060391* 8305060398 8305060401*	50-454 50-254 50-254 50-373 50-373	F 8 8 8
	8305120124* 8305120185 8305120252* 8305130081	50-470 50-470 50-336 50-470	B E P E		8305060416 8305060422* 8305060443 8305060444*	50-237 50-237 50-295 50-295	8 9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305040484 8305040492* 8305040493 8305040509* 8305040511	50-237 50-237 50-373 50-373 50-237	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		8305170378* 8305170383 8305170388* 8305170425* 8305170565	50-373 50-373 50-373 50-373 50-454
	8305060517* 8305060528 8305060544* 8305060554* 8305060554*	50-237 50-295 50-295 50-373 50-373	\$ \$ \$ Q		8305170565 8305180376 8305180376 8305180376 8305180376	50-454 50-237 50-237 50-237 50-237
	8305060559* 8305060563 8305060567 8305060567* 8305060571*	50-456 50-249 50-295 50-373 50-249	9 8 9 9		8305180385 8305180385 8305180397* 8305180787 8305190084*	50-454 50-454 50-454 70-2973 50-373
	8305040572* 8305040581 8305040590 8305040594* 8305040599*	50-295 50-249 50-237 50-249 50-237	8 8 8 8		8305190145* 8305190353* 8305200295 8305200307* 8305200351	50-373 50-373 50-237 50-237 50-275
	8305040403 8305040411* 8305040479* 8305040484* 8305090231	50-237 50-237 50-295 50-295 71-6346	9 F F		8305200522* 8305200522* 8305200540* 8305200540* 8305200621	50-454 50-454 50-454 50-454 50-373
	8305100018 8305100092 8305100190* 8305100237 8305100237	50-374 50-237 50-10 50-454 50-454	S G G A		8305200621 8305200621 8305200621 8305200621 8305200647*	50-373 50-373 50-373 50-373 50-373
	8305100237 8305100237 8305100352 8305110082 8305110082	50-454 50-454 50-374 50-373 50-373	A A S P P		8305200455* 8305200465* 8305200475* 8305200481* 8305230500	50-373 50-373 50-373 50-373 50-10
	8305110215 8305110447 8305110452* 8305120013 8305120013	50-454 50-373 50-373 50-275 50-295	Q R R R		8305230500 8305230500 8305230584 8305230584 8305240007	50-10 50-10 50-373 50-373 50-373
	8305120016# 8305120016# 8305120299 8305130001 8305130001	50-295 50-295 50-454 50-456 50-456	R R Q A A		8305240007 8305240025 8305240073 8305240110 8305240110	50-373 50-373 50-373 50-373 50-373
	8305130038 8305130038 8305130038 8305130051 8305130051	50-237 50-237 50-237 50-454 50-454	P P A A		8305240111 8305240202 8305240207 8305240214 8305240229	50-374 50-237 50-237 50-304 50-373
	8305130051 8305130051 8305130135# 8305130144# 8305130155#	50-454 50-454 50-454 50-373 50-373	A A Q Q Q		8305240245 8305240245 8305240308* 8305240308* 8305240311	50-237 50-237 50-373 50-373 50-295
	8305130155* 8305130197 8305130202 8305130209 8305130209	50-373 50-304 50-237 50-237 50-237	F B R R R		8305240315* 8305240315* 8305240317 8305240318 8305240321	50-373 50-373 50-254 50-373 50-254
	8305130211* 8305130212 8305130220* 8305140059 8305140059	50-304 50-234 50-254 50-454 50-454	8 8 6 6		8305240334 8305240335 8305240339 8305240354 8305240366	50-373 50-237 70-2973 50-373 50-249
	8305160060 8305160060 8305170134 8305170140* 8305170159	50-454 50-454 50-237 50-237 50-237	후 명 명		8305240381 8305240425 8305240473 8305240473 8305240474	50-373 50-373 50-295 50-295 50-237
	8305170163* 8305170167 8305170167 8305170184* 8305170184*	50-237 50-254 50-254 50-254 50-254	8 0 0 0		8305240506 8305250077 8305250077 8305250377 8305250377	50-275 50-275 50-275 50-237 50-237
	8305170218 8305170218 8305170297 8305170297 8305170231*	50-295 50-295 50-454 50-454 50-374	P P Q Q Q		8305250377 8305260282* 8305260286 8305260287 8305260287	50-237 50-454 50-265 50-456 50-456
	8305170372 8305170372 8305170374 8305170376* 8305170376*	50-254 50-254 50-254 50-254	R R 8 R R		8305240290 8305240290 8305270079 8305270079 8305270193*	50-237 50-237 50-456 50-456 50-456

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305270195 8305270237 8305270237 8305270395 8305270395 8305270419	50-373 50-373 50-237 50-237	- 8 8 9 0 0		8305110310* 8305110310* 8305110393 8305110403* 8305130018	50-3 R 50-3 R 50-247 8 50-247 8 50-247 P	t 1 3
	8303270419 8303270419 8303270489* 8303270489* 8303270489*	50-237 50-454 50-454	P P Q Q		8305130022* 8305130024* 8305130064 8305130071 8305160020	50-247 6 50-247 8	9 9 8
	8305310037 8305310095 8305310117 * 8305310142 8305310149	50-295 50-237 50-254	P Q Q S S		8305160025* 8305160075 8305160079* 8305240527 8305250483	50-247 50-247 50-247 50-247	8 8 8 9
	8305310152 8305310158 8305310160 8305310165 8305310182	50-237 50-304	8 8 8 8	Consumers Power Co	8305020079 8305020083* 8305020138 8305020145* 8305020173	50-255 50-255 50-255 50-255	F B B B
Computerh Engineering Services. Inc Computer Systems Support Corp Connecticut Yenkee Atomic Power Co	8305020433* 8305180421* 8305230293* 8304110486 8305020397*	50-206 CONTRACT CONTRACT 50-213 50-213	P Q Q		8305020179# 8305020202 8305020274 8305020398 8305030111	50-155 50-155 50-329 50-329	8 P E R
	8305050054 8305050054 8305050054 8305050112 8305060213	50-213 50-213 50-213 50-213 50-213	P P P F		8305030155 8305030642 8305040441 8305040441 8305040455	50-255 50-329 50-329 50-413	8 0 0 H
	8305090404 8305090465 8305090465 8305090465 8305100331	50-213 50-213 50-213 50-213 50-213	ቴ ቴ ቴ		8305040475 8305040509 8305040509 8305060388 8305060393*	50-255 50-329 50-329 50-255 50-255	00088
	8305100385 8305110049 8305110076* 8305110574* 8305140183	50-213 50-213 50-213 50-213 50-213	# F F F		8305060477 8305060483 8305060483 8305060495 8305090052	50-255 50-329 50-155 50-329	S A A O R
	8305140189* 8305170213 8305170305 8305200608 8305200701*	50-213 50-213 50-213 50-213 50-213	P C S S		8305090052 8305090060* 8305090060* 8305100076 8305100085*	50-329 50-329 50-329 50-255 50-255	R R R R
Conner & Wetterhahn	8305230616 8305250510 8305250565* 8305270224 8305020441	50-213 50-213 50-213 50-213 50-352	P P Q Q		8305100170 8305100250 8305100264 8305100264 8305100279	50-255 50-255 50-329 50-329 50-255	4000
Conover & Associates, Inc. Insurance Conservation Council of North Carolina	8303030363 8303060478 8303240489 8303120011 8303060532	50-352 50-352 50-352 70-1621 50-400	0		8305100287* 8305100291* 8305100306 8305100341 8305100378	50-255 50-255 50-255 50-255 50-255	P B 0 8
Consolidated Edison Co of New York, Inc	8305070475 8305020428 8305030373 8305030380* 8305030400	50-400 50-247 50-247 50-247 50-247	G G S S		9305100384* 9305100376 8305100403* 8305110305 8305110305	50-255 50-255 50-255 50-329 50-329	8 8 8 8
	8305030407* 8305030455 8305030458* 8305030531 8305030531	50-247 50-247 50-247 50-247 50-247	9 P P O		8305110396 8305110402# 8305120147 8305120273 8305120273	50-255 50-327 50-327	RFOG
	6305040242* 6305040247* 6305040247* 6305040249* 6305040249*	50-3 50-3 50-3 50-3 50-3	F F F F		8305130140 8305130145* 8305130182* 8305130185 8305130208	50-329 50-155 50-255	8 0
	8305040254* 8305040505 8305040505 8305040505 8305040461 8305090425	50-3 50-247 50-247 50-579 50-247	F Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q		8305130214* 8305130215 8305130225 8305130230* 8305160070	50-155 50-255 50-255 50-255	8 8 8 P
	8305090425 8305100175 8305100208 8305110302 8305110302	50-247 50-247 50-247 50-3 50-3	T P Q R R		8305170131 8305170131 8305170283 8305170283 8305170300#	* 50-255	A B B Q
		10-3 10-3 10-3	R R R R		8305170373 8305170391 8305170391 8305170397 8305170397	50-329 50-329 50-329 50-329 50-329	A

AUYHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	t Y	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY
	8305170404 8305170409 8305170409 8305170410 8305170422	50-155 50-329 50-329 50-155 50-329	F 8 8 P A	Dairyland Power Cooperative	8305030178* 8305050004 8305050010* 8305020146 8305020170*	50-341 50-341 50-341 50-409 50-409	A A A S
	8305170422 8305170440 8305170440 8305170467 8305170467	50-329 50-329 50-329 50-329 50-329	A S B A A		8305020182* 8305100025 8305110298 8305120066 8305130112*	50-409 50-409 50-409 50-409 50-409	5 P P Q
	8305170489 8305170489 8305170539 8305170539 8305190065	50-329 50-329 50-329 50-329 50-329	S S A A		8305130267* 8305130271* 8305160050 8305230029 8305230398	50-409 50-409 50-409 50-409 50-409	Q Q F J
	8305190065 8305190196 8305190280 8305190284* 8305190298	50-329 50-155 50-329 50-329 50-329	A P A Q	Davisson, M T DeKalb Area Alliance for Responsible Energy	8305240327 8305310169 8305160332* 8305030508	50-409 50-409 50-367 50-454	Q F A T
	8305190298 8305190300* 8305190300* 8305190317 8305200218	50-329 50-329 50-329 50-155 PR	0 G G		8305030516* 8305100286 8305170567* 8305170572* 8308170572*	50-454 50-454 50-454 50-454	T 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	8305200349 8305200349 8305200389 8305200610 8305200680	50-329 50-329 50-329 50-155 50-329	8 8 A 0 8		8305170576* 8305170581* 8305170588* 8305170580*	50-454 50-454 50-454 50-454	0000
	6305200680 6305230044 6305230270 6305240008* 6305240008*	50-329 50-155 50-155 50-329 50-329	8 G R G	Debevoise & Liberman	8305170590* 8305170593* 8305170593* 8303290382 6305020473	50-454 50-454 50-454 50-377 50-460	0 0000
	8305240010 8305240011 8305240043 8305240137 8305240137	50-329 50-255 50-255 50-329 50-329	8 6 K K		8305040538 8305050009 8305050018 8305050019 8305060491	50-413 50-440 50-445 50-460 50-508	G G G G T
	8305240280 8305240270 8305240322 8305240353 8305240353	50-155 50-255 50-329 50-329 50-329) 0 A A		8305090511 8305100267 8305100267 8305100270	50-445 50-445 50-445 50-445 50-445 50-445	
	8305240371* 8305240410 8305240427 8305240427 8305240438	50-255 50-255 50-327 50-329 50-155	G R A O		8305100287* 8305100287* 8305100287* 8305100275 8305100277*	50-413 50-413 50-445 50-445 50-413	00000
	8305240491 8305240491 8305240505 8305240505 8305240565*	50-329 50-329 50-155 50-155 50-155	9 P P		8305100297* 8305100305* 8305100305* 8305100321 8305100321	50-413 50-413 50-413 50-445 50-445	00000
	8302550599* 8302590532 8302590532 8302590518 8302590518	50-329 50-329 50-329 50-329 50-155	8 8 8 0		8305130240 8305170514 8305180358 8305180447 8305240355	50-445 50-460 PR PR FOIA	0
	8305260309 8305260309 8305260324 8305260324 8305270057	50-330 50-330 50-329 50-329 50-329	8 8 8 K	Decision Brience Consortium, Inc Dal-Aware Unlimited, Inc	8305240465 8305240485 8305250406 8305110528 8305310013	50-460 50-413 PR NUREG 50-352	G G
	8305270057 8305270063* 8305270063* 8305270066* 8305270547	50-329 50-329 50-329 50-329 50-329	K K K Q	Detroit Edison Co.	8305020085 8305020370 8305030349 8305030476 8305030585	50-341 50-341 50-341 50-341 50-341	8 4 8 8 8
	8305270610* 8305310168 8305310190 8305310190 8305310197	50-324 50-255 50-329 50-329 50-255	Q B A A B		8305030594 8305090480 8305100015 8305100118 8305100119	50-341 50-341 50-341 50-341 50-341	S F S A
Continuum Dynamics, Inc. Cornell Univ. Cortland, NY Cottor Corp.	9305310202 9305130104* 9305110476 9305240554 9305060319	50-255 50-271 NUREO 50-247 WASTE			8305100154 8305100373* 8305100379* 8305170207 8305170535	50-341 50-341 50-341 50-341 50-341	8 9 9
Crears, Inc Cygna Energy Hervices	8305060325* 8305260356 8305260360 8305270105* 8305030171	WABTE WABTE WABTE CONTRA 50-341	HOT MOT CT	Daylance & O'Meara, Ltd Disc Corp.	8305170662 8305230552 8305090285 8305090018	70-2926 50-341 50-566 XPDRTLIG	A A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEO	ORY
Dougherty, J B Downers Grove Orthopedic Associates, Downers Grove, IL	8305030056* 8305130072 8305180341 8305030480	XPORTL 50-322 PR PR	IC		8305170292 8305170296 8305170324 8305170338* 8305170355	50-413 50-413 50-269 50-269 50-369	8 F 9
Duke Pawer Co	8305020020	50-413			8305170358# 8305170455	30-369 30-269	8
	8305020326 8305020372 8305020375* 8305040229 8305040229	50-413 50-269 50-269 50-369 50-369			8305170455 8305170455 8305170460#	30-269 30-269 30-269	R
	8305040240* 8305040240* 8305040244* 8305040260* 8305040273	50-369 50-369 50-369 50-369 50-369	8 8 8		8305170460# 8305170460# 8305170507 8305170536 8305170536	50-269 50-369 50-369 50-369	8
	8305040273 8305040467 8305040538 8305040564 8305040564	50-369 50-370 50-413 50-269 50-269	9 P P		8305170540# 8305170540# 8305170566# 8305170566# 8305190020	50-369 50-369 50-269 50-269 50-370	RRS
	8305040564 8305040568* 8305040568* 8305040568* 8305040577*	50-269 50-269 50-269 50-269 50-369	₽ የ የ የ		8305190032 8305200401 8305200401 8305200438 8305200440*	50-370 50-413 50-413 50-369 50-369	± € € ₽ ₽
	8305040606* 8305050008 8305050014* 8305050135 8305050135	50-369 50-413 50-413 50-369	F A F F		8305200440* 8305200474 8305200474 8305200544 8305240259*	50-369 50-413 50-413 50-269 50-287	EGP
	8305050153 8305050254 8305050254 8305050283 8305060224	50-370 50-269 50-269 50-369 50-369	8 8 9		8305240485 8305240485 8305250278 8305250281 8305250281	50-413 50-413 50-369 50-369 50-369	Q P P
	8305060382 8305060403 8305060403 8305060413 8305060413	PR 50-369 50-369 50-369 50-369	8 8 P		6305250282 8305250287 8305250287 8305250290 8305250404	50-413 50-369 50-370 50-369	8 P P B
	8305090435 8305090468 8305090468 8305090472 8305090472	50-287 50-413 50-413 50-369 50-369	P 0 0 B B		8305250439 8305250442 8305250449 8305250479 8305250479	50-370 50-369 50-414 50-269 50-269	8 P P
	8305100002 8305100003* 8305100007 8305100148 8305100148	50-369 50-369 50-369 50-369 50-369	8 9 9 0		8305250479 8305250499 8305250507 8305250525 8305250549	50-269 50-370 50-370 50-370 50-369	P 8 8 8
	8305100282 8305100282 8305100289* 8305100289* 8305100297*	50-413 50-413 50-413 50-413 50-413	00000		8305250549 8305250556 8305250556 8305250556 8305260261	50-369 50-269 50-269 50-269	8 8
	8305100297# 8305100305# 8305100305# 8305100327 8305100342	50-413 50-413 50-413 50-369 50-413	00000		8305240241 8305240241 8305240241 8305240241 8305270005	50-269 50-269 50-269 50-269 50-413	*
	8305100342 8305100347 8305100366 8305100383 8305100383	50~413 50~369 50~369 50~369 50~369	C P S P		8305270069 8305270259 8305270279# 8305270274# 8305270366#	50-413 50-269 50-269 50-269 50-369	6 P P Q
	8305100370# 8305100370# 8305100415 8305100415 8305110085	50~369 50~369 50~413 50~413 50~369	P P Q G		8305310025 8305310025 8305310035 8305310035 8305310052	50-413 50-413 50-413 50-413 50-349	0 0 0 0 8
	8305110281 8305110283* 8305110323 8305110335* 8305130025	50-369 50-369 50-270 50-270 50-269	8 8 8		8305310081 8305310081 8305310081 8305310200 8305310200	50-249 50-249 50-249 50-413 50-413	0 0 E E
	8305130158 8305130192 8305130192 8305160285* 8305160286*	50-369 50-369 50-369 50-369 50-369	r 8 F F F	Duquesne Light Co	8305020357 8305020426 8305030311 8305030316* 8305030573	50-334 50-412 50-334 50-334 50-334	P F B R
	8305150293* 8305170258 8305170269* 8305170277	50-413 50-370 50-370 50-369	F S F		8305030595* 8305060261 8305060269* 8305060604 8305060609*	50-334 50-334 50-334 50-334 50-334	R R P P

	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AFFILIATION	CCESSION NUMBER	SUBJECT CATEGOR	
~-		8305060614* 8305100104 8305100268 8305100337 8305110295	50-334 P 50-412 S 50-334 G 50-334 F 50-412 S	i i i	83 83 81	105110361 105110361 105110366 305110366	50~400 50~400 50~400 50~400 50~400	0 0 0
		8305110343 8305110353* 8305110360 8305110424 8305120402	50-334 F	B P	Edelstein & Payne Si Bi Bi	305240500 305240500	50~400 50~400 50~400 50~400 50~400	0 0 0 0
		8305120411* 8305160058 8305160064* 8305180256 8305180259*	50-334 5 50-334 5 50-412 5	8 8 9 F	Elactric Power Research Institute 8	305250420	PR PR NUREO 50-413 50-413	G Q
		8305180283 8305180287* 8305180559 8305180569* 8305180576*	50-412 50-412 50-412	К К К С	Energy Fuels Nuclear, Inc 8	305250511* 305250589* 305020481 305020484* 303310020*	50-483 50-483 40-8681 40-8681 50-333	о 0 8
		8305180585* 8305180592* 8305180598* 8305180606* 8305180613*	50-412 50-412 50-412	K K K K	Enørgy, Dopt of E	305200637* 305200691* 303240390 305020036 305030688	50-373 50-373 50-537 71-9510 50-201	Р С Р
		8305180625* 8305180634* 8305180641* 8305180650* 8305180655*	50-412 50-412 50-412	Х К К К	\$ 6	1305060524 1305070576* 130511013B 1305110142 1305110220	50-537 50-445 WASTE MG WASTE MG 50-537	QΤ
		8305180461* 8305180464* 8305180473* 8305180481* 8305180485*	50-412 50-412	K K K		9305110438 9305110448 9305110447* 9305180210 9305180670	50-537 50-537 50-537 71-6439 71-6272	9
		8305180693* 8305180695* 8305180697* 8305180705* 8305180708*	50-412 50-412 50-412 50-412 50-412	K K K		8305180676# 8305180684 8305170337 8305200676 8305200648#	71-6272 71-9150 50-537 50-537 50-537	
		8305180715# 8305180720# 8305180728# 8305180735# 8305180740#	50-412 50-412 50-412 50-412 50-412	K K K		8305230080 8305240064 8305240475 8305240480 8305240503	71-5407 71-4553 50-537 50-537 50-537	
		8305180746* 8305180747* 8305180755* 8305180760* 8305180764*	50-412 50-412 50-412 50-412 50-412	K K K	Energy, Dept of, Clinch River Dreeder	8309260003 6309310003* 8305310188 83053170449 8309200459	71-5552 50-537 50-537 50-537 50-537	A G A B
		8305180747* 8305180749* 8305190185 8305190309* 8305200429	50-412 50-412 50-334 50-334 50-412	8 8 K	Energy, Dapt of, Idaho Operations Ofc	8305200463* 8305230113 8305230285 9305230272* 8305230015	50-537 50-537 50-537 50-537 50-201	A
		8305200439# 8305230387 8305230520 8305230527# 8305240248	50-334 50-334 50-334 50-334 50-412	0 8 8 K	Epler, E P European Communities, Commission of	8305240614 8305070255* 8305020005 8305020076 8305020482	50-201 50-272 XPORTL XPORTL 50-443	IC IC
		8305240401 8305240404 8305250478* 8305250516 8305270187	50-334 50-334 50-412 50-334 50-334	11 0 0 1	Exster, NH Exsen Corp	8305020482 8305020486* 8305020486* 8305030719 8305260143	50-443 50-443 50-443 40-806 40-806	9
	EUS Nuclear, Inc. EG40, Inc	8305270170# 8305270662# 8305030564# 8304220257# 8305030474#	50-334 50-412 50-298 50-321 50-483	9 9 9	Exyon Nuclear Co . Inc (subs of Exxon Corp)	8305030272 8305090010 8305100178 8305100184	TOPREP XPORTL 70-125 70-125 XPORTL	.1C 57 57
	ENGA, Inc	8305110467 8305110482 8305110518 8305110523 8305060347	NUREO NUREO NUREO NUREO NUREO			8305170584 8305170514 8305170621* 8305180047 8305180073* 8305180642	XPORTI XPORTI XPORTI XPORTI XPORTI	LIC LIC LIC LIC
	Eason Diving & Marine Contractors, Inc Ebasco Sarvices, Inc (subs of Enserch Corp.) Ecological Analysts, Inc	8304110519#		g P R		8305180648* 8305180833 8305240310 8305240018 8305260064		57 LIC P LIC
	Edőlemen: H	8305040485 8305110145 8305110122 8305110222 8305110222	30-400 50-400 50-400 50-400 50-400	000	FOI Services Fansteel Metals (subs of Fansteel, Inc.) Fansteel, Inc	6305120573	FOIA 40-75 40-75) 80

AUTHOR AFF [LTATION	ACCESSION NUMBER	SUBJECT CATEGOI	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEORY	ſ
Federal American Partners Federal Emergency Management Agency	8305140261* 8305200037* 8305200419 8305060506 8305060429*	40-7580 40-4492 50-247 50-247 50-247			8305250397 8305250415 8305250416 8305250455 8305250462	PR 50-389 50-389	В Р Р
	8305070572* 8305100122 8305100124* 8305100131* 8305100136*	50-445 50-295 50-295 50-295 50-295	0 # F F		8305250472 8305250472 8305250481 8305250484 8305250491#	50~335 50~335	PPPP
	8305100143 8305120426* 8305120427* 8305200465* 8305230474	50-287 50-207 50-209 50-215 COMMISS	F F F F		8305250519 8305250519 8305270104 8305270125 8305270129	50-250 50-250 50-387 50-389 50-250	P
Ferguson, Inc Finland	8305230479* 8305230670 8305310049 8305200637* 8305240015	COMMISS: 50-3 50-247 50-373 NUREQ	ION F F P		8305270153 8305270168 8305270170 8305270251 8305270360*	50-387 50-335 50-335 50-387 50-387	* * * * *
Fleischaker, D S Florida Power & Light Co	8305060451 8305070438 8305200273* 8305020084 8305020168	50-275 50-275 50-275 50-335 50-335	9 9 9 9	Florida Power Corp	8305270520# 8305270572# 8305310034 8305310184 8305030036	50-389 50-335 50-250 50-389 50-302	9 9 9
	8305020345 8305020519 8305030168 8305030173* 8305030240*	50-335 50-335 50-251 50-251 50-387	P R R F		8305030050 8305050016 8305050025* 8305070462 8305100278*	50-302 50-302 50-302 50-302	P 8 8 P 8
	8305030244 * 8305030304 8305030340 8305030341 8305030341	50-389 50-389 50-335 50-335 50-335	F 9 0 R R		8305110380 8305110390* 8305130002 8305130012 8305130043	20-303 20-303 20-303 20-303 20-303	8 P P R
	8305030392 8305030392 8305030441 8305030404 8305040563	50-250 50-250 PR 50-389 50-335	0 0 8 F		8305130047# 8305130067 8305130179 8305130188# 8305170399	50-302 50-302 50-302 50-302	R P B 9
	8305040566* 8305050127 8305050136* 8305070432 8305070476	50-335 50-335 50-335 50-250 50-335	F 8 8 8 8		8305170402* 8305170344 8305200378 8305230393 8305240359	50-302 50-302 50-302 50-302	8 P P
	8305100001 8305100088 8305100103 8305100165 8305100182	50-250 50-387 50-335 50-250 50-335	G S & A & S & S & S & S & S & S & S & S &		8305270092 8305270253* 8305270258* 8305270295 8305270312*	20-305 20-305 20-305 20-305 20-305	P 0 0 0
	8305100227 8305100236 8305100251 8305100253* 8305100269	50-389 50-335 50-251 50-251 50-389	8 P 9 9 9	Fracture Proof Design Corp	8305270318* 8305270503* 8305030412* 8305060407* 8305060417*	20-589 20-589 20-589 20-305 20-305	9 P P
	8305110487 8305110496* 8305130008 8305130118 8305130121	50-250 50-250 50-250 50-389 50-335	8 8 6 6 6	Franklin Institute/Franklin Research Center	8305200412* 8206300177* 8208060247* 8209210332* 8304070286*	50-264 50-309 50-336 50-269	P P P P
	8305160010 8305160282# 8305160284* 8305170191 8305170197*	50-251 50-387 50-387 50-387 50-389	P F 당 당		8305110545* 8305170106* 8305190322* 8305200720* 8305230284*	CONTRACT 50-272 50-387 50-338 50-213	9 8 P
	8305170244 8305170250* 8305170310 8305170356 8305170463	50-335 50-335 50-387 50-387 50-335	8 8 8 F	Friends of the Earth	8305310241* 8305160024 8305160024 8305160028* 8305160028*	50~285 50~247 50~247 50~247 50~247	20000
	6305170520 6305170520 8305170525* 8305170525* 8305170546	50-250 50-250 50-250 50-250 50-250	P P P F	Fulton.MO Future Coatings, Inc. Future Resources Associates, Inc.	8305250304* 8305250354* 8305250536* 8305180183 8305180353	50-483 50-483 50-483 40-8035 PR	0
	8305200181 8305200346 8305200346 8305200489 8305230016	50-389 50-335 50-335 50-335 71-5957	8 # F F	QA Technologies, Inc./General Atomic Co Gesconade County, MD	8305020435 8305040375 8305040670 8305180837# 8305250363#	50-358 XPORTLIC XPORTLIC XPORTLIC 50-483	;
	8305230532 8305240372 8305250272 8305250302 8305250395	50-335 50-335 50-335 50-335 50-335	P P 9 9	General Electric Co.	8305250573* 8303240338 8305020050 8305020355	50-483 50-447 70-1007 50-447	A E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFELIATION	ACCESSION NUMBER	SUBJECT	y
	8305020345* 8305020347* 8305020520 8305030403 8305040433	QA799 QA999 70-754 50-447 TOPREP	^		8305120068* 8305120312 8305120317* 8305120323* 8305120326*	50-320 50-320 50-320 50-320	P T T T
	8305040458 8305040466* 8305040558 8305040561* 8305040567*	TOPREP TOPREP XPORTLIC XPORTLIC XPORTLIC			8305120335* 8305120338* 8305120341* 8305120350* 8305120357*	50-320 50-320 50-320 50-320	T T T T
	8305050168 8305050426 8305060076* 8305060160* 8305060171*	70-1113 NUREO 50-331 FOIA FOIA	р		8305130065 8305130070* 8305130074* 8305130180 8305160023*	50-289 50-289 50-289 50-289 50-219	P P G
	8305090483 8305090495* 8305090497* 8305100298 8305100370*	TOPREP TOPREP TOPREP 50-447 50-325	E P		8305170435 8305170448 8305170558 8305190158 8305190240	50-320 50-320 50-219 50-289 50-289	P P P R
	8305110196 8305170578 8305170693* 8305180417 8305180713	NUREG XPORTLIC CONTRACT XPORTLIC XPORTLIC			8305190247* 8305200173 8305200179* 8305200500 8305200502	50-289 50-289 50-289 50-219 50-289	R P G P
	8305200157 8305200552 8305240034 8305260037 8305260048*	50-447 TOPREP 70-1301 50-447 50-447	A E E		8305200547 8305200551* 8305200563 8305230037 8305230402	50-289 50-289 50-320 50-219 50-219	8 8 7 9 9
Omneral Physics Corp	8305240075 8305240325* 8305270378* 8305310115* 8305110491	XPORTLIC 50-324 50-333 70-1113 NUREO	P P		8305230436 8305230437 * 8305240349 8305240536 8305240536	50-219 50-219 50-220 50-219 50-219	R R R Q
General Public Utilities - OPU Service Corp	8305020210 8305020232* 8305020362 8305020465*	50-289 50-289 50-219 50-219	R Q P I		8305240534 8305250203* 8305250255 8305250263* 8305250267	50-219 50-289 50-320 50-320 50-289	9 9 9 9
	8305030095 8305030102 8305030112* 8305030127* 8305030365	50-287 50-287 50-287 50-287 50-217	8 8 8 F		8305250271* 8305250385 8305260085 8305260094 8305270082	50-289 50-320 50-289 50-289 50-219	P Q P P
	8305030441 8305030441 8305030447# 8305030462 8305030470#	50-289 50-219 50-219 50-320 50-320	6 8 9 R R		8305270203 8305310001 8305310004* 8305310007* 8305310010*	50-287 50-320 50-320 50-320 50-320	R 8 8
	8305030476* 8305030484* 8305030527 8305030535* 8305030695*	50-320 50-320 50-320 50-320 50-289	R R 9 8 F F		8305310014# 8305310017# 8305310030# 8305310030# 8305310034#	50-320 50-320 50-320 50-320 50-320	8 8 8 8 8
	8305040580* 8305050022 830505030304* 8305050307* 8305050381*	50-320	F F F F		8305310041* 8305310047* 8305310058 8305310058 8305310041*	50-320 50-320 50-320 50-320 50-320	8 8 8 9 6
	8305060082 8305060458 8305060458 8305060458 83050604604		P R R R		8305310066* 8305310072* 8305310078* 8305310080* 8305310087*	50-320 50-320 50-320 50-320	9 9 9 9
	8305060444 8305060649 8305060649 8305090351 8305090453	50-289 50-289 50-289 50-289	R R P		8305310071* 8305310076* 8305310101* 8305310103* 8305310107*	50-320 50-320 50-320 50-320 50-320	8
	8305110284 8305110287* 8305110324 8305110324*	50-320 50-320 50-287	8 8 8 8	George Washington Univ	8305310114* 8305310118 8305310156 8305310205 8305040353*		P P F CT
	8305110342* 8305110346 8305110351* 8305110370 8305110374	50-289 50-289 50-320 50-219	8 9 8	Georgia Power Co.	8305030261 8305030261 8305030261 8305030634 8305030634	50-321 50-321 50-321 50-321	H H P P
	8305120015 8305120015 8305120055 83051200640 83051200640	50-320 50-287 50-289	Н Р Р		9305030665* 9305030665* 9305030697* 9305030690* 9305040654*	50-321 50-321 50-321	F F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJEC CATEOD	
	8305040457* 8305050030 8305050040* 8305050093	50-321 50-321 50-321 50-321 50-424	F 5 8 8	Gilbert/Commonwealth Cos	9305020443# 9305060277# 8305110313 8305110322 8305120355#	50-244 50-395 50-395	P 8 9
	8305050087* 8305060051 8305060254 8305060306 8305060306	50-321 50-321 PR 50-321 50-321	S P P	Golder Associates Good Sameritan Hosp Downers Grove, IL Government Accountability Project	8305190201* 8305050404* 8305180436 8305190097* 8305190124*	PR 90-329	τ ^P α
	8305040449 8305040449 8305100141 8305110249 8305110270	50-321 50-321 50-424 50-321 50-321	F F S S S	Greater New York Council on Energy	8305190216 8305190292* 8305190304* 8305260166 8305250223		9 9 9
	8305110272* 8305110273* 8305110287 8305110293* 8305110364	50-321 50-321 50-321 50-321 50-321	5 9 8 8	Guild, R Guif Nuclear, Inc Guif States Utilities Co	8305060252 8305240031 8305030422 8305060435 8305060475	50-413 71-9163 50-458 50-458 50-458	\$ B B
	8305110364 8305110375 8305110389* 8305110404 8305110410	50-321 50-366 50-366 50-321 50-366	9 8 8 5 5		8305100198 8305100198 8305120321 8305120343 8305120367	50-458 50-458 50-458 50-458 50-458	A B G B
	8305110412= 8305110417* 8305110429 8305110431 8305110434*	50-321 50-366 50-366 50-321 50-321	8 8 5 5		8305120409 8305120413 8305120424 8305170281 8305170385	50-458 50-458 50-458 50-458 50-458	***
	8305110436* 8305130235 8305130242* 8305140144 8305140144	50-366 50-366 50-366 50-321 50-321	\$ \$ 9 9		8305170468 8305170468 8305170473* 8305170479 8305200151	50-458 50-458 50-458 50-458 50-458	K K S S
	B305160159 B305170178 B305170254 B305170262# B305170276	50-364 50-321 50-321 50-321 50-366	P 8 8 8		8305200264 8305200390 8305230009* 8305230438 8305230462	50-458 50-458 50-458 50-458 50-458	6 F 8
	B3051702B4* B3051703B9 B305170394* B305170434 B30517043B*	50-366 50-366 50-366 50-321 50-321	8 9 9 9		8305240469 8305260268 8305260279 8305260318 8305310042	50-458 50-458 50-458 50-458 50-458	8 8 8 8
	8305170442 8305170445* 8305170481 8305170499* 8305170502	50-321 50-321 50-366 50-366 50-366	5 6 8 8 8	HMM Associates, Inc HPT, Inc Hempton, NH	8305310102 8305090614* 8305060675 (8305180448* 8305190346	50-458 50-443 NUREO 50-322 50-443	F H 0
	8305170506* 8305180279 8305180279 8305180284* 8305180284*	50-346 50-321 50-321 50-321 50-321	B R R R	Hardy Associates, Inc Harmon & Weiss	8305230104 8305030502 8305030541 8305040447 8305040382	71-9135 50-537 50-443 50-329 PR	0
	8305200453 8305200453 8305230463 8305230468* 8305230486	50-321 50-321 50-364 50-366 50-366	P 8 8 8		8305040573 8305100204 8305160002 8305160002 8305160019	PR 50-247 50-443 50-443	0 0 0
	8305230490* 8305230495 8305230498* 8305230548 8305230577*	50-366 50-366 50-366 50-321 50-321	8 8 8 8 8 8 8		8305160019 8305160073 8305160149 8305160181 8305180363	50-443 50-289 50-537 50-537 PR	0 0
	8305240250 8305250452 8305250530 8305250530 8305260278	50-366 50-424 50-321 50-321 50-366	P 8 F F P		8305190221 8305200470 8305240538 8305240538 8305240548	50-537 PR 50-247 50-247 50-247	0
	8305270123 8305270128 8305270128 8305270234 8305270336*	50-366 50-321 50-321 50-321 50-321	S Q Q 8 Q	Hartford Insurance Group Hartsville Group	8305240342* 8305240353 8305270539 8305180299 8305180452	50-247 50-537 50-358 50-261 50-261	9 9 9 9
	8305270508# 8305310073 8305310084# 8305310072#	50-366 50-366 50-366 50-366	G G G	Harleton Laboratories America: Inc Hittman Corp Hittman Nuclear & Development Corp (subs Hittman Corp.)	8305030592* 8305230730 8305040159*	50-461 71-9151 71-9079	R
	8305310124 8305310146 8305310180	50-346 50-321 50-321	s s		8305040176# 8305260355# 8305260373#	71-9079 71-9151 71-9151	
Geotechnical Engineers, Inc Getty Dil Co (Petrotomics)	8305310206 8305060384# 8305020439	50-366 50-329 40-6659	g A	Holtoran & Associates House of Rep	8305240144 8305240154* 8305130087	TOPREP TOPREP 50-443	o

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY
House of Rep , Energy & Commerce House of Rep , Government Operations	8305170457 8305240555 8305240558* 8305230703 8305230475*	50-440 50-247 50-247 50-289 COMMISSI	е т т U		8305020440 8305040265* 8305040265* 8305040268* 8305040268*	50-315 50-315 50-315 50-315 50-315	\$ F F
House of Rep , Interior & Insular Affairs	8305040145* 8305230369* 8305230388* 8305230735* 8305240272*	50-287 COMMISSI 50-289 COMMISSI 50-358	U		8305060400 8305060406* 8305060411* 8305060414* 8305090363	50-315 50-315 50-315 50-315 50-315	8 8 8 8
Hause of Rep , Science & Technology Kauston Lighting & Power Co	8305240275* 8305230664* 8305240023* 8305030430 8305060456	50-358 COMMISSI 50-537 PR 50-498	g ON U		8305090363 8305120318 8305120324* 8305120396 8305120399*	50-315 50-314 50-314 50-315 50-315	R 5 5 5 5
	8305110225 8305170510 8305180358 8305230416 8305230416	50-498 50-498 PR 50-498 50-498	9 8		8305130097 8305130101* 8305130164 8305130174* 8305130178	50-315 50-315 50-314 50-314 50-315	5 5 5 5
	8305230525 8305230525 8305250054 8305250058*	50-498 50-498 50-498 50-498 50-498	8 9 K K K		8305130191* 8305130206 8305160054 8305160054 8305160062*	50-315 50-315 50-315 50-315 50-315	9 R R R
Haward Univ Hunton & Williams	8305230058* 8305310177 8305230311* 8305030855 83050308557	50-498 50-498 CONTRACT 50-338 50-322	K A G		8305160062* 8305160104 8305160108* 8305160121 8305160121	50-315 50-315 50-315 50-315 50-315	R P P P
	8305030560 8305040461 8305050024 8305050029* 8305100391	50-322 50-322 50-322 50-322 50-322	0 0 T T		8305160126* 8305160126* 8305170270 8305170270 8305170274*	50-315 50-315 50-315 50-315 50-315	P
	8305130077 8305140004 8305170208 8305170378 8305170382*	50-322 50-322 50-322 50-322 50-322	0 0 0 0		8305170441 8305170444* 8305170446 8305170451* 8305240086*	50-315 50-315 50-316 50-316 50-315	55 55 55 55
Hydrogen Cantrol Owners Group, BHR-6 Mark IJI IRT Carp	8305310040 8305310051 8305130126 8305230026	50-322 50-322 50-416 70-1359	0 0 P		8305240145 8305240327 8305240330 8305240345 8305240342	50-316 50-315 50-315 50-315 50-315	88888
Ichthyological Associates, Inc Illinois Pour- Co	8305230035* 8305020215* 8305060465* 8303240346 8304050254*	70-1359 50-289 50-289 50-441 50-441	R R A K K		8305240370* 8305240374* 8305260281 8305260281 8305270087	50-315 50-315 50-315 50-315 50-315	88668
	8305020111 8305030559 8305040298 8305040574 8305120475	50-461 50-461 50-461 50-461 50-461	9 R S G		6305270107 6305270223 6305270227* 6305270230* 6305270444	50-315 50-316 50-316 50-316 50-315	8 8 8
	8305130146 8305200667 8305240142 8305240413*	30-461 50-461 50-461 50-461	E A A	Institute of Electrical & Electronic Engineers Institute of Nuclear Power Operations	8305310088 8305310179 8305110119 8305240476*	50-315 50-314 NUREG 50-217	P S
	8305240421# 8305260247#	50-461 50-461	A A		8305240519* 8305250517	50-244 PR	R
	8305240253* 8305270017 8305310127 8305310183	50-461 50-461 50-461 50-461	A B B	Instituto di Ingegneria Nucleare, Milan. Italy Interior, Dept of, Geological Survey	8305040399 8305180334 8305190514* 8305230031*	PR CONTRACT CONTRACT	
Illinois, State of	8305180334 8305190151* 8305190167*	PR 50-373 50-373	Q Q	International Brotherhood of Electrical Workers	8305240517	50-247	н
Indiane & Michigan Electric Co	8305170379* 8303280126 8303280136*	50-373 50-315 50-315	P 5	Towa Electric Light & Power Co	8305030131 8305030374 8305030376* 8305040387	50-331 50-331 50-331 50-331	9 8 9
	8305020072 8305020078* 8305020141 8305020151*	50-316 50-316 50-315 50-315	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8305060060 8305060066* 8305060472 8305100095 83051000320	50-331 50-331 50-331 50-331 50-331	P P S P
	8305020161 8305020171* 8305020177* 8305020172 8305020178*	50-316 50-316 50-316 50-316 50-316	3 9 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9		8305100372* 8305130094 8305180346 8305180349*	50-331 50-331 50-331 50-331	0 8 R
	8305020299 8305020312* 8305020317 8305020321*	50-315 50-315 50-315 50-315	8 8 8		8305230562 8305240120 8305240221	50-331 50-331 50-331	P S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC*		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8305240236 8305240511 8305270429 8305270440 8305270451*	50-331 50-331 50-331 50-331 50-331	8 8 8		8305120297 8305120300* 8305120329 8305130069 8305180341	50-922 50-322 50-322 50-322 PR	0000
Iowa Geological Survey Isham, Lincoln & Beale	8305270460* 8305090162 8305060461 8305060495 8305100264	50-331 NUREG 50-599 50-155 50-329	9 0 0	Kudzu Alliance	8305240548 8305310063 8305240500 8305240500 8305240507	50-322 50-322 50-400 50-400	00000
	8305100264 8305100341 8305100418 8305100418 8305110141	50-329 50-329 50-329 50-329 50-155	0000	Labat-Anderson, Inc Labor, Dept of	8305240507 8305200134* 8305040145* 8305040220* 8305120474*	50-400 CONTRACT FOIA 40-672 FOIA	, 0
	8305110215 8305120273 8305120299 8305130185 8305170297	50-454 50-329 50-454 50-155 50-454	00000	Lawler, Matusky & Skelly Engineers	8305230597* 8305230650* 8305230650* 8305230656*	50-410 50-410 50-410 50-410 50-410	****
	8305170297 8305170365 8305170365 8305200610 8305240373	50-454 50-454 50-454 50-155 50-329	00000		8305230656* 8305230661* 8305230666* 8305230678* 8305230678*	50-410 50-410 50-410 50-410 50-410	* ****
Isomedix, Inc. (subs. of Masefield Enterprises, Inc.) Japan	8305240438 8305240491 8305270547 8305020268*	50-155 50-329 50-329 04999 XPORTL 10	9	Lawrence Berkeley Laboratory Lawrence Livermore Laboratory	8305240552 8209020402* 8303310020* 8304040471* 8305130355	71-6550 50-335 50-333 50-335 50-537	P P P
	8305170580 8305170582 8305180627 8305180817 8305180826	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		LeBoauf, Lamb, Leiby & MacRae	8305070480 8305130073 8305130073 8305130078 8305130078	50-341 50-546 50-546 50-546 50-546	F0000
Jarsey Central Power & Light Co Joint Applicants-Clinch River Breeder Reactor	8305130308* 8305130308* 8305130309* 8305130309* 8305030542	50-272 50-272 50-272 50-272 50-37	F # F O	League of Homen Voters of Rockford, IL	8305130244 8305130244 8305180358 8305030508 8305030516*	50-546 50-546 PR 50-454 50-454	0 0 T
Joint Applicants-Palo Varde Joint Applicants-South Teras Project Joint Intervenors-Diable Canyon	8305030594 8305020434 8305040499 8305090438 8305110212	50-529 50-498 50-498 50-275 50-275	00000		8305100286 8305170549* 8305170572* 8305170572* 8305170576*	50-454 50-454 50-454 50-454 50-454	00000
	8305110212 8305110383 8305110383 8305120285 8305200273*	50-275 50-275 50-275 50-275 50-275	0 0 0 P		8305170581* 8305170581* 8305170588* 8305170570* 8305170570*	50-454 50-454 50-454 50-454 50-454	00000
KMC, Inc Kansas City Power & Light Kansas Oas & Electric Co	8305180308 8305230572> 8305020421 8305030354 8305030378	FOIA 50-482 50-482 50-482 50-482	I F S	League of Homen Voters of Buffolk Co., NY Lewis, H	9305170593* 8305170593* 8305180347 8305030418 8305200441	50~454 50-454 PR PR PR	0
	8305030492 8305030622# 8305060346# 8305060354# 8305060488	50-482 50-482 50-482 50-482 50-482	8 0 F F 0	Literature Research Corp. Littan Industries, Inc	8305200456 8305240516 8305040284* 8305270625 8305170376*	PR 50-352 CONTRACT 50-321 50-329	6 H
	8305120391 8305200335 8305230489* 8305230567 8305230570*	50-482 50-482 50-482 50-482 50-482	9 0 1		9303030360 9303040303 9303040461 9303040308 9303040314#	20-355 20-355 20-355 20-355 20-355	O E O E
Kansas, State of	8305240313 8305270058 8305310110# 8305310148 8305070142	50-482 50-482 50-482 50-482 NUREO	0 0 8		3305050024 8305050027* 9305050107 9305060153* 9305060164*	50-322 50-322 50-322 FOIA FOIA	T T
Kansas, Univ of Kaufmann.J E Kann-McCoe M elect Corp	8305200196# 8305130361# 8305200052 8305230196#	50-148 CONTRACT 40-8027 70-1193 '78	ā		3305070134* 3305100237* 9305120306* 9305120311* 9305120328	20-355 20-355 20-355 20-355	8
		Ð	0		3305120380* 3305130077 3305160006 3305160070 3305160075	20-355 20-355 20-355 20-355	0 0 E A
					8305180244 8305180324# 8305180331# 8305190208	50-322 50-322 50-322 50-322	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	DRY
	8305190271 8305190378 8305190362* 8305200549 8305200594*	50-322 50-322 50-322 50-322 50-322	9		8305230142* 8305230146* 8305230191* 8305230154* 8305230157*	50-309 50-309 50-309 50-309 50-309	F F F
	8305200651 8305240447 8305270013 8305310040 8305310050	50-322 50-322 50-322 50-322 50-322	04804		8305230162# 8305230167# 8305230175# 8305230181# 8305230383	50-309 50-309 50-309 50-309 50-309	F F F P
Los Alamos Scientific Laboratory	8305310051 8305110062 8305110083 8305130292 8305160299	50-322 REB REB RES 50-537	G		8305230472 8305230483* 8305240266 8305240270 8305250427	50-309 50-309 50-309 50-309 50-309	9 9 P 0
Louisa County. VA Louisiana Power & Light Co	8305200659 8305020341 8305020411 8305020450 8305020479	50-338 50-382 50-382 50-382 50-382	0 8 8	Haine, State of Management Analysis Co	8305310067 8305030565 8305030567* 8305240386 8305250529	50-309 50-309 50-309 50-309 PR	G G G
	8305050017 8305060367 8305060425 6305060566 8305060587	50-382 50-382 50-382 50-382 50-382	R 8 8	Mapleton Intervenors Mark Controls Corp Marsh & McLennan, Inc	8305250535* 8305120005 8305120484* 8305030377 8305040180	PR FOIA 50-461 50-389 50-348	ر 3
	8305130019 8305170223 8305170265 8305170290 8305170327	50-382 50-382 50-382 50-382 50-382	8 8 H 8		8305040186 8305040202 8305040202 8305040204 8305040208	50-335 50-321 50-321 50-302 50-250	,,,,,
	8305170351 8305170484 8305170472 8305170500 8305180429	50-382 50-382 50-382 50-382 50-382	8880		8305040243 8305120004 8305120039 8305120110 8305120136	50-327 50-213 50-293 50-244 50-245	
	8305180468 8305200542 8305270138 8305270147 8305270194	50-382 50-382 50-382 50-382 50-382	8 8 8		8305120156 8305120208 8305120208 8305120208	50-245 50-29 50-286 50-286 50-286	1 (((
Louisiana, Btate of Lowenstein, Newman, Reis, Axelrad & Toll	8305270373 8305310074 8305100328 8305270165 8305020434	50-382 50-382 50-458 State F 50-498	E 0 0 0		8305160005 8305160005 8305160026 8305160063 8305160084	50-259 50-259 50-315 TOPREP 50-89) (
M & T Chemicals, Inc	8305110225 8305180404 8305160301 8305160303* 8305160305*	50-498 PR XPORTLIO XPORTLIO XPORTLIO	Ċ		8305160105 8305160157 8305190022 8305200270 8305200270	50-346 50-272 50-302 50-321 50-321	3 7 7 7 7
Magnaflux, Corp Mains Yankse Atomic Power Co	8305130221# 8305130233# 8305130237# 8305130241# 8305020393#	50~155 50~155 50~155 50~155 50~309	G G G	Maryland, State of	8305230027 8305230027 8305060289 8305180439* 8305270130	50-321 50-321 PR 50-170 State Pr	J U Tog
	8305030491 8305030496* 8305040533 8305050220 8305050225*	50-309 50-309 50-309 50-309 50-309	P P P	Haryland, Univ of Massachusetts Institute of Technology Massachusetts, Commonwealth of,	8305110512 8305070315* 8305160043 8305070523 8305100307	NUREQ MISC 50~20 50~443 50~213	8 F
	8305060494 8305060503* 8305060549* 8305110344	50-309 50-309 50-309 50-309 50-309	8 8 8	Materials Engineering Testing Services, Inc Maxwell, J C HcDermott, Inc.	8305060347 8305240015 8305130347 8304200001	NUREG NUREG 50-443 TOPREP	٥
	8305110425 8305110433* 8305130054 8305130078 8305130128	50~309 50~309 50~309 50~309 50~309	9 8 P P	Metal Bellows Corp Matrocom, Inc Metropolitan Edison Co	B3051003B2* B3051003B2* B305100395* B305100395* B305170661*	50-438 50-438 50-438 50-438 CONTRAC 50-289	A A A A T O
	8305160065 8305160082* 8305190308 8305200314 8305200341	50~309 50~309 50~309 50~309 50~309	8 8 1 F	THE TOPE THE BUSSIN OU	8305030591 8305070431 8305100283 8305100310 8305100357 8305120292	50-287 50-289 50-289 50-289 50-289	9 0000
	8305200360 8305200374* 8305200467 8305200469 8305200473*	50-309 50-309 50-309 50-309 50-309	887		8305180277 8305240287 8305240487 8305250202 8305250223*	50-289 50-289 50-289 50-289 50-289	00000
	8305200529 8305200578 8305230127 8305230137* 8305230140*	50-307 50-309 50-309 50-309 50-309	44 11 18	Metropolitan Transportation Authority New York, NY Michigan, Univ. of	8305020401 8305180159* 8305200149*	50-247 FOIA CONTRAC	0

AUTHOR AFFILIATION	ACCESS I DN NUMBER	SUBJECT CATEGOR'	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOORY	
Middle South Utilities, Inc - Middle South Energy, Inc Miller,D S	8305200461 8305160079 8305170255 8305240473	PR 50-309 50-309 50-309	0	Montana X-Ray, Inc	8305180125* 8304130034 8304130042* 8305200071* 8305250576*	40-6500 71-494 71-494 CONTRACT	G
Minamota, State of Miranda Associates, Inc Mississippi Power & Light Co	8305030472 8305180460 8305120150# 8304110321 8304110328#	PR CONTRACT 50-416 50-416	P P	Morgan Associates	8305030549 8305100208 8305130064 8305130071 8305240466	50-247 50-247 50-247	0 0 0 0
	8304110335* 8304170378 8304280037 8304280049* 8305030553	50-416 50-416 50-416 50-416 50-416	P P P P S	Morgan, Lewis & Bocklus Multimedia Program Production, Inc NPB Industries, Inc NUS Gorg	8303240374# 8305110445 8305170370# 8305240356 8304060126#	50-537 50-373 50-445	Q P B E
	8305030562 8305050075 8305050077 8305050131 8305050167	50-416 50-416 50-416 50-416 50-416	5 F 8 8		8305030337 8305030343* 8305230039* 8305230057* 8305230059	TOPREP TOPREP FOIA FOIA FOIA	
	8305050176* 8305050227 8305050256 8305050241* 8305110275	50-416 50-416 50-416 50-416 50-416	s s s s	NUBAG, Inc NUTECH Engineers, Inc	8305230145 8305230176* 8305270075* 8305040643* 8305060055*	CONTRACT	P P
	8305110279* 8305110291 8305110418 8305130124 8305130126	50-416 50-416 50-416 50-416 50-416	5 5 6 6	National Electrical Contractors Association	8305060096 8305200307* 8305310097* 8305240517	F01A 50-237 50-366 30-247	\$ Q H
	8305130124 8305130200*	50-416 50-416	s	National Emergency Civil Liberties Committee	8305240532	50-247 CONTRACT	9
	8305170424 8305170426* 8305170427 8305170430	50-416 50-416 50-416 50-416	ទ	National Covernors' Association National Wildlifs Federation Natural Resources Defense Council	8305260380* 8305170272 8305030502 8305100210 8305100274	50-522 50-537 50-537 50-537	0000
	8305170431# 8305170433# 8305170015 8305170015 8305200280	50-416 50-416 50-416 50-416 50-416	8 5 J 5		8305100350 8305120291 8305160149 8305160181 8305170272	50-537 50-537 50-537 50-537 50-522	90000
	8305200286* 8305200484 8305200473* 8305200523 8305200532*	50-416 50-416 50-416 50-416 50-416	5 5 8 8		8305170272 8305170279 8305170279 8305170347 8305170347	50-522 50-522 50-522 50-522	00000
	8305200604 8305230608 8305240143 8305240143 8305240265#	50-416 50-416 50-416 50-416 50-416	8 P P P	Navy, Dept of Pearl Harbor Naval Shippard	8305170557 8305170557 8305170221 8305240553	50-522 50-522 50-537 50-537 71-9033	0000
	8305240496 8305250072 8305250365 8305250405 8305250434	50-416 50-416 50-416 50-416 50-416	P R S S	Nawyn, R Nebraska Public Power District	8305170730 8305130300* 8305020449 8305020464* 8305030393 8305030554	CONTRACT 50-298 50-298 50-298 50-298	P P P
	8305250487 8305250513 8305250579 8305270400# 8305270410#	50-416 50-416 50-416 50-416 50-416	5 5 0 0		8305030588 8305050113 8305060380 8305060383* 8305060574	50-298 50-298 50-298 50-298 50-298	P 1 1 8
	8305270473 8305270515 8305270593* 8305310065 8305310069	50-416 50-416 50-416 50-416 50-416	8 9 9 9	Nebraska, State of	8305040584* 8305120433 8305120439* 8305270349 8305270349	50-298 50-298 50-298 50-298 NUREQ	988
Missouri, State of	8305310146 8305310196 8305310204 8305310207 8305250341#	50-416 50-416 50-416 50-416 30-483	S = = = = 0	Neytron Products, Inc	8305120041* 8305120045* 8305130288 8305270093* 8305050343*	FOIA FOIA 40-8829 CONTRACT	,
	8305250356# 8305250424#	50-483 50-483	0	New England Coalition on Nuclear Pollution	8305030541	50-443	0
Missouri, Univ. of, Columbia Missouri. Univ. of, Rolla	8305250344# 8305250548# 8305260341# 8305030375	50-483 50-483 CONTRACT	G C R	. 5	8305160002 8305160002 8305160019 8305160019	50-443 50-443 50-443 50-443	0000
Mitsubishi International Corp (subs of Mitsubishi Corp)	8305020553 8305020557*	50-123 XPORTLIC XPORTLIC	P C	New Mexico State Univ R-w York, NY	8305140048 8305270048* 8305030408 8305030408	50-443 50-320 50-247 50-247	9400
Mitsui & Co (U B A), Inc (subs of Mitsui & Co , Ltd.)	8305260317	XPORTL10	c .		#9140E020EB	50-247 50-247	0
Molycorp, Inc. Monsanto Co	8305180200 8305180117	40-7097 40-6500			8305030617* 8305030627*	50-247 50-247	0

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGORY	_	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
New York, State Univ of, Buffalo New York, State of	8305030629* 8305170264 8305240532 8305100252 8304040394*	50-247 State Pro 50-247 50-57 50-322			8305050054 8305050054 8305050054 8305050229 8305050229	50-213 50-213 50-213 50-245 50-245	P P P P
	8305130204* 8305180260* 8305190014 8305240312 8305240312	50-322 50-322 State Pro 50-247 50-247) } =		8305040424 8305040455 8305040501 8305040512* 83050904465	50-336 50-423 50-245 50-245 50-213	9 9 5
New York, State of, Energy Research &	8305240541 8305240541 8305310070* 8305180805	50-247 50-247 50-247 PROJ	년 년 -		8305090465 8305090465 8305090465 8305090471 8305090474*	50-213 50-213 50-213 50-245 50-245	P P P
Davelopment Administration	8305180810	PROJ			8305100368	50-245	P F
Niegarz Mohawk Power Corp	8304110516 8304210238 8304210240* 8305030515 8305040483	50-220 50-410 50-410 50-410 50-220	역 서 서 두		8305110574# 8305110579# 8305120241 8305170010	50-213 50-213 50-336 50-336	F P R
	8305040493* 8305040500* 8305050020 8305050031* 8305060043	50-220 50-220 50-220 50-220	P B P P		8305180268 8305180304 8305180311* 8305200533	50-245 50-245 50-245 50-423	P P S
	8305060046* 8305060048* 8305060426 8305060428*	50-220 50-220 50-220 50-220	p p S S		8305230323 8305230330* 8305230338* 8305230508 8305230549	50-245 50-245 50-245 50-336 50-245	F F F
	8305040533 8305040540* 8305100272 8305100277* 8305110315	50-220 50-220 50-220 50-220 50-410	5 8 R R A		8305230557* 8305230414 8305250510 8305250510 8305250510	50-245 50-213 50-213 50-213 50-213	8 P P P
	8305110357* 8305110372* 8305120334 8305120372	50-410 50-410 50-410 50-410 50-410	C K B B M		8305250510 8305250518* 8305250518* 8305250518* 8305250518*	50-213 50-213 50-213 50-213 50-213	5 5 6
	8305140015 8305140015 8305140073 8305140077 8305140103*	50-220 50-220 50-220 50-220 50-220	g G R R R		8305270036 8305270037* 8305270074 8305270089 8305270114	50-423 50-423 50-336 50-336 50-245	8 0 8 P
	8305170393 8305170395* 8305200283 8305200290* 8305200345 6305200383*	50-220 50-220 50-220 50-220 50-220	9 9 9 9	Northeast Utilities	8305270239 8305270454 8305020093 8305020093 8305020093	50-336 50-336 50-245 50-245 50-245	S I I I
	8305230431* 8305230431* 8305230582* 8305230583* 8305230585*	50-220 50-410 50-410 50-410 50-410	P A A A A		8305030404 8305030620 8305030624* 8305030628* 8305040447	50-245 50-245 50-245 50-245 50-336	Р Р Р
	8305230481* 8305230481* 8305230484* 8305230484*	50-410 50-410 50-410 50-410	A A A		8305050034 8305050054 8305050054 8305050054 83050506229	TOPREP 50-213 50-213 50-213 50-245	P P P
	8305230687* 8305230687* 8305230691* 8305230696*	50-410 50-410 50-410 50-410 50-410	A A A A		8305050229 8305060213 8305060244 8305060424 8305060455	50-245 50-213 PR 50-336 50-423	P F Q
	8305230696* 8305230699* 8305230699* 8305240402 8305240498	50-410 50-410 50-410 50-220 50-410	A A P A		8305090465 8305090465 8305090465 8305090471 8305100368	50-213 50-213 50-213 50-245 50-245	P P P
	8305250430 8305260086 8305270026 8305270075 8305270645*	50-410 50-410 50-220 50-220 50-410	8 K P 8 G		8305110574* 8305120241 8305170010 8305180268 8305180304	50-213 50-336 50-336 50-245 50-245	FPRP
Nitsho-Iwai American Corp Northampton County, PA Northeast Nuclear Energy Co (subs of	8305170125# 8305180709 8305270573 8305030404	XPORTLIC XPORTLIC 30-443 50-245	G P		8305200441 8305200533 8305200587 8305230323	PR 50-423 50-423 50-245	8 4 F
Northeast Utilities)	8305030620	50-245	p p		8305230508	50-336	P
	8305030624* 8305030628* 8305040034*	50-245 50-245 50-245	면 면 단		8305230614 8305270034 8305270037# 8305270074	50-213 50-423 50-423 50-336	P 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	RY
Northeast Utilities Service Co	8305270114 8305270239 8305270454 8305060244 8305100335*	50-245 50-334 50-336 PR 50-213	5 8 8	Office of Management & Budget	8305270048* 8305310237 8305040001 8305040003 8305070006	50-320 NUREO ORO ORO ORO	P
Northern States Power Co	8305110071* 8303180429 8305020320 8305020320 8305020329*	50-213 50-263 50-282 50-282 50-282	F G G	Dhio Citizens for Responsible Energy	8305040528 8305040528 8305040541 8305040541 8305040544	50-440 50-440 50-440 50-440 50-440	99999
	8305020329* 8305020488 8305020492* 8305030221* 8305030226*	50-282 50-263 50-263 50-282 50-282	0 8 8 F		8305040544 8305090234 8305170305 8305170305 8305170341	50-440 F01A 50-440 50-440 50-440	0
	8305030603 8305030613* 8305120389 8305160056	50-263 50-263 50-263 50-282 50-282	Ж К Р R	Ohio State Univ Ohio, State of	8305170341 8305180347 8305180404 8305110192* 8305090545*	50-440 PR PR CONTRAC 50-358	• T A
	8305140076# 8305160092 8305160098# 8305180352 8305230523	50-282 50-263 50-263 50-263 50-282	R R R G F	Oxlahoma, State of Oxlahoma, Univ of Omaha Public Power District	8305070561* 8305070162 8305250478 8305030156 8305030160*	50-358 NUREQ 50-112 50-265 50-265	H P P
NuPhara, Inc	8305230523 8305240153 8305240166 8305250409 8305180056*	50-282 50-304 50-282 PR FOIA	F 8 8		8305030429# 8305040619# 8305040624# 8305060069 8305060091#	50-265 50-265 50-265 50-265 50-265	F F I
Nuclear Assurance Corp Nuclear Data, Inc	8305180063* 8305180241* 8305180269* 8305060251* 8305180560*	FOIA FOIA FOIA CONTRACT			8305060186 8305100226 8305120603# 8305160027 8305160111	50-265 50-265 50-265 50-265 50-285	F F P
Nuclear Fuel Services, Inc. (subs of Getty Dil Co)	8305180542* 8305030694	CONTRACT 70-143			9305160116# 9305170465 8305170470#	50-265 50-265 50-285	R R
	8305030699 8305050099 8305180852	70-143 70-143 70-143			8305230588 8305240474	50-285 50-285	P
Nuclear Information & Resources Services	8305190003 8305190033 8305200658 8305240051 8305200218	70-143 70-143 70-143 71-143 PR		On-Line Computer Systems, Inc. Oregon Environmental Council Orrick, Herrington & Sutcliffe	8305110232* 8305170272 8305170195 8305170195 8305170212	CONTRACT 50-522 50-361 50-361 50-361	* 0000
Nuclear Metals, Inc	8208040242* 8208060244* 830502028# 8305020294* 8305040141*	40-672 40-672 XPORTLIC XPORTLIC 40-672		Osage County, MD Ossining, NY Pacific Gas & Electric Co	8305190212 8305250372# 8305240508 8305020388 8305020388	50-361 50-483 50-247 50-133 50-275	0 0 F P
	B305040181* B305060189* B305070723 B305120246* B305120278*	40-672 40-672 XPORTLIC 40-672 40-672			8305030188 8305030188 8305030193 8305030193	50-275 50-275 50-275 50-275 50-275	FFF
	8305120352* 8305120364* 8305120381* 8305120480* 8305120494*	40-672 40-672 70-82 40-672 40-672			8305030510 8305040320 8305040328* 8305040473* 8305050198	50-275 50-275 50-275 50-275 50-275	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
	8305120511* 8305120617* 8305120627* 8305130011* 8305130042*	40-672 FDIA 40-672 40-672 40-672			8303060299 8303100339 8303100346 8303120042 8303120323	50-323 PROJ PROJ 50-275 50-275	Q P P
Nuclear Packaging, Inc.	8303040105* 8305040110* 8305040142* 8303040148* 8305040132*	71-9181 71-9181 71-9175 71-9175 71-9175			8305120333 8305120339* 8305160172 8305160176* 8305170336	50-275 50-275 50-275 50-275 50-275	P P P B
Nuclear Power Services, Inc Nuclear System O'Connor & Hennan O'Neill: J	8305200483* 8304270399 8305180070* 8305180074* 8305120287		P		8305170342* 8305170157 8305230407 8305240238 8305240242*	50-133 50-275 50-133 50-275 50-275	8 F R R
Dak Ridge Associated Univ Oak Ridge National Laboratory	8305170245 8305240528 8305230254* 8305020538	50-155 50-155 FOIA NUREQ RES	0 0		8305240375 8305240397 8305260274* 8305260274* 8305270249	50-275 50-275 50-275 50-275 50-275	P G G G
	8305110120 8305130341 8305250155 8305260004*	NUREG NUREG RES 71-5552			8305270622 8305270622 8305310130 8305310135* 8305310140*	50-275 50-275 50-275 50-275 50-275	9 0 P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	RY	AUTHOR AFFILIATION	ACCES NUME	ER	SUBJECT CATEGOR	
Pacific International Palmetto Alliance Parants Concerned About Indian Point	8305030250 8305040252 8305310155 8305030433* 8305170220	XPORTLIC 50-413 50-413 50-247 50-247			830502 830502 830502 830502	0255 5 0335 5 0335 5	0-352 0-352 0-352 0-352 0-352	E A A Q
Pathfinder Mines Corp	8305240543 8305020410 8305020504# 8305030277 8305260357	50-247 40-6622 40-6622 40-6622 40-2259			830502 830503 830503 830503 830503	0454 5 0299 5 0299 5	0~352 0~352 0~352 0~352 0~352	E A A
Pannsylvania Powar & Light Co	8305020387 8305030144 8305030153* 8305030334 8305030338*	50-387 50-387 50-387 50-387 50-387	P P S S		830503 830503 830503 830505 830505	0563 5 0563 5 0021 5	0-352 0-352 0-352 0-277 0-277	A Q P P
	8305050287* 8305060442 8305060543 8305060592 8305060598*	50-387 50-387 50-387 50-387 50-387	F 8 9 8		830505 830505 830505 830505	0027* 50 0033* 50 0033* 50	0-277 0-277 0-277 0-277 0-277	P P P Q
	8305100016 8305100019# 8305100021# 8305100308 8305100317#	50-387 50-387 50-387 50-387 50-387	P P P P		830504 830504 830504 830504	0457 50 0478 50 0507 50	0-352 0-352 0-352 0-352 0-277	A Q A Q
	8305110097 8305110097 8305110104* 8305110104* 8305110108*	50-397 50-387 50-387 50-387 50-387	K K K K		9305046 9305106 9305106 9305106 9305116	0275 50 0275 50 0359 50	0-277 0-352 0-352 0-277 0-277	Q A A F B
	8305110160 8305110160 8305110241 8305110247# 8305110246	50-387 50-387 50-387 50-387 50-387	8 8 8		8305116 8305116 8305126 8305126	0349# 50 0320 50 0358 50	7~352 7~277	8 8 8
	8305110358# 8305110421 8305110430# 8305120422 8305120430#	50-387 50-387 50-387 50-387 50-387	8 8 8		8305136 8305146 8305146 8305146	0001 50 0001 50 0117 50)~352)~352	AGGKK
	8305130114 8305130311# 8305130311# 8305130314# 8305130314#	50-387 50-387 50-387 50-387 50-387	8 F F		8305170 8305170 8305170 8305180 8305180	228 50 401 50 343 50	-352 -277 -352	A E P A A
	8305160124 8305160132 8305160140 8305160151# 8305180646	50-387 50-387 50-387 50-387 70-2983	8 8 8 8		83051 80 83051 80 83051 80 83051 80	387 50 402 50 402 50	-352 -352 -352	E
	8305190285 8305190285 8305190295 8305190319 8305200555	50-387 50-387 50-387 50-387 50-387	P P B B		8305180 8305180 8305180 8305180 8305180	414 50 419 50 419 50	-352 -352 -352	EAAE
	8305200561* 8305200640 8305200646* 8305230471 8305230477*	50-387 50-387 50-387 50-387 50-387	\$ \$ \$ \$ \$		8305180 8305180 8305180 8305180	426# 50- 431# 50- 431# 50-	-352 -352 -352	E E E
	8305230541 8305270064 8305270064 8305270255 8305310208	50-387 50-387 50-387 50-387 50-387	ም P G G		8305180 8305180 8305180 8305180	432 50- 438* 50- 438* 50-	-352 -352	A E E E
Pennsylvania State Univ. Pannsylvania, Commonwealth of,	8305180353 8305270040* 8305270044* 8305060529 8305060536*	PR 50-320 50-320 50-352 50-352	P P A A		8305180 8305180 8305180 8305180	443* 50- 443* 50- 451 50-	-352 -352 -352	E E E
	8305120278 8305120278 8305120280* 8305120280* 8305170533	50-352 50-352 50-352 50-352 50-352	o o o		8305190; 8305190; 8305200; 93052304 8305240;	359 50- 415 50- 496 50-	-352 (-352 (C C E A J
Perkins, Coie, Stone, Olsen & Williams	8305230332* 8305310027 8305310027 8305310082 8305310082	CONTRACT 50-522 50-522 50-522 50-522	r a a		93052404 93052404 93052509 93052509	189 50- 187 50- 133 50-	-352 -352 -352	P .
Philadelphia Electric Co.	8301310260 8301310274# 8303020099 8303020099 8303020255	50-352 50-352 50-277 50-277 50-352	K F P		8305250; 8305250; 8305270; 8305270; 8305270;	135# 50~ 117 50~ 184 50~	352 278 277	A 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8305270375 8305270375 8305310009 8305310009 8305310045	50-352 50-352 50-352 50-352 50-352			8305130134 8305130134* 8305160088 8305160106 8305160112*	50-333 50-333 50-286 50-333 50-333	R P P
Philadelphia, PA	8305310045 8305160174 8305160174 8305160177 8305160177	50-352 50-352 50-352 50-352 50-352	E G G		8305200265 8305200268* 8305200272* 8305200405 8305230375	50-333 50-333 50-333 50-284 50-333	P P P
Pickard, Lowe & Garrick, Inc Pittsburgh Testing Laboratory	B305240314 B305110152* B305270110* B305310141* B305030516*	50-352 CONTRACT CONTRACT 50-244 50-454	Ī		8305230454 8305230459= 8305230592+ 8305230592= 8305230597	50-333 50-333 50-410 50-410 50-284	8 8 A A
Pittsburgh, Univ of Planning Research Corp Plateau Resources, Ltd	8305310157* 8305270022 8305270027* 8305160295* 8305040047	50-244 50-320 50-320 50-413 40-7869	P P F		8305230599# 8305230599# 8305240090 8305240099 8305240234	50-410 50-410 50-284 50-284 50-286	AAPF
Portland General Electric Co	8305040052* 8305260418 8305020535 8305040417 8305060600	40-7849 40-8698 71-6601 50-344 50-344	F P		8305240328 8305240338 8305240347 8305240442 8305240463	50-286 50-286 50-333 50-333	P P P
	8305060606* 8305130143 8305130152* 8305130164 8305130224	50-344 50-344 50-344 50-344 50-344	P \$ 8 0 8		8305240466 8305240466 8305240492 8305240529 8305270189	50-247 50-247 50-333 50-286 50-333	Q Q P R
	8305130232* 8305130240 8305180246 8305200013 8305230581	50-344 50-344 PR 50-344 50-344	8 P P		8305270284* 8305270340 8305270352* 8305270364* 8305270399*	50-333 50-333 50-333 50-333	о Р Р
	8305240275 8305270182 8305270186* 8305270188* 8305270205	50-344 50-344 50-344 50-344 50-344	P P P P	Power Engineering Project Management Corp	8305030461 8303240390 8305110220 8305110438 8305110448	FR 50-537 50-537 50-537 50-537	0 0 0
Potterfield, A Power Authority of the State of New York	8305270211* 8305270282* 8305030408 8305020209 8305020381	50-344 50-344 50-247 50-333 50-286	Р Р С Р		8305110449* 8305120313 8305190339 8305200636 8305200648*	50-537 50-537 50-537 50-537 50-537	0000
	8305030408 8305030547 8305040311 8305040424 8305040434*	50-286 50-247 50-333 50-333 50-333	P G P P	Public Interest Research Group, New York	8305240475 8305240480 8305240503 8305310188 8305030608	50-537 50-537 50-537 50-537 50-247	0000
	8305040438* 8305050026 8305050037 8305050037 8305060397	50-333 50-333 50-247 50-247 50-286	P Q G		8305030608 8305030619# 8305030619# 8305030629# 8305030629#	50-247 50-247 50-247 50-247 50-247	0000
	8305060427 8305060431 8305060432* 8305060433* 8305060439	50-286 50-286 50-286 50-286 50-286	P P P P		8305030641# 8305030641# 8305030646# 8305030646# 8305250337	50-247 50-247 50-247 50-247	99999
	8305060446* 8305060447* 8305060496 8305060476 8305060500	50-286 50-286 50-247 50-247 50-286	P G G	Public Service Co of Colorado	8305020462 8305050146 8305050214 8305050222# 8305050228#	50-267 50-267 50-267 50-267 50-267	9 9 9
	8303100208 8305100340 8305110033 8303110058* 8303110063#	50-247 50-333 50-286 50-286 50-286	G 8 P P		8305060479 8305060484* 8305060546 8305060552* 8305090489	50-267 50-267 50-267 50-267 50-267	B R R R
	8305110167 8305110259 8305110264* 8305110400 8305110405	50-286 50-333 50-333 50-333 50-333	G S S S		8305090565# 8305120570# 8305120578# 8305160048 8305160053	50-267 50-267 50-267 50-267 50-267	R F P P
	8305110408* 8305110416* 8305110510 8305110514* 8305130039	50-333 50-333 50-333 50-333 50-286	8 8 9 8		8305170380 8305200494 8305230426 8305230427* 8305240477	50-267 50-267 50-267 50-267 50-267	P R R
,	8305130064 8305130071 8305130117 8305130120* 8305130123*	50-247 50-247 50-286 50-286 50-286	9 9 P P	Public Service Co of Indiana, Inc	8305310111 8304250167 8304250167 8304250190* 8305020118	50-247 50-546 50-546 50-546 50-546	PAKS

AUTHOR AFFILIATION	ACCESS LOIL NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY
	8305020291 8305020291 8305040494 8305120457 8305130073	50-546 50-546 50-546 50-546 50-546	S		8305200067 8305200394 8305200397* 8305200537 8305200546*	50-272 50-272 50-272 50-311 50-311	1 8 8 8
	8305130073 8305130098 8305130098 8305130119 8305130119	50-546 50-546 50-546 50-546 50-546	0 0 0 A A		6305230094 6303230504 8305230504 8305230510 8305240291*	50-311 50-272 50-272 50-317 50-272	P P 9 9
	8305130207 8305130207 8305130244 8305130244 8305170306	50-546 50-546 50-546 50-546 50-546	8 8 0 0 A		8305250387 8305250501 8305270053* 8305270053* 8305310185	50-354 50-311 50-272 50-272 50-354	R G G V
	8305170312* 8305200289 8305200289 8305230654 8305240408	50-346 50-346 50-546 50-346 50-546	A F A S	Puget Sound Power & Light Co Purdue Research Foundation	8305310027 8305310027 8305310082 8305310082 8305060183*	50-522 50-522 50-522 50-522 CONTRACT	0 0 0 0 r
	8305240408 8305260233 8305260233 8305260332 8305260332	50-546 50-546 50-546 50-546 50-546	8 F F 8	Guadrex Corp Guirk. Lawler & Matusky Engineers	83050703884 8305230607# 8305230607# 8305230614# 8305230614#	GA999 50-410 50-410 50-410 50-410	A A A
Public Bervice Co of New Hampshire	8305040300 8305040300 8305040316 8305040316 8395050006	50-443 50-443 50-443 50-443 50-443	0 0 0 F		8305230422* 8305230622* 8305230628* 8305230628* 8305230637*	50-410 50-410 50-410 50-410 50-410	AAAAA
	8305160037 8305170164 8305200353 8305200353 8305200402	50-443 50-443 50-443 50-443 50-443	8 9 9 9 9 6	R E Williams & Associates, Inc	8305230637* 8305230644* 8305230644* 8305020471 8305030705	30-410 50-410 50-410 40-6622 40-8584	AAA
	8305200402 8305250244 8305270019 8305270019 8305310147	50-443 50-443 50-443 50-443 50-443	S S A A O	R F Reedy, Inc Radiation Menagement Corp	8305180427 8305110509* 8305250428* 9305250458* 8305250468*	50-275 CDNTRACT 50-483 50-483 50-483	R
Public Barvice Electric & Gas Co of New Jersey	8304180491 8304180513* 8305020150 8305020186 8305020186	50-311 50-311 50-272 50-272 50-272	8 8 8 P	Radio TV Reports. Inc Reliance Electric Co Ransselaer Polytechnic Inst	8305250482* 8305190088* 8305190119* 8305190103* 8305170466	50-483 50-329 50-373 GA999 50-225	0 0 F
	8305020267* 8305040262 8305040262 8305050013 8305060470	50-272 50-272 50-272 50-272 50-354	G S F P	Reuter-Stokes, Inc Rhode Island & Providence Plantation Rhone-Poulene, Inc Rid(halgh, Eggers & Associates	8305040004 8305240384 8305250445 8305030181 8305160363	50-193 71-9100 PRDJ	s
	8305050476 8305060480 8305060482* 8305060489* 8305070457	50-272 50-311 50-272 50-311 50-272	9 8 9 9	Riley, J L Robert L Cloud Associates, Inc	8305230041 8305230054* 8305230056* 8305030552 8305030573	50-275	g R
	8305070457 8305070457* 8305070457* 8305110007 8305110154	50-272 50-272 50-272 50-311 50-272	P P P	Rochester Gas & Electric Corp	8305030581* 8305180417 8305230224* 8305030021 8305030024*	50-275 50-275 50-244 50-244	R R R P
	8305110154 8305110156# 8305110156# 8305110255 8305110271	50~272 50~272 50~272 50~354 50~311	88 84 84		B305030352 B305050248 * B305060271 B305060404 B305110065	50-244 50-244 50-244 50-244	P P P
	8305110274* 8305120384 8305160052 8305160057* 8305160085	50~311 50~354 50~311 50~311 50~272	8 8 8 8 9		8305110318 8305110328* 8305130084 8305130086* 8305160114	50-244 50-244 50-244 50-244	8 8 8 9
	8305160085 8305160096 8305160102* 8305160118 8305160123*	50-272 50-311 50-311 50-311 50-311	0 9 8 8 8		8305160119* 8305180816 8305190170 8305190175* 8305190234	50-244 71-9080 50-244 50-244 50-244	9 9
	9305170018 9305170021* 9305170142 9305170147* 9305170328	50-272 50-272 50-311 50-311 50-272	R R R R		8305190238* 8305230452 8305230458* 8305230526 8305230561	50-244 50-244 50-244 50-244 50-244	
	8305170328 8305170367 8305170370* 8305170490*	50-272 50-311 50-311 50-354	P 8 9 0		8305230564* 8305270578* 8305310020 8305310085 8305310125	50-244 50-244 50-244 50-244 50-244	9 P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY .	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
Rochester, Univ of, Rockland County, NY	8305310133+ 8305310218 8305310232 8305060200+ 8305180424	50-244 50-244 50-244 40-672 50-247	P F P		8305170302* 8305170302* 8305170303* 8305170303* 8305170303*	50~373 P 50~373 P 50~373 P 50~373 P 50~373 P
Rockwell International Corp	8305180424 8305240535 8305240535 8305270586 8305120404#	50-247 50-247 50-247 50-247 50-410	0 0 0 0 8		8305170357* 8305200301* 8305200481* 8305200488* 8305250084*	50-373 P 50-237 S 50-373 P 50-373 P 50-275 P
Rocky Mountain Energy Co Rolf Jansen & Associates, Inc	8305310219 8305310220* 8305250171 8305260364 8305120517*	70-25 70-25 40-8697 40-8380 CONTRACT	ī	Sassafras Audubon Society Schwalb, Donnenfeld, Bray & Silbert	8305270501* 8305060236 8305180330 8305180369 8305120560#	50-454 G PR PR PR CONTRACT
Rondout Associates Ropps & Gray	8305130352 8305040300 8305040300 8305040316 8305040316	50-443 50-443 50-443 50-443 50-443	0 0 0 0	Science Applications, Inc	8305230012* 8206100204 8206100210* 8207080458* 8209150251*	ABVCH RES RES 50-321 P 50-250 G
Roy F Weston, Inc Runkle, J D Ruskin Manufacturing Co	8305040533 8305310147 8305170116 8305060532 8305130113	50-309 50-443 40-6500 50-400 50-400	0 0 5		8209200375* 8303080182 8303080187* 8303080194 8303080202*	50-313 F RES RES RES RES
Rye. NH Bacramento Municipal Utility District	8305250331 8305020383 8305020384 8305020415 8305020483	50-443 50-312 50-312 50-312 50-312	H P P Q		8303080209 8303080215# 8303170122 8305200110# 8305270052#	RES RES NURES 50-277 G 50-271 G
	8305030287 8305030290* 8305030551 8305030561* 8305060415	50-312 50-312 50-312 50-312 50-312	8 8 8 9 9	Seabrook, NH Seaccast Anti-Pollution League	8305020425 8305020425 8305020429* 8305020429* 8305180344	50-443 9 50-443 9 50-443 9 50-443 9 PR
	83050A0419 83050A0421= 83050A0429 8305100099 8305100229	50-312 50-312 50-312 50-312 50-312	P P F P	Senate	8305190199 8305110401* 8305180114* 8305180123* 8305310239*	50-443 9 COMMISSION FOIA FOIA 50-309 H
	8305100276 8305100338 8305100344 8305100381 8305120073	50-312 50-312 50-312 50-312 TOPREP	P P Q	Genate, Environment & Public Works Benate, Judiciary Committee Sensible Maine Power	8309110584# 8305230464# 8305160099 8309190295 8305240483	COMMISSION COMMISSION 50-309 0 50-309 0 50-309 0
	8305130099 8305130105 8305130160 8305130163 8305130219	50-312 50-312 50-312 50-312 50-312	0 8 8 8	Shaw. Pittman, Potts & Trowbridge	8305240493 8305020438 8305020470 8305030467 8305030591	50-307 9 50-266 9 50-440 P 50-483 9 50-287 9
	8305130231 * 8305230454 8305230593 8305240326 8305270080	50-312 50-312 50-312 50-312 50-312	S Q P R Q		8305040307 8305040307 8305040506 8305040506 8305090431	50-440 0 50-440 0 50-440 T 50-440 T 50-289 0
Safe Energy Coalition Bafe Energy for New Haven	8305270432 8305310171 8305230229 8305030508 8305030516*	TOPREP 50-312 FOIA 50-454 50-454	P T T		8305090470 8305090537 8305100283 8305100310 8305100357	50-241 9 50-358 T 50-289 9 50-289 9 50-289 9
Safety Light Corp Sag Herbor: NY Salaya, M E , Intervenor Salisbury,MA	8305190057* 8305180459* 8305180461* 8305180288 8305090501	XPDRTLIC 50~322 50-322 50-482 50-443	С Н Н О		8305110266 8305120292 8305120391 8305120092 8305130097	50-483 9 50-287 9 50-482 9 50-261 9 50-312 9
San Diego Gas & Electric Co Ban Frencisco Examiner	8305070501 8305070502* 8305070502* 8305120178 8305160172	50-443 50-443 50-443 50-206 50-312	0 0 0 H 0		8305130137 8305130162 8305160012 8305170291 8305170450	50-261 9 50-261 9 50-269 9 50-266 9 50-400 9
Bandia Laboratories	8305050432 8305040675 8305110491 8305110528 8305120556	NUREO NUREO NUREO NUREO 50-597	0		8305170497 8305180277 8305180429 8305190249 8305200630	50-400 9 50-287 9 50-382 9 50-483 9 50-400 6
	8305170122 8305170132 8305170135 8305180488* 8305310209	NUREG NUREG NUREG 71-9150 NUREG	,		8305240287 8305240313 8305240486 8305240515 8305240550	50-289 0 50-482 0 50-289 0 50-440 0 50-400 0
Sergent & Lundy, Inc.	8305310210 8305090467 8305090469* 8305120074* 8305190302*	NUREO TOPREP TOPREP 50-358 50-373	Q P		8305250202 8305250205 8305250208* 8305250225* 8305250274	50-289 0 50-483 0 50-289 0 50-289 0 50-483 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8305250297* 8305250300* 8305250346* 8305250351* 8305250358*	50-483 50-483 50-483 50-483 50-483			8305180465 8305200311 8305200352* 8305200510 8305200513	50-395 50-395 50-395 50-395 50-395	0 0 5 £
	8305250359* 8305250383* 8305250386* 8305250401* 8305250403*	50-493 50-483 50-483 50-483 50-483	G O G G		8305200515* 8305200626 8305200633* 8305250349 8305250492	50-395 50-395 50-395 50-395 50-395	8 9 9 P
	8305250412* 8305250419* 8305250440* 8305250444* 8305250448*	50-483 50-483 50-483 50-483 50-483	c G G	South Carolina, State of	8305270422# B305270441# 8305040577 B305040582* 8305040584#	50-395 50-395 50-239 50-238 50-238	O R R R
	8305250451* 8305250461* 8305250463* 8305250474* 8305250477*	50-483 50-483 50-483 50-483 50-483	e 0 0 0	Southern California Editon Co	8305040413* 8305230428* 8304150372* 8305020427 8305030354	50-238 COMMISS 50-361 50-206 50-361	R SION R P S
	8305250484* 8305250470* 8305250502* 8305250506* 8305250515*	50-483 50-483 50-483 50-483 50-483	0 0 0 0		8305030359* 8305030360 8305030432 8305060448 8305060450*	50~361 50~361 50~361 50~362 50~362	8 8 8
	8305250521* 8305250524* 8305250540* 8305250542* 8305250553*	50-483 50-483 50-483 50-483 50-483	0 0 0 0		8305060467 8305060505 8305060514# 8305090278 8305190377	50~361 50~361 50~361 50~361 50~206	8 8 9 9
	\$305250557* \$305250559* \$305250562* \$305250583* \$305250584*	50-483 50-483 50-483 50-483 50-483	0000		8305120164 8305120189 8305160011 8305160014# 8305160047	50-206 50-206 50-361 50-361 50-362	ម្មាល
Sheiter Island, NY Shoraham Opponents Coalition	8305260164 8305260148 8305310170 8305180367* 8305130072	50~483 50~483 50~483 50~322 50~322	0 0 0 H		8305160051* 8305160055 8305160055 8305160069* 8305160101*	50-361 50-361 50-361 50-361	8 8 8
Sierra Club	8305030502 8305100350 8305120271 8305160149 8305160181	50~537 50~537 50~537 50~537 50~537	0 0 0		8305160110 8305160115* 8305160125* 8305170278	50-362 50-362 50-362 50-362 50-361	8 8 8 8
Simpson, O H Binclair, M	8305170221 8305240533 8305230220 8305230220 8305250215	50-537 50-537 FOIA 50-329 50-329	0		8305170276 8305170471 8305170471 8305170026 8305170028	50-361 50-361 50-361 50-361 50-361	8 F F P
Sinnissippi Alliance for the Environment (SAFE)		50-329 50-329 50-329 50-454	e o o		8305170175 8305170175 8305170212 8305170212 8305170252	50-341 50-341 50-341 50-341 50-361	9999
	8305170549* 8305170572* 8305170572* 8305170574* 8305170581*	50-434 50-434 50-434 50-434	9 9 9 9		8305170252 8305240178 8305240458 8305240458 8305240501	50-341 50-204 50-341 50-361 50-204	6 F F
	8305170581* 8305170588* 8305170590* 8305170590* 8305170593*	50-454 50-454 50-454 50-454 50-454	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		8305240509 8305250512 8305270131 8305270157 8305270243	50-206 50-206 50-361 50-362 50-361	8 8 8
Small Susiness Administration Snell & Hilmer	8305170593* 8305200222 8305200154* 8305030594 8305240482	50-434 PR CONTRACT 50-529 30-529	0	Southold, NY Southwest X-Ray	8303270321 8303270408 8303190039 8303020061 8303040671	50-361 50-361 50-322 71-6717 71-495	H 8 8
South Carolina Electric & Qas Co.	8305310215 8305030627 8305030637* 8305050057 8305050061*	50-528 50-395 50-395 50-395 50-395	9 8 8 8	Bpiegel & McDiarmid St Louis Univ , St Louis, MO Stamiris, B	8305040679* 8305100339 8305090117* 8305170121 8305190216	71-495 PROJ CONTRAC NUREG 50-329	T Q
	8305050233 8305050239*	50-395 50-395	8	Standardized Nuclear Unit Power Plant	B305260166 B305020073	50-329 50-482	0 8
	8305050317* 8305050321* 8305060619 8305100089	50-395 50-395 50-395 50-395	ቸ ም 8	Bystem	8305040430 8305110014 8305110014	50-482 50-482 50-482	9 A A
	8305100091* 8305100301 8305180373 8305180442	50-395 50-395 50-395 50-395	8 P P		8305110014 8305110047 8305110047 8305110047	50-482 50-482 50-482 50-482	A E E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY	
	8305130007 8305130007 8305130007 8305180373 8305310175	50-482 50-482 50-482 50-482 50-482	A A A E A	Teledyne Engineering Services	8305030282* 8305050297 8305050303* 8305100225* 8305180395	50-275 50-275 50-322	RRRRR
State, Dept of State, Dept of, Bureau of Oceans & Inti Environ & Scientific Affairs Steinberg, Greenstein, Ocrelick, Price &		XPORTLIC XPORTLIC			8305180403* 8305200358 8305200364* 8305240342	50-275 50-275	R R R
Laveson Stone & Webster Engineering Corp	8305030271 8305030282*	50-275 50-275	R R		8305270001 8305270117* 8305270294	50-322 50-245	A P P
	8305030461 8305050069 8305100173 8305100179*	PR 50-423 50-275 50-275	K R R	Teledyne Wah Chang Albany	8305270305* 8305270317 8305090014	50-275	P
	B305120203 B305120211* B305120214*	50-275 50-275 50-275 50-275	R R R	Tennesses Valley Authority	8305070114 8304170477 8304170537* 8305030041 8305030041		B A A
	8305170511 8305170517* 8305180377 8305180383	50-275 50-275 50-275 PR	R R		8305030072 8305030072 8305030082 8305030082	50~390 50~390 50~390 50~390	8 8
	8305180454 8305180463* 8305230213	PR 50-358 50-275	F R		8305030121 8305030121 8305030174	50-390 50-390 50-327	A
	8305230221* 8305230556 8305230559* 8305230701*	50-275 50-275 50-275 50-410	R R A		8305030183* 8305030252 8305030252	50-327 50-438 50-438 50-276	8 8
	8305250406 8305250466 8305250467* 8305270003	PR 50-275 50-275 PR	R R		8305030272# 8305030370 8305030370 8305030434	50-296 50-438 50-438 50-390	8 8 8
Stone & Webster, Inc	8305310186 8305310191* 8305030509 8305030545*	50-275 50-275 50-275 50-275	R R R		8305030434 8305030501 8305030543 8305030543	50-390 50-259 50-390 50-390	A 8 E E
Storr, J F. Structural Dynamics Research Corp	8305240223 8305230603* 8303240487*	50-329 50-410 50-313	A A P		8305030558 8305030569 8305030578	50-43 0 50-327 50-390	A B
Structural Mechanics Associates Suffalk County, NY	8303240495* 8305170544* 8305050001 8305050005*	50-313 50-327 50-322 50-322	P A Q Q		8305030578 8305030579* 8305030606 8305030606	50-390 50-390 50-390	884
	8305050007 8305050518 8305070136* 8305100157 8305100239*	50-322 50-322 50-322 50-322	a 0 0		8305030625 8305030631 * 8305040253 8305040253	50-259 50-259 50-390 50-390	9 4 4
	8305120300* 8305120300* 8305120329 8305120332*	50-322 50-322 50-322	0 0		8305040511 8305040511 8305040511 8305040517* 8305040517*	50-259 50-259 50-259 50-259 50-259	6656
Sugarman, R J	8305130069 8305240548 8305310063 8305310013	50-322 50-322 50-352	0		8305040517# 8305040633# 8305040655# 8305050047	50-259 50-259 50-259 50-390	P F B
Sunflower Alliance	8305120476* 8305120476* 8305040325	40-215 40-215 50-440	0		8305050047 8305050067 8305050067	50-390 50-390 50-390	8
	6305040325 6305040487 6305040487 6305040548	50-440 50-440 50-440 50-440	9099		8305050078 8305050078 8305050120 8305050120	50-390 50-390 50-438 50-438	9 9
	8305100274 8305100274 8305100367	50-440 50-440 50-440	0 0 0		8305050122 8305050122 8305050123 8305050128*	50-438 50-438 50-327 50-327	8 8
Sweden	8305180818 8305180818	50-440 XPORTLIC XPORTLIC			8305050152 8305050152 8305050152	50-328 50-328 50-328	8
Syncor International TERA Corp	8305260060 8305060294 8304220515 8305200553	XPORTLIC PR 50-329 50-329	A		8305050152 8305050152	50-328 50-328	8
	B305200553 B305200567# B305200567# B305200575*	50-329 50-329 50-329 50-329	A A A		8305050183 8305050188 8305050188 8305050188	50-327 50-390 50-390 50-390	8 8 8 8
	8305310198 8305310198 8305310203* 8305310203*	50-329 50-329 50-329 50-329	R R R		8305050188 8305050188 8305050206* 8305050211 8305050217*	50-390 50-390 50-327 50-328 50-328	8888

AUTHGR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEOOR		AUTHOR AFFILIATIO	M	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305050218 8305050224* 8305050232 8305050232 8305050238	50-328 50-328 50-390 50-390 50-260	8 8 9 8 9			B3052001B7 B305200274 B305200274 B305200275 B305200275	50~390	8 8 8
	8305050243 8305050243 8305050245* 8305050266 8305050272*	50-390 50-390 50-260 50-259 50-259	9 6 9 8			8305200288 8305200300* 8305200325 8305200325 8305200343	50-260 50-260 50-390 50-390 50-390	8 A A B
	8305100012 8305100014* 8305100031 8305100036* 8305100081	50-259 50-259 50-260 50-260 50-259	8 8 9 9 9			9305200343 8305200387 9305200420 9305200424* 8305200427	50-390 50-390 50-260 50-260 50-327	8 8 8 8
	8305100083* 8305100101 8305100101 8305100107 8305100113*	50-259 50-327 50-327 50-296 50-296	2 4 5			8305200432* 8305200519 8305200519 8305200569 8305200577	50-327 50-438 50-438 50-438 50-327	6 5 9
	8305100189 8305100193* 8305100234 8305100234 8305100234	50-518 50-518 50-259 50-259 50-259	A A F F F			8305200581* 8305230433 8305230433 8305230447 8305230447	50-327 50-370 50-370 50-370	8 8 8 8
	8305100240 8305100240 8305100285 8305100292* 8305100358	50-438 50-438 50-260 50-260 50-438	A A 8 6 A			8305230482 8305230482 8305230530 8305230536* 8305230545	50-370 50-390 50-327 50-327 50-438	ង្គម្
	8305100349* 8305110292 8305110304 8305110304 8305110317	50-438 50-439 50-438 50-390	A 8 8 9 9			8305230545 8305230551 8305230551 8305230545 8305230545	50-438 50-438 50-438 50-438 50-438	8 8 8 8
	8305110319 8305110319 8305110319 8305110319 8305110325	50-390 50-390 50-390 50-390 50-327	8 8 5 8			8305230547 8305230547 8305230575 8305240323 8305240323	50-390 50-390 50-390 50-327 50-327	s s r r
	8305110329* 8305110355 8305110367* 8305110373 8305110382*	50-327 50-259 50-259 50-327 50-327	5 8 8			8305240394 8305250342 8305250357 8305250380 8305250400	50-327 50-328 50-260 50-328 50-328	មេខ១១១
	8305110406 8305110406 8305110409 8305110419* 8305110438	50-438 50-438 50-328 50-328 50-537	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8			8305250402 8305250421 8305250421 8305250425 8305250425	50-259 50-390 50-390 50-390 50-390	8 8 A A
	8305110441 8305110448 8305110449* 8305110505 8305130003	50-439 50-537 50-537 50-391 50-259	S 0 0 8 P			8305250433 8305250435 8305250473 8305250473 8305250508	50-328 50-390 50-259 50-259 50-294	8 P P 8
	8305130020 8305130027 8305130027 8305130041 8305130085	50-390 50-327 50-327 50-327 50-259	E. P P 원			830525052 <i>6</i> 8305250532 8305260307 8305270021 8305270030	50-327 50-327 50-327 50-259 50-259	8 8 6
	830513089 930513091# 8305130131 8305130133 8305130133	50-439 50-259 50-260 50-390 50-390	8 8 8 8 8			8305270133 8305270171 8305270177 8305270206* 8305270206*	50~390 50~259 50~259 50~259 50~259	G G G
	8305130141* 8305130147 8305130147 8305130154 8305130154	50-240 50-438 50-438 50-438 50-438	8 8 8			8305270204* 8305270233* 8305270233* 8305270355* 8305270386*	50-259 50-390 50-390 50-259 50-438	G G G G
	8305130217 8305130217 8305170030 8305170034* 8305170145	50-390 50-390 50-296 50-296 50-327	8 8 8 8 P			8305270567* 8305270592* 8305270592* 8305270597* 8305270608*	50-390 50-438 50-438 50-438 50-438	0 0 0
	8305170145 8305170237 8305170240* 8305170288 8305170289	50-327 50-566 50-566 50-370 50-370	P A A S S			8305270652* 8305270660* 8305270660* 8305270660* 8305310039	50-259 50-259 50-259 50-259 50-390	Q Q Q E .
	8305170299 8305170299 8305170330 8305170340* 8305200187	50~390 50~390 50~260 50~260 50~438	8 8 8			8305310053 8305310053 8305310054 8305310057*	50-327 50-327 50-296 50-327 50-327	р

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	8305310077 8305310138 9305310138 8305310147 8305310172	50-327 50-438 50-438 50-327 50-390	0 8 8 F 9		6305130205* 8305170162 8305170171* 8305170201 8305170205*	50-346 50-346 50-346 50-346 50-346	8 8 8 8
	8305310187 8305310193 8305310193 8305310214 8305310214	50-327 50-438 50-438 50-438 50-438	P 55 55 55 55 55 55 55 55 55 55 55 55 55		8305170462 8305180411 8305190149 8305190154* 8305200337*	50-346 50-346 50-346 50-346 50-346	PRRO
Teton Exploration Drilling Co , Inc Texas AbM Univ , College Station, TX	8305130281 8305050252 8305050257# 8305070073# 8305070586#	40-8728 50-128 50-128 50-128 50-445	P P G		8305200514* 8305200520* 8305200527* 8305200572 8305230714	50-346 50-346 50-346 50-346 50-346	9 9 8 P
Texas Instruments, Inc Texas Utilities Generating Co	8305180426 8305230497 8305250528 8305230480* 8305050018	71-5607 71-5607 50-128 50-410 50-445	R A G		8305240072* 8305240219 8305240251 8305240341 8305240351	50-346 50-346 50-346 50-346 50-346	0 8 6 8
	8305090507 8305090507 8305090513* 8305090517*	50-445 50-445 50-445 50-445 50-445	T T T T		8305240423 8305240241 8305240245* 8305240248* 8305240273	50-346 50-346 50-346 50-346 50-346	P P P 8
	8305090517* 8305090521* 8305090521* 8305090525* 8305090525*	50-445 50-445 50-445 50-445 50-445	T T T T	Torray Pines Technology	8305260303 8305310038 8305020367 8305020368* 8305020432	50-344 50-344 50-358 50-358 50-358	Q B A A A
	8305070530* 8305070530* 8305070726* 8305100267 8305100267	50-445 50-445 50-445 50-445 50-445	T A Q Q	Transmuclear, Inc	8305130301 8305180831 8305190452 8305230107 8305230118*	XPORTLIC XPORTLIC XPORTLIC 71-9015 71-9015	;
	8305100270 8305100270 8305100295 8305100295 8305100321	50-445 50-445 50-445 50-445 50-445	0000	Transportation, Dept of Trial Lawyers for Public Justice Twomey, Latham & Shea	8305230125 * 8305240097 8305230234 * 8305180792 * 8305100201	71-9015 XPDRTLIC FOIA CONTRACT 50-322	
	8305100321 8305130260 8305130260 8305160138 8305160138	50-445 50-445 50-445 50-445 50-445	0 0 K K	US Ecology, Inc (formerly Nuclear Engineering) Underwriters Laboratory	8305180447 8305030517 8305110134 8305110155	PR 27-39 27-48 27-48	
	8305160141# 8305140141# 8305170029 8305170002 8305200298	50-445 50-445 70-2932 70-2932 50-445		Uniformed Services Univ of the Health Sciences Union 76 Minerals Exploration Co Union Carbide Corp	8303070035* 8303270035* 8303060387 8303020021 8303060347	CONTRACT 50-320 40-8584 XPORTLIC RES	P
Teras Utilities Services, Inc	8305200298 8305200419* 8305200674* 8305100125 8305100130	50-445 50-445 50-445 50-445 50-445	g g A R		8305130346 8305170504* 8305170508* 8305180334 8305260386	AGRS 50-54 50-54 PR 40-279	9
Texas, State of Texas, Univ of Three Mile Island Alert	8305100135# 8305310151 8305070510# 8305100005 8305100212	50-445 50-445 50-445 50-192 50-289	R A T P Q	Union Electric Co	8305260395 8305260397* 8303240307 8303240311* 8304150354	40-279 40-279 50-483 50-483 50-482	4 4 8
Toledo Edison Ca	8305180369 8305200669 8305240444 8305240449 8305040305	PR 50-289 50-289 50-289 50-346	0 0 P		8305030263* 8305030467 8305060293* 8305170136* 8305170188*	50-483 50-483 50-483 50-483 50-483	0 0000
	8305040472 8305040480* 8305040491 8305040497* 8305040503*	50-346 50-346 50-346 50-346 50-346	6 6 6		8305170227* 8305190249 8305200518* 8305250205 8305250294	50-483 50-483 50-483 50-483	8 0000
	8305040395 8305040519 8305040523* 8305040401* 8305040408*	50-346 50-346 50-346 50-346	POGF		8305250297* 8305250300* 8305250304* 8305250341* 8305250346*	50-483 50-483 50-483 50-483 50-483	0 0000
	8305040499* 8305040702* 8305110385 8305110437 8305130032	50-346 50-346 50-346 50-346	F P P		8305250351* 8305250354* 8305250356* 8305250356* 8305250359*	50-483 50-483 50-483 50-483 50-483	0 0000
	8305130093 8305130095* 8305130190 8305130195* 8305130201*	50-346 50-346 50-346 50-346 50-346	8 8 9 8		8305250360* 8305250363* 8305250372* 8305250383*	50-483 50-483 50-483 50-483	0 000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJ	
	8305250388* 8305250374* 8305250401* 8305250403* 8305250408*	50-483 50-483 50-483 50-483 50-483	000	Utility Workers Union of America Vermont Yankee Nuclear Power Corp	8305190369 8305190380 8305240454 8305050101 8305050108	50-40 50-24 50-27	7 P 7 0 1 8
	8305250412# 8305250419# 8305250424# 8305250428# 8305250432#	50-483 50-483 50-483 50-483 50-483	0000		8305130103 8305170006 8305170007 8305200517 8305240195	50-27 50-27 50-27 50-27 50-27	1 R 1 R 1 P
	8305250436# 8305250440# 8305250444# 8305250448# 8305250451#	50-483 50-483 50-483 50-483 50-483	0000		8305240343 8305250569 8305250574* 8305270141 8305310212	50-271 50-271 50-271 50-271 50-271	4 J 4 J
	8305250458* 8305250461* 8305250463* 8305250468* 8305250474*	50-483 50-483 50-483 50-483 50-483	00000	Vet Admin Hosp Omaha:NE Virginia Electric & Power Co	8305310012 8305030158 8305030145* 8305030277 8305030283*	50-339	1 S 1 S 7 S
	8305250477# 8305250482# 8305250486# 8305250490# 8305250496#	50-483 50-483 50-483 50-483 50-483	00000		8305030357 83050303644 8305030555 8305030555 8305030611	50-339 50-339 50-330 50-338 50-338	8 8 9
	8305250502* 8305250504* 8305250511* 8305250515* 8305250521*	50-483 50-483 50-483 50-483	0000		8305030615* 8305030635 8305030640* 8305040173 8305040173	50-338 50-339 50-339 50-338 50-338	8
	8305250524* 8305250531* 8305250536* 8305250540* 8305250542*	50-483 50-483 50-483 50-483 50-483	00000		8305040409 8305040409 8305050118 8305050121* 8305050126	50-338 50-338 50-281 50-286	
	8305250544* 8305250548* 8305250552* 8305250553* 8305250557*	50-483 50-483 50-483 50-483 50-483	00000		8305050130* 8305050184 8305050191* 8305050210 8305050215*	50-281 50-338 50-338 50-339 50-339	8 8
	8305250559# 8305250562# 8305250564# 8305250573# 8305250576#	50-483 50-483 50-483 50-483 50-483	0 0 0		8305050271 8305050276# 8305060061 8305060061 8305060283	50-937 50-937 50-281 50-281	8 0 F
	8305250580* 8305250583* 8305250584* 8305250587* 8305250589*	50-483 50-483 50-483 50-483 50-483	0 0 0		8305060556 8305060556 8305060561* 8305060561* 8305070137	50-339 50-280 50-280 50-280 50-280	4 4 4
Union of Concerned Scientists	8305260164 8305260168 8305260173# 8305030608 8305030608	50-483 50-483 50-483 50-247 50-247	0000		8305100023 8305100029# 8305100108 8305100108	50-280 50-337 50-337 50-280 50-280	6 8 0
	8305030619* 8305030619* 8305030629* 8305030629* 8305030641*	50-247 50-247 50-247 50-247 50-247	0 0		8305100111# 8305100115 8305100120# 8305100129# 8305100259	50-280 50-280 50-280 50-280 50-280	P B B B
	8305030641# 8305030646# 8305030646# 8305030652# 8305060382	50-247 50-247 50-247 50-247 PR	0	•	9305100257 9305100315 9305110285 9305110288* 9305110380	50-339 50-339 50-336 50-336 50-338	8 9 5
	8305100204 8305160073 8305180356 8305230005 8305230243	50-247 50-289 PR FOIA FOIA	0		9305110336* 9305110453 9305110445* 9305120047 9305120244	50-339 50-339 50-339 50-339	8 8
	8305240249 8305240538 8305240538 8305240542* 8305240542*	50-245 50-247 50-247 50-247 50-247	P 0 0		8305120250* 8305120386 8305130058 8305130058	50-281 50-280 50-280 50-280	PPPF
United Engineers & Constructors, Inc (subs. of Raytheon Co.) United Nuclear Corp	8305200495 8305200177 8305250578* 8305250582* 8305250586*	70-371 70-371 70-371 70-371 70-371	S		8305130058 8305130058 8305130125 8305130130* 8305130136* 8305130198	50-260 50-260 50-261 50-261 50-260	F
Uranium Resources, Inc Utah, Univ. of	8305240371 8305140228 8305170349 8305170360*	70-820 40-8786 50-407 50-407	P P		8305130203* 8305130228 8305130228 8305130243* 8305170406 8305170412*	50-280 50-280 50-280 50-280 50-338	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8

Souther Ton

AUTHOR Affiliation	ACCESSION	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER		
	8305180372 27E0818058 8305190219 8305190253	50-260 50-260 50-338 50-339	P P Q	Hest Valley Agricultural Protection Council, Inc	830516003		
	8305200146 8305200163 8305200163	50-338 50-280 50-280	S P P		8305160034 8305160080	50-529 50-529 50-529	000
	8305200279 8305200284* 8305200499	50-339 50-339 30-280	\$ \$ P	West Valley Nuclear Services Co . inc West Virginia Univ Westchester County Association, Inc	8305140086 8305230020 8305240616 8305240308	# 50~201 # 50~201 # 50~129	9 0 0
	8305200479 8305200574 8305200583* 8305230424 8305230432*	50-280 50-338 50-338 50-281 50-281	P 8 8 8	Westchester County, NY	8305240517 8305190342 8305240533 8305240539 8305240539	50~247 50~247 50~247	H
	8305230451 * 8305250288 8305250384 8305250417	50-281 50-338 50-339 50-338	8 8 8	Western Nuclear, Inc (subs of Phelps Dodge Corp)	8305020407	40-1162	Ť
	8305260232 8305260323 8305260323 8305270143	50-338 50-338 50-338	b b	Westinghouse Electric Corp	8305020417- 8305250175 8304180548 8304180558:	40-1162 TOPREP TOPREP	
	8305270150 8305270220 8305270220 8305270248*	50-339 50-338 50-338 50-280	P P Q		8305020075 8305020076 8305020272 8305020272 8305030426	50-266	P
	8305270323 8305270335 8305270407* 8305270416*	50-338 50-339 50-338 50-338	5 0		9305030438# 8305050200 9305050208# 8305050288#	TOPREP TOPREP TOPREP	
Virginia, Univ of, Charlottesville, VA	8305270426* 8305310099 8305230548 8305270226*	50-338 50-339 50-339 50-396 50-42	e P P		8305090015 8305090202* 8305090212	XPORTE10 PROJ PROJ	
HSI Corp Wabash Valley Power Association, Inc	8305070300* 8305240087* 8305130073 8305130073	CONTRACT CONTRACT 50-546 50-546			8305110377* 8305110378* 8305110398*	50~334	PPS
	8305130048 8305130048 8305130244 8305130244	50-546 50-546 50-546	0 0 0		8305130303 8305170302 8305170307* 8305170311*	XPORTLIC TOPREP TOPREP TOPREP	
Wail Street Journal	8305170306 8305200289	50~546 50~546 FOIA	A F		8305170314 8305170314 8305170319 8305170319	50~454 50~454	9000
Washington Public Power Supply System	8303290382 8305020473 8305030146 8305030172#	50-397 50-460 50-460 50-460	G Q K K		8305170334 8305170334 8305170408 8305170408	50-454 50-454	0 7 7
	8305030300 8305030324 8305030489 8305030500	50-397	S 8 8		8305170411# 8305170411# 8305170522	50~454 50~454 50~454	T T
	8305030507 8305040565 8305040613* 8305050009	TOPREP TOPREP	8		8305170522 8305170554 8305180019 8305180262	50~454 TOPREP 71~9070 TOPREP	0
	8305050159 8305050159 8305050164* 8305060491	50-397 50-397	0		8305180273* 8305200304 8305200315* 8305200332* 8305200481*	TOPREP PR GA999 GA999 50~373	,
	8305100097 8305100110 8305100246	50~508 50~397 50~460	A A K		8305230255 8305240346* 8305260057*	TOPREP GA999 XPORTLIC	
	8305100304 8305120233 8305120236* 8305130106 8305130245	50-397 50-397 50-397	A K K S R	8	9305260070 9305260330 9305270006 9305270012#	XPORTLIC XPORTLIC TOPREP TOPREP	
	8305160041 8305160049 8305170156	50-297 (50-508 50-297 (E S A	E E Whittaker Coro	3305270459# 3305270481 3305270488#	70-1151 TOPREP TOPREP	
	8305230308* 8305230308* 8305240463	50-305 (50-305 (50-460 (G.	Hillians-Pohinetta t Assault	305120269# 305120269# 305120279# 305090012#	40~672 40~672 70~82 40~672 GDNTRACT	
Washington, State of Waste Management Group, Inc	8305310164 8305100416* 8305310076	50-305 F 50-237 C 50-460 G	G.	8 8	305170614# 305170456 305170456 305170486	CONTRACT 50~400 0 50~400 0 50~400 0	}
Hater, Waste & Land, Inc We Try Harder, Inc We Try Harder, Inc West Branch Conservation Association	6305240388 630505030389* 6305050035 6305260405	40-229 CONTRACT 50-247 (50-247 (S: S: Wilt, D.D.	305170486 305170491 305170491 305040487	50-400 6 50-400 6 50-400 0 50-440 0))

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y
	8305040487 8305040548 8305040548 8305100294 8305100294	50-440 50-440 50-440 50-440 50-440	G G G	Wisconsin. Btate of Wright.D Wyle Laboratories	8305040660* 8305310154 8305110198* 8305100349* 8305100355*	CONTRACT 50-305 CONTRACT GA999 GA999	R
Wisconsin Electric Power Co	8305100367 8305100367 8305310031 8305020438 8305030275	50-440 50-440 50-440 50-266 50-301	6 0 H 0 8	Wyoming Hineral Corp Wyoming, State of	83051100B9* 8305240403* 8305270011* 8305260144 8305030253	50-373 0A979 50-261 40-8502 40-8728	9
	8305030280* 8305030374 8305030382* 8305030523 8305040408	50-301 50-266 50-266 50-266 50-266	8 8 8 8 8		8305030262* 8305030273* 8305030709 8305030711 8305030713	40-8728 40-8728 40-8728 40-2239 40-8697	
	8305060408 8305110075 8305110075 8305110181 8305110181	50-266 50-266 50-266 50-266 50-266	P P P		8305040002 8305040222 8305040224 8305040357 8305040451	40-8584 40-8348 40-8380 40-8714 40-8697	
	8305110187* 8305110187* 8305110201 8305110201 8305120408	50-266 50-266 50-266 50-266 50-266	9 9 9		8305130363 8305140205 8305140209 8305140211 8305160274	40-8064 40-2259 40-8502 40-8584 40-8380	
	830512040B 8305130007 8305130007 8305130034 8305140167	50-266 50-266 50-266 50-266 50-266	0 P P 8 R		8305160276 8305170242 8305200031 8305250175 8305250241	40-299 40-8064 40-4492 40-8102 40-8697	
	8305160171* 8305170144* 8305170252* 8305170263* 8305170291	50-266 50-266 50-266 50-266 50-266	R Q Q	Yala Univ , New Haven, CT Yankee Atomic Electric Co	8305260363 8305260368 8305260389 8305030646# 8305030590	40-299 40-299 40-299 50-247 50-29	G S
	8305170226 8305200227 8305200227 8305230724 8305240131	50-266 50-266 50-266 50-266 50-266	8 Q P P		8305030597# 8305050006 8305050263 8305050268* 8305060192	50-29 50-443 50-29 50-29 50-29	9 F 5 F
	8305240331 8305240350 8305240379 8305240412 8305240497	50-301 50-301 50-266 50-301 50-266	8 8 8		8305040215 8305100228 8305110010 8305110020* 8305170459	50-29 50-29 50-29 50-29 50-29	ቻ F F P
Wisconsin Public Service Corp	8305240497 8305270241 8305270558 8305270558 8305030314	50-266 50-266 50-266 50-266 50-305	P Q Q		8305180342 8305190164 8305200353 8305200353 8305200402		8888
	8305030600 8305030602* 8305040009* 8305040014* 8305050106	50-305 50-305 50-305 50-305 50-305	9 F F R		8305200402 8305240358 8305240364 8305250244 8305270019	50-443 50-29 50-29 50-443 50-443	S P P S A
	8305100102 8305100114 8305100389 8305100397* 8305110003	50-305 50-305 50-305 50-305 50-305	P 8 8	Yarktown, NY	8305270019 8305240541 8305240546 8305240546 8305270583		A H 0 0
	8305130250 8305130251* 8305170150 8305170267 8305170271*	50-305 50-305 50-305 50-305 50-305	P B	Zack Co	8305270583 8305190112*		o s
	8305170323 8305180261 8305230728 8305270009 8305270198	50-305 50-305 50-305 50-305 50-305	О Р Р				

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this Index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
0383-03	8305130086*	50-244 P	
04-0640-0062 RO1	8305030564*	50-278 P	
186-028-14	8305200110*	50-277 G	
186-028-24	8305270052*	50-271 G	
282 ROI	8305120250*	50-281 P	
45307-1	8305270011*	50-261 P	
46511-3	8305110089*	50-373 P	
71-1C2-RADMC-R1	8305020272*	50-266 P	
77-1140877-01	B305070464*	50-302 P	
77-1141514-00	8305020404*	50-329 €	
77-1142162-00	8305110443×	50-346 P	
8 15 1-0 ROI	0305270501*	50-454 Q	
8206100210	8206100210*	REB	8AI-1-186-03-04
83-154 RO2	8305030412*	50-286 P	
83-154 R03	8305200412*	50-266 P	
8303080182	8303080182	RES	BAI-1-186-03-61
8303080187	83030B0187*	RES	8AT-1-186-03-61
8303080174	6303080194	REB	SAI-1-184-03-61
8303080505	8303080505*	RES	184-03-61
8303080209	8303080209	RES	BAI-1-186-03-61
6303080215	8303080215*	RES	8AI-1-186-03-61
8305030025	8305030025	RES	
B305060349	8305060347	RES	
8305110062	6305110062	RES	
8305110083	8305110083	RES	
8305130292	8305130292	RES	
8305250155	8305250155	REB	NRC-60-10-01-05
8305250168	8305250168	RES	
8305250174	8305250174	RES	
AB-442	8305030347*	50-335 R	
APL-01-014	83032404B7*	50-313 P	
APL-02-013	8303240495*	50-313 P	
B14/TER-8-7	8303310050*		TAG 44373
BAH-1774	B305270309*	50-269 F	
BNWL-2159	8011180782*	MISC	NRC-1
BWNP-20004 (6-76) R3	8305020372*		15-1120580-03
CEN-247 (N)-NP	8305120252*	50-336 F	•
CQ8/8114R028	0305310211	WARTE MOT	
CDM058 0011 0007	#70E00260EB	50-237	
CPC-2A ROI	8303240565*	50-155 F	•
COD-003490 ROO	8305190303*	50-373 F	
CR 729 RA	8305100395*	50-43B #	•
CR 790 RA	8305100382*	50~43B	
CRBRP-3 VOZ ROS	8305310003*	50-537	1
CT-25086A	8305170311#	TOPREP	
DRR-AF-001-DB ROO	8305200688*	50-373 F	,
E-350B R01	8305230125*		5 548A-23
END~043447	#305230292*		4
E8-LPD-83-001 R01 F-A5818-1	8305190322*		3
FATE-82-114	#3010A0137*		
GPC-04-104 R01	83050A0055*	40	GPC004 0104
OPC-07-102 RA DRFT	8305310097*		3
LMBE-75/0363&191/029	8305230687*		4
LMSE-76/0081&191-033	8305230441*	JU-410 1	7

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
LMSE-B2/0091&191-058	8305230587*	50-410 A	
MPGP-1 ROS DRFT	8305190300*		HPGP-1
NEDO-24011-A-5 ERR	8303090497*	TOPREP	B2NED057
NEDO-24011-A011-A-US	8305090495*	TOPREP	B2NEDQ58
NEDO-24582 RO1	8305260325*		B1NED0078
NEDO-24712-A	8305040466*	TOPREP	79NED122R1
NMP11K	B304110519*	50-220 R	
NP-PS-53-0378 RO	B305030343*	TOPREP	
NUC3-E1	B305100144*	50-293 R	
NUREG-0020 VO7 NO1	8305170128	NUREO	
NUREO-0040 VO7 NO1	8305040689	NUREO	
NUREG-0472 DO7 RO3	B305060007*		PHR-8T8-1
NUREQ-0405 VO5 NO3	8305060680	NUREO	
NUREO-0540 VO4 NO1	8305040693	NUREQ	
NUREQ-0580 V12 N04	8305170099	NUREO	
NUREO-0728 RO1	8305090046	NUREO	
NUREG-0748 VO3 NO3	8305110240	NUREO	PSRP-6 2 2 R4
NUREO-0800 RO4 NUREO-0827	8305170092 8305040682	NURED 50-409 P	
NUREG-0837 VOZ NOSER	8305170579	NUREG	
NUREQ-0869 FC	8305170123	NUREO	
NUREQ-0871 VO2 NO2	8305110114	NUREO	
NUREQ-0887 803	8305170074	50-440 E	
NUREQ-0876 SOL	8305170668	00 11D G	
NUREG-0897 FC	8305170118	NUREO	
NUREO-0940 VO2 NO1	B305110174	NUREC	
NUREQ-0941	9305190796	NUREO 50-413 E	
NUREO-0754 801	8305170712 8305170037	50-413 E 50-537 E	
NUREQ-0968 801 NUREQ-0969	8305110118	50-337 E	
	8305170149	50-400 D	
NUREG-1000 VOI	8305170674	50-272 8	
MUREO/BR-0006 R01	8305090040	NUREO NUREO	
NUREQ/BR-0006 RO1 ER NUREQ/BR-0025 V09 N4	8305070035	NUREG	
NUMERALBE-OUTS AND MA	B305170137		
NUREQ/BR-0051 VO4 No	B305040740 B305110119	NUREO	BNL-NUREQ-51579
NUREO/CP-0035 NUREO/CP-0043	8303270109	NUREO	BINC MOVER. DIOLI
NUREO/CR-0169 VOI	8303110482	NUREO	E00-2037
NUREO/CR-2000 VO2 N3	8305020538	NUREO	DRML/NSIC-200
NUREQ/CR-2000 VO2 N4	8305310237	NUREO	DRNL/NSTC-200
NUREG/CR-2001	8305050426	NUREO	EPRI NP-2372
NUREQ/CR-2003 RO1	8305060675	NUREO	BAND81-7074
NUREG/CR-2069 ROI	8305110120	NUREG	DRNL/NSIC-181/R
NUREQ/CR-2326	8305310210	NUREO	BAND81-1994
NUREO/CR-2331 VOR N3	8305110237	NUREC	BNL-NUREQ-51454
NUREQ/CR-2482 V02	B305170101	NUREO	BNL-NUREO-51494
NUREG/CR-2568	8305110196	NUREO	0EAP-22046
NUREQ/CR-2716 V04	8305110208	NUREO	PNL-4275-4 BAND82-7054
NUREG/CR-2743	8305110528	NUREO	
NUREG/CR-2744 V02	8305110491	NUREO	SAND82-7057
NUREQ/CR-2769	8305110457	NUREO	PML-4414 ANL-82-24
NUREG/CR-2774 VO4	8305110148	NUREO NUREO	PNL-4434
NUREO/CR-2924	8305040674 8305110126		BNL-NUREO-
NUREQ/CR-3013	9303110140	SOURCE C	

REPORT	ACCESSION	BUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEGORY	NUMBER
NUREG/CR-3014	8305180782	NUREG	PNL-4516
NUREG/CR-3073	8305110131	NUREG	BNL-NUREG-51616
NUREQ/CR-3074	8305110227	NUREG	BNL-NUREG-51423
1 POE-33\Q3RUM	B305020547	NUREG	BNL-NUREG-51430
NUREQ/CR-3100	8305310209	NUREG	SAND82~2702
NUREQ/CR-3114 ERR	8305130341	NUREO	ORNL/TM~8614
NUREG/CR-3117	8305070162	NUREG	
NUREQ/CR-3119 V01	8305110027	NUREG	
NUREG/CR-3136	B305060233	NUREQ	PNL-4604
NUREG/CR-3140	8305050432	NUREQ	8AND82-2985
NUREQ/CR-3173	8305170121	NUREG	
NUREQ/CR-3184	8305110523	NUREO	EQG-2244
NUREG/CR-3187	8305110127	NUREG	BNL-NUREG-51653
NUREG/CR-3195	8305110518	NUREO	EGQ-2246
NUREQ/CR-3216	8305110467	NUREO	EGG-2249
NURED/CR-3220	8305110162	NUREO	ANL-83-15
NUREQ/CR-3229	8305060347	NUREG	
NUREO/CR-3230	8305240015	NUREO	MEA-2013
NUREQ/CR-3235 VOI	9305170122	NUREO	SAND82-1557
NUREQ/CR-3235 V02-04	8305170132	NUREG	8AND82-1557
NUREQ/CR-3235 V05-04	8305170135	NUREO	9AND82-1557
NUREQ/CR-3240	8305170086		C6616-03RUM-1MB
NUREO/CR-3255	8305110476	NUREO	
NUREQ/CR-3261	8305110512	NUREO	
ORNL/ENG/TM-5 DRF 01	8305260004*	71-5552	22245
P105-4-839-033 R01	8305030581*	50-275 R	
PALEX-83	8305020083*	30-255 F	
RB-NRR-80-102	B303250034*	POIA	
BAI-186-028-18	8209150251*	50-250 G	
SAI-186-028-39	8209200375*	50-313 P	

REPORT NUMBER		HUBJECT	OTHER REPORT NUMBER
9AI-186-029-34 SECY-82-013D	8207080458* 8305230070*		P
SECY-83-017	8305180328*	50-237	P
SECY-83-019	8305180322#	FOIA	
SECY-83-059	8302280090	SECY	
SECY-83-059B	8304220083	SECY	
SECY-83-047	9305250250	SECY	_
SECY-83-140	9305020530		P S
SECY-83-158 9ECY-83-195	8305170232 8305270118	SECY	5
9204-83-173	8202510118	3561	
SL-TR-1A ROS	8305090469*		
SMA 13701 05R003 V05	B305170544#		A ISBUANCES OM
SR 8031-5510 ROO	8305100281*		A
TER-C5257-207/208	8208060249*		P
TER-05257-28	8206300177*	50-309	P
TER-C5504-101/102	8305200720*		P TAC 8147
TER-C5506-356 DRFT	8305310241*		P TAC 07991
TER-C5506-358 DRFT	8305230284*		Р
TER-05506-374/375/37			P TAC 08065
TER-C5506-99	8207210332*	50-336	P
TR-5318-1 RO1	B305270119*	50-245	P
TR-83021-1 ROO	830503017E*	50-341	Α
TR-83021-1 ROD ERR	8305050010*		A
UCID-19450	8207020602*		P
UCID-1945Q RO1	B304060471*	50-335	P
WCAP-10252	8305110398*		P
WP-0676	8305230725*		Р
WP89-0A-004 R07	8305040613*		_
Y1003J01A46 R01	B305060076*		P .
Y1003J01A\$3	B305100370*	50-325	Р
109 9591015001A	B30527037B#	50-333	P

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCEPPION AUMOND

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSIO									
	PRINCIPAL	DATE	SUBJEC	т	ACCESSIO	N NUMBER			
ENCLOSURE	DOCUMENT	TESUED	CATEGO	RY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
7908080036	8305180001	83/03/09	50~498	G					
7909180214	8305180001	83/03/09	50~498	8	8211180501	8305160195	83/03/31	50-312	Gr
7911150353	0305160005	83/04/12	FOIA		8212070092	B305120607	83/04/28	MISC	
8005140294	8305180001	83/03/09	50~498	Α	8301060137	6303240026	83/03/09	50-309	P
8005280930	8305180001	83/03/09	50~498	a	8301120436	8305040323	83/05/04	50-247	P
					8301310274	8301310260	83/01/28	50-352	K
8004070238	8305180001	83/03/09	50~498	a					
8006090440	B3051B0001	83/03/09	50~498	G	8302250480	8305230704	83/05/16	50-470	Α
B006090443	8305180001	83/03/09	30~498	Ä	8303080187	8303080182	83/02/28	RES	
8006180378	8305020007	83/01/11	FOLA		8303080202	8303080194	83/02/28	RES	
8008120773	10008180001	83/03/09	50~498	Α	8303080215	8303080209	83/02/28	RES	
				•	8303170135	B30504Q648	83/05/03	50-423	A
8008250310	8305020007	83/01/11	FOTA		0000170100	020000000	W47.007.00	00 120	
8008250337	8305020007	83/01/11	FOTA		8303240029	8303240026	83/03/09	50-309	р
8008250463	8305020007	83/01/11	FOLA		8303240311	8303240307	83/03/21	50-483	A
8007120352	8305180001	83/03/09	50~498	G	8303240394	8303240390	83/03/23	50-537	G
8010090450	8305180001	83/03/09	50~498	Ä	8303240487			50-313	P
0010010100	9993190001	63/03/04	30-498			B30324Q480	83/03/22		p
8010280578	8305180001	83/03/09	50-324	P	8303240495	8303240480	83/03/22	50-313	-
8010280378	8305180001	83/03/09			*********				_
8011180782			50~498	Α	8303280136	8303560159	83/03/17	50-315	8
	8305040596	75/01/25	MISC		8303280182	8303280177	83/02/23	40-2061	-
8103130267	0305020007	83/01/11	FOIA	_	8303280325	8303280319	83/03/14	50-302	P
81032503B5	8305180001	83/03/09	50~498	G	B303300005	8303300001	83/03/11	50-295	P
**********					6303300003	8303300001	83/03/11	50-275	P
8103300576	8305240254	B3/03/31	30-416	A					
8104030770	8305020007	B3/01/11	FOIA		8303300396	8303300387	83/03/11	50-260	P
8104060877	8305020007	83/01/11	FOIA		8303300401	8303300387	93/03/11	50-260	P
B10B250739	8305240252	83/04/14	COMMISS	ION	8303300408	8303300387	83/03/11	50-260	P
B111030653	8305070529	83/03/10	FOIA		8303310020	8305030135	83/04/18	50-333	P
					8304010139	8305120407	83/04/28	RISC	
8111030655	8305090529	83/03/10	FOIA						
8112160259	8305120224	83/03/01	40-672		8304040394	8304040391	83/03/30	20~322	Ų
8112270557	8305120224	83/03/01	70-925		8304040591	8305120607	83/04/28	RISC	
8201070110	8305060135	83/03/03	40-672		8304050254	8304060243	83/03/26	50-461	К
8203150093	8305090529	83/03/10	50-443	F	8304060126	830406011B	83/04/04	50-440	E
					8304060471	8305120146	83/05/03	50~335	P
8203180052	8305060073	83/03/14	50-204	Ρ					
B204190027	8305060073	83/03/14	50-206	P	8304070286	8305130294	83/04/20	50-269	p
8206100210	8204100204	82/04/08	REB		8304080009	830506035B	83/04/13	TOPREP	
8204300177	8305230381	93/05/11	50-309	p-	B304110328	8304110321	83/04/07	50-416	P
8207080458	8305040769	83/04/20	50-321	P	8304110335	8304110321	83/04/07	50-416	ڄ
				•	8304110519	8304110516	83/03/30	50-220	R
820708052B	8305020066	83/04/29	50-255	P					
8207300178	8305120488	83/03/25	50-271	à	B304110706	B304110696	83/03/24	50-293	9
8208060242	8305060135	83/03/03	40-672	•	8304120042	8304120027	83/03/30	50-321	P
B208060244	8305040135	83/03/03	40-672		9304120412	B304120409	83/03/23	50-373	Ġ
B208060249	8305090144	83/04/20	50~338	P	8304130042	8304130034	B3/03/05	71-494	•
020000247	0303070144	03/04/20	30-338	r	8304140161	8305260322	83/05/24	50-352	G
8208170078	8305090529	83/03/10	50-443	F	0304140101	9301590355	04/05/64	20 00E	•
8208250506	8305190005	83/03/10	50-373	þ	8304140328	8305090295	83/04/22	MISC	
8209020402				P	8304150147	8304150143	83/03/30	50-313	q
	8305120146	83/05/03	50~335				B3/03/30	50-313	ă
8209150251	8305090085	83/04/26	50~250	Ġ.	8304150154	8304150143		50-440	G
8209200375	8305090147	83/04/18	50~313	Р	8304150364	8304150362	83/04/01		
00000140			:	_	8304150372	83041 50368	83/03/15	50-361	R
8209210332	8305040058	83/04/21	50-336	Þ	000410455	GD05010415	55 (04 (1)	50-454	F
8211030191	8305140195	83/03/31	50-312	a	8304150458	8305040062	B3/04/11		r
8211100028	8305140255	83/03/24	50-312	S	8304180420	8305260149	B3/05/10	WISC	-
8211110645	8305140255	83/03/24	50-312	8	8304180513	8304180491	83/04/06	50-311	S
8211150068	8305140255	83/03/24	50-312	G	8304180554	8304180541	63/04/05	70-1143	
					6304180558	8304180548	83/04/12	TOPREP	

	N NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DBCUHENT	DATE ISSUED	CATEGO	RY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT	
8304190537 8304210240 8304220257 8304250163 8304250190	B304190499 B30421023B B305060671 B304250152 B304250167	83/04/13 83/04/13 83/04/22 83/04/11 83/04/21	50-327 50-410 50-321 70-2953 50-546	\$ K P K	8305020324 8305020327 8305020327 8305020332 8305020332	8305020322 8305020322 8305020322 8305020322	83/04/18 83/04/18 83/04/19 83/04/18 83/04/08	50-57 50-57 50-282 50-57 50-461	G G G
8304270426 8304270427 8304280049 8305020004 8305020008	8304270424 8304270424 8304280037 8305020002 8305020002	83/04/22 83/04/22 83/04/25 83/04/18 83/04/18	50-313 50-313 50-416 71-9177 71-9177	F F	8305020344 8305020348 8305020352 8305020353 8305020354	8305020340 8305020347 8305020349 8305020351 8305020350	83/04/26 83/04/15 83/04/11 83/04/13 83/04/18	50-317 50-315 50-305 50-373 50-483	G G B G
8305020010 9305020015 8305020014 8305020019 8305020022	8305020007 8305020007 8305020007 8305020007 8305020007	63/01/11 63/01/11 63/01/11 63/01/11 63/01/11	FOIA FOIA FOIA FOIA		8305020356 8305020357 8305020360 8305020365 8305020365	8305020349 8305020350 8305020358 9305020364 8305020364	83/04/11 83/04/19 83/04/18 83/04/28 83/04/28	50-305 50-483 50-331 9A979 9A999	0
6305020027 8305020031 6305020035 8305020039 6305020042	8305020007 8305020007 8305020007 8305020007 8305020007	63/01/11 83/01/11 83/01/11 83/01/11 63/01/11	FDIA FDIA FDIA FDIA FOIA		8305020368 8305020345 8305020345 8305020378 8305020392	8305020367 8305020364 8305020372 8305020373 8305020384	83/04/21 83/04/28 83/04/22 83/04/25 83/04/28	50-358 QA999 50-269 50-368 50-312	PSP
8305020047 8305020049 8305020057 8305020063 8305020070	8305020007 8305020007 8305020007 8305020007 8305020007	83/01/11 83/01/11 83/01/11 83/01/11 83/01/11	FOIA FOIA FOIA FOIA		8305020393 8305020397 8305020397 8305020404 8305020404	8305020384 8305020387 8305020375 8305020378 8305020400	83/04/26 83/04/27 83/04/26 83/04/13 83/04/26	50-309 50-255 50-213 50-329 50-470	0 0 0 E E
8305020076 8305020078 8305020081 8305020083 8305020070	8305020075 8305020072 8305020007 8305020079 8305020086	83/03/30 83/04/19 83/01/11 83/04/11 83/04/21	70-698 50-316 70-378 50-235 50-373	\$ F 8	8305020417 8305020429 8305020430 9305020433 8305020433	8305020407 8305020425 8305020422 8305020427 8305020422	83/03/31 83/04/22 83/01/11 83/04/28 83/01/11	40-1142 50-443 50-445 50-206 50-445	0000
8305020072 8305020095 8305020104 8305020114 8305020115	8305020089 8305020007 8305020100 8305020109 8305020110	63/04/29 63/01/11 63/04/25 63/04/21 83/04/25	50-528 FOIA 50-10 50-373 50-456	g 8	8305020443 8305020444 8305020445 8305020464 8305020465	8305020439 8305020422 8305020436 8305020449 8305020461	83/03/02 83/01/11 83/04/28 83/04/27 83/04/27	40-6659 50-445 50-313 50-296 50-219	0 0 P 1
8305020137 8305020145 8305020151 8305020152 8305020154	8305020128 8305020138 8305020141 9305020007 8305020142	83/04/25 83/04/21 83/04/19 83/01/11 83/04/20	50-266 50-255 50-315 FOIA 50-254	P 8 8	B305020480 B305020484 B305020486 B305020492 B305020504	8305020467 8305020481 8305020482 8305020488 8305020410	83/04/13 83/02/28 83/04/24 83/04/22 83/03/24	50-10 40-8681 50-443 50-263 40-6622	9 9
8305020158 8305020160 8305020169 8305020170 8305020171	B305020007 B305020150 B305020007 B305020146 B305020161	83/01/11 83/04/27 83/01/11 83/04/21 83/04/22	FOIA 50-272 FOIA 50-409 50-314	5 5	8305020505 8305020525 8305020525 8305020539 8305020545	8305020007 8305020007 8305020523 8305020007 8305020007	83/01/11 83/01/11 83/03/28 83/01/11 83/01/11	FOIA FOIA 70-824 70-378 FOIA	
8305020172 8305020177 8305020176 8305020179 8305020182	8305020165 8305020161 8305020007 8305020173 8305020146	83/04/27 83/04/22 83/01/11 83/04/21 83/04/21	50-400 50-314 FDIA 50-255 50-409	888	8305020550 8305020554 8305020557 8305020558 8305020540	8305020007 8305020007 8305020553 8305020007 8305020007	83/01/11 83/01/11 83/04/14 83/01/11 83/01/11	FOIA FOIA XPORTLIC FOIA FOIA	
8305020187 8305020191 8305020196 8305020198 8305020200	8305020007 8305020007 8305020007 8305020192 8305020007	83/01/11 83/01/11 83/01/11 83/04/22 83/01/11	FOIA FOIA FOIA 50-316 FOIA	s	8305020364 8305020367 8305020571 8305020603 8305030008	8305020007 8305020007 8305020007 8305020602 8305020007	83/01/11 83/01/11 83/01/11 83/04/21 83/01/11	FOIA FOIA FOIA 50-335 FOIA	P
8305020201 8305020204 8305020207 8305020212 8305020215	8305020007 8305020007 8305020007 8305020007 8305020210	83/01/11 83/01/11 83/01/11 83/01/11 83/04/28	FOIA FOIA FOIA FOIA 50-289	R	8305030019 8305030020 8305030022 8305030023 8305030024	B305030016 B305020007 B305030016 B305020007 B305030021	83/04/06 83/01/11 83/04/06 83/01/11 83/04/22	50-389 FDIA 50-389 FDIA 50-244	P P P
8305020220 8305020232 8305020234 8305020234 8305020251	8305020007 8305020226 8305020224 8305020205 8305020241	83/01/11 83/04/26 83/04/26 83/04/15 83/04/15	FOIA 50-289 50-456 50-373 50-373	0 5 5	8305030027 8305030035 8305030047 8305030055 8305030056	8305020007 8305020007 8305020007 8305020007 8305030018	83/01/11 83/01/11 83/01/11 83/01/11 83/04/11	FOIA FOIA FOIA XPORTLIC	:
8305020256 8305020267 8305020268 8305020274 8305020285	8305020246 8305020258 8305020261 8305020264 8305020264	83/04/21 83/04/26 83/04/28 83/04/11 83/04/11	50-249 50-272 GA999 50-341 50-341	9 9	9305030063 8305030070 8305030073 8305030077 8305030080	8305020007 8305030066 8305020007 8305030074 8305020007	83/01/11 83/04/19 83/01/11 83/04/20 83/01/11	FOIA 50-333 FOIA 70-1257 FDIA	p
8305020292 8305020295 8305020296 8305020306 8305020307	8305020272 8305020289 8305020288 8305020007 8305020289	83/04/13 83/02/02 83/04/14 83/01/11 83/02/02	50-266 GA999 XPORTLIC FOIA GA999	P	8305030084 8305030087 8305030072 8305030072 8305030078	8305030076 8305020007 8305030076 8305020007 8305020007	83/04/28 83/01/11 83/04/22 83/01/11 83/01/11	50-295 FOIA 50-295 FOIA FOIA	F
8305020312 8305020318 8305020319 8305020321 8305020323	8305020299 8305020007 8305020316 8305020317 8305020007	83/04/22 83/01/11 83/02/02 83/04/22 83/01/11	50-315 FOIA GA999 50-315 FOIA	8	8305030105 8305030112 8305030114 8305030117 8305030125	8305020007 8305030102 8305030104 8305030104 8305020007	83/01/11 83/04/20 83/04/22 83/04/22 83/01/11	FOIA 50-287 50-275 50-275 FOIA	6 F F

ACCESSION	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	EUBJECT CATEOORY	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED	CATEGO	
8305030127 8305030142 8305030145 8305030147 8305030153	8305030095 8305020007 8305030139 8305020007 8305030144	83/04/19 83/01/11 83/04/18 83/01/11 83/04/29	50-289 FOIA 50-277 FOIA 50-387	S Q P	8305030342 8305030364 8305030366 8305030371 8305030380	8305030358 8305030357 8305030358 8305030348 8305030373	83/04/15 83/04/20 83/04/15 83/04/28 83/04/21	GA999 50-339 GA999 70-27 50-247	s
8305030154 8305030160 8305030169 8305030164 8305030165	8303020007 8303030156 8303020007 8303030151 8303030158	83/01/11 83/04/28 83/01/11 83/04/19 83/04/20	FOIA 50-285 FOIA 50-320 50-338	P 0 8	8305030382 8305030388 8305030390 8305030396 8305030407	8303030376 8303030383 8303030385 8303030394 8303030400	83/04/25 83/04/18 83/04/25 83/04/25 83/04/15	50-266 50-318 50-313 50-331 50-247	8 8 8
8305030149 8305030172 8305030173 8305030174 8305030178	8305020007 8305030146 8305030168 8305020007 8305030171	83/01/11 83/04/18 83/04/29 83/01/11 83/04/29	FOIA 50-440 50-251 FOIA 50-341	K R	8303030412 8305030419 8305030429 8305030435 8305030438	8305030408 8305030411 8305030425 8305030425 8305030426	83/04/28 83/04/22 83/04/29 83/04/29 83/04/28	50-286 50-324 50-285 50-285 TOPREP	P S F
9305030179 9305030183 9305030185 9305030189 9305030189	8305020007 8305030174 8305020007 8305030180 8305020007	83/01/11 83/04/26 83/01/11 83/04/22 83/01/11	FOIA 50-327 FOIA 50-275 70-378	S F	8305030446 8305030447 8305030458 8305030470 8305030471	8305030440 8305030441 8305030456 8305030462 8305030466	83/04/25 83/04/20 83/04/28 83/04/28 83/04/12	50-304 50-219 50-247 50-320 QA999	5 8 P R
8305030193 8305030195 8305030200 8305030201 8305030207	9305030180 9305020007 9305030191 9305020007 9305020007	83/04/22 83/01/11 83/04/15 83/01/11 83/01/11	50-275 70-378 50-275 70-378 70-378	F	8305030473 8305030474 8305030475 8305030478 8305030481	8305030465 8305030469 8305030466 8305030462 8305030463	83/04/25 83/04/04 83/04/12 83/04/28 83/04/28	50-325 50-483 0A999 50-320 50-324	B G R P
8305030208 8305030212 8305030213 8305030218 8305030221	8305030198 8305020007 8305020007 8305020007 8305030214	83/04/19 83/01/11 83/01/11 83/01/11 83/04/22	50~317 70~378 70~378 70~378 50~282	Q F	8305030484 8305030496 8305030511 8305030516 8305030518	8305030462 8305030491 8305030509 8305030508 8305030509	83/04/28 83/04/29 83/04/12 83/04/27 83/04/12	50-320 50-309 GA999 50-454 GA999	R P T
9305030225 8305030226 9305030233 8305030239 8305030240	8305020007 8305030214 8305020007 8305030231	83/01/11 83/04/22 83/01/11 83/01/11 83/04/22	70-378 50-282 70-378 70-378 50-389	F	8305030521 8305030525 8305030533 8305030535 8305030536	8305030513 8305030507 8305030528 8305030527 8305030512	83/04/29 83/04/12 83/04/29 83/04/20 83/04/22	50~264 GA999 50-358 50-320 50-324	G K S
8305030244 8305030246 8305030247 8305030251 8305030255	B305030231 B305030237 B305020007 B305020007 B305020007	83/04/22 83/04/20 83/01/11 83/01/11	50-389 40-8027 70-378 70-378 70-378	F	8303030537 8305030545 8305030547 8305030561 8305030564	8305030524 8305030538 8305030540 8305030551 8305030554	83/05/02 83/04/25 83/04/22 83/04/19 83/04/27	50-440 50-275 50-324 50-312 50-298	T R 8 8
8305030260 8305030262 8305030263 8305030264 8305030268	8305020007 8305030253 8305030258 8305020007 8305020007	83/01/11 83/03/25 83/04/28 83/01/11 83/01/11	70-378 40-8728 50-483 70-378 70-378	a	6305030567 8305030579 8305030581 8305030587 8305030589	8305030565 8305030569 8305030573 8305030577 8305030580	83/04/29 83/04/26 83/04/29 83/04/28 83/04/22	50-309 50-327 50-275 50-312 50-364	9 8 8 9 8
8305030272 8305030273 8305030278 8305030280 8305030281	8305030246 8305030253 8305020007 8305030275 8305020007	83/04/26 83/03/25 83/01/11 83/04/26 83/01/11	50-294 40-8726 70-378 50-301 70-378	8	8305030392 8305030395 8305030397 8305030402 8305030410	8305030559 8305030593 8305030590 8305030600 8305030603	83/04/26 83/04/27 83/04/19 83/04/29 83/04/29	50~461 50~334 50~27 50~305 50~263	R R B P K
8305030282 8305030283 8305030286 8305030269 8305030270	8305030271 8305030279 8305020007 8305020007 8305030287	83/04/25 83/04/20 83/01/11 83/01/11 83/04/12	50-275 50-339 70-378 70-378 50-312	R	8305030413 8305030415 8305030418 8305030419 8305030422	8305030603 8305030611 8305030612 8305030608 8305030617	83/04/29 83/04/21 83/04/20 83/04/19 83/04/27	50-263 50-338 50-324 50-247 50-482	8 0 0 8 X
8305030293 8305030296 8305030301 8305030304 8305030307	6305030288 6305020007 8305020007 6305030299	83/04/28 83/01/11 83/01/11 83/01/11	50-324 70-378 70-378 70-378 50-352	P A	8305030624 8305030628 8305030629 8305030631 8305030633	8305030420 8305030420 8305030408 8305030425 8305030408	83/04/26 83/04/26 83/04/19 83/04/22 83/04/19	50-245 50-245 50-247 50-259 50-247	P 0 0
8305030308 8305030309 8305030312 8305030314 8305030320	8305030297 8305020007 8305020007 8305030311 8305020007	83/04/28 83/01/11 83/01/11 83/04/13 83/01/11	70-944 70-378 70-376 50-334 70-378	8	8305030437 8305030640 8305030641 8305030646 8305030652	8305030627 8305030635 8305030608 8305030608 8305030608	83/04/22 83/04/21 83/04/19 83/04/19 83/04/19	50-395 50-339 50-247 50-247 50-247	8 0 0
8305030323 8305030326 8305030331 8305030332 8305030333	8305020007 8305020007 8305030325 8305020007 83050303321	83/01/11 83/01/11 83/04/27 83/01/11 83/04/22	70-378 70-378 50-313 70-378 50-254	Q S	8305030465 8305030484 8305030467 8305030470 8305030475	8305030634 8305020007 8305030685 8305030665 8305030693	83/04/22 83/01/11 83/04/25 83/04/25 83/04/22	50-321 FOIA 50-321 50-321 50-287	P F F
8305030335 8305030338 8305030339 8305030343 8305030347	8305020007 8305030334 8305020007 8305030337 8305030341	63/01/11 63/04/21 83/01/11 63/04/27 83/04/28	70-378 50-387 FDIA TOPREP 50-335	8 R	8305030720 8305030722 8305040009 8305040014 8305040016	8305030716 8305110415 8305040007 8305040007 8305040010	83/04/25 83/05/10 83/04/25 83/04/25 83/04/22	71-9105 REVIEW 6 50-305 50-305 50-395	F F P
8305030348 8305030351 8305030353 8305030359 8305030361	8305030334 8305030349 8305030350 8305030354 8305030355	83/04/29 83/04/15 83/04/19 83/04/18 83/04/20	50~10 GA999 50~309 50~361 50~324	G G S S	8305040021 8305040034 8305040039 8305040052 8305040060	8305040010 8305040022 8305040022 8305040047 8305020007	83/04/22 83/04/25 83/04/25 83/04/13 83/01/11	50-395 50-245 50-245 40-7869 70-378	F

ACCESSION					ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT	_
8305040068 8305040074 8305040080 8305040081 8305040089	8305040054 8305040069 8305040069 8305020007 8305020007	83/04/20 83/04/22 83/04/22 83/01/11 83/01/11	50-287 50-454 50-454 FOIA FOIA	e F F	8305040487 6305040492 8305040493 8305040497 8305040498	8305020007 8305040479 8305040483 8305040491 8305040479	83/01/11 83/04/28 83/05/02 83/05/02 83/04/28	50-220 50-346	0 P P
8305040093 8305040103 8305040105 8305040108 8305040110	8305020007 8305020007 8305040096 8305040095 8305040096	83/01/11 83/01/11 83/04/25 83/04/18 83/04/25	FOIA FOIA 71-9181 50-331 71-9181	Р	8303040300 8303040501 8305040502 8305040503 8305040510	8305040483 8305020007 8305020007 8305040491 8305020007	83/05/02 83/01/11 83/01/11 83/05/02 83/01/11	FOIA FOIA	P
8305040114 8305040115 8305040120 8305040122 8305040123	8305020007 8305040095 8305020007 8305040117 8305040117	83/01/11 83/04/18 83/01/11 83/04/19 83/04/19	F01A 50-331 F01A 50-205 50-305	P Q G	8305040514 8308040515 8305040516 8305040517 8305040519	9305040509 8305040507 9305040504 8305040511 8305020007	83/04/22 83/04/26 83/05/02 83/04/28 83/01/11	50-445 50-440	E T T P
8305040127 8305040145 8305040150 8305040158 8305040159	8305020007 8305040138 8305040146 8305020007 8305040147	83/01/11 83/04/20 83/04/25 83/01/11 83/04/25	FOIA 50-289 50-318 FOIA 71-9079	U S	8305040522 8305040523 8305040524 8305040536 8305040536	8305040518 8305020007 8305040520 8305040534 8305040534	83/04/20 83/01/11 83/05/02 83/05/03 83/05/03	FOIA	G P G G
8305040165 8305040175 8305040176 8305040183 8305040189	8305020007 8305020007 8305040147 8305020007 8305020007	83/01/11 83/01/11 83/04/25 83/01/11 83/01/11	FOIA FOIA 71-9079 FOIA FOIA		8303040539 8305040540 8305040542 8305040543 8305040545	8305040534 8305040534 8305040534 8305040534 8305040534	83/05/03 83/05/03 83/05/03 83/05/03 83/05/03	50-155 50-155 50-155 50-155 50-155	00000
8305040200 8305040211 8305040217 8305040224 8305040234	8305020007 8305020007 8305020007 8305020007 8305020007	83/01/11 83/01/11 83/01/11 83/01/11	FOIA FOIA FOIA FOIA		8305040553 8305040554 8305040555 8305040556 8305040559	8305040552 8305020007 8305040551 8305020007 8305020007	83/04/25 83/01/11 83/05/02 83/01/11 83/01/11	CONTRACT FOIA 50-237 FOIA FOIA	P
8305040239 8305040240 8305040242 8305040244 8305040246	8305020007 8305040229 8305040235 9305020007 8305040229	83/01/11 83/05/02 83/04/22 83/01/11 83/05/02	FDIA 50-369 50-3 FOIA 50-369	8 F	8303040560 8305040561 8305040566 8305040566 8305040567	8305040557 8305040558 8305020007 8305040563 8305040558	83/05/03 83/04/14 83/01/11 83/04/12 83/04/14	50-445 XPORTLIC FOIA 50-335 XPORTLIC	Ģ F
8305040247 8305040249 8305040250 8305040254 8305040254	8305040235 8305040235 8305020007 8305040235 8305020007	83/04/22 83/04/22 83/01/11 83/04/22 83/01/11	50-3 50-3 FOIA 50-3 FOIA	F F	8305040568 8305040569 8305040578 8305040578 8305040579	8305040564 8305020007 8305020007 8305020007 8305020007	83/04/28 83/01/11 83/01/11 83/01/11 83/01/11	50-269 F01A F01A F01A F01A	P
8305040240 8305040245 8305040246 8305040248 8305040272	8305040227 8305040257 8305020007 8305040259 8305020007	83/05/02 83/04/25 83/01/11 83/04/25 83/01/11	50-369 50-315 FOIA 50-315 FDIA	S F	8305040580 8305040583 8305040586 8305040587 8305040588	8305040575 8305020007 8305020007 8305020007 8305040565	B3/04/25 83/01/11 83/01/11 83/01/11 83/04/26	50-320 70-378 70-378 70-378 TOPREP	F
8305040279 8305040284 8305040287 8305040290 8305040294	8305020007 8305040280 9305020007 8305020007 9305020007	83/01/11 83/04/25 83/01/11 83/01/11	FOIA CONTRACT FOIA FOIA FOIA		8305040573 8305040597 8305040599 8305040603 8305040606	8305020007 8305040584 8305020007 8305020007 8305040584	83/01/11 83/04/26 83/01/11 83/01/11 83/04/26	70-378 50-369 70-378 70-378 50-369	F
8305040297 8305040310 8305040328 8305040345 8305040363	8305020007 8305020007 8305040320 8305040341 8305040354	83/01/11 83/01/11 83/05/02 83/04/28 83/04/25	F01A F01A 50-275 CONTRACT 50-315	P	8305040613 8305040619 8305040624 8305040624 8305040633	8305040545 8305040614 8305040614 8305040621 8305040628	83/04/25 83/04/25 83/04/25 83/04/26 83/04/26	TOPREP 50-285 50-285 50-334 50-259	4 4 4
8305040346 8305040371 8305040374 8305040376 8305040380	8305020007 8305040365 8305040354 8305020007 8305020007	83/01/11 83/04/19 83/04/25 83/01/11 83/01/11	FOIA 50-373 50-315 FOIA FOIA	R P	8305040643 8305040654 8305040655 8305040659 8305040660	8305040635 8305040648 8305040628 8305040648 8305040650	83/04/21 83/04/25 83/04/26 83/04/25 83/04/29	CONTRACT 50-321 50-259 50-321 CONTRACT	++
8305040382 8305040387 8305040392 8305040403 8305040408	8305040354 8305020007 8305020007 8305020007 8305020007	93/04/25 93/01/11 93/01/11 93/01/11 93/01/11	50-315 FOIA FOIA FOIA FOIA	P	8305040674 8305040678 8305040677 8305040687 8303040696	8305020007 8305020007 8305040671 8305020007 8305020007	83/01/11 83/01/11 83/04/13 83/01/11 83/01/11	70-378 70-378 71-495 70-378 70-378	
8305040414 8305040421 8305040425 8305040434 8305040438	8305020007 8305040412 8305020007 8305040424 8305040424	83/01/11 83/05/03 83/01/11 83/04/29 83/04/29	F01A 50-400 F01A 50-333 50-333	G P	8305040737 8305040745 8305040785 8305040787 8305040790	8305040730 8305040730 8305040780 8305040783 8305040780	83/04/22 83/04/22 83/04/25 83/04/21 83/04/25	50-259 50-259 50-322 50-317 50-322	P G P
8305040450 8305040456 8305040459 8305040466 8305040468	8305020007 8305040446 8305040453 8305040458 8305020007	83/01/11 83/05/02 83/04/29 83/04/11 83/01/11	FOIA 50-237 50-313 TOPREP 70-378	P R	8305040793 8303040795 8305050010 8305050010	9305040783 9305040793 9305050001 9305050004 9305050008	83/04/21 83/04/21 83/05/02 83/05/03 82/12/30	50-317 50-317 50-322 50-341 50-413	PGAA
8305040473 8305040478 8305040480 8305040484 8305040485	8305040320 8305020007 8305040472 8305020007 8305040479	83/05/02 83/01/11 83/05/02 83/01/11 83/04/28	50-275 FOIA 50-344 FOIA 50-400	P P Q	8305050028 8305050027 8305050029 8305050033	8305050016 8305050021 8305050024 8305050020 8305050021	83/04/27 83/05/04 83/05/02 83/05/02 83/05/04	50-302 50-277 50-322 50-220 50-277	8 P P P

ACCESSION					ACCESS I	IN NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC	
B305050040 B305050041 B305050071 B305050076 B3050500B7	8305050030 8305050057 8305050069 8305050073 8305050083	83/04/21 83/04/29 83/04/21 83/04/21 83/04/21	50-321 50-395 GA999 50-286 50-321	5 8 F	8305050316 8305050317 8305050319 8305050321 8305050322	8305020007 83050505031 8305020007 8305050311 8305020007	83/01/11 83/04/25 83/01/11 83/04/25 83/01/11	70-378 50-379 70-378 50-375 70-378	F
830505090 830505091 8305050093 8305050097 8305050104	8305050088 8305050088 8305050088 8305050094 8305050102	83/04/21 83/04/21 83/04/21 83/04/19 83/04/21	0A779 0A779 0A777 0A777 0A777		8305050326 8305050328 8305050330 8305050333 8305050335	8305020007 8305020007 8305020007 8305020007 8305020007	63/01/11 63/01/11 63/01/11 63/01/11 63/01/11	70-378 70-378 70-378 70-378 70-378	
8305050108 8305050110 8305050111 8305050115 8305050117	8305050101 9305050102 8305050107 8305050114 8305050114	83/04/25 83/04/21 83/04/13 83/04/13 83/04/13	50-271 04999 04999 04999 04999	8	8305050337 8305050339 8305050342 8305050349	8305020007 8305020007 8305020007 8305020007	83/01/11 83/01/11 83/01/11 83/01/11	70-378 70-378 FOIA FOIA FOIA	
8305050117 8305050121 8305050128 8305050130 8305050138	8305050116 8305050118 8305050123 8305050118 8305050127	83/04/01 83/04/27 83/04/29 83/04/27 83/04/28	50-443 50-281 50-327 50-281 50-335	0 8 8 8	8305050351 8305050353 8305050355 8305050355 8305050361	8305020007 8305050341 8305020007 8305020007 8305020007	83/01/11 83/04/13 83/01/11 93/01/11 83/01/11	F01A 50-269 F01A F01A F01A	5
8305050140 8305050147 8305050149 8305050151 8305050154	8305050134 8305050141 8305050145 8305050144 8305050148	83/04/21 83/04/21 83/04/19 83/04/20 83/04/27	70-1402 50-277 GA979 50-293 50-348	0 9 8	8305050363 8305050373 8305050381 8305050389 8305050404	8305020007 8305050366 8305050377 8305050385 8305050400	83/01/11 83/04/25 83/04/25 83/04/26 83/03/28	FDIA 50-387 50-320 CONTRACT	
8305050158 8305050163 8305050164 8305050166 8305050167	8305050148 8305050157 8305050159 830505016£ 8305050162	83/04/27 83/04/21 83/05/03 83/04/20 83/04/21	50-348 50-458 50-397 40-3079 0A999	6 0	9305040007 9305060034 9305060046 9305060048	B305060001 B305060023 B305060043 B305060043 B305060042	83/04/25 83/04/25 83/05/03 83/05/03	50~266 50~282 50~220 50~220 50~307	P P P P
8305050171 8305050175 8305050178 8305050179 8305050180	8305050162 8305050172 8305050167 8305050162 8305050172	83/04/21 83/04/20 83/04/28 83/04/21 83/04/20	0A999 50-334 50-414 0A999 50-334	0 8 0	8305040053 8305040064 8305040064 8305040074 8305040084	8305040051 8305040058 8305060040 8305040040	83/04/28 83/04/21 83/05/04 83/05/04 83/04/21	50~321 50~336 50~331 50~331 50~317	5 5 5 F
8305050181 8305050182 8305050184 8305050190 8305050191	8305050177 8305050176 8305050177 8305050187 8305050186	83/04/13 83/04/21 83/04/13 83/04/20 83/04/27	GA979 70-1224 GA999 50-247 50-338	G B	8305040071 8305040117 8305040120 8305040134 8305040140	8305040069 8305060112 8305060109 8305060109	83/04/29 83/03/14 83/04/22 83/04/22 83/04/22	50-285 FOLA 50-338 50-338 50-338	1 9 9
8305050192 8305050203 8305050204 8305050208 8305050215	8305050177 8305050195 8305050183 8305050200 8305050210	83/04/13 83/04/29 83/04/27 83/04/20 83/04/27	9A999 50-348 50-327 TOPREP 50-339	8 9	8305040141 8305040142 8305040145 8305040148 8305040152	8305060135 8305060133 8305060133 8305060133	83/03/03 83/04/25 83/03/03 83/04/25 83/04/25	40-672 71-9175 FOIA 71-9175 71-9175	
8305050217 8305050222 8305050224 8305050225 8305050226	8305050211 8305050214 8305050218 8305050220 8305050217	83/04/29 83/04/19 83/04/27 83/04/25 83/04/15	50-328 50-267 50-328 50-309 0A999	8 8 P	8305060153 8305060154 8305060155 8305060156 8305060160	8305060144 8305060133 8305060144 8305060135 8305060144	83/03/17 83/04/25 83/03/17 83/03/03 83/03/17	FOIA 71-9175 FOIA 40-672 FOIA	
8305050228 8305050230 8305050234 8305050239 8305050241	8305050214 8305050223 8305050223 8305050233	83/04/19 83/04/21 83/04/21 83/04/29 83/04/15	50-267 50-97 50-97 50-395 GA999	9 0 8	8305040164 8305040171 8305040180 8305040181 8305040183	8305060144 8305060144 8305060176 8305060135 8305060174	93/03/17 83/03/17 93/03/02 83/03/03 83/02/25	FOIA FOIA 50-325 40-672 CONTRACT	₽
8305050244 8305050245 8305050248 8305050255 8305050257	8305050242 8305050238 8305050246 8305050251 8305050252	83/04/29 83/04/28 83/04/27 83/04/21 83/04/29	50-324 50-240 50-244 9A779 50-128	8 9 P	6305040169 6305040193 6305040193 6305040200	8305040135 8305040187 8305040135 8305040135 8305040135	63/03/03 63/04/25 63/03/03 63/03/03 63/03/03	40-672 71-6294 40-672 40-672 40-672	
8305050258 8305050261 8305050262 8305050267 8305050268	8305050251 8305050254 8305050251 8305050245 8305050243	83/04/21 83/04/27 83/04/21 83/04/28 83/04/27	GA999 50-416 GA999 50-324 50-29	83 83	8305060212 8305060214 8305060220 8305060228 8305060232	8305040208 8305040135 8305040135 8305040225 8305040225	83/04/21 83/03/03 83/03/03 83/05/03 83/05/03	71-5979 40-672 40-672 50-206 50-206	P
8305050272 8305050274 8305050287 8305050288 8305050289	8305050264 8305050271 8305040323 8305050283 8305050285	83/04/29 83/04/27 83/05/04 83/04/26 83/04/25	50-259 50-339 50-247 50-349 50-387	88 P P F	8305060234 8305060239 8305060251 8305060269 8305060277	8305060225 8305060235 8305060246 8305060261 8305060271	83/05/03 83/04/25 83/04/24 83/04/25 83/04/28	50-206 50-206 CONTRACT 50-334 50-244	P P R P
8305050292 8305050295 8305050297 8305050301 8305050303	9305020007 9305040323 9305020007 9305020007 9305050299	83/01/11 83/05/04 83/01/11 83/01/11 83/05/02	70-378 50-247 70-378 70-378 50-275	e R	8305040279 8305040282 8305040287 8305040288 8305040291	8305040266 8305040130 8305040264 8305040130 8305040266	83/04/22 83/04/27 83/04/22 83/04/27 83/04/22	50-293 50-395 50-293 50-395 50-293	Р Р Р
8305050304 8305050306 8305050307 8305050310 8305050312	8305050300 8305020007 8305050300 8305020007 8305020007	83/04/25 83/01/11 83/04/25 83/01/11 83/01/11	50-289 70-378 50-289 70-378 70-378	F	83050A0293 83050A0293 83050A0308 83050A0308 83050A0312	6305040284 6305040130 8305040298 6305040298 8305040298	83/05/03 83/04/27 83/04/22 83/04/22 83/04/22	50-483 50-395 50-389 50-389 50-389	Q P P P

ACCESSION					ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y	ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8305040325 8305040324 8305040344	8305040319 8305040320 8305040338	83/04/01 83/04/01 83/04/25	HASTE MG CONTRACT 50-482	T	8305060669 8305060670 8305060679	9305060666 9305060666 9305060673	83/04/27 83/04/27 83/04/25	50-344 50-344 50-295	P
8305060351 8305060354	8305060341 8305060338	83/02/23 63/04/25	CONTRACT 50-482		8305040484 8305040494	8305060673 8305060683	83/04/25 83/04/27	50-295 50-361	P
8305060369 8305060381 8305060383	8305060363 8305060372 8305060380	83/03/25 83/05/03 83/05/07	40-8783 50-206 50-298	p I	8305060679 8305060700 8305060702	8305060692 8305060696 8305060692	83/04/25 83/03/28 83/04/25	50-346 10CFR 50-346	F
8305040384 8305040385	9305060379 9305060372	83/04/12 83/05/03	50-329 50-206	A P	8305040703 8305070003	8305060483 8305070001	83/04/27 83/04/21	50-361 GA999	P
8305060391 8305060393	8305060370 8305060388	83/04/27 83/04/29	50-254 50-255	8	9305090012 8305090019	8305090009 8305090014	83/04/29 83/04/15	CONTRACT 50-348	r P
8305060401	8705060398	83/04/28	50-373	S	8305090023 8305090027	8305070014 8305070014	83/04/15	50-348	P
8305060405 8305060406	9305060402 9305060400	83/04/27 83/04/29	50-317 50-315	8	B305070027	8305090016	83/04/15 83/04/15	50-348 50-348	P
8305060407 8305060411	B305060397 B305060400	83/05/03 83/04/29	50-284 50-315	P 6	8305090037 8305090038	8305090029 8305090024	83/04/27 83/03/21	50-2B0 FDIA	Œ
8305060414 8305060417	9305060400 9305060397	83/04/29 83/05/03	50-315 50-286	8 P	8305090043 8305090047	8305090024 8305090024	83/03/21 83/03/21	FOIA FOIA	
8305060418	8305060410	83/05/03	50~295	a	B305090051	8305090045	83/04/27	50-280	P
8305060421 8305060422	8305060419 8305060416	83/04/19 83/04/26	50-312 50-237	p S	B305070055 B305070056	8305090024 8305090048	83/03/21 83/04/28	FOIA 71-5814	
8305060428	8305060426	83/04/27	50-220	8	8305090057	8305090024	83/03/21	FOIA	
8305060432 8305060433	9305060431 9305060431	83/05/03 83/05/03	50-286 50-286	P	8305090058 8305090060	8305090050 8305090052	83/04/29 83/04/29	CONTRACT 50-329	R
B305060440	B305060431	E0/60/68	20-567	P	8305070062	8305070032	83/04/27	50-280	P
P205060444	8305040443	83/04/08	50-295	5	B305090070	8305090045	83/04/27	50-280	P
8303060446 8303060447	8305060427 8305060427	83/05/03 83/05/03	50-286 50-286	P	8305090073 8305090091	8305070066	83/05/04 83/04/26	50-128 50-250	G G
8305060450 8305060454	8305060448 8305060452	83/03/31 83/04/25	50-362 50-313	8	8305090104 8305090111	8305090085 8305090078	83/04/26 83/04/15	50-250 50-269	Q P
B305060460	B305060458	83/04/29	50-289	R	8305090117	B305090068	83/04/29	CONTRACT	
8305060464 8305060465	8305040458 8305040458	83/04/29 83/04/29	50-289 50-289	R	8305090121 8305090124	8305090113 8305090078	83/04/28	71-5980 50-269	Р
8305060482	8305060476	83/04/28	50-272	8	8303070124	8305070122	83/04/15 83/04/28	CONTRACT	
8305060484 8305060489	8305060479 8305060480	83/04/28 83/04/29	50-247 50-311	5	8305090136 8305090138	9305090129 9305090078	83/05/05 83/04/15	50-322 50-269	Ç P
8305060492	8305060486	83/04/29	50-237	8	8305090140	8305090133	83/04/28	71-5875	
8305040503 8305060509	8305060494 8305060493	83/04/28 83/04/27	50-309 50-373	8	8305090149 8305090150	8305090144 8305090145	83/04/20 83/04/28	50-338 71 - 5874	þ
8305060512 8305060514	6305060501	83/04/29 83/04/08	50-245	8	8305090154 8305090160	8305090147 8305090147	83/04/18	50-313	p
8305060517	8305060505 8305060511	63/04/25	50-361 50-237	8	6305090179	8305090147	83/04/18 83/04/18	50-313 50-313	P
8305060523 8305060536	8305060519 8305060529	83/04/29 83/04/26	50-346 50-352	Q A	8305090197 8305090202	8305090186 8305090212	83/04/26 83/04/29	50-331 PROJ	F
8305060540	8305040533	B3/04/27	50-220	s	8305090228	8305090217	B3/04/28	TOPREP	
8305060544	83030A052B	83/04/29	50-295	8	8305090255	8305090244	83/04/29	50-272	8
B305060549 B305060552	8305060538 8305060546	83/04/25 83/04/13	50-309 50-267	8	8305070270 8305070300	8305090279 8305090291	83/05/02 83/05/03	MIBC CONTRACT	
8305040553	8305060548	83/04/26	50-333	F	8305090313	8305090306	83/03/22	50-373	G
8305060554 8305060557	9305060542 9305060549	83/05/03 83/04/26	50-373 50-333	g F	8305090315 8305090327	8305090279 8305090321	83/05/02 83/04/26	MISC 50-280	P
B305060559	8305060547	83/05/02	50-456	G	8305090331	B305090321	B3/04/26	50-280	P
8305060561 8305060568	8305060556 8305060562	83/05/02 83/04/28	50-280 50-447	E	8305090335 8305090372	8305090321 8305090338	83/04/26 83/05/03	50~280 50~470	P
8305040549	8303060542	83/05/03	50-373	0	8305070388	8305090371	83/05/04	GA999	
8305060571 8305060572	8305060563 83 0 3060567	83/04/22 83/04/29	50-249 50-295	8	8305070373 8305090398	8305090388	83/04/20 83/04/20	94994 94999	
8305040582	6305060577	83/02/28	50-238	R	6305090403	8305090392	83/04/20	QA999	
8305060583 8305060584	8305060575 8305060574	83/04/25 83/04/29	50-313 50-298	F S	8305090404 8305090413	8305090386 8305090386	83/04/20 83/04/20	QA999 QA999	
8305060586	8305060577	83/02/28	90-23B	R	8305090418	9305090409	83/05/06	50-390	ā
8305060571 8305060574	8305060575 8305060581	83/04/25 83/03/25	50-313 50-249	8	8305090436 8305090442	8305090426 8305090426	83/05/05 83/05/05	50-245 50-245	P
8305060598	8305060592	83/04/29	50-387	s	8305070459	8305090457	83/05/04	50-272	P
8305060599 8305060601	8305060590 8305060595	83/04/27 83/04/25	50-237 50-346	8 F	8305090460 8305090461	8305090426 8305090454	83/05/05 83/05/06	50-245 50-395	P
8305060606	9305060600	B3/05/02	50-344	P	8305090463	8305090426	B3/05/05	50-245	₽
8305060408 8305060409	8305060575 8305060 6 04	93/04/25 93/04/28	50-346 50-334	b E	8305090464 8305090469	8305090462 8305090467	83/04/29 83/04/29	50-302 TOPREP	P
8305060611 8305060613	8305060603 8305060577	83/04/27 83/02/28	50~237 50~238	8 8	B305090474 B305090482	8305090471 8305090479	83/05/02 83/04/20	50-245 QA999	P
8205060614	8305060604	83/04/28	50-334	P	8305070485	8305090479	B3/04/20 B3/04/20	0A999	
8305060621 8305060626	6305060616 6305060616	83/04/26 83/04/26	50~348 50~348	F	8305090490 8305090491	9305090487 9305090486	83/05/06 83/05/02	50-440 50-213	Ģ
8305060629	8305060506	B3/05/04	50-247	G	E305090492	8305090488	83/05/02	50-213	p
8305040431 8305040434	8305060627 8305060623	83/04/25 83/05/03	50-317 40-8202	F	E305070493 E303090495	8305090487 8305090483	83/05/06	50-440 TOPREP	0
8305060635	8305060627	83/04/25	50-317	F	8305090497	8305070483	83/05/04	TOPREP	
8305060663	8305060658	B3/04/22	50-280	P	8305090502	0305090501	83/05/02	50-443	Q

ACCESSION						ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEGO	
8305090510 8305090513 8305090516 8305090517 8305090521	8305070507 8305090507 8305090512 8305090507 8305090507	83/05/05 83/05/05 83/05/05 83/05/05 83/05/05	50-445 50-445 100FR 50-445 50-445	T T T	8305100271 8305100273 8305100275 8305100275 8305100281	8305100262 8305100268 8305100272 8305100269	83/04/20 83/05/06 83/05/06 83/04/29 83/05/02 83/05/04	50-275 50-334 50-220 50-389 50-352	G G R R
8305090525 8305090530 8305090545 8305090549 8305090557	8305090507 8305090507 8305090542 8305090542 8305090554	83/05/05 83/05/05 83/03/17 83/03/17 83/04/13	50~445 50~445 50~358 50~358 TOPREP	T A T	8305100297 8305100297 8305100297 8305100297	8305100282 8305100279 8305100285	B3/05/D5 B3/05/04 B3/05/05 B3/05/04 B3/05/04	50-255 50-413 50-255 50-260 50-413	P O P B O
8305090561 8305090565 8305090578 8305090586 8305090589	8305090542 8305090489 8305090568 8305090564 8305090584	83/03/17 83/04/25 83/05/05 83/05/05	50~358 50~267 50~445 50~445 50~302	A R G G G	8305100307 8305100307 8305100317 8305100335 8305100345	8305100303 8305100308 8305100331	83/05/04 83/04/05 83/05/05 83/04/14 83/05/04	50-413 50-482 50-387 50-213 06999	G P P
8305090592 8305090600 8305090607 8305090612 8305090614	8305090548 8305090548 8305090548 8305090529	83/05/05 83/05/05 83/05/05 83/04/27 83/03/10	50-445 50-445 50-445 50-269 50-443	4000	8305100349 8305100335 8305100355 8305100365	8305100348 8305100334 8305100348	83/05/04 83/04/14 83/05/04 83/04/14 83/05/06	0A999 50-313 0A999 50-313 50-156	0 0
8305090418 8305090425 8305090432 8305090440 8305090446	8305090568 8305090568 8305090568 8305090568 830509058	83/05/05 83/05/05 83/05/05 83/05/05 83/05/05	50-445 50-445 50-445 50-445 50-445	00000	8305100347 8305100370 8305100371 8305100372 8305100373	8305100362 8305100363 8305100364	83/05/04 83/05/06 83/05/04 83/05/04 83/03/21	50-438 50-325 50-156 50-331 50-443	A p 0 0
8303090648 8303090650 8303090652 8303090654 8303090660	8305070548 8305070548 8305070543 8305070568 8305070568	83/05/02 83/05/05 83/05/02 83/05/05 83/05/05	50-410 50-445 50-410 50-445 50-445	4 G 4 O O	8305100382 8305100384 8305100387 8305100390 8305100392	8305100378 8305100379 8305100383	83/05/04 83/04/27 83/04/22 83/05/04 83/03/21	50-438 50-255 50-237 50-349 50-443	A S G P
8305090726 8305090731 8305100003 8305100009 8305100014	8305090722 8305090730 8305100002 8305100004 8305100012	83/05/02 83/05/03 83/04/26 83/04/11 83/05/04	50-445 XPORTLIC 50-369 50-192 50-259	A 9 0 8	8305100393 8305100395 8305100397 8305100397 8305100400	8305100388 8305100358 8305100389 8305100356	83/05/04 83/05/04 83/05/03 83/05/04 83/03/21	50-341 50-438 50-305 50-341 50-443	G A B G
8305100019 8305100021 8305100029 8305100036 8305100082	8305100016 8305100016 8305100023 8305100031 8305100080	83/05/04 83/05/04 83/04/29 83/05/04 83/04/22	50-387 50-387 50-339 50-240 50-346	P 8 8 0	8305100402 8305100403 8305100410 8305100411	8305100379 8305100376 8305100404 8305100405 6305100356	83/04/22 83/04/27 83/04/07 83/04/25 83/03/21	50-237 50-255 50-135 50-286 50-443	8 9 9 9
8305100083 8305100084 8305100085 8305100090 8305100091	8305100081 8305100080 8305100074 8305100080 8305100089	83/05/03 83/04/22 83/04/27 83/04/22 83/05/02	50-259 50-346 50-255 50-346 50-395	8 Q R G 6	8305100414 8305100416 8305100417 8305100417 8305100424	8305100404 8305100379 8305100412 8305100356 8305100356	83/04/07 83/04/22 83/05/05 83/03/21 83/03/21	50-155 50-237 50-324 50-443 50-443	0 0 R 0 0
8305100109 8305100111 8305100113 8305100116 8305100120	8305100100 8305100108 8305100107 8305100112 8305100115	83/05/05 83/05/04 83/05/03 83/04/12 83/05/03	50-324 50-280 50-296 50-482 50-280	9 9 8	8305100425 8305100428 8305100429 8305100430 8305100431	9305100356 8305100427 8305100356 8305100356 8305100427	83/03/21 83/04/25 83/03/21 83/03/21 83/04/25	50-443 50-247 50-443 50-443 50-247	00000
8305100126 8305100127 8305100131 8305100135 8305100136	8305100122 8305100130 8305100130 8305100122	83/04/08 83/05/03 83/04/08 83/05/06 83/04/08	50-295 50-280 50-295 50-445 50-295	F 8 8 8	8305100432 8305100433 8305110008 8305110013 8305110020	8305100356 8305100427 8305110005 8305110011 8305110010	83/03/21 83/04/25 83/05/03 83/05/03 83/03/15	50-443 50-247 CONTRACT 71-9103 50-29	6 0 F
8305100139 8305100141 8305100142 8305100144 8305100155	8305100132 8305100124 8305100137 8305100138 8305100151	83/05/03 83/03/25 83/04/11 83/04/29 83/04/22	50-364 50-329 50-458 50-293 50-482	S T G R G	8305110029 8305110030 8305110035 8305110039 8305110041	8305110024 8305110024 8305110033 8305110037 8305110031	83/04/19 83/04/19 83/05/04 83/05/03 83/04/29	NUREO NUREO 71-9901 50-331 CONTRACT	P
8305100160 8305100164 8305100174 8305100179 8305100185	8305100151 8305100158 8305100172 8305100173 8305100173	83/04/22 83/04/20 83/05/09 83/05/04 83/05/04	50-482 50-443 50-454 50-275 50-275	Q Q R R	B305110043 B305110043 B305110052 B305110055 B305110055	8305110037 8305110037 8305110030 8305110030 8305110030	83/05/03 83/05/03 83/04/29 83/04/29 83/04/29	50-331 50-331 50-305 50-305 50-305	P P P P
8305100190 8305100193 8305100216 8305100218 8305100221	8305100181 8305100189 8305100215 8305100215 8305100219	83/05/03 83/05/05 83/04/18 83/04/18 83/04/20	50-10 50-518 50-331 50-331 50-443	G A G Q	8305110058 8305110063 8305110071 8305110089 8305110104	8305110053 8305110053 8305110069 8305110082 8305110097	83/05/05 83/05/05 83/03/09 83/05/03 83/05/05	50-213 50-373	PFFK
8305100225 8305100237 8305100242 8305100244 8305100245	8305100224 8305100238 8305100241 8305100241 8305100243	83/05/06 83/04/01 83/04/22 83/04/22 83/03/18	50-322 50-322 50-285 50-285 50-329	0 0 0 T	8305110108 8305110132 8305110151 8305110152 8305110154	8305110097 8305110128 8305110150 8305110146 8305110154	83/05/05 83/04/26 83/05/06 83/05/03 83/04/27	50-335 71-9100 CONTRACT	K P
8305100248 8305100249 8305100253 8305100265 8305100266	8305100243 8305100247 8305100251 8305100259 8305100262	93/03/18 93/04/13 93/05/02 83/04/29 93/04/20	50-329 50-445 50-251 50-339 50-295	T 0 8 8	8305110143 8305110149 8305110173 8305110173 8305110174	8305110159 8305110165 8305110165 8305110171 8305110165	83/04/26 83/05/03 83/05/03 83/05/03 83/05/03	50~348 50-373	P P P

ACCESSION					N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEODRY
8305110182 8305110184 8305110187 8305110188 8305110192	8305110179 8305110179 8305110181 8305110179 8305110190	63/04/25 83/04/25 63/05/04 63/04/25 83/04/25	50-361 P 50-361 P 50-364 P 50-361 P CONTRACT	8305110443 8305110447 8305110452 8305110455 8305110465	8305110437 8305110445 8305110447 8305110450 8305110453	83/05/06 83/05/10 83/05/05 83/05/10 83/05/05	50-346 P 50-537 9 50-373 R 50-537 9 50-339 8
8305110198 8305110199 8305110205 8305110224 8305110228	B305110194 B305110193 B305110193 B305110219 B305110219	83/05/03 83/04/29 83/04/29 83/05/05 83/05/05	CONTRACT 50-313 P 50-313 P 50-336 P 50-336 P	8305110485 8305110493 8305110496 8305110508 8305110509	8305110415 8305110415 8305110487 8305110501 8305110504	83/05/10 83/05/10 83/05/03 83/04/26 83/04/15	REVIEW GRP SO-250 B 50-333 G CONTRACT
8305110230 8305110232 8305110234 8305110236 8305110242	8305110219 8305110229 8305110100 8305110233 8305110100	83/05/05 83/05/05 83/04/29 83/04/29 83/04/29	50-336 P CONTRACT 50-331 P CONTRACT 50-331 P	8305110514 8305110542 8305110543 8305110545 8305110545	8305110510 8305110540 8305110538 8305110539 8305110538	83/04/27 83/04/28 83/04/21 83/04/14 83/04/21	50-333 8 50-266 F 50-286 F CONTRACT 50-286 F
B305110243 B305110247 B305110249 B205110250 B305110253	8305110100 8305110241 8305110246 8305110246 8305110246	83/04/29 83/04/22 83/05/03 83/05/03 83/05/03	50-331 P 50-387 6 50-327 P 50-327 P 50-327 P	8305110556 8305110560 8305110566 8305110574 8305110579	8305110549 8305110549 8305110549 8305110569 8305110569	83/04/25 83/04/25 83/04/25 83/04/26 83/04/26	50-331 P 50-331 P 50-331 P 50-213 F 50-213 F
8305110254 8305110260 8305110264 8305110265 8305110267	8305110251 8305110257 8305110259 8305110261 8305110261	83/05/06 83/05/05 83/04/21 83/04/29 83/04/29	50~261 8 50~364 9 50~333 8 50~277 0	8305110581 8305110584 8305110401 8305110414 8305110424	8305230324 8305240155 8305240155 8305110612 8305110625	83/05/05 83/04/22 83/04/22 83/05/06 83/04/27	PR COMMISSION COMMISSION 71-9788 50-313 P
8305110272 8305110273 8305110274 8305110277 8305110279	8305110269 8305110270 8305110271 8305110276 8305110275	83/04/26 83/04/26 83/04/26 83/04/27 83/04/29	50-321 S 50-321 S 50-311 S 50-317 Q 50-416 S	8305120014 8305120016 8305120016 8305120023 8305120035	8305120010 8305120010 8305120010 8305120010	83/03/21 83/05/09 83/03/21 83/03/21 83/03/21	FOIA 50-295 R FDIA FOIA FOIA
8305110283 8305110284 8305110287 8305110288 8305110293	8305110281 8305110282 8305110286 8305110285 8305110289	83/04/29 83/05/04 83/04/29 83/05/05 83/05/03	50-369 8 50-325 8 50-287 8 50-338 8 50-321 8	8305120041 8305120045 8305120052 8305120052 8305120062	8305120010 8305120010 8305120010	83/03/21 83/03/21 83/03/21 83/03/21	FOIA FOIA FOIA FOIA
8305110307 8305110310 8305110311 8305110320 8305110326	8305110302 8305110302 8305110308 8305110314 8305110321	83/05/02 83/05/02 83/05/03 83/04/27 83/04/28	50-3 R 50-3 R 50-348 P 50-309 Q 50-320 S	8305120064 8305120065 8305120067 8305120068 8305120072	9305120055 9305120010 9305120057 9305120055 9305120057	83/05/06 83/03/21 83/05/03 83/05/06 83/05/03	50-289 P FOIA 50-70 P 50-289 P 50-70 P
8305110328 8305110329 8305110335 8305110336 8305110338	9305110318 9305110325 9305110323 9305110330 9305110331	83/04/25 83/05/05 83/04/29 83/05/05 83/04/29	50-244 S 50-327 S 50-270 S 50-339 S 50-287 Q	8305120074 8305120078 8305120076 8305120076 8305120097	8305120070 8305120057 8305120085 8305120089 8305120085	83/03/21 83/05/03 83/05/05 83/05/03 83/05/05	50-358 0 50-70 P 50-275 P 50-73 P 50-275 P
8305110341 8305110342 8305110349 8305110351 8305110353	8305110334 8305110333 8305110340 8305110344 8305110343	B3/04/25 B3/04/29 B3/04/21 B3/04/25 B3/04/25	50-273	8305120100 8305120124 8305120130 8305120133 8305120135	8305120089 8305120120 8305120142 8305120144 8305120145	83/05/03 83/05/10 83/05/03 83/05/03 83/04/11	50-79 P 50-470 B CONTRACT 50-335 P 50-445 G
8305110358 8305110357 8305110363 8305110365 8305110367	8305110348 8305110315 8305110352 8305110356 8305110355	83/04/25 83/05/05 83/04/27 83/04/25 83/05/06	50-387 8 50-410 C 50-317 S 50-293 8 50-259 S	8305120140 8305120149 8305120171 8305120180 8305120187	830512014A 8305120143 830512014A 8305120163 8305120163	83/05/03 83/04/26 83/05/03 83/04/26 83/04/26	50-335 P 50-273 P 50-335 P 50-273 P 50-273 P
8305110372 8305110376 8305110377 8305110378 8305110382	8305110315 8305110369 8305110360 8305110370 8305110373	83/05/05 83/04/28 83/05/02 83/04/25 83/05/05	50-410 K 50-333 0 50-334 P 50-320 S 50-327 S	8305120211 8305120214 8305120234 8305120236 8305120240	8305120203 8305120203 8305120224 8305120233 8305120224	83/05/09 83/05/09 83/03/01 83/03/15 83/03/01	50-275 R 50-275 R 40-672 50-397 K 40-672
8305110390 8305110391 8305110392 8305110395	8305110375 8305110380 8305110369 8305110384 8305110388	83/04/26 83/05/02 83/04/28 83/04/25 83/04/29	50-366 8 50-302 8 50-333 0 50-293 8 50-225 0	8305120246 8305120250 8305120251 8305120252 8305120252	8305120224 8305120244 8305120224 8305120224 8305120224	83/03/01 83/05/09 83/03/01 83/05/03 83/03/01	40-672 50-281 P 10-672 50-336 P 40-672
8305110398 8305110402 8305110403 8305110408 8305110412	8305110360 8305110376 8305110373 8305110400 8305110404	83/05/02 83/05/05 83/04/27 83/04/25 83/04/29	50-334 P 50-255 R 50-247 B 50-339 B 50-321 S	8305120240 8305120244 8305120268 8305120267 8305120274	8305120224 8305120224 8305120224 8305120224 8305120224	83/03/01 83/03/01 83/03/01 83/03/01	40-672 40-672 40-672 70-82 40-672
8305110416 8305110417 8305110419 8305110423 8305110428	8305110405 8305110410 8305110409 8305110415 8305110415	83/04/21 83/04/28 83/05/06 83/05/10	50-333 8 50-366 8 50-328 8 REVIEW GRP REVIEW GRP	8305120279 8305120280 8305120283 8305120284 8305120289	8305120224 8305120278 8305120224 8305120224 8305120224	83/03/01 83/05/09 83/03/01 83/03/01 83/03/01	40-672 50-352 <i>G</i> 40-672 40-672 40-672
8305110430 8305110432 8305110433 8305110434 8305110434	8305110421 8305110415 8305110425 8305110429 8305110429	83/04/28 83/05/10 83/05/03 83/04/26 83/04/28	50-387 B REVIEW GRP 50-309 S 50-321 S 50-346 S	8305120294 8305120296 8305120300 8305120300	8305120224 8305120224 8305120277 8305120224 8305120301	83/03/01 83/03/01 83/05/09 83/03/01 83/05/06	40-672 40-672 50-322 @ 40-672 50-322 @

ACCESS10	NUMBER					SION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEGO		ENCLOSUR	PRINCIPAL	DATE 188UED	SUBJECT CATEGOR	٩Y
8305120307 9305120310 9305120311 8305120316 8305120317	8305120224 8305120224 8305120301 8305120224 8305120312	83/03/01 83/03/01 83/05/06 83/03/01 83/05/06	40-672 40-672 50-322 40-672 50-320	 G 7	#3051205 #3051205 #3051205 #3051205 #3051205	11 8305120224 12 8305120504 14 8305120224 15 8305120224	83/03/01 83/05/03 83/03/01 83/03/01 83/03/03	40-672 50-313 40-672 40-672 CONTRACT	P
8305120323 8305120324 8305120326 8305120330 8305120332	8305120312 8305120318 8305120312 8305120312	83/05/04 83/05/04 83/05/06 83/05/06 83/05/09	50-320 50-316 50-320 50-320 50-322	T S T T	83051205 83051205 83051205 83051205 83051205	19 8305120224 23 8305120224 27 8305120224	83/03/01 83/03/01 83/03/01 83/03/01	40-672 40-672 40-672 40-672 40-672	
8305120338 8305120338 8305120339 8305120341 8305120344	8302150315 8302150315 8302150315 8302150315	83/05/06 83/05/06 83/05/10 83/05/06 83/05/06	50-320 50-320 50-275 50-320 50-320	T P T T	83051205 83051205 83051205 83051205 83051205	37 8305120524 40 8305120224 44 8305120524	83/03/30 83/03/30 83/03/01 83/03/30 83/05/06	50-128 50-128 40-672 50-128 CONTRACT	P P
8305120347 8305120348 8305120350 8305120352 8305120353	8305120312 8305120345 8305120312 8305120224 8305120346	83/05/06 83/04/27 83/05/06 83/03/01 83/03/16	50-320 50-461 50-320 40-672 50-374	r a T	83051205 83051205 83051205 83051205	78 8305120564 95 8305120580 97 8305120580	83/05/02 83/05/05 83/05/05 83/05/05	50-267 50-267 50-373 50-373 50-373	****
8305120355 8305120354 8305120357 8305120359 8305120364	8305120312 8305120224 8305120312 8305120224 8305120361	83/03/01 83/03/01 83/03/04 83/03/01 83/04/26	50-320 40-672 50-320 40-672 50-374	T G	83051206 83051206 83051206 83051206	03 0305120594 04 8305120598 09 8305120224	83/03/01 83/05/02 83/05/03 83/03/01 83/04/28	40-672 50-285 50-250 40-672 MISC	F G
8305120349 8305120349 8305120372 8305120374 8305120376	8305120361 8305120224 8305120224 8305120370 8305120224	83/04/26 83/03/01 83/03/01 83/05/11	50-374 40-672 40-672 50-237 40-672	Gi P	83051206 83051206 83051206 83051206 83051206	17 8305120224 20 8305120224 21 8305120611	83/03/01 83/03/01 83/03/01 83/05/04 83/03/01	F01A F01A 40-672 50-275 40-672	þ
8305120380 8305120381 8305120397 8305120399 8305120404	8305120378 8305120224 8305120394 8305120396 8305120392	83/03/03 83/03/01 83/02/09 83/05/04 83/04/26	50-322 70-82 GA999 50-315 50-410	G S S	83051 206: 83051 206: 83051 206: 83051 206: 83051 206:	30 8305120224 33 8305120224 42 8305120224	83/03/01 83/03/01 83/03/01 83/03/01	40-672 40-672 40-672 40-672 70-925	
8305120411 8305120418 8305120420 8305120423 8305120423	8305120402 8305120414 8305120415 8305120419 8305120421	83/05/02 83/05/02 83/04/27 83/04/25 83/05/04	50-334 50-313 50-373 50-546 50-309	8 9 0 F	83051300 83051300 83051300 83051300	11 8305120224 16 8305120224 17 8305130010	83/03/01 83/03/01 83/03/01 83/05/04 83/05/11	40~672 40~672 40~672 50~338 50~445	P G
8305120427 8305120428 8305120430 8305120437 8305120439	8305120421 8305120419 8305120422 8305120429 8305120433	83/05/04 83/04/25 83/04/21 83/04/29 83/04/29	50-309 50-344 50-387 50-358 50-298	F 0 8 8 8	83051300/ 83051300/ 83051300/ 83051300/ 83051300/	23 8305130010 24 8305130018 31 8305120224	83/05/09 83/05/04 83/05/09 83/03/01 83/03/01	50-247 50-338 50-247 40-672 40-672	P P
8305120443 8305120444 8305120447 8305120449 8305120450	8305120438 8305120440 8305120498 8305120440 8305120224	89/04/28 83/04/25 83/04/28 83/04/25 83/03/01	50-373 50-237 50-373 50-237 40-672	0 0 0	83051300 83051300 83051300 83051300	92 9305120224 9305130043 9305120224	83/05/11 83/03/01 83/05/09 83/03/01 83/03/01	50-445 40-672 50-302 40-672 40-672	g R
8305120451 8305120454 8305120462 8305120463 8305120466	8305120445 8305120224 8305120224 8305120456 8305120224	83/05/06 83/03/01 83/03/01 83/04/25 83/03/01	50-313 40-672 40-672 50-266 40-672	o o	83051300 83051300 83051300 83051300	74 8305130045 84 8305130084 71 8305130085	83/05/09 83/05/09 83/05/02 83/05/06 83/05/05	50-287 50-289 50-244 50-259 50-346	P P S S
8305120468 8305120470 8305120471 8305120472 8305120474	8305120454 8305120460 8305120465 8305120224 8305120224	83/04/25 83/05/02 83/04/29 83/03/01 83/03/01	50-266 50-397 40-215 FOIA FOIA	E	830513051 830513011 830513011 830513011	04 8305130103 12 8305130109 20 8305130117	83/04/15 83/05/11 83/05/10 83/05/03 83/05/03	50-315 50-271 50-409 50-286 50-286	В 0 Р
8305120476 8305120477 8305120478 8305120480 8305120483	8305120465 8305120460 8305120224 8305120224 8305120224	83/04/29 83/05/02 83/03/01 83/03/01	40-215 50-397 40-672 40-672 40-672	E	83051301: 83051301: 83051301: 83051301: 83051301:	34	83/05/04 83/05/07 83/05/10 83/05/06 83/05/05	50-281 50-333 50-454 50-261 50-260	8 9 8
8305120484 8305120485 8305120489 8305120491 8305120493	8305120475 8305120460 8305120224 8305120460 8305120224	83/05/04 83/05/02 83/03/01 83/05/02 83/03/01	50-461 50-397 40-672 50-397 40-672	E E	83051301 83051301 83051301 83051301	8305130140 82 8305130143 8305130149	83/05/10 83/05/09 83/05/09 83/05/11 83/05/05	50-373 50-255 50-344 50-373 50-324	2000
8305120494 8305120498 8305120500 8305120502 8305120503	9305120224 9305120495 9305120495 9305120495 9305120224	83/03/01 83/05/04 83/03/01 83/05/04 83/03/01	40-672 50-266 40-672 50-266 40-672	þ	83051301: 83051301: 83051301: 83051301: 83031301:	76 8305130170 82 8305130171 84 8305130177	83/04/15 83/05/06 83/05/11 83/05/04 83/05/06	50-314 50-324 50-327 50-324 50-302	88059
8305120505 8305120506 8305120507 8305120508 8305120509	8305120495 8305120504 8305120224 8305120504 8305120224	83/05/04 83/05/03 83/03/01 83/05/03 83/03/01	50-266 50-313 40-672 50-313 40-672	P P	83051302 83051302 83051302 83051302	95 8305130190 90 8305130194 91 8305130190	83/05/09 83/05/05 83/05/06 83/05/05 83/05/02	50-315 50-346 50-416 50-346 50-237	8 8 8 R

ACCESSIO					ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGORY	,
8305130203 8305130204 8305130205 8305130211 8305130214	8305130198 8305130090 8305130190 8305130196 8305130208	83/05/06 83/05/10 83/05/05 83/05/10 83/05/09	50-280 50-322 50-346 50-304 50-255	80886	8305160261 8305160271 8305160282 8305160284 8305160285	8305140258 8305140255 8305140279 8305140279 8305140283	83/03/22 83/03/24 83/05/02 83/05/02 83/05/02	50-389 50-389	G F F
8305130220 8305130221 8305130223 8305130230 8305130231	8305130212 8305130215 8305120488 8305130225 8305130219	83/05/03 83/05/04 83/03/25 83/05/09 83/04/28	50-254 50-155 50-271 50-255 50-312	5 0 9 8	83051 60286 83051 60270 83051 60273 83051 60273 83051 60303	8305160283 8305160288 8305160292 8305160292 8305160301	83/05/02 83/05/02 83/05/02 83/05/02	50-313 50-413	FFF
8305130232 8305130233 8305130234 8305130237	8305130224 8305130215 8305130227 8305130215 8305130215	83/05/04 83/05/10 83/05/04 83/05/04	50-344 50-155 70-1308 50-155 50-155	S Q Q	8305160312 8305160312 8305160316 8305160316 8305160340	8305160301 8305160304 8305160304 8305160318 8305160337	83/05/03 83/05/02 83/05/02 83/05/04	50-247 50-367	G 0 A P
8305130242 8305130243 8305130251 8305130261 8305130267	8305130235 8305130228 8305130250 8305130254 8305130258	83/04/28 83/05/06 83/05/10 83/05/03	50-366 50-280 50-305 71-495 50-409	S R Q	8305160341 8305160342 8305160349 8305160351 8305160356	8305160337 8305160337 8305160346 8305160346 8305160346	83/05/04 83/05/04 83/04/26 83/04/26 83/04/26	50~299 50~261 50~261	P P P P
8305130271 8305130294 8305130300 8305130308 8305130309	8305130258 8305130274 8305130279 8305130307 8305130307	83/05/05 83/04/20 83/05/09 83/05/02 83/05/02	50-409 50-269 CONTRACT 50-272 50-272	Q P F	8305160365 8305160366 8305160368 8305160369 8305170007	8305140343 8305140342 8305140342 8305140342 8305170006	83/04/14 83/05/05 83/05/05 83/05/05 83/05/12	50-327 50-327	P P R
8305130311 8305130314 8305130325 8305130333 8305130339	8305130310 8305130310 8305130322 8305130330 8305130335	B3/05/02 B3/05/02 B3/04/22 B3/04/15 B3/04/25	50-387 50-387 40-8752 40-8783 50-443	F	8305170009 8305170014 8305170019 8305170021 8305170022	8305170004 8305170010 8305170015 8305170018 8305170013	83/04/29 83/05/12 83/05/05 83/05/10 83/04/27	50-336 50-311 50-272	Q R P R Q
8305130344 8305130361 8305160014 8305160023 8305160025	8305130343 8305130356 8305160011 8305160018 8305160020	83/05/10 83/05/10 83/05/05 83/05/10 83/05/01	30-382 CONTRACT 50-361 50-219 30-247	A . S . G . S	8305170023 8305170028 8305170034 8305170047	8305170015 8305170015 8305170030 8305170039 8305170039	83/05/05 83/05/05 83/05/09 83/05/13 83/05/13	50-311 50-296 50-289	P P 8 0
8305160028 8305160037 8305160051 8305160057 8305160062	8305160024 8305160029 8305160047 8305160052 8305160054	83/05/10 83/05/11 83/05/03 83/05/06 83/05/03	50-247 50-142 50-362 50-311 50-315	0 0 0 0 R	8305170051 8305170052 8305170054 8305170058 8305170058	8305170039 8305170027 8305170039 8305170027 8305170039	83/05/13 83/05/04 83/05/13 83/05/04 83/05/13	50-220 50-289 50-220	0 4 0 4 0
8305160064 8305160067 8305160072 8305160076 8305160078	8305160058 8305160055 8305160071 8305160056 8305160067	83/05/02 83/05/05 83/05/12 83/05/11 83/04/29	50-334 50-361 50-528 50-262 70-754	8 8 A R	6303170060 8303170067 8303170070 8303170071 8303170072	8305170027 8305170063 8305170065 8305170069 8305170069	83/05/04 83/05/13 83/04/01 83/05/02 83/05/02	50-142 CONTRACT 50-271	P 0 P P
8305160079 8305160082 8305160087 8305160091 8305160098	8305160075 8305160065 9305160083 8305160083 8305160092	83/04/30 83/05/03 83/05/02 83/05/02 83/05/11	50-247 50-309 50-354 50-354 50-263	8 9 9 8	8305170075 8305170077 8305170080 8305170085 8305170085	8305170069 8305170065 8305170076 8305170079 8305170064	83/05/02 83/04/01 83/05/04 83/05/05 83/04/29	CONTRACT 50-315 50-272	P P B
8305160100 8305160101 8305160102 8305160103 8305160107	8305160094 8305160055 8305160096 8305160097 8305160094	83/05/10 83/05/05 83/04/28 83/04/25 83/05/10	50-348 50-361 50-311 50-220 50-348	G S R G	8305170087 8305170090 8305170095 8305170098 6305170102	8305170079 8305170079 8305170064 8305170093 8305170097	83/05/05 83/05/05 83/04/29 83/05/10 83/05/11	50-272 50-272	PPSA
8305140108 8305140112 8305140115 8305140114 8305160119	8305160104 8305160105 8305160110 8305160111 8305160114	83/05/11 83/05/12 83/05/03 83/05/11 83/05/03	50-315 50-333 50-362 50-285 50-244	P 8 8 8	8305170104 8305170109 8305170110 8305170112 8305170113	8305170064 8305170076 8305170064 8305170076 8305170108	83/04/29 83/05/04 83/04/29 83/05/04 83/05/10	50-315 50-272	8 P B P
8305160123 8305160125 8305160126 8305160136 8305160139	8305140118 8305140120 8305140121 8305160134 8305160137	83/05/05 83/05/03 83/05/10 83/05/09 83/05/02	50-311 50-362 50-315 50-293 50-293	8 8 R Q	8305170119 8305170124 8305170125 8305170127 8305170136	8305170117 8305170117 8305170120 8305170117 8305170130	83/05/05 83/05/05 83/05/11 83/05/05 83/05/09	50-272 XPORTLIC 50-272	P P G
8305160141 8305160142 8305160151 8305160171 8305160176	8305140138 8305140137 8305140124 8305140169 8305140172	83/05/09 83/05/02 83/05/06 83/05/10 83/05/11	50-445 50-293 50-387 50-246 50-275	K G B R P	8305170140 8305170144 8305170147 8305170163 8305170163	8305170134 8305170138 8305170142 8305170148 8305170159	83/05/04 83/05/10 83/05/10 83/04/27 83/05/05	50-266 50-311 50-546	8 0 R 0 8
8305160179 8305160189 8305160199 8305160200 8305160204	8305160089 8305160183 8305160194 8305160195 8305160195	83/05/10 83/05/02 83/05/02 83/03/31 83/03/31	50-528 50-213 50-289 50-312 50-312	0 P Q Q	8305170168 8305170171 8305170174 8305170188 8305170188	8305170166 8305170162 8305170166 8305170167 8305170182	83/04/27 83/05/05 83/04/27 83/05/09 83/05/09	50-346 50-155 50-254	8 9 9
8305160213 8305160218 8305160222 8305160234 8305160239	8305160195 8305160195 8305160195 8305160240 8305160256	83/03/31 83/03/31 83/03/31 83/05/04 83/04/19	50-312 50-312 50-312 50-445 40-8675	9	8305170197 8305170205 8305170224 8305170225 8305170227	8305170191 8305170201 8305170212 8305170219 8305170222	83/05/09 83/05/05 83/05/04 83/05/06 83/05/09	50-346 50-498 50-528	8 9 A 0

ACCESSI	ON NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8305170233 8305170234 8305170236 8305170240 8305170248		83/05/04 83/05/04 83/05/12 83/05/12	50-361 50-361 50-361 50-366 50-454	P P A Q	8305170499 8305170501 8305170504 8305170506 8305170508	8305170481 8305170494 8305170495 8305170502 8305170495	83/05/05 83/04/22 83/05/10 83/05/05 83/05/10	50-364 50-275 50-54 50-366 50~54	8 0 8
8305170250 8305170251 8305170252 8305170259 8305170240	8305170244 8305170245 8305170241 8305170246 8305170255	83/05/09 83/05/12 83/05/09 83/05/12	50-335 71-9015 50-244 50-317 71-9151	5 0 P	9305170517 8305170521 8305170525 9305170530 8305170532	8305170511 8305170515 8305170520 8305170515 8305170529	83/05/12 83/04/18 83/05/13 83/04/18 83/05/13	50~275 50~361 50~250 50~361 50~293	R O P O R
8305170262 8305170263 8305170266 8305170269 8305170271	8305170254 8305170241 8305170246 8305170258 8305170267	83/05/05 83/05/07 83/05/05 83/05/06 83/05/06	50-321 50-266 50-317 50-370 50-305	8 0 0	8305170537 8305170540 8305170544 8305170553 8305170564	8305170531 8305170536 8305170537 8305170550 8305170560	83/04/22 83/05/13 83/04/28 83/05/06 83/04/25	50-528 50-349 50-329 50-358 50-528	Q R A Q
8305170273 8305170274 8305170284 8305170285 8305170298	8305170246 8305170270 8305170276 8305170282 8305170284	83/03/05 83/04/19 83/05/05 83/05/09 83/04/27	50-317 50-315 50-366 50-400 50-341	6 8 8	8305170566 8305170567 8305170567 8305170370 8305170370	6305170561 6305170562 6305170565 6305170568 6305170568	83/05/05 83/04/08 83/03/12 83/04/27 83/04/29	50-249 50-344 50-454 70-8 70-8	13 G G
8305170300 8305170304 8305170307 8305170308 8305170311	8305170295 8305170294 8305170302 8305170303 8305170302	83/05/05 83/04/27 83/04/15 83/04/27 83/04/15	50-255 50-341 TOPREP 50-346 TOPREP	G G	8305170572 8305170576 8305170581 8305170588 8305170589	9305170545 9305170545 9305170545 9305170545 9305170545	83/05/12 83/05/12 83/05/12	50-454 50-454 50-454 50-454 50-454	0 0 0
8305170312 8305170313 8305170315 8305170318 8305170331	8305170306 8305170309 8305170303 8305170309 8305170322	83/05/13 83/04/29 83/04/27 83/04/29 83/05/11	50-546 50-445 50-346 50-445 50-374	A G G	8305170593 8305170607 8305170614 8305170621 8305170645	8305170565 8305170606 8305170603 8305170616 8305170619	83/05/12 83/04/28 83/05/03 83/05/05 83/05/09	50-454 CONTRACT CONTRACT XPORTLIC 50-301	9
8305170333 8305170338 8305170339 8305170340 8305170342	8305170327 8305170324 8305170332 8305170330 8305170336	83/04/29 83/04/22 83/04/08 83/05/09 83/05/06	50-298 50-269 50-275 50-260 50-133	0 8 9 8	8305170661 8305170666 8305170678 8305170678 8305170682	6305170648 8305170657 8305170669 8305170669 8305170669	83/05/13 83/05/04 83/05/05 83/05/05 83/05/05		444
8305170343 8305170344 8305170348 8305170349 8305170353	8305170335 8305170337 8305170337 8305170334 8305170337	83/05/05 83/04/27 83/04/27 83/04/19 83/04/27	50-397 50-295 50-295 50-397 50-295	@ @ @ @	8305170683 8305170685 8305170693 8305170705 8305170726	8305170457 8305170477 8305170688 8305170701 8305170723	83/05/04 83/05/11 83/05/13 83/05/06 83/05/09		F F A P
8305170358 8305170341 8305170365 8305170370 8305170376	8305170355 8305170359 8305170363 8305170367 8305170372	83/05/05 83/04/26 83/05/03 83/05/06 83/05/02	50~369 50~361 50~206 50~311 50~254	8 9 8 8	8305170730 8305180008 8305180010 8305180013	8305170723 8305180007 8305180005 8305180007 8305180005	83/05/09 83/05/04 83/04/12 83/05/04 83/04/12	FOIA	P P
8305170378 8305170381 8305170382 8305170387 8305170388	8305170374 8305170375 8305170377 8305170384 8305170383	83/05/03 83/04/18 83/05/04 83/04/08 83/05/04	50-373 50-397 50-528 50-508 50-373	8 0 8	8305180014 8305180015 8305180016 8305180020 8305180021	8305180007 8305180012 8305180005 8305180005	83/05/04 83/05/05 83/04/12 83/05/05 83/04/12	50~375 FOLA	P P P
8305170390 8305170394 8305170395 8305170394 8305170400	8305170384 8305170389 8305170393 8305170392 8305170398	83/04/08 83/05/05 83/05/10 83/05/13 83/04/28	50-508 50-366 50-220 50-329 50-373	G E R H	8305180023 8305180025 8305180031 8305180033 8305180036	8305180012 8305180024 8305180005 8305180024 8305180030	83/03/03 83/03/03 83/03/03 83/03/03 83/03/03	F01A 50-275	ዮ የ የ
E305170402 E305170403 E305170411 E305170412 E305170413	8305170399 8305170398 8305170408 8305170406 8305170408	83/05/09 83/04/28 83/04/26 83/05/10 83/04/26	50-302 50-373 50-454 50-338 50-454	8 1 8 7	8305180037 8305180039 8305180041 8305180044	8305180005 8305180026 8305180030 8305180005 8305180034	83/04/12 83/04/27 83/05/05 83/04/12 83/05/05		P P
8305170420 8305170421 8305170425 8305170426 8305170431	8305170417 8305170417 8305170423 8305170424 8305170427	83/04/14 83/04/14 83/05/12 83/05/09 83/05/09	50-361 50-361 50-373 50-416 50-416	0 0 0	8305180047 8305180048 8305180049 8305180050 8305180052	8305180038 8305180040 8305180030 8305180026 8305180005	83/05/10 83/05/05 83/05/05 83/04/27 83/04/12	50-247 50-324 50-368 50-298 FOIA	Р Р Р
8305170432 8305170433 8305170437 8305170438 8305170438	8305170429 8305170430 9305170429 8305170434 8305170434	93/04/25 83/05/09 83/04/25 83/05/05 83/04/26	50-89 50-414 50-89 50-321 50-397	0 8 0 8	8305180054 8305180057 8305180058 8305180059 8305180061	8305180005 8305180040 8305180053 8305180034 8305180040	83/04/12 83/05/05 83/05/05 83/05/05 83/05/05	FOIA 50-324 50-367 50-269 50-324	4 4 4
8305170444 8305170445 8305170451 8305170454 8305170460	8305170441 8305170442 8305170446 8305170447 8305170435	83/05/06 83/05/05 83/05/06 83/05/13 83/05/13	50-315 50-321 50-316 50-358 50-269	8 8 0 R	8305180063 8305180064 8305180066 8305180070	8305180005 8305180001 8305180053 8305180034 8305180005	83/04/12 83/03/09 83/05/05 83/05/05 83/04/12	FOIA 30-498 30-369 50-269 FOIA	Q P P
8305170470 8305170473 8305170480 8305170490 8305170498	8305170465 8305170468 8305170474 8305170487 8305170494	83/05/12 83/05/13 83/04/14 83/05/11 83/05/04	50-285 50-458 50-341 50-354 50-508	R K G G	8305180071 8305180072 8305180073 8305180074 8305180075	8305180024 8305180053 8305180065 8305180003	83/04/29 83/05/05 83/05/05 83/04/12 83/03/09	50-298 50-369 XPORTLIC FDIA 50-498	P P Q

ACCESSION					ACCESSION	NUMBER			
ENCLOSUAE	PRINCIPAL DOCUMENT	DATE 19SUED	SUBJECT CATEGOR	Y	ENCLOBURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	Y
0800816068 9305160091 9305160092 9305180092	8305180005 8305180001 8305180005 8305180005	83/04/12 83/03/09 83/05/03 83/04/12 83/05/03	FOIA 50-498 50-331 FOIA 50-331	G P P	8305180421 8305180426 8305180431 8305180438 8305180439	8305180412 8305180414 8305180414 8305180414 8305180437	83/05/12 83/05/16 83/05/16 83/05/16 83/05/17	CONTRACT 50-352 50-352 50-352 50-170	E
8305180074 8305180074 8305180100 8305180104 8305180106	8305180001 8305180005 8305180005 8305180099 8305180005	83/03/09 83/04/12 83/04/12 83/05/05 83/04/12	50-498 FOIA FOIA 50-289 FOIA	Q: P	8305180440 8305180443 8305180448 8305180459 8305180461	B305180433 B305180414 B305180445 B305180430 B305180430	83/05/17 83/05/16 83/05/17 83/05/17	50-217 50-352 50-322 50-322 50-322	PEHHH
8305180111 8305180114 8305180116 8305180121 8305180123	8305180005 8305180102 8305180005 8305180001 8305180005	83/04/12 83/05/05 83/04/12 83/03/09 83/04/12	FDIA 50-346 FDIA 50-448 FDIA	P A	8305180463 8305180466 8305180548 8305180560 8305180562	8305180458 8305180465 8305180547 8305180557 8305180557	83/05/13 83/05/11 83/05/05 83/05/13	30-358 50-395 50-298 CONTRACT CONTRACT	F G P
8305180125 8305180126 8305180128 8305180135 8305180146	9305180117 9305180097 9305180099 9305180102 8305180143	83/04/15 83/05/05 83/05/05 83/05/05 83/05/16	40-6500 50-269 50-269 50-346 50-247	P P G	B305180566 B305180569 B305180576 B305180577 B305180579	8305180559 8305180559 8305180559 8305180572 8305180556	83/05/05 83/05/16 83/05/16 83/04/28 83/05/05	50-324 50-412 50-412 50-333 50-317	P K C F P
8305180148 8305180153 8305180157 8305180159 8305180144	8303180001 8305180001 8305180001 8305180005 8303180005	83/03/09 83/04/12 83/03/09 83/04/12 83/04/12	50-498 F01A 50-498 FDIA F01A	A G	8305180580 8305180585 8305180587 8305180572 8305180578	8305180573 8305180559 8305180586 8305180559 8305180559	83/05/02 83/05/16 83/05/03 83/05/16 83/05/16	50-305 50-412 50-261 50-412 50-412	5 K P K K
8305180167 8305180174 8305180175 8305180178 8305180181	8305180001 8305180005 8305180001 8305180005 8305180001	83/03/09 83/04/12 83/03/09 83/04/12 83/03/09	50-498 Foia 50-498 Foia 50-498	Q Q G	8305180404 8305180407 8305180413 8305180414 8305180425	8305180559 8305180556 8305180559 8305180556 8305180559	83/05/16 83/05/05 83/05/16 83/05/05 83/05/16	50-412 50-317 50-412 50-317 50-412	**
8305180185 8305180187 8305180189 8305180196 8305180202	8305180102 8305180102 8305180001 8305180005 8305180001	83/04/12 83/05/05 83/03/09 83/04/12 83/03/09	FOIA 50-345 50-498 FDIA 50~498	P @	8305180630 8305180634 8305180641 8305180648 8305180650	8305180626 8305180559 8305180559 8305180642 8305180559	83/04/18 83/05/16 83/05/16 83/04/19 83/05/16	71-5607 50-412 50-412 70-1257 50-412	K K
8305180204 8305180207 8305180211 8305180214 8305180221	8305180197 8305180005 8305180001 8305180197 8305180001	83/05/03 83/04/12 83/03/09 83/05/03 83/03/09	50-293 FOIA 50-498 50-293 50-498	P G P A	8305180655 8305180661 8305180666 8305180673 8305180674	8305180559 8305180559 8305180559 8305180559 8305180668	83/05/14 83/05/16 83/05/16 83/05/16 83/04/14	50-412 50-412 50-412 50-412 ACRE	K K K
6305180223 6305180224 6305160227 6305180233 6305180234	8305180005 8305180213 8305180197 8305180005 8305180213	83/04/12 83/05/04 83/05/03 83/04/12 83/05/04	FOIA 50-327 50-293 FOIA 50-327	P P	830518047 <i>6</i> 830518047 <i>8</i> 8305180481 8305180485 8305180488	8305180470 8305180448 8305180559 8305180559 8305180484	93/04/15 93/04/14 93/05/16 93/05/16 93/04/19	71-6272 ACRS 50-412 50-412 71-9150	ĸĸ
8305180236 8305180241 8305180245 8305180247 8305180248	8305180001 8305180038 8305180238 8305180205 8305180213	83/03/09 83/04/12 83/05/06 83/04/12 83/05/04	50-498 F01A 50-320 F01A 50-327	A P P	8305180693 8305180695 8305180697 8305180702 8305180705	8305180559 8305180559 8305180559 8305180491 8305180559	83/05/14 83/05/16 83/05/16 83/04/28 83/05/16	50-412 50-412 50-412 50-295 50-412	KKKPK
8305180249 8305180250 8305180253 8305180254 8305180257	8305180238 8305180001 8305180238 8305180001	83/05/06 83/03/09 83/05/06 83/03/09 83/03/09	50-320 50-498 50-320 50-498 50-498	P A P T T	8305180708 8305180715 8305180720 8305180721 8305180725	8305180559 8305180559 8305180559 8305180712 8305180712	83/05/16 83/05/16 83/05/16 83/05/02 83/05/02	50-412 50-412 50-412 50-348 50-348	*****
8305180258 8305180257 8305180260 8305180263 8305180267	8305180005 830518025A 8305180252 8305180005 8305180005	83/04/12 83/05/16 83/05/17 83/04/12 83/04/12	FOIA 50-412 50-322 FOIA FOIA	F U	8305180728 8305180731 8305180735 8305180740 8305180743	8305180559 8305180712 8305180559 8305180559 8305180694	83/05/16 83/05/02 83/05/16 83/05/16 83/05/05	50-412 50-348 50-412 50-412 50-313	4
8305180273 8305180276 8305180284 8305180285 8305180287	8305180262 8305180001 8305180279 8305180005 8305180283	83/04/29 83/03/09 83/05/06 83/04/12 83/05/16	TOPREP 50-498 50-321 FOIA 50-412	Q R K	8305180746 8305180749 8305180755 8305180760 8305180764	8305180559 8305180559 8305180559 8305180559 8305180559	83/05/14 83/05/14 83/05/16 83/05/16		KKKKK
8305180291 8305180297 8305180311 8305180313 8305180315	8305180205 8305180272 8305180304 8305180304 8305180001	83/04/12 83/05/16 83/05/10 83/05/06 83/03/09	FDIA 50-155 50-245 PR 50-498	P P	8305180767 8305180769 8305180792 8305180804 8305180836	8305180559 8305180559 8305180785 8305180790 8305180830	83/05/14 83/05/14 83/05/13 83/05/02 83/05/06	50-412 50-412 CONTRACT 50-361 50-272	K K 88
8305180322 8305180324 8305180326 8305180328 8305180331	8305180314 8305180244 8305180001 8305180314 8305180244	83/03/29 83/05/12 83/03/09 83/03/29 83/05/12	FO1A 50-322 50-498 50-237 50-322	G A P G	8305180839 8305180854 8305190006 8305190007 8305190027	8305180835 8305180854 8305190004 8305190004 8305190019	93/05/10 93/05/02 93/05/09 93/05/08 93/05/06	70-2973 70-2973	P G
8305180337 8305180349 8305180367 8305180397 8305180403	8305180001 8305180346 8305180366 8305180365 8305180375	83/03/09 83/05/13 83/05/17 83/05/09 83/05/13	50-498 50-331 50-322 50-454 50-275	A R H A	B305190029 B30519003B B305190045 B305190050 B305190054	8305190024 8305190031 8305190005 B305190005 8305190046	83/05/04 83/05/05 83/03/11 83/03/11 83/05/03	50-322 50-327 50-327	8 0 0 0 A

	N NUMBER					SION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEOD	RY	ENCLOSUR	PRINCIPAL E DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8305190057 8305190060 8305190061 8305190068 8305190077	8305190053 8305190044 8305190005 8305190044 8305190046	83/05/09 83/05/03 83/03/11 83/05/03 83/05/03	XPORTLI 50-397 FOIA 50-397 50-397		83051903 83051903 83051903 83051903 83051903	87 8305190005 90 8305190005 93 8305190005 96 8305190005	83/03/11 83/03/11 83/03/11	50-373 50-373 50-373 50-329 50-373	0 P S Q
8305170084 8305170088 8305170077 8305170102 8305170108	8305170005 8305170005 8305170005 8305170005	83/03/11 83/03/11 83/03/11 83/03/11	50-373 50-329 50-329 50-329 50-329	8 0 0	83051705 83052000 83052000 83052000 83052000	04 8305200002 37 8305200031 71 8305200062	83/04/12	CONTRAC CONTRAC 40-4492 CONTRAC 50-336	Т
8305190112 8305190119 8305190124 8305190128 8305190132	8305170005 8305170005 8305170005 8305170005	83/03/11 83/03/11 83/03/11 83/03/11	50-329 50-373 50-373 50-373 FDIA	8 0 0	83052000 83052001 83052001 83052001 83052001	06 B305200103 07 B305200100 10 B305200100	83/05/04 83/04/28 83/05/02 83/05/02 83/05/12	50-336 50-269 50-277 50-277 50-400	P 0 0 0
8305190145 8305190151 8305190153 8305190154 8305190162	8305190005 8305190005 8305190005 8305190149 8305190005	83/03/11 83/03/11 83/03/11 83/03/11	50-373 50-373 FOIA 50-346 50-373	P Q R Q	83052001 83052001 83052001 93052001	37 8305200129 49 8305200145 65 8305200159	83/04/29 83/05/11 83/05/13 83/05/13 83/05/17	CONTRAC XPORTL I CONTRAC 70-2982 50-289	C
8305190167 8305190169 8305190174 8305190175 8305190179	8305170005 8305170163 8305170163 8305170170 8305170005	83/03/11 83/05/06 83/05/06 83/05/06 83/03/11	50-373 50-272 50-272 50-244 50-373	G G S G	83052002 83052003 83052003 83052003	99 8305200190 04 8305200198 38 8305200100	83/03/14 83/04/19 83/05/02 83/05/02 83/05/03	50-148 50-382 NUREG 50-277 50-255	G G
8305170181 8305170183 8305170184 8305170187 8305170171	8305170176 8305170178 8305170005 8305170005 8305170187	83/05/09 83/05/06 83/03/11 83/03/11 83/05/04	50-293 50-255 50-373 50-373 50-271	8 0 0	83052002 83052002 83052002	53 8305200251 56 8305200251 68 8305200265	83/05/03 83/05/04 83/05/04 83/05/13 83/05/13	50-255 50-382 50-382 50-333 50-333	9 9 P P
8305190201 8305190207 8305190232 8305190238 8305190247	8305170174 8305170005 8305170005 8305170234 8305170240	83/05/13 83/03/11 83/03/11 83/05/06 83/05/13	50~155 FOIA FOIA 50~244 50~289	P S R	83052003: 83052003: 83052003:	94 9305200279 86 9305200280 90 9305200283	83/05/04 83/05/11 83/05/09 83/05/11 83/05/12	50-275 50-339 50-416 50-220 50-240	8888
8305170256 8305170263 8305170266 8305170273 8305170276	8305170251 8305170260 8305170260 8305170267 8305170005	83/05/06 83/05/05 83/05/05 83/05/16 83/03/11	50~331 50~219 50~219 50~358 FOLA	G G G	83052003 83052003 83052003 83052003 83052003	07 8305200295 15 8305200308 18 8305200310	83/05/13 83/05/13 83/05/10 83/05/17 83/05/13	50-237 50-237 GA799 70-143 50-313	8
8305190281 8305190283 8305190284 8305190289 8305190290	8305190278 8305190005 8305190280 8305190005 8305190287	83/03/31 83/03/11 83/03/11 83/03/31	50~358 50~373 50~329 50~373 50~317	A Q A Q S	83052003 83052003 83052003 83052003 83052003	27 8305200306 92 8305200308 97 8305200330	83/05/10 83/05/12 83/05/10 83/05/18 83/05/04	GA999 50-348 GA999 50-346 GA999	R Gr
8305190292 8305190294 8305190299 8305190302	8305170005 8305170005 8305170005 8305170278 8305170005	83/03/11 83/03/11 83/03/11 83/05/06 83/03/11	50-373 50-373 FOIA 50-329 50-373	0 0 0 P	83052003 83052003 83052003 83052003 83052003	52 8305200357 54 8305200358 74 8305200360	83/05/12 83/05/12 83/05/16 83/05/12 83/04/28	50-375 50-364 50-275 50-309 0A999	e R R
8305190303 8305190304 8305190306 8305190307 8305190309	8305190005 8305190005 8305190005 8305190005 8305190185	83/03/11 83/03/11 83/03/11 83/03/11	50-373 50-373 FDIA 50-329 50-334	Р О О 8	830520037 83052003E 83052003F 83052003F 83052004F	93 8305200382 92 8305200384 97 8305200394	83/04/28 83/05/17 83/04/25 83/05/09 83/05/16	GA979 50-220 50-220 50-272 50-285	9 9 8 P
8305170311 8305170313 8305170314 8305170322 8305170327	8305190310 8305190310 8305190312 8305190319	83/05/05 83/05/05 83/05/16 83/03/11	50-271 50-271 50-358 50-387 50-373	G G A 5	83052004 83052004 83052004 83052004 830520042	8 6305200411 9 6305200416 2 8305200411	83/05/10 83/05/10 83/05/18 83/05/10 83/05/11	GA979 GA979 50-445 GA979 50-260	e G
8305190330 8305190332 8305190334 8305190337 8305190341	8305190326 8305190005 8305190331 8305190005 8305190005	83/05/07 83/03/11 83/05/04 83/03/11	50-293 50-373 50-410 FQIA FOIA	8 P 0	830520043 830520043 83052004 830520045 830520045	9305200436 9305200438 9305200445	83/05/13 83/05/17 83/05/17 83/04/04 83/05/10	50-327 50-334 50-369 50-313 GAPP9	8 9 8
8305190352 8305190353 8305190357 8305190360 8305190361	8305190348 8305190005 8305190005 8305190349 8305190356	83/05/05 83/03/11 83/03/11 83/05/12 83/05/04	50-318 50-373 50-373 50-407 M18C	8 P P	830520046 830520046 830520046 830520047 830520047	3 9305200459 5 9305200458 9 8305200446	83/05/10 83/05/20 83/05/20 83/05/10 83/05/16	0A999 50-537 50-315 0A999 50-309	B F
8305190365 8305190367 8305190369 8305190371 8305190374	8305170005 8305170005 8305170349 8305170364 8305170005	83/03/11 83/03/11 83/05/12 83/05/14 83/03/11	50-373 50-373 50-407 50-155 FOIA	P P Q	83052004B 830520049 830520051 830520051 830520051	3 8305200484 4 8305200509 5 8305200510	83/05/17 83/05/12 83/05/17 83/05/13 83/05/13	70-925 50-416 50-346 50-395 50-483	8 Q 8
8305170375 8305170377 8305170380 8305170382 8305170384	8305190366 8305190005 8305190347 8305190378 8305190005	83/05/14 83/03/11 83/05/12 83/03/14 83/03/11	50-155 50-373 50-407 50-322 50-373	о Р G	830520032 630520032 830820032 830820052 830520053	2 8305200508 7 8305200509 8 8305200516	83/05/17 83/05/17 83/05/17 83/04/27 83/05/11	50-345 50-454 50-345 50-267 50-416	0 0 0 0

ACCESS10						ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	CATEG	DRY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY
8305200540 8305200543 8305200546 8305200551 8305200561	8305200508 8305200538 8305200537 8305200547 8305200555	83/03/17 83/03/06 83/03/11 83/03/06 83/05/11	50-454 50-324 50-311 50-289 50-387	0 8 8 8	8305230167 8305230167 8305230179 8305230176 8305230179	8305230159 8305230127 8305230165	93/05/17 83/05/13 83/05/17 83/05/02 83/03/22	50-309 F CONTRACT 50-309 F 71-496 70-1193
8305200565 8305200547 8305200575 8305200581 8305200583	8305200554 8305200553 8305200553 8305200577 8305200574	83/05/17 83/05/18 83/05/18 83/05/12 83/05/13	50-369 50-329 50-329 50-327 50-338	0 A 8 8	8305230161 8305230186 8305230196 8305230197 8305230207	8305230112 8305230112 8305230187	83/05/17 83/03/22 83/03/22 83/05/17 83/03/22	50-309 F 70-1193 70-1193 50-320 T 40-1478
8305200584 8305200593 8305200594 8305200411 8305200423	8305200544 8305200587 8305200570 8305200571 8305200619	83/05/13 83/05/13 83/05/18 83/05/02 83/05/18	50-317 GA797 50-322 50-263 REVIEW	Q	8305230209 8305230221 8305230222 8305230222 8305230233	8305230213 8305230112 8305230216	83/05/17 83/05/18 83/03/22 83/05/11 83/03/22	50-320 T 50-275 R 40-1478 50-275 R 40-1478
8305200624 8305200627 8305200628 8305200633 8305200634	8305200413 8305200419 8305200420 8305200424 8305200419	83/05/19 83/05/18 83/05/17 83/05/12 83/05/18	50-142 REVIEW 50-317 50-395 REVIEW	GRP G S	8305230234 8305230249 8305230251 8305230254 8305230274	8305230245	83/03/21 83/05/17 83/04/28 83/04/28 83/05/17	FOIA CONTRACT FOIA FOIA CONTRACT
8305200637 8305200644 8305200646 8305200647 8305200648	8305200621 8305200631 8305200640 8305200621 8305200636	83/05/11 83/05/04 83/05/11 83/05/11 83/05/19	50-373 50-317 50-387 50-373 50-537	R 8	8305230284 8305230289 8305230292 8305230293 8305230308	8305230276 8305230281 8305230285 8305230287 8305230300	83/05/19 83/05/13 83/05/19 83/05/02 83/05/13	50-219 P CONTRACT 50-537 A CONTRACT 50-305 P
8305200650 8305200654 8305200655 8305200661 8305200664	8305200431 8305200419 8305200421 8305200419 8305200419	83/05/04 83/05/18 83/05/11 83/05/18 83/05/18	50-317 REVIEW 50-373 REVIEW REVIEW	ORP	830523031 1 830523031 4 8305230330 8305230332 8305230333	8305230278 8305230305 8305230323 8305230324 8305230324	83/05/11 83/04/29 83/05/13 83/05/12 83/05/06	CONTRACT 50-458 G 50-245 F CONTRACT PR
8305200665 8305200671 8305200673 8305200674 8305200675	8305200621 8305200619 830520066 8305200666 8305200621	83/05/11 83/05/18 83/05/04 83/05/18 83/05/11	50-373 REVIEW QA999 50-445 50-373	ORP ORP	8305230338 8305230348 8305230349 8305230388 8305230399	8305230323 8305230337 8305230360 8305230377 8305230381	83/05/13 83/05/06 83/05/05 83/05/05	50-245 F 50-313 G COMMISSION 50-289 U 50-309 P
8305200677 8305200678 8305200679 8305200681 8305200683	8305200619 830520066 8305200676 8305200621	93/05/18 83/05/04 83/05/13 93/05/11 93/05/11	REVIEW 0A979 50-400 50-373 50-373	ORP K P P	8305230406 8305230425 8305230427 8305230428 8305230431	8305230397 8305230420 8305230426 8305230420 8305050020	83/05/05 83/04/27 83/05/12 83/04/27 83/05/02	COMMISSION COMMISSION 50-267 R COMMISSION 50-220 P
8305200484 8305200488 8305200491 8305200701 8305200710	8305200621 8305200621 8305200681 8305200608 8305200709	83/05/11 83/05/11 83/05/11 83/05/12 83/05/05	50-373 50-373 50-373 50-213 50-338	5 P P B P	8305230432 8305230434 8305230437 8305230440 8305230441	8305230424 8305230429 8305230434 8305230435 8305230430	83/05/13 83/05/13 83/05/17 83/04/28 83/04/18	50-281 B 50-293 G 50-219 R 50-289 U 50-213 8
8305200717 8305200720 8305200724 8305230004 8305230009	8305200709 8305200709 8305200709 8305230003 8305230007	83/05/05 83/05/05 83/05/05 83/05/03 83/05/20	50-338 50-338 50-338 50-528 50-488	P P A F	B305230443 B305230446 B305230449 B305230451 B305230453	8305230435 8305230435 8305230445 8305230424 8305230435	83/04/28 83/04/28 83/05/13 83/05/13 83/04/28	50-289 U 50-289 U 50-445 Q 50-281 8 50-289 U
8305230010 8305230012 8305230017 8305230020 8305230025	8305230004 8305230006 8305230006 8305230015 8305230006	83/04/29 83/04/29 83/04/29 83/04/18 83/04/29	ABVCM ABVCM ABVCH 50-201 ADVCM	P	830523045B 8305230459 8305230460 8305230461 8305230467	9305230452 8305230454 9305230455 8305230457 9305230464	83/05/06 83/05/04 83/05/17 83/04/29 83/05/06	50-244 8 50-333 8 50-287 0 COMMISSION 50-285 0
8305230031 8305230032 8305230035 8305230035 9800823089	8305230024 8305230006 8305230026 8305230026 8305230028	83/05/09 83/04/29 83/01/25 83/01/25 83/03/31	CONTRAC ADVCM 70-135 70-135 FOIA	9	8305230468 8305230469 8305230475 8305230476 8305230477	8305230463 8305230465 8305230464 8305230473 8305230471	83/05/09 83/05/02 83/05/06 83/05/06 83/05/04	50-366 B COMMISSION 50-285 Q 50-482 Q 50-387 B
8305230040 8305230047 8305230048 8305230056 8305230057	8305230004 8305230029 8305230004 8305230041 8305230028	83/04/29 83/03/31 83/04/29 83/04/14 83/03/31	ADVCM FOIA ADVCM PROJ FOIA		8305230479 8305230480 8305230483 8305230487 8305230490	8305230485	83/05/03 83/05/06 83/05/10 83/05/18 83/05/09	CDMMISSION 50-482 0 50-309 8 50-482 0 50-346 8
8305230070 8305230086 8305230116 8305230125 8305230134	8305230065 8305230080 8305230107 8305230107 8305230112	89/03/31 83/04/12 83/05/03 83/05/03 83/03/22	FOIA 71-560 71-901 71-901 70-119	5	8305230478 8305230513 8305230515 8305230517 8305230521	8305230495 8305230510 8305230509 8305230511 8305230514	83/05/09 83/05/05 83/05/09 83/04/29 83/04/27	50-366 S 50-317 S 50-293 S MISC 50-293 S
9305230137 9305230139 9305230140 9305230142 8305230145	8305230127 8305230112 8305230127 8305230127 8305230128	83/05/17 83/03/22 83/05/17 83/05/17	50-309 70-1193 50-309 50-313	F F F	8305230524 8305230527 8305230528 8305230531 8305230534	8305230511 8305230520 8305230522 8305230511 8305230530	83/04/29 83/05/09 83/05/05 83/04/29 83/05/16	MISC 50-334 8 50-318 8 MISC 50-327 8
8305230146 8305230151 8305230154 8305230157 8305230162	8305230127 8305230127 8305230127 8305230127 8305230127	83/05/17 83/05/17 83/05/17 83/05/17 83/05/17	50-309 50-309 50-309 50-309 50-309	1 1 1 1	8305230537 8305230538 8305230544 8305230550 8305230557	8305230535 8305230533 8305230540 8305230540 8305230549	83/05/12 83/05/04 83/05/13 83/05/13 83/05/10	50-293 R 50-293 8 50-348 8 50-348 8 50-245 8

ACCESSION N							IN NUMBER			
P ENCLOSURE	RINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	٧		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 15SUED	SUBJEC CATEGO	
6305230559 8 8305230560 8 8305230564 8 8305230570 8	305230556 305230555 305230561 305230567 305230567	83/05/18 83/05/05 83/05/05 83/05/18 83/05/18	50-275 50-317 50-244 50-482 50-482	R 9 9 1 1		8305240361 8305240363 8305240369 8305240370 8305240371	8305240352 8305240352 8305240365 8305240365 8305240362	83/05/20 83/05/20 83/03/31 83/05/16 93/05/17	0A999 0A999 FOIA 50-315	5 0
8305230582 8 8305230585 8 8305230587 8	305230568 305230574 305230574 305230574 305230574	83/05/09 83/05/13 83/05/13 93/05/13	50-321 50-410 50-410 50-410 50-410	8 A A A		8305240374 8305240373 8305240403 8305240413 8305240415	8305240362 8305240390 8305240400 8305240407 8305240411	83/05/14 83/05/20 83/05/20 83/05/17 83/05/20	50~315 50~275 GA999 50~461 GA999	g Q A
8305230403 B 8305230407 B 8305230414 B	305230574 305230574 305230574 305230574 305230573	83/05/13 83/05/13 83/05/13 83/05/13 83/04/19	50-410 50-410 50-410 50-410 50-237	A A A B		8305240421 8305240433 8305240435 8305240437 8305240445	8305240407 8305240426 8305240431 8305240426 8305240426	83/05/19 83/04/25 83/05/20 83/04/25 83/04/25	50~461 GA999 GA999 GA999 GA999	A
9305230428 8: 9305230437 8: 9305230444 8:	905230574 905230574 905230574 905230574 905230574	83/05/13 83/05/13 83/05/13 83/05/13 83/05/13	50-410 50-410 50-410 50-410 50-410	A A A A		8305240452 8305240457 8305240462 8305240476 8305240484	8305240426 8305240449 8305240426 8305240488 8305240481	83/04/25 83/05/23 83/04/25 83/05/04 83/05/20	GA777 50-287 GA777 50-217 50-348	G R I
9305230461 8 9305230464 8 9305230466 8	305230574 305230574 305230640 305230574 305230670	83/05/13 83/05/13 83/05/13 83/05/13 83/04/18	50-410 50-410 CDMMISSIO 50-410 50-3	A A DN A F		8305240519 8305240539 8305240542 8305240536 8305240538	8305240510 8305240533 8305240538 8305240552 8305240555	83/05/06 83/05/20 83/05/23 83/05/03 83/05/20	50-244 50-247 50-247 71-6550 50-247	R T G
8305230480 8: 8305230481 8: 8305230484 8:	305230574 305230574 305230574 305230574 305230574	83/05/13 83/05/13 83/05/13 83/05/13	50-410 50-410 50-410 50-410 50-410	A A A		8305240545 8305240570 8305240574 8305240618 8305250034	8303240305 8303240366 8303240366 8303240614 8303230029	83/03/11 83/05/18 83/05/18 83/04/21 83/03/29	50-155 50-3 50-3 50-201 FOIA	P T T P
8305230695 83 8305230696 83 8305230699 83	305230574 305230692 305230574 305230574 305230574	83/05/13 83/04/20 83/05/13 83/05/13	50-410 COMMISSIO 50-410 50-410 50-410	A A A		8305250038 8305250043 8305250058 8305250084 8305250135	8305250029 8305250029 8305250056 8305250077 8305250133	83/03/29 83/03/29 83/05/20 83/05/19 83/05/20	FOIA FOIA 50-498 50-295 50-352	K P
8305230725 8: 8305230735 8: 8305240005 8:	305230717 305230723 305230732 305240003 305240006	83/05/18 83/05/12 83/05/20 83/05/20	50-369 50-368 COMMISSIC 50-445 50-329	8 P P O O		8305250144 8305250186 8305250208 8305250221 8305250225	8305240087 8305250064 8305250202 8305250209 8305250202	83/03/31 81/20/28 83/20/28 11/20/28	50-373 50-275 50-287 50-361 50-289	F R O P
8305240016 83 8305240023 83 8305240026 83	305240001 305240001 305240019 305240020 305240032	83/05/20 83/05/20 83/05/10 83/05/07 83/05/17	50-358 50-358 50-537 50-255 50-255	0 0 0 0		8305250228 8305250230 8305250263 8305250271 8305250275	8305250207 8305250257 8305250267 8305250267	83/05/18 83/05/13 83/05/13 83/05/13	50-341 50-284 50-320 50-289 50-219	P G P G
8305240061 83 8305240072 83 8305240084 83	305240049 305240029 305240067 305240075 305240078	83/05/19 83/05/06 83/05/17 83/05/06 83/05/17	50-313 50-282 50-346 CDMMISSIC 50-315	G G C ON G		9305250297 9305250300 9305250303 9305250304 9305250306	8305250274 8305250274 8305250277 8305250274 8305250277	83/05/20 83/05/20 83/05/20 83/05/20	50-483 50-483 50-277 50-483 50-277	0000
8305240125 83 8305240154 83 8305240167 83	305240087 305240087 305240144 305240155 305240155	83/03/31 83/03/31 83/05/16 83/04/22 83/04/22	50-373 50-373 TOPREP COMMISSIO COMMISSIO			8305250308 8305250309 8305250312 8305250313 8305250314	8305250305 8305250307 8305250310 8305250311 8305250310	83/05/11 83/05/13 83/05/11 83/05/04 83/05/11	GEN TEC 50-213 50-307 COMMISSI 50-307	0
8305240220 83 8305240232 83 8305240242 83	305240135 305240216 305240227 305240238 305240241	93/04/22 93/05/17 93/05/10 93/05/13 93/05/06	50-29 50-275	ON O O R O		6305250341 8305250346 8305250351 8305250354 8305250356	8305250294 8305250294 8305250294 8305250294 8305250294	83/05/20 83/05/20 83/05/20 83/05/20 83/05/20	50-493 50-493 50-493 50-493 50-493	0000
8305240256 83 8305240259 83 8305240240 83	305240241 305240252 305240254 305240254 305240252	83/05/06 83/04/14 83/03/31 83/03/31 83/04/14	50-373 50-358 50-287 50-414 50-358	G G P P		8305250358 8305250359 8305250360 8305250363 8305250372	8305250294 8305250294 8305250294 8305250294 8305250294	83/02/50 83/02/50 83/02/50 83/02/50	50-483 50-483 50-483 50-483 50-483	00000
8305240247 83 8305240248 83 8305240249 83	305240254 305240252 305240264 305240254 305240252	83/03/31 83/04/14 83/05/04 83/03/31 83/04/14	30-317	P Q P Q		8305250383 8305250388 8305250393 8305250394 8305250399	8305250294 8305250294 8305250377 8305250294 8305250377	83/05/19 83/05/20 83/05/20	50-483 50-483 50-237 50-483 50-237	00000
8305240291 83 8305240292 83 8305240306 83	305240252 305240285 305240284 305240302 305240301	83/04/14 93/05/19 83/05/18 83/05/06 83/05/17	50-272 50-331 50-315	9 9 9 9		8305250401 8305250403 8305250407 8305250408 8305250412	8305250294 8305250294 8305250377 8305250294 8305250294	83/05/20 83/05/20 83/05/20 83/05/20	50-483 50-483 50-237 50-483 50-483	0 0
8305240315 83 8305240340 83 8305240346 83	305240302 305240301 305240337 305240344 305240352	83/05/06 83/05/17 83/05/09 83/05/20 83/05/20		G G		B305250413 B305250419 B305250424 B305250428 B305250431	8305250377 8305250294 8305250294 8305250294 8305250427	83/05/19 83/05/20 83/05/20 83/05/20 83/05/11	50~237 50~483 50~483 50~483 50~29	0

ACCESSION NUMBER				ACCESSIO	N NUMBER			
PRINCIPAL ENCLOSURE DOCUMENT	DATE 199UED	SUBJECT CATEOORY	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	BUBJECT CATEGORY	Υ
8305250432 9305250274 8305250436 9305250274 8305250440 8205250274 8305250441 8305250438 8305250442 8305250437	83/05/20 83/05/20 83/05/20 83/05/12 83/05/11	50~483 50~483 50~483 50~244 50~245	00000	8305260211 8305260222 8305260224 8305260225 8305260231	8305260207 8305260206 8305260221 8305260223	83/05/11 83/05/23 83/05/12 83/05/13 83/05/13	50-250 CONTRACT 50-440 50-358 50-358	P G G
B305250444 8305250274 B305250446 8305250438 B305250449 B305250294 B305250450 B305250294 8305250451 B305250294	83/05/20 83/05/12 83/05/20 83/05/11 83/05/20	50~483 50~244 50~483 50~271 50~483	0000	8305260239 6305260243 8305260245 8305260247 8305260248	8305260236 8305260236 8305260241 8305260246 8305260241	83/05/09 83/05/09 83/05/19 83/05/19 83/05/19	30-440 50-440 50-346 50-461 50-346	0 0 0 P A P
8305250453 8305250438 8305250454 8305250454 8305250458 8305250274 8305250461 8305250274 8305250463 8305250274	83/05/12 83/05/19 83/05/20 83/05/20	50-244 50-184 50-483 50-483 50-483	0 0 0	8305260230 8305260233 8305260235 8305260238 8305260262	8305260244 8305260246 8305260252 8305260256 8305260257	83/05/12 83/05/19 83/05/05 83/05/12 83/05/19	50-461 50-461 50-397 50-409 50-275	0 0 0
8305250465 8305250459 8305250467 8305250466 8305250468 8305250274 8305250474 8305250274 8305250477 8305250274	83/05/11 83/05/20 83/05/20 83/05/20 83/05/20	50-336 50-275 50-483 50-483 50-483	G R O O	8303260246 8305260272 8305260273 8305260274 8305260282	8305260259 8305260270 8305260269 8305260270 8305260278	83/05/20 83/05/23 83/05/10 83/05/23 83/05/20	50-155 50-275 40-8137 50-275 50-454	0 0 0
8305250482 8305250274 8305250481 8305250481 8305250480 8305250274 8305250490 8305250274 8305250491 8305250472	83/05/20 83/05/20 83/05/20	50~483 50~335 50~483 50~483 50~250	0 P 0 P	8303260304 8303260311 8303260313 8303260321 8303260321	6305260301 6305260309 6305260309 6305260319 6305260320	83/05/23 83/05/19 83/05/19 83/05/03 83/05/24	50-278 50-330 50-330 50-328 50-324	98805
B305230493	83/05/16 83/05/20 83/05/20 83/05/13 83/05/20	PR 50-483 50-412 50-287 50-483	0 0	8305260326 8305260327 8305260331 8305260334 8305260337	8305260319 8305260322 8305260329 8305260329 8305260336	83/05/03 83/05/24 83/05/12 83/05/12 83/05/23	50-528 50-352 50-373 50-373 50-358	G G G A
8303250304 8303250497 8203250305 8305250495 8305250506 8305250294 8305250309 8305250294 8305250311 8305250294	83/05/11 83/05/13 83/05/20 83/05/12 83/05/20	50-213 50-289 50-483 50-286 50-483	0 0 0	8305260338 8305260345 8305260355 8305260373 8305260380	8305260336 8305260340 8305260350 8305260350 8305260377	83/05/23 83/05/13 83/05/13 83/05/14	50-358 CONTRACT 71-9151 71-9151 CONTRACT	A
8305250515 8305250294 8305250518 8305250510 8305250520 8305250512 8305250521 8305250514	83/05/20 83/05/18 83/05/23 83/05/20 83/05/18	50-483 50-213 50-206 50-483 50-220	9999	8305260379 8303260401 8303260405 8303270010 8303270011	8305240395 8305240397 8305240397 8305270007 8305270008	83/04/28 83/03/28 83/03/28 83/05/26 83/05/20	40-277 50-358 50-358 50-255 50-261	A T F
8305250524 8305250294 8305250331 8305250294 8305250333 8305250529 8305250334 8305250294 8305250540 8305250294	83/05/20 83/05/20 83/05/20 83/05/20 83/05/20	50-483 50-483 PR 50-483 50-483	0 0 0	8305270012 8305270027 8305270034 8305270033 8305270037	8305270006 8305270022 8305270032 8305270022 8305270033	83/04/11 83/03/08 83/05/16 83/03/08 83/05/20	XPORTLIC	P G
8305250542 8305250274 8305250544 8305250274 8305250546 8305250541 8305250548 8305250274 8305250552 8305250274	83/05/20 83/05/20 83/05/09 83/05/20 83/05/20	50-483 50-483 50-280 50-483 50-483	0 0 0	8305270040 8305270046 8305270048 8305270050 8305270052	8305270022 8305270022 8305270022 8305270045 8305270045	83/03/08 83/03/08 83/03/08 83/03/19 83/05/19	50-320	P P G G
8305250553 8305250294 8305250557 8305250294 8305250539 8305250294 8305250562 8305250294 8305250565 8305250560	83/05/20 83/05/20 83/05/20 83/05/20	50-483 50-483 50-483 50-483 50-213	0 0 0	8305270053 8305270053 8305270063 8305270066 8305270071	8305270043 8305270045 8305270057 8305270057 8305270060	83/05/23 83/05/19 83/05/16 83/05/16	50-329	G G K K
8305250544 8305250294 8305250548 8305250543 8305250579 8305250294 8305250574 8305250549 8305250575 8305250571	83/05/20 83/05/13 83/05/20 83/05/20 83/05/13	50-483 70-371 50-483 50-271 50-387	0 P Q	8305270086 830527099 8305270094 8305270095 8305270100	8305270083 8305270090 8305270091 8305270092 8305270097	83/04/20 83/05/16 83/04/18 83/05/20 83/04/28	TOATTACT 50-375	GI CI P
8305250576 8305250274 8305250577 8305250572 8305250578 8305250563 8305250580 8305250274 8305250582 8305250563	83/05/20 83/05/10 83/05/13 83/05/20 83/05/13	50-483 50-271 70-371 50-483 70-371	G G	8305270101 8305270105 8305270110 8305270116 8305270119	8305270098 8305270103 8305270108 8305270113 8305270114	83/04/19 83/05/06 83/05/18 83/04/11 83/05/18	CONTRACT CONTRACT 70-1113	Gi P
8305230583 8305250274 8305250584 8305250274 8305250586 8305250563 8305250587 8305250274 8305250589 8305250274	83/05/20 83/05/20 83/05/13 83/05/20 83/05/20	50-483 50-483 70-371 50-483 50-483	0	8305270121 8305270145 8305270145 8305270151 8305270159	8305270112 8305270142 8305270144 8305270146 8305270156	83/04/06 83/05/18 83/05/24 83/03/25 83/04/27	70-1151 QA999	G G
8305250590 8305250588 8305250604 8305250603 8305250607 8305250605 8305260002 8305260001 8305260004 8305260003	83/05/19 83/05/18 83/05/18 83/05/19 83/04/18	50-289 40-8027 70-371 50-537 71-5552	P L	8305270160 8305270167 8305270179 8305270186 8305270188	8305270154 8305270161 8305270176 8305270182 8305270182	83/03/29 83/05/18 83/05/05 83/05/24 83/05/24	70~143 50~389 50~344	G P P
830526004B 8305260037 8305260057 8305260055 8305260087 8305260081 8305260173 8305260168 8305260183 8305260182	83/05/24 83/05/18 83/04/08 83/05/23 83/05/17	50-447 XPORTLIC CONTRACT 50-483 50-275	E G	8305270190 8305270190 8305270200 8305270206 8305270208	8305270187 8305270191 8305270197 8305270202 8305270204	83/05/23 83/05/23 83/05/02 83/04/07 83/05/13	50-456 50-537 50-259	P G G

ACCESSION					ACCESS10				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT	ξĄ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT	
8305270211 8305270212 8305270219 8305270226 8305270227	8305270205 8305270209 8305270215 8305270196 8305270223	83/05/24 83/05/25 83/05/06 83/05/10 83/05/20	50-344 50-302 50-250 50-62 50-316	9 0 0 5	8305270379 8305270381 8305270383 8305270383 8305270384	8305270349 8305270345 8305270327 8305270377 8305270376	83/04/19 83/05/09 83/04/04 83/04/14 83/05/05	50-389 50-259 50-369 50-400 50-250	0 0 0 0
8305270230 8305270231 8305270233 8305270234 8305270244	8305270229 8305270229 8305270228 8305270232 8305270238	83/05/20 83/04/01 83/05/19 83/05/05 83/04/18	50-316 50-261 50-390 50-389 50-338	9	8305270386 8305270387 8305270387 8305270391 8305270394	8305270372 8305270374 8305270380 8305270377 8305270372	83/05/04 83/05/06 83/05/04 83/04/14 83/05/04	50-438 50-269 50-261 50-400 50-438	0 0 0
8305270245 8305270248 8305270252 8305270253 8305270254	8305270240 8305270242 8305270242 8305270247 8305270174	83/04/15 83/05/03 83/05/03 83/04/29 83/04/22	50-389 50-280 50-280 50-302 70-1201	G G G	9305270397 9305270398 9305270399 9305270400 9305270401	8305270377 8305270372 8305270392 8305270388 8305270390	83/04/14 83/05/04 83/05/20 83/05/19 83/04/26	50-400 50-438 50-333 50-416 50-261	9 9 9
8305270256 8305270257 8305270258 8305270260 8305270263	8305270250 8305270242 8305270247 8305270247 8305270250	83/04/29 83/05/03 83/04/29 83/04/29 83/04/29	50-324 50-280 50-302 50-302 50-324	G G G	8305270402 8305270404 8305270403 8305270404 8305270407	8305270385 8305270393 8305270327 8305270327 8305270394	83/03/29 83/04/21 83/04/04 83/04/14 83/04/07	50-369 50-413 50-369 50-400 50-338	Q Q Q Q
8305270264 8305270265 8305270268 8305270269 8305270270	8305270247 8305270242 8305270250 8305270247 8305270261	83/04/29 83/05/03 83/04/29 83/04/29 83/05/25	50-302 50-280 50-324 50-302 50-341	0 0 0	8305270410 8305270411 8305270415 8305270416 8305270417	8305270388 8305270403 8305270372 8305270374 8305270409	83/05/19 83/04/05 83/05/04 83/04/07 83/03/28	50-416 50-269 50-436 50-339 50-416	0 0 0
8305270272 8305270274 8305270277 8305270278 8305270279	8305270267 8305270250 8305270267 8305270273 8305270259	83/05/13 83/04/29 83/05/13 83/05/06 83/05/19	GA999 50~324 GA999 50~537 50~269	G G P	8305270418 8305270420 8305270421 8305270422 8305270422	8305270388 8305270413 8305270374 8305270412 8305270388	83/05/19 83/05/09 83/04/07 83/04/11 83/05/19	50-416 50-390 50-339 50-395 50-416	G G G
8305270281 8305270282 8305270283 8305270284 8305270284	8305270271 8305270205 8305270275 8305270274 8305270267	83/05/16 83/05/24 83/05/12 83/05/23 83/05/13	50~400 50~344 50~416 50~333 94999	9 9 9	5305270426 6305270427 6305270428 6305270430 6305270430	8305270414 8305270409 8305270327 8305270394 8305270412	83/03/09 83/03/28 83/04/04 83/04/07 83/04/11	50-338 50-416 50-367 50-338 50-375	0 0 0
8305270292 8305270293 8305270294 8305270297 8305270298	8305270271 8305270289 8305270259 8305270287 8305270291	83/05/16 83/03/29 83/05/19 83/05/06 83/05/13	50~400 50~389 50~269 50~335 GA799	а е е	8305270435 8305270437 8305270438 8305270439 8305270441	8305270425 8305270414 8305270388 8305270423 8305270431	83/05/11 83/05/09 83/05/19 83/04/29 83/04/13	50-269 50-338 50-416 50-280 50-395	0 0
8305270301 8305270303 8305270304 8305270305 8305270306	8305270271 8305270290 8305270288 8305270294 8305270300	83/03/16 83/03/23 83/03/23 83/03/20 83/03/30	50-400 50-390 50-332 50-275 50-416	0 0 P 0	8305270442 8303270443 8303270445 8305270445 8305270446	8305270374 8305270412 8305270434 8305270436 8305270414	83/04/07 83/04/11 83/05/20 83/04/25 83/05/09	50~338 50~395 50~309 50~395 50~338	0 0 0
8305270307 8305270308 8305270309 8305270311 8305270312	8305270291 8305270271 8305270259 8305270302 8305270302	83/05/13 83/05/14 83/05/19 83/05/10 83/05/20	0A999 50-400 50-269 GA999 50-302	G P	8305270449 8305270451 8305270452 8305270453 8305270455	9305270431 9305270440 9305270431 9305270447 9305270414	83/04/13 83/05/16 83/04/13 83/04/04 83/05/09	50~395 50~331 50~395 50~389 50~338	0 8 0 0
8305270315 8305270318 8305270319 8305270322 8305270325	8305270310 8305270280 8305270314 8305270313 8305270316	83/03/30 83/05/20 83/04/14 83/03/23 83/03/23	50-389 50-302 50-537 50-327 50-62	G G G	8305270458 8305270459 8305270460 8305270462 8305270466	9305270431 9305270430 8305270440 9305270412 8305270436	83/04/13 83/04/06 83/05/16 83/04/11 83/60/28	50-395 70-1151 50-331 50-395 50-302	0 8 0 0
8305270328 8305270334 8305270336 8305270337 8305270338	8305270320 8305270324 8305270332 8305270330 8305270324	83/05/10 83/03/25 83/04/27 83/03/28 83/03/06	50-424 50-413 50-321 50-424 50-269	@ @ @ @	8305270467 8305270469 8305270470 8305270471 8305270474	8305270450 8305270465 8305270463 8305270450 8305270461	83/04/06 83/04/22 83/04/05 83/04/06 83/04/11	70-1151 50-111 50-416 70-1151 50-261	g g
8305270339 8305270342 8305270343 8305270348 8305270351	8305270329 8305270333 8305270332 8305270341 8305270332	83/05/06 83/05/10 83/04/27 83/03/31 83/04/27	50-335 50-324 50-321 50-400 50-321	0 0 0	8305270478 8305270480 8305270487 8305270487 8305270488	8305270464 8305270450 8305270472 8305270479 8305270481	83/05/05 83/04/06 83/04/06 83/04/07 83/05/18	50-395 70-1151 50-537 50-241 TOPREP	0 0 0
8305270352 8305270354 8305270355 8305270356 8305270357	8305270340 8305270347 8305270345 8305270350 8305270332	83/05/25 83/04/06 83/05/09 83/05/11 83/04/27	50-333 50-302 50-259 50-321 50-321	р С С	B305270489 B305270490 B305270492 B305270493 B305270494	8305270476 8305270483 8305270484 8305270486 8305270479	83/05/24 83/04/04 83/05/04 83/05/06 83/04/07	50-454 50-280 50-400 50-305 50-261	@ @ @
8305270360 8305270362 8305270364 8305270365 8305270366	8305270349 8305270345 8305270340 8305270349 8305270327	83/04/19 83/05/09 83/05/25 83/04/19 83/04/04	50-389 50-259 50-333 50-389 50-369	9 9 9	8305270496 8305270500 8305270501 8305270502 8305270503	8305270468 8305270479 8305270476 8305270486 8305270499	83/03/25 83/04/07 83/05/24 83/05/06 83/04/13	50-518 50-261 50-454 50-305 50-302	G G G
8305270367 8305270368 8305270370 8305270371 8305270378	8305270359 8305270345 8305270358 8305270349 8305270340	83/04/26 83/05/09 83/03/30 83/04/19 83/05/25	50-335 50-259 50-348 50-389 50-333	0 0 0	8305270506 8305270508 8305270509 8305270516 8305270518	8305270479 8305270491 8305270499 8305270499 8305270497	83/04/07 83/04/07 83/04/13 83/04/13 83/04/05	50-269 50-366 50-302 50-269	0 0

ACCESS I D						ON NUMBER			
		b		_		do the to		DI 171 187 4	_
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	CATEOC	
8305270519	8305270512	83/05/10	50-395	a	5055074150	20010			_
8305270520	8305270507	83/05/02	50~387	Q	8305270452		83/04/07	50-259	9
8305270521	B305270511	83/04/27	50~369	O	8305270458	8305270642	83/04/07	50-259	a
B305270522	0305270512	83/05/10	50-395	ā	6305270659	8305270451	83/04/11	50-390	-G
8305270523	8305270491	83/04/07	50-345 50-366	ä	8305270660	8305270653	83/04/13	50-259	Œ
					8305270461	0305270642	83/04/07	50-259	G
8305270525	8305270499	83/04/13	50-302 50-259	g	6305270862	8305270656	83/05/24	50-412	G
8305270526	8305270514	83/03/30		Q	8305270464	8305270653	B3/04/13	50-259	Ğ.
8305270527	B305270513	B3/04/22	20-580	G.	8305270665	8305270653	83/04/13	50-259	G.
8305270528	8305270510	83/04/22	50-259	G	8305270666	8305270642	83/04/07	30-259	ã
8305270529	8305270507	83/05/02	50-389	Q	630327044B	8305270653	83/04/13	50-259	æ
B305270532	8305270512	83/05/10	50-395	a	8305310003	8305230113	83/05/17	50~537	
8305270534	0305270517	83/03/29	50-338	Q	8305310004	8305310001			A
8305270535	8305270507	83/05/02	50-389	G	8305310007	8305310001	83/05/19	50-320	8
8305270536	8305270491	83/04/07	50-366	Q			83/05/19	50-320	
8305270537	8305270524	83/04/11	50-438	Q.	8305310010	8305310001	83/05/19	50-320	8
8305270541	8305270513				8305310014	8305310001	83/05/19	50-320	8
8305270541	8305270513	83/04/22 83/05/02	50-280 50-389	Q	8305310019	B305310001	83/05/19	50-320	8
				g .	8305310022	8305310016	83/04/28	70-1201	-
9305270544	8305270530	10/4/01	50-338	a	8305310024	8305310001	83/05/19	50-320	8
8305270550	B305270491	83/04/07	50-366	Q.	8305310030	8305310001	83/05/19	50-320	8
B305270551	8305270546	83/04/05	50-400	œ	8305310036	8305310001	83/05/19	50-320	ĕ
					8305310041	8305310001			
8305270556	8305270548	83/04/20	70-27		8305310047		83/05/19	50-320	8
8305270562	8305270540	83/04/15	50-390	Q		8305310001	83/05/19	50-320	8
8305270567	8305270557	83/05/02	50-390	œ	6305310054	8305310001	83/05/19	50-320	8
8305270572	8305270559	83/04/14	50-335	G	8305310057	8305310053	83/05/25	50-327	P
0305270574	8305270565	83/03/29	\$0-260	a	8305310041	8305310001	83/05/19	50-320	8
8305270576	8305270561	83/04/06	50~335	Q	9305310066	930531000i	83/05/19	50-320	8
8305270578	8305270571	83/05/19	50-244	ñ	8305310070	9305310059	83/05/25	50-247	Ū
8305270579	8305270559	83/04/14	30-335	œ.	8305310072	8305310001	83/05/19	50-320	6
8305270584	8305270559	83/04/14	50-335	œ.	8305310078	8305310001	83/05/19	50-320	ã
					8305310080	8305310001	83/05/19	50-320	8
8305270587	8305270548	83/04/05	50-251	G	0305310004				
8305270588	8305270580	83/05/05	50-324	Q	8305310084	8305310073	83/05/24	50-366	G.
8305270592	8305270582	83/05/05	50-438	Q	8305310087	8305310001	83/05/19	50-320	8
8305270593	8305270585	83/04/25	50-416	Q.	8305310087	8305310083	83/05/20	50-269	b
8305270594	8305270559	83/04/14	50-335	G	8305310091	8305310001	83/05/19	50-320	8
8305270596	8305270585	83/04/25	50-416	Q.	8305310092	8305310073	83/05/26	50-366	G
8305270597	8305270589	83/04/29	50-43B	Q	8305310074	8305310001	83/05/19	50-320	8
8305270599	8305270580	83/05/06	50-324	Q	8305310097	8305310073	93/05/26	50-366	a
				a	1010155058	1000125028	83/05/19	50-320	s
8305270601	8305270582	83/05/05	50-439	-	8305310103	830531005B	63/05/25	50-320	P
8305270602	8305270590	83/04/13	50-413	a	8305310107	8305310001	83/05/19	50-320	8
8305270607	8305270582	83/05/05	50-438	a					
8305270608	8305270589	83/04/29	50-43B	G	6305310110	8305310104	B3/05/25	50~482	G
B305270610	8305270580	83/05/06	50-324	Q	8305310112	8305310105	B3/05/12	50-254	Œ
8305270413	8305270600	83/05/25	70-143		6305310114	8305310001	83/05/19	20-320	8
8305270614	0303270605	83/05/12	50-346	œ	8305310115	8305310109	83/04/06	70-1113	
8305270615	8305270609	83/05/10	50-400	G	8305310117	8305310113	83/05/24	50-237	Œ
8305270616	8305270589	83/04/29	50-438	a	8305310133	8305310125	83/05/19	50-244	Р
8305270617				-	8305310134	8305310132	83/04/06	70-1113	•
8305270617	8305270580 8305270582	83/05/06	50-324 50-438	G	8305310135	8305310130	83/05/23	50-275	р
		83/05/05		a	8305310140	8305310130	83/05/23		þ
8305270619	8305270589	83/04/29	50-438	G	8305310141	8305310125	83/05/19	50-275 50-244	þ
8305270420	8305270609	83/05/10	50-400	Q				20-K44	
B305270621	8305270580	83/05/06	50-324	Q:	8305310153	8305310150	83/05/27	50-204	8
8305270626	8305270607	83/05/10	50-400	ē	8305310157	6305310125	83/05/19	50-244	₽
8305270628	B305270580	93/05/06	50-324	ā	8305310159	8305310125	83/05/19	50-244	P
8305270629	B305270589	83/04/29	50-43B	ā	8305310181	8305310176	83/05/16	50-331	Q.
8305270631	8305270609	83/05/10	50-400	ä	8305310191	8305310186	83/05/26	50-275	R
					8305310199	8305310194	83/05/25	50-313	9
8305270632	8305270623	83/05/03	50-400	a	8305310203	8305310178			_
8305270635	6303270580	83/05/06	50-324	G.	8305310220	8305310178	83/05/27	50-329	R
8305270639	8305270585	83/04/25	50-416	Q	6303310239	9305310239	83/05/05	70-25	
8305270645	8305270638	83/05/19	50-410	G	8305310237		B3/05/20	50~309	H
8305270648	B305270640	83/04/25	70-143		5303310541	8305310240	83/05/17	50-582	P

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5 Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2 Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2. Preparatory and backup documents for item 1.
- 3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators,
- 2. NRC examination results.
- 3. Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- 1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
- All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4 Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements, description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- I Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1 Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2 Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

1&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. 1&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. 1&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE. For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are.

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.
- NOTE. For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "p" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

- inspection reports
 - Inspection reports of the applicant's quality assurance program.
 - 2. Notices of deviations.
 - 3. Follow-up correspondence resolving deviations cited.

2 Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

- Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of liaison and cooperative activities regarding such functions as licensing and siting. It includes

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4 NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3 Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		NUREG-0540 Vol. 5, No. 5			
4 TITLE AND SUBTITLE (Add Volume No , if appropriate)		2 (Leave blank)			
Title List of Documents Made Publicly Availabl	е	1			
Title List of Documents Made Publicly Availabl May 1-31, 1983		3 RECIPIENT'S ACC	CESSION NO		
7 AUTHOR(S)		5 DATE REPORT C	OMPLETED		
		MONTH	YEAR		
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include .	7 0-1-1	0.75 5-8-9-			
Division of Technical Information and Document		DATE REPORT IS	YEAR		
Office of Administration	COILCEOI	August	1983		
U.S. Nuclear Regulatory Commission		6 (Leave blank)			
Washington, DC 20555					
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	Zıp Codel	8 (Leave blank)			
Same as 9, above.	,	10 PROJECT/TASK/	WORK UNIT NO		
Suite as 5, above.		11 FIN NO			
13 TYPE OF REPORT	PERIOD COVERE	D (Inclusive dates)			
Monthly	May	y 1-31, 1983			
15. SUPPLEMENTARY NOTES		14 (Leave blank)			
16 ABSTRACT (200 words or less)					
This document is a monthly publication contain received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	information r plants and received ar The followi	includes (1) d other uses o nd generated b ing indexes ar	docketed f radio- y NRC e included:		
17. KEY WORDS AND DOCUMENT ANALYSIS	7a DESCRIPTORS				
17b IDENTIFIERS/OPEN-ENDED TERMS					
18 AVAILABILITY STATEMENT	19 SECURITY	CLASS (This report)	21 NO OF PAGES		
	Unclas	sified	22 02/05		
Unlimited	20 SECURITY Unclas	CLASS (This page)	22 PRICE S		